

**OWNER:** ABS JETS  
**ADDRESS:** ABS JETS C/O CAIMITO ENTERPRISES  
 LIMITED  
 PRAGUE 6 161 00  
**PHONE:** +420 220 111 196  
**FAX:** +420 220 112 623

**OPERATOR:** ABS JETS  
**ADDRESS:** ABS JETS C/O CAIMITO ENTERPRISES  
 LIMITED  
 PRAGUE 6 161 00  
**PHONE:** +420 220 111 196  
**FAX:** +420 220 112 623

**ANALYST:** GARY LEEVER  
**EMAIL:** GARY.LEEVER@CAMPSYSTEMS.COM

+44 (790) 312-5319 (DIRECT)  
 912-298-1280 (OFFICE)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST  
 ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO  
 CAMP.

**Filter Criteria:** Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe, Engine, APU Etc;

<b>AIRCRAFT</b>	<b>SERIAL/REGNO:</b> 6160/OK-EVO	<b>MODEL:</b> G650	<b>MANUFACTURER:</b> GULFSTREAM AEROSPACE CORPORATION
-----------------	----------------------------------	--------------------	---

<b>DATES</b>		<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
CERTIFICATION DATE:	24-AUG-2015	2718.9	A/C HRS	as of	27-JUN-2025
INSERVICE DATE:	11-MAR-2016	989	AFL	as of	_____
MANUFACTURER DATE:	06-AUG-2015	2050	APH	as of	_____
		0	APS	as of	_____

<b>APU</b>	<b>SERIAL/PART:</b> P-269/WE3800700-1	<b>MODEL:</b> RE220(GVI)	<b>MANUFACTURER:</b> HONEYWELL
<b>INSTALLED ON 13-AUG-2015</b>		<b>LAST ACTUALS</b>	<b>CURRENT ACTUAL</b>
0	APU HRS	2050 APU HRS	as of 27-JUN-2025

<b>ENGINE NO. 1</b>	<b>SERIAL/PART:</b> 26163/DEL116	<b>MODEL:</b> BR725A1-12 (G650)	<b>MANUFACTURER:</b> ROLLS-ROYCE DERBY PLC
<b>INSTALLED ON 28-NOV-2022</b>		<b>LAST ACTUALS</b>	<b>CURRENT ACTUAL</b>
0	ENG. HRS	2051.7 A/C HRS	667.2 ENG. HRS as of 27-JUN-2025

<b>ENGINE NO. 2</b>	<b>SERIAL/PART:</b> 26162/DER116	<b>MODEL:</b> BR725A1-12 (G650)	<b>MANUFACTURER:</b> ROLLS-ROYCE DERBY PLC
<b>INSTALLED ON 28-NOV-2022</b>		<b>LAST ACTUALS</b>	<b>CURRENT ACTUAL</b>
0	ENG. HRS	2051.7 A/C HRS	667.2 ENG. HRS as of 27-JUN-2025

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
	<b>AIRFRAME - AD - 6160/OK-EVO</b>						
	994081 - FAA AD 2023-21-05 THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES						NOT APPLICABLE - BY PN OF EQUIPMENT INSTALLED
		DAYS	30 (s)	29-FEB-2024			
		HRS/MSC		2373.5			
		AFL		818			
EASA 994048	EASA AD 2017-0192 - RECARO AIRCRAFT SEATING MODEL 3510A/3150D - MODIFICATION					MANDATORY	NOT APPLICABLE - NA. N/A BY SEAT P/N INSTALLED
		MOS		28-FEB-2018			
		HRS/MSC	-	646.3			
		AFL		171			
EASA 994049	EASA AD 2017-0225 - SCHROTH SAFETY PRODUCTS GMBH - SEAT RESTRAINT SYSTEMS – AFM AMENDMENT / MODIFICATION					MANDATORY	NOT APPLICABLE - NA. N/A BY EQUIPMENT INSTALLED
		MOS		28-FEB-2018			
		HRS/MSC	-	646.3			
		AFL		171			
EASA 994050	EASA AD 2016-0167 R1 - REAR CABIN ATTENDANT SEAT – INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - NA. N/A BY EQUIPMENT INSTALLED
		MOS		28-FEB-2018			
		HRS/MSC	-	646.3			
		AFL		171			
EASA 994052	EASA AD 2018-0195 - ANJOU AERONAUTIQUE - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSY					MANDATORY	NOT APPLICABLE - NA. N/A BY EQUIPMENT INSTALLED
		MOS		28-SEP-2018			
		HRS/MSC	-	794			
		AFL		217			
EASA 994053	EASA AD 2018-0223 - B/E AEROSPACE FISCHER - SEAT ENERGY ABSORBER ASSY - MODIFICATION					MANDATORY	NOT APPLICABLE - NA. N/A BY EQUIPMENT INSTALLED
		MOS		31-OCT-2018			
		HRS/MSC	-	858.5			
		AFL		229			
EASA 994055	EASA AD 2018-0247 TRIG AVIONICS LTD TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - NA. N/A BY PN OF EQUIPMENT INSTALLED
		MOS		30-NOV-2018			
		HRS/MSC	-	870.8			
		AFL		238			
EASA 994057	EASA AD 2019-0004 - THALES AVS FRANCE SAS - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS					MANDATORY	NOT APPLICABLE - NA. N/A BY MANUFACTURER OF EQUIPMENT INSTALLED
		MOS		28-FEB-2019			
		HRS/MSC	-	925.3			
		AFL		256			
EASA 994058	EASA AD 2018-0262 - IPECO HOLDING LTD - PILOT AND CO-PILOT SEATS - MODIFICATION / INSPECTION					MANDATORY	NOT APPLICABLE - NA. N/A BY MANUFACTURER OF EQUIPMENT INSTALLED
		MOS		28-FEB-2019			
		HRS/MSC	-	925.3			
		AFL		256			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 994060	EASA AD 2019-0010 - SAFRAN AEROSYSTEMS - LIFE JACKET - REMOVAL/REPAIR					MANDATORY	NOT APPLICABLE - NA. N/A BY MANUFACTURER OF EQUIPMENT INSTALLED
		MOS		27-MAR-2019			
		HRS/MSC	-	952.2			
		AFL		277			
FAA 2015-20-10	AD 2015-20-10 GULFSTREAM AEROSPACE CORPORATION					MANDATORY	COMPLIED WITH - CW
13-NOV-2015		MOS		05-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
FAA 2015-24-06	AD 2015-24-06 GULFSTREAM AEROSPACE CORPORATION					CANCELLED	NOT APPLICABLE - NA
04-DEC-2015		MOS		23-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
FAA 2017-04-01	FAA 2017-04-01 - FLIGHT CONTROLS - ACCOMPLISH AN FCC SOFTWARE UPDATE AS APPLICABLE					MANDATORY	NOT APPLICABLE - NA. NO FURTHER ACTION REQ'D DUE PCW ASC037
28-MAR-2017		MOS		16-MAY-2018			
		HRS/MSC	- (s)	703.3			
		AFL		184			
FAA 2017-20-08	FAA 2017-20-08 - FUSELAGE - REVISE THE LIMITATIONS SECTION OF THE APPLICABLE GULFSTREAM AFM SPECIFIED IN PARAGRAPHS (H)(1) THROUGH (H)(6) OF THIS AD TO INCLUDE THE INFORMATION IN THE APPLICABLE GULFSTREAM AFM SUPPLEMENT (AFMS) SPECIFIED					MANDATORY	COMPLIED WITH - CW. SUPPLEMENT INSTALLED INTO THE AFM
06-NOV-2017		MOS		16-NOV-2017			
		HRS/MSC	- (s)	542			
		AFL		147			
FAA 2018-12-07	FAA 2018-12-07 - LANDING GEAR - MODIFICATION OF THE MLG AND BRAKE ASSEMBLIES FOLLOWING THE ACCOMPLISHMENT OF GULFSTREAM G650 CB155B, DATED JULY 26, 2017 AND GULFSTREAM G650ER CUSTOMER BULLETIN 155B DATED JULY 26, 2017					MANDATORY	NOT APPLICABLE - NA. NO FURTHER ACTION REQ'D DUE PREVIOUS ACCOMPLISHMENT OF CB155A AND ASC084A
23-JUL-2018		MOS		02-JUL-2018			
		HRS/MSC	- (s)	725.7			
		AFL		191			
FAA 2018-20-04	FAA 2018-20-04 - FLIGHT CONTROL - REVISE THE NORMAL PROCEDURES AND ABNORMAL PROCEDURES SECTIONS OF THE AIRPLANE FLIGHT MANUAL					MANDATORY	COMPLIED WITH - CW. REQUIREMENTS SATISFIED AS SUPPLEMENT INCLUDED IN ELECTRONIC AFM
15-OCT-2018		MOS		01-OCT-2018			
		HRS/MSC	- (s)	795.9			
		AFL		218			
FAA 2019-23-11	FAA 2019-23-11 - FLIGHT CONTROLS - REVISE THE AIRPLANE FLIGHT MANUAL (AFM) BY ADDING AN AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS), WHICH CONTAINS OPERATING LIMITATIONS AND ABNORMAL PROCEDURES FOR LOSS OF RUDDER OR YAW DAMPER					MANDATORY	COMPLIED WITH - PCW ASC134A PT1 FAA AMOC # 7A0-19-14875
30-DEC-2019		DAYs		02-JAN-2020			
		HRS/MSC	-	1300.7			
		AFL		382			
FAA 2020-02-18	FAA 2020-02-18 - FLIGHT CONTROLS - REVISE THE AIRPLANE FLIGHT MANUAL (AFM) BY ATTACHING AN AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS)					MANDATORY	COMPLIED WITH - REQUIREMENT OF AD SATISFIED
13-FEB-2020		DAYs		14-FEB-2020			
		HRS/MSC	-	1322.8			
		AFL		396			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-11-01	FAA 2020-11-01 - FLIGHT CONTROLS - PFCAS REMOTE ELECTRONICS UNIT (REU) - SOFTWARE UPDATE					MANDATORY	COMPLIED WITH - CB 201 / ASC 069 CARRIED OUT 25 APRIL 2018
27-JUL-2020		MOS HRS/MSC - AFL		30-JUN-2020 1403.3 435			
FAA 994046	FAA AD 2017-22-02 – PILOT AND CO-PILOT SEATS – MODIFICATION					MANDATORY	NOT APPLICABLE - NA. N/A BY EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		28-FEB-2018 646.3 171			
FAA 994047	FAA AD 2017-19-05 - SIEMENS S.A.S SMOKE DETECTOR REPLACEMENT					MANDATORY	NOT APPLICABLE - NA. N/A BY PN INSTALLED
		MOS HRS/MSC - AFL		28-FEB-2018 646.3 171			
FAA 994051	FAA AD 2018-03-04 - ROSEMOUNT PITOT PROBES					MANDATORY	NOT APPLICABLE - NA. BY SN OF EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		28-MAR-2018 693.4 179			
FAA 994054	FAA AD 2018-19-15 GEVEN S.P.A. SEAT ASSEMBLIES, TYPE D1- 02 AND D1-03					MANDATORY	NOT APPLICABLE - NA. N/A BY EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		30-NOV-2018 870.8 238			
FAA 994056	FAA AD 2018-23-01 ZODIAC SEATS FRANCE CABIN ATTENDANT SEATS					MANDATORY	NOT APPLICABLE - NA. N/A DUE EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		30-NOV-2018 870.8 238			
FAA 994059	FAA AD 2019-01-02 - ASPEN AVIONICS, INC., EVOLUTION FLIGHT DISPLAY UNITS					MANDATORY	NOT APPLICABLE - NA. N/A BY MANUFACTURER OF EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		28-FEB-2019 925.3 256			
FAA 994062	FAA AD 2019-07-03 - EQUIPMENT / FURNISHINGS – REAR CABIN ATTENDANT SEAT – INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - NA. N/A DUE EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		31-JUL-2019 1125.8 323			
FAA 994063	FAA AD 2019-13-03 - TRIG AVIONICS TT31 MODE S TRANSPONDERS AVADYNE CORPORATION AXP340 MODE S TRANSPONDERS BENDIX KING / HONEYWELL KT74 TRANSPONDERS					MANDATORY	NOT APPLICABLE - NA. N/A BY PN OF EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		31-JUL-2019 1125.8 323			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 994064	FAA AD 2019-14-05 - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - MODIFICATION					MANDATORY	NOT APPLICABLE - NA. N/A BY PN OF EQUIPMENT INSTALLED
		MOS		31-JUL-2019			
		HRS/MSC	-	1125.8			
		AFL		323			
FAA 994065	FAA AD 2019-15-10 - EQUIPMENT / FURNISHINGS - SAFRAN LIFE JACKETS					MANDATORY	NOT APPLICABLE - NA. N/A BY MANUFACTURER OF EQUIPMENT INSTALLED
		MOS		30-AUG-2019			
		HRS/MSC	-	1160.4			
		AFL		338			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APPLIANCE - 6160/OK-EVO</b>							
CAA UK G-2025-0002	APPLIANCE AD - CAA UK G-2025-0002 - PILOT & CO-PILOT SEATS - INSPECTION / MODIFICATION (MANDATORY)					MANDATORY	NOT APPLICABLE - BY PART:
25-APR-2025		MOS HRS/MSC - AFL		16-APR-2025			
EASA 2019-0235	EASA 2019-0235 - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - E.L.T. NEVER INSTALLED ON A HELICOPTER
04-OCT-2019		MOS HRS/MSC - AFL		05-OCT-2020 1497.1 485			
EASA 2021-0137	APPLIANCE AD - SAFRAN SEATS - PILOT & CO-PILOT SEATS / LONGITUDINAL LOCKING SYSTEM PINS - MEASUREMENT / ADJUSTMENT						NOT APPLICABLE - N/A BY PN OF EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		30-JUN-2021 1629.8 577			
EASA 2024-0024	APPLIANCE AD - EASA 2024-0024 - NAVIGATION - DIGITAL AIR DATA COMPUTER - REPLACEMENT (MANDATORY)					MANDATORY	NOT APPLICABLE - BY PART:
07-FEB-2024		MOS HRS/MSC - AFL		25-JAN-2024			
EASA 2025-0088	APPLIANCE AD - EASA 2025-0088 - NAVIGATION - SATELLITE BASED AUGMENTATION SYSTEMS / GLOBAL POSITIONING SYSTEM RECEIVER - REPLACEMENT (MANDATORY)					MANDATORY	
30-APR-2025		MOS HRS/MSC AFL	24	(EFF)	30-APR-2027		
+ FAA 1974-08-09 R03	FAA 1974-08-09 R03 - EQUIPMENT/FURNISHINGS - INSTALLATION OF PLACARDS PROHIBITING SMOKING IN THE LAVATORY AND DISPOSAL OF CIGARETTES IN THE LAVATORY WASTE RECEPTACLES					MANDATORY	COMPLIED WITH
28-MAR-2012		MOS HRS/MSC - AFL		07-JUL-2022 1906.9 641			
FAA 2015-08-07	FAA 2015-08-07 - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	COMPLIED WITH - CW
16-JUN-2015		MOS HRS/MSC - (s) AFL		20-MAR-2017 372.3 97			
FAA 2015-23-09 INSPECT	AD 2015-23-09 ZODIAC AEROTECHNICS FLIGHTCREW OXYGEN MASK REGULATORS (PART 1 - INSPECT)					MANDATORY	NOT APPLICABLE - NA
28-DEC-2015		MOS HRS/MSC - (s) AFL		07-JAN-2016 12.3 5			
FAA 2015-23-09 REPLACE	AD 2015-23-09 ZODIAC AEROTECHNICS FLIGHTCREW OXYGEN MASK REGULATORS (PART 2 - REPLACE)					MANDATORY	NOT APPLICABLE - NA
28-DEC-2015		MOS HRS/MSC - (s) AFL		07-JAN-2016 12.3 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2016-11-20	FAA 2016-11-20 - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					CANCELLED	NOT APPLICABLE - NA. N/A BY PBE PART NUMBER INSTALLED
15-JUL-2016		MOS HRS/MSC AFL	-	22-JUL-2016 145.1 34			
FAA 2017-18-12	FAA 2017-18-12 - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE - NA. N/A BY PART, ESSEX INDUSTRIES P/N: MR10093N INSTALLED
		MOS HRS/MSC AFL	- (s)	27-APR-2018 701.4 182			
FAA 2018-21-14	FAA 2018-21-14 - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NA. N/A BY PN OF CREW OXYGEN MASK REGULATORS INSTALLED
27-MAR-2019		MOS HRS/MSC AFL	- (s)	27-MAR-2019 952.2 277			
FAA 2019-21-06	APPLIANCE AD - FAA AD 2019-21-06 - EQUIPMENT/FURNISHINGS - IPECO PILOT & CO-PILOT SEATS MODIFICATION (N/A EQUIPMENT NOT INSTALLED)					N/A EQUIPMENT NOT INSTALLED	NOT APPLICABLE - N/A BY MANUFACTURER OF SEATS INSTALLED
		MOS HRS/MSC AFL	N/A	29-NOV-2019 1259.4 365			
FAA 2020-18-51-E	FAA 2020-18-51-E - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT					MANDATORY	NOT APPLICABLE - N/A EQUIPMENT/PART NUMBER NOT INSTALLED
31-AUG-2020		MOS HRS/MSC AFL	- (s)	28-AUG-2020 1442.5 461			
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT (NOT APPLICABLE)					NOT APPLICABLE	NOT APPLICABLE - N/A DUE EQUIPMENT NOT INSTALLED
		MOS HRS/MSC AFL	N/A	30-APR-2021 1610.9 566			
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE (NOT APPLICABLE)					NOT APPLICABLE	NOT APPLICABLE - N/A BY PN OF EQUIPMENT INSTALLED
		MOS HRS/MSC AFL	N/A	30-APR-2021 1610.9 566			
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPDATE (NOT APPLICABLE)					NOT APPLICABLE	NOT APPLICABLE - N/A DUE EQUIPMENT NOT INSTALLED
		MOS HRS/MSC AFL	N/A	30-APR-2021 1610.9 566			
FAA 2021-23-12	FAA 2021-23-12 - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	COMPLIED WITH
09-DEC-2021		MOS HRS/MSC AFL	-	30-DEC-2021 1733.9 608			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-09-09	FAA 2023-09-09 - EXHAUST TURBINE SYSTEM (RECIP) - SPOT-WELDED MULTI-SEGMENT EXHAUST TAILPIPE V-BAND COUPLING - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
39-22432 17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-09-09 PARA (H)	FAA 2023-09-09 PARA (H) - REVIEW THE AIRCRAFT MAINTENANCE RECORDS TO DETERMINE THE NUMBER OF HOURS TIS ACCUMULATED ON EACH V-BAND COUPLING					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-09-09 PARA (I)	FAA 2023-09-09 PARA (I) - REMOVE THE V-BAND COUPLING FROM SERVICE AND INSTALL A NEW V-BAND COUPLING					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-09-09 PARA (J)	FAA 2023-09-09 PARA (J) - VISUALLY INSPECT THE V-BAND COUPLING					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-09-09 PARA (K)	FAA 2023-09-09 PARA (K) - INSPECTIONS WITHOUT REMOVAL OF THE V-BAND COUPLING					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
39-22432 17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-09-09 PARA (L)	FAA 2023-09-09 PARA (L) - INSPECTIONS WITH THE SPOT-WELDED, MULTI-SEGMENT EXHAUST TAILPIPE V-BAND COUPLING REMOVED					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
39-22432 17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-09-09 PARA (M)	FAA 2023-09-09 PARA (M) - INSTALLATION PROHIBITIONS					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT AND ENGINE MODEL
17-JUL-2023		MOS HRS/MSC - AFL			05-MAR-2024		
FAA 2023-10-02	APPLIANCE AD - FAA 2023-10-02 - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION (MANDATORY)					MANDATORY	NOT APPLICABLE - NOT ADOPTED BY EASA
26-MAY-2023		MOS HRS/MSC - (s) AFL			30-JUN-2023 2217.8 769		
FAA 2023-10-02 PARA (H)	FAA 2023-10-02 PARA (H) - REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE- 2023 - SATISFIED BY FAA 2021-23-12) (MANDATORY)					MANDATORY	NOT APPLICABLE - PCW THROUGH FAA AD 2021-23-12
26-MAY-2023		MOS HRS/MSC - (s) AFL			30-JUN-2023 2217.8 769		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-10-02 PARA (I)	FAA 2023-10-02 PARA (I) - REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023) (MANDATORY)					MANDATORY	NOT APPLICABLE - NOT ADOPTED BY EASA
26-MAY-2023		MOS HRS/MSC - (s) AFL		30-JUN-2023 2217.8 769			
FAA 2023-12-25	FAA 2023-12-25 - EQUIPMENT / FURNISHINGS - SURVITEC GROUP LIMITED (RFD BEAUFOT LTD.) TYPE 102 MK 3, 102 MK 4 AND TYPE 105 MK 1 LIFE JACKETS - REPLACE					MANDATORY	NOT APPLICABLE - BY MANUFACTURER OF EQUIPMENT INSTALLED
39-22484 23-AUG-2023		MOS HRS/MSC - (s) AFL		22-JUL-2023 2252.6 778			
FAA 2023-13-11 39-22496 05-SEP-2023	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT (MANDATORY)					MANDATORY	NOT APPLICABLE - BY PART:
FAA 2023-13-11 PARA (H) 39-22496 05-SEP-2023	INSPECT THE OXYGEN VALVE ASSEMBLIES AND OXYGEN CYLINDER AND VALVE ASSEMBLIES (MANDATORY)					MANDATORY	NOT APPLICABLE - BY PART:
FAA 2023-13-11 PARA (J) 39-22496 05-SEP-2023	REPORT THE RESULTS OF THE INSPECTION AND RETURN PARTS (AS REQUIRED) (MANDATORY)					MANDATORY	NOT APPLICABLE - BY PART:
FAA 2023-14-10 39-22510 07-SEP-2023	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - INSPECTION/MODIFICATION (MANDATORY)					MANDATORY	NOT APPLICABLE - BY MANUFACTURER OF EQUIPMENT INSTALLED
FAA 2023-14-10 PARA (G)(1) 07-SEP-2023	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (SEATS THAT HAVE NOT INSTALLED THE TRACK LOCK SPRING MODIFICATION KIT) (MANDATORY)					MANDATORY	NOT APPLICABLE - BY MANUFACTURER OF EQUIPMENT INSTALLED
FAA 2023-14-10 PARA (G)(2) 07-SEP-2023	INSPECT THE TRACK LOCK SPRING OF EACH SEAT (MANDATORY)					MANDATORY	NOT APPLICABLE - BY MANUFACTURER OF EQUIPMENT INSTALLED
FAA 2023-14-10 PARA (G)(3) 07-SEP-2023	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO (MANDATORY)					MANDATORY	NOT APPLICABLE - BY MANUFACTURER OF EQUIPMENT INSTALLED
FAA 2023-14-10 PARA (H) 07-SEP-2023	MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT (MANDATORY)					MANDATORY	NOT APPLICABLE - BY MANUFACTURER OF EQUIPMENT INSTALLED
		MOS HRS/MSC - AFL		09-AUG-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-21-05	APPLIANCE AD - FAA 2023-21-05 - NAVIGATION - FLIGHT MANAGEMENT COMPUTER 2/NAVIGATION MODULES - OPERATIONAL LIMITATIONS/AMENDMENT (MANDATORY)					MANDATORY	NOT APPLICABLE - BY PART: N/A BY PN OF EQUIPMENT INSTALLED
39-22577 12-DEC-2023		MOS HRS/MSC - AFL		28-MAR-2024			
FAA 2025-07-01	APPLIANCE AD - 2025-07-01 - THOMMEN AIRCRAFT EQUIPMENT AG (THOMMEN) AC32 DIGITAL AIR DATA COMPUTERS (ADCS) (MANDATORY)					MANDATORY	NOT APPLICABLE - NOT EQUIPPED:
39-23002 15-MAY-2025		MOS HRS/MSC - AFL		28-APR-2025			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - 6160/OK-EVO</b>							
ACB	ACB004A PART I	ACB004A PART I - LANDING GEAR (ATA 32), INSPECTION - BRAKE INLET SELF-SEALING COUPLINGS TORQUE				MANDATORY	COMPLIED WITH - CW
06-NOV-2015		MOS HRS/MSC - (s) AFL		05-JAN-2016 12.3 5			
ACB	ACB004A PART II	ACB004A PART II - LANDING GEAR (ATA 32), INSPECTION - BRAKE INLET SELF-SEALING COUPLINGS TORQUE				MANDATORY	NOT APPLICABLE - NA
06-NOV-2015		MOS HRS/MSC - (s) AFL		23-MAR-2017 372.3 97			
ACB	ACB006	ACB006 - ENGINE (ATA 72), INSPECTION- HIGH PRESSURE COMPRESSOR VARIABLE STATOR VANES MECHANISM (ROLLS-ROYCE NMSB SB-BR700-72-900178)					COMPLIED WITH - CW
11-JUL-2019		MOS HRS/MSC - (s) AFL		13-JUL-2019 1090.8 314			
ACB	ACB007	ACB007 - FUSELAGE STRUCTURE (ATA 53) - OPERATIONAL LIMITATIONS - AUXILIARY POWER UNIT ENCLOSURE INSTALLATION				MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
04-JAN-2021		MOS HRS/MSC - AFL		05-JAN-2021 1592.1 544			
ACB	ACB008	ACB008 - ACB008 - FUSELAGE STRUCTURE (ATA 53), OPERATIONAL LIMITATIONS - AUXILIARY POWER UNIT ENCLOSURE INSTALLATION - SEALANT APPLICATION				MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
02-JUL-2021		MOS HRS/MSC - AFL					
ACB	ACB009	ACB009 - ACB009 - FUSELAGE STRUCTURE (ATA 53) - OPERATIONAL LIMITATIONS - AUXILIARY POWER UNIT ENCLOSURE INSTALLATION - EXHAUST DUCT FASTENER PITCH				MANDATORY	COMPLIED WITH
22-OCT-2021		MOS HRS/MSC - AFL		24-OCT-2021 1694.9 601			
ASC	ASC001B	ASC 001B - G650 DATAPLATE - INSTALLATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS HRS/MSC - AFL		05-MAY-2016 0 0			
ASC	ASC002A	ASC002A - COMMUNICATIONS (ATA 23) COMMUNICATION MANAGEMENT FUNCTION (CMF) ARINC DIRECT (SM) DATALINK SERVICE PROVIDER				OPTIONAL	COMPLIED WITH - CW
08-APR-2014		MOS HRS/MSC - AFL		05-JAN-2016 12.3 5			
ASC	ASC003A	ASC003A - COMMUNICATIONS (ATA 23) COMMUNICATION MANAGEMENT FUNCTION (CMF) SATCOM DIRECT SM DATALINK SERVICE PROVIDER				CANCELLED	
08-APR-2014		MOS HRS/MSC - AFL		0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC004	ASC004 - INFORMATION SYSTEMS (ATA 46) AIRCRAFT HEALTH AND TREND MONITORING SYSTEM (AHTMS) - CELL PHONE DATA TRANSMISSION OPTION					CANCELLED	COMPLIED WITH - CW
16-AUG-2013		MOS		05-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
ASC ASC004A	ASC004A - INFORMATION SYSTEMS (ATA 46) - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM (AHTMS) - CELL PHONE DATA TRANSMISSION OPTION					CANCELLED	
21-JUN-2016		MOS					
		HRS/MSC	-	0			
		AFL		0			
ASC ASC005B	ASC005B - NAVIGATION (ATA 34) RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
15-MAY-2014		MOS		05-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
ASC ASC005C	ASC005C - NAVIGATION (ATA 34) - RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	NOT APPLICABLE - PCW EARLIER REVISION
21-JUL-2023		MOS		15-AUG-2023			
		HRS/MSC	-				
		AFL					
ASC ASC006B	ASC006B - NAVIGATION (ATA 34) LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					CANCELLED	COMPLIED WITH - CW
08-APR-2014		MOS		05-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
ASC ASC006C	ASC006C - NAVIGATION (ATA 34) - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					CANCELLED	NOT APPLICABLE - NA. PCW ASC006B
		MOS		27-APR-2018			
		HRS/MSC	-	701.4			
		AFL		182			
ASC ASC006D	ASC006D - NAVIGATION (ATA 34) - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					OPTIONAL	NOT APPLICABLE - PREVIOUS REVISION CARRIED OUT
03-MAR-2021		MOS					
		HRS/MSC	-				
		AFL					
ASC ASC007A	ASC007A - NAVIGATION (ATA 34) PREDICTIVE WINDSHEAR (PWS) - ACTIVATION					OPTIONAL	COMPLIED WITH - CW
22-MAY-2014		MOS		05-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
ASC ASC008A	ASC008A - INDICATING / RECORDING (ATA 31) XM WEATHER SYSTEM - INSTALLATION (NEW INSTALLATIONS DISCONTINUED SEE ALL MOL-22-0016)					OPTIONAL	
05-JUN-2014		MOS					
		HRS/MSC	-	0			
		AFL		0			
ASC ASC010 PART 1	ASC010 PART 1 - AIRCRAFT GENERAL (ATA 4) EUROPEAN AVIATION SAFETY AGENCY (EASA) CERTIFICATION BASIC REQUIREMENTS					CANCELLED	COMPLIED WITH - CW
17-JUN-2013		MOS		01-JUL-2016			
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC010 PART 2	ASC010 PART 2 - AIRCRAFT GENERAL (ATA 4) EUROPEAN AVIATION SAFETY AGENCY (EASA) CERTIFICATION BASIC REQUIREMENTS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
17-JUN-2013		MOS		23-OCT-2019			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC010A PART 1	ASC010A PART 1 - AIRCRAFT GENERAL (ATA 04) - EUROPEAN AVIATION SAFETY AGENCY (EASA) CERTIFICATION BASIC REQUIREMENTS (FQMS IN LBS)					OPTIONAL	NOT APPLICABLE - NA. ASC 010 COMPLIED WITH AT BUILD. NO FURTHER WORK REQUIRED.
23-OCT-2019		MOS		24-OCT-2019			
		HRS/MSC	-	1205.8			
		AFL		354			
ASC ASC010A PART 2	ASC010A PART 2 - AIRCRAFT GENERAL (ATA 04) - EUROPEAN AVIATION SAFETY AGENCY (EASA) CERTIFICATION BASIC REQUIREMENTS (FQMS IN KGS)					OPTIONAL	NOT APPLICABLE - NA. ASC 010 COMPLIED WITH AT BUILD. NO FURTHER WORK REQUIRED
23-OCT-2019		MOS		24-OCT-2019			
		HRS/MSC	-	1205.8			
		AFL		354			
ASC ASC014B PART 1	ASC014B PART 1 - AIRCRAFT GENERAL (ATA 4) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		05-APR-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC014B PART 2	ASC014B PART 2 - AIRCRAFT GENERAL (ATA 4) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		05-APR-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC014C PART 1	ASC014C PART 1 - AIRCRAFT GENERAL (ATA 4) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
05-APR-2016		MOS		28-OCT-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC014C PART 2	ASC014C PART 2 - AIRCRAFT GENERAL (ATA 4) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
05-APR-2016		MOS		28-OCT-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC014D PART 1	ASC014D PART 1 - AIRCRAFT GENERAL (ATA 4) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					OPTIONAL	
28-OCT-2016		MOS					
		HRS/MSC	-	0			
		AFL		0			
ASC ASC014D PART 2	ASC014D PART 2 - AIRCRAFT GENERAL (ATA 4) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					OPTIONAL	
28-OCT-2016		MOS					
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC016	ASC016 - ENGINE FUEL AND CONTROL (ATA 73), ENGINE ELECTRONIC CONTROLLER - K7.1.3 SOFTWARE UPGRADE				OPTIONAL	COMPLIED WITH - CW	
	MOS			19-FEB-2018			
	HRS/MSC	-		632.8			
	AFL			168			
ASC ASC026	ASC026 - PLACARDS AND MARKINGS (ATA 11) - AIRPORT ACCESS - 74,900 POUND WEIGHT LIMITATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
06-SEP-2013	MOS			28-OCT-2016			
	HRS/MSC	-		0			
	AFL			0			
ASC ASC026A	ASC026A - PLACARDS AND MARKINGS (ATA 11) - AIRPORT ACCESS 74,900 POUND WEIGHT LIMITATION				OPTIONAL		
28-OCT-2016	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC027	ASC027 - PLACARDS AND MARKINGS (ATA 11) - AIRPORT ACCESS - 90,000 POUND WEIGHT LIMITATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
06-SEP-2013	MOS			28-OCT-2016			
	HRS/MSC	-		0			
	AFL			0			
ASC ASC027A	ASC027A - PLACARDS AND MARKINGS (ATA 11) - AIRPORT ACCESS - 90,000 POUND WEIGHT LIMITATION				OPTIONAL		
28-OCT-2016	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC028	ASC028 - PLACARDS AND MARKINGS (ATA 11) - AIRPORT ACCESS - 95,000 POUND WEIGHT LIMITATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
06-SEP-2013	MOS			28-OCT-2016			
	HRS/MSC	-		0			
	AFL			0			
ASC ASC028A	ASC028A - PLACARDS AND MARKINGS (ATA 11) - AIRPORT ACCESS - 95,000 POUND WEIGHT LIMITATION				OPTIONAL		
28-OCT-2016	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC030	ASC030 - PLACARDS AND MARKINGS (ATA 11) - MAXIMUM ZERO FUEL WEIGHT REDUCTION - 60,000 POUNDS				OPTIONAL		
20-MAY-2014	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC036	ASC036 - NAVIGATION (ATA 34) - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT VERSION 2 INSTALLATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
15-DEC-2014	MOS			15-JUN-2016			
	HRS/MSC	-		0			
	AFL			0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC036A	ASC036A - NAVIGATION (ATA 34) - AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) OUT VERSION 2INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-JUN-2016		MOS		24-AUG-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC036B	ASC036B - NAVIGATION (ATA 34) - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT VERSION 2 INSTALLATION					OPTIONAL	COMPLIED WITH - CW. COMPLIED WITH AS ASC 036 AT BUILD
23-AUG-2016		MOS		07-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
ASC ASC037	ASC037 - FLIGHT CONTROLS (ATA 27) - FCC SOFTWARE UPDATE					CANCELLED	COMPLIED WITH - CW
		MOS		18-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
ASC ASC037A	ASC037A - FLIGHT CONTROLS (ATA 27) - FCC SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW. PREVIOUSLY COMPLIED WITH AT BUILD 18 JAN 2016
		MOS		06-NOV-2016			
		HRS/MSC	-	243.6			
		AFL		67			
ASC ASC038	ASC038 - INDICATING / RECORDING (ATA 31) - PLANEVIEW II AVIONICS ENHANCEMENT					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-DEC-2016		MOS		22-DEC-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC038A	ASC038A - INDICATING / RECORDING (ATA 31) - PLANEVIEW II AVIONICS ENHANCEMENT					CANCELLED	COMPLIED WITH - CW
22-DEC-2016		MOS		30-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
ASC ASC038B	ASC038B - INDICATING / RECORDING (ATA 31) - PLANEVIEW II AVIONICS ENHANCEMENT					OPTIONAL	COMPLIED WITH
15-JUL-2019		MOS		29-SEP-2022			
		HRS/MSC	-	1996.9			
		AFL		677			
ASC ASC046	ASC046 - PLACARDS AND MARKINGS (ATA 11) - MAXIMUM ZERO FUEL WEIGHT REDUCTION 59,500 POUNDS					OPTIONAL	
20-MAY-2014		MOS					
		HRS/MSC	-	0			
		AFL		0			
ASC ASC048 PART 2	ASC048 PART 2 - FLIGHT CONTROLS (ATA 27), SPOILER JOINT ANTI-ROTATION RETENTION WASHER - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
12-AUG-2016		MOS		26-OCT-2017			
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC048A PART 2	ASC048A PART 2 - FLIGHT CONTROLS (ATA 27) - SPOILER JOINT ANTI-ROTATION RETENTION WASHER - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
26-OCT-2017		MOS		12-APR-2018			
		HRS/MSC	-	701			
		AFL		181			
ASC ASC051	ASC051 - ELECTRICAL POWER (ATA 24) - SECONDARY POWER DISTRIBUTION - SYSTEM (SPDS) SOFTWARE UPDATE					CANCELLED	COMPLIED WITH - CW
01-NOV-2016		MOS		31-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
ASC ASC051A	ASC051A - ELECTRICAL POWER (ATA 24) - SECONDARY POWER DISTRIBUTION SYSTEM (SPDS) SOFTWARE UPDATE					OPTIONAL	NOT APPLICABLE - NA. PCW ASC 051. AFMS G650-2016-02 CONFIRMED AS REMOVED
		MOS		16-MAY-2018			
		HRS/MSC	-	703.3			
		AFL		184			
ASC ASC054B	ASC054B - EQUIPMENT AND FURNISHINGS (ATA 25) - EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - INSTALLATION, AIRCRAFT SERVICE CHANGE (NOT APPLICABLE)					NOT APPLICABLE	NOT APPLICABLE - BY AIRCRAFT S/NO
06-APR-2021		MOS					
		HRS/MSC	-				
		AFL					
ASC ASC055A	ASC055A - LANDING GEAR (ATA 32) AUTOBRAKE SYSTEM - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
11-DEC-2015		MOS		06-JUN-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC055B	ASC055B - LANDING GEAR (ATA 32) - AUTOBRAKE SYSTEM - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-JUN-2016		MOS		07-DEC-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC055C	ASC055C - LANDING GEAR (ATA 32) - AUTOBRAKE SYSTEM - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
06-DEC-2016		MOS		31-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
ASC ASC058	ASC058 - DOORS (ATA 52) MAIN ENTRANCE DOOR - STORAGE BOX SPRING REPLACEMENT					OPTIONAL	COMPLIED WITH - CW
28-MAY-2015		MOS		01-JUL-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC065	ASC065 - DOORS (ATA 52), MAIN ENTRANCE DOOR MANUAL OPERATION MECHANISM - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
26-JUN-2017		MOS		15-JUN-2018			
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC065A	ASC065A - DOORS (ATA 52) - MAIN ENTRANCE DOOR MANUAL OPERATION MECHANISM - INSTALLATION					OPTIONAL	
	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC068	ASC068 - EQUIPMENT AND FURNISHINGS (ATA 25) - BAGGAGE COMPARTMENT - GRAB HANDLE - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
01-JUN-2016	MOS			12-OCT-2016			
	HRS/MSC	-		0			
	AFL			0			
ASC ASC068A	ASC068A - EQUIPMENT AND FURNISHINGS (ATA 25) - BAGGAGE COMPARTMENT GRAB HANDLE - INSTALLATION					OPTIONAL	
12-OCT-2016	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC069	ASC069 - FLIGHT CONTROLS (ATA 27) PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
28-SEP-2017	MOS			24-APR-2018			
	HRS/MSC	-		701			
	AFL			181			
ASC ASC070	ASC070 - AIR CONDITIONING (ATA 21), COCKPIT AIR DUCTING - VELOCITY REDUCTION					OPTIONAL	
15-DEC-2016	MOS						
	HRS/MSC	-		0			
	AFL			0			
ASC ASC071	ASC071 - COMMUNICATION(ATA 23) - COMMUNICATION MANAGEMENT FUNCTION (CMF) GLOBAL DATA CENTER (GDC) DATALINK SERVICE PROVIDER, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT S/NO
27-MAY-2021	MOS						
	HRS/MSC	-					
	AFL						
ASC ASC073	ASC073 - LANDING GEAR (ATA 32) - TIRE PRESSURE MONITORING UNIT (TPMU) SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
18-AUG-2016	MOS			21-MAR-2017			
	HRS/MSC	-		372.3			
	AFL			97			
ASC ASC074	ASC074 - LANDING GEAR (ATA 32) - NOSE WHEEL STEERING SYSTEM - UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-APR-2017	MOS			16-JUN-2017			
	HRS/MSC	-		0			
	AFL			0			
ASC ASC074A	ASC074A - LANDING GEAR (ATA 32) - NOSE WHEEL STEERING SYSTEM - UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-JUN-2017	MOS			15-AUG-2017			
	HRS/MSC	-		0			
	AFL			0			
ASC ASC074B	ASC074B - LANDING GEAR (ATA 32) - NOSE WHEEL STEERING SYSTEM - UPGRADE					OPTIONAL	COMPLIED WITH - CW
15-AUG-2017	MOS			11-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC074C	ASC074C - LANDING GEAR (ATA 32) - NOSE WHEEL STEERING SYSTEM - UPGRADE					OPTIONAL	NOT APPLICABLE - ASC074B PCW. NO FURTHER ACTION REQUIRED
11-AUG-2020		MOS HRS/MSC - AFL		10-SEP-2020 1448.4 465			
ASC ASC075	ASC075 - PLACARDS AND MARKINGS (ATA 11) - BAGGAGE COMPARTMENT ACCESS MODIFICATION					OPTIONAL	COMPLIED WITH - CW
31-JAN-2017		MOS HRS/MSC - AFL		19-APR-2018 701 181			
ASC ASC076	ASC076 - INFORMATION SYSTEMS (ATA 46) - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM - SOFTWARE UPDATE 2					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS HRS/MSC - AFL		28-OCT-2019 0 0			
ASC ASC076A	ASC076A - INFORMATION SYSTEMS (ATA 46) - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM - SOFTWARE UPDATE 2					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
25-OCT-2019		MOS HRS/MSC - AFL		04-NOV-2019 0 0			
ASC ASC076B	ASC076B - INFORMATION SYSTEMS (ATA 46) - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM - SOFTWARE UPDATE 2					OPTIONAL	COMPLIED WITH
01-NOV-2019		MOS HRS/MSC - AFL		05-FEB-2020 1310.3 388			
ASC ASC078	ASC078 - COMMUNICATIONS (ATA 23) HIGH-DEFINITION (HD) CAMERA SYSTEM - INSTALLATION					OPTIONAL	
31-MAR-2017		MOS HRS/MSC - AFL		0 0 0			
ASC ASC079	ASC079 - LANDING GEAR (ATA 32) - LANDING GEAR CONTROL UNIT MOD D UPDATE					OPTIONAL	COMPLIED WITH - CW
06-MAY-2016		MOS HRS/MSC - AFL		09-APR-2018 701 181			
ASC ASC081	ASC081 - DOORS (ATA 52), MAIN ENTRANCE DOOR LATCH ACTUATOR - UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
08-MAY-2017		MOS HRS/MSC - AFL		21-AUG-2017 0 0			
ASC ASC081A	ASC081A - DOORS (ATA 52), MAIN ENTRANCE DOOR LATCH ACTUATOR - UPGRADE					CANCELLED	COMPLIED WITH - CW
18-AUG-2017		MOS HRS/MSC - AFL		23-APR-2018 701 181			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC081B	ASC081B - DOORS (ATA 52) - MAIN ENTRANCE DOOR LATCH ACTUATOR - UPGRADE					OPTIONAL	NOT APPLICABLE - NA. NO FURTHER ACTION REQ'D AS PREVIOUSLY COMPLIED WITH ASC081A
28-JUN-2018		MOS		02-JUL-2018			
		HRS/MSC	-	725.7			
		AFL		191			
ASC ASC083	ASC083 - WINGS (ATA 57) - FLAP TRACK D RUB STRIPS - REMOVAL					OPTIONAL	COMPLIED WITH
12-DEC-2019		MOS		15-JAN-2021			
		HRS/MSC	-	1594.1			
		AFL		547			
ASC ASC084	ASC 084 MAIN LANDING GEAR AND BRAKE ASSEMBLY - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
29-JUL-2016		MOS		19-AUG-2016			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC084A	ASC 084A MAIN LANDING GEAR AND BRAKE ASSEMBLY - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
19-AUG-2016		MOS		29-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
ASC ASC085	ASC 085 KA-BAND FIN CAP RADOME - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
10-MAR-2017		MOS		07-MAR-2019			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC085A	ASC 085A KA-BAND FIN CAP RADOME - INSTALLATION					CANCELLED	
06-MAR-2019		MOS					
		HRS/MSC	-	0			
		AFL		0			
ASC ASC086	ASC 086 MAIN ENTRY DOOR - SERVICE DOOR PANEL SECURITY COVER - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
23-JUN-2016		MOS		21-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
ASC ASC087	ASC 087 MODIFICATION (FOR INSTALLATION OF 72P5210904Z005 MAIN ENTRANCE DOOR DAMPER ASSEMBLY					OPTIONAL	
20-MAR-2018		MOS					
		HRS/MSC	-	0			
		AFL		0			
ASC ASC088	ASC 088 ENGINE ELECTRONIC CONTROLLER - K8.0.2 SOFTWARE UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
10-SEP-2018		MOS		26-SEP-2018			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC088A	ASC 088A ENGINE ELECTRONIC CONTROLLER - K8.0.2 SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
26-SEP-2018		MOS		11-MAR-2019			
		HRS/MSC	-	925.3			
		AFL		256			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC089	ASC 089 DOORS (ATA 52), MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP STOP BOLTS - REPLACEMENT					OPTIONAL	COMPLIED WITH - CW
16-DEC-2016		MOS		29-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
ASC ASC090A	ASC 090A HYDRAULIC FILTER MONITORING SYSTEM - INSTALLATION AND ACTIVATION					OPTIONAL	COMPLIED WITH
28-FEB-2020		MOS		29-JAN-2022			
		HRS/MSC	-	1745.4			
		AFL		610			
ASC ASC091	ASC 091 ACOUSTIC DOOR NOISE REDUCTION - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
09-AUG-2017		MOS		01-DEC-2017			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC091A	ASC 091A ACOUSTIC DOOR NOISE REDUCTION - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
01-DEC-2017		MOS		10-APR-2018			
		HRS/MSC	-	701			
		AFL		181			
ASC ASC092	ASC 092 PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) MOTOR CONTROL ELECTRONICS (MCE) SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
28-SEP-2017		MOS		24-APR-2018			
		HRS/MSC	-	701			
		AFL		181			
ASC ASC093	ASC 093 FLIGHT CONTROLS (ATA 27) - FCC SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
		MOS		23-APR-2018			
		HRS/MSC	-	701			
		AFL		181			
ASC ASC094	ASC 094 DOORS (ATA 52) - ELECTRIC MAIN ENTRANCE DOOR (EMED) WEAR PAD MODIFICATION					OPTIONAL	COMPLIED WITH - CW
21-DEC-2016		MOS		22-DEC-2016			
		HRS/MSC	-	285.5			
		AFL		77			
ASC ASC095	ASC 095 AUXILIARY POWER UNIT ENCLOSURE INSTALLATION - MODIFICATION					SUPERSEDED	- SUPERSEDED
20-DEC-2019		MOS					
		HRS/MSC	-				
		AFL					
ASC ASC096	ASC 096 8.8 KHZ UNDERWATER ACOUSTIC BEACON (UAB) INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
01-NOV-2017		MOS		17-OCT-2019			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC096A PART 1	ASC 096A 8.8 KHZ UNDERWATER ACOUSTIC BEACON (UAB) INSTALLATION (PART 1)					OPTIONAL	
17-OCT-2019		MOS					
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC096A PART 2	ASC 096A 8.8 KHZ UNDERWATER ACOUSTIC BEACON (UAB) INSTALLATION (PART 2)					OPTIONAL	
17-OCT-2019	MOS HRS/MSC - AFL	0 0					
ASC ASC097	ASC 097 PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) CONNECTOR UPDATES				OPTIONAL	COMPLIED WITH - CW	
28-SEP-2017	MOS HRS/MSC - AFL	24-APR-2018 701 181					
ASC ASC098	ASC 098 HORIZONTAL STABILIZER CONTROL UNIT (HSCU) SOFTWARE UPDATE				OPTIONAL	COMPLIED WITH - CW	
	MOS HRS/MSC - AFL	09-APR-2018 701 181					
ASC ASC099	ASC 099 MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP MECHANISM IMPROVEMENT				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
	MOS HRS/MSC - AFL	16-JAN-2018 0 0					
ASC ASC099A	ASC 099A MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP MECHANISM IMPROVEMENT				OPTIONAL	COMPLIED WITH - CW	
15-JAN-2018	MOS HRS/MSC - AFL	24-APR-2018 701 181					
ASC ASC100A	ASC100A - INDICATING / RECORDING (ATA 31) - PLANEVIEW™ II AVIONICS ENHANCEMENT, AIRCRAFT SERVICE CHANGE (OPTIONAL)				OPTIONAL	COMPLIED WITH	
03-APR-2024	MOS HRS/MSC - AFL	06-DEC-2024 2483.7 900					
ASC ASC101	ASC 101 STEEP APPROACH TO LANDING ACTIVATION				OPTIONAL		
15-JUL-2019	MOS HRS/MSC - AFL	0 0					
ASC ASC102	ASC 102 MODIFICATION FCC SOFTWARE V8.2 UPDATE				OPTIONAL	COMPLIED WITH - CW	
15-NOV-2018	MOS HRS/MSC - AFL	14-MAR-2019 925.3 256					
ASC ASC103	ASC 103 AUXILIARY HYDRAULIC PUMP - GROUNDING INSTALLATION				OPTIONAL	COMPLIED WITH - CW	
07-AUG-2018	MOS HRS/MSC - AFL	06-MAR-2019 925.3 256					
ASC ASC105	ASC 105 - DATA LAN MANAGEMENT UNIT HARNESS - SERVICE LOOP INSTALLATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
	MOS HRS/MSC - AFL	12-MAR-2019 0 0					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC105A	ASC 105A - DATA LAN MANAGEMENT UNIT HARNESS - SERVICE LOOP INSTALLATION					OPTIONAL	
12-MAR-2019	MOS HRS/MSC - AFL			0 0			
ASC ASC106	ASC 106 PILOT CLOCK WIRING HARNESS - SERVICE LOOP INSTALLATION					OPTIONAL	
13-FEB-2018	MOS HRS/MSC - AFL			0 0			
ASC ASC109	ASC109 - PLACARDS / MARKINGS (ATA 11) - CATEGORY II APPROACH ENHANCEMENT, AIRCRAFT SERVICE CHANGE (SUPERSEDED)					SUPERSEDED	NOT APPLICABLE - SUPERSEDED
26-MAR-2021	MOS HRS/MSC - AFL						
ASC ASC109A	ASC109A - PLACARDS / MARKINGS (ATA 11) - CATEGORY II APPROACH ENHANCEMENT, AIRCRAFT SERVICE CHANGE (OPTIONAL)				26-SEP-2022 1996.9 677	OPTIONAL	COMPLIED WITH
20-APR-2021	MOS HRS/MSC - AFL						
ASC ASC110A	ASC 110A FLAP ELECTRONIC CONTROL UNIT (FECU) SOFTWARE - UPDATE					OPTIONAL	COMPLIED WITH
23-JAN-2020	MOS HRS/MSC - AFL			02-FEB-2022 1745.4 610			
ASC ASC111	ASC 111 ENGINE FIRE BOTTLE HARNESS INSTALLATION - MODIFICATION					CANCELLED	COMPLIED WITH - CW
31-JUL-2018	MOS HRS/MSC - AFL			14-MAR-2019 925.3 256			
ASC ASC111A	ASC 111A ENGINE FIRE BOTTLE HARNESS INSTALLATION - MODIFICATION					OPTIONAL	COMPLIED WITH - CW. PCW CB220 - NO FURTHER ACTION REQ'D
21-MAR-2019	MOS HRS/MSC - AFL			26-APR-2019 993.7 286			
ASC ASC113	ASC 113 APU EXHAUST FAIRING DRAINAGE - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
24-AUG-2018	MOS HRS/MSC - AFL			03-DEC-2018 0 0			
ASC ASC113A	ASC 113A APU EXHAUST FAIRING DRAINAGE - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
30-NOV-2018	MOS HRS/MSC - AFL			13-MAR-2019 925.3 256			
ASC ASC116	ASC 116 BATTERY CHARGER MODE CONTROL RELAYS AND ELECTRICAL BACKUP HYDRAULIC ACTUATOR BATTERY CHARGER NO. 2 - REMOVAL					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
13-FEB-2019	MOS HRS/MSC - AFL			10-APR-2019 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC116A	ASC 116A BATTERY CHARGER MODE CONTROL RELAYS AND ELECTRICAL BACKUP HYDRAULIC ACTUATOR BATTERY CHARGER NO. 2 - REMOVAL				OPTIONAL	COMPLIED WITH	
10-APR-2019		MOS HRS/MSC - AFL		05-FEB-2020 1310.3 388			
ASC ASC117	ASC 117 HYDRAULIC LINE SUPPORT BRACKET INSTALLATION - MODIFICATION TO PROVIDE SIDE BRACE ACTUATOR CLEARANCE				OPTIONAL	COMPLIED WITH - CW	
06-FEB-2019		MOS HRS/MSC - AFL		05-MAR-2019 925.3 256			
ASC ASC122A	FIRE PROTECTION (ATA 26) - ENGINE FIRE EXTINGUISHING BOTTLE CARTRIDGE WIRING - MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)				OPTIONAL	COMPLIED WITH	
20-JAN-2021		MOS HRS/MSC - AFL		30-JAN-2022 1745.4 610			
ASC ASC123	ASC 123 APU ELECTRONIC CONTROL UNIT SOFTWARE - UPDATE				CANCELLED	COMPLIED WITH - CW	
01-APR-2019		MOS HRS/MSC - AFL		03-OCT-2019 1201.5 351			
ASC ASC123A	ASC 123A APU ELECTRONIC CONTROL UNIT SOFTWARE - UPDATE				OPTIONAL	COMPLIED WITH - NFA REQ'D DUE PCW INITIAL REV	
27-APR-2020		MOS HRS/MSC - AFL		10-MAY-2020 1395.3 426			
ASC ASC124	ASC 124 PYLON SEAL RETAINER - MODIFICATION				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.	
21-JAN-2019		MOS HRS/MSC - AFL		08-FEB-2019 0 0			
ASC ASC124A	ASC 124A PYLON SEAL RETAINER - MODIFICATION				OPTIONAL	COMPLIED WITH	
08-FEB-2019		MOS HRS/MSC - AFL		19-JAN-2020 1310.3 388			
ASC ASC125	ASC125 - NAVIGATION (ATA 34) - HEADS UP DISPLAY (HUD) II SOFTWARE UPDATE, AIRCRAFT SERVICE CHANGE (OPTIONAL)				OPTIONAL	COMPLIED WITH	
21-JUL-2023		MOS HRS/MSC - AFL		06-DEC-2024 2483.7 900			
ASC ASC131	ASC 131 FLAP TRACK C ROLLER FITTING - RUB PAD INSTALLATION				OPTIONAL	COMPLIED WITH	
12-DEC-2019		MOS HRS/MSC - AFL		15-JAN-2021 1594.1 547			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC133	ASC 133 ENGINE ELECTRONIC CONTROLLER - K9.0.1 SOFTWARE UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
05-AUG-2019		MOS		23-AUG-2019			
		HRS/MSC	-	0			
		AFL		0			
ASC ASC133A	ASC 133A ENGINE ELECTRONIC CONTROLLER - K9.0.1 SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
22-AUG-2019		MOS		27-AUG-2019			
		HRS/MSC	-	1160.4			
		AFL		338			
ASC ASC134 PART I	ASC 134 (PART 1) WEDGE INSTALLATION - TRAILING EDGE, RUDDER					CANCELLED	COMPLIED WITH
03-DEC-2019		MOS		08-DEC-2019			
		HRS/MSC	-	1261.8			
		AFL		366			
ASC ASC134A PART I	ASC 134A (PART 1) WEDGE INSTALLATION - TRAILING EDGE, RUDDER					CANCELLED	COMPLIED WITH
06-DEC-2019		MOS		08-DEC-2019			
		HRS/MSC	-	1261.8			
		AFL		366			
ASC ASC134A PART II	ASC 134A (PART 2) WEDGE INSTALLATION - TRAILING EDGE, RUDDER						COMPLIED WITH
06-DEC-2019		MOS		05-FEB-2020			
		HRS/MSC	-	1310.3			
		AFL		388			
ASC ASC134B PART I	ASC 134B (PART 1) WEDGE INSTALLATION - TRAILING EDGE, RUDDER					NOT APPLICABLE	COMPLIED WITH - PCW ASC134A - NFA REQ'D
21-FEB-2020		MOS		01-MAY-2020			
		HRS/MSC	N/A	1395.3			
		AFL		426			
ASC ASC134B PART II	ASC 134B (PART 2) WEDGE INSTALLATION - TRAILING EDGE, RUDDER					OPTIONAL	COMPLIED WITH - PCW ASC134A - NFA REQ'D
21-FEB-2020		MOS		01-MAY-2020			
		HRS/MSC	-	1395.3			
		AFL		426			
ASC ASC135	ASC 135 FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE V10.1					OPTIONAL	COMPLIED WITH
23-MAR-2020		MOS		27-JAN-2021			
		HRS/MSC	-	1594.1			
		AFL		547			
ASC ASC138	ASC138 - ENGINE FUEL & CONTROL (ATA 73) - ENGINE ELECTRONIC CONTROLLER - K10.1 SOFTWARE UPGRADE, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	COMPLIED WITH - LDI GVI_902_00104_13_060321 PREVIOUSLY INSTALLED DURING PREVIOUS COMPLIANCE WITH ASC138-X-REFER TO GULFSTREAM AEROSPACE LIMITED WORK ORDER SC21504.SQUAWK 21.2 FOR DETAILS.
18-JUN-2021		MOS		06-MAY-2022			
		HRS/MSC	-	1867.2			
		AFL		630			
ASC ASC139	ASC139 - EQUIPMENT AND FURNISHINGS (ATA 25) - EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - REMOVAL, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	COMPLIED WITH
13-JUL-2021		MOS		29-NOV-2024			
		HRS/MSC	-	2483.7			
		AFL		900			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC140	ASC140 - INFORMATION SYSTEMS (ATA 46) - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM (AHTMS) SOFTWARE UPDATE, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	COMPLIED WITH
02-NOV-2022		MOS HRS/MSC - AFL		18-OCT-2023 2315.6 802			
ASC ASC142	ASC142 - FUSELAGE STRUCTURE (ATA 53) - AUXILIARY POWER UNIT ENCLOSURE - EXHAUST DUCT FASTENER PITCH MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT S/NO
04-APR-2022		MOS HRS/MSC - AFL					
ASC ASC144	ASC144 - NAVIGATION (ATA 34) - ATTITUDE HEADING REFERENCE UNIT LABEL INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	COMPLIED WITH
15-FEB-2024		MOS HRS/MSC - AFL		28-NOV-2024 2483.7 900			
ASC ASC146	EQUIPMENT AND FURNISHINGS (ATA 25) - EBHA PDB TERMINAL BRACKET COVER - INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	COMPLIED WITH
29-SEP-2023		MOS HRS/MSC - AFL		05-DEC-2024 2483.7 900			
ASC ASC902	ASC902 - INDICATING / RECORDING (ATA 31) - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS HRS/MSC - AFL		22-DEC-2016 0 0			
ASC ASC902A	ASC902A - INDICATING / RECORDING (ATA 31) - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
		MOS HRS/MSC - AFL		30-MAR-2017 372.3 97			
ASC ASC902B	ASC902B - INDICATING / RECORDING (ATA) - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH
15-JUL-2019		MOS HRS/MSC - AFL		29-SEP-2022 1996.9 677			
CB CB067A	CB067A - INDICATING/RECORDING SYSTEMS (ATA 31), MODIFICATION - CO-PILOTS CREW ALERTING SYSTEM (CAS) SCROLL SWITCH WIRING					MANDATORY	NOT APPLICABLE - NA
20-JAN-2015		MOS HRS/MSC - (s) AFL		05-JAN-2016 12.3 5			
CB CB069A	CB069A - FUSELAGE (ATA 53) INSPECTION - TAILCONE ASSEMBLY SEALANT APPLICATION					MANDATORY	NOT APPLICABLE - NA
05-FEB-2015		MOS HRS/MSC - (s) AFL		28-JAN-2016 21.2 7			
CB CB076B	CB076B - COMMUNICATIONS (ATA 23), MODIFICATION - HIGH SPEED DATA - SOFTWARE UPGRADE					MANDATORY	COMPLIED WITH - CW. FOUND EMBODIED
18-MAR-2015		MOS HRS/MSC - (s) AFL		06-JUN-2016 108.8 28			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB087	CB087 - FIRE PROTECTION (ATA 26), INSPECTION - ENGINE FIRE BOTTLE CARTRIDGE (SQUIB) ELECTRICAL CONNECTIONS					CANCELLED	NOT APPLICABLE - NA. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-SEP-2015		MOS HRS/MSC AFL	-	05-JAN-2016 12.3 5			
CB CB087A	CB087A - FIRE PROTECTION (ATA 26) INSPECTION - ENGINE FIRE BOTTLE CARTRIDGE (SQUIB) ELECTRICAL CONNECTIONS					MANDATORY	NOT APPLICABLE - NA
15-SEP-2015		MOS HRS/MSC AFL	- (s)	05-JAN-2016 12.3 5			
CB CB088	CB088 - DOORS (ATA 52), REPLACEMENT - MAIN ENTRANCE DOOR TORQUE TUBE BEARING HOUSING HARDWARE					MANDATORY	NOT APPLICABLE - NA
15-SEP-2015		MOS HRS/MSC AFL	- (s)	05-JAN-2016 12.3 5			
CB CB089	CB089 - EQUIPMENT AND FURNISHINGS (ATA 25), REPLACEMENT - FLASHLIGHTS (ASC 025)					MANDATORY	NOT APPLICABLE - NA
06-JUL-2015		MOS HRS/MSC AFL	- (s)	05-JAN-2016 12.3 5			
CB CB090	CB090 - EQUIPMENT AND FURNISHINGS (ATA 25), INSPECTION - PASSENGER SEAT RESTRAINT SYSTEM (AMSAFE SB 504443-25-02)					CANCELLED	NOT APPLICABLE - NA. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-SEP-2015		MOS HRS/MSC AFL	-	05-JAN-2016 12.3 5			
CB CB090A	CB090A - EQUIPMENT AND FURNISHINGS (ATA 25), INSPECTION - PASSENGER SEAT RESTRAINT SYSTEM (AMSAFE SB 504443-25-02)					CANCELLED	NOT APPLICABLE - NA. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-SEP-2015		MOS HRS/MSC AFL	-	05-JAN-2016 12.3 5			
CB CB090B	CB090B - EQUIPMENT AND FURNISHINGS (ATA 25), INSPECTION - PASSENGER SEAT RESTRAINT SYSTEM (AMSAFE SB 504443-25-02)					MANDATORY	NOT APPLICABLE - NA
16-OCT-2015		MOS HRS/MSC AFL	- (s)	05-JAN-2016 12.3 5			
CB CB091	CB091 - STANDARD PRACTICES (ATA 20), INSPECTION - ITT CANNON CONNECTORS					CANCELLED	NOT APPLICABLE - NA
16-SEP-2015		MOS HRS/MSC AFL	-	24-FEB-2016 25 9			
CB CB091A	CB091A - STANDARD PRACTICES (ATA 20) INSPECTION - ITT CANNON CONNECTORS					MANDATORY	NOT APPLICABLE - NA
11-FEB-2016		MOS HRS/MSC AFL	- (s)	24-FEB-2016 25 9			
CB CB092	CB092 - NACELLES AND PYLONS (ATA 54), INSPECTION - GEARBOX BREather FLEX BOOT CLAMPS					MANDATORY	NOT APPLICABLE - NA
16-SEP-2015		MOS HRS/MSC AFL	- (s)	05-JAN-2016 12.3 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB093	CB093 - EQUIPMENT AND FURNISHINGS (ATA 25), REPLACEMENT - FLASHLIGHTS (OXLEY)					MANDATORY	NOT APPLICABLE - NA
16-SEP-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB094	CB094 - ICE AND RAIN PROTECTION (ATA 30), INSTALLATION - WINDSHIELD HEAT TEMPERATURE SENSING ELEMENT BONDING JUMPER (ASC 067)				MANDATORY	NOT APPLICABLE - NA	
21-SEP-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB095	CB095 - WATER/WASTE (ATA 38), REPLACEMENT - WATER STERILIZER FILTERS					MANDATORY	COMPLIED WITH - CW
14-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB096	CB096 - EQUIPMENT AND FURNISHINGS (ATA 25), INSPECTION - VELCRO INSTALLATION ONUPPER INSTRUMENT PANEL AND GLARESHIELD					MANDATORY	NOT APPLICABLE - NA
20-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB097	CB097 - LANDING GEAR (ATA 32), INSPECTION - MAIN LANDING GEAR DOOR STOP BOLT RIGGING					MANDATORY	NOT APPLICABLE - NA
20-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB098	CB098 - ICE AND RAIN PROTECTION (ATA 30), INSPECTION - INLET COWL ANTI-ICE PRESSURE SENSING LINE					MANDATORY	NOT APPLICABLE - NA
22-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB099	CB099 - DOORS (ATA 52), INSPECTION - MAIN ENTRANCE DOOR (MED) WIRING HARNESS ROUTING					MANDATORY	NOT APPLICABLE - NA
22-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB100	CB100 - DOORS (ATA 52), INSPECTION - MAIN ENTRANCE DOOR DAMPER RIGGING					MANDATORY	NOT APPLICABLE - NA
28-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB101	CB101 - DOORS (ATA 52), INSPECTION - AUXILIARY PRESSURE BULKHEAD DOOR TRACK					MANDATORY	NOT APPLICABLE - NA
29-OCT-2015	MOS HRS/MSC - (s) AFL			05-JAN-2016 12.3 5			
CB CB102	CB102 - FLIGHT CONTROLS (ATA 27), MODIFICATION - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPGRADE 6.24 (ASC 037)					MANDATORY	COMPLIED WITH - CW
06-NOV-2015	MOS HRS/MSC - (s) AFL			18-JAN-2016 12.3 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB103	CB103 - FIRE PROTECTION (ATA 26), INSPECTION - ENGINE FIRE BOTTLE ELECTRICAL HARNESS ROUTING					CANCELLED	NOT APPLICABLE - NA
10-NOV-2015		MOS		05-JAN-2016			
		HRS/MSC	-	12.3			
		AFL		5			
CB CB104A	CB104A - ELECTRICAL POWER (ATA 24), MODIFICATION - UNINTERRUPTIBLE POWER SUPPLY (UPS) BATTERY UPGRADE					MANDATORY	COMPLIED WITH - CW
12-NOV-2015		MOS		05-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
CB CB105	CB105 - STARTING (ATA 80), INSPECTION - STARTER AIR VALVE (ROLLS-ROYCE NMSB BR700-80-900020)					MANDATORY	NOT APPLICABLE - NA
17-NOV-2015		MOS		05-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
CB CB106	CB106 - FLIGHT CONTROLS (ATA 27), INSPECTION - ELEVATOR HINGES FOR PAINT DAMAGE					MANDATORY	NOT APPLICABLE - NA
17-NOV-2015		MOS		05-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
CB CB107	CB107 - WINGS (ATA 57), INSPECTION - INBOARD WING SKINS FOR EXPOSURE OF SHAVED FASTENERS (TRIUMPH SB MAA7-71258-08)					CANCELLED	NOT APPLICABLE - NA
		MOS		14-OCT-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB108	CB108 - ENGINE FUEL AND CONTROL (ATA 73) REPLACEMENT - ENGINE DRIVEN FUEL PUMP V-BAND CLAMP (ROLLS-ROYCE SB-BR700-73-101929)					MANDATORY	COMPLIED WITH - CW
		MOS		05-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
CB CB109	CB109 - FUSELAGE (ATA 53) INSPECTION - AFT PRESSURE BULKHEAD CHANNEL BEAM FASTENERS					MANDATORY	NOT APPLICABLE - NA
30-DEC-2015		MOS		05-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
CB CB110	CB110 - ELECTRICAL POWER (ATA 24) INSPECTION - WIRE HARNESS TO SUPPORT BRACKET CONTACT					MANDATORY	NOT APPLICABLE - NA
07-JAN-2016		MOS		11-JAN-2016			
		HRS/MSC	- (s)	12.3			
		AFL		5			
CB CB111	CB111 - ELECTRICAL POWER (ATA 24) INSPECTION - ELECTRICAL BACKUP HYDRAULIC ACTUATOR (EBHA) DISTRIBUTION BOX POWER CABLES					MANDATORY	NOT APPLICABLE - NA
20-JAN-2016		MOS		21-JAN-2016			
		HRS/MSC	- (s)	21.2			
		AFL		7			
CB CB112	CB112 - ELECTRICAL POWER (ATA 24) INSPECTION - TRANSFORMER RECTIFIER UNIT (TRU) ELECTRICAL CONNECTOR WIRING					MANDATORY	NOT APPLICABLE - NA
27-JAN-2016		MOS		28-JAN-2016			
		HRS/MSC	- (s)	21.2			
		AFL		7			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB113	CB113 - ELECTRICAL POWER (ATA 24) INSPECTION - CIRCUIT BREAKER PANEL ELECTRICAL HARNESS CONTACT IN RIGHT ELECTRONIC EQUIPMENT RACK (REER)					MANDATORY	NOT APPLICABLE - NA
27-JAN-2016		MOS HRS/MSC - (s) AFL		28-JAN-2016 21.2 7			
CB CB114	CB114 - HYDRAULIC POWER (ATA 29) INSPECTION - HYDRAULIC FITTINGS AT LEFT SIDE FUSELAGE STATION (FS) 739 BULKHEAD					MANDATORY	NOT APPLICABLE - NA
28-JAN-2016		MOS HRS/MSC - (s) AFL		28-JAN-2016 21.2 7			
CB CB115	CB115 - DOORS (ATA 52) - REPLACEMENT - MAIN ENTRANCE DOOR HANDRAIL HARDWARE					MANDATORY	NOT APPLICABLE - NA
16-FEB-2016		MOS HRS/MSC - (s) AFL		24-FEB-2016 25 9			
CB CB116	CB116 - WATER/WASTE (ATA 38) INSPECTION - WATER SYSTEM TANK DRAIN HOSE CONTACT ON WATER TANK SHELF SUPPORT					MANDATORY	NOT APPLICABLE - NA
17-FEB-2016		MOS HRS/MSC - (s) AFL		24-FEB-2016 25 9			
CB CB117	CB117 - WATER / WASTE (ATA 38) INSPECTION - WATER TANK ELECTRICAL HARNESS INSTALLATION					MANDATORY	NOT APPLICABLE - NA
17-FEB-2016		MOS HRS/MSC - (s) AFL		24-FEB-2016 25 9			
CB CB118	CB118 - POWERPLANT (ATA 71) REPLACEMENT - ENGINE DRIVEN HYDRAULIC PUMP V-BAND CLAMP (ROLLS-ROYCE SB-BR700-71-101928)					MANDATORY	COMPLIED WITH - CW
17-FEB-2016		MOS HRS/MSC - (s) AFL		24-FEB-2016 25 9			
CB CB119	CB119 - WINGS (ATA 57) INSTALLATION ADD DRAIN HOLE IN FIXED TRAILING EDGE LOWER SKIN (TRIUMPH SB MAA7-71258-10)					CANCELLED	NOT APPLICABLE - NA
18-FEB-2016		MOS HRS/MSC - AFL		24-FEB-2016 25 9			
CB CB120	CB120 - FIRE PROTECTION (ATA 26) INSPECTION - ENGINE / AUXILIARY POWER UNIT (APU) FIRE BOTTLE THERMAL RELIEF DISCHARGE PORT					CANCELLED	NOT APPLICABLE - NA
18-FEB-2016		MOS HRS/MSC - AFL		24-FEB-2016 25 9			
CB CB121	CB121 - FLIGHT CONTROLS (ATA 27), INSPECTION - FLAP TORQUE SHAFTS HARDWARE					MANDATORY	COMPLIED WITH - CW
23-FEB-2016		MOS HRS/MSC - (s) AFL		24-FEB-2016 25 9			
CB CB122	CB122 - ELECTRICAL POWER (ATA 24), INSPECTION - RAM AIR TURBINE (RAT) ELECTRICAL HARNESS MISSING OVERBRAID GROUND					MANDATORY	NOT APPLICABLE - NA
24-FEB-2016		MOS HRS/MSC - (s) AFL		25-FEB-2016 25 9			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB123	CB123 - ELECTRICAL POWER (ATA 24) INSPECTION HYDRAULIC SYSTEM MANIFOLDS WIRING INSTALLATION					CANCELLED	NOT APPLICABLE - NA
25-FEB-2016		MOS		25-FEB-2016			
		HRS/MSC	-	25			
		AFL		9			
CB CB124	CB124 - ELECTRICAL POWER (ATA 24) INSPECTION ELECTRICAL HARNESS AT FUSELAGE STATION 321 BELOW FLOORS					MANDATORY	NOT APPLICABLE - NA
25-FEB-2016		MOS		25-FEB-2016			
		HRS/MSC	- (s)	25			
		AFL		9			
CB CB125	CB125 - FUSELAGE (ATA 53), INSPECTION - BAGGAGE COMPARTMENT FORWARD ELECTRONIC EQUIPMENT RACK FOR CONTACT WITH FUSELAGE STRUCTURE					MANDATORY	NOT APPLICABLE - NA
03-MAR-2016		MOS		05-MAR-2016			
		HRS/MSC	- (s)	27.2			
		AFL		10			
CB CB126	CB126 - POWERPLANT (ATA 71), REPLACEMENT - ENGINE DRIVEN HYDRAULIC PUMP DEPRESSURIZATION VALVE CONNECTOR					CANCELLED	COMPLIED WITH - CW
		MOS		16-DEC-2016			
		HRS/MSC	-	283.9			
		AFL		76			
CB CB126A	CB126A - POWERPLANT (ATA 71), REPLACEMENT - ENGINE DRIVEN HYDRAULIC PUMP DEPRESSURIZATION VALVE CONNECTOR					MANDATORY	COMPLIED WITH - CW. PREVIOUSLY COMPLIED WITH CB126 ON 16-DEC-2016 @ 283.9 FH, 76 FC
08-MAR-2016		MOS		03-MAR-2017			
		HRS/MSC	- (s)	365.2			
		AFL		95			
CB CB127	CB127 - POWERPLANT (ATA 71), INSPECTION - RIGHT ENGINE GENERAL SERVICES HARNESS INSTALLATION (ROLLS-ROYCE NMSB SB-BR700-71-900578)					MANDATORY	NOT APPLICABLE - NA
08-MAR-2016		MOS		10-MAR-2016			
		HRS/MSC	- (s)	31.2			
		AFL		11			
CB CB135	CB135 - DOORS (ATA 52), REPLACEMENT - MAIN ENTRANCE DOOR BOTTOM FOLDING STEP LINK ASSEMBLY, P/N 60P5260000A004					MANDATORY	COMPLIED WITH - CW
08-APR-2016		MOS		12-DEC-2016			
		HRS/MSC	- (s)	283.9			
		AFL		76			
CB CB138	CB138 - ENGINE (ATA 72), INSPECTION - ACCESSORY GEARBOX RADIAL DRIVE SHAFT SEAL (ROLLS-ROYCE SB-BR700-72-900589)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-APR-2016		MOS		27-APR-2016			
		HRS/MSC	-	0			
		AFL		0			
CB CB138A	CB138A - ENGINE (ATA 72) - INSPECTION - ACCESSORY GEARBOX RADIAL DRIVE SHAFT SEAL(ROLLS-ROYCE NMSB SB-BR700-72-900589)					MANDATORY	COMPLIED WITH - CW
15-APR-2016		MOS		22-MAY-2017			
		HRS/MSC	- (s)	388			
		AFL		102			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB142	CB142 - FUEL (ATA 28) - REPLACEMENT - PRESSURE FUELING SHUT-OFF VALVES, P/N L94-51-602, WITH P/N L94-51-603				CANCELLED		NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
02-MAY-2016		MOS		17-OCT-2018			
		HRS/MSC	-	0			
		AFL		0			
CB CB142A	CB142A - FUEL (ATA 28) - REPLACEMENT - PRESSURE FUELING SHUT-OFF VALVES, P/N L94-51-602, WITH P/N L94-51-603				CANCELLED		NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
17-OCT-2018		MOS		09-OCT-2019			
		HRS/MSC	- (s)	0			
		AFL		0			
CB CB142B	CB142B - FUEL (ATA 28) - REPLACEMENT - PRESSURE FUELING SHUT-OFF VALVES, P/N L94-51-602, WITH P/N L94-51-603				CANCELLED		
09-OCT-2019		MOS					
		HRS/MSC	- (s)	0			
		AFL		0			
CB CB143	CB143 - LANDING GEAR (ATA 32) - MODIFICATION - LANDING GEAR CONTROL UNIT (LGCU) MOD D UPDATE (ASC 079)				CANCELLED		NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-MAY-2016		MOS		10-MAY-2016			
		HRS/MSC	-	0			
		AFL		0			
CB CB143A	CB143A - LANDING GEAR (ATA 32) - MODIFICATION LANDING GEAR CONTROL UNIT (LGCU) MOD D UPDATE (ASC 079)				MANDATORY		COMPLIED WITH - CW
06-MAY-2016		MOS		09-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB144	CB144 - FUSELAGE STRUCTURE (ATA 53) - INSPECTION - COCKPIT WINDSHIELD AND SIDE WINDOW FRAME CORROSION				MANDATORY		COMPLIED WITH - CW
19-MAY-2016		MOS		04-FEB-2017			
		HRS/MSC	- (s)	372.2			
		AFL		97			
CB CB152	CB152 - STABILIZERS (ATA 55) INSPECTION - HORIZONTAL STABILIZER INBOARD LEADING EDGE SEAL INSTALLATION				MANDATORY		COMPLIED WITH - CW
21-JUL-2016		MOS		23-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB155	CB155 - LANDING GEAR (ATA 32), MODIFICATION - MAIN LANDING GEAR AND BRAKE ASSEMBLY (ASC 084)				CANCELLED		NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
29-JUL-2016		MOS		19-AUG-2016			
		HRS/MSC	-	0			
		AFL		0			
CB CB155A	CB155A - LANDING GEAR (ATA 32) - MODIFICATION - MAIN LANDING GEAR AND BRAKE ASSEMBLY (ASC 084A)				CANCELLED		COMPLIED WITH - CW
		MOS		28-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB155B	CB155B - LANDING GEAR (ATA 32), MODIFICATION - MAIN LANDING GEAR AND BRAKE ASSEMBLY (ASC 084A)					MANDATORY	NOT APPLICABLE - NA. PREVIOUSLY COMPLIED WITH CB155A
		MOS		11-AUG-2017			
		HRS/MSC	- (s)	445			
		AFL		121			
CB CB158	CB158 - LANDING GEAR (ATA 32), MODIFICATION - TIRE PRESSURE MONITORING UNIT (TPMU) SOFTWARE UPGRADE					MANDATORY	COMPLIED WITH - CW
18-AUG-2016		MOS		21-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB160	CB160 - ENGINE AND FUEL CONTROL (ATA 73), MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K7.1.3 SOFTWARE UPGRADE (ASC 016)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		15-AUG-2017			
		HRS/MSC	-	0			
		AFL		0			
CB CB160A	CB160A - ENGINE AND FUEL CONTROL (ATA 73), MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K7.1.3 SOFTWARE UPGRADE (ASC 016)					MANDATORY	COMPLIED WITH - CW
15-SEP-2016		MOS		20-FEB-2018			
		HRS/MSC	- (s)	632.8			
		AFL		168			
CB CB161	CB161 - ENGINE AND FUEL CONTROL (ATA 73), MODIFICATION - REPLACEMENT OF FUEL LOW PRESSURE SWITCH (ROLLS-ROYCE SB-BR700-73-101965)					MANDATORY	COMPLIED WITH - CW
		MOS		22-FEB-2018			
		HRS/MSC	- (s)	632.3			
		AFL		168			
CB CB162	CB162 - ENGINE AND FUEL CONTROL (ATA 73), MODIFICATION - REVISED FUEL SYSTEM (ROLLS-ROYCE SB-BR700-73-101957)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		15-AUG-2017			
		HRS/MSC	-	0			
		AFL		0			
CB CB166	CB166 - ELECTRICAL POWER (ATA 24) - MODIFICATION - SECONDARY POWER - DISTRIBUTION SYSTEM (SPDS) SOFTWARE - UPDATE (ASC 051)					CANCELLED	COMPLIED WITH - CW
01-NOV-2016		MOS		31-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
CB CB166A	CB166A - ELECTRICAL POWER (ATA 24) - MODIFICATION - SECONDARY POWER DISTRIBUTION SYSTEM (SPDS) SOFTWARE UPDATE (ASC 051)					MANDATORY	NOT APPLICABLE - NA. NO FURTHER ACTION REQ'D DUE PCW CB 166 AND ASC051A REQUIREMENTS ARE SATISFIED
		MOS		16-MAY-2018			
		HRS/MSC	- (s)	703.3			
		AFL		184			
CB CB168	CB168 - DOORS (ATA 52), INSPECTION - MAIN ENTRANCE DOOR HANDRAIL DRIVE FITTINGS					MANDATORY	COMPLIED WITH - CW
17-NOV-2016		MOS		12-DEC-2016			
		HRS/MSC	- (s)	283.9			
		AFL		76			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB169	CB169 - EQUIPMENT / FURNISHINGS (ATA 25) MODIFICATION - FORWARD LEFT SIDE LAVATORY WIRING INSTALLATION					CANCELLED	COMPLIED WITH - CW
22-NOV-2016		MOS		12-APR-2018			
		HRS/MSC	-	701			
		AFL		181			
CB CB169A	CB169A - EQUIPMENT / FURNISHINGS (ATA 25) - MODIFICATION - FORWARD LEFT SIDE LAVATORY WIRING INSTALLATION					MANDATORY	NOT APPLICABLE - NA. PCW CB169
		MOS		21-JUN-2018			
		HRS/MSC	- (s)	721.2			
		AFL		188			
CB CB170	CB170 - WATER / WASTE (ATA 38), MODIFICATION - REMOVAL OF WATER STERILIZER FILTER END CAP SET SCREW (IWG-A6 VENDOR SERVICE BULLETIN)					MANDATORY	COMPLIED WITH - CW
		MOS		21-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB171	CB171 - ELECTRICAL POWER (ATA 24), INSPECTION - MAIN BATTERY GROUND PADS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
12-DEC-2016		MOS		26-JAN-2017			
		HRS/MSC	-	0			
		AFL		0			
CB CB171A	CB171A - ELECTRICAL POWER (ATA 24) - INSPECTION - MAIN BATTERY GROUND PADS					MANDATORY	COMPLIED WITH - CW
12-DEC-2016		MOS		21-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB172	CB172 - DOORS (ATA 52), REPLACEMENT - MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP STOP BOLTS (ASC 089)					MANDATORY	COMPLIED WITH - CW
20-DEC-2016		MOS		29-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB174	CB174 - FLIGHT CONTROLS (ATA 27) - INSPECTION - HORIZONTAL STABILIZER TRIM ACTUATOR HARNESS					MANDATORY	COMPLIED WITH - CW
14-FEB-2017		MOS		23-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB175	CB175 - ELECTRICAL POWER (ATA 24), REPLACEMENT RAM AIR TURBINE (RAT) CONTROL HANDLE LOCKOUT PIN					MANDATORY	COMPLIED WITH - CW
23-FEB-2017		MOS		21-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB176	CB176 - DOORS (ATA 52), REPLACEMENT - MAIN ENTRANCE DOOR HANDRAIL DRIVE FITTINGS					MANDATORY	COMPLIED WITH - CW
27-FEB-2017		MOS		24-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB177	CB177 - LANDING GEAR (ATA 32), INSPECTION - MAIN LANDING GEAR SIDE BRACE ACTUATOR BAND CLAMPS					CANCELLED	COMPLIED WITH - CW
01-MAR-2017		MOS		06-APR-2018			
		HRS/MSC	-	701			
		AFL		181			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB177A	CB177A - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR SIDE BRACE ACTUATOR BAND CLAMPS (RESCINDED AND SUPERSEDED BY CB239 & ASC117)					CANCELLED	
06-FEB-2019		MOS		01-JUN-2019			
		HRS/MSC	-	1054			
		AFL		304			
CB CB178	CB178 - FUEL (ATA 28), INSPECTION - FUEL CELL OVER-WING WIRING AT FUSELAGE STATION 536					MANDATORY	COMPLIED WITH - CW
01-MAR-2017		MOS		21-MAR-2017			
		HRS/MSC	- (s)	372.3			
		AFL		97			
CB CB179	CB179 - ELECTRICAL POWER (ATA 24), INSPECTION - TAIL COMPARTMENT GROUND PADS					CANCELLED	COMPLIED WITH - CW
15-MAR-2017		MOS		31-MAR-2017			
		HRS/MSC	-	372.3			
		AFL		97			
CB CB179A	CB179A - ELECTRICAL POWER (ATA 24) - INSPECTION - TAIL COMPARTMENT GROUND PADS					CANCELLED	NOT APPLICABLE - NA. NO FURTHER ACTION REQ'D DUE PCW CB179
		MOS		16-MAY-2018			
		HRS/MSC	-	703.3			
		AFL		184			
CB CB179B	CB179B - INSPECTION – TAIL COMPARTMENT GROUND PADS						NOT APPLICABLE - NA. NO FURTHER ACTION REQUIRED
11-JUL-2019		MOS		17-JUL-2019			
		HRS/MSC	- (s)	1117.9			
		AFL		318			
CB CB180	CB180 - FUSELAGE (ATA 53), INSPECTION - AFT MID LOWER DRAIN VALVES AT FUSELAGE STATION 756					MANDATORY	COMPLIED WITH - CW
04-APR-2017		MOS		07-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB183	CB183 - DOORS (ATA 52), INSPECTION - MAIN ENTRANCE DOOR FORWARD AND AFT LOCK OUT MECHANICAL STOP BRACKET ASSEMBLIES SEALING					MANDATORY	COMPLIED WITH - CW
08-MAY-2017		MOS		19-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB184	CB184 - DOORS (ATA 52), INSPECTION - MAIN ENTRANCE DOOR P-CLAMP ORIENTATION					MANDATORY	COMPLIED WITH - CW
08-MAY-2017		MOS		10-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB186 PART I	CB186 PART I - FLIGHT CONTROLS (ATA 27), REPLACEMENT - FLAP ELECTRONIC CONTROL UNIT					MANDATORY	NOT APPLICABLE - NA. N/A BY FLAP UNIT S/N INSTALLED
06-JUN-2017		MOS		06-JUN-2017			
		HRS/MSC	- (s)	424.9			
		AFL		108			
CB CB186 PART II	CB186 PART II - FLIGHT CONTROLS (ATA 27), REPLACEMENT - FLAP ELECTRONIC CONTROL UNIT					MANDATORY	NOT APPLICABLE - NA. N/A BY FLAP UNIT S/N INSTALLED
06-JUN-2017		MOS		06-JUN-2017			
		HRS/MSC	- (s)	424.9			
		AFL		108			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB187	CB187 - LANDING GEAR (ATA 32), INSPECTION - NOSE LANDING GEAR UPPER TORQUE ARM PIN					CANCELLED	NOT APPLICABLE - NA. N/A BY TORQUE ARM PIN SN FITTED (SN: 00435 INSTALLED)
22-JUN-2017		MOS HRS/MSC - AFL		29-JUN-2017 428 110			
CB CB187A	CB187A - LANDING GEAR (ATA 32) - INSPECTION - NOSE LANDING GEAR UPPER TORQUE ARM PIN						COMPLIED WITH - CW. NO FURTHER ACTION REQUIRED
15-MAY-2019		MOS HRS/MSC - (s) AFL		01-JUN-2019 1054 304			
CB CB190	CB190 - PNEUMATIC SYSTEMS (ATA 36), INSPECTION - BLEED AIR MANIFOLD GAMAH COUPLERS					MANDATORY	COMPLIED WITH - CW. NIL DEFECTS NOTED
27-JUN-2017		MOS HRS/MSC - (s) AFL		29-JUN-2017 428 110			
CB CB193	CB193 - LANDING GEAR (ATA 32) INSPECTION - NOSE LANDING GEAR DOOR ACTUATOR TORQUE TUBES - AFT BEARINGS					MANDATORY	COMPLIED WITH - CW
15-AUG-2017		MOS HRS/MSC - (s) AFL		09-APR-2018 701 181			
CB CB194	CB194 - HYDRAULIC POWER (ATA 29), INSPECTION - HYDRAULIC RETURN TUBE AT FUSELAGE STATION (FS) 1080 LEFT					MANDATORY	COMPLIED WITH - CW
15-AUG-2017		MOS HRS/MSC - (s) AFL		10-APR-2018 701 181			
CB CB196	CB196 - DOORS (ATA 52) - MODIFICATION - MAIN ENTRANCE DOOR BOTTOM FOLDING STEP MECHANISM IMPROVEMENT (ASC 099)					MANDATORY	COMPLIED WITH - CW
25-AUG-2017		MOS HRS/MSC - (s) AFL		24-APR-2018 701 181			
CB CB197	CB197 - FLIGHT CONTROLS (ATA 27) MODIFICATION - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPGRADE 7.1 (ASC 093)					MANDATORY	COMPLIED WITH - CW
31-AUG-2017		MOS HRS/MSC - (s) AFL		23-APR-2018 701 181			
CB CB199	CB199 - FLIGHT CONTROLS (ATA 27) MODIFICATION - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) MOTOR CONTROL ELECTRONICS (MCE) SOFTWARE UPGRADE (ASC 092)					MANDATORY	COMPLIED WITH - CW
28-SEP-2017		MOS HRS/MSC - (s) AFL		24-APR-2018 701 181			
CB CB200	CB200 - FLIGHT CONTROLS (ATA 27) MODIFICATION - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) CONNECTOR INSTALLATION (ASC 097)					MANDATORY	COMPLIED WITH - CW
28-SEP-2017		MOS HRS/MSC - (s) AFL		24-APR-2018 701 181			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB201	CB201 - FLIGHT CONTROLS (ATA 27) MODIFICATION - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) SOFTWARE UPGRADE (ASC 069)					MANDATORY	COMPLIED WITH - CW
28-SEP-2017		MOS		24-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB202	CB202 - WINGS (ATA 57) - INSPECTION - WIRING INSTALLATION AT OUTBOARD FLIGHT SPOILER ATTACH FITTINGS					MANDATORY	COMPLIED WITH - CW
18-OCT-2017		MOS		10-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB203	CB203 - ELECTRICAL POWER (ATA 24) INSPECTION - WIRE ROUTING ON REER FORWARD BULKHEAD					MANDATORY	COMPLIED WITH - CW
12-DEC-2017		MOS		09-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB204	CB204 - FLIGHT CONTROLS (ATA 27) MODIFICATION - HORIZONTAL STABILIZER CONTROL UNIT (HSCU) MOD 4 (ASC 098)					CANCELLED	COMPLIED WITH - CW
25-JAN-2018		MOS		09-APR-2018			
		HRS/MSC	-	701			
		AFL		181			
CB CB204A	CB204A - FLIGHT CONTROLS (ATA 27) - MODIFICATION - HORIZONTAL STABILIZER CONTROL UNIT (HSCU) HARDWARE MOD 4 VERIFICATION AND SOFTWARE UPDATE (ASC 098)					CANCELLED	NOT APPLICABLE - NA. PCW CB204, NO FURTHER ACTION REQUIRED
		MOS		12-JUN-2018			
		HRS/MSC	-	721.2			
		AFL		188			
CB CB204B	CB204B - FLIGHT CONTROLS (ATA 27) MODIFICATION - HORIZONTAL STABILIZER CONTROL UNIT (HSCU) HARDWARE MOD 4 VERIFICATION AND SOFTWARE UPDATE (ASC 098)					MANDATORY	COMPLIED WITH - CW. NO FURTHER ACTION REQ'D DUE PCW CB 204 INITIAL REV
06-NOV-2018		MOS		13-NOV-2018			
		HRS/MSC	- (s)	863.8			
		AFL		233			
CB CB205	CB205 - FUSELAGE (ATA 53), REPLACEMENT - CABIN FLOORBOARD 7D					MANDATORY	COMPLIED WITH - OFF PN: 60P5315629A001 ON PN: 60P5315629A002 OFF/ON SN: NSN
02-MAR-2018		MOS		21-DEC-2023			
		HRS/MSC	-	2315.6			
		AFL		802			
CB CB206	CB206 - EQUIPMENT AND FURNISHINGS (ATA 25) - LIFE RAFT GAS CYLINDER REPLACEMENT AT OVERHAUL (UTAS SB 25-470)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-MAR-2018		MOS		18-MAY-2018			
		HRS/MSC	-	0			
		AFL		0			
CB CB206A	CB206A - EQUIPMENT AND FURNISHINGS (ATA 25) - LIFE RAFT GAS CYLINDER REPLACEMENT AT OVERHAUL (UTAS SB 25-470)					CANCELLED	COMPLIED WITH - CW
		MOS		12-OCT-2018			
		HRS/MSC	- (s)	809.6			
		AFL		221			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB206B	CB206B - EQUIPMENT AND FURNISHINGS (ATA 25) - LIFE RAFT GAS CYLINDER REPLACEMENT AT OVERHAUL (UTAS SB 25-470 / SB 25-476)					MANDATORY	COMPLIED WITH
05-DEC-2019		MOS		20-JAN-2021			
		HRS/MSC	-	1594.1			
		AFL		547			
CB CB207	CB207 - ELECTRICAL POWER (ATA 24) - INSPECTION - WIRE ROUTING AFT EQUIPMENT BAY AND WHEEL WELL					MANDATORY	COMPLIED WITH - CW
		MOS		19-APR-2018			
		HRS/MSC	- (s)	701			
		AFL		181			
CB CB208	CB208 - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR AXLE FITTING ASSEMBLY (UTC AEROSPACE SB C1A5400-32-009)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		13-FEB-2019			
		HRS/MSC	-	0			
		AFL		0			
CB CB208A	CB208A - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR AXLE FITTING ASSEMBLY (UTC AEROSPACE SB C1A5400-32-009)					MANDATORY	COMPLIED WITH
13-FEB-2019		MOS		05-FEB-2020			
		HRS/MSC	- (s)	1310.3			
		AFL		388			
CB CB208B	CB208B - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR AXLE FITTING ASSEMBLY (UTC AEROSPACE SB C1A5400-32-009)					MANDATORY	COMPLIED WITH - NFA REQ'D DUE PCW REV A
08-MAY-2020		MOS		10-MAY-2020			
		HRS/MSC	-	1395.3			
		AFL		426			
CB CB211	CB211 - FLIGHT CONTROLS (ATA 27) INSPECTION - FLIGHT CONTROLS WIRING HARNESS INSTALLATION UNDER ELECTRICAL BACKUP HYDRAULIC ACTUATOR (EBHA) BATTERY					MANDATORY	COMPLIED WITH - CW
		MOS		11-MAR-2019			
		HRS/MSC	- (s)	925.3			
		AFL		256			
CB CB213 PART I	CB213 PART I - FLIGHT CONTROLS (ATA 27) - REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT					CANCELLED	COMPLIED WITH - CW
		MOS		12-JUN-2018			
		HRS/MSC	-	721.2			
		AFL		188			
CB CB213 PART II	CB213 PART II - FLIGHT CONTROLS (ATA 27) - REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		07-SEP-2018			
		HRS/MSC	-	0			
		AFL		0			
CB CB213A PART I	CB213A PART I - FLIGHT CONTROLS (ATA 27) - REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT					CANCELLED	COMPLIED WITH - CW. PART 1 PCW ON CMP CODE 982130 ON 12 JUN 2018 - CB 213 INITIAL REV
07-SEP-2018		MOS		12-OCT-2018			
		HRS/MSC	-	809.6			
		AFL		221			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB213A PART II	CB213A PART II - FLIGHT CONTROLS (ATA 27) - REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
07-SEP-2018		MOS HRS/MSC AFL	-	01-NOV-2018 0 0			
CB CB213B PART I	CB213B PART I -					MANDATORY	COMPLIED WITH - CW. NO FURTHER ACTION REQ'D DUE PCW CB213 INITIAL REV
07-SEP-2018		MOS HRS/MSC AFL	- (s)	01-MAR-2019 925.3 256			
CB CB213B PART II	CB213B PART II -					MANDATORY	COMPLIED WITH - CW
07-SEP-2018		MOS HRS/MSC AFL	- (s)	04-MAR-2019 925.3 256			
CB CB214	CB214 - EQUIPMENT AND FURNISHINGS (ATA 25) - ELECTRONIC CONTROL UNIT (ECU) SOFTWARE FOR VIP SEATS(RCO SB RCO2017-10-12-1)					MANDATORY	NOT APPLICABLE - NA. N/A BY SEAT PN
		MOS HRS/MSC AFL	-	21-JUN-2018 721.2 188			
CB CB215	CB215 - EQUIPMENT / FURNISHINGS (ATA 25) - MODIFICATION - FORWARD LEFT SIDE LAVATORY CABINET WIRING INSTALLATION (GPM412004707-301 MONUMENT)					MANDATORY	NOT APPLICABLE - NA. N/A BY A/C SERIAL NUMBER
31-JUL-2018		MOS HRS/MSC AFL	-	21-JUN-2018 721.2 188			
CB CB220	CB220 - FIRE PROTECTION (ATA 26) - MODIFICATION - ENGINE FIRE BOTTLE HARNESS (ASC 111)					CANCELLED	COMPLIED WITH - CW
21-MAR-2019		MOS HRS/MSC AFL	-	11-MAR-2019 925.3 256			
CB CB220A	CB220A - FIRE PROTECTION (ATA 26) - MODIFICATION - ENGINE FIRE BOTTLE HARNESS (ASC 111)						COMPLIED WITH - CW. PCW CB220 - NO FURTHER ACTION REQ'D
21-MAR-2019		MOS HRS/MSC AFL	- (s)	26-APR-2019 993.7 286			
CB CB221	CB221 - HYDRAULIC POWER (ATA 29) - MODIFICATION - AUXILIARY HYDRAULIC PUMP GROUNDING INSTALLATION (ASC 103)					MANDATORY	COMPLIED WITH - CW
07-AUG-2018		MOS HRS/MSC AFL	-	08-MAR-2019 925.3 256			
CB CB223	CB223 - FUSELAGE STRUCTURE (ATA 53) - INSPECTION / MODIFICATION - FUSELAGE SKIN AND APU EXHAUST FAIRING (ASC 113)						COMPLIED WITH - CW
24-AUG-2018		MOS HRS/MSC AFL	- (s)	27-FEB-2019 925.3 256			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB224	CB224 - ENGINE FUEL AND CONTROL (ATA 73) - MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) K8.0.2 SOFTWARE UPGRADE (ASC 088)						COMPLIED WITH - CW
10-SEP-2018		MOS HRS/MSC - (s) AFL		11-MAR-2019 925.3 256			
CB CB225	CB225 - FLIGHT CONTROLS (ATA 27) - RETROFIT OF ELECTRICAL BACKUP (EB) HYDRAULIC MANIFOLDS					MANDATORY	
15-OCT-2018		MOS HRS/MSC - (s) AFL		0 0			
CB CB225A	CB225A - FLIGHT CONTROLS (ATA 27) - RETROFIT OF ELECTRICAL BACKUP (EB) HYDRAULIC MANIFOLDS					MANDATORY	COMPLIED WITH
14-OCT-2020		MOS HRS/MSC - AFL		27-JAN-2021 1594.1 547			
CB CB226	CB226 - FLIGHT CONTROLS (ATA 27) - INSPECTION - MOTOR CONTROL ELECTRONICS (MCE) J3 CONNECTOR (PARKER SB 469300-27-002 AND SB 469400-27-002)					MANDATORY	COMPLIED WITH
15-OCT-2018		MOS HRS/MSC - AFL		13-JAN-2021 1594.1 547			
CB CB227	CB227 - FLIGHT CONTROLS (ATA 27) - INSPECTION - AILERON MOTOR CONTROL ELECTRONICS (MCE) AND OUTBOARD SPOILER J-BOX CONNECTORS					MANDATORY	COMPLIED WITH - CW
15-OCT-2018		MOS HRS/MSC - (s) AFL		28-FEB-2019 925.3 256			
CB CB228	CB228 - NAVIGATION (ATA 34) - AIR DATA PROBE HEAT FAULT MONITORING - LOADABLE DIAGNOSTIC INFORMATION (LDI) UPDATE					MANDATORY	COMPLIED WITH - CW
19-OCT-2018		MOS HRS/MSC - (s) AFL		01-MAR-2019 925.3 256			
CB CB231	CB231 - FLIGHT CONTROLS (ATA 27) - MODIFICATION - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPGRADE 8.2 (ASC 102)					MANDATORY	COMPLIED WITH - CW
15-NOV-2018		MOS HRS/MSC - (s) AFL		14-MAR-2019 925.3 256			
CB CB232	CB232 - FIRE PROTECTION (ATA 26) - INSPECTION - RIGHT ENGINE FIRE BOTTLE ELECTRICAL HARNESS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
04-DEC-2018		MOS HRS/MSC - AFL		05-DEC-2018 0 0			
CB CB232A	CB232A - FIRE PROTECTION (ATA 26) - INSPECTION - RIGHT ENGINE FIRE BOTTLE ELECTRICAL HARNESS					MANDATORY	COMPLIED WITH - CW
05-DEC-2018		MOS HRS/MSC - (s) AFL		14-MAR-2019 925.3 256			
CB CB233	CB233 - ENGINE STARTING (ATA 80) - REPLACEMENT - BR725 ENGINE STARTER AIR VALVE (ROLLS ROYCE NMSB SB-BR700- 80-900634)					CANCELLED	COMPLIED WITH - CW
11-DEC-2018		MOS HRS/MSC - AFL		01-MAR-2019 925.3 256			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB233A	CB233A -					MANDATORY	NOT APPLICABLE - NA. NO FURTHER ACTION REQUIRED
		MOS		17-JUL-2019			
		HRS/MSC	- (s)	1117.9			
		AFL		318			
CB CB233B	CB233B - CB 233 - ENGINE STARTING (ATA 80) - REPLACEMENT - BR725 ENGINE STARTER AIR VALVE - (ROLLS ROYCE NOT APPLICABLE NMSB SB-BR700-80-900634)					NOT APPLICABLE - COMPLIANCE REMOVED AT REV B	
		MOS					
08-APR-2021		HRS/MSC	-				
		AFL					
CB CB236	CB236 - POWERPLANT (ATA 71) - INSPECTION - FORWARD UPPER ENGINE MOUNT FITTING CONTACT WITH PYLON SEAL RETAINER (ASC 124)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		01-FEB-2019			
21-JAN-2019		HRS/MSC	-	0			
		AFL		0			
CB CB236A	CB236A - POWERPLANT (ATA 71) - INSPECTION - FORWARD UPPER ENGINE MOUNT FITTING CONTACT WITH PYLON SEAL RETAINER (ASC 124)					MANDATORY	COMPLIED WITH
		MOS		19-JAN-2020			
01-FEB-2019		HRS/MSC	-	1310.3			
		AFL		388			
CB CB237	CB237 - INDICATING/RECORDING SYSTEMS (ATA 31) - INSPECTION - DISPLAY UNIT TRAY ASSEMBLY, GROUND STRAP PLATING FLAKING					MANDATORY	COMPLIED WITH - CW
		MOS		11-MAR-2019			
31-JAN-2019		HRS/MSC	-	925.3			
		AFL		256			
CB CB239	CB239 - LANDING GEAR (ATA 32) - MODIFICATION - MAIN LANDING GEAR SIDE BRACE ACTUATOR CONFIGURATION AND CLEARANCE (ASC 117)					MANDATORY	COMPLIED WITH - CW
		MOS		05-MAR-2019			
06-FEB-2019		HRS/MSC	- (s)	925.3			
		AFL		256			
CB CB240	CB240 - ELECTRICAL POWER (ATA 24) - MODIFICATION - BATTERY CHARGER, P/N 100-1311-01, UPGRADE TO MOD 11						COMPLIED WITH - CW
		MOS		01-OCT-2019			
13-FEB-2019		HRS/MSC	- (s)	1201.5			
		AFL		351			
CB CB241	CB241 - LANDING GEAR (ATA 32) - REPLACEMENT - MAIN LANDING GEAR SHOCK STRUTS					MANDATORY	COMPLIED WITH
		MOS		05-FEB-2020			
13-FEB-2019		HRS/MSC	-	1310.3			
		AFL		388			
CB CB242	CB242 - ELECTRICAL POWER (ATA 24) - MODIFICATION - REMOVE BATTERY CHARGER MODE CONTROL RELAYS (ASC 116)					MANDATORY	COMPLIED WITH
		MOS		05-FEB-2020			
13-FEB-2019		HRS/MSC	-	1310.3			
		AFL		388			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB245	CB245 - FIRE PROTECTION (ATA 26) - INSPECTION - LEFT ENGINE FIRE BOTTLE GROUND TERMINALS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
21-MAR-2019		MOS		13-AUG-2019			
		HRS/MSC	-	0			
		AFL		0			
CB CB245A	CB245A - FIRE PROTECTION (ATA 26) - INSPECTION - LEFT ENGINE FIRE BOTTLE GROUND TERMINALS					COMPLIED WITH - CW	
13-AUG-2019		MOS		29-SEP-2019			
		HRS/MSC	- (s)	1201.5			
		AFL		351			
CB CB246	CB246 - ENGINE (ATA 72) - INSPECTION - HIGH PRESSURE COMPRESSOR VARIABLE STATOR VANES MECHANISM (ROLLS-ROYCE NMSB SBBR700-72-900178)					COMPLIED WITH - CW	
26-MAR-2019		MOS		13-JUL-2019			
		HRS/MSC		1090.8			
		AFL		314			
CB CB247	CB247 - WINGS (ATA 57) - INSPECTION - WING INTERNAL - IGNITION SOURCE PROTECTION SEALANT (TRIUMPH G650 WING SERVICE BULLETIN MAA7-71258-07_TGI)					MANDATORY	COMPLIED WITH
28-MAR-2019		MOS		05-FEB-2020			
		HRS/MSC	-	1310.3			
		AFL		388			
CB CB248	CB248 - ELECTRICAL POWER (ATA 24) - INSPECTION - WIRE ROUTING FLIGHT DECK AND VESTIBULE					MANDATORY	COMPLIED WITH
28-MAR-2019		MOS		20-JAN-2020			
		HRS/MSC	-	1310.3			
		AFL		388			
CB CB249	CB249 - AUXILIARY POWER UNIT (ATA 49) - UPDATE - APU ELECTRONIC CONTROL UNIT SOFTWARE (ASC 123)					CANCELLED	COMPLIED WITH - CW
01-APR-2019		MOS		03-OCT-2019			
		HRS/MSC	- (s)	1201.5			
		AFL		351			
CB CB249A	CB249A - AUXILIARY POWER UNIT (ATA 49) - UPDATE - APU ELECTRONIC CONTROL UNIT SOFTWARE (ASC 123)					MANDATORY	COMPLIED WITH - PCW INITIAL REV - NFA REQ'D
27-APR-2020		MOS		01-MAY-2020			
		HRS/MSC	-	1395.3			
		AFL		426			
CB CB250	CB250 - ELECTRICAL POWER (ATA 24) - INSPECTION - WIRE ROUTING CABIN AND BAGGAGE COMPARTMENT					MANDATORY	COMPLIED WITH
16-APR-2019		MOS		12-DEC-2022			
		HRS/MSC	-	2051.9			
		AFL		725			
CB CB251	CB251 - FLIGHT CONTROLS (ATA 27) - MODIFICATION - FLAP ELECTRONIC CONTROL UNIT (FECU) SOFTWARE (ASC 110)					MANDATORY	COMPLIED WITH
09-MAY-2019		MOS		02-FEB-2022			
		HRS/MSC	-	1745.4			
		AFL		610			
CB CB252	CB252 - COMMUNICATIONS (ATA 23) - MODIFICATION - JETWAVE SYSTEM BLV7.1 SOFTWARE RELEASE (HONEYWELL SB JETWAVE-23-0007)					NOT APPLICABLE - NA. NOT INSTALLED	
30-MAY-2019		MOS		02-SEP-2019			
		HRS/MSC	- (s)	1160.4			
		AFL		338			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB253	CB253 - ENGINE FUEL AND CONTROL (ATA 73) - MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K9.0.1 SOFTWARE UPGRADE (ASC 133)						COMPLIED WITH - CW
05-AUG-2019		MOS HRS/MSC - (s) AFL		27-AUG-2019 1160.4 338			
CB CB254	CB254 - ELECTRICAL POWER (ATA 24) - INSPECTION - WIRE ROUTING VESTIBULE OUTBOARD OF LEFT ELECTRONIC EQUIPMENT RACK (LEER)				05-FEB-2022 1745.4 610	MANDATORY	COMPLIED WITH
14-AUG-2019		MOS HRS/MSC - AFL					
CB CB255	CB255 - FUEL (ATA 28) - INSPECTION - OVERWING GRAVITY FUELING ADAPTER INSTALLATION					MANDATORY	COMPLIED WITH
17-SEP-2019		MOS HRS/MSC - AFL		22-JAN-2020 1310.3 388			
CB CB257	CB257 - IGNITION (ATA 74) - REPLACEMENT OF ENGINE IGNITER PLUGS WITH P/N CH34760-2 (ROLLS-ROYCE SB-BR700-74-102003)						COMPLIED WITH - CW. P/C/W 27 AUGUST 2019. ENGINE IGNITER PLUGS REPLACED WITH P/N CH34760-2
18-OCT-2019		MOS HRS/MSC - (s) AFL		21-OCT-2019 1201.9 352			
CB CB259	CB259 - HYDRAULIC POWER (ATA 29) - HYDRAULIC FILTER MONITORING SYSTEM - INSTALLATION AND ACTIVATION (ASC 090)					MANDATORY	COMPLIED WITH
25-OCT-2019		MOS HRS/MSC - AFL		29-JAN-2022 1745.4 610			
CB CB261	CB261 - DOORS (ATA 52) - INSPECTION - MAIN ENTRANCE DOOR WIRING HARNESS INSTALLATION					MANDATORY	COMPLIED WITH
07-NOV-2019		MOS HRS/MSC - AFL		12-JAN-2021 1594.1 547			
CB CB261A	CB261A - CB261A - DOORS (ATA 52), INSPECTION - MAIN ENTRANCE DOOR WIRING HARNESS INSTALLATION					MANDATORY	NOT APPLICABLE - ORIGINAL CB CARRIED OUT 27 JANUARY 2021. NO FURTHER WORK REQUIRED
15-JUL-2021		MOS HRS/MSC - AFL					
CB CB262	CB262 - WINGS (ATA 57) - MODIFICATION - FLAP TRACK D RUB STRIPS REMOVAL (ASC 083)					MANDATORY	COMPLIED WITH
12-DEC-2019		MOS HRS/MSC - AFL		15-JAN-2021 1594.1 547			
CB CB263	CB263 - INFORMATION SYSTEMS (ATA 46) - MODIFICATION - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM - SOFTWARE UPDATE 2 (ASC 076B)					MANDATORY	COMPLIED WITH
29-JAN-2020		MOS HRS/MSC - AFL		05-FEB-2020 1310.3 388			
CB CB264	CB264 - WINGS (ATA 57) - INSPECTION - WINGLET ATTACH JOINTS					CANCELLED	NOT APPLICABLE - SUPERSEDED:
20-FEB-2020		MOS HRS/MSC - AFL		31-MAY-2023			

Task No.	Description		Unit	Interval	Compliance	Next Due	Disposition	MOC
CB	CB264A - WINGS (ATA 57), INSPECTION - WINGLET ATTACH JOINTS						MANDATORY	COMPLIED WITH
			MOS		11-JAN-2021			
03-APR-2020			HRS/MSC	-	1594.1			
			AFL		547			
CB	CB265 - FLIGHT CONTROLS (ATA 27) , MODIFICATION OF RUDDER TRAILING EDGE (ASC 134)						MANDATORY	COMPLIED WITH - ASC 134 PT 1 CARRIED OUT 08 DECEMBER 2019
			MOS		30-JUN-2020			
03-DEC-2019			HRS/MSC	-	1403.3			
			AFL		435			
CB	CB266 - NAVIGATION (ATA 34) - INSPECTION - AHRU CONNECTORS						MANDATORY	COMPLIED WITH
			MOS		21-DEC-2023			
27-MAR-2020			HRS/MSC	-	2315.6			
			AFL		802			
CB	CB267 - ELECTRICAL WIRING INSTALLATIONS (ATA 97) - INSPECTION - BELOW-FLOORS WIRING INSTALLATION AT FUSELAGE STATION (FS) 370						MANDATORY	COMPLIED WITH
			MOS		21-DEC-2023			
01-APR-2020			HRS/MSC	-	2315.6			
			AFL		802			
CB	CB268 - NACELLES AND PYLONS (ATA 54) - INSPECTION - PYLON WIRING INSTALLATION FOR CONTACT WITH PYLON RIB OPENINGS						MANDATORY	COMPLIED WITH
			MOS		14-JAN-2021			
01-MAY-2020			HRS/MSC	-	1594.1			
			AFL		547			
CB	CB269 - FUSELAGE STRUCTURE (ATA 53) - INSPECTION - HORIZONTAL DRAG BRACE SPLICE FASTENERS AT FUSELAGE STATION (FS) 245.5						MANDATORY	COMPLIED WITH
			MOS		18-JAN-2022			
11-JUN-2020			HRS/MSC	-	1745.4			
			AFL		610			
CB	CB271 - LIGHTING (ATA 33) - REPLACEMENT - COCKPIT LIGHTING CONTROL PANELS - CONNECTOR PLATE RETAINING SCREWS						MANDATORY	COMPLIED WITH
			MOS		15-JAN-2021			
24-JUN-2020			HRS/MSC	-	1594.1			
			AFL		547			
CB	CB272 - ENGINE AIR (ATA 75) - REPLACEMENT - STAGE 5 HANDLING BLEED VALVES (ROLLS-ROYCE SB-BR700-75-900673)						CANCELLED	NOT APPLICABLE - N/A DUE BLEED VALVES ACCUMULATED > 900 HOURS
			MOS		03-JUL-2020			
01-JUL-2020			HRS/MSC	- (s)	1403.2			
			AFL		435			
CB	CB272A - ENGINE AIR (ATA 75) - REPLACEMENT - STAGE 5 HANDLING BLEED VALVES (ROLLS-ROYCE SB-BR700-75-900673)						MANDATORY	NOT APPLICABLE - ALL ENGINE HBVS HAVE ACCUMULATED 1505 HOURS
			MOS		16-OCT-2020			
14-OCT-2020			HRS/MSC	-	1508.3			
			AFL		492			
CB	CB275 - ELECTRICAL WIRING INSTALLATIONS (ATA 97) - INSPECTION - WIRING INSTALLATION BELOW BAGGAGE FLOOR						MANDATORY	COMPLIED WITH
			MOS		12-JAN-2021			
15-OCT-2020			HRS/MSC	-	1594.1			
			AFL		547			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB276	CB276 - FLIGHT CONTROLS (ATA 27) - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE V10.1 (ASC 135)					MANDATORY	COMPLIED WITH
12-NOV-2020		MOS		27-JAN-2021			
		HRS/MSC	-	1594.1			
		AFL		547			
CB CB277	CB277 - FIRE PROTECTION (ATA 26) - MODIFICATION - ENGINE FIRE EXTINGUISHING BOTTLE CARTRIDGE WIRING (ASC 122)					MANDATORY	COMPLIED WITH
19-NOV-2020		MOS		30-JAN-2022			
		HRS/MSC	-	1745.4			
		AFL		610			
CB CB277A	CB277A - CB277A - FIRE PROTECTION (ATA 26) - MODIFICATION - ENGINE FIRE EXTINGUISHING BOTTLE CARTRIDGE WIRING (ASC 122)					MANDATORY	NOT APPLICABLE - NFA REQ'D DUE PCW INITIAL REVISION
09-DEC-2022		MOS		23-FEB-2023			
		HRS/MSC	-	2127.1			
		AFL		746			
CB CB278	CB278 - WINGS (ATA 57) - INSPECTION - UNPRIMED WING SKIN FASTENERS INBOARD OF REAR BEAM STATION (RBS) 62					CANCELLED	- CANCELLED
20-NOV-2020		MOS					
		HRS/MSC	-				
		AFL					
CB CB278A	CB278A - WINGS (ATA 57) - INSPECTION - UNPRIMED WING SKIN FASTENERS INBOARD OF REAR BEAM STATION (RBS) 62					MANDATORY	COMPLIED WITH
10-AUG-2021		MOS		21-DEC-2023			
		HRS/MSC	-	2315.6			
		AFL		802			
CB CB279	CB279 - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR SPONSON BEAM UPPER INBOARD SHIM					SUPERSEDED	NOT APPLICABLE - SUPERSEDED
11-DEC-2020		MOS					
		HRS/MSC	-				
		AFL					
CB CB279A	CB279A - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR SPONSON BEAM UPPER INBOARD SHIM					MANDATORY	COMPLIED WITH
10-MAR-2021		MOS		08-FEB-2022			
		HRS/MSC	-	1745.4			
		AFL		610			
CB CB280	CB280 - STABILIZERS (ATA 55) - INSPECTION - RIGHT SIDE HORIZONTAL STABILIZER - CLAMP INSTALLATION (FOKKER SB GF-20-0011)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
18-MAR-2021		MOS					
		HRS/MSC	-				
		AFL					
CB CB281	CB281 - CB281 - FIRE PROTECTION (ATA 26) - INSPECTION - LEFT FIRE BOTTLE/APU CARTRIDGE WIRE HARNESS SHIELD GROUND					MANDATORY	NOT APPLICABLE - ASC 122A NOT INCORPORATED
22-APR-2021		MOS					
		HRS/MSC	-				
		AFL					
CB CB282	CB282 - CB282 - WINGS (ATA 57) - REPLACEMENT - FLAP TRACK B CLOSE-OUT SKIN					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
24-MAY-2021		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB282A	CB282A - CB282A - WINGS (ATA 57) - REPLACEMENT - FLAP TRACK B CLOSE-OUT SKIN					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
28-SEP-2021		MOS					
		HRS/MSC	-				
		AFL					
CB CB282B	CB282B - CB282B - WINGS (ATA 57) - REPLACEMENT - FLAP TRACK B CLOSE-OUT SKIN					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
21-JAN-2022		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
CB CB282C	CB282C - CB282C - WINGS (ATA 57) - REPLACEMENT - FLAP TRACK B CLOSE-OUT SKIN					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/N
31-JAN-2023		MOS		10-FEB-2023			
		HRS/MSC	-	2092.8			
		AFL		741			
CB CB283	CB283 - CB283 - ENGINE FUEL & CONTROL (ATA 73) - MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K10.1 SOFTWARE UPGRADE (ASC 138)					SUPERSEDED	COMPLIED WITH
18-JUN-2021		MOS		30-JAN-2022			
		HRS/MSC	-	1745.4			
		AFL		610			
CB CB283A	CB283A - CB283A - ENGINE FUEL AND CONTROL (ATA 73) - MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K10.1 SOFTWARE UPGRADE (ASC 138)					MANDATORY	COMPLIED WITH
21-JAN-2022		MOS		08-FEB-2022			
		HRS/MSC	-	1745			
		AFL		610			
CB CB285	CB285 - COMMUNICATIONS (ATA 23) - MODIFICATION - JETWAVE SYSTEM BLV8.1 SOFTWARE RELEASE (HONEYWELL SB JETWAVE-23-0009)						NOT APPLICABLE - JETWAVE SYSTEM NOT INSTALLED
11-AUG-2021		MOS					
		HRS/MSC	-				
		AFL					
CB CB286	CB286 - CB286 - FUSELAGE STRUCTURE (ATA 53) INSPECTION - WIRING MOUNTING AND BRACKET INSTALLATION AT FS 942.5					MANDATORY	COMPLIED WITH
09-SEP-2021		MOS		14-DEC-2022			
		HRS/MSC	-	2051.9			
		AFL		725			
CB CB287	CB287 - CB287 - STABILIZERS (ATA 55) - INSPECTION - HORIZONTAL STABILIZER WIRING INSTALLATION (FOKKER SB GF-19-0015)					MANDATORY	COMPLIED WITH
28-OCT-2021		MOS		16-DEC-2022			
		HRS/MSC	-	2051.9			
		AFL		725			
CB CB288	CB288 - CB288 - FLIGHT CONTROLS (ATA 27) - INSPECTION - FLY-BY-WIRE HARNESS - CLAMP INSTALLATION AT FUSELAGE STATIONS 733.2 AND 1019.19					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
09-NOV-2021		MOS					
		HRS/MSC	-				
		AFL					
CB CB289	CB289 - POWERPLANT (ATA 71) - INSPECTION - ENGINE COWL HINGE LINES (ROLLS-ROYCE SB-BR700-71-900701)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
11-NOV-2021		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB289A	CB289A - POWERPLANT (ATA 71), INSPECTION - ENGINE COWL HINGE LINES (ROLLS-ROYCE SB-BR700-71-900701)			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
06-DEC-2021							
CB CB289B	CB289B - POWERPLANT (ATA 71), INSPECTION - ENGINE COWL HINGE LINES (ROLLS-ROYCE SB-BR700-71-900701)			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
10-MAR-2022							
CB CB289C	CB289C - POWERPLANT (ATA 71), INSPECTION - ENGINE COWL HINGE LINES (ROLLS-ROYCE SB-BR700-71-900701)			MOS HRS/MSC - AFL	10-FEB-2023 2092.8 741	MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/N
17-JAN-2023							
CB CB289D	POWERPLANT (ATA 71) - INSPECTION - ENGINE COWL HINGE LINES (ROLLS-ROYCE SB-BR700-71-900701), CUSTOMER BULLETIN (MANDATORY)			MOS HRS/MSC - AFL	22-DEC-2023	MANDATORY	NOT APPLICABLE - BY SERIAL:
21-NOV-2023							
CB CB290	CB290 - CB290 - FLIGHT CONTROLS (ATA 27) - INSPECTION - FLAP TRACK B OUTBOARD ROLLER FITTING HARDWARE			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
28-JAN-2022							
CB CB291	CB291 - CB291 - ELECTRICAL WIRING INSTALLATIONS (ATA 97), INSPECTION - VERTICAL FIN CONNECTORS			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
30-MAR-2022							
CB CB292	CB292 - CB292 - FUSELAGE STRUCTURE (ATA 53) - INSPECTION - AUXILIARY POWER UNIT ENCLOSURE			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/NO
04-APR-2022							
CB CB294	CB294 - CB294 - INSPECTION - ENGINE FIRE BOTTLE THERMAL RELIEF DISCHARGE PORT			MOS HRS/MSC - AFL	01-DEC-2022 2051.9 725	MANDATORY	COMPLIED WITH
25-AUG-2022							
CB CB295	CB295 - CB295 - DOORS (ATA 52) - INSPECTION - MAIN ENTRANCE DOOR ELECTRICAL HARNESS INSTALLATION			MOS HRS/MSC - AFL	17-DEC-2022 2051.9 725	MANDATORY	NOT APPLICABLE - N/A BY SERIAL NUMBER
22-SEP-2022							
CB CB296	CB296 - FUSELAGE (ATA 53) - INSPECTION - ELECTRICAL CONNECTOR IDENTIFICATION DECAL - FS 224			MOS HRS/MSC - AFL	21-DEC-2023 2315.6 802	MANDATORY	COMPLIED WITH
13-FEB-2023							
CB CB297	CB297 - CB297 - FLIGHT CONTROLS (ATA 27) - INSPECTION - HORIZONTAL STABILIZER PART NUMBER			MOS HRS/MSC - AFL	19-JAN-2024 2340.1 811	MANDATORY	NOT APPLICABLE - N/A BY SERIAL NUMBER
09-MAY-2023							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB298	CB298 - ELECTRICAL POWER (ATA 24) - INSPECTION - AIRCRAFT MAIN BATTERIES (SAFT SB0323), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - N/A BY SERIAL NUMBER
18-MAY-2023		MOS HRS/MSC - AFL		19-JAN-2024 2340.1 811			
CB CB298A	CB298A - ELECTRICAL POWER (ATA 24) - INSPECTION - AIRCRAFT MAIN BATTERIES (SAFT SB0323), CUSTOMER BULLETIN (MANDATORY)				16-NOV-2023	MANDATORY	NOT APPLICABLE - BY SERIAL:
10-NOV-2023		MOS HRS/MSC - AFL					
CB CB298B	ELECTRICAL POWER (ATA 24) - INSPECTION - AIRCRAFT MAIN BATTERIES (SAFT SB0323), CUSTOMER BULLETIN (MANDATORY)				22-DEC-2023	MANDATORY	NOT APPLICABLE - BY SERIAL:
21-NOV-2023		MOS HRS/MSC - AFL					
CB CB299	CB299 - INFORMATION SYSTEMS (ATA 46) - MODIFICATION - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM (AHTMS) - SOFTWARE UPDATE (ASC 140), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	COMPLIED WITH
05-JUL-2023		MOS HRS/MSC - AFL		09-DEC-2024 2483.7 900			
CB CB300	CB300 - LANDING GEAR (ATA 32) - INSPECTION - NOSE LANDING GEAR CONTROL MANIFOLD CONNECTOR, CUSTOMER BULLETIN (MANDATORY)				15-AUG-2023	MANDATORY	NOT APPLICABLE - BY SERIAL:
04-AUG-2023		MOS HRS/MSC - AFL					
CB CB300A	CB300A - LANDING GEAR (ATA 32) - INSPECTION - NOSE LANDING GEAR CONTROL MANIFOLD CONNECTOR, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - BY SERIAL:
05-SEP-2023		MOS HRS/MSC - AFL		18-SEP-2023			
CB CB301	CB301 - ELECTRICAL POWER (ATA 24) - INSPECTION - COCKPIT ELECTRICAL WIRE HARNESS TERMINATIONS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - BY SERIAL:
07-SEP-2023		MOS HRS/MSC - AFL		18-SEP-2023			
CB CB302	CB302 - FLIGHT CONTROLS (ATA 27) - INSPECTION - FLAP ACTUATOR ATTACH FITTING HARDWARE, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - BY SERIAL:
07-SEP-2023		MOS HRS/MSC - AFL		18-SEP-2023			
CB CB303	CB303 - NAVIGATION (ATA 34) - MODIFICATION - WEATHER RADAR SYSTEM PROCESSOR V4 SOFTWARE RELEASE (HONEYWELL SB 930-1003-34-0008), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	COMPLIED WITH - FOUND SATISFACTORY
12-SEP-2023		MOS HRS/MSC - AFL		21-DEC-2023 2315.6 802			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB303A	CB303A - NAVIGATION (ATA 34) - MODIFICATION - WEATHER RADAR SYSTEM PROCESSOR V4 SOFTWARE RELEASE (HONEYWELL SB 930-1003-34-0008), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	COMPLIED WITH - PREVIOUSLY COMPLIED WITH UNDER CB303 UNDER JET AVIATION GENEVA WORK ORDER #10000414.
25-JAN-2024		MOS HRS/MSC AFL		19-FEB-2024 2346.3 815			
CB CB304	CB304 - EQUIPMENT AND FURNISHINGS (ATA 25) - INSTALLATION - EBHA PDB TERMINAL BRACKET COVER (ASC 146), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	COMPLIED WITH
29-SEP-2023		MOS HRS/MSC AFL		05-DEC-2024 2483.7 900			
CB CB305	CB305 - COMMUNICATIONS (ATA 23) - REPLACEMENT - SATELLITE DATA UNITS (SDU) DL150-00, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - BY SERIAL:
17-NOV-2023		MOS HRS/MSC AFL		22-DEC-2023			
CB CB306	CB306 - NAVIGATION (ATA 34) INSPECTION - AHRU CONNECTORS WITH PITCH AND ROLL INFORMATION RECORDED AND THE INSTALLATION OF AHRU LABELS ASC 144, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	COMPLIED WITH
15-FEB-2024		MOS HRS/MSC AFL		29-NOV-2024 2483.7 900			
CB CB307	CB307 - WATER/WASTE (ATA 38) - INSPECTION - FORWARD (FWD) WATER TANK ATTACHMENT CLIP AND SENSOR CONNECTOR ORIENTATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - BY SERIAL:
19-JUN-2024		MOS HRS/MSC AFL		08-JUL-2024			
CB CB321	CB321 - POWERPLANT (ATA 71) INSPECTION - ENGINE INLET COWL, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	NOT APPLICABLE - BY SERIAL:
19-MAR-2025		MOS HRS/MSC AFL		24-MAR-2025			
CB CB323	CB323 - FUSELAGE (ATA 53) - MODIFICATION - AFT FUSELAGE WATER DRAINAGE (ASC 159), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
19-MAY-2025		MOS HRS/MSC AFL	24	(EFF)	19-MAY-2027		
CB CB324	CB324 - FLIGHT CONTROLS (ATA 27) REPLACEMENT - FLIGHT CONTROL COMPUTER (FCC) CHANNEL A COM-MON MODULES, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
30-MAY-2025		MOS HRS/MSC AFL	12	(EFF)	30-MAY-2026		
CSB CSB008	SB CSB-6008 - CSB008 -CABIN SYSTEMS (ATA 44) ADVANCED CABIN SERVER (ACS) SYSTEM SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - PRODUCTION EQUIVALENT. EFFECTIVITY: THIS CABIN SERVICE BULLETIN IS APPLICABLE TO AIRCRAFT WITH AC FIRMWARE VERSION 4.4.3.9 INSTALLED. SERIAL NUMBER EFFECTIVITY INCLUDES 6003 THRU 6129. FINAL PHASE CUT-IN 6130 AND SUB.
04-JUN-2015		MOS HRS/MSC AFL		04-JUN-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CSB CSB009	CE-CSB-6009 - CSB009 - GULFSTREAM CABIN MANAGEMENT SYSTEMS (ATA 44) GCMS FIRMWARE UPGRADE					CANCELLED	COMPLIED WITH - PRODUCTION EQUIVALENT. EFFECTIVITY: THIS CABIN SERVICE BULLETIN IS APPLICABLE TO AIRCRAFT WITH GCMS CONTROLLER FIRMWARE VERSION 1.9.0 INSTALLED OR LATER APPROVED VERSION. SERIAL NUMBER EFFECTIVITY INCLUDES 6001 THRU 6135. FINAL PHASE CUT-IN STARTS WITH SERIAL NUMBER 6136
04-JUN-2015	MOS HRS/MSC - AFL			04-JUN-2015 0 0			
CSB CSB010	CE-CSB-6010 - CSB 010 - CABIN SYSTEMS (ATA 44) - ADVANCED CABIN SERVER (ACS) SYSTEM SOFTWARE UPGRADE				15-DEC-2016	OPTIONAL	COMPLIED WITH - CW
17-MAY-2016	MOS HRS/MSC - AFL			283.9 76			
CSB CSB011	CE-CSB-6011 - CSB011 - CABIN SYSTEMS (ATA 44) GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS) FIRMWARE UPDATE				15-DEC-2016	OPTIONAL	COMPLIED WITH - CW
17-MAY-2016	MOS HRS/MSC - AFL			283.9 76			
CSB CSB012	CE-CSB-6012 - CSB012 - CABIN SYSTEMS (ATA 44) - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS) FIRMWARE UPDATE				10-APR-2018	OPTIONAL	COMPLIED WITH - CW
11-AUG-2017	MOS HRS/MSC - AFL			701 181			
CSB CSB013	CE-CSB-6013 - CSB013 - CABIN SYSTEMS (ATA 44) - ADVANCED CABIN SERVER (ACS) (GEN 4) - CABINVIEWTM SOFTWARE UPGRADE				11-MAR-2019	OPTIONAL	COMPLIED WITH - CW
10-MAY-2018	MOS HRS/MSC - AFL			925.3 256			
CSB CSB014	CE-CSB-6014 - CSB014 - CABIN SYSTEMS (ATA 44) - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 1) FIRMWARE UPDATE				11-MAR-2019	OPTIONAL	COMPLIED WITH - CW
06-AUG-2018	MOS HRS/MSC - AFL			925.3 256			
CSB CSB015	CE-CSB-6015 - CSB015 - CABIN SYSTEMS (ATA 44) - ADVANCED CABIN SERVER (ACS) (GEN 4) CABINVIEW SOFTWARE UPGRADE				22-JUN-2019	OPTIONAL	COMPLIED WITH - CW
31-DEC-2018	MOS HRS/MSC - AFL			1058.2 307			
CSB CSB017	CE-CSB-6017 - CSB017 - CABIN SYSTEMS (ATA 44) - GULFSTREAM CABIN MANAGEMENT SYSTEM - (GCMS 1) FIRMWARE UPDATE				08-JUL-2019	OPTIONAL	COMPLIED WITH - CW
08-APR-2019	MOS HRS/MSC - AFL			1090.2 313			
CSB CSB019	CE-CSB-6019 - CSB019 - CABIN SYSTEMS (ATA 44) - GEN 1 TO GEN 2 CONTROLLER UPGRADE					OPTIONAL	
03-MAY-2019	MOS HRS/MSC - AFL			0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CSB CSB021	CE-CSB-6021 - CSB021 - CABIN SYSTEMS (ATA 44) - ADVANCED CABIN SERVER (ACS) (GEN 4) CABINVIEW SOFTWARE UPGRADE V2.2.3						COMPLIED WITH
19-NOV-2019		MOS		27-OCT-2020			
		HRS/MSC	-	1514.9			
		AFL		496			
CSB CSB022	CE-CSB-6022 - CSB022 - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 1) FIRMWARE UPDATE V1.10.6					OPTIONAL	COMPLIED WITH
10-SEP-2019		MOS		01-MAY-2020			
		HRS/MSC	-	1395.3			
		AFL		426			
CSB CSB024	CE-CSB-6024 - CSB024 - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 1) FIRMWARE UPDATE V1.10.7					OPTIONAL	COMPLIED WITH
14-AUG-2020		MOS		17-SEP-2020			
		HRS/MSC	- (s)	1453.85			
		AFL		469			
CSB CSB027	CE-CSB-6027 - CSB027 - GULFSTREAM CABIN MANAGEMENT SYSTEM - (GCMS 1) FIRMWARE UPDATE V1.10.9, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	COMPLIED WITH
13-OCT-2021		MOS		01-DEC-2022			
		HRS/MSC	-	2051.9			
		AFL		725			
CSB CSB029A	CE-CSB-6029A - CSB029A - CABIN SYSTEMS - ADVANCED CABIN SERVER (ACS) (GEN 4) CABIN VIEW SOFTWARE UPDATE V2.2.5, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	COMPLIED WITH
24-JAN-2022		MOS		30-NOV-2022			
		HRS/MSC	-	2051.9			
		AFL		725			
CSB CSB031	CE-CSB-6031 - CSB031 - CABIN SYSTEMS - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE V2.4.9, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	NOT APPLICABLE - DUE GCMS 1 SYSTEM INSTALLED
22-MAR-2023		MOS		26-MAR-2023			
		HRS/MSC	-	2168.8			
		AFL		759			
SB 52-10-02-011	SB 52-10-02-011 - ENFLITE SB 52-10-02-011 - 42600 SERIES ELECTRIC POCKET DOORS DRIVE GEAR ASSEMBLY REPLACEMENT					OPTIONAL	
02-FEB-2015		MOS					
		HRS/MSC	-	0			
		AFL		0			
SB ASC903A	ASC903A - INDICATING / RECORDING (ATA 31) - PLANEVIEW™ II MASTER OPERATING SYSTEM SOFTWARE UPDATE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	COMPLIED WITH
03-APR-2024		MOS		09-DEC-2024			
		HRS/MSC	-	2483.7			
		AFL		900			
SB MP-15-6510.1	SB MP-15-6510.1 - SB 52-10-02-014 - POCKET DOOR GENERAL UPGRADE					OPTIONAL	COMPLIED WITH - CW
		MOS		06-MAR-2019			
		HRS/MSC	-	925.3			
		AFL		256			
SB MP-15-6510.4	SB MP-15-6510.4 - POCKET DOOR DESCENDER (MP-15-6510)					OPTIONAL	COMPLIED WITH - CW
		MOS		11-MAR-2019			
		HRS/MSC	-	925.3			
		AFL		256			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB MP-16-6502.1	SB MP-16-6502.1 - SUB-WOOFER WIRE HARNESS ( NO: VMP-16-6502)					OPTIONAL	COMPLIED WITH - CW
	MOS			08-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6505	SB MP-16-6505 - EXIT SIGNS (MP-16-6505)					OPTIONAL	COMPLIED WITH - CW
	MOS			12-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6506	SB MP-16-6506 - GALLEY PULLOUT WORK SURFACE (MP-16-6506)					OPTIONAL	COMPLIED WITH - CW
	MOS			12-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6507	SB MP-16-6507 - TIA BREW BASKET (MP 16-6507)					OPTIONAL	COMPLIED WITH - CW
	MOS			13-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6518	SB MP-16-6518 - CABIN ACOUSTICS ENHANCEMENT (MP-16-6518)					OPTIONAL	COMPLIED WITH - CW
	MOS			12-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6519	SB MP-16-6519 - CONVECTION OVEN FIRMWARE UPDATE R09 (MP-16-6519)					OPTIONAL	COMPLIED WITH - CW
	MOS			14-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6524	SB MP-16-6524 - MANUAL DOOR SWITCH - (MP-16-6524)					OPTIONAL	COMPLIED WITH - CW
	MOS			11-MAR-2019			
	HRS/MSC	-		925.3			
	AFL			256			
SB MP-16-6525	SB MP-16-6525 - AFT LAV DOOR ENHANCEMENT MODIFICATION (AFT LAV CLOSET/TOILET LIGHT BLEED) (MP-16-6525)					OPTIONAL	NOT APPLICABLE - NA. N/A BY A/C S/N
	MOS			29-JUN-2018			
	HRS/MSC	-		725.8			
	AFL			191			
SB MP-16-6526	SB MP-16-6526 - AFT LAV DOOR ENHANCEMENT MODIFICATION (MP 16-6526)					OPTIONAL	
	MOS						
	HRS/MSC	-		0			
	AFL			0			
SB MP-16-6530	SB MP-16-6530 - RFU FORWARD GALLEY - MP-16-6530					OPTIONAL	
	MOS						
	HRS/MSC	-		0			
	AFL			0			
SB MP-17-6501	SB MP-17-6501 - AFT LAVATORY DOOR MAGNETIC BUMPER ASSEMBLY - HANGING MIRROR CONFIGURATION - MP-17-6501					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
	MOS			01-MAR-2017			
	HRS/MSC	-		0			
	AFL			0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB MP-17-6510	SB MP-17-6510 - FLIGHT CONTROL COMPUTERS (FCC) V7.1 SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
	MOS			23-APR-2018			
	HRS/MSC	-		701			
	AFL			181			
SB MP-17-6512	SB MP-17-6512 - EMED STOP BOLTS					OPTIONAL	
	MOS						
	HRS/MSC	-		0			
	AFL			0			
STC ST04027AT-D	STC ST04027AT-D - SATCOM DIRECT ROUTER (SDR) INSTALLATION					OPTIONAL	COMPLIED WITH - CW
	MOS			18-JAN-2016			
	HRS/MSC	-		12.3			
	AFL			5			
STC ST04252AT-D	STC ST04252AT-D - AIRCRAFT INTERIOR					OPTIONAL	COMPLIED WITH - CW
	MOS			18-JAN-2016			
	HRS/MSC	-		12.3			
	AFL			5			
STC ST04254AT-D	STC ST04254AT-D - BROAD BAND MULTI-LINK (BBML) HIGHSPEED DATA SYSTEM VIASAT MOBILE TERMINAL VMT-1500-03					INFORMATIONAL	COMPLIED WITH - CW
	MOS			18-JAN-2016			
	HRS/MSC	-		12.3			
	AFL			5			
STC ST04277AT-D	STC ST04277AT-D - LIGHTNING SENSOR					OPTIONAL	COMPLIED WITH - CW
	MOS			18-JAN-2016			
	HRS/MSC	-		12.3			
	AFL			5			
VSB 3202908-36-1912	SB 3202908-36-1912 - HONEYWELL SB 3202908-36-1912 - REWORK FOUR INCH DIAMETER CHECK VALVE, PN 3202908-1 TO PN 3202908-2, USED ON THE GULFSTREAM G650.				RECOMMENDED	COMPLIED WITH - CW. MRI PARENT CODE: 361104	
	MOS			24-AUG-2015			
	HRS/MSC	-		0			
	AFL			0			
VSB 3202908-36-1912	SB 3202908-36-1912 - HONEYWELL SB 3202908-36-1912 - REWORK FOUR INCH DIAMETER CHECK VALVE, PN 3202908-1 TO PN 3202908-2, USED ON THE GULFSTREAM G650.				RECOMMENDED	COMPLIED WITH - CW. MRI PARENT CODE: 361105	
	MOS			24-AUG-2015			
	HRS/MSC	-		0			
	AFL			0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APU - SB - P-269/WE3800700-1</b>							
499003 APU - APU - APU SOAP OIL SAMPLE AND FILTER ELEMENT ANALYSIS							
		MOS				RECURRING	
		HRS/MSC	500		2223 M		
		AFL					
		APUS					
SB	49-7933 R06	APU - SB 49-7933 R06 - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		13-MAR-2017			
	26-JAN-2016	HRS/MSC	-	0			
		APUS		0			
SB	49-7933 R08	APU - SB 49-7933 R08 - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS				CANCELLED	
		MOS					
	27-JUL-2017	HRS/MSC	DUE	0			
		APUS		0			
SB	49-7997 R03	APU - SB 49-7997 R03 - STANDARD STORAGE AND PRESERVATION GUIDELINES				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		28-FEB-2017			
		HRS/MSC	-	0			
		APUS		0			
SB	49-8252	APU - SB 49-8252 - AIRBORNE - AUXILIARY POWER UNIT (APU) - APPROVED FUELS FOR HONEYWELL COMMERCIAL APUS				CANCELLED	
		MOS					
	31-AUG-2018	HRS/MSC	-	0			
		APUS		0			
SIL	APU-49 R13	APU - SIL APU-49 R13 - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER (RECOMMENDED)				RECOMMENDED	
		MOS					
	23-NOV-2023	HRS/MSC	A/R	(EFF)	13-DEC-2025 M	RECURRING	
		APUS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - AD - 26163/DEL116</b>							
EASA 2013-0110	NO. 1 ENGINE - EASA 2013-0110 - ENGINE FUEL AND CONTROL - SPILL RETURN TO FUEL PUMP TUBE - REPLACEMENT			MANDATORY		COMPLIED WITH - AT BUILD	
31-MAY-2013	MOS HRS/MSC - APUS ENC			17-NOV-2022 0 0			
EASA 2013-0229 R02	NO. 1 ENGINE - EASA 2013-0229 R02 - ENGINE FUEL AND CONTROL - FUEL METERING UNIT - REPLACEMENT			MANDATORY	04-FEB-2023	NOT APPLICABLE - BY PN OF FMU INSTALLED	
07-OCT-2013		DAYS HRS/MSC - ENC		33.8 15			
EASA 2024-0136	NO. 1 ENGINE - EASA 2024-0136 - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAM - AMENDMENT (MANDATORY)			MANDATORY			
25-JUL-2024	MOS HRS/MSC ENC	12		25-JUL-2025			
FAA 2013-12-03	NO. 1 ENGINE - FAA 2013-12-03 - ENGINE FUEL AND CONTROL - SPILL RETURN TO FUEL PUMP TUBE - REPLACEMENT			MANDATORY	04-FEB-2023	COMPLIED WITH - AT BUILD	
14-JUN-2013	MOS HRS/MSC - ENC			17-NOV-2022 0 0			
FAA 2014-12-03	NO. 1 ENGINE - FAA 2014-12-03 - ENGINE FUEL AND CONTROL - FUEL METERING UNITS (FMUS) - REPLACEMENT			MANDATORY	33.8 15	NOT APPLICABLE - N/A BY PN OF FMU INSTALLED	
17-JUL-2014		DAYS HRS/MSC - ENC		04-FEB-2023 33.8 15			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 2 - AD - 26162/DER116</b>							
EASA 2013-0110	NO. 2 ENGINE - EASA 2013-0110 - ENGINE FUEL AND CONTROL - SPILL RETURN TO FUEL PUMP TUBE - REPLACEMENT			MANDATORY		COMPLIED WITH - AT BUILD	
31-MAY-2013		MOS		17-NOV-2022			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0229 R02	NO. 2 ENGINE - EASA 2013-0229 R02 - ENGINE FUEL AND CONTROL - FUEL METERING UNIT - REPLACEMENT			MANDATORY		NOT APPLICABLE - N/A BY PN OF FMU INSTALLED	
07-OCT-2013		DAYs		04-FEB-2023			
		HRS/MSC	-	33.8			
		ENC		15			
EASA 2024-0136	NO. 2 ENGINE - EASA 2024-0136 - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAM - AMENDMENT (MANDATORY)			MANDATORY			
25-JUL-2024		MOS	12		<b>25-JUL-2025</b>		
		HRS/MSC					
		ENC					
FAA 2013-12-03	NO. 2 ENGINE - FAA 2013-12-03 - ENGINE FUEL AND CONTROL - SPILL RETURN TO FUEL PUMP TUBE - REPLACEMENT			MANDATORY		COMPLIED WITH - AT BUILD	
14-JUN-2013		MOS		15-NOV-2022			
		HRS/MSC	-	0			
		ENC		0			
FAA 2014-12-03	NO. 2 ENGINE - FAA 2014-12-03 - ENGINE FUEL AND CONTROL - FUEL METERING UNITS (FMUS) - REPLACEMENT			MANDATORY		NOT APPLICABLE - N/A BY PN OF FMU INSTALLED	
17-JUL-2014		DAYs		04-FEB-2023			
		HRS/MSC	-	33.8			
		ENC		15			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - SB - 26163/DEL116</b>							
SB	BR700-71-101776 R01	NO. 1 ENGINE - SB BR700-71-101776 R01 - POWER PLANT - DRAINS TANK EJECTOR - INTRODUCTION OF A REVISED SEAL RING PART NUMBER FOR SPARES PURPOSES, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
		MOS		05-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-71-101928 R01	NO. 1 ENGINE - SB BR700-71-101928 R01 - POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS FOR THE HYDRAULIC PUMP, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
		MOS		25-SEP-2024			
	27-MAR-2024	HRS/MSC	-				
		ENC					
SB	BR700-71-101987 R01	NO. 1 ENGINE - SB BR700-71-101987 R01 - POWER PLANT - CORE ENGINE HARNESS - INTRODUCTION OF NEW LANE A AND LANE B CORE ENGINE HARNESSES AND DELETION OF THE TURBINE CASE COOLING (TCC) VALVE THERMOCOUPLES, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
		MOS		05-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-72-101737 R01	NO. 1 ENGINE - SB BR700-72-101737 R01 - HIGH PRESSURE (HP) COMPRESSOR FRONT SPLIT CASE - INTRODUCTION OF TWO ADDITIONAL BORESCOPE ACCESS PORTS TO THE HP COMPRESSOR, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE SN
		MOS		01-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-72-101743 R02	NO. 1 ENGINE - SB BR700-72-101743 R02 - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF NEW LP COMPRESSOR BLADES WITH LASER SHOCK PEENING TREATMENT ON THE HUB LEADING EDGE OF THE BLADE AIRFOIL, SERVICE BULLETIN (RECOMMENDED)				RECOMMENDED	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
		MOS		05-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-72-102214 R02	NO. 1 ENGINE - SB BR700-72-102214 R02 - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF A NEW HP COMPRESSOR FRONT CASE ASSEMBLY MADE BY A DIFFERENT SUPPLIER, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE S/N
		MOS		06-MAR-2024			
	23-JUN-2023	HRS/MSC	-				
		ENC					
SB	BR700-73-101708 R01	NO. 1 ENGINE - SB BR700-73-101708 R01 - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED MAIN FUEL PUMP, SERVICE BULLETIN (RECOMMENDED)				RECOMMENDED	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE SN
		MOS		28-NOV-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-73-101767 R01	NO. 1 ENGINE - SB BR700-73-101767 R01 - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A NEW MAIN FUEL PUMP WITH MODIFIED GEARS AND IMPELLER HOUSING, SERVICE BULLETIN (RECOMMENDED)				RECOMMENDED	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE SN
		MOS		29-NOV-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101769 R01	NO. 1 ENGINE - SB BR700-73-101769 R01 - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - INTRODUCTION OF A REVISED SHUT-OFF VALVE SERVO VALVE (SOVSV) WITH A NEW GAS DISCHARGE TUBE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-101775 R01	NO. 1 ENGINE - SB BR700-73-101775 R01 - ENGINE FUEL AND CONTROL - LOW PRESSURE (LP) TURBINE OVERSPEED CONTROL UNIT AND MANIFOLD SPLITTER - INTRODUCTION OF A REVISED OVERSPEED AND SPLITTER UNIT (OSU), SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE SN
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-101792 R02	NO. 1 ENGINE - SB BR700-73-101792 R02 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.2.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101793 R04	NO. 1 ENGINE - SB BR700-73-101793 R04 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-101801 R01	NO. 1 ENGINE - SB BR700-73-101801 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.1.4 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-101847 R02	NO. 1 ENGINE - SB BR700-73-101847 R02 - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW SPILL RETURN TO FUEL PUMP TUBE MADE FROM A DIFFERENT MATERIAL AND A NEW ASSEMBLY PROCEDURE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		17-NOV-2022 0 0			
SB BR700-73-101886 R01	NO. 1 ENGINE - SB BR700-73-101886 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.2.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101892 R02	NO. 1 ENGINE - SB BR700-73-101892 R02 - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A LOW PRESSURE (LP) FUEL SWITCH SENSE LINE TUBE WITH INCREASED VOLUME, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101902 R02	NO. 1 ENGINE - SB BR700-73-101902 R02 - ENGINE FUEL AND CONTROL - T30 THERMOCOUPLES - INTRODUCTION OF A REVISED T30 THERMOCOUPLE INSTALLATION ON THE LEFT SIDE OF THE CORE ENGINE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - N/A BY ENGINE SN
10-NOV-2023		MOS HRS/MSC ENC		04-DEC-2023			
SB BR700-73-101923 R01	NO. 1 ENGINE - BR700-73-101923 R01 - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW FUEL TUBE WITH AN INCREASED WALL THICKNESS, WHICH IS INSTALLED BETWEEN THE FUEL COOLED OIL COOLER (FCOC) AND THE MAIN FUEL PUMP, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101929 R01	NO. 1 ENGINE - BR700-73-101929 R01 - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-101957 R02	NO. 1 ENGINE - SB BR700-73-101957 R02 - ENGINE FUEL AND CONTROL - FUEL SYSTEM - INTRODUCTION OF A REVISED FUEL SYSTEM, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101965 R02	NO. 1 ENGINE - BR700-73-101965 R02 - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE SWITCH - INTRODUCTION OF A REVISED FUEL LOW PRESSURE (LP) SWITCH WITH A DECREASED PRESSURE TRIGGER POINT, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-101967 R02	NO. 1 ENGINE - BR700-73-101967 R02 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K7.1.3 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-102000 R01	NO. 1 ENGINE - BR700-73-102000 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K8.0.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-102134 R03	NO. 1 ENGINE - BR700-73-102134 R03 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K9.0.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-102183 R01	NO. 1 ENGINE - BR700-73-102183 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K10.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	NOT APPLICABLE - NFA REQ'D DUE PCW AT INITIAL REVISION
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-74-101762 R02	NO. 1 ENGINE - BR700-74-101762 R02 - IGNITION - IGNITER PLUG - INTRODUCTION OF IGNITER PLUGS WITH SILVER COATED THREADS, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-74-102002 R01	NO. 1 ENGINE - BR700-74-102002 R01 - IGNITION - IGNITER PLUG - INTRODUCTION OF AN IGNITER PLUG WITH REVISED SEMICONDUCTOR PELLET BONDING, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-74-102003 R02	NO. 1 ENGINE - SB BR700-74-102003 R02 - IGNITION - IGNITER PLUG - INTRODUCTION OF AN ALTERNATIVE IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-74-102151 R01	NO. 1 ENGINE - SB BR700-74-102151 R01 - IGNITION - IGNITER PLUG - DEFINITION OF ONE EXISTING IGNITER PLUG AS THE SINGLE STANDARD FOR FUTURE USE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-75-101799 R01	NO. 1 ENGINE - SB BR700-75-101799 R01 - AIR - BUFFER AIR VALVE - INTRODUCTION OF A NEW BUFFER AIR VALVE, CHANGES TO THE HP4 AIR TUBE AND THE HP2 RESTRICTOR ADAPTER AND INTRODUCTION OF A NEW BUFFER AIR VALVE SETTING PROCEDURE, SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-75-101831 R02	NO. 1 ENGINE - SB BR700-75-101831 R02 - AIR - AIR TUBES AND FITTINGS - DEACTIVATION OF THE TURBINE CASE COOLING (TCC) SYSTEM TO MITIGATE TCC VALVE RELIABILITY CONCERNs, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-75-101918 R01	NO. 1 ENGINE - BR700-75-101918 R01 - AIR - TURBINE CASE COOLING (TCC) CONTROL VALVE SYSTEM AND AIR TUBES AND FITTINGS - DELETION OF THE TCC CONTROL VALVE SYSTEM AND MODIFICATION OF ADJACENT COMPONENTS, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-75-101999 R01	NO. 1 ENGINE - BR700-75-101999 R01 - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF A REVISED HANDLING BLEED VALVE SOLENOID CONTROL BLOCK WITHOUT A CONTROL VALVE FOR THE TURBINE CASE COOLING (TCC) VALVE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 2 - SB - 26162/DER116</b>							
SB	BR700-71-101776 R01	NO. 2 ENGINE - SB BR700-71-101776 R01 - POWER PLANT - DRAINS TANK EJECTOR - INTRODUCTION OF A REVISED SEAL RING PART NUMBER FOR SPARES PURPOSES, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
		MOS		05-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-71-101928 R01	NO. 2 ENGINE - SB BR700-71-101928 R01 - POWER PLANT - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT (QECU) - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS FOR THE HYDRAULIC PUMP, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
		MOS		25-SEP-2024			
	27-MAR-2024	HRS/MSC	-				
		ENC					
SB	BR700-71-101987 R01	NO. 2 ENGINE - SB BR700-71-101987 R01 - POWER PLANT - CORE ENGINE HARNESS - INTRODUCTION OF NEW LANE A AND LANE B CORE ENGINE HARNESSES AND DELETION OF THE TURBINE CASE COOLING (TCC) VALVE THERMOCOUPLES, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
		MOS		05-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-72-101737 R01	NO. 2 ENGINE - SB BR700-72-101737 R01 - HIGH PRESSURE (HP) COMPRESSOR FRONT SPLIT CASE - INTRODUCTION OF TWO ADDITIONAL BORESCOPE ACCESS PORTS TO THE HP COMPRESSOR, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE S/N
		MOS		01-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-72-101743 R02	NO. 2 ENGINE - SB BR700-72-101743 R02 - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF NEW LP COMPRESSOR BLADES WITH LASER SHOCK PEENING TREATMENT ON THE HUB LEADING EDGE OF THE BLADE AIRFOIL, SERVICE BULLETIN (RECOMMENDED)				RECOMMENDED	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
		MOS		05-DEC-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-72-102214 R02	NO. 2 ENGINE - SB BR700-72-102214 R02 - HIGH PRESSURE (HP) COMPRESSOR FRONT CASE - INTRODUCTION OF A NEW HP COMPRESSOR FRONT CASE ASSEMBLY MADE BY A DIFFERENT SUPPLIER, SERVICE BULLETIN (OPTIONAL)				OPTIONAL	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE S/N
		MOS		06-MAR-2024			
	23-JUN-2023	HRS/MSC	-				
		ENC					
SB	BR700-73-101708 R01	NO. 2 ENGINE - SB BR700-73-101708 R01 - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED MAIN FUEL PUMP, SERVICE BULLETIN (RECOMMENDED)				RECOMMENDED	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE S/N
		MOS		28-NOV-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					
SB	BR700-73-101767 R01	NO. 2 ENGINE - SB BR700-73-101767 R01 - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A NEW MAIN FUEL PUMP WITH MODIFIED GEARS AND IMPELLER HOUSING, SERVICE BULLETIN (RECOMMENDED)				RECOMMENDED	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE S/N
		MOS		29-NOV-2023			
	10-NOV-2023	HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101769 R01	NO. 2 ENGINE - SB BR700-73-101769 R01 - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - INTRODUCTION OF A REVISED SHUT-OFF VALVE SERVO VALVE (SOVSV) WITH A NEW GAS DISCHARGE TUBE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-101775 R01	NO. 2 ENGINE - SB BR700-73-101775 R01 - ENGINE FUEL AND CONTROL - LOW PRESSURE (LP) TURBINE OVERSPEED CONTROL UNIT AND MANIFOLD SPLITTER - INTRODUCTION OF A REVISED OVERSPEED AND SPLITTER UNIT (OSU), SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY SERIAL: N/A BY ENGINE SN
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-101792 R02	NO. 2 ENGINE - SB BR700-73-101792 R02 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.2.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101793 R04	NO. 2 ENGINE - SB BR700-73-101793 R04 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-101801 R01	NO. 2 ENGINE - SB BR700-73-101801 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.1.4 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-101847 R02	NO. 2 ENGINE - SB BR700-73-101847 R02 - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW SPILL RETURN TO FUEL PUMP TUBE MADE FROM A DIFFERENT MATERIAL AND A NEW ASSEMBLY PROCEDURE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		15-NOV-2022 0 0			
SB BR700-73-101886 R01	NO. 2 ENGINE - SB BR700-73-101886 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K6.2.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101892 R02	NO. 2 ENGINE - SB BR700-73-101892 R02 - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A LOW PRESSURE (LP) FUEL SWITCH SENSE LINE TUBE WITH INCREASED VOLUME, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101902 R02	NO. 2 ENGINE - SB BR700-73-101902 R02 - ENGINE FUEL AND CONTROL - T30 THERMOCOUPLES - INTRODUCTION OF A REVISED T30 THERMOCOUPLE INSTALLATION ON THE LEFT SIDE OF THE CORE ENGINE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - N/A BY ENGINE SN
10-NOV-2023		MOS HRS/MSC ENC		04-DEC-2023			
SB BR700-73-101923 R01	NO. 2 ENGINE - BR700-73-101923 R01 - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW FUEL TUBE WITH AN INCREASED WALL THICKNESS, WHICH IS INSTALLED BETWEEN THE FUEL COOLED OIL COOLER (FCOC) AND THE MAIN FUEL PUMP, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101929 R01	NO. 2 ENGINE - BR700-73-101929 R01 - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-101957 R02	NO. 2 ENGINE - SB BR700-73-101957 R02 - ENGINE FUEL AND CONTROL - FUEL SYSTEM - INTRODUCTION OF A REVISED FUEL SYSTEM, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-73-101965 R02	NO. 2 ENGINE - BR700-73-101965 R02 - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE SWITCH - INTRODUCTION OF A REVISED FUEL LOW PRESSURE (LP) SWITCH WITH A DECREASED PRESSURE TRIGGER POINT, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-101967 R02	NO. 2 ENGINE - BR700-73-101967 R02 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K7.1.3 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-73-102000 R01	NO. 2 ENGINE - BR700-73-102000 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K8.0.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-73-102134 R03	NO. 2 ENGINE - BR700-73-102134 R03 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K9.0.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-102183 R01	NO. 2 ENGINE - BR700-73-102183 R01 - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF K10.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01, SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	NOT APPLICABLE - NFA REQ'D DUE PCW AT INITIAL REVISION
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-74-101762 R02	NO. 2 ENGINE - BR700-74-101762 R02 - IGNITION - IGNITER PLUG - INTRODUCTION OF IGNITER PLUGS WITH SILVER COATED THREADS, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-74-102002 R01	NO. 2 ENGINE - BR700-74-102002 R01 - IGNITION - IGNITER PLUG - INTRODUCTION OF AN IGNITER PLUG WITH REVISED SEMICONDUCTOR PELLET BONDING, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-74-102003 R02	NO. 2 ENGINE - SB BR700-74-102003 R02 - IGNITION - IGNITER PLUG - INTRODUCTION OF AN ALTERNATIVE IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		29-NOV-2023			
SB BR700-74-102151 R01	NO. 2 ENGINE - SB BR700-74-102151 R01 - IGNITION - IGNITER PLUG - DEFINITION OF ONE EXISTING IGNITER PLUG AS THE SINGLE STANDARD FOR FUTURE USE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		01-DEC-2023			
SB BR700-75-101799 R01	NO. 2 ENGINE - SB BR700-75-101799 R01 - AIR - BUFFER AIR VALVE - INTRODUCTION OF A NEW BUFFER AIR VALVE, CHANGES TO THE HP4 AIR TUBE AND THE HP2 RESTRICTOR ADAPTER AND INTRODUCTION OF A NEW BUFFER AIR VALVE SETTING PROCEDURE, SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-75-101831 R02	NO. 2 ENGINE - SB BR700-75-101831 R02 - AIR - AIR TUBES AND FITTINGS - DEACTIVATION OF THE TURBINE CASE COOLING (TCC) SYSTEM TO MITIGATE TCC VALVE RELIABILITY CONCERNs, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - FOR INFO ONLY
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-75-101918 R01	NO. 2 ENGINE - BR700-75-101918 R01 - AIR - TURBINE CASE COOLING (TCC) CONTROL VALVE SYSTEM AND AIR TUBES AND FITTINGS - DELETION OF THE TCC CONTROL VALVE SYSTEM AND MODIFICATION OF ADJACENT COMPONENTS, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			
SB BR700-75-101999 R01	NO. 2 ENGINE - BR700-75-101999 R01 - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF A REVISED HANDLING BLEED VALVE SOLENOID CONTROL BLOCK WITHOUT A CONTROL VALVE FOR THE TURBINE CASE COOLING (TCC) VALVE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY ENGINE S/N
10-NOV-2023		MOS HRS/MSC ENC		05-DEC-2023			