

Total projection: 21-Nov-2023 / Hrs 5274:25 / Ldg 4,025

Company

Owner: Airstream a.s.
Operator: Airstream a.s.

Major Assemblies

Airframe	Beechjet 400A	RK-313	09-Nov-2022	4914:25 Hrs	3,665 Ldg	314:19 ACH
Eng 1	JT15D-5	PCE-JA0092	09-Nov-2022	5714:38 Hrs	4,626 Enc	
Eng 2	JT15D-5	PCE-JA0093	09-Nov-2022	5714:38 Hrs	4,626 Enc	

Additional Information

Earliest due: 7 DAYS, 11 HRS, 1,335 LDG, General Categories: RVSM,EMM

Cost:
Man Hrs: 168+

Analyst: Charmaine Palm cpalm@traxxall.com

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
05-20-01	Scheduled IFA-200 Hour Special Inspections						RE			≈20-Nov-2022
5 A/F					Mos	29-Jul-2022				
					Hrs	4725:08	200	+40	4925:08	10:43 Hrs (+40)
					Ldg	3,551				
H270034	PITCH TRIM ACTUATOR AND ATTACH BRACKET ASSEMBLY - / a. Detail inspect pitch trim actuator and attach bracket assembly for condition (Ref. Chapter 27-40-00, Figure 210). / b. Visually inspect the jackscrew and jacknut for metallic shavings, contamination / particles embedded in the grease, or wrapped around the jackscrew threads. / c. Perform the LUBRICATION SCHEDULE - HORIZONTAL STABILIZER PIVOT FITTING procedure (Ref. Chapter 12-20-00).						RE	Scheduled Special Inspections		≈20-Nov-2022
27 A/F					Mos	29-Jul-2022				
					Hrs	4725:05	200	+40	4925:05	10:40 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	3,551				
H300013	DEICE SYSTEM TERMINAL BOARDS (TB011 & TB061) - Detail inspect for corrosion, security and evidence of damage. If corrosion is not found, treat terminal boards with Lektro-Tect Super Corr-A Corrosion Preventative Compound. If corrosion is found, perform TERMINAL BOARD (TB011 and TB061) INSPECTION (Ref. Chapter 30-12-00).						RE	Scheduled Special Inspections		≈20-Nov-2022
30 A/F					Mos	29-Jul-2022				
					Hrs	4725:05	200	+40	4925:05	10:40 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	3,551				
H520019	ENTRANCE DOOR STEP ASSEMBLY (RK-1 thru RK-558 with Kit 128-4045 Installed, RK-559 and After) / a. Detail inspect the cabin step assembly for cracks, loose or failed fasteners, any indication of structural damage, condition, and proper operation. / b. Check torque of the lower step forward and aft attachment nuts (Ref. Chapter 20-10-05). / c. Inspect both the upper and lower rod link assemblies for cracks, distortion, and condition. / d. Check the latch sleeve and bolt rotate freely.						RE	Scheduled Special Inspections		≈20-Nov-2022
52 A/F					Mos	29-Jul-2022				
					Hrs	4725:05	200	+40	4925:05	10:40 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: RK-1 thru RK-558 with Kit 128-4045 Installed, RK-559 and After)				Ldg	3,551				
047102	Engine Carry-Through Brackets - b. Visually Inspect the Engine Carry-Through Bracket (Left Engine, Forward Beam, Aft Bracket) for Cracks Using a 10x Magnifying Glass (Ref. Figure 1). Remove and Replace if Crack is Found. Contact BC Customer Support for Replacement Assistance						RE	AWL - Inspection Limitations		≈20-Nov-2022
71 A/F					Mos	29-Jul-2022				
Unknown					Hrs	4725:05	200	+20	4925:05	10:40 Hrs (+20)
Unknown					Ldg	3,551				
	Brand C:531083 (Manual Adjustment: 0 Hrs) (UPDATE NOTE: WP Z2200016) (SOURCE: Maintenance Manual 040002) (NOTE: or cracks using a 10x magnifying glass (Ref. Figure 1). Remove and replace if crack is found. Contact BC Customer Support for replacement assistance.)									
2002-01-23	Left Engine Forward Carry-Through Mount Bracket						RE		Mandatory	≈25-Nov-2022
54 A/F					Mos	06-Aug-2022				
					Hrs	4729:35	200		4929:35	15:10 Hrs
	Eff: 14-Feb-2002 Complied With				Ldg	3,554				
	Update Nav Database						RE			
34 A/F					Days	29-Oct-2022	30		28-Nov-2022	7 Days
					Hrs					
					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-20-04		SCHEDULED IFA-C INSPECTIONS						RE		Scheduled Inspections	≈29-Jan-2023
	5 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs		1,600	+40	[4992:37]	78:12 Hrs (+40)
						Ldg					
08-10-01-001		Aircraft Weighing and Balancing						RE			
	8 A/F					Mos	31-Jan-2019	48		31-Jan-2023	71 Days
	Inspected Date 31-Jan-2019					Hrs					
						Ldg					
256006		First Aid Kit Inspection (check seal, date)						RE			
	25 A/F					Mos	29-Jun-2022	12		[31-Jan-2023]	71 Days
		Brand C:256076 (UPDATE NOTE: ITEMS VALID THROUGH 31-JAN-2023)				Hrs					
						Ldg					
CZ CAA REQUIREMENT 1.5.4		WEIGHT & BALLANCE RENEWAL						RE			
	0 A/F					Mos	01-Feb-2019	48		01-Feb-2023	72 Days
						Hrs					
						Ldg					
00-CUS-001		Camo Part M AD Monitoring						RE			
	100 A/F					Mos	03-Feb-2022	12		[03-Feb-2023]	74 Days
		(UPDATE NOTE: ADMINISTRATIVE ACTION CAMO CZ.CAMO.0092)				Hrs					
						Ldg					
00-CUS-002		Camo Part M SB Monitoring						RE			
	100 A/F					Mos	03-Feb-2022	12		[03-Feb-2023]	74 Days
		(UPDATE NOTE: ADMINISTRATIVE ACTION CZ.CAMO.0092)				Hrs					
						Ldg					
045706		Main Landing Gear Support Fitting - Inspect for Cracks (By Eddy Current Inspection), Loose or Failed Fasteners and Evidence of Structural Damage						T		AWL - Inspection Limitations	≈05-Feb-2023
	57 A/F	Left				Mos					
	Unknown					Hrs		5,000	+20	5000	85:35 Hrs (+20)
	Unknown					Ldg					
		Brand C:321049 (SOURCE: Maintenance Manual 040002)									
045706		Main Landing Gear Support Fitting - Inspect for Cracks (By Eddy Current Inspection), Loose or Failed Fasteners and Evidence of Structural Damage						T		AWL - Inspection Limitations	≈05-Feb-2023
	57 A/F	Right				Mos					
	Unknown					Hrs		5,000	+20	5000	85:35 Hrs (+20)
	Unknown					Ldg					
		Brand C:321050 (SOURCE: Maintenance Manual 040002)									
710300-0101		Engine Carry-Through Bracket Bolts						RE		AWL - Life Limit	≈05-Feb-2023
	71 A/F	Fwd - No.1				Mos	05-Mar-2001				
	Unknown	New	0			Hrs	0	5,000		5000	85:35 Hrs
	Unknown					Ldg	0				
		Brand C:531085, MM:047103 (SOURCE: Maintenance Manual 040002)									
710300-0102		Engine Carry-Through Bracket Bolts						RE		AWL - Life Limit	≈05-Feb-2023
	71 A/F	Fwd - No.2				Mos	05-Mar-2001				
	Unknown	New	0			Hrs	0	5,000		5000	85:35 Hrs
	Unknown					Ldg	0				
		Brand C:531090, MM:047103 (SOURCE: Maintenance Manual 040002)									
710300-0103		Engine Carry-Through Bracket Bolts						RE		AWL - Life Limit	≈05-Feb-2023
	71 A/F	Aft - No.1				Mos	05-Mar-2001				
	Unknown	New	0			Hrs	0	5,000		5000	85:35 Hrs
	Unknown					Ldg	0				
		Brand C:531085, MM:047103 (SOURCE: Maintenance Manual 040002)									

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
710300-0104		Engine Carry-Through Bracket Bolts								RE	AWL - Life Limit	≈05-Feb-2023
	71 A/F	Aft - No.2					Mos	05-Mar-2001				
	Unknown	New					Hrs	0	5,000	5000	85:35 Hrs	
	Unknown						Ldg	0				
	Brand C:531090, MM:047103 (SOURCE: Maintenance Manual 040002)											
H243026		MAIN BATTERY - Perform the EMERGENCY CAPACITY TEST in accordance with battery manufacturer's maintenance recommendations.								T	Scheduled Special Inspections	
	24 A/F						Mos	06-Aug-2022	12		09-Feb-2023	80 Days
	RG-380E/40L						Hrs	4729:35	600	+40	5329:35	415:10 Hrs (+40)
	41195108						Ldg	3,554				
	Certified Date 09-Feb-2022 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
042804		Fuel System - Auxiliary Fuel Tank (Outer Tank Structure Only) - Inspect for Corrosion, Fatigue, Cracks Loose or Failed Fasteners, and General Condition. Use Borescope as Needed.								RE	AWL - Inspection Limitations	≈13-Feb-2023
	28 A/F	Left					Mos					
	Unknown						Hrs	2608:31	2,400	+20	5008:31	94:06 Hrs (+20)
	Unknown						Ldg					
	(SOURCE: Maintenance Manual 040002)											
042804		Fuel System - Auxiliary Fuel Tank (Outer Tank Structure Only) - Inspect for Corrosion, Fatigue, Cracks Loose or Failed Fasteners, and General Condition. Use Borescope as Needed.								RE	AWL - Inspection Limitations	≈13-Feb-2023
	28 A/F	Right					Mos					
	Unknown						Hrs	2608:31	2,400	+20	5008:31	94:06 Hrs (+20)
	Unknown						Ldg					
	(SOURCE: Maintenance Manual 040002)											
323000-1401		Emergency MLG Door-Open Cable								RE	AWL - Life Limit	≈13-Feb-2023
	32 A/F	Left					Mos					
	Unknown						Hrs	2608:31	2,400		5008:31	94:06 Hrs
	Unknown						Ldg					
	Brand C:323093, MM:043221 (SOURCE: Maintenance Manual 040002)											
120031		Spoiler Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation								RE	Servicing	
	12 A/F						Mos	27-Feb-2019	48		27-Feb-2023	3.3 Months
							Hrs	3549:21	6,500	+20	10049:21	5134:56 Hrs (+20)
							Ldg					
	AMM:22-13-00, Brand A:123001, Brand C:123001											
120032		Elevator Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation								RE	Servicing	
	12 A/F						Mos	27-Feb-2019	48		27-Feb-2023	3.3 Months
							Hrs	3549:21	6,500	+20	10049:21	5134:56 Hrs (+20)
							Ldg					
	AMM:22-13-00, Brand A:123002, Brand C:123002											
120033		Rudder Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation								RE	Servicing	
	12 A/F						Mos	27-Feb-2019	48		27-Feb-2023	3.3 Months
							Hrs	3549:21	6,500	+20	10049:21	5134:56 Hrs (+20)
							Ldg					
	AMM:22-13-00, Brand A:123003, Brand C:123003											
H313011		FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON (RK-36 and After) - Functional test. Refer to the Dukane (Seacom Division) Technical Manual in Chapter 23 of the Component Maintenance Manual, P/N 128-590001-81 or subsequent for test procedures.								RE	Scheduled Special Inspections	
	31 A/F						Yrs	28-Feb-2021	2		28-Feb-2023	3.3 Months
	Unknown						Hrs					
	Unknown						Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
043224		Pneumatic Storage Bottle - b. Hydrostatically Test Bottle in Accordance with Title 49 CFR Chapter 1, Section 180.209 or Replace with New Bottle								RE	AWL - Inspection Limitations	
	32 A/F						Yrs	28-Feb-2020	3		28-Feb-2023	3.3 Months
	23111321						Hrs					
	1780						Ldg					
	Hydrostatic Tested Date 28-Feb-2020 Brand C:323085 (SOURCE: Maintenance Manual 040002)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
335100-0201		Emergency Light Power Supply - Battery								RE	AWL - Life Limit
	33 A/F	Fwd	0				Yrs	10-Feb-2020	3	28-Feb-2023	3.3 Months
	044017-1	New					Hrs				
	Unknown						Ldg				
	ALM:043301 (SOURCE: MODEL 400/400A ALM 04-00-02)										
34-91-00-021		EGPWS/TAWS Terrain Database Version Verification								RE	
	34 A/F						Mos	05-Aug-2022	6	28-Feb-2023	3.3 Months
							Hrs	4729:35			
							Ldg	3,554			
FAR 91.411		Pitot/ Static Systems Leak check per FAR 91.411 Appendix E of Part 43								RE	FAR91, FAR 91
	34 A/F	Copilot					Mos	28-Feb-2021	24	28-Feb-2023	3.3 Months
	Unknown						Hrs				
	Unknown						Ldg				
	Certified Date 28-Feb-2021										
FAR 91.411		Pitot/ Static Systems Leak check per FAR 91.411 Appendix E of Part 43								RE	FAR91, FAR 91
	34 A/F	Pilot					Mos	28-Feb-2021	24	28-Feb-2023	3.3 Months
	Unknown						Hrs				
	Unknown						Ldg				
		Inspected Date 28-Feb-2021									
H340006		MACH OVERSPEED WARNING SYSTEM - Perform functional test by use of pitot/static tester (Ref. AIR-SPEED AND MACH WARNING TEST, Chapter 34-12-00).								RE	Scheduled Special Inspections
	34 A/F						Yrs	28-Feb-2021	2	28-Feb-2023	3.3 Months
							Hrs				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H340007		AIR DATA SYSTEM (RVSM Only) (RK-1 thru RK-299 that have complied with Service Bulletin No. 34-3431; RK-300 and After) - Measure step height of the Static port. Check air data system for RVSM accuracy (Ref. Chapter 34-10-01).								RE	Scheduled Special Inspections
	34 A/F						Yrs	28-Feb-2021	2	28-Feb-2023	3.3 Months
							Hrs				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: RK-1 thru RK-299 that have complied with Service Bulletin No. 34-3431; RK-300 and After)										
34-4154		Navigation - Introduction of Automatic Dependent Surveillance - Broadcast Out (ADSB OUT) Installation Kit								T (A/R)	Optional
	34 A/F						Mos	17-Aug-2017		[01-Mar-2023]	3.3 Months
	Eff. 17-Aug-2017 Deferred	OFFER AVAILABILITY					Hrs				
	(AVG MAN HRS: 168)						Ldg				
00-CUS-003		Major Repairs, Modifications Review								RE	
	100 A/F						Mos	30-Mar-2022	12	30-Mar-2023	4.3 Months
							Hrs				
	(UPDATE NOTE: CAMO ADMINISTRATIVE ACTION)										
25-CUS-002		First Aid Kit - Expiration								RE	
	25 A/F						Mos	28-Apr-2022	12	28-Apr-2023	5.3 Months
							Hrs	4509:35			
							Ldg	3,416			
H262001		COCKPIT PORTABLE FIRE EXTINGUISHER - Inspect weight, operating pressure and condition.								RE	Scheduled Special Inspections
	26 A/F						Yrs	28-Apr-2022	1	28-Apr-2023	5.3 Months
	Weighed Date 28-Apr-2022						Hrs	4509:35			
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H262002		CABIN PORTABLE FIRE EXTINGUISHER - Inspect weight, operating pressure and condition.								RE	Scheduled Special Inspections
	26 A/F						Yrs	28-Apr-2022	1	28-Apr-2023	5.3 Months
	Weighed Date 28-Apr-2022						Hrs	4509:35			
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-JT15D-006		Systems - Oil System - Oil Filter Element (non-cleanable), JT15D-5 (Post-SB7476 and Post-SB7581) and JT15D-5R Engines - Remove and Inspect the Oil Filter for Foreign Matter. Reject and Replace the Oil Filter if any Foreign Matter is found						RE		EMM - Requirement	
	79 ENG1					Yrs	28-Apr-2022	1		28-Apr-2023	5.3 Months
						Hrs	5309:48	800	-/+50	6109:48	395:10 Hrs (+50)
		Ref:79-21-01(JT15D-5R), Ref:79-20-01(JT15D-5) (NOTE: At 800 ± 50 hours or one year whichever comes first)				Enc	4,127				
79-JT15D-006		Systems - Oil System - Oil Filter Element (non-cleanable), JT15D-5 (Post-SB7476 and Post-SB7581) and JT15D-5R Engines - Remove and Inspect the Oil Filter for Foreign Matter. Reject and Replace the Oil Filter if any Foreign Matter is found						RE		EMM - Requirement	
	79 ENG2					Yrs	28-Apr-2022	1		28-Apr-2023	5.3 Months
						Hrs	5309:48	800	-/+50	6109:48	395:10 Hrs (+50)
		Ref:79-21-01(JT15D-5R), Ref:79-20-01(JT15D-5) (NOTE: At 800 ± 50 hours or one year whichever comes first)				Enc	4,127				
79-JT15D-015		Systems - Oil System - Oil Filter Element (cleanable) - Remove Oil Filter Element and Inspect for Foreign Matter, Clean and Inspect. Reject and Replace Unserviceable Oil Filter Element						RE		EMM - Requirement	
	79 ENG1					Yrs	28-Apr-2022	1		28-Apr-2023	5.3 Months
						Hrs	5309:48	800	-/+50	6109:48	395:10 Hrs (+50)
		Ref:79-20-01 (NOTE: At 800 ± 50 hours or one year whichever comes first and at HSI interval (Ref. SB7003 for interval).)				Enc	4,127				
79-JT15D-015		Systems - Oil System - Oil Filter Element (cleanable) - Remove Oil Filter Element and Inspect for Foreign Matter, Clean and Inspect. Reject and Replace Unserviceable Oil Filter Element						RE		EMM - Requirement	
	79 ENG2					Yrs	28-Apr-2022	1		28-Apr-2023	5.3 Months
						Hrs	5309:48	800	-/+50	6109:48	395:10 Hrs (+50)
		Ref:79-20-01 (NOTE: At 800 ± 50 hours or one year whichever comes first and at HSI interval (Ref. SB7003 for interval).)				Enc	4,127				
00-CUS-004		Report Airco Hours						RE			
	100 A/F					Mos	28-Apr-2022	12		28-Apr-2023	5.3 Months
						Hrs	4509:35				
						Ldg	3,416				
79-JT15D-005		Systems - Oil System - Oil Filter Element (cleanable), Remove the Oil Filter Element, Inspect for Foreign Matter and Reject/Replace Unserviceable Oil Filter Element						RE		EMM - Requirement	≈15-May-2023
	79 ENG1					Mos	08-Nov-2022				
						Hrs	5710:28	200	-/+10%	5899:48	185:10 Hrs (+20)
		Ref:79.20.01-mp (Tol. Adjustment: -10.7 Hrs)				Enc	4,624				
05-JT15D-001		Engine Minor Inspection						RE			≈25-May-2023
	5 ENG1					Mos	08-Nov-2022				
						Hrs	5710:28	200	-/+20	5909:48	195:10 Hrs (+20)
		(Tol. Adjustment: -0.7 Hrs)				Enc	4,624				
05-JT15D-001		Engine Minor Inspection						RE			≈25-May-2023
	5 ENG2					Mos	08-Nov-2022				
						Hrs	5710:28	200	-/+20	5909:48	195:10 Hrs (+20)
		(Tol. Adjustment: -0.7 Hrs)				Enc	4,624				
H240019		STARTER-GENERATOR (Generator removal is not necessary.) (Ref. Chapter 80-10-00). / a. Inspect for security and visible damage. / b. Inspect brushes for wear. / c. Inspect electrical connections for security, wear, deterioration and damage.						RE			≈26-May-2023
	24 A/F					Mos	08-Nov-2022				
						Hrs	4910:15	200		5110:15	195:50 Hrs
						Ldg	3,663				
H240020		LH STARTER-GENERATOR (Generator removal is not necessary.) (Ref. Chapter 80-10-00). / a. Inspect for security and visible damage. / b. Inspect brushes for wear. / c. Inspect electrical connections for security, wear, deterioration and damage.						RE	Scheduled Special Inspections		≈26-May-2023
	24 A/F					Mos	08-Nov-2022				
						Hrs	4910:15	200		5110:15	195:50 Hrs
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	3,663				
2001-03-06		Bleed Air Supply Tube Assembly						RE		Mandatory	≈26-May-2023
	36 A/F					Mos	08-Nov-2022				
		Eff: 22-Mar-2001 Complied With				Hrs	4910:15	200		5110:15	195:50 Hrs
						Ldg	3,663				

Total projection: 21-Nov-2023 / Hrs 5274:25 / Ldg 4,025

Beechjet 400A OK-IMO,SN RK-313

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-CUS-001		Engine Bleed Valve Actuator Visual Inspection						RE			≈26-May-2023
	72 ENG1					Mos	05-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
72-CUS-001		Engine Bleed Valve Actuator Visual Inspection						RE			≈26-May-2023
	72 ENG2					Mos	08-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
72-CUS-002		Engine Electric Bleed Valve Control - Visual Inspection						RE			≈26-May-2023
	72 ENG1					Mos	08-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
72-CUS-002		Engine Electric Bleed Valve Control - Visual Inspection						RE			≈26-May-2023
	72 ENG2					Mos	08-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
72-CUS-003		Engine Main Wiring Harness Visual Inspection						RE			≈26-May-2023
	72 ENG1					Mos	08-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
72-CUS-003		Engine Main Wiring Harness Visual Inspection						RE			≈26-May-2023
	72 ENG2					Mos	08-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
		Visually Inspect Electronic Bleed Valve Control						RE			≈26-May-2023
	73 ENG1					Mos	08-Nov-2022				
						Hrs	5710:28	200		5910:28	195:50 Hrs
						Enc	4,624				
H730003		FUEL PUMP OUTLET FILTER, P/N 3059778 (JT15D-5 and JT15D-5R) - Check for foreign matter and/or distortion. Install new filter at each inspection. Refer to Pratt & Whitney JT15D-5/-5R Maintenance Manual, Chapter 73-10-02.						RE	Scheduled Special Inspections		≈26-May-2023
	73 A/F					Mos	08-Nov-2022				
						Hrs	4910:15	200	+40	5110:15	195:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	3,663				
H730004		FUEL PUMP OUTLET FILTER, P/N 3059778 (JT15D-5 and JT15D-5R) - Check for foreign matter and/or distortion. Install new filter at each inspection. Refer to Pratt & Whitney JT15D-5/-5R Maintenance Manual, Chapter 73-10-02.						RE	Scheduled Special Inspections		≈26-May-2023
	73 A/F					Mos	08-Nov-2022				
						Hrs	4910:15	200	+40	5110:15	195:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	3,663				
H740003		ENGINE IGNITOR PLUGS - Inspect for wear and condition. Refer to Pratt & Whitney JT15D-5/-5R Maintenance Manual, Chapter 74-20-02.						RE	Scheduled Special Inspections		≈26-May-2023
	74 A/F					Mos	08-Nov-2022				
						Hrs	4910:15	200	+40	5110:15	195:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	3,663				
34-CUS-009		ADSB Installation						RE (-)			
	34 A/F					Mos				[07-Jun-2023]	6.6 Months
						Hrs					
						Ldg					
05-20-02		SCHEDULED IFA-A INSPECTIONS						RE		Scheduled Inspections	≈10-Jun-2023
	5 A/F					Mos	29-Jul-2022	12		31-Jul-2023	8.4 Months
						Hrs	4725:08	400	+40	5125:08	210:43 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Ldg	3,551				

Total projection: 21-Nov-2023 / Hrs 5274:25 / Ldg 4,025

Beechjet 400A OK-IMO,SN RK-313

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-JT15D-005	Systems - Oil System - Oil Filter Element (cleanable), Remove the Oil Filter Element, Inspect for Foreign Matter and Reject/Replace Unservicable Oil Filter Element						RE		EMM - Requirement	≈10-Jun-2023
79 ENG2	Ref:79.20.01-mp (Tol. Adjustment: 14.8 Hrs)				Mos	08-Nov-2022				
					Hrs	5710:28	200	-/+10%	5925:18	210:40 Hrs (+20)
					Enc	4,624				
25-CUS-005	Cockpit + Cabin Personal Floating Devices - Check						RE			
25 A/F					Mos	29-Jun-2022	12		29-Jun-2023	7.3 Months
					Hrs	4656:35				
					Ldg	3,508				
35-CUS-001	Portable Breathing Equipment (PBE) Air Liquid Visual Inspection						RE			
35 A/F					Mos	29-Jun-2022	12		29-Jun-2023	7.3 Months
					Hrs	4656:35				
					Ldg	3,508				
H330007	CABIN SECTION - EMERGENCY LIGHTING SYSTEM / a. - Move the EMER LT switch to the TEST/ON position and ensure emergency lighting illuminates. Return EMER LT switch to the OFF position.						RE		Scheduled Inspections	≈10-Jul-2023
33 A/F	(UPDATE NOTE: CRS RCRAFT 2022_17_OKIMO) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Mos	28-Jul-2022	12		31-Jul-2023	8.4 Months
					Hrs	4755:05	400	+40	5155:05	240:40 Hrs (+40)
					Ldg	3,581				
H240013	AHRS POWER SUPPLY BATTERY (JET Model P5835) - Perform battery capacitance test (Ref. Chapter 24-30-02 in the Component Maintenance Manual, 128-590001-81 or subsequent.						RE		Scheduled Special Inspections	
24 A/F 501-1228-04 11930 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Yrs	15-Jul-2022	1		15-Jul-2023	7.9 Months
					Hrs					
					Ldg					
CZ-CAA ST-092/1.5.3	ELT test and inspection per National Authority						RE			
25 A/F					Mos	15-Jul-2022	12	+1m	15-Jul-2023	7.9 Months (+31 Days)
					Hrs	4695:45				
					Ldg	3,533				
H250018	EMERGENCY LOCATOR TRANSMITTER (If installed) - Inspect the ELT as required by 14 CFR 91.207 (d) for: / a. Proper installation. / b. Battery corrosion. / c. Operation of controls and crash sensor. / d. The presence of sufficient signal radiated from it's antenna. Refer to the Artex Maintenance Manual, Document Numbers 570-1015 or 570-5000 or subsequent, for the appropriate ELT model number.						RE		Scheduled Special Inspections	
25 A/F 453-5000-366 11393 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Yrs	15-Jul-2022	1		15-Jul-2023	7.9 Months
					Hrs	4695:45				
					Ldg	3,533				
H313005	FLIGHT DATA RECORDER (if applicable) - Perform the FLIGHT DATA RECORDER (FDR) INSPECTION CHECK (Ref. Chapter 31-30-00).						RE		Scheduled Special Inspections	
31 A/F S800-2000-00 41075514 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Yrs	28-Jul-2022	1		28-Jul-2023	8.3 Months
					Hrs	4725:05				
					Ldg	3,541				
05-20-01-01	IFA Program Renewal						RE			
5 A/F					Mos	29-Jul-2022	12		29-Jul-2023	8.3 Months
					Hrs	4725:08				
					Ldg	3,551				
342001A	Compass Swing						RE			
34 A/F					Mos	05-Aug-2022	12	+1m	05-Aug-2023	8.6 Months (+31 Days)
					Hrs	4729:35				
					Ldg	3,554				

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
CZ CAA 092/1.5.5		CZ-CAA REQUIREMENT CAA-ST-092-n-07 - MAGNETIC COMPASS						RE				
	34 A/F					Mos	05-Aug-2022	12		05-Aug-2023	8.6 Months	
						Hrs	4729:35					
		(UPDATE NOTE: PERFORMED TEXTRON CRS 70001552)				Ldg	3,554					
045304		Aft Fuselage Baggage Compartment Velcro (Hook Only) - Inspect Velcro for Damage or Dirt Which Could Reduce Holding Ability						RE	AWL - Inspection Limitations		≈05-Aug-2023	
	53 A/F	Aft				Mos	28-Aug-2022					
	Unknown					Hrs	4779:50	400	+20	5179:50	265:25 Hrs (+20)	
	Unknown					Ldg	3,581					
		Brand C:256050 (UPDATE NOTE: CRS RCA Z2200018) (SOURCE: Maintenance Manual 040002) (NOTE: (*) This part is not practical to mark with a part number/serial number. If removal from the airplane is required before the end of its published replacement life limitation, then it should be bagged and identified with accumulated hours/cycles and records should be maintained to ensure compliance with the life limitation.)										
73-CUS-003		Engine Motive Flow Valve Inspection and Recertification						RE			≈26-Aug-2023	
	73 ENG1					Mos						
						Hrs		6,000		6000	285:22 Hrs	
						Enc						
73-CUS-003		Engine Motive Flow Valve Inspection and Recertification						RE			≈26-Aug-2023	
	73 ENG2					Mos						
						Hrs		6,000		6000	285:22 Hrs	
						Enc						
335100-0202		Emergency Light Power Supply - Battery						RE		AWL - Life Limit		
	33 A/F	Aft	0			Yrs	10-Aug-2020	3		31-Aug-2023	9.4 Months	
	Unknown					Hrs						
	Unknown					Ldg						
		ALM:043301 (SOURCE: MODEL 400/400A ALM 04-00-02)										
323000-1402		Emergency MLG Door-Open Cable						T		AWL - Life Limit	≈04-Sep-2023	
	32 A/F	Right				Mos						
	Unknown		0			Hrs	2608:31	2,600		5208:31	294:06 Hrs	
	Unknown					Ldg						
		Brand C:323094, MM:043221 (SOURCE: Maintenance Manual 040002)										
05-00-00-001		Airworthiness Review Certificate (ARC) Renewal/Extension						RE (Due)		Custom Task		
	5 A/F					Mos	28-Sep-2022			[05-Oct-2023]	10.6 Months	
		Expiration Date 05-Oct-2023				Hrs	4856:36					
						Ldg	3,629					
79-JT15D-007		Systems - Oil System - Oil Filter Element (non-cleanable), JT15D-5 (Post-SB7476 and Post-SB7581) and JT15D-5R Engines - Remove and Inspect the Oil Filter for Foreign Matter. Reject and Replace the Oil Filter if any Foreign Matter is found						RE		EMM - Requirement	≈25-Oct-2023	
	79 ENG1					Mos	28-Apr-2022					
						Hrs	5309:48	750	-/+50	6059:48	345:10 Hrs (+50)	
		Ref:79-21-01 (JT15D-5R), Ref:79-20-01 (JT15D-5) (NOTE: At HSI interval (Ref. SB7003 for interval)				Enc	4,127					
79-JT15D-007		Systems - Oil System - Oil Filter Element (non-cleanable), JT15D-5 (Post-SB7476 and Post-SB7581) and JT15D-5R Engines - Remove and Inspect the Oil Filter for Foreign Matter. Reject and Replace the Oil Filter if any Foreign Matter is found						RE		EMM - Requirement	≈25-Oct-2023	
	79 ENG2					Mos	28-Apr-2022					
						Hrs	5309:48	750	-/+50	6059:48	345:10 Hrs (+50)	
		Ref:79-20-01 (JT15D-5), Ref:79-21-01 (JT15D-5R) (NOTE: At HSI interval (Ref. SB7003 for interval)				Enc	4,127					