

- Major Assemblies

Owner: Airstream a.s.
Operator: Airstream a.s.

Airframe	560XL (Citation Excel)	560-5183	25-Jan-2024	7052:40 Hrs	4,653 Ldg	2029 Hrs(APU)	4,326 Start(APU)
Eng 1	PW545A	PCE-DB0373	25-Jan-2024	6742:55 Hrs	4,454 Enc		
Eng 2	PW545A	PCE-DB0416	25-Jan-2024	6155:30 Hrs	4,127 Enc		
APU 1	RE100[XL]	P-233	18-Jan-2024	2029 Hrs	4,326 APUS		

Additional Information

Program Type: MSG-3, General Categories: Honeywell Avionics

Cost:
Man Hrs:

Analyst: Stephen Crosthwaite scrosthwaite@traxxall.com

Task No	Description												
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining		
▼ 0 - GENERAL													
290029/LR	AIRCRAFT STATION LICENCE RENEWAL							RE					
	0 A/F						Yrs	04-Mar-2022	5	[25-Feb-2027]	3.1 Years		
							Hrs						
							Ldg						
5264/5	AIRWORTHINESS REVIEW CERTIFICATE (ARC)							RE					
	0 A/F						Mos	03-Sep-2023	12	[05-Sep-2024]	7.3 Months		
							Hrs						
							Ldg						
C550015527	INSURANCE CERTIFICATE (ALLIANZ)							RE					
	0 A/F						Mos	01-Feb-2023	12	01-Feb-2024	2 Days		
							Hrs						
							Ldg						
CZ-CAA 092/1.5.1	CZ-CAA REQUIREMENT CAA-ST-092-n-07 - PITOT STATIC SYSTEM LEAK TEST (PERFORMED TOGETHER WITH FULLFILMENT CFR 91.411							RE					
	0 A/F						Mos	22-Jun-2022	24	22-Jun-2024	4.8 Months		
							Hrs	5998:42					
							Ldg	3,966					
CZ-CAA 092/1.5.2	TC MODE S AND MODE C GORUND TESTING IN ACCORDANCE WITH EASA.SIB 2011-15R1 (NOTE: PERFORMED WITH WITH FAR 91.413)							RE					
	0 A/F						Mos	22-Jun-2022	24	22-Jun-2024	4.8 Months		
							Hrs	5998:42					
							Ldg	3,966					
CZ-CAA 092/1.5.4	AIRCRAFT WEIGHT&BALANCE							RE					
	0 A/F						Mos	20-Jul-2022	48	20-Jul-2026	2.5 Years		
							Hrs	5999:12					
							Ldg	3,967					
CZ-CAA 092/1.5.5	MAGNETIC COMPASS CALIBRATION CZ - CAA REQUIREMENT CAA-ST-092-n-07							RE					
	0 A/F						Mos	28-Jun-2023	12	28-Jun-2024	5 Months		
							Hrs	6582:45					
							Ldg	4,450					
CZ-CAA 092/1.5.6	IFR/VOR/ILS/DME/RALT/COM IN FLIGHT (AIRBORN)VERIFICATION - CZ-CAA REQUIREMENT CAA-ST-092-n(07)							RE (-)					
	0 A/F						Mos	26-Jun-2022					
							Hrs	5998:42					
(UPDATE NOTE: ATL No.2) (NOTE: Cancelled by Authority. See customer mail)							Ldg	3,966					
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS													
053401	Special Inspection UNIFIS 3000							RE (N/A)					
	5 A/F						Mos	23-Nov-2021					
							Hrs	5998:30					
							Ldq	3,965					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
053402		TNC Bulkhead Connector - Inspection							T		≈20-Mar-2061
	5 A/F					Mos	27-Nov-2009				
		(Manual Adjustment: -2383 Ldg)				Hrs	2983				
						Ldg	2,383	18,000		18,000	13,347 Ldg
053403		NAV Antenna - Inspection							T		≈29-Sep-2149
	5 A/F					Mos	27-Nov-2009				
		(Manual Adjustment: -2383 Ldg)				Hrs	2983				
						Ldg	2,383	49,800		49,800	45,147 Ldg
053404		UHF Antenna FS 262 - Inspection							T		≈15-Dec-2189
	5 A/F					Mos	27-Nov-2009				
		(Manual Adjustment: -2383 Ldg)				Hrs	2983				
						Ldg	2,383	85,000		85,000	80,347 Ldg
053405		Omnistar Antenna - Inspection							T		≈15-Dec-2189
	5 A/F					Mos	27-Nov-2009				
		(Manual Adjustment: -2383 Ldg)				Hrs	2983				
						Ldg	2,383	150,000		150,000	145,347 Ldg
053406		GPS Antenna FS 178 - Inspection							RE		≈15-Dec-2189
	5 A/F					Mos	27-Nov-2009				
		(Manual Adjustment: -2383 Ldg)				Hrs	2983				
						Ldg	2,383	150,000		150,000	145,347 Ldg
053407		Fuselage Side Skin Conn. - Inspection							RE		≈15-Dec-2189
	5 A/F					Mos	27-Nov-2009				
		(Manual Adjustment: -2383 Ldg)				Hrs	2983				
						Ldg	2,383	150,000		150,000	145,347 Ldg
053408		Printer Stand - Special Inspection							RE (N/A)		
	5 A/F					Mos	17-Jun-2021				
		(NOTE: Printer stand removed by Minor change and STC deactivated. See customer email)				Hrs	5979:12				
						Ldg	3,951				
053424		Compass Swing - Inspection							RE		
	5 A/F					Mos	22-Jun-2022	24		30-Jun-2024	5.1 Months
						Hrs	5998:35				
						Ldg	3,966				
05-50-00(A)(1)		Hard/overweight landings - Check							RE (A/R)	Unscheduled Maintenance Check	
	5 A/F					Mos					
		(NOTE: (1) A hard landing is a landing that is made by an airplane with a sink rate that is more than the permitted sink rate.				Hrs					
		(2) Related to a hard landing is an overweight landing, which is landing the airplane at any gross weight which is more than the placard landing weights.)				Ldg					
05-50-00(A)(10)		Airplane towed with a large fuel unbalance or high drag/side loads because of ground handling - Check							RE (A/R)	Unscheduled Maintenance Check	
	5 A/F					Mos					
						Hrs					
						Ldg					
05-50-00(A)(11)		Airplane Operation Through Deep Standing Water - Check							RE (A/R)	Unscheduled Maintenance Check	
	5 A/F					Mos					
						Hrs					
						Ldg					
05-50-00(A)(12)		Nose Landing Gear Tow Limits - Check							RE (A/R)	Unscheduled Maintenance Check	
	5 A/F					Mos					
						Hrs					
						Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00(A)(13)	 5 A/F	Exposure to High Winds While the Aircraft is Parked Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
						Ldg					
05-50-00(A)(14)	 5 A/F	Interior Cabin/Tailcone Fluid Spill						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
	Ref:Chapter 20, Interior Finish - Cleaning/Painting					Ldg					
05-50-00(A)(15)	 5 A/F	Engine Fire Extinguisher Discharge Inspection						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
						Ldg					
05-50-00(A)(16)	 5 A/F	Auxiliary Power Unit (APU) Fire Extinguisher Discharge Inspection						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
						Ldg					
05-50-00(A)(2)	 5 A/F	Overspeed (Above 8000 ft) - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
	(NOTE: Note: A condition in which the airplane is operated at airspeeds that are more than those permitted by the Approved Airplane Flight Manual at altitudes that are more than 8000 feet.)					Ldg					
05-50-00(A)(3)	 5 A/F	Overspeed (Below 8000 ft) - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
	(NOTE: Note: A condition in which the airplane is operated at airspeeds that are more than those permitted by the Approved Airplane Flight Manual at altitudes that are less than 8000 feet. Overspeed conditions at this altitude also increase the chance for birdstrike damage to the airplane.)					Ldg					
05-50-00(A)(4)	 5 A/F	Flap System Overspeed - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
	(NOTE: Note: A condition in which the flaps are extended at airspeeds that are more than those permitted by the Approved Airplane Flight Manual.)					Ldg					
05-50-00(A)(5)	 5 A/F	Landing Gear Assembly Overspeed - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
	(NOTE: Note: A condition in which the landing gear is extended at airspeeds that are more than those permitted by the Approved Airplane Flight Manual.)					Ldg					
05-50-00(A)(6)	 5 A/F	Dangerous air turbulence or dangerous maneuvers - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos	08-Mar-2023				
						Hrs	6287:15				
	(UPDATE NOTE: CRS 2023_06_OKCAA) (NOTE: (1) Conditions that can dangerously shake an airplane. Dangerous maneuvers are any maneuvers that are more than those permitted by the Approved Airplane Flight Manual.)					Ldg	4,162				
05-50-00(A)(7)	 5 A/F	Accidental in-flight thrust reverser deployment - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
						Ldg					
05-50-00(A)(8)	 5 A/F	Lightning Strike - Check						RE (A/R)	Unscheduled Maintenance Check		
						Mos					
						Hrs					
						Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00(A)(9)	Foreign Object Damage - Check						RE (A/R)	Unscheduled Maintenance Check		
5 A/F										
055601	Inspect Windshield Surface Re-Seal						RE (A/R)	Custom Task		
5 A/F						12-Apr-2002		294		
059015	Airworthiness Review Certificate ARC - Renewal/Extension						RE			
5 A/F						03-Sep-2023	365		[05-Sep-2024]	7.3 Months
▼ 8 - LEVELING AND WEIGHING.										
08-10-01-001	Aircraft Weighing and Balancing						RE			
8 A/F						17-Jun-2021	48		17-Jun-2025	1.4 Years
Inspected Date 17-Jun-2021										
▼ 11 - PLACARDS AND MARKINGS										
11-00-00-AQS	PREPARATION FOR COMMERCIAL OPERATION - PERFORM PLACARD AND MARKINGS INSPECTION IN ACCORDANCE WITH AMM AND NATIONAL REQUIREMENTS						RE (-)			
11 A/F										
▼ 12 - SERVICING - ROUTINE MAINTENANCE										
12-20-27-6400	Flap Roller Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
12 A/F	5-12-01					28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
(ZONE: 512, 522, 612, 622) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)										
12-20-32-6100	Shimmy Damper Servicing						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
12 A/F	5-12-01					28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
5543001-12 01482-12X (ZONE: 710) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)										
12-20-32-6400	Landing Gear and Landing Gear Doors Lubrication						RE	05-10-01, 05-10-02, Category 5, Category 6		
12 A/F	5-12-01					28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
MRBR Task:32-50-00-601, MRBR Task:52-80-00-602, MRBR Task:52-80-00-601, MRBR Task:32-20-00-604, MRBR Task:32-20-00-602, MRBR Task:32-20-00-601, MRBR Task:32-10-00-601 (ZONE: 710, 720, 730) (Tol. Adjustment: -11d) (SOURCE: 560XL MM)										
12-20-52-6400	Cabin Door Hinge Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
12 A/F	5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
(ZONE: 810, 811) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 52-10-00-2200)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
12-26-00-6001		15 Day High Exposure Area Wash					RE (N/A)			Discretionary Maintenance		
	12 A/F						Days	03-Sep-2019				
							Hrs	5869:24				
	Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)						Ldg	3,898				
12-26-00-6002		45 Day Medium Exposure Area Wash					RE (N/A)			Discretionary Maintenance		
	12 A/F						Days	03-Sep-2019				
							Hrs	5869:24				
	Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)						Ldg	3,898				
12-26-00-6003		90 Day Low Exposure Area Wash					RE (N/A)			Discretionary Maintenance		
	12 A/F						Days	03-Sep-2019				
							Hrs	5869:24				
	Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)						Ldg	3,898				
▼ 21 - AIR CONDITIONING AND PRESSURIZATION												
12-20-21-1600		Water Separator (Cleaning) Restoration					RE			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Dec-2027	
	21 A/F	5-12-07					Mos	29-Sep-2023				
	2341316-2						Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
	314						Ldg	4,505				
	(ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02)											
12-20-21-1601		Ozone Converters (Cleaning) Restoration					RE			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈09-Feb-2031	
	21 A/F	Left5-12-22					Mos					
	31A437-1						Hrs		6,600	-/+25	(9583)	2530:20 Hrs (+25)
	03810716						Ldg					
	(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)											
12-20-21-1601		Ozone Converters (Cleaning) Restoration					RE			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈09-Feb-2031	
	21 A/F	Right5-12-22					Mos					
	31A437-1						Hrs		6,600	-/+25	(9583)	2530:20 Hrs (+25)
	03840719						Ldg					
	(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)											
21-22-00-2900		Cabin Air Distribution Check Valves (Borescope) Special Detailed Inspection					RE			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	21 A/F	5-12-16					Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
							Hrs					
	(ZONE: 161, 162) (SOURCE: 560 XL MM Section 5-10-02)						Ldg					
21-22-00-9600		Cockpit Side Window Defog Filter Discard					RE (A/R)			Discretionary Maintenance		
	21 A/F						Mos					
							Hrs					
	Ref:Chapter 21, Warm Air Distribution - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00) (NOTE: As Necessary)						Ldg					
21-30-00-7200		Pressurization System Operational and Functional Check					RE			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	21 A/F	5-12-03					Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs	6620:35				
	(ZONE: 241, 261, 262) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-03)						Ldg	4,370				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
21-31-05-7200		Cabin Altitude Pressure Switch Functional Check									
	21 A/F	5-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	GB300NA161					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	0119704					Hrs					
		(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
21-52-00-2100		Vapor Cycle Cooling System Hour Meter Visual Check (Airplanes Incorporating Vapor Cycle Cooling with 1134104-1 and -5 Compressor Motors)									
	21 A/F	4-12-MP						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, Airworthiness Limitations Inspection Time Limits		
						Mos	01-Jun-2021				
						Hrs	5979:13				
		MRBR Task:21-52-00-205 (ZONE: 322) (UPDATE NOTE: CRS TEXTAV DUSSELDORF 6000729) (SOURCE: 560 XL MM Section 4-10-01, 5-10-01, 5-10-02)				Ldg	3,951				
21-52-00-2101		Vapor Cycle Cooling System 500 Compressor Hour Maintenance (Airplanes Incorporating Vapor Cycle Cooling System with 1134104-1 and -5 Compressor Motors)									
	21 A/F							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos					
						Hrs					
		MRBR Task:21-52-00-201, MRBR Task:21-52-00-202, MRBR Task:21-52-00-203 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02)				Ldg					
21-52-00-2200		Vapor Cycle Cooling System 12 Month Maintenance (Airplanes Incorporating Vapor Cycle Cooling System)									
	21 A/F							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos					
						Hrs					
		MRBR Task:21-52-00-204 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02)				Ldg					
21-52-00-9600		Vapor Cycle Cooling System 500 Compressor Hour Drive Motor Brush Discard (Airplanes Incorporating Vapor Cycle Cooling System with 1134104-1 and -5 Compressor Motors)									
	21 A/F							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, Airworthiness Limitations Inspection Time Limits		
						Mos					
						Hrs					
		MRBR Task:21-52-00-901 (ZONE: 311) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02, 5-10-02, 5-18-00)				Ldg					
▼ 23 - COMMUNICATIONS											
23-10-00-7100		Crew Oxygen Mask Microphone and Switch Operational Check									
	23 A/F	Copilot5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	MC10-16-150					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	SE75654					Hrs	6582:45				
		(ZONE: 242) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,450				
23-10-00-7100		Crew Oxygen Mask Microphone and Switch Operational Check									
	23 A/F	Pilot5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	MC10-16-150EX					Mos	29-Sep-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	B124425					Hrs					
		(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
23-50-00-7100		Audio Amplifier Emergency Switch Operational Check (Airplanes -5001 thru - 6000)									
	23 A/F	5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
						Hrs	6582:45				
		(ZONE: 241, 242) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,450				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining			
23-60-00-7200		Static Discharging System Functional Check												
	23 A/F	5-12-11					Mos	28-Jun-2023	24	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS -/+1m (30-Jun-2025)	1.4 Years (+30 Days)			
							Hrs	6582:45						
							Ldg	4,450						
(ZONE: 532, 540, 632, 641, 341, 353, 354, 323) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)														
23-70-00-9600		DK120 or DK120/90 Cockpit Voice Recorder Underwater Locator Beacon Battery Discard												
	23 A/F 068E5542-00 ULB020579						Mos	20-Apr-2018	72	05-10-01, 05-10-02, 05-12-00, Category 9 31-Jan-2025	1 Year			
							Hrs	5322:30						
							Ldg	3,625						
Expiration Date 01-Jan-2025														
MRBR Task:23-70-00-901, MRBR Task:23-70-00-902 (ZONE: 312) (SOURCE: 560XL MM) (NOTE: 72 Months (DK120) Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation Dukane Seacom 03-TM-0037 (DK120) or 03-TM-0063 (DK120/90) Technical Manual Underwater Acoustic Beacon.)														
▼ 24 - ELECTRICAL POWER														
24-32-00-7200		44 Amp-Hour Marathon Ni-Cad Main Battery (Capacity Check) Functional Check												
	24 A/F S3597-8 41137879	5-12-20					Mos	RE (N/A) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS						
							Hrs							
							Ldg							
(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)														
24-32-00-7201		43 Amp-Hour Saft Ni-Cad Main Battery (Capacity Check) Functional Check												
	24 A/F S3597-8 41137879	5-12-20					Mos	RE (N/A) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS						
							Hrs							
							Ldg							
(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)														
24-32-00-7202		42 Amp-Hour Concorde Lead Acid Main Battery (Capacity Check) Functional Check												
	24 A/F S3597-8 41137879	5-12-21					Mos	28-Jun-2023	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS -/+1m 30-Jun-2024	≈20-Jun-2024 5.1 Months (+30 Days)			
							Hrs	6582:45	600					
							Ldg	4,450	146:32 Hrs (+25)					
(ZONE: 311) (Tol. Adjustment: -11d, 16.4 Hrs) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00) (NOTE: Per Supplier Recommendation. Reference Concorde Battery Corp. 24-30-71 Component Maintenance Manual. The recurring interval may be adjusted after the useful battery life is established, based on operations)														
24-32-00-7204		L3 Com PS-855B Standby Battery Pack (Capacity Check) Functional Check												
	24 A/F 501-1228-04 14485	Left5-12-01					Mos	28-Jun-2023	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS -/+1m (16-Jun-2024)	4.6 Months (+30 Days)			
							Hrs	6582:45						
							Ldg	4,450						
(ZONE: 211) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00) (NOTE: NOTE:Per Supplier Recommendation. Reference 24-30- 08 L3 Communications Component Maintenance Manual Capacity Test)														
24-32-00-7204		L3 Com PS-855B Standby Battery Pack (Capacity Check) Functional Check												
	24 A/F 501-1228-04 86175	Right5-12-01					Mos	28-Jun-2023	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS -/+1m (16-Jun-2024)	4.6 Months (+30 Days)			
							Hrs	6582:45						
							Ldg	4,450						
(ZONE: 212) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00) (NOTE: NOTE:Per Supplier Recommendation. Reference 24-30- 08 L3 Communications Component Maintenance Manual Capacity Test)														
24-41-02-7200		External Power Overvoltage System Functional Check												
	24 A/F	5-12-13					Mos	RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS -/+1m (17-Mar-2024)				47 Days (+31)		
							Hrs							
							Ldg							
(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)														

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 25 - EQUIPMENT/FURNISHINGS											
25-11-01-2200		Crew Seat Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	25 A/F	Copilot5-12-08					Mos	29-Sep-2023			
	Unknown						Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
	Unknown						Ldg	4,505			
(ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02)											
25-11-01-2200		Crew Seat Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	25 A/F	Pilot5-12-08					Mos	29-Sep-2023			
	Unknown						Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
	Unknown						Ldg	4,505			
(ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02)											
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.15-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
(ZONE: 252, 261, 262, 171)											
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.25-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)											
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.35-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)											
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.45-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)											
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.15-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)											
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.25-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)											

Task No		Description							Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.35-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
	Unknown											
	Unknown											
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.45-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
	Unknown											
	Unknown											
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-02-AQS		PREPARATION FOR COMMERCIAL OPERATION - PERFORM INSPECTION OF SIDE FACING SEATS IN ACCORDANCE WITH AMM, CMM							RE (-)			
	25 A/F											
25-22-02-AQS		PREPARATION FOR COMMERCIAL OPERATION - PERFORM INSPECTION CABIN SIDEWALL AND SIDE LEDGE IN ACCORDANCE WITH AMM, CMM AND CABIN INTERIOR MANUAL							RE (-)			
	25 A/F											
25-23-01-AQS		PREPARATION FOR COMMERCIAL OPERATION - PERFORM INSPECTION OF FWD REFRESHMENT CENTER IN ACCORDANCE AMM, CMM AND CABIN INTERIOR MANUAL							RE (-)			
	25 A/F											
25-25-01-AQS		PREPARATION FOR COMMERCIAL OPERATION - PERFORM INSPECTION OF SIDESLEDGE TABLES IN ACCORDANCE AMM, CMM AND CABIN INTERIOR MANUAL							RE (-)			
	25 A/F											
25-40-03-AQS		PREPARATION FOR COMMERCIAL OPERATION - PERFORM AFT BULKHEAD CLOSET INSPECTION IN ACCORDANCE WITH AMM, CMM AND CABIN INTERIOR MANUAL							RE (-)			
	25 A/F											
25-60-00-2200		First Aid Kit Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	5-12-01										
	Unknown						28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)	
	Unknown						6582:45					
		(ZONE: 241, 242) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2201		Smoke Goggle Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left5-12-01										
	MXP210-000						28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)	
	Unknown						6582:45					
		(ZONE: 241) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-2201		Smoke Goggle Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right5-12-01					Mos	28-Jun-2023	12	-/+1m (16-Jun-2024)	4.6 Months (+30 Days)
	Unknown						Hrs	6582:45			
	Unknown	(ZONE: 242) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,450			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Copilot					Mos				
	P1074-207						Hrs				
	18040160312	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Lavatory					Mos				
	P01074-201						Hrs				
	22070930056	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.15-12-12					Mos	28-Apr-2023	60	-/+1m (28-Apr-2028)	4.2 Years (+30 Days)
	P01074-207						Hrs	6402			
	22070930057	(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.25-12-12					Mos	28-Apr-2023	60	-/+1m (28-Apr-2028)	4.2 Years (+30 Days)
	P01074-207						Hrs	6402			
	21020120036	(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.35-12-12					Mos	28-Apr-2023	60	-/+1m (28-Apr-2028)	4.2 Years (+30 Days)
	P01074-207						Hrs	6402			
	19031750037	(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.45-12-12					Mos	28-Apr-2023	60	-/+1m (28-Apr-2028)	4.2 Years (+30 Days)
	P01074-207						Hrs	6402			
	21020120033	(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.10					Mos				
	Unknown						Hrs				
	Unknown	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.11					Mos				
	Unknown						Hrs				
	Unknown	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.9									
	Unknown										
	Unknown										
(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Pilot									
	P01074-207										
	19031750034										
(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.15-12-12									
	P01074-207						28-Apr-2023	60	-/+1m	(28-Apr-2028)	4.2 Years (+30 Days)
	21020120035							6402			
(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)								4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.25-12-12									
	PO1074-207						28-Apr-2023	60	-/+1m	(28-Apr-2028)	4.2 Years (+30 Days)
	19031750043							6402			
(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)								4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.35-12-12									
	P01074-207						28-Apr-2023	60	-/+1m	(28-Apr-2028)	4.2 Years (+30 Days)
	21020120038							6402			
(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)								4,243			
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.45-12-12									
	P01074-207						28-Apr-2023	60	-/+1m	(28-Apr-2028)	4.2 Years (+30 Days)
	22070930057							6402			
(ZONE: 251, 252, 261, 262) (UPDATE NOTE: CRS RCA 2023_11_OKCAA) (SOURCE: 560 XL MM Section 5-10-02)								4,243			
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Copilot									
	P1074-207										
	18040160312										
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02	MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Lavatory									
	P01074-201										
	22070930056										
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description					Categories		Time							
SEQ	PN/SN	MOC Note or Component Condition					TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.1								0	Mos	17-Jun-2021	120		30-Jun-2031	7.4 Years
	P01074-207										Hrs	5979:12				
	22070930057										Ldg	3,951				
	Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.2								0	Mos	17-Jun-2021	120		30-Jun-2031	7.4 Years
	P01074-207										Hrs	5979:12				
	21020120036										Ldg	3,951				
	Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.3								0	Mos	17-Jun-2021	120		30-Jun-2031	7.4 Years
	P01074-207										Hrs	5979:12				
	19031750037										Ldg	3,951				
	Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.4								0	Mos	17-Jun-2021	120		30-Jun-2031	7.4 Years
	P01074-207										Hrs	5979:12				
	21020120033										Ldg	3,951				
	Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.10									Mos					
	Unknown										Hrs					
	Unknown										Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.11									Mos					
	Unknown										Hrs					
	Unknown										Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.9									Mos					
	Unknown										Hrs					
	Unknown										Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration											RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Pilot									Mos					
	P01074-207										Hrs					
	19031750034										Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)															

Task No		Description							Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.1				0	Mos	17-Jun-2021	120	30-Jun-2031	7.4 Years
	P01074-207					0	Hrs	5979:12			
	21020120035					0	Ldg	3,951			
		Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.2				0	Mos	17-Jun-2021	120	30-Jun-2031	7.4 Years
	PO1074-207					0	Hrs	5979:12			
	19031750043					0	Ldg	3,951			
		Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.3				0	Mos	17-Jun-2021	120	30-Jun-2031	7.4 Years
	P01074-207						Hrs	5979:12			
	21020120038						Ldg	3,951			
		Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.4				0	Mos	17-Jun-2021	120	30-Jun-2031	7.4 Years
	P01074-207					0	Hrs	5979:12			
	22070930057					0	Ldg	3,951			
		Manufactured Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Copilot					Mos				
	P1074-207						Hrs				
	18040160312						Ldg				
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Lavatory					Mos				
	P01074-201						Hrs				
	22070930056						Ldg				
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Left No.1					Mos				
	P01074-207						Hrs				
	22070930057						Ldg				
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Left No.2					Mos				
	P01074-207						Hrs				
	21020120036						Ldg				
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.3					Mos				
	P01074-207						Hrs				
	19031750037						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.4					Mos				
	P01074-207						Hrs				
	21020120033						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.10					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.11					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.9					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Pilot					Mos				
	P01074-207						Hrs				
	19031750034						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.1					Mos				
	P01074-207						Hrs				
	21020120035						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.2					Mos				
	PO1074-207						Hrs				
	19031750043						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.3					Mos				
	P01074-207						Hrs				
	21020120038						Ldg				
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.4									
	P01074-207										
	22070930057										
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
25-60-00-9602		Crew Flashlight D-Cell Battery Discard							RE	05-10-01, 05-10-02, Category 8	
	25 A/F	5-12-01									
	Unknown										
	Unknown										
		MRBR Task:33-50-00-901 (ZONE: 241, 242) (Tol. Adjustment: -11d) (SOURCE: 560XL MM)									
25-60-10-7200		Artex 110-4 Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5001 thru -5500 Not Incorporating SB560XL-25-11)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F										
	453-5000-999										
	210-04997										
		(SOURCE: 560 XL MM Section 5-10-02, 5-13-00)									
25-60-10-7201		Artex 110-406 Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5501 thru -5564 and Airplanes -5002 thru -5372 Not Incorporating SB560XL-25-11)							RE (N/A)	05-10-01, 05-10-02, Category 8	
	25 A/F										
	453-5000-999										
	210-04997										
		MRBR Task:25-60-00-204, MRBR Task:25-60-00-205, MRBR Task:25-60-00-701, MRBR Task:25-60-00-703, MRBR Task:25-60-00-704 (SOURCE: 560XL MM)									
25-60-10-7202		Artex C406-2 Emergency Locator Transmitter System Detailed Inspection and Functional Test (Airplanes -5501 thru -5564 and Airplanes -5002 thru -5372 Incorporating SB560XL-25-11)							RE (N/A)	05-10-01, 05-10-02, Category 8	
	25 A/F										
	453-5000-999										
	210-04997										
		MRBR Task:25-60-00-204, MRBR Task:25-60-00-205, MRBR Task:25-60-00-206, MRBR Task:25-60-00-209, MRBR Task:25-60-00-701, MRBR Task:25-60-00-703, MRBR Task:25-60-00-704, MRBR Task:25-60-00-706 (SOURCE: 560XL MM)									
25-60-10-7203		Artex C406-N Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5565 and On)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F										
	453-5000-999										
	210-04997										
		(SOURCE: 560 XL MM Section 5-10-02, 5-13-00)									
25-60-10-9600		Emergency Locator Transmitter Battery Discard							RE	05-10-01, 05-10-02, 05-12-00, Category 8	
	25 A/F					0					
	Expiration Date 31-May-2028										
	MRBR Task:25-60-00-902 (SOURCE: 560XL MM)										
25-90-60-AQS		PREPARATION FOR COMMERCIAL OPERATION - PERFORM EMERGENCY EQUIPMENT INSPECTION IN ACCORDANCE WITH AMM AND LIST OF EMERGENCY EQUIPMENT (LOPA)							RE (-)		
	25 A/F										
	(UPDATE NOTE: CRS AEROPARTNER 2906/22 - SMOKE GOOGLES REPLACED)										
▼ 26 - FIRE PROTECTION											
26-11-00-7200		Optional Baggage Compartment and Lavatory Smoke Detection System Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	5-12-06									
	(ZONE: 235, 311) (SOURCE: 560 XL MM Section 5-10-02)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
26-20-00-2200		Left Engine Fire Deployment Check Tee Special Detailed Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F					Mos						
						Hrs						
	(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: Anytime bottle 1 or 2 of the associated Engine Fire Extinguishing System is fired)					Ldg						
26-20-00-2200		Right Engine Fire Deployment Check Tee Special Detailed Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F					Mos						
						Hrs						
	(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: Anytime bottle 1 or 2 of the associated Engine Fire Extinguishing System is fired)					Ldg						
26-21-00-7100		Left Engine Fire Extinguishing System Functional Check							RE	05-10-01, 05-10-02, Category 8, Category 9		
	26 A/F	5-12-06				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
						Hrs						
	MRBR Task:26-20-00-701, MRBR Task:26-20-00-702, MRBR Task:26-20-00-703, MRBR Task:26-20-00-704, MRBR Task:26-20-00-706, MRBR Task:26-20-00-709 (ZONE: 313, 235, 321) (SOURCE: 560XL MM)					Ldg						
26-21-00-7100		Right Engine Fire Extinguishing System Functional Check							RE	05-10-01, 05-10-02, Category 8, Category 9		
	26 A/F	5-12-06				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
						Hrs						
	MRBR Task:26-20-00-701, MRBR Task:26-20-00-702, MRBR Task:26-20-00-703, MRBR Task:26-20-00-704, MRBR Task:26-20-00-706, MRBR Task:26-20-00-709 (ZONE: 314, 235, 322) (SOURCE: 560XL MM)					Ldg						
26-21-01-7100		Engine Fire Extinguisher Aft Bottle Low Pressure Switch Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F					Mos	23-Jun-2020	60		23-Jun-2025	1.4 Years	
	Hydrostatic Tested Date 23-Jun-2020					Hrs						
	MRBR Task:26-20-00-711 (ZONE: 312) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00) (NOTE: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-20-202 Component Maintenance Manual.)					Ldg						
26-21-01-7100		Engine Fire Extinguisher Fwd Bottle Low Pressure Switch Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F					Mos	24-Jun-2020	60		24-Jun-2025	1.4 Years	
	Hydrostatic Tested Date 24-Jun-2020					Hrs						
	MRBR Task:26-20-00-711 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00) (NOTE: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-20-202 Component Maintenance Manual.)					Ldg						
26-21-01-7200		Optional Aft Vanity Fire Extinguisher Bottle (Weight Check) Functional Check (Airplanes - 6224 and On)							RE (N/A)	Regulatory Inspections/Time Limits		
	26 A/F					Mos						
	Unknown					Hrs						
	Unknown					Ldg						
		(SOURCE: 560 XL MM Section 5-13-00, 5-18-00)										
26-21-01-7800		Engine Fire Extinguisher Bottle (Hydrostatic Test) Restoration							RE	Regulatory Inspections/Time Limits		
	26 A/F	Aft				Mos	23-Jun-2020	60		30-Jun-2025	1.4 Years	
	30400037-1					Hrs						
	43839B1					Ldg						
		Hydrostatic Tested Date 23-Jun-2020										
		(SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
26-21-01-7800		Engine Fire Extinguisher Bottle (Hydrostatic Test) Restoration							RE	Regulatory Inspections/Time Limits	
	26 A/F	Fwd					Mos	24-Jun-2020	60	24-Jun-2025	1.4 Years
	30400037-1						Hrs				
	56971B1						Ldg				
		Hydrostatic Tested Date 24-Jun-2020 (SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945)									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Aft - No.1					Mos	17-Jun-2021	72	17-Jun-2027	3.4 Years
	13083-5						Hrs	5979:12			
	ESD20A782-001						Ldg	3,951			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual)									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Aft - No.2					Mos	17-Jun-2021	72	30-Jun-2027	3.4 Years
	13083-5						Hrs	5979:12			
	ESD20A783-001						Ldg	3,951			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual)									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Fwd - No.1					Mos	22-Nov-2021	72	30-Nov-2027	3.8 Years
	13083-5						Hrs	5998:30			
	Unknown						Ldg	3,965			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual)									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Fwd - No.2					Mos	22-Nov-2021	72	30-Nov-2027	3.8 Years
	13083-5						Hrs	5998:30			
	Unknown						Ldg	3,965			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual)									
26-21-01-9601		13083-5 Auxiliary Power Unit Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F						Mos	22-Nov-2021	72	30-Nov-2027	3.8 Years
	13083-5						Hrs	5998:30			
	ESD21H845-001						Ldg	3,965			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual)									
26-21-01-9602		AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE (N/A)	05-10-01, 05-10-02, Category 8	
	26 A/F	Aft - No.1					Mos				
	13083-5						Hrs				
	ESD20A782-001						Ldg				
		MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
26-21-01-9602		AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Aft - No.2				Mos					
	13083-5					Hrs					
	ESD20A783-001					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)											
26-21-01-9602		AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Fwd - No.1				Mos					
	13083-5					Hrs					
	Unknown					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)											
26-21-01-9602		AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Fwd - No.2				Mos					
	13083-5					Hrs					
	Unknown					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)											
26-21-01-9603		AE 13083-5 Auxiliary Power Unit Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F					Mos					
	13083-5					Hrs					
	ESD21H845-001					Ldg					
MRBR Task:25-20-00-904 (ZONE: 322) (SOURCE: 560XL MM)											
26-22-00-2200		Portable Fire Extinguisher Detailed and (Weight) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Cabin				Mos	16-Aug-2023	12		31-Aug-2024	7.1 Months
	C352TS					Hrs	6748:50				
	Y-690536					Ldg	4,452				
(ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02, 5-13-00) (NOTE: NOTE: Per Supplier Recommendation and/or Local Regulatory Requirement. Reference NFPA 10)											
26-22-00-2200		Portable Fire Extinguisher Detailed and (Weight) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Cockpit				Mos	16-Aug-2023	12		31-Aug-2024	7.1 Months
	C352TS					Hrs	6748:50				
	Y-690538					Ldg	4,452				
(ZONE: 262) (SOURCE: 560 XL MM Section 5-10-02, 5-13-00) (NOTE: NOTE: Per Supplier Recommendation and/or Local Regulatory Requirement. Reference NFPA 10)											
26-22-00-2201		Portable Fire Extinguisher Restoration (Internal Inspection)						RE	Regulatory Inspections/Time Limits		
	26 A/F	Cabin				Mos	17-Jun-2021	72		17-Jun-2027	3.4 Years
	C352TS					Hrs	5979:12				
	Y-690536					Ldg	3,951				
(SOURCE: 560 XL MM Section 5-13-00) (NOTE: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers)											
26-22-00-2201		Portable Fire Extinguisher Restoration (Internal Inspection)						RE	Regulatory Inspections/Time Limits		
	26 A/F	Cockpit				Mos	06-Jun-2018	72		06-Jun-2024	4.3 Months
	C352TS					Hrs	5386				
	Y-690538					Ldg	3,670				
(SOURCE: 560 XL MM Section 5-13-00) (NOTE: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers)											

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
26-22-00-7800		Portable Fire Extinguisher (Hydrostatic Test) Functional Check							RE	Regulatory Inspections/Time Limits		
	26 A/F	Cabin					Mos	06-Jun-2018	72	30-Jun-2024	5.1 Months	
	C352TS						Hrs	5386				
	Y-690536						Ldg	3,670				
	31-Jan-2014											
(SOURCE: 560 XL MM Section 5-13-00)												
26-22-00-7800		Portable Fire Extinguisher (Hydrostatic Test) Functional Check							RE	Regulatory Inspections/Time Limits		
	26 A/F	Cockpit					Mos	06-Jun-2018	72	30-Jun-2024	5.1 Months	
	C352TS						Hrs	5386				
	Y-690538						Ldg	3,670				
	31-Jan-2014											
(SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers)												
26-23-00-7100		Auxiliary Power Unit Fire Extinguishing System Operational and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	5-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)	
							Hrs					
							Ldg					
	(ZONE: 235, 313) (SOURCE: 560 XL MM Section 5-10-02)											
26-23-00-7101		Auxiliary Power Unit Fire Extinguisher Bottle Low Pressure Switch Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Hydrostatic Tested Date 01-Oct-2021 (ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-22-202 Component Maintenance Manual.)					Mos	01-Oct-2021	60	01-Oct-2026	2.7 Years	
							Hrs					
							Ldg					
26-23-00-7800		APU Fire Extinguisher Bottle (Hydrostatic Test) Restoration							RE	Regulatory Inspections/Time Limits		
	26 A/F	30100033-7 37250A1 Hydrostatic Tested Date 01-Oct-2021 (SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945)					Mos	01-Oct-2021	60	31-Oct-2026	2.8 Years	
							Hrs					
							Ldg					
▼ 27 - FLIGHT CONTROLS												
12-20-27-6401		Trim Actuators Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	27 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m (16-Jun-2024)	4.6 Months (+30 Days)	
							Hrs	6582:45				
							Ldg	4,450				
	(ZONE: 340, 351, 352, 532) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended to do this task at the same time as Tasks 27-10-00-2202 and 27-20-00-2201.)											
12-20-27-6403		Horizontal Stabilizer Scissor Fitting Bolts and Aft Pivot Bolts Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	27 A/F	5-12-03					Mos	11-Jul-2023	24	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)	
							Hrs	6620:35				
							Ldg	4,370				
	(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)											
27-10-00-2201		Aileron Left Wing Cable Detailed Inspection (Airplanes -5556 and On, and Airplanes -5002 thru - 5555 Incorporating SB560XL-27-22)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023		-/+25 (9209)	2156:20 Hrs (+25)	
							Hrs	6839:30				
							Ldg	4,505				
	(ZONE: 313, 314, 512, 522, 532) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2203)											

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
27-10-00-2201		Aileron Right Wing Cable Detailed Inspection (Airplanes -5556 and On, and Airplanes -5002 thru - 5555 Incorporating SB560XL-27-22)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
		(ZONE: 612, 622, 632) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2203)					Ldg	4,505			
27-10-00-2202		Aileron Trim Actuator Detailed Inspection							RE	05-10-01, 05-10-02, Category 6	
	27 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024) 4.6 Months (+30 Days)
	Unknown						Hrs	6582:45			
	Unknown	MRBR Task:27-10-00-208 (ZONE: 532) (Tol. Adjustment: -11d) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended to do this task at the same time as Tasks 12-20-27-6401 and 27-20-00-2201.)					Ldg	4,450			
27-10-00-2203		Aileron and Aileron Trim Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
		(ZONE: 141,153,163,165,236,241,242,313,512,522,532,534) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2201)					Ldg	4,505			
27-10-00-7201		Aileron Trim Tab and Pushrod (Free Play) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Dec-2027
	27 A/F	5-12-07					Mos	29-Sep-2023			
							Hrs	6839:30	1,600	-/+25	(8439:30) 1386:50 Hrs (+25)
		(ZONE: 532) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,505			
27-20-00-2200		Rudder Bias Cable Assembly Detailed Inspection (Airplanes - 5001, -5044, -5052, -5085, -5088 and On. And Airplanes -5002 thru -5043, -5045 thru -5051, -5053 thru -5084 and -5086 thru - 5087 Incorporating SB560XL-27-06)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
		(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,505			
27-20-00-2201		Rudder Trim Actuator Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	27 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024) 4.6 Months (+30 Days)
	Unknown						Hrs	6582:45			
	Unknown	(ZONE: 340) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended to do this task at the same time as Tasks 12-20-27-6401 and 27-10-00-2202)					Ldg	4,450			
27-20-00-2202		Rudder and Rudder Trim Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
		(ZONE: 241, 242, 251, 252, 263, 264, 321, 322, 340, 341) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,505			
27-20-00-7201		Rudder Trim Actuator and Pushrod (Free Play) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Dec-2027
	27 A/F	5-12-07					Mos	29-Sep-2023			
							Hrs	6839:30	1,600	-/+25	(8439:30) 1386:50 Hrs (+25)
		(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,505			
27-31-00-2200		Elevator and Trim Tab System Detailed Inspection							RE	05-10-01, 05-10-02, Category 5, Category 6	
	27 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025) 1.4 Years (+30 Days)
							Hrs				
		MRBR Task:27-30-00-204, MRBR Task:27-30-00-205, MRBR Task:27-30-00-208, MRBR Task:27-30-00-211, MRBR Task:27-30-00-212 (ZONE: 241, 242, 141, 353, 354, 142, 340) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-30-00-2200 and 55-20-00-2200)					Ldg				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
27-31-00-2201		Elevator and Elevator Trim Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023				
							Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
			(ZONE: 340,322,141,151,163,165,313,321,236,161,171,311) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,505				
27-31-00-7201		Elevator Trim Tab and Pushrod (Free Play) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈04-Dec-2027
	27 A/F	5-12-07					Mos	29-Sep-2023				
							Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
			(ZONE: 353, 354) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,505				
27-40-00-7200		Two-Position Horizontal Stabilizer Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023				
							Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
			(ZONE: 252, 340) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,505				
27-51-00-2200		Flap Cables Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	27 A/F	5-12-08					Mos	29-Sep-2023				
							Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
			(ZONE: 514, 614, 241) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,505				
27-71-00-7100		Control (Gust) Lock System Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	27 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
							Hrs	6582:45				
							Ldg	4,450				
57-50-00-2200		Left Speed Brake Panels and Attachment Fittings Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	27 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs					
			(ZONE: 522) (SOURCE: 560 XL MM Section 5-10-03)				Ldg					
57-50-00-2200		Right Speed Brake Panels and Attachment Fittings Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	27 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs					
			(ZONE: 622) (SOURCE: 560 XL MM Section 5-10-03)				Ldg					
▼ 28 - FUEL												
28-00-02-2200		Microbiological Contamination Inspection (Airplanes Not Using the Biocidal Preventative Treatment)							RE (N/A)		Discretionary Maintenance	
	28 A/F						Mos					
							Hrs					
			Ref:Chapter 28, Fuel Contamination - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)				Ldg					
28-00-02-2201		Microbiological Contamination Inspection (Airplanes Using the Biocidal Preventative Treatment)							RE (N/A)		Discretionary Maintenance	
	28 A/F						Mos	23-Nov-2020				
							Hrs					
			Ref:Chapter 28, Fuel Contamination - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)				Ldg					
28-11-04-2200		Fuel Filler Cap Detailed Inspection and Lubrication							RE			05-10-01, 05-10-02, Category 9
	28 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
							Hrs	6582:45				
			MRBR Task:28-10-00-601, MRBR Task:28-10-00-201 (ZONE: 531) (Tol. Adjustment: -11d) (SOURCE: 560XL MM)				Ldg	4,450				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
28-11-04-2200		Fuel Filler Cap Detailed Inspection and Lubrication						RE	05-10-01, 05-10-02, Category 9		
	28 A/F	5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		MRBR Task:28-10-00-601, MRBR Task:28-10-00-201 (ZONE: 631) (Tol. Adjustment: -11d) (SOURCE: 560XL MM)				Hrs	6582:45				
						Ldg	4,450				
28-42-00-7100		Fuel Low Level Float Switch Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	28 A/F	5-12-06				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 57-00-00-2101 and 57-00-00-2102)				Hrs					
						Ldg					
▼ 29 - HYDRAULIC POWER											
29-11-04-9600		Hydraulic System Filters Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	29 A/F	5-12-13				Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		(ZONE: 313) (SOURCE: 560 XL MM Section 5-10-02)				Hrs					
						Ldg					
▼ 30 - ICE AND RAIN PROTECTION											
30-11-00-7100		Bleed Air Anti-Ice Systems Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	30 A/F	5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		(ZONE: 162, 235) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	6582:45				
						Ldg	4,450				
30-12-00-7100		Horizontal Stabilizer Deice System Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	30 A/F	5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		(ZONE: 311, 312, 321, 322, 340) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	6582:45				
						Ldg	4,450				
▼ 31 - INDICATING / RECORDING SYSTEM											
31-20-01-9600		Left Digital Clock AA Long Life Battery Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	31 A/F	Left5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	M877A5V					Hrs	6582:45				
	Unknown					Ldg	4,450				
		(ZONE: 235) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)									
31-20-01-9600		Right Digital Clock AA Long Life Battery Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	31 A/F	Right5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	M877A5V					Hrs	6582:45				
	Unknown					Ldg	4,450				
		(ZONE: 235) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)									
31-30-04-9600		DK120 or DK120/90 Flight Data Recorder Underwater Locator Beacon Battery Discard						RE	05-10-01, 05-10-02, 05-12-00, Category 9		
	31 A/F					0	10-Jul-2018	72		30-Jun-2024	5.1 Months
	810-2008/K					Hrs	5400:36				
	Unknown					Ldg	3,678				
		Expiration Date 01-Jun-2024									
		MRBR Task:31-30-00-901, MRBR Task:31-30-00-902, MRBR Task:31-31-00-902, MRBR Task:31-31-00-901 (SOURCE: 560XL MM) (NOTE: 72 Months (DK120) Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation. Reference L3 Communications FA2100FDR Component Maintenance Manual or the Dukane Seacom 03-TM-0037 (DK120) Technical Manual)									

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	DUE	Remaining
▼ 32 - LANDING GEAR												
32-00-00-2101		Left Main Landing Gear Door General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs					
			(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100)				Ldg					
32-00-00-2101		Nose Landing Gear Door General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs					
			(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100)				Ldg					
32-00-00-2101		Right Main Landing Gear Door General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs					
			(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100)				Ldg					
32-00-00-7100		Landing Gear System General Visual Inspection, Operational Check and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs					
			(ZONE: 211, 235,313, 710, 720, 730) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 53-10-00-2100, and 57-10-00-2100)				Ldg					
32-10-00-2200		Left Main Landing Gear Detailed Inspection							RE	05-10-01, 05-10-02, Category 5, Category 6		≈25-Jan-2030
	32 A/F	5-12-08					Mos	29-Sep-2023				
							Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
			MRBR Task:32-10-00-201, MRBR Task:32-10-00-202, MRBR Task:32-10-00-203, MRBR Task:32-10-00-204, MRBR Task:32-10-00-205 (ZONE: 720) (SOURCE: 560XL MM)				Ldg	4,505				
32-10-00-2200		Right Main Landing Gear Detailed Inspection							RE	05-10-01, 05-10-02, Category 5, Category 6		≈25-Jan-2030
	32 A/F	5-12-08					Mos	29-Sep-2023				
							Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
			MRBR Task:32-10-00-201, MRBR Task:32-10-00-202, MRBR Task:32-10-00-203, MRBR Task:32-10-00-204, MRBR Task:32-10-00-205 (ZONE: 730) (SOURCE: 560XL MM)				Ldg	4,505				
32-10-00-9600		Main Landing Gear Oleo Breather Vent Discard (If Installed)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	Left					Mos					
							Hrs					
			Unknown				Ldg					
		Unknown										
		(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02)										
32-10-00-9600		Main Landing Gear Oleo Breather Vent Discard (If Installed)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	Right					Mos					
							Hrs					
							Ldg					
		Unknown										
		Unknown										
		(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02)										
32-20-00-2200		Nose Landing Gear Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	32 A/F	5-12-08					Mos	29-Sep-2023				
							Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
			(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	4,505				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-30-09-7800		Emergency Gear Extension/Brake Pneumatic Storage Bottle (Hydrostatic Test) Restoration						RE	Regulatory Inspections/Time Limits		
	32 A/F	40005347-3 7388 Hydrostatic Tested Date 17-Jun-2021 (SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation: US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The pneumatic storage bottle is manufactured under U.S. DOT 3HT)				Mos	17-Jun-2021	36		30-Jun-2024	5.1 Months
						Hrs	5979:12				
						Ldg	3,951				
32-40-00-2200		Main Landing Gear Brakes Detailed Inspection, Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check						RE (A/R)	05-10-01, 05-10-02, Category 6		
	32 A/F	Left 2-1601-1 0730 MRBR Task:32-40-00-203, MRBR Task:32-41-00-201, MRBR Task:32-42-00-201, MRBR Task:32-41-00-701, MRBR Task:32-42-00-701, MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 720) (SOURCE: 560XL MM) (NOTE: Every Wheel Removal)				Mos	20-Apr-2018				
						Hrs	5322:30				
						Ldg	3,625				
32-40-00-2200		Main Landing Gear Brakes Detailed Inspection, Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check						RE (A/R)	05-10-01, 05-10-02, Category 6		
	32 A/F	Right 2-1601-1 2112 MRBR Task:32-40-00-203, MRBR Task:32-41-00-201, MRBR Task:32-42-00-201, MRBR Task:32-41-00-701, MRBR Task:32-42-00-701, MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 730) (SOURCE: 560XL MM) (NOTE: Every Wheel Removal)				Mos					
						Hrs					
						Ldg					
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈04-Dec-2027
	32 A/F	Left Inboard5-12-07 98281-3 528 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)				Mos	29-Sep-2023				
						Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
						Ldg	4,505				
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈04-Dec-2027
	32 A/F	Left Outboard5-12-07 98281-3 1046 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)				Mos	29-Sep-2023				
						Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
						Ldg	4,505				
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈04-Dec-2027
	32 A/F	Right Inboard5-12-07 98281-4 542 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)				Mos	29-Sep-2023				
						Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
						Ldg	4,505				
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈04-Dec-2027
	32 A/F	Right Outboard5-12-07 98281-4 546 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)				Mos	29-Sep-2023				
						Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
						Ldg	4,505				
32-40-00-2202		Emergency Brake System Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Jan-2030
	32 A/F	5-12-08 (ZONE: 211, 235, 720, 730) (SOURCE: 560 XL MM Section 5-10-02)				Mos	29-Sep-2023				
						Hrs	6839:30	2,400	-/+25	(9209)	2156:20 Hrs (+25)
						Ldg	4,505				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-40-00-2203		Nose Landing Gear Axle General Visual Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos				
							Hrs				
	MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 710) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00) (NOTE: Every Wheel Removal)						Ldg				
32-40-00-7100		Emergency Brake System Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25 (9209)	2156:20 Hrs (+25)
	(ZONE: 211, 235) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	4,505			
32-40-00-9600		Brake System Filters Discard (Airplanes -5001 thru -5500)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25 (9209)	2156:20 Hrs (+25)
	(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	4,505			
32-40-00-9601		Power Brake and Antiskid Filter Element Discard (Airplanes -5501 and On)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos				
							Hrs				
	(ZONE: 165) (SOURCE: 560 XL MM Section 5-10-02)						Ldg				
32-41-00-2101		Optional Nose Wheel Spin Up General Visual Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos				
							Hrs				
	(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00) (NOTE: Every Wheel Removal)						Ldg				
32-41-00-2200		Left Main Landing Gear Wheel and Tire Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	32 A/F						Mos	03-Sep-2022	24	-/+1m [17-Jun-2024]	4.6 Months (+30 Days)
							Hrs	5999:12			
	(ZONE: 720) (UPDATE NOTE: CRS AEROPARTNER 2906/22) (SOURCE: 560 XL MM Section 5-10-01, 5-10-03, 5-12-00) (NOTE: Every Wheel Removal not to Exceed 24 Months)						Ldg	3,967			
32-41-00-2200		Right Main Landing Gear Wheel and Tire Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	32 A/F						Mos	03-Sep-2022	24	-/+1m [17-Jun-2024]	4.6 Months (+30 Days)
							Hrs	5999:12			
	(ZONE: 730) (UPDATE NOTE: CRS AEROPARTNER 2906/22) (SOURCE: 560 XL MM Section 5-10-01, 5-10-03, 5-12-00) (NOTE: Every Wheel Removal not to Exceed 24 Months)						Ldg	3,967			
32-41-00-2800		Nose Landing Gear Wheel (Eddy Current) Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos				
	3-1418						Hrs				
	7640						Ldg				
		(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-47-42 Component Maintenance Manual)									
32-41-00-2801		Main Landing Gear Wheel (Eddy Current) Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos	06-Jun-2018			
	3-1571-6						Hrs	5386:06			
	0493						Ldg	3,670			
		(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-45-48 Component Maintenance Manual)									

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
32-41-00-2801		Main Landing Gear Wheel (Eddy Current) Special Detailed Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	Right					Mos					
	3-1571-6						Hrs					
	1865						Ldg					
	(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-45-48 Component Maintenance Manual)											
32-41-00-7200		Optional Nose Wheel Spin up Functional Check							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos					
							Hrs					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00) (NOTE: Every Wheel Removal)						Ldg					
32-50-00-2200		Steering System Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
							Hrs					
	(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 32-50-00-7200)						Ldg					
32-50-00-7200		Steering Cable System Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
							Hrs					
	(ZONE: 710, 241, 242) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 32-50-00-2200)						Ldg					
CAA-230123-003		NOSE LANDING GEAR CLOSE TO BE WORN							N/N (-)			Squawk, -
	32 A/F						Mos	25-Jan-2023				
	Open						Hrs	6225:20				
	(Date reported: 23-Jan-2023), (Reported by: KALLISTA, Title: Pilot)(Classification date: 19-Jan-2023), (Recorded by: KASIK, Title: CAMO)						Ldg	4,126				
▼ 33 - LIGHTS												
33-40-00-7200		Tail Light Assembly (NAV-LED 72 segment) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	5-12-03					Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown						Hrs	6620:35				
	Unknown						Ldg	4,370				
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: -5001 and On Incorporating NAV-LED 72 Segment Tail Light Assembly)												
33-50-00-7100		Emergency Lighting System Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	5-12-03					Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
							Hrs	6620:35				
	(ZONE: 166, 241, 251, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	4,370				
33-50-00-7200		Emergency Battery Pack (Capacity Check) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	Aft5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	9913-1						Hrs	6582:45				
	2232						Ldg	4,450				
MRBR Task:33-50-00-701 (ZONE: 261, 262) (Tol. Adjustment: -11d) (SOURCE: 560XL MM Section 5-10-01, 5-10-02, 5-12-01)												
33-50-00-7200		Emergency Battery Pack (Capacity Check) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	Fwd5-12-01					Mos	11-Jul-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	9913-1 EX						Hrs	6620:35				
	2788						Ldg	4,370				
MRBR Task:33-50-00-701 (ZONE: 251, 252) (SOURCE: 560XL MM Section 5-10-01, 5-10-02, 5-12-01)												

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
33-50-00-9600		Emergency Lighting Battery Pack Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Inspection Documents		
	33 A/F	Aft					Mos	48	-/+1m	17-Jun-2025	1.4 Years (+30 Days)	
	9913-1						Hrs					
	2232						Ldg					
Restored Date 17-Jun-2021												
(SOURCE: 560 XL MM Section 5-10-01, 5-12-00) (NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored emergency lighting battery pack and/or refer to Avtech Emergency Battery Pack Component Maintenance Manual, 33-50-01.)												
33-50-00-9600		Emergency Lighting Battery Pack Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Inspection Documents		
	33 A/F	Fwd					Mos	11-Jul-2023	48	-/+1m	11-Jul-2027 3.4 Years (+31 Days)	
	9913-1 EX						Hrs	6620:35				
	2788						Ldg	4,370				
Restored Date 11-Jul-2023												
(SOURCE: 560 XL MM Section 5-10-01, 5-12-00) (NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored emergency lighting battery pack and/or refer to Avtech Emergency Battery Pack Component Maintenance Manual, 33-50-01.)												
▼ 34 - NAVIGATION												
23-90-20-7200		Transponder Functional Check (Airplanes -5001 thru -6000)							RE	Regulatory Inspections/Time Limits		
	34-52 A/F						Mos	22-Jun-2022	24		30-Jun-2024 5.1 Months	
	11-01997-00						Hrs	5998:42				
	20S12180						Ldg	3,966				
(UPDATE NOTE: TRANSPONDER ATC GARMIN GTX3000 INSTALLED PER EASA STC 10069146 ADS-B OUT (ELLIOT FAA STC ST0242CH CRS AEROPARTNER 2206/22) (SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation: 14 CFR Part 91.413)												
23-90-20-7200		Transponder Functional Check (Airplanes -5001 thru -6000)							RE	Regulatory Inspections/Time Limits		
	34-52 A/F	No.1					Mos	22-Jun-2022	24		30-Jun-2024 5.1 Months	
	011-01997-00						Hrs	5998:42				
	20S012015						Ldg	3,966				
(UPDATE NOTE: TRANSPONDER ATC GARMIN GTX3000 INSTALLED PER EASA STC 10069146 ADS-B OUT (ELLIOT FAA STC ST0242CH CRS AEROPARTNER 2206/22) (SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation: 14 CFR Part 91.413)												
24-32-00-7203		L3 Com PS-835D Standby Battery Pack (Capacity Check) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	34 A/F	Left5-12-01					Mos	28-Jun-2023	12	-/+1m	30-Jun-2024 5.1 Months (+30 Days)	
	501-1228-04						Hrs	6582:45				
	14485						Ldg	4,450				
(ZONE: 211) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00) (NOTE: Note: IAW the manufacture instructions)												
24-32-00-7203		L3 Com PS-835D Standby Battery Pack (Capacity Check) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	34 A/F	Right5-12-01					Mos	28-Jun-2023	12	-/+1m	30-Jun-2024 5.1 Months (+30 Days)	
	501-1228-04						Hrs	6582:45				
	86175						Ldg	4,450				
(ZONE: 212) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00) (NOTE: NOTE:Per Supplier Recommendation. Reference 24-30- 04 L3 Communications Component Maintenance Manual Capacity Test)												
24-32-00-7205		Securaplane Standby Battery (Energy Level Test) Functional Check							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	34 A/F	Left					Mos					
	501-1228-04						Hrs					
	14485						Ldg					
(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)												

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
24-32-00-9600		Securaplane Battery Discard							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	34 A/F	Left					Mos					
	501-1228-04						Hrs					
	14485						Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
34-53-07-7200		Transponder System Functional Check (Airplanes -6001 and On)							RE (N/A)	Regulatory Inspections/Time Limits		
	34 A/F						Mos					
	011-01997-00						Hrs					
	20S012015						Ldg					
	(SOURCE: 560 XL MM Section 5-13-00)											
34-53-07-7200		Transponder System Functional Check (Airplanes -6001 and On)							RE (N/A)	Regulatory Inspections/Time Limits		
	34 A/F						Mos					
	11-01997-00						Hrs					
	20S12180						Ldg					
	(SOURCE: 560 XL MM Section 5-13-00)											
34-90-10-7200		Pitot-Static System Functional Check (Airplanes -5001 thru -6000)							RE	Regulatory Inspections/Time Limits		
	34 A/F						Mos	22-Jun-2022	24	30-Jun-2024	5.1 Months	
							Hrs	5998:35				
							Ldg	3,996				
	(SOURCE: 560 XL MM Section 5-13-00) (NOTE: Regulation: 14 CFR 91.411, 91.413 and RVSM certification. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes)											
34-90-12-7200		Pitot-Static System Functional Check (Airplanes -6001 and On)							RE (N/A)	Regulatory Inspections/Time Limits		
	34 A/F						Mos					
							Hrs					
							Ldg					
	(SOURCE: 560 XL MM Section 5-13-00)											
965-0976-040 DATABASE UPDATE		EGPWS DATABASE UPDATE							RE (-)			
	34 A/F						Mos	23-Oct-2023		[10-Apr-2024]	71 Days	
							Hrs	6883:40				
							Ldg	4,537				
	(UPDATE NOTE: DB634)											
FMS DATABASE		FMS DATABASE EXPIRATION							RE (-)			
	34 A/F						Mos	05-Jul-2023				
							Hrs					
							Ldg					
	(UPDATE NOTE: PERFORMED BY CREW)											
▼ 35 - OXYGEN												
35-10-00-2200		Crew Mask and Stowage Boxe Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	Copilot5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
	Unknown						Hrs					
	Unknown						Ldg					
	(ZONE: 245) (SOURCE: 560 XL MM Section 5-10-02)											
35-10-00-2200		Crew Mask and Stowage Boxe Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	Pilot5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)	
	Unknown						Hrs					
	Unknown						Ldg					
	(ZONE: 246) (SOURCE: 560 XL MM Section 5-10-02)											

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
35-10-00-9600		MC10-16-150, MC10-16-100 or MLD20- 505 Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration							RE	05-10-01, 05-10-02, Category 8	
	35 A/F	Copilot				2	Mos	21-Mar-2019	72	31-Jan-2025	1 Year
	MC10-16-150						Hrs	5618:12			
	SE75654						Ldg	2,783			
	Restored Date 31-Jan-2019										
		MRBR Task:35-10-00-901, MRBR Task:35-10-00-902 (ZONE: 245) (SOURCE: 560XL MM) (NOTE: Tracked by Component Time Limits. NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored MC10-16-150, MC10-16-100, or MLD20-505 Crew Mask and/or reference EROS (Intertechnique) 35-13-63 (MC10- 16-150 and MC10-16-100) and 35-13-64 (MLD20-505) Component Maintenance Manual and IPL)									
35-10-00-9600		MC10-16-150, MC10-16-100 or MLD20- 505 Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration							RE	05-10-01, 05-10-02, Category 8	
	35 A/F	Pilot				0	Mos	29-Sep-2023	72	30-Sep-2029	5.7 Years
	MC10-16-150EX						Hrs				
	B124425						Ldg				
	Restored Date 29-Sep-2023										
		MRBR Task:35-10-00-901, MRBR Task:35-10-00-902 (ZONE: 246) (SOURCE: 560XL MM) (NOTE: Tracked by Component Time Limits. NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored MC10-16-150, MC10-16-100, or MLD20-505 Crew Mask and/or reference EROS (Intertechnique) 35-13-63 (MC10- 16-150 and MC10-16-100) and 35-13-64 (MLD20-505) Component Maintenance Manual and IPL)									
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	35 A/F	No.15-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
	(ZONE: 171) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200)										
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	35 A/F	No.25-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
	(ZONE: 172) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200)										
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	35 A/F	No.35-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
	(ZONE: 251) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200)										
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	35 A/F	No.45-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
	(ZONE: 252) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200)										
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	35 A/F	No.55-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)
	Unknown						Hrs				
	Unknown						Ldg				
	(ZONE: 261) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection									
	35 A/F	No.65-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Hrs					
	(ZONE: 262) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200)					Ldg					
35-20-00-7100		Passenger Oxygen System Operational Check									
	35 A/F	5-12-03						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs	6620:35				
	(ZONE: 171, 172, 235, 251, 252, 261, 262, 235) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,370				
35-20-00-7200		Passenger Oxygen System Functional Check									
	35 A/F	5-12-06						RE	05-10-01, 05-10-02, Category 8, Category 9		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
	MRBR Task:21-30-00-702, MRBR Task:35-10-00-704, MRBR Task:35-10-00-705, MRBR Task:35-10-00-706, MRBR Task:35-10-00-707 (ZONE: 171, 172, 235, 251, 252, 261, 262) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Task 35-20-00-2200)					Ldg					
35-30-00-2200		Optional Protective Breathing Equipment Detailed Inspection									
	35 A/F							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	DP3113(A)					Mos	03-Sep-2022				
	MR-10051N					Hrs	5999:12				
	(ZONE: 245) (UPDATE NOTE: CRS AEROPARTNER 2906/22) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	3,967				
35-90-00-7800		Oxygen Bottle Assembly (Hydrostatic Test) Restoration									
	35 A/F							RE	Regulatory Inspections/Time Limits		
	804882-14					Mos	25-Jun-2021	60		25-Jun-2026	2.4 Years
	ALT281-34942					Hrs					
	Hydrostatic Tested Date 25-Jun-2021 (SOURCE: 560 XL MM Section 5-13-00) (NOTE: NOTE: The Oxygen Bottle Assembly is manufactured Under U.S. DOT-SP 8162.)					Ldg					
35-90-00-7801		Portable Oxygen Bottle Assembly (Hydrostatic Test) Restoration									
	35 A/F							RE (N/A)	Regulatory Inspections/Time Limits		
	Unknown					Mos					
	Unknown					Hrs					
	(SOURCE: 560 XL MM Section 5-13-00) (NOTE: NOT APPLICABLE)					Ldg					
▼ 36 - PNEUMATIC											
36-11-03-2100		Precooler Heat Exchanger General Visual Inspection									
	36 A/F	Left5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	2340594-6					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	302					Hrs	6582:45				
	(ZONE: 411) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,450				
36-11-03-2100		Precooler Heat Exchanger General Visual Inspection									
	36 A/F	Right5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	Unknown					Hrs	6582:45				
	(ZONE: 412) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	4,450				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
36-12-00-2200		Auxiliary Power Unit Bleed Air Check Valve Detailed Inspection									
	36 A/F	5-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
36-15-00-1700		Particulate Trap (Cleaning) Restoration									
	36 A/F	5-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 171, 261) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
▼ 38 - WATER/WASTE											
38-30-02-2200		Externally Serviceable Toilet System Detailed Inspection									
	38 A/F	5-12-03						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Hrs	6620:35				
		(ZONE: 172, 170, 315) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 53-10-11-2200)				Ldg	4,370				
▼ 49 - AIRBORNE AUXILIARY POWER											
49-00-00-2100		Auxiliary Power Unit General Visual Inspection and Operational Check									
	49 A/F	5-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200)				Ldg					
49-00-00-2103		Auxiliary Power Unit Containment Box Assembly General Visual Inspection									
	49 A/F	5-12-13						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		(ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
490020		CHANGE OIL BRAND - PERFORM TRANSFER FROM OIL 2380 TO MOBILJET (APU)									
	49 APU1							RE (-)			
						Mos	23-Oct-2023				
						Hrs	1944				
49-30-00-9600		Auxiliary Power Unit Fuel Filter Element Discard									
	49 APU1							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos	29-Sep-2023	24		30-Sep-2025	1.7 Years
		MRBR Task:49-01-00-901 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.)				Hrs	1944	900		2844	815 Hrs
						APUS	4,216				
49-40-00-2200		Auxiliary Power Unit Igniter Plug Detailed Inspection									
	49 APU1							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	304634-2					Mos	29-Sep-2023	24		30-Sep-2025	1.7 Years
	2H12					Hrs	1944	900		2844	815 Hrs
		MRBR Task:49-01-00-201 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)				APUS	4,216				
49-70-01		APU CHIP DETECTOR INSPECTION									
	49 A/F							RE			≈21-Sep-2024
						Mos	29-Sep-2023	12		29-Sep-2024	8.1 Months
						Hrs	6839:30	450	-/+25	7289:30	236:50 Hrs (+25)
						Ldg	4,505				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
49-70-01-2200		Auxiliary Power Unit Magnetic Chip Collector Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	49 APU1						Mos	29-Sep-2023	12		8.1 Months	
		MRBR Task:49-01-00-202 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.)					Hrs	1944	450	30-Sep-2024	365 Hrs	
							APUS	4,216		2394		
49-90-00-9600		Auxiliary Power Unit Oil and Oil Filter Discard							RE	05-10-01, 05-10-02, Category 9		
	49 APU1						Mos	29-Sep-2023	24	30-Sep-2025	1.7 Years	
		MRBR Task:49-01-00-904 (SOURCE: 560XL MM) (NOTE: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.)					Hrs	1944	900	2844	815 Hrs	
							APUS	4,216				
▼ 52 - DOORS												
12-20-52-6401		Door Keyed Cam Lock Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	52 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m (16-Jun-2024)	4.6 Months (+30 Days)	
		(ZONE: 211, 212, 323, 331, 810, 811, 831) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)					Hrs	6582:45				
							Ldg	4,450				
52-10-00-2100		Cabin Door Seals General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	52 A/F	5-12-01					Mos	28-Jun-2023	12	-/+1m (16-Jun-2024)	4.6 Months (+30 Days)	
		(ZONE: 810) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)					Hrs	6582:45				
							Ldg	4,450				
52-10-00-2200		Cabin Door Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Structures Inspection Tasks		
	52 A/F	5-12-06					Mos		48	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)	
		(ZONE: 810, 811) (SOURCE: 560 XL MM Section 5-10-02, 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 12-20-52-6400)					Hrs					
							Ldg					
52-10-00-2200		Cabin Door Assembly Detailed Inspection.							RE	Airworthiness Limitations Inspection Time Limits		≈09-Mar-2046
	52 A/F	4-12-ME					Mos					
		(ZONE: 810, 811) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000		(15000)	7947:20 Hrs	
							Ldg					
52-20-00-2200		Emergency Exit Door Assembly Detailed Inspection and Operational Check							RE	05-10-01, 05-10-02, Category 6, Category 8, Category 9		
	52 A/F	5-12-03					Mos	11-Jul-2023	24	-/+1m (17-Jun-2025)	1.4 Years (+30 Days)	
		MRBR Task:52-20-00-201, MRBR Task:52-20-00-202, MRBR Task:52-20-00-203, MRBR Task:52-20-00-701, MRBR Task:52-20-00-702 (ZONE: 820, 821) (SOURCE: 560XL MM)					Hrs	6620:35				
							Ldg	4,370				
52-20-00-2200		Emergency Exit Door Assembly Detailed Inspection and Operational Check							RE	04-10-01, 04-10-02, Airworthiness Limitations Inspection Time Limits, Category 6, Category 8, Category 9		≈09-Mar-2046
	52 A/F	4-12-ME					Mos					
		MRBR Task:52-20-00-201, MRBR Task:52-20-00-202, MRBR Task:52-20-00-203, MRBR Task:52-20-00-701, MRBR Task:52-20-00-702 (ZONE: 820, 821) (SOURCE: 560XL MM)					Hrs	15,000		(15000)	7947:20 Hrs	
							Ldg					
52-20-00-2201		Emergency Exit Door Internal Detailed Inspection							RE	MSG-3 Structures Inspection Tasks		
	52 A/F	5-12-16					Mos		96	-/+1m (31-Mar-2024)	61 Days (+30)	
		(ZONE: 820) (SOURCE: 560 XL MM Section 5-10-03)					Hrs					
							Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
52-30-00-2200		Baggage Door Assembly Detailed Inspection									
	52 A/F	5-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 830, 831) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
▼ 53 - FUSELAGE											
53-00-00-2100		Left Fuselage Fairing Internal Zonal General Visual Inspection									
	53 A/F	5-12-06						RE	MSG-3 Zonal Inspection Tasks		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:53-100-03 (ZONE: 153, 163, 165, 313) (SOURCE: 560 XL MM Section 5-10-04)				Ldg					
53-00-00-2100		Right Fuselage Fairing Internal Zonal General Visual Inspection									
	53 A/F	5-12-06						RE	MSG-3 Zonal Inspection Tasks		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:53-100-03 (ZONE: 154, 164, 166, 314) (SOURCE: 560 XL MM Section 5-10-04)				Hrs					
						Ldg					
53-00-00-2101		Fuselage and Fairing External Zonal General Visual Inspection									
	53 A/F	5-12-06						RE	MSG-3 Zonal Inspection Tasks		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:53-200-03, MRBR Task:53-100-05 (ZONE: 155, 167, 169, 315, 156, 168, 170, 316) (SOURCE: 560XL MM) (NOTE: Zones Cont: 111, 143, 144, 213, 214, 223, 224, 253, 254, 263, 264, 153, 154, 163, 164, 165, 166, 263, 264. NOTE: It is recommended you do this task at the same time as Task 53-00-00-2201)				Hrs					
						Ldg					
53-00-00-2102		Communication and Navigation Antenna Mounting Corrosion General Visual Inspection									
	53 A/F	5-12-06						RE	05-10-01, 05-10-03		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:53-20-01-002 (ZONE: 263, 264) (SOURCE: 560XL MM) (NOTE: This is a CPCP Task)				Hrs					
						Ldg					
53-00-00-2201		Forward and Aft Lower Fairing External L/HIRF Detailed Inspection									
	53 A/F	5-12-06						RE	MSG-3 L/HIRF Inspection Tasks		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 155, 156, 315, 316) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Task 53-00-00-2101)				Hrs					
						Ldg					
53-10-00-2100		Nose Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection									
	53 A/F	5-12-06						RE	MSG-3 Zonal Inspection Tasks		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:32-700-01 (ZONE: 710) (SOURCE: 560 XL MM Section 5-10-04) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 57-10-00-2100)				Hrs					
						Ldg					
53-10-00-2101		Nose Section Internal Zonal General Visual Inspection and Restoration									
	53 A/F	5-12-13						RE	05-10-01, 05-10-04, 05-10-05		
						Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		MRBR Task:211-102E, MRBR Task:212-102E, MRBR Task:221-102E, MRBR Task:222-102E, MRBR Task:53-200-01, MRBR Task:112-001, MRBR Task:211-001, MRBR Task:212-001, MRBR Task:221-001, MRBR Task:222-001 (ZONE: 110, 211, 212, 221, 222) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2102 and 53-10-00-2103)				Hrs					
						Ldg					
53-10-00-2102		Nose Avionics Components Wiring and Bulkhead Connectors Standalone EZAP General Visual Inspection									
	53 A/F	5-12-13						RE	MSG-3 Zonal Inspection Tasks		
						Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		(ZONE: 211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-05) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2101 and 53-10-00-2103)				Hrs					
						Ldg					
53-10-00-2103		Nose Avionics L/HIRF Standalone General Visual Inspection (Airplanes -5001 thru -6000)									
	53 A/F	5-12-13						RE	MSG-3 L/HIRF Inspection Tasks		
						Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		(ZONE: 211, 212) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2101 and 53-10-00-2102)				Hrs					
						Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
53-10-00-2200	53 A/F	Nose Landing Gear and Wheel Well Structure and Corrosion General Visual and Detailed Inspection							REMSG-3 Structures Inspection Tasks			
		5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		(ZONE: 710, 711) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task)					Hrs	6582:45				
							Ldg	4,450				
53-10-00-2201	53 A/F	Nose Structure Internal Detailed Inspection							REMSG-3 Structures Inspection Tasks			
		5-12-16					Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
		(ZONE: 110, 211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-03)					Hrs					
							Ldg					
53-10-00-2202	53 A/F	Nose Non-Metallic Structure (Radome, Door Drip Caps) Internal Detailed Inspection							REMSG-3 Structures Inspection Tasks			
		5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 110,211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 53-10-00-2203)					Hrs					
							Ldg					
53-10-00-2203	53 A/F	Radome Diverter Strips L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks			
		5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 111) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Task 53-10-00-2202)					Hrs					
							Ldg					
53-10-11-2200	53 A/F	Lower Aft Cabin Internal (Below Externally Serviced Toilet) Structural and Corrosion (Borescope) Special Detailed Inspection							REMSG-3 Structures Inspection Tasks			
		5-12-03					Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 172) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task. NOTE: It is recommended you do this task at the same time as Task 38-30-02-2200.)					Hrs	6620:35				
							Ldg	4,370				
53-10-11-2201	53 A/F	Aft Cabin Lower Skin (Below Drop Aisle) Internal Structural and Corrosion Detailed Inspection							REMSG-3 Structures Inspection Tasks			
		5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 151, 152, 161, 162, 171, 172) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task)					Hrs					
							Ldg					
53-10-11-2202	53 A/F	Lower Aft Cabin Internal (Below Carry-Out Toilet) Structural and Corrosion Detailed Inspection							REMSG-3 Structures Inspection Tasks			
		5-12-03					Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 171) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task.)					Hrs	6620:35				
							Ldg	4,370				
53-10-11-2501	53 A/F	Forward Pressure Bulkhead (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits		≈26-Dec-2026
		4-12-MD					Mos		120		(30-Jun-2029)	5.4 Years
		(ZONE: 141, 142, 241, 242) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	6,000			(8101:36)	1048:56 Hrs
							Ldg					
53-10-11-2502	53 A/F	Aft Pressure Bulkhead General Visual Inspection						RE		Airworthiness Limitations Inspection Time Limits		≈09-Mar-2046
		4-12-ME					Mos					
		(ZONE: 171, 172, 261, 262) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000			(15000)	7947:20 Hrs
							Ldg					
53-10-12-2100	53 A/F	Baggage Door and Forward Tailcone Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
		5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:53-300-01 (ZONE: 311, 312) (SOURCE: 560 XL MM Section 5-10-04) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2102, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200)					Hrs					
							Ldg					
53-10-12-2101	53 A/F	Tailcone External Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
		5-12-06					Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:53-300-02 (ZONE: 317, 318, 323, 324) (SOURCE: 560 XL MM Section 5-10-04)					Hrs					
							Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
53-10-12-2102	 53 A/F	Auxiliary Power Unit Enclosure and Stinger Internal Zonal General Visual Inspection and Restoration 5-12-06						RE	05-10-01, 05-10-04, 05-10-05		
								48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
53-10-12-2103	 53 A/F	Forward Tailcone Avionics Components, Wire Bundles and Connectors Standalone EZAP General Visual Inspection 5-12-06						RE	MSG-3 EZAP Inspection Tasks		
								48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
53-10-12-2104	 53 A/F	Auxiliary Power Unit Generator Power Feeder Cables Standalone EZAP General Visual Inspection 5-12-06						RE	MSG-3 EZAP Inspection Tasks		
								48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
53-10-12-2200	 53 A/F	Auxiliary Power Unit Generator, Auxiliary Power Unit Generator Control Unit and Left / Right Engine Generator Control Unit L/HIRF Detailed Inspection 5-12-06						RE	MSG-3 L/HIRF Inspection Tasks		
								48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
53-20-00-2100	 53 A/F	Cockpit Internal (Below Floorline) Zonal General Visual Inspection and Restoration 5-12-13						RE	05-10-01, 05-10-04, 05-10-05		
								72	-/+1m	(17-Mar-2024)	47 Days (+31)
53-20-00-2101	 53 A/F	Cockpit Internal (Above Floorline) Zonal General Visual Inspection and Restoration 5-12-16						RE	05-10-01, 05-10-04, 05-10-05		
								96	-/+1m	(31-Mar-2024)	61 Days (+30)
53-20-00-2102	 53 A/F	Cockpit Wire Bundles Standalone EZAP General Visual Inspection 5-12-13						RE	MSG-3 Zonal Inspection Tasks		
								72	-/+1m	(17-Mar-2024)	47 Days (+31)
53-20-00-2103	 53 A/F	Cockpit Avionics Components and Wire Bundles Standalone EZAP General Visual Inspection 5-12-16						RE	MSG-3 EZAP Inspection Tasks		
								96	-/+1m	(31-Mar-2024)	61 Days (+30)
53-20-00-2104	 53 A/F	Cockpit Avionics Control Head L/HIRF Standalone General Visual Inspection 5-12-16						RE	MSG-3 L/HIRF Inspection Tasks		
								96	-/+1m	(31-Mar-2024)	61 Days (+30)
53-30-00-2100	 53 A/F	Cabin Internal Zonal General Visual Inspection and Restoration 5-12-16						RE	05-10-01, 05-10-04, 05-10-05		
								96	-/+1m	(31-Mar-2024)	61 Days (+30)

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
53-30-00-2101	53 A/F	Forward Cabin (Below Floorline) Internal General Visual Inspection and Restoration 5-12-16 MRBR Task:235-102E, MRBR Task:236-102E, MRBR Task:245-102E, MRBR Task:246-102E, MRBR Task:53-100-06, MRBR Task:151-001, MRBR Task:152-001 (ZONE: 151, 152) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-20-00-2104, and 56-11-00-2204)						RE	05-10-01, 05-10-04, 05-10-05		
						Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
						Hrs					
						Ldg					
53-30-00-2200	53 A/F	Elevator and Elevator Trim Control System Support Structural Detailed Inspection 5-12-06 (ZONE: 141, 142, 241, 242, 151, 152, 161, 162, 171, 172) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 55-20-00-2200)						REMSG-3 Structures Inspection Tasks			
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
53-30-01-2100	53 A/F	Upper Fuselage Skin from Right Stringer 13 to Left Stringer 13 General Visual Inspection 4-12-MJ (ZONE: 213, 243, 253, 263, 323, 214, 244, 254, 264, 324) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						RE	Airworthiness Limitations Inspection Time Limits		≈14-Aug-2040
						Mos					
						Hrs	13,000			(13000)	5947:20 Hrs
						Ldg					
53-30-01-2101	53 A/F	Lower Fuselage Skin from Right Stringer 13 to Left Stringer 13 General Visual Inspection 4-12-ME (ZONE: 143, 151, 161, 171, 213, 144, 152, 162, 172, 214) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						RE	Airworthiness Limitations Inspection Time Limits		≈09-Mar-2046
						Mos					
						Hrs	15,000			(15000)	7947:20 Hrs
						Ldg					
53-30-01-2500	53 A/F	Fuselage External Surface (Eddy Current) Special Detailed Inspection 5-12-25 (ZONE: 143, 144, 223, 224, 243, 244, 253, 254, 263, 264) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: Zone cont.: 317, 318, 323, 324)						REMSG-3 Structures Inspection Tasks			≈29-Sep-2036
						Mos					
						Hrs	7,200		-/+25	(11609)	4556:20 Hrs (+25)
						Ldg					
53-30-01-2501	53 A/F	Upper Fuselage Skin Splice at BL 0.00 (Eddy Current) Special Detailed Inspection 4-12-ME (ZONE: 241, 242, 251, 252, 261, 262) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						RE	Airworthiness Limitations Inspection Time Limits		≈09-Mar-2046
						Mos					
						Hrs	15,000			(15000)	7947:20 Hrs
						Ldg					
53-30-01-2502	53 A/F	Lower Fuselage Skin Splices at Stringers 13R and 13L (Eddy Current) Special Detailed Inspection 4-12-ME (ZONE: 151, 161, 171, 152, 162, 172) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						RE	Airworthiness Limitations Inspection Time Limits		≈09-Mar-2046
						Mos					
						Hrs	15,000			(15000)	7947:20 Hrs
						Ldg					
53-31-00-2200	53 A/F	Composite Ventral Strake (Coin Tap) Special Detailed Inspection 5-12-16 (ZONE: 323, 324) (SOURCE: 560 XL MM Section 5-10-03)						REMSG-3 Structures Inspection Tasks			
						Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
						Hrs					
						Ldg					
53-USER-01	53 A/F	FR-560-5183-8823 - Surface Eddy Current Inspect Around the Initial Row of Fasteners Common to the -1 Splice Doubler, as well as One Row Above and Below						RE			≈26-Dec-2026
						Mos		120		[30-Jun-2029]	5.4 Years
						Hrs		2,400		[8101:36]	1048:56 Hrs
						Ldg					
▼ 54 - NACELLES/PYLONS											
54-50-01-2100	54 A/F	Left Side Engine Cowlings and Pylons Internal and External Zonal General Visual Inspection and Restoration 5-12-03 MRBR Task:71-400-01, MRBR Task:411-001, MRBR Task:412-001, MRBR Task:415-001, MRBR Task:421-001, MRBR Task:71-400-02, MRBR Task:413-001, MRBR Task:414-001, MRBR Task:431-001, MRBR Task:441-001, MRBR Task:411-101E, MRBR Task:412-101E, MRBR Task:415-101E, MRBR Task:421-101E (ZONE: 411, 413, 410, 430) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 71-00-00-2100 and 71-00-00-2200)						RE	05-10-01, 05-10-04, 05-10-05		
						Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs	6620:35				
						Ldg	4,370				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
54-50-01-2100		Right Side Engine Cowlings and Pylons Internal and External Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
	54 A/F	5-12-03				Mos	11-Jul-2023	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:71-400-01, MRBR Task:411-001, MRBR Task:412-001, MRBR Task:415-001, MRBR Task:421-001, MRBR Task:71-400-02, MRBR Task:413-001, MRBR Task:414-001, MRBR Task:431-001, MRBR Task:441-001, MRBR Task:411-101E, MRBR Task:412-101E, MRBR Task:415-101E, MRBR Task:421-101E (ZONE: 412, 414, 420, 440) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 71-00-00-2100 and 71-00-00-2200)				Hrs	6620:35				
						Ldg	4,370				
54-50-10-2100		Left Aft Engine Beam General Visual Inspection						RE (N/A)		Airworthiness Limitations	
	54 A/F					Mos				Inspection Time Limits	
		(ZONE: 311, 411) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
54-50-10-2100		Right Aft Engine Beam General Visual Inspection						RE (N/A)		Airworthiness Limitations	
	54 A/F					Mos				Inspection Time Limits	
		(ZONE: 312, 412) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
54-50-10-2500		Left Forward Engine Beam Upper Angles, Horizontal Cap Flange at BL 30.5 thru BL 42.0 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations	
	54 A/F					Mos				Inspection Time Limits	
		(ZONE: 311, 411) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
54-50-10-2500		Right Forward Engine Beam Upper Angles, Horizontal Cap Flange at BL 30.5 thru BL 42.0 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations	
	54 A/F					Mos				Inspection Time Limits	
		(ZONE: 312, 412) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
▼ 55 - STABILIZERS											
55-00-00-2200		Empennage Cove Structure and Corrosion Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	55 A/F	5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		(ZONE: 321, 322, 341 353, 354) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task.)				Hrs	6582:45				
						Ldg	4,450				
55-10-00-2100		Empennage External Zonal General Visual Inspection						RE		MSG-3 Zonal Inspection Tasks	
	55 A/F	5-12-13				Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		MRBR Task:55-300-01 (ZONE: 341, 353, 354) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2200 and 55-10-00-2201)				Hrs					
						Ldg					
55-10-00-2101		Horizontal Stabilizer Surfaces Internal Zonal General Visual Inspection						RE		MSG-3 Zonal Inspection Tasks	
	55 A/F	5-12-16				Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
		MRBR Task:55-300-03 (ZONE: 351, 352) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Task 55-10-00-2900)				Hrs					
						Ldg					
55-10-00-2200		Horizontal Stabilizer Position Switches L/HIRF Detailed Inspection						RE		MSG-3 L/HIRF Inspection Tasks	
	55 A/F	5-12-13				Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		(ZONE: 342) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2100 and 55-10-00-2201)				Hrs					
						Ldg					
55-10-00-2201		Flux Detectors L/HIRF Detailed Inspection						RE		MSG-3 L/HIRF Inspection Tasks	
	55 A/F	5-12-13				Mos		72	-/+1m	(17-Mar-2024)	47 Days (+31)
		(ZONE: 351, 352) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2100 and 55-10-00-2200)				Hrs					
						Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
55-10-00-2900		Internal Horizontal Stabilizer (Borescope) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	55 A/F	5-12-16				Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
		(ZONE: 351, 352) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 55-10-00-2101)				Hrs					
						Ldg					
55-20-00-2200		Elevator Assembly Detailed Inspection						RE	05-10-01, 05-10-02, 05-10-03, Category 5		
	55 A/F	Left5-12-06				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		MRBR Task:55-20-01-001, MRBR Task:55-20-01-002 (ZONE: 354) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 53-30-00-2200)									
55-20-00-2200		Elevator Assembly Detailed Inspection						RE	05-10-01, 05-10-02, 05-10-03, Category 5		
	55 A/F	Right5-12-06				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		MRBR Task:55-20-01-001, MRBR Task:55-20-01-002 (ZONE: 353) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 53-30-00-2200)									
55-30-00-2102		Vertical Stabilizer Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
	55 A/F	5-12-16				Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
		MRBR Task:55-300-02 (ZONE: 340) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2900)				Hrs					
						Ldg					
55-30-00-2200		Rudder and Rudder Trim Control System Structural Support Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	55 A/F	5-12-06				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 141,142,161,162,241,242,311,312,313,323,324,341) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 55-40-00-2200)				Hrs					
						Ldg					
55-30-00-2201		Vertical Stabilizer Pivot Fitting Detailed Inspection						TMSG-3 Structures Inspection Tasks			≈12-Jun-2025
	55 A/F	5-12-17				Mos					
		(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-03)				Hrs		6,000	-/+25	(7550)	497:20 Hrs (+25)
						Ldg					
55-30-00-2500		Vertical Stabilizer Rear Spar Cap at WL 146 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations Inspection Time Limits	
	55 A/F					Mos					
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
55-30-00-2501		Vertical Stabilizer Rear Spar Nested Angle at WL 146 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations Inspection Time Limits	
	55 A/F					Mos					
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
55-30-00-2502		Vertical Stabilizer Rear Spar Strap at WL 146.00 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations Inspection Time Limits	
	55 A/F					Mos					
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					
55-30-00-2503		Vertical Stabilizer Forward Spar Strap at WL 150 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations Inspection Time Limits	
	55 A/F					Mos					
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01)				Hrs					
						Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
55-30-00-2504		Vertical Stabilizer Forward Spar Strap at WL 188.00 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations Inspection Time Limits	
	55 A/F										
(ZONE: 340) (SOURCE: 560 XL MM Section 4-10-01)											
55-30-00-2900		Vertical Stabilizer (Areas With Limited Access) (Borescope) Internal Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	55 A/F	5-12-16						96	-/+1m	(31-Mar-2024)	61 Days (+30)
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2102)											
55-40-00-2200		Rudder and Rudder Trim Tab Detailed Inspection						RE		05-10-01, 05-10-02, 05-10-03, Category 5	
	55 A/F	5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
MRBR Task:55-40-01-001 (ZONE: 341) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2200)											
▼ 56 - WINDOWS											
56-11-00-2200		Heated Windshield Assembly Hump Seal Detailed Inspection						RE		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	56 A/F	Left5-12-01									
	NP139721-9							12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	12067H0570										
(ZONE: 243) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)											
56-11-00-2200		Heated Windshield Assembly Hump Seal Detailed Inspection						RE		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	56 A/F	Right5-12-01									
	NP139731-2							12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
	13319H6327										
(ZONE: 244) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02)											
56-11-00-2201		Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection						RE		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Dec-2027
	56 A/F	Left5-12-07									
	NP139703-3										
	511										
(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)											
56-11-00-2201		Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection						RE		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Dec-2027
	56 A/F	Right5-12-07									
	NP139703-4										
	570										
(ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02)											
56-11-00-2202		Windshield Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	56 A/F	5-12-03									
								24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
(ZONE: 241, 242, 243, 244) (SOURCE: 560 XL MM Section 5-10-03)											
56-11-00-2203		Windshield Retainer Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	56 A/F	5-12-16									
								96	-/+1m	(31-Mar-2024)	61 Days (+30)
(ZONE: 243, 244) (SOURCE: 560 XL MM Section 5-10-03)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
56-11-00-2204		Cockpit and Openable Side Window Internal Structure Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	56 A/F	5-12-16					Mos	96	-/+1m	(31-Mar-2024)	61 Days (+30)
		(ZONE: 241, 242, 243, 244) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-20-00-2104, and 53-30-00-2101)					Hrs				
							Ldg				
56-11-00-2207		Openable Side Cockpit Window (Transparency) Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	56 A/F	Left5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	NP139703-3						Hrs				
	511						Ldg				
		(ZONE: 241, 243) (SOURCE: 560 XL MM Section 5-10-03)									
56-11-00-2207		Openable Side Cockpit Window (Transparency) Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	56 A/F	Right5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	NP139703-4						Hrs				
	570						Ldg				
		(ZONE: 242,244) (SOURCE: 560 XL MM Section 5-10-03)									
56-11-00-7200		Heated Windshield Assembly Fastener Torque Functional Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	56 A/F	Left5-12-08					Mos	29-Sep-2023			
	NP139721-9						Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
	12067H0570						Ldg	4,505			
		(ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02)									
56-11-00-7200		Heated Windshield Assembly Fastener Torque Functional Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	56 A/F	Right5-12-08					Mos	29-Sep-2023			
	NP139731-2						Hrs	6839:30	2,400	-/+25	(9209) 2156:20 Hrs (+25)
	13319H6327						Ldg	4,505			
		(ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02)									
56-11-00-7201		Left Windshield Surface Seal (Mist Spray) Functional Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	56 A/F	Left5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024) 4.6 Months (+30 Days)
	NP139721-9						Hrs	6582:45			
	12067H0570						Ldg	4,450			
		(ZONE: 243) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: Operational Environment May Require Reduced Interval)									
56-11-00-7201		Right Windshield Surface Seal (Mist Spray) Functional Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	56 A/F	Right5-12-01					Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024) 4.6 Months (+30 Days)
	NP139731-2						Hrs	6582:45			
	13319H6327						Ldg	4,450			
		(ZONE: 244) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: Operational Environment May Require Reduced Interval)									
▼ 57 - WINGS											
57-00-00-2100		Left Wing External Zonal General Visual Inspection								RE MSG-3 Zonal Inspection Tasks	
	57 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		MRBR Task:57-500-01, MRBR Task:510-001, MRBR Task:511-001, MRBR Task:512-001, MRBR Task:521-001, MRBR Task:522-001, MRBR Task:531-001, MRBR Task:532-001, MRBR Task:542-001, MRBR Task:610-001, MRBR Task:611-001, MRBR Task:612-001, MRBR Task:621-001, MRBR Task:622-001, MRBR Task:631-001, MRBR Task:632-001, MRBR Task:641-001, MRBR Task:57-20-03-001, MRBR Task:57-50-02-001, MRBR Task:57-20-04-001 (ZONE: 511, 512, 515, 521, 522, 531, 532, 540) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100)					Hrs				
							Ldg				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-00-00-2100	 57 A/F	Right Wing External Zonal General Visual Inspection 5-12-06 MRBR Task:57-500-01, MRBR Task:510-001, MRBR Task:511-001, MRBR Task:512-001, MRBR Task:521-001, MRBR Task:522-001, MRBR Task:531-001, MRBR Task:532-001, MRBR Task:542-001, MRBR Task:610-001, MRBR Task:611-001, MRBR Task:612-001, MRBR Task:621-001, MRBR Task:622-001, MRBR Task:631-001, MRBR Task:632-001, MRBR Task:641-001, MRBR Task:57-20-03-001, MRBR Task:57-50-02-001, MRBR Task:57-20-04-001 (ZONE: 611, 612, 615, 621, 622, 631, 632, 641) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100)						RE	MSG-3 Zonal Inspection Tasks		
						Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
57-00-00-2101	 57 A/F	Left Wing Internal Zonal General Visual Inspection 5-12-06 (ZONE: 513, 514, 515, 523, 524, 533, 534) (SOURCE: 560 XL MM Section 5-10-04) (NOTE: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task.NOTE: It is recommended you do this task at the same time as Task 57-00-00-2102)				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
57-00-00-2101	 57 A/F	Right Wing Internal Zonal General Visual Inspection 5-12-06 (ZONE: 613, 614, 615, 623, 624, 633, 634) (SOURCE: 560 XL MM Section 5-10-04) (NOTE: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task.NOTE: It is recommended you do this task at the same time as Task 57-00-00-2102)				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
57-00-00-2102	 57 A/F	Left Wing Fuel Probe Wiring Harness Standalone EZAP General Visual Inspection 5-12-06 (ZONE: 513, 514, 515, 523, 524, 533, 534) (SOURCE: 560 XL MM Section 5-10-05) (NOTE: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task. NOTE: It is recommended you do this task at the same time as Task 57-00-00-2101)				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
57-00-00-2102	 57 A/F	Right Wing Fuel Probe Wiring Harness Standalone EZAP General Visual Inspection 5-12-06 (ZONE: 613, 614, 615, 623, 624, 633, 634) (SOURCE: 560 XL MM Section 5-10-05) (NOTE: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task. NOTE: It is recommended you do this task at the same time as Task 57-00-00-2101)				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
57-00-00-2200	 57 A/F	Left Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection 5-12-01 (ZONE: 512, 516, 522, 532) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task)				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
						Hrs	6582:45				
						Ldg	4,450				
57-00-00-2200	 57 A/F	Right Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection 5-12-01 (ZONE: 614, 615, 624, 634) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task)				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
						Hrs	6582:45				
						Ldg	4,450				
57-10-00-2100	 57 A/F	Left Main Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection 5-12-06 MRBR Task:32-700-02, MRBR Task:721- 001, MRBR Task:731-001 (ZONE: 730) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100)				Mos		48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Hrs					
						Ldg					
57-10-00-2100	 57 A/F	Right Main Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection 5-12-06 MRBR Task:32-700-02, MRBR Task:721- 001, MRBR Task:731-001 (ZONE: 720) (UPDATE NOTE: CRS TXTAV DUSSELDORF 60000729) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100)				Mos	01-Jun-2021	48	-/+1m	30-Jun-2025	1.4 Years (+30 Days)
						Hrs	5979:13				
						Ldg	3,951				
57-10-00-2101	 57 A/F	Left and Right Wing Forward Spar (Forward Side) and Wing Tip Internal Standalone General Visual Inspection 5-12-16 (ZONE: 513, 523, 533, 541, 613, 623, 633, 642) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 57-30-01-2100)				Mos		96	-/+1m	(31-Mar-2024)	61 Days (+30)
						Hrs					
						Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-10-00-2200		Left Main Landing Gear and Wheel Well Structure and Corrosion General Visual Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		(ZONE: 720) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task)				Hrs	6582:45				
						Ldg	4,450				
57-10-00-2200		Right Main Landing Gear and Wheel Well Structure and Corrosion General Visual Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-01				Mos	28-Jun-2023	12	-/+1m	(16-Jun-2024)	4.6 Months (+30 Days)
		(ZONE: 730) (Tol. Adjustment: -11d) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: This is a CPCP Task)				Hrs	6582:45				
						Ldg	4,450				
57-10-00-2500		Left Lower Wing Main Spar Lower Skin Splice at WS 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈22-Apr-2025
	57 A/F	4-12-MF				Mos					
		(ZONE: 515) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	7,500			(7500)	447:20 Hrs
						Ldg					
57-10-00-2500		Right Lower Wing Main Spar Lower Skin Splice at WS 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈22-Apr-2025
	57 A/F	4-12-MF				Mos					
		(ZONE: 516) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	7,500			(7500)	447:20 Hrs
						Ldg					
57-10-00-2501		Left Lower Wing Main Spar Skin Splice Flange at WS 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈10-Jun-2036
	57 A/F	4-12-ML				Mos					
		(ZONE: 515) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	11,500			(11500)	4447:20 Hrs
						Ldg					
57-10-00-2501		Right Lower Wing Main Spar Skin Splice Flange at WS 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈10-Jun-2036
	57 A/F	4-12-ML				Mos					
		(ZONE: 615) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	11,500			(11500)	4447:20 Hrs
						Ldg					
57-10-00-2502		Left Lower Wing Main Spar at WS 114.57 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈20-Jan-2035
	57 A/F	4-12-MM				Mos					
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	11,000			(11000)	3947:20 Hrs
						Ldg					
57-10-00-2502		Right Lower Wing Main Spar at WS 114.57 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈20-Jan-2035
	57 A/F	4-12-MM				Mos					
		(ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	11,000			(11000)	3947:20 Hrs
						Ldg					
57-10-00-2503		Left Lower Wing Main Spar at WS 131.07 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈25-Jun-2029
	57 A/F	4-12-MN				Mos					
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	9,000			(9000)	1947:20 Hrs
						Ldg					
57-10-00-2503		Right Lower Wing Main Spar at WS 131.07 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈25-Jun-2029
	57 A/F	4-12-MN				Mos					
		(ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs	9,000			(9000)	1947:20 Hrs
						Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-10-00-2504		Left Lower Wing Main Spar at WS 149.57 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈24-Mar-2039
	57 A/F	4-12-MO									
						Mos					
						Hrs		12,500		(12500)	5447:20 Hrs
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Ldg					
57-10-00-2504		Right Lower Wing Main Spar at WS 149.57 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈24-Mar-2039
	57 A/F	4-12-MO									
						Mos					
						Hrs		12,500		(12500)	5447:20 Hrs
		(ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Ldg					
57-30-01-2100		Wing Tip Internal Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
	57 A/F	5-12-16						96	-/+1m	(31-Mar-2024)	61 Days (+30)
						Mos					
						Hrs					
		MRBR Task:541-101E, MRBR Task:642-101E, MRBR Task:57-500-03, MRBR Task:541-001, MRBR Task:642-001 (ZONE: 541, 642) (SOURCE: 560XL MM) (NOTE: NOTE: It is recommended you do this task at the same time as Task 57-10-00-2101)				Ldg					
57-50-03-2200		Aileron, Aileron Trim Tab and Hinge Brackets Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Mos					
						Hrs					
		(ZONE: 532, 534, 632, 634) (SOURCE: 560 XL MM Section 5-10-03) (NOTE: NOTE: It is recommended you do this task at the same time as Task 57-60-00-2200)				Ldg					
57-50-04-2900		Flap (Coin Tap) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Mos					
						Hrs					
		(ZONE: 612) (SOURCE: 560 XL MM Section 5-10-03)				Ldg					
57-50-04-2900		Flap (Coin Tap) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	Left Inboard5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Mos					
	Unknown					Hrs					
		(ZONE: 512) (SOURCE: 560 XL MM Section 5-10-03)				Ldg					
57-50-04-2900		Flap (Coin Tap) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	Left Outboard5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Mos					
	Unknown					Hrs					
		(ZONE: 612) (SOURCE: 560 XL MM Section 5-10-03)				Ldg					
57-50-04-2900		Flap (Coin Tap) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	Right Inboard5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
	Unknown					Mos					
	Unknown					Hrs					
		(ZONE: 522) (SOURCE: 560 XL MM Section 5-10-03)				Ldg					
▼ 58 - *Unassigned											
57-60-00-2200		Aileron, Aileron Wing Sectors and Aileron Trim Components Structure Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Structures Inspection Tasks		
	58 A/F	5-12-06						48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
						Mos					
						Hrs					
		MRBR Task:27-10-00-213, MRBR Task:27-10-01-001, MRBR Task:27-10-01-002 (ZONE: 141, 142, 161, 162, 241, 242, 512, 522, 523, 612,) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-10-03) (NOTE: Zones Cont: 622, 632. NOTE: It is recommended you do this task at the same time as Task 57-50-03-2200)				Ldg					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 71 - POWER PLANT											
54-50-01-2101		Left Engine Cowling, Engine Pylon Firewall General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	71 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 71-00-00-2201)					Hrs				
							Ldg				
54-50-01-2101		Right Engine Cowling, Engine Pylon Firewall General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	71 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02) (NOTE: NOTE: It is recommended you do this task at the same time as Task 71-00-00-2201)					Hrs				
							Ldg				
71-00-00-2100		Left Engine Fire Detection Element Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
	71 A/F	5-12-03					Mos	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-05) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2200)					Hrs	6620:35			
							Ldg	4,370			
71-00-00-2100		Right Engine Fire Detection Element Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
	71 A/F	5-12-03					Mos	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-05) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2200)					Hrs	6620:35			
							Ldg	4,370			
71-00-00-2200		Left Engine Starter Generator, Alternator, Alternator PCU, Full Authority Digital Electronic Control L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
	71 A/F	5-12-03					Mos	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2100)					Hrs	6620:35			
							Ldg	4,370			
71-00-00-2200		Right Engine Starter Generator, Alternator, Alternator PCU, Full Authority Digital Electronic Control L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
	71 A/F	5-12-03					Mos	24	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2100)					Hrs	6620:35			
							Ldg	4,370			
71-00-00-2201		Left Engine Cowling L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
	71 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 430, 440) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Task 54-50-01-2101)					Hrs				
							Ldg				
71-00-00-2201		Right Engine Cowling L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
	71 A/F	5-12-06					Mos	48	-/+1m	(17-Jun-2025)	1.4 Years (+30 Days)
		(ZONE: 430, 440) (SOURCE: 560 XL MM Section 5-10-06) (NOTE: NOTE: It is recommended you do this task at the same time as Task 54-50-01-2101)					Hrs				
							Ldg				
71-00-PW-009		Engine Externals and Compressor Wash (Desalination)						RE (A/R)		EMM - Requirement	
	71 ENG1						Mos				
		(NOTE: As general observations warrant. As necessary by ECTM or at every approx. 20 °C ITT increase. Also by visual inspection of compressor gas path when you operate the engine in an adverse environment)					Hrs				
							Enc				
71-00-PW-009		Engine Externals and Compressor Wash (Desalination)						RE (A/R)		EMM - Requirement	
	71 ENG2						Mos				
		(NOTE: As general observations warrant. As necessary by ECTM or at every approx. 20 °C ITT increase. Also by visual inspection of compressor gas path when you operate the engine in an adverse environment)					Hrs				
							Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-22-00-9600		Engine Aft Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈07-Apr-2032
	71 A/F	Left					Mos	23-Aug-2001			
	LM451-SA2					0	Hrs	0	10,000	+100	10000
	LK0412						Ldg				2947:20 Hrs (+100)
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
71-22-00-9600		Engine Aft Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈07-Apr-2032
	71 A/F	Right					Days	23-Aug-2001			
	LM451-SA2					0	Hrs	0	10,000	+100	10000
	LK0391						Ldg				2947:20 Hrs (+100)
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Nov-2051
	71 A/F	Lower - Left					Mos	25-Jan-2024			
	9912480-1EX						Hrs	7052:40	10,000	+100	17052:40
	LK3665						Ldg	4,653			10000 Hrs (+100)
		(UPDATE NOTE: CRS ELITE JET GmbH 24-042) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈07-Apr-2032
	71 A/F	Lower - Right					Days	23-Aug-2001			
	LM451-SA4					0	Hrs	0	10,000	+100	10000
	LK0930						Ldg				2947:20 Hrs (+100)
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Nov-2051
	71 A/F	Upper - Left					Mos	25-Jan-2024			
	9912480-1EX						Hrs	7052:40	10,000	+100	17052:40
	LK3606						Ldg	4,653			10000 Hrs (+100)
		(UPDATE NOTE: CRS ELITE JET GmbH 24-042) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈10-Jun-2042
	71 A/F	Upper - Right				0	Mos	28-Feb-2013			
	LM451-SA4					0	Hrs	3654:48	10,000	+100	13654:48
	LK0538					0	Ldg	2,768			6602:08 Hrs (+100)
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
71-71-00-2100		Left Engine Drains General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	71 A/F	5-12-08					Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25	(9209)
							Ldg	4,505			2156:20 Hrs (+25)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)									
71-71-00-2100		Right Engine Drains General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Jan-2030
	71 A/F	5-12-08					Mos	29-Sep-2023			
							Hrs	6839:30	2,400	-/+25	(9209)
							Ldg	4,505			2156:20 Hrs (+25)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)									
719001		Performance Recovery Wash							RE (A/R)		
	71 ENG1						Mos	17-Jun-2021			
							Hrs				
							Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
719001		Performance Recovery Wash						RE (A/R)			
	71 ENG2					Mos	17-Jun-2021				
						Hrs					
						Enc					
▼ 72 - ENGINE											
		ENGINE No. 2 INSTALLATION						RE (-)			
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-01		FOD						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-01		FOD						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-02		Bird Strike						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-02		Bird Strike						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-03		Engine Windmilling In Flight						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-03		Engine Windmilling In Flight						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-04		Lightning Strike						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-04		Lightning Strike						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-05		Fuel Filter Impending Bypass						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-05		Fuel Filter Impending Bypass						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-06		Engine Exposed To Fire Extinguishing Agent						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
	Brand A:726009					Enc					
05-50-00-06		Engine Exposed To Fire Extinguishing Agent						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
	Brand A:726009					Enc					
05-50-00-07		Incorrect Engine Shutdown On The Ground						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
	Brand A:726011					Enc					
05-50-00-07		Incorrect Engine Shutdown On The Ground						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
	Brand A:726011					Enc					
05-50-00-08		Heavy Landing						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
	Brand A:726013					Enc					
05-50-00-08		Heavy Landing						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
	Brand A:726013					Enc					
05-50-00-09		Sustained Running At An Oil Temperature Outside Of Limits						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
	Brand A:726015					Enc					
05-50-00-09		Sustained Running At An Oil Temperature Outside Of Limits						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
	Brand A:726015					Enc					
05-50-00-10		ITT Spike On Engine Start Due To A Frozen Fan						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
	Brand A:726017					Enc					
05-50-00-10		ITT Spike On Engine Start Due To A Frozen Fan						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
	Brand A:726017					Enc					
05-50-00-11		Loose High Pressure Compressor Case Bolts						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
	Brand A:726019					Enc					
05-50-00-11		Loose High Pressure Compressor Case Bolts						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
	Brand A:726019					Enc					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-12		Data Collection Unit (DCU) Inoperative						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
		Brand A:726021				Hrs					
						Enc					
05-50-00-12		Data Collection Unit (DCU) Inoperative						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
		Brand A:726021				Hrs					
						Enc					
05-50-00-13		Aircraft Flown Through A Cloud Of Volcanic Ash						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
		Brand A:726023				Hrs					
						Enc					
05-50-00-13		Aircraft Flown Through A Cloud Of Volcanic Ash						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
		Brand A:726023				Hrs					
						Enc					
05-50-00-14		Starter Generator Fail Indication						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-14		Starter Generator Fail Indication						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-15		Hydraulic Pump Unscheduled Removal						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-15		Hydraulic Pump Unscheduled Removal						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-16		Fuel Contamination (Fuel contamination with Diesel Exhaust Fluid (DEF) additive, improper concentration of biocide or hydraulic fluid or as recommended by P&WC.)						RE (A/R)		EMM - Unscheduled	
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-16		Fuel Contamination (Fuel contamination with Diesel Exhaust Fluid (DEF) additive, improper concentration of biocide or hydraulic fluid or as recommended by P&WC.)						RE (A/R)		EMM - Unscheduled	
	72 ENG2					Mos					
						Hrs					
						Enc					
720023		Engine Preservation - Engine Inactive For 91 Days And Over						RE (A/R)			
	72 ENG1					Mos	17-Jun-2021				
						Hrs	5835:52				
						Enc	3,890				
720023		Engine Preservation - Engine Inactive For 91 Days And Over						RE (A/R)			
	72 ENG2					Mos	17-Jun-2021				
						Hrs	5835:52				
						Enc	3,890				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
720024		Engine Depreservation Procedure						RE (A/R)			
	72 ENG1					Mos	17-Jun-2021				
						Hrs					
						Enc					
720024		Engine Depreservation Procedure						RE (A/R)			
	72 ENG2					Mos	17-Jun-2021				
						Hrs					
						Enc					
72-00-PW-057		Low Utilization Inspection						T		EMM - Requirement	
	72 ENG1					Yrs	19-Sep-2017	10		30-Sep-2027	3.7 Years
		(NOTE: An additional 1 month or 10 flight-hours, whichever comes first, is available for scheduling purposes. Following the overhaul of a low utilization engine, the recommended initial on-wing Low Utilization Inspection (LUI) is at 10 years after engine overhaul.)				Hrs	4972:48				
						Enc	3,474				
72-00-PW-057		Low Utilization Inspection						T		EMM - Requirement	
	72 ENG2					Yrs	19-Sep-2017	10		30-Sep-2027	3.7 Years
		(NOTE: An additional 1 month or 10 flight-hours, whichever comes first, is available for scheduling purposes. Following the overhaul of a low utilization engine, the recommended initial on-wing Low Utilization Inspection (LUI) is at 10 years after engine overhaul.)				Hrs	4972:48				
						Enc	3,474				
72-00-PW-059		Engine - Overhaul						RE		EMM - Requirement	≈20-Jan-2033
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
72-00-PW-059		Engine - Overhaul						RE	05-20-00,	EMM - Requirement	≈09-Sep-2034
	72 ENG2					Mos	19-Sep-2017				
		(SOURCE: PW535B MM (P/N 3071822); PW545A MM (P/N 30J1272))				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
72-00-PW-061		Engine - Hot Section Inspection (HSI)						RE		EMM - Requirement	≈05-Feb-2026
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
						Enc	3,474				
72-00-PW-061		Engine - Hot Section Inspection (HSI)						RE		EMM - Requirement	≈24-Sep-2027
	72 ENG2					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
						Enc	3,474				
72-31-00-201		Engine Mount General Visual Inspection: Do a check for security and condition of the engine mount.						RE		EMM - Periodic Inspection	≈08-May-2026
	72 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
72-31-00-201		Engine Mount General Visual Inspection: Do a check for security and condition of the engine mount.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	72 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
72-31-00-202		LP Compressor Section - External Engine General Visual Inspection: Do an inspection for fuel and oil leaks, corrosion, cracks and signs of damage.						RE		EMM - Periodic Inspection	≈13-Apr-2026
	72 ENG1	72EH0000,...				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	≈7540:20	
						Enc	4,451				
72-31-00-202		LP Compressor Section - External Engine General Visual Inspection: Do an inspection for fuel and oil leaks, corrosion, cracks and signs of damage.						RE		EMM - Periodic Inspection	≈29-Oct-2025
	72 ENG2	72EH0000,...				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	≈6789:05	
						Enc	4,015				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD.						RE	EMM - Periodic Inspection		≈08-May-2026
	72 ENG1	72EH0800				Mos	23-Oct-2023				
		(NOTE: NOTE: For engine that operates more than 40% of the time in zones considered extreme in terms of environmental harshness per environment maps (Ref. 05-20-00, ENGINE EXTERNALS AND COMPRESSOR WASH, Fig. 1 thru 6), do a borescope/visual inspection of the bleed valve seat on the intermediate case, main intermediate case flanges. Do a magnesium corrosion treatment as necessary (Ref. 70-00-00, STANDARD PRACTICES - MAINTENANCE PROCEDURES).)				Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	72 ENG2	72EH0800				Mos	25-Oct-2023				
		(NOTE: NOTE: For engine that operates more than 40% of the time in zones considered extreme in terms of environmental harshness per environment maps (Ref. 05-20-00, ENGINE EXTERNALS AND COMPRESSOR WASH, Fig. 1 thru 6), do a borescope/visual inspection of the bleed valve seat on the intermediate case, main intermediate case flanges. Do a magnesium corrosion treatment as necessary (Ref. 70-00-00, STANDARD PRACTICES - MAINTENANCE PROCEDURES).)				Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD. When outside air temperature is 5°C (41°F) or below: Examine the bottom center area of the fan case for ice. Make sure that the fan turns freely.						RE (PreFlight)	EMM - Periodic Inspection		
	72 ENG1	72EH0000				Mos					
						Hrs					
						Enc					
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD. When outside air temperature is 5°C (41°F) or below: Examine the bottom center area of the fan case for ice. Make sure that the fan turns freely.						RE (PreFlight)	EMM - Periodic Inspection		
	72 ENG2	72EH0000				Mos					
						Hrs					
						Enc					
72-31-00-901		Low Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	72 ENG1	(SOURCE: PW545A MM (P/N 30J1272))				Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
72-31-00-901		Low Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	72 ENG2	(SOURCE: PW545A MM (P/N 30J1272))				Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
72-32-00-201		Compressor Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈05-Feb-2026
	72 ENG1	(SOURCE: PW545A MM (P/N 30J1272))				Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
						Enc	3,474				
72-32-00-201		Compressor Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈24-Sep-2027
	72 ENG2	(SOURCE: PW545A MM (P/N 30J1272))				Mos	27-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
						Enc	3,474				
72-32-00-901		High Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	72 ENG1	(SOURCE: PW545A MM (P/N 30J1272))				Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-32-00-901		High Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-40-00-201		Combustion Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈05-Feb-2026
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-40-00-201		Combustion Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈24-Sep-2027
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-40-00-901		Combustion Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-40-00-901		Combustion Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-50-00-201		Turbine Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈05-Feb-2026
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-50-00-201		Turbine Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈24-Sep-2027
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-50-00-701		Performance Calibration (5-Point Run) Functional Check: Do a performance calibration check (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) and compare with previous 5-point performance calibration. Alternatively, monitor the engine performance through Engine Condition Trend Monitoring (ECTM).						RE	EMM - Periodic Inspection		≈08-May-2026
	72 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
	(Tol. Adjustment: 24.3 Hrs)					Enc	4,451				
72-50-00-701		Performance Calibration (5-Point Run) Functional Check: Do a performance calibration check (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) and compare with previous 5-point performance calibration. Alternatively, monitor the engine performance through Engine Condition Trend Monitoring (ECTM).						RE	EMM - Periodic Inspection		≈25-Apr-2028
	72 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
72-50-00-702		Acceleration/Deceleration Functional Check: Refer to 71-00-00, POWER PLANT - ADJUSTMENT/TEST.						RE	EMM - Periodic Inspection		≈08-May-2026
	72 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
72-50-00-702		Acceleration/Deceleration Functional Check: Refer to 71-00-00, POWER PLANT - ADJUSTMENT/TEST.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	72 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-50-00-901		Turbine Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273. Discard the HPT nut and keywasher.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-50-00-901		Turbine Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273. Discard the HPT nut and keywasher.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-60-00-201		Engine Accessory General Visual Inspection: Do a check for security of installation and general condition of accessories and gearbox.						RE	EMM - Periodic Inspection		≈08-May-2026
	72 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
72-60-00-201		Engine Accessory General Visual Inspection: Do a check for security of installation and general condition of accessories and gearbox.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	72 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
72-60-00-901		Accessory Gearbox (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-60-00-901		Accessory Gearbox (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-70-00-201		Bypass Ducts and Fairings General Visual Inspection: Do a check for cleanliness and FOD. Do an inspection for cracks in the outer bypass duct, rear bypass duct, struts and fairing.						RE	EMM - Periodic Inspection		≈08-May-2026
	72 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
72-70-00-201		Bypass Ducts and Fairings General Visual Inspection: Do a check for cleanliness and FOD. Do an inspection for cracks in the outer bypass duct, rear bypass duct, struts and fairing.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	72 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
72-70-00-202		Bypass Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈05-Feb-2026
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-70-00-202		Bypass Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈24-Sep-2027
	72 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
72-70-00-901		Bypass Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	72 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
72-70-00-901		Bypass Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.							RE	EMM - Periodic Inspection		≈09-Sep-2034
72	ENG2						Mos	27-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)	
	(SOURCE: PW545A MM (P/N 30J1272))						Enc	3,474				
CAA-240115-020		PERFORM LH AND RH ENGINE PERFORMANCE CHECK AFTER RH ENGINE INSTALLATION							N/N (-)		Squawk, -	
72	A/F						Mos					
	Open						Hrs					
	(Date reported: 15-Jan-2024), (Reported by: KASIK, Title: CAMO)(Classification date: 15-Jan-2024), (Recorded by: KASIK, Title: CAMO)						Ldg					
▼ 73 - ENGINE - FUEL AND CONTROL												
73-00-PW-001		Fuel Control Unit and Pump - Overhaul (at Engine Overhaul)							RE	EMM - Requirement		≈20-Jan-2033
73	ENG1						Mos	19-Sep-2017				
	1012635-3						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)	
	F53332						Enc	3,474				
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-001		Fuel Control Unit and Pump - Overhaul (at Engine Overhaul)							RE	EMM - Requirement		≈09-Sep-2034
73	ENG2						Mos	27-Sep-2017				
	1012635-3						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)	
	F62168						Enc	3,474				
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-002		Fuel to Oil Heat Exchanger - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement		≈20-Jan-2033
73	ENG1						Mos	19-Sep-2017				
	31J2955-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)	
	M174623						Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-002		Fuel to Oil Heat Exchanger - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement		≈09-Sep-2034
73	ENG2						Mos	27-Sep-2017				
	31J2955-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)	
	M48596						Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-003		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement		≈20-Jan-2033
73	ENG1	No.1					Mos	19-Sep-2017				
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)	
	DEAAB07879						Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-003		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement		≈09-Sep-2034
73	ENG2	No.1					Mos	27-Sep-2017				
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)	
	DEAAB09206						Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-004		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement		≈20-Jan-2033
73	ENG1	No.2					Mos	19-Sep-2017				
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)	
	DEAAB07880						Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-004		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement		≈09-Sep-2034
73	ENG2	No.2					Mos	27-Sep-2017				
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)	
	DEAAB09295						Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-005		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
✎	73 ENG1	No.3					Mos	19-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)
	DEAAB07881						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-005		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
✎	73 ENG2	No.3					Mos	27-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)
	DEAAB09296						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-006		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
✎	73 ENG1	No.4					Mos	19-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)
	DEAAB07882						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-006		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
✎	73 ENG2	No.4					Mos	27-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)
	DEAAB09297						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-007		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
✎	73 ENG1	No.5					Mos	19-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)
	DEAAB07883						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-007		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
✎	73 ENG2	No.5					Mos	27-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)
	DEAAB09298						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-008		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
✎	73 ENG1	No.6					Mos	19-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)
	DEAAB07884						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-008		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
✎	73 ENG2	No.6					Mos	27-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)
	DEAAB09300						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-009		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
✎	73 ENG1	No.7					Mos	19-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3229:53 Hrs (+100)
	DEAAB07885						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-009		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
✎	73 ENG2	No.7					Mos	27-Sep-2017			
	30J2313-02						Hrs	4972:48	5,000	+100	9972:48 3817:18 Hrs (+100)
	DEAAB09301						Enc	3,474			
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-010		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1	No.8				Mos	19-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	DEAAB07886					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-010		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2	No.8				Mos	27-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	DEAAB09303					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-011		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1	No.9				Mos	19-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	DEAAB07887					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-011		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2	No.9				Mos	27-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	DEAAB09304					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-012		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1	No.10				Mos	19-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	DEAAB07889					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-012		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2	No.10				Mos	27-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	DEAAB09305					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-013		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1	No.11				Mos	19-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	DEAAB07890					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-013		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2	No.11				Mos	27-Sep-2017				
	30J2313-02					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	DEAAB09306					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-014		Flow Divider - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	819710-2					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	F54072					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE 1: The accessories have the same TBO as the engine. If the accessory was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessory is operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).)									
73-00-PW-014		Flow Divider - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	30J1415-02					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	F59026					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-015		Fuel Filter Differential Pressure Switch - Examine and functional test (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
73-00-PW-015		Fuel Filter Differential Pressure Switch - Examine and functional test (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
73-00-PW-016		Fuel Manifold - Inspect/Examine (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	Unknown					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	Unknown					Enc	3,474				
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-016		Fuel Manifold - Inspect/Examine (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	Unknown					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	Unknown					Enc	3,474				
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-017		Fuel Filter - Inspect and replace (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
		Ref:73-10-05 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
73-00-PW-017		Fuel Filter - Inspect and replace (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
		Ref:73-10-05 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
73-00-PW-018		Fuel Shut-off Cable - Do an Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	31J2557-02					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	506					Enc	3,474				
		Ref:CIR Manual P/N 30J2306 (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-018		Fuel Shut-off Cable - Do an Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	31J2557-02					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	488					Enc	3,474				
		Ref:CIR Manual P/N 30J2306 (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-019		Fuel Shut-off Valve - Visual Inspection and Check Freedom of Movement (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	31J2944-01					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	375					Enc	3,474				
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-019		Fuel Shut-off Valve - Visual Inspection and Check Freedom of Movement (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	31J2944-01					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	426					Enc	3,474				
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-020		Engine Wiring Harness - Examine and do a functional test (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	31J2080-05					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	AA17702					Enc	3,474				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-020		Engine Wiring Harness - Examine and do a functional test (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	31J2080-05					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	AA18565					Enc	3,474				
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-021		T1 FCU Sensor - Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	30J1580-04					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	KC-07-11100					Enc	3,474				
	Ref:73-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-021		T1 FCU Sensor - Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	30J1580-04					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	KC-15-2707					Enc	3,474				
	Ref:73-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-022		T0 FCU Sensor - Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
	31J2113-03					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	RTM2521					Enc	3,474				
	Ref:73-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)										
73-00-PW-022		T0 FCU Sensor - Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
	31J2113-03					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	RTJ9438					Enc	3,474				
	Ref:73-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-10-00-201		Hot Section Components (HSI): Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection	≈05-Feb-2026
	73 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
		(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.)				Enc	3,474				
73-10-00-201		Hot Section Components (HSI): Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection	≈24-Sep-2027
	73 ENG2					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
		(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.)				Enc	3,474				
73-10-00-202		External Tubing General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE		EMM - Periodic Inspection	≈08-May-2026
	73 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
73-10-00-202		External Tubing General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	73 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
73-10-00-203		Flexible Tubing General Visual Inspection: For Pre-SB30253 Engine: Every 150 EH but not more than 200 EH. For Post-SB30253 Engine: No action is necessary.						RE (N/A)		EMM - Periodic Inspection	
	73 ENG1					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-10-00-203		Flexible Tubing General Visual Inspection: For Pre-SB30253 Engine: Every 150 EH but not more than 200 EH. For Post-SB30253 Engine: No action is necessary.						RE (N/A)		EMM - Periodic Inspection	
	73 ENG2						Mos				
							Hrs				
							Enc				
73-10-00-204		Fuel Metering and Control Components General Visual Inspection: Do a check for security, leakage (No leakage permitted) and general condition.						RE		EMM - Periodic Inspection	≈08-May-2026
	73 ENG1	72EH0800					Mos	23-Oct-2023			
							Hrs	6740:20	800	-/+25 (7564:40)	821:45 Hrs (+25)
		(NOTE: For FCU's which are Pre-SB30545, comply with SB30545 compliance instructions. For FCU's which are Post-SB30545, no additional action is required.)					Enc	4,451			
73-10-00-204		Fuel Metering and Control Components General Visual Inspection: Do a check for security, leakage (No leakage permitted) and general condition.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	73 ENG2	72EH0800					Mos	25-Oct-2023			
							Hrs	5989:05	800	-/+25 (7683:40)	1528:10 Hrs (+25)
		(NOTE: For FCU's which are Pre-SB30545, comply with SB30545 compliance instructions. For FCU's which are Post-SB30545, no additional action is required.)					Enc	4,015			
73-10-00-205		Fuel Distribution - Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition.						RE		EMM - Periodic Inspection	≈08-May-2026
	73 ENG1	72EH0800					Mos	23-Oct-2023			
							Hrs	6740:20	800	-/+25 (7564:40)	821:45 Hrs (+25)
							Enc	4,451			
73-10-00-205		Fuel Distribution - Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	73 ENG2	72EH0800					Mos	25-Oct-2023			
							Hrs	5989:05	800	-/+25 (7683:40)	1528:10 Hrs (+25)
							Enc	4,015			
73-10-00-206		Fuel Filter Element Detailed Inspection: Do an inspection for foreign material and damage.						RE		EMM - Periodic Inspection	≈08-May-2026
	73 ENG1	72EH0800					Mos	23-Oct-2023			
							Hrs	6740:20	800	-/+25 (7564:40)	821:45 Hrs (+25)
							Enc	4,451			
73-10-00-206		Fuel Filter Element Detailed Inspection: Do an inspection for foreign material and damage.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	73 ENG2	72EH0800					Mos	25-Oct-2023			
							Hrs	5989:05	800	-/+25 (7683:40)	1528:10 Hrs (+25)
							Enc	4,015			
73-10-00-207		Emergency Fuel Shutoff System Detailed Inspection: Do an inspection through hole in the exhaust cone and check for- Security of control lever- Signs of oil leaks or carbon at No.5 bearing area. Do an inspection of cable and linkages. Emergency Fuel Shut-off Pin: Do a dimension check for one time per engine at first access.(Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE		EMM - Periodic Inspection	≈08-May-2026
	73 ENG1	72EH0800					Mos	23-Oct-2023			
							Hrs	6740:20	800	-/+25 (7564:40)	821:45 Hrs (+25)
		(Tol. Adjustment: 24.3 Hrs)					Enc	4,451			
73-10-00-207		Emergency Fuel Shutoff System Detailed Inspection: Do an inspection through hole in the exhaust cone and check for- Security of control lever- Signs of oil leaks or carbon at No.5 bearing area. Do an inspection of cable and linkages. Emergency Fuel Shut-off Pin: Do a dimension check for one time per engine at first access.(Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE		EMM - Periodic Inspection	≈25-Apr-2028
	73 ENG2	72EH0800					Mos	25-Oct-2023			
							Hrs	5989:05	800	-/+25 (7683:40)	1528:10 Hrs (+25)
							Enc	4,015			
73-10-00-701		Emergency Fuel Shutoff System Operational Check: Removal/Adjustment & Installation (Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE		EMM - Periodic Inspection	≈05-Feb-2026
	73 ENG1						Mos	19-Sep-2017			
							Hrs	4972:48	2,500	-/+25 7472:48	729:53 Hrs (+25)
		(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-10-00-701		Emergency Fuel Shutoff System Operational Check: Removal/Adjustment & Installation (Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection		≈24-Sep-2027
	73 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	2,500	-/+25	7472:48	1317:18 Hrs (+25)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
73-10-00-901		Fuel Filter Element Discard: Install the new fuel filter element.						RE	EMM - Periodic Inspection		≈17-Nov-2024
	73 ENG1					Mos	17-Jun-2021				
						Hrs	5835:52	1,200	-/+25	7035:52	292:57 Hrs (+25)
						Enc	3,890				
73-10-00-901		Fuel Filter Element Discard: Install the new fuel filter element.						RE	EMM - Periodic Inspection		≈06-Jun-2029
	73 ENG2					Mos	29-Sep-2023				
						Hrs	6883:40	1,200	-/+25	8083:40	1928:10 Hrs (+25)
						Enc	4,537				
73-10-00-902		Fuel Distribution (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
73-10-00-902		Fuel Distribution (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
731090		Fuel System - Fuel Flow Divider Valve: Security, Leakage And General Condition						RE (A/R)			
	73 ENG1					Mos	20-Apr-2018				
						Hrs	5179:10				
						Enc	3,564				
731090		Fuel System - Fuel Flow Divider Valve: Security, Leakage And General Condition						RE (A/R)			
	73 ENG2					Mos	20-Apr-2018				
						Hrs	5179:10				
						Enc	3,564				
73-20-00-201		Fuel Controlling - Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets. Examine the cables for sign of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion. Examine the control linkage and rod end bearings for freedom of movement.						RE	EMM - Periodic Inspection		≈08-May-2026
	73 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
73-20-00-201		Fuel Controlling - Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets. Examine the cables for sign of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion. Examine the control linkage and rod end bearings for freedom of movement.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	73 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
73-20-00-901		Fuel Controlling - Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again. (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after wiring harness replacement.						RE	EMM - Periodic Inspection		≈08-May-2026
	73 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	7564:40	821:45 Hrs (+25)
	(Tol. Adjustment: 24.3 Hrs) (SOURCE: PW545A MM (P/N 30J1272))					Enc	4,451				
73-20-00-901		Fuel Controlling - Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again. (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after wiring harness replacement.						RE	EMM - Periodic Inspection		≈21-Jan-2028
	73 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	6883:40	800	-/+25	7589:05	1433:35 Hrs (+25)
	(Tol. Adjustment: -94.6 Hrs) (UPDATE NOTE: PERFORMED AT REPAIR SHOP AND AT ENGINE INSTALLATION) (SOURCE: PW545A MM (P/N 30J1272))					Enc	4,537				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-20-00-902		Fuel Controlling (Engine TBO) Restoration: (Ref. 05-20-00, SCHEDULED MAINTENANCE CHECKS, 3. Engine Accessories at Engine Overhaul).						RE		EMM - Periodic Inspection	≈20-Jan-2033
	73 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
		(SOURCE: PW545A MM (P/N 30J1272))				Enc	3,474				
73-20-00-902		Fuel Controlling (Engine TBO) Restoration: (Ref. 05-20-00, SCHEDULED MAINTENANCE CHECKS, 3. Engine Accessories at Engine Overhaul).						RE		EMM - Periodic Inspection	≈09-Sep-2034
	73 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
		(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.)				Enc	3,474				
▼ 74 - IGNITION											
74-00-PW-001		Ignition Exciter Box - Clean and Examine (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	74 ENG1					Mos	19-Sep-2017				
	500335-1					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	NNA04267603					Enc	3,474				
		Ref:74-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)									
74-00-PW-001		Ignition Exciter Box - Clean and Examine (at Engine Overhaul)						RE		EMM - Requirement	≈17-Jan-2035
	74 ENG2					Mos	21-Jan-2024				
	31J2807-07					Hrs	7050:40	5,000	+100	10100	3944:30 Hrs (+100)
	NNA16050184					Enc	4,651				
		Ref:74-10-01 (Tol. Adjustment: -1950.7 Hrs) (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
74-00-PW-002		Ignition Cable - Examine (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	74 ENG1	Inboard				Mos	19-Sep-2017				
	Unknown					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	Unknown					Enc	3,474				
		Ref:74-20-01-mc (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
74-00-PW-002		Ignition Cable - Examine (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	74 ENG2	Inboard				Mos	27-Sep-2017				
	Unknown					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	Unknown					Enc	3,474				
		Ref:74-20-01-mc (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
74-00-PW-003		Ignition Cable - Examine (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	74 ENG1	Outboard				Mos	19-Sep-2017				
	Unknown					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	Unknown					Enc	3,474				
		Ref:74-20-01-mc (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
74-00-PW-003		Ignition Cable - Examine (at Engine Overhaul)						RE		EMM - Requirement	≈17-Jan-2035
	74 ENG2	Outboard				Mos	21-Jan-2024				
	30J3125-02					Hrs	7050:40	5,000	+100	10100	3944:30 Hrs (+100)
	NNA13180181					Enc	4,651				
		Ref:74-20-01-mc (Tol. Adjustment: -1950.7 Hrs) (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
74-00-PW-004		Inboard Ignition Plug - Clean and Inspect (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	74 ENG1					Mos	19-Sep-2017				
	502600-1					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	NNA17020164					Enc	3,474				
		Ref:74-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)									
74-00-PW-004		Inboard Ignition Plug - Clean and Inspect (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	74 ENG2					Mos	27-Sep-2017				
	30J2825-01					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	NNA11360118					Enc	3,474				
		Ref:74-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
74-00-PW-005		Outboard Ignition Plug - Clean and Inspect (at Engine Overhaul)						RE		EMM - Requirement	≈29-May-2033
	74 ENG1					Mos	16-Aug-2023				
	502600-1					Hrs	6748:50	5,000	+100	10100	3357:05 Hrs (+100)
	13280058					Enc	4,452				
	Ref:74-20-02-mp (Tol. Adjustment: -1648.8 Hrs) (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
74-00-PW-005		Outboard Ignition Plug - Clean and Inspect (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	74 ENG2					Mos	27-Sep-2017				
	30J2825-01					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	NNA11360043					Enc	3,474				
	Ref:74-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
74-20-00-201		Ignition Exciter General Visual Inspection: Do a check for security and general condition.						RE		EMM - Periodic Inspection	≈08-May-2026
	74 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
74-20-00-201		Ignition Exciter General Visual Inspection: Do a check for security and general condition.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	74 ENG2	72EH0800				Mos	21-Jan-2024				
						Hrs	7050:40	800	-/+25	(7683:40)	1528:10 Hrs (+25)
		(Tol. Adjustment: -271.5 Hrs)				Enc	4,651				
74-20-00-202		Igniters (Tip Measurement) Functional Check (Pre-SB30340): Do a check for cleanliness and measure erosion. (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES).						RE		EMM - Periodic Inspection	≈26-May-2024
	74 ENG1					Mos	16-Aug-2023				
						Hrs	6605:30	300	-/+25	6864:40	121:45 Hrs (+25)
		(Tol. Adjustment: -40.8 Hrs) (SOURCE: PW545A MM (P/N 30J1272))				Enc	4,366				
74-20-00-202		Igniters (Tip Measurement) Functional Check (Pre-SB30340): Do a check for cleanliness and measure erosion. (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES).						RE		EMM - Periodic Inspection	≈04-Dec-2026
	74 ENG2					Mos	25-Oct-2023				
						Hrs	6883:40	300	-/+25	7183:40	1028:10 Hrs (+25)
		(UPDATE NOTE: PERFORMED AT ENGINE INSTALLATION AFTER REPAIR (NEW IGNITERS INSTALLED AT REPAIR)) (SOURCE: PW545A MM (P/N 30J1272))				Enc	4,537				
74-20-00-203		Igniters (Tip Measurement) Functional Check (Post-SB30340): Do a check for cleanliness and measure erosion (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES).						RE (N/A)		EMM - Periodic Inspection	
	74 ENG1					Mos	15-Nov-2022				
						Hrs	5964:40				
		(UPDATE NOTE: CRS AEROPARTNER 1411/22) (SOURCE: PW545A MM (P/N 30J1272))				Enc	4,000				
74-20-00-203		Igniters (Tip Measurement) Functional Check (Post-SB30340): Do a check for cleanliness and measure erosion (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES).						RE (N/A)		EMM - Periodic Inspection	
	74 ENG2					Mos	15-Nov-2022				
						Hrs	5964:40				
		(UPDATE NOTE: CRS AEROPARTNER 1411/22) (SOURCE: PW545A MM (P/N 30J1272))				Enc	4,000				
74-20-00-205		Ignition Cables General Visual Inspection: Do a check for chafing, wear and security.						RE		EMM - Periodic Inspection	≈08-May-2026
	74 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
74-20-00-205		Ignition Cables General Visual Inspection: Do a check for chafing, wear and security.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	74 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
74-20-00-206		Ignition (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection	≈05-Feb-2026
	74 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
		(SOURCE: PW545A MM (P/N 30J1272))				Enc	3,474				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
74-20-00-206	74 ENG2	Ignition (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION). (SOURCE: PW545A MM (P/N 30J1272))				Mos	27-Sep-2017	RE	EMM - Periodic Inspection		≈24-Sep-2027
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
						Enc	3,474				
74-20-00-701	74 ENG1	Igniters Operational Check: Do an operational test (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES). 72EH0800				Mos	23-Oct-2023	RE	EMM - Periodic Inspection		≈08-May-2026
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
74-20-00-701	74 ENG2	Igniters Operational Check: Do an operational test (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES). 72EH0800				Mos	25-Oct-2023	RE	EMM - Periodic Inspection		≈25-Apr-2028
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
74-20-00-901	74 ENG1	Ignition (Engine TBO) Restoration: (Ref. 05-20-00, SCHEDULED MAINTENANCE CHECKS, 3. Engine Accessories at Engine Overhaul). (SOURCE: PW545A MM (P/N 30J1272))				Mos	19-Sep-2017	RE	EMM - Periodic Inspection		≈20-Jan-2033
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
74-20-00-901	74 ENG2	Ignition (Engine TBO) Restoration: (Ref. 05-20-00, SCHEDULED MAINTENANCE CHECKS, 3. Engine Accessories at Engine Overhaul). (SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.)				Mos	27-Sep-2017	RE	EMM - Periodic Inspection		≈09-Sep-2034
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
▼ 75 - BLEED AIR											
75-00-PW-001	75 ENG1	EEC - Inspection (at Engine Overhaul) (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Mos	19-Sep-2017	RE	EMM - Requirement		≈20-Jan-2033
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
75-00-PW-001	75 ENG2	EEC - Inspection (at Engine Overhaul) (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Mos	27-Sep-2017	RE	EMM - Requirement		≈09-Sep-2034
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
75-00-PW-002	75 ENG1 540-0406-4 2500 (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 1. The accessories have the same TBO as the engine. If the accessories was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessories are operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).)	Anti-Icing Valve - Overhaul or Refurbish (at Engine Overhaul)				Mos	19-Sep-2017	RE	EMM - Requirement		≈20-Jan-2033
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
75-00-PW-002	75 ENG2 540-0406-4 2594 (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Anti-Icing Valve - Overhaul or Refurbish (at Engine Overhaul)				Mos	27-Sep-2017	RE	EMM - Requirement		≈09-Sep-2034
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
75-00-PW-003	75 ENG1 31J2374-05 AMA0708 Ref:75-30-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)	P3 Air Inertial Separator - Inspect/Examine (at Engine Overhaul)				Mos	19-Sep-2017	RE	EMM - Requirement		≈20-Jan-2033
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
75-00-PW-003		P3 Air Inertial Separator - Inspect/Examine (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	75 ENG2					Mos	27-Sep-2017				
	31J2374-04					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	0424					Enc	3,474				
	Ref:75-30-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-005		BOV Torque Motor - Replace with new (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	75 ENG1					Mos	19-Sep-2017				
	30J2596-01					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	39A939					Enc	3,474				
	(SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE 1: The accessories have the same TBO as the engine. If the accessory was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessory is operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).)										
75-00-PW-005		BOV Torque Motor - Replace with new (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	75 ENG2					Mos	27-Sep-2017				
	30J2595-01					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	41A425					Enc	3,474				
	(SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE 1: The accessories have the same TBO as the engine. If the accessory was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessory is operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).)										
75-00-PW-005		Compressor Air Bleed Valve - Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	75 ENG1					Mos	19-Sep-2017				
	30J2596-01					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	39A939					Enc	3,474				
	Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)										
75-00-PW-005		Compressor Air Bleed Valve - Inspection (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	75 ENG2					Mos	27-Sep-2017				
	30J2595-01					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	41A425					Enc	3,474				
	Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)										
75-00-PW-006		Linear Variable Differential Transformer (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	75 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
	(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-006		Linear Variable Differential Transformer (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	75 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
	(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-10-00-201		Anti-ice Valve and P3 Anti-ice Tube (Leak Check) General Visual Inspection: Do a check for leakage at P3 air supply to bleed valve, ant-ice valve, anti-ice air tube and FCU.						RE		EMM - Periodic Inspection	≈08-May-2026
	75 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
75-10-00-201		Anti-ice Valve and P3 Anti-ice Tube (Leak Check) General Visual Inspection: Do a check for leakage at P3 air supply to bleed valve, ant-ice valve, anti-ice air tube and FCU.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	75 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
75-10-00-202		P3 Bellows Seal and Bleed Air Transfer Tube General Visual Inspection: For Pre-SB30196 Engine: - Do a check for cracks.- Replace the P3 bellows on condition (Ref. 72-30-05, GAS GENERATOR CASE - MAINTENANCE PRACTICES).For Post-SB30196 Engine: Do a visual inspection for air leak.						RE	EMM - Periodic Inspection		≈08-May-2026
	75 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
	(Tol. Adjustment: 24.3 Hrs)					Enc	4,451				
75-10-00-202		P3 Bellows Seal and Bleed Air Transfer Tube General Visual Inspection: For Pre-SB30196 Engine: - Do a check for cracks.- Replace the P3 bellows on condition (Ref. 72-30-05, GAS GENERATOR CASE - MAINTENANCE PRACTICES).For Post-SB30196 Engine: Do a visual inspection for air leak.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	75 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
75-10-00-203		Bleed Off Valve General Visual Inspection: Examine the torque motor electrical connection for security, fraying and corrosion.						RE	EMM - Periodic Inspection		≈08-May-2026
	75 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
		(NOTE: NOTE: If Pre-SB30420 intercompressor bleed valve servo valve, then replace it with Post-SB30420 configuration. For Post-SB30126 and Pre-SB30334 Engines comply with SB30335: Do an inspection through BOV bore. For Pre-SB30126 or Post-SB30334 Engines: No action is necessary. For Pre-SB30060 Engines: Do a borescope inspection for vibration damper/thermal insulation blanket on first-stage HPC stator and first-stage and second-stage rotors (Ref. 72-00-00, ENGINE GENERAL - INSPECTION). For Pre-SB30092 and Pre-SB30097 Engine: Do a borescope inspection of the combustion liner and HP turbine vane ring. For Post-SB30060, Post-SB30092 and Post-SB30097 Engines: No action is necessary.)				Enc	4,451				
75-10-00-203		Bleed Off Valve General Visual Inspection: Examine the torque motor electrical connection for security, fraying and corrosion.						RE	EMM - Periodic Inspection		≈25-Apr-2028
	75 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
		(NOTE: NOTE: If Pre-SB30420 intercompressor bleed valve servo valve, then replace it with Post-SB30420 configuration. For Post-SB30126 and Pre-SB30334 Engines comply with SB30335: Do an inspection through BOV bore. For Pre-SB30126 or Post-SB30334 Engines: No action is necessary. For Pre-SB30060 Engines: Do a borescope inspection for vibration damper/thermal insulation blanket on first-stage HPC stator and first-stage and second-stage rotors (Ref. 72-00-00, ENGINE GENERAL - INSPECTION). For Pre-SB30092 and Pre-SB30097 Engine: Do a borescope inspection of the combustion liner and HP turbine vane ring. For Post-SB30060, Post-SB30092 and Post-SB30097 Engines: No action is necessary.)				Enc	4,015				
75-10-00-204		Air System (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈05-Feb-2026
	75 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
75-10-00-204		Air System (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection		≈24-Sep-2027
	75 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
75-10-00-901		Air System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	75 ENG1					Mos	19-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
75-10-00-901		Air System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	75 ENG2					Mos	27-Sep-2017				
						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272))					Enc	3,474				
751080		Air System - Do A Borescope Inspection Of The Combustion Liner And Hp Turbine Vane Ring						RE			≈17-Oct-2024
	75 ENG1					Mos	16-Jan-2023				
						Hrs	6205:20	800	-/+10%	[7005:20]	262:25 Hrs (+80)
						Enc	4,114				
751080		Air System - Do A Borescope Inspection Of The Combustion Liner And Hp Turbine Vane Ring						RE			≈25-Apr-2028
	75 ENG2					Mos	17-Oct-2023				
						Hrs	6883:40	800	-/+10%	7683:40	1528:10 Hrs (+80)
						Enc					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
▼ 76 - ENGINE CONTROLS												
4-50-00-7100		Time Limited Dispatch Fault Visual Check								RE (N/A)	Airworthiness Limitations Inspection Time Limits	
	76 A/F						Mos					
							Hrs					
	(ZONE: 247) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						Ldg					
76-10-00-7200		Left Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5001 thru -5196 Not Incorporating SB560XL-76-03)								RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	76 A/F	5-12-18					Mos					
							Hrs					
	(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)						Ldg					
76-10-00-7200		Right Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5001 thru -5196 Not Incorporating SB560XL-76-03)								RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	76 A/F	5-12-18					Mos					
							Hrs					
	(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)						Ldg					
76-10-00-7201		Left Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 thru -6000, and Airplanes -5001 thru -5196 Incorporating SB560XL-76-03)								RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈24-Nov-2024
	76 A/F	5-12-19					Mos	25-Jan-2024				
							Hrs	7052:40	300	-/+25	(7352:40)	300 Hrs (+25)
	(ZONE: 410) (UPDATE NOTE: CRS ELITE JET 24-042) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	4,653				
76-10-00-7201		Right Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 thru -6000, and Airplanes -5001 thru -5196 Incorporating SB560XL-76-03)								RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈24-Nov-2024
	76 A/F	5-12-19					Mos	25-Jan-2024				
							Hrs	7052:40	300	-/+25	(7352:40)	300 Hrs (+25)
	(ZONE: 420) (UPDATE NOTE: CRS ELITE JET 24-042) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	4,653				
▼ 77 - ENGINE INDICATING												
77-00-PW-001		N1 Speed Sensor - Inspection (at Engine Overhaul)								RE	EMM - Requirement	≈20-Jan-2033
	77 ENG1						Mos	19-Sep-2017				
	31J2072-01						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	CH672						Enc	3,474				
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)												
77-00-PW-001		N1 Speed Sensor - Inspection (at Engine Overhaul)								RE	EMM - Requirement	≈09-Sep-2034
	77 ENG2						Mos	27-Sep-2017				
	31J2072-01						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	CH733						Enc	3,474				
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)												
77-00-PW-002		N2 Speed Sensor - Inspection (at Engine Overhaul)								RE	EMM - Requirement	≈20-Jan-2033
	77 ENG1						Mos	19-Sep-2017				
	31J2073-01						Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	CH1547						Enc	3,474				
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.)												
77-00-PW-002		N2 Speed Sensor - Inspection (at Engine Overhaul)								RE	EMM - Requirement	≈09-Sep-2034
	77 ENG2						Mos	27-Sep-2017				
	31J2073-01						Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	CH1620						Enc	3,474				
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)												

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
77-00-PW-003		T6 Harness and Thermocouples - Inspect and do a functional check (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	77 ENG1					Mos	19-Sep-2017				
		Ref:77-20-02 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
77-00-PW-003		T6 Harness and Thermocouples - Inspect and do a functional check (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	77 ENG2					Mos	27-Sep-2017				
		Ref:77-20-02 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
77-00-PW-004		T1 Harness - Inspect and do a functional check (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	77 ENG1					Mos	19-Sep-2017				
		Ref:77-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
77-00-PW-004		T1 Harness - Inspect and do a functional check (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	77 ENG2					Mos	27-Sep-2017				
		Ref:77-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
77-00-PW-005		Data Collection Unit - Download data (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	77 ENG1					Mos	19-Sep-2017				
	30J1557-01					Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	DP01-1447					Enc	3,474				
		(SOURCE: EMM 05-20-00 Par. 3 Table 1) (NOTE: NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM., NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace)									
77-00-PW-005		Data Collection Unit - Download data (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	77 ENG2					Mos	27-Sep-2017				
	30J1557-01					Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	DP01-1526					Enc	3,474				
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)									
77-10-00-201		Engine Indicating (N1, N2, and ITT) - Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets, cables for signs of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion.						RE		EMM - Periodic Inspection	≈08-May-2026
	77 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
77-10-00-201		Engine Indicating (N1, N2, and ITT) - Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets, cables for signs of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	77 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
77-10-00-202		Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection	≈05-Feb-2026
	77 ENG1					Mos	19-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
						Enc	3,474				
77-10-00-202		Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection	≈24-Sep-2027
	77 ENG2					Mos	27-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
						Enc	3,474				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
77-10-00-901		Engine Indicating (N1, N2, and ITT) - Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after the replacement of wiring harness (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST).						RE	EMM - Periodic Inspection		≈08-May-2026
	77 ENG1	72EH0800				Mos	23-Oct-2023				
		(Tol. Adjustment: 24.3 Hrs)				Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
77-10-00-901		Engine Indicating (N1, N2, and ITT) - Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after the replacement of wiring harness (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST).						RE	EMM - Periodic Inspection		≈25-Apr-2028
	77 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
77-10-00-902		Engine Indicating Speed Sensor System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033
	77 ENG1					Mos	19-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
77-10-00-902		Engine Indicating Speed Sensor System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034
	77 ENG2					Mos	27-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
▼ 78 - EXHAUST											
12-20-78-6400		Left Thrust Reverser Guide Rod (D-5100NS Aerosol Spray Method) Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈24-Nov-2024
	78 A/F	5-12-19				Mos	25-Jan-2024				
		(ZONE: 410) (UPDATE NOTE: CRS ELITE JET 24-042) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	7052:40	300	-/+25	(7352:40)	300 Hrs (+25)
						Ldg	4,653				
12-20-78-6400		Right Thrust Reverser Guide Rod (D-5100NS Aerosol Spray Method) Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈24-Nov-2024
	78 A/F	5-12-19				Mos	25-Jan-2024				
		(ZONE: 420) (UPDATE NOTE: CRS ELITE JET 24-042) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	7052:40	300	-/+25	(7352:40)	300 Hrs (+25)
						Ldg	4,653				
12-20-78-6401		Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and On)						RE	05-10-01, 05-10-02, 05-12-00, Category 6		≈24-Nov-2024
	78 A/F	Left5-12-19				Mos	25-Jan-2024				
	64ND-78002-3 373					Hrs	7052:40	300	-/+25	(7352:40)	300 Hrs (+25)
		MRBR Task:78-30-00-602 (ZONE: 410) (UPDATE NOTE: CRS ELITE JET 24-042) (SOURCE: 560XL MM) (NOTE: This task gives a Thrust Reverser Pivot Point Lubrication method that is an alternate to Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication which is completed at a 600 Flight Hour interval. It is not required to complete this task if Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication is currently being followed.)				Ldg	4,653				
12-20-78-6401		Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and On)						RE	05-10-01, 05-10-02, 05-12-00, Category 6		≈24-Nov-2024
	78 A/F	Right5-12-19				Mos	25-Jan-2024				
	64ND-78002-4 382					Hrs	7052:40	300	-/+25	(7352:40)	300 Hrs (+25)
		MRBR Task:78-30-00-602 (ZONE: 420) (UPDATE NOTE: CRS ELITE JET 24-042) (SOURCE: 560XL MM) (NOTE: This task gives a Thrust Reverser Pivot Point Lubrication method that is an alternate to Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication which is completed at a 600 Flight Hour interval. It is not required to complete this task if Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication is currently being followed.)				Ldg	4,653				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
12-20-78-6402		Left Thrust Reverser Pivot Point (C-5A Anti-Seize Method) Lubrication (Airplanes -5001 and On)						RE (N/A)	05-10-01, 05-10-02, Category 6		
	78 A/F	5-12-02				Mos					
		MRBR Task:78-30-00-603 (ZONE: 410) (SOURCE: 560XL MM) (NOTE: NOTE: This task is not required if the Thrust Reverser Pivot Point (WC-393 Method) Lubrication is used)				Hrs					
						Ldg					
12-20-78-6402		Right Thrust Reverser Pivot Point (C-5A Anti-Seize Method) Lubrication (Airplanes -5001 and On)						RE (N/A)	05-10-01, 05-10-02, Category 6		
	78 A/F	5-12-02				Mos					
		MRBR Task:78-30-00-603 (ZONE: 420) (SOURCE: 560XL MM) (NOTE: NOTE: This task is not required if the Thrust Reverser Pivot Point (WC-393 Method) Lubrication is used)				Hrs					
						Ldg					
78-10-00-201		Exhaust and Mixer: GVI obvious signs of damage or loose debris.						RE (PreFlight)	EMM - Periodic Inspection		
	78 ENG1	72EH0000				Mos					
						Hrs					
						Enc					
78-10-00-201		Exhaust and Mixer: GVI obvious signs of damage or loose debris.						RE (PreFlight)	EMM - Periodic Inspection		
	78 ENG2	72EH0000				Mos					
						Hrs					
						Enc					
78-10-00-201		Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection	≈05-Feb-2026	
	78 ENG1					Mos	19-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	2,500	+50	7472:48	729:53 Hrs (+50)
						Enc	3,474				
78-10-00-201		Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection	≈24-Sep-2027	
	78 ENG2					Mos	27-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	2,500	+50	7472:48	1317:18 Hrs (+50)
						Enc	3,474				
78-10-00-202		Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an inspection through hole in theexhaust cone for - Security of control lever - Signs of oil leaks or carbon at No.5 bearing area - Examine the cable and linkages.						RE	EMM - Periodic Inspection	≈17-Jan-2028	
	78 ENG1					Mos	16-Aug-2023				
		(Tol. Adjustment: -32.7 Hrs)				Hrs	6605:30	1,600	-/+25	8172:48	1429:53 Hrs (+25)
						Enc	4,366				
78-10-00-202		Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an inspection through hole in theexhaust cone for - Security of control lever - Signs of oil leaks or carbon at No.5 bearing area - Examine the cable and linkages.						RE	EMM - Periodic Inspection	≈05-Sep-2029	
	78 ENG2					Mos	10-Oct-2023				
		(Tol. Adjustment: -310.9 Hrs)				Hrs	6883:40	1,600	-/+25	8172:48	2017:18 Hrs (+25)
						Enc	4,537				
78-10-00-901		Turbine Exhaust Case and Mixer (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection	≈20-Jan-2033	
	78 ENG1					Mos	19-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
78-10-00-901		Turbine Exhaust Case and Mixer (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection	≈09-Sep-2034	
	78 ENG2					Mos	27-Sep-2017				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
78-31-00-2200		Thrust Reverser Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Dec-2027	
	78 A/F	Left5-12-07				Mos	29-Sep-2023				
	64ND-78002-3					Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)
	373					Ldg	4,505				
	(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)										

Task No		Description							Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
78-31-00-2200		Thrust Reverser Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈04-Dec-2027	
	78 A/F	Right5-12-07				Mos	29-Sep-2023					
	64ND-78002-4					Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)	
	382					Ldg	4,505					
	(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)											
78-31-00-7200		Thrust Reverser Assembly Functional Check and Operational Check						RE	05-10-01, 05-10-02, Category 6, Category 9		≈04-Dec-2027	
	78 A/F	Left5-12-07				Mos	29-Sep-2023					
	64ND-78002-3					Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)	
	373					Ldg	4,505					
	MRBR Task:78-30-00-701, MRBR Task:78-30-00-702 (ZONE: 410, 235) (SOURCE: 560XL MM)											
78-31-00-7200		Thrust Reverser Assembly Functional Check and Operational Check						RE	05-10-01, 05-10-02, Category 6, Category 9		≈04-Dec-2027	
	78 A/F	Right5-12-07				Mos	29-Sep-2023					
	64ND-78002-4					Hrs	6839:30	1,600	-/+25	(8439:30)	1386:50 Hrs (+25)	
	382					Ldg	4,505					
	MRBR Task:78-30-00-701, MRBR Task:78-30-00-702 (ZONE: 420, 235) (SOURCE: 560XL MM)											
▼ 79 - OIL												
790020		Change Oil						RE (A/R)				
	79 ENG1						Mos	04-Mar-2014				
							Hrs	3817:18				
							Enc	2,863				
790020		Change Oil						RE (A/R)				
	79 ENG2						Mos	04-Mar-2014				
							Hrs	3817:18				
							Enc	2,863				
790020-1		CHANGE OIL BRAND - PERFORM TRANSFER FROM OIL 2380 TO MOBILJET (DB0373)						RE (-)				
	79 ENG1						Mos	23-Oct-2023				
							Hrs	6740:20				
							Enc	4,451				
79-00-PW-001		Oil Filter Differential Pressure Switch - Examine and do a functional test (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033	
	79 ENG1						Mos	19-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
							Enc	3,474				
79-00-PW-001		Oil Filter Differential Pressure Switch - Examine and do a functional test (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034	
	79 ENG2						Mos	27-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
							Enc	3,474				
79-00-PW-002		Chip Detector/Collector - Examine (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033	
	79 ENG1 30J2027-01 AB0152						Mos	19-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
							Enc	3,474				
Ref:79-30-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)												
79-00-PW-002		Chip Detector/Collector - Examine (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034	
	79 ENG2 ST3753-02 AB0035						Mos	27-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
							Enc	3,474				
Ref:79-30-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)												

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-00-PW-003		Oil Tank Filler Cap - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	79 ENG1					Mos	19-Sep-2017				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
79-00-PW-003		Oil Tank Filler Cap - Overhaul or Refurbish (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	79 ENG2					Mos	27-Sep-2017				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
79-00-PW-004		Oil Level Indicator (sight glass) - Inspect (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	79 ENG1					Mos	19-Sep-2017				
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
79-00-PW-004		Oil Level Indicator (sight glass) - Inspect (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	79 ENG2					Mos	27-Sep-2017				
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
79-00-PW-005		Oil Filter - Examine and replace (at Engine Overhaul)						RE		EMM - Requirement	≈20-Jan-2033
	79 ENG1					Mos	19-Sep-2017				
		Ref:79-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
						Enc	3,474				
79-00-PW-005		Oil Filter - Examine and replace (at Engine Overhaul)						RE		EMM - Requirement	≈09-Sep-2034
	79 ENG2					Mos	27-Sep-2017				
		Ref:79-20-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
						Enc	3,474				
79-10-00-201		External Oil Tube General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE		EMM - Periodic Inspection	≈08-May-2026
	79 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
79-10-00-201		External Oil Tube General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	79 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
79-10-00-202		Oil System - Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition. No leakage permitted.						RE		EMM - Periodic Inspection	≈08-May-2026
	79 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
79-10-00-202		Oil System - Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition. No leakage permitted.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	79 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
79-10-00-203		Accessory Gear Box Pad Seal General Visual Inspection: Examine the pad seals for oil leaks.						RE		EMM - Periodic Inspection	≈08-May-2026
	79 ENG1	72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
79-10-00-203		Accessory Gear Box Pad Seal General Visual Inspection: Examine the pad seals for oil leaks.						RE		EMM - Periodic Inspection	≈25-Apr-2028
	79 ENG2	72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-10-00-204	79 ENG1	Oil System - External Engine General Visual Inspection: Examine for fuel and oil leaks, corrosion, cracks and signs of damage.						RE	EMM - Periodic Inspection	≈08-May-2026	
		72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
79-10-00-204	79 ENG2	Oil System - External Engine General Visual Inspection: Examine for fuel and oil leaks, corrosion, cracks and signs of damage.						RE	EMM - Periodic Inspection	≈25-Apr-2028	
		72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
79-10-00-205	79 ENG1	Oil Filter Detailed Inspection: Remove and do a check for foreign material and damage.						RE	EMM - Periodic Inspection	≈08-May-2026	
		72EH0800				Mos	23-Oct-2023				
						Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
79-10-00-205	79 ENG2	Oil Filter Detailed Inspection: Remove and do a check for foreign material and damage.						RE	EMM - Periodic Inspection	≈25-Apr-2028	
		72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
79-10-00-206	79 ENG1	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass.						RE (Preflight)	EMM - Periodic Inspection		
		72EH0000				Mos					
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs					
						Enc					
79-10-00-206	79 ENG2	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass.						RE (Preflight)	EMM - Periodic Inspection		
		72EH0000				Mos					
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs					
						Enc					
79-10-00-206/601	79 ENG1	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. Monitor the oil quality on condition and do analysis periodically as observations warrant (Ref. 72-00-00, ENGINE, GENERAL - SERVICING).						RE	EMM - Periodic Inspection	≈08-May-2026	
		72EH0800				Mos	23-Oct-2023				
		(Tol. Adjustment: 24.3 Hrs)				Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				
79-10-00-206/601	79 ENG2	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. Monitor the oil quality on condition and do analysis periodically as observations warrant (Ref. 72-00-00, ENGINE, GENERAL - SERVICING).						RE	EMM - Periodic Inspection	≈25-Apr-2028	
		72EH0800				Mos	25-Oct-2023				
						Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
						Enc	4,015				
79-10-00-207	79 ENG1	Oil Filter Bypass Valve Functional Check (Ref. 79-30-02, OIL PRESSURE SWITCH-MAINTENANCE PRACTICES - INSPECTION).						RE	EMM - Periodic Inspection	≈02-Sep-2026	
		(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.)				Mos	20-Apr-2018				
						Hrs	5179:10	2,500	+50	7679:10	936:15 Hrs (+50)
						Enc	3,564				
79-10-00-207	79 ENG2	Oil Filter Bypass Valve Functional Check (Ref. 79-30-02, OIL PRESSURE SWITCH-MAINTENANCE PRACTICES - INSPECTION).						RE	EMM - Periodic Inspection	≈20-Apr-2028	
		(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.)				Mos	20-Apr-2018				
						Hrs	5179:10	2,500	+50	7679:10	1523:40 Hrs (+50)
						Enc	3,564				
79-10-00-208/209	79 ENG1	Magnetic Chip Detector/Collector General Visual Inspection: (Ref. 79-30-01, CHIP DETECTION-MAINTENANCE PRACTICES - REMOVAL/INSTALLATION). Remove and do a check for metallic debris.						RE	EMM - Periodic Inspection	≈08-May-2026	
		72EH0800				Mos	23-Oct-2023				
		(SOURCE: PW545A MM (P/N 30J1272))				Hrs	6740:20	800	-/+25	(7564:40)	821:45 Hrs (+25)
						Enc	4,451				

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
79-10-00-208/209		Magnetic Chip Detector/Collector General Visual Inspection: (Ref. 79-30-01, CHIP DETECTION-MAINTENANCE PRACTICES - REMOVAL/INSTALLATION). Remove and do a check for metallic debris.						RE	EMM - Periodic Inspection		≈25-Apr-2028	
	79 ENG2	72EH0800					Mos	25-Oct-2023				
							Hrs	5989:05	800	-/+25	(7683:40)	1528:10 Hrs (+25)
	(SOURCE: PW545A MM (P/N 30J1272))						Enc	4,015				
79-10-00-901		Oil Filter Discard: Install the new oil filter element.						RE	EMM - Periodic Inspection		≈17-Nov-2024	
	79 ENG1						Mos	17-Jun-2021				
							Hrs	5835:52	1,200	-/+25	7035:52	292:57 Hrs (+25)
	(SOURCE: PW545A MM (P/N 30J1272))						Enc	3,890				
79-10-00-901		Oil Filter Discard: Install the new oil filter element.						RE	EMM - Periodic Inspection		≈06-Jun-2029	
	79 ENG2						Mos	25-Oct-2023				
							Hrs	6883:40	1,200	-/+25	8083:40	1928:10 Hrs (+25)
	(UPDATE NOTE: NEW FILTERS PROVIDED AT ENGINE EPAIR) (SOURCE: PW545A MM (P/N 30J1272))						Enc	4,537				
79-10-00-902		Engine Restoration (TBO): Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈20-Jan-2033	
	79 ENG1						Mos	19-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48	3229:53 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.)						Enc	3,474				
79-10-00-902		Engine Restoration (TBO): Do the engine restoration at an approved facility IAW PW545A per Overhaul Manual P/N 30J1273.						RE	EMM - Periodic Inspection		≈09-Sep-2034	
	79 ENG2						Mos	19-Sep-2017				
							Hrs	4972:48	5,000	+100	9972:48	3817:18 Hrs (+100)
	(SOURCE: PW545A MM (P/N 30J1272)) (NOTE: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.)						Enc	3,474				
▼ 80 - STARTING												
80-10-00-9600		Engine Starter - Generator (Bearings Discard and Armature Functional Check) Restoration						RE	05-10-01, 05-10-02, Category 6		≈25-Aug-2024	
	80 A/F	Left					Mos	17-Feb-2023				
	300SGL138Q-4						Hrs	6263	1,000	-/+25	7263	210:20 Hrs (+25)
	S00137						Ldg	4,148				
MRBR Task:80-10-00-901 (SOURCE: 560XL MM)												
80-10-00-9600		Engine Starter - Generator (Bearings Discard and Armature Functional Check) Restoration						RE	05-10-01, 05-10-02, Category 6		≈25-Aug-2024	
	80 A/F	Right					Mos	17-Feb-2023				
	300SGL138Q-4						Hrs	6263	1,000	-/+25	7263	210:20 Hrs (+25)
	8694XL						Ldg	4,148				
MRBR Task:80-10-00-901 (SOURCE: 560XL MM)												
80-11-00-2200		Auxiliary Power Unit Starter - Generator Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈13-Mar-2025	
	80 A/F						Mos	29-Sep-2023				
	300SGL138Q-6						Hrs	6839:30				
	S00115						Ldg	4,505				
	(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) (NOTE: NOTE:Per Supplier Recommendation. Reference Skurka Aerospace Incorporated 300SGL Series Installation Maintenance Manual.)						Hrs (APU)	1944	500	-/+25	2444	415 Hrs(APU) (+25)
80-11-00-9600		Auxiliary Power Unit Starter - Generator (Bearings Discard and Armature Functional Check) Restoration						RE	05-10-01, 05-10-02, Category 9		≈03-Aug-2025	
	80 A/F						Mos	03-Sep-2019				
	300SGL138Q-6						Hrs	5869:24				
	S00115						Ldg	3,898				
	MRBR Task:80-10-00-902 (SOURCE: 560XL MM)						Hrs	1584:12	1,000	-/+25	2584:12	555:12 Hrs(APU) (+25)
			0				Hrs (APU)					

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining			
▼ 90 - GENERAL - SUPPLEMENTAL TYPE CERTIFICATE (STC)														
CLS-22-C560-AC313		COCKPIT CONTROLS, INDICATING AND DIMMING INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.1														
90 A/F							Mos	29-Sep-2023	24	-/+1m	[29-Sep-2025] 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	[7139:30] 86:50 Hrs (+25)			
(NOTE: MCAC CERTIFICATE AC313-9910 REV.0)							Ldg	4,505						
CLS-22-C560-AC313		DME ANTENNA INSTALLATION F.S.203 INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.10														
90 A/F							Mos	29-Sep-2023	24	-/+1m	29-Sep-2025 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	7139:30 86:50 Hrs (+25)			
							Ldg	4,505						
CLS-22-C560-AC313		TRANSPONDER ANTENNA INSTALLATION INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.11														
90 A/F							Mos	29-Sep-2023	24	-/+1m	29-Sep-2025 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	7139:30 86:50 Hrs (+25)			
							Ldg	4,505						
CLS-22-C560-AC313		VHF ANTENNA INSTALLATION INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.12														
90 A/F							Mos	29-Sep-2023	24	-/+1m	29-Sep-2025 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	7139:30 86:50 Hrs (+25)			
							Ldg	4,505						
CLS-22-C560-AC313		UHF ANTENNA INSTALLATION INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.13														
90 A/F							Mos	29-Sep-2023	24	-/+1m	29-Sep-2025 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	7139:30 86:50 Hrs (+25)			
							Ldg	4,505						
CLS-22-C560-AC313		VHF/UHF ANTENNA INSTALLATION INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.14														
90 A/F							Mos	29-Sep-2023	24	-/+1m	29-Sep-2025 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	7139:30 86:50 Hrs (+25)			
							Ldg	4,505						
CLS-22-C560-AC313		GPS ANTENNA INSTALLATION F.S.450.0 INSPECTION								RE	≈21-Apr-2024			
ATP25.0113.15														
90 A/F							Mos	29-Sep-2023	24	-/+1m	29-Sep-2025 1.7 Years (+30 Days)			
							Hrs	6839:30	300	-/+25	7139:30 86:50 Hrs (+25)			
							Ldg	4,505						
CLS-22-C560-AC313		TNC BULKHEAD CONNECTOR INSTALLATION CHECK								T	≈05-Apr-2072			
ATP25.0113.16														
90 A/F							Mos	03-Sep-2022						
							Hrs	5999:12						
							Ldg	3,967	18,000	21,967	17,314 Ldg			
CLS-22-C560-AC313		NAV ANTENNA INSTALLATION CHECK								T	≈15-Oct-2160			
ATP25.0113.17														
90 A/F							Mos	03-Sep-2022						
							Hrs	5999:12						
							Ldg	3,967	49,800	53,767	49,114 Ldg			
CLS-22-C560-AC313		UHF ANTENNA INSTALLATION CHECK								T	≈15-Dec-2189			
ATP25.0113.18														
90 A/F							Mos	03-Sep-2022						
							Hrs	5999:12						
							Ldg	3,967	85,000	88,967	84,314 Ldg			

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
CLS-22-C560-AC313 ATP25.0113.19		OMNISTAR ANTENNA INSTALLATION CHECK						T			≈15-Dec-2189	
90 A/F					Mos	03-Sep-2022						
					Hrs	5999:12						
					Ldg	3,697	150,000			153,697	149,044 Ldg	
CLS-22-C560-AC313 ATP25.0113.2		RIGHT HAND CIRCUIT BREAKER PANEL INSPECTION						RE			≈21-Apr-2024	
90 A/F		(NOTE: MCAC CERTIFICATE AC313-9910 REV.0)			Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						
CLS-22-C560-AC313 ATP25.0113.20		GPS ANTENNA CHECK						T			≈15-Dec-2189	
90 A/F					Mos	03-Sep-2022						
					Hrs	5999:12						
					Ldg	3,697	150,000			153,697	149,044 Ldg	
CLS-22-C560-AC313 ATP25.0113.21		FUSELAGE SIDE SKIN CONNECTORS CHECK						T			≈15-Dec-2189	
90 A/F					Mos	03-Sep-2022						
					Hrs	5999:12						
					Ldg	3,967	150,000			153,967	149,314 Ldg	
CLS-22-C560-AC313 ATP25.0113.3		RIGHT HAND SIDE INNER SIDE PANEL INSPECTION						RE			≈21-Apr-2024	
90 A/F					Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						
CLS-22-C560-AC313 ATP25.0113.4		INTERFACE PANEL INSTALLATION INSPECTION						RE			≈21-Apr-2024	
90 A/F					Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						
CLS-22-C560-AC313 ATP25.0113.5		PRINTER PLUG FLOOR PANEL						RE			≈21-Apr-2024	
90 A/F					Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						
CLS-22-C560-AC313 ATP25.0113.6		GLIDE SLOPE ANTENNA INSTALLATION						RE			≈21-Apr-2024	
90 A/F					Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						
CLS-22-C560-AC313 ATP25.0113.7		DME ANTENNA INSTALLATION F.S.78 INSPECTION						RE			≈21-Apr-2024	
90 A/F					Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						
CLS-22-C560-AC313 ATP25.0113.8		ADF ANTENNA INSTALLATION INSPECTION						RE			≈21-Apr-2024	
90 A/F					Mos	29-Sep-2023	24	-/+1m	29-Sep-2025	1.7 Years (+30 Days)		
					Hrs	6839:30	300	-/+25	7139:30	86:50 Hrs (+25)		
					Ldg	4,505						

560XL (Citation Excel) OK-CAA,SN 560-5183

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
CLS-22-C560-AC313 ATP25.0113.9		DUAL MARKERS ANTENNA INSTALLATION INSPECTION						RE			≈21-Apr-2024	
	90 A/F						Mos	29-Sep-2023	24	-/+ 1m	29-Sep-2025	1.7 Years (+30 Days)
							Hrs	6839:30	300	-/+ 25	7139:30	86:50 Hrs (+25)
							Ldg	4,505				
ICA-3832-560 No.1		ADS-B OUT GPS ANTENNA CONNECTOR HOLE INSPECTION						RE			≈28-Sep-2050	
	90 A/F	(UPDATE NOTE: TRANSPONDER ATC GARMIN GTX3000 INSTALLED PER EASA STC 10069146 ADS-B OUT (ELLIOT FAA STC ST0242CH CRS AEROPARTNER 2206/22) (NOTE: REFER TO ELLIOT AVIATION ICA-3832-560 FOR FURTHER INSTRUCTIONS)					Mos	22-Jun-2022				
							Hrs	5998:42				
							Ldg	3,966	10,271		14,237	9,584 Ldg
ICA-3832-560 No.2		ADS-B OUT GPS ANTENNA FASTENER HOLE INSPECTION						RE			≈11-Aug-2035	
	90 A/F	(UPDATE NOTE: TRANSPONDER ATC GARMIN GTX3000 INSTALLED PER EASA STC 10069146 ADS-B OUT (ELLIOT FAA STC ST0242CH CRS AEROPARTNER 2206/22) (NOTE: REFER TO ELLIOT AVIATION ICA-3832-560 FOR FURTHER INSTRUCTIONS)					Mos	22-Jun-2022				
							Hrs	5998:42				
							Ldg	3,966	4,835		8,801	4,148 Ldg
ICA-3832-560 No.3		ADS-B OUT UAT ANTENNA CONNECTOR HOLE INSPECTION						RE			≈20-May-2058	
	90 A/F	(UPDATE NOTE: TRANSPONDER ATC GARMIN GTX3000 INSTALLED PER EASA STC 10069146 ADS-B OUT (ELLIOT FAA STC ST0242CH CRS AEROPARTNER 2206/22) (NOTE: REFER TO ELLIOT AVIATION ICA-3832-560 FOR FURTHER INSTRUCTIONS)					Mos	22-Jun-2022				
							Hrs	5998:42				
							Ldg	3,966	13,016		16,982	12,329 Ldg
ICA-3832-560 No.4		ADS-B OUT UAT ANTENNA FASTENER HOLE						RE			≈07-Dec-2042	
	90 A/F	(UPDATE NOTE: TRANSPONDER ATC GARMIN GTX3000 INSTALLED PER EASA STC 10069146 ADS-B OUT (ELLIOT FAA STC ST0242CH CRS AEROPARTNER 2206/22) (NOTE: REFER TO ELLIOT AVIATION ICA-3832-560 FOR FURTHER INSTRUCTIONS)					Mos	22-Jun-2022				
							Hrs	5998:42				
							Ldg	3,966	7,466		11,432	6,779 Ldg