

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

REG:	Model	SN	Year	ENGINE			Engine Type	Eng s/n					
PH-LPH	EC 120B	1256	2001				ARRIUS 2F	34279					
SB Issue Date	SB	AD Issue Date	MD	EASA-AD DGAC-AD	ACTION	A / NA	INTERVAL	D. DATE	TYPE	REMARK	ACTION TAKEN	DATE	MECH
01-09-2000	A319 73 4808	29-11-2000		F-2000-482(A)	FCU - INCREASE OF THE MAX FUEL FLOW	N/A			MOD		N/A BY P/N FCU		
14-08-2004 29-01-2008	A319 73 4001/7	2-6-1999		F-1999-233(A)	FUEL INJECTOR MANIFOLDS REPLACEMENT	A	400		REPL		SUPERSEDED BY J		
1-10-2003	SL2260/03/24				FCU ADAPTER ATTACHMENT	A			CHK		CHECKED I/A/W SL2260/03/24	17-5-2005	HELI-HOLLAND
6-6-2003	SL 2239/03/ ARRIUS 2F/22	09-07-2003		F-2003-219	ENGINE SERIAL NUMBER 34084 STOLEN	N/A			CHK		BY SERIAL NUMBER		
31-7-2008	319 72 4822B				CENTRIFUGAL DIFFUSER VANE CHECK (RECOMMENDED)	A	500		CHK	FIRST CHECK AT 1500FH	INCORPORATED IN ARRIUS 2F MM	27-5-2016	TURBOMECA
26-4-2005	ALERT FAX 057/05/DSO/TM	25-05-2005		EASA 2005-3868 F-2005-073R1	GROUNDING DUE TO HP BLADE FAILURE	N/A			GND		N/A BY S/N MODULE 2	26-4-2005	HELI-HOLLAND
11-5-2005	A319 73 4823	08-06-2005		EASA 2005-4736 F-2005-088	POSITION OF ADJUSTED FCU FUEL FILTER	N/A	600FH/24MTH		CHK		CANCELLED BY EASA AD 2024-01115-CN	30-8-2011	TURBOMECA
21-06-2005 03-04-2006	A319 79 4802 A319 79 4802R1	20-07-2005		EASA 2005-6069 F-2005-122	REPLACEMENT OF CHECK VALVE PISTON O-RING	A	500		REPL	REPL. BY EASA AD 2006-0141	ASB 319 79 4802 C/W	8-11-2005	HELI-HOLLAND
1-8-2005	SL2359/05/29				ACCIDENT- DELTA PRESSURE DIAPHRAGM CHK FCU SERIAL NUMBER > 260B AND 151M	N/A			CHK	FCU S/N 248M	REPORT TURBOMECA C/W SL2359/05/29	4-8-2002	HELI-HOLLAND
3-8-2005	A319 73 4825	31-08-2005		EASA 2005-6192 F-2005-143R1	FUEL CONTROL UNIT. CHECK AND REPLACEMENT OF THE CONSTANT DELTA P DEVICE DIAPHRAGM	N/A		28-2-2006	REPL	REPL. BY EASA AD 2006-0237	N/A BY FCU S/N 248M	8-8-2005	HELI-HOLLAND
17-3-2006	319 73 4055	09-08-2006		EASA 2006-0237	FCU INCORPORATION OF MODIFICATION TF 55	A		31-7-2007	MOD		C/W MSB 319 73 4055	4-5-2006	HELI-HOLLAND
3-4-2006	A319 79 4802R1	29-05-2006		EASA 2006-0141	REPLACEMENT OF CHECK VALVE PISTON O-RING	N/A	500		REPL	SUPERSEDE 2005-122	Tf 75 C/W	1-7-2009	HISPACOPTER
3-8-2005	A319 73 4825	09-08-2006		EASA 2006-0237	FUEL CONTROL UNIT. CHECK AND REPLACEMENT OF THE CONSTANT DELTA P DEVICE DIAPHRAGM	N/A		31-7-2007	REPL		N/A BY FCU S/N 248M	8-8-2005	HELI-HOLLAND
19-9-2006	319 72 4012B	01-03-2007		EASA 2007-0057	GAS GENERATOR FRONT BEARING	A		30-4-2008	MOD		SUPERSEDED BY EASA AD 2007-0057R1	26-6-2001	HELI-HOLLAND
14-5-2008	319 79 4075B	25-09-2008		EASA 2008-0170	CHECK VALVE WITH SEAL FREE PISTON Tf 75	A		31-5-2009	REPL		C/W I/A/W SB 319 79 4075	1-7-2009	HISPACOPTER
14-5-2008	319 75 4810	17-06-2008		EASA 2008-0134	INSPECTION OF PLAY BETWEEN THE P3 AIR PIPE (FIRST SECTION) AND THE RH REAR HALF-WALL.	A			CHK	SUPS. BY 2008- 134R1	INSPECTED I/A/W SB 319 75 4810	1-7-2009	HISPACOPTER
14-5-2008	319 75 4810	17-02-2009		EASA 2008- 0134R1	INSPECTION OF PLAY BETWEEN THE P3 AIR PIPE (FIRST SECTION) AND THE RH REAR HALF-WALL.	A	100		CHK		SUPERSEDED BY B AND EASA AD 2011-0182	10-11-2008	HELI-HOLLAND
8-9-2009	319 79 4831				LUBRICATION UNIT INSPECTION OF JET BONDING ON EJECTOR ASSEMBLY	A			CHK		INSPECTED I/A/W SB 319 79 4831		
31-5-2010	319 73 4077				ADDITION OF AN AUXILLARY DELTA P VALVE Tf77	N/A		30-10-2010	MOD	SL 2743/09/ ARRIUS2F/47	SUPERSEDED BY B	14-10-2010	HELI-HOLLAND
7-12-2010	319 73 4077B				ADDITION OF AN AUXILLARY DELTA P VALVE Tf77	N/A		30-10-2010	MOD	SL 2743/09/ ARRIUS2F/47	SUPERSEDED BY C	14-10-2010	HELI-HOLLAND
25-1-2011	319 75 4810B	22-09-2011		EASA 2011-0182	INSPECTION OF PLAY BETWEEN THE P3 AIR PIPE (FIRST SECTION) AND THE RH REAR HALF-WALL.	A	100		CHK	CHK WITHIN 100 FH	SUPERSEDED BY AD2011- 0182R1		
18-3-2011	A319 73 4001/J	2-6-1999		F-1999-233(A)	FUEL INJECTOR MANIFOLDS REPLACEMENT	A	400		REPL		SUPERSEDED BY K		
25-1-2011	319 75 4810B	03-02-2012		EASA 2011- 0182R1	INSPECTION OF PLAY BETWEEN THE P3 AIR PIPE (FIRST SECTION) AND THE RH REAR HALF-WALL.	N/A	100		CHK	CHK WITHIN 100 FH	DISTANCE BETWEEN FIRE WALL AND P3 AIRPIPE >0.5 MM	18-1-2012	HELI-HOLLAND
10-2-2012	A319 73 4001/K	2-6-1999		F-1999-233(A)	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	A	400		REPL		SUPERSEDED BY EASA AD 2012-0150		
10-2-2012	A319 73 4001/K	8-8-2012		EASA 2012-0150	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	A	400		REPL		SUPERSEDED BY L		
3-10-2012	319 73 4077C				ADDITION OF AN AUXILLARY DELTA P VALVE Tf77	N/A		30-10-2010	MOD	SL 2743/09/ ARRIUS2F/47	AIRFRAME COMPATIBLE WITH Tf 77,SUPS BY D	14-10-2010	HELI-HOLLAND
17-1-2013	A319 73 4001/L	8-8-2012		EASA 2012-0150	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	A	400		REPL		SUPERSEDED BY M		

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

REG:	Model	SN	Year	ENGINE			Engine Type	Eng s/n						
PH-LPH	EC 120B	1256	2001				ARRIUS 2F	34279						
SB Issue Date	SB	AD Issue Date	MD	EASA-AD DGAC-AD	ACTION	A / NA	INTERVAL	D. DATE	TYPE	REMARK	ACTION TAKEN	DATE	MECH	
21-5-2013	319 79 4831C				LUBRICATION DEVICE. CHECK OF THE NOZZLE BONDING ON THE EJECTOR ASSY	N/A		1-1-2015	CHK	P/N 0319155040	INSPECTED I/A/W SB 319 79 4831	30-10-2013	TURBOMECA	
22-5-2013	319 79 4835	01-10-1013		EASA 2013-0243	LUBRICATION DEVICE. CHECK OF THE NOZZLE BONDING ON THE EJECTOR ASSY	N/A		31-10-2013	CHK	S/N 337M	SUPERSEDED BY B	1-11-2013	HELI-HOLLAND	
1-7-2013	A319 73 4001/M	8-8-2012		EASA 2012-0150	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	A	400		REPL		SUPERSEDED BY N	10-3-2014	HELI-HOLLAND	
17-1-2013	319 73 4083B				RH AND LH INJECTOR HALF MANIFOLDS AND PRIVILEGE INJECTOR PIPE REPLACEMENT Tf 83	A			MOD		MANIFOLDS REPLACED I/A/W Tf 83	14-12-2017	HELI-HOLLAND	
25-11-2013	319 79 4834				LUBRICATION DEVICE - VISUAL INSPECTION OF LUBRICATING DEVICE DRIVE-LINK SPLINES	A		30-9-2018	CHK	CHK WITHIN 500 FH	SUPERSEDED BY B			
2-12-2013	319 73 4077D				ADDITION OF AN AUXILLARY DELTA P VALVE Tf77	N/A		30-10-2010	MOD	SL 2743/09/ ARRIUS2F/47	SUPERSEDED BY E	1-5-2015	HELI-HOLLAND	
21-10-2014	319 79 4834B	7-5-2015		EASA 2015-0049	LUBRICATION DEVICE - VISUAL INSPECTION OF LUBRICATING DEVICE DRIVE-LINK SPLINES	A		30-9-2018	CHK	CHK WITHIN 500 FH	INSPECTED I/A/W SB 319 79 4834	1-5-2015	HELI-HOLLAND	
12-2-2015	319 73 4077E	03-03-2016		EASA 2016-0041	FUEL CONTROL UNIT, MODIFICATION, ADDITION OF AN AUXILLARY DELTA P VALVE Tf77	N/A		17-12-2016	MOD		MOD TF-77 C/W	1-5-2015	HELI-HOLLAND	
12-2-2015	319 79 4835B	01-10-1013		EASA 2013-0243	LUBRICATION DEVICE. CHECK OF THE NOZZLE BONDING ON THE EJECTOR ASSY	N/A		31-10-2013	CHK	S/N 337M	SUPERSEDED BY EASA AD 2015-0057	1-11-2013	HELI-HOLLAND	
2-2-2015	319 73 4837				UPDATING OF THE ENGINE LOG BOOK TO EXTEND THE TBO OF THE ARRIUS 2F PUMP AND METERING VALVE ASSEMBLY, ADJUSTED	A			MOD		UPDATED ENGINE LOGBOOK	1-5-2015	HELI-HOLLAND	
12-2-2015	319 79 4835B	01-04-2015		EASA 2015-0057	LUBRICATION DEVICE. CHECK OF THE NOZZLE BONDING ON THE EJECTOR ASSY	N/A		15-5-2015	CHK	S/N 337M	BY S/N LUBRICATION UNIT	1-11-2013	HELI-HOLLAND	
23-3-2016	319 73 4085				INTRODUCTION OF INSULATING SEALS BELOW THE INJECTOR FLANGE OF INJECTOR MANIFOLDS AND FIRST INJECTOR, MODIFICATION Tf85	A			MOD	INCORPORATE DURING MANIFOLD CHG	INSULATING SEALS FITTED I/A/W SB 319 73 4085, Tf 85 C/W	14-12-2017	HELI-HOLLAND	
17-5-2016	A319 73 4001/N	8-8-2012		EASA 2012-0150	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	N/A	400		REPL		SUPERSEDED BY EASA AD 2016-0138	19-10-2009	HELI-HOLLAND	
17-5-2016	A319 73 4001/N	14-7-2016		EASA 2016-0138	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	N/A	400		REPL		SUPERSEDED BY EASA AD 2016-0138R1	19-10-2009	HELI-HOLLAND	
17-5-2016	A319 73 4001/N	28-7-2016		EASA 2016-0138R1	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	A	400		REPL		SUPERSEDED BY EASA AD 2017-0070	19-10-2009	HELI-HOLLAND	
13-12-2016	319 73 4839				CHECK OF THE PREFERRED INJECTOR PIPE ASSY	A		31-8-2018	REPL		PREF INJECTOR REPLACED I/A/W SB319734439	14-12-2017	HELI-HOLLAND	
17-5-2016	A319 73 4001/N	25-4-2017		EASA 2017-0070	PRIVILEGE INJECTOR MANIFOLD REPLACEMENT	A	400		REPL		INCOMP. IN COMPONENT RECORD & MAINTENANCE MANUAL	19-10-2009	HELI-HOLLAND	
27-11-2017	A319 794840	16-1-2018		EASA 2018-0012-E	INSPECTION OF THE MAGNETIC HEADS OF THE ELECTRICAL MAGNETIC PLUG ASSEMBLIES, PRE MOD TF34 & TF36	N/A		18-2-2018	CHK		FOUND N/A BY P/N & S/N	14-12-2017	HELI-HOLLAND	
19-09-2006 04-05-2016	319 72 4012B 319 72 4084B	26-03-2018		EASA 2007-0057R1	GAS GENERATOR FRONT BEARING	A		30-4-2008	MOD	PERFORM TF12 OR TF84	TF 12A C/W AT FACTORY	26-6-2001	HELI-HOLLAND	
24-1-2022	319 77 4097				PYROMETRIC HARNESS - CHANGE IN THE MATERIAL OF THE THERMOCOUPLE PROBES AND ROUTING MODIFICATION MOD TF97	A			MOD	PERFORM MOD TF18 AT THE SAME TIME				
21-7-2022	319 73 4850				PREFERENCE INJECTOR - PREVENTIVE FLAME-OUT CHK VIA THE PREFERENCE INJECTOR VALVE TEST	N/A		21-01-23	CHK	PERFORM WITHIN 100FH AFTER CHG	TSI PREFERENCE INJECTOR <100FH	28-7-2022	HELI-HOLLAND	
6-3-2023	319 73 4852				FUEL SYSTEM - REPLACEMENT OF THE PREFERENCE INJECTOR	A		06-03-27	REPL	REPLACE WITHIN 400FH				
16-04-2024	319 72 4853				GAS GENERATOR - DECREASE OF THE USE LIMIT OF THE HIGH PRESSURE TURBINE BLADES	N/A	2500CYC	16-05-24	SLL	DECREASE TO 2500 CYC	SUPERSEDED BY B	29-04-2024	HELI-HOLLAND	
11-05-2005	A319 73 4823	21-06-2024		2024-0115-CN	POSITION OF ADJUSTED FCU FUEL FILTER	N/A	600FH/24MTH		CHK		CANCELLATION OF DGAC AD F-2005-088	24-06-2024	HELI-HOLLAND	
10-10-2024	319 72 4853B	18-11-2024		2024-0218	GAS GENERATOR - DECREASE OF THE USE LIMIT OF THE HIGH PRESSURE TURBINE BLADES	N/A	2500CYC	16-05-24	SLL	DECREASE TO 2500 CYC	SUPERSEDED BY C & EASA AD 2024-0218R1	29-04-2024	HELI-HOLLAND	

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

REG:	Model	SN Year		ENGINE			Engine Type	Eng s/n						
PH-LPH	EC 120B	1256	2001				ARRIUS 2F	34279						
SB Issue Date	SB	AD Issue Date	MD	EASA-AD AD	DGAC- AD	ACTION	A / NA	INTERVAL	D. DATE	TYPE	REMARK	ACTION TAKEN	DATE	MECH
21-10-2024	319 73 4854	22-10-2024		2024-0202-E		FUEL CONTROL UNIT - REMOVE FROM SERVICE	N/A		24-11-24	REPL	PERFORM WITHIN 15FH	NOT LISTED IN APPENDIX 1	01-11-2024	HELI-HOLLAND
12-12-2024	319 72 4853C	19-12-2024		2024-0218R1		GAS GENERATOR - DECREASE OF THE USE LIMIT OF THE HIGH PRESSURE TURBINE BLADES	N/A	4500CYC	16-05-24	SLL	DECREASE TO 4500 CYC	NOT LISTED IN APPENDIX 1	29-04-2024	HELI-HOLLAND