

Company

Owner: Time Air
Operator: Time Air

Major Assemblies

Airframe	Beechjet 400XT (Nextant)	RK-295	04-Oct-2023	15050:38 Hrs	11,028 Ldg	3132:02 ACH	
Eng 1	FJ44-3AP	252709	04-Oct-2023	7199:01 Hrs	4,372 Enc	0.3 Oil Up	Fuel Up
Eng 2	FJ44-3AP	252710	04-Oct-2023	7199:01 Hrs	4,372 Enc	0.2 Oil Up	Fuel Up

Additional Information

Program Type: IFA, General Categories: DFDR Installed,Emtq LED Cabin Lighting Instl,Astronics 115 Inverter Installed,(UASC) TAWS A Installed,Interior Cabin Configuration Installation,TAP

Cost:
Man Hrs: 123.6+

Analyst: Laurence Kirk lkirk@traxxall.com

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining	
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS											
05-0T-01	LMM Check Timeair (Operator inspection requirement)						RE				
 5 A/F						Mos	16-Aug-2023	0.5	+10d	31-Aug-2023	OVD
						Hrs	15050:38				
						Ldg	11,028				
05-20-00-814A-300A-A Check 3	Major Periodic Inspections - Check 3						RE (-)		LMM - Requirement		
 5 ENG1						Mos	16-Dec-2014				
						Hrs	1857:06				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Pre SB FJ44-72-132)					Enc	1,110				
05-20-00-814A-300A-A Check 3	Major Periodic Inspections - Check 3						RE (-)		LMM - Requirement		
 5 ENG2						Mos	16-Dec-2014				
						Hrs	1857:06				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Pre SB FJ44-72-132)					Enc	1,110				
05-20-00-814A-300A-A Check 4	Major Periodic Inspections - Check 4						RE (-)		LMM - Requirement		
 5 ENG1						Mos	01-Aug-2018				
						Hrs	4395:48		+50		
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 3 was performed, but no later than 5000 total operating hours (whichever occurs first).)					Enc					
05-20-00-814A-300A-A Check 4	Major Periodic Inspections - Check 4						RE (-)		LMM - Requirement		
 5 ENG2						Mos	01-Aug-2018				
						Hrs	4395:48		+50		
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 3 was performed, but no later than 5000 total operating hours (whichever occurs first).)					Enc					
05-20-00-814A-300A-A Check 5	Major Periodic Inspections - Check 5						RE (-)		LMM - Requirement		
 5 ENG1						Mos	25-May-2022				
						Hrs	6771:07		+50		
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 4 was performed.)					Enc	4,099				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
05-20-00-814A-300A-A Check 5		Major Periodic Inspections - Check 5						RE (-)		LMM - Requirement		
5	 5 ENG2	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 4 was performed.)					Mos	25-May-2022				
							Hrs	6771:07		+50		
							Enc	4,099				
05-20-00-814A-300A-A Check 6		Major Periodic Inspections - Check 6						T		LMM - Requirement	≈15-Sep-2026	
6	 5 ENG1	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 5 was performed, but no later than 5000 hours after Check 4 (whichever occurs first).)					Mos					
							Hrs	0	10,000	+50	[9500]	2300:59 Hrs (+50)
							Enc					
05-20-00-814A-300A-A Check 6		Major Periodic Inspections - Check 6						T		LMM - Requirement	≈28-Jul-2026	
6	 5 ENG2	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 5 was performed, but no later than 5000 hours after Check 4 (whichever occurs first).)					Mos					
							Hrs	10,000	+50	[9395:48]	2196:47 Hrs (+50)	
							Enc					
05-20-00-814A-300A-A Check 7		Major Periodic Inspections - Check 7						T		LMM - Requirement	≈28-Nov-2029	
7	 5 ENG1	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 6 was performed.)					Mos					
							Hrs	0	12,500	+50	[12000]	4800:59 Hrs (+50)
							Enc					
05-20-00-814A-300A-A Check 7		Major Periodic Inspections - Check 7						T		LMM - Requirement	≈10-Oct-2029	
7	 5 ENG2	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 6 was performed.)					Mos					
							Hrs	12,500	+50	[11895:48]	4696:47 Hrs (+50)	
							Enc					
05-20-00-814A-300A-A Check 8		Major Periodic Inspections - Check 8						T		LMM - Requirement	≈10-Feb-2033	
8	 5 ENG1	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 7 was performed, but no later than 5000 hours after Check 6 (whichever occurs first).)					Mos					
							Hrs	0	15,000	+50	[14500]	7300:59 Hrs (+50)
							Enc					
05-20-00-814A-300A-A Check 8		Major Periodic Inspections - Check 8						T		LMM - Requirement	≈23-Dec-2032	
8	 5 ENG2	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Table 3 Major Periodic Inspections for Engine See Table 1 Determination of Major Periodic Inspection Intervals. Perform inspection 2500 engine operating hours after Check 7 was performed, but no later than 5000 hours after Check 6 (whichever occurs first).)					Mos					
							Hrs	15,000	+50	[14395:48]	7196:47 Hrs (+50)	
							Enc					
05-20-00-814A-300A-A-1.1		Routine Periodic Inspection - Pre Flight Check						RE (A/R)		LMM - Requirement		
	5 ENG1	05-0T-01 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Mos	16-Aug-2023		(31-Aug-2023)	OVD	
							Hrs	7199:01				
							Enc	4,372				

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-20-00-814A-300A-A-1.1	Routine Periodic Inspection - Pre Flight Check						RE (A/R)		LMM - Requirement	
5 ENG2	05-0T-01					Mos 16-Aug-2023			(31-Aug-2023)	OVD
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs 7199:01				
						Enc 4,372				
05-20-00-814A-300A-A-1.2	Routine Periodic Inspection - Post Flight Check						RE (A/R)		LMM - Requirement	
5 ENG1						Mos				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Inspection procedure performed after each flight)					Hrs				
						Enc				
05-20-00-814A-300A-A-1.2	Routine Periodic Inspection - Post Flight Check						RE (A/R)		LMM - Requirement	
5 ENG2						Mos				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Inspection procedure performed after each flight)					Hrs				
						Enc				
05-20-00-814A-300A-A-1.4	Routine Periodic Inspection - Check 1						RE		LMM - Requirement	≈15-Oct-2023
5 ENG1						Mos 26-Jul-2022				
	(Manual Adjustment: 0 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs 6920:56	300	+30	7220:56	21:55 Hrs (+30)
						Enc 4,201				
05-20-00-814A-300A-A-1.4	Routine Periodic Inspection - Check 1						RE		LMM - Requirement	≈15-Oct-2023
5 ENG2						Mos 26-Jul-2022				
	(Manual Adjustment: 0 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs 6920:56	300	+30	7220:56	21:55 Hrs (+30)
						Enc 4,201				
05-20-00-814A-300A-A-1.5	Routine Periodic Inspection - Check 2						RE		LMM - Requirement	≈02-Mar-2024
5 ENG1						Mos 26-Jul-2022				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Inspections at every 600 engine operating hours, but no more than 300 engine operating hours after Check 1 was performed (whichever occurs first).)					Hrs 6920:56	600	+30	7520:56	321:55 Hrs (+30)
						Enc 4,201				
05-20-00-814A-300A-A-1.5	Routine Periodic Inspection - Check 2						RE		LMM - Requirement	≈02-Mar-2024
5 ENG2						Mos 26-Jul-2022				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Inspections at every 600 engine operating hours, but no more than 300 engine operating hours after Check 1 was performed (whichever occurs first).)					Hrs 6920:56	600	+30	7520:56	321:55 Hrs (+30)
						Enc 4,201				
05-20-01	Scheduled IFA-200 Hour Special Inspections i.a.w. IFA AMM-supplement and NXT1-ICA						RE			≈21-Dec-2023
5 A/F						Mos 06-Apr-2023				
	(AVG MAN HRS: 18) (Tol. Adjustment: -36.2 Hrs)					Hrs 15050:38	200	+40	15214:28	163:50 Hrs (+40)
						Ldg 11,028				
05-20-02	SCHEDULED IFA-A INSPECTIONS						RE		Scheduled Inspections	
5 A/F						Mos 11-Nov-2022	12		30-Nov-2023	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs 14814:28	400	+40	15214:28	163:50 Hrs (+40)
						Ldg 10,886				
05-20-03	SCHEDULED IFA-B INSPECTIONS						RE		Scheduled Inspections	≈24-Jun-2024
5 A/F						Mos 11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs 14814:28	800	+40	15614:28	563:50 Hrs (+40)
						Ldg 10,886				
05-20-04	SCHEDULED IFA-C INSPECTIONS						RE		Scheduled Inspections	≈10-Jul-2024
5 A/F						Mos 12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs 14049:30	1,600	+40	15649:30	598:52 Hrs (+40)
						Ldg 10,401				
05-20-05	SCHEDULED IFA-D INSPECTIONS						RE		Scheduled Inspections	≈29-Jul-2026
5 A/F						Mos 12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)					Hrs 14049:30	3,200	+40	17249:30	2198:52 Hrs (+40)
						Ldg 10,401				

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
05-20-06 5 A/F	ICA – Interior cabin configuration with 2 place divan, IFA-A inspections i.a.w. doc. AF-528, alternatively AF-479					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886	12 400		RE 30-Nov-2023 15214:28	57 Days 163:50 Hrs (+40)
05-20-07 5 A/F	ICA – Interior cabin configuration with 2 place divan, IFA-B inspections i.a.w. doc. AF-528, alternatively AF-479					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886			RE 15614:28	≈24-Jun-2024 563:50 Hrs (+40)
05-20-08 5 A/F	ICA – Interior cabin configuration with 2 place divan, IFA-C inspections i.a.w. doc. AF-528, alternatively AF-479					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401			RE 15649:30	≈10-Jul-2024 598:52 Hrs (+40)
05-20-09 5 A/F	ICA - EWIS, IFA-B inspections i.a.w. doc. NXT1-ICA-EWIS revision B					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886			RE 15614:28	≈24-Jun-2024 563:50 Hrs (+40)
05-20-10 5 A/F	ICA - EWIS, IFA-C inspections i.a.w. doc. NXT1-ICA-EWIS revision B					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401			RE 15649:30	≈10-Jul-2024 598:52 Hrs (+40)
05-20-11 5 A/F	ICA - NXT1, IFA-A inspections i.a.w. doc. NXT1-ICA					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886	12 400		RE 30-Nov-2023 15214:28	57 Days 163:50 Hrs (+40)
05-20-12 5 A/F	ICA - NXT1, IFA-B inspections i.a.w. doc. NXT1-ICA					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886			RE 15614:28	≈24-Jun-2024 563:50 Hrs (+40)
05-20-13 5 A/F	ICA - NXT1, IFA-C inspections i.a.w. doc. NXT1-ICA					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401			RE 15649:30	≈10-Jul-2024 598:52 Hrs (+40)
05-20-14 5 A/F	ICA - Pro Line 21, IFA-A inspections i.a.w. doc. 373-00-0002					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886	12 400		RE 30-Nov-2023 15214:28	57 Days 163:50 Hrs (+40)
05-20-15 5 A/F	ICA - Pro Line 21, IFA-B inspections i.a.w. doc. 373-00-0002					Mos 11-Nov-2022 Hrs 14814:28 Ldg 10,886			RE 15614:28	≈24-Jun-2024 563:50 Hrs (+40)
05-20-16 5 A/F	ICA - Pro Line 21, IFA-C inspections i.a.w. doc. 373-00-0002					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401			RE 15649:30	≈10-Jul-2024 598:52 Hrs (+40)
05-50-00-01 5 A/F	Hard or Overweight Landing - Inspection (SOURCE: Model 400/400A MM)					Mos Hrs Ldg			RE (A/R) Unscheduled Maintenance Check	
05-50-00-02 5 A/F	Turbulent Air (Including Severe Maneuvers) - Inspection (SOURCE: Model 400/400A MM)					Mos Hrs Ldg			RE (A/R) Unscheduled Maintenance Check	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
05-50-00-03	Lightning Strike - Inspection						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
	(SOURCE: Model 400/400A MM)					Hrs				
						Ldg				
05-50-00-04	Foreign Object Damage Checks - Inspection						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
	(SOURCE: Model 400/400A MM)					Hrs				
						Ldg				
05-50-00-05	High Drag/Side-Load Imbalance - Inspection						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
	(SOURCE: Model 400/400A MM)					Hrs				
						Ldg				
05-50-00-06	Single Generator Operation - Inspection						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
	(SOURCE: Model 400/400A MM)					Hrs				
						Ldg				
05-50-00-07	Air-Speed (Overspeed) Limitations Exceeded - Inspection						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
	(SOURCE: Model 400/400A MM)					Hrs				
						Ldg				
05-50-00-08	Towing Mishaps - Inspection						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
	(SOURCE: Model 400/400A MM)					Hrs				
						Ldg				
05-50-00-09	Accomplish Inspection After Operations In or Around Volcanic Ash						RE (A/R)	Unscheduled Maintenance Check		
 5 A/F						Mos				
						Hrs				
						Ldg				
05-50-00-803A-913A-A	Recommended Maintenance - Polish Fan Rotor						RE (A/R)	LMM - Requirement		
 5 ENG1						Mos				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs				
						Enc				
05-50-00-803A-913A-A	Recommended Maintenance - Polish Fan Rotor						RE (A/R)	LMM - Requirement		
 5 ENG2						Mos				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs				
						Enc				
FJ44-05-002	Engine - Unserviceable Parts - Notification						RE (-)	Informational		
 5 ENG1						Mos				
Eff: 02-Oct-2015	INFORMATIONAL					Hrs				
						Enc				
FJ44-05-002	Engine - Unserviceable Parts - Notification						RE (-)	Informational		
 5 ENG2						Mos				
Eff: 02-Oct-2015	INFORMATIONAL					Hrs				
						Enc				
FJ44-05-002 Rev 3	Engine - Unserviceable Parts - Notification						RE (-)	Informational		
 5 ENG1						Mos	16-Dec-2019			
Eff: 12-Mar-2019 Not Applicable						Hrs	5246:04			
(UPDATE NOTE: NA by P/N) (NOTE: COMPLIANCE: Engines previously in compliance with this service document are compliant with this revision and do not need to perform this revision.)						Enc	3,175			

Task No	Description											Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
FJ44-05-002 Rev 3 	Engine - Unserviceable Parts - Notification											RE (-)	Informational
	5 ENG2					Mos	16-Dec-2019						
	Eff: 12-Mar-2019 Not Applicable					Hrs	5246:04						
	(UPDATE NOTE: NA by P/N) (NOTE: COMPLIANCE: Engines previously in compliance with this service document are compliant with this revision and do not need to perform this revision.)					Enc	3,175						
RH Eng - Oil Filter Kit resample 	i.a.w. WO 19-0554											RE (-)	
	5 A/F					Mos	14-Nov-2019						
						Hrs	13029:33						
	(UPDATE NOTE: P/N of/on 120241 S/N on 1045324)					Ldg	9,781						
TIME AIR 	Work need to be performed i.a.w. Maintenance program TA-400XT-001 Ch.20,Increased flight activity manual supplement and other maintenance manuals in actual revision as needed.											RE (-)	
	5 A/F					Mos							
						Hrs							
						Ldg							
WIPSID-05-1000 	Engine - Unserviceable Parts - Notification											RE (-)	Informational
	5 ENG1					Mos	10-Jan-2021						
	Eff: 07-Mar-2020 Superseded					Hrs	6092:48						
	(UPDATE NOTE: Superseded by revision 1)					Enc	3,685						
WIPSID-05-1000 	Engine - Unserviceable Parts - Notification											RE (-)	Informational
	5 ENG2					Mos	10-Jan-2021						
	Eff: 07-Mar-2020 Superseded					Hrs	6092:48						
	(UPDATE NOTE: Superseded by revision 1)					Enc	3,685						
WIPSID-05-1000 Rev 1 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG1					Mos							
	Eff: 10-Jun-2020					Hrs							
						Enc							
WIPSID-05-1000 Rev 1 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG2					Mos							
	Eff: 10-Jun-2020					Hrs							
						Enc							
WIPSID-05-1000 Rev 2 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG1					Mos							
	Eff: 16-Jul-2021					Hrs							
						Enc							
WIPSID-05-1000 Rev 2 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG2					Mos							
	Eff: 16-Jul-2021					Hrs							
						Enc							
WIPSID-05-1000 Rev 3 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG1					Mos							
	Eff: 03-Mar-2022					Hrs							
						Enc							
WIPSID-05-1000 Rev 3 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG2					Mos							
	Eff: 03-Mar-2022					Hrs							
						Enc							
WIPSID-05-1000 Rev 4 	Engine - Unserviceable Parts - Notification											T (-)	Informational
	5 ENG1					Mos							
	Eff: 26-Sep-2022					Hrs							
						Enc							

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
WIPSID-05-1000 Rev 4  5 ENG2 Eff: 26-Sep-2022	Engine - Unserviceable Parts - Notification						T (-)		Informational	
WIPSID-05-1000 Rev 5  5 ENG1 Eff: 10-Jul-2023	Engine - Unserviceable Parts - Notification						T (A/R)		Informational	
WIPSID-05-1000 Rev 5  5 ENG2 Eff: 10-Jul-2023	Engine - Unserviceable Parts - Notification						T (A/R)		Informational	
WIPSID-05-1003  5 ENG1 Eff: 05-May-2023 (NOTE: EFFECTIVITY: Refer to Par. 1.A. for more information.)	Time Limits/Maintenance Checks - Forms						T (A/R)		Informational	
WIPSID-05-1003  5 ENG2 Eff: 05-May-2023 (NOTE: EFFECTIVITY: Refer to Par. 1.A. for more information.)	Time Limits/Maintenance Checks - Forms						T (A/R)		Informational	
WISL-05-1022  5 ENG1 Eff: 07-Apr-2020	Time Limits/Maintenance Checks - Unserviceable Parts - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
WISL-05-1022  5 ENG2 Eff: 07-Apr-2020	Time Limits/Maintenance Checks - Unserviceable Parts - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
WISL-05-1095  5 ENG1 Eff: 03-May-2022	Time Limits/Maintenance Checks - Airworthiness Limitations - Revision to Line Maintenance Manual						T (-)		Service Letter	
WISL-05-1095  5 ENG2 Eff: 03-May-2022	Time Limits/Maintenance Checks - Airworthiness Limitations - Revision to Line Maintenance Manual						T (-)		Service Letter	
WISL-05-1095 Rev 1  5 ENG1 Eff: 13-Oct-2022	Time Limits/Maintenance Checks - Airworthiness Limitations - Revision to Line Maintenance Manual (This Service Document is No Longer Available)						RE (-)		Service Letter	
WISL-05-1095 Rev 1  5 ENG2 Eff: 13-Oct-2022	Time Limits/Maintenance Checks - Airworthiness Limitations - Revision to Line Maintenance Manual (This Service Document is No Longer Available)						RE (-)		Service Letter	
WISL-05-1149  5 ENG1 Eff: 14-Apr-2023 (NOTE: EFFECTIVITY: Refer to Par.1.A. of this SL for more information.)	Time Limits / Maintenance Checks - Scheduled Maintenance Checks - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
WISL-05-1149  5 ENG2 Eff: 14-Apr-2023 (NOTE: EFFECTIVITY: Refer to Par.1.A. of this SL for more information.)	Time Limits / Maintenance Checks - Scheduled Maintenance Checks - Revision to Line Maintenance Manual						T (A/R)		Service Letter	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 8 - LEVELING AND WEIGHING.										
08-10-01-001	Aircraft Weighing and Balancing (Inform Chiefpilot before MX)						RE			
8 A/F						Mos	24-Jul-2020	48	31-Jul-2024	10 Months
Inspected Date 24-Jul-2020						Hrs	13495:48			
						Ldg	10,084			
▼ 11 - PLACARDS AND MARKINGS										
041101	Emergency Exit Placards - Door handle cover - Replace with new placard in accordance with Chapter 11-30-00 in the Model 400/400A Maintenance Manual						RE			
11 A/F						Yrs	18-Feb-2022	5	[30-Apr-2026]	2.6 Years
						Hrs				
						Ldg				
041102	Emergency Exit Placards - Handle - Replace with new placard in accordance with Chapter 11-30-00 in the Model 400/400A Maintenance Manual						RE			
11 A/F						Yrs	31-May-2021	5	31-May-2026	2.7 Years
						Hrs				
						Ldg				
110100-0101	Emergency Exit Placards (Pull) (Self-Illuminating) - Door Handle Cover						RE		AWL - Life Limit	
11 A/F						Yrs	18-Feb-2022	5	30-Apr-2026	2.6 Years
758-14-1						Hrs	14572:58			
45613						Ldg	10,722			
Manufactured Date 30-Apr-2021										
MM:041101 (SOURCE: Maintenance Manual 040002)										
110200-0101	Emergency Exit Placards (Pull) (Self-Illuminating) - Door Handle						RE		AWL - Life Limit	
11 A/F						Yrs	18-Feb-2022	5	31-May-2026	2.7 Years
758-14-1						Hrs	14572:58			
45704						Ldg	10,722			
Manufactured Date 31-May-2021										
MM:041102 (SOURCE: Maintenance Manual 040002)										
11-2012-02 Rev BB	Nextant - Replacement of Production Data Plate						RE (-)		Mandatory	
11 A/F						Mos	01-Feb-2013			
Eff: 07-Jan-2013 Complied With	C/W iaw SB instructions					Hrs	8038			
						Ldg	6,796			
11-NXT1-D10	LEFT- HAND POWER PLANT, PYLON AND NACELLE - PLACARDS AND DECALS - Inspect for security, presence and legibility.						RE		ICA	≈24-Jun-2024
11 A/F	05-20-12					Mos	11-Nov-2022			
						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)						Ldg	10,886			
11-NXT1-E10	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - PLACARDS AND DECALS - Inspect for security, presence and legibility.						RE		ICA	≈24-Jun-2024
11 A/F	05-20-12					Mos	11-Nov-2022			
						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)						Ldg	10,886			
H110001	PILOT'S COMPARTMENT - INTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility. Refer to the appropriate Model 400A Pilots Operating Manual, Section 2, Operating Limitations.						RE		Scheduled Inspections	≈24-Jun-2024
11 A/F	05-20-03					Mos	11-Nov-2022			
						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						Ldg	10,886			
H110002	CABIN SECTION - INTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility. Refer to the appropriate Model 400A Pilots Operating Manual, Sections 2, Operating Limitations.						RE		Scheduled Inspections	≈24-Jun-2024
11 A/F	05-20-03					Mos	11-Nov-2022			
						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						Ldg	10,886			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H110003		FORWARD FUSELAGE - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H110004		MIDFUSELAGE - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H110005		LEFT-HAND WING - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H110006		RIGHT-HAND WING - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H110008		AFT FUSELAGE - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H110009		VERTICAL STABILIZER - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H110011		LEFT-HAND POWER PLANT, PYLON AND NACELLE - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: The JT15D-5/-5R engine inspection requirements must be completed at this interval. Refer to JT15D-5/-5R Pratt and Whitney Maintenance Manual, Chapter 72-00-00.)				Ldg	10,886				
H110012		RIGHT-HAND POWER PLANT, PYLON AND NACELLE - EXTERIOR PLACARDS AND DECALS - Inspect for security, presence and legibility (Ref. Chapter 11-22-00).						RE		Scheduled Inspections	≈24-Jun-2024
	11 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: The JT15D-5/-5R engine inspection requirements must be completed at this interval. Refer to JT15D-5/-5R Pratt and Whitney Maintenance Manual, Chapter 72-00-00.)				Ldg	10,886				
▼ 12 - SERVICING - ROUTINE MAINTENANCE											
120031		Spoiler Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation						RE		Servicing	
	12 A/F					Mos	04-Dec-2019	48		04-Dec-2023	61 Days
						Hrs	13058	6,500	+20	19558	4507:22 Hrs (+20)
		AMM:22-13-00 (NOTE: Refer to Rockwell Collins SVO 85B/85C SIL 1-01)				Ldg	9,799				
120032		Elevator Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation						RE		Servicing	
	12 A/F					Mos	04-Dec-2019	48		04-Dec-2023	61 Days
						Hrs	13058	6,500	+20	19558	4507:22 Hrs (+20)
		AMM:22-13-00 (NOTE: Refer to Rockwell Collins SVO=85B/85C SIL 1-01)				Ldg	9,799				
120033		Rudder Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation						RE		Servicing	
	12 A/F					Mos	04-Dec-2019	48		04-Dec-2023	61 Days
						Hrs	13058	6,500	+20	19558	4507:22 Hrs (+20)
		AMM:22-13-00 (NOTE: Rudder Servo/Servo Mount Clutch Teeth (Grease) by requirement or at Removal/Installation)				Ldg	9,799				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H120001		PILOT'S COMPARTMENT - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120002		CABIN SECTION - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120003		FORWARD FUSELAGE - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120004		MIDFUSELAGE - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120005		LEFT-HAND WING - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120006		RIGHT-HAND WING - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120007		LANDING GEAR AND BRAKES - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120008		AFT FUSELAGE - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120009		VERTICAL STABILIZER - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120010		HORIZONTAL STABILIZER - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	
	12 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H120015		PILOT'S COMPARTMENT - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	≈24-Jun-2024
	12 A/F	05-20-03					Mos	11-Nov-2022			
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
H120017		FORWARD FUSELAGE - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	≈24-Jun-2024
	12 A/F	05-20-03					Mos	11-Nov-2022			
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
H120018		MIDFUSELAGE - Lubricate items as specified in Chapter 12.						RE		Scheduled Inspections	≈24-Jun-2024
	12 A/F	05-20-03					Mos	11-Nov-2022			
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H120019	LEFT-HAND WING - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H120020	RIGHT-HAND WING - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H120021	LANDING GEAR AND BRAKES - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H120022	AFT FUSELAGE - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H120023	VERTICAL STABILIZER - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H120024	HORIZONTAL STABILIZER - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H120025	PILOT'S COMPARTMENT - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120027	FORWARD FUSELAGE - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120028	MIDFUSELAGE - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120029	LEFT-HAND WING - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120030	RIGHT-HAND WING - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120031	LANDING GEAR AND BRAKES - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120032	AFT FUSELAGE - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H120033	VERTICAL STABILIZER - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120034	HORIZONTAL STABILIZER - Lubricate items as specified in Chapter 12.								RE	Scheduled Inspections
 12 A/F	05-20-04					Mos	12-May-2021			≈10-Jul-2024
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
						Ldg	10,401			
H120035	Perform LUBRICATION SCHEDULE - MAIN LANDING GEAR (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120036	Perform LUBRICATION SCHEDULE - MAIN LANDING GEAR (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120039	Perform LUBRICATION SCHEDULE - FLAP ASSEMBLY (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120040	Perform LUBRICATION SCHEDULE - FLAP ASSEMBLY (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120041	Perform LUBRICATION SCHEDULE - NOSE LANDING GEAR (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120042	Perform LUBRICATION SCHEDULE - MAIN LANDING GEAR AND NOSE LANDING GEAR DOORS (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120043	Perform LUBRICATION SCHEDULE - FUEL CAPS (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
H120044	Perform LUBRICATION SCHEDULE - FUEL CAPS (Ref. Chapter 12-20-00).								RE	Scheduled Special Inspections
 12 A/F	05-20-01					Mos	06-Apr-2023			≈21-Dec-2023
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	11,028			
TA-LMM-01	Check brake system accumulator - I. a. w. AMM 128-590001-9, ch. 12-10-00 , page 246								RE (-)	
 12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	15050:38			
						Ldg	11,028			
TA-LMM-05	Check Fluids and Gases								RE (-)	
 12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	15050:38			
						Ldg	11,028			

Task No		Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
TA-LMM-08			Check Nose Gear Tire Inflation Pressure - I.a.w. AMM 128-590001-9, ch. 12-10-00 , page 263 Gear tire 120 +- 5 psig on jacks at 70°F (21,1°C) or 125 +- 5 psig with airplane on the ground at 70°F (21,1°C) .						RE (-)				
	12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD		
							Hrs	15050:38					
							Ldg	11,028					
TA-LMM-09			Check Main Gear Tire Inflation Pressure - I.a.w. AMM 128-590001-9, ch. 12-10-00 , page 264 Gear tire 125 +- 5 psig on jacks at 70°F (21,1°C) or 130 +- 5 psig with airplane on the ground at 70°F (21,1°C) .						RE (-)				
	12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD		
							Hrs	15050:38					
							Ldg	11,028					
TA-LMM-11			Perform Hydraulic Package Servicing - I.a.w. AMM 128-590001-9, ch. 12-10-00 , page 245						RE (-)				
	12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD		
							Hrs	15050:38					
							Ldg	11,028					
TA-LMM-12			Perform Wing Sump Draining - I.a.w. AMM 128-590001-9, ch. 12-10-00 , page 239						RE (-)				
	12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD		
							Hrs	15050:38					
							Ldg	11,028					
TA-LMM-13			Check Oxygen System In Cocpit - I.a.w. AMM 128-590001-9, ch. 12-10-00 , page 254 Must be in the green band.						RE (-)				
	12 A/F	05-0T-01					Mos	16-Aug-2023		(31-Aug-2023)	OVD		
							Hrs	15050:38					
							Ldg	11,028					
▼ 20 - STANDARD PRACTICES – AIRFRAME													
20.001 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of the Throttle quadrant assembly Throttle RVDT installation and center pedestal control panel Engine Sunc, GDAL/WOW test switch and Flight Idle Switch.						RE			EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
							Ldg	10,886					
20.002 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of FADEC/Engine annunciators located in the pilot's lower instrumental panel.						RE			EWIS, ICA	≈10-Jul-2024
	20 A/F	05-20-10					Mos	12-May-2021					
							Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)	
							Ldg	10,401					
20.003 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of Master Warning/Master Caution Panel and Overhead Switch panel.						RE			EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
							Ldg	10,886					
20.004 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of Ground Idle Annunciators						RE			EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
							Ldg	10,886					
20.005 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of System circuit breakers						RE			EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
							Ldg	10,886					
20.006 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of FADEC CH A Harnesses, Left RVDT harness and Left Maintenance Harness						RE			EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
							Ldg	10,886					
20.007 (EWIS)			Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of FADEC CH B Harnesses, Right RVDT harness and Right Maintenance Harness						RE			EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
							Ldg	10,886					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
20.008 (EWIS)		Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of wire runs from Aft Cockpit to aft bulkhead, down both left and right hand sides of aircraft. Left side encompasses the FADEC CH A harnesses, RVDT, Left Maintenance and #1 DCU wiring. Right side encompasses the FADEC CH B harnesses, RVDT, Right Maintenance and #2 DCU wiring.						RE		EWIS, ICA	≈10-Jul-2024
	20 A/F	05-20-10				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA-EWIS (ZONE: 261 (Cabin Area to Aft Bulkhead))					Ldg	10,401				
20.009 (EWIS)		Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of FADEC Computers, FADEC Interface units, Bleed Air Interface units, FADEC to FADEC harness, and FADEC to engine firewall harness.						RE		EWIS, ICA	≈10-Jul-2024
	20 A/F	05-20-10				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA-EWIS (ZONE: 310 (Aft of Pressure Bulkhead))					Ldg	10,401				
20.010 (EWIS)		Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of EWIS wires, termination points, connectors, electrical splices, clamp for support, cable ties around harness, and labels.						RE		EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	Ref:NXT1-ICA-EWIS (ZONE: 410 (Left Engine))					Ldg	10,886				
20.011 (EWIS)		Standalone EWIS Zonal Inspection - General Visual Inspection (GVI) of EWIS components wires, termination points, connectors, electrical splices, clamps for support, cable ties around harness, and labels.						RE		EWIS, ICA	≈24-Jun-2024
	20 A/F	05-20-09				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	Ref:NXT1-ICA-EWIS (ZONE: 420 (Right Engine))					Ldg	10,886				
ESC-200423-042		Inspection finding:Wing and H-stab leading edges need polishing						N/N (-)		Squawk, -	
	20 A/F					Mos					
	Open					Hrs					
	(Date reported: 23-Apr-2020), (Reported by: PB, Title: Engineer)(Classification date: 23-Apr-2020), (Recorded by: TT, Title: CAMO)					Ldg					
▼ 21 - AIR CONDITIONING AND PRESSURIZATION											
		Service Air Condition (Every March) (Operator inspection requirement)						RE			
	21 A/F					Mos	25-May-2022	12		[24-Oct-2023]	20 Days
						Hrs	14622:44				
						Ldg	10,755				
210000-0101		A/C Motor Brushes						RE (O/C)			
	21 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
210000-0201		Air Conditioning Drive Motor (Check AC hours)						RE			≈04-Aug-2031
	21 A/F					Mos	04-Aug-2022				
	1134104-1	Overhauled				Hrs	14779:27				
	6516					Ldg	10,863				
			0			ACH	3124	3,000		6124	2991:58 ACH
210000-0301		Environmental Control Unit						RE (O/C)			
	21 A/F					Mos	21-Nov-2000				
	45AS63018-13					Hrs	0				
	Unknown					Ldg	0				
210000-0401		Blower Motor						RE (O/C)			
	21 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
210000-0501	Cabin Pressure Indicator						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
45AS86832-5						Hrs	0			
Unknown						Ldg	0			
210000-0601	Anti-Ice Pressure Switch						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-0701	Manual Pressure Control						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-0801	Valve Solenoid						RE (O/C)			
21 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-0802	Valve Solenoid						RE (O/C)			
21 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-0901	Duct Temp Selector						RE (O/C)			
21 A/F	Fwd					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-0902	Duct Temp Selector						RE (O/C)			
21 A/F	Aft					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-1001	Skin Sensor						RE (O/C)			
21 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-1002	Skin Sensor						RE (O/C)			
21 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-1101	Anti-Ice Pressure Switch						RE (O/C)			
21 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
210000-1102	Anti-Ice Pressure Switch						RE (O/C)			
21 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
210000-1201		Temperature Indicator								RE (O/C)		
	21 A/F	Cabin					Mos	21-Nov-2000				
	5003-3016						Hrs	0				
	Unknown						Ldg	0				
210000-1301		Sensor, Low Limit Switch								RE (O/C)		
	21 A/F						Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
210000-1401		Air Conditioner Control								RE (O/C)		
	21 A/F						Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
210000-1501		Temperature Control Sensor								RE (O/C)		
	21 A/F	No.1					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
210000-1502		Temperature Control Sensor								RE (O/C)		
	21 A/F	No.2					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
210000-1601		Controller, Cabin Temperature								RE (O/C)		
	21 A/F	No.1					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
210000-1602		Controller, Cabin Temperature								RE (O/C)		
	21 A/F	No.2					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
210016		Compressor Drive Motor Brushes Inspection - Part of Freon Air Conditioner 500 Hour Inspection								RE	Special Scheduled Inspections	≈15-Mar-2024
	21 A/F	215005					Mos	17-Jul-2022				
							Hrs	14764:27				
							Ldg	10,852				
							ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)
210017		Compressor/Shaft Seal Inspection - Part of Freon Air Conditioner 500 Hour Inspection								RE	Special Scheduled Inspections	≈15-Mar-2024
	21 A/F	215005					Mos	17-Jul-2022				
							Hrs	14764:27				
							Ldg	10,852				
							ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)
210018		Compressor Drive Belt/Pulley Visual Inspection - Part of Freon Air Conditioner 500 Hour Inspection								RE	Special Scheduled Inspections	≈15-Mar-2024
	21 A/F	215005					Mos	17-Jul-2022				
							Hrs	14764:27				
							Ldg	10,852				
							ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
210019 	21 A/F	Condenser Fan/Outlet Shroud Inspection - Part of Freon Air Conditioner 500 Hour Inspection 215005						RE	Special Scheduled Inspections		≈15-Mar-2024	
						Mos	17-Jul-2022					
						Hrs	14764:27					
						Ldg	10,852					
						ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)	
210020 	21 A/F	Condenser Coil Inspection - Part of Freon Air Conditioner 500 Hour Inspection 215005						RE	Special Scheduled Inspections		≈15-Mar-2024	
						Mos	17-Jul-2022					
						Hrs	14764:27					
						Ldg	10,852					
						ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)	
210021 	21 A/F	Electrical Wiring Inspection - Part of Freon Air Conditioner 500 Hour Inspection 215005						RE	Special Scheduled Inspections		≈15-Mar-2024	
						Mos	17-Jul-2022					
						Hrs	14764:27					
						Ldg	10,852					
						ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)	
210022 	21 A/F	Receiver Dryer Assembly Inspection - Part of Freon Air Conditioner 500 Hour Inspection 215005						RE	Special Scheduled Inspections		≈15-Mar-2024	
						Mos	17-Jul-2022					
						Hrs	14764:27					
						Ldg	10,852					
						ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)	
210023 	21 A/F	Belt Cover Check - Part of Freon Air Conditioner 500 Hour Inspection 215005						RE	Special Scheduled Inspections		≈15-Mar-2024	
						Mos	17-Jul-2022					
						Hrs	14764:27					
						Ldg	10,852					
						ACH	2962:42	500	+20	(3462:42)	330:40 ACH (+20)	
211000-0101 	21 A/F Unknown Unknown	Emergency Pressure Valve						RE (O/C)				
						Mos	21-Nov-2000					
						Hrs	0					
						Ldg	0					
211000-0201 	21 A/F Unknown Unknown	Bleed Air Pressure Switch						RE (O/C)				
						Mos	21-Nov-2000					
						Hrs	0					
						Ldg	0					
211000-0301 	21 A/F Unknown Unknown	Test Valve						RE (O/C)				
						Mos	21-Nov-2000					
						Hrs	0					
						Ldg	0					
212000-0101 	21 A/F Unknown Unknown	Ceiling Air Outlet Shutoff Valve						RE (O/C)				
						Mos	21-Nov-2000					
						Hrs	0					
						Ldg	0					
212000-0201 	21 A/F Unknown Unknown	Cockpit Mode Air Selector						RE (O/C)				
						Mos	21-Nov-2000					
						Hrs	0					
						Ldg	0					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
212000-0301	Diffuser						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
212000-0401	Defogger Blower						RE (O/C)			
21 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
212000-0402	Defogger Blower						RE (O/C)			
21 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
212000-0501	Check Valve						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
213000-0101	Cabin Pressure Control Module						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
213000-0201	Pneumatic Relay						RE (O/C)			
21 A/F						Mos	31-Oct-2019			
130358-3	Overhauled		0			Hrs	13005:36			
42-284			0			Ldg	9,767			
213000-0301	Cabin Pressure Altitude Regulator						RE (O/C)			
21 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
213000-0302	Cabin Pressure Altitude Regulator						RE (O/C)			
21 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
213000-0401	Vacuum Regulator						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
213000-0501	Pressure Control Regulator						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
213000-0601	S2 Solenoid Valve						RE (O/C)			
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
213000-0701		S3 Solenoid Valve									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
213000-0801		Manual Control Valve									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
213000-0901		Outflow Valve									
	21 A/F	No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
213000-0902		Outflow Valve									
	21 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
213000-1001		Dump Valve									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
213100-0101		Cabin Air Pressure Controller									
	21 A/F						Mos	21-Nov-2000			
	130356-9						Hrs	0			
	117-335						Ldg	0			
213100-0201		Cabin Pressure Auxiliary Volume Tank									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
213100-0301		Cabin Altitude Switch									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0101		Refrigeration Unit									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0201		Air Conditioning Unit									
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0301		Temperature Modulator Valve									
	21 A/F	Cockpit					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
215000-0302		Temperature Modulator Valve								RE (O/C)	
	21 A/F	Cabin					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0401		Turbine Cooling By-Pass Valve								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0501		Ejector Shut-Off Valve								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0601		Ram Air Check Valve								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0701		Zone No. 2 Modulator Shut-Off Valve								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0801		Air Temperature Bulb								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-0901		Environmental Control Valve								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-1001		Cooling Turbine								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-1101		Primary Heat Exchanger								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-1201		Secondary Heat Exchanger								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
215000-1301		Thermal Switch								RE (O/C)	
	21 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
215005		500-Hour Intervals, Air-Conditioning Operating System Inspections						RE		Special Scheduled Inspections	≈15-Mar-2024
	21 A/F					Mos	17-Jul-2022				
		(NOTE: Refer to Enviro Systems 21-00-12 in the Component Maintenance Manual, P/N 128-590001-81 or subsequent.)				Hrs	14764:27				
						Ldg	10,852				
						ACH	2962:42	500	+20	3462:42	330:40 ACH (+20)
216000-0101		Cockpit Temperature Sensor						RE (O/C)			
	21 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0201		Temperature Sensor						RE (O/C)			
	21 A/F	Cabin				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0301		High Limit Sensor						RE (O/C)			
	21 A/F	Cockpit				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0302		High Limit Sensor						RE (O/C)			
	21 A/F	Cabin				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0401		Low Limit Sensor						RE (O/C)			
	21 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0501		Duct Temperature Sensor						RE (O/C)			
	21 A/F	Cockpit				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0502		Duct Temperature Sensor						RE (O/C)			
	21 A/F	Cabin				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0601		Sensor, Duct Temperature						RE (O/C)			
	21 A/F	Fwd				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0602		Sensor, Duct Temperature						RE (O/C)			
	21 A/F	Aft				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
216000-0701		Temperature Sensor Blower						RE (O/C)			
	21 A/F	Cockpit				Mos	13-Sep-2021				
	19A3008					Hrs	14379				
	R17773					Ldg	10,595				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
216000-0702	Temperature Sensor Blower								RE (O/C)	
21 A/F	Cabin					Mos	26-Sep-2019			
19A3008	New	0				Hrs				
1131		0				Ldg				
216000-0801	Temperature Selector								RE (O/C)	
21 A/F	Cockpit					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
216000-0901	Cabin Temperature Selector								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
216000-1001	Overtemperature Switch								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
216000-1101	Mode Selector								RE (O/C)	
21 A/F	Cockpit					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
216000-1102	Mode Selector								RE (O/C)	
21 A/F	Cabin					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
216000-1201	Cabin Altitude Differential Pressure Indicator								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
217000-0101	Water Separator								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
217000-0201	Coalescer								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
218000-0101	Air Conditioning Compressor								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
218000-0201	Receiver Dryer								RE (O/C)	
21 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
218000-0301	Evaporator Module									
21 A/F	Fwd					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
218000-0302	Evaporator Module									
21 A/F	Aft					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
218000-0401	Air Conditioning Compressor/Condenser Module									
21 A/F						Mos	21-Nov-2000		RE (O/C)	
1134400-1						Hrs	0			
146A						Ldg	0			
219000-0302	PRSOV, High Flow									
21 A/F	Right					Mos	24-Jan-2023		RE (-)	
5915-00-01	Repaired			0		Hrs	14913:30			
0164				0		Ldg	10,941			
219000-0304	PRSOV, Low Flow									
21 A/F						Mos	24-Feb-2023		RE (-)	
5914-00-1						Hrs	14983:13			
116						Ldg	10,987			
21-CUS-001	RIGHT UPPER VENTILATION HOSE CHECK UNDER RIGHT CEILING PANEL									
21 A/F						Mos	11-Nov-2022		RE (-)	
(NOTE: Inspection performed)						Hrs	14814:28			
						Ldg	10,886			
96-17-10	Outflow/Safety Valves (This AD is superseded by AD 98-06-30)								RE (-)	Mandatory
21 A/F						Mos				
Eff: 20-Aug-1996						Hrs				
						Ldg				
98-06-30	Outflow/Safety Valves								RE (-)	Mandatory
21 A/F						Mos				
Eff: 24-Apr-1998						Hrs				
						Ldg				
H210001	CABIN SECTION - FWD & AFT EVAPORATOR BOX ASSEMBLIES (RK-78, RK-87 and After) - Inspect intake air filter for cleanliness and condition.								RE	Scheduled Inspections ≈24-Jun-2024
21 A/F	05-20-03					Mos	11-Nov-2022			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H210002	FORWARD FUSELAGE - OUTFLOW SAFETY VALVE POPPET SEATS (as viewed from nose avionics compartment) - Inspect for condition and contamination.								RE	Scheduled Inspections ≈24-Jun-2024
21 A/F	05-20-03					Mos	11-Nov-2022			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
						Ldg	10,886			
H210003	AFT FUSELAGE - ENVIRONMENTAL CONTROL UNIT (ECU) AND DUCTING - Clean or replace coalescer sock.								RE	Scheduled Inspections
21 A/F	05-20-02					Mos	11-Nov-2022	12		(30-Nov-2023) 57 Days
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
						Ldg	10,886			

Task No SEQ PN/SN	Description MOC Note or Component Condition					CW	REQ	TOL	Categories		Time Remaining
		TSNI	TSOI	TSRI	TSI				DUE		
H210006	PILOT'S COMPARTMENT - AIR-CONDITIONING CONTROL SWITCH PANEL (copilots sidepanel) (RK-78, RK-87 and After) - Inspect for condition and operation. 05-20-03								RE	Scheduled Inspections	≈24-Jun-2024
21 A/F	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Mos	11-Nov-2022					
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
					Ldg	10,886					
H210008	CABIN SECTION - VAPOR CYCLE COOLING SYSTEM - EVAPORATORS (RK-78, RK-87 and After) / a. Inspect forward and aft evaporator module plumbing and wiring for condition within cabin area and at the aft pressure bulkhead pass through locations. / b. Detail inspect the forward and aft evaporator Lexan housing assemblies at the junction of the shroud assembly and the escutcheon for signs of separation, cracks and condensate leakage (Ref. Enviro Systems CMM, Chapter 21-00-12 in the Component Maintenance Manual, 128-590001-81 or subsequent). / c. Inspect the forward and aft evaporator coil fins for damage and cleanliness. / d. Inspect the forward and aft evaporator blower motor, wheel and scroll for cleanliness, smooth (vibration free) operation (Ref. Enviro Systems CMM, Chapter 21-00-12, Section 3.3 in the Component Maintenance Manual, 128-590001-81 or subsequent). / e. Inspect the forward and aft evaporator module cold air ducting for condition. / f. Inspect the forward and aft evaporator drain outlets and tubing for obstruction and ensure drain tubing routing will allow complete moisture drainage. / g. Verify 25 5 F drop across the forward and aft evaporator coils (Ref. Enviro Systems CMM, Chapter 21-00-12 Section 12.1 in the Component Maintenance Manual, 128-590001-81 or subsequent). 05-20-04								RE	Scheduled Inspections	≈10-Jul-2024
21 A/F	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Mos	12-May-2021					
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)	
					Ldg	10,401					
H210010	AFT FUSELAGE - ENVIRONMENTAL CONTROL UNIT (ECU) AND DUCTING / a. Remove ECU (also known as Refrigeration Unit) and detail inspect the primary and secondary heat exchanger for condition, corrosion and obstruction (Ref. Chapter 21-50-00). / b. Remove and inspect bleed air check valves (P/N 45AS63023) for condition and freedom of movement. / c. Inspect ECU ram air inlet and discharge ducts for condition and obstruction. / d. (RK-1 thru RK-109, except RK-98) - Detail inspect duct temperature sensors, high limit temperature sensors, pressure regulator and associated plumbing for condition, cracks or eroded housings and evidence of air leakage (Ref. Figure 621 and Figure 622). / e. (RK-98, RK-110 and After) - Detail inspect duct temperature sensors, high limit temperature sensors and their associated wiring and plumbing for condition and evidence of air leakage. / f. Inspect conditioned air ducting, plenums and insulation material for condition and evidence of air leakage. / g. Inspect aft fuselage insulation blanket for torn or punctured material and evidence of hot air leakage (sooting and/or discoloration). Investigate potential leaks. / h. Inspect the four thermal switches (S187) (S188) (S189) (S190) and wire harnesses for condition, obstruction and deterioration. / i. Perform BLEED AIR HIGH TEMPERATURE SWITCH (350 F) OPERATIONAL CHECK (Ref. Chapter 21-50-00). / j. Perform BLEED AIR OVERTEMPERATURE SWITCH (400 F) OPERATIONAL CHECK (Ref. Chapter 21-50-00). / k. BLEED AIR OVERPRESSURE SWITCH - Perform BLEED AIR OVERPRESSURE SWITCH OPERATIONAL CHECK (Ref. Chapter 21-50-00). 05-20-04								RE	Scheduled Inspections	≈10-Jul-2024
21 A/F	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Mos	12-May-2021					
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)	
					Ldg	10,401					
H210011	AFT FUSELAGE - VAPOR CYCLE COOLING SYSTEM (RK-78, RK-87 and After) / a. Inspect compressor/condenser module assembly and ducting for condition (compressor/condenser module not removed). / b. Inspect wire harness and grounding points (airframe and module) for condition and evidence of overheating. / c. Inspect remote refrigerant servicing assembly and refrigerant system plumbing (from the rear pressure bulkhead to the compressor/condenser module) for condition and routing. / d. Inspect remote refrigerant servicing placard for presence and legibility. / e. Inspect circuit breakers, fuses, load shed module and wiring for condition and evidence of overheating. 05-20-03								RE	Scheduled Inspections	≈24-Jun-2024
21 A/F	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Mos	11-Nov-2022					
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
					Ldg	10,886					
H210012	AFT FUSELAGE - VAPOR CYCLE COOLING SYSTEM - COMPRESSOR CONDENSER MODULE (RK-78, RK-87 and After) / a. Inspect compressor drive belt cover for condition. / b. Remove and inspect compressor drive belt for condition, deterioration and evidence of improper tracking. / c. Inspect compressor pulley, shaft and shaft seal for condition. / d. Perform COMPRESSOR BEARING INSPECTION (Ref. Enviro System CMM, Chapter 21-00-12, Section 12.4 in the Component Maintenance Manual, 128-590001-81 or subsequent). / e. Inspect drive motor brushes for condition and calculate remaining brush life (Ref. Enviro System CMM, Chapter 21-00-12, Section 3.4 in the Component Maintenance Manual, 128-590001-81 or subsequent). Replace brushes if necessary. / f. Inspect drive motor brush holders and commutator for condition, arcing, heat distortion and contamination. / g. Perform MOTOR INSULATION RESISTANCE CHECK (Ref. Enviro System CMM, Chapter 21-00-12, Section 12.2 in the Component Maintenance Manual, 128-590001-81 or subsequent). / h. Perform MOTOR BEARING INSPECTION (Ref. Enviro System CMM, Chapter 21-00-12, Section 12.3 in the Component Maintenance Manual, 128-590001-81 or subsequent). / i. Inspect condenser fan, condenser coil and coil fins for condition, accumulation of dirt and damaged fan blades or coil fins. / j. Inspect condenser fan shroud and the condenser outlet shroud for cracking and/or separation between the shroud and the condenser coil. / k. Inspect receiver/dryer assembly, mounting and plumbing for condition. / l. Install and tension compressor drive belt (Ref. Chapter 21-51-00). / m. Verify refrigerant charge level and operating pressures. 05-20-04								RE	Scheduled Inspections	≈10-Jul-2024
21 A/F	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Mos	12-May-2021					
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)	
					Ldg	10,401					
H210016	PILOT'S COMPARTMENT - COCKPIT SIDE WINDOW DEFOG BLOWER - Perform COCKPIT SIDE WINDOW DEFOG BLOWER TEST (Ref. Chapter 30-40-00). 05-20-03								RE	Scheduled Inspections	≈24-Jun-2024
21 A/F	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Mos	11-Nov-2022					
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)	
					Ldg	10,886					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H210017	PILOT'S COMPARTMENT - CEILING AIR OUTLET SHUTOFF VALVE (RK-1 thru RK-97 and RK-99 thru RK-109) - Perform the appropriate CEILING AIR OUTLET SHUTOFF VALVE TEST procedure (Ref. Chapter 21-20-00).						RE (N/A)		Scheduled Inspections	
21 A/F										
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H210018	AFT FUSELAGE - ENVIRONMENTAL CONTROL UNIT (ECU) AND DUCTING (Panels 311RL and 312FR removed) - Detail inspect ECU, bleed air manifold assembly and associated ducting for condition and evidence of hot air leakage (where visible) (Ref. Figure 608).						RE		Scheduled Inspections	≈24-Jun-2024
21 A/F	05-20-03									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H210019	ENGINE GROUND RUN AND OPERATIONAL CHECKS - CABIN PRESSURE CONTROL SYSTEM - Perform CABIN PRESSURIZATION SYSTEM OPERATIONAL TEST (Ref. Chapter 21-30-00).						RE		Scheduled Inspections	
21 A/F	05-20-02									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)									
H210020	ENGINE GROUND RUN AND OPERATIONAL CHECKS - ENVIRONMENTAL CONTROL UNIT - Perform REFRIGERATION UNIT OPERATIONAL CHECK (Ref. Chapter 21-50-00).						RE		Scheduled Inspections	≈24-Jun-2024
21 A/F	05-20-03									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Not required if ENVIRONMENTAL SYSTEM CHECK (RK-1 AND AFTER) is performed. - NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)									
H210021	ENGINE GROUND RUN AND OPERATIONAL CHECKS - ENVIRONMENTAL SYSTEM - Perform ENVIRONMENTAL SYSTEM CHECK (RK-1 AND AFTER) (Ref. Chapter 21-00-00).						RE		Scheduled Inspections	≈10-Jul-2024
21 A/F	05-20-04									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)									
H210022	ENGINE GROUND RUN AND OPERATIONAL CHECKS - CABIN PRESSURE CONTROL SYSTEM - Perform CABIN PRESSURE CONTROL SYSTEM CHECK (Ref. Chapter 21-00-00).						RE		Scheduled Inspections	≈24-Jun-2024
21 A/F	05-20-03									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)									
H210023	CABIN SECTION - ENVIRONMENTAL SYSTEM / a. Perform WING ANTI-ICE OUTER CONTAINMENT DUCT PRESSURE SWITCH FUNCTIONAL TEST (Ref. Chapter 30-10-00). / b. Detail inspect wing anti-ice and conditioned air ducting for condition, specified clearance from insulation materials and wire harnesses, deterioration and evidence of overheating. NOTE: Assure specified clearances are maintained the entire length of the ducting.						RE		Scheduled Inspections	≈10-Jul-2024
21 A/F	05-20-04									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)									
H210028	PILOT'S COMPARTMENT - PRESSURIZATION CONTROL COMPONENTS AIR FILTERS/SCREENS / a. Perform CABIN ALTITUDE (CABIN PRESSURE LOW) SWITCH (S092) FUNCTIONAL TEST (Ref. Chapter 21-30-00). / b. CABIN AIR PRESSURE CONTROLLER FILTER - Clean or replace filter as necessary (Ref. Chapter 21-30-00). / c. SOLENOID VALVE (S2) AIR FILTER - Perform the SOLENOID VALVE (S2) AIR FILTER servicing procedure and inspect filter for condition (Ref. Chapter 21-30-00). / d. OUTFLOW/SAFETY VALVE STATIC PORT SCREENS (RK-49 and After) - Perform the OUTFLOW/SAFETY VALVE STATIC PORT SCREENS servicing procedure and inspect screens for condition (Ref. Chapter 21-30-00). / e. CABIN HIGH PRESSURE SWITCH AIR FILTER (RK-93 and After) - Perform the CABIN HIGH PRESSURE SWITCH AIR FILTER servicing procedure and inspect screen for condition (Ref. Chapter 21-30-00).						RE		Scheduled Inspections	≈24-Jun-2024
21 A/F	05-20-03									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H210029	PILOT'S COMPARTMENT - CABIN PRESSURE CONTROL FILTER CARTRIDGE ASSEMBLY (Below Floor Panels) - Replace filter cartridge.						RE		Scheduled Inspections	≈10-Jul-2024
21 A/F	05-20-04									
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)									

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H210030	PILOT'S COMPARTMENT - PRESSURIZATION CONTROL SYSTEM - Inspect plumbing for condition and routing.						RE		Scheduled Inspections	≈10-Jul-2024
 21 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H210034	SCHEDULED D INSPECTIONS - COMPRESSOR/CONDENSER MODULE (compressor/ condenser module removed) (RK-78, RK-87 and After) / a. Perform detailed inspection of attach points to mounting plate for cracks, loose or missing fasteners and any other indication of structural damage. / b. Perform detailed inspection of support structure for cracks, loose or missing fasteners and any other indication of structural damage. / c. Perform detailed inspection of the support structure attachment to the airframe for cracks, loose or missing fasteners and any other indication of structural damage. / d. Perform detailed inspection of the air exhaust, skin doublers and adjacent skin (both inside and outside the airplane) between FS 437.6 (11115) and FS 457.3 (11615) for cracks, loose or missing fasteners and any other indication of structural damage.						RE		Scheduled Inspections	≈29-Jul-2026
 21 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H210035	CABIN SECTION - OVERHEAD AIR OUTLET / a. Inspect for condition and mechanical operation. / b. (RK-78, RK-87 thru RK-109, except RK-98) - Assure outlets do not fully close.						RE (N/A)		Scheduled Inspections	
 21 A/F					Mos					
					Hrs					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg					
H210036	PILOT'S COMPARTMENT - VENTILATION BLOWER SYSTEM / a. Detail inspect ventilation blower and ducting for condition. / b. Perform VENTILATION BLOWER CHECK (Ref. Chapter 21-21-00).						RE		Scheduled Inspections	≈10-Jul-2024
 21 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H210037	DRIVE MOTOR - Perform overhaul of the drive motor per the Chapter 21-00-12, Section 7.1.2 in the Component Maintenance Manual, 128-590001-81 or subsequent.						RE		Scheduled Special Inspections	≈04-Aug-2031
 21 A/F					Mos	04-Aug-2022				
1134104-1					Hrs	14779:27				
6516					Ldg	10,863				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				ACH	3124	3,000		6124	2991:58 ACH
SIB:2019-02	Explosive Door Openings on Parked Aeroplanes.						RE (-)			
 21 A/F					Mos	30-Oct-2019				
Not Applicable					Hrs	13005:36				
(UPDATE NOTE: N/A by non APU)					Ldg	9,767				
▼ 22 - AUTOFLIGHT										
220000-0101	Card, Flight Management Computer						RE (O/C)			
 22 A/F	No.1				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
220000-0102	Card, Flight Management Computer						RE (O/C)			
 22 A/F	No.2				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
220000-0103	Card, Flight Management Computer						RE (O/C)			
 22 A/F	No.3				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
220000-0104	Card, Flight Management Computer						RE (O/C)			
 22 A/F	No.4				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
220000-0202		Card, Flight Control									
	22 A/F	No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0203		Card, Flight Control									
	22 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0301		Card, Cage									
	22 A/F	No.1					Mos	21-Nov-2000			
	822-1029-101						Hrs	0			
	4LOL						Ldg	0			
220000-0302		Card, Cage									
	22 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0401		Card, Power Supply									
	22 A/F	No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0402		Card, Power Supply									
	22 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0403		Card, Power Supply									
	22 A/F	No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0404		Card, Power Supply									
	22 A/F	No.4					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0405		Card, Power Supply									
	22 A/F	No.5					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0406		Card, Power Supply									
	22 A/F	No.6					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
220000-0501		Card, Input/Output Concentrator									
	22 A/F						Mos	03-May-2017			
	622-9817-001						Hrs	11274			
	1NTL						Ldg	8,668			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
220000-0601		Aileron Servo								RE (O/C)	
22	A/F	Unknown Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
221000-0101		Servo, Spoiler								RE (O/C)	
22	A/F	SVO-85B Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
221000-0201		Servo, Elevator								RE (O/C)	
22	A/F	622-6717-104 46YC					Mos	25-Nov-2020			
							Hrs	13830:28			
							Ldg	10,279			
221000-0301		Servo, Rudder								RE (O/C)	
22	A/F	622-6717-104 GF3J					Mos	01-Aug-2014			
							Hrs	9348			
							Ldg	7,539			
221000-0401		Spoiler Servo Drive Mount								RE (O/C)	
22	A/F	SMT-85B Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
221000-0501		Elevator Servo Drive Mount								RE (O/C)	
22	A/F	SMT-85C Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
221000-0601		Rudder Servo Drive Mount								RE (O/C)	
22	A/F	SMT-85C Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
221000-0701		Mode Select Panel								RE (O/C)	
22	A/F	No.1 Unknown Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
221000-0702		Mode Select Panel								RE (O/C)	
22	A/F	No.2 622-8330-003 355WV					Mos	01-Aug-2014			
							Hrs	9348			
							Ldg	7,539			
221000-0801		Autopilot Panel								RE (O/C)	
22	A/F	622-6208-204 2YKKJ					Mos	01-Mar-2017			
							Hrs	11177			
							Ldg	8,632			
95-18-04		Autopilot & Rudder Boost Improvement Kit								T (A/R)	Mandatory
22	A/F	Eff: 10-Oct-1995					Mos				
							Hrs				
							Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
ESC-230726-107		Perform MSP check						N/N (-)		Squawk, -	
✖	22 A/F					Mos					
	Open					Hrs					
	(Date reported: 26-Jul-2023), (Reported by: CAMO, Title: CAMO)(Classification date: 26-Jul-2023), (Recorded by: CAMO, Title: CAMO)										
						Ldg					
H220001		COLLINS SERVO MOUNT SLIP CLUTCH - Test the Collins servo mount slip clutches in the elevator, rudder and spoiler servo mounts per the Rockwell-Collins Beechjet Avionics System Manual (P/N 523-0775807) Section 5.2.2 SVO-85 () Servo/SMT-85 ()/-87 () Servo Mount.						RE	Scheduled Special Inspections	≈17-Dec-2029	
📷	22 A/F					Mos	17-Jan-2012				
						Hrs	7691	12,200	+40	19891	4840:22 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
						Ldg	6,533				
▼ 23 - COMMUNICATIONS											
		CVR operational check (read-out included) iaw AMC1 CAT.GEN.MPA.195 (b)						RE			
📷	23 A/F					Mos	11-Nov-2022	12		30-Nov-2023	57 Days
						Hrs	14814:28				
						Ldg	10,886				
		HF Control KFS 594						RE (-)			
⚙️	23 A/F					Mos	25-May-2022				
	071-1274-00					Hrs	14622:44				
	3142					Ldg	10,755				
230000-0201		Maintenance Diagnostic Computer (MDC-3110)						RE (O/C)			
⚙️	23 A/F					Mos	21-Nov-2000				
	822-1987-006					Hrs	0				
	4B2MW					Ldg	0				
230000-0301		Lightning HIRF Protector						RE (O/C)			
⚙️	23 A/F	No.1				Mos	21-Nov-2000				
	822-0287-801					Hrs	0				
	Unknown					Ldg	0				
230000-0302		Lightning HIRF Protector						RE (O/C)			
⚙️	23 A/F	No.2				Mos	21-Nov-2000				
	822-0287-801					Hrs	0				
	Unknown					Ldg	0				
230000-0401		Inertia Switch						RE (O/C)			
⚙️	23 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
230000-0501		Antenna, Comm						RE (O/C)			
⚙️	23 A/F	No.1				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
230000-0502		Antenna, Comm						RE (O/C)			
⚙️	23 A/F	No.2				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
230000-0601		Control, Audio Video						RE (O/C)			
⚙️	23 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
231000-0101		VHF Transceiver (VHF-422C)								RE (O/C)	
23 A/F	822-1115-001	No.1					Mos	19-Jan-2018			
	2DH2Y	New					Hrs	11765			
							Ldg	8,978			
231000-0102		VHF Transceiver (VHF-422C)								RE (O/C)	
23 A/F	822-1115-001	No.2					Mos	19-Jan-2018			
	25P4	New					Hrs	11765			
							Ldg	8,978			
231000-0201		VHF Communication Antenna								RE (O/C)	
23 A/F	CI108	No.1					Mos	19-Mar-2019			
	575640						Hrs	12473:10			
							Ldg	9,436			
231000-0202		VHF Communication Antenna								RE (O/C)	
23 A/F	CI 108-BCH-L	No.2					Mos	07-Jun-2018			
	553726						Hrs	12076			
							Ldg	9,190			
231000-0301		Flight Phone Antenna								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
233000-0101		Cabin Flight Phone Handset								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
233000-0201		Cockpit Flight Phone Handset								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
233000-0301		Cockpit Flight Phone (C118E) Forward Control								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
233000-0401		Cockpit Flight Phone (C118E) Aft Control								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
233000-0501		Flight Phone(Rt18D) Transceiver								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
233000-0601		Flight Phone Controller								RE (O/C)	
23 A/F	Unknown						Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
233000-0701		Radio Tuning Unit								RE (O/C)	
✖	23 A/F	No.1					Mos	17-Feb-2023			
	822-1825-111						Hrs	14973:06			
	26LWK						Ldg	10,980			
233000-0702		Radio Tuning Unit								RE (O/C)	
✖	23 A/F	No.2					Mos	10-Mar-2023			
	822-1825-111						Hrs	15004:14			
	1991						Ldg	11,000			
235000-0101		Audio Control Panel								RE (O/C)	
✖	23 A/F	Pilot					Mos	21-Nov-2000			
	128-340329-21						Hrs	0			
	Unknown						Ldg	0			
235000-0102		Audio Control Panel								RE (O/C)	
✖	23 A/F	Copilot					Mos	21-Nov-2000			
	128-340329-23						Hrs	0			
	Unknown						Ldg	0			
235000-0201		Audio Amplifier								RE (O/C)	
✖	23 A/F	No.1					Mos	11-Nov-2022			
	438-001						Hrs	14814:28			
	1789						Ldg	10,886			
235000-0202		Audio Amplifier								RE (O/C)	
✖	23 A/F	No.2					Mos	11-Nov-2022			
	438-001						Hrs	14814:28			
	4437						Ldg	10,886			
235000-0301		Aural Warning Tone Generator								RE (O/C)	
✖	23 A/F	New					Mos	25-Jun-2015			
	603						Hrs	10075			
	830						Ldg	7,978			
237000-0101		Cockpit Voice Recorder (CVR)								RE (O/C)	
✖	23 A/F						Mos	26-Jan-2021			
	2100-1020-00						Hrs	13957:22			
	000152092						Ldg	10,348			
237000-0201		Cockpit Voice Recorder Impact Switch								RE (O/C)	
✖	23 A/F						Mos	21-Nov-2000			
	6895-D-1-X-2.5-2.5						Hrs	0			
	Unknown						Ldg	0			
237000-0301		Cockpit Voice Recorder Control Unit								RE (O/C)	
✖	23 A/F						Mos	21-Nov-2000			
	93-A151-30						Hrs	0			
	Unknown						Ldg	0			
237000-0401		Cockpit Voice Recorder Underwater Locator Beacon								RE (O/C)	
✖	23 A/F						Mos	26-Jan-2021			
	Unknown						Hrs	13957:22			
	Unknown						Ldg	10,348			

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
238000-0101		Display Control Panel						RE (O/C)			
⚙️	23 A/F	No.1					Mos	21-Nov-2000			
	822-1828-002						Hrs	0			
	490WH						Ldg	0			
238000-0102		Display Control Panel						RE (O/C)			
⚙️	23 A/F	No.2					Mos	21-Nov-2000			
	822-1828-002						Hrs	0			
	4908P						Ldg	0			
23-CVR-1		CVR - ULB battery						RE			
⚙️	23 A/F		2				Mos	16-Jan-2023	72	16-Nov-2028	5.1 Years
	DK120/90	New	0				Hrs	14901:20			
	AT182964		0				Ldg	10,933			
H230001		FORWARD FUSELAGE - ANTENNA - Inspect antennas and fillet seal for cracks, corrosion, burns, security and evidence of damage (Ref. Figure 602).						RE		Scheduled Inspections	
📷	23 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						Ldg	10,886			
H230002		MIDFUSELAGE - ANTENNA - Inspect antennas and fillet seal for cracks, corrosion, burns, security and evidence of damage (Ref. Figure 602).						RE		Scheduled Inspections	
📷	23 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						Ldg	10,886			
H230003		AFT FUSELAGE - ANTENNA - Inspect antennas and fillet seal for cracks, corrosion, burns, security and evidence of damage (Ref. Figure 602).						RE		Scheduled Inspections	
📷	23 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						Ldg	10,886			
H230004		PILOT'S COMPARTMENT - COCKPIT WARNING SYSTEM - Perform COCKPIT VOICE RECORDER FUNCTIONAL TEST (Ref. Chapter 23-70-00).						RE		Scheduled Inspections	≈24-Jun-2024
📷	23 A/F	05-20-03					Mos	11-Nov-2022			
	2100-1020-00						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
	000152092						Ldg	10,886			
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)										
H230005		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (RK-36 and After) - Functional test. Refer to the Dukane (Seacom Division) Technical Manual in Chapter 23 of the Component Maintenance Manual, P/N 128-590001-81 or subsequent for test procedures.						RE		Scheduled Special Inspections	
📷	23 A/F						Yrs	16-Jan-2023	2	31-Jan-2025	1.3 Years
	2100-1020-00						Hrs	14901:20			
	000152092						Ldg	10,933			
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
No. 1 - Aviation Headset		LH Pilot Headset						RE (-)			
⚙️	23 A/F	Pilot					Mos	19-May-2020			
	324843-2020						Hrs	13289:33			
	070407960140296AF						Ldg	9,953			
No. 2 - Aviation Headset		RH Copilot headset						RE (-)			
⚙️	23 A/F	Copilot					Mos				
	324843-2020						Hrs				
	Unknown						Ldg				
▼ 24 - ELECTRICAL POWER											
		LH and RH S/G Brushes						RE (-)			
⚙️	24 A/F						Mos	05-Nov-2019			
	23080-1902						Hrs	13005:36			
	N/A						Ldg	9,767			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
RH Generator Sensor RCCB										
	24 A/F SM600BA10A1 106741					Mos	18-Jun-2019		RE (-)	
						Hrs	12663:28			
						Ldg	9,551			
042401 Starter/Generator - Replace with airworthy unit										
	24 A/F 45AS88801-017 Y01237 (SOURCE: Maintenance Manual 040002)	Left				Mos	25-May-2022		RE	AWL - Inspection Limitations ≈27-Jun-2024
						Hrs	14622:44	1,000		15622:44 572:06 Hrs
						Ldg	10,755			
042401 Starter/Generator - Replace with airworthy unit										
	24 A/F 45AS88801-017 P1367 (SOURCE: Maintenance Manual 040002)	Right				Mos	25-May-2022		RE	AWL - Inspection Limitations ≈27-Jun-2024
						Hrs	14622:44	1,000		15622:44 572:06 Hrs
						Ldg	10,755			
2001-20-07 Bus Bars										
	24 A/F Eff: 15-Nov-2001					Mos			T (A/R)	Mandatory
						Hrs				
						Ldg				
2006-15-16 Generator control unit (GCU) installation kits										
	24 A/F Eff: 05-Sep-2006					Mos			T (A/R)	Mandatory
						Hrs				
						Ldg				
2013-03-07 Electrical Power System Wiring										
	24 A/F Eff: 19-Mar-2013 Complied "C/W iaw SB33-4002 on 6.7.2011 @ ACTT> 7691h, ACTC> 6553ldg" With					Mos	19-Apr-2013		RE (-)	Mandatory
						Hrs	8216			
						Ldg				
240000-0101 Standby Battery Power Supply										
	24 A/F 501-1228-04 7095	No.1				Mos	13-Sep-2021		RE (O/C)	
						Hrs	14379			
						Ldg	10,595			
240000-0201 AHRS Battery Power Supply										
	24 A/F Unknown Unknown					Mos	21-Nov-2000		RE (O/C)	
						Hrs	0			
						Ldg	0			
240000-0301 Inverter, Dual Voltage										
	24 A/F SPC-5(C) Unknown	No.1				Mos	21-Nov-2000		RE (O/C)	
						Hrs	0			
						Ldg	0			
240000-0302 Inverter, Dual Voltage										
	24 A/F SPC-5(C) Unknown	No.2				Mos	21-Nov-2000		RE (O/C)	
						Hrs	0			
						Ldg	0			
240000-0401 Inverter										
	24 A/F Unknown Unknown					Mos	21-Nov-2000		RE (O/C)	
						Hrs	0			
						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
240000-0501	Generator Control Unit									
24 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
45AS88801-025						Hrs	0			
Unknown						Ldg	0			
240000-0502	Generator Control Unit									
24 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
45AS88801-025						Hrs	0			
Unknown						Ldg	0			
240000-0601	Temp Selector									
24 A/F	Cockpit					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
240000-0701	Power Supply									
24 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
24-0T-11	LH Starter-Generator Brushes (Operator inspection requirement) - Perform inspection of brushes - In case of need replace with new brush set (4ea per Starter-Generator) i.a.w. CMM 23700 (24-00-10)Goodrich Manual								RE	≈21-Feb-2024
24 A/F						Mos	06-Apr-2023			
						Hrs	15050:38	300	+40	15350:38 300 Hrs (+40)
						Ldg	11,028			
24-0T-21	RH Starter-Generator Brushes (Operator inspection requirement) - Perform inspection of brushes - In case of need replace with new brush set (4ea per Starter-Generator) i.a.w. CMM 23700 (35-00-10)Goodrich Manual								RE	≈21-Feb-2024
24 A/F						Mos	06-Apr-2023			
						Hrs	15050:38	300	+40	15350:38 300 Hrs (+40)
						Ldg	11,028			
242000-0101	Static Inverter									
24 A/F	Left					Mos	01-Nov-2013		RE (O/C)	
SPC-5(B)	New					Hrs	8722			
165						Ldg	7,201			
242000-0102	Static Inverter									
24 A/F	Right					Mos	01-Nov-2013		RE (O/C)	
SPC-5(B)	New					Hrs	8722			
927						Ldg	7,201			
242000-0201	Ac Voltmeter									
24 A/F						Mos	21-Nov-2000		RE (O/C)	
N241100-2						Hrs	0			
J20963						Ldg	0			
242000-0301	AC/DC Volt - Ammeter									
24 A/F						Mos	21-Nov-2000		RE (O/C)	
N241100-2						Hrs	0			
J20963						Ldg	0			
243000-0201	DC Instrument Cluster									
24 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
243000-0301		Battery Feed Protection Unit						RE (O/C)				
	24 A/F	New					Mos	06-Jul-2017				
	50284-003						Hrs	11398				
	P1061C						Ldg	87,598				
243000-0401		Battery Ground Fault Protection Panel						RE (O/C)				
	24 A/F	Unknown Unknown					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243000-0501		Main Battery						RE		AWL - Life Limit		
	24 A/F	RG-380E/40L 41231367 MM:042402, Ref:BT101 (SOURCE: Maintenance Manual 040002)	0				Mos	11-Nov-2022	24	11-Nov-2024	1.1 Years	
				0				Hrs	14814:28	1,200	16014:28	963:50 Hrs
								Ldg	10,886			
243000-0601		Starter/Generator						RE			≈27-Jun-2024	
	24 A/F	Left					Mos	25-May-2022				
	45AS88801-017			0				Hrs	14622:44	1,000	15622:44	572:06 Hrs
	Y01237							Ldg	10,755			
243000-0602		Starter/Generator						RE			≈27-Jun-2024	
	24 A/F	Right					Mos	25-May-2022				
	45AS88801-017			0				Hrs	14622:44	1,000	15622:44	572:06 Hrs
	P1367							Ldg	10,755			
243000-0701		Cabin Temperature Selector						RE (O/C)				
	24 A/F	Unknown Unknown					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243000-0801		Overcurrent Sensor Relay						RE (O/C)				
	24 A/F	Left					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243000-0802		Overcurrent Sensor Relay						RE (O/C)				
	24 A/F	Left					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243000-0803		Overcurrent Sensor Relay						RE (O/C)				
	24 A/F	Right					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243000-0901		Battery Temperature Indicator						RE (O/C)				
	24 A/F	Unknown Unknown					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243000-1001		Starter/Generator Positive Ground Fault Current Transformer						RE (O/C)				
	24 A/F	Left					Mos	21-Nov-2000				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
243000-1002	Starter/Generator Positive Ground Fault Current Transformer						RE (O/C)			
 24 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
243000-1101	Starter/Generator Negative Ground Fault Current Transformer						RE (O/C)			
 24 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
243000-1102	Starter/Generator Negative Ground Fault Current Transformer						RE (O/C)			
 24 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
243000-1401	Forward Fuselage Current Transformer						RE (O/C)			
 24 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
243000-1501	Fuselage Current Transformer						RE (O/C)			
 24 A/F	Aft					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
243100-0101	Load Bus Tie Remote Controlled Circuit Breaker						RE (O/C)			
 24 A/F	Left					Mos	11-Nov-2022			
45AS88810-003						Hrs	14814:28			
004416						Ldg	10,886			
243100-0102	Load Bus Tie Remote Controlled Circuit Breaker (RCCB)						RE (O/C)			
 24 A/F	Right					Mos	11-Nov-2022			
45AS88810-003						Hrs	14814:28			
004415						Ldg	10,886			
243100-0201	Indicator Panel						RE (O/C)			
 24 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
243100-0202	Indicator Panel						RE (O/C)			
 24 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
24-NTXI-D16.a	LEFT- HAND POWER PLANT, PYLON AND NACELLE - STARTER GENERATOR - (Generator removal is not necessary) - Inspect for security, visible damage and installation.						RE		ICA	≈21-Dec-2023
 24 A/F	05-20-01					Mos	06-Apr-2023			
						Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
Ref:NTX1-ICA Ch.05 (Tol. Adjustment: -36.2 Hrs) (SOURCE: FAA STC ST02371LA)						Ldg	11,028			
24-NTXI-D16.b	LEFT- HAND POWER PLANT, PYLON AND NACELLE - STARTER GENERATOR - (Generator removal is not necessary) - Inspect Brushes for cracks and wear.						RE		ICA	≈21-Dec-2023
 24 A/F	05-20-01					Mos	06-Apr-2023			
						Hrs	15050:38	200	+40	(15214:28) 163:50 Hrs (+40)
Ref:NTX1-ICA Ch.05 (Tol. Adjustment: -36.2 Hrs) (SOURCE: FAA STC ST02371LA)						Ldg	11,028			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
24-NTXI-D16.c	LEFT- HAND POWER PLANT, PYLON AND NACELLE - STARTER GENERATOR - (Generator removal is not necessary) - Inspect commutator and electrical connections for security, wear, deterioration and damage.						RE		ICA	≈21-Dec-2023
 24 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NTX1-ICA Ch.05 (Tol. Adjustment: -36.2 Hrs) (SOURCE: FAA STC ST02371LA)				Ldg	11,028				
24-NTXI-E16.a	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - STARTER GENERATOR - (Generator removal is not necessary) - Inspect for security, visible damage and installation.						RE		ICA	≈21-Dec-2023
 24 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NTX1-ICA Ch.05 (Tol. Adjustment: -36.2 Hrs) (SOURCE: FAA STC ST02371LA)				Ldg	11,028				
24-NTXI-E16.b	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - STARTER GENERATOR - (Generator removal is not necessary) - Inspect Brushes for cracks and wear.						RE		ICA	≈21-Dec-2023
 24 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NTX1-ICA Ch.05 (Tol. Adjustment: -36.2 Hrs) (SOURCE: FAA STC ST02371LA)				Ldg	11,028				
24-NTXI-E16.c	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - STARTER GENERATOR - (Generator removal is not necessary) - Inspect commutator and electrical connections for security, wear, deterioration and damage.						RE		ICA	≈21-Dec-2023
 24 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NTX1-ICA Ch.05 (Tol. Adjustment: -36.2 Hrs) (SOURCE: FAA STC ST02371LA)				Ldg	11,028				
24-PL21-E1	AUX BATTERY SYSTEM TESTS 6 Months- Perform a periodic Test of the Battery. The procedure is provided in the JET PS835 Function Check section 7 located in this manual.						RE		ICA	
 24 A/F					Mos	16-Aug-2023	6		30-Nov-2023	57 Days
					Hrs	15050:38				
	Ref:373-00-0002 Ch.05 (Tol. Adjustment: -95d) (SOURCE: FAA STC ST10959SC) (NOTE: Every 3 - 6 Months)				Ldg	11,028				
24-PL21-E2	AUX BATTERY SYSTEM TESTS 12 Months - Perform a Battery Capacity Test of the Battery. The procedure is referenced in the Maintenance Practices Section of the JET Emergency Battery Component Installation Manual, P/N TP-336 (Rev G. or later revision). Refer to this manual for additional related information regarding the maintenance of the PS-835 Emergency Battery.						RE		ICA	
 24 A/F					Mos	11-Nov-2022	12		30-Sep-2023	OVD
					Hrs	14814:28				
	Ref:373-00-0002 Ch.05 (Tol. Adjustment: -59d) (SOURCE: FAA STC ST10959SC)				Ldg	10,886				
24-STC-01	Astronics 115 VAC Cabin Inverter - Wire/Cable/Racks/Connectors - Inspect system installation components condition and security.						RE		STC, Astronics 115 Inverter Installed	≈24-Jun-2024
 24 A/F					Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	[15614:28]	563:50 Hrs (+40)
	Ref:DB1108018 (SOURCE: STC ST03960AT)				Ldg	10,886				
93-20-01	Engine Electronic Fuel Control Wiring						T (A/R)		Mandatory	
 24 A/F					Mos					
	Eff: 02-Nov-1993				Hrs					
					Ldg					
H240001	PILOT'S COMPARTMENT - ELECTRICAL COMPONENTS - AREA INSPECTION - (Accessible without interior disassembly) - Inspect for condition and evidence of overheating.						RE		Scheduled Inspections	≈24-Jun-2024
 24 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H240002	AFT FUSELAGE - BATTERY INSTALLATION / a. Inspect battery installation for condition. / b. Inspect battery terminal connector for security of connection, corrosion and evidence of overheating. Disassemble and clean if corrosion is noted.						RE		Scheduled Inspections	≈24-Jun-2024
 24 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				

Task No	Description						Categories			Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H240004		PILOT'S COMPARTMENT - ELECTRICAL EQUIPMENT (SIDE JUNCTION) PANEL, POWER RELAY PANEL, RESISTOR RELAY (LOAD SHED) PANEL, CIRCUIT BREAKER PANELS and ASSOCIATED WIRING - Detail inspect for condition, deterioration and evidence of overheating.						RE		Scheduled Inspections	≈10-Jul-2024
	24 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401				
H240005		CABIN SECTION - ELECTRICAL COMPONENTS - AREA INSPECTION - (Accessible without interior disassembly) - Inspect for condition and evidence of overheating.						RE		Scheduled Inspections	≈24-Jun-2024
	24 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886				
H240007		FORWARD FUSELAGE - ELECTRICAL AND AVIONICS COMPONENTS - AREA INSPECTION (Forward of the pressure bulkhead; Avionics removal not required) / a. Detail inspect electrical and avionics components, wiring and connectors for condition, deterioration and evidence of overheating. / b. Detail inspect avionics shelves and mounting for condition. / c. Detail inspect pitot and static system plumbing for condition, deterioration and routing. / d. Detail inspect plumbing, coax and wiring for condition at the forward pressure bulkhead feed through locations.						RE		Scheduled Inspections	≈10-Jul-2024
	24 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401				
H240008		AFT FUSELAGE - BATTERY, EXTERNAL POWER AND GENERATOR GROUNDING TERMINALS AND HARDWARE - Inspect for security of connection, corrosion and evidence of overheating. Disassemble and clean if corrosion is noted, or if generator load split is noted (Ref. Chapter 20-20-03). Access through panels 311FL and 312DR as shown in Chapter 06-50-00.						RE		Scheduled Inspections	≈24-Jun-2024
	24 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886				
H240009		AFT FUSELAGE - ELECTRICAL COMPONENTS - AREA INSPECTION - Inspect aft fuselage area electrical components for condition and evidence of overheating.						RE		Scheduled Inspections	≈24-Jun-2024
	24 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886				
H240011		ENGINE GROUND RUN AND OPERATIONAL CHECKS - INVERTER SYSTEM - Perform INVERTER SYSTEM FUNCTIONAL TEST (Ref. Chapter 24-20-00).						RE		Scheduled Inspections	≈24-Jun-2024
	24 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)					Ldg	10,886				
H240012		STANDBY POWER SUPPLY BATTERY (JET Model P5835) - Perform battery capacitance test (Ref. Chapter 24-30-02 in the Component Maintenance Manual, 128-590001-81 or subsequent.						RE		Scheduled Special Inspections	
	24 A/F					Yrs	11-Nov-2022	1		30-Nov-2023	57 Days
						Hrs	14814:28				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	10,886				
H240013		AHRS POWER SUPPLY BATTERY (JET Model P5835) - Perform battery capacitance test (Ref. Chapter 24-30-02 in the Component Maintenance Manual, 128-590001-81 or subsequent.						RE		Scheduled Special Inspections	
	24 A/F					Yrs	11-Nov-2022	1		30-Nov-2023	57 Days
						Hrs	14814:28				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	10,886				
H240014		CABIN SECTION - ELECTRICAL COMPONENTS - AREA INSPECTION (With Interior Panels Removed) / a. Inspect cabin sidewall and toilet area electrical components, wiring and connectors for condition, deterioration and evidence of overheating. / b. Detail inspect L/H and R/H control junction boxes for condition and indication of damage to the PCB cards, mounting or surrounding support structure. (Removal of junction boxes not required) / c. Inspect PCB electrical wiring and connectors for condition, deterioration and evidence of overheating.						RE		Scheduled Inspections	≈10-Jul-2024
	24 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401				
H240015		CABIN SECTION - GENERATOR CONTROL UNITS (GCU) - Inspect both GCUs and electrical connectors for condition and security of connection.						RE		Scheduled Inspections	≈24-Jun-2024
	24 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Lda	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H240016	FORWARD FUSELAGE - ELECTRICAL AND AVIONICS COMPONENTS - AREA INSPECTION (Forward of the pressure bulkhead; Avionics removal not required) - Inspect for condition and evidence of overheating.						RE		Scheduled Inspections	≈24-Jun-2024
24 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H240017	PILOT'S COMPARTMENT - ELECTRICAL WIRING AND CONNECTORS (Below Floor Panels) - Detail inspect for condition, deterioration and evidence of overheating.						RE		Scheduled Inspections	≈10-Jul-2024
24 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H240018	ENGINE GROUND RUN AND OPERATIONAL CHECKS - DC GENERATION AND CONTROL SYSTEM - Perform DC GENERATION AND CONTROL SYSTEM FUNCTIONAL TEST (Ref. Chapter 24-30-00).						RE		Scheduled Inspections	≈10-Jul-2024
24 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)				Ldg	10,401				
H240019	STARTER-GENERATOR (Generator removal is not necessary.) (Ref. Chapter 80-10-00). / a. Inspect for security and visible damage. / b. Inspect brushes for wear. / c. Inspect electrical connections for security, wear, deterioration and damage.						RE		Scheduled Special Inspections	≈21-Dec-2023
24 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	11,028				
H240020	STARTER-GENERATOR (Generator removal is not necessary.) (Ref. Chapter 80-10-00). / a. Inspect for security and visible damage. / b. Inspect brushes for wear. / c. Inspect electrical connections for security, wear, deterioration and damage.						RE		Scheduled Special Inspections	≈21-Dec-2023
24 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	11,028				
H243026	MAIN BATTERY - Perform the EMERGENCY CAPACITY TEST in accordance with battery manufacturer's maintenance recommendations.						T		Scheduled Special Inspections	
24 A/F					Mos	11-Nov-2022	12		30-Nov-2023	57 Days
					Hrs	14814:28	600	+40	15414:28	363:50 Hrs (+40)
	(Manual Adjustment: 0d) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	10,886				
▼ 25 - EQUIPMENT/FURNISHINGS										
	Infant life vest						RE (-)			
25 A/F					Mos	21-Dec-2020				
P0640-101	New				Hrs	13889:42				
20080750013					Ldg	10,310				
	Restored Date 20-Aug-2020									
	Recertify No.1 Infant Life Vest						RE			
25 A/F					Yrs	21-Dec-2020	5		20-Aug-2025	1.9 Years
P0640-101					Hrs	13889:42				
20080750013					Ldg	10,310				
	Certified Date 20-Aug-2020									
	Toilet						RE (-)			
25 A/F					Mos					
OK-ESC					Hrs					
Unknown					Ldg					
	Toilet Pump U/S						RE (-)			
25 A/F					Mos	29-Jul-2019				
5250-7					Hrs	12821:08				
P9552					Ldg	9,654				

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		First Aid Kit Expiration					RE (Due)				
	25 A/F						Mos	21-Nov-2022		31-Dec-2023	88 Days
	AVKIT 220						Hrs	14830:35			
	LI211119N						Ldg	10,895			
	Expiration Date 31-Dec-2023										
2007-0256-CN		CANCELLED: Equipment / Furnishings - Seat Restraint System Plastic Rotary Buckle Handle - Inspection / Replacement					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos				
	Eff: 11-May-2021						Hrs				
	(NOTE: NOTE: This Notice cancels EASA AD 2007-0256 dated 19 September 2007.)										
2007-24-01		Undersized, and consequently unprotected, wire in the galley cabinets.					T (A/R) Mandatory				
	25 A/F						Mos				
	Eff: 02-Jan-2008						Hrs				
	Brand A:9990-2007-24-01										
2009-07-02		Flightcrew seats					RE (-) Mandatory				
	25 A/F						Mos				
	Eff: 30-Apr-2009						Hrs				
	(NOTE: Raytheon Mandatory SB 25-2536 R2)										
2016-0164		Cabin Attendant Seat - Inspection (Superseded by AD 2017-0001)					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos				
	Eff: 24-Aug-2016						Hrs				
2016-0210		Seat Energy Absorber Assembly – Replacement					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos				
	Eff: 07-Nov-2016						Hrs				
2019-15-10		Safran Aerosystems Life Jackets with P/N 210225-2, P/N 216200-0, or P/N 216203-0 - Inspect/ Replace/ Repair					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos	16-Dec-2019			
	Eff: 19-Sep-2019 Not Applicable						Hrs	13097:41			
	(UPDATE NOTE: NA by P/N) (NOTE: NOTE: Refer to Zodiac Aerospace Services Service Bulletin (SB) 25-65-33, Revision 02, dated March 15, 2019.)										
2019-21-06		Ipeco Pilot and Co-Pilot Seats - Modification/ Re-Identification (This AD replaces AD 2017-22-02) (Superseded by FAA AD 2023-14-10)					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos	16-Dec-2019			
	Eff: 13-Dec-2019 Not Applicable						Hrs	13097:41			
	(UPDATE NOTE: NA by P/N)										
2019-21-06 Par. (g)(1)		Ipeco Pilot and Co-Pilot Seats - Modify and Re-Identify					T (-) Mandatory (Appliance AD)				
	25 A/F						Yrs	16-Dec-2019			
	Eff: 12-Dec-2017 Not Applicable						Hrs	13097:41			
	(UPDATE NOTE: NA by P/N) (NOTE: APPLICABILITY: For seats that have not installed the tracklock spring modification kit.)										
2019-21-09		Aviointeriors S.p.A. (Aviointeriors) Centaurus Economy Class 13E, 13H, and 13K Passenger Seats with Life Vest Pouch, P/N 313907100004 - Inspection/ Replacement					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos	16-Dec-2019			
	Eff: 18-Dec-2019 Not Applicable						Hrs	13097:41			
	(UPDATE NOTE: NA by P/N)										
2019-21-09 Par. (g)(1)		Aviointeriors S.p.A. (Aviointeriors) Centaurus Economy Class 13E, 13H, and 13K Passenger Seats with Life Vest Pouch, P/N 313907100004 - Inspection					RE (-) Mandatory (Appliance AD)				
	25 A/F						Mos	16-Dec-2019			
	Eff: 18-Dec-2019 Not Applicable						Hrs	13097:41			
	(UPDATE NOTE: NA by P/N)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2019-21-09 Par. (g)(2)(3)	Aviointeriors S.p.A. (Aviointeriors) Centaurus Economy Class 13E, 13H, and 13K Passenger Seats with Life Vest Pouch, P/N 313907100004 - Replacement								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	16-Dec-2019			
Eff: 18-Dec-2019 Not Applicable						Hrs	13097:41			
(UPDATE NOTE: NA by P/N) (NOTE: After the effective date of this AD, do not install an Aviointeriors Centaurus Economy Class passenger seat with a P/N identified in paragraph (c) of this AD unless the affected seat life vest pouch assembly has been inspected in accordance with paragraph (g)(1) of this AD, and depending on the finding, replaced with a part eligible for installation.)						Ldg	9,828			
2021-0137	Equipment/Furnishings - Pilot and Co-Pilot Seats/Longitudinal Locking System Pins - Measurement/Adjustment								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	17-Aug-2021			
Eff: 22-Jun-2021 Not Applicable	N/A by PN					Hrs	14294:02			
(NOTE: APPLICABILITY: 191 series pilot seats, having Part Number (P/N) 19101-00-00, and 191 series co-pilot seats, having P/N 19102-00-00.						Ldg	10,545			
COMPLIANCE: Within 750 flight hours after the effective date of this AD, measure the length of the LH and RH locking pin installed in the longitudinal seat locking system in accordance with the instructions of the SB.)										
2021-07-13	Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	14-Nov-2021			
Eff: 11-May-2021 Not Applicable	NA BY PN					Hrs	14475:17			
						Ldg	10,658			
2021-07-13 Par. (e)(1)	Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Inspect the Buckle Handle for a Crack								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	14-Nov-2021			
Eff: 11-May-2021 Not Applicable	NA BY PN					Hrs	14475:17			
(NOTE: COMPLIANCE: Within 6 months, inspect the buckle handle for a crack. If the buckle handle is cracked, before further flight, remove the buckle as depicted in Figure 5 and by following the Procedures, paragraph 9, of SB 25-1111432, and replace it with an airworthy buckle, except you are not required to return the removed buckle to Pacific Scientific.)						Ldg	10,658			
2021-07-13 Par. (e)(2)	Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Measure the Thickness of the Buckle Handle Vane								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	14-Nov-2021			
Eff: 11-May-2021 Not Applicable	NA BY PN					Hrs	14475:17			
(NOTE: COMPLIANCE: Within 12 months, measure the thickness of the buckle handle vane as depicted in Figure 3 of SB 25-1111432. If the handle vane thickness is 0.125 inch or greater, before further flight, remove the buckle from service and replace it with an airworthy buckle.)						Ldg	10,658			
2022-07-05	Parachute - MARS A.S. ATL-88/90-1B (Commercially known as ATL-15 SL) Emergency Parachutes								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	17-May-2022			
Eff: 04-Apr-2022 Not Applicable						Hrs	14622:44			
(NOTE: APPLICABILITY: This AD applies to MARS A.S. ATL-88/90-1B (commercially known as ATL-15 SL) emergency parachutes that meet either of the criterion in paragraph (c)(1) or (2) of this AD: (1) The parachute has a date of manufacture of January 1, 2016, or later; or (2) The date of manufacture of the parachute is unknown.)						Ldg	10,755			
2022-24-04	Parachute - Modify and Re-identify Emergency Parachute (P/N) 09994, P/N 09995 and P/N 09996								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	16-Dec-2022			
Eff: 18-Dec-2022 Not Applicable						Hrs				
(AVG MAN HRS: 6) (NOTE: APPLICABILITY: This AD applies to MarS A.S. ATL-88/90-1B (commercially known as ATL-15 SL) emergency parachutes part number (P/N) 09994, P/N 09995, and P/N 09996 (no dash number) that meet either of the criterion in paragraph (c)(1) or (2) of this AD: (1) The parachute has a date of manufacture of January 1, 2016, or later; or (2) The date of manufacture of the parachute is unknown.						Ldg				
COMPLIANCE: As of the effective date of this AD, modify and re-identify each emergency parachute in accordance with the Service Bulletin Procedure, paragraph 7.b., of MarS a.s. Service Bulletin No. 01/04/2022, Rev. C, dated April 8, 2022.)										
2023-12-25	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets								RE (-)	Mandatory
25 A/F						Mos	23-Jul-2023			
Eff: 23-Aug-2023 Not Applicable	N/A Due to wrong manufacturer					Hrs				
(NOTE: APPLICABILITY: This AD applies to Survitec Group Limited (RFD Beaufort Ltd.) life jackets identified in paragraphs (c) (1) and (2) of this AD, having a part number and serial number identified in tables 2 through 13 of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021, and a date of manufacture between October 1, 2018, and April 30, 2019, inclusive.)						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
2023-12-25 Par. (g)		Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection						RE (-)		Mandatory	
25 A/F						Mos	23-Jul-2023				
Eff: 23-Aug-2023 Not Applicable		N/A Due to wrong manufacturer				Hrs					
		(NOTE: COMPLIANCE: Within 4 months after the effective date of this AD, do a general visual inspection for a discrepancy (mismatch of the valise/container description and life jacket type) of the life jacket, in accordance with paragraphs 2.A. through 2.C. of the Accomplishment Instructions of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021.)				Ldg					
2023-12-25 Par. (h)		Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action						RE (-)		Mandatory	
25 A/F						Mos	23-Jul-2023				
Eff: 23-Aug-2023 Not Applicable		N/A Due to wrong manufacturer				Hrs					
		(NOTE: COMPLIANCE: Before further flight after accomplishing the requirements of paragraph (g) of this AD, do the applicable actions required by paragraph (h)(1) and (2) of this AD.)				Ldg					
2023-14-10		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)						RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	06-Aug-2023				
Eff: 07-Sep-2023 Not Applicable		N/A by PN				Hrs					
		(NOTE: APPLICABILITY: (1) This AD applies to: (i) Ipeco Holdings Limited (Ipeco) pilot and co-pilot seats with a part number (P/N) listed in Paragraph 1.A., Planning Information, Tables 1 and 2, of Ipeco Service Bulletin (SB) Number 063-25-14, Revision 00, dated August 14, 2018, and (ii) Ipeco pilot seat P/N 3A063-0099-01-1 and Ipeco co-pilot seat P/N 3A063-0100-01-1. (2) These seats are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR 42 and ATR 72 airplanes.)				Ldg					
2023-14-10 Par. (g)(1)		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat						RE (-)		Mandatory (Appliance AD)	
25 A/F						Yrs	06-Aug-2023				
Eff: 12-Dec-2017 Not Applicable		N/A by PN				Hrs					
		(NOTE: COMPLIANCE: For seats that have not installed the track lock spring modification kit, within two years after December 12, 2017 (the effective date of AD 2017-22-02, Amendment 39-19082 (82 FR 51552, November 7, 2017)), modify and re-identify each affected pilot and co-pilot seat using the Accomplishment Instructions of Ipeco SB Number 063-25-08, Revision 00; Ipeco SB Number 063-25-09, Revision 00; or Ipeco SB Number 063-25-10, Revision 00; all dated May 31, 2016, as applicable to each affected seat.)				Ldg					
2023-14-10 Par. (g)(2)(i)		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat						RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	06-Aug-2023				
Eff: 07-Sep-2023 Not Applicable		N/A by PN				Hrs	0				
						Ldg					
2023-14-10 Par. (g)(2)(ii)		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat						RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	06-Aug-2023				
Eff: 07-Sep-2023 Not Applicable		N/A by PN				Hrs					
		(NOTE: COMPLIANCE: If, during any inspection as required by paragraph (g)(2)(i) of this AD, any damage on, or incorrect installation of, any track lock spring is found on the pilot or co-pilot seat, before further flight, replace both track lock springs of the affected seat with a part eligible for installation using the Accomplishment Instructions, paragraph 3.3.3.1 or 3.3.3.2, as applicable, of Ipeco SB Number 063-25-14, Revision 00, dated August 14, 2018.)				Ldg					
2023-14-10 Par. (h)		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action						RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	06-Aug-2023				
Eff: 07-Sep-2023 Not Applicable		N/A by PN				Hrs					
		(NOTE: COMPLIANCE: As a mandatory terminating action to the inspections required by paragraph (g)(2)(i) of this AD, within 12 months after the effective date of this AD, or at the next Base Maintenance check, whichever occurs later, modify and re-identify each affected seat in accordance with the Accomplishment Instructions of Ipeco SB Number 063-25-15, Issue 2; SB Number 063-25-16, Issue 2; SB Number 063-25-17, Issue 2; or SB Number 063-25-18, Issue 2; all dated March 8, 2022, as applicable to each affected seat.)				Ldg					
250000-0201		Valve, Shutoff						RE (O/C)			
25 A/F						Mos	21-Nov-2000				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
250000-0301		Motor, Torque								RE (O/C)	
	25 A/F	No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
250000-0302		Motor, Torque								RE (O/C)	
	25 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
250000-0303		Motor, Torque								RE (O/C)	
	25 A/F	No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
250000-0401		Emergency Locator Transmitter (ELT)								RE (O/C)	
	25 A/F	(UPDATE NOTE: New battery expire JUL/2027)					Mos	11-Nov-2022			
	453-5000						Hrs	14814:28			
	210-11856						Ldg	10,886			
251000-0101		Crew Seat								RE (O/C)	
	25 A/F	Pilot					Mos	21-Nov-2000			
	MHI 45A91203-321						Hrs	0			
	Unknown						Ldg	0			
251000-0102		Crew Seat								RE (O/C)	
	25 A/F	Copilot					Mos	21-Nov-2000			
	MHI 45A91203-321						Hrs	0			
	Unknown						Ldg	0			
252000-0101		Passenger Seat								RE (O/C)	
	25 A/F	Left No.1					Mos	21-Nov-2000			
	128-530135						Hrs	0			
	Unknown						Ldg	0			
252000-0102		Passenger Seat								RE (O/C)	
	25 A/F	Left No.2					Mos	21-Nov-2000			
	128-530135						Hrs	0			
	Unknown						Ldg	0			
252000-0103		Passenger Seat								RE (O/C)	
	25 A/F	Left No.3					Mos	21-Nov-2000			
	128-530135						Hrs	0			
	Unknown						Ldg	0			
252000-0104		Passenger Seat								RE (O/C)	
	25 A/F	Right No.1					Mos	21-Nov-2000			
	128-530135						Hrs	0			
	Unknown						Ldg	0			
252000-0105		Passenger Seat								RE (O/C)	
	25 A/F	Right No.2					Mos	21-Nov-2000			
	128-530135						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
252000-0106	Passenger Seat									
25 A/F	Right No.3					Mos	21-Nov-2000		RE (O/C)	
128-530135						Hrs	0			
Unknown						Ldg	0			
252000-0201	Swivel Seat									
25 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
252000-0301	Toilet Seat									
25 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
254000-0101	Lavatory Timer Valve Assembly									
25 A/F						Mos	01-Nov-2012		RE (O/C)	
3012-24	New					Hrs	7921			
T6575						Ldg	6,721			
254000-0201	Pump Motor Lavatory									
25 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
256000-0201	Elt Antenna									
25 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
256000-0301	ELT Battery - Replacement									
25 A/F								RE	Life Limit	
452-0133		0				Mos	18-Feb-2022	60	[31-Jan-2027]	3.3 Years
393080-007						Hrs	14572:58			
(SOURCE: 25-61-00 P 203-212)						Ldg	10,722			
256000-0401	Life Vest									
25 A/F	Pilot					Mos			RE (O/C)	
P01074-201						Hrs				
18111080053						Ldg				
256000-0402	Life Vest									
25 A/F	Copilot					Mos			RE (O/C)	
P01074-201						Hrs				
18111080027						Ldg				
256000-0501	Life Vest (Passenger)									
25 A/F	No.1					Mos			RE (O/C)	
P01074-201						Hrs				
18031560036						Ldg				
256000-0502	Life Vest (Passenger)									
25 A/F	No.2					Mos			RE (O/C)	
P01074-201						Hrs				
18031560032						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
256000-0503		Life Vest (Passenger)								RE (O/C)	
✖	25 A/F	No.3									
	P01074-201										Mos
	18031560070										Hrs
											Ldg
256000-0504		Life Vest (Passenger)								RE (O/C)	
✖	25 A/F	No.4									
	P01074-201										Mos
	18031560023										Hrs
											Ldg
256000-0505		Life Vest (Passenger)								RE (O/C)	
✖	25 A/F	No.5									
	P01074-201										Mos
	18031560009										Hrs
											Ldg
256000-0506		Life Vest (Passenger)								RE (O/C)	
✖	25 A/F	No.6									
	P01074-201										Mos
	18031560016										Hrs
											Ldg
256000-0507		Life Vest (Passenger)								RE (O/C)	
✖	25 A/F	No.7									
	P01074-201										Mos
	18031560086										Hrs
											Ldg
256000-0508		Life Vest (Passenger)								RE (O/C)	
✖	25 A/F	No.8									
	Unknown										Mos
	Unknown										Hrs
											Ldg
256000-0509		Life Vest								RE (O/C)	
✖	25 A/F	No.9									
	Unknown										Mos
	Unknown										Hrs
											Ldg
256000-0510		Life Vest								RE (O/C)	
✖	25 A/F	No.10									
	Unknown										Mos
	Unknown										Hrs
											Ldg
256000-0511		Life Vest								RE (O/C)	
✖	25 A/F	No.11									
	Unknown										Mos
	Unknown										Hrs
											Ldg
256000-0601		First Aid Kit								RE (O/C)	
✖	25 A/F										
	AVKIT 220										Mos
	L1211119N										Hrs
											Ldg
74-08-09 R3		Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles								RE (-)	Mandatory
✖	25 A/F										
	Eff: 28-Mar-2012 Complied	C/W iaw AD instructions									Mos
	With										Hrs
		(AVG MAN HRS: 3) (NOTE: Not Recurring in Europe)									Ldg

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
93-25-15		Escape Hatch Substructure Rivets						T (A/R)		Mandatory	
	25 A/F					Mos					
	Eff: 14-Feb-1994					Hrs					
						Ldg					
94-05-09		Cabin Seat Frames						T (A/R)		Mandatory	
	25 A/F					Mos					
	Eff: 07-Apr-1994					Hrs					
						Ldg					
96-03-07		Flightcrew Seats (This AD is superseded by AD 2009-07-02)						RE (-)		Mandatory	
	25 A/F					Mos					
	Eff: 12-Feb-1996					Hrs					
						Ldg					
AFI-100		Cabin Configuration Installations - Inspect for damage to upholstery						RE	STC, Interior Cabin Configuration Installation		
	25 A/F	05-20-06				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,886				
AFI-101		Cabin Configuration Installations - Inspect safety belts for wear cuts, fraying, damage, and deterioration.						RE	STC, Interior Cabin Configuration Installation		
	25 A/F	05-20-06				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,886				
AFI-102		Cabin Configuration Installations - Inspect safety belt attachment fittings for wear and damage.						RE	STC, Interior Cabin Configuration Installation		
	25 A/F	05-20-06				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,886				
AFI-103		Cabin Configuration Installations - Inspect foot fittings for damage, and corrosion.						RE	STC, Interior Cabin Configuration Installation		≈10-Jul-2024
	25 A/F	05-20-08				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,401				
AFI-104		Cabin Configuration Installations - Inspect seat frame for damage, and corrosion.						RE	STC, Interior Cabin Configuration Installation		
	25 A/F	05-20-06				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,886				
AFI-105		Cabin Configuration Installations - Inspect overall seat for fit and function.						RE	STC, Interior Cabin Configuration Installation		
	25 A/F	05-20-06				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,886				
AFI-106		Cabin Configuration Installations - Check operation of toilet assembly						RE (A/R)	STC, Interior Cabin Configuration Installation		
	25 A/F					Mos					
						Hrs					
	(SOURCE: FAA STC ST01572WI) (NOTE: After each flight after toilet is used)					Ldg					
AFI-107		Cabin Configuration Installations - Check Aft divider door assembly for smooth, even operation.						RE	STC, Interior Cabin Configuration Installation		≈24-Jun-2024
	25 A/F	05-20-07				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: FAA STC ST01572WI)					Ldg	10,886				

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
CF-48-05 25 A/F	Emergency Flare Installations (Previously issued as T/11/48)						T (A/R)		Mandatory	
						Mos				
						Hrs				
						Ldg				
CF-59-01 25 A/F Eff: 31-Mar-1959	Floor-Mounted Hand-Pump Type Fire Extinguishers						RE (-)		Mandatory	
						Mos				
						Hrs				
						Ldg				
CF-83-31R2 25 A/F Eff: 07-Apr-1986	Lavatory Flush Pump Motors						RE (-)		Mandatory	
						Mos				
						Hrs				
						Ldg				
G-2021-0003 25 A/F Eff: 16-Jun-2021 Not Applicable (UPDATE NOTE: N/A by PN) (NOTE: APPLICABILITY: Survitec Group Limited (hereafter referred to as "Survitec" in this AD) Emergency Breathing System (EBS) P/N 12677009 fitted to Halo Passenger Lifejacket P/Ns 00031010 and 00031031. COMPLIANCE: Within 1 month after the effective date of this AD, perform inspection of the EBS in accordance with Alert Service Bulletin 25-206-A.)	Equipment/Furnishings - Life Jacket - Inspection						RE (-)		Mandatory (Appliance AD)	
						Mos	15-Jun-2021			
						Hrs	14128:53			
						Ldg	10,451			
G-2021-0004 25 A/F Eff: 05-Jul-2021 Not Applicable (UPDATE NOTE: NA by PN) (NOTE: APPLICABILITY: Survitec Group Limited (hereafter referred to as "Survitec" in this AD) Life Raft with packed assembly P/N 00051054 (Port) and 00051055 (Starboard). COMPLIANCE: Within 12 months after the effective date of this AD, perform inspection and functional check of life raft in accordance with Alert Service Bulletin 25-197-A.)	Equipment/Furnishings - Life Raft - Inspection						RE (-)		Mandatory (Appliance AD)	
						Mos	19-Aug-2021			
						Hrs	14294:02			
						Ldg	10,545			
H250001 25 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)	PILOT'S COMPARTMENT - PILOT'S AND COPILOT'S SEATS / a. Inspect upholstery, safety belts and shoulder harness for condition and proper operation of shoulder harness inertial reels. / b. Inspect seat adjusting mechanisms for proper locking.						RE		Scheduled Inspections	
						Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
						Ldg	10,886			
H250002 25 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)	PILOT'S COMPARTMENT - SMOKE GOGGLES - Inspect goggles and storage box for condition.						RE		Scheduled Inspections	
						Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
						Ldg	10,886			
H250003 25 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)	CABIN SECTION - DIVIDER AND PARTITIONS (Removal not required) - Inspect for condition.						RE		Scheduled Inspections	≈24-Jun-2024
						Mos	11-Nov-2022			
						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
						Ldg	10,886			
H250004 25 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)	CABIN SECTION - PASSENGER AND TOILET SEAT / a. Inspect upholstery, safety belts and shoulder harness for condition and proper operation of shoulder harness inertia reels. / b. Inspect seat adjusting mechanisms for proper locking (toilet seat exempt). / c. Inspect shoulder harness attachment post for worn or missing grommet and proper engagement with seat belt. / d. Check toilet servicing.						RE		Scheduled Inspections	
						Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
						Ldg	10,886			
H250005 25 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)	CABIN SECTION - REFRESHMENT CENTER AND STORAGE CABINETS (Removal not required) - Inspect for condition.						RE		Scheduled Inspections	≈24-Jun-2024
						Mos	11-Nov-2022			
						Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
						Ldg	10,886			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H250007		CABIN SECTION - SEAT RAILS AND ATTACHMENTS - Detail inspect seat rails and their attachments for condition and structural damage (Ref. Figure 603).						RE		Scheduled Inspections	≈10-Jul-2024
	25 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H250009		PILOT'S COMPARTMENT - RELIEF TUBE - If installed, inspect plumbing and storage box for condition.						RE		Scheduled Inspections	≈24-Jun-2024
	25 A/F	05-20-03				Mos	11-Nov-2022				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
						Ldg	10,886				
H250010		CABIN SECTION - PASSENGER AND TOILET SEAT - Perform operational check of the toilet assembly flushing system (Ref. Chapter 38, Component Maintenance Manual, P/N 128-590001-81.						RE		Scheduled Inspections	≈24-Jun-2024
	25 A/F	05-20-03				Mos	11-Nov-2022				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
						Ldg	10,886				
H250018		EMERGENCY LOCATOR TRANSMITTER (If installed) - Inspect the ELT as required by 14 CFR 91.207 (d) for: / a. Proper installation. / b. Battery corrosion. / c. Operation of controls and crash sensor. / d. The presence of sufficient signal radiated from it's antenna. Refer to the Artex Maintenance Manual, Document Numbers 570-1015 or 570-5000 or subsequent, for the appropriate ELT model number.						RE		Scheduled Special Inspections	
	25 A/F					Yrs	11-Nov-2022	1		11-Nov-2023	38 Days
	453-5000					Hrs	14814:28				
	210-11856					Ldg	10,886				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256030		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256030.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256030.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Yrs	19-Mar-2019				
	P01074-201					Hrs	12473:10				
	18111080053					Ldg	9,436				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256030.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
	25 A/F	Pilot				Yrs		10		20-Nov-2028	5.1 Years
	P01074-201					Hrs					
	18111080053					Ldg					
	Restored Date 20-Nov-2018										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256031		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256031.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256031.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Yrs	19-Mar-2019				
	P01074-201					Hrs	12473:10				
	18111080027					Ldg	9,436				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H256031.3	LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
 25 A/F	Copilot						10		20-Nov-2028	5.1 Years
P01074-201										
18111080027										
Restored Date 20-Nov-2018										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256032	INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256032.1	LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256032.2	SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256032.3	LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
 25 A/F	No.1						10		16-Mar-2028	4.5 Years
P01074-201										
18031560036										
Restored Date 16-Mar-2018										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256033	INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256033.1	LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256033.2	SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256033.3	LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
 25 A/F	No.2						10		16-Mar-2028	4.5 Years
P01074-201										
18031560032										
Restored Date 16-Mar-2018										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256034	INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256034.1	LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
 25 A/F										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H256034.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256034.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
	25 A/F	No.3						10		16-Mar-2028	4.5 Years
	P01074-201										
	18031560070										
	Restored Date 16-Mar-2018										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256035		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256035.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256035.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256035.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
	25 A/F	No.4						10		16-Mar-2028	4.5 Years
	P01074-201										
	18031560023										
	Restored Date 16-Mar-2018										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256036		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256036.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256036.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256036.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
	25 A/F	No.5						10		16-Mar-2028	4.5 Years
	P01074-201										
	18031560009										
	Restored Date 16-Mar-2018										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H256037		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H256037.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256037.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256037.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
	25 A/F	No.6				Yrs		10		16-Mar-2028	4.5 Years
	P01074-201					Hrs					
	18031560016					Ldg					
	Restored Date 16-Mar-2018										
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256038		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256038.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256038.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Hrs					
						Ldg					
H256038.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE		Scheduled Special Inspections	
	25 A/F	No.7				Yrs		10		16-Mar-2028	4.5 Years
	P01074-201					Hrs					
	18031560086					Ldg					
	Restored Date 16-Mar-2018										
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256039		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F	No.8				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256039.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F	No.8				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256039.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F	No.8				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256039.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.						RE (N/A)		Scheduled Special Inspections	
	25 A/F	No.8				Yrs	16-Oct-2018				
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H256040		INDIVIDUAL FLOATATION DEVICE (Model Number GA-12) - Recertify device once a year after being placed in service.							RE (N/A)	Scheduled Special Inspections	
	25 A/F	No.9					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256040.1		LIFE PRESERVER (Model XF-35 - P/N P01074-113) - Recertify preserver every five years after being placed in service.							RE (N/A)	Scheduled Special Inspections	
	25 A/F	No.9					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256040.2		SCV-37 FLOATATION VEST (P/N HS3701C) - Recertify vest every ten years after being placed in service.							RE (N/A)	Scheduled Special Inspections	
	25 A/F	No.9					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H256040.3		LIFE PRESERVER (Model XF-35 - P/N P01074-201) - Recertify preserver every ten years after being placed in service.							RE (N/A)	Scheduled Special Inspections	
	25 A/F	No.9					Yrs	16-Oct-2018			
	Unknown						Hrs				
	Unknown						Ldg				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
SB-25-2021-04		Galley Espresso, Espresso Provisions, and Microwave Wiring - Potential Unsafe Condition							RE (-)	Mandatory	
	25 A/F						Mos	19-Nov-2021			
	Eff: 08-Nov-2021 Not Applicable	No findings					Hrs	14493:42			
							Ldg	10,674			
	(AVG MAN HRS: 3) (NOTE: COMPLIANCE: This Service Bulletin should be accomplished within the next 30 aircraft operating hours or at the next maintenance event, whichever comes first. NOTE: This service bulletin is not applicable to aircraft with dual hot cups (coffee/water) in the galley.)										
SB-25-2022-01		Modification to Galley Electrical Power Distribution Wiring to Correct a Potential Unsafe Condition							T (A/R)	Recommended	
	25 A/F						Mos	31-Jan-2023			
	Eff: 28-Nov-2022 Not Applicable	N/A due to wrong aircraft S/N					Hrs				
							Ldg				
	(AVG MAN HRS: 8) (NOTE: COMPLIANCE: RECOMMENDED - This Service Bulletin may be accomplished at the next convenient maintenance event at which downtime is sufficient to accomplish the modification. NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO AIRCRAFT WITH DUAL HOT CUPS (COFFEE/WATER) IN THE GALLEY.)										
▼ 26 - FIRE PROTECTION											
042601		Fire Bottle Engine Cartridge (Squib) - Service Life Limit							RE	AWL - Life Limit	
	26 A/F	Left No.1					Mos	15-Aug-2021	48	15-Aug-2025	1.9 Years
	13083-5						Hrs	14294:02			
	N/A						Ldg	10,545			
	(SOURCE: Maintenance Manual 040002)										
042601		Fire Bottle Engine Cartridge (Squib) - Service Life Limit							RE	AWL - Life Limit	
	26 A/F	Left No.2					Mos	15-Aug-2021	48	15-Aug-2025	1.9 Years
	13083-5						Hrs	14294:02			
	N/A						Ldg	10,545			
	(SOURCE: Maintenance Manual 040002)										
042601		Fire Bottle Engine Cartridge (Squib) - Service Life Limit							RE	AWL - Life Limit	
	26 A/F	Right No.1					Mos	15-Aug-2021	48	15-Aug-2025	1.9 Years
	13083-5						Hrs	14294:02			
	N/A						Ldg	10,545			
	(SOURCE: Maintenance Manual 040002)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
042601		Fire Bottle Engine Cartridge (Squib) - Service Life Limit						RE		AWL - Life Limit	
	26 A/F	Right No.2					Mos	15-Aug-2021	48	15-Aug-2025	1.9 Years
	13083-5						Hrs	14294:02			
	N/A						Ldg	10,545			
	(SOURCE: Maintenance Manual 040002)										
042602		Engine Fire Extinguisher Bottle - Hydrostatic Test						RE		AWL - Inspection Limitations	
	26 A/F	Left					Yrs	15-Aug-2021	5	31-Aug-2026	2.9 Years
	30400018						Hrs	14294:02			
	43628B1						Ldg	10,545			
	Hydrostatic Tested Date 11-Aug-2021										
	(SOURCE: Maintenance Manual 040002)										
042602		Engine Fire Extinguisher Bottle - Hydrostatic Test						RE		AWL - Inspection Limitations	
	26 A/F	Right					Yrs	15-Aug-2021	5	31-Aug-2026	2.9 Years
	30400018						Hrs	14294:02			
	53937B1						Ldg	10,545			
	Hydrostatic Tested Date 11-Aug-2021										
	(SOURCE: Maintenance Manual 040002)										
2000-05-06		Engine Fire Extinguisher Bottle Squibs						T (A/R)		Mandatory	
	26 A/F						Mos				
	Eff: 12-Apr-2000						Hrs				
							Ldg				
2021-0185		Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement						RE (-)		Mandatory (Appliance AD)	
	26 A/F						Mos	17-Aug-2021			
	Eff: 19-Aug-2021 Not Applicable	N/A by PN					Hrs	14294:02			
	(NOTE: APPLICABILITY: For Group 1 aircraft with HAFEX (Halon-free) hand-held fire extinguishers, having Part Number (P/N) P3APP003010A, P/N P3APP003010B or P/N P3APP003010C, all serial numbers (s/n).										
	COMPLIANCE: Within 30 days after the effective date of this AD, and, thereafter, at intervals not to exceed 6 months, inspect each affected fire extinguisher in accordance with the instructions of paragraph 3.2.C of the VSB, or equivalent maintenance instructions issued by the design (change) approval holder (see Note 1 of this AD).)										
2021-0185R2		Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement						RE (-)		Mandatory (Appliance AD)	
	26 A/F						Mos				
	Eff: 14-Sep-2022 Not Applicable	N/A due to wrong P/N					Hrs				
							Ldg				
2021-22-07		Fire Protection - Impaired Fire Extinguisher						RE (-)		Mandatory (Appliance AD)	
	26 A/F						Days	14-Nov-2021			
	Eff: 17-Nov-2021 Not Applicable	NA BY PN					Hrs	14475:17			
							Ldg	10,658			
2022-01-03		Fire Bottle, Portable - HAFEX (Halon-free) Hand-Held P3HAFEX Fire Extinguisher						RE (-)		Mandatory (Appliance AD)	
	26 A/F						Mos	28-Feb-2022			
	Eff: 07-Mar-2022 Not Applicable	NA by PN					Hrs	14572:58			
							Ldg	10,722			
	(NOTE: Required Actions: (1) Within 12 months after the effective date of this AD, remove each fire extinguisher identified in the introductory text of paragraph (c) from service.)										
260000-0101		Fire Detector						RE (O/C)			
	26 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
261000-0101	 26 A/F Unknown Unknown	Engine Fire Detection Control Unit Left						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
261000-0102	 26 A/F Unknown Unknown	Engine Fire Detection Control Unit Right						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
261000-0201	 26 A/F Unknown Unknown	Engine Fire Detection Sensor Left						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
261000-0202	 26 A/F Unknown Unknown	Engine Fire Detection Sensor Right						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
262000-0101	 26 A/F 30400018 43628B1	Engine Fire Extinguisher Bottle Left						RE (O/C)			
						Mos	15-Aug-2021				
						Hrs	14294:02				
						Ldg	10,545				
262000-0102	 26 A/F 30400018 53937B1	Engine Fire Extinguisher Bottle Right						RE (O/C)			
						Mos	15-Aug-2021				
						Hrs	14294:02				
						Ldg	10,545				
262000-0201	 26 A/F C352TS G-97925033	Portable Fire Extinguisher Cockpit New						RE (O/C)			
						Mos	16-Jan-2023				
			0			Hrs	14901:20				
			0			Ldg	10,933				
262000-0202	 26 A/F C352TS Y173443	Portable Fire Extinguisher Cabin						RE (O/C)			
						Mos	01-Jan-2011				
						Hrs					
						Ldg					
262000-0301	 26 A/F 13083-5 N/A Manufactured Date 25-Mar-2021 MM:042601 (SOURCE: Maintenance Manual 040002)	Fire Bottle Engine Cartridge (Squib) Left No.1						RE		AWL - Life Limit	
						Mos	15-Aug-2021	72	25-Mar-2027	3.5 Years	
						Hrs	14294:02				
						Ldg	10,545				
262000-0302	 26 A/F 13083-5 N/A Manufactured Date 25-Mar-2021 MM:042601 (SOURCE: Maintenance Manual 040002)	Fire Bottle Engine Cartridge (Squib) Left No.2						RE		AWL - Life Limit	
						Mos	15-Aug-2021	72	25-Mar-2027	3.5 Years	
						Hrs	14294:02				
						Ldg	10,545				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
262000-0303		Fire Bottle Engine Cartridge (Squib)								RE	AWL - Life Limit
	26 A/F	Right No.1					Mos	15-Aug-2021	72	09-Nov-2026	3.1 Years
	13083-5						Hrs	14294:02			
	N/A						Ldg	10,545			
		Manufactured Date 09-Nov-2020									
		MM:042601 (SOURCE: Maintenance Manual 040002)									
262000-0304		Fire Bottle Engine Cartridge (Squib)								RE	AWL - Life Limit
	26 A/F	Right No.2					Mos	15-Aug-2021	72	09-Nov-2026	3.1 Years
	13083-5						Hrs	14294:02			
	N/A						Ldg	10,545			
		Manufactured Date 09-Nov-2020									
		MM:042601 (SOURCE: Maintenance Manual 040002)									
262000-0401		Cabin Baggage Smoke Detector								RE (O/C)	
	26 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
26-NXT1-D13		LEFT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE FIRE EXTINGUISHER TUBING AND DETECTOR LOOP - Inspect for dents, security, cracks and condition.								RE	ICA ≈24-Jun-2024
	26 A/F	05-20-12					Mos	11-Nov-2022			
							Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
26-NXT1-D14		LEFT- HAND POWER PLANT, PYLON AND NACELLE - FIRE DETECTOR SENSOR CABLE INSPECTION - Inspect sensor cable for proper mounting, chafing security and general condition. Inspect cable for signs of bleed air leakage, cleanliness, nicks and abrasions.								RE	ICA ≈24-Jun-2024
	26 A/F	05-20-12					Mos	11-Nov-2022			
							Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
26-NXT1-E13		RIGHT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE FIRE EXTINGUISHER TUBING AND DETECTOR LOOP - Inspect for dents, security, cracks and condition.								RE	ICA ≈24-Jun-2024
	26 A/F	05-20-12					Mos	11-Nov-2022			
							Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
26-NXT1-E14		RIGHT- HAND POWER PLANT, PYLON AND NACELLE - FIRE DETECTOR SENSOR CABLE INSPECTION - Inspect sensor cable for proper mounting, chafing security and general condition. Inspect cable for signs of bleed air leakage, cleanliness, nicks and abrasions.								RE	ICA ≈24-Jun-2024
	26 A/F	05-20-12					Mos	11-Nov-2022			
							Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
H260002		AFT FUSELAGE - FIRE EXTINGUISHER SYSTEM / a. Inspect fire extinguisher containers for proper pressure (Ref. Chapter 26-20-00, Chart 201). / b. Inspect red overboard discharge disk for presence condition.								RE	Scheduled Inspections
	26 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)									
H260003		AFT FUSELAGE - FIRE EXTINGUISHER SYSTEM / a. Perform NACELLE FIRE EXTINGUISHER CONTAINER INSPECTION (Ref. Chapter 26-20-00) / b. Inspect fire extinguisher discharge plumbing for condition.								RE	Scheduled Inspections ≈24-Jun-2024
	26 A/F	05-20-03					Mos	11-Nov-2022			
							Hrs	14814:28	800	+40 (15614:28)	563:50 Hrs (+40)
							Ldg	10,886			
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H260004		AFT FUSELAGE - FIRE DETECTION SYSTEM - Perform FIRE DETECTION SYSTEM FUNCTIONAL TEST (RK-1 AND AFTER) (Ref. Chapter 26-10-00).								RE	Scheduled Inspections ≈10-Jul-2024
	26 A/F	05-20-04					Mos	12-May-2021			
							Hrs	14049:30	1,600	+40 (15649:30)	598:52 Hrs (+40)
							Ldg	10,401			
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H260005		AFT FUSELAGE - FIRE EXTINGUISHER SYSTEM / a. Perform FIRE EXTINGUISHER ACTUATOR CARTRIDGE/SQUIB INSPECTION (Ref. Chapter 26-20-00). / b. Perform NACELLE FIRE EXTINGUISHING SYSTEM FUNCTIONAL TEST (RK-1 AND AFTER) (Ref. Chapter 26-20-00).						RE		Scheduled Inspections	≈10-Jul-2024
	26 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H260006		PILOT'S COMPARTMENT - FIRE DETECTION SYSTEM - Perform FIRE DETECTION SYSTEM OPERATIONAL TEST (Ref. Chapter 26-10-00).						RE		Scheduled Inspections	≈24-Jun-2024
	26 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H262001		COCKPIT PORTABLE FIRE EXTINGUISHER - Inspect weight, operating pressure and condition.						RE		Scheduled Special Inspections	
	26 A/F	Cockpit				Yrs	16-Jan-2023	1		31-Jan-2024	4 Months
	C352TS					Hrs	14901:20				
	G-97925033					Ldg	10,933				
		Weighed Date 16-Jan-2023									
		(AVG MAN HRS: 0.5) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H262002		CABIN PORTABLE FIRE EXTINGUISHER - Inspect weight, operating pressure and condition.						RE		Scheduled Special Inspections	
	26 A/F	Cabin				Yrs	16-Aug-2023	1		31-Aug-2024	11.1 Months
	C352TS					Hrs	15050:38				
	Y173443					Ldg	11,028				
		Weighed Date 16-Aug-2023									
		(AVG MAN HRS: 0.5) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H262005		COCKPIT FIRE EXTINGUISHER - Hydrostatically test cylinder.						RE		Scheduled Special Inspections	
	26 A/F	Cockpit				Yrs	16-Jan-2023	12		16-Jan-2035	11.3 Years
	C352TS					Hrs	14901:20				
	G-97925033					Ldg	10,933				
		Hydrostatic Tested Date 16-Jan-2023									
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H262006		CABIN FIRE EXTINGUISHER - Hydrostatically test cylinder.						RE		Scheduled Special Inspections	
	26 A/F	Cabin				Yrs	01-Jan-2012	12		01-Jan-2024	89 Days
	C352TS					Hrs					
	Y173443					Ldg					
		Hydrostatic Tested Date 01-Jan-2012									
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
▼ 27 - FLIGHT CONTROLS											
2004-03-35		Printed circuit board (PCB)						T (A/R)		Mandatory	
	27 A/F					Mos					
		Eff: 24-Mar-2004				Hrs					
						Ldg					
2014-21-06		Flight controls - (Pitch Trim Actuator)						RE		Mandatory	≈08-Oct-2023
	27 A/F					Mos	23-Apr-2020				
		Eff: 28-Nov-2014 Complied With				Hrs	13258:28	1,800		15058:28	07:50 Hrs
		(NOTE: Accomplishment Instructions of Hawker Beechcraft Service Bulletin SB 27-4100, dated March 2012.)				Ldg	9,933				
270000-0101		Spoiler Servo Mount Clutch Teeth						RE (O/C)			
	27 A/F					Mos	21-Nov-2000				
	622-5027-002					Hrs					
	Unknown					Ldg					
270000-0201		Elevator Servo Mount Clutch Teeth						RE (O/C)			
	27 A/F					Mos	21-Nov-2000				
	622-6717-104					Hrs					
	5A3M					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
270000-0301		Rudder Servo Mount Clutch Teeth						RE (O/C)			
27	A/F						Mos	21-Nov-2000			
	622-6717-104						Hrs				
	GF3J						Ldg				
270000-0401		Roll Trim Indicator						RE (O/C)			
27	A/F						Mos	21-Nov-2000			
	45AS86848-001						Hrs	0			
	Unknown						Ldg	0			
270000-0501		Trim Actuator						RE (O/C)			
27	A/F	Left					Mos	01-Aug-2014			
	45AS61014-107						Hrs	9314			
	990709						Ldg	7,512			
270000-0502		Trim Actuator						RE (O/C)			
27	A/F	Right					Mos	12-Jan-2015			
	45AS61014-108	New					Hrs	9742			
	051008						Ldg	7,779			
270000-0601		Trim Tab Actuator Motor						RE (O/C)			
27	A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
270000-0701		Rudder Pedal						RE (O/C)			
27	A/F	Pilot - Left					Mos	11-Nov-2021			
	45AS38401-011						Hrs	14471.02			
	0240						Ldg	10,655			
270000-0702		Rudder Pedal						RE (O/C)			
27	A/F	Pilot - Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
270000-0703		Rudder Pedal						RE (O/C)			
27	A/F	Copilot - Left					Mos	01-Aug-2013			
	45AS38401-012	New					Hrs	8512			
	2324						Ldg	7,069			
270000-0704		Rudder Pedal						RE (O/C)			
27	A/F	Copilot - Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
270000-0801		Transducer-Pressure						RE (O/C)			
27	A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
270000-0802		Transducer-Pressure						RE (O/C)			
27	A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
270000-0901	Stabilizer, Trim Position Transmitter									
27 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
270000-1001	Pitch Trim Controller									
27 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
76621-4						Hrs	0			
Unknown						Ldg	0			
270000-1002	Pitch Trim Controller									
27 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
76621-4						Hrs	0			
Unknown						Ldg	0			
270000-1101	Follow Up Unit Switch									
27 A/F	Left					Mos	01-Oct-2013		RE (O/C)	
45AS61015-025	New					Hrs	8610			
98H78						Ldg	7,135			
270000-1102	Follow Up Unit Switch									
27 A/F	Right					Mos	14-Sep-2016		RE (O/C)	
45AS61015-025	New					Hrs	10897			
38F4						Ldg	8,473			
270000-1201	Flap Position Transmitter									
27 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
270000-1202	Flap Position Transmitter									
27 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
270000-1301	Flap Position Asymmetry									
27 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
270000-1302	Flap Position Asymmetry									
27 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
270000-1401	Flap Cylinder									
27 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
270000-1402	Flap Cylinder									
27 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
272000-0101	Rudder Trim Tab Actuator								RE (O/C)	
27 A/F						Mos	24-Feb-2023			
45AS61014-111	Overhauled			0		Hrs	14983:13			
070703				0		Ldg	10,987			
272000-0201	Rudder Trim Position Indicator								RE (O/C)	
27 A/F						Mos	12-May-2021			
720-303						Hrs	14049:30			
1103						Ldg	10,401			
272000-0301	Pressure Transducer								RE (O/C)	
27 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
272000-0302	Pressure Transducer								RE (O/C)	
27 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
27-2015-01 Rev IR	Nextant - Rudder Boost Shielding Correction								RE (-)	Mandatory
27 A/F						Mos	13-Mar-2015			
Eff: 10-Mar-2015 Complied	C/W iaw SB					Hrs	9901			
With						Ldg	7,877			
273000-0101	Pilot Column Control								RE (O/C)	
27 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
273000-0201	Copilot Column Control								RE (O/C)	
27 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
274000-0101	Pitch Trim Position Indicator								RE (O/C)	
27 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
275000-0101	Flap Assembly								RE (O/C)	
27 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
275000-0102	Flap Assembly								RE (O/C)	
27 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
275000-0201	Flap Follow-Up Switch								RE (O/C)	
27 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
275000-0202	 27 A/F Unknown Unknown	Flap Follow-Up Switch Right								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
275100-0101	 27 A/F Unknown Unknown	Flap System Lock Valve Left								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
275100-0102	 27 A/F Unknown Unknown	Flap System Lock Valve Right								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
275155-0101	 27 A/F Unknown Unknown	Flap Position Indicator								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
276000-0101	 27 A/F Unknown Unknown	Speed Brake Actuator								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
27-NXT1-A2	 27 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	PILOT COMPARTMENT - Verify RVDT installation for security, condition and chafing of the wiring harnesses. 05-20-12								RE	ICA ≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
							Ldg	10,886			
95-25-05	 27 A/F Eff: 16-Jan-1996	Securing Rivets On Control Push Rods								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
96-25-03	 27 A/F Eff: 24-Jan-1997	Flap Roller Retention Components								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
H270001	 27 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)	PILOT'S COMPARTMENT - RUDDER PEDALS (Above Floor Panels) - Inspect for condition and freedom of movement. 05-20-02								RE	Scheduled Inspections
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
							Ldg	10,886			
H270002	 27 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)	HORIZONTAL STABILIZER - PITCH TRIM POSITION TRANSMITTER AND LINKAGE - Inspect for condition. 05-20-03								RE	Scheduled Inspections ≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
							Ldg	10,886			
H270003	 27 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)	HORIZONTAL STABILIZER - PITCH TRIM OPERATION - Perform the complete PITCH TRIM SYSTEM FUNCTIONAL TEST (Ref. Chapter 27-40-00). 05-20-04								RE	Scheduled Inspections ≈10-Jul-2024
							Mos	12-May-2021			
							Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
							Ldg	10,401			
H270005	 27 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)	VERTICAL STABILIZER - RUDDER TRIM TAB AND HINGE - Inspect for condition. 05-20-03								RE	Scheduled Inspections ≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
							Ldg	10,886			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H270006	PILOT'S COMPARTMENT - CONTROL COLUMN (Above Floor Panels) / a. Inspect for condition and freedom of movement. / b. Inspect wire harness on forward side of the control column for damage and security.						RE		Scheduled Inspections	
27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H270008	MIDFUSELAGE - SPOILER OPERATION / a. Perform Spoiler OPERATIONAL CHECK (Ref. Chapter 27-60-00). NOTE: Not required if the complete SPOILER CONTROL SYSTEM FUNCTIONAL TEST procedure is performed. / b. Inspect spoiler servo cables for condition, routing and broken strands. / c. Perform SPOILER SERVO OPERATIONAL CHECKOUT (Ref. Chapter 22-13-00).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270009	VERTICAL STABILIZER - RUDDER OPERATION - Perform the complete RUDDER CONTROL SYSTEM FUNCTIONAL TESTS procedure (Ref. Chapter 27-20-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270010	VERTICAL STABILIZER - RUDDER TRIM OPERATION - Perform the complete RUDDER TRIM SYSTEM ADJUSTMENT/TEST procedure (Ref. Chapter 27-20-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270024	AFT FUSELAGE - CONTROL CABLES / a. Inspect thrust control cables and bellcranks for condition and routing. / b. Inspect rudder control cables, pulleys, guard pins and brackets from the aft pressure bulkhead to the rudder quadrant for condition, routing and broken strands. / c. Inspect rudder servo, servo cables and cable blocks for condition, routing, slippage and broken strands. / d. Perform RUDDER SERVO OPERATIONAL CHECKOUT (Ref. Chapter 22-13-00). / e. Inspect elevator control cables, pulleys, guard pins and brackets from the aft pressure bulkhead to the elevator quadrant for condition, routing and broken strands. / f. Inspect elevator servo, servo cables and cable blocks for condition, routing, slippage and broken strands. / g. Perform ELEVATOR SERVO OPERATIONAL CHECKOUT (Ref. Chapter 22-13-00).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270025	AFT FUSELAGE - CONTROL CABLES / a. Perform RUDDER SERVO CABLE TENSION ADJUSTMENT (Ref. Chapter 22-13-00). / b. Perform rudder SERVO CABLE CLEARANCE CHECK (Ref. Chapter 22-13-00). / c. Perform ELEVATOR SERVO CABLE TENSION ADJUSTMENT (Ref. Chapter 22-13-00). / d. Perform elevator SERVO CABLE CLEARANCE CHECK (Ref. Chapter 22-13-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270027	VERTICAL STABILIZER - ELEVATOR CABLES (Where accessible through access panels) / a. Detail inspect cables for proper routing, corrosion and broken strands. / b. Inspect pulleys and brackets for condition and security.						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270028	VERTICAL STABILIZER - ELEVATOR QUADRANT ASSEMBLY, PUSHROD AND CONNECTING HARDWARE, STOP BOLTS AND DOWN SPRING - Detail inspect for condition, seized bearings, freedom of movement and sufficient engagement of rod ends.						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270030	VERTICAL STABILIZER - RUDDER TRIM OPERATION / a. Perform RUDDER TRIM OPERATIONAL TEST (Ref. Chapter 27-20-00).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: This check is not required if the complete RUDDER TRIM SYSTEM ADJUSTMENT/TEST procedure is performed.)				Ldg	10,886				
H270031	HORIZONTAL STABILIZER - ELEVATOR HINGES AND BOLTS, TORQUE TUBE AND HORN LEVER, LEVER AND LINK ASSEMBLY, STOP BOLTS AND HEATER HORN/COUNTER BALANCE - Detail inspect for condition, seized bearings, freedom of movement and sufficient engagement of rod ends (Ref. Figure 605, Sheet 1).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H270032	HORIZONTAL STABILIZER - ELEVATOR OPERATION / a. Perform elevator NEUTRAL POSITION CHECK, Step a. and b. (Ref. Chapter 27-30-00). NOTE: This check is not required if the complete ELEVATOR ADJUSTMENT/TEST procedure in Chapter 27-30-00 is performed. / b. Perform elevator OPERATIONAL TEST (Ref. Chapter 27-30-00). NOTE: This check is not required if the complete ELEVATOR ADJUSTMENT/TEST procedure in Chapter 27-30-00 is performed.						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270034	PITCH TRIM ACTUATOR AND ATTACH BRACKET ASSEMBLY - / a. Detail inspect pitch trim actuator and attach bracket assembly for condition (Ref. Chapter 27-40-00, Figure 210). / b. Visually inspect the jackscrew and jacknut for metallic shavings, contamination / particles embedded in the grease, or wrapped around the jackscrew threads. / c. Perform the LUBRICATION SCHEDULE - HORIZONTAL STABILIZER PIVOT FITTING procedure (Ref. Chapter 12-20-00).						RE		Scheduled Special Inspections	≈21-Dec-2023
27 A/F	05-20-01				Mos	06-Apr-2023				
					Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	11,028				
H270035	HORIZONTAL STABILIZER - PITCH TRIM OPERATION / a. Perform TAKEOFF WARNING HORN CHECK (Ref. Chapter 27-40-00). NOTE: This check is not required if the complete PITCH TRIM SYSTEM FUNCTIONAL TEST procedure is performed. / b. Perform NORMAL OPERATIONAL TEST (Ref. Chapter 27-40-00). NOTE: This check is not required if the complete PITCH TRIM SYSTEM FUNCTIONAL TEST procedure is performed. / c. Perform EMERGENCY OPERATIONAL TEST (Ref. Chapter 27-40-00). NOTE: This check is not required if the complete PITCH TRIM SYSTEM FUNCTIONAL TEST procedure is performed.						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270037	VERTICAL STABILIZER - RUDDER TRIM ACTUATOR AND LINKAGE - Inspect for condition.						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270038	MIDFUSELAGE - SPOILER SYSTEM / a. Inspect spoiler mixer assembly, push rods and left and right sector assembly for condition, freedom of movement, seized bearings and sufficient engagement of rod ends. / b. Inspect speed brake actuator, hydraulic plumbing and limit switches condition. / c. Perform the complete SPOILER CONTROL SYSTEM FUNCTIONAL TEST (Ref. Chapter 27-60-00). / d. Perform SPOILER SERVO CABLE TENSION ADJUSTMENT (Ref. Chapter 22-13-00). / e. Perform spoiler SERVO CABLE CLEARANCE CHECK (Ref. Chapter 22-13-00). / f. Perform the complete SPEED BRAKE SYSTEM ADJUSTMENT/TEST procedure (Ref. Chapter 27-60-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270039	PILOT'S COMPARTMENT - FLIGHT CONTROL SECTOR MODULE / a. Detail inspect sector module assembly, control cables and push rods for condition, routing, freedom of movement, seized bearings and sufficient engagement of rod ends (Ref. Chapter 27-20-00, Figure 207). / b. Detail inspect rudder bungee and spoiler feel spring assembly for condition. / c. Detail inspect idler pulley and bracket installation (P/N 45A61341) for condition, cable routing, guide pin installation and freedom of movement.						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270041	CABIN SECTION - ELEVATOR, RUDDER AND SPOILER CONTROL CABLES, PULLEYS AND BRACKETS - Detail inspect for condition, routing and broken cable strands.						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270042	PILOT'S COMPARTMENT - RUDDER PEDALS (Below Floor Panels) (Ref. Chapter 27-20-00, Figure 207) / a. Detail inspect rudder pedals, rudder torque tube assembly and rudder and steering push rods for condition, freedom of movement, seized bearings and sufficient engagement of rods ends. / b. Detail inspect rudder bungee and feel spring assembly, bellcranks and push rods for condition, freedom of movement, seized bearings and sufficient engagement of rod ends. / c. Detail inspect brake master cylinders and hoses for condition and interference. / d. Detail inspect brake mixer valves and plumbing for condition.						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H270044		SCHEDULED D INSPECTIONS - RUDDER TORQUE TUBE ATTACHMENT AND TRIM TAB ACTUATOR ATTACHMENT / a. Perform a detailed inspection of the rudder torque tube attachment and rudder trim tab actuator attachments for cracks using a 10X magnifying glass. Focus on welds. / b. Detail inspect attaching bolts and surrounding structure for condition (Ref. Figure 606).						RE		Scheduled Inspections	≈29-Jul-2026
	27 A/F	05-20-05				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
						Ldg	10,401				
H270045		SCHEDULED D INSPECTIONS - ELEVATOR TORQUE TUBE / a. Perform detailed inspection of the elevator torque tube attachment for cracks with a 10X magnifying glass. Focus on welds. / b. Detail inspect attaching bolts and surrounding structure for condition (Ref. Figure 607).						RE		Scheduled Inspections	≈29-Jul-2026
	27 A/F	05-20-05				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
						Ldg	10,401				
H270047		PILOT'S COMPARTMENT - CONTROL YOKE - Inspect for condition and freedom of movement.						RE		Scheduled Inspections	
	27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
						Ldg	10,886				
H270048		LH and RH FLAP CABLES AND INTERCONNECT CABLES - Check cable tensions (Ref. Chapter 27-50-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270049		LH and RH FLAP CABLES AND INTERCONNECT CABLES - Check cable tensions (Ref. Chapter 27-50-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270050		LH and RH SPOILER CABLES - Check cable tension (Ref. Chapter 27-60-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270051		LH and RH SPOILER CABLES - Check cable tension (Ref. Chapter 27-60-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270052		RUDDER CONTROL CABLES - Check cable tensions (Ref. Chapter 27-20-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270053		RUDDER SERVO CABLES - Check cable tensions (Ref. Chapter 22-13-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270054		ELEVATOR CONTROL CABLES - Check cable tensions (Ref. Chapter 27-30-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270055		ELEVATOR SERVO CABLES - Check cable tensions (Ref. Chapter 22-13-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					
H270056		SPOILER SERVO CABLES - Check cable tension (Ref. Chapter 22-13-00).						RE (A/R)		Scheduled Special Inspections	
	27 A/F					Mos					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)				Hrs			+40		
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H270057	LH and RH FLAP CABLES AND INTERCONNECT CABLES - Check cable tensions (Ref. Chapter 27-50-00).						RE (A/R)		Scheduled Special Inspections	
27 A/F					Mos					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS FROM THE AIRPLANE BUILD)				Hrs			+40		
					Ldg					
H270058	LH and RH FLAP CABLES AND INTERCONNECT CABLES - Check cable tensions (Ref. Chapter 27-50-00).						RE (A/R)		Scheduled Special Inspections	
27 A/F					Mos					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS FROM THE AIRPLANE BUILD)				Hrs			+40		
					Ldg					
H270059	LH and RH SPOILER CABLES - Check cable tension (Ref. Chapter 27-60-00).						RE (A/R)		Scheduled Special Inspections	
27 A/F					Mos					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS FROM THE AIRPLANE BUILD)				Hrs			+40		
					Ldg					
H270060	LH and RH SPOILER CABLES - Check cable tension (Ref. Chapter 27-60-00).						RE (A/R)		Scheduled Special Inspections	
27 A/F					Mos					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: 200-FLYING HOURS FROM THE AIRPLANE BUILD)				Hrs			+40		
					Ldg					
H270061	PILOT'S COMPARTMENT - CONTROL COLUMN (Below Floor Panels) / a. Perform CONTROL COLUMN FREE PLAY CHECK (Ref. Chapter 27-30-00). / b. Detail inspect control columns, torque tube assembly and push rods for condition, interference, freedom of movement, seized bearings and sufficient engagement of rod ends (Ref. Chapter 27-30-00, Figure 206). / c. Detail inspect spoiler bellcranks and spoiler push rods for condition, interference, freedom of movement, seized bearings and sufficient engagement of rod ends.						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H270062	LEFT-HAND WING - FLAP OPERATION (Perform in conjunction with RH wing) - Perform the complete FLAP CONTROL SYSTEM FUNCTIONAL TEST (Ref. Chapter 27-50-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H270062	RIGHT-HAND WING - FLAP OPERATION (Perform in conjunction with LH wing) - Perform the flap system OPERATIONAL TEST (Ref. Chapter 27-50-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H270102	LEFT-HAND WING - WING FLAPS SYSTEM (Flaps Extended) - (External Inspection Only) - Inspect for condition.						RE		Scheduled Inspections	
27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				
H270103	LEFT-HAND WING - ROLL TRIM TAB, HINGE AND COUNTERBALANCE (External Inspection Only) / a. Inspect for condition. / b. Inspect static wick for condition and evidence of lightning strike.						RE		Scheduled Inspections	
27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				
H270104	LEFT-HAND WING - SPOILER PANELS AND HINGES - Inspect panels, hinges and bonding straps for condition.						RE		Scheduled Inspections	
27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				
H270105	LEFT-HAND WING - ROLL TRIM OPERATION - Perform the ROLL TRIM SYSTEM OPERATIONAL TEST (Ref. Chapter 27-10-00).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Not required if the complete ROLL TRIM TESTING procedure is performed.)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H270109	LEFT-HAND WING - WING FLAPS SYSTEM (Flaps Extended) / a. Detail inspect flap actuator, flap drive linkage and all control levers for condition and seized bearings. / b. Inspect flap hydraulic plumbing for routing and condition. / c. Inspect flap position transmitter for condition and seized linkage. / d. Inspect flap follow-up switch for condition and seized linkage. / e. Detail inspect flap cables, flap interconnect cables and pulleys for condition, routing and broken strands. NOTE: Closely examine the flap cables at the middle control lever where they pass through the stopper fittings for evidence of slippage or corrosion. (No inter strand corrosion permitted, Ref. Chapter 20-10-08). / f. Detain inspect main flap rollers, main flap tracks, attachments and push-pull rods for condition, seized bearings and sufficient engagement of rod ends. / g. Detain inspect aft flap rollers, aft flap tracks, attachments and push-pull rods for condition, seized bearings and sufficient engagement of rod ends.						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270111	LEFT-HAND WING - FLAP OPERATION (Perform in conjunction with RH wing inspection) - Perform the flap system OPERATIONAL TEST (Ref. Chapter 27-50-00).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Not required if the complete FLAP CONTROL SYSTEM FUNCTIONAL TEST is performed.)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270113	LEFT-HAND WING - ROLL TRIM ACTUATOR, ATTACHMENT, DRIVE LINKAGE, POTENTIOMETER and NEUTRAL SWITCH - Inspect for condition, seized bearings and sufficient engagement of rod ends (Ref. Chapter 27-10-00, Figure 202).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270114	LEFT-HAND WING - ROLL TRIM OPERATION - Perform the complete ROLL TRIM TESTING procedure (Ref. Chapter 27-10-00).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H270115	LEFT-HAND WING - SPOILER SECTOR AND PUSHRODS - Detail inspect for condition, seized bearings and sufficient engagement of rod ends (Ref. Chapter 27-60-00, Figure 211).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270116	LEFT-HAND WING - SPOILER CABLES - Detail inspect cables and pulleys for proper routing and condition (No inter strand corrosion permitted, Ref. Chapter 20-10-08).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270118	MIDFUSELAGE - SPEED BRAKE OPERATION - Perform Speed Brake OPERATIONAL TEST (Ref. Chapter 27-60-00).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Not required if the complete SPEED BRAKE SYSTEM ADJUSTMENT/TEST procedure is performed.)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270143	LEFT-HAND WING - SPOILER FAIRLEADS, WS 54.2 (1377) - Inspect for fraying, wear and security (Ref. Figure 617).						RE		Scheduled Inspections	≈10-Jul-2024
27 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H270147	LEFT-HAND WING - LEFT SPOILER BRACKET SUPPORT FITTING (P/N 45A62036) - Detail inspect for cracks and any other indications of structural damage. (Disassembly is not required). (Ref. IPC Figure 27-60-20-01).						RE		Scheduled Inspections	≈24-Jun-2024
27 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H270202	RIGHT-HAND WING - WING FLAPS SYSTEM (Flaps Extended) - (External Inspection Only) - Inspect for condition.						RE		Scheduled Inspections	
27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H270203	RIGHT-HAND WING - ROLL TRIM TAB, HINGE AND COUNTERBALANCE (External Inspection Only) / a. Inspect for condition. / b. Inspect static wick for condition and evidence of lightning strike.						RE		Scheduled Inspections	
 27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H270204	RIGHT-HAND WING - SPOILER PANELS AND HINGES - Inspect panels, hinges and bonding straps for condition.						RE		Scheduled Inspections	
 27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H270205	RIGHT-HAND WING - ROLL TRIM OPERATION - Perform the ROLL TRIM SYSTEM OPERATIONAL TEST (Ref. Chapter 27-10-00).						RE		Scheduled Inspections	≈24-Jun-2024
 27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Not required if the complete ROLL TRIM TESTING procedure is performed.)				Ldg	10,886				
H270209	RIGHT-HAND WING - WING FLAPS SYSTEM (Flaps Extended) / a. Detail inspect flap actuator, flap drive linkage and all control levers for condition and seized bearings. / b. Inspect flap hydraulic plumbing for routing and condition. / c. Inspect flap position transmitter for condition and seized linkage. / d. Inspect flap follow-up switch for condition and seized linkage. / e. Detail inspect flap cables, flap interconnect cables and pulleys for condition, routing and broken strands. NOTE: Closely examine the flap cables at the middle control lever where they pass through the stopper fittings for evidence of slippage or corrosion. (No inter strand corrosion permitted, Ref. Chapter 20-10-08). / f. Detail inspect main flap rollers, main flap tracks, attachments and push-pull rods for condition, seized bearings and sufficient engagement of rod ends. / g. Detail inspect aft flap rollers, aft flap tracks, attachments and push-pull rods for condition, seized bearings and sufficient engagement of rod ends.						RE		Scheduled Inspections	≈24-Jun-2024
 27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270211	RIGHT-HAND WING - FLAP OPERATION (Perform in conjunction with LH wing inspection) - Perform the flap system OPERATIONAL TEST (Ref. Chapter 27-50-00).						RE		Scheduled Inspections	≈24-Jun-2024
 27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Not required if the complete FLAP CONTROL SYSTEM FUNCTIONAL TEST is performed.)				Ldg	10,886				
H270213	RIGHT-HAND WING - ROLL TRIM ACTUATOR, ATTACHMENT, DRIVE LINKAGE, POTENTIOMETER and NEUTRAL SWITCH - Inspect for condition, seized bearings and sufficient engagement of rod ends (Ref. Chapter 27-10-00, Figure 202).						RE		Scheduled Inspections	≈24-Jun-2024
 27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270214	RIGHT-HAND WING - ROLL TRIM OPERATION - Perform the complete ROLL TRIM TESTING procedure (Ref. Chapter 27-10-00).						RE		Scheduled Inspections	≈10-Jul-2024
 27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H270215	RIGHT-HAND WING - SPOILER SECTOR AND PUSHRODS - Detail inspect for condition, seized bearings and sufficient engagement of rod ends (Ref. Chapter 27-60-00, Figure 211).						RE		Scheduled Inspections	≈24-Jun-2024
 27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270216	RIGHT-HAND WING - SPOILER CABLES - Detail inspect cables and pulleys for proper routing and condition (No inter strand corrosion permitted, Ref. Chapter 20-10-08).						RE		Scheduled Inspections	≈24-Jun-2024
 27 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270243	RIGHT-HAND WING - SPOILER FAIRLEADS, WS 54.2 (1377) - Inspect for fraying, wear and security (Ref. Figure 617).						RE		Scheduled Inspections	≈10-Jul-2024
 27 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H270247		RIGHT-HAND WING - RIGHT SPOILER BRACKET SUPPORT FITTING (P/N 45A62036) - Detail inspect for cracks and any other indications of structural damage. (Disassembly is not required) (Ref. IPC Figure 27-60-20-01).						RE		Scheduled Inspections	≈24-Jun-2024
	27 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H270250		VERTICAL STABILIZER - RUDDER OPERATION - Perform OPERATIONAL TEST (Ref. Chapter 27-20-00).						RE		Scheduled Inspections	≈24-Jun-2024
	27 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: This check is not required if the complete RUDDER CONTROL SYSTEM FUNCTIONAL TEST is performed.)				Ldg	10,886				
H270251		VERTICAL STABILIZER - VERTICAL STABILIZER TIP FAIRINGS / a. Inspect for condition. / b. Inspect static wick for condition and evidence of lightning strike. / c. Check tail navigation light and cap assembly (P/N 45A23325) for security and cracks.						RE		Scheduled Inspections	
	27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H270252		VERTICAL STABILIZER - PITCH TRIM ACTUATOR - / a. Perform the PITCH TRIM ACTUATOR INSPECTION/CHECK - BACKLASH procedure (Ref. Chapter 27-40-00). Backlash Measurement: _____						RE		Scheduled Inspections	
	27 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
TA270109		LH WING FLAPS SYSTEM (Operator inspection requirements) - Detail inspect flap cables, flap interconnect cables and pulleys for condition, routing and broken strands. NOTE: Closely examine the flap cables at the middle control lever where they pass through the stopper fittings for evidence of slippage or corrosion. (No inter strand corrosion permitted, Ref. Chapter (20-10-08).						RE			
	27 A/F					Mos	11-Nov-2022	12		11-Nov-2023	38 Days
						Hrs	14814:28	400	+40	15214:28	163:50 Hrs (+40)
						Ldg	10,886				
TA270209		RH WING FLAPS SYSTEM (Operator inspection requirements) - Detail inspect flap cables, flap interconnect cables and pulleys for condition, routing and broken strands. NOTE: Closely examine the flap cables at the middle control lever where they pass through the stopper fittings for evidence of slippage or corrosion. (No inter strand corrosion permitted, Ref. Chapter (20-10-08).						RE			
	27 A/F					Mos	11-Nov-2022	12		11-Nov-2023	38 Days
						Hrs	14814:28	400	+40	15214:28	163:50 Hrs (+40)
						Ldg	10,886				
▼ 28 - FUEL											
		Fuel drain valves O-rings replacement (Operator inspection requirements)						RE (-)			
	28 A/F					Mos	31-Oct-2019				
						Hrs	13005:36				
						Ldg	9,767				
		Fuel microbiological contamination test (operator req. only)						RE			
	28 A/F					Mos	16-Aug-2023	12		16-Aug-2024	10.6 Months
						Hrs	15050:38				
						Ldg	11,028				
		Fuel microbiological contamination tanks cleaning						RE (A/R)			
	28 A/F					Mos	14-Sep-2016				
						Hrs	10897				
						Ldg	8,473				
042802		Fuel System - Auxiliary Fuel Tank - Inspect (Outer Structure Only)						RE (N/A)		AWL - Inspection Limitations	
	28 A/F	Left				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
		(SOURCE: Maintenance Manual 040002)									

Task No		Description							Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
042802		Fuel System - Auxiliary Fuel Tank - Inspect (Outer Structure Only)						RE (N/A)		AWL - Inspection Limitations	
	28 A/F	Right				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
042803		Fuel System - Auxiliary Fuel Tank - Inspect (Outer Structure Only)						RE (N/A)		AWL - Inspection Limitations	
	28 A/F	Left				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
042803		Fuel System - Auxiliary Fuel Tank - Inspect (Outer Structure Only)						RE (N/A)		AWL - Inspection Limitations	
	28 A/F	Right				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
042804		Fuel System - Auxiliary Fuel Tank - Inspect (Outer Structure Only)						RE		AWL - Inspection Limitations	≈12-Jul-2026
	28 A/F	Left				Mos	11-Nov-2022				
	Unknown					Hrs	14814:28	2,400	+20	17214:28	2163:50 Hrs (+20)
	Unknown					Ldg	10,886				
	(SOURCE: Maintenance Manual 040002)										
042804		Fuel System - Auxiliary Fuel Tank - Inspect (Outer Structure Only)						RE		AWL - Inspection Limitations	≈12-Jul-2026
	28 A/F	Right				Mos	11-Nov-2022				
	Unknown					Hrs	14814:28	2,400	+20	17214:28	2163:50 Hrs (+20)
	Unknown					Ldg	10,886				
	(SOURCE: Maintenance Manual 040002)										
2004-22-02		Spoiler mixer bay						RE (-)		Mandatory	
	28 A/F					Mos					
	Eff: 01-Dec-2004					Hrs					
	(NOTE: Within 400 flight hours or 12 months after the effective date of this AD, whichever occurs first, do the actions in paragraphs (f)(1) and (f)(2) of this AD. Do all actions in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 53-3486, dated June 2003)										
280000-0101		Fuel System - Auxiliary Fuel Tank						RE (O/C)		AWL - Life Limit	
	28 A/F	Left				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
	MM:042801 (SOURCE: Maintenance Manual 040002)										
280000-0102		Fuel System - Auxiliary Fuel Tank						RE (O/C)		AWL - Life Limit	
	28 A/F	Right				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
	MM:042801 (SOURCE: Maintenance Manual 040002)										
280000-0201		Fuselage Fuel Cap						RE (O/C)			
	28 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
280000-0301		Valve - Fuel Vent						RE (O/C)			
	28 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
280000-0401		Fuselage Fuel Tank								RE (O/C)	
⚙	28 A/F	Aft					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0501		Auxiliary Fuel Tank								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0502		Auxiliary Fuel Tank								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0601		Fuel Cap								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0602		Fuel Cap								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0701		Mid-Fuselage Fuel Tank								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0702		Mid-Fuselage Fuel Tank								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0801		Wing Fuel Tank								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0802		Wing Fuel Tank								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-0901		Bladder Tank Fuselage								RE (O/C)	
⚙	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1001		Fuel Cell Bladder Forward Tank								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
280000-1002		Fuel Cell Bladder Forward Tank								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1101		Bladder Tank Carry Through								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1102		Bladder Tank Carry Through								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1202		Fuel Cell Bladder Aft Fuselage								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1301		Switch Float								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1302		Switch Float								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1401		Fuel Totalizer								RE (O/C)	
⚙	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1501		Fuel Probe Center Section								RE (O/C)	
⚙	28 A/F	Aft					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
	Brand C:284040										
280000-1601		Fuel Flow indicator								RE (O/C)	
⚙	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1602		Fuel Flow indicator								RE (O/C)	
⚙	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
280000-1701		Fuel Temperature Indicator								RE (O/C)	
⚙	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
281000-0101		Forward Flapper Check Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0102		Forward Flapper Check Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0201		Middle Flapper Check Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0202		Middle Flapper Check Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0301		Aft Flapper Check Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0302		Aft Flapper Check Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0401		Wing Carry Thru Float Switch								RE (O/C)	
	28 A/F	Left					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
281000-0402		Wing Carry Thru Float Switch								RE (O/C)	
	28 A/F	Right					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
281000-0502		Wing Aft Inboard Float Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0601		Wing Surge Space Vent Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0602		Wing Surge Space Vent Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
281000-0701		Level Control Valve									
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0702		Level Control Valve									
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0801		Wing Tank Sniffle Valve									
	28 A/F	Left Outboard					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0802		Wing Tank Sniffle Valve									
	28 A/F	Left Inboard					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0803		Wing Tank Sniffle Valve									
	28 A/F	Right Inboard					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0804		Wing Tank Sniffle Valve									
	28 A/F	Right Outboard					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-0901		Aft Fuselage Tank Sniffle Valve									
	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-1001		Vent Float Valve									
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-1002		Vent Float Valve									
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
281000-1101		Upper Aft Fuselage									
	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282000-0101		Booster Pump									
	28 A/F	Left No.1					Mos	01-Apr-2016			
	45AS48015-002	New					Hrs	10608			
	48F15						Ldg	8,291			

Task No	Description											Categories	Time
SEQ	PN/SN	MOC	Note or Component	Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
282000-0102			Booster Pump							RE (O/C)			
	28 A/F		Right No.1						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0103			Booster Pump							RE (O/C)			
	28 A/F		Left No.2						Mos	16-Mar-1219			
	45AS48015-002								Hrs	11074			
	10BN2								Ldg	8,568			
282000-0104			Booster Pump							RE (O/C)			
	28 A/F		Right No.2						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0201			Primary Jet Pump							RE (O/C)			
	28 A/F		Left						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0202			Primary Jet Pump							RE (O/C)			
	28 A/F		Right						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0301			Transfer Jet Pump							RE (O/C)			
	28 A/F		Left No.1						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0302			Transfer Jet Pump							RE (O/C)			
	28 A/F		Left No.2						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0303			Transfer Jet Pump							RE (O/C)			
	28 A/F		Right No.1						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0304			Transfer Jet Pump							RE (O/C)			
	28 A/F		Right No.2						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0401			Fuel Crossfeed Valve							RE (O/C)			
	28 A/F								Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
282000-0501			Crossfeed Valve							RE (O/C)			
	28 A/F		Left						Mos	22-Apr-2022			
	45AS48017-007								Hrs	14605:09			
	1903								Ldg	10,742			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
282000-0502	Crossfeed Valve								RE (O/C)	
28 A/F	Right					Mos	22-Dec-2016			
45AS48017-007	New					Hrs	11074			
2012						Ldg	8,568			
282000-0601	Fuel Transfer Shut-Off Valve								RE (O/C)	
28 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0602	Fuel Transfer Shut-Off Valve								RE (O/C)	
28 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0701	Fuel Feed Shut-Off Valve								RE (O/C)	
28 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0702	Fuel Feed Shut-Off Valve								RE (O/C)	
28 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0801	Motive Flow Shut-Off Valve								RE (O/C)	
28 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0802	Motive Flow Shut-Off Valve								RE (O/C)	
28 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0901	Manual Defuel Valve								RE (O/C)	
28 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
282000-0902	Manual Defuel Valve								RE (O/C)	
28 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
28-2013-11	Nextant - Boost Pump System Automatic Latching Improvement								RE (-)	Mandatory
28 A/F						Mos	28-Nov-2013			
Eff: 12-Nov-2013 Complied	C/W iaw SB instructions					Hrs	8722			
With						Ldg	7,201			
28-2016-02 Rev IR	Nextant - Lube Oil (Fuel/Oil) Cooler Flush & Flow Check								RE (-)	Mandatory
28 A/F						Mos	01-May-2017			
Eff: 19-Dec-2016 Complied	C/W i.a.w. SB instructions					Hrs	11237			
With						Ldg	8,668			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
282100-0101		Fuel Filter								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282100-0102		Fuel Filter								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0101		(Transfer Fuel) Low Pressure Switch								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0102		(Transfer Fuel) Low Pressure Switch								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0201		(Fuel Feed) Low Pressure Switch								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0202		(Fuel Feed) Low Pressure Switch								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0301		Wing No. 1 Drain Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0302		Wing No. 1 Drain Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0401		Wing No. 2 Drain Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0402		Wing No. 2 Drain Valve								RE (O/C)	
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0501		Wing No. 3 Drain Valve								RE (O/C)	
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
282200-0502		Wing No. 3 Drain Valve						RE (O/C)			
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0601		Wing No. 4 Drain Valve						RE (O/C)			
	28 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
282200-0602		Wing No. 4 Drain Valve						RE (O/C)			
	28 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0101		Wing Fuel Quantity Indicator						RE (O/C)			
	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0201		Fuselage Fuel Quantity Indicator						RE (O/C)			
	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0301		Quantity Amplifier						RE (O/C)			
	28 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0401		Probe Fuel Quantity						RE (O/C)			
	28 A/F	Left No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0402		Probe Fuel Quantity						RE (O/C)			
	28 A/F	Left No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0403		Probe Fuel Quantity						RE (O/C)			
	28 A/F	Left No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0404		Probe Fuel Quantity						RE (O/C)			
	28 A/F	Left No.4					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
284000-0405		Probe Fuel Quantity						RE (O/C)			
	28 A/F	Right No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
284000-0406	Probe Fuel Quantity									
28 A/F	Right No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284000-0407	Probe Fuel Quantity									
28 A/F	Right No.3					Mos	01-Apr-2014		RE (O/C)	
128-389001-3						Hrs	9029			
B1187						Ldg	7,361			
284000-0408	Probe Fuel Quantity									
28 A/F	Right No.4					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284000-0501	Fuel Probe Auxiliary Tank									
28 A/F	Fwd					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284000-0601	Fuel Probe Carry Thru									
28 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284000-0602	Fuel Probe Carry Thru									
28 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284000-0801	Filler Tank									
28 A/F	Aft					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284100-0101	Tank Low Level Float Switch									
28 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284100-0102	Tank Low Level Float Switch									
28 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284100-0201	Wing Fuel Overpressure Switch									
28 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
284100-0202	Wing Fuel Overpressure Switch									
28 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
284100-0301	28 A/F Unknown Unknown	Wing No. 1 Float Switch Left								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
284100-0302	28 A/F Unknown Unknown	Wing No. 2 Float Switch Left								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
284100-0303	28 A/F Unknown Unknown	Wing No. 1 Float Switch Right								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
284100-0304	28 A/F Unknown Unknown	Wing No. 2 Float Switch Right								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
92-16-14	28 A/F Eff: 01-Sep-1992	Fuselage Fuel Tanks								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
93-09-11	28 A/F Eff: 17-Jun-1993	Aft Fuel Filler Tank Installation								T (TBD)	Mandatory
							Mos				
							Hrs				
							Ldg				
99-21-08	28 A/F Eff: 12-Nov-1999	Fuel Drain Tube Assembly								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
H280001	28 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)	MIDFUSELAGE - FUEL STORAGE AREA - Inspect for evidence of fuel leakage from underside of the fuselage. 05-20-02								RE	Scheduled Inspections
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H280002	28 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: RK-1 thru RK-507 without Kit 128-9008 installed)	MIDFUSELAGE - FUEL SYSTEM PLUMBING AND COMPONENT MOUNTING (RK-1 thru RK-507 without Kit 128-9008 installed) (Gain access through panels 311AB and 312AB) - Inspect for condition and leakage. 05-20-02								RE	Scheduled Inspections
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H280005	28 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: RK-1 thru RK-507 without Kit 128-9008 installed)	MIDFUSELAGE - MOTIVE-FLOW SHUTOFF VALVE, CROSSFEED VALVE, AND FUEL SHUTOFF VALVE (RK-1 thru RK-507 without Kit 128-9008 Installed) - Inspect for condition and leakage. 05-20-02								RE	Scheduled Inspections
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
H280006	28 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: RK-106 thru RK-507 with Kit 128-9008 installed; RK-508 and After)	MIDFUSELAGE - FUEL SYSTEM PLUMBING AND COMPONENT MOUNTING (RK-106 thru RK-507 with Kit 128-9008 installed; RK-508 and After) (Gain access through panels 311AB and 312AB) - Inspect for condition and leakage. 05-20-03								RE	Scheduled Inspections
							Mos	11-Nov-2022			
							Hrs	14814:28	800	(15614:28)	563:50 Hrs (+40)
							Ldg	10,886			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H280007		MIDFUSELAGE - MOTIVE-FLOW SHUTOFF VALVE, CROSSFEED VALVE, AND FUEL SHUTOFF VALVE (RK-106 thru RK-507 with Kit 128-9008 Installed; RK-508 and After) - Inspect for condition and leakage.						RE		Scheduled Inspections	≈24-Jun-2024
	28 A/F	05-20-03				Mos	11-Nov-2022				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: RK-106 thru RK-507 with Kit 128-9008 installed; RK-508 and After)				Hrs	14814:28	800		(15614:28)	563:50 Hrs (+40)
						Ldg	10,886				
H280008		AFT FUSELAGE - FLAME ARRESTER (P/N 128-920211) - Remove and inspect for cracks and obstructions.						RE		Scheduled Inspections	≈10-Jul-2024
	28 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H280009		AFT FUSELAGE - ANTI-VAPOR SYSTEM - Detail inspect anti-vapor system flex ducts for condition and absence of trapped fluid.						RE		Scheduled Inspections	≈10-Jul-2024
	28 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H280010		AFT FUSELAGE - VENT SURGE TANK - Inspect vent surge tank and plumbing for condition.						RE		Scheduled Inspections	≈10-Jul-2024
	28 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H280011		CABIN SECTION - FUSELAGE AUXILIARY FUEL STORAGE AREAS / a. Detail inspect fuel cell interior for condition, evidence of fuel cell detachment and foreign material. / b. (RK-106 thru RK-507 with Kit 128-9008 and 128-9009 Installed; RK-508 thru RK-529 with Kit 128-9009 Installed; RK-530 and After) - Detail inspect fuel cell interior for indication of fungal or microbial contamination (Ref. Chapter 28-11-00). / c. Detail inspect fuel vent valves and vent float valves for condition and freedom of movement. / d. Detail inspect fuel vent plumbing, support brackets, hoses, clamps, bonding jumpers and clamshell couplings for condition. / e. Detail inspect fuel probe, mount bracket and wire harness for condition (located in the right fuel cell only). / f. Detail inspect interconnect tubes, hoses, clamps and bonding jumpers for condition. / g. Inspect fuel storage area access doors and nutplates for condition.						RE		Scheduled Inspections	≈10-Jul-2024
	28 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H280012		MIDFUSELAGE - MID- FUSELAGE FUEL STORAGE AREAS / a. Detail inspect fuel cell interior for condition, evidence of fuel cell detachment and foreign material. / b. (RK-106 thru RK-507 with Kit 128-9008 and 128-9009 Installed; RK-508 thru RK-529 with Kit 128-9009 Installed; RK-530 and After) - Detail inspect fuel cell interior for indication of fungal or microbial contamination (Ref. Chapter 28-11-00). / c. Detail inspect transfer pumps, fuel level float switches and mount brackets for condition and obstruction. / d. Detail inspect engine fuel feed plumbing, transfer fuel plumbing and check valve and motive flow plumbing for condition. / e. Detail inspect fuel vent float valve assembly for condition and freedom of movement. / f. Detail inspect fuel vent plumbing, support brackets, hoses, clamps, bonding jumpers and clamshell couplings for condition. / g. Detail inspect inboard and outboard fuel probes, mount brackets and wire harness conduit for condition (located in left fuel cell only). / h. Detail inspect interconnect tubes, hoses, clamps and bonding jumpers for condition. / i. Detail inspect interconnect tube check valves for condition and freedom of movement. / j. Detail inspect acceleration check valves for condition and freedom of movement. / k. Inspect fuel storage area access door and nutplates for condition.						RE		Scheduled Inspections	≈10-Jul-2024
	28 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H280018		CABIN SECTION - FUSELAGE AUXILIARY FUEL TANK ASSEMBLY (P/N 128-920185-1, -7, -19 and 128-920186-1, -7, -19) - Inspect the Auxiliary Fuel Tank Assembly (Outer Tank Structure Only) for corrosion, fatigue, cracks, loose or failed fasteners and general condition. Use borescope as necessary. (Ref. Figure 610).						RE		Scheduled Inspections	≈10-Jul-2024
	28 A/F	05-20-04				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
H280018		SCHEDULED D INSPECTIONS - FUEL TANK, FUSELAGE FILLER (128-920022) (Outer Tank Inspection Only) - Detail inspect for corrosion, fatigue cracks, loose or failed fasteners and general condition (Ref. Figure 608).						RE		Scheduled Inspections	≈29-Jul-2026
	28 A/F	05-20-05				Mos	12-May-2021				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
						Ldg	10,401				

Task No	Description	TSNI TSOI TSRI TSI				CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H280019	AFT FUSELAGE - AFT FUSELAGE FUEL STORAGE AREA / a. Remove and inspect aft fuselage safety foam for condition and deterioration (Ref. Chapter 28-11-00). / b. Detail inspect fuel cell interior for condition, evidence of fuel cell detachment and foreign material. / c. (RK-106 thru RK-507 with Kit 128-9008 and 128-9009 Installed; RK-508 thru RK-529 with Kit 128-9009 Installed; RK-530 and After) - Detail inspect fuel cell interior for indication of fungal or microbial contamination (Ref. Chapter 28-11-00). / d. Detail inspect fuel vent valve for condition and freedom of movement. / e. Detail inspect fuel vent interconnect tube, clamps, and bonding jumpers for condition. / f. Detail inspect flap check valve, interconnect tube, hoses, clamps and bonding jumpers for condition. / g. Inspect fuel storage area access door and nutplates for condition.						RE		Scheduled Inspections	≈10-Jul-2024
28 A/F	05-20-04					Mos	12-May-2021			
						Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401			
H280020	AFT FUSELAGE - FILLER TANK FUEL STORAGE AREA / a. Remove and inspect filler tank safety foam for condition and deterioration (Ref. Chapter 28-11-00). / b. Detail inspect fuel cell interior for condition, evidence of fuel cell detachment and foreign material. / c. (RK-106 thru RK-507 with Kit 128-9008 and 128-9009 Installed; RK-508 thru RK-529 with Kit 128-9009 Installed; RK-530 and After) - Detail inspect fuel cell interior for indication of fungal or microbial contamination (Ref. Chapter 28-11-00). / d. Detail inspect fuel vent valve for condition and freedom of movement. / e. Detail inspect fuel vent interconnect tube, clamps, and bonding jumpers for condition. / f. Detail inspect acceleration check valve, interconnect tube, hoses, clamps and bonding jumpers for condition. / g. Inspect fuel storage area access door and nutplates for condition.						RE		Scheduled Inspections	≈10-Jul-2024
28 A/F	05-20-04					Mos	12-May-2021			
						Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401			
H280022	SCHEDULED D INSPECTIONS - MIDFUSELAGE FUEL TANK (P/N 45A30901) - Perform detailed inspection for corrosion, fatigue cracks, loose or missing fasteners and general condition. Inspect fore and aft liners for cracks (Ref. Figure 608).						RE		Scheduled Inspections	≈29-Jul-2026
28 A/F	05-20-05					Mos	12-May-2021			
						Hrs	14049:30	3,200	+40	(17249:30) 2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05) (NOTE: NOTE: Initially, it is not necessary to completely remove the fuel bladder for this inspection, but access to the inside of the tank structure must be made (Note - corrosion will typically be at the bottom of the tank between the fuel bladder and the tank structure where moisture may have accumulated). The outer tank structure should be inspected thoroughly (borescope where required) to check for possible corrosion, fatigue cracks, loose or missing fasteners. In the event that corrosion is found during the initial phase of this inspection, a more thorough inspection, with the fuel bladder removed, is required.)					Ldg	10,401			
H280023	SCHEDULED D INSPECTIONS - AFT FUEL CELL COMPARTMENT (P/N 45A34891) - Perform detailed inspection for corrosion, fatigue cracks, loose or missing fasteners and general condition (Ref. Figure 608).						RE		Scheduled Inspections	≈29-Jul-2026
28 A/F	05-20-05					Mos	12-May-2021			
						Hrs	14049:30	3,200	+40	(17249:30) 2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05) (NOTE: NOTE: Initially, it is not necessary to completely remove the fuel bladder for this inspection, but access to the inside of the tank structure must be made (Note - corrosion will typically be at the bottom of the tank between the fuel bladder and the tank structure where moisture may have accumulated). The outer tank structure should be inspected thoroughly (borescope where required) to check for possible corrosion, fatigue cracks, loose or missing fasteners. In the event that corrosion is found during the initial phase of this inspection, a more thorough inspection, with the fuel bladder removed, is required.)					Ldg	10,401			
H280024	SCHEDULED D INSPECTIONS - AFT FUEL CELL COMPARTMENT BULKHEAD (P/N 45A34704) - Perform detailed inspection for corrosion, fatigue cracks, loose or missing fasteners and general condition (Ref. Figure 608).						RE		Scheduled Inspections	≈29-Jul-2026
28 A/F	05-20-05					Mos	12-May-2021			
						Hrs	14049:30	3,200	+40	(17249:30) 2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05) (NOTE: NOTE: Initially, it is not necessary to completely remove the fuel bladder for this inspection, but access to the inside of the tank structure must be made (Note - corrosion will typically be at the bottom of the tank between the fuel bladder and the tank structure where moisture may have accumulated). The outer tank structure should be inspected thoroughly (borescope where required) to check for possible corrosion, fatigue cracks, loose or missing fasteners. In the event that corrosion is found during the initial phase of this inspection, a more thorough inspection, with the fuel bladder removed, is required.)					Ldg	10,401			
H280025	MIDFUSELAGE - FUEL FILL SYSTEM FLAME ARRESTOR (P/N 128-920212) - Remove and inspect for cracks and obstruction.						RE		Scheduled Inspections	≈10-Jul-2024
28 A/F	05-20-04					Mos	12-May-2021			
						Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401			
H280026	ENGINE GROUND RUN AND OPERATIONAL CHECKS - FUEL SYSTEM - Perform FUEL PUMP OPERATIONAL TEST WITH ENGINE OPERATION (Ref. Chapter 28-20-00).						RE		Scheduled Inspections	≈10-Jul-2024
28 A/F	05-20-04					Mos	12-May-2021			
						Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)					Ldg	10,401			

Task No SEQ PN/SN	Description MOC Note or Component Condition								Categories	Time
		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H280027 28 A/F	PILOT'S COMPARTMENT - FUEL QUANTITY INDICATORS - Perform DRY CALIBRATION - WING AND FUSELAGE FUEL QUANTITY (Ref. Chapter 28-41-00). 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04) (NOTE: For aircraft with KIT Pro Line Avionics Kit (ICA 373-00-0002, STC ST10959SC)): This task should be accomplished according the Fuel Quantity Adjustment and Test portion per this ICA's Functional Tests. A Wet or Dry Calibration test per the functional checks is appropriate for returning the aircraft back to service)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280106 28 A/F	LEFT-HAND WING - FUEL COLLECTOR TANK / a. Detail inspect fuel tank structure for cracks, loose or missing fasteners and evidence of structural damage. / b. Inspect collector tank flapper valves (P/N 16C112) for condition, obstruction and freedom of movement. / c. Detail inspect electric boost pump, primary jet pump, inlet screens and pump mounting brackets for condition and obstruction. / d. Inspect low level float switch (P/N 45A48013) for condition, obstruction and freedom of movement. / e. Detail inspect electric boost pump plumbing, primary jet pump plumbing, manifold, check valves, clamps and bonding jumpers for condition. / f. Detail inspect forward and aft transfer jet pumps and pick-up tubes for condition and obstruction. / g. Inspect fuel storage area access doors and nutplates for condition. / h. Perform PRESSURE RELIEF VALVE OPERATIONAL CHECK AND REPAIR (Ref. Chapter 28-11-00). 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280116 28 A/F	LEFT-HAND WING - FUEL VENT SYSTEM / a. Inspect the inboard forward wing float vent valve for condition, deterioration and freedom of movement. / b. Inspect the inboard aft wing float vent valve for condition, deterioration and freedom of movement. / c. Inspect the wing surge space vent valve and flapper valve for condition, deterioration and freedom of movement. / d. Inspect fuel vent plumbing, hoses, clamps and bonding jumpers for condition and deterioration. 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280117 28 A/F	LEFT-HAND WING - WING OVERPRESSURE SWITCH - Remove and perform WING OVERPRESSURE SWITCH TEST (Ref. Chapter 28-41-00). 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280126 28 A/F	LEFT-HAND WING - FUEL LEVEL CONTROL SHUT-OFF VALVE (P/N 1323-518100M2) - Inspect for condition, obstruction and freedom of movement. Ensure presence of two washers on each mounting bolt (Ref. Figure 619). 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280206 28 A/F	RIGHT-HAND WING - FUEL COLLECTOR TANK / a. Detail inspect fuel tank structure for cracks, loose or missing fasteners and evidence of structural damage. / b. Inspect collector tank flapper valves (P/N 16C112) for condition, obstruction and freedom of movement. / c. Detail inspect electric boost pump, primary jet pump, inlet screens and pump mounting brackets for condition and obstruction. / d. Inspect low level float switch (P/N 45A48013) for condition, obstruction and freedom of movement. / e. Detail inspect electric boost pump plumbing, primary jet pump plumbing, manifold, check valves, clamps and bonding jumpers for condition. / f. Detail inspect forward and aft transfer jet pumps and pick-up tubes for condition and obstruction. / g. Inspect fuel storage area access doors and nutplates for condition. / h. Perform PRESSURE RELIEF VALVE OPERATIONAL CHECK AND REPAIR (Ref. Chapter 28-11-00). 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280216 28 A/F	RIGHT-HAND WING - FUEL VENT SYSTEM / a. Inspect the inboard forward wing float vent valve for condition, deterioration and freedom of movement. / b. Inspect the inboard aft wing float vent valve for condition, deterioration and freedom of movement. / c. Inspect the wing surge space vent valve and flapper valve for condition, deterioration and freedom of movement. / d. Inspect fuel vent plumbing, hoses, clamps and bonding jumpers for condition and deterioration. 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H280217 28 A/F	RIGHT-HAND WING - WING OVERPRESSURE SWITCH - Remove and perform WING OVERPRESSURE SWITCH TEST (Ref. Chapter 28-41-00). 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos 12-May-2021 Hrs 14049:30 Ldg 10,401	RE 1,600		Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H280226	RIGHT-HAND WING - FUEL LEVEL CONTROL SHUT-OFF VALVE (P/N 1323-518100M2) - Inspect for condition, obstruction and freedom of movement. Ensure presence of two washers on each mounting bolt (Ref. Figure 619).						RE		Scheduled Inspections	≈10-Jul-2024
 28 A/F	05-20-04					Mos	12-May-2021			
						Hrs	14049:30	1,600	+40	(15649:30) 598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Ldg	10,401			
NE-20-04	The recommendation in this bulletin provide general guidance on the use of Kathon FP1.5 and Biobor JF biocide jet fuel additives that can be used to supplement existing manufacturer procedures.						RE (-)			
 28 A/F						Mos	06-Apr-2020			
Complied With	In compliance with document NXT1-ICA Rev J					Hrs				
						Ldg				
TA-28-01	Fuel Transfer PCB A182 card						RE (-)			
 28 A/F						Mos	11-Mar-2020			
128-364100-5						Hrs	13175:44			
316000						Ldg	9,882			
▼ 29 - HYDRAULIC POWER										
290000-0101	Hydraulic Package Assembly						RE (O/C)			
 29 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
290000-0201	Valve Package Assembly						RE (O/C)			
 29 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
290000-0301	Shutoff Valve						RE (O/C)			
 29 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
290000-0302	Shutoff Valve						RE (O/C)			
 29 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
290000-0401	Hydraulic Pump						RE (O/C)			
 29 A/F	Left					Mos	13-Sep-2018			
45AS65020-001						Hrs	12300			
MX691508c						Ldg	9,328			
290000-0402	Hydraulic Pump						RE (O/C)			
 29 A/F	Right					Mos	01-Aug-2014			
45AS65020-001	New					Hrs	9314			
MX-527306C (PV3-022-25)						Ldg	7,512			
290000-0501	Valve-Shutoff						RE (O/C)			
 29 A/F						Mos	01-Jan-2013			
979494-4	New					Hrs	8026			
2176						Ldg	6,785			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
290000-0502	Valve-Shutoff									
 29 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
291000-0101	Hydraulic Isolation Valve									
 29 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
291000-0102	Hydraulic Isolation Valve									
 29 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
293000-0101	Hydraulic Pressure Transducer									
 29 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
293000-0201	Hydraulic Pressure Indicator									
 29 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
293000-0301	Hydraulic Low Level Switch									
 29 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
293000-0401	Hydraulic Low Pressure Switch									
 29 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
293000-0402	Hydraulic Low Pressure Switch									
 29 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
H290001	AFT FUSELAGE - HYDRAULIC RESERVOIR - Check hydraulic fluid level.								RE	Scheduled Inspections
 29 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						Ldg	10,886			
H290002	AFT FUSELAGE - HYDRAULIC PACKAGE, SYSTEM PLUMBING, COMPONENTS - Detail inspect for condition and cleanliness.								RE	Scheduled Inspections
 29 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
						Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						Ldg	10,886			
H290003	AFT FUSELAGE - HYDRAULIC PACKAGE FLUID FILTER ELEMENTS - Replace (Ref. Chapter 29-10-00).								RE	Scheduled Inspections
 29 A/F	05-20-03					Mos	11-Nov-2022			≈24-Jun-2024
						Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						Ldg	10,886			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H290004		AFT FUSELAGE - HYDRAULIC PACKAGE AIR FILTER - Clean (Ref. Chapter 29-10-00 in the Component Maintenance Manual, P/N 128-590001-81 or subsequent).						RE		Scheduled Inspections	≈24-Jun-2024
	29 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H290006		CABIN SECTION - HYDRAULIC PLUMBING - Detail inspect for condition and leakage.						RE		Scheduled Inspections	≈10-Jul-2024
	29 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H290101		LANDING GEAR AND BRAKES - LEFT BRAKE HYDRAULIC/PNEUMATIC LINES AND HOSES - Inspect for condition and routing on the strut and in the wheel well.						RE		Scheduled Inspections	≈24-Jun-2024
	29 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H290201		LANDING GEAR AND BRAKES - RIGHT BRAKE HYDRAULIC/PNEUMATIC LINES AND HOSES - Inspect for condition and routing on the strut and in the wheel well.						RE		Scheduled Inspections	≈24-Jun-2024
	29 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
SA-2013-03 Rev A		Nextant - Potential Aircraft Hydraulic Hose Failure						RE (-)		Service Letter	
	29 A/F					Mos	19-Apr-2013				
	Eff: 16-Apr-2013 Complied With	C/W iaw SB instructions				Hrs	8216				
						Ldg	6,898				
▼ 30 - ICE AND RAIN PROTECTION											
2000-09-12		Wing Ice Protection System						T (A/R)		Mandatory	
	30 A/F					Mos					
	Eff: 16-Jun-2000					Hrs					
						Ldg					
300000-0101		Stab Deice Contactor (K251)						RE (O/C)			
	30 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
300000-0201		Ice Detector						RE (O/C)			
	30 A/F	Left				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
300000-0202		Ice Detector						RE (O/C)			
	30 A/F	Right				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
300000-0203		Ice Detector						RE (O/C)			
	30 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
300000-0301		Heater Mat						RE (O/C)			
	30 A/F	Left No.1				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
300000-0302	Heater Mat								RE (O/C)	
30 A/F	Left No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
300000-0303	Heater Mat								RE (O/C)	
30 A/F	Right No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
300000-0304	Heater Mat								RE (O/C)	
30 A/F	Right No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
300000-0401	Horizontal, Sequence Timer								RE (O/C)	
30 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
300000-0501	Leading Edge Low Temperature Thermal Switch								RE (O/C)	
30 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
300000-0601	Anti-ice Valve								RE (O/C)	
30 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
300000-0602	Anti-ice Valve								RE (O/C)	
30 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
301000-0101	Wing Anti-Ice Control Valve								RE (O/C)	
30 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
301000-0201	Wing Overtemp S054 Switch								RE (O/C)	
30 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
301000-0301	Wing Overtemp S052 Switch								RE (O/C)	
30 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
301000-0401	Wing S158 Overtemp Switch								RE (O/C)	
30 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
301000-0501		Wing S157 Overtemp Switch						RE (O/C)			
⚙	30 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-0601		Wing S191 Overtemp Switch						RE (O/C)			
⚙	30 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-0701		Wing S192 Overtemp Switch						RE (O/C)			
⚙	30 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-0801		Wing S055 Overtemp Switch						RE (O/C)			
⚙	30 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-0901		Wing S053 Overtemp Switch						RE (O/C)			
⚙	30 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-1001		Anti-Ice Temperature Controller						RE (O/C)			
⚙	30 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-1101		Deice Timer Unit						RE (O/C)			
⚙	30 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301000-1201		Horizontal Stabilizer Heater Mat						RE (O/C)			
⚙	30 A/F	Left					Mos	07-Apr-2022			
	128-380078-9						Hrs	14605:09			
	HK00324						Ldg	10,742			
301000-1202		Horizontal Stabilizer Heater Mat						RE (O/C)			
⚙	30 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
301100-0101		Wing Anti-Ice Duct Switch						RE (O/C)			
⚙	30 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
302000-0101		Nacelle Inlet Bleed Air Valve						RE (O/C)			
⚙	30 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
302000-0102	Nacelle Inlet Bleed Air Valve									
30 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
302000-0201	Pressure Regulator Shutoff Valve									
30 A/F	Left					Mos	01-Mar-2014		RE (O/C)	
45AS63019-009 (1896-00-3) New						Hrs	8990			
1987						Ldg	7,338			
302000-0202	Pressure Regulator Shutoff Valve									
30 A/F	Right					Mos	24-Feb-2023		RE (O/C)	
45AS63019-009	Overhauled			0		Hrs	14983:13			
1388				0		Ldg	10,987			
302000-0301	Nacelle Temperature Switch									
30 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
302000-0302	Nacelle Temperature Switch									
30 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
302000-0401	Outboard Engine Bleed Line Duct Assembly									
30 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
302000-0402	Inboard Engine Bleed Line Duct Assembly									
30 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
304000-0101	Windshield Wiper Motor									
30 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
304000-0102	Windshield Wiper Motor									
30 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
304000-0201	Windshield Temperature Control									
30 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
304000-0202	Windshield Temperature Control									
30 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
94-25-10		Airplane Flight Manual Changes - Icing Conditions (This AD is superseded by AD 99-21-26)						RE (-)		Mandatory	
	30 A/F					Mos					
	Eff: 13-Dec-1994					Hrs					
						Ldg					
99-21-26		Airplane Flight Manual Changes - Icing Conditions						T (A/R)		Mandatory	
	30 A/F					Mos					
	Eff: 22-Nov-1999					Hrs					
	Brand A:9900-1999-21-26					Ldg					
H300006		PILOT'S COMPARTMENT - HORIZONTAL STABILIZER DEICE SYSTEM - Perform Horizontal Stabilizer Deice System OPERATIONAL TEST (Ref. Chapter 30-12-00).						RE		Scheduled Inspections	≈24-Jun-2024
	30 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886				
H300007		FORWARD FUSELAGE - WINDSHIELD WIPERS (RK-1 thru RK-242 without Kit 128-5405 installed) - Inspect wiper arms and blades for condition.						RE (N/A)		Scheduled Inspections	
	30 A/F					Mos					
						Hrs					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: RK-1 thru RK-242 without Kit 128-5405 installed)					Ldg					
H300008		FORWARD FUSELAGE - WINDSHIELD WIPERS (RK-1 thru RK-242 without Kit 128-5405 installed) - Perform WIPER ON WET GLASS OPERATIONAL TEST (Ref. Chapter 30-40-00).						RE (N/A)		Scheduled Inspections	
	30 A/F					Mos					
						Hrs					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: RK-1 thru RK-242 without Kit 128-5405 installed)					Ldg					
H300009		FORWARD FUSELAGE - WINDSHIELD HEAT - Perform windshield heat OPERATIONAL TEST (Ref. Chapter 30-40-00).						RE		Scheduled Inspections	≈24-Jun-2024
	30 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886				
H300010		ENGINE GROUND RUN AND OPERATIONAL CHECKS - WING LEADING EDGE ANTI-ICE SYSTEM - Perform WING LEADING EDGE ANTI-ICE ADJUSTMENT/TEST (Ref. Chapter 30-10-00).						RE		Scheduled Inspections	≈24-Jun-2024
	30 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)					Ldg	10,886				
H300011		Perform ELEVATOR HORN INSPECTION/CHECK (Ref. Chapter 30-12-00).						RE		Scheduled Special Inspections	≈21-Dec-2023
	30 A/F	05-20-01				Mos	06-Apr-2023				
						Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	11,028				
H300012		Perform ELEVATOR HORN INSPECTION/CHECK (Ref. Chapter 30-12-00).						RE		Scheduled Special Inspections	≈21-Dec-2023
	30 A/F	05-20-01				Mos	06-Apr-2023				
						Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	11,028				
H300013		DEICE SYSTEM TERMINAL BOARDS (TB011 & TB061) - Detail inspect for corrosion, security and evidence of damage. If corrosion is not found, treat terminal boards with Lektro-Tect Super Corr-A Corrosion Preventative Compound. If corrosion is found, perform TERMINAL BOARD (TB011 and TB061) INSPECTION (Ref. Chapter 30-12-00).						RE		Scheduled Special Inspections	≈21-Dec-2023
	30 A/F	05-20-01				Mos	06-Apr-2023				
						Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)					Ldg	11,028				
▼ 31 - INDICATING / RECORDING SYSTEM											
		DFDR L3 operational check (read-out included) iaw AMC1 CAT.GEN.MPA.195 (b)						RE			
	31 A/F					Mos	11-Nov-2022			30-Nov-2023	57 Days
						Hrs	14814:28				
						Ldg	10,886				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		5 year check of sensor parameters iaw AMC1 CAT.GEN.MPA.195 (b)								RE	
	31 A/F						Mos	25-May-2022	60	25-May-2027	3.6 Years
							Hrs	14622:44			
							Ldg	10,755			
310000-0101		Hobbs Meter								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0201		Accelerometer								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0301		Flap Indicator								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0401		Cabin Rate of Climb Indicator								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0501		Flight Data Recorder (FDR)								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0601		FDR Impact Switch								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0701		Flight Data Entry Panel								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0801		Environmental Controller								RE (O/C)	
	31 A/F Unknown Unknown	No.1					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0802		Environmental Controller								RE (O/C)	
	31 A/F Unknown Unknown	No.2					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
310000-0901		Power Supply (Aft)								RE (O/C)	
	31 A/F Unknown Unknown						Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
310000-1001		Angle of Attack Indicator								RE (O/C)	
	31 A/F	New					Mos	22-Dec-2017			
	30AN						Hrs	11704			
	0382						Ldg	8,940			
312000-0501		Flight Data Recorder Underwater Locator Beacon								RE (O/C)	
	31 A/F	Unknown Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
31-2012-03		Nextant - Dimming of the Master Caution Panel								RE (-)	Mandatory
	31 A/F	Eff: 14-Jul-2012 Not Applicable N/A - no dimming function on RK-295					Mos	13-May-2013			
							Hrs				
							Ldg				
313000-0101		DFDR								RE (O/C)	STC, DFDR Installed
	31 A/F	2100-2043-00 Unknown Ref:NX1111003 (SOURCE: FAA STC ST03110CH)					Mos	21-Nov-2000			
							Hrs				
							Ldg				
313000-0201		DFDR - ULB battery								RE	STC
	31 A/F	DK-120/90 AT57963 Expiration Date 31-Dec-2023 Ref:NX1111003 (SOURCE: FAA STC ST03110CH)	0				Mos	12-Mar-2018	72	31-Dec-2023	88 Days
						Hrs					
						Ldg					
314000-0101		Configuration Strapping Unit								RE (O/C)	
	31 A/F	No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
314000-0102		Configuration Strapping Unit								RE (O/C)	
	31 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
314000-0201		IAPS/IO Concentrator								RE (O/C)	
	31 A/F	No.1A					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
314000-0202		IAPS/IO Concentrator								RE (O/C)	
	31 A/F	No.1B					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
314000-0203		IAPS/IO Concentrator								RE (O/C)	
	31 A/F	No.2A					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
314000-0204	 31 A/F Unknown Unknown	IAPS/IO Concentrator No.2B						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
314000-0301	 31 A/F Unknown Unknown	IAPS/IO Power Supply No.1A						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
314000-0302	 31 A/F Unknown Unknown	IAPS/IO Power Supply No.1B						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
314000-0303	 31 A/F 622-9945-021 3482	IAPS/IO Power Supply No.2A New						RE (O/C)			
						Mos	05-Jan-2017				
						Hrs	11079				
						Ldg	8,571				
314000-0304	 31 A/F Unknown Unknown	IAPS/IO Power Supply No.2B						RE (O/C)			
						Mos	21-Nov-2000				
						Hrs	0				
						Ldg	0				
31-ICA-DFDR	 31 A/F Ref:NX1111003 (SOURCE: FAA STC ST03110CH)	DFDR System - DFDR Reasonableness and Function Test (Download / Correlation check) 05-20-04						RE		STC, DFDR Installed	≈10-Jul-2024
						Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
						Ldg	10,401				
31-ICA-DFDR	 31 A/F DK-120/90 AT57963 Certified Date 30-Dec-2017 Ref:NX1111003 (SOURCE: FAA STC ST03110CH)	DFDR System - DFDR Under Water Locator Device - Battery replacement						RE		STC, DFDR Installed	
						Yrs	12-Mar-2018	6		30-Dec-2023	87 Days
						Hrs					
						Ldg					
31-ICA-DFDR	 31 A/F DK-120/90 AT57963 Ref:NX1111003 (SOURCE: FAA STC ST03110CH)	DFDR System - DFDR Under Water Locator Device - Functional Test						RE		STC, DFDR Installed	
						Mos	18-Feb-2022	24		18-Feb-2024	4.6 Months
						Hrs	14572:58				
						Ldg	10,722				
31-ICA-DFDR	 31 A/F Ref:NX1111003 (SOURCE: FAA STC ST03110CH)	DFDR System - Wire/Cable/Racks/Connectors - Inspect system installation components condition and security. 05-20-04,...						RE		STC, DFDR Installed	≈24-Jun-2024
						Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	≠15614:28	
						Ldg	10,886				
H312020	 31 A/F Unknown Unknown 30-May-2017 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)	UNDERWATER LOCATOR BEACON (RK-36 and After) - Replace battery. Refer to the Dukane (Seacom Division) Technical Manual in Chapter 23 of the Component Maintenance Manual, P/N 128-590001-81 or subsequent for test procedures.						RE (N/A)		Scheduled Special Inspections	
						Yrs	01-Jun-2017				
						Hrs					
						Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H313005		FLIGHT DATA RECORDER (if applicable) - Perform the FLIGHT DATA RECORDER (FDR) INSPECTION CHECK (Ref. Chapter 31-30-00).						RE (N/A)		Scheduled Special Inspections	
	31 A/F					Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H313011		FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON (RK-36 and After) - Functional test. Refer to the Dukane (Seacom Division) Technical Manual in Chapter 23 of the Component Maintenance Manual, P/N 128-590001-81 or subsequent for test procedures.						RE (N/A)		Scheduled Special Inspections	
	31 A/F					Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
▼ 32 - LANDING GEAR											
043202		Main Gear Struts - Teardown/Inspect/Repair						RE (N/A)		AWL - Inspection Limitations	
	32 A/F	Left				Mos					
	128-810085-605					Hrs					
	05090201ICT					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043202		Main Gear Struts - Teardown/Inspect/Repair						RE (N/A)		AWL - Inspection Limitations	
	32 A/F	Right				Mos					
	128-810085-606					Hrs					
	05090201ICT					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043203		Main Gear Struts - Teardown/Inspect/Repair						RE (N/A)		AWL - Inspection Limitations	
	32 A/F	Left				Mos					
	128-810085-605					Hrs					
	05090201ICT					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043203		Main Gear Struts - Teardown/Inspect/Repair						RE (N/A)		AWL - Inspection Limitations	
	32 A/F	Right				Mos					
	128-810085-606					Hrs					
	05090201ICT					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043204		Main Gear Struts - Teardown/Inspect/Repair						RE		AWL - Inspection Limitations	≈31-Oct-2023
	32 A/F	Left				Mos	26-Mar-2012				
	128-810085-605					Hrs	7706	7,400	+20	15106	55:22 Hrs (+20)
	05090201ICT					Ldg	6,568	5,000	+15	11,568	540 Ldg (+15)
	(SOURCE: Maintenance Manual 040002)										
043204		Main Gear Struts - Teardown/Inspect/Repair						RE		AWL - Inspection Limitations	≈31-Oct-2023
	32 A/F	Right				Mos	26-Mar-2012				
	128-810085-606					Hrs	7706	7,400	+20	15106	55:22 Hrs (+20)
	05090201ICT					Ldg	6,568	5,000	+15	11,568	540 Ldg (+15)
	(SOURCE: Maintenance Manual 040002)										
043206		Main Gear Side Strut Assemblies - Teardown/Inspect/Repair Main						RE (N/A)		AWL - Inspection Limitations	
	32 A/F	Left				Mos					
	128-810081-5					Hrs					
	01040501					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043206		Main Gear Side Strut Assemblies - Teardown/Inspect/Repair Main						RE (N/A)		AWL - Inspection Limitations	
	32 A/F	Right				Mos					
	128-810081-6					Hrs					
	RK305					Ldg					
	(SOURCE: Maintenance Manual 040002)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
043207		Main Gear Side Strut Assemblies - Teardown/Inspect/Repair Main						RE (N/A)	AWL - Inspection Limitations		
	32 A/F	Left				Mos					
	128-810081-5					Hrs					
	01040501					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043207		Main Gear Side Strut Assemblies - Teardown/Inspect/Repair Main						RE (N/A)	AWL - Inspection Limitations		
	32 A/F	Right				Mos					
	128-810081-6					Hrs					
	RK305					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043208		Main Gear Side Strut Assemblies - Teardown/Inspect/Repair Main						RE	AWL - Inspection Limitations	≈31-Oct-2023	
	32 A/F	Left				Mos	26-Mar-2012				
	128-810081-5					Hrs	7706	7,400	+20	15106	55:22 Hrs (+20)
	01040501					Ldg	6,568	5,000	+15	11,568	540 Ldg (+15)
	(SOURCE: Maintenance Manual 040002)										
043208		Main Gear Side Strut Assemblies - Teardown/Inspect/Repair Main						RE	AWL - Inspection Limitations	≈31-Oct-2023	
	32 A/F	Right				Mos	26-Mar-2012				
	128-810081-6					Hrs	7706	7,400	+20	15106	55:22 Hrs (+20)
	RK305					Ldg	6,568	5,000	+15	11,568	540 Ldg (+15)
	(SOURCE: Maintenance Manual 040002)										
043211		Nose Gear Strut Assembly - Teardown/Inspect/Repair						RE (N/A)	AWL - Inspection Limitations		
	32 A/F					Mos					
	128-820028-605					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043212		Nose Gear Strut Assembly - Teardown/Inspect/Repair						RE (N/A)	AWL - Inspection Limitations		
	32 A/F					Mos					
	128-820028-605					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043213		Nose Gear Strut Assembly - Teardown/Inspect/Repair						RE	AWL - Inspection Limitations	≈24-Oct-2023	
	32 A/F					Mos	20-Jan-2012				
	128-820028-605					Hrs	7691	7,400	+20	15091	40:22 Hrs (+20)
	Unknown					Ldg	6,553	5,000	+15	11,553	525 Ldg (+15)
	(SOURCE: Maintenance Manual 040002)										
043215		Nose Gear Drag Strut Assembly - Teardown/Inspect/Repair						RE (N/A)	AWL - Inspection Limitations		
	32 A/F					Mos					
	128-820044-603					Hrs					
	21724B					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043216		Nose Gear Drag Strut Assembly - Teardown/Inspect/Repair						RE (N/A)	AWL - Inspection Limitations		
	32 A/F					Mos					
	128-820044-603					Hrs					
	21724B					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043217		Nose Gear Drag Strut Assembly - Teardown/Inspect/Repair						RE	AWL - Inspection Limitations	≈24-Oct-2023	
	32 A/F					Mos	24-Jan-2012				
	128-820044-603					Hrs	7691	7,400	+20	15091	40:22 Hrs (+20)
	21724B					Ldg	6,553	5,000	+15	11,553	525 Ldg (+15)
	(SOURCE: Maintenance Manual 040002)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
043219		Nose Gear Upper Drag Strut Assembly - Teardown/Inspect/Repair						RE (N/A)		AWL - Inspection Limitations	
	32 A/F					Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043220		Nose Gear Upper Drag Strut Assembly - Teardown/Inspect/Repair						RE (N/A)		AWL - Inspection Limitations	
	32 A/F					Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: Maintenance Manual 040002)										
043222		Wheel Speed Transducer - Replace with airworthy unit						RE		AWL - Life Limit	≈29-Oct-2029
	32 A/F	Left				Yrs	12-Aug-2022	10		12-Aug-2032	8.9 Years
	140-03110					Hrs	14786:10	5,000		19786:10	4735:32 Hrs
	2046					Ldg	10,868				
	Certified Date 12-Aug-2022										
	(SOURCE: Maintenance Manual 040002)										
043222		Wheel Speed Transducer - Replace with airworthy unit						RE		AWL - Life Limit	≈09-Feb-2027
	32 A/F	Right				Yrs	18-Jun-2019	10		13-Jun-2029	5.7 Years
	Unknown					Hrs	12663:28	5,000		17663:28	2612:50 Hrs
	Unknown					Ldg	9,551				
	Certified Date 13-Jun-2019										
	(SOURCE: Maintenance Manual 040002)										
043224		Pneumatic Storage Bottle - Hydrostatically Test						RE		AWL - Inspection Limitations	
	32 A/F					Yrs	06-Apr-2023	3		28-Feb-2026	2.4 Years
	23111321-1					Hrs	15050:38				
	3139					Ldg	11,028				
	Hydrostatic Tested Date 21-Feb-2023										
	(SOURCE: Maintenance Manual 040002)										
2000-25-04		Anti-Skid Valve Assembly						RE (-)		Mandatory	
	32 A/F					Mos					
	Eff: 17-Jan-2001					Hrs					
	(NOTE: Model MU-300, MU-300-10, 400, 400A, and 400T series airplanes; as listed in Raytheon Aircraft Service Bulletin SB 32-3300, dated December 1999; certificated in any category.)										
320000-0101		Nose Gear Upper Drag Strut Assembly						RE (O/C)		AWL - Life Limit	
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
	MM:043218, MM:043225 (SOURCE: Maintenance Manual 040002) (NOTE: With Kit 128-8001 Installed)										
320000-0201		Nitrogen Gauge						RE (O/C)			
	32 A/F	Right No.1				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
320000-0202		Nitrogen Gauge						RE (O/C)			
	32 A/F	Right No.2				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
320000-0301		Landing Gear Warning Horn PCB						RE (O/C)			
	32 A/F	No.1				Mos	26-Jul-2022				
	122-382038-1					Hrs	14772:33				
	659					Ldg	10,857				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
320000-0401											
	32 A/F	Main Landing Gear Swivel						RE (O/C)			
	Unknown	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
320000-0402											
	32 A/F	Main Landing Gear Swivel						RE (O/C)			
	Unknown	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
320000-0501											
	32 A/F	Main Landing Gear Brake Assembly						RE (O/C)			
	400-8002-97	Left					Mos	11-Nov-2022			
	FEB97-488						Hrs	14814:28			
							Ldg	10,886			
320000-0502											
	32 A/F	Main Landing Gear Brake Assembly						RE (O/C)			
	400-8002-97	Right					Mos	11-Nov-2022			
	FEB98585						Hrs	14814:28			
							Ldg	10,886			
320000-0601											
	32 A/F	Power Brake Relay						RE (O/C)			
	38-771						Mos	12-Sep-2017			
	545						Hrs	11570			
							Ldg	8,862			
320000-0702											
	32 A/F	Landing Gear Warning Horn PCB						RE (O/C)			
	Unknown	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
							Ldg	0			
32-0T-01											
	32 A/F	Overhaul LH Main Wheel Assy after 5x tire exchange						RE (Wheel Change)			
	5010720-1	Left					Mos	11-Nov-2022			
	AUG001496						Hrs	14814:28			
							Ldg	10,886			
32-0T-01											
	32 A/F	Overhaul RH Main Wheel Assy after 5x tire exchange						RE (Wheel Change)			
	5010720-1	Right					Mos	11-Nov-2022			
	APR082341						Hrs	14814:28			
							Ldg	10,886			
321000-0101											
	32 A/F	Main Gear Strut Assy						RE		AWL - Life Limit	≈07-Mar-2038
	128-810085-605	Left					Mos	26-Mar-2012			
	05090201ICT	Overhauled					Hrs	7706			
			4,997				Ldg	6,568	15,000	16,571	5,543 Ldg
MM:043201 (SOURCE: Maintenance Manual 040002) (NOTE: (For airplanes RK-1 thru RK-23 With Kit 128-8001 Installed) - If the initial overhaul or teardown inspection has been complied with following the installation of Kit 128-8001, the 7,400 hour/5,000 landings inspection interval criteria will apply to all subsequent inspections. If the initial overhaul or teardown inspection has not been complied with following the installation of Kit 128-8001, contact Beechcraft Corporation at 800.429.5372 to determine the initial inspection interval based on the number of landings accumulated on the landing gear prior to installation of Kit 128-8001.)											

Task No	Description										Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
321000-0102	Main Gear Strut Assy											
32 A/F	Right					Mos	26-Mar-2012				RE	AWL - Life Limit ≈07-Mar-2038
128-810085-606	Overhauled					Hrs	7706					
05090201ICT		4,997				Ldg	6,568	15,000		16,571		5,543 Ldg
MM:043201 (SOURCE: Maintenance Manual 040002) (NOTE: (For airplanes RK-1 thru RK-23 With Kit 128-8001 Installed) - If the initial overhaul or teardown inspection has been complied with following the installation of Kit 128-8001, the 7,400 hour/5,000 landings inspection interval criteria will apply to all subsequent inspections. If the initial overhaul or teardown inspection has not been complied with following the installation of Kit 128-8001, contact Beechcraft Corporation at 800.429.5372 to determine the initial inspection interval based on the number of landings accumulated on the landing gear prior to installation of Kit 128-8001.)												
321000-0201	MLG Shock Strut											
32 A/F	Left					Mos	21-Nov-2000				RE (O/C)	
Unknown						Hrs	0					
Unknown						Ldg	0					
321000-0202	MLG Shock Strut											
32 A/F	Right					Mos	21-Nov-2000				RE (O/C)	
Unknown						Hrs	0					
Unknown						Ldg	0					
321000-0301	Main Gear Side Strut Assy											
32 A/F	Left					Mos	26-Mar-2012				RE	AWL - Life Limit ≈24-Apr-2046
128-810081-5	Overhauled					Hrs	7706					
01040501		1,872				Ldg	6,568	15,000		19,696		8,668 Ldg
(SOURCE: Maintenance Manual 040002)												
321000-0302	Main Gear Side Strut Assy											
32 A/F	Right					Mos	26-Mar-2012				RE	AWL - Life Limit ≈15-Mar-2038
128-810081-6	Overhauled					Hrs	7706					
RK305		4,989				Ldg	6,568	15,000		16,579		5,551 Ldg
(SOURCE: Maintenance Manual 040002)												
321000-0401	Main Landing Gear Torque Link Bolt											
32 A/F	Left					Mos	17-Jan-2012				RE	AWL - Life Limit ≈13-Aug-2037
Unknown						Hrs						
Unknown		0				Ldg	6,553	9,800		16,353		5,325 Ldg
MM:043209 (SOURCE: Maintenance Manual 040002) (NOTE: (*) This part is not practical to mark with a part number/serial number. If removal from the airplane is required before the end of its published replacement life limitation, then it should be bagged and identified with accumulated hours/cycles and records should be maintained to ensure compliance with the life limitation.)												
321000-0402	Main Landing Gear Torque Link Bolt											
32 A/F	Right					Mos	17-Jan-2012				RE	AWL - Life Limit ≈13-Aug-2037
Unknown						Hrs						
Unknown		0				Ldg	6,553	9,800		16,353		5,325 Ldg
MM:043209 (SOURCE: Maintenance Manual 040002) (NOTE: (*) This part is not practical to mark with a part number/serial number. If removal from the airplane is required before the end of its published replacement life limitation, then it should be bagged and identified with accumulated hours/cycles and records should be maintained to ensure compliance with the life limitation.)												
322000-0101	Nose Landing Gear Shock Strut											
32 A/F						Mos	21-Nov-2000				RE (O/C)	
Unknown						Hrs	0					
Unknown						Ldg	0					
322000-0201	Nose Gear Strut Assembly											
32 A/F						Mos	20-Jan-2012				RE	AWL - Life Limit ≈21-Feb-2038
128-820028-605						Hrs	7691					
Unknown		4,997				Ldg	6,553	15,000		16,556		5,528 Ldg
MM:043210 (SOURCE: Maintenance Manual 040002)												

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
322000-0301		Nose Gear Drag Strut Assembly						RE		AWL - Life Limit	≈25-May-2038
	32 A/F						Mos	24-Jan-2012			
	128-820044-603						Hrs	7691			
	21724B		4,899				Ldg	6,553	15,000	16,654	5,626 Ldg
	MM:043214 (SOURCE: Maintenance Manual 040002)										
322000-0401		Nose Wheel Shimmy Damper						RE (O/C)			
	32 A/F						Mos	11-Nov-2021			
	54100-41						Hrs	14471:02			
	00104						Ldg	10,655			
323000-0101		Main Landing Gear Actuating Cylinder						RE (O/C)			
	32 A/F	Left					Mos	21-Nov-2000			
	45AS38515-007						Hrs				
	1152						Ldg				
323000-0102		Main Landing Gear Actuating Cylinder						RE (O/C)			
	32 A/F	Right					Mos	21-Nov-2000			
	45AS38515-008						Hrs				
	1170						Ldg				
323000-0201		Nose Landing Gear Actuating Cylinder						RE (O/C)			
	32 A/F						Mos	21-Nov-2000			
	45AS39503-3						Hrs				
	18						Ldg				
323000-0301		Main Landing Gear Uplock Mechanism Actuator						RE (O/C)			
	32 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
323000-0302		Main Landing Gear Uplock Mechanism Actuator						RE (O/C)			
	32 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
323000-0401		Nose Gear Uplock Mechanism Actuator						RE (O/C)			
	32 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
323000-0501		Down Lock Release Cylinder						RE (O/C)			
	32 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
323000-0502		Down Lock Release Cylinder						RE (O/C)			
	32 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
323000-0601		Main Landing Gear Downlock Mechanism Actuator						RE (O/C)			
	32 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
323000-0602		Main Landing Gear Downlock Mechanism Actuator Right						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-0701		Nose Gear Downlock Mechanism Actuator						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-0801		Main Landing Gear Door Actuator Left						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-0802		Main Landing Gear Door Actuator Right						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-0901		Main Landing Gear Up Lock Release Cylinder Left						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-0902		Main Landing Gear Up Lock Release Cylinder Right						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-1001		Nose Landing Gear Up Lock Release Cylinder						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-1101		Pneumatic Storage Bottle Overhauled Manufactured Date 31-Mar-2020 MM:043223 (SOURCE: Maintenance Manual 040002)						RE		AWL - Life Limit	
	32 A/F					Yrs	06-Apr-2023	15	31-Mar-2035	11.5 Years	
	23111321-1					0	Hrs	15050:38			
	3139					0	Ldg	11,028			
323000-1201		Emergency Brake/Gear Down Pressure Indicator						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
323000-1301		Landing Gear Control Unit						RE (O/C)			
	32 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
324000-0701	Emergency Brake Valve									
32 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324000-0801	Mixer Valve									
32 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0101	Mixer Valve									
32 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0201	Parking Brake Valve									
32 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0202	Parking Brake Valve									
32 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0301	Accumulator, Hydraulic Emergency Brake									
32 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0401	Skid Control Box									
32 A/F						Mos	11-Nov-2022		RE (O/C)	
42-901						Hrs	14814:28			
852						Ldg	10,886			
324100-0501	Brake Fluid Reservoir									
32 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0601	Master Brake Cylinder									
32 A/F	Pilot - Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0602	Master Brake Cylinder									
32 A/F	Pilot - Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
324100-0603	Master Brake Cylinder									
32 A/F	Copilot - Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
324100-0604	 32 A/F Unknown Unknown	Master Brake Cylinder Copilot - Right								RE (O/C)	
							Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
324100-0701	 32 A/F 140-03110 2046	Wheel Speed Transducer Left Overhauled								RE	≈29-Oct-2029
			0				Mos	12-Aug-2022	120	12-Aug-2032	8.9 Years
			0	0			Hrs	14786:10	5,000	19786:10	4735:32 Hrs
					0		Ldg	10,868			
324100-0702	 32 A/F Unknown Unknown MM:043222 (SOURCE: Maintenance Manual 040002)	Wheel Speed Transducer Right								RE	AWL - Life Limit ≈09-Feb-2027
			0				Mos	18-Jun-2019	120	18-Jun-2029	5.7 Years
			0				Hrs	12663:28	5,000	17663:28	2612:50 Hrs
							Ldg	9,551			
93-01-07	 32 A/F Eff: 02-Mar-1993	End Clevis Fitting								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
94-04-07	 32 A/F Eff: 07-Mar-1994	Main Landing Gear Hubcaps								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
94-04-07 (A) (1) L/H	 32 A/F	Degradation Or Loss Of Braking Performance								RE (-)	Mandatory
							Mos				
							Hrs				
							Ldg				
94-04-07 (A) (1) R/H	 32 A/F	Degradation Or Loss Of Braking Performance								RE (-)	Mandatory
							Mos				
							Hrs				
							Ldg				
94-04-07 (A) (2) L/H	 32 A/F	Degradation Or Loss Of Braking Performance								RE (-)	Mandatory
							Mos				
							Hrs				
							Ldg				
94-04-07 (A) (2) R/H	 32 A/F	Degradation Or Loss Of Braking Performance								RE (-)	Mandatory
							Mos				
							Hrs				
							Ldg				
94-11-09	 32 A/F Eff: 07-Jul-1994	Main Landing Gear Wire Harness								T (A/R)	Mandatory
							Mos				
							Hrs				
							Ldg				
ESC-200812-056	 32 A/F Open (Date reported: 12-Aug-2020), (Reported by: Zdeněk Ovečka , Title: Pilot)(Classification date: 12-Aug-2020), (Recorded by: Lukas Polansky, Title: CAMO)	Check Brakes status								N/N (-)	Squawk, -
							Mos				
							Hrs				
							Ldg				
H320001	 32 A/F (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)	LANDING GEAR AND BRAKES - NOSE WHEEL AND TIRE / a. Check tire for correct inflation, wear, damage or deterioration. / b. Check wheel for condition and missing or broken wheel tie bolts and nuts. 05-20-02								RE	Scheduled Inspections
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H320002	LANDING GEAR AND BRAKES - NOSE LANDING GEAR STRUT ASSEMBLY - Check for proper nitrogen servicing and signs of fluid leakage (Ref. Chapter 12-10-00).						RE		Scheduled Inspections	
32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H320003	LANDING GEAR AND BRAKES - NOSE LANDING GEAR WHEEL WELL / a. Inspect attach fittings, support structure and keels skins for cracks, loose or missing fasteners, corrosion and evidence of damage. / b. Inspect wire harness for condition, deterioration and routing.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320009	LANDING GEAR AND BRAKES - LANDING GEAR EXTENSION/RETRACTION SYSTEM - Perform NORMAL EMERGENCY EXTENSION RETRACTION VERIFICATION CHECK (Ref. Chapter 32-30-00).						RE		Scheduled Inspections	
32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: NOTE: This check is not required if the LANDING GEAR FUNCTIONAL TEST is performed.)				Ldg	10,886				
H320013	PILOT'S COMPARTMENT - MASTER BRAKE CYLINDERS (Above Floor Panels) - Clean piston rod surfaces and upper surface of cylinder bodies and inspect for condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320014	FORWARD FUSELAGE - NITROGEN SYSTEM - Detail inspect nitrogen cylinder, plumbing and valve for condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320015	MIDFUSELAGE - BRAKE SYSTEM - Inspect power brake valve, parking brake valves and accumulator for condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320017	LANDING GEAR AND BRAKES - NOSE LANDING GEAR DRAG STRUT ASSEMBLY / a. Detail inspect for condition. / b. Inspect downlock hydraulic actuator cylinder and hydraulic lines for condition and routing. / c. Inspect bearings in the lower drag strut for slippage (Ref. Figure 602). / d. Inspect downlock switch and bracket for proper mounting and condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320018	LANDING GEAR AND BRAKES - NOSE LANDING GEAR UPLOCK ASSEMBLY / a. Detail inspect uplock hook mechanism for condition and freedom of movement. / b. Inspect uplock hydraulic actuator cylinder and hydraulic lines for condition and routing. / c. Inspect uplock switch and bracket for proper mounting and condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320019	LANDING GEAR AND BRAKES - NOSE LANDING GEAR EMERGENCY EXTENSION CABLE - Inspect for condition and proper routing.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320020	LANDING GEAR AND BRAKES - NOSE LANDING GEAR STRUT ASSEMBLY / a. Detail inspect strut assembly for security, wear, cracks, loose or missing fasteners and any evidence of damage or corrosion. / b. Inspect hydraulic actuator cylinder and hydraulic lines for condition and routing.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H320023	PILOT'S COMPARTMENT - EMERGENCY LANDING GEAR / a. Detail inspect emergency landing gear extension T-handle and cable assembly, forward quadrant assembly, attaching control cables and cable terminals, and support structure for condition (Ref. Figure 602). / b. Detail inspect emergency door close T-handle and cable assembly and plumbing for condition.						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H320024	LANDING GEAR AND BRAKES - BRAKE SYSTEM / a. Perform PARKING BRAKE SYSTEM FUNCTIONAL CHECK (POWER MODE) (Ref. Chapter 32-40-00). / b. Perform EMERGENCY BRAKE SYSTEM FUNCTIONAL CHECK (Ref. Chapter 32-40-00). / c. Perform POWER BRAKE ANIT-SKID CONTROL VALVE FILTER CLEANING (Ref. Chapter 32-40-00). / d. Perform BRAKE SYSTEM FUNCTIONAL TESTING procedure (Ref. Chapter 32-40-00).						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H320026	LANDING GEAR AND BRAKES - ANTI-SKID SYSTEM / a. Perform WHEEL SPEED TRANSDUCER INSPECTION (Ref. Chapter 32-40-00). NOTE: This check is not required if the complete BRAKE SYSTEM FUNCTIONAL TESTING procedure in Chapter 32-40-00 is performed. / b. Perform ANTI-SKID RESPONSE CHECK (Ref. Chapter 32-40-00). NOTE: This check is not required if the complete BRAKE SYSTEM FUNCTIONAL TESTING procedure in Chapter 32-40-00 is performed. / c. Perform FAILURE DETECTION CIRCUIT CHECK (Ref. Chapter 32-40-00). NOTE: This check is not required if the complete BRAKE SYSTEM FUNCTIONAL TESTING procedure in Chapter 32-40-00 is performed. / d. Perform TOUCH-DOWN PROTECTION CIRCUIT CHECK (Ref. Chapter 32-40-00). NOTE: This check is not required if the complete BRAKE SYSTEM FUNCTIONAL TESTING procedure in Chapter 32-40-00 is performed.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320030	LANDING GEAR AND BRAKES - NOSE LANDING GEAR SHIMMY DAMPER / a. Inspect shimmy damper for condition. / b. Check shimmy damper servicing (Ref. Chapter 32-20-00).						RE		Scheduled Inspections	
32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H320031	CABIN SECTION - EMERGENCY LANDING GEAR CABLES - Perform EMERGENCY LANDING GEAR SYSTEM CABLE TENSION CHECK (Ref. Chapter 32-30-00).						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H320032	PILOT'S COMPARTMENT - EMERGENCY BRAKE - Detail inspect emergency brake lever and control cable mechanism, control valve assembly, springs and plumbing for condition.						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H320035	SCHEDULED D INSPECTIONS - MAIN LANDING GEAR DOOR ACTUATOR FITTING - Perform a detailed inspection of the fitting for cracks using a 10x magnifying glass (Ref. Figure 602).						RE		Scheduled Inspections	≈29-Jul-2026
32 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H320036	SCHEDULED D INSPECTIONS - NOSE LANDING GEAR SUPPORT FITTING (P/N 45A31311) - Perform a detailed inspection for cracks, loose or missing fasteners and evidence of structural damage (Ref. Figure 610).						RE		Scheduled Inspections	≈29-Jul-2026
32 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H320037	LANDING GEAR AND BRAKES - NOSE WHEEL AND TIRE / a. Clean and inspect wheel bearings and cones. Re-lubricate wheel bearings (Ref. Chapter 12-20-00). / b. Inspect axle, caps and spacers for condition and corrosion.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H320038		LANDING GEAR AND BRAKES - NOSE WHEEL STEERING SYSTEM - / a. Detail inspect cam assembly, lever assembly and steering rod for condition, seized bearings and freedom of movement. / b. Perform NOSE GEAR TORQUE ARM ASSEMBLY CHECK (Ref. Chapter 32-50-00).						RE		Scheduled Inspections	≈24-Jun-2024
	32 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320039		LANDING GEAR AND BRAKES - BRAKE SYSTEM ACCUMULATOR - Check accumulator pre-charge pressure.						RE		Scheduled Inspections	
	32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H320040		LANDING GEAR AND BRAKES - LANDING GEAR SYSTEM / a. Perform LANDING GEAR FUNCTIONAL TEST (Ref. Chapter 32-00-00). / b. Perform nose steering NEUTRAL POSITION CHECK (Ref. Chapter 32-50-00).						RE		Scheduled Inspections	≈24-Jun-2024
	32 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320041		PILOT'S COMPARTMENT - MANUAL BRAKE SYSTEM - Perform BRAKE MIXING VALVE FUNCTIONAL CHECK (Ref. Chapter 32-40-00).						RE		Scheduled Inspections	≈24-Jun-2024
	32 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H3200LH		MAIN WHEELS / a. Inspect wheel for cracks and damage in accordance with Chapter 32-40-54 or 32-40-99 in the Component Maintenance Manual, 128-590001-81 or subsequent. / b. Clean and inspect wheel bearings and cones, lubricate wheel bearings (Ref. Chapter 12-20-00). / c. Check wheel brake disc drive keys for loose and missing hardware. / d. Inspect axle, nut and spacers for corrosion and condition. / e. Perform HUBCAP INSPECTION (Ref. Chapter 32-40-00).						RE (T/C)		Scheduled Special Inspections	
	32 A/F	Left				Mos	11-Nov-2022				
	5010720-1					Hrs	14814:28				
	AUG001496					Ldg	10,886				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: TIRE CHANGE- Accomplish at every tire change. Refer to the Model MU-300/400/400A Component Maintenance Manual.)									
H3200NO		NOSE WHEEL / a. Inspect wheel for cracks and damage in accordance with Chapter 32-46-12 in the Component Maintenance Manual, 128-590001-81 or subsequent. / b. Clean and inspect wheel bearings and cones, lubricate wheel bearings (Ref. Chapter 12-20-00). / c. Inspect axle, caps and spacers for corrosion and condition.						RE (T/C)		Scheduled Special Inspections	
	32 A/F					Mos	24-Jun-2022				
	5006450-5					Hrs	14701:38				
	OCT06-10243					Ldg	10,812				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: TIRE CHANGE- Accomplish at every tire change. Refer to the Model MU-300/400/400A Component Maintenance Manual.)									
H3200RH		MAIN WHEELS / a. Inspect wheel for cracks and damage in accordance with Chapter 32-40-54 or 32-40-99 in the Component Maintenance Manual, 128-590001-81 or subsequent. / b. Clean and inspect wheel bearings and cones, lubricate wheel bearings (Ref. Chapter 12-20-00). / c. Check wheel brake disc drive keys for loose and missing hardware. / d. Inspect axle, nut and spacers for corrosion and condition. / e. Perform HUBCAP INSPECTION (Ref. Chapter 32-40-00).						RE (T/C)		Scheduled Special Inspections	
	32 A/F	Right				Mos	11-Nov-2022				
	5010720-1					Hrs	14814:28				
	APR082341					Ldg	10,886				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: TIRE CHANGE- Accomplish at every tire change. Refer to the Model MU-300/400/400A Component Maintenance Manual.)									
H320104		LANDING GEAR AND BRAKES - LEFT MAIN WHEEL / a. Check tire for correct inflation, wear, damage or deterioration. / b. Check for missing or broken wheel tie bolts and nuts.						RE		Scheduled Inspections	
	32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H320105		LANDING GEAR AND BRAKES - LEFT BRAKE ASSEMBLY - Check brake wear indicator pin. Refer to the appropriate MAIN LANDING GEAR BRAKE WEAR LIMITS procedure (Ref. Chapter 32-40-00).						RE		Scheduled Inspections	
	32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H320106	LANDING GEAR AND BRAKES - LEFT MAIN LANDING GEAR STRUT ASSEMBLY - Check for proper nitrogen servicing and signs of fluid leakage (Ref. Chapter 12-10-00).						RE		Scheduled Inspections	
32 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H320107	LANDING GEAR AND BRAKES - LEFT MAIN ACTUATOR BRACKET - Detail inspect for evidence of interference between the actuator bracket and the wing spar (i.e. paint damage) (Ref. Figure 604). Replace if interference is found.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320108	LANDING GEAR AND BRAKES - LEFT MAIN WHEEL WELL AND AREA INSPECTION (Panel Removal Not Required) / a. Inspect wheel well area structure and skin for cracks, loose and missing fasteners, corrosion and evidence of damage. / b. Inspect wire harness for condition, routing and evidence of tire rub.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320109	LANDING GEAR AND BRAKES - LEFT BRAKE ASSEMBLY - Detail inspect brake assembly for condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320120	LANDING GEAR AND BRAKES - LEFT LANDING GEAR SAFETY SWITCH - Inspect switch, linkage, mounting and wire harness for condition.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320121	LANDING GEAR AND BRAKES - LEFT MAIN LANDING GEAR SIDE STRUT ASSEMBLY / a. Detail inspect side strut assembly for condition. / b. Inspect bearings in the lower side strut assembly, balancer arm and link assembly for slippage (Ref. Figure 603). / c. Inspect downlock actuator, hydraulic plumbing and downlock mechanism for condition and routing. / d. Inspect downlock switch, mount hardware and wire harness for condition and routing.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320122	LANDING GEAR AND BRAKES - LEFT MAIN LANDING GEAR AND DOOR UPLOCK HOOK AND UPLOCK ASSEMBLIES / a. Inspect hydraulic uplock cylinder and hydraulic plumbing for condition and routing. / b. Detail inspect uplock hook mechanism for condition and freedom of movement. / c. Inspect uplock switch, mount bracket and wire harness for condition and routing.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320123	LANDING GEAR AND BRAKES - LEFT MAIN GEAR ATTACH FITTINGS, SUPPORTING SPARS, RIB AND UPLOCK FITTING - Inspect rear spar and fitting for cracks, missing fasteners, corrosion and evidence of structural damage (Ref. Figure 620).						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H320124	LANDING GEAR AND BRAKES - LEFT MAIN LANDING GEAR STRUT ASSEMBLY / a. Detail inspect strut assembly for security, wear, cracks, loose or missing fasteners and any evidence of damage or corrosion. / b. Inspect hydraulic actuator cylinder and hydraulic lines for corrosion.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320125	LANDING GEAR AND BRAKES - LEFT MAIN WHEEL / a. Clean and inspect wheel bearings and cones. Re-lubricate wheel bearings (Ref. Chapter 12-20-00). / b. Inspect wheel brake disc drive keys for loose and missing hardware. / c. Inspect axle, nut and spacer for condition and corrosion.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI TSOI TSRI TSI				CW	REQ	TOL	Categories	Time
									DUE	Remaining
H320126	LANDING GEAR AND BRAKES - LEFT MAIN WHEEL WELL - AREA INSPECTION (Panels Removed) / a. Inspect fuel plumbing and fittings for condition and evidence of damage. / b. Inspect fuel transfer low pressure switch (S129) and mounting for condition. / c. Inspect electrical wire harnesses for condition and deterioration. / d. Inspect MLG inboard door actuator and plumbing for condition and evidence of leakage. / e. Inspect emergency landing gear extension cables, pulleys and bellcranks for condition, routing and broken strands. 05-20-04 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)					Mos Hrs Ldg	12-May-2021 14049:30 10,401	RE 1,600 +40	Scheduled Inspections (15649:30)	≈10-Jul-2024 598:52 Hrs (+40)
H320204	LANDING GEAR AND BRAKES - RIGHT MAIN WHEEL - a. Check tire for correct inflation, wear, damage or deterioration. / b. Check for missing or broken wheel tie bolts and nuts. 05-20-02 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 12 400 +40	Scheduled Inspections (30-Nov-2023) (15214:28)	57 Days 163:50 Hrs (+40)
H320205	LANDING GEAR AND BRAKES - RIGHT BRAKE ASSEMBLY - Check brake wear indicator pin. Refer to the appropriate MAIN LANDING GEAR BRAKE WEAR LIMITS procedure (Ref. Chapter 32-40-00). 05-20-02 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 12 400 +40	Scheduled Inspections (30-Nov-2023) (15214:28)	57 Days 163:50 Hrs (+40)
H320206	LANDING GEAR AND BRAKES - RIGHT MAIN LANDING GEAR STRUT ASSEMBLY - Check for proper nitrogen servicing and signs of fluid leakage (Ref. Chapter 12-10-00). 05-20-02 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 12 400 +40	Scheduled Inspections (30-Nov-2023) (15214:28)	57 Days 163:50 Hrs (+40)
H320207	LANDING GEAR AND BRAKES - RIGHT MAIN ACTUATOR BRACKET - Detail inspect for evidence of interference between the actuator bracket and the wing spar (i.e. paint damage) (Ref. Figure 604). Replace if interference is found. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 800 +40	Scheduled Inspections (15614:28)	≈24-Jun-2024 563:50 Hrs (+40)
H320208	LANDING GEAR AND BRAKES - RIGHT MAIN WHEEL WELL AND AREA INSPECTION (Panel Removal Not Required) / a. Inspect wheel well area structure and skin for cracks, loose and missing fasteners, corrosion and evidence of damage. / b. Inspect wire harness for condition, routing and evidence of tire rub. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 800 +40	Scheduled Inspections (15614:28)	≈24-Jun-2024 563:50 Hrs (+40)
H320209	LANDING GEAR AND BRAKES - RIGHT BRAKE ASSEMBLY - Detail inspect brake assembly for condition. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 800 +40	Scheduled Inspections (15614:28)	≈24-Jun-2024 563:50 Hrs (+40)
H320220	LANDING GEAR AND BRAKES - RIGHT LANDING GEAR SAFETY SWITCH - Inspect switch, linkage, mounting and wire harness for condition. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 800 +40	Scheduled Inspections (15614:28)	≈24-Jun-2024 563:50 Hrs (+40)
H320221	LANDING GEAR AND BRAKES - RIGHT MAIN LANDING GEAR SIDE STRUT ASSEMBLY / a. Detail inspect side strut assembly for condition. / b. Inspect bearings in the lower side strut assembly, balancer arm and link assembly for slippage (Ref. Figure 603). / c. Inspect downlock actuator, hydraulic plumbing and downlock mechanism for condition and routing. / d. Inspect downlock switch, mount hardware and wire harness for condition and routing. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 800 +40	Scheduled Inspections (15614:28)	≈24-Jun-2024 563:50 Hrs (+40)
H320222	LANDING GEAR AND BRAKES - RIGHT MAIN LANDING GEAR AND DOOR UPLOCK HOOK AND UPLOCK ASSEMBLIES / a. Inspect hydraulic uplock cylinder and hydraulic plumbing for condition and routing. / b. Detail inspect uplock hook mechanism for condition and freedom of movement. / c. Inspect uplock switch, mount bracket and wire harness for condition and routing. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Mos Hrs Ldg	11-Nov-2022 14814:28 10,886	RE 800 +40	Scheduled Inspections (15614:28)	≈24-Jun-2024 563:50 Hrs (+40)

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H320223	LANDING GEAR AND BRAKES - RIGHT MAIN GEAR ATTACH FITTINGS, SUPPORTING SPARS, RIB AND UPLOCK FITTING - Inspect rear spar and fitting for cracks, missing fasteners, corrosion and evidence of structural damage (Ref. Figure 620).						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H320224	LANDING GEAR AND BRAKES - RIGHT MAIN LANDING GEAR STRUT ASSEMBLY / a. Detail inspect strut assembly for security, wear, cracks, loose or missing fasteners and any evidence of damage or corrosion. / b. Inspect hydraulic actuator cylinder and hydraulic lines for corrosion.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320225	LANDING GEAR AND BRAKES - RIGHT MAIN WHEEL / a. Clean and inspect wheel bearings and cones. Re-lubricate wheel bearings (Ref. Chapter 12-20-00). / b. Inspect wheel brake disc drive keys for loose and missing hardware. / c. Inspect axle, nut and spacer for condition and corrosion.						RE		Scheduled Inspections	≈24-Jun-2024
32 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H320226	LANDING GEAR AND BRAKES - RIGHT MAIN WHEEL WELL - AREA INSPECTION (Panels Removed) / a. Inspect fuel plumbing and fittings for condition and evidence of damage. / b. Inspect fuel transfer low pressure switch (S129) and mounting for condition. / c. Inspect electrical wire harnesses for condition and deterioration. / d. Inspect MLG inboard door actuator and plumbing for condition and evidence of leakage. / e. Inspect emergency landing gear extension cables, pulleys and bellcranks for condition, routing and broken strands.						RE		Scheduled Inspections	≈10-Jul-2024
32 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H322013	NOSE LANDING GEAR RETRACTION CYLINDER (P/N 45AS39503) - Perform Eddy current inspection of the retraction cylinder mounting lug for evidence of cracks in accordance with Chapter 20-80-03. Removal of the spherical bearing is not required. Refer to Figure 602.						RE (N/A)		Scheduled Special Inspections	
32 A/F					Mos					
45AS39503-3					Hrs					
18					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H322014	NOSE LANDING GEAR RETRACTION CYLINDER (P/N 45AS39503) - Perform Eddy current inspection of the retraction cylinder mounting lug for evidence of cracks in accordance with Chapter 20-80-03. Removal of the spherical bearing is not required. Refer to Figure 602.						RE		Scheduled Special Inspections	≈05-Sep-2024
32 A/F					Mos	13-Sep-2021				
45AS39503-3					Hrs	14379	1,400	+40	15770	719:22 Hrs (+40)
18					Ldg	10,595	1,400		11,995	967 Ldg
	(Tol. Adjustment: -9 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H322113	MAIN LANDING GEAR RETRACTION CYLINDER (P/N 45AS38515) - Perform Eddy current inspection of the retraction cylinder mounting lug for evidence of cracks in accordance with Chapter 20-80-03. Removal of the spherical bearing is not required. Refer to Figure 601.						RE (N/A)		Scheduled Special Inspections	
32 A/F	Left				Mos					
45AS38515-007					Hrs					
1152					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H322114	MAIN LANDING GEAR RETRACTION CYLINDER (P/N 45AS38515) - Perform Eddy current inspection of the retraction cylinder mounting lug for evidence of cracks in accordance with Chapter 20-80-03. Removal of the spherical bearing is not required. Refer to Figure 601.						RE		Scheduled Special Inspections	≈05-Sep-2024
32 A/F	Left				Mos	13-Sep-2021				
45AS38515-007					Hrs	14379	1,400	+40	15770	719:22 Hrs (+40)
1152					Ldg	10,595	1,400		11,995	967 Ldg
	(Tol. Adjustment: -9 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H322213	MAIN LANDING GEAR RETRACTION CYLINDER (P/N 45AS38515) - Perform Eddy current inspection of the retraction cylinder mounting lug for evidence of cracks in accordance with Chapter 20-80-03. Removal of the spherical bearing is not required. Refer to Figure 601.						RE (N/A)		Scheduled Special Inspections	
32 A/F	Right				Mos					
45AS38515-008					Hrs					
1170					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									

Task No		Description							Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H322214		MAIN LANDING GEAR RETRACTION CYLINDER (P/N 45AS38515) - Perform Eddy current inspection of the retraction cylinder mounting lug for evidence of cracks in accordance with Chapter 20-80-03. Removal of the spherical bearing is not required. Refer to Figure 601.						RE	Scheduled	Special Inspections	≈05-Sep-2024
	 32 A/F	Right				Mos	13-Sep-2021				
	45AS38515-008					Hrs	14379	1,400	+40	15770	719:22 Hrs (+40)
	1170					Ldg	10,595	1,400		11,995	967 Ldg
	(Tol. Adjustment: -9 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
TA-LMM-03		LH - Check Brake Wear Indicator Pin - When the end of the wear indicator pin is aligned with the brake housing sub assembly flange (with the brake applied), the brake assembly should be removed for maintenance and the wear pads must be replaced. I.a.w. AMM 128-590001-9, ch. 32-40-00, page 5						RE (-)			
	 32 A/F	05-0T-01				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	15050:38				
						Ldg	11,028				
TA-LMM-04		LH - Check and Measure Tire Wear - I. a. w. AMM 128-590001-9, ch. 32-40-00 , page 250						RE (-)			
	 32 A/F	05-0T-01				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	15050:38				
						Ldg	11,028				
TA-LMM-05		RH - Check Brake Wear Indicator Pin - When the end of the wear indicator pin is aligned with the brake housing sub assembly flange (with the brake applied), the brake assembly should be removed for maintenance and the wear pads must be replaced. I.a.w. 128-590001-9, ch. 32-40-00, page 5						RE (-)			
	 32 A/F	05-0T-01				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	15050:38				
						Ldg	11,028				
TA-LMM-06		RH - Check and Measure Tire Wear - I. a. w. AMM 128-590001-9, ch. 32-40-00 , page 250						RE (-)			
	 32 A/F	05-0T-01				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	15050:38				
						Ldg	11,028				
TA-LMM-07		NG - Check and Measure Tire Wear - I. a. w. AMM 128-590001-9, ch. 32-40-00 , page 250						RE (-)			
	 32 A/F	05-0T-01				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	15050:38				
						Ldg	11,028				
▼ 33 - LIGHTS											
043301		Perform the Inspection/Check of Power Supply and Battery Discharge Test on the batteries in accordance with Chapter 33-51-00 in the Model 400/400A Maintenance Manual.						RE (N/A)	AWL - Inspection Time Limits		
	 33 A/F	Aft				Mos					
	87-5106-2					Hrs					
	995322					Ldg					
	Ref:330005 (SOURCE: Model 400/400A ALM (128-590001-305)) (NOTE: For batteries with 3 to 5 years from date of installation, complete task code 330005 in Chapter 05-20-02 in the Model 400/400A Maintenance Manual every 6 months.)										
043301		Perform the Inspection/Check of Power Supply and Battery Discharge Test on the batteries in accordance with Chapter 33-51-00 in the Model 400/400A Maintenance Manual.						RE (N/A)	AWL - Inspection Time Limits		
	 33 A/F	Fwd				Mos					
	87-5106-2					Hrs					
	Unknown					Ldg					
	Ref:330005 (SOURCE: Model 400/400A ALM (128-590001-305)) (NOTE: For batteries with 3 to 5 years from date of installation, complete task code 330005 in Chapter 05-20-02 in the Model 400/400A Maintenance Manual every 6 months.)										
330000-0101		Inverter, Dual Voltage						RE (O/C)			
	 33 A/F	No.3				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
330000-0102		Inverter, Dual Voltage						RE (O/C)			
	 33 A/F	No.4				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
330000-0103	Inverter, Dual Voltage									
33 A/F	No.5					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0201	Seat Belt Ordinance Sign Tray									
33 A/F	Lavatory					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0301	Actuator Light, Landing									
33 A/F	Left					Mos	27-Mar-2020		RE (O/C)	
45AS88830-007						Hrs	13253:42			
010412						Ldg	9,929			
330000-0302	Actuator Light, Landing									
33 A/F	Right					Mos	25-Jun-2015		RE (O/C)	
45AS88830-007						Hrs	10075			
081005						Ldg	7,978			
330000-0401	Lens Assembly									
33 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0501	Wing Tip Lens									
33 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0502	Wing Tip Lens									
33 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0601	Florescent Light Starter									
33 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0602	Florescent Light Starter									
33 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0603	Florescent Light Starter									
33 A/F	No.3					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
330000-0604	Florescent Light Starter									
33 A/F	No.4					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
330000-0605		Florescent Light Starter						RE (O/C)			
33 A/F		No.5					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0606		Florescent Light Starter						RE (O/C)			
33 A/F		No.6					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0607		Florescent Light Starter						RE (O/C)			
33 A/F		No.7					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0608		Florescent Light Starter						RE (O/C)			
33 A/F		No.8					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0609		Florescent Light Starter						RE (O/C)			
33 A/F		No.9					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0610		Florescent Light Starter						RE (O/C)			
33 A/F		No.10					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0701		Lamp Dimmer						RE (O/C)			
33 A/F		No.5					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0801		Power Supply						RE (O/C)			
33 A/F		Fwd					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
330000-0802		Power Supply						RE (O/C)			
33 A/F		Aft					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
331000-0101		Instrument Light (PS103) Power Supply						RE (O/C)			
33 A/F							Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
331000-0102		Instrument Light (PS104) Power Supply						RE (O/C)			
33 A/F							Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
331000-0103		Instrument Light (PS105) Power Supply									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
331000-0104		Instrument Light (PS106) Power Supply									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
331000-0105		Instrument Light (PS107) Power Supply									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
331000-0201		Interior Light (4034) Power Supply									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
331000-0202		Interior Light(4035) Power Supply									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
331000-0203		Interior Light(4036) Power Supply									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
332000-0101		Strobe light									
⚙	33 A/F	Aft				Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
334000-0101		Wing Anti-Collision Light									
⚙	33 A/F	Left				Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
334000-0102		Wing Anti-Collision Light									
⚙	33 A/F	Right				Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
334000-0201		Tail Anti-Collision Light									
⚙	33 A/F					Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				
334000-0301		Landing Light									
⚙	33 A/F	Left				Mos	21-Nov-2000			RE (O/C)	
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No	Description											Categories	Time
SEQ	PN/SN	MOC	Note or Component	Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
334000-0302			Landing Light							RE (O/C)			
	33 A/F		Right						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
334000-0401			Tail Flood Light							RE (O/C)			
	33 A/F		Left						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
334000-0402			Tail Flood Light							RE (O/C)			
	33 A/F		Right						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
334000-0501			Tail Navigation Light							RE (O/C)			
	33 A/F								Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
334000-0601			Forward Recognition Light							RE (O/C)			
	33 A/F								Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
334000-0701			Wing Ice Inspection Light							RE (O/C)			
	33 A/F								Mos	03-Aug-2020			
	01-7079-24								Hrs	13529:56			
	20-0089								Ldg	10,105			
334000-0801			Anti-Collision Light Power Supply							RE (O/C)			
	33 A/F								Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
334000-0901			Tail Rotating Beacon							RE (O/C)			
	33 A/F								Mos	24-Jan-2023			
	01-0790724-12		New		0				Hrs	14913:30			
	10099760002				0				Ldg	10,941			
335000-0101			Emergency Light Power Supply							RE (O/C)			
	33 A/F		Left Fwd						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
335000-0102			Emergency Light Power Supply							RE (O/C)			
	33 A/F		Right Fwd						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			
335000-0103			Emergency Light Power Supply							RE (O/C)			
	33 A/F		Left Aft						Mos	21-Nov-2000			
	Unknown								Hrs	0			
	Unknown								Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
335000-0104		Emergency Light Power Supply								RE (O/C)	
	33 A/F	Right Aft					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
335000-0105		Emergency Light Power Supply								RE (O/C)	
	33 A/F	Fwd					Mos	21-Nov-2000			
	87-5106-2						Hrs	0			
	Unknown						Ldg	0			
335000-0106		Emergency Light Power Supply								RE (O/C)	
	33 A/F	Aft					Mos	21-Nov-2000			
	87-5106-2						Hrs	0			
	995322						Ldg	0			
335000-0201		Emergency Light Power Supply Battery								RE	AWL - Life Limit
	33 A/F	Fwd	0			Yrs	18-Feb-2022	5		[31-Jan-2027]	3.3 Years
	Unknown					Hrs	14572:58				
	Unknown					Ldg	10,722				
ALM:043302 (SOURCE: Model 400/400A ALM (128-590001-305)) (NOTE: Replace batteries with new batteries in accordance with Chapter 33-51-00 in the Model 400/400A Maintenance Manual.)											
335000-0202		Emergency Light Power Supply Battery								RE	AWL - Life Limit
	33 A/F	Aft	0			Yrs	18-Feb-2022	5		[31-Jan-2027]	3.3 Years
	Unknown					Hrs	14572:58				
	Unknown					Ldg	10,722				
ALM:043302 (SOURCE: Model 400/400A ALM (128-590001-305)) (NOTE: Replace batteries with new batteries in accordance with Chapter 33-51-00 in the Model 400/400A Maintenance Manual.)											
335000-0301		Lamp Dimmer								RE (O/C)	
	33 A/F	No.1					Mos	06-Nov-2020			
	76699-01						Hrs	13793:41			
	12151						Ldg	10,260			
335000-0302		Lamp Dimmer								RE (O/C)	
	33 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
335000-0303		Lamp Dimmer								RE (O/C)	
	33 A/F	No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
335000-0304		Lamp Dimmer								RE (O/C)	
	33 A/F	No.4					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
335115-0101		Switching (A390) Module								RE (O/C)	
	33 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description							Categories		Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
33-ICA-EMTQ		Emtq LED Cabin Lighting - Wire/Cable/Racks/Connectors - Inspect system installation components							RE	STC, Emtq LED Cabin Lighting Instl		≈24-Jun-2024	
	33 A/F	05-20-04,...					Mos	11-Nov-2022					
							Hrs	14814:28	800	+40	≠15614:28		
							Ldg	10,886					
(SOURCE: STC ST03960AT)													
95-25-06		Modify Standby Instrument Lighting System							T (A/R)	Mandatory			
	33 A/F	Eff: 16-Jan-1996					Mos						
							Hrs						
							Ldg						
AFI-108		Cabin Configuration Installations - Visually inspect LED Lighting for damage or missing parts.							RE	STC, Interior Cabin Configuration Installation			
	33 A/F	05-20-06					Mos	11-Nov-2022	12	(30-Nov-2023)		57 Days	
							Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)	
							Ldg	10,886					
(SOURCE: FAA STC ST01572WI)													
AFI-109		Cabin Configuration Installations - Perform operational test of all LED cabin lighting.							RE	STC, Interior Cabin Configuration Installation			
	33 A/F	05-20-06					Mos	11-Nov-2022	12	(30-Nov-2023)		57 Days	
							Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)	
							Ldg	10,886					
(SOURCE: FAA STC ST01572WI)													
AFI-110		Cabin Configuration Installations - Perform Function Test of Emergency Lighting Power Supply							RE	STC, Interior Cabin Configuration Installation			
	33 A/F						Mos	16-Aug-2023	12	31-May-2024		8 Months	
							Hrs	15050:38					
							Ldg	11,028					
(Tol. Adjustment: -82d) (SOURCE: FAA STC ST01572WI)													
AFI-111		Cabin Configuration Installations - Perform Battery Discharge Test of Emergency Lighting Power Supply.							RE	STC, Interior Cabin Configuration Installation			
	33 A/F						Mos	16-Aug-2023	12	31-May-2024		8 Months	
							Hrs	15050:38					
							Ldg	11,028					
(Tol. Adjustment: -82d) (SOURCE: FAA STC ST01572WI)													
CF-58-03		Emergency Lighting for Aircraft Cabin Interiors							RE (-)	Mandatory			
	33 A/F	Eff: 30-Jun-1959					Mos						
							Hrs						
							Ldg						
H330001		CABIN SECTION - CABIN INTERIOR LIGHTS - Inspect all for condition and operation.							RE	Scheduled Inspections			
	33 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)		57 Days	
							Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)	
							Ldg	10,886					
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)													
H330003		CABIN SECTION - EMERGENCY LIGHTING SYSTEM / b. (RK-98, RK-110 and After) - Perform EMERGENCY LIGHTING SYSTEM OPERATIONAL INSPECTION (Ref. Chapter 33-51-00).							RE	Scheduled Inspections			
	33 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)		57 Days	
							Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)	
							Ldg	10,886					
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)													
H330004		VERTICAL STABILIZER - FORWARD RECOGNITION LIGHT ASSEMBLY - Inspect for condition.							RE	Scheduled Inspections			
	33 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)		57 Days	
							Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)	
							Ldg	10,886					
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)													
H330005		HORIZONTAL STABILIZER - TAIL FLOOD LIGHTS - Inspect for condition.							RE	Scheduled Inspections			
	33 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)		57 Days	
							Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)	
							Ldg	10,886					
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)													

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H330006	PILOT'S COMPARTMENT - COCKPIT ADVISORY, CAUTION AND WARNING LIGHTS - Inspect all for condition and operation.						RE		Scheduled Inspections	
 33 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H330007	CABIN SECTION - EMERGENCY LIGHTING SYSTEM / a. (RK-1 thru RK-109, except RK-98) - Move the EMER LT switch to the TEST/ON position and ensure emergency lighting illuminates. Return EMER LT switch to the OFF position.						RE (N/A)		Scheduled Inspections	
 33 A/F					Mos					
					Hrs					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg					
H330008	PILOT'S COMPARTMENT - FLIGHT COMPARTMENT LIGHTING - Perform FLIGHT COMPARTMENT LIGHTS FUNCTIONAL TEST (Ref. Chapter 33-11-00).						RE		Scheduled Inspections	≈24-Jun-2024
 33 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H330009	PILOT'S COMPARTMENT - EXTERIOR LIGHTING - Perform EXTERIOR LIGHTS ADJUSTMENT AND TEST (Ref. Chapter 33-40-00).						RE		Scheduled Inspections	≈24-Jun-2024
 33 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H330010	CABIN SECTION - EMERGENCY LIGHTING SYSTEM / a. (RK-1 thru RK-109, except RK-98) - Perform the complete EMERGENCY LIGHT POWER SUPPLY FUNCTIONAL TESTING AND CHARGING PROCEDURE (Ref. Chapter 33-50-00).						RE (N/A)		Scheduled Inspections	
 33 A/F	Aft				Mos					
87-5106-2					Hrs					
995322					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H330010	CABIN SECTION - EMERGENCY LIGHTING SYSTEM / a. (RK-1 thru RK-109, except RK-98) - Perform the complete EMERGENCY LIGHT POWER SUPPLY FUNCTIONAL TESTING AND CHARGING PROCEDURE (Ref. Chapter 33-50-00).						RE (N/A)		Scheduled Inspections	
 33 A/F	Fwd				Mos					
87-5106-2					Hrs					
Unknown					Ldg					
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H330011	CABIN SECTION - EMERGENCY LIGHTING SYSTEM / b. (RK-98, RK-110 and After) - Perform Emergency Lighting System FUNCTIONAL TEST PROCEDURES (Ref. Chapter 33-51-00).						RE		Scheduled Inspections	≈24-Jun-2024
 33 A/F	Aft05-20-03				Mos	11-Nov-2022				
87-5106-2					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
995322					Ldg	10,886				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H330011	CABIN SECTION - EMERGENCY LIGHTING SYSTEM / b. (RK-98, RK-110 and After) - Perform Emergency Lighting System FUNCTIONAL TEST PROCEDURES (Ref. Chapter 33-51-00).						RE		Scheduled Inspections	≈24-Jun-2024
 33 A/F	Fwd05-20-03				Mos	11-Nov-2022				
87-5106-2					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
Unknown					Ldg	10,886				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)									
H330012	RIGHT-HAND WING - ANTI-COLLISION LIGHT ASSEMBLY - Inspect for condition.						RE		Scheduled Inspections	
 33 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H330013	LEFT-HAND WING - ANTI-COLLISION LIGHT ASSEMBLY - Inspect for condition.						RE		Scheduled Inspections	
 33 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
TA-LMM-14	Perform Emergency Lighting System Functional Test - I.a.w. AMM 128-590001-9, ch. 33-51-00 , page 201						RE (-)			
 33 A/F	05-0T-01				Mos	16-Aug-2023			(31-Aug-2023)	OVD
					Hrs	15050:38				
					Ldg	11,028				

Task No	Description					Categories		Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
TA-LMM-15 	33 A/F	Perform Cockpit Lamp Test I. a. w. AMM 128-590001-9, ch. 33-11-00, page 252 05-0T-01						RE (-)			
						Mos	16-Aug-2023		(31-Aug-2023)	OVD	
						Hrs	15050:38				
						Ldg	11,028				
TA-LMM-16 	33 A/F	Check Exterior Lights i. a. w. AMM 128-590001-9, ch. 33-40-00, page 254 05-0T-01						RE (-)			
						Mos	16-Aug-2023		(31-Aug-2023)	OVD	
						Hrs	15050:38				
						Ldg	11,028				
▼ 34 - NAVIGATION											
	34 A/F	Compass Swing. i.a.w AMM 34-20-01 and 34-21-00 (NOTE: i.a.w. regulation no. CAA-STC-092-n/07)						RE			
						Mos	16-Aug-2023	12	31-Aug-2024	11.1 Months	
						Hrs	15050:38				
						Ldg	11,028				
	34 A/F 08090021-6 1407	Digital Discrete Adapter						RE (-)			
						Mos					
						Hrs					
						Ldg					
	34 A/F	Leak check copilot pitot/static system (MANDATORY iaw CAA-ST-092-n/07)						RE			
						Mos	13-Sep-2021	24	30-Sep-2023	OVD	
						Hrs	14379				
						Ldg	10,595				
	34 A/F	Leak check pilot pitot/static system (MANDATORY iaw CAA-ST-092-n/07)						RE			
						Mos	13-Sep-2021	24	30-Sep-2023	OVD	
						Hrs	14379				
						Ldg	10,595				
2020-10744 	34 A/F Not Applicable	The FAA is adopting a new airworthiness directive (AD) for certain Rockwell Collins, Inc. (Rockwell Collins) flight management systems (FMS) installed on airplanes. This AD was prompted by reports of the flight management computer (FMC) software issuing incorrect turn commands when the altitude climb field is edited or the temperature compensation is activated on the FMS control display unit. This AD requires disabling the automatic temperature compensation feature of the FMS through the configuration strapping units (CSU) and revising the airplane flight manual (AFM) Limitations section. The FAA is issuing this AD to address the unsafe condition on these products. P/N						RE (-)			
						Mos	02-Jun-2020				
						Hrs	13334:45				
						Ldg	9,976				
2020-18-51 	34 A/F Eff: 28-Aug-2020 Not Applicable (UPDATE NOTE: Not Applicable by PN) (NOTE: (1) Before further flight, revise the limitations section of the existing Airplane Flight Manual (AFM) for your airplane by inserting a copy of this AD or by making a pen and ink change to add:)	Attitude and Direction Data System - BendixKing/Sandia						RE (-)	Mandatory (Appliance AD)		
						Mos	22-Sep-2020				
						Hrs	13682:10				
						Ldg	10,195				
2021-08-07 	34 A/F Eff: 12-May-2021 Not Applicable (NOTE: Applicability: This AD applies to Rockwell Collins, Inc. GPS-4000S Global Positioning System (GPS) part number (P/N) 822-2189-100 installed on airplanes, certificated in any category.)	Navigation System - GPS-4000S Global Positioning System						RE (-)	Mandatory (Appliance AD)		
						Mos					
						Hrs					
						Ldg					
2021-08-15 	34 A/F Eff: 17-May-2021 Not Applicable (NOTE: Required Action and Compliance: Within 24 months after the effective date of this AD, update the GTS processor software to a version that is not 3.13 or earlier, except 3.12.1. Software version 3.12.1 does not contain the unsafe condition.)	Garmin International GMN-00962 GTS Processor Units						RE (-)	Mandatory (Appliance AD)		
						Mos	14-Nov-2021				
						Hrs	14475:17				
						Ldg	10,658				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2021-23-12	Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes) (This AD is Superseded by FAA AD 2023-10-02)						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	11-Jun-2023				
Eff: 03-Jan-2022 Not Applicable	AD not adopted by EASA				Hrs					
	(NOTE: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.)				Ldg					
2022-0024	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	10-Feb-2022				
Eff: 18-Feb-2022 Not Applicable	Na by manufacturer of FMC				Hrs	14572:58				
	(NOTE: APPLICABILITY: Thales Flight Management Computer (FMC) 2 Navigation Modules (NAVM), identified by Part Number C13084CA03. These FMC2 NAVM are known to be installed on, but not limited to, Dassault (formerly Bréguet) Br.1150 Atlantique 2 (ATL2) maritime patrol aeroplanes.)				Ldg	10,722				
2022-0024 Par. (1)	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment: Operational Limitation(s)						RE (-)		Mandatory (Appliance AD)	
34 A/F					Days	10-Feb-2022				
Eff: 18-Feb-2022 Not Applicable	Na by manufacturer of FMC				Hrs	14572:58				
	(NOTE: COMPLIANCE: Within 30 days after the effective date of this AD, amend the applicable AFM to refer to Thales FMS User Manual J68952AA-01, containing the limitations specified in Table 1 of this AD, inform all flight crew and, thereafter, operate the Flight Management System (FMS) in accordance with Table 2 of this AD.)				Ldg	10,722				
2022-0024 Par. (2)	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment: Use of Navigation Database						RE (-)		Mandatory (Appliance AD)	
34 A/F					Days	10-Feb-2022				
Eff: 18-Feb-2022 Not Applicable	Na by manufacturer of FMC				Hrs	14572:58				
	(NOTE: COMPLIANCE: Within 30 days after the effective date of this AD, update the navigation database delivered to installers and operators to remove some navigation procedures as defined in the SIL, and, thereafter, use only a regularly updated navigation database where the above-mentioned procedures have been removed.)				Ldg	10,722				
2023-10-02	Navigation - Radio Altimeters (This AD Replaces AD 2021-23-12)						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	11-Jun-2023				
Eff: 26-May-2023 Not Applicable	AD not adopted by EASA				Hrs					
	(NOTE: APPLICABILITY: This AD applies to all transport and commuter category airplanes equipped with a radio (also known as radar) altimeter. These radio altimeters are installed on various transport and commuter category airplanes including, but not limited to, the airplanes for which the design approval holder is identified in paragraphs (c)(1) through (18) of this AD. (1) The Boeing Company (2) Airbus SAS (3) Bombardier Inc.(4) Embraer S.A. (including type certificates previously held by Yaborá Indústria Aeronáutica S.A., which are now held by Embraer S.A.) (5) Gulfstream Aerospace Corporation (6) Gulfstream Aerospace LP (7) Textron Aviation Inc. (8) Pilatus Aircraft Limited (9) Fokker Services B.V. (10) Saab AB, Support and Services (11) DeHavilland Aircraft of Canada Limited (12) Airbus Canada Limited Partnership (13) ATR-GIE Avions de Transport Régional (14) MHI RJ Aviation ULC (15) BAE Systems (Operations) Limited (16) Lockheed Martin Corporation/Lockheed Martin Aeronautics Company (17) Viking Air Limited (18) Dassault Aviation)				Ldg					
2023-10-02 Par. (h)	Navigation - Radio Altimeters - Airplane Flight Manual (AFM) Revision Until June 30, 2023						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	11-Jun-2023				
Eff: 25-May-2023 Not Applicable	AD not adopted by EASA				Hrs					
	(NOTE: COMPLIANCE: For non-radio altimeter tolerant airplanes, before further flight, revise the Limitations Section of the existing AFM to include the information specified in figure 3 to paragraph (h) of this AD. This may be done by inserting a copy of figure 3 to paragraph (h) of this AD into the existing AFM. If an operator has complied with paragraph (g) of AD 2021-23-12, that action satisfies the requirements of this paragraph.)				Ldg					
2023-10-02 Par. (i)	Navigation - Radio Altimeters - AFM Revision After June 30, 2023						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	11-Jun-2023				
Eff: 29-Jun-2023 Not Applicable	AD not adopted by EASA				Hrs					
	(NOTE: COMPLIANCE: On or before June 30, 2023, revise the Limitations Section of the existing AFM to include the information specified in figure 4 to paragraph (i) of this AD. This may be done by inserting a copy of figure 4 to paragraph (i) of this AD into the existing AFM. Incorporating the AFM revision required by this paragraph terminates the AFM revision required by paragraph (h) of this AD. (2) Before further flight after incorporating the limitations specified in figure 4 to paragraph (i) of this AD, remove the AFM revision required by paragraph (h) of this AD.)				Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
340000-0101	Card, Auto-Pilot Trim Computer									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0201	TCAS Omni Directional Antenna									
34 A/F	Fwd					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0301	Flight Management Computer									
34 A/F	No.1					Mos	06-Nov-2020		RE (O/C)	
822-0868-123						Hrs	13793:41			
1208						Ldg	10,260			
340000-0501	Flight Control Computer									
34 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0601	Pitot Static Probe									
34 A/F	Pilot					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0602	Pitot Static Probe									
34 A/F	Copilot					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0701	Altimeter									
34 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0702	Altimeter									
34 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0802	Coupler Glideslope									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-0901	Course Heading Panel									
34 A/F	New					Mos	01-Oct-2014		RE (O/C)	
822-1280-003						Hrs	9536			
4KG55						Ldg	7,660			
340000-1001	VOR Coupler									
34 A/F	New					Mos	19-Jan-2018		RE (O/C)	
DMH21-1						Hrs	11765			
21957						Ldg	8,978			

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
340000-1101	Coupler, Navigation Marker								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1201	Mount Assembly								RE (O/C)	
34 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1202	Mount Assembly								RE (O/C)	
34 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1301	Standby Airspeed Indicator								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1401	Differential Pressure Switch								RE (O/C)	
34 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1402	Differential Pressure Switch								RE (O/C)	
34 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1403	Differential Pressure Switch								RE (O/C)	
34 A/F	No.3					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1501	Signal Interface Adapter								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1601	Standby Compass								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1701	AOA Transmitter								RE (O/C)	
34 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-1702	AOA Transmitter								RE (O/C)	
34 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
340000-1801		Pilots Multifunctional Display								RE (O/C)	
	34 A/F						Mos	01-Jun-2022			
	822-1753-416						Hrs	14628:53			
	4CBFX						Ldg	10,762			
340000-1901		Sensor, Display								RE (O/C)	
	34 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
340000-2001		Attitude Heading Computer								RE (O/C)	
	34 A/F	No.1					Mos	01-Jan-2013			
	822-1378-001						Hrs	8038			
	4LPH0						Ldg	6,796			
340000-2101		Compensation Unit								RE (O/C)	
	34 A/F	No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
340000-2102		Attitude Heading Computer (AHC 3000A)								RE (O/C)	
	34 A/F	No.2					Mos	21-Nov-2000			
	822-1378-001						Hrs	0			
	4BWN6						Ldg	0			
	(NOTE: MFR 1BSP7										
	DMF 112011)										
340000-2202		Compensation Unit								RE (O/C)	
	34 A/F	No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
340000-2301		Flux Detector								RE (O/C)	
	34 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
340000-2302		Flux Detector								RE (O/C)	
	34 A/F	Right					Mos	25-May-2022			
	622-5812-001						Hrs	14622:44			
	101595						Ldg	10,755			
340000-2401		Radio Altimeter Converter								RE (O/C)	
	34 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
340000-2501		Radio Altimeter								RE (O/C)	
	34 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
340000-2602	ADF Receiver (NOT USED)									
 34 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-2701	ADF Antenna									
 34 A/F						Mos	13-Mar-2015		RE (O/C)	
622-7383-001						Hrs	9901			
44099Y						Ldg	7,877			
340000-2801	Glideslope Antenna									
 34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-2901	ATC Antenna									
 34 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-2902	ATC Antenna									
 34 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
340000-3001	Marker Beacon Antenna									
 34 A/F						Mos	06-Apr-2023		RE (O/C)	
DM N27-3	New	0				Hrs	15050:38			
19497		0				Ldg	11,028			
34-0T-01	Perform Obstacle Database Update									
 34 A/F						Mos	16-Aug-2023	3	16-Nov-2023	43 Days
						Hrs	15050:38			
						Ldg	11,028			
34-0T-03	RVSM Height monitoring (EUR RMA) - contact Flight Dispatch and FOM to schedule flight over HMU within following 6 months to comply with the RVSM monitoring requirement. Compliance isn't required with Part-145 procedures. Compliance is verified trough: https://www.eurocontrol.int/rmalive/operatorList.do								T (At opportunity)	
 34 A/F						Mos			+6m	
						Hrs			+250	
						Ldg				
341000-0101	Pitot Tube									
 34 A/F	Left					Mos	04-Aug-2017		RE (O/C)	
PH1100-MU-L-1	New					Hrs	11476			
1920603						Ldg	8,809			
341000-0102	Pitot Tube									
 34 A/F	Right					Mos	04-Aug-2017		RE (O/C)	
PH1100-MU-R-1	New					Hrs	11476			
1885406						Ldg	8,809			
341000-0201	Lower Pilot Static Port									
 34 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
341000-0202		Upper Pilot Static Port									
	34 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0203		Upper Copilot Static Port									
	34 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0204		Lower Copilot Static Port									
	34 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0301		Third System Static Port									
	34 A/F						Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0401		Mach/Airspeed Indicator									
	34 A/F	Pilot					Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0402		Mach/Airspeed Indicator									
	34 A/F	Copilot					Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0502		Instantaneous Vertical Speed Indicator									
	34 A/F	Copilot					Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341000-0601		(ALT-55B) Radio Altimeter Indicator transceiver									
	34 A/F						Mos	12-Aug-2022		RE (O/C)	
	622-2855-011						Hrs	14786:10			
	9055						Ldg	10,868			
341100-0201		Altimeter									
	34 A/F	StandBy					Mos	22-Nov-2016		RE (O/C)	
	132739-42	New					Hrs	11049			
	1055451						Ldg	8,554			
341100-0301		Mach/Airspeed Warning Horn									
	34 A/F						Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
341100-0401		Altitude Alert Warning Horn									
	34 A/F						Mos	21-Nov-2000		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
341100-0501	Gear Warning Horn									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-0601	Trim Warning Horn									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-0701	Air Data Computer									
34 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
822-0389-468		11,196				Hrs	11446			
4342		8,639				Ldg	8,789			
(NOTE: ADC-850D Robbed from OK-EAS)										
341100-0702	Air Data Computer (ADC-850D)									
34 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
822-0389-468						Hrs	0			
3719						Ldg	0			
341100-0801	Stall Warning Computer									
34 A/F	Left					Mos	23-Apr-2020		RE (O/C)	
0020BG1						Hrs	13258:28			
21920						Ldg	9,933			
341100-0802	Stall Warning Computer									
34 A/F	Right					Mos	23-Apr-2020		RE (O/C)	
0020BG1						Hrs	13258:28			
23138						Ldg	9,933			
341100-0901	Temperature Probe									
34 A/F	Aft					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-1001	Rosemount Probe									
34 A/F	Fwd					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-1101	Navigation Data Computer									
34 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-1102	Navigation Data Computer									
34 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-1201	(55B) Radio Altitude Transceiver									
34 A/F						Mos	21-Sep-2017		RE (O/C)	
622-2855-001						Hrs	11591			
YYYY						Ldg	8,874			
(NOTE: (robbed from OK-JFA))										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
341100-1301	Radio Altimeter Converter									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341100-1401	Antenna Radar Altimeter									
34 A/F	No.1					Mos	03-Aug-2022		RE (O/C)	
S67-2002-14						Hrs	14777:12			
543-107057						Ldg	10,860			
341100-1402	Antenna Radar Altimeter									
34 A/F	No.2					Mos	03-Aug-2022		RE (O/C)	
S67-2002-14						Hrs	14777:12			
543-107085						Ldg	10,860			
341200-0101	Angle Of Attack Transmitter									
34 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341200-0102	Angle Of Attack Transmitter									
34 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341200-0201	Stall Warning Shaker									
34 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341200-0202	Stall Warning Shaker									
34 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
341200-0301	Angle Of Attack Indexer									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
342000-0101	Standby Magnetic Compass									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
342000-0201	Third Attitude Indicator									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
342000-0202	TCAS Omni Directional Antenna									
34 A/F	Aft					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
34-2014-01 Rev IR	Nextant - Radio Altimeter Wiring Correction								RE (-)	Mandatory
 34 A/F						Mos	16-May-2014			
Eff: 09-Jan-2014 Complied	C/W - previously under WO 13-0712					Hrs				
With						Ldg				
342100-0101	Altitude Sensor								RE (O/C)	
 34 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
342100-0102	Altitude Sensor								RE (O/C)	
 34 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
342100-0201	Air Speed Sensor								RE (O/C)	
 34 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
342100-0202	Air Speed Sensor								RE (O/C)	
 34 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
342100-0301	Indicator, Standby Horizon								RE (O/C)	
 34 A/F						Mos	01-Oct-2014			
122-382015-11						Hrs	9502			
1442						Ldg	7,642			
343000-0101	Vor/Loc Antenna								RE (O/C)	
 34 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
343000-0102	Vor/Loc Antenna								RE (O/C)	
 34 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
343000-0302	Flight Management Computer								RE (O/C)	
 34 A/F	No.2					Mos	11-Mar-2020			
822-0868-123						Hrs	13175:44			
NJLV						Ldg	9,882			
344000-0101	Weather Radar Unit								RE (O/C)	
 34 A/F						Mos	01-Aug-2013			
622-8440-003	New					Hrs	8530			
1428						Ldg	7,084			

Task No	Description										Categories	Time		
SEQ	PN/SN	MOC	Note or Component	Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	DUE	Remaining
345000-0101	⚙️ 34 A/F 622-7382-101 4CHY (NOTE: WT: 3.9 LB)	ADF Receiver (ADF-462)	No.1								RE (O/C)			
								Mos	21-Nov-2000					
								Hrs	0					
								Ldg	0					
345000-0201	⚙️ 34 A/F 622-7194-201 4635	VHF Navigation Receiver	No.1								RE (O/C)			
								Mos	01-Aug-2014					
								Hrs	9348					
								Ldg	7,539					
345000-0202	⚙️ 34 A/F Unknown Unknown	VHF Navigation Receiver	No.2								RE (O/C)			
								Mos	21-Nov-2000					
								Hrs	0					
								Ldg	0					
345000-0301	⚙️ 34 A/F 622-7309-101 3190	DME Transceiver (DME-442)	No.1 New								RE (O/C)			
								Mos	18-Jun-2019					
				0				Hrs	12663:28					
				0				Ldg	9,551					
345000-0302	⚙️ 34 A/F 622-7309-101 5WMV	DME Transceiver (DME-422)	No.2								RE (O/C)			
								Mos	16-Oct-2018					
								Hrs	12346					
								Ldg	9,353					
345000-0401	⚙️ 34 A/F 622-9210-502 1RW8T	Transponder (TDR-94D)	No.1 Upgraded								RE (O/C)			
								Mos	31-Oct-2019					
								Hrs	13005:36					
								Ldg	9,767					
345000-0402	⚙️ 34 A/F 622-9210-502 2459	Transponder (TDR-94D)	No.2 Upgraded								RE (O/C)			
								Mos	31-Oct-2019					
								Hrs	13005:36					
								Ldg	9,767					
345000-0501	⚙️ 34 A/F Unknown Unknown	Microphone									RE (O/C)			
								Mos	21-Nov-2000					
								Hrs	0					
								Ldg	0					
345000-0601	⚙️ 34 A/F Unknown Unknown	DME Antenna	No.1								RE (O/C)			
								Mos	21-Nov-2000					
								Hrs	0					
								Ldg	0					
345000-0602	⚙️ 34 A/F Unknown Unknown	DME Antenna	No.2								RE (O/C)			
								Mos	21-Nov-2000					
								Hrs	0					
								Ldg	0					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
345000-0701	Vlf (Loop) Antenna									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345600-0102	Flight Control Computer									
34 A/F	No.2					Mos	01-Feb-2013		RE (O/C)	
822-1019-313						Hrs	8085			
269F5						Ldg	6,825			
345600-0401	Air Data Module									
34 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345600-0402	Air Data Module									
34 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0102	Data Acquisition									
34 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0201	Sensor, Display									
34 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0202	Sensor, Display									
34 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0301	Mode Select Panel									
34 A/F	Pilot					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0302	Mode Select Panel									
34 A/F	Copilot					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0401	Control Display Unit CDU									
34 A/F	No.1					Mos	06-Nov-2020		RE (O/C)	
822-0892-019						Hrs	13793:41			
2CPKG						Ldg	10,260			
345700-0402	Control Display Unit CDU									
34 A/F	No.2					Mos	01-Nov-2012		RE (O/C)	
822-0892-015	New					Hrs	7921			
3TXB						Ldg	6,721			

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
345700-0501	Control Display Coupler								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
345700-0601	Data Base Unit								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0101	Receiver Computer Unit								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0201	Flight Display								RE (O/C)	
34 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0301	Copilot Multifunction Display								RE (O/C)	
34 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0401	Flight Display								RE (O/C)	
34 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0501	Air Data Select								RE (O/C)	
34 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0502	Air Data Select								RE (O/C)	
34 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0601	Altitude Awareness								RE (O/C)	
34 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0602	Altitude Awareness								RE (O/C)	
34 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0701	GPS Antenna								RE (O/C)	
34 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
346000-0702	GPS Antenna									
 34 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-0801	GPS Receiver (GPS-4000S)									
 34 A/F	No.1					Mos	21-Nov-2000			
822-2189-004						Hrs	0			
1BNDT						Ldg	0			
(NOTE: MFR 4V792										
DMF 082003										
WT: 6 LB)										
346000-0802	GPS Receiver									
 34 A/F	No.2					Mos				
822-2189-004						Hrs				
46F7T						Ldg				
346000-0901	TCAS Transmitter									
 34 A/F						Mos	06-Nov-2020			
822-1293-033						Hrs	13793:41			
141261						Ldg	10,260			
346000-1001	TCAS Directional Antenna									
 34 A/F	Upper					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-1002	TCAS Directional Antenna									
 34 A/F	Lower					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
346000-1101	EGPWS Computer									
 34 A/F						Mos	11-Nov-2021			
3010-00-00						Hrs	14471:02			
1671						Ldg	10,655			
34-ICA-TAWS	(UASC) TAWS A - Airport Database periodic update (Operator inspection requirements)									
 34 A/F						Mos	16-Aug-2023	RE	STC	
						Hrs	15050:38	12	16-Aug-2024	10.6 Months
Ref:373-00-0041 (SOURCE: ST10959SC)						Ldg	11,028			
34-ICA-TAWS	(UASC) TAWS A - Wire/Cable/Racks/Connectors - Inspect system installation components condition and security.									
 34 A/F	05-20-04,...					Mos	11-Nov-2022	RE	STC, (UASC) TAWS A Installed	≈24-Jun-2024
						Hrs	14814:28	800	+40	≈15614:28
Ref:373-00-0041 (SOURCE: ST10959SC)						Ldg	10,886			
34-PL21-A1	PILOTS COMPARTMENT - FLIGHT DISPLAYS - Inspect for security, installation, and general condition.									
 34 A/F	05-20-14					Mos	11-Nov-2022	RE	ICA	
						Hrs	14814:28	400	+40	(30-Nov-2023) 57 Days
Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)						Ldg	10,886		(15214:28)	163:50 Hrs (+40)
34-PL21-A2	PILOTS COMPARTMENT - MASTER CAUTION/MASTER WARNING PANEL - Inspect for security, installation and general condition.									
 34 A/F	05-20-14					Mos	11-Nov-2022	RE	ICA	
						Hrs	14814:28	400	+40	(30-Nov-2023) 57 Days
Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)						Ldg	10,886		(15214:28)	163:50 Hrs (+40)

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
34-PL21-A3	34 A/F	PILOTS COMPARTMENT - PILOT and COPILOT REVERSIONARY SWITCH PANELS - Inspect for security, installation, and general condition. 05-20-14 Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)						RE	12	(30-Nov-2023)	57 Days
34-PL21-A4	34 A/F	PILOTS COMPARTMENT - PEDESTAL MOUNTED SWITCH PANEL - Inspect for security, installation, and general condition. 05-20-14 Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)						RE	12	(30-Nov-2023)	57 Days
34-PL21-A5	34 A/F	PILOTS COMPARTMENT - REVERSIONARY RELAY PANEL - Inspect for security, installation, and general condition. 05-20-16 Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)						RE	1,600	(15649:30)	598:52 Hrs (+40)
34-PL21-D1	34 A/F	WIRE/CABLE/RACKS/CONNECTIONS - Inspect system installation components including wires bundles, cables, racks, and connector condition and security. 05-20-16 Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)						RE	1,600	(15649:30)	598:52 Hrs (+40)
ESC-200812-059	34 A/F	RH MFD shut down during climb for about 2 minutes with yellow box XTLK on others displays Open (Date reported: 12-Aug-2020), (Reported by: Zdenek Ovecka, Title: Pilot)(Classification date: 12-Aug-2020), (Recorded by: Lukas Polansky, Title: CAMO)						N/N (-)		Squawk, Cosmetic	
H340001	34 A/F	FORWARD FUSELAGE - PITOT/STATIC SYSTEM / a. Drain any moisture from pitot and static plumbing drain valves. / b. Inspect static ports for obstruction. 05-20-02 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						RE	12	(30-Nov-2023)	57 Days
H340003	34 A/F	FORWARD FUSELAGE - AOA TRANSMITTER PROBE - Inspect for cleanliness of air inlet ports (if cone-type probe), evidence of overheating or damage and freedom of probe rotation. 05-20-02 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						RE	400	(15214:28)	163:50 Hrs (+40)
H340004	34 A/F	PILOT'S COMPARTMENT - PRIMARY FLIGHT DISPLAY (PFD) AND MULTIFUNCTION DISPLAY (MFD) COOLING FANS - Inspect screens for lint, carpet fibers and indication of blockage. 05-20-03 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)						RE	800	(15614:28)	563:50 Hrs (+40)
H340005	34 A/F	PILOT'S COMPARTMENT - FLIGHT INFORMATION DISPLAYS AND INSTRUMENTS / a. Inspect all for condition. / b. Check oxygen and nitrogen operating pressures. 05-20-02 (SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						RE	400	(15214:28)	163:50 Hrs (+40)
H340006	34 A/F	MACH OVERSPEED WARNING SYSTEM - Perform functional test by use of pitot/static tester (Ref. AIR-SPEED AND MACH WARNING TEST, Chapter 34-12-00). (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)						RE	2	31-Aug-2025	1.9 Years
H340007	34 A/F	AIR DATA SYSTEM (RVSM Only) (RK-1 thru RK-299 that have complied with Service Bulletin No. 34-3431; RK-300 and After) - Measure step height of the Static port. Check air data system for RVSM accuracy (Ref. Chapter 34-10-01). (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: RK-1 thru RK-299 that have complied with Service Bulletin No. 34-3431; RK-300 and After)						RE	2	30-Sep-2023	OVD

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H340008		PILOT'S COMPARTMENT - STALL WARNING SYSTEM / a. Perform stall warning system - SELF TEST (Ref. Chapter 34-11-00). / b. Perform FAULT INDICATOR TEST (Ref. Chapter 34-11-00).						RE		Scheduled Inspections	≈24-Jun-2024
	34 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H340010		FORWARD FUSELAGE - PITOT TUBES / a. Perform PITOT TUBE INSPECTION (Ref. Chapter 34-12-00). / b. Perform UNPAINTED SURFACE INSPECTION (Ref. Chapter 12-20-00).						RE		Scheduled Inspections	
	34 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H340011		FORWARD FUSELAGE - PITOT, STATIC AND AOA SENSOR - Perform PITOT/STATIC AND AOA HEATING SYSTEM OPERATIONAL CHECK (Ref. Chapter 30-30-00).						RE		Scheduled Inspections	≈24-Jun-2024
	34 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H340012		Inspect and test ALTIMETER i.a.w. EASA SIB No: 2011-15 (In latest revision) - Check per current CFR's.						RE		Scheduled Special Inspections	
	34 A/F					Yrs	13-Sep-2021	2		30-Sep-2023	OVD
						Hrs	14379				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	10,595				
H340013		Inspect and test Transponders No.1 and No.2 i.a.w. EASA SIB No: 2011-15 (In latest revision) - Check per current CFR's.						RE		Scheduled Special Inspections	
	34 A/F					Yrs	13-Sep-2021	2		30-Sep-2023	OVD
						Hrs	14379				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	10,595				
H340014		Inspect and test Air Data Computer i.a.w. EASA SIB No: 2011-15 (In latest revision) - Check per current CFR's.						RE		Scheduled Special Inspections	
	34 A/F					Yrs	13-Sep-2021	2		30-Sep-2023	OVD
						Hrs	14379				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	10,595				
H341101		PILOT'S COMPARTMENT - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) (RK-483 and After - Optional) - Inspect the Data Base Unit (DBU) for proper mounting and security of attachment (Ref. Chapter 34-59-00).						RE (N/A)		Scheduled Inspections	
	34 A/F					Mos					
						Hrs					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg					
H341176		AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) WIRING (RK-483 and After - Optional) - Visually inspect for signs of chafing, security and corrosion.						RE (N/A)		Scheduled Special Inspections	
	34 A/F					Mos					
						Hrs					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg					
H341177		AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) ANTENNA FUSELAGE FEED-THROUGH (FS 378.54 - lower fuselage (RK-483 and After - Optional) - Detail inspect for corrosion and wear. Using Eddy current method (with a surface probe) inspect for cracks and any indication of structural damage. Antenna removal is required (Ref. Chapter 34-59-00).						RE (N/A)		Scheduled Special Inspections	
	34 A/F					Mos					
						Hrs					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg					
H341178		AFT FUSELAGE - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) (Optional Equipment - RK-483 and After) - Inspect the Data Management Unit (DMU), the Configuration Module, and the mount rack for proper mounting and security of attachment (Ref. Chapter 34-59-00).						RE (N/A)		Scheduled Inspections	
	34 A/F					Mos					
						Hrs					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SAIB CE-19-19		TDR-94() ATC/Mode S Transponders modified by Rockwell Collins Service Bulletin TDR-94()-34-30; this is marked on the unit as MOD "30". Issues include instances where aircraft were not detected by a Multilateration (MLAT) ground system, where an aircraft was not tracked when close to the airport, or where a duplicate return was sensed by an Air Traffic Control Radar Beacon System (ATCRBS) ground station.The loss of detection / duplicate reports usually occur when TDR-94() MOD 30 equipped aircraft are close to the ground station. For MLAT stations, this is usually within 1 nautical mile of the ground station; other ground systems have had issues at a greater distance. This issue is only evident near ground stations that have not implemented Dynamic Minimum Trigger Level (MTL).						RE (-)			
	34 A/F	Not Applicable (UPDATE NOTE: MOD 30 not installed on TDR.)				Mos	09-Dec-2019				
					Hrs	13072:26					
					Ldg	9,810					
TA 2020-00586		The FAA is adopting a new airworthiness directive (AD) for certain Aspen Avionics, Inc., Evolution Flight Display (EFD) EFD1000 Emergency Backup Display, EFD1000 Multi-Function Display, and EFD1000 Primary Flight Display systems installed on various airplanes. This AD imposes operating restrictions on these display systems by revising the Limitations section of the airplane flight manual (AFM). This AD was prompted by an automatic reset occurring when the display internal monitor detects a potential fault, causing intermittent loss of airspeed, attitude, and altitude information during flight. The FAA is issuing this AD to address the unsafe condition on these products.						RE (-)			
	34 A/F	Not Applicable (UPDATE NOTE: Have not this P/N installed on A/C)				Mos	17-Aug-2020				
					Hrs	13587:24					
					Ldg	10,136					
TA-LMM-FMS		Update FMS						RE (-)			
	34 A/F					Mos					
					Hrs						
					Ldg						
▼ 35 - OXYGEN											
043502		Oxygen Cylinder - Hydrostatically Test						RE		AWL - Inspection Limitations	
	35 A/F	101-384207-13 580872501 Hydrostatic Tested Date 10-Aug-2021 (SOURCE: Maintenance Manual 040002)				Yrs	15-Aug-2021	5		31-Aug-2026	2.9 Years
					Hrs	14294:02					
					Ldg	10,545					
2003-10-13		Low-pressure oxygen tubing						T (A/R)		Mandatory	
	35 A/F	Eff: 01-Jul-2003				Mos					
					Hrs						
					Ldg						
2023-13-11		Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)						RE (-)		Mandatory (Appliance AD)	
	35 A/F	Eff: 05-Sep-2023 Not Applicable (NOTE: APPLICABILITY: This AD applies to AVOX Systems Inc. (formerly Scott Aviation) oxygen cylinder and valve assemblies having part number (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, or 891311-14; and oxygen valve assemblies (body and gage assemblies) having P/N 807206-01. These assemblies might be installed on, but not limited to, the aircraft identified in paragraphs (c)(1) through (12) of this AD, certificated in any category. COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1 or Appendix 2, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review.)				Days	06-Aug-2023				
			N/A by PN				Hrs				
							Ldg				
350000-0101		Oxygen Regulator						RE (O/C)			
	35 A/F	172400 N/A				Mos	15-Aug-2021				
					Hrs	14294:02					
					Ldg	10,545					
350000-0201		Protective Breathing Equipment (PBE)						RE		Life Limit, Special Scheduled Inspections	
	35 A/F	802300-14 E18090305 Manufactured Date 10-Dec-2018 IFA MM:H350012, MM:350012				Yrs	18-May-2019	10		31-Dec-2028	5.2 Years
			New				Hrs	12578:03			
							Ldg	9,503			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
350000-0401	Oxygen Mask Container									
35 A/F	No.1					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
350000-0402	Oxygen Mask Container									
35 A/F	No.2					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
350000-0403	Oxygen Mask Container									
35 A/F	No.3					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
350000-0404	Oxygen Mask Container									
35 A/F	No.4					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
350000-0405	Oxygen Mask Container									
35 A/F	No.5					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
350000-0406	Oxygen Mask Container									
35 A/F	Aft					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
350000-0501	Oxygen Pressure Gauge									
35 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
351000-0101	Oxygen Cylinder									
35 A/F										
101-384207-13						Yrs	01-Sep-2013	15	AWL - Life Limit	4.9 Years
580872501						Hrs	8722		01-Sep-2028	
Manufactured Date 01-Sep-2013						Ldg	7,201			
MM:043501 (SOURCE: Maintenance Manual 040002) (NOTE: (DOT E-8162 / DOT SP-8162))										
351000-0201	Oxygen Cylinder Regulator									
35 A/F										
101-384207-13		0				Mos	11-Nov-2022	72	11-Nov-2028	5.1 Years
6290						Hrs	14814:28			
						Ldg	10,886			
351000-0301	Oxygen Pressure Indicator									
35 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
351000-0401	Crew Mask Regulator Assembly									
35 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
351000-0402	Crew Mask Regulator Assembly									
35 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
351000-0501	Oxygen Mask (Crew)									
35 A/F	Pilot	0				Mos	21-Jun-2021	72	08-Jan-2027	3.3 Years
174252-92						Hrs	14128:53			
13892						Ldg	10,451			
Overhaul Date 08-Jan-2021										
351000-0502	Oxygen Mask (Crew)									
35 A/F	Copilot	0				Mos	22-Nov-2021	72	22-Nov-2027	4.1 Years
174252-92						Hrs	14493:42			
17320						Ldg	10,674			
(NOTE: Removed from OK-PPP (OVH Date set incorrectly))										
351031-0101	Crew Oxygen Mask Regulator Assembly									
35 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
351031-0102	Crew Oxygen Mask Regulator Assembly									
35 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
352000-0101	Oxygen Mask (Passenger)									
35 A/F	No.1	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0102	Oxygen Mask (Passenger)									
35 A/F	No.2	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0103	Oxygen Mask (Passenger)									
35 A/F	No.3	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0104	Oxygen Mask (Passenger)									
35 A/F	No.4	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
352000-0105	Oxygen Mask (Passenger)									
35 A/F	No.5	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0106	Oxygen Mask (Passenger)									
35 A/F	No.6	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0107	Oxygen Mask (Passenger)									
35 A/F	No.7	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0108	Oxygen Mask (Passenger)									
35 A/F	No.8	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0109	Oxygen Mask (Passenger)									
35 A/F	No.9	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0110	Oxygen Mask (Passenger)									
35 A/F	No.10	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0111	Oxygen Mask (Passenger)									
35 A/F	No.11	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0112	Oxygen Mask (Passenger)									
35 A/F	No.12	5				Mos	27-Mar-2020	96	27-Oct-2027	4.1 Years
174095-58						Hrs	13253:42			
N/A						Ldg	9,929			
352000-0201	Oxygen Valve Assembly									
35 A/F									RE (O/C)	
Unknown						Mos	21-Nov-2000			
Unknown						Hrs	0			
						Ldg	0			
353001-0101	Portable Oxygen Cylinder									
35 A/F		0				Yrs	21-Nov-2000	35	AWL - Life Limit	
Unknown						Hrs	0		21-Nov-2035	12.1 Years
Unknown						Ldg				
Manufactured Date 21-Nov-2000										
Ref:Task 043506 (SOURCE: Maintenance Manual 040002) (NOTE: (DOT 3AA 1800))										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H350001		PILOT'S COMPARTMENT - PILOT'S AND COPILOT'S OXYGEN SYSTEM - Perform the appropriate FLIGHT CREW OXYGEN SYSTEM OPERATIONAL CHECK (Ref. Chapter 35-11-00).						RE		Scheduled Inspections	≈24-Jun-2024
	35 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H350002		PILOT'S COMPARTMENT - PASSENGER OXYGEN SYSTEM - Perform PASSENGER OXYGEN SYSTEM CHECK (Ref. Chapter 35-21-00).						RE		Scheduled Inspections	≈24-Jun-2024
	35 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H350003		OXYGEN VALVE - Refer to PASSENGER OXYGEN CONTROL VALVE O-RING REPLACEMENT (Ref. Chapter 35-21-00).						RE		Scheduled Special Inspections	
	35 A/F					Yrs	16-Aug-2023	4		16-Aug-2027	3.9 Years
						Hrs	15050:38				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)				Ldg	11,028				
H350004		FORWARD FUSELAGE - OXYGEN SYSTEM / a. (RK-156 thru RK-389 with Kit 128-5600 Installed, RK-390 and After) - Inspect oxygen service door, hinge and latch for condition and proper operation. / b. Inspect green overboard discharge disk for presence and condition.						RE		Scheduled Inspections	
	35 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400		(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: RK-156 thru RK-389 with Kit 128-5600 Installed, RK-390 and After)				Ldg	10,886				
H350005		PILOT'S COMPARTMENT - PILOT'S AND COPILOT'S OXYGEN SYSTEM - Perform FLIGHT CREW MASK - INSPECTION/CHECK (Ref. Chapter 35-11-00)						RE		Scheduled Inspections	
	35 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H350006		PILOT'S COMPARTMENT - PROTECTIVE BREATHING EQUIPMENT (PBE) P/N 802300-XX (If Installed) - Inspect in accordance with AVOX SYSTEMS Instruction 89253.01 (Ref. Chapter 35 in the Component Maintenance Manual, P/N 128-590001-81 or subsequent).						RE		Scheduled Inspections	
	35 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H350007		CABIN SECTION - PORTABLE OXYGEN & MASK (If Installed) - Inspect for condition and operating pressure.						RE (N/A)		Scheduled Inspections	
	35 A/F					Mos					
						Hrs					
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg					
H350008		CABIN SECTION - PASSENGER OXYGEN SYSTEM - Inspect each passenger oxygen mask assembly and supply tubing for condition and deterioration of its elastomeric and vinyl components.						RE		Scheduled Inspections	≈24-Jun-2024
	35 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H350009		FORWARD FUSELAGE - OXYGEN SYSTEM - Detail inspect oxygen cylinder, regulator, and plumbing for condition.						RE		Scheduled Inspections	≈24-Jun-2024
	35 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H350010		CREW OXYGEN MASK (BE AEROSPACE, SWEEP-ON 2000) - Perform overhaul six years from date of manufacture or last overhaul.						RE		Scheduled Special Inspections	
	35 A/F	Copilot				Yrs	22-Nov-2021	6		08-Jan-2027	3.3 Years
	174252-92					Hrs	14493:42				
	17320					Ldg	10,674				
		Overhaul Date 08-Jan-2021									
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									
H350010		CREW OXYGEN MASK (BE AEROSPACE, SWEEP-ON 2000) - Perform overhaul six years from date of manufacture or last overhaul.						RE		Scheduled Special Inspections	
	35 A/F	Pilot				Yrs	21-Jun-2021	6		21-Jun-2027	3.7 Years
	174252-92					Hrs	14128:53				
	13892					Ldg	10,451				
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)									

Task No		Description							Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.1					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.10					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.11					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.12					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.2					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.3					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.4					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.5					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.6					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											
H350011		PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE	Scheduled Special Inspections		
	35 A/F	No.7					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
	174080-26						Hrs	13253:42			
	Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H350011	PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE		Scheduled Special Inspections	
 35 A/F	No.8					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
174080-26						Hrs	13253:42			
Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H350011	PASSENGER OXYGEN MASK (BE AEROSPACE, P/N 174080 and 174095) - Overhaul or replace.						RE		Scheduled Special Inspections	
 35 A/F	No.9					Yrs	27-Mar-2020	8	[27-Oct-2027]	4.1 Years
174080-26						Hrs	13253:42			
Unknown						Ldg	9,929			
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
H350013	OXYGEN CYLINDER REGULATOR (P/N 172400) - Overhaul during oxygen cylinder hydrostatic inspection, but no later than six years from date of manufacturer or last overhaul.						RE		Scheduled Special Inspections	
 35 A/F						Yrs	15-Aug-2021	6	10-Aug-2027	3.9 Years
172400						Hrs	14294:02			
N/A						Ldg	10,545			
Overhaul Date 10-Aug-2021										
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)										
▼ 36 - PNEUMATIC										
043601	Bleed Air Supply Tube Assembly - Inspection						RE		AWL - Inspection Limitations	≈21-Dec-2023
 36 A/F	Left					Mos	11-Nov-2022			
Unknown						Hrs	14814:28	400	+20	15214:28 163:50 Hrs (+20)
Unknown						Ldg	10,886			
(AVG MAN HRS: 1.5) (SOURCE: Maintenance Manual 040002) (NOTE: Airplanes with less than 1,000 hours or have not complied with 1,000 hour inspection))										
043601	Bleed Air Supply Tube Assembly - Inspection						RE		AWL - Inspection Limitations	≈21-Dec-2023
 36 A/F	Right					Mos	11-Nov-2022			
Unknown						Hrs	14814:28	400	+20	15214:28 163:50 Hrs (+20)
Unknown						Ldg	10,886			
(SOURCE: Maintenance Manual 040002) (NOTE: Airplanes with less than 1,000 hours or have not complied with 1,000 hour inspection))										
2001-03-06	Bleed Air Supply Tube Assembly						RE		Mandatory	≈21-Dec-2023
 36 A/F						Mos	11-Nov-2022			
Complied With						Hrs	14814:28	400	+20	15214:28 163:50 Hrs (+20)
(AVG MAN HRS: 1.5)										
						Ldg	10,886			
360000-0101	Bleed Air Supply Tube Assembly						RE (O/C)			
 36 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
360000-0102	Bleed Air Supply Tube Assembly						RE (O/C)			
 36 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
360000-0201	De-ice Shut Off Valve						RE (O/C)			
 36 A/F	Left					Mos	21-Feb-2017			
6104-00-1						Hrs	11177			
0011						Ldg	8,632			
360000-0202	De-ice Shut Off Valve						RE (O/C)			
 36 A/F	Right					Mos	21-Feb-2017			
6104-00-1						Hrs	11177			
0010						Ldg	8,632			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
360000-0301	Pressure Regulator									
36 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
360000-0401	Bleed Air Pressure Regulator									
36 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
360000-0402	Bleed Air Pressure Regulator									
36 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0101	Bleed Air Check Valve									
36 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0102	Bleed Air Check Valve									
36 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0201	Flow Increasing Valve									
36 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0301	Suction Pressure Ejector									
36 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0401	Door Seal Valve									
36 A/F						Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0501	Bleed Air Actuator Valve									
36 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
361000-0502	Bleed Air Actuator Valve									
36 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
36-2012-01	Nextant - Engine and Wiring Anti-Ice System Reliability Improvement									
36 A/F						Mos	29-Nov-2012		RE (-)	Mandatory
Eff: 10-May-2012 Complied	Found SB already accomplished					Hrs	7921			
With						Ldg	6,721			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H360001		ENGINE GROUND RUN AND OPERATIONAL CHECKS - BLEED AIR SYSTEM CHECK VALVES - Perform BLEED AIR SYSTEM CHECK VALVE OPERATIONAL CHECK (Ref. Chapter 21-10-00).						RE		Scheduled Inspections	≈24-Jun-2024
	36 A/F	05-20-03					Mos 11-Nov-2022				
							Hrs 14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03) (NOTE: NOTE: Observe all operating limitations in the Model 400A FAA Approved Airplane Flight Manual.)					Ldg 10,886				
▼ 39 - ELECTRICAL - ELECTRONIC PANELS AND MULTIPURPOSE COMPONENTS											
390000-0101		Remote Control Circuit Breaker						RE (O/C)			
	39 A/F						Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
391000-0101		Clock						RE (O/C)			
	39 A/F	Left					Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
391000-0102		Clock						RE (O/C)			
	39 A/F	Right					Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
393100-0101		Pressure (S088) Switch						RE (O/C)			
	39 A/F						Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
396000-0101		Panel Annunciator						RE (O/C)			
	39 A/F						Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
93-02-12		Left-Hand Interstage (LH ITT) Circuit Breaker Wiring						T (A/R)		Mandatory	
	39 A/F						Mos				
	Eff: 26-Mar-1993						Hrs				
							Ldg				
▼ 52 - DOORS											
520000-0101		Entrance Door Key						RE (O/C)			
	52 A/F						Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
520000-0201		Entrance Door						RE (O/C)			
	52 A/F						Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				
520000-0301		Escape Hatch						RE (O/C)			
	52 A/F						Mos 21-Nov-2000				
	Unknown						Hrs 0				
	Unknown						Ldg 0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
521000-0101		Entrance Door Assembly								RE (O/C)	
	52 A/F	Unknown Unknown					Mos				
							Hrs				
							Ldg				
522000-0102		Emergency Exit Door Assembly								RE (O/C)	
	52 A/F	Unknown Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
523000-0101		Baggage Door Lock Set								RE (O/C)	
	52 A/F	Unknown Unknown					Mos	21-Nov-2000			
							Hrs	0			
							Ldg	0			
52-NXT1-D6		LEFT- HAND POWER PLANT, PYLON AND NACELLE - OIL FILLER DOOR - Inspect door, hinge and latch for evidence of damage and proper operation.								RE	ICA
	52 A/F	05-20-11					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)					Ldg	10,886			
52-NXT1-E6		RIGHT- HAND POWER PLANT, PYLON AND NACELLE - OIL FILLER DOOR - Inspect door, hinge and latch for evidence of damage and proper operation.								RE	ICA
	52 A/F	05-20-11					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)					Ldg	10,886			
93-16-12		Emergency Door Frame Support								T (A/R)	Mandatory
	52 A/F	Eff: 13-Oct-1993					Mos				
							Hrs				
							Ldg				
H520002		FORWARD FUSELAGE - AVIONICS ACCESS DOORS - Inspect doors and seals for condition.								RE	Scheduled Inspections
	52 A/F	05-20-03					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886			
H520003		FORWARD FUSELAGE - LANDING LIGHT AND DOORS - Inspect door, hinge and light assembly for condition.								RE	Scheduled Inspections
	52 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Ldg	10,886			
H520004		LANDING GEAR AND BRAKES - NOSE LANDING GEAR DOORS / a. Inspect doors and hinges for condition. / b. Inspect the uplock hook emergency release cable and linkage for condition and routing (Ref. Figure 601, Detail A and C).								RE	Scheduled Inspections
	52 A/F	05-20-02					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)					Ldg	10,886			
H520005		LANDING GEAR AND BRAKES - NOSE LANDING GEAR DOORS - Detail inspect door linkage installation for condition, seized bearings and sufficient engagement of rod ends								RE	Scheduled Inspections
	52 A/F	05-20-03					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886			
H520006		AFT FUSELAGE - BAGGAGE DOORS - Inspect baggage door seals for condition.								RE	Scheduled Inspections
	52 A/F	05-20-03					Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)					Ldg	10,886			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H520007		AFT FUSELAGE - FUEL TANK FILLER RECEPTACLE AND DOOR / a. Inspect fuel cap, fuel cap lanyard and fuel cap adapter for condition. / b. Inspect fuel cap latching mechanism for proper operation.						RE		Scheduled Inspections	
	52 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H520008		CABIN SECTION - DOOR WARNING SYSTEM - Perform DOOR WARNING SYSTEM CHECK (Ref. Chapter 52-70-00).						RE		Scheduled Inspections	≈24-Jun-2024
	52 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H520009		CABIN SECTION - ENTRANCE DOOR LATCH AND LOCK MECHANISM - Inspect operation of entrance door latch mechanism and ensure proper function of lock mechanism (Ref. Figure 601).						RE		Scheduled Inspections	≈24-Jun-2024
	52 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H520010		CABIN SECTION - EMERGENCY EXIT LATCH AND LOCK MECHANISM - Inspect operation of emergency exit door latch mechanism and ensure proper function of lock mechanism.						RE		Scheduled Inspections	≈24-Jun-2024
	52 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H520011		AFT FUSELAGE - EXTERNAL POWER RECEPTACLE / a. Inspect for security, corrosion and evidence of overheating. Disassemble and clean if corrosion is noted. / b. Inspect main junction electrical components for condition and evidence of overheating.						RE		Scheduled Inspections	≈24-Jun-2024
	52 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H520014		CABIN SECTION - EMERGENCY EXIT DOOR (Emergency exit door removed) / a. Detail inspect emergency exit door seal for condition and deterioration. / b. Detail inspect emergency exit door latching mechanism and lock for condition. / c. Detail inspect the perimeter of emergency exit door (including attaching frames, intercostals, gussets, and skin) for cracks, loose or missing fasteners and any indication of structural damage (Ref. Figure 604). / d. Detail inspect the perimeter of fuselage emergency exit opening (including attaching frames, intercostals, gussets, and skin) for cracks, loose or missing fasteners and any indication of structural damage (Ref. Figure 605). / e. Detail inspect the fuselage emergency exit frame reinforcement clips for condition (Ref. Figure 605). / f. Detail inspect the emergency exit door inner skin and skin splices for condition.						RE		Scheduled Inspections	≈10-Jul-2024
	52 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H520015		CABIN SECTION - MAIN ENTRANCE DOOR / a. Detail inspect main entrance door latching mechanism and lock for condition, security and wear (Ref. Figure 606). / b. Inspect door lock switches and wiring for condition. / c. Inspect travel of entrance door lock switches. Refer to ENTRANCE DOOR LOCK SWITCHES ADJUSTMENT, Chapter 52-10-00.						RE		Scheduled Inspections	≈10-Jul-2024
	52 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H520017		SCHEDULED D INSPECTIONS - ENTRANCE DOOR - (Window installation, door frames, fittings, bolts, door mechanism and handle cases) - Perform detailed inspection for cracks, loose or missing fasteners and any indication of structural damage (Ref. Figure 609).						RE		Scheduled Inspections	≈29-Jul-2026
	52 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H520018		SCHEDULED D INSPECTIONS - ENTRANCE DOOR LAND AND SUPPORTING FRAMES, LATCH PIN RECEPTACLES AND DOOR LAND GUIDES - Perform detailed inspection for cracks, loose or missing fasteners and any indication of structural damage. Inspect latch pin receptacles for cracks and structural damage (Ref. Figure 609).						RE		Scheduled Inspections	≈29-Jul-2026
	52 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H520019	ENTRANCE DOOR STEP ASSEMBLY (RK-1 thru RK-558 with Kit 128-4045 Installed, RK-559 and After) / a. Detail inspect the cabin step assembly for cracks, loose or failed fasteners, any indication of structural damage, condition, and proper operation. / b. Check torque of the lower step forward and aft attachment nuts (Ref. Chapter 20-10-05). / c. Inspect both the upper and lower rod link assemblies for cracks, distortion, and condition. / d. Check the latch sleeve and bolt rotate freely.						RE		Scheduled Special Inspections	≈21-Dec-2023
52 A/F	05-20-01				Mos	06-Apr-2023				
	(Tol. Adjustment: -36.2 Hrs) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: RK-1 thru RK-558 with Kit 128-4045 Installed, RK-559 and After)				Hrs	15050:38	200	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	11,028				
H520032	CABIN SECTION - MOISTURE DRAIN HOLES AND VALVES / a. Inspect drain holes for obstruction. / b. Inspect drain holes for condition.						RE		Scheduled Inspections	≈10-Jul-2024
52 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H520105	LANDING GEAR AND BRAKES - LEFT MAIN LANDING GEAR DOORS / a. Inspect doors and hinges for condition. / b. Inspect the uplock hook emergency release cable and linkage for condition and routing (Ref. Figure 601, Detail A and C).						RE		Scheduled Inspections	
52 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				
H520113	LANDING GEAR AND BRAKES - LEFT MAIN LANDING GEAR DOOR BEAMS AND FITTINGS - Detail inspect the beams and fittings for cracks, loose or missing fasteners and evidence of damage.						RE		Scheduled Inspections	≈10-Jul-2024
52 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H520205	LANDING GEAR AND BRAKES - RIGHT MAIN LANDING GEAR DOORS / a. Inspect doors and hinges for condition. / b. Inspect the uplock hook emergency release cable and linkage for condition and routing (Ref. Figure 601, Detail A and C).						RE		Scheduled Inspections	
52 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				
H520213	LANDING GEAR AND BRAKES - RIGHT MAIN LANDING GEAR DOOR BEAMS AND FITTINGS - Detail inspect the beams and fittings for cracks, loose or missing fasteners and evidence of damage.						RE		Scheduled Inspections	≈10-Jul-2024
52 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
▼ 53 - FUSELAGE										
045304	Aft Fuselage Baggage Compartment Velcro (Hook Only) - Inspect						RE		AWL - Inspection Limitations	≈21-Dec-2023
53 A/F	Aft				Mos	11-Nov-2022				
N/A					Hrs	14814:28	400	+40	15214:28	163:50 Hrs (+40)
N/A					Ldg	10,886				
	(SOURCE: Maintenance Manual 040002)									
530000-0101	Bullet Cover Assembly						RE (O/C)			
53 A/F					Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
530000-0201	Forward Fuselage Upper Assembly						RE (O/C)			
53 A/F					Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
530000-0301	Forward Fuselage Lower Assembly						RE (O/C)			
53 A/F					Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
530000-0401	Bulkhead Assembly						RE (O/C)			
53 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530000-0501	Fuselage Assembly						RE (O/C)			
53 A/F	Fwd					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530000-0502	Fuselage Assembly						RE (O/C)			
53 A/F	Aft					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530000-0601	Bay A Keel Assembly						RE (O/C)			
53 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530000-0701	Floor Support						RE (O/C)			
53 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530000-0801	Mid Upper Fuselage						RE (O/C)			
53 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530000-0901	Mid Lower Fuselage						RE (O/C)			
53 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
530100-0101	Nose Landing Gear Fitting Assembly						RE		AWL - Life Limit	≈05-Feb-2034
53 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs				
Unknown		0				Ldg	0	15,000	15,000	3,972 Ldg
MM:045301 (SOURCE: Maintenance Manual 040002)										
530100-0102	Nose Landing Gear Fitting Assembly						RE		AWL - Life Limit	≈05-Feb-2034
53 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs				
Unknown		0				Ldg	0	15,000	15,000	3,972 Ldg
MM:045301 (SOURCE: Maintenance Manual 040002)										
530200-0101	Main Landing Gear Fitting Assembly						RE		AWL - Life Limit	≈05-Feb-2034
53 A/F	Left					Mos	21-Nov-2000			
45A33506						Hrs				
Unknown		0				Ldg	0	15,000	15,000	3,972 Ldg
MM:045302 (SOURCE: Maintenance Manual 040002)										
530200-0102	Main Landing Gear Fitting Assembly						RE		AWL - Life Limit	≈05-Feb-2034
53 A/F	Right					Mos	21-Nov-2000			
45A33506						Hrs				
Unknown		0				Ldg	0	15,000	15,000	3,972 Ldg
MM:045302 (SOURCE: Maintenance Manual 040002)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
530300-0101		Aft Fuselage Baggage Compartment Velcro (Hook Only)						RE		AWL - Life Limit	≈06-May-2024
	53 A/F	Aft				Mos	09-Sep-2019				
	N/A		0			Hrs	12910:38	2,600	+20	15510:38	460 Hrs (+20)
	N/A					Ldg	9,709				
	MM:045303 (SOURCE: Maintenance Manual 040002)										
531000-0101		Nose Landing Gear Side Panel Support Assembly						RE (O/C)			
	53 A/F	Left				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
531000-0102		Nose Landing Gear Side Panel Support Assembly						RE (O/C)			
	53 A/F	Right				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
531000-0201		Lower Forward Fuselage						RE (O/C)			
	53 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
534000-0101		Main Landing Gear Uplock Fitting						RE (O/C)			
	53 A/F	Left				Mos	16-Dec-2014				
	128-430003	New				Hrs	9678				
	Unknown					Ldg	7,741				
534000-0102		Main Landing Gear Uplock Fitting						RE (O/C)			
	53 A/F	Right				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
535000-0101		Radome						RE (O/C)			
	53 A/F					Mos	16-Oct-2018				
	128-410000-003	New				Hrs	12346				
	NRD-0003					Ldg	9,353				
53-NXT1-B1		SECTION CABIN - AFT PRESSURE BULKHEAD CONNECTOR DOUBLERS - Inspect the two upper and one lower installed connector feed through doublers for security, loose or missing fasteners, and overall general condition.						RE		ICA	≈10-Jul-2024
	53 A/F	05-20-13				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)										
53-PL21-AWL1		Bulkhead Penetration - Perform HFEC Inspection						RE		AWL - ICA	≈12-Jul-2026
	53 A/F					Mos	11-Nov-2022				
						Hrs	14814:28	2,400		17214:28	2163:50 Hrs
	Ref:373-00-0002 (SOURCE: FAA STC ST10959SC)										
53-PL21-AWL2		VHF Antenna - Perform HFEC Inspection						T		AWL - ICA	≈18-Jul-2033
	53 A/F					Mos					
						Hrs	7691	15,000		22691	7640:22 Hrs
	Ref:373-00-0002 (SOURCE: FAA STC ST10959SC)										
53-PL21-B1		SECTION CABIN - AFT EQUIPMENT SHELF - Inspect for security of attachment, installation and general condition, inspect Z brackets that attach the shelf to the AFT Pressure Bulkhead for security of attachment, loose fasteners, and general condition.						RE		ICA	≈10-Jul-2024
	53 A/F	05-20-16				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
53-PL21-B2	SECTION CABIN - AFT SHELF MOUNTED EQUIPMENT - Inspect DCU's, Ground blocks, Maintenance switch panel, and Fuel Quantity Interface Adapter for security of attachment, loose or missing fasteners, cable routing, chafing, and general overall condition.						RE		ICA	≈24-Jun-2024
 53 A/F	05-20-15				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)				Ldg	10,886				
53-PL21-C1	TCAS/TRANSPONDER/GPS 2/XM ANTENNA INSPECTIONS - (TCAS - Directional antenna upper fuselage FS 150, L-Band antenna lower fuselage FS 124) (Transponder - Two Lband Antennas upper fuselage FS 190) (GPS 2/XM - Upper fuselage FS 177) - Inspect antenna exterior condition and security.						RE		ICA	
 53 A/F	05-20-14				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)				Ldg	10,886				
53-PL21-C2	TCAS/TRANSPONDER/GPS 2/XM ANTENNA INSPECTIONS - (TCAS - Directional antenna upper fuselage FS 150, L-Band antenna lower fuselage FS 124) (Transponder - Two Lband Antennas upper fuselage FS 190) (GPS 2/XM - Upper fuselage FS 177) - Check Fuselage skin for cracks, indentations, and loose or missing rivets around the above antennas.						RE		ICA	≈10-Jul-2024
 53 A/F	05-20-16				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)				Ldg	10,401				
53-PL21-C3	TCAS/TRANSPONDER/GPS 2/XM ANTENNA INSPECTIONS - (TCAS - Directional antenna upper fuselage FS 150, L-Band antenna lower fuselage FS 124) (Transponder - Two Lband Antennas upper fuselage FS 190) (GPS 2/XM - Upper fuselage FS 177) - Inspect antenna interior mounting and aircraft structure for condition and security.						RE		ICA	≈10-Jul-2024
 53 A/F	05-20-16				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)				Ldg	10,401				
53-PL21-F1	FORWARD PRESSURE BULKHEAD FEED-THRU PLATE INSPECTIONS - Inspect upper right hand forward pressure bulkhead plate (Hawker Beechjet 400A Maintenance Manual) for cracks, failed fasteners, corrosion and evidence of structural damage.						RE		ICA	≈10-Jul-2024
 53 A/F	05-20-16				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:373-00-0002 Ch.05 (SOURCE: FAA STC ST10959SC)				Ldg	10,401				
53-STC-05	Cabin Configuration Installations - Forward Bulkhead Feedthrough - Connector Hole Inspection						RE		AWL, STC, Interior Cabin Configuration Installation	≈30-Sep-2027
 53 A/F					Mos	23-Apr-2020				
	(SOURCE: FAA STC ST01572WI)				Hrs	13258:28				
					Ldg	9,933	2,627		12,560	1,532 Ldg
53-STC-06	Cabin Configuration Installations - Forward Bulkhead Feedthrough - Fastener Hole Inspection						RE		AWL, STC, Interior Cabin Configuration Installation	≈20-Dec-2045
 53 A/F					Mos	31-Oct-2019				
	(SOURCE: FAA STC ST01572WI)				Hrs	13005:36				
					Ldg	9,767	9,796		19,563	8,535 Ldg
AFI-112	Cabin Configuration Installations - Visually Inspect forward pressure bulkhead feedthrough for cracks.						RE	STC, Interior Cabin Configuration Installation		≈10-Jul-2024
 53 A/F	05-20-08				Mos	12-May-2021				
	(SOURCE: FAA STC ST01572WI)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
AFI-113	Cabin Configuration Installations - Visually inspect relocated equipment for security and visible damage.						RE	STC, Interior Cabin Configuration Installation		≈24-Jun-2024
 53 A/F	05-20-07				Mos	11-Nov-2022				
	(SOURCE: FAA STC ST01572WI)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H530001	FORWARD FUSELAGE - FUSELAGE MOISTURE DRAIN HOLE - Inspect drain holes for obstruction.						RE	Scheduled Inspections		≈24-Jun-2024
 53 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H530002	AFT FUSELAGE - DORSAL FIN AND VENTRAL FIN - (Exterior inspection only, panel removal not required) - Inspect fins for condition (Ref. Chapter 53-50-00).						RE		Scheduled Inspections	≈24-Jun-2024
53 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H530003	MIDFUSELAGE - WING/FUSELAGE FILLET (Exterior inspection only, fillet removal is not required) - Inspect for condition.						RE		Scheduled Inspections	≈24-Jun-2024
53 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H530005	AFT FUSELAGE - COMPRESSOR/CONDENSER INLET AND EXHAUST PORTS - Inspect inlet and exhaust ports for condition and obstruction.						RE		Scheduled Inspections	≈24-Jun-2024
53 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H530006	FORWARD FUSELAGE - RADOME AND lightning DIVERTER STRIPS / a. Inspect for condition. / b. Inspect radome erosion boot for condition, if installed.						RE		Scheduled Inspections	
53 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				
H530007	AFT FUSELAGE - AFT FUSELAGE BAGGAGE PANELS / a. Inspect baggage compartment composite panels for condition and oil or grease contamination. / b. Inspect baggage compartment panels and supporting frame structure velcro fastener material for condition.						RE		Scheduled Inspections	≈24-Jun-2024
53 A/F	05-20-03				Mos	11-Nov-2022				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
					Ldg	10,886				
H530010	PILOT'S COMPARTMENT - FLOOR PANELS / a. Inspect for corrosion and structural damage. / b. Detail inspect floor support assembly for corrosion and structural damage (Ref. Figure 601).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H530011	CABIN SECTION - FUSELAGE INNER SKIN AND SPLICE - Detail inspect fuselage inner skin and skin splice for condition (Ref. Figure 607).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H530012	CABIN SECTION - AFT PRESSURE BULKHEAD / a. Detail inspect cabin side of aft pressure bulkhead structure for cracks, loose or missing fasteners, corrosion and evidence of structural damage (Ref. Figure 608). / b. Detail inspect aft pressure bulkhead check valves [F.S. 322.4 (8190)] for condition, obstruction and freedom of movement (Ref. Figure 609).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H530013	PILOT'S COMPARTMENT - MOISTURE DRAIN HOLES AND VALVES / a. Inspect drain holes for obstruction. / b. Inspect drain valves for condition.						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H530014	FORWARD FUSELAGE - FORWARD PRESSURE BULKHEAD / a. Detail inspect forward pressure bulkhead and center windshield post attachment for cracks, loose or missing fasteners, corrosion and evidence of structural damage (Ref. Figure 611). / b. Detail inspect nose landing gear wheel well stringers located in the upper corners for cracks (Ref. Figure 612).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
					Ldg	10,401				
H530015	FORWARD FUSELAGE - FUSELAGE SKIN AND ACCESS DOORS (Exterior inspection only, panel removal is not required) - Inspect for condition.						RE		Scheduled Inspections	
53 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
					Ldg	10,886				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H530016	MIDFUSELAGE - FRAME REINFORCEMENT CLIPS (45A33273), FS 279.4 (7096) - Detail inspect for cracks and any indication of structural damage (Ref. Figure 613).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530017	MIDFUSELAGE - EMERGENCY GEAR DOWN BRACKET ASSEMBLY ATTACH CLIP, FS 279.4 (7096) - Detail inspect for cracks and any indication of structural damage (Ref. Figure 614).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530018	MIDFUSELAGE - KEEL STRUCTURE - Inspect keel for cracks, loose or missing fasteners and evidence of structural damage (Ref. Figure 615).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530019	MIDFUSELAGE - FUSELAGE SKIN - Detail inspect for cracks, loose or missing fasteners and indications of structural damage, especially around entrance door and escape hatch corners.						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530020	MIDFUSELAGE - LOWER FRAME AND SPLICE, FS 307.2 (7803) - Detail inspect for cracks and any indication of structural damage (Ref. Figure 616).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530021	AFT FUSELAGE - FUSELAGE SKIN, ACCESS DOORS AND FAIRINGS (Exterior inspection only, panel removal is not required) / a. Inspect for condition. / b. Inspect doors, hinges and latches for condition and proper operation.						RE		Scheduled Inspections	
53 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H530022	AFT FUSELAGE - FORWARD ENGINE CARRY-THROUGH BEAM - Using a borescope, detail inspect the yoke/carry-through beam joints for cracks, loose or missing fasteners (Ref. Figure 623).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530023	VERTICAL STABILIZER - FAIRING OF VERTICAL STABILIZER-TO-FUSELAGE - Inspect for cracks, loose or missing fasteners and any indication of structural damage.						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530024	VERTICAL STABILIZER - VERTICAL STABILIZER FRONT SPAR ATTACHMENT AND FRAME - Using a 10x magnifying glass, detail inspect for cracks (especially at attaching points, doubler and stringer cutout through frame), loose or missing fasteners and any indication of structural damage. Pay particular attention to cracks emitting from fastener holes (Ref. Figure 624).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530025	VERTICAL STABILIZER - VERTICAL STABILIZER REAR SPAR ATTACHMENT AND FRAME - Using a 10x magnifying glass, detail inspect for cracks (especially at attaching points and doubler), loose or missing fasteners and any indication of structural damage. Pay particular attention to cracks emitting from fastener holes (Ref. Figure 624).						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
H530026	SCHEDULED D INSPECTIONS - LOWER FITTING OF WINDSHIELD CENTER POST - Perform detailed inspection for cracks, loose or missing fasteners and any indication of structural damage (Ref. Figure 601).						RE		Scheduled Inspections	≈29-Jul-2026
53 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H530027	SCHEDULED D INSPECTIONS - FRAME AND INTERCOSTALS BEHIND INNER SKIN - Perform detailed inspection for cracks, loose or missing fasteners and any indication of structural damage (Ref. Model 400/400A Structural Repair Manual, Chapter 53-10-47B).						RE		Scheduled Inspections	≈29-Jul-2026
53 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H530028	SCHEDULED D INSPECTIONS - CABIN FRAMES AND STRINGERS - Perform detailed inspection for leaks, loose or missing fasteners and any indication of structural damage.						RE		Scheduled Inspections	≈29-Jul-2026
53 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H530029	CABIN SECTION - FLOOR PANELS - Detail inspect for corrosion and structural damage.						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H530030	SCHEDULED D INSPECTIONS - ELEVATOR CONTROL-COLUMN-SUPPORT BOX (LH & RH) - Detail inspect for cracks in the stringers (P/N 45A61176) located under the support bracket. Inspect all four corners.						RE		Scheduled Inspections	≈29-Jul-2026
53 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H530031	SCHEDULED D INSPECTIONS - AFT FUSELAGE BAGGAGE COMPARTMENT - Perform detailed inspection of compartment structure for cracks, corrosion and structural damage.						RE		Scheduled Inspections	≈29-Jul-2026
53 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H530033	FORWARD FUSELAGE - RVSM REGION - Perform RVSM REGION INSPECTION to verify the area is free from damage, deterioration or repair.						RE		Scheduled Inspections	≈24-Jun-2024
53 A/F	05-20-03				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H530034	AFT FUSELAGE - FUSELAGE SKIN - Detail inspect for cracks, loose or missing fasteners and indication of structural damage.						RE		Scheduled Inspections	≈10-Jul-2024
53 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H531095	MAIN LANDING GEAR FITTING ASSEMBLY (P/N 45A33506) INSPECTION (RK-1 THRU RK-352) - Perform a detail visual inspection and a borescope inspection. Refer to the MAIN LANDING GEAR FITTINGS - INSPECTION/CHECK, Chapter 53-40-00.						RE (N/A)		Scheduled Special Inspections	
53 A/F	Left				Mos	07-Jun-2011				
128-430003					Hrs	7691				
Unknown					Ldg	6,553				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: NOTE Replacement of NAS1203 and NAS1204 bolts with HL21PB Hi-Lok bolts in the Main Landing Gear Fitting Assembly is terminating action for the 200 hour subsequent interval. Refer to Chapter 53-40-00, Figure 601, Detail C, Bolts A and B.)									
H531095	MAIN LANDING GEAR FITTING ASSEMBLY (P/N 45A33506) INSPECTION (RK-1 THRU RK-352) - Perform a detail visual inspection and a borescope inspection. Refer to the MAIN LANDING GEAR FITTINGS - INSPECTION/CHECK, Chapter 53-40-00.						RE (N/A)		Scheduled Special Inspections	
53 A/F	Right				Mos	07-Jun-2011				
Unknown					Hrs	7691				
Unknown					Ldg	6,553				
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: NOTE Replacement of NAS1203 and NAS1204 bolts with HL21PB Hi-Lok bolts in the Main Landing Gear Fitting Assembly is terminating action for the 200 hour subsequent interval. Refer to Chapter 53-40-00, Figure 601, Detail C, Bolts A and B.)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H531096		MID FUSELAGE MAIN LANDING GEAR UPLOCK FITTING (P/N 45A33480) INSPECTION (RK-1 THRU RK-604) - Perform a detail visual inspection and a borescope inspection. Refer to the MAIN LANDING GEAR FITTINGS - INSPECTION/CHECK, Chapter 53-40-00.						RE (N/A)		Scheduled Special Inspections	
	53 A/F										
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01) (NOTE: NOTE Replacement of the Mid Fuselage Main Landing Gear Uplock Fitting P/N 45A33480 with P/N 128-430003 is terminating action for the 200 hour subsequent interval.)									
H532001		AFT FUSELAGE - TAIL CONE - Inspect tail cone and anti-collision light for condition.						RE		Scheduled Inspections	
	53 A/F	05-20-02						12		(30-Nov-2023)	57 Days
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)						14814:28	400	+40	163:50 Hrs (+40)
								10,886			
▼ 54 - NACELLES/PYLONS											
2007-19-05		Engine cowlings panels						T (A/R)		Mandatory	
	54 A/F										
	Eff: 23-Oct-2007										
2011-03-12		Left and Right Pylon Firewall Structure Firewall Sealant Inspection						T (A/R)		Mandatory	
	54 A/F										
	Eff: 14-Mar-2011										
54-2013-08 Rev B		Nextant - Pylon Drain Holes Missing						RE (-)		Mandatory	
	54 A/F										
	Eff: 17-May-2013 Not Applicable	N/A by S/N						13-May-2013			
54-NXT1-D1		LEFT- HAND POWER PLANT, PYLON AND NACELLE - PYLON SKIN - Inspect for cracks or loose or failed fasteners.						RE		ICA	≈24-Jun-2024
	54 A/F	05-20-12									
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
54-NXT1-D2		LEFT- HAND POWER PLANT, PYLON AND NACELLE - NACELLE - Inspect the upper, lower and inboard cowlings for damaged fasteners and receptacles. Ensure all ¼-turn fasteners are present and secured. Inspect fastener holes for cracks and elongation.						RE		ICA	
	54 A/F	05-20-11									
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
54-NXT1-D3		LEFT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE INLET - Inspect for loose or failed fasteners, attachment and condition.						RE		ICA	
	54 A/F	05-20-11									
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
54-NXT1-D5		LEFT- HAND POWER PLANT, PYLON AND NACELLE - Perform UNPAINTED SURFACE INSPECTION.						RE		ICA	
	54 A/F	05-20-11									
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
54-NXT1-D7		LEFT- HAND POWER PLANT, PYLON AND NACELLE - PYLON NACELLE SEAL Inspect seal for deterioration, tears and missing sections.						RE		ICA	≈10-Jul-2024
	54 A/F	05-20-13									
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									
54-NXT1-D8		LEFT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE/PYLON FIREWALL - inspect for damage, deteriorated firewall sealant and corrosion.						RE		ICA	≈10-Jul-2024
	54 A/F	05-20-13									
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
54-NXT1-D9	LEFT- HAND POWER PLANT, PYLON AND NACELLE - Inspect Rib Extensions for damage security loose or failed fasteners, attachment and condition.						RE		ICA	≈10-Jul-2024
 54 A/F	05-20-13				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,401				
54-NXT1-E1	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - PYLON SKIN - Inspect for cracks or loose or failed fasteners.						RE		ICA	≈24-Jun-2024
 54 A/F	05-20-12				Mos	11-Nov-2022				
					Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,886				
54-NXT1-E2	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - NACELLE - Inspect the upper, lower and inboard cowlings for damaged fasteners and receptacles. Ensure all ¼-turn fasteners are present and secured. Inspect fastener holes for cracks and elongation.						RE		ICA	
 54 A/F	05-20-11				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,886				
54-NXT1-E3	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE INLET - Inspect for loose or failed fasteners, attachment and condition.						RE		ICA	
 54 A/F	05-20-11				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,886				
54-NXT1-E5	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - Perform UNPAINTED SURFACE INSPECTION.						RE		ICA	
 54 A/F	05-20-11				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
					Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,886				
54-NXT1-E7	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - PYLON NACELLE SEAL Inspect seal for deterioration, tears and missing sections.						RE		ICA	≈10-Jul-2024
 54 A/F	05-20-13				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,401				
54-NXT1-E8	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE/PYLON FIREWALL - inspect for damage, deteriorated firewall sealant and corrosion.						RE		ICA	≈10-Jul-2024
 54 A/F	05-20-13				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,401				
54-NXT1-E9	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - Inspect Rib Extensions for damage security loose or failed fasteners, attachment and condition.						RE		ICA	≈10-Jul-2024
 54 A/F	05-20-13				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,401				
H540007	SCHEDULED D INSPECTIONS - FORWARD AND AFT ENGINE CARRY-THROUGH - Remove the firewall blanket, and perform detailed inspection for cracks, loose or missing fasteners and evidence of structural damage through existing access holes. If engine is not removed, borescope inspection is required (Ref. Figure 603).						RE		Scheduled Inspections	≈29-Jul-2026
 54 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H540008	SCHEDULED D INSPECTIONS - FRAME AND PYLON RIB - Perform detailed inspection for cracks, loose or missing fasteners and indications of structural damage (Ref. Figure 604).						RE		Scheduled Inspections	≈29-Jul-2026
 54 A/F	05-20-05				Mos	12-May-2021				
					Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
TA-1-1	LH - Engine Air Intake						RE (O/C)			
 54 A/F	Left				Mos					
	N541000-003				Hrs					
	R0010HLG				Ldg					
	(NOTE: MFG DATE: 02/20 REV: H)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
TA-1-2		RH - Engine Air Intake						RE (O/C)			
	54 A/F N541000-002 Unknown	Right									
TA-2-1		LH - FWD Lower Cowling						RE (O/C)			
	54 A/F N540000-001 RK-413	Left Lower Fwd									
TA-2-2		RH - FWD Lower Cowling						RE (O/C)			
	54 A/F N540000-001 RK-413	Right Lower Fwd									
TA-3-1		LH - Upper Cowling						RE (O/C)			
	54 A/F N542000-001 RK-413	Left Upper									
TA-3-2		RH - Upper Cowling						RE (O/C)			
	54 A/F N542000-001 RK-413	Right Upper									
TA-4-1		LH - Lower inboard Cowling						RE (O/C)			
	54 A/F N544000-001 RK-413	Left Lower Inboard									
TA-4-2		RH - Lower inboard Cowling						RE (O/C)			
	54 A/F N544000-001 RK-413	Right Lower Inboard									
TA-5-1		LH - Upper inboard cowling						RE (O/C)			
	54 A/F N544000-003 RK-413	Left Upper Inboard									
TA-5-2		RH - Upper inboard cowling						RE (O/C)			
	54 A/F N544000-003 RK-413	Right Upper Inboard									
TA-6-1		LH - Aft lower Cowling						RE (O/C)			
	54 A/F N543000-001 RK-413	Left Lower Aft									
TA-6-2		RH - Aft lower Cowling						RE (O/C)			
	54 A/F N543000-001 RK-413	Right Lower Aft									

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
TA-7-1		LH - Engine Exhaust						RE (O/C)			
	54 A/F	Left				Mos					
	N780000-001					Hrs					
	RK-413					Ldg					
TA-7-2		RH - Engine Exhaust						RE (O/C)			
	54 A/F	Right				Mos					
	N780000-001					Hrs					
	RK-413					Ldg					
▼ 55 - STABILIZERS											
045502		Horizontal Stabilizer - Pitch Trim Actuator - Replace with an airwothy unit						RE		AWL - Life Limit	≈08-Oct-2023
	55 A/F					Mos	23-Apr-2020				
	45AS61023-143 OVH					Hrs	13258:28	1,800		15058:28	07:50 Hrs
	ET0496					Ldg	9,933				
	(SOURCE: Maintenance Manual 040002)										
045505		Horizontal Stabilizer - Rib Assembly - Radiographic or Borescope Inspection						RE		AWL - Inspection Limitations	≈14-Apr-2026
	55 A/F					Mos	25-May-2022				
	Unknown					Hrs	14622:44	2,400		17022:44	1972:06 Hrs
	Unknown					Ldg	10,755				
	(SOURCE: Maintenance Manual 040002)										
2014-15-15		Horizontal Stabilizer Rib Assemblies						RE		Mandatory	≈14-Apr-2026
	55 A/F					Mos	25-May-2022				
	Eff: 05-Sep-2014 Complied With					Hrs	14622:44	2,400		17022:44	1972:06 Hrs
	(NOTE: Before the accumulation of 7,400 total flight hours or within 6 months after the effective date of this AD, whichever occurs later, perform a radiographic (x-ray) inspection or a borescope inspection for cracking of the horizontal stabilizer rib assemblies)										
550000-0101		Horizontal Stabilizer Assembly						RE (O/C)			
	55 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
550000-0201		Horizontal Stabilizer - Rib Assembly						RE (O/C)			
	55 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
550000-0301		Tip Rib Assembly						RE (O/C)			
	55 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
550000-0401		Leading Edge Assembly						RE (O/C)			
	55 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
550000-0501		Cover Assembly						RE (O/C)			
	55 A/F					Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
550000-0601	Front Spar Assembly								RE (O/C)	
55 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
550000-0701	Stabilizer Assy-Empennage Vertical								RE (O/C)	
55 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
550000-0801	Trim Tab Assembly								RE (O/C)	
55 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
550100-0101	Horizontal Stabilizer - Elevator Hinge Assembly								RE	AWL - Life Limit ≈03-Mar-2033
55 A/F	Left Outboard					Mos	21-Nov-2000			
45A21188		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045501 (SOURCE: Maintenance Manual 040002)										
550100-0102	Horizontal Stabilizer - Elevator Hinge Assembly								RE	AWL - Life Limit ≈03-Mar-2033
55 A/F	Left Inboard					Mos	21-Nov-2000			
45A21187		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045501 (SOURCE: Maintenance Manual 040002)										
550100-0103	Horizontal Stabilizer - Elevator Hinge Assembly								RE	AWL - Life Limit ≈03-Mar-2033
55 A/F	Right Inboard					Mos	21-Nov-2000			
45A21187		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045501 (SOURCE: Maintenance Manual 040002)										
550100-0104	Horizontal Stabilizer - Elevator Hinge Assembly								RE	AWL - Life Limit ≈03-Mar-2033
55 A/F	Right Outboard					Mos	21-Nov-2000			
45A21188		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045501 (SOURCE: Maintenance Manual 040002)										
550200-0101	Horizontal Stabilizer - Pitch Trim Actuator								RE	≈08-Oct-2023
55 A/F		0				Mos	23-Apr-2020			
45AS61023-143 OVH	Overhauled	0	0			Hrs	13258:28	1,800	15058:28	07:50 Hrs
ET0496		0	0			Ldg	9,933			
(UPDATE NOTE: Dual Release OHF: 24.05.2018)										
550300-0101	Vertical Stabilizer - Rudder Hinge Assembly								RE	AWL - Life Limit ≈03-Mar-2033
55 A/F	Upper					Mos	21-Nov-2000			
45A23205		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045503 (SOURCE: Maintenance Manual 040002)										
550300-0102	Vertical Stabilizer - Rudder Hinge Assembly								RE	AWL - Life Limit ≈03-Mar-2033
55 A/F	Lower					Mos	21-Nov-2000			
45A23204		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045503 (SOURCE: Maintenance Manual 040002)										

Task No	Description	Categories	Time
SEQ PN/SN	MOC Note or Component Condition	DUE	Remaining
552000-0101	Rudder Hinge Assembly		
55 A/F	No.1		
Unknown			
Unknown			
552000-0102	Rudder Hinge Assembly		
55 A/F	No.2		
Unknown			
Unknown			
552000-0201	Elevator Assembly		
55 A/F	Left		
Unknown			
Unknown			
552000-0202	Elevator Assembly		
55 A/F	Right		
Unknown			
Unknown			
55-2013-07	Nextant - Pitch Trim Actuator		
55 A/F			
Eff: 10-Apr-2013 Not Applicable	N/A by S/N		
554000-0101	Rudder Assembly		
55 A/F			
Unknown			
Unknown			
55-4071	Stabilizers - Improved Horizontal Stabilizer Ribs (Kit 128-6200)		
55 A/F			
Eff: 01-Mar-2012 Complied With	C/W iaw SB instructions		
55-4162	Stabilizers - Horizontal Stabilizer Pivot Fitting and Upper Rear Spar Inspection		
55 A/F			
Eff: 19-Jan-2017 Complied With	C/W iaw SB instructions		
(AVG MAN HRS: 18)			
H550001	VERTICAL STABILIZER - STABILIZER SKIN, LEADING EDGE AND ACCESS PANELS (Exterior inspection only, panel removal is not required) - Inspect skin for condition.	RE	Scheduled Inspections
55 A/F	05-20-02		
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)			
H550002	VERTICAL STABILIZER - RUDDER ASSEMBLY (Exterior inspection only, panel removal is not required) - Inspect skin and static wicks for condition and evidence of lightning strike.	RE	Scheduled Inspections
55 A/F	05-20-02		
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)			
H550003	VERTICAL STABILIZER - RUDDER HINGES AND BOLTS, TORQUE TUBE AND BELLCRANK, STOP BOLTS AND RUDDER COUNTER-BALANCE - Detail inspect for condition, seized bearings, freedom of movement and sufficient engagement of rod ends.	RE	Scheduled Inspections
55 A/F	05-20-03		
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H550004		HORIZONTAL STABILIZER - STABILIZER SKIN, LEADING EDGES AND ACCESS PANELS (Exterior inspection only, panel removal is not required) / a. Inspect for condition. / b. Perform the UNPAINTED SURFACE INSPECTION (Ref. Chapter 12-20-00).						RE		Scheduled Inspections	
	55 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H550005		HORIZONTAL STABILIZER - ELEVATOR ASSEMBLY (Exterior inspection only, panel removal is not required) - Inspect skin and static wicks for condition and evidence of lightning strike.						RE		Scheduled Inspections	
	55 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H550007		VERTICAL STABILIZER - VERTICAL STABILIZER SIDE RAILS AND ROLLER - (Ref. Chapter 55-30-00). / a. Perform SIDE RAIL INSPECTION. / b. Perform SIDE ROLLER BRACKET ASSEMBLY INSPECTION.						RE		Scheduled Inspections	≈24-Jun-2024
	55 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
H550008		HORIZONTAL STABILIZER - AFT PIVOT FITTING ASSEMBLY - Detail inspect for condition.						RE		Scheduled Inspections	≈10-Jul-2024
	55 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H550009		HORIZONTAL STABILIZER - FRONT AND REAR SPAR AND FITTINGS - Remove (4) inspection hole covers. Using a borescope inspect for cracks and loose or failed fasteners at the forward and aft spar locations (Ref. Figures 625 and Figure 626).						RE		Scheduled Inspections	≈10-Jul-2024
	55 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H550010		HORIZONTAL STABILIZER - ELEVATOR OPERATION - Perform complete ELEVATOR ADJUSTMENT/TEST procedure (Ref. Chapter 27-30-00).						RE		Scheduled Inspections	≈10-Jul-2024
	55 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H550011		SCHEDULED D INSPECTIONS - VERTICAL STABILIZER RIBS AND STRINGERS - Perform detailed inspection for cracks, loose or missing fasteners and any indications of structural damage.						RE		Scheduled Inspections	≈29-Jul-2026
	55 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H550012		SCHEDULED D INSPECTIONS - HORIZONTAL STABILIZER FRONT AND REAR SPAR FITTINGS / a. Perform a detailed inspection of the rear spar fitting lugs using Eddy current. Refer to the HORIZONTAL STABILIZER REAR SPAR FITTINGS (LUGS) INSPECTION procedure in Chapter 55-50-00. / b. Inspect Horizontal Stabilizer pivot bolts and bushings for wear, corrosion, chemical intrusion and damage. / c. Visually inspect the surrounding area for loose or missing fasteners and any indication of structural damage.						RE		Scheduled Inspections	≈29-Jul-2026
	55 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H550013		HORIZONTAL STABILIZER - HORIZONTAL STABILIZER STRINGERS AND SKINS - Horizontal Stabilizer Station (HSS) 0.00 to HSS 11.81 (300) - Detail inspect for cracks, loose or missing fasteners in the stringers and skins.						RE		Scheduled Inspections	≈10-Jul-2024
	55 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H550014		VERTICAL STABILIZER - VERTICAL STABILIZER - Detail inspect vertical stabilizer skin for cracks, loose or missing fasteners and any indication of structural damage.						RE		Scheduled Inspections	≈10-Jul-2024
	55 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
H550015		HORIZONTAL STABILIZER RIB INSPECTION (P/N 45A21112-5, 45A21113-5, 45A21101-11, 45A21116-5, 45A21117-5) - Perform radiographic (X-Ray) inspection of the horizontal stabilizer rib assemblies in accordance with Chapter 55-10-00. As an alternate means of inspection, a borescope inspection may be performed in accordance with Chapter 55-10-00.							RE	Scheduled Special Inspections		≈12-Jul-2026
	55 A/F					Mos	11-Nov-2022					
	Unknown					Hrs	14814:28	2,400	+40	17214:28	2163:50 Hrs (+40)	
	Unknown					Ldg	10,886					
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)												
H550016		HORIZONTAL STABILIZER INTERNAL STRUCTURE (Airplanes modified by Kit 128-6200) - Detail inspect for cracks, corrosion, missing fasteners and evidence of structural damage using either the radiographic (X-Ray) or borescope inspection procedure (Ref. Chapter 55-10-00).							RE	Scheduled Special Inspections		≈12-Jul-2026
	55 A/F					Mos	11-Nov-2022					
						Hrs	14814:28	2,400	+40	17214:28	2163:50 Hrs (+40)	
						Ldg	10,886					
(SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)												
▼ 56 - WINDOWS												
		New Windows Surface Seal Gen III.							RE (-)			
	56 A/F					Mos	23-Aug-2020					
	Complied With					Hrs	13600:47					
	(UPDATE NOTE: We have still Gen II, but accept information about new version GEN III. in case of need.)											
						Ldg	10,143					
560000-0101		Windshield Temperture Control							RE (O/C)			
	56 A/F	Left				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
560000-0102		Windshield Temperture Control							RE (O/C)			
	56 A/F	Right				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
560000-0201		Cabin Window							RE (O/C)			
	56 A/F	Left No.1				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
560000-0202		Cabin Window							RE (O/C)			
	56 A/F	Left No.2				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
560000-0203		Cabin Window							RE (O/C)			
	56 A/F	Left No.3				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
560000-0204		Cabin Window							RE (O/C)			
	56 A/F	Left No.4				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
560000-0205		Cabin Window							RE (O/C)			
	56 A/F	Left No.5				Mos	21-Nov-2000					
	Unknown					Hrs	0					
	Unknown					Ldg	0					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
560000-0206		Cabin Window						RE (O/C)			
56	A/F	Right No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560000-0207		Cabin Window						RE (O/C)			
56	A/F	Right No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560000-0208		Cabin Window						RE (O/C)			
56	A/F	Right No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560000-0209		Cabin Window						RE (O/C)			
56	A/F	Right No.4					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560000-0210		Cabin Window						RE (O/C)			
56	A/F	Right No.5					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560000-0211		Entrance Door Cabin Window						RE (O/C)			
56	A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560000-0212		Escape Hatch Cabin Window						RE (O/C)			
56	A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
561000-0101		Windshield						RE (O/C)			
56	A/F	Left					Mos	29-Oct-2018			
	45AS31001-023	New					Hrs	12348			
	18222H5296						Ldg	9,356			
561000-0102		Windshield						RE (O/C)			
56	A/F	Right					Mos	01-Feb-2013			
	45AS31001-024	New					Hrs	8063			
	12268H1087						Ldg	6,813			
561000-0201		Cockpit Side Window						RE		AWL - Life Limit	≈20-Feb-2032
56	A/F	Left					Mos	06-Sep-2002			
	45AS31010		0				Hrs	1593	20,000	21593	6542:22 Hrs
	Unknown						Ldg				
	MM:045601 (SOURCE: Maintenance Manual 040002)										
561000-0202		Cockpit Side Window						RE		AWL - Life Limit	≈05-Jun-2040
56	A/F	Right					Mos	20-Feb-2013			
	45AS31010-22	New	0				Hrs	8063	20,000	28063	13012:22 Hrs
	1992						Ldg	6,813			
	MM:045601 (SOURCE: Maintenance Manual 040002)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
562000-0101		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.1					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0102		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.2					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0103		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.3					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0104		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.4					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0105		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.5					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0106		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.6					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0107		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.1					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0108		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.2					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0109		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.3					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0110		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.4					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
562000-0111		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.5					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0112		Cabin Window (Inner)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.6					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0201		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.1					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0202		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.2					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0203		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.3					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0204		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.4					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0205		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.5					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0206		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Left No.6					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0207		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.1					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											
562000-0208		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
56 A/F		Right No.2					Mos	21-Nov-2000			
128-530035-1/-3/-5			0				Hrs	0	20,000	20000	4949:22 Hrs
Unknown							Ldg				
MM:045602 (SOURCE: Maintenance Manual 040002)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
562000-0209		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
✎	56 A/F	Right No.3				Mos	21-Nov-2000				
	128-530035-1/-3/-5		0			Hrs	0	20,000		20000	4949:22 Hrs
	Unknown					Ldg					
	MM:045602 (SOURCE: Maintenance Manual 040002)										
562000-0210		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
✎	56 A/F	Right No.4				Mos	21-Nov-2000				
	128-530035-1/-3/-5		0			Hrs	0	20,000		20000	4949:22 Hrs
	Unknown					Ldg					
	MM:045602 (SOURCE: Maintenance Manual 040002)										
562000-0211		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
✎	56 A/F	Right No.5				Mos	21-Nov-2000				
	128-530035-1/-3/-5		0			Hrs	0	20,000		20000	4949:22 Hrs
	Unknown					Ldg					
	MM:045602 (SOURCE: Maintenance Manual 040002)										
562000-0212		Cabin Window (Outer)						RE		AWL - Life Limit	≈06-Feb-2030
✎	56 A/F	Right No.6				Mos	21-Nov-2000				
	128-530035-1/-3/-5		0			Hrs	0	20,000		20000	4949:22 Hrs
	Unknown					Ldg					
	MM:045602 (SOURCE: Maintenance Manual 040002)										
ESC-200814-065		Apply LH and RH Windshield Coating						N/N (-)		Squawk, -	
✎	56 A/F					Mos					
	Open					Hrs					
	(Date reported: 14-Aug-2020), (Reported by: Kohout, John, Title: Director of Maintenance)(Classification date: 14-Aug-2020), (Recorded by: Kohout, John, Title: Director of Maintenance)										
						Ldg					
H560001		FORWARD FUSELAGE - WINDSHIELD AND FLIGHT COMPARTMENT WINDOWS - Inspect for pits, scratches, crazing, delamination and proper sealing (Ref. Chapter 56-00-00).						RE		Scheduled Inspections	
✎	56 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)										
						Ldg	10,886				
H560002		FORWARD FUSELAGE - WINDSHIELD EXTERNAL FRAME AND PROTECTORS / a. Inspect for condition and proper sealing. / b. Perform the UNPAINTED SURFACE INSPECTION (Ref. Chapter 12-20-00).						RE		Scheduled Inspections	
✎	56 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)										
						Ldg	10,886				
H560004		FORWARD FUSELAGE - WINDSHIELD SURFACE SEAL COATING (RK-1 thru RK-242 with Kit 128-5405 installed; RK-243 and After) - Inspect and if required, reapply the Surface Seal Coating in accordance with Chapter 56 in the Component Maintenance Manual, P/N 128-590001-81 or subsequent.						RE		Scheduled Inspections	
✎	56 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02) (NOTE: RK-1 thru RK-242 with Kit 128-5405 installed; RK-243 and After)										
						Ldg	10,886				
H560005		MIDFUSELAGE - PASSENGER COMPARTMENT WINDOWS - Inspect for cracks, delamination and sealant condition.						RE		Scheduled Inspections	
✎	56 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)										
						Ldg	10,886				
H560006		SCHEDULED D INSPECTIONS - CABIN WINDOW FRAME - Perform detailed inspection for cracks, loose or missing fasteners and evidence of damage.						RE		Scheduled Inspections	≈29-Jul-2026
✎	56 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)										
						Ldg	10,401				

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H560007	PILOT'S COMPARTMENT - WINDSHIELD GLASS, COCKPIT SIDE WINDOW GLASS, AND RETAINERS (Interior windshield trim panels removed) / a. Detail inspect windshield frame for cracks or structural damage, loose or missing fasteners and evidence of water leakage. / b. Detail inspect (using an optical prism) the periphery of the windshield screen and mounting holes for cracks or evidence of damage. (Refer to ASTM F2108-06 - Standard Practice for Inspection of Transparent Parts by Prism). / c. Inspect windshield seal, P/N 45A97010, for evidence of migration from under the windshield.						RE		Scheduled Inspections	≈10-Jul-2024
56 A/F	05-20-04				Mos	12-May-2021				
					Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
▼ 57 - WINGS										
045706	Perform Eddy Current Inspection of LH Main Landing Gear Support Fitting						RE		AWL - Inspection Limitations	≈03-Feb-2026
57 A/F	Left				Mos	11-Nov-2021				
45A10207					Hrs	14471:02	2,400	+20	16871:02	1820:24 Hrs (+20)
Unknown					Ldg	10,655				
	(SOURCE: Maintenance Manual 040002)									
045706	Perform Eddy Current Inspection of RH Main Landing Gear Support Fitting						RE		AWL - Inspection Limitations	≈03-Feb-2026
57 A/F	Right				Mos	11-Nov-2021				
45A10207					Hrs	14471:02	2,400	+20	16871:02	1820:24 Hrs (+20)
Unknown					Ldg	10,655				
	(SOURCE: Maintenance Manual 040002)									
570000-0101	Wing Assembly						RE (O/C)			
57 A/F	Left				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
570000-0102	Wing Assembly						RE (O/C)			
57 A/F	Right				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
570000-0201	Spoiler Hinge Fitting						RE (O/C)			
57 A/F	Left No.1				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
570000-0202	Spoiler Hinge Fitting						RE (O/C)			
57 A/F	Left No.2				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
570000-0203	Spoiler Hinge Fitting						RE (O/C)			
57 A/F	Left No.3				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
570000-0204	Spoiler Hinge Fitting						RE (O/C)			
57 A/F	Left No.4				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				
570000-0205	Spoiler Hinge Fitting						RE (O/C)			
57 A/F	Left No.5				Mos	21-Nov-2000				
Unknown					Hrs	0				
Unknown					Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
570000-0206		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Left No.6					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0207		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Right No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0208		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Right No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0209		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Right No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0210		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Right No.4					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0211		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Right No.5					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0212		Spoiler Hinge Fitting								RE (O/C)	
	57 A/F	Right No.6					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0301		Spoiler Hinge Assembly								RE (O/C)	
	57 A/F	Left No.1					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0302		Spoiler Hinge Assembly								RE (O/C)	
	57 A/F	Left No.2					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0303		Spoiler Hinge Assembly								RE (O/C)	
	57 A/F	Left No.3					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
570000-0304		Spoiler Hinge Assembly								RE (O/C)	
	57 A/F	Left No.4					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
570000-0305		Spoiler Hinge Assembly									
57 A/F		Left No.5					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0306		Spoiler Hinge Assembly									
57 A/F		Left No.6					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0307		Spoiler Hinge Assembly									
57 A/F		Right No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0308		Spoiler Hinge Assembly									
57 A/F		Right No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0309		Spoiler Hinge Assembly									
57 A/F		Right No.3					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0310		Spoiler Hinge Assembly									
57 A/F		Right No.4					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0311		Spoiler Hinge Assembly									
57 A/F		Right No.5					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0312		Spoiler Hinge Assembly									
57 A/F		Right No.6					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0401		Wing-To-Fuselage Attach Bolts (for replacement tracking)									
57 A/F		Left					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570000-0402		Wing-To-Fuselage Attach Bolts (for replacement tracking)									
57 A/F		Right					Mos	21-Nov-2000		RE (O/C)	
Unknown							Hrs	0			
Unknown							Ldg	0			
570100-0101		Wings - Main Flap Rails Support Assembly									
57 A/F		Left Outboard					Mos	21-Nov-2000		RE	AWL - Life Limit
45A10422			0				Hrs	0	22,400		22400
Unknown							Ldg				7349:22 Hrs
MM:045701 (SOURCE: Maintenance Manual 040002)											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
570100-0102	Wings - Main Flap Rails Support Assembly								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Left Inboard					Mos	21-Nov-2000			
45A10420		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045701 (SOURCE: Maintenance Manual 040002)										
570100-0103	Wings - Main Flap Rails Support Assembly								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Left Center					Mos	21-Nov-2000			
Unknown		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045701 (SOURCE: Maintenance Manual 040002)										
570100-0104	Wings - Main Flap Rails Support Assembly								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Right Center					Mos	21-Nov-2000			
Unknown		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045701 (SOURCE: Maintenance Manual 040002)										
570100-0105	Wings - Main Flap Rails Support Assembly								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Right Inboard					Mos	21-Nov-2000			
45A10420		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045701 (SOURCE: Maintenance Manual 040002)										
570100-0106	Wings - Main Flap Rails Support Assembly								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Right Outboard					Mos	21-Nov-2000			
45A10422		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045701 (SOURCE: Maintenance Manual 040002)										
570200-0101	Wings - Aft Flap Rail								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Left Outboard					Mos	21-Nov-2000			
45A16087		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045702 (SOURCE: Maintenance Manual 040002)										
570200-0102	Wings - Aft Flap Rail								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Left Inboard					Mos	21-Nov-2000			
45A16127		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045702 (SOURCE: Maintenance Manual 040002)										
570200-0103	Wings - Aft Flap Rail								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Right Inboard					Mos	21-Nov-2000			
45A16127		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045702 (SOURCE: Maintenance Manual 040002)										
570200-0104	Wings - Aft Flap Rail								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Right Outboard					Mos	21-Nov-2000			
45A16087		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045702 (SOURCE: Maintenance Manual 040002)										
570300-0101	Wings - Flap Mechanism Bolt								RE	AWL - Life Limit ≈03-Mar-2033
57 A/F	Left					Mos	21-Nov-2000			
Unknown		0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown						Ldg				
MM:045703 (SOURCE: Maintenance Manual 040002) (NOTE: (*) This part is not practical to mark with a part number/serial number. If removal from the airplane is required before the end of its published replacement life limitation, then it should be bagged and identified with accumulated hours/cycles and records should be maintained to ensure compliance with the life limitation.)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
570300-0102		Wings - Flap Mechanism Bolt						RE		AWL - Life Limit	≈03-Mar-2033
57 A/F		Right					Mos	21-Nov-2000			
Unknown			0				Hrs	0	22,400	22400	7349:22 Hrs
Unknown							Ldg				
MM:045703 (SOURCE: Maintenance Manual 040002) (NOTE: (*) This part is not practical to mark with a part number/serial number. If removal from the airplane is required before the end of its published replacement life limitation, then it should be bagged and identified with accumulated hours/cycles and records should be maintained to ensure compliance with the life limitation.)											
570400-0101		Wings - Spoiler Assembly						RE		AWL - Life Limit	≈10-Mar-2036
57 A/F		Left Outboard					Mos	18-Feb-2022			
45A10502-001			4415:33				Hrs	14572:58	14,600	24757:25	9706:47 Hrs
Unknown							Ldg	10,722			
MM:045704 (SOURCE: Maintenance Manual 040002)											
570400-0102		Wings - Spoiler Assembly						RE		AWL - Life Limit	≈10-Mar-2036
57 A/F		Left Inboard					Mos	18-Feb-2022			
45A10501-011			4415:33				Hrs	14572:58	14,600	24757:25	9706:47 Hrs
Unknown							Ldg	10,722			
MM:045704 (SOURCE: Maintenance Manual 040002)											
570400-0103		Wings - Spoiler Assembly						RE		AWL - Life Limit	≈10-Mar-2036
57 A/F		Right Inboard					Mos	18-Feb-2022			
45A10501-012			4415:33				Hrs	14572:58	14,600	24757:25	9706:47 Hrs
Unknown							Ldg	10,722			
MM:045704 (SOURCE: Maintenance Manual 040002)											
570400-0104		Wings - Spoiler Assembly						RE		AWL - Life Limit	≈10-Mar-2036
57 A/F		Right Outboard					Mos	18-Feb-2022			
45A10502-002			4415:33				Hrs	14572:58	14,600	24757:25	9706:47 Hrs
Unknown							Ldg	10,722			
MM:045704 (SOURCE: Maintenance Manual 040002)											
570500-0101		Main Landing Gear Support Fitting						RE		AWL - Life Limit	≈05-Feb-2034
57 A/F		Left					Mos	21-Nov-2000			
45A10207							Hrs				
Unknown			0				Ldg	0	15,000	15,000	3,972 Ldg
MM:045705 (SOURCE: Maintenance Manual 040002)											
570500-0102		Main Landing Gear Support Fitting						RE		AWL - Life Limit	≈05-Feb-2034
57 A/F		Right					Mos	21-Nov-2000			
45A10207							Hrs				
Unknown			0				Ldg	0	15,000	15,000	3,972 Ldg
MM:045705 (SOURCE: Maintenance Manual 040002)											
571000-0101		Rear Spar Assembly						RE (O/C)			
57 A/F							Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
575000-0101		Aft Flap Assembly						RE (O/C)			
57 A/F		Left					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			
575000-0102		Aft Flap Assembly						RE (O/C)			
57 A/F		Right					Mos	21-Nov-2000			
Unknown							Hrs	0			
Unknown							Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
575000-0201	Aft Flap Rail Assembly									
57 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
575000-0202	Aft Flap Rail Assembly									
57 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
575000-0203	Aft Flap Rail Assembly									
57 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
575000-0204	Aft Flap Rail Assembly									
57 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
576000-0101	Roll Trim									
57 A/F	Left					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
576000-0102	Roll Trim									
57 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
577000-0101	Spoiler Inst-Wing									
57 A/F	Left Outboard					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
577000-0102	Spoiler Inst-Wing									
57 A/F	Left Inboard					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
577000-0103	Spoiler Inst-Wing									
57 A/F	Right Inboard					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
577000-0104	Spoiler Inst-Wing									
57 A/F	Right Outboard					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
H570008	WING-TO-FUSELAGE ATTACH BOLTS - Detail inspect for corrosion, wear and any evidence of damage. Magnetic particle inspect for cracks (Ref. Chapter 57-40-00).								T Scheduled Special Inspections	
57 A/F						Yrs	13-May-2016	10	11-May-2026	2.6 Years
(Manual Adjustment: -2d) (SOURCE: MODEL 400/400A MMS-IFA / 05-20-01)						Hrs				
						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H570009		MIDFUSELAGE - WING ATTACH FITTINGS / a. Inspect for exfoliation, corrosion, wear and installed condition. / b. Inspect adjacent area for corrosion and any evidence of structural damage.						RE		Scheduled Inspections	≈10-Jul-2024
	57 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H570012		SCHEDULED D INSPECTIONS - MAIN FLAP CENTER RAIL ASSEMBLY AND CENTER FLAP ROLLERS - Perform detailed inspection for loose or missing fasteners, bolts of center flap roller for condition and any indication of structural damage (Ref. Figure 605).						RE		Scheduled Inspections	≈29-Jul-2026
	57 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H570013		SCHEDULED D INSPECTIONS - WING FRONT AND REAR SPAR FITTINGS - Perform detailed inspection of attachment fittings using Eddy current procedures. Refer to WING FORWARD AND AFT SPAR FITTING INSPECTION procedures, Chapter 57-40-00. (The wing does not have to be removed.)						RE		Scheduled Inspections	≈29-Jul-2026
	57 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H570014		SCHEDULED D INSPECTIONS - FORWARD AND AFT CARRY-THROUGH (LUGS) (P/N 45A33511 and 45A33512) - Perform detailed inspection of lugs using Eddy current procedures. Refer to FORWARD AND AFT CARRY-THROUGH (LUGS) INSPECTION procedures, Chapter 57-40-00. (The wing does not have to be removed.)						RE		Scheduled Inspections	≈29-Jul-2026
	57 A/F	05-20-05				Mos	12-May-2021				
						Hrs	14049:30	3,200	+40	(17249:30)	2198:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-05)				Ldg	10,401				
H570102		LEFT-HAND WING - WING SKIN (Exterior inspection only, fairing removal is not required) - Inspect skin for condition.						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570103		LEFT-HAND WING - FUEL TANK FILLER RECEPTACLE / a. Inspect fuel cap, fuel cap lanyard and fuel cap adapter assembly for condition. / b. Inspect fuel cap latching mechanism for proper operation.						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570106		LEFT-HAND WING - WING LEADING AND TRAILING EDGE ASSEMBLIES / a. Inspect for condition. / b. Perform the UNPAINTED SURFACE INSPECTION (Ref. Chapter 12-20-00).						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570107		LEFT-HAND WING - WING FUEL STORAGE AND INSPECTION ACCESS PANELS (Exterior inspection only, panel removal is not required) - Inspect for condition and evidence of fuel leakage.						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570111		LEFT-HAND WING - WING FUEL STORAGE AREA INSPECTION / a. Detail inspect integral wing tank ribs, stringers and skins for cracks, loose or missing fasteners, corrosion, deteriorated sealant and evidence of structural damage. Ensure compartments are free of foreign materials. / b. (RK-106 thru RK-507 with Kit 128-9008 and 128-9009 Installed; RK-508 thru RK-529 with Kit 128-9009 Installed; RK-530 and After) - Detail inspect integral wing tank compartments for indication of fungal or microbial contamination (Ref. Chapter 28-11-00). / c. Detail inspect wing ribs at BP 35(890), WS 50.6 (1285) and WCS 65.4 (1660) and drain holes on stringers for cracks, loose or missing fasteners and any indication of structural damage. (Ref. Figure 618).						RE		Scheduled Inspections	≈10-Jul-2024
	57 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H570112		LEFT-HAND WING - SPOILER BRACKET (P/N 45A10152) REAR SPAR AREA (WCS 2513) - Inspect bracket for security and cracking. Pay particular attention to the area surrounding the bracket holes and mounting hardware (Ref. Figure 609).						RE		Scheduled Inspections	≈24-Jun-2024
	57 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
H570202		RIGHT-HAND WING - WING SKIN (Exterior inspection only, fairing removal is not required) - Inspect skin for condition.						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570203		RIGHT-HAND WING - FUEL TANK FILLER RECEPTACLE / a. Inspect fuel cap, fuel cap lanyard and fuel cap adapter assembly for condition. / b. Inspect fuel cap latching mechanism for proper operation.						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570206		RIGHT-HAND WING - WING LEADING AND TRAILING EDGE ASSEMBLIES / a. Inspect for condition. / b. Perform the UNPAINTED SURFACE INSPECTION (Ref. Chapter 12-20-00).						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570207		RIGHT-HAND WING - WING FUEL STORAGE AND INSPECTION ACCESS PANELS (Exterior inspection only, panel removal is not required) - Inspect for condition and evidence of fuel leakage.						RE		Scheduled Inspections	
	57 A/F	05-20-02				Mos	11-Nov-2022	12		(30-Nov-2023)	57 Days
						Hrs	14814:28	400	+40	(15214:28)	163:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-02)				Ldg	10,886				
H570211		RIGHT-HAND WING - WING FUEL STORAGE AREA - AREA INSPECTION / a. Detail inspect integral wing tank ribs, stringers and skins for cracks, loose or missing fasteners, corrosion, deteriorated sealant and evidence of structural damage. Ensure compartments are free of foreign materials. / b. (RK-106 thru RK-507 with Kit 128-9008 and 128-9009 Installed; RK-508 thru RK-529 with Kit 128-9009 Installed; RK-530 and After) - Detail inspect integral wing tank compartments for indication of fungal or microbial contamination (Ref. Chapter 28-11-00). / c. Detail inspect wing ribs at BP 35 (890), WS 50.6 (1285) and WCS 65.4 (1660) and drain holes on stringers fro cracks, loose or missing fasteners and any indication of structural damage. (Ref. Figure 618).						RE		Scheduled Inspections	≈10-Jul-2024
	57 A/F	05-20-04				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-04)				Ldg	10,401				
H570212		RIGHT-HAND WING - SPOILER BRACKET (P/N 45A10152) REAR SPAR AREA (WCS 2513) - Inspect bracket for security and cracking. Pay particular attention to the area surrounding the bracket holes and mounting hardware (Ref. Figure 609).						RE		Scheduled Inspections	≈24-Jun-2024
	57 A/F	05-20-03				Mos	11-Nov-2022				
						Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
		(SOURCE: MODEL 400/400A MMS-IFA / 05-20-03)				Ldg	10,886				
▼ 70 - STANDARD PRACTICES - ENGINES											
05-20-00-814A-300A-A-7.1.22		Visually check installed electrical component bonding surfaces and harness connectors, identified in Component Bonding Requirements Table, to make sure that there are no visible signs of corrosion. If corrosion is present, clean surfaces						RE		LMM - Requirement	≈02-Mar-2024
	70 ENG1	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
		Ref:70-03-01-201 (SOURCE: FJ44-3AP LMM (P/N 111000-202))				Enc	4,201				
05-20-00-814A-300A-A-7.1.22		Visually check installed electrical component bonding surfaces and harness connectors, identified in Component Bonding Requirements Table, to make sure that there are no visible signs of corrosion. If corrosion is present, clean surfaces						RE		LMM - Requirement	≈02-Mar-2024
	70 ENG2	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
		Ref:70-03-01-201 (SOURCE: FJ44-3AP LMM (P/N 111000-202))				Enc	4,201				
▼ 71 - POWER PLANT											
047105		Engine Aft Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left				Mos					
	96276-02					Hrs					
	1275					Ldg					
		MM:047105 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))									
047105		Engine Aft Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right				Mos					
	96276-02					Hrs					
	1281					Ldg					
		MM:047105 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
047105		Engine Forward Lower Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left									
	96276-01										
	0188										
	MM:047105 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047105		Engine Forward Lower Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right									
	96276-01										
	0282										
	MM:047105 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047105		Engine Forward Upper Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left									
	96276-01										
	0184										
	MM:047105 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047105		Engine Forward Upper Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right									
	96276-01										
	0189										
	MM:047105 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047106		Engine Aft Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left									
	96276-02										
	1275										
	MM:047106 (SOURCE: Maintenance Manual 040002) (NOTE: (Barry Controls))										
047106		Engine Aft Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right									
	96276-02										
	1281										
	MM:047106 (SOURCE: Maintenance Manual 040002) (NOTE: (Barry Controls))										
047106		Engine Forward Lower Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left									
	96276-01										
	0188										
	MM:047106 (SOURCE: Maintenance Manual 040002) (NOTE: (Barry Controls))										
047106		Engine Forward Lower Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right									
	96276-01										
	0282										
	MM:047106 (SOURCE: Maintenance Manual 040002) (NOTE: (Barry Controls))										
047106		Engine Forward Upper Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left									
	96276-01										
	0184										
	MM:047106 (SOURCE: Maintenance Manual 040002) (NOTE: (Barry Controls))										
047106		Engine Forward Upper Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right									
	96276-01										
	0189										
	MM:047106 (SOURCE: Maintenance Manual 040002) (NOTE: (Barry Controls))										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
047107		Engine Aft Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left				Mos					
	96276-02					Hrs					
	1275					Ldg					
	MM:047107 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047107		Engine Aft Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right				Mos					
	96276-02					Hrs					
	1281					Ldg					
	MM:047107 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047107		Engine Forward Lower Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left				Mos					
	96276-01					Hrs					
	0188					Ldg					
	MM:047107 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047107		Engine Forward Lower Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right				Mos					
	96276-01					Hrs					
	0282					Ldg					
	MM:047107 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047107		Engine Forward Upper Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Left				Mos					
	96276-01					Hrs					
	0184					Ldg					
	MM:047107 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
047107		Engine Forward Upper Mount Isolator - Replacement						RE (N/A)		AWL - Life Limit	
	71 A/F	Right				Mos					
	96276-01					Hrs					
	0189					Ldg					
	MM:047107 (SOURCE: Maintenance Manual 040002) (NOTE: (Lord Corporation))										
05-20-00-814A-300A-A-7.1.08		Use EMT to Interrogate FADEC for faults Troubleshoot applicable faults, as required. Before returning the engine to service, verify that the TLD annunciator is not illuminated						RE		LMM - Requirement	≈08-Oct-2023
	71 ENG1	05-20-00-814A-300A-A-1.4,...				Mos	26-Jul-2022				
						Hrs	6920:56	300	+30	≈7206:51	
	Ref:71-00-00-101 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Isolate BIT fault per 71-00-00-101.)										
						Enc	4,201				
05-20-00-814A-300A-A-7.1.08		Use EMT to Interrogate FADEC for faults Troubleshoot applicable faults, as required. Before returning the engine to service, verify that the TLD annunciator is not illuminated						RE		LMM - Requirement	≈08-Oct-2023
	71 ENG2	05-20-00-814A-300A-A-1.4,...				Mos	26-Jul-2022				
						Hrs	6920:56	300	+30	≈7206:51	
	Ref:71-00-00-101 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Isolate BIT fault per 71-00-00-101.)										
						Enc	4,201				
05-50-00-801A-042A-A-2		Water Rinse						RE (A/R)		Recommended	
	71 ENG1					Mos					
						Hrs	10692				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))										
						Enc	8,344				
05-50-00-801A-042A-A-2		Water Rinse						RE (A/R)		Recommended	
	71 ENG2					Mos					
						Hrs	10692				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))										
						Enc	8,344				
05-50-00-801A-042A-A-3		Compressor Cleaning						RE (A/R)		LMM - Requirement	
	71 ENG1					Mos					
						Hrs	10692				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: If engine performance has gradually degraded (increase in ITT, increase in N2, increase in fuel consumption), perform the compressor cleaning procedure)										
						Enc	8,344				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
05-50-00-801A-042A-A-3	 71 ENG2	Compressor Cleaning (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: If engine performance has gradually degraded (increase in ITT, increase in N2, increase in fuel consumption), perform the compressor cleaning procedure)						RE (A/R)		LMM - Requirement		
05-50-00-870-002	 71 A/F	Perform fresh water rinse procedure to remove salt or other corrosive substances from the interior of the engine. I.n.w. LMM FJ44-3AP 111000-202 ch. 71-00-03 P.B. 701. (NOTE: Operational request) (NOTE: N/A during winter)						RE			≈21-Nov-2023	
710000-0101	 71 A/F Unknown Unknown	Engine Air Intake Duct Assembly Left						RE (O/C)				
710000-0102	 71 A/F Unknown Unknown	Engine Air Intake Duct Assembly Right						RE (O/C)				
710000-0201	 71 A/F N541000-003 R0010ADG	Inlet Assembly No.1 Tested/Inspected (UPDATE NOTE: The inlet was removed to service OK-PPP, then it was put back. FK)						RE (O/C)				
710000-0202	 71 A/F Unknown Unknown	Inlet Assembly No.2						RE (O/C)				
712000-0101	 71 A/F 96276-01 0184	Engine Forward Upper Mount Left Overhauled (Manual Adjustment: -13 Hrs)						RE			≈30-Jul-2024	
712000-0102	 71 A/F 96276-01 0189	Engine Forward Upper Mount Right Overhauled (Manual Adjustment: -13 Hrs)						RE			≈30-Jul-2024	
712000-0201	 71 A/F 96276-01 0188	Engine Forward Lower Mount Left Overhauled (Manual Adjustment: -13 Hrs)						RE			≈30-Jul-2024	
712000-0202	 71 A/F 96276-01 0282	Engine Forward Lower Mount Right Overhauled (Manual Adjustment: -13 Hrs)						RE			≈30-Jul-2024	

Task No	Description										Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
712000-0301	Engine Aft Upper Mount						RE			≈30-Jul-2024		
71 A/F	Left	0			Mos	22-Dec-2017						
96276-02	Overhauled	0			Hrs	11704	4,000		15691	640:22 Hrs		
1275		0			Ldg	8,940						
(Manual Adjustment: -13 Hrs)												
712000-0302	Engine Aft Upper Mount						RE			≈30-Jul-2024		
71 A/F	Right	0			Mos	22-Dec-2017						
96276-02	Overhauled	0			Hrs	11704	4,000		15691	640:22 Hrs		
1281		0			Ldg	8,940						
(Manual Adjustment: -13 Hrs)												
712000-0402	Engine Aft Lower Mount						RE			≈30-Jul-2024		
71 A/F	Left				Mos	22-Dec-2017						
96276-02	Overhauled	0			Hrs	11704	4,000		15691	640:22 Hrs		
1276					Ldg	8,940						
(Manual Adjustment: -13 Hrs)												
712000-0402	Engine Aft Lower Mount						RE			≈30-Jul-2024		
71 A/F	Right	0			Mos	22-Dec-2017						
96276-02	Overhauled	0			Hrs	11704	4,000		15691	640:22 Hrs		
1282		0			Ldg	8,940						
(Manual Adjustment: -13 Hrs)												
71-2013-03	Nextant - Addition of Nameplates to Aft Engine Vibration Isolators, P/N 96276-02 Due to Omitted Serial Numbers						RE (-)			Mandatory		
71 A/F					Mos	24-Jun-2013						
Eff: 24-Apr-2013 Complied	C/W iaw SB instructions				Hrs	8357						
With					Ldg	6,979						
71-NXT1-AWL1	Engine Forward Upper Mount - Overhaul						RE		AWL - ICA	≈30-Jul-2024		
71 A/F	Left				Mos	22-Dec-2017						
96276-01					Hrs	11704	4,000		15691	640:22 Hrs		
0184					Ldg							
Ref:NXT1-ICA Ch.04 (Manual Adjustment: -13 Hrs) (SOURCE: FAA STC ST02371LA)												
71-NXT1-AWL1	Engine Forward Upper Mount - Overhaul						RE		AWL - ICA	≈30-Jul-2024		
71 A/F	Right				Mos	22-Dec-2017						
96276-01					Hrs	11704	4,000		15691	640:22 Hrs		
0189					Ldg							
Ref:NXT1-ICA Ch.04 (Manual Adjustment: -13 Hrs) (SOURCE: FAA STC ST02371LA)												
71-NXT1-AWL2	Engine Forward Lower Mount - Overhaul						RE		AWL - ICA	≈30-Jul-2024		
71 A/F	Left				Mos	22-Dec-2017						
96276-01					Hrs	11704	4,000		15691	640:22 Hrs		
0188					Ldg							
Ref:NXT1-ICA Ch.04 (Manual Adjustment: -13 Hrs) (SOURCE: FAA STC ST02371LA)												
71-NXT1-AWL2	Engine Forward Lower Mount - Overhaul						RE		AWL - ICA	≈30-Jul-2024		
71 A/F	Right				Mos	22-Dec-2017						
96276-01					Hrs	11704	4,000		15691	640:22 Hrs		
0282					Ldg							
Ref:NXT1-ICA Ch.04 (Manual Adjustment: -13 Hrs) (SOURCE: FAA STC ST02371LA)												
71-NXT1-AWL3	Engine Aft Mount - Overhaul						RE		AWL - ICA	≈30-Jul-2024		
71 A/F	Left				Mos	22-Dec-2017						
96276-02					Hrs	11704	4,000		15691	640:22 Hrs		
1275					Ldg							
Ref:NXT1-ICA Ch.04 (Manual Adjustment: -13 Hrs) (SOURCE: FAA STC ST02371LA)												

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-NXT1-AWL3	71 A/F 96276-02 1281 Ref:NXT1-ICA Ch.04 (Manual Adjustment: -13 Hrs) (SOURCE: FAA STC ST02371LA)	Engine Aft Mount - Overhaul Right						RE		AWL - ICA	≈30-Jul-2024
							Mos	22-Dec-2017			
							Hrs	11704	4,000	15691	640:22 Hrs
							Ldg				
71-NXT1-D18	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - NACELLE ANTI-ICING DUCT Inspect clamps, hose and duct for fatigue cracks and other damage. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-D19	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - BLEED AIR SYSTEM Inspect ducts for condition and attachment, security and signs of bleed air leakage. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-D20	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - Inspect valves, mounts, switches and attach brackets for security of attachment and condition and signs of bleed are leakage. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-D4	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - Inspect integrity of PT2/TT2 sensor and mounting surface for security of attachment, safety wire and general condition of the shock mount material. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-E18	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - NACELLE ANTI-ICING DUCT Inspect clamps, hose and duct for fatigue cracks and other damage. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-E19	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - BLEED AIR SYSTEM Inspect ducts for condition and attachment, security and signs of bleed air leakage. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-E20	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - Inspect valves, mounts, switches and attach brackets for security of attachment and condition and signs of bleed are leakage. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
71-NXT1-E4	71 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - Inspect integrity of PT2/TT2 sensor and mounting surface for security of attachment, safety wire and general condition of the shock mount material. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40 (15214:28)	163:50 Hrs (+40)
							Ldg	10,886			
SB400-71-01 Rev 1	71 ENG1 Not Applicable (UPDATE NOTE: Williams engines)	POWER PLANT - INSTALLATION OF PRATT & WHITNEY SERVICE BULLETIN NUMBERS 7646 AND 7649 - INLET FLANGE SUPPORT PLATES AND FAN CASE DAMPER RING						RE (-)			
							Mos	31-Oct-2019			
							Hrs	5153:59			
							Enc	3,114			
SB400-71-01 Rev 1	71 ENG2 Not Applicable (UPDATE NOTE: Williams engines)	POWER PLANT - INSTALLATION OF PRATT & WHITNEY SERVICE BULLETIN NUMBERS 7646 AND 7649 - INLET FLANGE SUPPORT PLATES AND FAN CASE DAMPER RING						RE (-)			
							Mos	31-Oct-2019			
							Hrs	5153:59			
							Enc	3,114			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
TA-71-01		Engine Aft Upper Mount								RE (-)	
	71 A/F	Left					Mos				
	96276-02						Hrs				
							Ldg				
TA-71-02		Engine Aft Upper Mount								RE (-)	
	71 A/F	Right					Mos				
	96276-02						Hrs				
							Ldg				
TA-71-03		Engine Aft Lower Mount								RE (-)	
	71 A/F	Left					Mos				
	96276-02						Hrs				
							Ldg				
TA-71-04		Engine Aft Lower Mount								RE (-)	
	71 A/F	Right					Mos				
	96276-02						Hrs				
							Ldg				
TA-LMM-CW		Clean the Power Plant - Compressor Wash i.a.w. Williams LMM - FJ44-3AP 111000-202 Ch.71-00-03 page 703 (Operator requirement inspections)								RE (-)	
	71 A/F						Mos	23-Apr-2020			
							Hrs	13258:28			
							Ldg	9,933			
WISL-71-1551		Power Plant - Steady State ITT Exceedance - Alternate Instructions for Continued Airworthiness								RE (-)	Service Letter
	71 ENG1						Mos	20-Jun-2023			
	Eff: 12-Jun-2023 Not Applicable						Hrs				
	(UPDATE NOTE: Not Applicable due to different SN)						Enc				
WISL-71-1551		Power Plant - Steady State ITT Exceedance - Alternate Instructions for Continued Airworthiness								RE (-)	Service Letter
	71 ENG2						Mos	20-Jun-2023			
	Eff: 12-Jun-2023 Not Applicable						Hrs				
	(UPDATE NOTE: Not Applicable due to different SN)						Enc				
▼ 72 - ENGINE											
		Accessory Drive Gearbox Housing Assembly								RE (O/C)	
	72 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
		Accessory Drive Gearbox Housing Assembly								RE (O/C)	
	72 ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
05-10-00-810A-042A-A-7.3		Time Limited Dispatch (TLD) Faults - Check								RE (N/A)	LMM - Requirement
	72 ENG1						Mos				
							Hrs				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc				
05-10-00-810A-042A-A-7.3		Time Limited Dispatch (TLD) Faults - Check								RE (N/A)	LMM - Requirement
	72 ENG2						Mos				
							Hrs				
	(SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc				
05-20-00-814A-300A-A-7.1.01		Inspect the engine inlet, fan rotor, fan tip shroud, fan stator, and 2nd LP turbine rotor for evidence of foreign object damage (FOD). Remove any obstructions.								RE (A/R)	LMM - Requirement
	72 ENG1	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023			(31-Aug-2023) OVD
							Hrs	7199:01			
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,372			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-20-00-814A-300A-A-7.1.01		Inspect the engine inlet, fan rotor, fan tip shroud, fan stator, and 2nd LP turbine rotor for evidence of foreign object damage (FOD). Remove any obstructions.						RE (A/R)		LMM - Requirement	
	72 ENG2	05-20-00-814A-300A-A-1.1				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	7199:01				
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372				
05-20-00-814A-300A-A-7.1.02		Inspect engine inlet and exhaust areas for evidence of oil leakage. If you find evidence of oil leakage, isolate the cause and correct.						RE (A/R)		LMM - Requirement	
	72 ENG1	05-20-00-814A-300A-A-1.1				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	7199:01				
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372				
05-20-00-814A-300A-A-7.1.02		Inspect engine inlet and exhaust areas for evidence of oil leakage. If you find evidence of oil leakage, isolate the cause and correct.						RE (A/R)		LMM - Requirement	
	72 ENG2	05-20-00-814A-300A-A-1.1				Mos	16-Aug-2023			(31-Aug-2023)	OVD
						Hrs	7199:01				
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372				
05-20-00-814A-300A-A-7.1.05		Check No Dispatch annunciator.						RE (A/R)		LMM - Requirement	
	72 ENG1	05-20-00-814A-300A-A-1.2,...				Mos	16-Aug-2023				
						Hrs	7199:01				
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372				
05-20-00-814A-300A-A-7.1.05		Check No Dispatch annunciator.						RE (A/R)		LMM - Requirement	
	72 ENG2	05-20-00-814A-300A-A-1.2,...				Mos	16-Aug-2023				
						Hrs	7199:01				
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372				
05-20-00-814A-300A-A-7.1.17		Clean fan rotor and physically inspect for defects (feel with fingers)						RE		LMM - Requirement	≈02-Mar-2024
	72 ENG1	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
	Ref:72-31-20-601 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,201				
05-20-00-814A-300A-A-7.1.17		Clean fan rotor and physically inspect for defects (feel with fingers)						RE		LMM - Requirement	≈02-Mar-2024
	72 ENG2	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
	Ref:72-31-20-601 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,201				
05-20-00-814A-300A-A-7.1.18		Visually inspect the installed spinner						RE		LMM - Requirement	≈02-Mar-2024
	72 ENG1	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
	Ref:72-30-10-601 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,201				
05-20-00-814A-300A-A-7.1.18		Visually inspect the installed spinner						RE		LMM - Requirement	≈02-Mar-2024
	72 ENG2	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
	Ref:72-30-10-601 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,201				
05-20-00-814A-300A-A-7.1.20		Change oil						RE		LMM - Requirement	≈02-Mar-2024
	72 ENG1	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
	Ref:72-00-03-301 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,201				
05-20-00-814A-300A-A-7.1.20		Change oil						RE		LMM - Requirement	≈02-Mar-2024
	72 ENG2	05-20-00-814A-300A-A-1.5				Mos	26-Jul-2022				
						Hrs	6920:56	600	+30	(7520:56)	321:55 Hrs (+30)
	Ref:72-00-03-301 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,201				
720001-0101		Fan Rotor						RE		LMM - Life Limit	≈27-May-2038
	72 ENG1					Mos	13-Oct-2011				
	115810	New				Hrs	0				
	HW33750					Enc	0	10,000		10,000	5,628 Enc
	DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
720001-0101		Fan Rotor						RE		LMM - Life Limit	≈27-May-2038
72	ENG2		0			Mos	13-Oct-2011				
115810		New	0			Hrs	0				
HW33748			0			Enc	0	10,000		10,000	5,628 Enc
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))											
720002-0101		IP Compressor Rotor						RE		LMM - Life Limit	≈27-May-2038
72	ENG1		0			Mos	13-Oct-2011				
78239			0			Hrs	0				
HW32118			0			Enc	0	10,000		10,000	5,628 Enc
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))											
720002-0101		IP Compressor Rotor						RE		LMM - Life Limit	≈27-May-2038
72	ENG2		0			Mos	13-Oct-2011				
78239		New	0			Hrs	0				
HW32112			0			Enc	0	10,000		10,000	5,628 Enc
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))											
720003-0101		Front LP Shaft Nut						RE (O/C)			
72	ENG1					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
720003-0101		Front LP Shaft Nut						RE (O/C)			
72	ENG2					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
720003-0101		LP Shaft Assembly						RE (O/C)		LMM - Life Limit	
72	ENG1					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Critical Non-Life Limited Parts)											
720003-0101		LP Shaft Assembly						RE (O/C)		LMM - Life Limit	
72	ENG2					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Critical Non-Life Limited Parts)											
720005-0101		Case & Insert Assy						RE (O/C)			
72	ENG1					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
720005-0101		Case & Insert Assy						RE (O/C)			
72	ENG2					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
720006-0101		Vane Assy Fan Stator						RE (O/C)			
72	ENG1					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				
720006-0101		Vane Assy Fan Stator						RE (O/C)			
72	ENG2					Mos	13-Oct-2011				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
720007-0101		Stage 3 LP Rotor Stator								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720007-0101		Stage 3 LP Rotor Stator								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720009-0101		Carbon Seal								RE (O/C)	
	72 ENG1	No.1 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720009-0101		Carbon Seal								RE (O/C)	
	72 ENG2	No.1 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720010-0101		Carbon Seal Runner								RE (O/C)	
	72 ENG1	No.1 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720010-0101		Carbon Seal Runner								RE (O/C)	
	72 ENG2	No.1 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720015-0101		Balance Piston								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720015-0101		Balance Piston								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
720020-0101		Combustor Module Assembly								RE (O/C)	
	72 ENG1	126808 AU20716					Mos	05-May-2022			
							Hrs	2317:59			
							Enc	1,207			
720020-0101		Combustor Module Assembly								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
721001-0101		Bearing No.1 Housing								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
721001-0101		Bearing No.1 Housing								RE (O/C)	
72	ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721002-0101		Ball Bearing, Split In Ring								RE (O/C)	
72	ENG1	No.1					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721002-0101		Ball Bearing, Split In Ring								RE (O/C)	
72	ENG2	No.1					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721003-0101		Roller-Outer GDE Bearing Assembly								RE (O/C)	
72	ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721003-0101		Roller-Outer GDE Bearing Assembly								RE (O/C)	
72	ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721004-0101		No.1.5 Bring, Roller Outer Race								RE (O/C)	
72	ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721004-0101		No.1.5 Bring, Roller Outer Race								RE (O/C)	
72	ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721006-0101		Interstage Housing Assembly								RE (O/C)	
72	ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721006-0101		Interstage Housing Assembly								RE (O/C)	
72	ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721008-0101		1st Reduction Bevel Gear								RE (O/C)	
72	ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
721008-0101		1st Reduction Bevel Gear								RE (O/C)	
72	ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
721009-0101	Shaft, Accessory Drive								RE (O/C)	
 72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
721009-0101	Shaft, Accessory Drive								RE (O/C)	
 72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
721009-0101	Tower Shaft								RE (O/C)	
 72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
721009-0101	Tower Shaft								RE (O/C)	
 72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722001-0101	Bearing, Roller - 1st Reduction Bevel Gear								RE (O/C)	
 72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722001-0101	Bearing, Roller - 1st Reduction Bevel Gear								RE (O/C)	
 72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722002-0101	Deep Groove 103 Ball Bearing								RE (O/C)	
 72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722002-0101	Deep Groove 103 Ball Bearing								RE (O/C)	
 72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722003-0101	1st Reduction Bevel Gear Support Bearing								RE (O/C)	
 72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722003-0101	1st Reduction Bevel Gear Support Bearing								RE (O/C)	
 72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
722004-0101	1st Reduction Pinion Gear								RE (O/C)	
 72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
722004-0101		1st Reduction Pinion Gear								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722005-0101		High Pressure Shaft								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722005-0101		High Pressure Shaft								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722006-0101		HP Shaft Seal Front Runner								RE (O/C)	
	72 ENG1	No.2 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722006-0101		HP Shaft Seal Front Runner								RE (O/C)	
	72 ENG2	No.2 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722007-0101		HP Shaft Front Bearing Housing Assembly								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722007-0101		HP Shaft Front Bearing Housing Assembly								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722008-0101		Split Inner Ring Ball Bearing								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722008-0101		Split Inner Ring Ball Bearing								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722009-0101		Carbon Face Seal Assembly								RE (O/C)	
	72 ENG1	No.2 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
722009-0101		Carbon Face Seal Assembly								RE (O/C)	
	72 ENG2	No.2 Unknown Unknown					Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
722010-0101		IP Vane Assembly (Stage 1 & 2)								RE (O/C)	
	72 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
722010-0101		IP Vane Assembly (Stage 1 & 2)								RE (O/C)	
	72 ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
722011-0101		HP Compressor Cover								RE (O/C)	
	72 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
722011-0101		HP Compressor Cover								RE (O/C)	
	72 ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
722015-0101		Diffuser Case Assembly								RE (O/C)	
	72 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
722015-0101		Diffuser Case Assembly								RE (O/C)	
	72 ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
723001-0101		Nozzle & Pri Plate Assy HP Turb								RE (O/C)	
	72 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
723001-0101		Nozzle & Pri Plate Assy HP Turb								RE (O/C)	
	72 ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
723002-0101		HP Turbine Rotor								RE (O/C)	
	72 ENG1	New					Mos	05-May-2022			
	110830						Hrs	1857:06			
	HW45433						Enc	810			
723002-0101		HP Turbine Rotor								RE (O/C)	
	72 ENG2						Mos	05-May-2022			
	110830						Hrs	0			
	HW45435						Enc	0			
723003-0101		HP Turbine Disk								RE	LMM - Life Limit ≈27-May-2038
	72 ENG1						Mos	05-May-2022			
	110825						Hrs	0			
	HW45433		0				Enc	0	10,000	10,000	5,628 Enc
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
723003-0101	HP Turbine Disk								RE	LMM - Life Limit ≈27-May-2038
72 ENG2		0			Mos	05-May-2022				
110825		0			Hrs	0				
HW45435		0			Enc	0	10,000		10,000	5,628 Enc
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))										
723004-0101	Inner Guided Roller Bearing								RE (O/C)	
72 ENG1					Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723004-0101	Inner Guided Roller Bearing								RE (O/C)	
72 ENG2					Mos	05-May-2022				
79027					Hrs	6771				
JT135278					Enc	4,099				
723005-0101	Carbon Seal Housing								RE (O/C)	
72 ENG1	No.3				Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723005-0101	Carbon Seal Housing								RE (O/C)	
72 ENG2	No.3				Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723006-0101	Carbon Seal								RE (O/C)	
72 ENG1	No.3				Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723006-0101	Carbon Seal								RE (O/C)	
72 ENG2	No.3				Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723007-0101	Carbon Seal, Fwd								RE (O/C)	
72 ENG1	No.4				Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723007-0101	Carbon Seal, Fwd								RE (O/C)	
72 ENG2	No.4				Mos	16-Dec-2014				
45075	New				Hrs	1857:06				
TX080E8					Enc	810				
723008-0101	Carbon Seal, Aft								RE (O/C)	
72 ENG1	No.4				Mos	13-Oct-2011				
Unknown					Hrs	0				
Unknown					Enc	0				
723008-0101	Carbon Seal, Aft								RE (O/C)	
72 ENG2	No.4				Mos	16-Dec-2014				
45075	New				Hrs	1857:06				
TX538E0					Enc	810				

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
723009-0101	1st Stage LP Turbine Nozzle								RE (O/C)	
72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723009-0101	1st Stage LP Turbine Nozzle								RE (O/C)	
72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723010-0101	Balance Assy, LP Turbine Rotor								RE (O/C)	
72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723010-0101	Balance Assy, LP Turbine Rotor								RE (O/C)	
72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723013-0101	Bearing Inner Race								RE (O/C)	
72 ENG1	No.4					Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723013-0101	Bearing Inner Race								RE (O/C)	
72 ENG2	No.4					Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723014-0101	Housing Assy Nozzle 2nd LP Turbine								RE (O/C)	
72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
723014-0101	Housing Assy Nozzle 2nd LP Turbine								RE (O/C)	
72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
724003-0101	Accessorie Drive Gearbox								RE (O/C)	
72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
724003-0101	Accessorie Drive Gearbox								RE (O/C)	
72 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
724035-0101	HPT Combuster Assembly								RE (O/C)	
72 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
724035-0101		HPT Combuster Assembly								RE (O/C)		
	72 ENG2						Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725101-0101		HP Compressor Rotor								RE	LMM - Life Limit	≈27-May-2038
	72 ENG1		0			Mos	13-Oct-2011					
	119001	New	0			Hrs	0					
	HW33843		0			Enc	0	10,000		10,000	5,628 Enc	
	DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))											
725101-0101		HP Compressor Rotor								RE	LMM - Life Limit	≈27-May-2038
	72 ENG2		0			Mos	13-Oct-2011					
	119001	New	0			Hrs	0					
	HW33860		0			Enc	0	10,000		10,000	5,628 Enc	
	DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))											
725201-0101		HPT Blade								RE (O/C)		
	72 ENG1	No.1					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0101		HPT Blade								RE (O/C)		
	72 ENG2	No.1					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0102		HPT Blade								RE (O/C)		
	72 ENG1	No.2					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0102		HPT Blade								RE (O/C)		
	72 ENG2	No.2					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0103		HPT Blade								RE (O/C)		
	72 ENG1	No.3					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0103		HPT Blade								RE (O/C)		
	72 ENG2	No.3					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0104		HPT Blade								RE (O/C)		
	72 ENG1	No.4					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725201-0104		HPT Blade								RE (O/C)		
	72 ENG2	No.4					Mos	13-Oct-2011				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0105		HPT Blade								RE (O/C)	
	72 ENG1	No.5					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0105		HPT Blade								RE (O/C)	
	72 ENG2	No.5					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0106		HPT Blade								RE (O/C)	
	72 ENG1	No.6					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0106		HPT Blade								RE (O/C)	
	72 ENG2	No.6					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0107		HPT Blade								RE (O/C)	
	72 ENG1	No.7					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0107		HPT Blade								RE (O/C)	
	72 ENG2	No.7					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0108		HPT Blade								RE (O/C)	
	72 ENG1	No.8					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0108		HPT Blade								RE (O/C)	
	72 ENG2	No.8					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0109		HPT Blade								RE (O/C)	
	72 ENG1	No.9					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0109		HPT Blade								RE (O/C)	
	72 ENG2	No.9					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0110		HPT Blade								RE (O/C)	
	72 ENG1	No.10					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0110		HPT Blade								RE (O/C)	
	72 ENG2	No.10					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0111		HPT Blade								RE (O/C)	
	72 ENG1	No.11					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0111		HPT Blade								RE (O/C)	
	72 ENG2	No.11					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0112		HPT Blade								RE (O/C)	
	72 ENG1	No.12					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0112		HPT Blade								RE (O/C)	
	72 ENG2	No.12					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0113		HPT Blade								RE (O/C)	
	72 ENG1	No.13					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0113		HPT Blade								RE (O/C)	
	72 ENG2	No.13					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0114		HPT Blade								RE (O/C)	
	72 ENG1	No.14					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0114		HPT Blade								RE (O/C)	
	72 ENG2	No.14					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0115		HPT Blade								RE (O/C)	
	72 ENG1	No.15					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0115		HPT Blade								RE (O/C)	
	72 ENG2	No.15					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0116		HPT Blade								RE (O/C)	
	72 ENG1	No.16					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0116		HPT Blade								RE (O/C)	
	72 ENG2	No.16					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0117		HPT Blade								RE (O/C)	
	72 ENG1	No.17					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0117		HPT Blade								RE (O/C)	
	72 ENG2	No.17					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0118		HPT Blade								RE (O/C)	
	72 ENG1	No.18					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0118		HPT Blade								RE (O/C)	
	72 ENG2	No.18					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0119		HPT Blade								RE (O/C)	
	72 ENG1	No.19					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0119		HPT Blade								RE (O/C)	
	72 ENG2	No.19					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0120		HPT Blade								RE (O/C)	
	72 ENG1	No.20					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0120		HPT Blade								RE (O/C)	
	72 ENG2	No.20					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0121		HPT Blade								RE (O/C)	
	72 ENG1	No.21					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0121		HPT Blade								RE (O/C)	
72	ENG2	No.21					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0122		HPT Blade								RE (O/C)	
72	ENG1	No.22					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0122		HPT Blade								RE (O/C)	
72	ENG2	No.22					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0123		HPT Blade								RE (O/C)	
72	ENG1	No.23					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0123		HPT Blade								RE (O/C)	
72	ENG2	No.23					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0124		HPT Blade								RE (O/C)	
72	ENG1	No.24					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0124		HPT Blade								RE (O/C)	
72	ENG2	No.24					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0125		HPT Blade								RE (O/C)	
72	ENG1	No.25					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0125		HPT Blade								RE (O/C)	
72	ENG2	No.25					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0126		HPT Blade								RE (O/C)	
72	ENG1	No.26					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0126		HPT Blade								RE (O/C)	
72	ENG2	No.26					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0127		HPT Blade								RE (O/C)	
72	ENG1	No.27					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0127		HPT Blade								RE (O/C)	
72	ENG2	No.27					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0128		HPT Blade								RE (O/C)	
72	ENG1	No.28					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0128		HPT Blade								RE (O/C)	
72	ENG2	No.28					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0129		HPT Blade								RE (O/C)	
72	ENG1	No.29					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0129		HPT Blade								RE (O/C)	
72	ENG2	No.29					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0130		HPT Blade								RE (O/C)	
72	ENG1	No.30					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0130		HPT Blade								RE (O/C)	
72	ENG2	No.30					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0131		HPT Blade								RE (O/C)	
72	ENG1	No.31					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0131		HPT Blade								RE (O/C)	
72	ENG2	No.31					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0132		HPT Blade								RE (O/C)	
72	ENG1	No.32					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0132	72 ENG2 Unknown Unknown	HPT Blade No.32						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0133	72 ENG1 Unknown Unknown	HPT Blade No.33						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0133	72 ENG2 Unknown Unknown	HPT Blade No.33						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0134	72 ENG1 Unknown Unknown	HPT Blade No.34						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0134	72 ENG2 Unknown Unknown	HPT Blade No.34						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0135	72 ENG1 Unknown Unknown	HPT Blade No.35						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0135	72 ENG2 Unknown Unknown	HPT Blade No.35						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0136	72 ENG1 Unknown Unknown	HPT Blade No.36						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0136	72 ENG2 Unknown Unknown	HPT Blade No.36						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0137	72 ENG1 Unknown Unknown	HPT Blade No.37						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				
725201-0137	72 ENG2 Unknown Unknown	HPT Blade No.37						RE (O/C)			
						Mos	13-Oct-2011				
						Hrs	0				
						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0138		HPT Blade								RE (O/C)	
	72 ENG1	No.38					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0138		HPT Blade								RE (O/C)	
	72 ENG2	No.38					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0139		HPT Blade								RE (O/C)	
	72 ENG1	No.39					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0139		HPT Blade								RE (O/C)	
	72 ENG2	No.39					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0140		HPT Blade								RE (O/C)	
	72 ENG1	No.40					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0140		HPT Blade								RE (O/C)	
	72 ENG2	No.40					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0141		HPT Blade								RE (O/C)	
	72 ENG1	No.41					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0141		HPT Blade								RE (O/C)	
	72 ENG2	No.41					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0142		HPT Blade								RE (O/C)	
	72 ENG1	No.42					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0142		HPT Blade								RE (O/C)	
	72 ENG2	No.42					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
725201-0143		HPT Blade								RE (O/C)	
	72 ENG1	No.43					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
725201-0143	 72 ENG2 Unknown Unknown	HPT Blade No.43						RE (O/C)			
							Mos	13-Oct-2011			
							Hrs	0			
							Enc	0			
725501-0101	 72 ENG1 72704 HW32188 DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))	1st LP Turbine Disk New						RE		LMM - Life Limit	≈27-May-2038
							Mos	13-Oct-2011			
							Hrs	0			
							Enc	0	10,000	10,000	5,628 Enc
725501-0101	 72 ENG2 72704 HW32181 DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))	1st LP Turbine Disk New						RE		LMM - Life Limit	≈27-May-2038
							Mos	13-Oct-2011			
							Hrs	0			
							Enc	0	10,000	10,000	5,628 Enc
725501-0201	 72 ENG1 66993 HW31706 DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))	2nd LP Turbine Disk New						RE		LMM - Life Limit	≈27-May-2038
							Mos	13-Oct-2011			
							Hrs	0			
							Enc	0	10,000	10,000	5,628 Enc
725501-0201	 72 ENG2 66993 HW31727 DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202))	2nd LP Turbine Disk New						RE		LMM - Life Limit	≈27-May-2038
							Mos	13-Oct-2011			
							Hrs	0			
							Enc	0	10,000	10,000	5,628 Enc
72-NXT1-D11	 72 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE ACCESSORIES - Inspect all for security and installation. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	163:50 Hrs (+40)
							Ldg	10,886			
72-NXT1-D12	 72 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - FUEL LINES AND HYDRAULIC LINES - Inspect for loose fittings, chafing, deterioration, wear, routing and evidence of damage. 05-20-12						RE		ICA	≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	563:50 Hrs (+40)
							Ldg	10,886			
72-NXT1-D15	 72 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - ELECTRICAL HARNESS - Inspect connectors, terminals and wires for condition, chafing, security and routing. Refer to chapter 71 of this supplement. 05-20-12						RE		ICA	≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	563:50 Hrs (+40)
							Ldg	10,886			
72-NXT1-D17	 72 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	LEFT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE MOUNTS Inspect for corrosion, damage, and deterioration and/or peeling of rubber isolators. (Engine removal is not necessary). 05-20-12						RE		ICA	≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	563:50 Hrs (+40)
							Ldg	10,886			
72-NXT1-E11	 72 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE ACCESSORIES - Inspect all for security and installation. 05-20-11						RE		ICA	
							Mos	11-Nov-2022	12	(30-Nov-2023)	57 Days
							Hrs	14814:28	400	+40	163:50 Hrs (+40)
							Ldg	10,886			
72-NXT1-E12	 72 A/F Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)	RIGHT- HAND POWER PLANT, PYLON AND NACELLE - FUEL LINES AND HYDRAULIC LINES - Inspect for loose fittings, chafing, deterioration, wear, routing and evidence of damage. 05-20-12						RE		ICA	≈24-Jun-2024
							Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	563:50 Hrs (+40)
							Ldg	10,886			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
72-NXT1-E15		RIGHT- HAND POWER PLANT, PYLON AND NACELLE - ELECTRICAL HARNESS - Inspect connectors, terminals and wires for condition, chafing, security and routing. Refer to chapter 71 of this supplement.							RE		ICA	≈24-Jun-2024
	72 A/F	05-20-12					Mos	11-Nov-2022				
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
			Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,886				
72-NXT1-E17		RIGHT- HAND POWER PLANT, PYLON AND NACELLE - ENGINE MOUNTS Inspect for corrosion, damage, and deterioration and/or peeling of rubber isolators. (Engine removal is not necessary).							RE		ICA	≈24-Jun-2024
	72 A/F	05-20-12					Mos	11-Nov-2022				
							Hrs	14814:28	800	+40	(15614:28)	563:50 Hrs (+40)
			Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)				Ldg	10,886				
72-TA-01		INDICATOR, LATCHING, DEL P, OIL FILTER							RE (-)			
	72 ENG1 115015 KM0910						Mos	06-May-2022				
							Hrs					
							Enc					
72-TA-01		INDICATOR, LATCHING, DEL P, OIL FILTER							RE (-)			
	72 ENG2 115015 KM1743						Mos	05-May-2022				
							Hrs					
							Enc					
Engine 1		Williams International - FJ44-3AP							RE (-)			
	72 A/F 111000-202 252709	Time at install:					Mos					
							Hrs					
							Ldg					
Engine 2		Williams International - FJ44-3AP							RE (-)			
	72 A/F 111000-202 252710	Time at install:					Mos					
							Hrs					
							Ldg					
FJ44-05-002 Rev 4		Engine - Unserviceable Parts - Notification							RE (-)	Informational		
	72 ENG1 Eff: 01-Oct-2019 Not Applicable (UPDATE NOTE: NA by P/N) (NOTE: COMPLIANCE: Engines previously in compliance with this service document are compliant with this revision and do not need to perform this revision.)						Mos	16-Dec-2019				
							Hrs	5246:04				
							Enc	3,175				
FJ44-05-002 Rev 4		Engine - Unserviceable Parts - Notification							RE (-)	Informational		
	72 ENG2 Eff: 01-Oct-2019 Not Applicable (UPDATE NOTE: NA by P/N) (NOTE: COMPLIANCE: Engines previously in compliance with this service document are compliant with this revision and do not need to perform this revision.)						Mos	16-Dec-2019				
							Hrs	5246:04				
							Enc	3,175				
FJ44-05-002 Rev 5		Engine - Unserviceable Parts - Notification (This Service Document has been Superseded by WIPSID-05-1000)							RE (-)	Informational		
	72 ENG1 Eff: 24-Mar-2020 Not Applicable (UPDATE NOTE: This Service Document has been superseded by WIPSID-05-1000.)						Mos	17-Aug-2020				
							Hrs	5735:47				
							Enc	3,483				
FJ44-05-002 Rev 5		Engine - Unserviceable Parts - Notification (This Service Document has been Superseded by WIPSID-05-1000)							RE (-)	Informational		
	72 ENG2 Eff: 24-Mar-2020 Not Applicable (UPDATE NOTE: This Service Document has been superseded by WIPSID-05-1000.)						Mos	17-Aug-2020				
							Hrs	5735:47				
							Enc	3,483				
FJ44-72-108 R1		Engine - Accessory Drive Shaft - Replace							T (A/R)	Recommended		
	72 ENG1 Eff: 03-Oct-2014 Deferred Next CSI						Mos	30-Jul-2018				
							Hrs	12216				
							Enc	9,275				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
FJ44-72-108 R1	Engine - Accessory Drive Shaft - Replace						T (A/R)		Recommended	
 72 ENG2					Mos	30-Jul-2018				
Eff: 03-Oct-2014 Deferred	Next CSI				Hrs	12216				
					Enc	9,275				
FJ44-72-113 R1	Engine - Case and Insert Assembly - Replace						T (A/R)		Recommended	
 72 ENG1					Mos	30-Jul-2018				
Eff: 27-Mar-2014 Deferred	Next CSI				Hrs	12216				
					Enc	9,275				
FJ44-72-113 R1	Engine - Case and Insert Assembly - Replace						T (A/R)		Recommended	
 72 ENG2					Mos	30-Jul-2018				
Eff: 27-Mar-2014 Deferred	Next CSI				Hrs	12216				
					Enc	9,275				
FJ44-72-118	Engine - 1st LP Heatshield/Nozzle Housing Assembly - Repetitive Inspection						RE (-)		Mandatory	
 72 ENG1					Mos	06-Jul-2017				
Eff: 12-Mar-2014 Cancelled	Cancelled due to installing new P/N 123407 on both engines				Hrs	11398				
					Enc	8,758				
FJ44-72-118	Engine - 1st LP Heatshield/Nozzle Housing Assembly - Repetitive Inspection						RE (-)		Mandatory	
 72 ENG2					Mos	06-Jul-2017				
Eff: 12-Mar-2014 Cancelled	Cancelled due to installing new P/N 123407 on both engines				Hrs	11398				
					Enc	8,758				
FJ44-72-130 R1	Engine - HP Compressor Rotor - Inspection						RE (-)		Recommended	
 72 ENG1					Mos	30-Jul-2018				
Eff: 08-May-2017 Complied	Rev 1 - Updated accomplishments instructions				Hrs	12216				
With	Next CSI				Enc	9,275				
(AVG MAN HRS: 4)										
FJ44-72-130 R1	Engine - HP Compressor Rotor - Inspection						RE (-)		Recommended	
 72 ENG2					Mos	30-Jul-2018				
Eff: 08-May-2017 Complied	Rev 1 - Updated accomplishments instructions				Hrs	12216				
With	Next CSI				Enc	9,275				
(AVG MAN HRS: 4)										
FJ44-72-132 R2	Engine - 1st LP Heatshield/Nozzle Housing Assembly - Replace						RE (-)		Mandatory	
 72 ENG1					Mos	30-Jul-2018				
Eff: 07-Oct-2016 Complied	Completion of this SB, eliminates the requirements to continue inspections per SB FJ44-72-118				Hrs	12216				
With					Enc	9,275				
FJ44-72-132 R2	Engine - 1st LP Heatshield/Nozzle Housing Assembly - Replace						RE (-)		Mandatory	
 72 ENG2					Mos	30-Jul-2018				
Eff: 07-Oct-2016 Complied	Completion of this SB, eliminates the requirements to continue inspections per SB FJ44-72-118				Hrs	12216				
With					Enc	9,275				
SL44-71-067	Engine - Bird Ingestion - Precautions						RE (-)		Service Letter	
 72 ENG1					Mos					
Eff: 27-Apr-2006					Hrs					
					Enc					
SL44-71-067	Engine - Bird Ingestion - Precautions						RE (-)		Service Letter	
 72 ENG2					Mos					
Eff: 27-Apr-2006					Hrs					
					Enc					
SL44-71-067 Rev 1	Engine - Bird Ingestion - Precautions						RE (-)		Service Letter	
 72 ENG1					Mos					
					Hrs					
					Enc					

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
SL44-71-067 Rev 1  72 ENG2	Engine - Bird Ingestion - Precautions						RE (-)		Service Letter	
										Mos
										Hrs
										Enc
SL44-71-067 Rev 2  72 ENG1 Eff: 27-Jan-2020	Engine - Bird Ingestion - Precautions						T (A/R)		Service Letter	
										Mos
										Hrs
										Enc
SL44-71-067 Rev 2  72 ENG2 Eff: 27-Jan-2020	Engine - Bird Ingestion - Precautions						T (A/R)		Service Letter	
										Mos
										Hrs
										Enc
WIPSID-72-1018  72 ENG1 Eff: 23-Mar-2020	Engine - Second Person Verification Requirements						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1018  72 ENG2 Eff: 23-Mar-2020	Engine - Second Person Verification Requirements						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1019  72 ENG1 Eff: 24-Mar-2020	Engine - Revision to Illustrated Parts Catalog						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1019  72 ENG2 Eff: 24-Mar-2020	Engine - Revision to Illustrated Parts Catalog						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1022  72 ENG1 Eff: 11-Sep-2020	Engine - Operating in Areas of Smoke						T (-)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1022  72 ENG2 Eff: 11-Sep-2020	Engine - Operating in Areas of Smoke						T (-)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1022 Rev 1  72 ENG1 Eff: 09-Jun-2023 (NOTE: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.)	Engine - Operating in Areas of Smoke						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1022 Rev 1  72 ENG2 Eff: 09-Jun-2023 (NOTE: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.)	Engine - Operating in Areas of Smoke						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1025  72 ENG1 Eff: 03-Feb-2021	Engine - Case and Insert Assembly - Revision to Illustrated Parts Catalog						T (A/R)		Informational	
										Mos
										Hrs
										Enc
WIPSID-72-1025  72 ENG2 Eff: 03-Feb-2021	Engine - Case and Insert Assembly - Revision to Illustrated Parts Catalog						T (A/R)		Informational	
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
WIPSID-72-1026	Engine - Fan Case - Rub Indications						T (A/R)		Informational	
 72 ENG1										
Eff: 13-Apr-2021										
WIPSID-72-1026	Engine - Fan Case - Rub Indications						T (A/R)		Informational	
 72 ENG2										
Eff: 13-Apr-2021										
WISB-72-1001 Rev 1	Engine - 1.5 Bearing Inner Race Retainer - Replace						T (-)		Recommended	≈15-Sep-2026
 72 ENG1										
Deferred										
WISB-72-1001 Rev 1	Engine - 1.5 Bearing Inner Race Retainer - Replace						RE (-)		Recommended	≈28-Jul-2026
 72 ENG2										
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection.)										
WISB-72-1021	Engine - 2nd Reduction Pinion Bearing Housing - Replace						T (-)		Recommended	≈06-May-2027
 72 ENG2										
(NOTE: APPLICABILITY: Engines Which Require 2500 Hour Interval.)										
WISB-72-1021 Rev 1	Engine - 2nd Reduction Pinion Bearing Housing - Replace						RE (-)		Recommended	
 72 ENG1										
Eff: 28-Jun-2021 Not Applicable	N/A by SN of engine					17-Aug-2021				
						6442:25				
(UPDATE NOTE: N/A by SN of engine)						3,889				
WISB-72-1021 Rev 1	Engine - 2nd Reduction Pinion Bearing Housing - Replace						T (-)		Recommended	≈06-May-2027
 72 ENG2										
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at Compressor Section Inspection (CSI) or as directed by Williams International.)										
WISB-72-1021 Rev 2	Engine - 2nd Reduction Pinion Bearing Housing - Replace						RE (-)		Recommended	
 72 ENG1										
Eff: 16-Dec-2021 Not Applicable	N/A by S/N									
WISB-72-1021 Rev 2	Engine - 2nd Reduction Pinion Bearing Housing - Replace						T		Recommended	≈06-May-2027
 72 ENG2										
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at Compressor Section Inspection (CSI) or as directed by Williams International.)							4,000	+50	[10000]	2800:59 Hrs (+50)
WISB-72-1022	Engine - Gearbox Assembly Ports - Identify						T		Recommended	≈28-Jul-2026
 72 ENG1										
(NOTE: APPLICABILITY: Engines Which Require 2500 Hour Interval.)										
WISB-72-1037	Engine - Accessory Drive Towershaft - Replace						RE (-)		Recommended	
 72 ENG1										
Eff: 09-Dec-2019 Superseded						10-Jan-2021				
(UPDATE NOTE: Superseded by revision 1)						6092:48				
						3,685				
WISB-72-1037	Engine - Accessory Drive Towershaft - Replace						RE (-)		Recommended	
 72 ENG2										
Eff: 09-Dec-2019 Superseded						10-Jan-2021				
(UPDATE NOTE: Superseded by revision 1)						6092:48				
						3,685				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
WISB-72-1037 Rev 1	Engine - Accessory Drive Towershaft - Replace								T (-)	Recommended
 72 ENG1						Mos	11-Jan-2021			
Deferred	Accidentally C/W					Hrs				
	(NOTE: COMPLIANCE: This service document should be complied with at the next Compressor Section Inspection (CSI).)					Enc				
WISB-72-1037 Rev 1	Engine - Accessory Drive Towershaft - Replace								T (-)	Recommended
 72 ENG2						Mos	11-Jan-2021			
Deferred	Accidentally C/W					Hrs				
	(NOTE: COMPLIANCE: This service document should be complied with at the next Compressor Section Inspection (CSI).)					Enc				
WISB-72-1037 Rev 2	Engine - Accessory Drive Towershaft - Replace								T	Recommended
 72 ENG1						Mos	03-May-2021			≈15-Sep-2026
						Hrs	0	9,500	+50	9500 2300:59 Hrs (+50)
						Enc				
WISB-72-1037 Rev 2	Engine - Accessory Drive Towershaft - Replace								T	Recommended
 72 ENG2						Mos	03-May-2021			≈15-Sep-2026
						Hrs	0	9,500	+50	9500 2300:59 Hrs (+50)
						Enc				
WISB-72-1037 Rev 3	Engine - Accessory Drive Towershaft - Replace								T (-)	Recommended
 72 ENG1						Mos				
						Hrs				
	(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc				
WISB-72-1037 Rev 3	Engine - Accessory Drive Towershaft - Replace								T (-)	Recommended
 72 ENG2						Mos				
						Hrs				
	(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc				
WISB-72-1037 Rev 4	Engine - Accessory Drive Towershaft - Replace								T	Recommended
 72 ENG1						Mos				≈15-Sep-2026
						Hrs		4,000	+50	[9500] 2300:59 Hrs (+50)
	(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc				
WISB-72-1037 Rev 4	Engine - Accessory Drive Towershaft - Replace								T	Recommended
 72 ENG2						Mos				≈15-Sep-2026
						Hrs		4,000	+50	[9500] 2300:59 Hrs (+50)
	(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc				
WISB-72-1041	Engine - Heat Exchanger Clamp Assembly - Replace								RE (-)	Recommended
 72 ENG1						Mos	06-May-2022			
Complied With						Hrs	6771:07			
	(NOTE: COMPLIANCE: This service document should be complied with at the next-scheduled Major Periodic Inspection.)					Enc	4,099			
WISB-72-1041	Engine - Heat Exchanger Clamp Assembly - Replace								RE (-)	Recommended
 72 ENG2						Mos	05-May-2022			
Complied With						Hrs	6771:07			
	(NOTE: COMPLIANCE: This service document should be complied with at the next-scheduled Major Periodic Inspection.)					Enc	4,099			
WISB-72-1041 Rev 1	Engine - Heat Exchanger Clamp Assembly - Replace								T (-)	Recommended
 72 ENG1						Mos	19-Aug-2021			
Not Applicable						Hrs				
	(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)					Enc				

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
WISB-72-1041 Rev 1	Engine - Heat Exchanger Clamp Assembly - Replace						T (-)		Recommended	
 72 ENG2						Mos 19-Aug-2021				
Not Applicable						Hrs				
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1041 Rev 2	Engine - Heat Exchanger Clamp Assembly - Replace						RE (-)		Recommended	
 72 ENG1						Mos				
Not Applicable						Hrs				
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1041 Rev 2	Engine - Heat Exchanger Clamp Assembly - Replace						RE (-)		Recommended	
 72 ENG2						Mos				
Not Applicable						Hrs				
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1041 Rev 3	Engine - Heat Exchanger Clamp Assembly - Replace						RE (-)		Recommended	
 72 ENG1						Mos 27-Jan-2023				
Declined						Hrs				
(UPDATE NOTE: Aircraft in compliance with previous revision) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1041 Rev 3	Engine - Heat Exchanger Clamp Assembly - Replace						RE (-)		Recommended	
 72 ENG2						Mos 27-Jan-2023				
Declined						Hrs				
(UPDATE NOTE: Aircraft in compliance with previous revision) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1041 Rev 4	Engine - Heat Exchanger Clamp Assembly - Replace						RE (-)		Recommended	
 72 ENG1						Mos 27-Jan-2023				
Declined						Hrs		+50		
(UPDATE NOTE: Aircraft in compliance with previous revision) (NOTE: EFFECTIVITY: Refer to Par.1.A. of this SB for the affected engine part number. COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1041 Rev 4	Engine - Heat Exchanger Clamp Assembly - Replace						RE (-)		Recommended	
 72 ENG2						Mos 27-Jan-2023				
Declined						Hrs		+50		
(UPDATE NOTE: Aircraft in compliance with previous revision) (NOTE: EFFECTIVITY: Refer to Par.1.A. of this SB for the affected engine part number. COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next scheduled Major Periodic Inspection.)						Enc				
WISB-72-1044	Engine - Balance Piston - Replace						T		Recommended	≈15-Sep-2026
 72 ENG1						Mos 03-May-2021				
						Hrs 0	9,500	+50	9500	2300:59 Hrs (+50)
						Enc				
WISB-72-1044	Engine - Balance Piston - Replace						T		Recommended	≈15-Sep-2026
 72 ENG2						Mos 03-May-2021				
						Hrs 0	9,500	+50	9500	2300:59 Hrs (+50)
						Enc				
WISB-72-1044 Rev 1	Engine - Balance Piston - Replace						T (-)		Recommended	≈15-Sep-2026
 72 ENG1						Mos				
						Hrs			[9500]	2300:59 Hrs
(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
WISB-72-1044 Rev 1  72 ENG2	Engine - Balance Piston - Replace						T (-)		Recommended	≈15-Sep-2026
	(NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)				Mos					
					Hrs				[9500]	2300:59 Hrs
					Enc					
WISB-72-1044 Rev 2  72 ENG1	Engine - Balance Piston - Replace						RE (-)		Recommended	
	(NOTE: EFFECTIVITY: Refer to Par. 1.A of this SB.				Mos					
	COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)				Hrs					
					Enc					
WISB-72-1044 Rev 2  72 ENG2	Engine - Balance Piston - Replace						RE (-)		Recommended	
	(NOTE: EFFECTIVITY: Refer to Par. 1.A of this SB.				Mos					
	COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)				Hrs					
					Enc					
WISB-72-1044 Rev 3  72 ENG1	Engine - Balance Piston - Replace						T		Recommended	≈15-Sep-2026
	(NOTE: EFFECTIVITY: Refer to Par.1.A. of this SB for the affected Engine Part Numbers.				Mos					
	COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)				Hrs		4,000	+50	[9500]	2300:59 Hrs (+50)
					Enc					
WISB-72-1044 Rev 3  72 ENG2	Engine - Balance Piston - Replace						T		Recommended	≈15-Sep-2026
	(NOTE: EFFECTIVITY: Refer to Par.1.A. of this SB for the affected Engine Part Numbers.				Mos					
	COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)				Hrs		4,000	+50	[9500]	2300:59 Hrs (+50)
					Enc					
WISB-72-1055  72 ENG1 Eff: 10-Mar-2023 Not Applicable	Engine - No. 1 Carbon Seal - Replacement						RE (-)		Recommended	
					Mos	02-May-2023				
					Hrs					
					Enc					
WISB-72-1055  72 ENG2 Eff: 10-Mar-2023 Not Applicable	Engine - No. 1 Carbon Seal - Replacement						RE (-)		Recommended	
					Mos	02-May-2023				
					Hrs					
					Enc					
WISL-05-1020  72 ENG1 Eff: 06-Mar-2020	Time Limits/Maintenance Checks - Scheduled Maintenance Checks - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
					Mos					
					Hrs					
					Enc					
WISL-05-1020  72 ENG2 Eff: 06-Mar-2020	Time Limits/Maintenance Checks - Scheduled Maintenance Checks - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
					Mos					
					Hrs					
					Enc					
WISL-72-1128  72 ENG1 Eff: 23-Mar-2020	Engine - Fan Rotor - Revision To Line Maintenance Manual						T (A/R)		Service Letter	
					Mos					
					Hrs					
					Enc					
WISL-72-1128  72 ENG2 Eff: 23-Mar-2020	Engine - Fan Rotor - Revision To Line Maintenance Manual						T (A/R)		Service Letter	
					Mos					
					Hrs					
					Enc					
WISL-72-1132  72 ENG1 Eff: 06-Apr-2020	Engine - Approved Engine Fuels - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
					Mos					
					Hrs					
					Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
WISL-72-1132	Engine - Approved Engine Fuels - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
 72 ENG2						Mos				
Eff: 06-Apr-2020						Hrs				
						Enc				
WISL-72-1140	Engine - Induction Heating - Revision to Engine Manual						T (A/R)		Service Letter	
 72 ENG1						Mos				
Eff: 22-Jun-2020						Hrs				
						Enc				
WISL-72-1140	Engine - Induction Heating - Revision to Engine Manual						T (A/R)		Service Letter	
 72 ENG2						Mos				
Eff: 22-Jun-2020						Hrs				
						Enc				
WISL-72-1262	Engine - Approved Engine Fuel - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
 72 ENG1						Mos				
Eff: 15-Dec-2022						Hrs				
(NOTE: EFFECTIVITY: This document applies to Williams International turbofan engines with Engine Part number identified in Par.1.A. of this SL.)						Enc				
WISL-72-1262	Engine - Approved Engine Fuel - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
 72 ENG2						Mos				
Eff: 15-Dec-2022						Hrs				
(NOTE: EFFECTIVITY: This document applies to Williams International turbofan engines with Engine Part number identified in Par.1.A. of this SL.)						Enc				
▼ 73 - ENGINE - FUEL AND CONTROL										
05-20-00-814A-300A-A-3.1	Fuel Delivery Unit (FDU) - Overhaul						RE		LMM - Requirement	≈10-Sep-2033
 73 ENG1						Mos	24-Aug-2022			
119149						Hrs	6952:56	8,000	+100	14952:56 7753:55 Hrs (+100)
CL8APU1050						Enc	4,223			
(SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-3.1	Fuel Delivery Unit (FDU) - Overhaul						RE		LMM - Requirement	≈08-Jan-2032
 73 ENG2						Mos	27-Jul-2020			
119148						Hrs	5645:16	8,000	+100	13645:16 6446:15 Hrs (+100)
CL8ATW0053						Enc	3,432			
(UPDATE NOTE: Adjusting CAMO due to missing engine information.) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-7.1.06	Check the overboard fuel drain ports for fuel leakage.						RE (A/R)		LMM - Requirement	
 73 ENG1	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	7199:01			
Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,372			
05-20-00-814A-300A-A-7.1.06	Check the overboard fuel drain ports for fuel leakage.						RE (A/R)		LMM - Requirement	
 73 ENG2	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	7199:01			
Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,372			
05-20-00-814A-300A-A-7.1.07	Use EMT to interrogate FADEC for operational limit exceedances. Resolve applicable exceedances, as required before returning the engine to service.						RE		LMM - Requirement	≈08-Oct-2023
 73 ENG1	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
						Hrs	6920:56	300	-/+30	≈7206:51
Ref:73-26-01-201 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,201			
05-20-00-814A-300A-A-7.1.07	Use EMT to interrogate FADEC for operational limit exceedances. Resolve applicable exceedances, as required before returning the engine to service.						RE		LMM - Requirement	≈08-Oct-2023
 73 ENG2	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
						Hrs	6920:56	300	-/+30	≈7206:51
Ref:73-26-01-201 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,201			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
05-20-00-814A-300A-A-7.1.09	Use EMT to Save Engine and FADEC data and send to Williams International								RE	LMM - Requirement ≈08-Oct-2023
73 ENG1	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
	Ref:73-26-01-201 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
05-20-00-814A-300A-A-7.1.09	Use EMT to Save Engine and FADEC data and send to Williams International								RE	LMM - Requirement ≈08-Oct-2023
73 ENG2	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
	Ref:73-26-01-201 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
05-20-00-814A-300A-A-7.1.11	Visually inspect and clean fuel start nozzle and start nozzle adapter								RE	LMM - Requirement ≈08-Oct-2023
73 ENG1	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
	Ref:73-12-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)					Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
05-20-00-814A-300A-A-7.1.11	Visually inspect and clean fuel start nozzle and start nozzle adapter								RE	LMM - Requirement ≈08-Oct-2023
73 ENG2	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
	Ref:73-12-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)					Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
05-20-00-814A-300A-A-7.1.12	Check fuel start nozzle spray pattern								RE	LMM - Requirement ≈08-Oct-2023
73 ENG1	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
	Ref:73-12-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)					Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
05-20-00-814A-300A-A-7.1.12	Check fuel start nozzle spray pattern								RE	LMM - Requirement ≈08-Oct-2023
73 ENG2	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
	Ref:73-12-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)					Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
05-20-00-814A-300A-A-7.1.19	Change fuel pump filter								RE	LMM - Requirement ≈02-Mar-2024
73 ENG1	05-20-00-814A-300A-A-1.5					Mos	26-Jul-2022			
	Ref:73-14-01-401 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs	6920:56	600	+30	(7520:56) 321:55 Hrs (+30)
						Enc	4,201			
05-20-00-814A-300A-A-7.1.19	Change fuel pump filter								RE	LMM - Requirement ≈02-Mar-2024
73 ENG2	05-20-00-814A-300A-A-1.5					Mos	26-Jul-2022			
	Ref:73-14-01-401 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs	6920:56	600	+30	(7520:56) 321:55 Hrs (+30)
						Enc	4,201			
05-20-00-814A-300A-A-7.1.23	Perform PMA Phase Out Test on FADEC and FDU								RE	LMM - Requirement ≈02-Mar-2024
73 ENG1	05-20-00-814A-300A-A-1.5					Mos	26-Jul-2022			
	Ref:73-26-01-201 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs	6920:56	600	+30	(7520:56) 321:55 Hrs (+30)
						Enc	4,201			
05-20-00-814A-300A-A-7.1.23	Perform PMA Phase Out Test on FADEC and FDU								RE	LMM - Requirement ≈02-Mar-2024
73 ENG2	05-20-00-814A-300A-A-1.5					Mos	26-Jul-2022			
	Ref:73-26-01-201 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs	6920:56	600	+30	(7520:56) 321:55 Hrs (+30)
						Enc	4,201			
05-20-00-814A-300A-A-7.1.24	(Rental Engine Only) Replace FDU-to-flowmeter fuel tube assembly and flowmeter-to-manifold fuel tube assembly								RE (N/A)	LMM - Requirement
73 ENG1						Mos				
	Ref:73-10-01-401 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
05-20-00-814A-300A-A-7.1.24	(Rental Engine Only) Replace FDU-to-flowmeter fuel tube assembly and flowmeter-to-manifold fuel tube assembly						RE (N/A)		LMM - Requirement	
73 ENG2										
	Ref:73-10-01-401 (SOURCE: FJ44-3AP LMM (P/N 111000-202))									
730000-0101	HMU						RE (O/C)			
73 A/F						21-Nov-2000				
Unknown						0				
Unknown						0				
730000-0201	Fuel Low Pressure Switch						RE (O/C)			
73 A/F	Left					21-Nov-2000				
Unknown						0				
Unknown						0				
730000-0202	Fuel Low Pressure Switch						RE (O/C)			
73 A/F	Right					21-Nov-2000				
Unknown						0				
Unknown						0				
731005-0101	Nozzle Assy Fuel						RE (O/C)			
73 ENG1						13-Oct-2011				
Unknown						0				
Unknown						0				
731005-0101	Nozzle Assy Fuel						RE (O/C)			
73 ENG2						13-Oct-2011				
Unknown						0				
Unknown						0				
731030-0101	Motive Flow Valve						RE (O/C)			
73 ENG1						13-Oct-2011				
Unknown						0				
Unknown						0				
731030-0101	Motive Flow Valve						RE (O/C)			
73 ENG2						13-Oct-2011				
Unknown						0				
Unknown						0				
732001-0101	Fuel Delivery Unit (FDU)						RE			≈10-Sep-2033
73 ENG1						24-Aug-2022				
119149		0				6952:56	8,000	+100	14952:56	7753:55 Hrs (+100)
CL8APU1050						4,223				
732001-0102	Fuel Delivery Unit (FDU)						RE			≈22-Oct-2024
73 ENG2		0				06-Jun-2012				
119148		02:12				20:43	8,000	+100	[8018:31]	819:30 Hrs (+100)
CL8ATW0053		12				19				
732002-0101	Elec Fuel Filter Indicator						RE (O/C)			
73 ENG1						05-May-2022				
57847	New					0				
GE6704						0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
732002-0101	Elec Fuel Filter Indicator								RE (O/C)	
73 ENG2						Mos	05-May-2022			
57847	New					Hrs	1857:06			
GE7861						Enc	810			
732012-0101	Fuel Manifold Assembly								RE (O/C)	LMM - Life Limit
73 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Critical Non-Life Limited Parts)										
732012-0101	Fuel Manifold Assembly								RE (O/C)	LMM - Life Limit
73 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
DMC:FJ-AAA-05-10-00-810A-042A-A (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: Critical Non-Life Limited Parts)										
732013-0101	Seal and Fuel Slinger Assembly								RE (O/C)	
73 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
732013-0101	Seal and Fuel Slinger Assembly								RE (O/C)	
73 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
73-2013-09 Rev A	Nextant - Fuel Inlet Port Inspection								RE (-)	Mandatory
73 A/F						Mos	28-Nov-2013			
Eff: 30-Jun-2013 Complied	C/W iaw SB instructions iaw Williams SB FJ44-73-050 R1					Hrs	8722			
With						Ldg	7,201			
732016-0101	Seal & Fuel Slinger Assembly-Rear								RE (O/C)	
73 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
732016-0101	Seal & Fuel Slinger Assembly-Rear								RE (O/C)	
73 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
732101-0101	Full Authority Digital Electronic Control (FADEC)								RE (O/C)	
73 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
732101-0101	Full Authority Digital Electronic Control (FADEC)								RE (O/C)	
73 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
733000-0101	Fuel Flow Transmitter								RE (O/C)	
73 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
733000-0102		Fuel Flow Transmitter								RE (O/C)	
	73 A/F	Right					Mos	07-Aug-2019			
	1/2-1-81-302	Overhauled					Hrs	12849:36			
	515255						Ldg	9,675			
733000-0201		Fuel Totalizer Condtioner								RE (O/C)	
	73 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
73-NXT1-C1		AFT FUSELAGE - AFT EQUIPMENT SHELF and INSTALLED EQUIPMENT - Lower the aft equipment hinged shelf assembly and conduct a visual inspection of the FADEC Airframe Interface Boxes and Bleed Air Temperature Controllers for security, electrical cable routing, and overall general condition.								RE	ICA ≈24-Jun-2024
	73 A/F	05-20-12					Mos	11-Nov-2022			
							Hrs	14814:28	800	+40	(15614:28) 563:50 Hrs (+40)
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)					Ldg	10,886			
73-NXT1-C2		AFT FUSELAGE - LH FADEC UNITS - Visually inspect the FADEC units for security, electrical cable routing, and overall general condition.								RE	ICA
	73 A/F	05-20-11					Mos	11-Nov-2022	12		(30-Nov-2023) 57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)					Ldg	10,886			
73-NXT1-C2		AFT FUSELAGE - RH FADEC UNITS - Visually inspect the FADEC units for security, electrical cable routing, and overall general condition.								RE	ICA
	73 A/F	05-20-11					Mos	11-Nov-2022	12		(30-Nov-2023) 57 Days
							Hrs	14814:28	400	+40	(15214:28) 163:50 Hrs (+40)
		Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST02371LA)					Ldg	10,886			
FJ44-73-044 R4		Engine Fuel And Control - Fuel Delivery Unit Replace								T (-)	Mandatory
	73 ENG2						Mos				
							Hrs				
							Enc				
FJ44-73-044 R5		Engine Fuel And Control - Fuel Delivery Unit Replace								RE (-)	Mandatory
	73 ENG1						Mos	19-May-2017			
	Eff: 14-Jun-2016 Complied With	already accomplished on both engines (s/n 252709, 252710) by Williams Int. on 6.6.2012 - see rev 4					Hrs				
		252710) by Williams Int. on 6.6.2012 - see rev 4					Enc				
		(AVG MAN HRS: 9)									
FJ44-73-044 R5		Engine Fuel And Control - Fuel Delivery Unit Replace								RE (-)	Mandatory
	73 ENG2						Mos	19-May-2017			
	Eff: 14-Jun-2016 Complied With	already accomplished on both engines (s/n 252709, 252710) by Williams Int. on 6.6.2012 - see rev 4					Hrs				
		252710) by Williams Int. on 6.6.2012 - see rev 4					Enc				
		(AVG MAN HRS: 9)									
FJ44-73-044 R6		Engine Fuel and Control - Fuel Delivery Unit Replace								RE (-)	Mandatory
	73 ENG1						Mos				
	Eff: 16-Mar-2017	This revision has no effect on engs. previously in compliance with this SB. See rev 5					Hrs				
	(AVG MAN HRS: 9)						Enc				
FJ44-73-044 R8		Engine Fuel and Control - Fuel Delivery Unit - Replace								RE (-)	Mandatory
	73 ENG1						Mos	16-Dec-2019			
	Not Applicable						Hrs	5246:04	+30		
	(AVG MAN HRS: 9) (UPDATE NOTE: NA by P/N) (NOTE: COMPLIANCE: This service bulletin is MANDATORY and should be accomplished at the next scheduled Routine Periodic Inspection (Check 1 or Check 2, whichever comes first) when the engine has accumulated more than 1200 operating hours, unless otherwise directed by Williams International. COMPLIANCE: This service document is accomplished if P/N 119148, 119149, or subsequent part number FDUs (reference the appropriate Illustrated Part Catalog) are installed. COMPLIANCE: Engines previously in compliance with this service document are compliant with this revision and do not need to perform this revision.)						Enc	3,175			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
FJ44-73-044 R8		Engine Fuel and Control - Fuel Delivery Unit - Replace						RE (-)		Mandatory	
	73 ENG2					Mos	16-Dec-2019				
	Not Applicable					Hrs	5246:04		+30		
	(AVG MAN HRS: 9) (UPDATE NOTE: NA by P/N) (NOTE: COMPLIANCE: This service bulletin is MANDATORY and should be accomplished at the next scheduled Routine Periodic Inspection (Check 1 or Check 2, whichever comes first) when the engine has accumulated more than 1200 operating hours, unless otherwise directed by Williams International.					Enc	3,175				
	COMPLIANCE: This service document is accomplished if P/N 119148, 119149, or subsequent part number FDUs (reference the appropriate Illustrated Part Catalog) are installed.										
	COMPLIANCE: Engines previously in compliance with this service document are compliant with this revision and do not need to perform this revision.)										
FJ44-73-046 R5		Engine Fuel and Control - Fuel Delivery Unit - Replace						RE (-)		Mandatory	
	73 ENG1					Mos	13-Dec-2018				
	Eff: 09-Nov-2018 Not Applicable	N/A by engines S/N				Hrs					
						Enc					
FJ44-73-049		Engine Fuel and Control - Fuel Filter & Filter Bowl - Inspection						RE (-)		Mandatory	
	73 ENG1					Mos	25-Apr-2013				
	Eff: 24-Apr-2013 Not Applicable	N/A by engines S/N				Hrs					
	(AVG MAN HRS: 1.5)					Enc					
FJ44-73-049		Engine Fuel and Control - Fuel Filter & Filter Bowl - Inspection						RE (-)		Mandatory	
	73 ENG2					Mos	25-Apr-2013				
	Eff: 24-Apr-2013 Not Applicable	N/A by engines S/N				Hrs					
	(AVG MAN HRS: 1.5)					Enc					
FJ44-73-050 R1		FCW - Oil - Lube Oil Cooler Fuel Inlet Port - Inspection						RE (-)		Mandatory	
	73 ENG1					Mos	04-Jul-2013				
	Eff: 01-Jul-2013 Complied With	C/W iaw SB instructions				Hrs	8384				
						Enc	6,996				
FJ44-73-050 R1		FCW - Oil - Lube Oil Cooler Fuel Inlet Port - Inspection						RE (-)		Mandatory	
	73 ENG2					Mos	04-Jul-2013				
	Eff: 01-Jul-2013 Complied With	C/W iaw SB instructions				Hrs	8384				
						Enc	6,996				
FJ44-73-060 R2		Engine Fuel and Control - FADEC Software Upload of CP416.03.01						RE (-)		Mandatory	
	73 ENG1					Mos					
	Complied With	if cannot be completed during next inspection, perform no later than next MPI				Hrs	10488				
						Enc	8,220				
FJ44-73-060 R2		Engine Fuel and Control - FADEC Software Upload of CP416.03.01						RE (-)		Mandatory	
	73 ENG2					Mos					
	Complied With	if cannot be completed during next inspection, perform no later than next MPI				Hrs	10488				
						Enc	8,220				
FJ44-73-060 R3		Engine Fuel and Control - FADEC Software Upload of CP416.03.01						RE (-)		Mandatory	
	73 ENG1					Mos					
	Eff: 22-Jan-2016 Complied With	already performed - see rev 2				Hrs					
						Enc					
FJ44-73-060 R3		Engine Fuel and Control - FADEC Software Upload of CP416.03.01						RE (-)		Mandatory	
	73 ENG2					Mos					
	Eff: 22-Jan-2016 Complied With	already performed - see rev 2				Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
WISB-73-1009 Rev 3	Engine Fuel and Control - Fuel Tube Assemblies - Replace						T (-)		Recommended	≈28-Jul-2026
 73 ENG1						Mos				
	(AVG MAN HRS: 1) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with when material is available during the next scheduled Compressor Section Inspection.)					Hrs			[9395:48]	2196:47 Hrs
						Enc				
WISB-73-1009 Rev 3	Engine Fuel and Control - Fuel Tube Assemblies - Replace						T (-)		Recommended	≈28-Jul-2026
 73 ENG2						Mos				
	(AVG MAN HRS: 1) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with when material is available during the next scheduled Compressor Section Inspection.)					Hrs			[9395:48]	2196:47 Hrs
						Enc				
WISB-73-1019	Engine Fuel and Control - Engine Maintenance Terminal (EMT) Software Upgrade to CP356.12.01						T (A/R)		Service Bulletin	
 73 ENG1						Mos				
Eff: 26-May-2021						Hrs				
						Enc				
WISB-73-1019	Engine Fuel and Control - Engine Maintenance Terminal (EMT) Software Upgrade to CP356.12.01						T (A/R)		Service Bulletin	
 73 ENG2						Mos				
Eff: 26-May-2021						Hrs				
						Enc				
WISB-73-1022	Engine Fuel and Control - Engine Maintenance Terminal (EMT) Software Upgrade to CP356.12.01						T (A/R)		Service Bulletin	
 73 ENG1						Mos				
Eff: 14-Jul-2021						Hrs				
						Enc				
WISB-73-1022	Engine Fuel and Control - Engine Maintenance Terminal (EMT) Software Upgrade to CP356.12.01						T (A/R)		Service Bulletin	
 73 ENG2						Mos				
Eff: 14-Jul-2021						Hrs				
						Enc				
WISL-73-1026	Engine Controls - EMT Communication Tooling - Revision to the Line Maintenance Manual						RE (-)		Service Letter	
 73 ENG1						Mos	16-Dec-2019			
Eff: 27-Sep-2019 Complied With						Hrs	5246:04			
						Enc	3,175			
WISL-73-1026	Engine Controls - EMT Communication Tooling - Revision to the Line Maintenance Manual						RE (-)		Service Letter	
 73 ENG2						Mos	16-Dec-2019			
Eff: 27-Sep-2019 Complied With						Hrs	5246:04			
						Enc	3,175			
WISL-73-1037	Engine Fuel and Control - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
 73 ENG1						Mos				
Eff: 18-Sep-2020						Hrs				
						Enc				
WISL-73-1037	Engine Fuel and Control - Revision to Line Maintenance Manual						T (A/R)		Service Letter	
 73 ENG2						Mos				
Eff: 18-Sep-2020						Hrs				
						Enc				
▼ 74 - IGNITION										
05-20-00-814A-300A-A-7.1.13	Remove and visually inspect the igniter plug						RE		LMM - Requirement	≈08-Oct-2023
 74 ENG1	Inboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
Unknown						Hrs	6920:56	300	+30	≈7206:51
Unknown						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
05-20-00-814A-300A-A-7.1.13	Remove and visually inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG2	Inboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
Unknown						Hrs	6920:56	300	+30	#7206:51
Unknown						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-7.1.13	Remove and visually inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG1	Outboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
68032						Hrs	6920:56	300	+30	#7206:51
CK1201361						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-7.1.13	Remove and visually inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG2	Outboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
68032						Hrs	6920:56	300	+30	#7206:51
CK1400687						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-7.1.14	Dimensionally inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG1	Inboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
Unknown						Hrs	6920:56	300	+30	#7206:51
Unknown						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)										
05-20-00-814A-300A-A-7.1.14	Dimensionally inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG2	Inboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
Unknown						Hrs	6920:56	300	+30	#7206:51
Unknown						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)										
05-20-00-814A-300A-A-7.1.14	Dimensionally inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG1	Outboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
68032						Hrs	6920:56	300	+30	#7206:51
CK1201361						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)										
05-20-00-814A-300A-A-7.1.14	Dimensionally inspect the igniter plug								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG2	Outboard05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
68032						Hrs	6920:56	300	+30	#7206:51
CK1400687						Enc	4,201			
Ref:74-22-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202)) (NOTE: (1) If parts are replaced/exchanged with new or certified-serviceable parts, inspection tasks do not need to be accomplished.)										
05-20-00-814A-300A-A-7.1.15	Do an operational test on the ignition system after inspection and reinstallation of the igniter plugs								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG1	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
						Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
Ref:74-00-10-501 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-7.1.15	Do an operational test on the ignition system after inspection and reinstallation of the igniter plugs								RE	LMM - Requirement ≈08-Oct-2023
 74 ENG2	05-20-00-814A-300A-A-1.4,...					Mos	26-Jul-2022			
						Hrs	6920:56	300	+30	#7206:51
						Enc	4,201			
Ref:74-00-10-501 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
741001-0101		Ignition Exciter								RE (O/C)	
	74 ENG1	Inboard					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
741001-0101		Ignition Exciter								RE (O/C)	
	74 ENG2	Inboard					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
741001-0102		Ignition Exciter								RE (O/C)	
	74 ENG1	Outboard					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
741001-0102		Ignition Exciter								RE (O/C)	
	74 ENG2	Outboard					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
741004-0101		Igniter Plug								RE (O/C)	
	74 ENG1	Inboard					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
741004-0101		Igniter Plug								RE (O/C)	
	74 ENG2	Inboard					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
741004-0102		Igniter Plug								RE (O/C)	
	74 ENG1	Outboard					Mos	01-Apr-2013			
	68032	New					Hrs	395:06			
	CK1201361						Enc	267			
741004-0102		Igniter Plug								RE (O/C)	
	74 ENG2	Outboard					Mos	01-Aug-2014			
	68032	New					Hrs	1493:06			
	CK1400687						Enc	881			
742003-0101		Short Igniter Lead Assy								RE (O/C)	
	74 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
742003-0101		Short Igniter Lead Assy								RE (O/C)	
	74 ENG2						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
742003-0102		Long Igniter Lead Assy								RE (O/C)	
	74 ENG1						Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
742003-0102	Long Igniter Lead Assy						RE (O/C)			
 74 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
WISB-74-1004 Rev 2	Ignition - Igniter Lead - Replace						RE (-)		Recommended	
 74 ENG1						Mos	13-Jun-2023			
Eff: 01-Jul-2021 Not Applicable	N/A by engine SN					Hrs				
(AVG MAN HRS: 0.5)						Enc				
WISB-74-1004 Rev 2	Ignition - Igniter Lead - Replace						RE (-)		Recommended	
 74 ENG2						Mos	13-Jun-2023			
Eff: 01-Jul-2021 Not Applicable	N/A by engine SN					Hrs				
(AVG MAN HRS: 0.5)						Enc				
▼ 75 - BLEED AIR										
05-20-00-814A-300A-A-7.1.21	Inspect acceleration bleed system						RE		LMM - Requirement	≈02-Mar-2024
 75 ENG1	05-20-00-814A-300A-A-1.5					Mos	26-Jul-2022			
						Hrs	6920:56	600	+30 (7520:56)	321:55 Hrs (+30)
Ref:75-30-01-601 (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,201			
05-20-00-814A-300A-A-7.1.21	Inspect acceleration bleed system						RE		LMM - Requirement	≈02-Mar-2024
 75 ENG2	05-20-00-814A-300A-A-1.5					Mos	26-Jul-2022			
						Hrs	6920:56	600	+30 (7520:56)	321:55 Hrs (+30)
Ref:75-30-01-601 (SOURCE: FJ44-3AP LMM (P/N 111000-202))						Enc	4,201			
755000-0101	HP Diverter Valve						RE (O/C)			
 75 ENG1						Mos	05-May-2022			
118651	New					Hrs	1984:59			
WL20016						Enc	1,389			
755000-0101	HP Diverter Valve						RE (O/C)			
 75 ENG2						Mos	25-Nov-2020			
118651						Hrs	5978:51			
WL20075						Enc	3,626			
FJ44-75-003	Air - Precooler/Duct Assembly - Replace						RE (-)		Recommended	
 75 ENG1						Mos	30-Jul-2018			
Eff: 16-Mar-2016 Deferred	"covered by TAP elitenext MPI not later than CSI"					Hrs	12216			
						Enc	9,275			
FJ44-75-003	Air - Precooler/Duct Assembly - Replace						RE (-)		Recommended	
 75 ENG2						Mos	30-Jul-2018			
Eff: 16-Mar-2016 Deferred	"covered by TAP elitenext MPI not later than CSI"					Hrs	12216			
						Enc	9,275			
SL44-75-009	Air-HP bleed diverter valve actuator motor brushes						RE (-)			
 75 ENG1						Mos				
Eff: 01-Jan-2001 Complied With	"Diverter valve assy p/n 118651, s/n WL20031 installed on Dec 2014 with TSN=687, CSN= 403. A/C hour at that time TH= 9678, TC=7741"					Hrs				
						Enc				
SL44-75-009	Air-HP bleed diverter valve actuator motor brushes						RE (-)			
 75 ENG2						Mos				
Eff: 01-Jan-2001 Complied With	"Diverter valve assy p/n 118651, s/n WL20031 installed on Dec 2014 with TSN=687, CSN= 403. A/C hour at that time TH= 9678, TC=7741"					Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
WISB-75-1001		Air - I.P. Bleed Valve Lever Pin - Replace						RE (-)		Recommended	
	75 ENG1					Mos					
	Eff: 17-May-2018					Hrs					
	(AVG MAN HRS: 0.1)					Enc					
WISB-75-1001		Air - I.P. Bleed Valve Lever Pin - Replace						RE (-)		Recommended	
	75 ENG2					Mos					
	Eff: 17-May-2018					Hrs					
	(AVG MAN HRS: 0.1)					Enc					
WISB-75-1001 Rev 1		Air - I.P. Bleed Valve Lever Pin - Replace						RE (-)		Recommended	
	75 ENG1					Mos					
						Hrs					
	(AVG MAN HRS: 0.1) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc					
WISB-75-1001 Rev 1		Air - I.P. Bleed Valve Lever Pin - Replace						RE (-)		Recommended	
	75 ENG2					Mos					
						Hrs					
	(AVG MAN HRS: 0.1) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc					
WISB-75-1001 Rev 2		Air - I.P. Bleed Valve Lever Pin - Replace						T		Recommended	≈15-Sep-2026
	75 ENG1					Mos	19-Aug-2021				
						Hrs		4,000	+50	[9500]	2300:59 Hrs (+50)
	(AVG MAN HRS: 0.1) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc					
WISB-75-1001 Rev 2		Air - I.P. Bleed Valve Lever Pin - Replace						T		Recommended	≈15-Sep-2026
	75 ENG2					Mos	19-Aug-2021				
						Hrs		4,000	+50	[9500]	2300:59 Hrs (+50)
	(AVG MAN HRS: 0.1) (NOTE: COMPLIANCE: This service document is RECOMMENDED and should be complied with at the next Compressor Section Inspection (CSI).)					Enc					
▼ 76 - ENGINE CONTROLS											
760000-0101		Engine Vibrator						RE (O/C)			
	76 A/F					Mos	21-Nov-2000				
	Unknown					Hrs		0			
	Unknown					Ldg		0			
760000-0201		Throttle Quadrant						RE (O/C)			
	76 A/F					Mos	21-Nov-2000				
	Unknown					Hrs		0			
	Unknown					Ldg		0			
761004-0101		RVDT						RE (O/C)			
	76 ENG1					Mos	13-Oct-2011				
	Unknown					Hrs		0			
	Unknown					Enc		0			
761004-0101		RVDT						RE (O/C)			
	76 ENG2					Mos	13-Oct-2011				
	Unknown					Hrs		0			
	Unknown					Enc		0			
76-NXT1-A1		PILOT COMPARTMENT - THRUST LEVER QUADRANT - Inspect for security, installation, thrust lever movement and adjustment, friction adjusting control and evidence of damage.						RE		ICA	≈10-Jul-2024
	76 A/F	05-20-13				Mos	12-May-2021				
						Hrs	14049:30	1,600	+40	(15649:30)	598:52 Hrs (+40)
	Ref:NXT1-ICA Ch.05 (SOURCE: FAA STC ST023711A)					Ldg	10,401				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
771001-0102		ITT Probe									
	76 ENG1	No.2					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0102		ITT Probe									
	76 ENG2	No.2					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0103		ITT Probe									
	76 ENG1	No.3					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0103		ITT Probe									
	76 ENG2	No.3					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0104		ITT Probe									
	76 ENG1	No.4					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0104		ITT Probe									
	76 ENG2	No.4					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0105		ITT Probe									
	76 ENG1	No.5					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0105		ITT Probe									
	76 ENG2	No.5					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0106		ITT Probe									
	76 ENG1	No.6					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
771001-0106		ITT Probe									
	76 ENG2	No.6					Mos	13-Oct-2011			
	Unknown						Hrs	0			
	Unknown						Enc	0			
WISL-76-1001		Engine Controls - Visually Inspect the LP Shaft Trip Sensor System - Revision to the Line Maintenance Manual									
	76 ENG1						Mos	16-Dec-2019		RE (-)	Service Letter
	Eff: 02-Oct-2019 Complied With						Hrs	5246:04			
	(NOTE: NOTE: To revise the shrink tubing inspection in TASK 76-20-01-220-801, prior to being incorporated into the applicable Line Maintenance Manual.)						Enc	3,175			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
WISL-76-1001		Engine Controls - Visually Inspect the LP Shaft Trip Sensor System - Revision to the Line Maintenance Manual						RE (-)		Service Letter	
	76 ENG2						Mos	16-Dec-2019			
	Eff: 02-Oct-2019 Complied With						Hrs	5246:04			
	(NOTE: NOTE: To revise the shrink tubing inspection in TASK 76-20-01-220-801, prior to being incorporated into the applicable Line Maintenance Manual.)						Enc	3,175			
▼ 77 - ENGINE INDICATING											
770000-0101		Vibration Signal Conditioner						RE (O/C)			
	77 A/F						Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0201		Sensor Vibration						RE (O/C)			
	77 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0202		Sensor Vibration						RE (O/C)			
	77 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0301		Turbine RPM Indicator						RE (O/C)			
	77 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0302		Turbine RPM Indicator						RE (O/C)			
	77 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0401		Fan RPM Indicator						RE (O/C)			
	77 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0402		Fan RPM Indicator						RE (O/C)			
	77 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0501		ITT Indicator						RE (O/C)			
	77 A/F	Left					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
770000-0502		ITT Indicator						RE (O/C)			
	77 A/F	Right					Mos	21-Nov-2000			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
771000-0101	Engine N1 (Fan) Indicator									
77 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
771000-0102	Engine N1 (Fan) Indicator									
77 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
771000-0201	Engine N2 (Turbine) Indicator									
77 A/F	No.1					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
771000-0202	Engine N2 (Turbine) Indicator									
77 A/F	No.2					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
771001-0101	ITT Probe									
77 ENG1	No.1					Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
771001-0101	ITT Probe									
77 ENG2	No.1					Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
771001-0101	N1 Dual Magnetic Speed Sensor									
77 ENG1						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
771001-0101	N1 Dual Magnetic Speed Sensor									
77 ENG2						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
771002-0101	N2 Dual Magnetic Speed Sensor									
77 ENG1						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
771002-0101	N2 Dual Magnetic Speed Sensor									
77 ENG2						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
771003-0101	TT2/PT2 Dual Pressure/Temperature Sensor									
77 ENG1						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
771003-0101	TT2/PT2 Dual Pressure/Temperature Sensor								RE (O/C)	
 77 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
772002-0101	ITT Harness Assembly								RE (O/C)	
 77 ENG1						Mos	05-May-2022			
75378	New					Hrs	0			
EMX004667						Enc	0			
772002-0101	ITT Harness Assembly								RE (O/C)	
 77 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
77-2013-12-A	Nextant - LH Engine Temperature Sensor Connector Orientation								RE (-)	
 77 A/F						Mos	01-Aug-2014			
Eff: 25-Jun-2014 Complied With	C/W iaw SB instructions					Hrs	9314			
						Ldg	7,512			
773000-0101	Engine Vibration Indicator								RE (O/C)	
 77 A/F						Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
774000-0101	A-Channel Airframe FADEC Harness								RE (O/C)	
 77 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
774000-0101	A-Channel Airframe FADEC Harness								RE (O/C)	
 77 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
774000-0102	B-Channel Airframe FADEC Harness								RE (O/C)	
 77 ENG1						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
774000-0102	B-Channel Airframe FADEC Harness								RE (O/C)	
 77 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
FJ44-77-013	Engine Indicating - FADEC Engine Harness Assembly - Rework								RE (-)	Recommended
 77 ENG1						Mos				
Eff: 20-Jun-2015						Hrs				
						Enc				
FJ44-77-013	Engine Indicating - FADEC Engine Harness Assembly - Rework								RE (-)	Recommended
 77 ENG2						Mos				
Eff: 20-Jun-2015						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
FJ44-77-013 R1	77 ENG1	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R1	77 ENG2	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R2	77 ENG1	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R2	77 ENG2	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R3	77 ENG1	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R3	77 ENG2	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R4	77 ENG1	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R4	77 ENG2	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R5	77 ENG1	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R5	77 ENG2	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R6	77 ENG1	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R6	77 ENG2	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
FJ44-77-013 R7	77 ENG1 Eff: 09-May-2016	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
FJ44-77-013 R7	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
 77 ENG2						Mos				
Eff: 09-May-2016						Hrs				
						Enc				
FJ44-77-013 R8	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
 77 ENG1						Mos				
Eff: 15-Nov-2018 Deferred	covered by TAP elite when performed in Williams Int Repair Station					Hrs				
	Next MPI					Enc				
FJ44-77-013 R8	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
 77 ENG2						Mos				
Eff: 15-Nov-2018 Deferred	covered by TAP elite when performed in Williams Int Repair Station					Hrs				
	Next MPI					Enc				
FJ44-77-013 R9	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
 77 ENG1						Mos				
Eff: 17-Jan-2019						Hrs				
						Enc				
FJ44-77-013 R9	Engine Indicating - FADEC Engine Harness Assembly - Rework						RE (-)		Recommended	
 77 ENG2						Mos				
Eff: 17-Jan-2019						Hrs				
						Enc				
▼ 79 - OIL										
05-20-00-814A-300A-A-3.2	Lube and Scavenge Pump - Overhaul						RE		LMM - Requirement	≈27-Sep-2026
 79 ENG1						Mos	12-Sep-2018			
125142						Hrs	4525:24	5,000	+100	9525:24 2326:23 Hrs (+100)
MX30005						Enc				
(SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-3.2	Lube and Scavenge Pump - Overhaul						RE		LMM - Requirement	≈27-Sep-2026
 79 ENG2						Mos	12-Sep-2018			
125142						Hrs	4525:24	5,000	+100	9525:24 2326:23 Hrs (+100)
MX21328						Enc				
(SOURCE: FJ44-3AP LMM (P/N 111000-202))										
05-20-00-814A-300A-A-7.1.03	Check the oil filter differential pressure (delta p) indicator. If indicator is illuminated or if mechanical button is extended, referto troubleshooting.						RE (A/R)		LMM - Requirement	
 79 ENG1	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	7199:01			
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372			
05-20-00-814A-300A-A-7.1.03	Check the oil filter differential pressure (delta p) indicator. If indicator is illuminated or if mechanical button is extended, referto troubleshooting.						RE (A/R)		LMM - Requirement	
 79 ENG2	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	7199:01			
	Ref:AFM (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372			
05-20-00-814A-300A-A-7.1.04	Check the oil level and add oil as required.						RE (A/R)		LMM - Requirement	
 79 ENG1	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	7199:01			
	Ref:72-00-03-301 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372			
05-20-00-814A-300A-A-7.1.04	Check the oil level and add oil as required.						RE (A/R)		LMM - Requirement	
 79 ENG2	05-20-00-814A-300A-A-1.1					Mos	16-Aug-2023		(31-Aug-2023)	OVD
						Hrs	7199:01			
	Ref:72-00-03-301 (SOURCE: FJ44-3AP LMM (P/N 111000-202))					Enc	4,372			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-20-00-814A-300A-A-7.1.10		Install new oil filter						RE		LMM - Requirement	≈08-Oct-2023
	79 ENG1	05-20-00-814A-300A-A-1.4,...				Mos	26-Jul-2022				
		Ref: 79-21-01-401 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))				Hrs	6920:56	300	+30	#7206:51	
						Enc	4,201				
05-20-00-814A-300A-A-7.1.10		Install new oil filter						RE		LMM - Requirement	≈08-Oct-2023
	79 ENG2	05-20-00-814A-300A-A-1.4,...				Mos	26-Jul-2022				
		Ref: 79-21-01-401 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))				Hrs	6920:56	300	+30	#7206:51	
						Enc	4,201				
05-20-00-814A-300A-A-7.1.16		Remove and inspect magnetic chip collectors						RE		LMM - Requirement	≈08-Oct-2023
	79 ENG1	05-20-00-814A-300A-A-1.4,...				Mos	26-Jul-2022				
		Ref: 79-30-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))				Hrs	6920:56	300	+30	#7206:51	
						Enc	4,201				
05-20-00-814A-300A-A-7.1.16		Remove and inspect magnetic chip collectors						RE		LMM - Requirement	≈08-Oct-2023
	79 ENG2	05-20-00-814A-300A-A-1.4,...				Mos	26-Jul-2022				
		Ref: 79-30-01-601 (Tol. Adjustment: -14.1 Hrs) (SOURCE: FJ44-3AP LMM (P/N 111000-202))				Hrs	6920:56	300	+30	#7206:51	
						Enc	4,201				
790000-0101		Oil Pressure Indicator						RE (O/C)			
	79 A/F	Left				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
790000-0102		Oil Pressure Indicator						RE (O/C)			
	79 A/F	Right				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
790000-0201		Oil Temperature Sensor						RE (O/C)			
	79 A/F	Left				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
790000-0202		Oil Temperature Sensor						RE (O/C)			
	79 A/F	Right				Mos	21-Nov-2000				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
790001-0101		Lube and Scavenge Pump						RE (O/C)			
	79 ENG1					Mos	12-Sep-2018				
	125142					Hrs	4525:24				
	MX30005					Enc					
790001-0101		Lube and Scavenge Pump						RE (O/C)			
	79 ENG2					Mos	12-Sep-2018				
	125142					Hrs	4525:24				
	MX21328					Enc					
791007-0101		Cover, Oil Tank						RE (O/C)			
	79 ENG1					Mos	13-Oct-2011				
	Unknown					Hrs	0				
	Unknown					Enc	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
791007-0101	Cover, Oil Tank						RE (O/C)			
 79 ENG2						Mos	13-Oct-2011			
Unknown						Hrs	0			
Unknown						Enc	0			
79-2012-05	Nextant - Oil Filter By-Pass Annunciator Fails to indicate Filter By-Pass						RE (-)		Mandatory	
 79 A/F						Mos	29-Nov-2012			
Eff: 26-Nov-2012 Complied C/W iaw SB						Hrs	7921			
With						Ldg	6,721			
792201-0101	Engine Oil Cooler						RE (O/C)			
 79 ENG1						Mos	12-May-2021			
121535						Hrs	6197:53			
PP1470						Enc	3,745			
792201-0101	Engine Oil Cooler						RE (O/C)			
 79 ENG2						Mos	12-May-2021			
121535						Hrs	6197:53			
PP1138						Enc	3,745			
792201B	Remove the Oil Cooler (P/N 121535 allowable alternate P/N 110718) and send to Nextant Aerospace for inspection and Flushing						RE			≈24-Jun-2024
 79 ENG1						Mos	11-Nov-2022			
121535						Hrs	6962:51	800	+40	7762:51 563:50 Hrs (+40)
PP1470						Enc	4,230			
792201B	Remove the Oil Cooler (P/N 121535 allowable alternate P/N 110718) and send to Nextant Aerospace for inspection and Flushing						RE			≈24-Jun-2024
 79 ENG2						Mos	11-Nov-2022			
121535						Hrs	6962:51	800	+40	7762:51 563:50 Hrs (+40)
PP1138						Enc	4,230			
793000-0101	Oil Pressure Transmitter						RE (O/C)			
 79 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
793000-0102	Oil Pressure Transmitter						RE (O/C)			
 79 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
793000-0201	Oil Pressure Switch						RE (O/C)			
 79 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
793000-0202	Oil Pressure Switch						RE (O/C)			
 79 A/F	Right					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			
793000-0301	Engine Oil Pressure Filter Switch						RE (O/C)			
 79 A/F	Left					Mos	21-Nov-2000			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
793000-0302	Engine Oil Pressure Filter Switch									
 79 A/F	Right					Mos	21-Nov-2000		RE (O/C)	
Unknown						Hrs	0			
Unknown						Ldg	0			
793508-0101	Oil Pressure Electrical Delta P Sensor									
 79 ENG1						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
793508-0101	Oil Pressure Electrical Delta P Sensor									
 79 ENG2						Mos	13-Oct-2011		RE (O/C)	
Unknown						Hrs	0			
Unknown						Enc	0			
FJ44-79-012	Oil - Lube Oil Cooler - Rework or Replace								RE (-)	Recommended
 79 ENG1						Mos	30-Jul-2018			
Eff: 20-Mar-2014 Deferred	Next CSI					Hrs	12216			
						Enc	9,275			
FJ44-79-012	Oil - Lube Oil Cooler - Rework or Replace								RE (-)	Recommended
 79 ENG2						Mos	30-Jul-2018			
Eff: 20-Mar-2014 Deferred	Next CSI					Hrs	12216			
						Enc	9,275			
FJ44-79-014	Oil - Oil Filler Cap Assembly - Replace								RE (-)	Mandatory
 79 ENG1						Mos	21-Aug-2015			
Eff: 19-Jan-2015 Complied	C/W iaw SB					Hrs				
With						Enc	8,048			
FJ44-79-014	Oil - Oil Filler Cap Assembly - Replace								RE (-)	Mandatory
 79 ENG2						Mos	21-Aug-2015			
Eff: 19-Jan-2015 Complied	C/W iaw SB					Hrs				
With						Enc	8,048			
FJ44-79-014 R1	Oil - Oil Filler Cap Assembly - Replace								RE (-)	Mandatory
 79 ENG1						Mos				
Eff: 11-Aug-2015 Complied	Already complied with original issue of the SB					Hrs				
With						Enc				
FJ44-79-014 R1	Oil - Oil Filler Cap Assembly - Replace								RE (-)	Mandatory
 79 ENG2						Mos				
Eff: 11-Aug-2015 Complied	Already complied with original issue of the SB					Hrs				
With						Enc				
FJ44-79-016 R3	Oil - Relief Valve Assembly - Replace								RE (-)	Recommended
 79 ENG1						Mos				
Eff: 28-Apr-2017 Not	N/A per S/N					Hrs				
Applicable						Enc				
(AVG MAN HRS: 1)										
FJ44-79-016 R3	Oil - Relief Valve Assembly - Replace								RE (-)	Recommended
 79 ENG2						Mos				
Eff: 28-Apr-2017 Not	N/A per S/N					Hrs				
Applicable						Enc				
(AVG MAN HRS: 1)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 98 - --											
SA-2012-02		Nextant - Engine Forebody Assembly - Crack from Hi-Lock Fasteners, Inner Barrel						RE (-)		Service Letter	
	98 A/F					Mos	29-Nov-2012				
	Eff: 30-Jan-2012 Complied With	C/W iaw SB, no cracks found				Hrs	7921				
						Ldg	6,721				
SA-2012-02 Rev A											
SA-2012-02 Rev A		Nextant - Engine Forebody Assembly - Crack from Hi-Lock Fasteners, Inner Barrel						RE (-)		Service Letter	
	98 A/F					Mos					
	Eff: 30-Jan-2012					Hrs					
						Ldg					
SA-2013-02 Rev B											
SA-2013-02 Rev B		Nextant - Engine Forebody Assembly - Crack from Hi-Lock Fasteners, Inner Barrel						RE (-)		Service Letter	
	98 A/F					Mos	20-Mar-2013				
	Eff: 21-Mar-2013 Not Applicable	N/A by S/N				Hrs					
						Ldg					
SA-2014-01											
SA-2014-01		Nextant - Engine Forebody Assembly - Inner Barrel Inlet Missing Fasteners in the Row Just Aft of the Inlet LIP Information						RE (-)			
	98 A/F					Mos					
	Eff: 22-Apr-2014	Operator's info - if any missing failed or loose fastener found on engine forebody assy inner barrel inlet				Hrs					
						Ldg					
▼ 100 - GENERAL											
2001-24-11		AFM - Emergency Procedures Section - Loss of Airspeed						RE (-)		Mandatory	
	100 A/F					Mos					
	Eff: 11-Dec-2001					Hrs					
						Ldg					
2006-21-02		Operating Limitations, Abnormal Procedures, and Normal Procedures						RE (-)		Mandatory	
	100 A/F					Mos					
	Eff: 25-Oct-2006					Hrs					
						Ldg					
93-01-08		Airplane Flight Manual (AFM) Revision						RE (-)		Mandatory	
	100 A/F					Mos					
	Eff: 04-Mar-1993					Hrs					
	(NOTE: Within 30 days after the effective date of this AD, revise the Limitations Section of the FAA-approved BEECHJET 400 Airplane Flight Manual by inserting the new pages contained in the BEECHJET 400 Airplane Flight Manual, A9 Revision, part number 128-590001-13A9, dated August 14, 1992.)					Ldg					
CF-58-02		Radio Equipment Installed Directly Under an Engine Fuel Primer in Aircraft Must Be Relocated Owing to Fire Hazard (This cancels Airworthiness Directive 51-4)						T (A/R)		Mandatory	
	100 A/F					Mos					
						Hrs					
	(NOTE: COMPLIANCE: Compliance with this Directive is effective immediately for all aircraft affected by this order.)					Ldg					