



Maintenance Next Due Report

Report Created On: 11 May 2026

Sorted by: Due Date

Includes recurring service information

^ Due Flag Indicates Items Due Within Standard Projection

Gulfstream Aerospace Corporation

G650

OK-EVO

S/N: 6160

Regulation: EU-EASA

Airworthiness Date: 24 Aug 2015

Phone: +1 912-298-1325

Fax: 1-912-963-0265/1-800-944-1775

Analyst: Duane Gerdes

| Airframe & Component Times | | | | | Total Time | |
|----------------------------|----------|--|------------|-------------|------------|--------|
| Logbook | Position | Description | Serial No. | Log Date | Hours | Cycles |
| Airframe | | GULFSTREAM AEROSPACE CORPORATION G650 | 6160 | 23 Mar 2026 | 3046.1 | 1117 |
| Engine | 1 | ROLLS-ROYCE DERBY PLC BR725A1-12 (G650) | 26163 | 23 Mar 2026 | 994.4 | 392 |
| Engine | 2 | ROLLS-ROYCE DERBY PLC BR725A1-12 (G650) | 26162 | 23 Mar 2026 | 994.4 | 392 |
| APU | | HONEYWELL RE220(GVI) | P-269 | 23 Mar 2026 | 2266.5 | 0 |

| Projected Through 11 May 2029 | |
|----------------------------------|--------|
| Hours | Cycles |
| 4126.1 | 2197 |
| 2074.4 | 1472 |
| 2074.4 | 1472 |
| 2986.5 | 360 |

| | | |
|--|--|--|
| The Next Scheduled Hourly Item is due at 1200 Hrs (205.6 ~(+50) Hrs Rem), Logbook: Engine, ATA: 792106 | The Next Scheduled Cycle Item is due at 1525 Cyc (408 Cyc Rem), Logbook: Airframe, ATA: 530017 | The Next Scheduled Calendar Item is due at 24 May 2026 (13d Rem), Logbook: Airframe, ATA: 313032 |
|--|--|--|

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|--|---------------|-----------------|------|------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | Revision | Date Issued | | | | | | | | |
| 313032 | Cockpit Voice Recorder (Cvr) - Inspect the Cvr Installation (EASA EUROCAE) | | | | HRS | 2909.1 | | | | | 24 May 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 01 Dec 2025 | 6 | 24 May 2026 | | 13d^ | |
| 315101^U | Blue Disc - Planeview System Charts - Update | | | | HRS | 3048.1 | | | | | 27 May 2026 |
| Airframe | Notes: CHARTS 14-2024 | | | | AFL | 1119 | | | | | |
| | | | | | DATE | 06 May 2026 | 14d | 27 May 2026 | | 16d^ | |
| 573203 | Winglet Leading Edge (Right) - Polishing | | | | HRS | 2909.1 | | | | | 27 May 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 19 Dec 2025 | 6 | 27 May 2026 | 27 Jun 2026 | 16d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|--------------------------------------|--|---------------|---|-------------|--------------------------|----------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| CB324 (983240) Airframe | CB324 - Flight Controls (ATA 27) Replacement - Flight Control Computer (FCC) Channel A Com-Mon Modules, Customer Bulletin (Mandatory) Notes: | | G650_CB_324 | | HRS AFL MOS MSC | | 12** | 30 May 2026 | | 19d^ | 30 May 2026 |
| 545005 Airframe 4 | Pylon Leading Edge - Polishing Notes: | | G650 AMM_545005 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |
| 545006 Airframe 4 | Pylon Leading Edge (Right) - Polishing Notes: | | G650 AMM_545006 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |
| 551108 Airframe 4 | Horizontal Stabilizer Leading Edge (Left) - Polishing Notes: | | G650 AMM_551108 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |
| 553011 Airframe 4 | Vertical Stabilizer Leading Edge - Polishing Notes: | | G650 AMM_553011 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |
| 574010 Airframe 4 | Wing Leading Edge - Polishing Notes: | | G650 AMM_574010 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |
| 574011 Airframe 4 | Wing Leading Edge (Right) - Polishing Notes: | | G650 AMM_574011 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |
| 711108 Airframe 4 | Inlet Cowl Lipskin (Left) - Nonabrasive Polish Notes: | | G650 AMM_711108 20-50-00 4 24 30-Oct-24 | | HRS AFL MOS | 2909.1 1065 | | | | | 31 May 2026 |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|---------------|------------------|-------------|------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 711109 | Inlet Cowl Lipskin (Right) - Nonabrasive Polish | | G650 AMM_711109 | | HRS | 2909.1 | | | | | 31 May 2026 |
| Airframe 4 | Notes: | | 20-50-00 | 4 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 19 Dec 2025 | 6 | 31 May 2026 | 30 Jun 2026 | 20d (+30d)^ | |
| 923200^U | Brake Wear Indicators - Detail Inspection | | | | HRS | 3046.1 | | | | | 02 Jun 2026 |
| Airframe | Notes: | | | | AFL | 1117 | | | | | |
| | | | | | MOS | 20 Apr 2026 | 2 | 02 Jun 2026* | 02 Jul 2026 | 22d (+30d)^ | |
| 346025 | FMS Nav Database - Update | | | | HRS | 3048.1 | | | | | 11 Jun 2026 |
| Airframe | Notes: NAV cycle 2407 | | | | AFL | 1119 | | | | | |
| | | | | | DATE | 06 May 2026 | 28d | 11 Jun 2026 | | 31d^ | |
| 923400^U | Aircraft Health and Trend Monitoring Data Download and Analyze | | | | HRS | 3048.1 | | | | | 30 Jun 2026 |
| Airframe | Notes: | | | | AFL | 1119 | | | | | |
| | | | | | MOS | 06 May 2026 | 1 | 30 Jun 2026 | | 50d^ | |
| 256406 | First AID Kit (No. 1) Time Limited Supplies - Discard | AFAK 1.0 | G650 A0MM_256406 | | HRS | 2794.6 | | | | | 31 Aug 2026 |
| Airframe 3 | Notes: | 101515005 | 05-10-00 | 3 | AFL | 1022 | | | | | |
| | | | 33 | 19-Jan-23 | MOS | 01 Sep 2025 | 12 | 31 Aug 2026 | | 3m 20d^ | |
| 122202 | Main Landing Gear - Lubrication | | G650 AMM_122202 | | HRS | 3048.1 | | | | | 31 Aug 2026 |
| Airframe 83 | Notes: | | 05-20-00 | 83 | AFL | 1119 | | | | | |
| | | | 20 | 15-Oct-22 | MOS | 06 May 2026 | 4 | 31 Aug 2026* | 30 Sep 2026 | 3m 20d (+30d)^ | |
| 122204 | Nose Landing Gear - Lubrication | | G650 AMM_122204 | | HRS | 3048.1 | | | | | 31 Aug 2026 |
| Airframe 83 | Notes: | | 05-20-00 | 83 | AFL | 1119 | | | | | |
| | | | 20 | 15-Oct-22 | MOS | 06 May 2026 | 4 | 31 Aug 2026* | 30 Sep 2026 | 3m 20d (+30d)^ | |
| 280007 | Microbiological Contamination Test of Fuel Tank - Special Detail Inspection | | G650 AMM_280007 | | HRS | 3048.1 | | | | | 31 Aug 2026 |
| Airframe 95 | Notes: | | 05-20-00 | 95 | AFL | 1119 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 06 May 2026 | 4 | 31 Aug 2026* | 30 Sep 2026 | 3m 20d (+30d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|--------------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 256143 | Life Raft (No. 1) - Restore | 1320FAUL-6K4-1-904 | G650 AMM_256143 | | HRS | 2315.6 | | | | | 31 Oct 2026 |
| Airframe 5 | Notes: History on 256146 | 13UL-01602 | 05-10-00 5 | | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 36 | 31 Oct 2026 | | 5m 20d^ | |
| 256144 | Life Raft (No. 2) - Restore | 1320FAUL-6K4-1-904 | G650 AMM_256144 | | HRS | 2315.6 | | | | | 31 Oct 2026 |
| Airframe 5 | Notes: History on 256145 | 13UL-01603 | 05-10-00 5 | | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 36 | 31 Oct 2026 | | 5m 20d^ | |
| 262403 | Portable FIRE Extinguisher (Cockpit) - Weight Check | | G650 AMM_262403 | | HRS | 2909.1 | | | | | 31 Oct 2026 |
| Airframe 90 | Notes: PN: 898052 SN: <NONE>. MRI PARENT CODE: 262400 | | 05-20-00 90 | | AFL | 1065 | | | | | |
| | | | 21 | 15-May-23 | MOS | 05 Dec 2025 | 12 | 31 Oct 2026* | 30 Nov 2026 | 5m 20d (+30d)^ | |
| 262415 | Portable FIRE Extinguisher (Forward Cabin) - Weight Check | | G650 A0MM_262415 | | HRS | 2909.1 | | | | | 31 Oct 2026 |
| Airframe 3 | Notes: PN: C354TS SN: <NONE>. | | 05-20-00 3 | | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 05 Dec 2025 | 12 | 31 Oct 2026* | 30 Nov 2026 | 5m 20d (+30d)^ | |
| 262439 | Portable FIRE Extinguisher (Aft Lavatory) - Weight Check | | G650 AMM_262439 | | HRS | 2909.1 | | | | | 31 Oct 2026 |
| Airframe 15 | Notes: PN: B371 SN: <NONE>. | | 05-20-00 15 | | AFL | 1065 | | | | | |
| | | | 17 | 30-Apr-21 | MOS | 05 Dec 2025 | 12 | 31 Oct 2026* | 30 Nov 2026 | 5m 20d (+30d)^ | |
| 256147 | Life Raft (No. 1) - Detailed Inspection | | G650 A0MM_256147 | | HRS | 2909.1 | | | | | 25 Nov 2026 |
| Airframe 2 | Notes: | | 05-20-00 2 | | AFL | 1065 | | | | | |
| | | | 30 | 25-Apr-22 | MOS | 12 Dec 2025 | 12 | 25 Nov 2026* | 25 Dec 2026 | 6m 14d (+30d)^ | |
| 256148 | Life Raft (No. 2) - Detailed Inspection | | G650 A0MM_256148 | | HRS | 2909.1 | | | | | 25 Nov 2026 |
| Airframe 2 | Notes: | | 05-20-00 2 | | AFL | 1065 | | | | | |
| | | | 30 | 25-Apr-22 | MOS | 12 Dec 2025 | 12 | 25 Nov 2026* | 25 Dec 2026 | 6m 14d (+30d)^ | |
| 313033 | Flight Data Recorder (FDR) - Read-Out of Recorded Data (EASA ICAO) | | | | HRS | 2909.1 | | | | | 28 Nov 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 01 Dec 2025 | 12 | 28 Nov 2026* | | 6m 17d^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 256611 | FIRE / Crash Axe - Detailed Inspection | | G650 A0MM_256611 | | HRS | 2909.1 | | | | | 29 Nov 2026 |
| Airframe 2 | Notes: | | 05-20-00 | 2 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 01 Dec 2025 | 12 | 29 Nov 2026* | 29 Dec 2026 | 6m 18d (+30d)^ | |
| 243905 | Flight Control System Uninterruptible Power Supply Battery - Restore | | G650 AMM_243905 | | HRS | 2051.9 | | | | | 30 Nov 2026 |
| Airframe 4 | Notes: | | 05-10-00 | 4 | AFL | 725 | | | | | |
| | | | 20 | 15-Oct-22 | MOS | 07 Dec 2022 | 48 | 30 Nov 2026 | | 6m 19d^ | |
| 256307 | Emergency Locator Transmitter - Detailed Inspection | | G650 AMM_256307 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 88 | Notes: | | 05-20-00 | 88 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 02 Dec 2025 | 12 | 30 Nov 2026* | | 6m 19d^ | |
| 256309 | Emergency Locator Transmitter - Operational Check (FAR 91.207) | | G650 AMM_256309 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 89 | Notes: BATTERY EXPIRATION 10-2020 | | 05-20-00 | 89 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | 12 | 30 Nov 2026* | | 6m 19d^ | |
| 304119 | Windshield Surface Seal (Right) - Detailed Inspection | | G650 AMM_304119 | | HRS | 2909.1 | 600 | 3509.1 | | 463 | 30 Nov 2026 |
| Airframe 98 | Notes: | | 05-20-00 | 98 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | | 6m 19d^ | |
| 122500 | External Baggage Door - Lubrication | | G650 AMM_122500 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 84 | Notes: | | 05-20-00 | 84 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 04 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 122501 | Main Entrance Door - Lubrication | | G650 AMM_122501 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 84 | Notes: | | 05-20-00 | 84 | AFL | 1065 | | | | | |
| | | | 20 | 15-Oct-22 | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 237202 | Cockpit Voice Recorder System - Operational Check | | G650 AMM_237202 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 03 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 241212 | Idg Oil Cooler and Lines (Left) - General Visual Inspection | | G650 AMM_241212 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 03 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 241213 | Idg Oil Cooler and Lines (Right) - General Visual Inspection | | G650 AMM_241213 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 03 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 243404 | Main Battery (Left) - Restore | | G650 AMM_243404 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 87 | Notes: | | 05-20-00 | 87 | AFL | 1065 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 18 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 243405 | Main Battery (Right) - Restore | | G650 AMM_243405 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 87 | Notes: | | 05-20-00 | 87 | AFL | 1065 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 02 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 243500 | Emergency Battery Power System (Forward) - Operational Check | | G650 AMM_243500 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 87 | Notes: | | 05-20-00 | 87 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 243501 | Emergency Battery Power System (Aft) - Operational Check | | G650 AMM_243501 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 87 | Notes: | | 05-20-00 | 87 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 243607 | Electrical Backup Hydraulic Actuator Nicad Battery - Restore | | G650 AMM_243607 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 87 | Notes: | | 05-20-00 | 87 | AFL | 1065 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 01 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256006 | Flashlight (Observer) - Operational Check | | G650 A0MM_256006 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 2 | Notes: PN: FLOX43553 SN: <NONE>. | | 05-20-00 | 2 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 256007 | Flashlight (Pilot) - Operational Check | | G650 AMM_256007 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 88 | Notes: | | 05-20-00 88 | | AFL | 1065 | | | | | |
| | | | 12 | 30-Oct-19 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256014 | Flashlight (Copilot) - Operational Check | | G650 AMM_256014 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 88 | Notes: | | 05-20-00 88 | | AFL | 1065 | | | | | |
| | | | 12 | 30-Oct-19 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256015 | Flashlight (Baggage Compartment) - Operational Check | | G650 AMM_256015 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 88 | Notes: | | 05-20-00 88 | | AFL | 1065 | | | | | |
| | | | 12 | 30-Oct-19 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256181 | Life Vest(S) - Detailed Inspection | | G650 A0MM_256181 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 2 | Notes: | | 05-20-00 2 | | AFL | 1065 | | | | | |
| | | | 30 | 25-Apr-22 | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256296 | Smoke Hood Tamper-Evident Seals (Aft Lavatory) - Detailed Inspection | | | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe | Notes: PN: MR-10039N SN: <NONE>. | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256404 | First AID Kit (No. 1) - Detailed Inspection | | G650 A0MM_256404 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 2 | Notes: PN: AFAK SN: 101515005. | | 05-20-00 2 | | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 01 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 256418 | Defibrillator - Detailed Inspection | | G650 A0MM_256418 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 2 | Notes: PN: 502861 SN: <NONE>. | | 05-20-00 2 | | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 262402 | Portable FIRE Extinguisher (Cockpit) - Detailed Inspection | | G650 AMM_262402 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 90 | Notes: PN: 898052 SN: <NONE>. | | 05-20-00 90 | | AFL | 1065 | | | | | |
| | | | 21 | 15-May-23 | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 262414 | Portable FIRE Extinguisher (Forward Cabin) - Detailed Inspection | | G650 A0MM_262414 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 2 | Notes: PN: C354TS SN: <NONE>. | | 05-20-00 | 2 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 262438 | Portable FIRE Extinguisher (Aft Lavatory) - Detailed Inspection | | G650 AMM_262438 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 15 | Notes: PN: B371 SN: <NONE>. | | 05-20-00 | 15 | AFL | 1065 | | | | | |
| | | | 17 | 30-Apr-21 | MOS | 05 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 262450 | Portable Water FIRE Extinguisher - Detailed Inspection | | G650 A0MM_262450 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 3 | Notes: PN: 892480 SN: <NONE>. | | 05-20-00 | 3 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 04 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 262500 | Trash Receptacle Enclosure (Forward Lavatory) - Detailed Inspection | | G650 A0MM_262500 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 3 | Notes: | | 05-20-00 | 3 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 18 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 262501 | Trash Receptacle Enclosure (Forward Galley / Annex) - Detailed Inspection | | G650 A0MM_262501 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 3 | Notes: | | 05-20-00 | 3 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 18 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 262505 | Trash Receptacle Enclosure (Aft Lavatory) - Detailed Inspection | | G650 A0MM_262505 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 3 | Notes: | | 05-20-00 | 3 | AFL | 1065 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 18 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 275108 | Flap Track and Roller - Detailed Inspection | | G650 AMM_275108 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 30 Nov 2026 |
| Airframe 29 | Notes: | | 05-10-10 | 29 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 02 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 304118 | Windshield Surface Seal (Left) - Detailed Inspection | | G650 AMM_304118 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 30 Nov 2026 |
| Airframe 98 | Notes: | | 05-20-00 | 98 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 320002 | Nose and Main Landing Gear and Doors - General Visual Inspection | | G650 AMM_320002 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 98.1 | Notes: | | 05-20-00 | 98.1 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 334202 | Anticollision Beacon Light - Operational Check | | G650 AMM_334202 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe | Notes: | | -- | | AFL | 1065 | | | | | |
| | | | 22 | 30-Oct-23 | MOS | 27 Nov 2025 | 12 | 30 Nov 2026 | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 381004^U | Shower Water System - Cleaning/Sanitisation | | | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 18 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 383104 | Vacuum Toilet System (Forward) - Cleaning | | G650 AMM_383104 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 12 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 383105 | Vacuum Toilet System (Aft) - Cleaning | | G650 AMM_383105 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 12 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 525102 | Auxiliary Pressure Bulkhead Door Seal - Detailed Inspection | | G650 AMM_525102 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 98.9 | Notes: | | 05-20-00 | 98.9 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 02 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 531711 | Cockpit Windshields, Side Windows and Cabin Windows Polished Exterior Surrounds - Detailed Inspection | | G650 AMM_531711 | | HRS | 2909.1 | | | | | 30 Nov 2026 |
| Airframe 98.22 | Notes: | | 05-20-00 | 98.22 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 19 Dec 2025 | 12 | 30 Nov 2026* | 31 Dec 2026 | 6m 19d (+31d)^ | |
| 313031 | Flight Data Recorder (FDR) - Download and Analyse Whole Flight Recording (EASA EUROCAE) | | | | HRS | 2909.1 | 3000 | 5909.1 | | 2863 | 01 Dec 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 01 Dec 2025 | 12 | 01 Dec 2026 | | 6m 20d^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|--------------------------------------|--|---------------|---------------------------|-------------|------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 313035 | Cockpit Voice Recorder (Cvr) - Read-Out of Recorded Data (EASA ICAO)& Otar (Bermudan & Cayman Is) | | | | HRS | 2909.1 | | | | | 01 Dec 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 01 Dec 2025 | 12 | 01 Dec 2026 | | 6m 20d^ | |
| 345316 | VOR / ILS / Data Link / GPS - Functional Check | | | | HRS | 2909.1 | | | | | 04 Dec 2026 |
| Airframe | Notes: | | | | AFL | 1065 | | | | | |
| | | | | | MOS | 04 Dec 2025 | 12 | 04 Dec 2026 | 04 Jan 2027 | 6m 23d (+31d)^ | |
| 792106 | No. 1 Engine - Oil System Pressure Filter Element - Discard | PN | G650 AMM_792106 | | HRS | 0 | 1200 | 1200 | 1250 | 205.6 (+50)^ | 05 Dec 2026 |
| Engine 9 | Notes: | SN-UNKNOWN | 05-20-00 | 9 | ENC | 0 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 17 Nov 2022 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 792106 | No. 2 Engine - Oil System Pressure Filter Element - Discard | PN | G650 AMM_792106 | | HRS | 0 | 1200 | 1200 | 1250 | 205.6 (+50)^ | 05 Dec 2026 |
| Engine 9 | Notes: | SN-UNKNOWN | 05-20-00 | 9 | ENC | 0 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 15 Nov 2022 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| APU-49 R13 (950012) APU | APU - Sil APU-49 R13 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended) | | 36-100/150_SIL_APU-49 R13 | | HRS | 2179 | 500 | 2679 | | 412.5 | 18 Dec 2026 |
| | Notes: | | | | APUS | 0 | | | | | |
| | | | | | MOS | 18 Dec 2025 | 12 | 18 Dec 2026 | | 7m 7d^ | |
| | | | | | MSC | | A/R | | | | |
| 340100 | Reduced Vertical Separation Minimum (RVSM) Monitoring Policy | | | | HRS | 2483.7 | | | | | 31 Dec 2026 |
| Airframe | Notes: | | | | AFL | 900 | | | | | |
| | | | | | MOS | 16 Dec 2024 | 24 | 31 Dec 2026 | | 7m 20d^ | |
| 351103 | Crew Oxygen Mask (Pilot) - Restore | MLD20-564 | G650 AMM_351103 | | HRS | 1594.1 | | | | | 31 Dec 2026 |
| Airframe 28 | Notes: MRI PARENT CODE: 351100 | B165248 | 05-10-00 | 28 | AFL | 547 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 12 Jan 2021 | 72 | 31 Dec 2026 | | 7m 20d^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 351104 | Crew Oxygen Mask (Copilot) - Restore | MLD20-564 | G650 AMM_351104 | | HRS | 1594.1 | | | | | 31 Dec 2026 |
| Airframe 28 | Notes: MRI PARENT CODE: 351101 | B165431 | 05-10-00 28 | | AFL | 547 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 12 Jan 2021 | 72 | 31 Dec 2026 | | 7m 20d^ | |
| 351105 | Crew Oxygen Mask (Observer) - Restore | MLD20-564 | G650 AMM_351105 | | HRS | 1594.1 | | | | | 31 Dec 2026 |
| Airframe 28 | Notes: MRI PARENT CODE: 351102 | B165359 | 05-10-00 28 | | AFL | 547 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 12 Jan 2021 | 72 | 31 Dec 2026 | | 7m 20d^ | |
| 243903 | Uninterruptible Power Supply Sealed Lead ACID Battery - Functional Check | | G650 AMM_243903 | | HRS | 2909.1 | | | | | 31 Dec 2026 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 12 | 31 Dec 2026* | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 256271 | Observers Smoke Goggles / Detachable Facepiece (Observers) - Detailed Inspection | | G650 AMM_256271 | | HRS | 2315.6 | | | | | 31 Dec 2026 |
| Airframe 88 | Notes: | | 05-20-00 88 | | AFL | 802 | | | | | |
| | | | 16 | 30-Nov-20 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 323916 | Landing Gear Emergency Extension System - Operational Check | | G650 AMM_323916 | | HRS | 2315.6 | 1800 | 4115.6 | 4165.6 | 1069.5 (+50) | 31 Dec 2026 |
| Airframe 33 | Notes: | | 05-10-10 33 | | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 334211 | Navigation Lights - Operational Check | | G650 AMM_334211 | | HRS | 2909.1 | | | | | 31 Dec 2026 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 12 | 31 Dec 2026* | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 352403 | Passenger Oxygen System (Manual MODE) - Operational Check | | G650 A0MM_352403 | | HRS | 2315.6 | | | | | 31 Dec 2026 |
| Airframe 4 | Notes: | | 05-20-00 4 | | AFL | 802 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 352404 | Passenger Oxygen System (Auto MODE) - Functional Check | | G650 A0MM_352404 | | HRS | 2315.6 | | | | | 31 Dec 2026 |
| Airframe 4 | Notes: | | 05-20-00 4 | | AFL | 802 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 352604 | Therapeutic Oxygen System - Functional Check | | G650 A0MM_352604 | | HRS | 2315.6 | | | | | 31 Dec 2026 |
| Airframe 4 | Notes: | | 05-20-00 | 4 | AFL | 802 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 352605 | Therapeutic Oxygen Mask - Detailed Inspection | | G650 A0MM_352605 | | HRS | 2315.6 | | | | | 31 Dec 2026 |
| Airframe 4 | Notes: PN: O2C33K08-01-030 SN: <NONE>. | | 05-20-00 | 4 | AFL | 802 | | | | | |
| | | | 27 | 11-Nov-20 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 525200 | Acoustic Door Automatic Opening - Operational Check | | G650 AMM_525200 | | HRS | 2315.6 | | | | | 31 Dec 2026 |
| Airframe 98.9 | Notes: | | 05-20-00 | 98.9 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 36 | 31 Dec 2026 | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 531712 | Cockpit Windshields, Side Windows and Cabin Windows Polished Exterior Surrounds Corrosion Inhibiting Coating - Restore | | G650 AMM_531712 | | HRS | 2909.1 | | | | | 31 Dec 2026 |
| Airframe 16 | Notes: | | 05-20-00 | 16 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 19 Dec 2025 | 12 | 31 Dec 2026* | 31 Jan 2027 | 7m 20d (+31d)^ | |
| 256419 | Defibrillator Time Limited Supplies - Discard | 502861 | G650 A0MM_256419 | | HRS | 2483.7 | | | | | 01 Jan 2027 |
| Airframe 3 | Notes: | B15H-00458 | 05-10-00 | 3 | AFL | 900 | | | | | |
| | | | 33 | 19-Jan-23 | MOS | 04 Dec 2024 | 12 | 01 Jan 2027 | | 7m 21d^ | |
| 256422 | Defibrillator Pads (SET 1) - Removal / Installation | 989803139261 | | | HRS | 2483.7 | | | | | 05 Jan 2027 |
| Airframe | Notes: | SN-UNKNOWN | | | AFL | 900 | | | | | |
| | | | | | MOS | 16 Dec 2024 | | 05 Jan 2027 | | 7m 25d^ | |
| | | | | | MSC | | - | | | | |
| 256423 | Defibrillator Pads (SET 2) - Removal / Installation | 989803139261 | | | HRS | 2483.7 | | | | | 05 Jan 2027 |
| Airframe | Notes: | SN-UNKNOWN | | | AFL | 900 | | | | | |
| | | | | | MOS | 16 Dec 2024 | | 05 Jan 2027 | | 7m 25d^ | |
| | | | | | MSC | | - | | | | |
| 256262 | Smoke Hood / Protective Breathing Equipment (Pbe) (Pilot) - Visual Check | | G650 AMM_256262 | | HRS | 2909.1 | | | | | 11 Jan 2027 |
| Airframe 88 | Notes: | | 05-20-00 | 88 | AFL | 1065 | | | | | |
| | | | | | MOS | 01 Dec 2025 | 12 | 11 Jan 2027* | 11 Feb 2027 | 8m 0d (+31d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 351112 | Crew Oxygen Mask / Regulator and Stowage Box (Pilot) - Detailed Inspection | | G650 AMM_351112 | | HRS | 2315.6 | | | | | 31 Jan 2027 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 36 | 31 Jan 2027* | 28 Feb 2027 | 8m 20d (+28d)^ | |
| 351113 | Crew Oxygen Mask / Regulator and Stowage Box (Copilot) - Detailed Inspection | | G650 AMM_351113 | | HRS | 2315.6 | | | | | 31 Jan 2027 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 36 | 31 Jan 2027* | 28 Feb 2027 | 8m 20d (+28d)^ | |
| 351114 | Crew Oxygen Mask / Regulator and Stowage Box (Observer) - Detailed Inspection | | G650 AMM_351114 | | HRS | 2315.6 | | | | | 31 Jan 2027 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 36 | 31 Jan 2027* | 28 Feb 2027 | 8m 20d (+28d)^ | |
| 352308 | Passenger Oxygen System Check Valve - Operational Check | | G650 AMM_352308 | | HRS | 0 | | | | | 28 Feb 2027 |
| Airframe 98.4 | Notes: | | -- 98.4 | | AFL | 0 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 11 Mar 2016 | 75 | 28 Feb 2027 | 31 Mar 2027 | 9m 17d (+31d)^ | |
| 315400 | Aircraft Configuration Message - Operational Check | | G650 AMM_315400 | | HRS | 2382.4 | | | | | 31 Mar 2027 |
| Airframe 98 | Notes: | | 05-20-00 98 | | AFL | 826 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 27 Mar 2024 | 36 | 31 Mar 2027 | 30 Apr 2027 | 10m 20d (+30d)^ | |
| 351106 | Crew Oxygen Mask and Regulator (Pilot) - Functional Test | | G650 AMM_351106 | | HRS | 1594.1 | | | | | 12 Apr 2027 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 547 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 12 Jan 2021 | 75 | 12 Apr 2027 | 12 May 2027 | 11m 1d (+30d)^ | |
| 351107 | Crew Oxygen Mask and Regulator (Copilot) - Functional Test | | G650 AMM_351107 | | HRS | 1594.1 | | | | | 12 Apr 2027 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 547 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 12 Jan 2021 | 75 | 12 Apr 2027 | 12 May 2027 | 11m 1d (+30d)^ | |
| 351108 | Crew Oxygen Mask and Regulator (Observer) - Functional Test | | G650 AMM_351108 | | HRS | 1594.1 | | | | | 12 Apr 2027 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 547 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 12 Jan 2021 | 75 | 12 Apr 2027 | 12 May 2027 | 11m 1d (+30d)^ | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|--|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| EASA 2025-0088 (992588) Airframe | Appliance AD - EASA 2025-0088 - Navigation - Satellite Based Augmentation Systems / Global Positioning System Receiver - Replacement (Mandatory) | | | | HRS | | | | | | 30 Apr 2027 |
| | Notes: | | | | AFL | | | | | | |
| | | | | | MOS | | 24** | 30 Apr 2027 | | 11m 19d^ | |
| | | | | | MSC | | | | | | |
| 530017 Airframe 13 | External Fuselage - General Visual Inspection | | | | HRS | 2051.9 | | | | | 28 Jun 2027 |
| | | | G650 AMM_530017 | | AFL | 725 | 800 | 1525 | | 408 | |
| | Notes: | | 05-10-10 | 13 | MOS | 07 Dec 2022 | | | | | |
| | | | 23 | 31-Mar-24 | | | | | | | |
| BR700-80-102332 R01 (883321) Engine | No. 1 Engine - Campaign Sb - BR700-80-102332 R01 - Starting - Starter AIR Valve - Introduction of A Modified Starter AIR Valve With A Modified Body Assembly and A New Filter Assembly, Service Bulletin (Recommended) | | | | HRS | | | | | | 31 Jul 2027 |
| | Notes: | | | | ENC | | | | | | |
| | | | | | MOS | | 36** | 31 Jul 2027 | | 14m 20d | |
| BR700-80-102332 R01 (883321) Engine | No. 2 Engine - Campaign Sb - BR700-80-102332 R01 - Starting - Starter AIR Valve - Introduction of A Modified Starter AIR Valve With A Modified Body Assembly and A New Filter Assembly, Service Bulletin (Recommended) | | | | HRS | | | | | | 31 Jul 2027 |
| | Notes: | | | | ENC | | | | | | |
| | | | | | MOS | | 36** | 31 Jul 2027 | | 14m 20d | |
| 122212 Airframe 83 | Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication | | | | HRS | 2909.1 | 600 | 3509.1 | | 463 | 23 Aug 2027 |
| | | | G650 AMM_122212 | | AFL | 1065 | | | | | |
| | Notes: | | 05-20-00 | 83 | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | | 18m 19d | |
| | | | 24 | 30-Oct-24 | | | | | | | |
| 242351 Airframe 87 | Ram AIR Turbine Built-In Test Switch - Operational Check | | | | HRS | 2909.1 | 600 | 3509.1 | | 463 | 23 Aug 2027 |
| | | | G650 AMM_242351 | | AFL | 1065 | | | | | |
| | Notes: | | 05-20-00 | 87 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | 19m 20d | |
| | | | 24 | 30-Oct-24 | | | | | | | |
| 281531 Airframe 96 | Fuel Vent System (Right) - Operational Check | | | | HRS | 2909.1 | 600 | 3509.1 | | 463 | 23 Aug 2027 |
| | | | G650 AMM_281531 | | AFL | 1065 | | | | | |
| | Notes: | | 05-20-00 | 96 | MOS | 12 Dec 2025 | | | | | |
| | | | 24 | 30-Oct-24 | | | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|--------------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 122211 | Nose Wheel Steering Unit - Lubrication | | G650 AMM_122211 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 83 | Notes: | | 05-20-00 | 83 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |
| 216141 | Zone Trim AIR Valve Cup Assembly (Cockpit) - Discard | 4000091-600-BT NSN | G650 AMM_216141 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 2 | Notes: | | 05-10-00 | 2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| 216142 | Zone Trim AIR Valve Cup Assembly (Forward Cabin) - Discard | 4000091-600-BT NSN | G650 AMM_216142 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 2 | Notes: | | 05-10-00 | 2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| 216143 | Zone Trim AIR Valve Cup Assembly (Aft Cabin) - Discard | 4000091-600-BT NSN | G650 AMM_216143 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 2 | Notes: | | 05-10-00 | 2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| 242109 | Idg (Left) - Detailed Inspection | | G650 AMM_242109 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| 242110 | Idg (Right) - Detailed Inspection | | G650 AMM_242110 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| 271002 | Aileron Actuating System Ibit Suite A Test - Operational Check | | G650 AMM_271002 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 32 | Notes: PN: 60P5760001A008 SN: <NONE>. | | 05-10-10 | 32 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 02 Dec 2025 | | | | | |
| 272004 | Rudder Actuating System Ibit Suite A Test - Operational Check | | G650 AMM_272004 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 32 | Notes: PN: 60P2212001Z001 SN: <NONE>. | | 05-10-10 | 32 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 02 Dec 2025 | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 273006 | Elevator Actuating System Ibit Suite A Test - Operational Check | | G650 AMM_273006 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 33 | Notes: | | 05-10-10 | 33 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 02 Dec 2025 | | | | | |
| 281530 | Fuel Vent System (Left) - Operational Check | | G650 AMM_281530 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 96 | Notes: | | 05-20-00 | 96 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 12 Dec 2025 | | | | | |
| 292511 | Auxiliary Hydraulic Pump Manifold Filter - Discard | 339980 | G650 AMM_292511 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 11 | Notes: | NSN | 05-10-00 | 11 | AFL | 1065 | | | | | |
| | | | 14 | 30-Nov-19 | MOS | 17 Feb 2026 | | | | | |
| 320003 | Nose and Main Landing Gear and Doors - Zonal Inspection | | G650 AMM_320003 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 | 98.1 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 324304 | Brake Wear Indicators (Left Outboard) - Detailed Inspection | | G650 AMM_324304 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.2 | Notes: | | 05-20-00 | 98.2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 324305 | Brake Wear Indicators (Left Inboard) - Detailed Inspection | | G650 AMM_324305 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.2 | Notes: | | 05-20-00 | 98.2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 324306 | Brake Wear Indicators (Right Inboard) - Detailed Inspection | | G650 AMM_324306 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.2 | Notes: | | 05-20-00 | 98.2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 324307 | Brake Wear Indicators (Right Outboard) - Detailed Inspection | | G650 AMM_324307 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.2 | Notes: | | 05-20-00 | 98.2 | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 521005 | Main Entrance Door - Functional Check | | G650 AMM_521005 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.8 | Notes: | | 05-20-00 98.8 | | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 05 Dec 2025 | | | | | |
| 531024 | Nose Landing Gear Wheel Well FS 148.5 - FS 223 - Zonal Inspection | | G650 AMM_531024 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.18 | Notes: | | 05-20-00 98.18 | | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |
| 533000 | Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Left) - Zonal Inspection | | G650 AMM_533000 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.26 | Notes: | | 05-20-00 98.26 | | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 533001 | Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Right) - Zonal Inspection | | G650 AMM_533001 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.26 | Notes: | | 05-20-00 98.26 | | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 533002 | Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Left) - Enhanced Zonal Inspection | | G650 AMM_533002 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.26 | Notes: | | 05-20-00 98.26 | | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 533003 | Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Right) - Enhanced Zonal Inspection | | G650 AMM_533003 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.26 | Notes: | | 05-20-00 98.26 | | AFL | 1065 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 561111 | Windshield Weather Seals (Humpseal) (Left) - Detailed Inspection | | G650 AMM_561111 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.43 | Notes: | | 05-20-00 98.43 | | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 27 Nov 2025 | 24 | 27 Nov 2027 | 27 Dec 2027 | 18m 16d (+30d) | |
| 561112 | Windshield Weather Seals (Humpseal) (Right) - Detailed Inspection | | G650 AMM_561112 | | HRS | 2909.1 | 600 | 3509.1 | 3559.1 | 463 (+50) | 23 Aug 2027 |
| Airframe 98.43 | Notes: | | 05-20-00 98.43 | | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 27 Nov 2025 | 24 | 27 Nov 2027 | 27 Dec 2027 | 18m 16d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 711406 | Engine Fixed Cowl (Left) - Detailed Inspection | | G650 AMM_711406 | | HRS | 2315.6 | 1200 | 3515.6 | | 469.5 | 30 Aug 2027 |
| Airframe 98.51 | Notes: | | 05-20-00 | 98.51 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | | | | | |
| 711407 | Engine Fixed Cowl (Right) - Detailed Inspection | | G650 AMM_711407 | | HRS | 2315.6 | 1200 | 3515.6 | | 469.5 | 30 Aug 2027 |
| Airframe 98.51 | Notes: | | 05-20-00 | 98.51 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | | | | | |
| 121408 | No. 1 Engine - AIR Turbine Starter Oil - Discard | | G650 AMM_121408 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 6 | Notes: | | 05-20-00 | 6 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 121408 | No. 2 Engine - AIR Turbine Starter Oil - Discard | | G650 AMM_121408 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 6 | Notes: | | 05-20-00 | 6 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 271182 | Aileron Free Play Backlash (Left) - Functional Check | | G650 AMM_271182 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 32 | Notes: | | 05-10-10 | 32 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 120 | 31 Dec 2033 | 31 Jan 2034 | 91m 20d (+31d) | |
| 271183 | Aileron Free Play Backlash (Right) - Functional Check | | G650 AMM_271183 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 32 | Notes: | | 05-10-10 | 32 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 120 | 31 Dec 2033 | 31 Jan 2034 | 91m 20d (+31d) | |
| 272002 | Rudder Free Play Backlash - Functional Check | | G650 AMM_272002 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 32 | Notes: PN: 60P2212001Z001 SN: <NONE>. | | 05-10-10 | 32 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 120 | 31 Dec 2033 | 31 Jan 2034 | 91m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 273008 | Elevator Free Play Backlash (Left) - Functional Check | | G650 AMM_273008 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 32 | Notes: | | 05-10-10 | 32 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 120 | 31 Dec 2033 | 31 Jan 2034 | 91m 20d (+31d) | |
| 273009 | Elevator Free Play Backlash (Right) - Functional Check | | G650 AMM_273009 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 32 | Notes: | | 05-10-10 | 32 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 120 | 31 Dec 2033 | 31 Jan 2034 | 91m 20d (+31d) | |
| 711000 | Engine Upper and Lower Cowl Doors (Left) - General Visual Inspection | | G650 AMM_711000 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | | | | | |
| 711001 | Engine Upper and Lower Cowl Doors (Right) - General Visual Inspection | | G650 AMM_711001 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | | | | | |
| 711004 | Engine Lower Fan Cowl Door (Left) - Enhanced Zonal Inspection | | G650 AMM_711004 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | 48 | 30 Sep 2027* | 31 Oct 2027 | 16m 19d (+31d) | |
| 711005 | Engine Lower Fan Cowl Door (Right) - Enhanced Zonal Inspection | | G650 AMM_711005 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | 48 | 30 Sep 2027* | 31 Oct 2027 | 16m 19d (+31d) | |
| 711104 | Inlet Cowl (Left) - General Visual Inspection | | G650 AMM_711104 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | | | | | |
| 711105 | Inlet Cowl (Right) - General Visual Inspection | | G650 AMM_711105 | | HRS | 2315.6 | 1200 | 3515.6 | 3565.6 | 469.5 (+50) | 30 Aug 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 | 98.5 | AFL | 802 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 21 Dec 2023 | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 723101 | No. 1 Engine - Lp Compressor Fan Blades - Detailed Inspection | | G650 AMM_723101 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 76 | Notes: | | 05-20-00 76 | | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 723101 | No. 2 Engine - Lp Compressor Fan Blades - Detailed Inspection | | G650 AMM_723101 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 76 | Notes: | | 05-20-00 76 | | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 723334 (723334) | No. 1 Engine - Variable Stator Vane Actuating Mechanism - Functional Check | | G650 AMM_723334 | | HRS | 263.9 | 1200 | 1463.9 | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 70 | Notes: | | 05-20-00 70 | | ENC | 77 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 723334 (723334) | No. 2 Engine - Variable Stator Vane Actuating Mechanism - Functional Check | | G650 AMM_723334 | | HRS | 263.9 | 1200 | 1463.9 | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 70 | Notes: | | 05-20-00 70 | | ENC | 77 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 723335 (723335) | No. 1 Engine - Variable Stator Vane Actuation Mechanism - Lubrication | | G650 AMM_723335 | | HRS | 263.9 | 1200 | 1463.9 | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 70 | Notes: | | 05-20-00 70 | | ENC | 77 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 723335 (723335) | No. 2 Engine - Variable Stator Vane Actuation Mechanism - Lubrication | | G650 AMM_723335 | | HRS | 263.9 | 1200 | 1463.9 | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 70 | Notes: | | 05-20-00 70 | | ENC | 77 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 723401 | No. 1 Engine - Lp Compressor Case Inner Surface - General Visual Inspection | | G650 AMM_723401 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 76 | Notes: | | 05-20-00 76 | | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 723401 | No. 2 Engine - Lp Compressor Case Inner Surface - General Visual Inspection | | G650 AMM_723401 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 76 | Notes: | | 05-20-00 76 | | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 723806 | No. 1 Engine - Lp Compressor Intake Rotating Fairing - General Visual Inspection | | G650 AMM_723806 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 76 | Notes: | | 05-20-00 | 76 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 723806 | No. 2 Engine - Lp Compressor Intake Rotating Fairing - General Visual Inspection | | G650 AMM_723806 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 76 | Notes: | | 05-20-00 | 76 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 02 Dec 2025 | | | | | |
| 780001 | No. 1 Engine - Engine Exhaust - General Visual Inspection | | G650 AMM_780001 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 04 Dec 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 780001 | No. 2 Engine - Engine Exhaust - General Visual Inspection | | G650 AMM_780001 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 04 Dec 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 792109 | No. 1 Engine - Magnetic Chip Detectors (Front Bearing Chamber) - Detailed Inspection | | G650 AMM_792109 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 29 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 792109 | No. 2 Engine - Magnetic Chip Detectors (Front Bearing Chamber) - Detailed Inspection | | G650 AMM_792109 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 29 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 792110 | No. 1 Engine - Magnetic Chip Detectors (Rear Bearing Chamber) - Detailed Inspection | | G650 AMM_792110 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 792110 | No. 2 Engine - Magnetic Chip Detectors (Rear Bearing Chamber) - Detailed Inspection | | G650 AMM_792110 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 792111 | No. 1 Engine - Magnetic Chip Detectors (Accessory Gearbox) - Detailed Inspection | | G650 AMM_792111 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 792111 | No. 2 Engine - Magnetic Chip Detectors (Accessory Gearbox) - Detailed Inspection | | G650 AMM_792111 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 801104 | No. 1 Engine - AIR Turbine Starter Magnetic Chip Collector - Detailed Inspection | | G650 AMM_801104 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 801104 | No. 2 Engine - AIR Turbine Starter Magnetic Chip Collector - Detailed Inspection | | G650 AMM_801104 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 27 Nov 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 801118 | No. 1 Engine - AIR Turbine Starter - General Visual Inspection | | G650 AMM_801118 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---|---|---------------|-----------------|-------------|------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 801118 | No. 2 Engine - AIR Turbine Starter - General Visual Inspection | | G650 AMM_801118 | | HRS | 857.4 | 600 | 1463.9* | 1513.9 | 469.5 (+50) | 30 Aug 2027 |
| Engine 8 | Notes: | | 05-20-00 | 8 | ENC | 340 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 03 Dec 2025 | | | | | |
| | | | ADDENDU | | | | | | | | |
| | | | M | | | | | | | | |
| 316322 | Displays Manual Reversion - Operational Check | | G650 AMM_316322 | | HRS | 1745.4 | 1800 | 3545.4 | 3595.4 | 499.3 (+50) | 29 Sep 2027 |
| Airframe 98 | Notes: | | 05-20-00 | 98 | AFL | 610 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 16 Jan 2022 | | | | | |
| 533904 | Wiring and Fuel Installations Located Inside Torque Box Upper Portion (FS 680 - FS 735) - Enhanced Zonal Inspection | | G650 AMM_533904 | | HRS | 2315.6 | | | | | 30 Sep 2027 |
| Airframe 98.14 | Notes: | | 05-20-00 | 98.14 | AFL | 802 | | | | | |
| | | | 21 | 15-May-23 | MOS | 21 Dec 2023 | 48 | 30 Sep 2027* | 31 Oct 2027 | 16m 19d (+31d) | |
| BR700-72-900780 R01 PART A (887801.001) Engine | No. 1 Engine - Accomplish Sb BR700-72-900780 R01 - High Pressure (Hp) Compressor Rear Inner Case - Hp Compressor Stages 7 to 10 Rear Inner Case Rotor Path Liner Borescope Inspection and Replacement of the Hp Compressor Stages 7 to 10 Rear Inner Case Assemblies - Non-Modification Service Bulletin, Service Bulletin BR700-72-900780 R01 Part A - Borescope Inspection of the High Pressure (Hp) Compressor Stages 7 to 10 Rear Inner Case Rotor Path Liner and Blade Tip Clearance Measurement (Recommended) | | | | HRS | | 1500** | 1500 | 1750 | 505.6 (+250) | 05 Oct 2027 |
| | Notes: | | | | ENC | | | | | | |
| | | | | | DATE | | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---|---|---------------|-----------------|------|------|---------------|------------------|------------------|---------|-----------------|--------------------|
| | | Serial Number | Section | Page | | | | | | | |
| Logbook | Notes | Revision | Date Issued | | | | | | | | |
| Mfg Ref Number | | | | | | | | | | | |
| BR700-72-900780 R01 PART A (887801.001) Engine | No. 2 Engine - Accomplish Sb BR700-72-900780 R01 - High Pressure (Hp) Compressor Rear Inner Case - Hp Compressor Stages 7 to 10 Rear Inner Case Rotor Path Liner Borescope Inspection and Replacement of the Hp Compressor Stages 7 to 10 Rear Inner Case Assemblies - Non-Modification Service Bulletin, Service Bulletin BR700-72-900780 R01 Part A - Borescope Inspection of the High Pressure (Hp) Compressor Stages 7 to 10 Rear Inner Case Rotor Path Liner and Blade Tip Clearance Measurement (Recommended) | | | | HRS | | 1500** | 1500 | 1750 | 505.6 (+250) | 05 Oct 2027 |
| | | | | | ENC | | | | | | |
| | | | | | DATE | | | | | | |
| BR700-72-900780 R01 PART B (887801.002) Engine | No. 1 Engine - Accomplish Sb BR700-72-900780 R01 - High Pressure (Hp) Compressor Rear Inner Case - Hp Compressor Stages 7 to 10 Rear Inner Case Rotor Path Liner Borescope Inspection and Replacement of the Hp Compressor Stages 7 to 10 Rear Inner Case Assemblies - Non-Modification Service Bulletin, Service Bulletin BR700-72-900780 R01 Part B - Replacement of the High Pressure (Hp) Compressor Stages 7 to 10 Rear Inner Case Assemblies (Recommended) | | | | HRS | | 1500** | 1500 | 1750 | 505.6 (+250) | 05 Oct 2027 |
| | | | | | ENC | | | | | | |
| | | | | | DATE | | | | | | |
| BR700-72-900780 R01 PART B (887801.002) Engine | No. 2 Engine - Accomplish Sb BR700-72-900780 R01 - High Pressure (Hp) Compressor Rear Inner Case - Hp Compressor Stages 7 to 10 Rear Inner Case Rotor Path Liner Borescope Inspection and Replacement of the Hp Compressor Stages 7 to 10 Rear Inner Case Assemblies - Non-Modification Service Bulletin, Service Bulletin BR700-72-900780 R01 Part B - Replacement of the High Pressure (Hp) Compressor Stages 7 to 10 Rear Inner Case Assemblies (Recommended) | | | | HRS | | 1500** | 1500 | 1750 | 505.6 (+250) | 05 Oct 2027 |
| | | | | | ENC | | | | | | |
| | | | | | DATE | | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|------------------|---|------------------------|-----------------------------|-------------|------------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 256308 | Emergency Locator Transmitter Battery Pack - Discard | 452-0133 397417-034 | G650 AMM_256308 05-10-00 | 6 | HRS AFL | 2315.6 802 | | | | | 31 Oct 2027 |
| Airframe 6 | Notes: | | 26 | 15-Nov-25 | MOS | 08 Oct 2023 | 60 | 31 Oct 2027 | | 17m 20d | |
| 711002 | Engine Internal (Left) - Zonal Inspection | | G650 AMM_711002 05-20-00 | 98.5 | HRS AFL | 2382.4 826 | 1200 | 3582.4 | 3632.4 | 536.3 (+50) | 05 Nov 2027 |
| Airframe 98.5 | Notes: | | 24 | 30-Oct-24 | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 711003 | Engine Internal (Right) - Zonal Inspection | | G650 AMM_711003 05-20-00 | 98.5 | HRS AFL | 2382.4 826 | 1200 | 3582.4 | 3632.4 | 536.3 (+50) | 05 Nov 2027 |
| Airframe 98.5 | Notes: | | 24 | 30-Oct-24 | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 717108 | No. 1 Engine - Drains Tubes and Fittings - Detailed Inspection | | G650 AMM_717108 05-20-00 | 9 | HRS ENC | 330.7 101 | 1200 | 1530.7 | 1580.7 | 536.3 (+50) | 05 Nov 2027 |
| Engine 9 | Notes: | | 24 ADDENDU M | 30-Oct-24 | MOS | 28 Mar 2024 | | | | | |
| 717108 | No. 2 Engine - Drains Tubes and Fittings - Detailed Inspection | | G650 AMM_717108 05-20-00 | 9 | HRS ENC | 330.7 101 | 1200 | 1530.7 | 1580.7 | 536.3 (+50) | 05 Nov 2027 |
| Engine 9 | Notes: | | 24 ADDENDU M | 30-Oct-24 | MOS | 25 Mar 2024 | | | | | |
| 720006 | No. 1 Engine - Combustion Section - Special Detailed Inspection | | G650 AMM_720006 05-20-00 | 75 | HRS ENC | 330.7 101 | 1200 | 1530.7 | 1580.7 | 536.3 (+50) | 05 Nov 2027 |
| Engine 75 | Notes: | | 24 | 30-Oct-24 | MOS | 28 Mar 2024 | | | | | |
| 720006 | No. 2 Engine - Combustion Section - Special Detailed Inspection | | G650 AMM_720006 05-20-00 | 75 | HRS ENC | 330.7 101 | 1200 | 1530.7 | 1580.7 | 536.3 (+50) | 05 Nov 2027 |
| Engine 75 | Notes: | | 24 | 30-Oct-24 | MOS | 27 Mar 2024 | | | | | |
| 720007 | No. 1 Engine - Hp Turbine - Special Detailed Inspection | | G650 AMM_720007 05-20-00 | 76 | HRS ENC | 330.7 101 | 1200 | 1530.7 | 1580.7 | 536.3 (+50) | 05 Nov 2027 |
| Engine 76 | Notes: | | 24 | 30-Oct-24 | MOS | 28 Mar 2024 | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 720007 | No. 2 Engine - Hp Turbine - Special Detailed Inspection | | G650 AMM_720007 | | HRS | 330.7 | 1200 | 1530.7 | 1580.7 | 536.3 (+50) | 05 Nov 2027 |
| Engine 76 | Notes: | | 05-20-00 76 | | ENC | 101 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 28 Mar 2024 | | | | | |
| 275071 | B Track Flap Roller (Right Outboard Upper Aft) - Discard | 60P5755371Z0 01 NSN | G650 AMM_275071 | | HRS | 1201.5 | 2400 | 3601.5 | 3651.5 | 555.4 (+50) | 25 Nov 2027 |
| Airframe 8 | Notes: MRI PARENT CODE: 275128 | | 05-10-00 8 | | AFL | 351 | | | | | |
| | | | 23 | 31-Mar-24 | MOS | 02 Oct 2019 | | | | | |
| 491304 | APU Compartment Drains - Operational Check | | G650 AMM_491304 | | HRS | 2909.1 | | | | | 29 Nov 2027 |
| Airframe 98.6 | Notes: | | 05-20-00 98.6 | | AFL | 1065 | | | | | |
| | | | 14 | 30-Nov-19 | MOS | 29 Nov 2025 | 24 | 29 Nov 2027 | 29 Dec 2027 | 18m 18d (+30d) | |
| 313104 | FDR - Functional / Reasonableness Check | | G650 AMM_313104 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98 | Notes: | | 05-20-00 98 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |
| 321052 | Main Landing Gear Corrosion Inhibiting Compound Reapplication (Left) | | G650 AMM_321052 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |
| 321053 | Main Landing Gear Corrosion Inhibiting Compound Reapplication (Right) | | G650 AMM_321053 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |
| 322005 | Nose Landing Gear Corrosion Inhibiting Compound Reapplication | | G650 AMM_322005 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |
| 323917 | Landing Gear Emergency Extension System - General Visual Inspection | | G650 AMM_323917 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.2 | Notes: | | 05-20-00 98.2 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+31d) | |

| ATA Logbook | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|-----------------------|-----------------|-----------|-----|---------------|---------------------|--------------------|-------------|--------------------|-----------------------|
| | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | Revision | Date Issued | | | | | | | | |
| 335000 | Exterior Emergency Lighting - Operational Check | | G650 AMM_335000 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.3 | Notes: | 8 | 05-20-00 98.3 | 30-Nov-16 | AFL | 1065 | | | | | |
| | | | | | MOS | 27 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+ 31d) | |
| 491302 | APU Compartment Drains - General Visual Inspection | | G650 AMM_491302 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.6 | Notes: | 22 | 05-20-00 98.6 | 30-Oct-23 | AFL | 1065 | | | | | |
| | | | | | MOS | 29 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+ 31d) | |
| 535001 | APU Interior and Exterior Enclosure - Zonal Inspection | | G650 AMM_535001 | | HRS | 2909.1 | | | | | 30 Nov 2027 |
| Airframe 98.35 | Notes: | 8 | 05-20-00 98.35 | 30-Nov-16 | AFL | 1065 | | | | | |
| | | | | | MOS | 29 Nov 2025 | 24 | 30 Nov 2027 | 31 Dec 2027 | 18m 19d (+ 31d) | |
| 256086 | Life Vest (No. 13) - Restore | 00002143 16075-014 | G650 AMM_256086 | | HRS | 2483.7 | | | | | 01 Dec 2027 |
| Airframe 5 | Notes: | | 05-10-00 5 | 30-Apr-21 | AFL | 900 | | | | | |
| | | | | | MOS | 16 Dec 2024 | | 01 Dec 2027 | | 18m 20d | |
| | | | | | MSC | | N/A | | | | |
| 080009^U | Aircraft Weighing | | | | HRS | 2315.6 | | | | | 18 Dec 2027 |
| Airframe | Notes: | | | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 18 Dec 2027* | | 19m 7d | |
| 313114 | FDR Underwater Locator Beacon - Cleaning | | G650 AMM_313114 | | HRS | 2909.1 | | | | | 21 Dec 2027 |
| Airframe 98 | Notes: | 23 | 05-20-00 98 | 31-Mar-24 | AFL | 1065 | | | | | |
| | | | | | MOS | 27 Nov 2025 | 24 | 21 Dec 2027* | 21 Jan 2028 | 19m 10d (+ 31d) | |
| 491303 | Interior and Exterior Surfaces of APU Compartment (APU Box) - Detailed Inspection | | G650 AMM_491303 | | HRS | 2315.6 | | | | | 21 Dec 2027 |
| Airframe 98.6 | Notes: | 14 | 05-20-00 98.6 | 30-Nov-19 | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 21 Dec 2027 | 21 Jan 2028 | 19m 10d (+ 31d) | |
| 533903 | Torque Box Internal Side (FS 680 - FS 735) - Zonal Inspection | | G650 AMM_533903 | | HRS | 2315.6 | | | | | 21 Dec 2027 |
| Airframe 98.14 | Notes: | 21 | 05-20-00 98.14 | 15-May-23 | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 21 Dec 2027 | 21 Jan 2028 | 19m 10d (+ 31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 341300 | AIR Data System (No. 1 - Left Upper) - Functional / Leak Test | | G650 AMM_341300 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 1 | 30-Sep-12 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341301 | AIR Data System (No. 2 - Right Upper) - Functional / Leak Test | | G650 AMM_341301 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 1 | 30-Sep-12 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341302 | AIR Data System (No. 3 - Left Lower) - Functional / Leak Test | | G650 AMM_341302 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 1 | 30-Sep-12 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341303 | AIR Data System (No. 4 / Standby - Right Lower) - Functional / Leak Test | | G650 AMM_341303 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 1 | 30-Sep-12 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341311 | Multi-Function Probe / AIR Data Computer (No. 1 - Left Upper) - Certification | | G650 AMM_341311 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 11 | 30-Mar-18 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341312 | Multi-Function Probe / AIR Data Computer (No. 2 - Right Upper) - Certification | | G650 AMM_341312 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 11 | 30-Mar-18 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341313 | Multi-Function Probe / AIR Data Computer (No. 3 - Left Lower) - Certification | | G650 AMM_341313 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 11 | 30-Mar-18 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |
| 341314 | Multi-Function Probe / AIR Data Computer (No. 4 / Standby - Right Lower) - Certification | | G650 AMM_341314 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 11 | 30-Mar-18 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027 | | | 19m 20d |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 345512 | ATC (No. 1) - Operational Check | | G650 AMM_345512 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 1 30-Sep-12 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | | 19m 20d | |
| 345513 | ATC (No. 2) - Operational Check | | G650 AMM_345513 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 1065 | | | | | |
| | | | 1 30-Sep-12 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | | 19m 20d | |
| 122209 | Main Landing Gear Shock Absorber (Left) - Servicing | | G650 AMM_122209 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 83 | Notes: | | 05-20-00 83 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 122210 | Nose Landing Gear Shock Absorber - Servicing | | G650 AMM_122210 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 83 | Notes: | | 05-20-00 83 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 122315 | Horizontal Stabilizer Actuator - Lubrication | | G650 AMM_122315 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 32 | Notes: | | 05-10-10 32 | | AFL | 1065 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 03 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 122323 | Aileron Actuator Toggle Links (Left) - Lubrication | | G650 AMM_122323 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 31 | Notes: | | 05-10-10 31 | | AFL | 1065 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 122324 | Aileron Actuator Toggle Links (Right) - Lubrication | | G650 AMM_122324 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 31 | Notes: | | 05-10-10 31 | | AFL | 1065 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 122325 | Rudder Actuator Toggle Links - Lubrication | | G650 AMM_122325 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 32 | Notes: | | 05-10-10 32 | | AFL | 1065 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 122326 | Elevator Actuator Toggle Links (Left) - Lubrication | | G650 AMM_122326 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 32 | Notes: | | 05-10-10 | 32 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 122327 | Elevator Actuator Toggle Links (Right) - Lubrication | | G650 AMM_122327 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 32 | Notes: | | 05-10-10 | 32 | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 01 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 236130 | Static Discharging (Left Wing) - Functional Check | | G650 AMM_236130 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 236131 | Static Discharging (Right Wing) - Functional Check | | G650 AMM_236131 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 236132 | Static Discharging (Left Horizontal Stabilizer) - Functional Check | | G650 AMM_236132 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 236133 | Static Discharging (Right Horizontal Stabilizer) - Functional Check | | G650 AMM_236133 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 236134 | Static Discharging (Center Horizontal Stabilizer) - Functional Check | | G650 AMM_236134 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 236135 | Static Discharging (Tail Cone) - Functional Check | | G650 AMM_236135 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 | 86 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 237216 | Cockpit Voice Recorder Underwater Locator Beacon - Operational Check | | G650 AMM_237216 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 86 | | AFL | 1065 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 27 Nov 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 237217 | Cockpit Voice Recorder Underwater Locator Beacon - Cleaning | | G650 AMM_237217 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 86 | Notes: | | 05-20-00 86 | | AFL | 1065 | | | | | |
| | | | 23 | 31-Mar-24 | MOS | 27 Nov 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 242308 | Ram AIR Turbine Ground - Functional Check | | G650 AMM_242308 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Dec 2027 |
| Airframe 31 | Notes: | | 05-10-10 31 | | AFL | 1065 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 08 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 251111 | Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection | | G650 AMM_251111 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 251112 | Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection | | G650 AMM_251112 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 251113 | Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection | | G650 AMM_251113 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 256608 | Ditching Line - Detailed Inspection | | G650 AMM_256608 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 89 | Notes: FOR S/N'S S02335912,S02362665,S02362658,S02357165 | | 05-20-00 89 | | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 262150 | Engine FIRE Extinguishing Firing Circuitry Integrity (Left) - Operational Check | | G650 AMM_262150 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 90 | Notes: | | 05-20-00 90 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 18 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 262151 | Engine FIRE Extinguishing Firing Circuitry Integrity (Right) - Operational Check | | G650 AMM_262151 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 90 | Notes: | | 05-20-00 90 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 262152 | APU FIRE Extinguishing Firing Circuitry Integrity - Operational Check | | G650 AMM_262152 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 90 | Notes: | | 05-20-00 90 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 271007 | Aileron Attachment (Left) - Detailed Inspection | | G650 AMM_271007 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 92 | Notes: | | 05-20-00 92 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 271008 | Aileron Attachment (Right) - Detailed Inspection | | G650 AMM_271008 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 92 | Notes: | | 05-20-00 92 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 272010 | Rudder Attachment - Detailed Inspection | | G650 AMM_272010 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 93 | Notes: PN: 60P2212001Z001 SN: <NONE>. | | 05-20-00 93 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 273010 | Elevator Attachment (Left) - Detailed Inspection | | G650 AMM_273010 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 93 | Notes: | | 05-20-00 93 | | AFL | 802 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 273011 | Elevator Attachment (Right) - Detailed Inspection | | G650 AMM_273011 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 93 | Notes: | | 05-20-00 93 | | AFL | 802 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 275000 | Flap Drive System - General Visual Inspection | | G650 AMM_275000 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 94 | Notes: | | 05-20-00 94 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 275009 | Flap Attaching Points - Detailed Inspection | | G650 AMM_275009 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 94 | Notes: | | 05-20-00 | 94 | AFL | 802 | | | | | |
| | | | 17 | 30-Apr-21 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 276003 | Spoiler Attachment Fittings (Corrosion) - Detailed Inspection | | G650 AMM_276003 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 95 | Notes: | | 05-20-00 | 95 | AFL | 802 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 281602 | Heated Fuel Return System Valve - Operational Check | | G650 AMM_281602 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 97 | Notes: | | 05-20-00 | 97 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 27 Nov 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 282633 | Engine Fuel Shut-Off Valve (Left) - Operational Check | | G650 AMM_282633 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 97 | Notes: | | 05-20-00 | 97 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 15 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 282634 | Engine Fuel Shut-Off Valve (Right) - Operational Check | | G650 AMM_282634 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 97 | Notes: | | 05-20-00 | 97 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 15 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 291524 | Hydraulic System Shut-Off Valves - Operational Check | | G650 AMM_291524 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 97 | Notes: PN: A2350-0129 SN: <NONE>. | | 05-20-00 | 97 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 15 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 291712 | Hydraulic System Accumulator Precharge (Autobrake System) - Detailed Inspection | | G650 AMM_291712 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 97 | Notes: | | 05-20-00 | 97 | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 18 Dec 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |
| 313113 | FDR Underwater Locator Beacon - Operational Check | | G650 AMM_313113 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98 | Notes: | | 05-20-00 | 98 | AFL | 1065 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 27 Nov 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 321050 | Main Landing Gear and Components (Left) - Detailed Inspection | | G650 AMM_321050 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 321051 | Main Landing Gear and Components (Right) - Detailed Inspection | | G650 AMM_321051 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 322004 | Nose Landing Gear Components - Detailed Inspection | | G650 AMM_322004 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 335100 | Cabin Emergency Lighting - Operational Check | | G650 A0MM_335100 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 3 | Notes: | | 05-20-00 3 | | AFL | 1065 | | | | | |
| | | | 27 11-Nov-20 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 352100 | Passenger Oxygen Drop-Down Mask Assemblies - Detailed Inspection | | G650 A0MM_352100 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 3 | Notes: | | 05-20-00 3 | | AFL | 1065 | | | | | |
| | | | 35 29-Mar-24 | | MOS | 04 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 381424 | Water Tank - General Visual Inspection | | G650 AMM_381424 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.5 | Notes: | | 05-20-00 98.5 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 491300 | APU Turbine Plenum Drain - Operational Check | | G650 AMM_491300 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.6 | Notes: | | 05-20-00 98.6 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 27 Nov 2025 | 24 | 31 Dec 2027* | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 521001 | Main Entrance Door (Internal) - Zonal Inspection | | G650 AMM_521001 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.7 | Notes: | | 05-20-00 98.7 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 522000 | Emergency Exit Doors - Functional Check | | G650 AMM_522000 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.8 | Notes: | | 05-20-00 98.8 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 522001 | Emergency Exit Door Seals - Detailed Inspection | | G650 AMM_522001 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.8 | Notes: | | 05-20-00 98.8 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 523400 | Baggage Door Seal FS 824.5 - FS 867- Detailed Inspection | | G650 AMM_523400 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.9 | Notes: | | 05-20-00 98.9 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 527103 | Auxiliary Pressure Bulkhead Door Warning Indication - Operational Check | | G650 AMM_527103 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.9 | Notes: | | 05-20-00 98.9 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 530003 | Exterior Skin Panel Installations (Enclosed By Pylons) FS 838 - FS 1059.625 - Detailed Inspection | | G650 AMM_530003 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.15 | Notes: | | 05-20-00 98.15 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 530004 | External Lower Fuselage FS 100 - FS 886 - Zonal Inspection | | G650 AMM_530004 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.9 | Notes: | | 05-20-00 98.9 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 530006 | Lower Forward Cabin and Midcabin Sections FS 245.5 - FS 511.5 - Zonal Inspection | | G650 AMM_530006 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 802 | | | | | |
| | | | 10 30-Nov-17 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 530007 | Aft Midcabin Fuselage Below Floor Level FS 739 - FS 886 - Zonal Inspection | | G650 AMM_530007 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 802 | | | | | |
| | | | 10 30-Nov-17 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 530011 | Lower Forward Cabin and Midcabin Sections FS 245.5 - FS 511.5 - Enhanced Zonal Inspection | | G650 AMM_530011 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.13 | Notes: | | 05-20-00 98.13 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 530012 | Lower Forward Cabin and Midcabin Cleaning and Dust Removal - Enhanced Zonal Inspection | | G650 AMM_530012 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.13 | Notes: | | 05-20-00 98.13 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 530013 | Aft Midcabin Fuselage Below Floor Level FS 739 - FS 886 - Enhanced Zonal Inspection | | G650 AMM_530013 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.13 | Notes: | | 05-20-00 98.13 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 532604 | Leer Cleaning and Dust Removal - Enhanced Zonal Inspection | | G650 AMM_532604 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.25 | Notes: | | 05-20-00 98.25 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 532605 | Reer Cleaning and Dust Removal - Enhanced Zonal Inspection | | G650 AMM_532605 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.25 | Notes: | | 05-20-00 98.25 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 534001 | Baggage Compartment Below Floor Hirf/L - Detailed Inspection | | G650 AMM_534001 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 535000 | APU and Aft Fuselage Below Floor - Zonal Inspection | | G650 AMM_535000 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.34 | Notes: | | 05-20-00 98.34 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 535003 | Aft Fuselage Above Floor FS 886 - FS 1083.46 - Zonal Inspection | | G650 AMM_535003 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.35 | Notes: | | 05-20-00 98.35 | | AFL | 1065 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 539104 | Forward Wtbf Drain Holes - Enhanced Zonal Inspection | | G650 AMM_539104 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.36 | Notes: | | 05-20-00 98.36 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 539303 | Lower Mid Wtbf Drain Holes - Enhanced Zonal Inspection | | G650 AMM_539303 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.37 | Notes: | | 05-20-00 98.37 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 545001 | Pylons (Internal) - Zonal Inspection | | G650 AMM_545001 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.38 | Notes: | | 05-20-00 98.38 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 545004 | Idg Feeder Cables and Wiring Installations - Enhanced Zonal Inspection | | G650 AMM_545004 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.38 | Notes: | | 05-20-00 98.38 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 552008 | Elevator (External) Left - Detailed Inspection | | G650 AMM_552008 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 23 | Notes: | | 05-10-10 23 | | AFL | 802 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 552009 | Elevator (External) Right - Detailed Inspection | | G650 AMM_552009 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 23 | Notes: | | 05-10-10 23 | | AFL | 802 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 554002 | Rudder (External) - Detailed Inspection | | G650 AMM_554002 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 24 | Notes: | | 05-10-10 24 | | AFL | 802 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 570009 | Wing (Lower Surface External) from Wtbf to Winglet (Left) - Zonal Inspection | | G650 AMM_570009 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.45 | Notes: | | 05-20-00 98.45 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 570010 | Wing (Lower Surface External) from Wtbf to Winglet (Right) - Zonal Inspection | | G650 AMM_570010 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.45 | Notes: | | 05-20-00 98.45 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 570011 | Wing (External) Flaps, Spoilers and Ailerons (Left) - Zonal Inspection | | G650 AMM_570011 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 30 | Notes: | | 05-10-10 30 | | AFL | 1065 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 570012 | Wing (External) Flaps, Spoilers and Ailerons (Right) - Zonal Inspection | | G650 AMM_570012 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 30 | Notes: | | 05-10-10 30 | | AFL | 1065 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571031 | Main Landing Gear Sponsons and Support Fittings (Left) - Detailed Inspection | | G650 AMM_571031 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 802 | | | | | |
| | | | 18 15-Oct-21 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571032 | Main Landing Gear Sponsons and Support Fittings (Right) - Detailed Inspection | | G650 AMM_571032 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 802 | | | | | |
| | | | 18 15-Oct-21 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571200 | Wing Rear Beam Wiring Harness Installation (Left) - Enhanced Zonal Inspection | | G650 AMM_571200 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571201 | Wing Rear Beam Wiring Harness Installation (Right) - Enhanced Zonal Inspection | | G650 AMM_571201 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571204 | Wing Rear Beam Spar and Aileron (Left) - Zonal Inspection | | G650 AMM_571204 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 571205 | Wing Rear Beam Spar and Aileron (Right) - Zonal Inspection | | G650 AMM_571205 | | HRS | 2315.6 | | | | | 31 Dec 2027 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 802 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571206 | Wing Rear Spar / Flap / Spoiler (Left) - Zonal Inspection | | G650 AMM_571206 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571207 | Wing Rear Spar / Flap / Spoiler (Right) - Zonal Inspection | | G650 AMM_571207 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571208 | Wing Rear Beam Rbs 135.66 - Rbs 441 Hirf/L (Left) - Detailed Inspection | | G650 AMM_571208 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 02 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 571209 | Wing Rear Beam Rbs 135.66 - Rbs 441 Hirf/L (Right) - Detailed Inspection | | G650 AMM_571209 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 02 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 574026 | Wing Leading Edge and Gap Bands (External) (Left) - Zonal Inspection | | G650 AMM_574026 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.48 | Notes: | | 05-20-00 98.48 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 574027 | Wing Leading Edge and Gap Bands (External) (Right) - Zonal Inspection | | G650 AMM_574027 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.48 | Notes: | | 05-20-00 98.48 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |
| 575301 | Flap Upper Surface (Left) - Detailed Inspection | | G650 AMM_575301 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+ 31d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|---------------|-----------------|-------------|------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 575302 | Flap Upper Surface (Right) - Detailed Inspection | | G650 AMM_575302 | | HRS | 2909.1 | | | | | 31 Dec 2027 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 783112 | T/Rev and Exhaust Internal (Left) - Zonal Inspection | | G650 AMM_783112 | | HRS | 2315.6 | 2400 | 4715.6 | 4765.6 | 1669.5 (+50) | 31 Dec 2027 |
| Airframe 98.54 | Notes: | | 05-20-00 98.54 | | AFL | 802 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 783113 | T/Rev and Exhaust Internal (Right) - Zonal Inspection | | G650 AMM_783113 | | HRS | 2315.6 | 2400 | 4715.6 | 4765.6 | 1669.5 (+50) | 31 Dec 2027 |
| Airframe 98.54 | Notes: | | 05-20-00 98.54 | | AFL | 802 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 21 Dec 2023 | 48 | 31 Dec 2027 | 31 Jan 2028 | 19m 20d (+31d) | |
| 499003^U | APU - APU - APU Soap Oil Sample and Filter Element Analysis | | | | HRS | 2179 | 500 | 2679 | | 412.5 | 28 Jan 2028 |
| APU | Notes: | | | | APUS | 0 | | | | | |
| | | | | | MOS | 18 Dec 2025 | | | | | |
| 122328 | Flap Actuator Ball Nut (Left) - Lubrication | | G650 AMM_122328 | | HRS | 2909.1 | 1200 | 4109.1 | | 1063 | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | | 20m 20d | |
| 243508 | Emergency Battery (Forward) - Restore | | G650 AMM_243508 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 4 | Notes: MRI PARENT CODE: 243504 | | 05-10-00 4 | | AFL | 1065 | | | | | |
| | | | 20 15-Oct-22 | | MOS | 01 Dec 2025 | 48 | 31 Jan 2028 | | 20m 20d | |
| 122329 | Flap Actuator Ball Nut (Right) - Lubrication | | G650 AMM_122329 | | HRS | 2909.1 | 1200 | 4109.1 | 4159.1 | 1063 (+50) | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122330 | Outboard Spoiler Actuator Toggle Link (Left) - Lubrication | | G650 AMM_122330 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 122331 | Outboard Spoiler Actuator Toggle Link (Right) - Lubrication | | G650 AMM_122331 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122333 | Aileron Hinge Fitting (Left) - Lubrication | | G650 AMM_122333 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122334 | Aileron Hinge Fitting (Right) - Lubrication | | G650 AMM_122334 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122335 | Rudder Hinge Fitting - Lubrication | | G650 AMM_122335 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122336 | Elevator Hinge Fitting (Left) - Lubrication | | G650 AMM_122336 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122337 | Elevator Hinge Fitting (Right) - Lubrication | | G650 AMM_122337 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 84 | Notes: | | 05-20-00 84 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 122600 | Ram AIR Turbine - Lubrication | | G650 AMM_122600 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 85 | Notes: | | 05-20-00 85 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 05 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 242312 | Ram AIR Turbine - General Visual Inspection | | G650 AMM_242312 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 05 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 243502 | Emergency Battery (Forward) - Functional Check (Level Test) | | G650 AMM_243502 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: PN: 100-0302-03 SN: <NONE>. | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 243503 | Emergency Battery (Aft) - Functional Check (Level Test) | | G650 AMM_243503 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: PN: 100-0302-03 SN: <NONE>. | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 251114 | Crew Seat Restraints (Pilot) - Detailed Inspection | | G650 AMM_251114 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | | | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 251115 | Crew Seat Restraints (Copilot) - Detailed Inspection | | G650 AMM_251115 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | | | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 251116 | Crew Seat Restraints (Observer) - Detailed Inspection | | G650 AMM_251116 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | | | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 251117 | Crew Seat Inertia Reels (Pilot) - Operational Check | | G650 AMM_251117 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | | | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 251118 | Crew Seat Inertia Reels (Copilot) - Operational Check | | G650 AMM_251118 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | | | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 251119 | Crew Seat Inertia Reels (Observer) - Operational Check | | G650 AMM_251119 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 87 | Notes: | | 05-20-00 87 | | AFL | 1065 | | | | | |
| | | | | | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|---------------|------------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 252100 | Passenger Seats Attachments and Locking (Left Seat No. 1) - Detailed Inspection | | G650 A0MM_252100 | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe 1 | Notes: | | 05-20-00 | 1 | AFL | 802 | | | | | |
| | | | 35 | 29-Mar-24 | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252101 | Passenger Seats Restraints - Detailed Inspection | | G650 A0MM_252101 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 1 | Notes: | | 05-20-00 | 1 | AFL | 1065 | | | | | |
| | | | 35 | 29-Mar-24 | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252102 | Passenger Seats Inertia Reels - Operational Check | | G650 A0MM_252102 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 1 | Notes: | | 05-20-00 | 1 | AFL | 1065 | | | | | |
| | | | 35 | 29-Mar-24 | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252129^U | Passenger Seats Attachments and Locking (Left Seat No. 2) - Detailed Inspection | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | Notes: | | | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252134^U | Passenger Seats Attachments and Locking (Right Seat No. 1) - Detailed Inspection | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | Notes: | | | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252135^U | Passenger Seats Attachments and Locking (Right Seat No. 2) - Detailed Inspection | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | Notes: | | | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252140^U | Passenger Seats Attachments and Locking (Conference Table, Forward Inboard Seat) - Detailed Inspection | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | Notes: | | | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 252141^U | Passenger Seats Attachments and Locking (Conference Table, Forward Outboard Seat) - Detailed Inspection | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | Notes: | | | | AFL | 802 | | | | | |
| | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|---------------------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|--------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 252142^U | Passenger Seats Attachments and Locking (Conference Table, Aft Inboard Seat) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 252143^U | Passenger Seats Attachments and Locking (Conference Table, Aft Outboard Seat) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 252148^U | Passenger Seats Attachments and Locking (Right Divan Seat No. 1) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 252149^U | Passenger Seats Attachments and Locking (Right Divan Seat No. 2) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 252150^U | Passenger Seats Attachments and Locking (Right Divan Seat No. 3) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 252151^U | Passenger Seats Attachments and Locking (Right Divan Seat No. 4) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 252152^U | Passenger Seats Attachments and Locking (Crew Compartment Seat) - Detailed Inspection Notes: | | | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe | | | | | AFL | 802 | | | | | |
| | | | | | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) |
| 282632 | APU Fuel Shut-Off Valve - Operational Check Notes: | | G650 AMM_282632 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe | | | 05-20-00 | 97 | AFL | 1065 | | | | | |
| 97 | | | 8 | 30-Nov-16 | MOS | 02 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 291708 | Hydraulic System Accumulator Precharge (Left Hydraulic System) - Detailed Inspection | | G650 AMM_291708 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 97 | Notes: | | 05-20-00 97 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 291709 | Hydraulic System Accumulator Precharge (Right Hydraulic System) - Detailed Inspection | | G650 AMM_291709 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 97 | Notes: | | 05-20-00 97 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 291710 | Hydraulic System Accumulator Precharge (Inboard Brake System) - Detailed Inspection | | G650 AMM_291710 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 97 | Notes: | | 05-20-00 97 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 291711 | Hydraulic System Accumulator Precharge (Outboard Brake System) - Detailed Inspection | | G650 AMM_291711 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 97 | Notes: | | 05-20-00 97 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 313105 | FDR Fail Message - Operational Check | | G650 AMM_313105 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98 | Notes: | | 05-20-00 98 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 324701 | Tire Pressure Monitor System - Functional Check | | G650 AMM_324701 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.2 | Notes: | | 05-20-00 98.2 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 15 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 491217 | APU AIR Inlet Duct Door and Actuator - Detailed Inspection | | G650 AMM_491217 | | HRS | 2315.6 | | | | | 31 Jan 2028 |
| Airframe 98.5 | Notes: | | 05-20-00 98.5 | | AFL | 802 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 21 Dec 2023 | 48 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+ 29d) | |
| 520001 | Fuselage Doors (External) - Zonal Inspection | | G650 AMM_520001 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.7 | Notes: | | 05-20-00 98.7 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 20 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+ 29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 521004 | Main Entrance Door Cockpit Overhead Panel Safety Switch - Operational Check | | G650 AMM_521004 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.7 | Notes: | | 05-20-00 98.7 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 530014 | Vestibule and Forward Cabin Below Floor Hirf/L - Detailed Inspection | | G650 AMM_530014 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.13 | Notes: | | 05-20-00 98.13 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 19 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 531015 | Internal Left and Right Fuselage Below Cockpit Floor AT FS 223 - FS 243 - Zonal Inspection | | G650 AMM_531015 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.16 | Notes: | | 05-20-00 98.16 | | AFL | 1065 | | | | | |
| | | | 10 30-Nov-17 | | MOS | 09 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 531016 | Internal Left and Right Fuselage Below Cockpit Floor FS 223 - FS 243 - Enhanced Zonal Inspection | | G650 AMM_531016 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.17 | Notes: | | 05-20-00 98.17 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 18 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 531021 | Cockpit Below Floor Cleaning and Dust Removal - Enhanced Zonal Inspection | | G650 AMM_531021 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.17 | Notes: | | 05-20-00 98.17 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 09 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 531022 | Leer Hirf/L - Detailed Inspection | | G650 AMM_531022 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.17 | Notes: | | 05-20-00 98.17 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 19 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 531023 | Reer Hirf/L - Detailed Inspection | | G650 AMM_531023 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.17 | Notes: | | 05-20-00 98.17 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 19 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 531036 | Radome to Structure Perimeter Steps - Detailed Inspection | | G650 AMM_531036 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.18 | Notes: | | 05-20-00 98.18 | | AFL | 1065 | | | | | |
| | | | 17 30-Apr-21 | | MOS | 18 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 531304 | Splice Installations Below Floor Left Side FS 245.5 - FS 324.5 - Detailed Inspection | | G650 AMM_531304 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.2 | Notes: | | 05-20-00 98.2 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 12 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 534002 | Baggage Compartment Above Floor Hirf/L - Detailed Inspection | | G650 AMM_534002 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 19 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 534003 | Baggage Compartment Above Floor Hirf/L - General Visual Inspection | | G650 AMM_534003 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 19 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 534803 | Baggage Compartment Aft Electronic Equipment Rack Cleaning and Dust Removal - Enhanced Zonal Inspection | | G650 AMM_534803 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.34 | Notes: | | 05-20-00 98.34 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 19 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 539503 | Aft Wtbf Drain Holes - Enhanced Zonal Inspection | | G650 AMM_539503 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.38 | Notes: | | 05-20-00 98.38 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 05 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 564000 | Primary and Auxiliary Pressure Bulkhead Viewport - Operational Check | | G650 AMM_564000 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.44 | Notes: | | 05-20-00 98.44 | | AFL | 1065 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 01 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 571027 | Wing Tank (Internal) BI 0 - Rbs 135 (Left) - Detailed Inspection | | G650 AMM_571027 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 1065 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 12 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |
| 571028 | Wing Tank (Internal) BI 0 - Rbs 135 (Right) - Detailed Inspection | | G650 AMM_571028 | | HRS | 2909.1 | | | | | 31 Jan 2028 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 1065 | | | | | |
| | | | 16 30-Nov-20 | | MOS | 12 Dec 2025 | 24 | 31 Jan 2028* | 29 Feb 2028 | 20m 20d (+29d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|----------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 571600 | Wing to Fuselage, Floor Support and Wtbf Fittings (Left) - Detailed Inspection | | G650 AMM_571600 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 610 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 21 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 571601 | Wing to Fuselage, Floor Support and Wtbf Fittings (Right) - Detailed Inspection | | G650 AMM_571601 | | HRS | 1745.4 | | | | | 31 Jan 2028 |
| Airframe 98.47 | Notes: | | 05-20-00 98.47 | | AFL | 610 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 21 Jan 2022 | 72 | 31 Jan 2028 | 29 Feb 2028 | 20m 20d (+29d) | |
| 381219 | Clean Water Sterilizer Quartz Glass Sleeve and Uv Sensor Window (System A) - Restore | | G650 AMM_381219 | | HRS | 2909.1 | 800 | 3709.1 | | 663 | 13 Mar 2028 |
| Airframe 29 | Notes: PN: 02-100102-004 SN: <NONE>. MRI PARENT CODE: 381225 | | 05-10-00 29 | | AFL | 1065 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 12 Dec 2025 | | | | | |
| 381220 | Clean Water Sterilizer Quartz Glass Sleeve and Uv Sensor Window (System B) - Restore | | G650 AMM_381220 | | HRS | 2909.1 | 800 | 3709.1 | | 663 | 13 Mar 2028 |
| Airframe 29 | Notes: PN: 02-100102-004 SN: <NONE>. MRI PARENT CODE: 381226 | | 05-10-00 29 | | AFL | 1065 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 12 Dec 2025 | | | | | |
| 381239 | Water Sterilizer Sediment Filter Cartridge (System A, Polypropylene Filter) - Discard | 05-01-0001 NSN | G650 AMM_381239 | | HRS | 2909.1 | 800 | 3709.1 | | 663 | 13 Mar 2028 |
| Airframe 30 | Notes: COMPLIANCE TRANSFERRED FROM 381237. | | 05-10-00 30 | | AFL | 1065 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 12 Dec 2025 | | | | | |
| 381240 | Water Sterilizer Sediment Filter Cartridge (System B, Polypropylene Filter) - Discard | 05-01-0001 NSN | G650 AMM_381240 | | HRS | 2909.1 | 800 | 3709.1 | | 663 | 13 Mar 2028 |
| Airframe 30 | Notes: | | 05-10-00 30 | | AFL | 1065 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 12 Dec 2025 | | | | | |
| 274005 | Horizontal Stabilizer Trim Actuator Structure - Detailed Inspection | | G650 AMM_274005 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 9 | Notes: | | 05-10-10 9 | | AFL | 0 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | | 22m 20d | |
| 520002 | Fuselage Doors (Interior) - Zonal Inspection | | G650 AMM_520002 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.7 | Notes: | | 05-20-00 98.7 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 522202 | Emergency Exit Doors - Zonal Inspection | | G650 AMM_522202 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.8 | Notes: | | 05-20-00 98.8 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 522203 | Emergency Exit Doors Internal Structure - Detailed Inspection | | G650 AMM_522203 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.8 | Notes: | | 05-20-00 98.8 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 523001 | Baggage Compartment Door - Zonal Inspection | | G650 AMM_523001 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.8 | Notes: | | 05-20-00 98.8 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 523111 | Baggage Door Interior Skin and Structure - Detailed Inspection | | G650 AMM_523111 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.9 | Notes: | | 05-20-00 98.9 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 530001 | Antenna Interface - Detailed Inspection | | G650 AMM_530001 | | HRS | 1745.4 | | | | | 31 Mar 2028 |
| Airframe 12 | Notes: | | 05-10-10 12 | | AFL | 610 | | | | | |
| | | | 26 15-Nov-25 | | MOS | 03 Feb 2022 | 72 | 31 Mar 2028* | 30 Apr 2028 | 22m 20d (+30d) | |
| 530002 | Cabin Fixed Windows Internal - Detailed Inspection | | G650 AMM_530002 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.14 | Notes: | | 05-20-00 98.14 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 530005 | Radome (Interior) and Equipment AREA Behind Radome - Zonal Inspection | | G650 AMM_530005 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.1 | Notes: | | 05-20-00 98.1 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 530009 | Cabin Above Floor from Vestibule to Baggage Compartment FS 245.5 - FS 886 - Zonal Inspection | | G650 AMM_530009 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.12 | Notes: | | 05-20-00 98.12 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 531008 | Forward Fuselage Below Floor FS 148.5 - FS 245.5 - Detailed Inspection | | G650 AMM_531008 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.16 | Notes: | | 05-20-00 | 98.16 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531011 | Cockpit Interior Above Headliner FS 167 - FS 245.5 - Zonal Inspection | | G650 AMM_531011 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.16 | Notes: | | 05-20-00 | 98.16 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531020 | Internal Below Pedestal - Zonal Inspection | | G650 AMM_531020 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.17 | Notes: | | 05-20-00 | 98.17 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531037 | Internal Cockpit Below Floor FS 167 - FS 189 - Zonal Inspection | | G650 AMM_531037 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.18 | Notes: | | 05-20-00 | 98.18 | AFL | 0 | | | | | |
| | | | 10 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028* | 30 Apr 2028 | 22m 20d (+30d) | |
| 531301 | Nose Wheel Well Trunnion and Drag Brace Fittings - Detailed Inspection | | G650 AMM_531301 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.2 | Notes: | | 05-20-00 | 98.2 | AFL | 0 | | | | | |
| | | | 18 | 15-Oct-21 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531305 | Splice Installations Below Floor (Dry Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection | | G650 AMM_531305 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.2 | Notes: | | 05-20-00 | 98.2 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531502 | Floor Structure Left Side FS 245.5 - FS 324.5 - Detailed Inspection | | G650 AMM_531502 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.21 | Notes: | | 05-20-00 | 98.21 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531503 | Floor Structure (Dry Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection | | G650 AMM_531503 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.21 | Notes: | | 05-20-00 | 98.21 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 531705 | Cockpit Internal Structure Headliner Removed - Detailed Inspection | | G650 AMM_531705 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.21 | Notes: | | 05-20-00 | 98.21 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531706 | Cockpit Splice and Crossbeam Internal - Detailed Inspection | | G650 AMM_531706 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.22 | Notes: | | 05-20-00 | 98.22 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531707 | Side Window Rails and Posts Internal (Left) - Detailed Inspection | | G650 AMM_531707 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.22 | Notes: | | 05-20-00 | 98.22 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531708 | Side Window Rails and Posts Internal (Right) - Detailed Inspection | | G650 AMM_531708 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.22 | Notes: | | 05-20-00 | 98.22 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531709 | Windshield Rails and Posts Internal (Left) - Detailed Inspection | | G650 AMM_531709 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.22 | Notes: | | 05-20-00 | 98.22 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 531710 | Windshield Rails and Posts Internal (Right) - Detailed Inspection | | G650 AMM_531710 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.22 | Notes: | | 05-20-00 | 98.22 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532101 | Interior Upper Forward Midcabin Panel Installation Headliner Removed FS 324.5 - FS 529 - Detailed Inspection | | G650 AMM_532101 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.23 | Notes: | | 05-20-00 | 98.23 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 532102 | Interior Left and Right Forward Midcabin Panel Installations Above Floor FS 324.5 - FS 529 - Detailed Inspection | | G650 AMM_532102 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.23 | Notes: | | 05-20-00 | 98.23 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532301 | Left and Right Stringer 6 and Midbay Skin Splices (Above Floor) FS 324.5 - FS 529 - Detailed Inspection | | G650 AMM_532301 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.24 | Notes: | | 05-20-00 | 98.24 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532502 | Cabin Below Floor Seat Track Beams and Support Structure (Dry Areas) FS 321 - FS 511.5 - Detailed Inspection | | G650 AMM_532502 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.25 | Notes: | | 05-20-00 | 98.25 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532600 | Leer FS 246 - FS 270 - Zonal Inspection | | G650 AMM_532600 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.25 | Notes: | | 05-20-00 | 98.25 | AFL | 826 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 26 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532601 | Leer FS 246 - FS 270 - Enhanced Zonal Inspection | | G650 AMM_532601 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.25 | Notes: | | 05-20-00 | 98.25 | AFL | 826 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 26 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532602 | Reer FS 251.5 - FS 285 - Zonal Inspection | | G650 AMM_532602 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.25 | Notes: | | 05-20-00 | 98.25 | AFL | 826 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 26 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 532603 | Reer FS 251.5 - FS 285 - Enhanced Zonal Inspection | | G650 AMM_532603 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.25 | Notes: | | 05-20-00 | 98.25 | AFL | 826 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 26 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 533101 | Interior Center Midcabin Side Panel Installation FS 529 - FS 747.75 - Detailed Inspection | | G650 AMM_533101 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.26 | Notes: | | 05-20-00 | 98.26 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533102 | Interior Upper Center Midcabin Panel Installation FS 529 - FS 747.75 - Detailed Inspection | | G650 AMM_533102 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.27 | Notes: | | 05-20-00 | 98.27 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533103 | Center Midcabin Mainframe Installation FS 529 and FS 686.5 - Detailed Inspection | | G650 AMM_533103 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.27 | Notes: | | 05-20-00 | 98.27 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533104 | Emergency Exit Door Internal Surround Structures - Detailed Inspection | | G650 AMM_533104 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.27 | Notes: | | 05-20-00 | 98.27 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533203 | Bulkhead Aft Face Below Floor FS 739 - Detailed Inspection | | G650 AMM_533203 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.27 | Notes: | | 05-20-00 | 98.27 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533500 | Pressure Floor Structure Below Floor FS 511.5 - FS 739 - Detailed Inspection | | G650 AMM_533500 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.29 | Notes: | | 05-20-00 | 98.29 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144** | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533503 | Pressure Floor Structure AT Wheel Wells Below Floor FS 511.5 - FS 669 - Detailed Inspection | | G650 AMM_533503 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 18 | Notes: | | 05-10-10 | 18 | AFL | 0 | | | | | |
| | | | 24 | 30-Oct-24 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 533900 | Torque Box Interior - Detailed Inspection | | G650 AMM_533900 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.3 | Notes: | | 05-20-00 | 98.3 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 533901 | Torque Box Exterior and Links - Detailed Inspection | | G650 AMM_533901 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.3 | Notes: | | 05-20-00 98.3 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534100 | Interior Upper Aft Mid Panel Installation FS 739 - FS 886 - Detailed Inspection | | G650 AMM_534100 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.31 | Notes: | | 05-20-00 98.31 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534101 | Interior Aft Mid Side Panel Installations FS 739 - FS 886 - Detailed Inspection | | G650 AMM_534101 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.31 | Notes: | | 05-20-00 98.31 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534104 | Aft Mid Splice Installations Above Floor FS 739 - FS 886 - Detailed Inspection | | G650 AMM_534104 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.31 | Notes: | | 05-20-00 98.31 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534201 | Aft Engine Mount Frame Installation Below Floor FS 951.31 - Detailed Inspection | | G650 AMM_534201 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.32 | Notes: | | 05-20-00 98.32 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534202 | Aft Mid Frame Installations Above Floor FS 823 and FS 868.5 - Detailed Inspection | | G650 AMM_534202 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.32 | Notes: | | 05-20-00 98.32 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534204 | Secondary Pressure Bulkhead Door FS 805.5 - Detailed Inspection | | G650 AMM_534204 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.32 | Notes: | | 05-20-00 98.32 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534205 | Secondary Pressure Bulkhead Above Floor FS 805.5 - Detailed Inspection | | G650 AMM_534205 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.32 | Notes: | | 05-20-00 98.32 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 534206 | Secondary Pressure Bulkhead Below Floor FS 805.5 - Detailed Inspection | | G650 AMM_534206 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.32 | Notes: | | 05-20-00 | 98.32 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534207 | Primary Pressure Bulkhead - Detailed Inspection | | G650 AMM_534207 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.33 | Notes: | | 05-20-00 | 98.33 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534500 | Aft Mid Auxiliary Pressure Floor Structures Above Floor (Dry Areas) FS 739 - FS 805.5 - Detailed Inspection | | G650 AMM_534500 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.33 | Notes: | | 05-20-00 | 98.33 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534501 | Aft Mid Auxiliary Pressure Floor Structures Above Floor (Wet Areas) FS 739 - FS 805.5 - Detailed Inspection | | G650 AMM_534501 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.33 | Notes: | | 05-20-00 | 98.33 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534502 | Aft Mid Auxiliary Pressure Floor Structures Below Floor (Dry Areas) FS 739 - FS 805.5 - Detailed Inspection | | G650 AMM_534502 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.33 | Notes: | | 05-20-00 | 98.33 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534503 | Aft Mid Auxiliary Pressure Floor Structures Below Floor (Wet Areas) FS 739 - FS 805.5 - Detailed Inspection | | G650 AMM_534503 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.33 | Notes: | | 05-20-00 | 98.33 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534600 | APU Enclosure FS 886 - FS 951.3 - General Visual Inspection | | G650 AMM_534600 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.33 | Notes: | | 05-20-00 | 98.33 | AFL | 826 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 26 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 534700 | Engine Mount Installation FS 886 - FS 951.31 - Detailed Inspection | | G650 AMM_534700 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.34 | Notes: | | 05-20-00 | 98.34 | AFL | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 534801 | Baggage Compartment Forward Electronic Equipment Rack Cleaning and Dust Removal - Enhanced Zonal Inspection | | G650 AMM_534801 | | HRS | 1745.4 | | | | | 31 Mar 2028 |
| Airframe 98.34 | Notes: | | 05-20-00 98.34 | | AFL | 610 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 08 Feb 2022 | 72 | 31 Mar 2028* | 30 Apr 2028 | 22m 20d (+30d) | |
| 535002 | Aft Fuselage Below Floor FS 951.31 - FS 1071.75 - Zonal Inspection | | G650 AMM_535002 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.35 | Notes: | | 05-20-00 98.35 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 535100 | Aft Fuselage Above Floor FS 951.31 - FS 1103.25 - General Visual Inspection | | G650 AMM_535100 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.35 | Notes: | | 05-20-00 98.35 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 535101 | Aft Fuselage Interior Below Floor FS 951.31 - FS 1103.25 - General Visual Inspection | | G650 AMM_535101 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.35 | Notes: | | 05-20-00 98.35 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 535103 | Aft Fuselage Interior Above Floor FS 951.31 - FS 1103.25 - General Visual Inspection | | G650 AMM_535103 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.36 | Notes: | | 05-20-00 98.36 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 551002 | Horizontal Stabilizer Assembly (External) Left - General Visual Inspection | | G650 AMM_551002 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.38 | Notes: | | 05-20-00 98.38 | | AFL | 826 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 551003 | Horizontal Stabilizer Assembly (External) Right - General Visual Inspection | | G650 AMM_551003 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.38 | Notes: | | 05-20-00 98.38 | | AFL | 826 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 551200 | Horizontal Stabilizer Center Box and Actuator Attachments - Detailed Inspection | | G650 AMM_551200 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 551500 | Horizontal Stabilizer Elevator Hinge Brackets (Left) - Detailed Inspection | | G650 AMM_551500 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 551501 | Horizontal Stabilizer Elevator Hinge Brackets (Right) - Detailed Inspection | | G650 AMM_551501 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.4 | Notes: | | 05-20-00 98.4 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 553006 | Vertical Stabilizer (External) - General Visual Inspection | | G650 AMM_553006 | | HRS | 2382.4 | | | | | 31 Mar 2028 |
| Airframe 98.41 | Notes: | | 05-20-00 98.41 | | AFL | 826 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 553007 | Vertical Stabilizer Assembly (Internal) - Detailed Inspection | | G650 AMM_553007 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.41 | Notes: | | 05-20-00 98.41 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 553501 | Vertical Stabilizer (Internal) Boomerang Fittings - Detailed Inspection | | G650 AMM_553501 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.42 | Notes: | | 05-20-00 98.42 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 554000 | Vertical Stabilizer Rudder Hinges and Support Fittings - Detailed Inspection | | G650 AMM_554000 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.42 | Notes: | | 05-20-00 98.42 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 571023 | Wing Aft, Spars, Splices and Spar Cans (External) Surfaces (Left) - Detailed Inspection | | G650 AMM_571023 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.45 | Notes: | | 05-20-00 98.45 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|-----|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 571024 | Wing Aft, Spars, Splices and Spar Cans (External) Surfaces (Right) - Detailed Inspection | | G650 AMM_571024 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.45 | Notes: | | 05-20-00 98.45 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 571025 | Wing Aft Spar Splices (External) Surfaces (Left) - Detailed Inspection | | G650 AMM_571025 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 571026 | Wing Aft Spar Splices (External) Surfaces (Right) - Detailed Inspection | | G650 AMM_571026 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.46 | Notes: | | 05-20-00 98.46 | | AFL | 0 | | | | | |
| | | | 8 31-Jul-12 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 575008 | Wing Flight Control Attach Fittings (Left) - Detailed Inspection | | G650 AMM_575008 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 575009 | Wing Flight Control Attach Fittings (Right) - Detailed Inspection | | G650 AMM_575009 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 575010 | Inboard / Outboard Fixed Trailing Edges and Cove Panels (Left) - Detailed Inspection | | G650 AMM_575010 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 575011 | Inboard / Outboard Fixed Trailing Edges and Cove Panels (Right) - Detailed Inspection | | G650 AMM_575011 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 575307 | Flap Fittings (Left) - Detailed Inspection | | G650 AMM_575307 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|--|---------------|-----------------|-------------|------|---------------|------------------|------------------|-------------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 575308 | Flap Fittings (Right) - Detailed Inspection | | G650 AMM_575308 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 576000 | Aileron Hinge Fittings and Forward Spar (Left) - Detailed Inspection | | G650 AMM_576000 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 576001 | Aileron Hinge Fittings and Forward Spar (Right) - Detailed Inspection | | G650 AMM_576001 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 577000 | Spoiler Hinge Fittings (Left) - Detailed Inspection | | G650 AMM_577000 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 577001 | Spoiler Hinge Fittings (Right) - Detailed Inspection | | G650 AMM_577001 | | HRS | 0 | | | | | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 11 Mar 2016 | 144 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 710035 | Nacelle, T/Rev and Exhaust External (Left, Viewed from Platform) - Zonal Inspection | | G650 AMM_710035 | | HRS | 2382.4 | 2400 | 4782.4 | 4832.4 | 1736.3 (+50) | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 826 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 710036 | Nacelle, T/Rev and Exhaust External (Right, Viewed from Platform) - Zonal Inspection | | G650 AMM_710036 | | HRS | 2382.4 | 2400 | 4782.4 | 4832.4 | 1736.3 (+50) | 31 Mar 2028 |
| Airframe 98.49 | Notes: | | 05-20-00 98.49 | | AFL | 826 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 28 Mar 2024 | 48 | 31 Mar 2028 | 30 Apr 2028 | 22m 20d (+30d) | |
| 492001 | APU - APU Fuel and Oil System (External) - General Visual Inspection | | G650 AMM_492001 | | HRS | 2179 | 600 | 2779 | 2829 | 512.5 (+50) | 28 Jun 2028 |
| APU 74 | Notes: | | 05-20-00 74 | | APUS | 0 | | | | | |
| | | | 8 30-Nov-16 | | MOS | 29 Nov 2025 | | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|---------------|-----------------|-------------|------|---------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 492102 | APU - Branched Wiring Harness (Wiring Harness) - General Visual Inspection | | G650 AMM_492102 | | HRS | 2179 | 600 | 2779 | 2829 | 512.5 (+50) | 28 Jun 2028 |
| APU 74 | Notes: | | 05-20-00 | 74 | APUS | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | | | | | |
| 493402 | APU - Fuel Filter Bypass Indicator - Detailed Inspection (Delta P Indicator) | | G650 AMM_493402 | | HRS | 2179 | 600 | 2779 | 2829 | 512.5 (+50) | 28 Jun 2028 |
| APU 74 | Notes: | | 05-20-00 | 74 | APUS | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | | | | | |
| 494202 | APU - Starter Motor - Detailed Inspection | | G650 AMM_494202 | | HRS | 2179 | 600 | 2779 | 2829 | 512.5 (+50) | 28 Jun 2028 |
| APU 75 | Notes: | | 05-20-00 | 75 | APUS | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | | | | | |
| 498100 | APU - APU Exhaust Duct (Internal Only) - General Visual Inspection | | G650 AMM_498100 | | HRS | 2179 | 600 | 2779 | 2829 | 512.5 (+50) | 28 Jun 2028 |
| APU 75 | Notes: | | 05-20-00 | 75 | APUS | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | | | | | |
| 498101 | APU - APU Fluted Exhaust and Turbine Bearing Support - General Visual Inspection | | G650 AMM_498101 | | HRS | 2179 | 600 | 2779 | 2829 | 512.5 (+50) | 28 Jun 2028 |
| APU 75 | Notes: | | 05-20-00 | 75 | APUS | 0 | | | | | |
| | | | 8 | 30-Nov-16 | MOS | 29 Nov 2025 | | | | | |
| 323912 | Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Hydrostatic) (Left) - Functional Check | | G650 AMM_323912 | | HRS | 2315.6 | | | | | 30 Jun 2028 |
| Airframe 34 | Notes: PN: 1159SCH233-11 SN: ALT603-12656. MRI PARENT CODE: 323900 | | -- | 34 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 60 | 30 Jun 2028 | | 25m 19d | |
| 323913 | Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Hydrostatic) (Right) - Functional Check | | G650 AMM_323913 | | HRS | 2315.6 | | | | | 30 Jun 2028 |
| Airframe 34 | Notes: PN: 1159SCH233-11 SN: ALT603-12659. MRI PARENT CODE: 323901 | | -- | 34 | AFL | 802 | | | | | |
| | | | 26 | 15-Nov-25 | MOS | 21 Dec 2023 | 60 | 30 Jun 2028 | | 25m 19d | |
| 256085 | Life Vest (No. 12) - Restore | 00002260 | G650 AMM_256085 | | HRS | 2483.7 | | | | | 31 Oct 2028 |
| Airframe 5 | Notes: | 1597-073 | 05-10-00 | 5 | AFL | 900 | | | | | |
| | | | 17 | 30-Apr-21 | MOS | 16 Dec 2024 | | 31 Oct 2028 | | 29m 20d | |
| | | | | | MSC | | N/A | | | | |

| ATA | Description | Part Number | Source Document | | UOM | Complied With | Freq (**Initial) | Next Due (*=Adj) | Max Due | Remains (^=Due) | Projected Due Date |
|----------------|---|--------------------|------------------|-------------|-----|---------------|------------------|------------------|---------|-----------------|--------------------|
| Logbook | | Serial Number | Section | Page | | | | | | | |
| Mfg Ref Number | Notes | | Revision | Date Issued | | | | | | | |
| 262452 | Portable Water FIRE Extinguisher - (Hydrostatic) Functional Check | | G650 A0MM_262452 | | HRS | 2315.6 | | | | | 31 Oct 2028 |
| Airframe 5 | Notes: PN: 892480 SN: 30816. | | 05-10-00 5 | | AFL | 802 | | | | | |
| | | | 35 29-Mar-24 | | MOS | 21 Dec 2023 | 60 | 31 Oct 2028 | | 29m 20d | |
| 352303 | Passenger Oxygen Cylinder - (Hydrostatic) Functional Check | | G650 AMM_352303 | | HRS | 2315.6 | | | | | 31 Oct 2028 |
| Airframe | Notes: PN: 805983-15 SN: C15051134. MRI PARENT CODE: 352300 | | -- | | AFL | 802 | | | | | |
| | | | 24 30-Oct-24 | | MOS | 21 Dec 2023 | 60 | 31 Oct 2028 | | 29m 20d | |
| 275076 | C Track Flap Roller (Left Inboard Upper Aft) - Discard | 60P5755371Z011 NSN | G650 AMM_275076 | | HRS | 1594.1 | 2400 | 3994.1 | 4044.1 | 948 (+50) | 27 Dec 2028 |
| Airframe 8 | Notes: MRI PARENT CODE: 275145 | | 05-10-00 8 | | AFL | 547 | | | | | |
| | | | 23 31-Mar-24 | | MOS | 11 Jan 2021 | | | | | |
| 275079 | C Track Flap Roller (Left Outboard Upper Forward) - Discard | 60P5755371Z007 NSN | G650 AMM_275079 | | HRS | 1594.1 | 2400 | 3994.1 | 4044.1 | 948 (+50) | 27 Dec 2028 |
| Airframe 8 | Notes: MRI PARENT CODE: 275148 | | 05-10-00 8 | | AFL | 547 | | | | | |
| | | | 23 31-Mar-24 | | MOS | 15 Jan 2021 | | | | | |
| 275080 | C Track Flap Roller (Left Outboard Upper Aft) - Discard | 60P5755371Z011 NSN | G650 AMM_275080 | | HRS | 1594.1 | 2400 | 3994.1 | 4044.1 | 948 (+50) | 27 Dec 2028 |
| Airframe 8 | Notes: MRI PARENT CODE: 275149 | | 05-10-00 8 | | AFL | 547 | | | | | |
| | | | 23 31-Mar-24 | | MOS | 15 Jan 2021 | | | | | |
| 275082 | C Track Flap Roller (Right Inboard Upper Aft) - Discard | 60P5755371Z011 NSN | G650 AMM_275082 | | HRS | 1594.1 | 2400 | 3994.1 | 4044.1 | 948 (+50) | 27 Dec 2028 |
| Airframe 8 | Notes: MRI PARENT CODE: 275151 | | 05-10-00 8 | | AFL | 547 | | | | | |
| | | | 23 31-Mar-24 | | MOS | 12 Jan 2021 | | | | | |
| 275085 | C Track Flap Roller (Right Outboard Upper Forward) - Discard | 60P5755371Z007 NSN | G650 AMM_275085 | | HRS | 1594.1 | 2400 | 3994.1 | 4044.1 | 948 (+50) | 27 Dec 2028 |
| Airframe 8 | Notes: MRI PARENT CODE: 275154 | | 05-10-00 8 | | AFL | 547 | | | | | |
| | | | 23 31-Mar-24 | | MOS | 15 Jan 2021 | | | | | |
| 275086 | C Track Flap Roller (Right Outboard Upper Aft) - Discard | 60P5755371Z011 NSN | G650 AMM_275086 | | HRS | 1594.1 | 2400 | 3994.1 | 4044.1 | 948 (+50) | 27 Dec 2028 |
| Airframe 8 | Notes: MRI PARENT CODE: 275155 | | 05-10-00 8 | | AFL | 547 | | | | | |
| | | | 23 31-Mar-24 | | MOS | 15 Jan 2021 | | | | | |