



TECH TIP

Product: DISPENSING VALVE – UF1 and UFB

Subject: REPLACEMENT BANJO VALVE FOR WATER AND SYRUP


Date: NOVEMBER 16, 2012

Effective Date: JANUARY 1, 2013

As part of the continuous improvement to our product lines, IMI Cornelius is updating the material selection of the “Banjo” valve to a more reliable and longer wearing material. The new parts are completely interchangeable with the old parts, and will not affect the operation of the valve.

Both water and syrup sides of the valve will now use a single component, **P/N 1947**.

- 1) **P/N 1947** (black) is the current part number, and looks identical to old **P/N 1947**.
- 2) **P/N 560003995** (white banjo) will be discontinued and replaced by **P/N 1947**.



Current Banjo Valve Set-up



New Banjo Valve Set-up

The new **P/N 1947** will have two identifying marks in area located below.

