



FFV SURE-FILL LEVER UPGRADE KIT (CCUSA P/N 24017)

This kit was developed to upgrade older style FFV Sure-Fill valves with components that reduce the intermittent effects caused by condensation (e.g., more insulation on the lever, use of some plastic components in place of metal, etc.) Only use this kit when:

1. The technician has determined that the problem definitely stems from condensation through the use of the diagnostic chart,
2. The installed FFV Sure-Fill valve was manufactured prior to 12/92 (mfg. date is located on bottom of the valve near the nozzle), and
3. The valve components have not previously been upgraded. If the valve has upgraded components, you should see black insulation coating $\approx 1/2$ " long on the valve lever where it exits the base plate of the valve. Insulation on older style valve stops where the lever exits the base plate of the valve.

The kit includes a new lever, plastic screws and washers, a lever spring, valve retainer bail, tape and a tube of silicon for sealing.