

CG Motorsports
11880 Hammersmith Way 150, Richmond, BC V7A 5C8
(604) 275-6638 | info@cgmotorsports.com




[Inspection Report](#) Visit Details

Your Visit

[View Details →](#)

Kurumasource Auto Sales LTD 2018 Mercedes-Benz C300
RO# 34935 | Time In 08/18/2026 08:18 AM
Service Advisor J Campbell

Vehicle Health



Technician Findings

✖ BUSHINGS

^

Finding:
Front lower control arm bushing to strut clevis is deteriorating.

Front thrust arms starting to crack

Rear lower rearward control arm bushing to subframe is deteriorating

⚠ WIPER BLADES

^

Finding:
Rear wipers are streaky

⚠ FRONT TIRE TREAD DEPTH

^

Finding:
4 - Sizing in photos for quoting staggered set up. Tires are DOT 2017, 9 years old.

⚠ OTHER RECOMMENDED SERVICES

^

Finding:
Lots of rust

Fault code list in photos



 DRIVELINE, DRIVESHAFT(S), AXLES



Finding:
Driveshaft flex disk is starting to crack



Inspections Performed

Simple Multi-Point Vehicle Inspection

Inspection Task	Findings
STANDARD INSPECTION	
 WIPER BLADES	Rear wipers are streaky
 TIRE PRESSURES	
 FRONT TIRE TREAD DEPTH	4 - Sizing in photos for quoting staggered set up. Tires are DOT 2017, 9 years old. 
 REAR TIRE TREAD DEPTH	6
 FRONT BRAKE PAD MEASUREMENT	10
 REAR BRAKE PAD MEASUREMENT	6
 WARNING LIGHTS ON	
 EXTERIOR LIGHTS	
SUSPENSION	
 ROTATION NEEDED?	
 ALIGNMENT NEEDED?	
 WEAR PATTERN DAMAGE	
 BRAKE LINE	
Front lower control arm bushing to strut clevis is deteriorating. Front thrust arms starting to crack Rear lower rearward control arm bushing to subframe is deteriorating	

Inspection Task	Findings
BUSHINGS	
STRUTS	
DRIVELINE	
DRIVELINE, DRIVESHAFT(S), AXLES	Driveshaft flex disk is starting to crack 
UNDERHOOD	
ENGINE AIR FILTER	
EXHAUST SYSTEM COMPONENTS	
HOSES & BELTS	
WASHER FLUID	
TRANSMISSION FLUID LEAKS	
ENGINE OIL LEAKS	
POWER STEERING LEAKS	
COOLANT	
DIFFERENTIAL LEAK	
BRAKE FLUID	
MAINTENANCE	
RECOMMENDED MILEAGE MAINTENANCE	
OTHER RECOMMENDED SERVICES	Lots of rust Fault code list in photos 

5 technician concerns found

Vehicle Drop off/Check-in quick inspection



Inspection Task

Findings

DAMAGE INSPECTION

✓ HOOD



✓ FRONT BUMPER



✓ DRIVER SIDE



✓ REAR BUMPER



✓ PASSENGER SIDE



✓ INTERIOR



✓ TRUNK



✓ WHEELS



✓ HEADLIGHTS AND TAILLIGHTS

Inspection Task	Findings
	   
 WINDSHIELD	 
0 technician concerns found	

Need a copy for your records?

 Print

Questions? Contact Us.

 Call

 Email

 Text

