


TOSOT Parts Diagram



41	Cold Plasma Generator		
40	Remote Controller		
39	Connecting Cable		
38	Connecting Cable		
37	Power Cord		
36	Electric Box Cover2		
35	Screw Cover		
34	Decorative Board (Right)		
33	Terminal Board		
32	Electric Box Cover		
31	Shield Cover of Electric Box		
30	Main Board		
29	Jumper		
28	Electric Box		
27	Lower Shield of Electric Box		
26	Electric Box Assy		
25	Drainage hose		
24	Stepping Motor		
23	Crank		
22	Connecting pipe clamp		
21	Wall Mounting Frame		
20	Motor Press Plate		
19	Fan Motor		
18	Cross Flow Fan		
17	Evaporator Assy		
16	Evaporator Support		
15	Ring of Bearing		
14	O-Gasket sub-assy of Bearing		
13	Rubber Plug (Water Tray)		
12	Rear Case Assy		
11	Left Axle Bush		
10	Helicoid tongue		
9	Air Louver		
8	Axle Bush		
7	Guide Louver		
6	Front Case		
5	Decorative Board (Left)		
4	Filter Sub-Assy		
3	Display Board		
2	Front Panel		
1	Decorative Strip		