


TOSOT Parts Diagram



39	Remote Controller
38	Temperature Sensor
37	Connecting Cable
36	Connecting Cable
35	Power Cord
34	Electric Box Assy
33	Lower Shield of Electric Box
32	Jumper
31	Electric Box Cover
30	Shield cover of Electric Box
29	Display Board
28	Main Board
27	Electric Box Cover2
26	Terminal Board
25	Electric Box
24	Axle Bush
23	Guide Lever
22	Crank
21	Stepping Motor
20	Discharge Hole
19	Connecting pipe clamp
18	Fan Motor
17	Motor Press Plug
16	Wall Mounting Frame
15	Cold Plasma Generator
14	Evaporator Assy
13	Evaporator Support
12	Cover Plate Fan
11	Cr-Gasket sub-assy of Bearing
10	Ring of Bearing
9	Rubber Plug (Water Tray)
8	Bear Case Assy
7	Left Axle Bush
6	Half-round Tongue
5	Air Louver (Manual)
4	Front Case Assy
3	Screw Cover
2	Filter Sub-assy
1	Front Panel Assy