


TOSOT Parts Diagram



35	Temperature Sensor
36	Temperature Sensor
37	Connecting Cable
38	Connecting Cable
39	Power Cord
1	Electric Box Assy
2	Lower Shield of Electric Box
3	Upper Shield of Electric Box
4	Shield cover of Electric Box
5	Display Board
6	Main Board
7	Electric Box Cover2
8	Terminal Board
9	Electric Box
10	Acute Bush
11	Acute Bush
12	Crush
13	Strapping Motor
14	Connecting pipe clamp
15	Fan Motor
16	Motor Press Plug
17	Wall Mounting Yarn
18	Cold Plasma Generator
19	Evaporator Assy
20	Evaporator Support
21	Condenser Fan
22	Condenser sub-assy of Bearing
23	Ring of Bearing
24	Ring of Bearing
25	Ring of Bearing
26	Ring of Bearing
27	Ring of Bearing
28	Ring of Bearing
29	Ring of Bearing
30	Ring of Bearing
31	Ring of Bearing
32	Ring of Bearing
33	Ring of Bearing
34	Ring of Bearing
35	Ring of Bearing
36	Ring of Bearing
37	Ring of Bearing
38	Ring of Bearing
39	Ring of Bearing