


3450 16th Ave. W., Seattle, WA 98119 • 206-634-1656 • www.dustystrings.com

Overture Stringing Diagram



indicates marked courses.
PB indicates phosphor bronze.
PBW indicates phosphor bronze wound.
All other strings are plain steel.
Superscript numbers indicate octaves. C⁴ is middle C.