

Dusty Strings


Makers of Harps and Hammered Dulcimers

3450 16th Ave. W., Seattle, WA 98119 • 206-634-1656 • www.dustystings.com

D550

Stringing Diagram

for instruments after serial #13168



All strings are loop end. Wire gauges are shown in inches.

PB indicates phosphor bronze wire.

PBW indicates phosphor bronze wound.

SSW indicates stainless steel wound.

Unspecified strings are plain steel.

Dots indicate marked courses.

Superscript numbers indicate octave. C4 is middle C.