

Dusty Strings

Makers of Harps and Hammered Dulcimers

3450 16th Ave. W., Seattle, WA 98119 • 206-634-1656 • www.dustystings.com

PD40 Stringing Diagram

	C ^{#6} -■	□--D ⁶ -.016"	
	B ⁵ --□	□--C ⁶ -.016"	
	A ⁵ --□	■--B ^{b5} -.016"	
	G ⁵ -□	■--G ^{#5} -.018"	
	F ⁵ --□	■--F [#] -.018"	
	E ^{b5} -■	□--E ⁵ --.020"	
	C ^{#5} -■	□--D ⁵ -.020"	
	B ⁴ --□	□--C ⁵ -.022"	
	A ⁴ --□	■--B ^{b4} -.022"	
	G ⁴ -□	■--G ^{#4} -.022"	
	F ⁴ --□	■--F ^{#4} -.022"	
	E ^{b4} -■	□--E ⁴ --.022" PB	■--F ^{#3} --.022" PB
□--F ³ -.022" PB	■--E ^{b3} -.022" PB	□--D ³ --.030" PBW	□--E ³ --.022" PB
■--C ^{#3} -.032" PBW	C ^{#4} ■	□--C ³ --.034" PBW	□--D ³ --.030" PBW
□--B ² -.040" PBW	B ³ --□	■--A ^{#2} --.040" PBW*	□--C ³ --.034" PBW
□--A ² -.044" PBW*	A ³ --□	■--G ^{#2} -.044" PBW*	■--A ^{#2} --.040" PBW*
□--G ² -.054" PBW*	G ³ -□		■--G ^{#2} -.044" PBW*

All strings are loop end. Wire gauges are shown in inches.

■ and □ indicate white and black bridge markers.

PB indicates phosphor bronze.

PBW indicates phosphor bronze wound.

All other strings are plain steel.

Small number indicate octaves. C⁴ is middle C.

* Single string courses.