




Shaun Arnold
11/06/2026 10:13 | Europe, London

#48

APA**Arnold Powered Access Ltd**Make & Model **LGMG SR1623D**Serial Number **0790136**Fleet Registration Number **16/23-33**Year of Manufacture: **2022**Safe Working Load* **680KG**Machine Hours: **1515**Customer Name **United Powered Access**Examination Location **Midleton Industrial Estate, 5, Guildford, United Kingdom, GU2 8XW**

Full Site Address: **C/O INTEGRA CLADDING
MCS BUILD LTD
C/O INTEGRA CLADDING LTD
MIDLETON IND ESTATE ROAD
GUILDFORD
GU2 8FT**

Lift Type: **None**Lift Type: **None**

Category C Defects/Observations: **Operators manual in poor condition.
1 x scissor pack bump stop missing**

Rectification date for above defects: **ASAP**

Examination date: **11/06/2026 | Europe/London (+01:00)**

Date of last examination: **16/12/2025 | Europe/London (+00:00)**

Date of next examination: **10/12/2026 | Europe/London (+00:00)**

Comments/Observations:

Engineers Name: **Shaun Arnold**

CAP Number: **04663**

Engineers Signature:



Thorough Examination: **Passed**

Report compliant with LOLER regulations 1998. Defects given time restrictions must be rectified by the stated date. If not rectified the LOLER will expire on the latest rectification date listed.

Arnold Powered Access Ltd

arnoldpoweredaccess@outlook.com

Ref: 17131/177736

Examination by: Shaun Arnold