

issues

INFORMATION BULLETIN No. Harmony LSA-048b

- 1. CONCERNING:** *All Harmony LSA aircraft without vortex generators.*
- 2. REASON:** *Issue a new Flight Manual for Harmony LSA without vortex generators, doc. No. HARMLSAULSFM, date of issue 25. 05. 2026.*
- 3. REQUIRED ACTIONS:** *The operator / owner is required to place Flight Manual for Harmony LSA without vortex generators on board the aircraft.*
- 4. LATEST DAY OF THE ACTION:** *Immediately after receiving this bulletin.*
- 5. CARRIED OUT BY:** *Operator / owner of the aircraft.*
- 6. COST COVERED BY:** *Operator / owner of the aircraft.*
- 7. NECESSARY MATERIAL:** *Flight Manual for Harmony LSA without vortex generators, doc. No. HARMLSAULSFM, date of issue 25. 05. 2026*
- 8. WORK PROCEDURE:** *Place the printed copy of Flight Manual for Harmony LSA without vortex generators, doc. No. HARMLSAULSFM delivered with the aircraft on board.*
- 9. APPENDICES:** *None.*

Valid from: 12. 06. 2026

QS-406/F-05K