

2005 | SN 154 | N91AJ

GULFSTREAM G100



HIGHLIGHTS

Engines & APU Enrolled on MSP Gold Programs
Universal UNS-1Ew FMS | Fresh B Inspection
New R/H Windshield | Four (4) New Brakes
Configured for 9 Passengers, with Enclosed Belted Aft Lav



AIRFRAME

Time Since New	5,667
Cycles Since New	4,210
Entry Into Service	2005

ENGINES

Description	Engine No. 1	Engine No. 2
Make	Honeywell	Honeywell
Model	TFE731-40R-200G	TFE731-40R-200G
Time Since New	5,667	5,667
Cycles Since New	4,210	4,210
Time to MPI (3,500 HRS)	401.1	401.1
Time to CZI (7,000 HRS)	1,334	1,334
Program	MSP Gold	MSP Gold

APU

Make	Honeywell GTCP36-150(W)
Time Since New	5,074
Cycles Since New	5,074
Program	MSP Gold

AVIONICS


Avionics Package:	Collins Pro Line 4
ADF:	Dual Collins ADF-462
Communication Radios:	Dual Collins VHF-422C
Cockpit Voice Recorder:	Yes
DME:	Dual Collins DME-442
EFIS:	Collins 4-tube
FMS:	Universal UNS-1Ew
Hi Frequency:	Yes
Navigation Radios:	Dual VHF
Radio Altimeter:	Yes
SATCOM:	Yes w/dual handsets
TAWS:	Honeywell Mark V EGPWS w/windshear
TCAS:	TCAS-II w/change 7
Transponder:	Dual Collins TDR-94D w/ ADSB-Out
Weather Radar:	Yes

EXTERIOR

Base Color:	Matterhorn White
Accent:	Red & Gold Accent Stripes
Year Painted:	Fuselage 2013; Rework & Stripes 2020

INTERIOR

Passengers:	Executive Nine (9) Passenger Configuration
Galley/Refreshment:	Forward Galley
Cabin Configuration:	Forward Three (3) Place Divan Opposite One (1) Forward Single Seat, Aft Four (4) Club
Lavatory:	Enclosed Belted Aft Lav w/ Lighted Sink & Mirror
Entertainment:	Cabin Management System



ADDITIONAL EQUIPMENT & FEATURES

- ADS-B Out
- Dual Air Data Computers
- Airborne Datalink
- Collins DBU-4000 Database Unit
- Winglets

INSPECTION STATUS

INSPECTION	LAST COMPLETED	NEXT DUE
A Inspection	At 5,667 TT	250 Hours Remaining
B Inspection	At 5,667 TT	500 Hours Remaining
C Inspection	At 5,177 TT, June 2023	At 6,177 TT, or June 2027











FAVOR DE NO
TIRAR PAPERS
EN EL BAÑO

Doors and drawers must be closed
on takeoff and landing



NOTES TO BE
No Cigarette Disposal
No Tirar Colillas



LIFE VEST
SALVAVIDAS







D. Cameron Jones
President

Jones Aviation Group
8226 Douglas Ave, Suite 525
Dallas, Texas 75225
214.454.7161
cameron@jonesaviationgroup.com

