

DEXIS - How to export scans as stl files

1. Select the export step of IS ScanFlow



2. From the export window, select the 'SAVE AS' icon on the left



- 3. Select your destination by clicking the 3 dots
- 4. Under Export Format, select STL
- 5. Click the 'SAVE' button

