

Maintenance Items

N204WC

Make & Model (Serial)
EMBRAER EMB 505 (Phenom 300) (50500098)

Operator
Sun Aviation LLC

Reported Date
03-May-2025

Hours
3043.40

Landings
2816

- Major Components

Component	Model (Serial)	Hours	Cycles
Engine 1	PW535E (PCE-DG0190)	3043.40	2816.00
Engine 2	PW535E (PCE-DG0194)	3043.40	2816.00

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
04 20-00 Airframe INSPECTION #62	LIFE LIMIT EMB-505 AIRPLANE OPERATION	07-MAY-2012	L: 5000			L: 5000	L: 2184
05 1254 Engine 1 INSPECTION #166	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
05 1254 Engine 2 INSPECTION #101	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
05 20-00-210-801 Engine 1 INSPECTION #249	NO. 1 ENGINE - OVERHAUL	30-DEC-2011	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
05 20-00-210-801 Engine 2 INSPECTION #341	NO. 2 ENGINE - OVERHAUL	20-JAN-2012	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
05 20-00-210-804 Engine 1 INSPECTION #49	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	18-APR-2024 H: 2895.60 C: 2711	M: 24	M: 1		18-APR-2026	M: 8 D: 20

Notes

(1)LOW UTILIZATION ENG IS DEFINED AS AN ENGINE THAT HAS NOT BEEN SUBJECTED TO DISASSEMBLY AND INSP OF BOTH HOT AND COLD SECTION AT AN APPROVED FACILITY BY THE END OF THE FOLLOWING SERVICE INTERVALS

- 10 YEARS SINCE ENTRY INTO SERVICE/OVERHAUL
- 11 YEARS SINCE ENGINE MANUFACTURE

(3) SUBSEQUENT LUI'S ARE TO BE PERFORMED EVERY 24 M INTERVAL PROVIDED THAT VISUAL INSP, BORESCOPE INSP, AND PERFORMANCE CAL RUNS ARE SAT. OTHERWISE, RETURN THE ENGINE TO AN APPROVED FACILITY FOR MAINTENANCE OR REPAIRS. NOTE: PERIODIC INSPECTIONS LISTED IN TASK 05-20-00-210-801, RECOMMENDED MAINTENANCE TASKS ARE SEPARATE REQUIREMENTS TO THE LUI AND ARE TO BE ACCOMPLISHED AT THE REQUIRED SPECIFIED INTERVALS.

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 20-00-210-804 Engine 2 INSPECTION #24	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	18-APR-2024 H: 2895.60 C: 2711	M: 24	M: 1		18-APR-2026	M: 8 D: 20
	Notes (1) LOW UTILIZATION ENG IS DEFINED AS AN ENGINE THAT HAS NOT BEEN SUBJECTED TO DISASSEMBLY AND INSP OF BOTH HOT AND COLD SECTION AT AN APPROVED FACILITY BY THE END OF THE FOLLOWING SERVICE INTERVALS • 10 YEARS SINCE ENTRY INTO SERVICE/OVERHAUL • 11 YEARS SINCE ENGINE MANUFACTURE (3) SUBSEQUENT LUI'S ARE TO BE PERFORMED EVERY 24 M INTERVAL PROVIDED THAT VISUAL INSP, BORESCOPE INSP, AND PERFORMANCE CAL RUNS ARE SAT. OTHERWISE, RETURN THE ENGINE TO AN APPROVED FACILITY FOR MAINTENANCE OR REPAIRS. NOTE: PERIODIC INSPECTIONS LISTED IN TASK 05-20-00-210-801, RECOMMENDED MAINTENANCE TASKS ARE SEPARATE REQUIREMENTS TO THE LUI AND ARE TO BE ACCOMPLISHED AT THE REQUIRED SPECIFIED INTERVALS.						
05 30-01 Airframe INSPECTION #596	800 FH MAINTENANCE PACKAGE	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
05 30-10 Airframe INSPECTION #239	1600 FH MAINTENANCE PACKAGE	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
05 30-20 Airframe INSPECTION #727	2400 FH MAINTENANCE PACKAGE	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
05 30-40 Airframe INSPECTION #1019	3200 FH MAINTENANCE PACKAGE	07-MAY-2012	H: 3200.00	H: 30.00		H: 3200.00	H: 156.60
05 30-42 Airframe INSPECTION #1777	3200 FH/60 MO MAINTENANCE PACKAGE	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
05 30-50 Airframe INSPECTION #1081	5600 FH MAINTENANCE PACKAGE	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
05 30-60 Airframe INSPECTION #1808	6400 FH MAINTENANCE PACKAGE	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 30-80 Airframe INSPECTION #1143	12 MO MAINTENANCE PACKAGE	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
05 30-81 Airframe INSPECTION #142	24 MO MAINTENANCE PACKAGE	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
05 30-82 Airframe INSPECTION #1387	36 MO MAINTENANCE PACKAGE	18-APR-2024 H: 2895.60 L: 2711	M: 36	M: 1		18-APR-2027	M: 20 D: 20
05 30-83 Airframe INSPECTION #1887	48 MO MAINTENANCE PACKAGE	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
05 30-84 Airframe INSPECTION #1271	60 MO MAINTENANCE PACKAGE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
05 30-87 Airframe INSPECTION #755	120 MO MAINTENANCE PACKAGE	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
05 30-90 Airframe INSPECTION #956	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
05 50-00-210-802 Engine 1 INSPECTION #470	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS	30-DEC-2011					
05 50-00-210-802 Engine 2 INSPECTION #471	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS	20-JAN-2012					
05 50-00-210-803 Engine 1 INSPECTION #451	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - ENGINE OVERTEMPERATURE	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 50-00-210-803 Engine 2 INSPECTION #467	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - ENGINE OVERTEMPERATURE	20-JAN-2012					
05 50-00-210-804 Engine 1 INSPECTION #468	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - ENGINE OVERSPEED	30-DEC-2011					
05 50-00-210-804 Engine 2 INSPECTION #463	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - ENGINE OVERSPEED	20-JAN-2012					
05 50-00-210-805 Engine 1 INSPECTION #472	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	30-DEC-2011					
05 50-00-210-805 Engine 2 INSPECTION #461	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	20-JAN-2012					
05 50-00-210-806 Engine 1 INSPECTION #467	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - LIGHTNING STRIKE	30-DEC-2011					
05 50-00-210-806 Engine 2 INSPECTION #454	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - LIGHTNING STRIKE	20-JAN-2012					
05 50-00-210-807 Engine 1 INSPECTION #462	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - DROPPED ENGINE	30-DEC-2011					
05 50-00-210-807 Engine 2 INSPECTION #458	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - DROPPED ENGINE	20-JAN-2012					
05 50-00-210-808 Engine 1 INSPECTION #469	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - HEAVY LANDING	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 50-00-210-808 Engine 2 INSPECTION #451	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - HEAVY LANDING	20-JAN-2012					
05 50-00-210-809 Engine 1 INSPECTION #456	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT	30-DEC-2011					
05 50-00-210-809 Engine 2 INSPECTION #468	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT	20-JAN-2012					
05 50-00-210-810 Engine 1 INSPECTION #453	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - ENGINE IMMERSION IN WATER	30-DEC-2011					
05 50-00-210-810 Engine 2 INSPECTION #464	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - ENGINE IMMERSION IN WATER	20-JAN-2012					
05 50-00-210-811 Engine 1 INSPECTION #457	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	30-DEC-2011					
05 50-00-210-811 Engine 2 INSPECTION #470	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	20-JAN-2012					
05 50-00-210-812 Engine 1 INSPECTION #471	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	30-DEC-2011					
05 50-00-210-812 Engine 2 INSPECTION #460	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	20-JAN-2012					
05 50-00-210-813 Engine 1 INSPECTION #459	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - LOSS OF OIL	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 50-00-210-813 Engine 2 INSPECTION #457	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - LOSS OF OIL	20-JAN-2012					
05 50-00-210-814 Engine 1 INSPECTION #464	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - CHIP DETECTOR LIGHT "ON"	30-DEC-2011					
05 50-00-210-814 Engine 2 INSPECTION #459	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - CHIP DETECTOR LIGHT "ON"	20-JAN-2012					
05 50-00-210-815 Engine 1 INSPECTION #461	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	30-DEC-2011					
05 50-00-210-815 Engine 2 INSPECTION #456	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	20-JAN-2012					
05 50-00-210-816 Engine 1 INSPECTION #460	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	30-DEC-2011					
05 50-00-210-816 Engine 2 INSPECTION #450	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	20-JAN-2012					
05 50-00-210-817 Engine 1 INSPECTION #455	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE	30-DEC-2011					
05 50-00-210-817 Engine 2 INSPECTION #469	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE	20-JAN-2012					
05 50-00-210-818 Engine 1 INSPECTION #452	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 50-00-210-818 Engine 2 INSPECTION #466	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS	20-JAN-2012					
05 50-00-210-819 Engine 1 INSPECTION #466	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - FUEL FILTER CONTAMINATION	30-DEC-2011					
05 50-00-210-819 Engine 2 INSPECTION #452	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - FUEL FILTER CONTAMINATION	20-JAN-2012					
05 50-00-210-820 Engine 1 INSPECTION #454	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN	30-DEC-2011					
05 50-00-210-820 Engine 2 INSPECTION #449	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN	20-JAN-2012					
05 50-00-210-821 Engine 1 INSPECTION #463	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL	30-DEC-2011					
05 50-00-210-821 Engine 2 INSPECTION #453	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL	20-JAN-2012					
05 50-00-210-822 Engine 1 INSPECTION #458	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	30-DEC-2011					
05 50-00-210-822 Engine 2 INSPECTION #465	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	20-JAN-2012					
05 50-00-210-823 Engine 1 INSPECTION #450	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - FUEL CONTAMINATION	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 50-00-210-823 Engine 2 INSPECTION #455	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - FUEL CONTAMINATION	20-JAN-2012					
05 50-00-210-824 Engine 1 INSPECTION #465	UNSCHEDULED MAINTENANCE - NO. 1 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE	30-DEC-2011					
05 50-00-210-824 Engine 2 INSPECTION #462	UNSCHEDULED MAINTENANCE - NO. 2 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE	20-JAN-2012					
05 H140-001 Airframe INSPECTION 120M #1613	EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE (L/HIRF)	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
05 H242-001 Airframe INSPECTION 120M #982	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE (L/HIRF)	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
05 H430-001 Airframe INSPECTION 60M #41	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS (L/HIRF)	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
05 H700-001 Airframe INSPECTION 60M #623	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDINGJUMPERS AND CONNECTORS (L/HIRF)	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
05 H700-002 Airframe INSPECTION 60M, NLG #1668	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDINGJUMPERS AND CONNECTORS (L/HIRF) Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
05 H700-003 Airframe INSPECTION 60M #766	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING (L/HIRF)	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 REVISION Engine 1 INSPECTION #432	REVISION STATUS (PLEASE SEE NOTES) COMPLIANCE NOT REQUIRED Notes PLEASE REFERENCE THE ATTACHMENT TAB TO REVIEW REVISION CHANGES MADE TO YOUR TRACKING. NEXT DUE DATE REFLECTED IS THE REVISION RELEASED DATE, PLEASE CONTACT AMP@ATP.COM OR CALL US AT 239-390-3199 IF WE CAN BE OF ANY ADDITIONAL ASSISTANCE						
05 REVISION Engine 2 INSPECTION #431	REVISION STATUS (PLEASE SEE NOTES) COMPLIANCE NOT REQUIRED Notes PLEASE REFERENCE THE ATTACHMENT TAB TO REVIEW REVISION CHANGES MADE TO YOUR TRACKING. NEXT DUE DATE REFLECTED IS THE REVISION RELEASED DATE, PLEASE CONTACT AMP@ATP.COM OR CALL US AT 239-390-3199 IF WE CAN BE OF ANY ADDITIONAL ASSISTANCE						
05 REVISION Airframe INSPECTION #2216	REVISION STATUS (PLEASE SEE NOTES) COMPLIANCE NOT REQUIRED - AMM (2757) SMR AR4 MAR 11/22 Notes PLEASE REFERENCE THE ATTACHMENT TAB TO REVIEW REVISION CHANGES MADE TO YOUR TRACKING. NEXT DUE DATE REFLECTED IS THE REVISION RELEASED DATE, PLEASE CONTACT AMP@ATP.COM OR CALL US AT 239-390-3199 IF WE CAN BE OF ANY ADDITIONAL ASSISTANCE.						
05 REVISION Airframe INSPECTION #2215	REVISION STATUS (PLEASE SEE NOTES) COMPLIANCE NOT REQUIRED - AMM (2757) SMR REV. 4 MAR 2021 Notes PLEASE REFERENCE THE ATTACHMENT TAB TO REVIEW REVISION CHANGES MADE TO YOUR TRACKING. NEXT DUE DATE REFLECTED IS THE REVISION RELEASED DATE, PLEASE CONTACT AMP@ATP.COM OR CALL US AT 239-390-3199 IF WE CAN BE OF ANY ADDITIONAL ASSISTANCE.						
05 Z210-002 Airframe INSPECTION 120M #1161	ZONAL INSPECTION - GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION Reference Number AMM 05-41-00-210 -802-A/600	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
05 Z430-002 Airframe INSPECTION 120M #151	ZONAL INSPECTION - GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE Reference Number AMM 05-46-00-210 -804-A/600	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 Z700-001 Airframe INSPECTION 60M #722	ZONAL INSPECTION - GVI - EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY Reference Number AMM 05-4 7 -00-21 0-801-A/600	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
12 Airframe INSPECTION #2057	EXTERIOR DETAILING AND BRIGHT WORK POLISH Notes FOXTROT AVIATION - SCHEDULED QUARTERLY	02-MAY-2019 H: 2052.70 L: 2048					
12 Airframe INSPECTION #2056	ROUTINE POST FLIGHT CLEAN, SERVICE AND INSPECT Notes 4 MH FOR EACH LANDING AT DTW	03-JUL-2019					
21 01-01 Airframe PART #1544	RH INSC ILLUM PANEL Part Number 441-42629-002 Serial Number 1098	07-MAY-2012					
21 20-01 Airframe PART #104	AVIONICS BLOWER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
21 20-02 Airframe PART #1381	AVIONICS/DISPLAY COOLING FAN Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
21 20-03 Airframe PART #1503	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY Part Number 1300250-9 Serial Number 368	07-MAY-2012					
21 20-03 Airframe PART #1410	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY Part Number 1300250-9 Serial Number 370	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 20-05 Airframe PART #600	GROUND COOLING FAN Part Number 1133660-3 Serial Number 277	12-MAY-2017 H: 1452.20 L: 1499					
21 21-02-001 Airframe INSPECTION 6400H #647	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
21 21-02-001 Airframe INSPECTION 6400H #952	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
21 23-01 Airframe PART #47	ELECTROMECHANICAL LINEAR ACTUATOR Part Number 100000-77 Serial Number 26735	07-MAY-2012					
21 23-03 Airframe PART #1964	RAM AIR VALVE Part Number 505-18030-405 Serial Number 0000694150	07-MAY-2012					
21 23-03-002 Airframe INSPECTION 6400H #781	OPERATIONAL CHECK OF RAM AIR VALVE POSITION	14-APR-2014 H: 623.30 L: 675	H: 6400.00	H: 30.00		H: 7023.30	H: 3979.90
21 23-03-003 Airframe INSPECTION 800H #1164	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
21 23-04-001 Airframe INSPECTION 6400H #838	OPERATIONAL CHECK OF RAM AIR CHECK VALVES	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
21 23-05-001 Airframe INSPECTION 1600H #437	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 24-01-001 Airframe INSPECTION 5600H, 6400H #2062	OPERATIONAL CHECK OF IFE COOLING FAN (EFFECTIVITY: ON EMBRAER 505 ACFT WITH IFE/CMS COOLING FAN)			H: 30.00			
21 31-00-002 Airframe INSPECTION 800H #1793	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
21 31-00-003 Airframe INSPECTION 800H #427	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
21 31-00-004 Airframe INSPECTION 5600H #908	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
21 31-00-005 Airframe INSPECTION 5600H #1402	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
21 31-01-001 Airframe PART - Overhaul #1027	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) Part Number 2119286-5 Serial Number 2119286-00693	20-DEC-2013 H: 513.10 L: 563	H: 5600.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 6113.10	H: 3069.70
	Notes BASED ON COMPONENT TSN OR TSO						
21 31-02-001 Airframe PART - Overhaul #1468	RESTORATION (REPAIR) OF OUTFLOW VALVE Part Number 103922-1 Serial Number 103922-00119	07-MAY-2012	H: 7200.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 7200.00	H: 4156.60
	Notes BASED ON COMPONENT TSN OR TSO						
21 31-03 Airframe PART #759	NEGATIVE PRESSURE RELIEF (NPR) VALVE Part Number 130664-2 Serial Number 34163-0438	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 31-03-001 Airframe INSPECTION 5600H #143	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
21 31-04 Airframe PART #1172	PRESSURE RELIEF (PRV) VALVE Part Number 103918-2 Serial Number 103918-00178	07-MAY-2012					
21 31-04-001 Airframe INSPECTION 5600H #11	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
21 41-04 Airframe PART #433	RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
21 52-01-002 Airframe INSPECTION #474	DISCARD OF COMPRESSOR DRIVE MODULE BELT	19-MAY-2016 H: 1156.90 L: 1222	H: 2000.00	H: 30.00		H: 3576.00	H: 532.60
21 52-01-003 Airframe INSPECTION 800H #1251	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
21 52-01-004 Airframe PART - Overhaul #683	RESTORATION (OVERHAUL) CDM - COMPRESSOR Part Number 1133640-5 Serial Number 179	10-MAY-2018 H: 1776.00 L: 1789	H: 2000.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 3776.00	H: 732.60
	Notes AS PER OPERATOR DISCRETION						
21 52-03 Airframe PART #1293	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE Part Number 1133860-4 Serial Number 189	07-MAY-2012					
21 52-03-001 Airframe INSPECTION 800H #202	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 52-04 Airframe PART #757	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER Part Number 1133850-104 Serial Number 514	07-MAY-2012					
21 52-06-001 Airframe INSPECTION 12M #996	SERVICING OF VCS REFRIGERANT FLUID	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
21 52-08 Airframe PART #1971	AIR CONDITION CONDENSER ASSEMBLY Part Number 1133760-2 Serial Number 209	07-MAY-2012					
21 52-08-001 Airframe INSPECTION 1600H #953	GENERAL VISUAL INSPECTION OF VCS CONDENSER	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
21 52-09 Airframe PART #657	AIR CONDITION MIX FLOW CONDENSER FAN Part Number 1133720-4 Serial Number 127	12-MAY-2017 H: 1452.20 L: 1499					
21 52-10 Airframe PART #1459	AIR CONDITION BLEED AIR HEAT EXCHANGER Part Number 1320260-2 Serial Number 210	07-MAY-2012					
21 61-00-001 Airframe INSPECTION 800H #1174	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
21 61-01 Airframe PART #485	ECS TEMPERATURE CONTROLLER Part Number 1300670-6 Serial Number 00159	11-MAY-2018 H: 1776.00 L: 1789					
	Notes MFD 11/2012						
21 61-03 Airframe PART #811	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH Part Number 1300450-10 Serial Number 1728	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 61-03 Airframe PART #1620	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH Part Number 1300450-10 Serial Number 1748	07-MAY-2012					
21 61-04 Airframe PART #1405	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH Part Number 1300450-10 Serial Number 1689	07-MAY-2012					
21 61-05 Airframe PART #1816	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH Part Number 1300450-10 Serial Number 1383	07-MAY-2012					
21 61-06-001 Airframe INSPECTION 6400H #1221	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
22 11-00 Airframe PART #1551	GMC 715 GUIDANCE PANEL Part Number 011-01430-00 Serial Number 15900596	07-MAY-2012					
22 11-00-001 Airframe INSPECTION #313	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO	18-APR-2024 H: 2895.60 L: 2711	M: 12	D: 30		18-APR-2025	M: -3 D: -11
22 11-00-001 Airframe INSPECTION #1866	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO	18-APR-2024 H: 2895.60 L: 2711	M: 12	D: 30		18-APR-2025	M: -3 D: -11
22 11-00-001 Airframe INSPECTION #1383	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO	18-APR-2024 H: 2895.60 L: 2711	M: 12	D: 30		18-APR-2025	M: -3 D: -11
22 11-00-001 Airframe INSPECTION #1119	FUNCTIONAL CHECK TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO	18-APR-2024 H: 2895.60 L: 2711	M: 12	D: 30		18-APR-2025	M: -3 D: -11

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 11-00-002 Airframe INSPECTION 12M #1094	LUBRICATION OF SERVO ACTUATORS	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
22 11-00-003 Airframe INSPECTION 3200H/60M #260	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
22 11-01 Airframe PART #1788	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO Part Number 011-00877-21 Serial Number 1A0005783	07-MAY-2012					
22 11-02 Airframe PART #266	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO Part Number 011-00878-20 Serial Number 1A1016670	12-MAY-2017 H: 1452.20 L: 1499					
22 11-02 Airframe PART #1650	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO Part Number 011-00878-20 Serial Number 1A1007320	24-APR-2019 H: 2052.70 L: 2048					
22 11-02 Airframe PART #1893	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO Part Number 011-00878-20 Serial Number 1A1008033	28-OCT-2023 H: 2850.90 L: 2677					
22 11-03 Airframe PART #529	AILERON GSM 86 AUTOPILOT SERVO MOUNT Part Number 011-01904-00 Serial Number 1GK007159	07-MAY-2012					
22 11-03-001 Airframe INSPECTION 36M #2289	DIS - DISCARD OF AILERON CLUTCH RETAINING BOLT AND WASHER Reference Number AMM TASK 22-11-03-960-801-A/200 Notes EFFECTIVITY: ON ACFT WITH AILERON CLUTCH RETAINING BOLT PN 211-00090-03 OR PRE-MOD SB 505-22-0006	03-MAY-2025 H: 3019.50 L: 2801	M: 36	M: 1		03-MAY-2028	M: 33 D: 4
22 11-06 Airframe PART #1311	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT Part Number 011-01904-00 Serial Number 1GK007155	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 11-09 Airframe PART #136	RUDDER GSM 86 AUTOPILOT SERVO MOUNT Part Number 011-01904-00 Serial Number 1GK007155	18-JUL-2022 H: 2611.00 L: 2496					
22 11-12 Airframe PART #736	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT Part Number 011-01904-00 Serial Number 1GK007157	07-MAY-2012					
23 10-01 Airframe PART #452	VHF ANTENNA Part Number S65-8280-41 Serial Number 322-2879	07-MAY-2012					
23 11-01 Airframe PART #1570	PS440 HF CONTROL DISPLAY UNIT Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
23 11-02 Airframe PART #495	REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
23 11-03 Airframe PART #793	KPA 1052 POWER AMPLIFIER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
23 11-04 Airframe PART #735	HF ANTENNA COUPLER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
23 12-02 Airframe PART #1593	BOTTOM VHF 2 ANTENNA Part Number S65-8280-41 Serial Number 322-4262	20-OCT-2017 H: 1623.30 L: 1648					
23 21-01 Airframe PART #1733	SELCAL CSD DECODER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 50-01 Airframe PART #548	LEFT GMA 1347D AUDIO PANEL Part Number 011-03568-20 Serial Number 4QF105357	03-MAY-2023 H: 2749.10 L: 2607					
23 50-02 Airframe PART #913	COPILOT HEADSET Part Number 026-55-999-0131 Serial Number 00200505	07-MAY-2012					
23 50-02 Airframe PART #398	PILOT HEADSET Part Number 026-55-999-0131 Serial Number 00200502	07-MAY-2012					
23 50-03 Airframe PART #26	HAND MICROPHONE Part Number 85-03-12369-04 Serial Number 259882	07-MAY-2012					
23 50-04 Airframe PART #670	COCKPIT SPEAKER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
23 50-05 Airframe PART #438	CDVR MICROPHONE Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
23 51-00-001 Airframe INSPECTION 3200H #1390	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE	07-MAY-2012	H: 3200.00	H: 30.00		H: 3200.00	H: 156.60
23 51-01 Airframe PART #1208	RIGHT GMA 1347D AUDIO PANEL Part Number 011-03568-20 Serial Number 4QF105792	03-MAY-2023 H: 2749.10 L: 2607					
23 51-05 Airframe PART #321	LEFT CONTROL PANEL Part Number 441-40943-002 Serial Number 0783	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 51-05 Airframe PART #472	RIGHT CONTROL PANEL Part Number 441-40943-002 Serial Number 0787	07-MAY-2012					
23 61-00-001 Airframe INSPECTION 48M #362	FUNCTIONAL CHECK OF STATIC DISCHARGERS	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
23 71-00-001 Airframe INSPECTION #2173	CHECKED BONDING AT GDU PANEL GROUND DS FOR FUNCTION & SECURITY. PERFORMED STATIC DISCHARGER FUNCTIONAL TEST. PERFORMED FIM TASK FOR HEADSEAT NOISE. Notes FLIGHT CREW REPORTS NOISE IN HEADSETS. NO DEFECT WERE NOTED. PERFORMED STATIC DISCHARGER FUNCTIONAL TEST. NO DEFECTS NOTED. PERFORMED FIM TASK FOR HEADSEAT NOISE. FOUND RADOME BOND AREAS CAKED WITH GREASE. CLEANED AS NEEDED. CHECKED MAJORITY OF BONDED PANEL FOR JUMPER INTEGRITY AND RESISTANCE, INCLUDING FLIGHT CONTROLS. NO HEADSET NOISE NOTED.	14-JUN-2021 H: 2404.60 L: 2331					
24 01-01 Airframe PART #1632	LEFT CONSOLE CONTROL PANEL Part Number 441-40929-002 Serial Number 0396	07-MAY-2012					
24 31-01-001 Airframe PART - Overhaul #161	RST - RESTORATION (OVERHAUL) OF STARTER GENERATOR - NO. 1 ENGINE STARTER GENERATOR Reference Number 24-31-01-920-801-A/200 AIPC 24-31-01 Part Number 400SG180Q Serial Number S00307XL Notes EFFECTIVITY: ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 ; NOTE: BASED ON COMPONENT TSN OR TSO	05-NOV-2021 H: 2498.40 L: 2416	H: 800.00	H: 30.00	M: 1 H: 0.00	H: 3298.40	H: 255.00
24 31-01-001 Airframe PART - Overhaul #359	RST - RESTORATION (OVERHAUL) OF STARTER GENERATOR - NO. 2 ENGINE STARTER GENERATOR Reference Number 24-31-01-920-801-A/200 AIPC 24-31-01 Part Number 400SG180Q Serial Number S00801XL Notes EFFECTIVITY: ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 ; NOTE: BASED ON COMPONENT TSN OR TSO	05-NOV-2021 H: 2498.40 L: 2416	H: 800.00	H: 30.00	M: 1 H: 0.00	H: 3298.40	H: 255.00
24 31-01-003 Airframe INSPECTION #1282	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB505-24-0017)			H: 30.00			

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 31-01-003 Airframe INSPECTION #616	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB505-24-0017)			H: 30.00			
24 31-02 Airframe PART #43	LEFT 28V DC GENERATOR CONTROL UNIT Part Number GCSG550-12B Serial Number 55059	19-MAY-2016 H: 1156.90 L: 1222					
24 31-02 Airframe PART #1169	RIGHT 28V DC GENERATOR CONTROL UNIT Part Number GCSG550-12B Serial Number 55054	19-MAY-2016 H: 1156.90 L: 1222					
24 31-07-001 Airframe INSPECTION - Overhaul 60M #1997	RESTORATION (CLEANING) OF SHUNT GENERATOR Reference Number AMM 24-31-07-100 -801-A/700	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
24 36-01-003 Airframe PART - Life Limited #927	DISCARD AFT MAIN BATTERY Part Number RG-390E Serial Number 41209222	18-JUL-2022 H: 2611.00 L: 2496	M: 24 L: 600	M: 1 L: 30	M: 2 L: 0	18-JUL-2024 L: 3096	M: -12 D: -11 L: 280
	Notes PLEASE CONFIRM EMBODIMENT OF CONCORDE BATTERY STC FOR THE AFT MAIN BATTERY - THIS WOULD MAKE THESE BATTERIES ON CONDITION AND REMOVE THE RECURRING INTERVAL						
24 36-01-003 Airframe PART #1325	DISCARD FORWARD MAIN BATTERY Part Number RG-390E Serial Number 41221730	18-JUL-2022 H: 2611.00 L: 2496		M: 1 L: 30		18-JUL-2024	M: -12 D: -11
	Notes THIS TASK IS SUPERSEDED DUE TO THE AIRCRAFT HAVING STC FOR INSTALLATION OF CONCORD BATTERIES. (THESE BATTERIES ARE NOW ON CONDITION).						
24 36-01-005 Airframe INSPECTION AFT BATTERY #1450	FUNCTIONAL CHECK AFT MAIN BATTERY (POST-MOD SB 505-24-0015) Part Number RG-390E Serial Number 41209222	03-FEB-2025 H: 2972.90 L: 2737	M: 6	M: 1		03-AUG-2025	M: 0 D: 5
	Notes THRESHOLD 12 MO IS APPLICABLE ONLY FOR NEW BATTERIES						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 36-01-005 Airframe INSPECTION FWD BATTERY #778	FUNCTIONAL CHECK FORWARD MAIN BATTERY (POST-MOD SB 505-24-0015) Part Number Serial Number RG-390E 41221730 Notes THRESHOLD 12 MO IS APPLICABLE ONLY FOR NEW BATTERIES	03-FEB-2025 H: 2972.90 L: 2737	M: 6	M: 1		03-AUG-2025	M: 0 D: 5
24 36-02-001 Airframe INSPECTION 6400H #105	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
24 54-05 Airframe PART #1532	28 VDC / 115 VAC STATIC INVERTER Part Number Serial Number AS-24-0026-001 0567	27-SEP-2013 H: 425.20 L: 463					
24 65-00 Airframe PART #354	W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE Part Number Serial Number PN UNKNOWN SN UNKNOWN	07-MAY-2012					
24 65-01 Airframe PART #733	LEFT POWER DISTRIBUTION BOX Part Number Serial Number SX7EG20-1B 0107	15-MAY-2013 H: 330.50 L: 349					
24 65-02 Airframe PART #403	RIGHT POWER DISTRIBUTION BOX Part Number Serial Number SX7EG21-1B 0129	15-MAY-2013 H: 330.50 L: 349					
24 65-04 Airframe PART #741	NOSE POWER DISTRIBUTION BOX Part Number Serial Number SX7EG22-1B 0072	04-JUN-2013 H: 330.50 L: 349					
25 Airframe PART #2076	HANDSET-WALL MOUNT Part Number Serial Number P12248-001 1224811732	16-MAY-2019 H: 2054.20 L: 2050					
25 Airframe INSPECTION #2071	UPDATE GO-GO SOFTWARE	25-APR-2019 H: 2052.70 L: 2048					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 11-01 Airframe PART #33	COPILOT SEAT Part Number 1419-02BE Serial Number 146-1419	07-MAY-2012					
25 11-01 Airframe PART #1522	PILOT SEAT Part Number 1419-01BE Serial Number 147-1419	07-MAY-2012					
25 11-01-001 Airframe INSPECTION 2400H #395	DETAILED INSPECTION COPILOT SEAT	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
25 11-01-001 Airframe INSPECTION 2400H #1303	DETAILED INSPECTION PILOT SEAT	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
25 11-01-002 Airframe INSPECTION 2400H #539	DETAILED INSPECTION OF COCKPIT SEAT BELTS	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
25 21-01 Airframe PART #1750	PAX 1 - RH AFT FACE SEAT Part Number 403174-4I2FZ Serial Number 51989	07-MAY-2012					
25 21-01 Airframe PART #137	PAX 2 - LH AFT FACE SEAT Part Number 403174-1I2FZ Serial Number 51983	07-MAY-2012					
25 21-01 Airframe PART #707	PAX 3 - RH AFT FACE SEAT Part Number 403174-2I2FZ Serial Number 51985	07-MAY-2012					
25 21-01 Airframe PART #76	PAX 6 - LH FWD FACE SEAT Part Number 403174-3I2FZ Serial Number 51987	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 21-01 Airframe PART #1356	PAX 7 - RH FWD FACE SEAT Part Number 403174-412FZ Serial Number 50843	07-MAY-2012					
25 21-01-001 Airframe INSPECTION 2400H #1523	DETAILED INSPECTION OF PASSENGER SEATS	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
25 21-01-002 Airframe INSPECTION 2400H #521	DETAILED INSPECTION OF PASSENGER SEAT BELTS	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
25 21-02-001 Airframe INSPECTION #2001	DETAILED INSPECTION OF DIVAN - A/C WITH DIVAN OR POST MOD SB 505-25-0038 Reference Number AMM 25-21-02-210 -802-A/600						
25 21-02-002 Airframe INSPECTION #2002	DETAILED INSPECTION OF DIVAN SEAT BELTS - A/C WITH DIVAN OR POST-MOD SB 505-25-0038 Reference Number AMM 25-21-02-210 -801-A/600						
25 21-03 Airframe PART #1980	PAX 4 - LH FWD FACE SEAT Part Number 403174-112FZ Serial Number 50839	07-MAY-2012					
25 21-03 Airframe PART #933	PAX 5 - RH FWD FACE SEAT Part Number 403174-212FZ Serial Number 50827	07-MAY-2012					
25 21-04-001 Airframe INSPECTION #1394	RST - RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) Reference Number AMM 25-21-04-920 -802-A/200 Notes EFFECTIVITY: ON AIRCRAFT WITH DIVAN OR POST-MOD SB 505-25-0038 NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY. NOTE: 84M FROM THE MANUFACTURING DATE (TOLERANCE NOT APPLICABLE).						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 21-04-002 Airframe INSPECTION #2192	DIS - DISCARD OF SEAT BELT AIRBAG LNFLATOR GAS CYLINDER Reference Number AMM 25-21-04-960 -801-A/200 Notes EFFECTIVITY: ON AIRCRAFT WITH DIVAN OR POST-MOD SB 505-25-0038. NOTE: FROM THE MANUFACTURING DATE (TOLERANCE NOT APPLICABLE)						
25 21-04-003 Airframe INSPECTION #2193	DET - DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG SYSTEM Reference Number AMM 25-21-04-210 -801-A/600 Notes EFFECTIVITY: ON AIRCRAFT WITH DIVAN OR POST-MOD SB 505-25-0038. NOTE: FROM THE ACFT MAINTENANCE START COUNTING DATE.			M: 1			
25 21-04-004 Airframe INSPECTION #2194	OPC - OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY Reference Number AMM 25-21-04-710 -801-A/500 Notes EFFECTIVITY: ON AIRCRAFT WITH DIVAN OR POST-MOD SB 505-25-0038. NOTE: FROM THE ACFT MAINTENANCE START COUNTING DATE.			M: 1			
25 22-25 Airframe PART #2221	NO. 2 PASSENGER SERVICE UNIT Part Number 4905-1 Serial Number 875			18-JUL-2022 H: 2611.00 L: 2496			
25 43-01-001 Airframe INSPECTION 3200H #1415	DETAILED VISUAL INSPECTION BELTED TOILET UNIT Notes EFFECTIVITY: ON ACFT WITH BELTED TOILET OR POST-MOD SB 505-25-0011 OR POST-MOD SB 505-25-0004			19-MAY-2016 H: 1156.90 L: 1222	H: 3200.00	H: 30.00	H: 4356.90 H: 1313.50
25 43-01-002 Airframe INSPECTION 3200H #708	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT Notes EFFECTIVITY: ON ACFT WITH BELTED TOILET OR POST-MOD SB 505-25-0011 OR POST-MOD SB 505-25-0004			19-MAY-2016 H: 1156.90 L: 1222	H: 3200.00	H: 30.00	H: 4356.90 H: 1313.50
25 60-01 Airframe PART #381	EMERGENCY LOCATOR TRANSMITTER Part Number S1821502-02 Serial Number LX1100018 940			07-MAY-2012			

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-03 Airframe PART #1364	ELT ANTENNA Part Number S65-8282-406 Serial Number 401-2056	07-MAY-2012					
25 61-00-001 Airframe INSPECTION ELT #1396	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM (FAR 91.207) Part Number S1821502-02 Serial Number LX1100018 940 Notes BEACON ID: 2DC74 345AA FFBFF / HEX ID: A1A2D5	18-APR-2024 H: 2895.60 L: 2711	M: 12			18-APR-2025	M: -3 D: -11
25 61-00-002 Airframe INSPECTION ELT #1796	GENERAL VISUAL INSPECTION EMERGENCY LOCATOR TRANSMITTER OF EMERGENCY LOCATOR TRANSMITTER (FAR 91.207) Part Number S1821502-02 Serial Number LX1100018 940	03-MAY-2025 H: 3019.50 L: 2801	M: 12			03-MAY-2026	M: 9 D: 4
25 61-04-001 Airframe PART - Expiration #1810	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY Part Number S1820506-01 Serial Number 22400389	18-APR-2024 H: 2895.60 L: 2711				30-SEP-2029	M: 50 D: 1
25 61-05-001 Airframe PART - Overhaul #720	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE Part Number S1825502-02 Serial Number TM0000016 710	18-JUL-2022 H: 2611.00 L: 2496	M: 120 H: 16000.00		M: 2 H: 0.00	18-MAY-2032 H: 18611.00	M: 81 D: 19 H: 15567.60
25 62-01 Airframe PART - Expiration #761	FIRST AID KIT Part Number 480F95	16-JUL-2024 H: 3927.90 L: 2736				30-JUN-2026	M: 11 D: 1
25 62-01-001 Airframe INSPECTION AID KIT #1226	VISUAL CHECK FIRST AID KIT Part Number 480F95	26-FEB-2025 H: 3005.30 L: 2787	M: 12			26-FEB-2026	M: 6 D: 28
25 62-02-001 Airframe PART - Overhaul #1363	RESTORATION (OVERHAUL) COPILOT LIFE VEST Part Number 66601-505 Serial Number L5277521 Notes INTERVAL: 120MO (RE-CERTIFIED AND RE-VACUUMED PACKED HAS 10 YEARS MAINTENANCE INTERVAL) INTERVAL: 60MO (RE-CERTIFIED AND PACKED SEWN CLOSED HAS 5 YEARS MAINTENANCE INTERVAL)	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 11	01-JUL-2031	M: 71 D: 2

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 62-02-001 Airframe PART - Overhaul #524	RESTORATION (OVERHAUL) NO. 1 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5336669	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 5	28-OCT-2031	M: 74 D: 29
Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).		I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #1881	RESTORATION (OVERHAUL) NO. 2 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5336668	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 5	28-OCT-2031	M: 74 D: 29
Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).		I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #1266	RESTORATION (OVERHAUL) NO. 3 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5336670	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 5	28-OCT-2031	M: 74 D: 29
Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).		I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #1101	RESTORATION (OVERHAUL) NO. 4 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5336671	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 5	28-OCT-2031	M: 74 D: 29
Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).		I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #1336	RESTORATION (OVERHAUL) NO. 5 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5417225	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 4	01-FEB-2032	M: 78 D: 3
Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).		I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #378	RESTORATION (OVERHAUL) NO. 6 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5417226	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 4	01-FEB-2032	M: 78 D: 3
Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).		I: 60 MO - For overhauled (packed sewn closed) Life Vest					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 62-02-001 Airframe PART - Overhaul #823	RESTORATION (OVERHAUL) NO. 7 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5417227	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 4	01-FEB-2032	M: 78 D: 3
	Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).	I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #1276	RESTORATION (OVERHAUL) NO. 8 PASSENGER LIFE VEST Part Number 66601-105 Serial Number L5417229	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 4	01-FEB-2032	M: 78 D: 3
	Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).	I: 60 MO - For overhauled (packed sewn closed) Life Vest					
25 62-02-001 Airframe PART - Overhaul #1069	RESTORATION (OVERHAUL) PILOT LIFE VEST Part Number 66601-505 Serial Number L5277530	18-JUL-2022 H: 2611.00 L: 2496	M: 120		M: 11	01-JUL-2031	M: 71 D: 2
	Notes I: 120 MO - For new or overhauled (re-vacuumed packed) Life Vest I: 60 MO - For overhauled (packed sewn closed) Life Vest NOTE: From the Manufacturing Date (Tolerance NOT Applicable).						
25 62-04-001 Airframe INSPECTION 24M #802	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
25 EEI-1 Airframe INSPECTION #1361	INSPECT EMERGENCY EQUIPMENT (FAR 91.409 AND FAR 91.513)	03-MAY-2025 H: 3019.50 L: 2801	M: 12			03-MAY-2026	M: 9 D: 4
26 11-01 Airframe PART #1067	LEFT ENGINE FIRE DETECTOR Part Number 3951-51-565/215C-5.1M Serial Number 46307	07-MAY-2012					
26 11-01 Airframe PART #558	RIGHT ENGINE FIRE DETECTOR Part Number 3951-51-565/215C-5.1M Serial Number 46208	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 11-01-001 Airframe INSPECTION 1600H #1628	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
26 11-01-001 Airframe INSPECTION 1600H #1296	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
26 11-01-002 Airframe INSPECTION 800H #1904	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
26 11-01-002 Airframe INSPECTION 800H #1682	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
26 15-01 Airframe PART #1892	MODEL 602 SMOKE DETECTOR Part Number 8930-223B60L014 Serial Number 21248	07-MAY-2012					
26 21-01 Airframe PART #222	ENGINE FIRE EXTINGUISHER BOTTLE Part Number 33000073-1 Serial Number 94684A1	04-MAY-2021 H: 2376.70 L: 2304					
	Notes DOM: 14-APRIL-2020						
26 21-01-001 Airframe INSPECTION PETF CTL PNL #949	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL Part Number 441-42702-002 Serial Number 0432	18-APR-2024 H: 2895.60 L: 2711	H: 2400.00	H: 30.00		H: 5295.60	H: 2252.20
	Notes TESTING IS WSA-CITN-39						
26 21-01A Airframe PART #418	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL Part Number 441-42702-002 Serial Number 0432	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 21-03-001 Airframe INSPECTION ENG BOTTLE #1932	FUNCTIONAL CHECK ENGINE FIRE EXTINGUISHER BOTTLE OF ENGINE EXTINGUISHING BOTTLE Part Number 33000073-1 Serial Number 94684A1 Notes TOLERANCE NOT APPLICABLE	04-MAY-2021 H: 2376.70 L: 2304	M: 120			04-MAY-2031	M: 69 D: 5
26 21-05-001 Airframe INSPECTION 2400H #1078	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
26 21-07-001 Airframe PART - Life Limited #937	DISCARD NO. 1 CARTRIDGE Part Number 33000073-1 Serial Number UNK Notes DOM: APRIL 2020 TOLERANCE NOT APPLICABLE	04-MAY-2021 H: 2376.70 L: 2304	M: 120		M: 13	04-APR-2030	M: 56 D: 6
26 21-07-001 Airframe PART - Life Limited #50	DISCARD NO. 2 CARTRIDGE Part Number 33000073-1 Serial Number UNK Notes DOM: APRIL 2020 TOLERANCE NOT APPLICABLE	04-MAY-2021 H: 2376.70 L: 2304	M: 120		M: 13	04-APR-2030	M: 56 D: 6
26 21-09-001 Airframe INSPECTION 2400H #1711	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
26 24-01-001 Airframe INSPECTION CAB EXT #1686	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER (PN BA51015G-3 OR BA51015-5 OR RTA1200) Part Number RT-A1200 Serial Number D58318537 Notes Weight: 1535 Grams	03-MAY-2025 H: 3019.50 L: 2801	M: 12			03-MAY-2026	M: 9 D: 4

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 24-01-001 Airframe INSPECTION COC EXT #906	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER (PN BA51015G-3 OR BA51015-5 OR RTA1200) Part Number RT-A1200 Serial Number D58318544 Notes Weight: 1539 Grams	03-MAY-2025 H: 3019.50 L: 2801	M: 12			03-MAY-2026	M: 9 D: 4
26 24-01-002 Airframe PART - Life Limited #860	DIS - DISCARD OF PORTABLE FIRE EXTINGUISHER - CABIN Reference Number AMM 26-24-01-960 -801-A/200 Part Number RT-A1200 Serial Number D58318537 Notes EFFECTIVITY: ON ACFT WITH PORTABLE FIRE EXTINGUISHER PN RTA 1200 OR PN P3APP003000-SERIES. NOTE: FROM THE MANUFACTURING DATE (TOLERANCE NOT APPLICABLE).	03-MAY-2023 H: 2749.10 L: 2607	M: 144		M: 0	25-FEB-2035	M: 114 D: 27
26 24-01-002 Airframe PART - Life Limited #536	DIS - DISCARD OF PORTABLE FIRE EXTINGUISHER - COCKPIT Reference Number AMM 26-24-01-960 -801-A/200 Part Number RT-A1200 Serial Number D58318544 Notes EFFECTIVITY: ON ACFT WITH PORTABLE FIRE EXTINGUISHER PN RTA 1200 OR PN P3APP003000-SERIES. NOTE: FROM THE MANUFACTURING DATE (TOLERANCE NOT APPLICABLE).	03-MAY-2023 H: 2749.10 L: 2607	M: 144		M: 0	25-FEB-2035	M: 114 D: 27
26 24-01-003 Airframe INSPECTION #1122	DIS - DISCARD OF PORTABLE FIRE EXTINGUISHER - CABIN Reference Number AMM 26-24-01-960 - -801-A/200 Part Number Serial Number - Notes EFFECTIVITY: ON ACFT WITH PORTABLE FIRE EXTINGUISHER PN BA51015G-3 OR PN BA51015-5. NOTE: FROM THE MANUFACTURING DATE (TOLERANCE NOT APPLICABLE).	01-JUL-2012					
26 24-01-003 Airframe INSPECTION #509	DIS - DISCARD OF PORTABLE FIRE EXTINGUISHER - COCKPIT Reference Number AMM 26-24-01-960 - -801-A/200 Part Number Serial Number - Notes EFFECTIVITY: ON ACFT WITH PORTABLE FIRE EXTINGUISHER PN BA51015G-3 OR PN BA51015-5. NOTE: FROM THE MANUFACTURING DATE (TOLERANCE NOT APPLICABLE).	01-JUL-2012					
26 24-01-004 Airframe INSPECTION #2061	FNC - WEIGHT CHECK OF PORTABLE FIRE EXTINGUISHER - COCKPIT Reference Number AMM 26-24-01-720 -801-A/500 Notes EFFECTIVITY: ON ACFT WITH PORTABLE FIRE EXTINGUISHER PN P3APP003000-SERIES. NOTE: FROM THE LAST ACCOMPLISHMENT DATE (TOLERANCE NOT APPLICABLE).						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 001 Airframe PART - Life Limited #1211	LEFT NO. 3 OUTBOARD FLAP ACTUATOR Part Number 475100-1013 Serial Number 0958	11-MAY-2018 H: 1776.00 L: 1789	H: 7200.00		M: 0 H: 0.00 L: 0	H: 8976.00	H: 5932.60
27 001 Airframe PART - Life Limited #545	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR Part Number 475100-1013 Serial Number 0921	11-MAY-2018 H: 1776.00 L: 1789	H: 7200.00		M: 0 H: 0.00 L: 0	H: 8976.00	H: 5932.60
27 002 Airframe PART - Life Limited #1117	LEFT NO. 2 OUTBOARD FLAP ACTUATOR Part Number 475000-2013 Serial Number 1882	11-MAY-2018 H: 1776.00 L: 1789	H: 7200.00		M: 0 H: 0.00 L: 0	H: 8976.00	H: 5932.60
27 002 Airframe PART - Life Limited #1689	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR Part Number 475000-2013 Serial Number 1880	11-MAY-2018 H: 1776.00 L: 1789	H: 7200.00		M: 0 H: 0.00 L: 0	H: 8976.00	H: 5932.60
27 003 Airframe PART - Life Limited #1550	LEFT NO. 1 INBOARD FLAP ACTUATOR (475000-1009) Part Number 475000-1013 Serial Number 1819	11-MAY-2018 H: 1776.00 L: 1789	H: 7200.00		M: 0 H: 0.00 L: 0	H: 8976.00	H: 5932.60
27 003 Airframe PART - Life Limited #857	RIGHT NO. 1 INBOARD FLAP ACTUATOR (475000-1009) Part Number 475000-1013 Serial Number 1785	11-MAY-2018 H: 1776.00 L: 1789	H: 7200.00		M: 0 H: 0.00 L: 0	H: 8976.00	H: 5932.60
27 004 Airframe PART - Life Limited #1521	ROLL TRIM ACTUATOR Part Number 470500-1005 Serial Number 0117	07-MAY-2012	H: 12000.00		M: 0 H: 0.00 L: 0	H: 12000.00	H: 8956.60
27 005 Airframe PART - Life Limited #218	YAW TRIM ACTUATOR Part Number 470600-1005 Serial Number 0133	07-MAY-2012	H: 12000.00		M: 0 H: 0.00 L: 0	H: 12000.00	H: 8956.60
27 006 Airframe PART - Life Limited #993	PITCH TRIM ACTUATOR Part Number 467500-1003 Serial Number 0133	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 007 Airframe PART - Life Limited #1112	LEFT SPOILER ACTUATOR Part Number 456800-1003 Serial Number 0255	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 007 Airframe PART - Life Limited #602	RIGHT SPOILER ACTUATOR Part Number 456800-1003 Serial Number 0254	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 008 Airframe PART #1912	ELECTRO - RUDDER GUST LOCK ACTUATOR Part Number SYLC-53058 Serial Number 1633	28-JUL-2015 H: 892.10 L: 968					
27 009 Airframe PART - Life Limited #461	RUDDER BOOSTER ACTUATOR Part Number 9125-3 Serial Number 0116T	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 01-01 Airframe PART #1958	LEFT CONTROL WHEEL Part Number 83912139 Serial Number 00604	07-MAY-2012					
27 01-01 Airframe PART #772	RIGHT CONTROL WHEEL Part Number 83912141 Serial Number 00066	07-MAY-2012					
27 01-03-001 Airframe INSPECTION 24M #363	LUBRICATION OF ROTARY BALL SPLINE	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
27 010 Airframe PART - Life Limited #1060	LEFT TOGGLE LINK Part Number 456870-1001 Serial Number 0473	08-APR-2014 H: 623.30 L: 675	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35623.30	H: 32579.90
27 010 Airframe PART - Life Limited #1153	RIGHT TOGGLE LINK Part Number 456870-1001 Serial Number 0474	08-APR-2014 H: 623.30 L: 675	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35623.30	H: 32579.90
27 011 Airframe PART - Life Limited #812	STICK PUSHER ACTUATOR Part Number 9124-1 Serial Number 0082T	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 012 Airframe PART - Life Limited #642	POWER DRIVE UNIT Part Number 467700-1003 Serial Number 0051	31-MAY-2013 H: 330.50 L: 349	H: 35000.00		M: 2 H: 449.00 L: 373	H: 34881.50	H: 31838.10

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 013 Airframe PART - Life Limited #725	LEFT FLAP POSITION SENSOR UNIT Part Number 457310-1001 Serial Number 0281	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 013 Airframe PART - Life Limited #404	RIGHT FLAP POSITION SENSOR UNIT Part Number 457310-1001 Serial Number 0285	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 014 Airframe PART - Life Limited #1903	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT Part Number 457360-1005 Serial Number SSW0474	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 014 Airframe PART - Life Limited #171	LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT Part Number 457360-1005 Serial Number SSW0475	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 014 Airframe PART - Life Limited #1525	RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT Part Number 457360-1005 Serial Number SSW0468	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 014 Airframe PART - Life Limited #682	RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT Part Number 457360-1005 Serial Number SSW0445	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 015 Airframe PART - Life Limited #351	LEFT CENTER FLAP FLEXIBLE 2 SHAFT Part Number 457360-1007 Serial Number SSW0182	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 015 Airframe PART - Life Limited #1741	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT Part Number 457360-1007 Serial Number SSW0186	07-MAY-2012	H: 35000.00		M: 0 H: 0.00 L: 0	H: 35000.00	H: 31956.60
27 03-01 Airframe PART #909	NO. 1 ELECTRONICS FLIGHT CONTROL Part Number 462900-1017 Serial Number 0218	13-JUL-2016 H: 1201.40 L: 1270					
27 03-01 Airframe PART #712	NO. 2 ELECTRONICS FLIGHT CONTROL Part Number 462900-1017 Serial Number 0201	05-AUG-2019 H: 2081.60 L: 2076					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 03-01-002 Airframe INSPECTION 5600H #1798	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
27 03-01-003 Airframe INSPECTION 5600H #1447	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
27 03-01-004 Airframe INSPECTION #1256	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 04-01 Airframe PART #786	TRIM ACTUATOR CONTROLLER	07-MAY-2012					
	Part Number 475200-1005	Serial Number 0142					
27 04-01-001 Airframe INSPECTION 5600H #1965	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
27 04-01-002 Airframe INSPECTION 5600H #1761	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
27 11-00-001 Airframe INSPECTION 3200H/60M #604	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
27 11-01 Airframe PART #1054	LEFT AILERON	18-JUL-2022 H: 2611.00 L: 2496					
	Part Number 505-14735-695	Serial Number 0000701812					
27 11-01 Airframe PART #1545	RIGHT AILERON	07-MAY-2012					
	Part Number 505-14740-4001	Serial Number 0000709521					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 11-02-001 Airframe INSPECTION #53	FNC - FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION Reference Number AMM 27-11-02-720 -801-A/500 Notes NOTE: ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT). BESIDES THIS ADDITIONAL ACCOMPLISHMENT AT 12 MO, DO IT ALIGNED WITH THE 3200 FH / 60 MO PACKAGE.	18-APR-2024 H: 2895.60 L: 2711	M: 60 H: 3200.00	M: 1 H: 30.00		18-APR-2029 H: 6095.60	M: 44 D: 20 H: 3052.20
27 11-02-001 Airframe INSPECTION #2210	FNC - FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION - ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT) Reference Number AMM 27-11-02-720 -801-A/500 Notes NOTE: ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT). BESIDES THIS ADDITIONAL ACCOMPLISHMENT AT 12 MO, DO IT ALIGNED WITH THE 3200 FH / 60 MO PACKAGE.	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
27 11-02-002 Airframe INSPECTION 3200H/60M #1074	DETAILED INSPECTION OF AILERON CONTROL CABLES	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
27 14-02-001 Airframe INSPECTION #1042	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY	07-MAY-2012	H: 6000.00	H: 30.00		H: 6000.00	H: 2956.60
27 14-02-002 Airframe INSPECTION #224	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 14-03 Airframe PART #1634	LEFT AILERON TAB Part Number 505-43063-4001 Serial Number 0000698281	07-MAY-2012					
27 21-00-001 Airframe INSPECTION 3200H/60M #392	GVI - GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS Reference Number AMM 27 -21-00-21 0-801-A/600	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
27 21-01 Airframe PART #926	RUDDER ASSEMBLY Part Number 505-39061-613 Serial Number 699609	18-JUL-2022 H: 2611.00 L: 2496					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 21-02-001 Airframe INSPECTION #1431	FNC - FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION Reference Number AMM 27-21-02-720 -801-A/500 Notes NOTE: ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT). BESIDES THIS ADDITIONAL ACCOMPLISHMENT AT 12 MO, DO IT ALIGNED WITH THE 3200 FH / 60 MO PACKAGE.	18-APR-2024 H: 2895.60 L: 2711	M: 60 H: 3200.00	M: 1 H: 30.00		18-APR-2029 H: 6095.60	M: 44 D: 20 H: 3052.20
27 21-02-001 Airframe INSPECTION #2211	FNC - FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT) Reference Number AMM 27-21-02-720 -801-A/500 Notes NOTE: ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT). BESIDES THIS ADDITIONAL ACCOMPLISHMENT AT 12 MO, DO IT ALIGNED WITH THE 3200 FH / 60 MO PACKAGE.	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
27 21-02-002 Airframe INSPECTION 3200H/60M #1038	DETAILED INSPECTION OF RUDDER CONTROL CABLES	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
27 23-00-001 Airframe INSPECTION 1600H #1757	OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
27 24-02-001 Airframe INSPECTION #748	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH	07-MAY-2012	H: 6000.00	H: 30.00		H: 6000.00	H: 2956.60
27 24-02-002 Airframe INSPECTION #270	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 24-03 Airframe PART #1771	RUDDER TRIM TAB Part Number 505-10450-403 Serial Number 0000699988	07-MAY-2012					
27 26-01 Airframe PART #24	VENTRAL RUDDER Part Number 505-07540-417 Serial Number 0000707504	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 31-00-001 Airframe INSPECTION 3200H/60M #476	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
27 31-01 Airframe PART #1218	LEFT ELEVATOR Part Number 505-43071-4001 Serial Number 0000709519	07-MAY-2012					
27 31-01 Airframe PART #340	RIGHT ELEVATOR Part Number 505-11094-002 Serial Number 0000705743	18-JUL-2022 H: 2611.00 L: 2496					
27 31-02-001 Airframe INSPECTION #1100	FNC - FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION Reference Number AMM 27-31-02-720 -801-A/500 Notes NOTE: ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT). BESIDES THIS ADDITIONAL ACCOMPLISHMENT AT 12 MO, DO IT ALIGNED WITH THE 3200 FH / 60 MO PACKAGE.	18-APR-2024 H: 2895.60 L: 2711	M: 60 H: 3200.00	M: 1 H: 30.00		18-APR-2029 H: 6095.60	M: 44 D: 20 H: 3052.20
27 31-02-001 Airframe INSPECTION #2212	FNC - FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT) Reference Number AMM 27-31-02-720 -801-A/500 Notes NOTE: ADDITIONAL TENSION CHECK AT THE FIRST 12 MO APPLICABLE FOR NEW CABLES (REPLACED OR NEW AIRCRAFT). BESIDES THIS ADDITIONAL ACCOMPLISHMENT AT 12 MO, DO IT ALIGNED WITH THE 3200 FH / 60 MO PACKAGE.	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
27 31-02-002 Airframe INSPECTION 3200H/60M #411	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES	18-JUL-2022 H: 2611.00 L: 2496	M: 60 H: 3200.00	M: 1 H: 30.00		18-JUL-2027 H: 5811.00	M: 23 D: 19 H: 2767.60
27 31-03 Airframe PART #58	LEFT ELEVATOR TAB Part Number 505-43073-4001 Serial Number 0000708403	07-MAY-2012					
27 31-03 Airframe PART #1330	RIGHT ELEVATOR TAB Part Number 505-43073-4002 Serial Number 0000703481	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 31-03-001 Airframe INSPECTION 5600H #314	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
27 31-03-002 Airframe INSPECTION 5600H #1561	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
27 36-03-001 Airframe INSPECTION 1600H #1496	OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
27 41-01-001 Airframe INSPECTION PTA #1535	DETAILED INSPECTION OF PITCH TRIM ACTUATOR Part Number 467500-1003 Serial Number 0133	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 41-01-002 Airframe INSPECTION PTA #112	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH Part Number 467500-1003 Serial Number 0133	07-MAY-2012	H: 6000.00	H: 30.00		H: 6000.00	H: 2956.60
27 41-01-003 Airframe INSPECTION 48M, PTA #173	LUBRICATION OF PITCH TRIM ACTUATOR Part Number 467500-1003 Serial Number 0133	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 41-01-004 Airframe INSPECTION PTA #1219	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK Part Number 467500-1003 Serial Number 0133	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 41-01-005 Airframe INSPECTION 48M, PTA #1376	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES Part Number 467500-1003 Serial Number 0133	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 41-01-006 Airframe INSPECTION 5600H, PTA #1205	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP Part Number 467500-1003 Serial Number 0133	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 43-02 Airframe PART #1663	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
27 50-01-01-901 Airframe INSPECTION #247	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
27 51-01-001 Airframe INSPECTION 48M #1177	LUBRICATION OF FLAP ACTUATORS BALL SCREWS	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-01-002 Airframe INSPECTION #1673	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60
27 51-01-002 Airframe INSPECTION #809	DETAILED VISUAL INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60
27 51-01-002 Airframe INSPECTION #88	DETAILED VISUAL INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60
27 51-01-002 Airframe INSPECTION #113	DETAILED VISUAL INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60
27 51-01-002 Airframe INSPECTION #1923	DETAILED VISUAL INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60
27 51-01-002 Airframe INSPECTION #677	DETAILED VISUAL INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 51-01-004 Airframe INSPECTION #1919	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER	07-MAY-2012	H: 7200.00	H: 30.00		H: 7200.00	H: 4156.60
27 51-01-005 Airframe INSPECTION 48M #1310	SERVICING OF FLAP ACTUATOR GEAR BOXES	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-05 Airframe PART #307	LEFT INBOARD FLAP Part Number 505-14401-4001 Serial Number 0000699734	07-MAY-2012					
27 51-05 Airframe PART #612	LEFT OUTBOARD FLAP Part Number 505-39079-4001 Serial Number 0000699731	07-MAY-2012					
27 51-05 Airframe PART #890	RIGHT INBOARD FLAP Part Number 505-14401-4002 Serial Number 0000701634	07-MAY-2012					
27 51-05 Airframe PART #1913	RIGHT OUTBOARD FLAP Part Number 505-39079-4002 Serial Number 0000706811	07-MAY-2012					
27 51-06-001 Airframe INSPECTION 48M #1155	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-001 Airframe INSPECTION 48M #870	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-001 Airframe INSPECTION 48M #1621	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 51-06-001 Airframe INSPECTION 48M #1072	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-001 Airframe INSPECTION 48M #115	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-001 Airframe INSPECTION 48M #1635	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-002 Airframe INSPECTION 48M #1347	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-002 Airframe INSPECTION 48M #978	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-002 Airframe INSPECTION 48M #377	DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-002 Airframe INSPECTION 48M #1053	DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-002 Airframe INSPECTION 48M #590	DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
27 51-06-002 Airframe INSPECTION 48M #705	DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 53-01 Airframe PART #1429	FLAP SELECTOR, PRODUCTION, LEVER Part Number 780501-9 Serial Number 1337	07-MAY-2012					
27 64-01-01-901 Airframe INSPECTION #1070	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILERMECHANICAL COMPONENTS- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
27 64-01-01-902 Airframe INSPECTION #697	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
27 64-01-02-901 Airframe INSPECTION #1572	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILERMECHANICAL COMPONENTS- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
27 65-00-001 Airframe INSPECTION 6400H #1526	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 65-01-001 Airframe INSPECTION 6400H #1838	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
27 66-01 Airframe PART #1412	NO. 1 CONTROL WHEEL POSITION SENSOR Part Number 456896-1001 Serial Number 019933	07-MAY-2012					
27 66-01 Airframe PART #537	NO. 2 CONTROL WHEEL POSITION SENSOR Part Number 456896-1001 Serial Number 032428	07-MAY-2012					
27 66-02 Airframe PART #1864	LEFT SPOILER SURFACE POSITION SENSOR Part Number 456897-1001 Serial Number 038965	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 66-02 Airframe PART #875	RIGHT SPOILER SURFACE POSITION SENSOR Part Number 456897-1001 Serial Number 040813	07-MAY-2012					
28 11-00-001 Airframe INSPECTION 12M #1113	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
28 11-05 Airframe PART #99	LEFT WING WATER DRAIN VALVE Part Number L83A13-628 Serial Number F36179	07-MAY-2012					
28 11-05 Airframe PART #704	RIGHT WING WATER DRAIN VALVE Part Number L83A13-628 Serial Number D94587	29-MAR-2016 H: 1135.50 L: 1197					
28 11-07 Airframe PART #503	LEFT WING DUMP VALVE Part Number V98A32-001 Serial Number F26646	07-MAY-2012					
28 11-07 Airframe PART #1262	RIGHT WING DUMP VALVE Part Number V98A32-001 Serial Number F31162	07-MAY-2012					
28 12-01-001 Airframe INSPECTION 800H #1037	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
28 12-03 Airframe PART #746	LEFT FUEL TANK FLOAT VENT VALVE Part Number L87-19-001P2 Serial Number F12303	07-MAY-2012					
28 12-03 Airframe PART #1692	RIGHT FUEL TANK FLOAT VENT VALVE Part Number L87-19-001P2 Serial Number F12304	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 12-03-001 Airframe INSPECTION 6400H #365	OPERATIONAL CHECK LEFT FLOAT VENT VALVE	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
28 12-03-001 Airframe INSPECTION 6400H #1231	OPERATIONAL CHECK RIGHT FLOAT VENT VALVE	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
28 21-01 Airframe PART #1791	LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
28 21-01 Airframe PART #184	RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
28 21-02 Airframe PART #798	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE Part Number P99C25-606P2 Serial Number F31916	07-MAY-2012					
28 21-02 Airframe PART #1789	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE Part Number P99C25-606P2 Serial Number F31918	07-MAY-2012					
28 21-03 Airframe PART #726	LEFT WING DC AUXILIARY BOOST PUMP CANISTER Part Number C93R25-606P2 Serial Number F22210	07-MAY-2012					
28 21-03 Airframe PART #1267	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER Part Number C93R25-606P2 Serial Number F22217	07-MAY-2012					
28 21-05 Airframe PART #1766	LEFT WING JET PUMP FEED LINE Part Number T99A19-602 Serial Number F35120	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 21-05 Airframe PART #1338	RIGHT WING JET PUMP FEED LINE Part Number T99A19-602 Serial Number F31937	07-MAY-2012					
28 21-07 Airframe PART #484	LEFT 0.75 SHUTOFF VALVE Part Number B97-15-601 Serial Number F27122	07-MAY-2012					
28 21-07 Airframe PART #1049	RIGHT 0.75 SHUTOFF VALVE Part Number B97-15-601 Serial Number F27125	07-MAY-2012					
28 21-07-001 Airframe INSPECTION #749	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
28 21-07-001 Airframe INSPECTION #1606	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
28 21-08 Airframe PART #132	FORWARD LEFT 28 VDC SOV ACTUATOR Part Number D97C00-644P2 Serial Number C703659	18-JUL-2022 H: 2611.00 L: 2496					
28 21-08 Airframe PART #1243	LEFT WING 28 VDC SOV ACTUATOR Part Number D97C00-644P2 Serial Number C701242	07-MAY-2012					
28 21-08 Airframe PART #973	REAR RIGHT 28 VDC SOV ACTUATOR Part Number D97C00-644P2 Serial Number C701244	07-MAY-2012					
28 21-09 Airframe PART #1661	LEFT WING SCAVENGER JET PUMP Part Number T99A19-603 Serial Number F33570	07-MAY-2012					
28 21-09 Airframe PART #1581	RIGHT WING SCAVENGER JET PUMP Part Number T99A19-603 Serial Number F33574	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 21-10 Airframe PART #480	3/4" (CROSSFEED) SHUT OFF VALVE Part Number B97H19-608P2 Serial Number F32457	07-MAY-2012					
28 21-10-001 Airframe INSPECTION #833	OPERATIONAL CHECK OF FUEL XFEED VALVE	07-MAY-2012	H: 12000.00	H: 30.00		H: 12000.00	H: 8956.60
28 21-11 Airframe PART #646	LEFT WING 1/2 INCH CHECK VALVE VALVE Part Number L96-13-001 Serial Number F22139	07-MAY-2012					
28 21-11 Airframe PART #150	RIGHT WING 1/2 INCH CHECK VALVE VALVE Part Number L96-13-001 Serial Number F22140	07-MAY-2012					
28 21-13 Airframe PART #1214	INSC ILLUM PANEL Part Number 441-42621-002 Serial Number 1110	07-MAY-2012					
28 23-01 Airframe PART #100	REFUEL CONTROL PANEL Part Number 742388-1-2 Serial Number 742388IN00 220	07-MAY-2012					
28 23-03 Airframe PART #762	LEFT WING PRESSURE REFUELING SOLENOID VALVE Part Number L94E31-653P2 Serial Number F22425	07-MAY-2012					
28 23-03 Airframe PART #262	RIGHT WING PRESSURE REFUELING SOLENOID VALVE Part Number L94E31-653P2 Serial Number F42362	07-MAY-2012					
28 23-04-001 Airframe INSPECTION 3200H #183	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER	19-MAY-2016 H: 1156.90 L: 1222	H: 3200.00	H: 30.00		H: 4356.90	H: 1313.50

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 23-07 Airframe PART #297	LEFT HIGH LEVEL SENSOR Part Number 722860-2-0	Serial Number 1136	19-JAN-2018 H: 1682.30 L: 1699				
28 23-07 Airframe PART #1003	RIGHT HIGH LEVEL SENSOR Part Number 722860-2-0	Serial Number 2134	20-APR-2018 H: 1772.30 L: 1783				
28 23-09 Airframe PART #123	FUEL PORT AND CAP Part Number K97-63-613	Serial Number F32304	07-MAY-2012				
28 41-01 Airframe PART #1335	NO. 1 LEFT PROBE Part Number 765896-1-0	Serial Number 765896IN00 333	07-MAY-2012				
28 41-01 Airframe PART #1975	NO. 1 RIGHT PROBE Part Number 765896-1-0	Serial Number 765896IN00 332	07-MAY-2012				
28 41-01 Airframe PART #1456	NO. 2 LEFT PROBE Part Number 765873-1-0	Serial Number 765873IN00 342	07-MAY-2012				
28 41-01 Airframe PART #815	NO. 2 RIGHT PROBE Part Number 765873-1-0	Serial Number 765873IN00 343	07-MAY-2012				
28 41-01 Airframe PART #376	NO. 3 LEFT PROBE Part Number 765874-1-0	Serial Number 765874IN00 338	07-MAY-2012				
28 41-01 Airframe PART #241	NO. 3 RIGHT PROBE Part Number 765874-1-0	Serial Number 765874IN00 316	07-MAY-2012				

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 41-01 Airframe PART #245	NO. 4 LEFT PROBE Part Number 765875-1-0 Serial Number 765875IN00 349	07-MAY-2012					
28 41-01 Airframe PART #257	NO. 4 RIGHT PROBE Part Number 765875-1-0 Serial Number 765875IN00 335	07-MAY-2012					
28 41-05 Airframe PART #299	EFCU ELECTRICAL FUEL CONTROL UNIT Part Number 738742-1-4 Serial Number 738790IN00 629	28-OCT-2016 H: 1281.00 L: 1364					
28 43-01 Airframe PART #587	TEMPERATURE SENSOR Part Number 798840-1-0 Serial Number 04404	29-MAR-2016 H: 1135.50 L: 1197					
28 43-01-001 Airframe INSPECTION 6400H #1186	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR	29-MAR-2016 H: 1135.50 L: 1197	H: 6400.00	H: 30.00		H: 7535.50	H: 4492.10
28 45-01 Airframe PART #1680	LEFT PRESSURE SWITCH Part Number D98C07-611 Serial Number 0781	07-MAY-2012					
28 45-01 Airframe PART #738	RIGHT PRESSURE SWITCH Part Number D98C07-611 Serial Number 0778	07-MAY-2012					
29 Airframe PART #2077	FILTER-ULTIPOR R ELEMENT Part Number 3032408-329 Serial Number No Lot Number	20-MAY-2019 H: 2054.20 L: 2050					
29 12-02 Airframe PART #1010	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR Part Number 3032763-002 Serial Number MX757788A	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 12-02 Airframe PART #1304	LEFT ENGINE DRIVEN HYDRAULIC PUMP Part Number 3032249-002 Serial Number MX754195	07-MAY-2012					
29 12-02 Airframe PART #1114	RIGHT ENGINE DRIVEN HYDRAULIC PUMP Part Number 3032249-002 Serial Number MX757115	07-MAY-2012					
29 12-02-001 Airframe INSPECTION 12M #310	VISUAL CHECK OF MANIFOLD/ RESERVOIR	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
29 12-02-002 Airframe INSPECTION 5600H #291	OPERATIONAL CHECK LEFT EDP CHECK VALVE	08-APR-2020 H: 2177.60 L: 2161	H: 5600.00	H: 30.00		H: 7777.60	H: 4734.20
29 12-02-002 Airframe INSPECTION 5600H #1284	OPERATIONAL CHECK RIGHT EDP CHECK VALVE	08-APR-2020 H: 2177.60 L: 2161	H: 5600.00	H: 30.00		H: 7777.60	H: 4734.20
29 15-03 Airframe PART #1874	CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR Part Number 0860231003 Serial Number 60231-2395	07-MAY-2012					
29 15-03-001 Airframe INSPECTION 12M, 25CUINACC #201	SERVICING CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR - ON A/C WITH HYDRAULIC ACCUMULATOR PN 11172-2 OR POST-MOD SB 505 -29-0005 Part Number 0860231003 Serial Number 60231-2395	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
29 15-04 Airframe PART #165	NO. 1 FSOV FIRE SHUT OFF VALVE Part Number 3032428-001 Serial Number AA309013	07-MAY-2012					
29 15-04 Airframe PART #1555	NO. 2 FSOV FIRE SHUT OFF VALVE Part Number 3032428-001 Serial Number AA309197	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 15-04-001 Airframe INSPECTION #1333	OPERATIONAL CHECK LEFT ENGINE HYDRAULIC SHUT-OFF VALVE	18-APR-2024 H: 2895.60 L: 2711	M: 48 H: 3200.00	D: 30 H: 30.00		18-APR-2028 H: 6095.60	M: 32 D: 20 H: 3052.20
29 15-04-001 Airframe INSPECTION #1911	OPERATIONAL CHECK RIGHT ENGINE HYDRAULIC SHUT-OFF VALVE	18-APR-2024 H: 2895.60 L: 2711	M: 48 H: 3200.00	D: 30 H: 30.00		18-APR-2028 H: 6095.60	M: 32 D: 20 H: 3052.20
29 15-05 Airframe PART #225	PRIORITY VALVE Part Number 2217-0001-401 Serial Number 00121	07-MAY-2012					
29 31-02-001 Airframe INSPECTION 5600H #1739	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEFVALVE	08-APR-2020 H: 2177.60 L: 2161	H: 5600.00	H: 30.00		H: 7777.60	H: 4734.20
30 01-01 Airframe PART #1253	MD INSC ILLUM PANEL Part Number 441-43234-002 Serial Number 1084	07-MAY-2012					
30 12-00-001 Airframe INSPECTION 6400H #990	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
30 12-01-001 Airframe INSPECTION 6400H #753	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
30 12-02 Airframe PART #1968	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE Part Number RYLB-53534-3 Serial Number 0121	07-MAY-2012					
30 12-02 Airframe PART #1084	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE Part Number RYLB-53534-4 Serial Number 0116	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 12-05 Airframe PART #145	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER Part Number APTE-485F-1000-50G Serial Number 7881-1-479	07-MAY-2012					
30 12-05 Airframe PART #1181	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
30 12-05 Airframe PART #1747	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER Part Number APTE-485F-1000-50G Serial Number 7881-1-397	07-MAY-2012					
30 12-05 Airframe PART #645	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER Part Number APTE-485F-1000-50G Serial Number 7881-1-509	07-MAY-2012					
30 12-05 Airframe PART #643	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
30 12-05 Airframe PART #1433	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER Part Number APTE-485F-1000-50G Serial Number 7881-1-353	07-MAY-2012					
30 12-05-001 Airframe INSPECTION 6400H #1127	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
30 12-05-001 Airframe INSPECTION 6400H #858	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
30 12-05-002 Airframe INSPECTION 6400H #1906	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 12-05-002 Airframe INSPECTION 6400H #880	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
30 21-01 Airframe PART #96	LEFT ENGINE ANTI-ICE PRESUURE VALVE Part Number 10030295 Serial Number 0000226	07-MAY-2012					
30 21-01 Airframe PART #976	RIGHT ENGINE ANTI-ICE PRESUURE VALVE Part Number 10030295 Serial Number 0000228	07-MAY-2012					
30 21-02 Airframe PART #775	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER Part Number APTE-477F-1000-100G Serial Number 7917-7-76	07-MAY-2012					
30 21-02 Airframe PART #1116	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER Part Number APTE-477F-1000-100G Serial Number 7917-7-53	07-MAY-2012					
30 21-02-001 Airframe INSPECTION E1 A-I P T, E2 A-I P T #2124	FNC - FUNCTIONAL CHECK OF ENGINE ANTI-ICING PRESSURE TRANSDUCER Reference Number AMM TASK 30-21-02-720-801-A/500 Part Number APTE-477F-1000-100G Serial Number 7917-7-76		H: 12000.00	H: 30.00		H: 12000.00	H: 8956.60
30 21-03-001 Airframe INSPECTION 5600H #1507	SDI - BORESCOPE INSPECTION OF PICCOLO TUBE Reference Number AMM 30-21-03-220 -801-A/600	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
30 21-04-001 Airframe INSPECTION 2400H #874	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
30 31-00-002 Airframe INSPECTION 24M #1124	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING (FAR 91.411)	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 41-01-002 Airframe INSPECTION 12M #2060	DISCARD OF WINDSHIELD RAIN REPELLENT COATING Reference Number AMM TASK 30-41-01-960-801-A/200 Notes THIS REQUIREMENT MAY BE SUPERSEDED BY REQUIREMENT 30-41-01-003 (AS PER OPERATOR DISCRETION)	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
30 41-01-003 Airframe INSPECTION 12M #2129	FNC - FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE Reference Number AMM TASK 30-41-01-720-801-A/500 Notes IF COMPLIED WITH REQUIREMENT 30-41-01-002, THIS REQUIREMENT MUST BE SIGNED OFF	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
30 42-00-001 Airframe INSPECTION 800H #1553	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
30 42-01 Airframe PART #1577	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL Part Number EPM-112-3 Serial Number 01315	07-MAY-2012					
30 42-01 Airframe PART #1596	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL Part Number EPM-112-3 Serial Number 01317	07-MAY-2012					
30 81-02 Airframe PART #1312	LEFT NOSE ICE DETECTOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 Airframe INSPECTION #2063	DOWNLOAD QAR DATA Notes MONTHLY INTERVAL	01-JUL-2019 H: 2081.60 L: 2076					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 30-02 Airframe PART #620	CVDR ACCELEROMETER Part Number 3001-01-111 Serial Number 1211-DTJ4530	07-MAY-2012					
31 30-03 Airframe PART #820	REAR CVDR IMPACT SWITCH Part Number 5930-4-000 Serial Number 5432	07-MAY-2012					
31 31-00-002 Airframe INSPECTION 12M #626	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER)	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
31 31-01 Airframe PART #278	(CVR / CVDR) COCKPIT VOICE RECORDER Part Number 2100-3083-50 Serial Number 000751835	07-MAY-2012					
31 31-03 Airframe PART #1422	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 31-03-001 Airframe PART - Expiration #1703	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY Part Number DK120/90 Serial Number AT201201	18-APR-2024 H: 2895.60 L: 2711				01-APR-2031	M: 68 D: 3
31 31-09 Airframe PART #477	CVDR CONTROL PANEL Part Number 441-42635-003 Serial Number 0379	07-MAY-2012					
31 33-01 Airframe PART #630	FDR - FLIGHT DATA RECORDER Part Number 2100-2044-00 Serial Number 000694782	07-MAY-2012					
31 33-03 Airframe PART FDR ULB #110	FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON Part Number PN UNKNOWN Serial Number SN UNKNOWN	12-MAY-2017 H: 1452.20 L: 1499					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 33-03-001 Airframe PART - Expiration #1552	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED) Part Number DK120 Serial Number AT54928	03-MAY-2023 H: 2749.10 L: 2607				01-SEP-2028	M: 37 D: 3
31 33-04 Airframe PART #1953	FORWARD CVDR IMPACT SWITCH Part Number 5930-4-000 Serial Number 5406	07-MAY-2012					
31 33-05 Airframe PART #1814	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 33-05 Airframe PART #382	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 33-05-001 Airframe INSPECTION #1804	FNC - FUNCTIONAL CHECK OF RUDDER FDR RVDT Reference Number AMM 31-33-05-720 -801-A/500 Notes EFFECTIVITY: ON ACFT 505: 00328-00328 00331-00333 00336-00336 00343-99800 WITH (FDR SYSTEM OR PROVISIONS FOR FDR SYSTEM) AND EASA CERTIFICATION	07-MAY-2012		M: 1			
31 33-05-002 Airframe INSPECTION #912	FNC - FUNCTIONAL CHECK OF ELEVATOR FDR RVDT Reference Number AMM 31-33-05-720 -802-A/500 Notes EFFECTIVITY: ON ACFT 505: 00328-00328 00331-00333 00336-00336 00343-99800 WITH (FDR SYSTEM OR PROVISIONS FOR FDR SYSTEM) AND EASA CERTIFICATION	07-MAY-2012		M: 1			
31 40-01 Airframe PART #1970	LH DCU UNIT Part Number 011-01457-00 Serial Number 16905030	19-MAY-2016 H: 1156.90 L: 1222					
31 40-01 Airframe PART #821	RH DCU UNIT Part Number 011-01457-00 Serial Number 16905521	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 40-02 Airframe PART #1400	LEFT GIA 63W INTEGRATED AVIONICS UNIT Part Number 011-01105-01 Serial Number 1HQ001397	07-MAY-2012					
31 40-02 Airframe PART #960	RIGHT GIA 63W INTEGRATED AVIONICS UNIT Part Number 011-01105-01 Serial Number 1HQ001407	07-MAY-2012					
31 41-01 Airframe PART #1318	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL Part Number 441-42627-001 Serial Number 1106	07-MAY-2012					
31 42-00-001 Airframe INSPECTION 6400H #1963	OPC - OPERATIONAL CHECK OF HSDB SWITCH REVERSION Reference Number AMM 31-42-00-710 -801-A/500	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
31 50-01 Airframe PART #48	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 50-01 Airframe PART #792	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT Part Number 011-00831-00 Serial Number 46713936	07-MAY-2012					
31 50-01 Airframe PART #763	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT Part Number 011-00831-00 Serial Number 46714295	07-MAY-2012					
31 50-01 Airframe PART #1319	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT Part Number 011-00831-00 Serial Number 46714308	07-MAY-2012					
31 61-00 Airframe PART #520	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) MFD AMLCD DISPLAY Part Number 011-037471-00 Serial Number 495001573	04-MAY-2021 H: 2376.70 L: 2304					
	Notes GDU1250A						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 61-00-001 Airframe INSPECTION 3200H #1302	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)	07-MAY-2012	H: 3200.00	H: 30.00		H: 3200.00	H: 156.60
31 61-00-001 Airframe INSPECTION 3200H #1685	OPERATIONAL CHECK MFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)	07-MAY-2012	H: 3200.00	H: 30.00		H: 3200.00	H: 156.60
31 61-00-001 Airframe INSPECTION 3200H #1749	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)	07-MAY-2012	H: 3200.00	H: 30.00		H: 3200.00	H: 156.60
31 61-01 Airframe PART #830	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY Part Number 011-03471-00 Serial Number 495001583	04-MAY-2021 H: 2376.70 L: 2304					
	Notes GDU1250A						
31 61-01 Airframe PART #585	NO. 2 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY Part Number 011-03471-00 Serial Number 495001579	04-MAY-2021 H: 2376.70 L: 2304					
	Notes GDU1250A						
31 61-05 Airframe PART #1697	TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 61-06 Airframe PART #497	NO. 1 BARO INSC ILLUMINATED PANEL Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
31 61-06 Airframe PART #1803	NO. 2 BARO INSC ILLUMINATED PANEL Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 00-00-001 Airframe INSPECTION 800H #251	GENERAL VISUAL INSPECTION OF OF MAIN LANDING GEAR POLYURETHANE FILMS	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
32 001 Airframe PART - Life Limited LHMLG STRUT #907	LEFT MLG SHOCK STRUT LEFT MAIN FITTING Part Number 2317-1201-503 Serial Number 1408106/001	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 002 Airframe PART - Life Limited RHMLG STRUT #584	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING Part Number 2317-1201-504 Serial Number 1408117/001	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 003 Airframe PART - Life Limited #331	LEFT PINTLE PIN Part Number 2317-1101-003 Serial Number 1409044/003	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 003 Airframe PART - Life Limited #1817	RIGHT PINTLE PIN Part Number 2317-1101-003 Serial Number 1409044/010	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 004 Airframe PART - Life Limited #1306	LEFT PINTLE PIN Part Number 2317-1102-001 Serial Number 1400167/009	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 004 Airframe PART - Life Limited #984	RIGHT PINTLE PIN Part Number 2317-1102-001 Serial Number 1400167/008	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 005 Airframe PART - Life Limited LHMLG STRUT #300	LEFT MLG SHOCK STRUT (MF - AS) AXLE Part Number 2317-1103-003 Serial Number 1388555/001	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 005 Airframe PART - Life Limited RHMLG STRUT #373	RIGHT MLG SHOCK STRUT (MF - AS) AXLE Part Number 2317-1103-003 Serial Number 1394459/002	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 006 Airframe PART - Life Limited LHMLG STRUT #1454	LEFT MLG SHOCK STRUT (TR - AS) AXLE Part Number 2317-1107-005 Serial Number 1407912/006	07-MAY-2012	L: 15300		M: 0 H: 0.00 L: 0	L: 15300	L: 12484
32 006 Airframe PART - Life Limited RHMLG STRUT #1247	RIGHT MLG SHOCK STRUT (TR - AS) AXLE Part Number 2317-1107-005 Serial Number 1409051/001	07-MAY-2012	L: 15300		M: 0 H: 0.00 L: 0	L: 15300	L: 12484
32 007 Airframe PART - Life Limited LHMLG STRUT #1778	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN Part Number 2317-1109-003 Serial Number 1399754/002	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 007 Airframe PART - Life Limited RHMLG STRUT #305	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN Part Number 2317-1109-003 Serial Number 1399754/008	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 008 Airframe PART - Life Limited LHMLG STRUT #816	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT Part Number 2317-1126-003 Serial Number 1426611/003	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 008 Airframe PART - Life Limited RHMLG STRUT #1371	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT Part Number 2317-1126-003 Serial Number 1426611/001	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 10-00 Airframe PART #1178	LEFT MAIN LANDING GEAR Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
32 10-00 Airframe PART #1688	RIGHT MAIN LANDING GEAR Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
32 10-01 Airframe PART #1280	LEFT MAIN LANDING GEAR LEG STRUT ASSY Part Number 2317-1100-405 Serial Number 00100	18-JUL-2022 H: 2611.00 L: 2496					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 10-01 Airframe PART #45	RIGHT MAIN LANDING GEAR LEG STRUT ASSY Part Number 2317-1100-406 Serial Number 00100	18-JUL-2022 H: 2611.00 L: 2496					
32 100 Airframe PART LH TRL ARM #133	LEFT MAIN LANDING GEAR TRAILING ARM ASSY Part Number 2317-1500-405 Serial Number 00103	07-MAY-2012					
32 100 Airframe PART RH TRL ARM #197	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY Part Number 2317-1500-406 Serial Number 00105	07-MAY-2012					
32 101 Airframe PART - Life Limited LH TRL ARM #1340	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE Part Number 2317-1502-003 Serial Number 1407541/00 4	07-MAY-2012	L: 15300		M: 0 H: 0.00 L: 0	L: 15300	L: 12484
32 101 Airframe PART - Life Limited RH TRL ARM #1222	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE Part Number 2317-1502-003 Serial Number 1407541/00 1	07-MAY-2012	L: 15300		M: 0 H: 0.00 L: 0	L: 15300	L: 12484
32 102 Airframe PART - Life Limited LH TRL ARM #152	LEFT MAIN LANDING GEAR TRAILING ARM AXLE Part Number 2317-1503-005 Serial Number 3069143	07-JUN-2022 H: 2611.00 L: 2496	L: 16800		L: 0	L: 19296	L: 16480
32 102 Airframe PART - Life Limited RH TRL ARM #504	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE Part Number 2317-1503-005 Serial Number 1399625/00 5	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 103 Airframe PART - Life Limited LH TRL ARM #1416	LEFT MAIN LANDING GEAR TRAILING ARM BOLT Part Number 2317-1509-001 Serial Number 1401017/00 1	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 103 Airframe PART - Life Limited RH TRL ARM #55	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT Part Number 2317-1509-001 Serial Number 1401017/00 2	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 104 Airframe PART - Life Limited #141	LEFT MAIN LANDING GEAR TRAILING ARM Part Number 2317-1513-501 Serial Number 1400189/00 1	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 105 Airframe PART - Life Limited #1633	RIGHT MAIN LANDING GEAR TRAILING ARM Part Number 2317-1513-502 Serial Number 1407550/00 1	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 106 Airframe PART - Life Limited LH TRL ARM #493	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN Part Number 2317-1505-001 Serial Number 1465310/00 1	07-JUN-2022 H: 2611.00 L: 2496	L: 16800		L: 0	L: 19296	L: 16480
32 106 Airframe PART - Life Limited RH TRL ARM #191	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN Part Number 2317-1505-001 Serial Number 1407754/00 2	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 11-00-001 Airframe INSPECTION 12M #1258	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
32 11-00-003 Airframe INSPECTION #1517	LUBRICATION OF MAIN LANDING GEAR	03-MAY-2025 H: 3019.50 L: 2801	M: 12 L: 650	M: 1 L: 30		03-MAY-2026 L: 3451	M: 9 D: 4 L: 635
32 11-01-001 Airframe INSPECTION LHMLG STRUT #2125	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH) Reference Number AMM TASK 32-11-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 11-01-002 Airframe INSPECTION RHMLG STRUT #2138	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH) Reference Number AMM TASK 32-11-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		08-JUN-2032 L: 14496	M: 82 D: 10 L: 11680

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 11-02-001 Airframe INSPECTION #2128	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH) Reference Number AMM TASK 32-11-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 11-02-002 Airframe INSPECTION #2131	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH) Reference Number AMM TASK 32-11-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 11-03-001 Airframe INSPECTION #2126	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH) Reference Number AMM TASK 32-11-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 11-03-002 Airframe INSPECTION #2130	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH) Reference Number AMM TASK 32-11-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		08-JUN-2032 L: 14496	M: 82 D: 10 L: 11680
32 11-03-004 Airframe INSPECTION LHSHKABSORB, RHSHKABSORB #1238	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER	03-MAY-2025 H: 3019.50 L: 2801	M: 12 L: 650	M: 1 L: 30		03-MAY-2026 L: 3451	M: 9 D: 4 L: 635
32 11-04-001 Airframe INSPECTION LH TRL ARM #2136	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH) Reference Number Part Number Serial Number AMM TASK 2317-1513-501 1400189/00 32-11-00-920-801-A/200 1 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		18-JUL-2032 L: 14496	M: 83 D: 19 L: 11680

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 11-04-002 Airframe INSPECTION RH TRL ARM #2137	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH) Reference Number Part Number Serial Number AMM TASK 2317-1513-502 1407550/00 32-11-00-920-801- 1 A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		18-JUL-2032 L: 14496	M: 83 D: 19 L: 11680
32 20-01 Airframe PART #441	NOSE LANDING GEAR Part Number Serial Number PN UNKNOWN SN UNKNOWN	07-MAY-2012					
32 200 Airframe PART LHSHKABSORB #847	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER Part Number Serial Number 2317-3000-403 00227	18-JUL-2022 H: 2611.00 L: 2496					
32 200 Airframe PART RSHKABSORB #1587	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER Part Number Serial Number 2317-3000-403 00228	18-JUL-2022 H: 2611.00 L: 2496					
32 201 Airframe PART - Life Limited LHSHKABSORB #1819	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER Part Number Serial Number 22317-3011-001 3003986	07-JUN-2022 H: 2611.00 L: 2496	L: 16800		L: 0	L: 19296	L: 16480
32 201 Airframe PART - Life Limited RSHKABSORB #518	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER Part Number Serial Number 2317-3011-001 1402706/00 6	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 202 Airframe PART - Life Limited LHSHKABSORB #434	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE Part Number Serial Number 2317-3021-001 1388090/00 1	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 202 Airframe PART - Life Limited RSHKABSORB #7	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE Part Number Serial Number 2317-3021-001 1402715/00 1	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 203 Airframe PART - Life Limited LHSHKABSORB #235	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING Part Number 2317-3001-003 Serial Number 1405825/004	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 203 Airframe PART - Life Limited RSHKABSORB #929	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING Part Number 2317-3001-003 Serial Number 1405825/008	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 204 Airframe PART - Life Limited LHSHKABSORB #1751	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT Part Number 2317-3004-001 Serial Number 1400169/009	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 204 Airframe PART - Life Limited RSHKABSORB #1841	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT Part Number 2317-3004-001 Serial Number 1400169/002	07-MAY-2012	L: 16800		M: 0 H: 0.00 L: 0	L: 16800	L: 13984
32 21-00-001 Airframe INSPECTION 12M, NLG #1754	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR Part Number PN UNKNOWN Serial Number SN UNKNOWN	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
32 21-00-003 Airframe INSPECTION NLG #886	LUBRICATION OF NOSE LANDING GEAR Part Number PN UNKNOWN Serial Number SN UNKNOWN	03-MAY-2025 H: 3019.50 L: 2801	M: 12 L: 650	M: 1 L: 30		03-MAY-2026 L: 3451	M: 9 D: 4 L: 635
32 21-01-001 Airframe INSPECTION NLGSHOCKSTRT #2140	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY Reference Number AMM TASK 32-21-00-920-801-A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 21-02 Airframe PART #253	NLG RETRACTION ACTUATOR Part Number 2117-1000-401 Serial Number 00108	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 21-03 Airframe PART #866	NLG DOWNLOCK ACTUATOR Part Number 2117-2000-401 Serial Number 00111	07-MAY-2012					
32 21-04-001 Airframe INSPECTION #2139	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY Reference Number AMM TASK 32-21-00-920-801- A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 21-05-001 Airframe INSPECTION #2123	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER Reference Number AMM TASK 32-21-00-920-801- A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		07-JUN-2032 L: 14496	M: 82 D: 9 L: 11680
32 21-05-004 Airframe INSPECTION NLG SHK ABS #1145	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER	03-MAY-2025 H: 3019.50 L: 2801	M: 12 L: 650	M: 1 L: 30		03-MAY-2026 L: 3451	M: 9 D: 4 L: 635
32 21-06-005 Airframe INSPECTION 12M, NLG, NLGSHOCKSTRT #1401	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER Part Number PN UNKNOWN Serial Number SN UNKNOWN	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
32 21-09-001 Airframe INSPECTION #2134	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY Reference Number AMM TASK 32-21-00-920-801- A/200 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE.	18-JUL-2022 H: 2611.00 L: 2496	M: 120 L: 12000	M: 1 L: 30		08-JUN-2032 L: 14496	M: 82 D: 10 L: 11680
32 23-03 Airframe PART #77	NLG DOOR - TORQUE TUBE ASSEMBLY Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 300 Airframe PART #1471	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR Part Number 2117-3000-601 Serial Number 00218	18-JUL-2022 H: 2611.00 L: 2496					
32 300 Airframe PART #607	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR Part Number 2117-3000-601 Serial Number 00221	18-JUL-2022 H: 2611.00 L: 2496					
32 301 Airframe PART - Life Limited LHLOCKACT #1742	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER Part Number 2117-3034-501 Serial Number 1403794/00 2		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 301 Airframe PART - Life Limited RHLOCKACT #1520	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER Part Number 2117-3034-501 Serial Number 1414787/00 4		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 302 Airframe PART - Life Limited #1681	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON Part Number 2117-3001-001 Serial Number 1409030/00 9		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 302 Airframe PART - Life Limited #1727	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON Part Number 2117-3001-001 Serial Number 1409030/01 0		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 303 Airframe PART - Life Limited #1505	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER Part Number 2117-3010-001 Serial Number 1399753/00 9		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 303 Airframe PART - Life Limited #1162	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER Part Number 2117-3010-001 Serial Number 1399753/00 2		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 304 Airframe PART - Life Limited LHLOCKACT #1865	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD Part Number 2117-3008-901 Serial Number 68030/0007		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 304 Airframe PART - Life Limited RHLOCKACT #1547	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD Part Number 2117-3008-901 Serial Number 68030/0008		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 305 Airframe PART - Life Limited LHLOCKACT #276	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON Part Number 2117-3009-007 Serial Number 1386481/00 2		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 305 Airframe PART - Life Limited RHLOCKACT #1823	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON Part Number 2117-3009-007 Serial Number 1386481/00 3		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 306 Airframe PART - Life Limited #1723	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN Part Number 2117-3019-001 Serial Number 1400170/00 6	19-MAY-2016 H: 1156.90 L: 1222	L: 12000		M: 48 H: 1156.90 L: 1222	L: 12000	L: 9184
32 306 Airframe PART - Life Limited #1538	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN Part Number 2117-3019-001 Serial Number 1400170/00 4	19-MAY-2016 H: 1156.90 L: 1222	L: 12000		M: 48 H: 1156.90 L: 1222	L: 12000	L: 9184
32 307 Airframe PART - Life Limited #1730	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE Part Number 2117-3007-001 Serial Number 1408695/00 6		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 307 Airframe PART - Life Limited #199	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE Part Number 2117-3007-001 Serial Number 1401016/00 2		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 308 Airframe PART - Life Limited LHLOCKACT #1142	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP Part Number 2117-3011-001 Serial Number 1409026/00 7		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184
32 308 Airframe PART - Life Limited RHLOCKACT #1698	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP Part Number 2117-3011-001 Serial Number 1409026/00 9		L: 12000		M: 0 H: 0.00 L: 0	L: 12000	L: 9184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 309 Airframe PART - Life Limited LHLOCKACT #207	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING Part Number 2117-3013-001 Serial Number 3054566	07-JUL-2022 H: 2611.00 L: 2496	L: 12000		M: 0 L: 0	L: 14496	L: 11680
32 309 Airframe PART - Life Limited RHLOCKACT #248	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING Part Number 2117-3013-001 Serial Number 3054568	07-JUN-2022 H: 2611.00 L: 2496	L: 12000		L: 0	L: 14496	L: 11680
32 31-01 Airframe PART #1902	LANDING GEAR CONTROL LEVER Part Number 827101-7 Serial Number 1121	07-MAY-2012					
32 31-04 Airframe PART #1645	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE Part Number 7342-1 Serial Number 0122T	07-MAY-2012					
32 31-05 Airframe PART #523	LH MLG UPLOCK BOX ASSY Part Number 2617-1000-401 Serial Number 00200	07-MAY-2012					
32 31-05 Airframe PART #470	NLG UPLOCK BOX ASSY Part Number 2617-1000-401 Serial Number 00206	07-MAY-2012					
32 31-05 Airframe PART #172	RH MLG UPLOCK BOX ASSY Part Number 2617-1000-402 Serial Number 00103	07-MAY-2012					
32 310 Airframe PART - Life Limited LHLOCKACT #1427	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT Part Number 2117-3029-001 Serial Number 00849	07-JUL-2022 H: 2611.00 L: 2496	L: 28000		M: 0 L: 0	L: 30496	L: 27680
32 310 Airframe PART - Life Limited RHLOCKACT #1674	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT Part Number 2117-3029-001 Serial Number 00853	07-JUL-2022 H: 2611.00 L: 2496	L: 28000		L: 0	L: 30496	L: 27680

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 311 Airframe PART - Life Limited LHLOCKACT #575	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END Part Number MTMKS14ALGA1 Serial Number 10071	07-JUL-2022 H: 2611.00 L: 2496	L: 10500		M: 0 L: 0	L: 12996	L: 10180
32 311 Airframe PART - Life Limited RHLOCKACT #289	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END Part Number MTMKS14ALGA1 Serial Number 00187	07-JUN-2022 H: 2611.00 L: 2496	L: 10500		L: 0	L: 12996	L: 10180
32 313 Airframe PART - Life Limited LHLOCKACT #667	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	L: 28000		M: 0 H: 0.00 L: 0	L: 28000	L: 25184
32 313 Airframe PART - Life Limited RHLOCKACT #316	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	L: 28000		M: 0 H: 0.00 L: 0	L: 28000	L: 25184
32 35-00-001 Airframe INSPECTION #658	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM	18-APR-2024 H: 2895.60 L: 2711	M: 24 H: 1600.00	D: 30 H: 30.00		18-APR-2026 H: 4495.60	M: 8 D: 20 H: 1452.20
32 35-00-002 Airframe INSPECTION #322	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES	18-APR-2024 H: 2895.60 L: 2711	M: 24 H: 1600.00	D: 30 H: 30.00		18-APR-2026 H: 4495.60	M: 8 D: 20 H: 1452.20
32 35-02 Airframe PART #1894	CENTER FUSELAGE FREE FALL VALVE Part Number 7343-2 Serial Number 0139T	07-MAY-2012					
32 400 Airframe PART #1579	NOSE LANDING GEAR SHOCK STRUT Part Number 2317-5100-403 Serial Number 00108	18-JUL-2022 H: 2611.00 L: 2496					
32 401 Airframe PART - Life Limited NLGSHOCKSTRT #947	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT Part Number 2310-1144-005 Serial Number 1409923/006	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 402 Airframe PART - Life Limited NLGSHOCKSTRT #911	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT Part Number 2310-1173-001 Serial Number 1408668/001	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 403 Airframe PART - Life Limited NLGSHOCKSTRT #1869	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN Part Number 2317-5105-001 Serial Number 1406719/007	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 403 Airframe PART - Life Limited NLGSHOCKSTRT #1879	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN Part Number 2317-5105-001 Serial Number 1406719/008	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 404 Airframe PART - Life Limited NLGSHOCKSTRT #1	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING Part Number 2317-5301-503 Serial Number 1802079/001	08-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880
32 405 Airframe PART - Life Limited NLGSHOCKSTRT #1849	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER Part Number 2117-4000-403 Serial Number 00106	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 406 Airframe PART - Life Limited NLGSHOCKSTRT #1834	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE Part Number 2317-5101-001 Serial Number 3007776	08-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880
32 407 Airframe PART - Life Limited NLGSHOCKSTRT #494	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK Part Number 2317-5201-001 Serial Number 1409036/007	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 407 Airframe PART - Life Limited NLGSHOCKSTRT #751	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK Part Number 2317-5201-001 Serial Number 1409036/009	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 408 Airframe PART - Life Limited NLGDRAGBRACE #694	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN Part Number 2317-6003-001 Serial Number 1406723/002	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 409 Airframe PART - Life Limited NLGSHOCKSTRT #706	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE Part Number 2310-1165-001 Serial Number 3026455	08-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880
32 41-00 Airframe PART #98	BRAKE CONTROL UNIT Part Number DAP00100-10 Serial Number SN UNKNOWN	12-MAY-2017 H: 1452.20 L: 1499					
32 41-00-001 Airframe INSPECTION 5600H #475	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
32 41-01 Airframe PART #649	BRAKE CONTROL UNIT TRAY Part Number DAP00134-01 Serial Number 0126	07-MAY-2012					
32 41-02 Airframe PART #1693	LH BRAKE PEDAL TRANSDUCER Part Number Q3008 Serial Number 031954	07-MAY-2012					
32 41-02 Airframe PART #985	RH BRAKE PEDAL TRANSDUCER Part Number Q3008 Serial Number 031974	07-MAY-2012					
32 41-02-001 Airframe INSPECTION 6400H, LH BRAKETRAN #385	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER Part Number Q3008 Serial Number 031954	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
32 41-02-001 Airframe INSPECTION 6400H, RH BRAKETRAN #1242	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER Part Number Q3008 Serial Number 031974	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 41-02-002 Airframe INSPECTION 1600H, LH BRAKETRAN #255	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER Part Number Q3008 Serial Number 031954	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
32 41-02-002 Airframe INSPECTION 1600H, RH BRAKETRAN #328	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER Part Number Q3008 Serial Number 031974	03-MAY-2023 H: 2749.10 L: 2607	H: 1600.00	H: 30.00		H: 4349.10	H: 1305.70
32 41-06 Airframe PART #1612	LH MLG WHEEL SPEED TRANSDUCER Part Number DAP00103-01 Serial Number 49KT	07-MAY-2012					
32 41-06 Airframe PART #1365	RH MLG WHEEL SPEED TRANSDUCER Part Number DAP00103-01 Serial Number 28KU	07-MAY-2012					
32 41-07 Airframe PART #440	BRAKE CONTROL MODULE Part Number DAP00101-02 Serial Number 132KB	07-MAY-2012					
32 410 Airframe PART - Life Limited NLGSHOCKSTRT #1052	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN Part Number 57675-1 Serial Number 01609	08-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880
32 411 Airframe PART - Life Limited NLGSHOCKSTRT #1220	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT Part Number 2310-1183-001 Serial Number 1403845/00 4	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 412 Airframe PART - Life Limited NLGSHOCKSTRT #148	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK Part Number 2317-5191-001 Serial Number 1413714/00 1	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 43-00-001 Airframe INSPECTION 5600H #190	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 43-01-001 Airframe INSPECTION 5600H #1008	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM	03-APR-2014 H: 623.30 L: 675	H: 5600.00	H: 30.00		H: 6223.30	H: 3179.90
32 43-02 Airframe PART #920	PRESSURE SWITCH Part Number DAP00108-01 Serial Number 061PD	12-JUN-2015 H: 850.20 L: 933					
32 43-04 Airframe PART #1955	EMERGENCY/PARKING BRAKE ACCUMULATOR Part Number DAP00106-01 Serial Number 103	07-MAY-2012					
32 43-05 Airframe PART #1662	EMERGENCY/PARKING BRAKE VALVE Part Number DAP00107-01 Serial Number 60KX	07-MAY-2012					
32 43-06 Airframe PART #675	PRESSURE TRANSDUCER Part Number DAP00109-01 Serial Number 7961-9-116	07-MAY-2012					
32 43-08 Airframe PART #1048	THERMAL RELIEF VALVE Part Number DAP00110-01 Serial Number 146	07-MAY-2012					
32 43-10 Airframe PART EMRBRAKEVALV #822	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE Part Number DAP00202-01 Serial Number 155	07-MAY-2012					
32 43-11 Airframe PART #1731	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE Part Number 2216-0001-401 Serial Number 00382	07-MAY-2012					
32 43-11-001 Airframe INSPECTION EMRBRAKEVALV #1446	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE Part Number DAP00107-01 Serial Number 60KX	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 45-01 Airframe PART #277	LEFT MAIN WHEEL Part Number DAP00098-02 Serial Number 5170NS	18-JUL-2022 H: 2611.00 L: 2496	L: 1500			L: 3996	L: 1180
32 45-01 Airframe PART - Life Limited #519	RIGHT MAIN WHEEL Part Number DAP00098-02 Serial Number 5100PG	18-JUL-2022 H: 2611.00 L: 2496	L: 1500		M: 1 L: 0	L: 3996	L: 1180
32 45-01-003 Airframe PART - Overhaul LHMLG WHEEL #2009	RESTORATION (OVERHAUL) OF LEFT MAIN LANDING GEAR WHEEL ASSEMBLY Reference Number AMM 32-45-00-920 Part Number DAP00098-02 Serial Number 5170NS Notes OR AT THE NEXT SUBSEQUENT TIRE CHANGE AFTER 1500 FLIGHT CYCLES	18-JUL-2022 H: 2611.00 L: 2496	L: 1500	L: 30	M: 1 L: 0	L: 3996	L: 1180
32 45-01-003 Airframe INSPECTION RHMLG WHEEL #1998	RESTORATION (OVERHAUL) OF RIGHT MAIN LANDING GEAR WHEEL ASSEMBLY Reference Number AMM 32-45-00-920 Part Number DAP00098-02 Serial Number 5100PG Notes OR AT THE NEXT SUBSEQUENT TIRE CHANGE AFTER 1500 FLIGHT CYCLES	18-JUL-2022 H: 2611.00 L: 2496	L: 1500	L: 30		L: 3996	L: 1180
32 45-02 Airframe PART LHMLG WHEEL #198	LEFT MAIN WHEEL TIRE Part Number 258K63-2 Serial Number 20410481	18-JUL-2022 H: 2611.00 L: 2496					
32 45-02 Airframe PART RHMLG WHEEL #795	RIGHT MAIN WHEEL TIRE Part Number 258K63-2 Serial Number 20331030	18-JUL-2022 H: 2611.00 L: 2496					
32 45-03 Airframe PART #1439	LH MLG HUB CAP Part Number DAP00131-02 Serial Number 63KS	07-MAY-2012					
32 45-03 Airframe PART #1434	RH MLG HUB CAP Part Number DAP00131-02 Serial Number 57KS	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 45-11 Airframe PART - Life Limited #1268	NOSE WHEEL Part Number Serial Number DAP00099-02 5003LF	29-AUG-2017 H: 1557.90 L: 1590	L: 1500		M: 0 H: 0.00 L: 0	L: 3090	L: 274
32 45-11-003 Airframe INSPECTION - Overhaul NLG WHEEL #1999	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY Reference Number Part Number Serial Number AMM 32-45-00-920 -801-A/200 DAP00099-02 5003LF Notes OR AT THE SUBSEQUENT TIRE CHANGE AFTER 1500 FLIGHT CYCLES	29-AUG-2017 H: 1557.90 L: 1590	L: 1500	L: 30		L: 3090	L: 274
32 45-12 Airframe PART NLG WHEEL #1091	NOSE TIRE Part Number Serial Number 156E23-1 12600534	22-SEP-2023 H: 2833.90 L: 2664					
32 45-21 Airframe PART #1184	LH MLG CARBON BRAKE ASSY Part Number Serial Number DAP00097-04 5020LK	17-OCT-2018 H: 1889.90 L: 1900					
32 45-21 Airframe PART #1156	RH MLG CARBON BRAKE ASSY Part Number Serial Number DAP00097-04 5193PE	07-DEC-2023 H: 2676.10 L: 2553					
32 500 Airframe PART NLG SHK ABS #1362	NOSE LANDING GEAR SHOCK ABSORBER Part Number Serial Number 2317-5170-403 00117	07-MAY-2012					
32 501 Airframe PART - Life Limited NLG SHK ABS #195	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK Part Number Serial Number 2317-5227-501 1404152/00 1	07-MAY-2012 H: 2611.00 L: 2496	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 502 Airframe PART - Life Limited NLG SHK ABS #936	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING Part Number Serial Number 2317-5113-005 3052435	08-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 503 Airframe PART - Life Limited NLG SHK ABS #580	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER Part Number 2317-5231-503 Serial Number 1404598/003	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 600 Airframe PART NLGDRAGBRACE #974	NOSE LANDING GEAR DRAG BRACE Part Number 2317-6000-403 Serial Number 00111	18-JUL-2022 H: 2611.00 L: 2496					
32 601 Airframe PART - Life Limited NLGDRAGBRACE #1146	NOSE LANDING GEAR UPPER DRAG BRACE Part Number 2317-6101-501 Serial Number 1410044/001	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 602 Airframe PART - Life Limited NLGDRAGBRACE #1108	NOSE LANDING GEAR LOWER DRAG BRACE Part Number 2317-6201-001 Serial Number 1406725/002	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 603 Airframe PART - Life Limited NLGDRAGBRACE #1737	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN Part Number 2317-6001-001 Serial Number 1402713/005	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 603 Airframe PART - Life Limited NLGDRAGBRACE #1279	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN Part Number 2317-6001-001 Serial Number 1402713/007	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 604 Airframe PART - Life Limited #779	NOSE LANDING GEAR DRAG BRACE PIN Part Number 2317-6003-001 Serial Number 1370978/002	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 61-01 Airframe PART #1536	LH WING PROXIMITY SWITCH Part Number 80-057-01 Serial Number 29376	07-MAY-2012					
32 61-01 Airframe PART #1664	NO. 1 LEFT MLG PROXIMITY SWITCH Part Number 80-057-01 Serial Number 29547	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 61-01 Airframe PART #1890	NO. 1 NLG PROXIMITY SWITCH Part Number 80-057-01 Serial Number 29377	07-MAY-2012					
32 61-01 Airframe PART #972	NO. 1 RIGHT MLG PROXIMITY SWITCH Part Number 80-057-01 Serial Number 29549	07-MAY-2012					
32 61-01 Airframe PART #619	NO. 2 LEFT MLG PROXIMITY SWITCH Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
32 61-01 Airframe PART #268	NO. 2 NLG PROXIMITY SWITCH Part Number 80-057-01 Serial Number 29383	07-MAY-2012					
32 61-01 Airframe PART #1647	NO. 2 RIGHT MLG PROXIMITY SWITCH Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
32 61-01 Airframe PART #290	NO. 3 LEFT MLG PROXIMITY SWITCH Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
32 61-01 Airframe PART #1534	NO. 3 RIGHT MLG PROXIMITY SWITCH Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
32 61-01 Airframe PART #19	RH WING PROXIMITY SWITCH Part Number 80-057-01 Serial Number 29372	07-MAY-2012					
32 700 Airframe PART NLGLOCKSTAY #178	NOSE LANDING GEAR LOCKING STAY Part Number 2317-6500-403 Serial Number 00103	18-JUL-2022 H: 2611.00 L: 2496					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 701 Airframe PART - Life Limited NLGLOCKSTAY #87	NOSE LANDING GEAR UPPER LOCKING STAY Part Number 2317-6521-003 Serial Number 1399685/001	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 702 Airframe PART - Life Limited NLGLOCKSTAY #784	NOSE LANDING GEAR LOWER LOCKING STAY Part Number 2317-6531-001 Serial Number 1403826/003	07-MAY-2012	L: 11200		M: 0 H: 0.00 L: 0	L: 11200	L: 8384
32 703 Airframe PART - Life Limited NLGLOCKSTAY #1403	LOWER NOSE LANDING GEAR LOCKING STAY BOLT Part Number 2310-1734-001 Serial Number 3038566	07-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880
32 703 Airframe PART - Life Limited NLGLOCKSTAY #1518	UPPER NOSE LANDING GEAR LOCKING STAY BOLT Part Number 2310-1734-001 Serial Number 3038567	07-JUN-2022 H: 2611.00 L: 2496	L: 11200		L: 0	L: 13696	L: 10880
33 01-01 Airframe PART #1332	OVERHEAD LIGHTS CONTROL PANEL Part Number 441-43246-001 Serial Number 1115	07-MAY-2012					
33 12-01 Airframe PART #1707	COCKPIT DIMMER Part Number 81-01760-002 Serial Number 0458	07-MAY-2012					
33 12-02 Airframe INSPECTION #1619	INSC ILLUM - TEST PANEL	07-MAY-2012					
33 31-02 Airframe PART NLG #1324	NOSE (WITH/WITHOUT FDR) W001, ELECTRICAL HARNESS Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
33 42-01 Airframe PART #1500	LH LWR FWD TAXI LIGHT ASSY Part Number 81017-3 Serial Number 000154	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 42-01 Airframe PART #1274	RH LWR FWD TAXI LIGHT ASSY Part Number 81017-4 Serial Number 000176	07-MAY-2012					
33 47-01 Airframe PART #374	LEFT LANDING LIGHT ASSY Part Number 81017-5 Serial Number 000170	07-MAY-2012					
33 47-01 Airframe PART #1683	RIGHT LANDING LIGHT ASSY Part Number 81017-6 Serial Number 000166	07-MAY-2012					
33 48-00-001 Airframe PART - Life Limited #1543	DISCARD LEFT NO. 1 NAVIGATION LIGHT Part Number 84004-7 Serial Number 000268	07-MAY-2012	H: 12000.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 12000.00	H: 8956.60
33 48-00-001 Airframe PART - Life Limited #1082	DISCARD LEFT NO. 2 NAVIGATION LIGHT Part Number 84015-1 Serial Number 000180	07-MAY-2012	H: 12000.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 12000.00	H: 8956.60
33 48-00-001 Airframe PART - Life Limited #1744	DISCARD RIGHT NO. 1 NAVIGATION LIGHT Part Number 84004-7 Serial Number 000149	12-DEC-2013 H: 507.50 L: 558	H: 12000.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 12507.50	H: 9464.10
33 48-00-001 Airframe PART - Life Limited #1080	DISCARD RIGHT NO. 2 NAVIGATION LIGHT Part Number 84075-2 Serial Number 000539	04-MAY-2021 H: 2376.70 L: 2304	H: 12000.00	H: 30.00	M: 0 H: 0.00	H: 14376.70	H: 11333.30
33 48-00-002 Airframe INSPECTION 2400H, 1NAV LIGHT #1486	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT Part Number 84004-7 Serial Number 000268	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
33 48-00-002 Airframe INSPECTION 2400H, 2NAV LIGHT #1601	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT Part Number 84015-1 Serial Number 000180	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 48-00-002 Airframe INSPECTION 2400H, RH1 NAVLIGHT #817	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT Part Number 84004-7 Serial Number 000149	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
33 48-00-002 Airframe INSPECTION 2400H, RH2 NAVLIGHT #409	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT Part Number 84075-2 Serial Number 000539	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
33 49-00-001 Airframe PART - Life Limited #1765	DISCARD NO. 1 STROBE LIGHT Part Number 84036-3 Serial Number 000176	07-MAY-2012	H: 8000.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 8000.00	H: 4956.60
33 49-00-001 Airframe PART - Life Limited #1438	DISCARD NO. 2 STROBE LIGHT Part Number 84036-4 Serial Number 000148	07-MAY-2012	H: 8000.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 8000.00	H: 4956.60
33 49-00-002 Airframe INSPECTION 2400H, 1STROBE #577	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT Part Number 84036-3 Serial Number 000176	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
33 49-00-002 Airframe INSPECTION 2400H, 2STROBE #389	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT Part Number 84036-4 Serial Number 000148	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
33 52-01 Airframe PART #1908	LH REAR EMERGENCY LIGHT BATTERY Part Number 6450LS-00 Serial Number 001013	18-APR-2024 H: 2895.60 L: 2711					
33 52-01 Airframe PART #1488	RH FWD EMERGENCY LIGHT BATTERY Part Number 6450LS-00 Serial Number 001208	18-APR-2024 H: 2895.60 L: 2711					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 52-01-001 Airframe INSPECTION REAR LI BATT #166	FNC - FUNCTIONAL CHECK OF EMERGENCY LIGHTS BATTERY - LH REAR Reference Number Part Number Serial Number AMM 33-52-01-720 6450LS-00 001013 -801-A/500 Notes EFFECTIVITY: ON ACFT WITH BE AEROSPACE EMERGENCY BATTERY PN (5434-00 OR 6434-00 OR 6450LS-00 OR 7450LS-00) OR POST MOD SB (505-33-0004 OR 505-33-0007). NOTE: FROM THE LAST ACCOMPLISHMENT DATE (TOLERANCE NOT APPLICABLE). THRESHOLD 18 MO IS APPLICABLE ONLY FOR NEW AIRCRAFT AND MUST BE ACCOMPLISHED WITH THE AIRCRAFT FIRST 12 MO MAINTENANCE CHECK.	18-APR-2024 H: 2895.60 L: 2711	M: 12			18-APR-2025	M: -3 D: -11
33 52-01-001 Airframe INSPECTION FWD LI BATT #1743	FNC - FUNCTIONAL CHECK OF EMERGENCY LIGHTS BATTERY - RH FWD Reference Number Part Number Serial Number AMM 33-52-01-720 6450LS-00 001208 -801-A/500 Notes EFFECTIVITY: ON ACFT WITH BE AEROSPACE EMERGENCY BATTERY PN (5434-00 OR 6434-00 OR 6450LS-00 OR 7450LS-00) OR POST MOD SB (505-33-0004 OR 505-33-0007). NOTE: FROM THE LAST ACCOMPLISHMENT DATE (TOLERANCE NOT APPLICABLE). THRESHOLD 18 MO IS APPLICABLE ONLY FOR NEW AIRCRAFT AND MUST BE ACCOMPLISHED WITH THE AIRCRAFT FIRST 12 MO MAINTENANCE CHECK.	18-APR-2024 H: 2895.60 L: 2711	M: 12			18-APR-2025	M: -3 D: -11
33 52-02 Airframe PART #2238	R/H EXTERIOR LOWER FWD EMERGENY LIGHT Part Number Serial Number 0435LS00-00 001735 Notes Removed exterior R/H lower FWD emergency light P/N: 5385-00, S/N: 000174 and installed NEW emergency light P/N: 0435LS00-00, S/N: 001735 IAW EMB Phenom 300 AMM 33-52-0 . Ops check good. Refer to Form F-100-01 issued by Embraer SA, Ce No. 2003950921, WO No: 0905213526, Authorization No. DQI 2020-001 I COPE-7203-01, Dated: 15/NOV/2022.	03-MAY-2023 H: 2749.10 L: 2607					
34 Airframe INSPECTION #2075	30 DAY VOR CHECK	10-JUL-2019					
34 Airframe INSPECTION #2072	UPDATE EGPWM DATABASES Notes 56 DAY CYCLE	12-AUG-2019 H: 2081.60 L: 2076					
34 00-01 Airframe PART #1481	ACSS TRANSPONDER Part Number Serial Number PN UNKNOWN SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 00-02 Airframe PART #791	TRANSPONDER RF RELAY Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 00-03 Airframe PART #1191	NO.1 IASP SMART PROBE Part Number 2015L-4B Serial Number 0178	10-SEP-2013 H: 410.00 L: 444					
34 00-03 Airframe PART #541	NO.2 IASP SMART PROBE Part Number 2015L-4B Serial Number 0314	07-MAY-2012					
34 00-04 Airframe PART #1928	SD CARD DATABASE Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 00000 Airframe INSPECTION #2054	UPDATE FMS NAVIGATION DATABASE Notes 28 DAY CYCLE	26-FEB-2025 H: 3005.30 L: 2787					
34 00000 Airframe INSPECTION #2053	UPDATE FMS TERMINAL CHARTS DATABASE Notes 14 DAY CYCLE	26-FEB-2025 H: 3005.30 L: 2787					
34 10-01 Airframe PART #1158	RADIO ALTIMETER Part Number 066-01153-0101 Serial Number KRA405B-12454	07-MAY-2012					
34 10-02 Airframe PART #1308	LEFT RADIO ALTIMETER TRANSMIT ANTENNA Part Number S67-2002-45 Serial Number 553-4514	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 10-02 Airframe PART #1533	RIGHT RADIO ALTIMETER RECEIVE ANTENNA Part Number S67-2002-45 Serial Number 553-4552	07-MAY-2012					
34 11-00 Airframe PART #1154	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT Part Number C16786DA01 Serial Number C16786002 702	07-MAY-2012					
34 11-00-001 Airframe INSPECTION IESI #1974	FUNCTIONAL CHECK IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (FAR 91.411) Part Number C16786DA01 Serial Number C16786002 702	18-APR-2024 H: 2895.60 L: 2711	M: 24	M: 1		18-APR-2026	M: 8 D: 20
34 11-02 Airframe PART #339	PITOT/STATIC PROBE Part Number 0856UT4 Serial Number 302195	21-FEB-2017 H: 1381.80 L: 1448					
34 11-02-001 Airframe INSPECTION STATIC PROBE #744	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK Part Number 0856UT4 Serial Number 302195	18-APR-2024 H: 2895.60 L: 2711	M: 24	M: 1		18-APR-2026	M: 8 D: 20
34 15-00-001 Airframe INSPECTION 24M #84	FUNCTIONAL CHECK OF AIR DATA SYSTEM (FAR 91.411)	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
34 15-00-002 Airframe INSPECTION 60M #873	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
34 15-00-003 Airframe INSPECTION 24M #85	DETAILED INSPECTION OF IASP (FAR 91.411)	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
34 20-01 Airframe PART #1441	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM Part Number 011-00868-10 Serial Number 42019317	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 20-01 Airframe PART #208	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM Part Number 011-00868-10 Serial Number 42019172	07-MAY-2012					
34 20-02 Airframe PART #1138	LEFT MAGNETOMETER Part Number 011-00870-10 Serial Number 1CM005907	07-MAY-2012					
34 20-02 Airframe PART #1202	RIGHT MAGNETOMETER Part Number 011-00870-10 Serial Number 1CM007264	07-MAY-2012					
34 21-00-001 Airframe INSPECTION 36M, LH MAGNO, RH MAGNO #2209	FNC - MAGNETIC INTERFERENCE CHECK ON THE MAGNETOMETERS Reference Number AMM 34-21-02-710 Part Number 011-00870-10 Serial Number 1CM005907 -801-A/500	18-APR-2024 H: 2895.60 L: 2711	M: 36	M: 1		18-APR-2027	M: 20 D: 20
34 23-00 Airframe PART #1073	MAGNETIC COMPASS Part Number KCA0120W Serial Number BG7621111	07-MAY-2012					
34 23-00-001 Airframe INSPECTION 36M #74	FNC - FUNCTIONAL CHECK OF STANDBY COMPASS Reference Number AMM 34-23-00-720 -801-A/500	18-APR-2024 H: 2895.60 L: 2711	M: 36	M: 1		18-APR-2027	M: 20 D: 20
34 30-01 Airframe PART #1772	LEFT VOR/LOC 2 & 3 BLADE ANTENNA Part Number S65-247170 Serial Number 173-2972	07-MAY-2012					
34 30-01 Airframe PART #1734	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE Part Number S65-247170 Serial Number 173-3008	07-MAY-2012					
34 40-01 Airframe PART #1465	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER Part Number 010-01294-10 Serial Number 3NV005388	04-MAY-2021 H: 2376.70 L: 2304					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 40-02 Airframe PART #1716	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA Part Number 013-00245-00 Serial Number 9440	07-MAY-2012					
34 40-02 Airframe PART #549	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA Part Number 013-00245-00 Serial Number 9429	07-MAY-2012					
34 40-03 Airframe PART #1204	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA Part Number 011-00883-20 Serial Number 47204312	07-MAY-2012					
34 40-04 Airframe PART #1020	TCAS II UNIT Part Number 9003500-55904 Serial Number TSE01003	07-MAY-2012					
34 40-04 Airframe INSPECTION #2172	XM RADIO DATA ID GDL69 - NEW DATA RADIO ID - N3HTB40D. Notes XM WEATHER INOPERATIVE. CHECKED XM INFO PAGE AND FOUND SE RVICE CLASS TO REPORT NONE. CONTACTED GARMIN TO FIND RADIO AND DATA ID FROM GDL69 THAT WAS PREVIOUSLY INSTALLED TO TRACE CUSTOMER ACCOUNT. OLD DATA ID WAS T2MGT0CY AND RADIO ID WAS U4RGT08N WHICH WAS OBTAINED FROM GARMIN PRODUCTION LOGS FOR OLD TAIL NUMBER N175MQ. TRANSFERRED DATAT ID TO NEW DATA RADIO ID WHICH IS N3HTB40D. PLACED AIRCRAFT ON FLIGHT LINE AND OBATINED SATELLIE PING SIGNAL AND OPTIONS LOADED AND METAR SIGNAL LOADED VIA SATELLITE.	14-JUN-2021 H: 2404.60 L: 2331					
34 40-05 Airframe PART #1487	TCAS II TOP ANTENNA Part Number 7514060-902 Serial Number ANE39043	07-MAY-2012					
34 43-02 Airframe PART #1560	LOWER TCAS L BAND ANTENNA Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-02 Airframe PART #1519	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA Part Number S65-5366-7L Serial Number 261-106517	07-MAY-2012					
34 50-02 Airframe PART #1245	TOP XPDR L BAND ANTENNA Part Number S65-5366-7L Serial Number 261-106485	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 50-03 Airframe PART #1237	KN 63 DISTANCE MEASURING UNIT Part Number 066-01070-0001 Serial Number 35235	07-MAY-2012					
34 50-05 Airframe PART #729	PHASING COUPLER Part Number SSPD-113-10 Serial Number 6896	07-MAY-2012					
34 50-06 Airframe PART #1792	MARKER BEACON ANTENNA Part Number S35-1000-2 Serial Number 102-9442	07-MAY-2012					
34 50-07 Airframe PART #140	MARKER BEACON ANTENNA SPLITTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-08 Airframe PART #963	VOR/LOC/GS ANTENNA SPLITTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-09 Airframe PART #4	VOR/LOC/GS ANTENNA RF CABLE Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-10 Airframe PART #120	GSR 56 IRIDIUM UNIT Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-11 Airframe PART #1341	IRIDIUM SATCOM ANTENNA Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-12 Airframe PART #69	GDL 59 DATALINK MANAGEMENT UNIT Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 50-13 Airframe PART #1529	WI-FI - DATALINK ANTENNA Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
34 50-14 Airframe PART #1783	ADF ANTENNA Part Number 622-7383-001 Serial Number 3Y7WN	07-MAY-2012					
34 50-15 Airframe PART #1180	ADF UNIT Part Number 622-7382-101 Serial Number 451TX	07-MAY-2012					
34 51-02 Airframe PART #940	NO. 1 DME L BAND ANTENNA Part Number S65-5366-7L Serial Number 261-106784	07-MAY-2012					
34 52-00 Airframe PART #514	NO. 1 TRANSPONDER Part Number 9006000-55000 Serial Number NXE09107 Notes SEE WORK DESCRIPTION	18-APR-2024 H: 2895.60 L: 2711					
34 52-00 Airframe PART #959	NO. 2 TRANSPONDER Part Number 9006000-55000 Serial Number NXE18858 Notes SEE WORK DESCRIPTION	18-APR-2024 H: 2895.60 L: 2711					
34 52-00-001 Airframe INSPECTION 1 ATC #1079	FUNCTIONAL CHECK NO. 1 TRANSPONDER Part Number 9006000-55000 Serial Number NXE09107	18-APR-2024 H: 2895.60 L: 2711	M: 24			18-APR-2026	M: 8 D: 20
34 52-00-001 Airframe INSPECTION 2 ATC #303	FUNCTIONAL CHECK NO. 2 TRANSPONDER Part Number 9006000-55000 Serial Number NXE18858	18-APR-2024 H: 2895.60 L: 2711	M: 24			18-APR-2026	M: 8 D: 20

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 52-04 Airframe PART #243	LOWER COAXIAL UNIT Part Number D2-729B005 Serial Number 573135	07-MAY-2012					
34 52-04 Airframe PART #1905	UPPER COAXIAL UNIT Part Number D2-729B005 Serial Number 573130	07-MAY-2012					
34 53-01 Airframe PART #449	ADF MOUNTING TRAY Part Number 622-5212-001 Serial Number 45NKG	07-MAY-2012					
34 60-03 Airframe PART #1764	FLIGHT MANAGEMENT SYSTEM PANEL Part Number 011-01428-20 Serial Number 48Y00642 Notes GCU477	04-MAY-2021 H: 2376.70 L: 2304					
34 FAR01 Airframe INSPECTION IESI #458	TEST IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT IESI (AS PER FAR OR RBHA 91.411) Part Number C16786DA01 Serial Number C16786002 702	26-JUL-2024 H: 2927.90 L: 2737	M: 24			26-JUL-2026	M: 11 D: 27
34 FAR02 Airframe INSPECTION 1 IASP #1212	TEST NO.1 IASP (AS PER FAR OR RBHA 91.411) Part Number 2015L-4B Serial Number 0178	26-JUL-2024 H: 2927.90 L: 2737	M: 24			26-JUL-2026	M: 11 D: 27
34 FAR02 Airframe INSPECTION 2 IASP #1592	TEST NO.2 IASP (AS PER FAR OR RBHA 91.411) Part Number 2015L-4B Serial Number 0314	26-JUL-2024 H: 2927.90 L: 2737	M: 24			26-JUL-2026	M: 11 D: 27
34 FAR03 Airframe INSPECTION STATIC PROBE #443	TEST PITOT STATIC PROBE (AS PER FAR OR RBHA 91.411) Part Number 0856UT4 Serial Number 302195	18-APR-2024 H: 2895.60 L: 2711	M: 24			18-APR-2026	M: 8 D: 20

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 FAR04 Airframe INSPECTION 1 ATC #1414	TEST NO. 1 TRANSPONDER (AS PER FAR OR RBHA 91.413) Part Number 9006000-55000 Serial Number NXE09107	18-APR-2024 H: 2895.60 L: 2711	M: 24			18-APR-2026	M: 8 D: 20
34 FAR04 Airframe INSPECTION 2 ATC #853	TEST NO. 2 TRANSPONDER (AS PER FAR OR RBHA 91.413) Part Number 9006000-55000 Serial Number NXE18858	18-APR-2024 H: 2895.60 L: 2711	M: 24			18-APR-2026	M: 8 D: 20
34 VOR-01-1 Airframe INSPECTION #1165	PERFORM VOR ACCURACY CHECK (FAR 91.171)	07-MAY-2012					
35 Airframe INSPECTION #2073	SERVICE OXYGEN SYSTEM	02-MAY-2019 H: 2052.70 L: 2048					
35 00-00-001 Airframe INSPECTION #1275	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	18-APR-2024 H: 2895.60 L: 2711	M: 36 H: 2400.00	D: 30 H: 30.00		18-APR-2027 H: 5295.60	M: 20 D: 20 H: 2252.20
35 01-00-001 Airframe INSPECTION 60M #1658	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
35 01-02 Airframe PART #567	OXYGEN CYLINDER TRANSDUCER Part Number 4441125-000 Serial Number 7743-9-182	07-MAY-2012					
35 01-05 Airframe PART #214	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH Part Number P24151 Serial Number 0114	07-MAY-2012					
35 01-06 Airframe PART #1209	OXYGEN SYSTEM CONTROL PANEL Part Number 441-40945-002 Serial Number 0388	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 01-07 Airframe PART #249	COCKPIT SENSOR Part Number P24099 Serial Number 0101	07-MAY-2012					
35 01-08 Airframe PART #925	PAX LOW PRESSURE OXYGEN SYSTEM SWITCH Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
35 01-09 Airframe PART #685	ALTITUDE COMPENSATING REGULATOR Part Number 4421135-001 Serial Number 00278	07-MAY-2012					
35 01-10 Airframe PART #888	LOW PRESSURE OXYGEN VALVE Part Number 4421132-109 Serial Number 00368	07-MAY-2012					
35 02-01 Airframe INSPECTION #1528	OXYGEN CYLINDER	19-MAY-2016 H: 1156.90 L: 1222					
35 02-01-001 Airframe INSPECTION OXY CYL #366	FUNCTIONAL CHECK OF OXYGEN CYLINDER ASSEMBLY Part Number 4441122-077 Serial Number 748637101 Notes FROM THE LAST ACCOMPLISHMENT DATE (TOLERANCE NOT APPLICABLE)	04-MAY-2021 H: 2376.70 L: 2304	M: 60			04-MAY-2026	M: 9 D: 5
35 02-01-003 Airframe PART - Life Limited #1641	DISCARD OF OXYGEN CYLINDER Part Number 4441122-077 Serial Number 748637101	31-JAN-2016	M: 180		M: 0 H: 0.00 L: 0	31-JAN-2031	M: 66 D: 2
35 02-01-004 Engine 1 INSPECTION OXY CYL #486	RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER Part Number 4441122-077 Serial Number 748637101 Notes NOTE: TOLERANCE IS NOT APPLICABLE		M: 60			04-MAY-2026	M: 9 D: 5

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 02-05 Airframe PART #1616	OXYGEN PRESSURE REGULATOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
35 11-00-001 Airframe INSPECTION #1573	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX Notes LH/RH	03-MAY-2025 H: 3019.50 L: 2801	M: 12 H: 800.00	D: 30 H: 30.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
35 11-01 Airframe PART #30	COPILOT OXYGEN MASK STOWAGE BOX Part Number 1186F6-23 Serial Number 00752	07-MAY-2012					
35 11-01 Airframe PART #364	PILOT OXYGEN MASK STOWAGE BOX Part Number 1186F6-23 Serial Number 01205	04-MAY-2021 H: 2376.70 L: 2304					
35 11-02 Airframe PART #1203	LEFT CREW OXYGEN MASK Part Number 174232-93 Serial Number 30553	03-MAY-2023 H: 2749.10 L: 2607					
35 11-02 Airframe PART #1193	RIGHT CREW OXYGEN MASK Part Number 174232-93 Serial Number 31233	03-MAY-2023 H: 2749.10 L: 2607					
35 11-02-001 Airframe INSPECTION LH CREW/MASK #1300	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK Part Number 174232-93 Serial Number 30553 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE	18-APR-2024 H: 2895.60 L: 2711	M: 24	M: 1		18-APR-2026	M: 8 D: 20
35 11-02-001 Airframe INSPECTION RH CREW/MASK #1305	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK Part Number 174232-93 Serial Number 31233 Notes FROM THE ACFT MAINTENANCE START COUNTING DATE	18-APR-2024 H: 2895.60 L: 2711	M: 24	M: 1		18-APR-2026	M: 8 D: 20

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 11-02-002 Airframe INSPECTION LH CREW/MASK #1346	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK Part Number 174232-93 Serial Number 30553	03-MAY-2023 H: 2749.10 L: 2607	M: 72 H: 3600.00	M: 1 H: 30.00		03-MAY-2029 H: 6349.10	M: 45 D: 4 H: 3305.70
35 11-02-002 Airframe INSPECTION RH CREW/MASK #790	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK Part Number 174232-93 Serial Number 31233	03-MAY-2023 H: 2749.10 L: 2607	M: 72 H: 3600.00	M: 1 H: 30.00		03-MAY-2029 H: 6349.10	M: 45 D: 4 H: 3305.70
35 11-02-003 Airframe INSPECTION #534	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK - ON A/C WITH MC40-SERIES Notes FROM AIRCRAFT MAINTENANCE START COUNTING DATE			M: 1			
35 11-02-003 Airframe INSPECTION #1395	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK - ON A/C WITH MC40-SERIES Notes FROM AIRCRAFT MAINTENANCE START COUNTING DATE			M: 1			
35 11-04-001 Airframe INSPECTION 36M #914	DETAILED VISUAL INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED)	18-APR-2024 H: 2895.60 L: 2711	M: 36	M: 1		18-APR-2027	M: 20 D: 20
35 21-00-001 Airframe INSPECTION #1025	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE	18-APR-2024 H: 2895.60 L: 2711	M: 36 H: 2400.00	D: 30 H: 30.00		18-APR-2027 H: 5295.60	M: 20 D: 20 H: 2252.20
35 21-00-002 Airframe INSPECTION #1559	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE	18-APR-2024 H: 2895.60 L: 2711	M: 36 H: 2400.00	D: 30 H: 30.00		18-APR-2027 H: 5295.60	M: 20 D: 20 H: 2252.20
35 21-01 Airframe PART #1372	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER Part Number 4411071-002 Serial Number 4411071-002-00129	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 21-01 Airframe PART #31	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER Part Number 4411072-112 Serial Number 4411072-112-00797	04-MAY-2021 H: 2376.70 L: 2304					
35 21-01 Airframe PART #1618	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER Part Number 4411072-112 Serial Number 4411072-112-00051	19-MAY-2017 H: 1457.50 L: 1506					
35 21-01 Airframe PART #1924	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER Part Number 4411072-002 Serial Number 4411072-002-00290	07-MAY-2012					
35 21-01 Airframe PART #1065	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER Part Number 4411072-002 Serial Number 4411072-002-00312	07-MAY-2012					
35 21-01 Airframe PART #2166	NO. 6 TWO MASK DEPLOYMENT OXYGEN CONTAINER Part Number 4411072-112 Serial Number 4411072-112-00798	04-MAY-2021 H: 2376.70 L: 2304					
35 21-01 Airframe PART #572	ONE MASK DEPLOYMENT OXYGEN CONTAINER CENTER CABIN Part Number 4411071-002 Serial Number 4411071-002-00111	19-MAY-2017 H: 1457.50 L: 1506					
35 21-01-001 Airframe INSPECTION 36M #752	DETAILED INSPECTION OF PASSENGER OXYGEN-MASKS ASSEMBLY Reference Number AMM 35-21-01-213 -801-A/600	18-APR-2024 H: 2895.60 L: 2711	M: 36	M: 1		18-APR-2027	M: 20 D: 20
35 31-01-001 Airframe PART - Life Limited #935	DIS - DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE) Reference Number AMM 35-31-01-960 -801-A/200 Part Number MR10022NEMB Serial Number E2105568 Notes EFFECTIVITY: ON ACFT WITH CREW PBE OR POST-MOD SB 505-25-0031. NOTE: FROM THE MANUFACTURING DATE. REPLACEMENT UNIT EXPIRES 25-JUL-2032	03-MAY-2023 H: 2749.10 L: 2607	M: 126	M: 1	M: 0	25-JUL-2032	M: 83 D: 26

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 01-01 Airframe PART #1501	PNEUMATIC INSC ILLUM PANEL Part Number 441-42633-002 Serial Number 1104	07-MAY-2012					
36 11-01 Airframe PART #1011	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE Part Number RYLB-53505-5 Serial Number 0029	30-OCT-2018 H: 1905.30 L: 1911					
36 11-01 Airframe PART #1066	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE Part Number RYLB-53505-6 Serial Number 1020	18-JUL-2022 H: 2611.00 L: 2496					
36 11-01-001 Airframe INSPECTION 2400H #861	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
36 11-01-002 Airframe INSPECTION 800H #271	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
36 11-02-001 Airframe INSPECTION 24M #1059	DETAILED INSPECTION OF BLEED LINE WATER DRAINS Notes EFFECTIVITY: ON EMBRAER 505 ACFT WITH WATER DRAIN IN THE AFT BLEED LINE OR POST-MOD SB 505-21-0008	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
36 11-03 Airframe PART #1075	AMS CONTROLLER Part Number SYLZ-53632-203 Serial Number 0184	06-NOV-2012 H: 167.90 L: 194					
36 11-04 Airframe PART #46	NO. 1 ENGINE FAN AIR VALVE Part Number RYLB-53527-1 Serial Number 0245	07-MAY-2012					
36 11-04 Airframe PART #1068	NO. 2 ENGINE FAN AIR VALVE Part Number RYLB-53527-1 Serial Number 0246	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 11-04-001 Airframe INSPECTION 2400H #1889	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
36 11-05 Airframe PART #258	LH INCONEL 625 BLEED PRE-COOLER Part Number 10965000-105 Serial Number HX-02767	13-MAR-2024 H: 2850.90 L: 2677					
36 11-05 Airframe PART #1210	RH INCONEL 625 BLEED PRE-COOLER Part Number 10964000-105 Serial Number T0020	13-MAR-2024 H: 2850.90 L: 2677					
36 11-06 Airframe PART #1640	CROSS BLEED VALVE Part Number RYLB-53506-1 Serial Number 0124	07-MAY-2012					
36 11-06-001 Airframe INSPECTION 800H #329	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
36 11-06-002 Airframe INSPECTION 6400H #1825	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
36 11-07 Airframe PART #1103	NO. 1 BLEED PRESSURE TRANSDUCER Part Number APTE-479F-1000-200G Serial Number 7917-6-448	07-MAY-2012					
36 11-07 Airframe PART #1909	NO. 2 BLEED PRESSURE TRANSDUCER Part Number APTE-479F-1000-200G Serial Number 7960-7-119	07-MAY-2012					
36 11-08 Airframe PART #983	NO. 1 BLEED TEMPERATURE SENSOR Part Number 8TJ107DAJ1 Serial Number 28239	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 11-08 Airframe PART #780	NO. 2 BLEED TEMPERATURE SENSOR Part Number 8TJ107DAJ1 Serial Number 28242	07-MAY-2012					
36 11-08 Airframe PART #760	NO. 3 BLEED TEMPERATURE SENSOR Part Number 8TJ107DAJ1 Serial Number 28244	07-MAY-2012					
36 11-08 Airframe PART #882	NO. 4 BLEED TEMPERATURE SENSOR Part Number 8TJ107DAJ1 Serial Number 28248	07-MAY-2012					
36 11-08-001 Airframe INSPECTION 6400H #402	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
36 11-08-001 Airframe INSPECTION 6400H #962	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
36 11-08-001 Airframe INSPECTION 6400H #895	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
36 11-08-001 Airframe INSPECTION 6400H #1978	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
36 21-01-001 Airframe INSPECTION #447	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS	07-MAY-2012	H: 6400.00	H: 30.00		H: 6400.00	H: 3356.60
38 Airframe INSPECTION #2055	SERVICE LAVATORY						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 33-00 Airframe PART #1509	TOILET ASSY Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
38 33-07 Airframe PART #1527	WASTE DRAIN VALVE Part Number 0218-0032-1 Serial Number 166412	07-MAY-2012					
44 12-07 Airframe PART #1452	3-CHANNEL AUDIO AMPLIFIER Part Number 0700-005 Serial Number 11120261	07-MAY-2012					
44 21-03 Airframe PART #83	DC-DC CONVERTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 21-09 Airframe PART #639	IFE INSC ILLUM PANEL Part Number 441-42725-001 Serial Number 0188	07-MAY-2012					
44 21-11 Airframe PART #618	XM RECEIVER Part Number 0500-200 Serial Number 11110160	07-MAY-2012					
44 21-13 Airframe PART #1035	XM HEAD CONTROL Part Number 0500-300 Serial Number 1105P039	07-MAY-2012					
44 21-15 Airframe PART #242	AUDIO VOLUME CONTROLLER Part Number 0700-008 Serial Number 11090260	07-MAY-2012					
44 21-17 Airframe PART #1369	IR RECEIVER WITH CONNECTOR Part Number 0500-018 Serial Number 1102P008	07-MAY-2012					
44 21-19 Airframe PART #1201	IR REMOTE CONTOLLER Part Number 0500-015 Serial Number 11100006	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
44 21-21 Airframe PART #355	WIRELESS AUDIO TRANSMITTER Part Number 0700-009 Serial Number 12010238	07-MAY-2012					
44 21-23 Airframe PART #1846	NO. 1 WIRELESS HEADPHONE Part Number 0500-100 Serial Number 11120113	07-MAY-2012					
44 21-25 Airframe PART #219	HEADPHONE DISTRIBUTION AMPLIFIER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 2127-0101 Airframe PART #17	LH NO. 1 AUDIO CONTROL JACK Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 2127-0102 Airframe PART #206	RH NO. 2 AUDIO CONTROL JACK Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 2127-0103 Airframe PART #865	LH NO. 3 AUDIO CONTROL JACK Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 2127-0104 Airframe PART #884	RH NO. 4 AUDIO CONTROL JACK Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 2127-0105 Airframe PART #228	LH NO. 5 AUDIO CONTROL JACK Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 2127-0106 Airframe PART #979	RH NO. 6 AUDIO CONTROL JACK Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
44 22-01 Airframe PART #1828	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER Part Number 0604-001 Serial Number 11120267	07-MAY-2012					
44 22-03 Airframe PART #237	10.4 INCH FOLD DOWN MONITOR Part Number 1043-302 Serial Number 11110272	07-MAY-2012					
44 32-01 Airframe PART #71	ATG5000 TRANSCEIVER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 32-03 Airframe PART #9	AIRCELL CONFIGURATION MODULE Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
44 32-05 Airframe PART #1196	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
52 00-00 Airframe PART #591	KEY LOCK KIT Part Number 505-38958-901 Serial Number 550168	07-MAY-2012					
52 0001 Airframe PART #2252	MAIN ENTRY DOOR LINING SHROUD Part Number 505-41771-4001 Serial Number 33986695/0 01	18-APR-2024 H: 2895.60 L: 2711					
52 10-00-001 Airframe INSPECTION 60M #1176	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
52 10-01-001 Airframe INSPECTION 60M #1760	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 10-01-01-901 Airframe INSPECTION #488	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE -EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
52 10-01-02-901 Airframe INSPECTION #1877	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
52 10-01-02-902 Airframe INSPECTION #1564	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
52 10-02-01-901 Airframe INSPECTION #773	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
52 10-20-001 Airframe INSPECTION 12M #439	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL	03-MAY-2025 H: 3019.50 L: 2801	M: 12	M: 1		03-MAY-2026	M: 9 D: 4
52 11-00-001 Airframe INSPECTION 48M #891	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
52 11-00-003 Airframe INSPECTION 800H #1876	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
52 13-21-001 Airframe PART - Life Limited 5600H #1802	DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED) Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	H: 5600.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 5600.00	H: 2556.60
52 13-22 Airframe PART #1458	MAIN DOOR BALANCING MECHANISM Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 13-22-001 Airframe PART 800H #1597	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE Part Number PN UNKNOWN Serial Number SN UNKNOWN	19-MAY-2016 H: 1156.90 L: 1222		H: 30.00			
	Notes ON AC WITH SINGLE CABLE IN THE MAIN-DOOR BALANCING-MECHANISM OR PRE-MOD SB 505-52-0005 SB 505-52-0005 was C/W on 5/12/2017						
52 13-22-004 Airframe INSPECTION 3200H #2059	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES (POST MODE SB 505-52-0005)		H: 3200.00	H: 30.00		H: 3200.00	H: 156.60
	Notes EFFECTIVITY: ON ACFT WITH DOUBLE CABLE IN THE MAIN-DOOR BALANCING-MECHANISM OR POST-MOD SB 505-52-0005						
52 13-23-001 Airframe PART - Life Limited 5600H #1872	DISCARD OF MAIN DOOR BALANCING MECHANISM PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED) Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	H: 5600.00	H: 30.00	M: 0 H: 0.00 L: 0	H: 5600.00	H: 2556.60
52 20-00 Airframe PART #1009	EMERGENCY DOOR Part Number 500-09700-437 Serial Number 0000706292	07-MAY-2012					
52 20-01-001 Airframe INSPECTION 120M #176	GVI - EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
52 20-01-002 Airframe INSPECTION T 120M/I 60M #1926	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
52 20-01-01-901 Airframe INSPECTION #39	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
52 20-01-01-902 Airframe INSPECTION #841	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 20-20-001 Airframe INSPECTION 48M #945	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
52 20-21-001 Airframe INSPECTION 24M #1391	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL	26-JUL-2024 H: 2927.90 L: 2737	M: 24	M: 1		26-JUL-2026	M: 11 D: 27
52 31-20-001 Airframe INSPECTION 48M #473	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
52 32-20-001 Airframe INSPECTION 48M #1000	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM	18-APR-2024 H: 2895.60 L: 2711	M: 48	M: 1		18-APR-2028	M: 32 D: 20
52 71-20 Airframe PART #517	LOWER PAX DOOR MICRO SWITCH ASSEMBLY Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
52 71-20 Airframe PART #1443	UPPER PAX DOOR MICRO SWITCH ASSEMBLY Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012					
52 71-21 Airframe PART #2239	PAX MAIN DOOR SEAL, SIL Part Number 505-38948-901 Serial Number 8012037486	03-MAY-2023 H: 2749.10 L: 2607					
53 00-00-001 Airframe INSPECTION 800H #1044	GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
53 05-00-001 Airframe INSPECTION 60M #1916	DETAILED INSPECTION OF FUSELAGE DRAINS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-001 Airframe INSPECTION T 120M/I 60M #1123	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 10-00-002 Airframe INSPECTION 120M #1836	EXTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
53 10-00-003 Airframe INSPECTION 120M, NLG #1005	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
53 10-01-01-901 Airframe INSPECTION #1583	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKINPANEL AND WINDSHIELD CUTOUT - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-01-01-902 Airframe INSPECTION #970	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELDCUTOUT - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-02-01-901 Airframe INSPECTION #455	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT ANDRIGHT SIDESKIN PANELS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-02-01-902 Airframe INSPECTION #1125	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELDCUTOUT - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-03-01-901 Airframe INSPECTION #52	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-03-01-902 Airframe INSPECTION #1925	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-04-01-901 Airframe INSPECTION #765	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-04-01-902 Airframe INSPECTION #1344	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-05-001 Airframe INSPECTION T 120M/I 60M #1756	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 10-05-01-901 Airframe INSPECTION #1077	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 10-07-001 Airframe INSPECTION 60M, NLG #1420	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 10-07-01-901 Airframe INSPECTION NLG #1379	SPECIAL DETAILED INSPECTION (BOREScope) OF TRUNNIONS,DRAG LOCKING STRUT AND FASTENERS. NOSELANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	H: 15000.00 L: 12000			H: 15000.00 L: 12000	H: 11956.60 L: 9184
53 10-07-02-901 Airframe INSPECTION NLG #469	DETAILED INSPECTION OF WHEEL WEEL STRUCTURE. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE- EXTERNAL Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	H: 15000.00 L: 12000			H: 15000.00 L: 12000	H: 11956.60 L: 9184
53 10-07-02-902 Airframe INSPECTION NLG #1295	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WEELSTRUCTURE. Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012	H: 15000.00 L: 12000			H: 15000.00 L: 12000	H: 11956.60 L: 9184
53 14-00 Airframe PART #686	NOSE RADOME Part Number 5190-102-1 Serial Number 384	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-001 Airframe INSPECTION T 120M/I 60M #637	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-00-002 Airframe INSPECTION T 120M/I 60M #160	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-01-01-901 Airframe INSPECTION #923	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKINPANEL - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-01-01-902 Airframe INSPECTION #67	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-02-01-901 Airframe INSPECTION #1200	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGESIDE SKIN PANEL - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-02-01-902 Airframe INSPECTION #801	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-03-01-901 Airframe INSPECTION #16	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGELOWER SKIN PANEL - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-03-01-902 Airframe INSPECTION #1594	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-04-01-901 Airframe INSPECTION #599	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGELONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-04-01-902 Airframe INSPECTION #594	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-04-02-901 Airframe INSPECTION #264	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-04-02-902 Airframe INSPECTION #1684	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-05-002 Airframe INSPECTION T 120M/I 60M #1130	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-05-003 Airframe INSPECTION T 120M/I 60M #709	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-05-01-901 Airframe INSPECTION #330	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-05-02-901 Airframe INSPECTION #232	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-05-03-901 Airframe INSPECTION #1915	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-05-04-901 Airframe INSPECTION #876	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-05-05-901 Airframe INSPECTION #1549	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-06-001 Airframe INSPECTION 60M #1762	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-06-002 Airframe INSPECTION T 120M/I 60M #918	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-06-01-901 Airframe INSPECTION #401	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE -EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-06-01-902 Airframe INSPECTION #114	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN ANDATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL	07-MAY-2012	H: 8750.00 L: 7000			H: 8750.00 L: 7000	H: 5706.60 L: 4184
53 20-07-01-901 Airframe INSPECTION #1132	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS.EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-07-01-902 Airframe INSPECTION #1910	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCYDOOR CUTOUT STRUCTURE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-08-002 Airframe INSPECTION T 120M/I 60M #1476	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-08-01-901 Airframe INSPECTION #345	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUTSTRUCTURE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-08-01-902 Airframe INSPECTION #1677	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE -EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-10-001 Airframe INSPECTION T 120M/I 60M #1531	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 20-10-01-901 Airframe INSPECTION #754	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTERFUSELAGE-TO-WING CONNECTIONS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-10-01-902 Airframe INSPECTION #1126	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 20-10-02-901 Airframe INSPECTION #168	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS -EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-00-001 Airframe INSPECTION T 120M/I 60M #23	EXTERNAL GENERAL VISUAL INSPECTION OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 30-00-002 Airframe INSPECTION T 120M/I 60M #1883	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 30-01-01-901 Airframe INSPECTION #1833	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFTFUSELAGE UPPER SKIN PANEL - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-01-01-902 Airframe INSPECTION #1227	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-02-01-901 Airframe INSPECTION #372	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL -INTERNAL	07-MAY-2012	H: 12500.00 L: 10000			H: 12500.00 L: 10000	H: 9456.60 L: 7184
53 30-02-01-902 Airframe INSPECTION #80	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-02-01-903 Airframe INSPECTION #622	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-03-01-901 Airframe INSPECTION #1851	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWERSKIN PANEL - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-03-01-902 Airframe INSPECTION #1959	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-04-001 Airframe INSPECTION T 120M/I 60M #954	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 30-04-01-901 Airframe INSPECTION #1895	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-04-01-902 Airframe INSPECTION #533	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-05-02-901 Airframe INSPECTION #872	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL	07-MAY-2012	H: 10000.00 L: 8000			H: 10000.00 L: 8000	H: 6956.60 L: 5184
53 30-06-01-901 Airframe INSPECTION #254	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	07-MAY-2012	H: 12500.00 L: 10000			H: 12500.00 L: 10000	H: 9456.60 L: 7184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-06-01-902 Airframe INSPECTION #1712	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLONCUTOUT STRUCTURES - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-06-01-903 Airframe INSPECTION #1718	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUTSTRUCTURES - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-07-001 Airframe INSPECTION T 120M/I 60M #498	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 30-07-002 Airframe INSPECTION T 120M/I 60M #507	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
53 30-07-01-901 Airframe INSPECTION #220	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICALSTABILIZER CONNECTION - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-07-01-902 Airframe INSPECTION #692	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZERCONNECTION - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
53 30-08-001 Airframe INSPECTION 120M #118	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
53 30-08-002 Airframe INSPECTION T 120M/I 60M #1976	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
54 00-00-001 Airframe INSPECTION 800H #304	GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
54 50-00-001 Airframe INSPECTION T 120M/I 60M #542	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
54 50-00-002 Airframe INSPECTION T 120M/I 60M #287	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
54 50-01-01-901 Airframe INSPECTION #1157	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
54 50-02-01-901 Airframe INSPECTION #1442	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
54 50-03-001 Airframe INSPECTION 60M #422	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
54 50-03-01-901 Airframe INSPECTION #325	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX -EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
54 50-03-01-902 Airframe INSPECTION #272	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
54 50-04-01-901 Airframe INSPECTION #246	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
54 50-05-001 Airframe INSPECTION 120M #1755	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
54 50-05-01-901 Airframe INSPECTION #394	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL	07-MAY-2012	H: 15000.00 L: 12000			H: 15000.00 L: 12000	H: 11956.60 L: 9184
54 50-05-02-901 Airframe INSPECTION #1349	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
54 50-06-01-901 Airframe INSPECTION #598	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL	07-MAY-2012	H: 15000.00 L: 12000			H: 15000.00 L: 12000	H: 11956.60 L: 9184
54 50-06-01-902 Airframe INSPECTION #674	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL	07-MAY-2012	H: 15000.00 L: 12000			H: 15000.00 L: 12000	H: 11956.60 L: 9184
55 00-00-001 Airframe INSPECTION 800H #1713	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
55 10-00 Airframe PART #1491	HORIZONTAL STABILIZER (COMPLETION) Part Number 505-10700-413 Serial Number 0000701643	07-MAY-2012					
55 10-00-001 Airframe INSPECTION 60M #500	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 10-00-002 Airframe INSPECTION 60M #688	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 10-01-001 Airframe INSPECTION 120M #678	GVI - EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS Reference Number NDT PART 5 TASK 55-10-00- 212-851-A	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-01-01-901 Airframe INSPECTION #1603	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS INHORIZONTAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-02-01-901 Airframe INSPECTION #1929	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTALSTABILIZER FRONT AND REAR SPARS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-02-01-902 Airframe INSPECTION #1093	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REARSPARS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-03-001 Airframe INSPECTION 120M #1352	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 10-03-002 Airframe INSPECTION 120M #531	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN Reference Number NDT PART 5 TASK 55-10-00- 290-852-A	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 10-03-01-901 Airframe INSPECTION #1676	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAINBOX UPPER AND LOWER SKIN - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-03-01-902 Airframe INSPECTION #1736	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWERSKIN - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-04-01-901 Airframe INSPECTION #839	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZERCOMPOSITE RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-05-001 Airframe INSPECTION T 120M/I 60M #285	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-05-01-901 Airframe INSPECTION #955	SPECIAL DETAILED INSPECTION (BOREScope) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-05-02-901 Airframe INSPECTION #1769	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-05-02-902 Airframe INSPECTION #628	SPECIAL DETAILED INSPECTION (BOREScope) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-05-03-901 Airframe INSPECTION #851	SPECIAL DETAILED INSPECTION (BOREScope) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-05-04-901 Airframe INSPECTION #399	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-05-05-901 Airframe INSPECTION #787	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-07-01-901 Airframe INSPECTION #1314	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-08-001 Airframe INSPECTION 120M #570	GVI - EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS Reference Number NDT PART 5 TASK 55-10-00- 212-852-A	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 10-08-01-901 Airframe INSPECTION #1136	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-09-001 Airframe INSPECTION 120M #758	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 10-09-01-901 Airframe INSPECTION #892	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITECOMMAND BOX - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-09-01-902 Airframe INSPECTION #818	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITECOMMAND BOX - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 10-10-001 Airframe INSPECTION T 120M/I 60M #1115	EXTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR TRIM-TAB FITTINGS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 10-10-01-901 Airframe INSPECTION #301	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORTFITTINGS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 20-01-002 Airframe INSPECTION 120M #734	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 20-01-01-901 Airframe INSPECTION #1326	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 20-01-01-902 Airframe INSPECTION #1285	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE.ELEVATOR MAIN BOX - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 20-02-01-901 Airframe INSPECTION #413	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 20-02-02-901 Airframe INSPECTION #337	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 20-03-001 Airframe INSPECTION 120M #564	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 20-03-01-901 Airframe INSPECTION #998	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUETUBE ASSY - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 20-03-02-901 Airframe INSPECTION #877	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 20-04-001 Airframe INSPECTION #1168	GVI - INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS	18-APR-2024 H: 2895.60 L: 2711	M: 60			18-APR-2029	M: 44 D: 20
	Notes TASKS WERE INCLUDED PER ANAC AD 2020-01-01 AND FAA AD 2020-12-08.						
55 20-04-002 Airframe INSPECTION #854	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS	18-APR-2024 H: 2895.60 L: 2711	M: 60			18-APR-2029	M: 44 D: 20
	Notes TASKS WERE INCLUDED PER ANAC AD 2020-01-01 AND FAA AD 2020-12-08.						
55 22-00-001 Airframe INSPECTION T 120M/I 60M #867	DET - EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 30-00 Airframe PART #215	VERTICAL STABILIZER	07-MAY-2012					
	Part Number 505-10100-413	Serial Number 0000702272					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-01-001 Airframe INSPECTION 120M #951	DET - EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER Reference Number NDT PART 5 TASK 55-30-00-214-851-A	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 30-01-002 Airframe INSPECTION T 120M/I 60M #1813	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 30-01-01-901 Airframe INSPECTION #1720	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICALSTABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-01-02-901 Airframe INSPECTION #1197	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGEATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-01-03-901 Airframe INSPECTION #1298	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-01-04-901 Airframe INSPECTION #1105	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICALSTABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-02-002 Airframe INSPECTION 120M #804	DET - INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER Reference Number NDT PART 5 TASK 55-30-00-213-852-A	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 30-02-01-901 Airframe INSPECTION #1630	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZERATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-02-03-901 Airframe INSPECTION #1506	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICALSTABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-02-04-901 Airframe INSPECTION #1569	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-02-05-901 Airframe INSPECTION #1602	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-02-06-901 Airframe INSPECTION #1030	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-02-07-901 Airframe INSPECTION #1950	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-03-001 Airframe INSPECTION 120M #743	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 30-03-002 Airframe INSPECTION 120M #1719	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 30-03-01-901 Airframe INSPECTION #1936	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-03-01-902 Airframe INSPECTION #1690	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-04-001 Airframe INSPECTION 60M #1678	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-04-01-901 Airframe INSPECTION #1753	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-05-002 Airframe INSPECTION 60M #700	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 30-05-01-901 Airframe INSPECTION #1907	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 30-06-001 Airframe INSPECTION T 120M/I 60M #1933	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
55 30-06-01-901 Airframe INSPECTION #635	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 40-01-002 Airframe INSPECTION 120M #659	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 40-01-01-901 Airframe INSPECTION #130	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 40-01-01-902 Airframe INSPECTION #850	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 40-02-001 Airframe INSPECTION 120M #1605	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 40-02-01-901 Airframe INSPECTION #273	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 40-02-02-901 Airframe INSPECTION #1654	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 40-03-001 Airframe INSPECTION 120M #1499	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
55 40-03-01-901 Airframe INSPECTION #1656	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
55 40-04-002 Airframe INSPECTION #2107	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS Reference Number NDT PART 5 TASK 55-40-00-211-851-A Notes TASKS WERE INCLUDED PER ANAC AD 2020-01-01 AND FAA AD 2020-12-08.	18-APR-2024 H: 2895.60 L: 2711	M: 60			18-APR-2029	M: 44 D: 20
55 40-04-003 Airframe INSPECTION #2108	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS Reference Number NDT PART 5 TASK 55-40-00-290-852-A Notes TASKS WERE INCLUDED PER ANAC AD 2020-01-01 AND FAA AD 2020-12-08.	18-APR-2024 H: 2895.60 L: 2711	M: 60			18-APR-2029	M: 44 D: 20
55 42-00-001 Airframe INSPECTION T 120M/I 60M #900	DET - EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 10-00 Airframe PART #1724	LEFT GLASS, HEATED WINDSHIELD Part Number NP-195301-3 Serial Number 11332H908 1	07-MAY-2012					
56 10-00 Airframe PART #453	RIGHT GLASS, HEATED WINDSHIELD Part Number NP-195301-4 Serial Number 11336H963 7	07-MAY-2012					
56 10-01-001 Airframe INSPECTION 60M #318	GVI - EXTERNAL GENERAL VISUAL INSPECTION OF SIDE WINDOW	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
56 10-01-002 Airframe INSPECTION RHWIND, LHWIND #1746	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS Part Number NP-195301-3 Serial Number 11332H908 1 Notes NOTE: THRESHOLD IS APPLICABLE AFTER WINDSHIELD/SIDE WINDOW INSTALLATION	18-APR-2019 H: 2052.70 L: 2048	H: 1600.00	H: 30.00		H: 3652.70	H: 609.30
56 10-03-001 Airframe INSPECTION T 120M/I 60M, LHSIDEWIN #1150	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
56 10-03-001 Airframe INSPECTION T 120M/I 60M, RHSIDEWIN #68	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
56 10-03-001 Airframe INSPECTION T 120M/I 60M, LHWIND #656	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE Part Number NP-195301-3 Serial Number 11332H908 1	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
56 10-03-001 Airframe INSPECTION T 120M/I 60M, RHWIND #186	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 10-03-01-901 Airframe INSPECTION #1696	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME ANDFASTENERS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
56 12-00 Airframe PART #72	LEFT ACRYLIC SIDE WINDOW Part Number NP-195302-3 Serial Number 11168H174 6	07-MAY-2012					
56 12-00 Airframe PART #721	RIGHT ACRYLIC SIDE WINDOW Part Number NP-195302-4 Serial Number 11292H485 0	07-MAY-2012					
56 20-00 Airframe PART #1461	NO. 1 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1540528	07-MAY-2012					
56 20-00 Airframe PART #1952	NO. 10 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639314	07-MAY-2012					
56 20-00 Airframe PART #462	NO. 11 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639315	07-MAY-2012					
56 20-00 Airframe PART #446	NO. 2 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1542889	07-MAY-2012					
56 20-00 Airframe PART #1732	NO. 3 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639231	07-MAY-2012					
56 20-00 Airframe PART #1920	NO. 4 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639233	07-MAY-2012					
56 20-00 Airframe PART #1353	NO. 5 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639234	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 20-00 Airframe PART #610	NO. 6 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639235	07-MAY-2012					
56 20-00 Airframe PART #244	NO. 7 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639239	07-MAY-2012					
56 20-00 Airframe PART #1240	NO. 8 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639240	07-MAY-2012					
56 20-00 Airframe PART #34	NO. 9 WINDOW TRANSPARENCY Part Number 14024 Serial Number 1639248	07-MAY-2012					
56 20-01-001 Airframe INSPECTION 60M #764	EXTERNAL GENERAL VISUAL INSPECTION OF THE PASSENGER WINDOW PANELS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 00-00-001 Airframe INSPECTION 800H #1292	GENERAL VISUAL INSPECTION OF OF WINGLET POLYURETHANE FILMS	18-JUL-2022 H: 2611.00 L: 2496	H: 800.00	H: 30.00		H: 3411.00	H: 367.60
57 10-00-001 Airframe INSPECTION T 120M/I 60M #1388	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 10-00-002 Airframe INSPECTION 120M #543	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF WING CENTER UPPER SKIN	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
57 10-01-001 Airframe INSPECTION 120M #1951	DET - EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-01-01-901 Airframe INSPECTION #964	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-02-002 Airframe INSPECTION T 120M/I 60M #849	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 10-02-01-901 Airframe INSPECTION #1135	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-03-002 Airframe INSPECTION T 120M/I 60M #1225	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 10-03-01-901 Airframe INSPECTION #957	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REARSPAR - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-04-002 Airframe INSPECTION 60M #1625	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 10-04-01-901 Airframe INSPECTION #1590	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-05-01-901 Airframe INSPECTION #1623	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-06-001 Airframe INSPECTION 120M #1031	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-07-001 Airframe INSPECTION 60M #1040	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 10-07-01-901 Airframe INSPECTION #981	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-07-01-902 Airframe INSPECTION #651	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-08-01-901 Airframe INSPECTION #902	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-08-02-901 Airframe INSPECTION #1795	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-11-001 Airframe INSPECTION 60M #1513	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 10-11-01-901 Airframe INSPECTION #1185	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRALSPLICES - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-11-01-902 Airframe INSPECTION #386	SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRALSPLICES - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 10-12-01-901 Airframe INSPECTION #187	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL	07-MAY-2012					
	Notes EFFECTIVITY SN 505-00004 ONLY THRESHOLD INTERVAL IS 12500 FLIGHT HOURS AND 10000 LANDINGS						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-01-001 Airframe INSPECTION 60M #126	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 50-01-01-901 Airframe INSPECTION #1250	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-01-01-902 Airframe INSPECTION #1261	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL	07-MAY-2012	H: 11250.00 L: 9000			H: 11250.00 L: 9000	H: 8206.60 L: 6184
57 50-01-02-901 Airframe INSPECTION #1424	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-01-03-901 Airframe INSPECTION #420	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-01-04-901 Airframe INSPECTION #1355	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-01-05-901 Airframe INSPECTION #205	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-01-05-902 Airframe INSPECTION #1140	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-02-001 Airframe INSPECTION 60M #368	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-02-01-901 Airframe INSPECTION #930	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-02-01-902 Airframe INSPECTION #1871	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-02-02-901 Airframe INSPECTION #1389	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 50-02-02-902 Airframe INSPECTION #460	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 52-00-001 Airframe INSPECTION T 120M/I 60M #1018	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 52-00-002 Airframe INSPECTION 60M #1660	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 52-01-01-901 Airframe INSPECTION #617	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE- INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 52-01-01-902 Airframe INSPECTION #234	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 52-02-01-901 Airframe INSPECTION #1704	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 52-03-01-901 Airframe INSPECTION #799	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL	07-MAY-2012	H: 11250.00 L: 9000			H: 11250.00 L: 9000	H: 8206.60 L: 6184
57 52-04-01-901 Airframe INSPECTION #1297	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORTFITTING - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 52-04-02-901 Airframe INSPECTION #442	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATORSUPPORT FITTING - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-00-001 Airframe INSPECTION 120M #231	SDI - SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE OUTBOARD FLAP	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
57 53-00-002 Airframe INSPECTION 60M #824	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 53-01-01-901 Airframe INSPECTION #209	SPECIAL DETAILED INSPECTION (BOREScope) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITESTRUCTURE - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-01-01-902 Airframe INSPECTION #147	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-02-01-901 Airframe INSPECTION #848	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-03-01-901 Airframe INSPECTION #1413	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL	07-MAY-2012	H: 11250.00 L: 9000			H: 11250.00 L: 9000	H: 8206.60 L: 6184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 53-04-01-901 Airframe INSPECTION #919	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-04-02-901 Airframe INSPECTION #942	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-04-03-901 Airframe INSPECTION #1050	SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 53-04-04-901 Airframe INSPECTION #279	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 60-00-001 Airframe INSPECTION #1914	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON	18-APR-2024 H: 2895.60 L: 2711	M: 60			18-APR-2029	M: 44 D: 20
	Notes TASKS WERE INCLUDED PER ANAC AD 2020-01-01 AND FAA AD 2020-12-08.						
57 60-00-002 Airframe INSPECTION 60M #15	SDI - SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF AILERON AND TAB	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
57 60-01-01-901 Airframe INSPECTION #1375	SPECIAL DETAILED INSPECTION (BOREScope) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX -INTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 60-01-01-902 Airframe INSPECTION #79	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 60-01-02-901 Airframe INSPECTION #13	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 60-02-01-901 Airframe INSPECTION #117	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 60-02-02-901 Airframe INSPECTION #782	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL	07-MAY-2012	H: 17500.00 L: 14000			H: 17500.00 L: 14000	H: 14456.60 L: 11184
57 70-02-001 Airframe INSPECTION 60M #217	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
60 8858 Airframe PART #2219	TEMPORARY REPAIR OF FWD BELLY FAIRING 191AL SEAL Part Number 505-37040-907 Serial Number NSN	07-DEC-2022 H: 2676.10 L: 2553					
	Notes PERMANANT REPAIR PERFORMED, NO FURTHER ACTION REQUIRED						
70 0010 Engine 1 INSPECTION #267	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION	30-DEC-2011					
70 0010 Engine 2 INSPECTION #282	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION	20-JAN-2012					
71 Engine 1 INSPECTION #378	PERFORM ENGINE PRESERVATION GROUND RUN	08-AUG-2019 H: 2081.60 C: 2076					
71 Engine 2 INSPECTION #378	PERFORM ENGINE PRESERVATION GROUND RUN	08-AUG-2019 H: 2081.60 C: 2076					
71 00-00-160-805 Engine 1 INSPECTION #33	NO. 1 ENGINE - PERFORM COMPRESSOR WASH (DESALINATION OR PERFORMANCE RECOVERY)	18-JUL-2022 H: 2611.00 C: 2496					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 00-00-160-805 Engine 2 INSPECTION #120	NO. 2 ENGINE - PERFORM COMPRESSOR WASH (DESALINATION OR PERFORMANCE RECOVERY)	18-JUL-2022 H: 2611.00 C: 2496					
71 00-00-760-810 Engine 1 INSPECTION #113	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	18-JUL-2022 H: 2611.00 C: 2496					
71 00-00-760-810 Engine 2 INSPECTION #209	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	18-JUL-2022 H: 2611.00 C: 2496					
71 00-00-760-823 Engine 1 INSPECTION #29	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	18-APR-2024 H: 2895.60 C: 2711	M: 12 H: 630.00	D: 30 H: 63.00		18-APR-2025 H: 3525.60	M: -3 D: -11 H: 482.20
71 00-00-760-823 Engine 2 INSPECTION #29	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	18-APR-2024 H: 2895.60 C: 2711	M: 12 H: 630.00	D: 30 H: 63.00		18-APR-2025 H: 3525.60	M: -3 D: -11 H: 482.20
71 11-00-001 Airframe INSPECTION 5600H #1432	GENERAL VISUAL INSPECTION OF UPPER MID COWL	07-MAY-2012	H: 5600.00	H: 30.00		H: 5600.00	H: 2556.60
71 20-00 Airframe PART #1888	LEFT AFT ENGINE MOUNT ISOLATOR Part Number LM-475-SA4 Serial Number LK0372	07-MAY-2012					
71 20-00 Airframe PART #106	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR Part Number LM-475-SA3 Serial Number LK0666	07-MAY-2012					
71 20-00 Airframe PART #267	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR Part Number LM-475-SA3 Serial Number LK0679	07-MAY-2012					
71 20-00 Airframe PART #111	RIGHT AFT ENGINE MOUNT ISOLATOR Part Number LM-475-SA4 Serial Number LK0436	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 20-00 Airframe PART #10	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR Part Number LM-475-SA3 Serial Number LK0623	07-MAY-2012					
71 20-00 Airframe PART #1787	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR Part Number LM-475-SA3 Serial Number LK0710	07-MAY-2012					
71 21-01-01-901 Airframe INSPECTION #1418	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY	07-MAY-2012	H: 7500.00 L: 6000			H: 7500.00 L: 6000	H: 4456.60 L: 3184
71 22-01-01-901 Airframe INSPECTION #1800	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL	07-MAY-2012	H: 4500.00 L: 3600			H: 4500.00 L: 3600	H: 1456.60 L: 784
71 22-01-01-902 Airframe INSPECTION #1149	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY	07-MAY-2012	H: 7500.00 L: 6000			H: 7500.00 L: 6000	H: 4456.60 L: 3184
71 31-00-001 Airframe INSPECTION 2400H #852	DETAILED INSPECTION OF PYLON FIREWALL SEAL	04-MAY-2021 H: 2376.70 L: 2304	H: 2400.00	H: 30.00		H: 4776.70	H: 1733.30
71 60-01 Airframe PART #1653	LEFT ENGINE AIR INLET Part Number 505-43420-403 Serial Number CPI-159	26-AUG-2015 H: 909.40 L: 989					
71 60-01 Airframe PART #571	RIGHT ENGINE AIR INLET Part Number 505-43430-403 Serial Number CPI-175	26-AUG-2015 H: 909.40 L: 989					
71 70-00-00-200-801 Engine 1 INSPECTION #233	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	30-DEC-2011					
71 70-00-00-200-801 Engine 2 INSPECTION #187	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 72-00-02-810-801 Engine 1 INSPECTION #149	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	18-APR-2024 H: 2895.60 C: 2711	M: 12 H: 630.00			18-APR-2025 H: 3525.60	M: -3 D: -11 H: 482.20
71 72-00-02-810-801 Engine 2 INSPECTION #255	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	18-APR-2024 H: 2895.60 C: 2711	M: 12 H: 630.00			18-APR-2025 H: 3525.60	M: -3 D: -11 H: 482.20
71 EN1 Airframe PART #396	NO. 1 ENGINE Part Number 3072913-01 Serial Number PCE-DG0190						
71 EN2 Airframe PART #181	NO. 2 ENGINE Part Number 3072913-01 Serial Number PCE-DG0194						
72 Engine 1 PART #406	FUEL CONTROL GEAR SHAFT Part Number 3134292 Serial Number SN UNKNOWN	31-JAN-2020					
72 00-00-212-801 Engine 1 INSPECTION 1E 800H/12M #46	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-801 Engine 2 INSPECTION 2E 800H/12M #367	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-802 Engine 1 INSPECTION 1E 800H/12M #352	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-802 Engine 2 INSPECTION 2E 800H/12M #85	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 00-00-212-803 Engine 1 INSPECTION 1E 800H/12M #179	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-803 Engine 2 INSPECTION 2E 800H/12M #158	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-804 Engine 1 INSPECTION 1E 800H/12M #98	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-804 Engine 2 INSPECTION 2E 800H/12M #148	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-805 Engine 1 INSPECTION 1E 800H/12M #348	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-805 Engine 2 INSPECTION 2E 800H/12M #279	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-806 Engine 1 INSPECTION 1E 800H/12M #87	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-806 Engine 2 INSPECTION 2E 800H/12M #318	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-807 Engine 1 INSPECTION 1E 800H/12M #93	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 00-00-212-807 Engine 2 INSPECTION 2E 800H/12M #319	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-808 Engine 1 INSPECTION 1E 800H/12M #194	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-808 Engine 2 INSPECTION 2E 800H/12M #151	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-809 Engine 1 INSPECTION 1E 800H/12M #158	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-212-809 Engine 2 INSPECTION 2E 800H/12M #107	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-280-820 Engine 1 INSPECTION 1E 800H/12M #8	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-280-820 Engine 2 INSPECTION 2E 800H/12M #128	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
72 00-00-640-802 Engine 1 INSPECTION #120	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL (DAILY/PREFLIGHT)	10-MAY-2018 H: 1776.00 C: 1789					
72 00-00-640-802 Engine 2 INSPECTION #51	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL (DAILY/PREFLIGHT)	10-MAY-2018 H: 1776.00 C: 1789					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 00-00-640-806 Engine 1 INSPECTION #379	OIL CHANGE INTERVAL						
	Notes OIL QUALITY IS TO BE MONITORED ON-CONDITION AND ANALYZED PERIODICALLY AS OBSERVATIONS WARRANT						
72 00-00-640-806-01 Engine 2 INSPECTION #379	OIL CHANGE INTERVAL						
	Notes OIL QUALITY IS TO BE MONITORED ON-CONDITION AND ANALYZED PERIODICALLY AS OBSERVATIONS WARRANT						
72 00-34-030-802 Engine 1 INSPECTION ENG 1 OH #418	DISCARD GAS GENERATOR CASE		C: 10000			C: 10000.00	C: 7184
	Notes PRE-SB 30556						
72 00-34-030-802 Engine 2 INSPECTION ENG 2 OH #417	DISCARD GAS GENERATOR CASE		C: 10000			C: 10000.00	C: 7184
	Notes PRE-SB 30556						
72 00-51-030-002 Engine 1 INSPECTION ENG 1 OH #431	DISCARD HP TURBINE NUT AND KEYWASHER		H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 00-51-030-002 Engine 2 INSPECTION ENG 2 OH #430	DISCARD HP TURBINE NUT AND KEYWASHER		H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0001 Engine 1 INSPECTION ENG 1 OH #396	FUEL METERING UNIT	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 1. THE ACCESSORIES HAVE THE SAME TBO AS THE ENGINE. IF THE ACCESSORIES WAS REPLACED SINCE LAST ENGINE OVERHAUL, IT CAN CONTINUE IN SERVICE PER OPERATOR DECISION AND IT MUST OBEY THE CONDITIONS THAT FOLLOW: A. THE ACCESSORIES ARE OPERATING CORRECTLY AT THE ENGINE REMOVAL FOR OVERHAUL. B. THE ACCESSORY REMAINING TIME (RUN TIME) MUST LET THE ENGINE REACH THE NEXT SCHEDULED MAINTENANCE EVENT (RECOMMENDED HSI) NOTE: 2. PROVIDING THE ACCESSORY WAS OPERATING CORRECTLY AT ENGINE REMOVAL, DO A GENERAL VISUAL INSPECTION. IF THE ACCESSORY IS REPORTED AS ALFUNCTIONING, EXAMINE AND TEST PER CMM. NOTE 3						
72 0001 Engine 2 INSPECTION ENG 2 OH #399	FUEL METERING UNIT	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 1. THE ACCESSORIES HAVE THE SAME TBO AS THE ENGINE. IF THE ACCESSORIES WAS REPLACED SINCE LAST ENGINE OVERHAUL, IT CAN CONTINUE IN SERVICE PER OPERATOR DECISION AND IT MUST OBEY THE CONDITIONS THAT FOLLOW: A. THE ACCESSORIES ARE OPERATING CORRECTLY AT THE ENGINE REMOVAL FOR OVERHAUL. B. THE ACCESSORY REMAINING TIME (RUN TIME) MUST LET THE ENGINE REACH THE NEXT SCHEDULED MAINTENANCE EVENT (RECOMMENDED HSI) NOTE: 2. PROVIDING THE ACCESSORY WAS OPERATING CORRECTLY AT ENGINE REMOVAL, DO A GENERAL VISUAL INSPECTION. IF THE ACCESSORY IS REPORTED AS ALFUNCTIONING, EXAMINE AND TEST PER CMM. NOTE 3						
72 0002 Engine 1 INSPECTION ENG 1 OH #385	OVERHAUL OR REFURBISH FUEL-TO-OIL HEAT EXCHANGER (FOHE)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes REF CMM						
72 0002 Engine 2 INSPECTION ENG 2 OH #383	OVERHAUL OR REFURBISH FUEL-TO-OIL HEAT EXCHANGER (FOHE)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes REF CMM						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0003 Engine 1 INSPECTION ENG 1 OH #395	OVERHAUL OR REFURBISH FUEL NOZZLES	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes REF CMM						
72 0003 Engine 2 INSPECTION ENG 2 OH #382	OVERHAUL OR REFURBISH FUEL NOZZLES	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes REF CMM						
72 0004 Engine 1 INSPECTION ENG 1 OH #401	EXAMINE AND DO A FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes REF CMM						
72 0004 Engine 2 INSPECTION ENG 2 OH #389	EXAMINE AND DO A FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes REF CMM						
72 0005 Engine 1 INSPECTION ENG 1 OH #394	EXAMINE PER CIR FUEL MANIFOLD TRANSFER TUBES	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0005 Engine 2 INSPECTION ENG 2 OH #385	EXAMINE PER CIR FUEL MANIFOLD TRANSFER TUBES	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0006 Engine 1 INSPECTION ENG 1 OH, 1 FUELFILTER #399	EXAMINE AND REPLACE FUEL FILTER	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Part Number PN UNKNOWN	Serial Number SN UNKNOWN					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0006 Engine 2 INSPECTION ENG 2 OH, 2 FUELFILTER #391	EXAMINE AND REPLACE FUEL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0007 Engine 1 INSPECTION ENG 1 OH #403	EXAMINE PER CIR FUEL SHUT-OFF CABLE	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0007 Engine 2 INSPECTION ENG 2 OH #390	EXAMINE PER CIR FUEL SHUT-OFF CABLE	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0008 Engine 1 INSPECTION ENG 1 OH #383	EXAMINE AND DO A FUNCTIONAL TEST PER CMM ENGINE WIRING HARNESS Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0008 Engine 2 INSPECTION ENG 2 OH #392	EXAMINE AND DO A FUNCTIONAL TEST PER CMM ENGINE WIRING HARNESS Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0009 Engine 1 INSPECTION ENG 1 OH #392	CLEAN AND EXAMINE IGNITION EXCITER BOX Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0009 Engine 2 INSPECTION ENG 2 OH #398	CLEAN AND EXAMINE IGNITION EXCITER BOX	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.							
72 0010 Engine 1 INSPECTION ENG 1 OH #393	EXAMINE IGNITION CABLES	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.							
72 0010 Engine 2 INSPECTION ENG 2 OH #388	EXAMINE IGNITION CABLES	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.							
72 0011 Engine 1 INSPECTION ENG 1 OH #382	EXAMINE P3 AIR INERTIAL SEPARATOR	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.							
72 0011 Engine 2 INSPECTION ENG 2 OH #393	EXAMINE P3 AIR INERTIAL SEPARATOR	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.							
72 0012 Engine 1 INSPECTION ENG 1 OH #386	EXAMINE PER CIR COMPRESSOR AIR BLEED VALVE	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0012 Engine 2 INSPECTION ENG 2 OH #386	EXAMINE PER CIR COMPRESSOR AIR BLEED VALVE	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0013 Engine 1 INSPECTION ENG 1 OH #391	REPLACE WITH NEW - BOV TORQUE MOTOR (REF. NOTE 1)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 1. THE ACCESSORIES HAVE THE SAME TBO AS THE ENGINE. IF THE ACCESSORY WAS REPLACED SINCE LAST ENGINE OVERHAUL, IT CAN CONTINUE IN SERVICE PER OPERATOR DECISION AND IT MUST OBEY THE CONDITIONS THAT FOLLOW: A. THE ACCESSORY IS OPERATING CORRECTLY AT THE ENGINE REMOVAL FOR OVERHAUL. B. THE ACCESSORY REMAINING TIME (RUN TIME) MUST LET THE ENGINE REACH THE NEXT SCHEDULED MAINTENANCE EVENT (RECOMMENDED HSI).						
72 0013 Engine 2 INSPECTION ENG 2 OH #387	REPLACE WITH NEW - BOV TORQUE MOTOR (REF. NOTE 1)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 1. THE ACCESSORIES HAVE THE SAME TBO AS THE ENGINE. IF THE ACCESSORY WAS REPLACED SINCE LAST ENGINE OVERHAUL, IT CAN CONTINUE IN SERVICE PER OPERATOR DECISION AND IT MUST OBEY THE CONDITIONS THAT FOLLOW: A. THE ACCESSORY IS OPERATING CORRECTLY AT THE ENGINE REMOVAL FOR OVERHAUL. B. THE ACCESSORY REMAINING TIME (RUN TIME) MUST LET THE ENGINE REACH THE NEXT SCHEDULED MAINTENANCE EVENT (RECOMMENDED HSI).						
72 0014 Engine 1 INSPECTION ENG 1 OH #389	LINEAR VARIABLE DIFFERENTIAL TRANSFORMER	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 2. PROVIDING THE ACCESSORY WAS OPERATING CORRECTLY AT ENGINE REMOVAL, DO A GENERAL VISUAL INSPECTION. IF THE ACCESSORY IS REPORTED AS MALFUNCTIONING, EXAMINE AND TEST PER CMM. NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.						
72 0014 Engine 2 INSPECTION ENG 2 OH #400	LINEAR VARIABLE DIFFERENTIAL TRANSFORMER	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 2. PROVIDING THE ACCESSORY WAS OPERATING CORRECTLY AT ENGINE REMOVAL, DO A GENERAL VISUAL INSPECTION. IF THE ACCESSORY IS REPORTED AS MALFUNCTIONING, EXAMINE AND TEST PER CMM. NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0015 Engine 1 INSPECTION ENG 1 OH #400	EXAMINE AND DO A FUNCTIONAL CHECK T6 WIRING HARNESS AND THERMOCOUPLES (PRE SB 30536)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0015 Engine 2 INSPECTION ENG 2 OH #403	EXAMINE AND DO A FUNCTIONAL CHECK T6 WIRING HARNESS AND THERMOCOUPLES (PRE SB 30536)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0016 Engine 1 INSPECTION ENG 1 OH #384	EXAMINE AND DO A FUNCTIONAL CHECK T6 WIRING HARNESS AND THERMOCOUPLES (POST SB 30536)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0016 Engine 2 INSPECTION ENG 2 OH #397	EXAMINE AND DO A FUNCTIONAL CHECK T6 WIRING HARNESS AND THERMOCOUPLES (POST SB 30536)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0017 Engine 1 INSPECTION ENG 1 OH #402	DATA COLLECTION UNIT	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 2. PROVIDING THE ACCESSORY WAS OPERATING CORRECTLY AT ENGINE REMOVAL, DO A GENERAL VISUAL INSPECTION. IF THE ACCESSORY IS REPORTED AS MALFUNCTIONING, EXAMINE AND TEST PER CMM. NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.						
72 0017 Engine 2 INSPECTION ENG 2 OH #396	DATA COLLECTION UNIT	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
	Notes NOTE: 2. PROVIDING THE ACCESSORY WAS OPERATING CORRECTLY AT ENGINE REMOVAL, DO A GENERAL VISUAL INSPECTION. IF THE ACCESSORY IS REPORTED AS MALFUNCTIONING, EXAMINE AND TEST PER CMM. NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0018 Engine 1 INSPECTION ENG 1 OH #387	EXAMINE AND DO A FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH Notes REF CMM	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0018 Engine 2 INSPECTION ENG 2 OH #395	EXAMINE AND DO A FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH Notes REF CMM	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0019 Engine 1 INSPECTION ENG 1 OH #388	EXAMINE CHIP DETECTOR/COLLECTOR	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0019 Engine 2 INSPECTION ENG 2 OH #394	EXAMINE CHIP DETECTOR/COLLECTOR	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0020 Engine 1 INSPECTION ENG 1 OH #397	OVERHAUL OR REFURBISH - OIL TANK FILLER CAP (REF. CMM)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0020 Engine 2 INSPECTION ENG 2 OH #402	OVERHAUL OR REFURBISH - OIL TANK FILLER CAP (REF. CMM)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0021 Engine 1 INSPECTION ENG 1 OH #390	INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS) (REF. CIR)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0021 Engine 2 INSPECTION ENG 2 OH #401	INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS) (REF. CIR)	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 0022 Engine 1 INSPECTION ENG 1 OH, 1OILFILTER #398	EXAMINE AND REPLACE OIL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0022 Engine 2 INSPECTION ENG 2 OH, 2OILFILTER #384	EXAMINE AND REPLACE OIL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	07-MAY-2012 H: 0.00	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
72 0050 Engine 1 INSPECTION #82	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	18-JUL-2022 H: 2611.00 C: 2496					
72 0050 Engine 2 INSPECTION #63	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	18-JUL-2022 H: 2611.00 C: 2496					
72 0060 Engine 1 INSPECTION #53	NO. 1 ENGINE - HOT SECTION INSPECTION (HSI)	30-OCT-2021 H: 2496.10 C: 2411	H: 2500.00	H: 50.00		H: 4996.10	H: 1952.70
72 0060 Engine 2 INSPECTION #81	NO. 2 ENGINE - HOT SECTION INSPECTION (HSI)	30-OCT-2021 H: 2496.10 C: 2411	H: 2500.00	H: 50.00		H: 4996.10	H: 1952.70
72 1010 Engine 1 PART #6	NO. 1 ENGINE - GEARBOX Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
72 1010 Engine 2 PART #180	NO. 2 ENGINE - GEARBOX Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
72 2001 Engine 1 PART #70	NO. 1 ENGINE - OIL PUMP Part Number 3073477-02 Serial Number EC01A003A 459	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 2001 Engine 2 PART #103	NO. 2 ENGINE - OIL PUMP Part Number 3073477-02 Serial Number EC01A003A 476	20-JAN-2012					
72 3004 Engine 1 PART - Life Limited #227	NO. 1 ENGINE - LP SHAFT ASSEMBLY Part Number 3073356-01 Serial Number A0032WRW	30-DEC-2011	C: 30000		M: 0 H: 0.00 C: 0	C: 30000.00	C: 27184
72 3004 Engine 2 PART - Life Limited #206	NO. 2 ENGINE - LP SHAFT ASSEMBLY Part Number 3073356-01 Serial Number A003351E	20-JAN-2012	C: 30000		M: 0 H: 0.00 C: 0	C: 30000.00	C: 27184
72 3010 Engine 1 PART - Life Limited #297	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR Part Number 3073311-01 Serial Number A00339XP	30-DEC-2011	C: 15000		M: 0 H: 0.00 C: 0	C: 15000.00	C: 12184
72 3010 Engine 2 PART - Life Limited #258	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR Part Number 3073311-01 Serial Number A0033L3H	20-JAN-2012	C: 15000		M: 0 H: 0.00 C: 0	C: 15000.00	C: 12184
72 3020 Engine 1 PART - Life Limited #260	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR Part Number 3073292-01 Serial Number TXA1C5462	30-DEC-2011	C: 15000		M: 0 H: 0.00 C: 0	C: 15000.00	C: 12184
72 3020 Engine 2 PART - Life Limited #239	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR Part Number 3073292-01 Serial Number TXA1C5787	20-JAN-2012	C: 15000		M: 0 H: 0.00 C: 0	C: 15000.00	C: 12184
72 3030 Engine 1 PART - Life Limited #362	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR Part Number 3072981-01 Serial Number A0032E69	30-DEC-2011	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 3030 Engine 2 PART - Life Limited #181	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR Part Number 3072981-01 Serial Number A0033BM1	20-JAN-2012	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 3040 Engine 1 PART - Life Limited #69	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR Part Number 3056210-01 Serial Number EAAC000M 360	30-DEC-2011	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3040 Engine 2 PART - Life Limited #289	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR Part Number 3056210-01 Serial Number EAAC000A 575	20-JAN-2012	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 3050 Engine 1 PART #346	NO. 1 ENGINE - FAN CASE ASSEMBLY Part Number 3074676-01 Serial Number EDA01145T	30-DEC-2011					
72 3050 Engine 2 PART #22	NO. 2 ENGINE - FAN CASE ASSEMBLY Part Number 3074676-01 Serial Number EDA01156K	20-JAN-2012					
72 3060 Engine 1 PART #324	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY ROLLER CYLINDRICAL BEARING Part Number 3052663-02 Serial Number FCN316435	30-DEC-2011					
72 3060 Engine 2 PART #223	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY ROLLER CYLINDRICAL BEARING Part Number 3071049-01 Serial Number FAA111495 2	20-JAN-2012					
72 3070 Engine 1 PART #356	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY Part Number 3075850-01 Serial Number A003420R	30-DEC-2011					
72 3070 Engine 2 PART #238	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY Part Number 3075850-01 Serial Number A003456P	20-JAN-2012					
72 3080 Engine 1 PART #83	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY Part Number 3076150-01 Serial Number RWA56D54 5	30-DEC-2011					
72 3080 Engine 2 PART #115	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY Part Number 3076150-01 Serial Number RWA57D58 1	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3090 Engine 1 PART #97	NO. 1 ENGINE - GAS GENERATOR DIFFUSER Part Number 3073236-01 Serial Number A0033W87	30-DEC-2011					
72 3090 Engine 2 PART #132	NO. 2 ENGINE - GAS GENERATOR DIFFUSER Part Number 3073236-01 Serial Number A003480W	20-JAN-2012					
72 3095 Engine 1 PART #283	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT Part Number 3052673-01 Serial Number PKAAA4045 62	30-DEC-2011					
72 3095 Engine 2 PART #278	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT Part Number 3052673-01 Serial Number PKAAA4131 05	20-JAN-2012					
72 3110 Engine 1 PART #15	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER Part Number 3052668-01 Serial Number AFD00H319	30-DEC-2011					
72 3110 Engine 2 PART #45	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER Part Number 3052668-01 Serial Number AFD00H483	20-JAN-2012					
72 3120 Engine 1 PART #61	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER Part Number 3072571-01 Serial Number UAAA3909	30-DEC-2011					
72 3120 Engine 2 PART #182	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER Part Number 3072571-01 Serial Number UAAA3908	20-JAN-2012					
72 3130 Engine 1 PART #36	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER Part Number 3072572-01 Serial Number AWE01402 6	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3130 Engine 2 PART #131	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER Part Number 3072572-01 Serial Number UAAB822	20-JAN-2012					
72 3140 Engine 1 PART #246	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING Part Number 3052737-01 Serial Number LPA000010 65	30-DEC-2011					
72 3140 Engine 2 PART #232	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING Part Number 3052737-01 Serial Number LPA000010 670	20-JAN-2012					
72 3150 Engine 1 PART #306	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR Part Number 3072574-01 Serial Number EAAC000M 169	30-DEC-2011					
72 3150 Engine 2 PART #111	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR Part Number 3072574-01 Serial Number EAAC000M 594	20-JAN-2012					
72 3160 Engine 1 PART #258	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING Part Number 3052670-02 Serial Number FCN338541	30-DEC-2011					
72 3160 Engine 2 PART #326	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING Part Number 3052670-02 Serial Number FCN338509	20-JAN-2012					
72 3170 Engine 1 PART #281	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT Part Number 3072280-01 Serial Number PKAAA4103 81	30-DEC-2011					
72 3170 Engine 2 PART #64	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT Part Number 3072280-01 Serial Number PKAAA4103 90	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3180 Engine 1 PART #125	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
72 3180 Engine 2 PART #1	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
72 3190 Engine 1 PART #182	NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
72 3190 Engine 2 PART #221	NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
72 34-01-040-801 Engine 1 INSPECTION - Life Limited #491	ENG 1 - FOR BS1348 ONLY: DISCARD THE HIGH COMPRESSOR ROTOR (SECOND-STAGE) IF HEAT CODE PREFIX BEGINS WITH 'E'. Reference Number Overhaul Manual, 72-34-01-040-801 Notes IF HIGH COMPRESSOR ROTOR (SECOND-STAGE) HAS ACCUMULATED MORE THAN 4000 HOURS AT A SCHEDULED MAINTENANCE TASK AT AN APPROVED MAINTENANCE FACILITY. DIS						
72 34-01-040-801 Engine 2 INSPECTION #489	ENG 2 - FOR BS1348 ONLY: DISCARD THE HIGH COMPRESSOR ROTOR (SECOND-STAGE) IF HEAT CODE PREFIX BEGINS WITH 'E'. Notes IF HIGH COMPRESSOR ROTOR (SECOND-STAGE) HAS ACCUMULATED MORE THAN 4000 HOURS AT A SCHEDULED MAINTENANCE TASK AT AN APPROVED MAINTENANCE FACILITY.						
72 3705 Engine 1 PART - Life Limited #225	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK Part Number 3053812-01 Serial Number A00339LH	30-DEC-2011	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 3705 Engine 2 PART - Life Limited #304	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK Part Number 3053812-01 Serial Number A003410W	20-JAN-2012	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 3706 Engine 1 PART - Life Limited #89	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK Part Number 3053743-01 Serial Number A0033D5L	30-DEC-2011	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 3706 Engine 2 PART - Life Limited #118	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK Part Number 3053743-01 Serial Number A00337MN	20-JAN-2012	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 4001 Engine 1 PART #111	NO. 1 ENGINE - INNER COMBUSTION LINER Part Number 3075516-01 Serial Number A0032YEL	30-DEC-2011					
72 4001 Engine 2 PART #337	NO. 2 ENGINE - INNER COMBUSTION LINER Part Number 3075516-01 Serial Number A0033DBB	20-JAN-2012					
72 4002 Engine 1 PART #146	NO. 1 ENGINE - OUTER COMBUSTION LINER Part Number 3075522-01 Serial Number A0033BAR	30-DEC-2011					
72 4002 Engine 2 PART #92	NO. 2 ENGINE - OUTER COMBUSTION LINER Part Number 3075522-01 Serial Number A0033FR3	20-JAN-2012					
72 4010 Engine 1 PART #288	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY Part Number 3075468-01 Serial Number ACM221834 132	30-DEC-2011					
72 4010 Engine 2 PART #14	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY Part Number 3075468-01 Serial Number ACM221834 515	20-JAN-2012					
72 4706 Engine 1 PART - Life Limited #103	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK Part Number 3053331-01 Serial Number A00333R9	30-DEC-2011	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 7184
72 4706 Engine 2 PART - Life Limited #292	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK Part Number 3053331-01 Serial Number A00300K5	20-JAN-2012	C: 10000		M: 0 H: 0.00 C: 0	C: 10000.00	C: 7184

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 4825 Engine 1 PART - Life Limited #340	NO. 1 ENGINE - CENTRIFUGAL IMPELLER Part Number 3052661-01 Serial Number A0032TPA	30-DEC-2011	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 4825 Engine 2 PART - Life Limited #164	NO. 2 ENGINE - CENTRIFUGAL IMPELLER Part Number 3052661-01 Serial Number EAAC000M 770	20-JAN-2012	C: 13500		M: 0 H: 0.00 C: 0	C: 13500.00	C: 10684
72 5010 Engine 1 PART #180	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE Part Number 3074951-01 Serial Number HWFN1835	30-DEC-2011					
72 5010 Engine 1 PART #22	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1934	30-DEC-2011					
72 5010 Engine 1 PART #20	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1951	30-DEC-2011					
72 5010 Engine 1 PART #214	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1952	30-DEC-2011					
72 5010 Engine 1 PART #188	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1957	30-DEC-2011					
72 5010 Engine 1 PART #354	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1963	30-DEC-2011					
72 5010 Engine 1 PART #295	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1964	30-DEC-2011					
72 5010 Engine 1 PART #5	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1973	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #102	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1985	30-DEC-2011					
72 5010 Engine 1 PART #79	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1998	30-DEC-2011					
72 5010 Engine 1 PART #325	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2001	30-DEC-2011					
72 5010 Engine 1 PART #21	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE Part Number 3074951-01 Serial Number HWFN1860	30-DEC-2011					
72 5010 Engine 1 PART #192	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2009	30-DEC-2011					
72 5010 Engine 1 PART #187	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2012	30-DEC-2011					
72 5010 Engine 1 PART #10	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2018	30-DEC-2011					
72 5010 Engine 1 PART #17	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2052	30-DEC-2011					
72 5010 Engine 1 PART #203	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2225	30-DEC-2011					
72 5010 Engine 1 PART #200	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2226	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #215	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2236	30-DEC-2011					
72 5010 Engine 1 PART #338	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2240	30-DEC-2011					
72 5010 Engine 1 PART #303	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2249	30-DEC-2011					
72 5010 Engine 1 PART #41	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2255	30-DEC-2011					
72 5010 Engine 1 PART #210	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1872	30-DEC-2011					
72 5010 Engine 1 PART #167	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2266	30-DEC-2011					
72 5010 Engine 1 PART #30	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN2275	30-DEC-2011					
72 5010 Engine 1 PART #328	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP1893	30-DEC-2011					
72 5010 Engine 1 PART #363	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2226	30-DEC-2011					
72 5010 Engine 1 PART #78	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2228	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #255	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2237	30-DEC-2011					
72 5010 Engine 1 PART #337	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2248	30-DEC-2011					
72 5010 Engine 1 PART #271	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2252	30-DEC-2011					
72 5010 Engine 1 PART #104	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2261	30-DEC-2011					
72 5010 Engine 1 PART #341	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2337	30-DEC-2011					
72 5010 Engine 1 PART #366	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1886	30-DEC-2011					
72 5010 Engine 1 PART #316	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP3136	30-DEC-2011					
72 5010 Engine 1 PART #42	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP3142	30-DEC-2011					
72 5010 Engine 1 PART #193	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP3158	30-DEC-2011					
72 5010 Engine 1 PART #119	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFW0396	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #265	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0421	30-DEC-2011					
72 5010 Engine 1 PART #169	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0422	30-DEC-2011					
72 5010 Engine 1 PART #80	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0433	30-DEC-2011					
72 5010 Engine 1 PART #186	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0438	30-DEC-2011					
72 5010 Engine 1 PART #4	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0447	30-DEC-2011					
72 5010 Engine 1 PART #342	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0448	30-DEC-2011					
72 5010 Engine 1 PART #353	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1903	30-DEC-2011					
72 5010 Engine 1 PART #26	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0452	30-DEC-2011					
72 5010 Engine 1 PART #351	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0455	30-DEC-2011					
72 5010 Engine 1 PART #161	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWF0456	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #344	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0463	30-DEC-2011					
72 5010 Engine 1 PART #323	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0467	30-DEC-2011					
72 5010 Engine 1 PART #228	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0468	30-DEC-2011					
72 5010 Engine 1 PART #339	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0469	30-DEC-2011					
72 5010 Engine 1 PART #264	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0471	30-DEC-2011					
72 5010 Engine 1 PART #135	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0474	30-DEC-2011					
72 5010 Engine 1 PART #178	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0475	30-DEC-2011					
72 5010 Engine 1 PART #308	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1906	30-DEC-2011					
72 5010 Engine 1 PART #311	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0482	30-DEC-2011					
72 5010 Engine 1 PART #256	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1912	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #231	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1923	30-DEC-2011					
72 5010 Engine 1 PART #309	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFN1932	30-DEC-2011					
72 5010 Engine 1 PART #176	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0483	30-DEC-2011					
72 5010 Engine 1 PART #202	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0487	30-DEC-2011					
72 5010 Engine 1 PART #221	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0500	30-DEC-2011					
72 5010 Engine 1 PART #277	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0503	30-DEC-2011					
72 5010 Engine 1 PART #72	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0504	30-DEC-2011					
72 5010 Engine 1 PART #261	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0509	30-DEC-2011					
72 5010 Engine 1 PART #320	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0511	30-DEC-2011					
72 5010 Engine 1 PART #312	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0516	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 1 PART #315	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0523	30-DEC-2011					
72 5010 Engine 1 PART #67	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HFWW0524	30-DEC-2011					
72 5010 Engine 2 PART #340	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2245	20-JAN-2012					
72 5010 Engine 2 PART #10	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5096	20-JAN-2012					
72 5010 Engine 2 PART #28	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5097	20-JAN-2012					
72 5010 Engine 2 PART #237	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5098	20-JAN-2012					
72 5010 Engine 2 PART #189	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5100	20-JAN-2012					
72 5010 Engine 2 PART #31	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5102	20-JAN-2012					
72 5010 Engine 2 PART #352	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5105	20-JAN-2012					
72 5010 Engine 2 PART #133	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5108	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #40	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5110	20-JAN-2012					
72 5010 Engine 2 PART #129	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5116	20-JAN-2012					
72 5010 Engine 2 PART #143	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5120	20-JAN-2012					
72 5010 Engine 2 PART #330	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2249	20-JAN-2012					
72 5010 Engine 2 PART #275	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5121	20-JAN-2012					
72 5010 Engine 2 PART #259	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5127	20-JAN-2012					
72 5010 Engine 2 PART #58	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5132	20-JAN-2012					
72 5010 Engine 2 PART #203	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5135	20-JAN-2012					
72 5010 Engine 2 PART #150	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5143	20-JAN-2012					
72 5010 Engine 2 PART #245	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5144	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #224	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5145	20-JAN-2012					
72 5010 Engine 2 PART #301	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5146	20-JAN-2012					
72 5010 Engine 2 PART #146	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5157	20-JAN-2012					
72 5010 Engine 2 PART #268	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5158	20-JAN-2012					
72 5010 Engine 2 PART #315	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2275	20-JAN-2012					
72 5010 Engine 2 PART #96	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5169	20-JAN-2012					
72 5010 Engine 2 PART #70	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5175	20-JAN-2012					
72 5010 Engine 2 PART #36	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5183	20-JAN-2012					
72 5010 Engine 2 PART #265	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5185	20-JAN-2012					
72 5010 Engine 2 PART #74	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5186	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #308	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5187	20-JAN-2012					
72 5010 Engine 2 PART #159	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5194	20-JAN-2012					
72 5010 Engine 2 PART #309	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5195	20-JAN-2012					
72 5010 Engine 2 PART #316	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5197	20-JAN-2012					
72 5010 Engine 2 PART #20	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5200	20-JAN-2012					
72 5010 Engine 2 PART #219	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFP2291	20-JAN-2012					
72 5010 Engine 2 PART #199	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5201	20-JAN-2012					
72 5010 Engine 2 PART #355	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5204	20-JAN-2012					
72 5010 Engine 2 PART #216	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5208	20-JAN-2012					
72 5010 Engine 2 PART #160	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5209	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #176	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5213	20-JAN-2012					
72 5010 Engine 2 PART #174	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5221	20-JAN-2012					
72 5010 Engine 2 PART #293	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5233	20-JAN-2012					
72 5010 Engine 2 PART #327	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5249	20-JAN-2012					
72 5010 Engine 2 PART #360	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5252	20-JAN-2012					
72 5010 Engine 2 PART #306	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5253	20-JAN-2012					
72 5010 Engine 2 PART #363	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5062	20-JAN-2012					
72 5010 Engine 2 PART #272	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5255	20-JAN-2012					
72 5010 Engine 2 PART #274	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5256	20-JAN-2012					
72 5010 Engine 2 PART #99	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5262	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #285	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5264	20-JAN-2012					
72 5010 Engine 2 PART #266	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5266	20-JAN-2012					
72 5010 Engine 2 PART #34	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5270	20-JAN-2012					
72 5010 Engine 2 PART #317	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5272	20-JAN-2012					
72 5010 Engine 2 PART #54	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5276	20-JAN-2012					
72 5010 Engine 2 PART #220	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5280	20-JAN-2012					
72 5010 Engine 2 PART #104	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5284	20-JAN-2012					
72 5010 Engine 2 PART #324	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5078	20-JAN-2012					
72 5010 Engine 2 PART #205	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5285	20-JAN-2012					
72 5010 Engine 2 PART #270	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5089	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #208	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5090	20-JAN-2012					
72 5010 Engine 2 PART #142	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5092	20-JAN-2012					
72 5010 Engine 2 PART #305	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5287	20-JAN-2012					
72 5010 Engine 2 PART #350	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5289	20-JAN-2012					
72 5010 Engine 2 PART #67	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5294	20-JAN-2012					
72 5010 Engine 2 PART #256	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5301	20-JAN-2012					
72 5010 Engine 2 PART #351	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFX5317	20-JAN-2012					
72 5010 Engine 2 PART #87	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFY6561	20-JAN-2012					
72 5010 Engine 2 PART #356	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFY6562	20-JAN-2012					
72 5010 Engine 2 PART #195	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFY6563	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5010 Engine 2 PART #33	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFY6566	20-JAN-2012					
72 5010 Engine 2 PART #123	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE Part Number 3077471-01 Serial Number HWFY6577	20-JAN-2012					
72 5015 Engine 1 PART #13	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING Part Number 3073355-01 Serial Number FCN337966	30-DEC-2011					
72 5015 Engine 2 PART #192	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING Part Number 3073355-01 Serial Number FCN337965	20-JAN-2012					
72 5020 Engine 1 PART #358	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY Part Number 3076552-01 Serial Number RWA54D73 6	30-DEC-2011					
72 5020 Engine 2 PART #83	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY Part Number 3076552-01 Serial Number RWA58D08 3	20-JAN-2012					
72 5025 Engine 1 PART #291	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER Part Number 3073353-01 Serial Number AWE01427 6	30-DEC-2011					
72 5025 Engine 2 PART #347	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER Part Number 3073353-01 Serial Number AWE01428 4	20-JAN-2012					
72 5030 Engine 1 PART #28	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 5030 Engine 2 PART #168	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
72 5035 Engine 1 PART #282	NO. 1 ENGINE - TURBINE (CASTING) VANE RING Part Number 3052361CL01 Serial Number PDAH26CB 01	30-DEC-2011					
72 5035 Engine 2 PART #135	NO. 2 ENGINE - TURBINE (CASTING) VANE RING Part Number 3052361CL01 Serial Number PDAH122W N01	20-JAN-2012					
72 5040 Engine 1 PART #292	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY Part Number 3073262CL02 Serial Number BHEWRAR 01	30-DEC-2011					
72 5040 Engine 2 PART #30	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY Part Number 3073262CL02 Serial Number BHEYCHE0 1	20-JAN-2012					
72 60-01-212-801 Engine 1 INSPECTION #419	INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES Notes EVERY 1200 FLIGHT HOURS.	03-MAY-2023 H: 2749.10 C: 2607	H: 1200.00	H: 100.00		H: 3949.10	H: 905.70
72 60-01-212-801 Engine 2 INSPECTION #418	INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES Notes EVERY 1200 FLIGHT HOURS.	03-MAY-2023 H: 2749.10 C: 2607	H: 1200.00	H: 100.00		H: 3949.10	H: 905.70
72 6010 Engine 1 PART #329	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING Part Number 3052549-01 Serial Number FCN339101	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 6010 Engine 2 PART #217	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING Part Number 3052549-01 Serial Number FCN340960	20-JAN-2012					
72 6020 Engine 1 PART #345	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012521 8	30-DEC-2011					
72 6020 Engine 2 PART #213	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012407 1	20-JAN-2012					
72 6030 Engine 1 PART #301	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012521 9	30-DEC-2011					
72 6030 Engine 2 PART #50	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012407 7	20-JAN-2012					
72 6040 Engine 1 PART #275	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012522 0	30-DEC-2011					
72 6040 Engine 2 PART #325	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012407 9	20-JAN-2012					
72 6050 Engine 1 PART #201	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012522 1	30-DEC-2011					
72 6050 Engine 2 PART #276	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING Part Number 3073908-01 Serial Number AEB012408 3	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 6060 Engine 1 PART #91	NO. 1 ENGINE - ACCESSORY DRIVE ROLLER FLANGED BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
72 6060 Engine 2 PART #124	NO. 2 ENGINE - ACCESSORY DRIVE ROLLER FLANGED BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
72 6070 Engine 1 PART #293	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY Part Number 3072949-01 Serial Number PKAAA3986 39	30-DEC-2011					
72 6070 Engine 2 PART #4	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY Part Number 3072949-01 Serial Number PKAAA3986 31	20-JAN-2012					
72 6080 Engine 1 PART #355	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT Part Number 3072279-01 Serial Number RWA46D37 2	30-DEC-2011					
72 6080 Engine 2 PART #184	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT Part Number 3072279-01 Serial Number RWA53D35 1	20-JAN-2012					
72 6090 Engine 1 PART #185	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING Part Number 3072235-01 Serial Number FAA111213 2	30-DEC-2011					
72 6090 Engine 2 PART #193	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING Part Number 3072235-01 Serial Number FAA080906 8	20-JAN-2012					
72 6110 Engine 1 PART #173	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING Part Number 3052605-01 Serial Number FAA111789 3	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 6110 Engine 2 PART #202	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING Part Number 3052605-01 Serial Number FAA111789 5	20-JAN-2012					
72 6120 Engine 1 PART #279	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
72 6120 Engine 2 PART #201	NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
72 6130 Engine 1 PART #110	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT Part Number 3072282-01 Serial Number PKAAA4068 45	30-DEC-2011					
72 6130 Engine 2 PART #139	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT Part Number 3072282-01 Serial Number PKAAA4124 28	20-JAN-2012					
72 7010 Engine 1 PART #122	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY Part Number 3075013-01 Serial Number KYAA008A9 67	30-DEC-2011					
72 7010 Engine 2 PART #185	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY Part Number 3075013-01 Serial Number KYAA009A0 14	20-JAN-2012					
72 7020 Engine 1 PART #85	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY Part Number 3074835-01 Serial Number KYAA009A0 35	30-DEC-2011					
72 7020 Engine 2 PART #167	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY Part Number 3074835-01 Serial Number KYAA009A0 39	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 793010 Engine 1 PART #196	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
72 793010 Engine 2 PART #312	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
73 10-04-000-801 Engine 1 PART - Life Limited #369	NO. 1 ENGINE - DISCARD THE FUEL MANIFOLD PAD(PRE-SB30539)		C: 9900			C: 9900.00	C: 7084
73 10-04-000-801 Engine 2 PART - Life Limited #369	NO. 2 ENGINE - DISCARD THE FUEL MANIFOLD PAD(PRE-SB30539)		C: 9900			C: 9900.00	C: 7084
73 10-05-000-801 Engine 1 PART - Life Limited #259	NO. 1 ENGINE - DISCARD FUEL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 C: 2496	H: 800.00	H: 80.00	H: 0.00	H: 3411.00	H: 367.60
73 10-05-000-801 Engine 2 PART - Life Limited #42	NO. 2 ENGINE - DISCARD FUEL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 C: 2496	H: 800.00	H: 80.00	H: 0.00	H: 3411.00	H: 367.60
73 10-05-212-801 Engine 1 INSPECTION 1 FUELFILTER #148	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	19-MAY-2025 H: 3019.50 C: 2801	M: 12	D: 30		19-MAY-2026	M: 9 D: 20
73 10-05-212-801 Engine 2 INSPECTION 2 FUELFILTER #214	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	19-MAY-2025 H: 3019.50 C: 2801	M: 12	D: 30		19-MAY-2026	M: 9 D: 20
73 10-07-212-801 Engine 1 INSPECTION 1E 800H/12M #86	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 10-07-212-801 Engine 2 INSPECTION 2E 800H/12M #247	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
73 1002 Engine 1 PART #37	NO. 1 ENGINE - FLOW DIVIDER Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
73 1002 Engine 2 PART #48	NO. 2 ENGINE - FLOW DIVIDER Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
73 1010 Engine 1 PART #473	NO. 1 ENGINE - HPT AIR SEAL Part Number 3052756-01 Serial Number ECB9930	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #314	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA98183	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #302	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA90827	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #310	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA90592	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #90	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAS8648	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #23	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA58791	30-OCT-2021 H: 2496.10 C: 2411					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1010 Engine 1 PART #211	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA200 01	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #34	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAB0S1 52	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #16	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAB051 54	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #177	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAB0S1 63	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #147	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA908 38	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 1 PART #84	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA908 40	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #472	NO. 2 ENGINE - HPT AIR SEAL Part Number 3052756-01 Serial Number ECB9931	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #240	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA777 31	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #90	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DE1BRE29 48	30-OCT-2021 H: 2496.10 C: 2411					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 1010 Engine 2 PART #228	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DE1BUA07 98	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #89	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA920 60	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #254	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAAB83 64	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #134	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA989 30	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #19	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA597 37	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #261	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DE1BUB03 04	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #178	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DE1BRE29 47	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #91	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DE1AEA04 56	30-OCT-2021 H: 2496.10 C: 2411					
73 1010 Engine 2 PART #109	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY Part Number 3057135-01 Serial Number DEAAA936 95	30-OCT-2021 H: 2496.10 C: 2411					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 103023 Engine 1 PART #477	NO. 1 ENGINE - NO. 1 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 1 PART #479	NO. 1 ENGINE - NO. 2 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 1 PART #480	NO. 1 ENGINE - NO. 3 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 1 PART #475	NO. 1 ENGINE - NO. 4 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 1 PART #476	NO. 1 ENGINE - NO. 5 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 2 PART #474	NO. 2 ENGINE - NO. 1 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 2 PART #473	NO. 2 ENGINE - NO. 2 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103023 Engine 2 PART #475	NO. 2 ENGINE - NO. 3 DIFFUSER TUBE Part Number 3075436-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103024 Engine 1 PART #474	NO. 1 ENGINE - NO. 1 SEAL RING Part Number 3056735-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 103025 Engine 1 PART #478	NO. 1 ENGINE - STARTER MAGNETIC SEAL Part Number 3059820-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103025 Engine 2 PART #476	NO. 2 ENGINE - STARTER MAGNETIC SEAL Part Number 3059820-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103026 Engine 2 PART #477	NO. 2 ENGINE - NO. 1 SEAL RING Part Number 3056735-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103026 Engine 2 PART #478	NO. 2 ENGINE - NO. 2 SEAL RING Part Number 3120160-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 103026 Engine 2 PART #479	NO. 2 ENGINE - NO. 3 SEAL RING Part Number 3120161-01 Serial Number SN UNKNOWN	30-OCT-2021 H: 2496.10 C: 2411					
73 20-02-212-801 Engine 1 INSPECTION 1E 800H/12M #117	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESS	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
73 20-02-212-801 Engine 2 INSPECTION 2E 800H/12M #353	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESS	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
73 2000 Engine 1 PART #245	NO. 1 ENGINE - TEMPERATURE SENSOR Part Number ATS-9-800 Serial Number 082511-21	30-DEC-2011					
73 2000 Engine 2 PART #112	NO. 2 ENGINE - TEMPERATURE SENSOR Part Number ATS-9-800 Serial Number 080211-1	20-JAN-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 2001 Engine 1 PART #217	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT Part Number 1012300-3-003 Serial Number 2011050012	18-APR-2014 H: 623.30 C: 675					
73 2001 Engine 2 PART #322	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT Part Number 1012300-3-003 Serial Number 2011070024	18-APR-2014 H: 623.30 C: 675					
73 2002 Engine 1 PART #248	NO. 1 ENGINE - FUEL METERING UNIT (FMU) Part Number 3071682-05 Serial Number F73073	30-DEC-2011					
73 2002 Engine 2 PART #323	NO. 2 ENGINE - FUEL METERING UNIT (FMU) Part Number 3071682-05 Serial Number F73161	20-JAN-2012					
73 2005 Engine 1 PART #52	NO. 1 ENGINE - N2 SPEED SENSOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
73 2005 Engine 2 PART #212	NO. 2 ENGINE - N2 SPEED SENSOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
73 2006 Engine 1 PART #268	NO. 1 ENGINE - N1 SPEED SENSOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
73 2006 Engine 2 PART #77	NO. 2 ENGINE - N1 SPEED SENSOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
73 2010 Engine 1 PART #57	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 2010 Engine 2 PART #362	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
73 21-01 Airframe PART #27	LEFT FADEC Part Number 1012300-3-003 Serial Number 2011050012	18-APR-2014 H: 623.30 L: 675					
73 21-01 Airframe PART #1472	RIGHT FADEC Part Number 1012300-3-003 Serial Number 2011070024	18-APR-2014 H: 623.30 L: 675					
73 30-02-212-801 Engine 1 INSPECTION 1E 800H/12M #212	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
73 30-02-212-801 Engine 2 INSPECTION 2E 800H/12M #52	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
73 33-01 Airframe PART #701	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER Part Number 8TJ300AAB2 Serial Number 27764	07-MAY-2012					
73 33-01 Airframe PART #1728	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER Part Number 8TJ300AAB2 Serial Number 26966	07-MAY-2012					
73 72-00-00-280-819 Engine 1 INSPECTION 1E 800H/12M #47	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
73 72-00-00-280-819 Engine 2 INSPECTION 2E 800H/12M #366	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
74 00-01-750-801 Engine 1 INSPECTION 1E 800H/12M, ENG 1 OH #372	NO. 1 ENGINE - OPERATIONAL CHECK - DO A FUNCTIONAL TEST OF IGNITION SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 00-01-750-801 Engine 2 INSPECTION 2E 800H/12M, ENG 2 OH #371	NO. 2 ENGINE - OPERATIONAL CHECK - DO A FUNCTIONAL TEST OF IGNITION SYSTEM	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 10-01-212-801 Engine 1 INSPECTION ENG 1 OH #449	NO. 1 ENGINE - EXAMINE - IGNITERS Reference Number TASK 74-20-02- 210-801 Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.	07-MAY-2012	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
74 10-01-212-801 Engine 1 INSPECTION 1E 800H/12M, ENG 1 OH #330	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER Part Number 31J2807-07 Serial Number NNA114803 67	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 10-01-212-801 Engine 2 INSPECTION ENG 2 OH #448	NO. 2 ENGINE - EXAMINE - IGNITERS Reference Number TASK 74-20-02- 210-801 Notes NOTE: 3. THE ENGINE TEST AFTER OVERHAUL DETERMINES IF THE ACCESSORY IS SERVICEABLE. IF ANY FAULTS ASSOCIATED WITH THE ACCESSORY ARE FOUND AT THE ENGINE TEST, EXAMINE THE ACCESSORY PER CMM OR REPLACE.	07-MAY-2012	H: 5000.00	H: 100.00		H: 5000.00	H: 1956.60
74 10-01-212-801 Engine 2 INSPECTION 2E 800H/12M, ENG 2 OH #204	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER Part Number 31J2807-07 Serial Number NNA120201 47	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 1001 Engine 1 PART #199	NO. 1 ENGINE - EXCITER IGNITION Part Number 31J2807-07 Serial Number NNA114803 67	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
74 1001 Engine 2 PART #179	NO. 2 ENGINE - EXCITER IGNITION Part Number 31J2807-07 Serial Number NNA120201 47	20-JAN-2012					
74 20-01-212-801 Engine 1 INSPECTION 1E 800H/12M, ENG 1 OH #32	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 20-01-212-801 Engine 2 INSPECTION 2E 800H/12M, ENG 2 OH #314	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 20-02-210-801 Engine 1 INSPECTION 1E 800H/12M, ENG 1 OH #371	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION - DO A VISUAL INSPECTION OF IGNITION IGNITERS	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 20-02-210-801 Engine 2 INSPECTION 2E 800H/12M, ENG 2 OH #372	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION - DO A VISUAL INSPECTION OF IGNITION IGNITERS	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
74 2000 Engine 1 PART #333	NO. 1 ENGINE - 5 O'CLOCK IGNITER Part Number 502600-1 Serial Number NNA172100 62	15-MAY-2018 H: 1776.00 C: 1789					
74 2000 Engine 2 PART #250	NO. 2 ENGINE - 5 O'CLOCK IGNITER Part Number 502600-1 Serial Number NNA173901 91	15-MAY-2018 H: 1776.00 C: 1789					
74 2001 Engine 1 PART #251	NO. 1 ENGINE - 7 O'CLOCK IGNITER Part Number 502600-1 Serial Number NNA174201 52	15-MAY-2018 H: 1776.00 C: 1789					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
74 2001 Engine 2 PART #233	NO. 2 ENGINE - 7 O'CLOCK IGNITER Part Number 502600-1 Serial Number NNA17210090	15-MAY-2018 H: 1776.00 C: 1789					
74 2002 Engine 1 PART #155	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD Part Number 3127408-01 Serial Number NNA15510171	19-APR-2016 H: 1156.20 C: 1221					
74 2002 Engine 2 PART #145	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD Part Number 3127408-01 Serial Number NNA15500153	18-APR-2016 H: 1156.20 C: 1221					
74 2003 Engine 1 PART #24	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD Part Number 3127408-02 Serial Number NNA15510207	19-APR-2016 H: 1156.20 C: 1221					
74 2003 Engine 2 PART #108	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD Part Number 3127408-02 Serial Number NNA15510064	18-APR-2016 H: 1156.20 C: 1221					
75 0001 Engine 1 PART #226	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE Part Number 3075987-01 Serial Number TR5698	30-DEC-2011					
75 0001 Engine 2 PART #303	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE Part Number 3075987-01 Serial Number TR5752	20-JAN-2012					
75 30-01-212-801 Engine 1 INSPECTION 1E 800H/12M #39	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00			03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
75 30-01-212-801 Engine 2 INSPECTION 2E 800H/12M #93	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00			03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
75 3001 Engine 1 PART #121	NO. 1 ENGINE - LINEAR TRANSFORMER Part Number 3071811-01 Serial Number 1474	30-DEC-2011					
75 3001 Engine 2 PART #358	NO. 2 ENGINE - LINEAR TRANSFORMER Part Number 3071811-01 Serial Number 1470	20-JAN-2012					
75 3002 Engine 1 PART #165	NO. 1 ENGINE - SERVO COMPUTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
75 3002 Engine 2 PART #280	NO. 2 ENGINE - SERVO COMPUTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
75 3010 Engine 1 PART #45	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY Part Number 3053367-01 Serial Number AHX050000 45	30-DEC-2011					
75 3010 Engine 2 PART #243	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY Part Number 3053367-01 Serial Number AHX050004 7	20-JAN-2012					
77 20-02-750-801 Engine 1 INSPECTION #131	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM Notes PRE-SB30536: EVERY 1600 FLIGHT HOURS OR 36 MONTHS, WHICHEVER COMES FIRST.	18-APR-2024 H: 2895.60 C: 2711	M: 36 H: 1600.00	D: 30 H: 100.00		18-APR-2027 H: 4495.60	M: 20 D: 20 H: 1452.20
77 20-02-750-801 Engine 2 INSPECTION #287	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM Notes PRE-SB30536: EVERY 1600 FLIGHT HOURS OR 36 MONTHS, WHICHEVER COMES FIRST.	18-APR-2024 H: 2895.60 C: 2711	M: 36 H: 1600.00	D: 30 H: 100.00		18-APR-2027 H: 4495.60	M: 20 D: 20 H: 1452.20

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
77 4001 Engine 1 PART #213	NO. 1 ENGINE - DATA COLLECTION UNIT Part Number 3075878-02 Serial Number 18057667	23-MAR-2018 H: 1753.00 C: 1768					
77 4001 Engine 2 PART #37	NO. 2 ENGINE - DATA COLLECTION UNIT Part Number 3075878-01 Serial Number 13-013455	12-SEP-2014 H: 753.40 C: 830					
79 Engine 1 INSPECTION #370	NO. 1 ENGINE - OIL SAMPLE ANALYSIS Notes Pratt & Whitney trial program	23-APR-2019 H: 2052.70 C: 2048					
79 Engine 2 INSPECTION #370	NO. 2 ENGINE - OIL SAMPLE ANALYSIS Notes Pratt & Whitney trial program	23-APR-2019 H: 2052.70 C: 2048					
79 0020 Engine 1 INSPECTION #150	NO. 1 ENGINE - CHANGE OIL	30-DEC-2011					
79 0020 Engine 2 INSPECTION #137	NO. 2 ENGINE - CHANGE OIL	20-JAN-2012					
79 20-01-000-801 Engine 1 PART - Life Limited #107	NO. 1 ENGINE - DISCARD OIL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 C: 2496	H: 800.00	H: 80.00	H: 0.00	H: 3411.00	H: 367.60
79 20-01-000-801 Engine 2 PART - Life Limited #140	NO. 2 ENGINE - DISCARD OIL FILTER Part Number PN UNKNOWN Serial Number SN UNKNOWN	18-JUL-2022 H: 2611.00 C: 2496	H: 800.00	H: 80.00	H: 0.00	H: 3411.00	H: 367.60

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 30-01-770-801 Engine 1 INSPECTION 1E 800H/12M #313	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
79 30-01-770-801 Engine 2 INSPECTION 2E 800H/12M #78	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
79 30-02-210-801 Engine 1 INSPECTION 1E 800H/12M #243	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
79 30-02-210-801 Engine 2 INSPECTION 2E 800H/12M #368	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH	03-MAY-2025 H: 3019.50 C: 2801	M: 12 H: 800.00	D: 30 H: 80.00		03-MAY-2026 H: 3819.50	M: 9 D: 4 H: 776.10
79 3003 Engine 1 PART #332	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER Part Number 3052640-01 Serial Number 25520002	30-DEC-2011					
79 3003 Engine 2 PART #2	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER Part Number 3052640-01 Serial Number 25520007	20-JAN-2012					
79 3010 Engine 1 PART #132	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	30-DEC-2011					
79 3010 Engine 2 PART #300	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR Part Number PN UNKNOWN Serial Number SN UNKNOWN	20-JAN-2012					
79 31-05 Airframe PART #710	LEFT ENGINE MAIN OIL PRESSURE SENSOR Part Number APTE-478A-1000-270D Serial Number 224	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 31-05 Airframe PART #1726	RIGHT ENGINE MAIN OIL PRESSURE SENSOR Part Number APTE-478A-1000-270D Serial Number 192	07-MAY-2012					
79 Z210-001 Airframe INSPECTION 120M #730	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z220-001 Airframe INSPECTION 60M #1217	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
79 Z220-002 Airframe INSPECTION 120M #1972	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z230-001 Airframe INSPECTION 120M #499	ZONAL INSPECTION - GVI - EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z230-002 Airframe INSPECTION 120M #1896	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z240-001 Airframe INSPECTION 120M #134	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z240-002 Airframe INSPECTION 60M #939	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
79 Z310-001 Airframe INSPECTION 120M #1002	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 Z310-002 Airframe INSPECTION 120M #335	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z320-001 Airframe INSPECTION 120M #819	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z320-002 Airframe INSPECTION 120M #1207	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z330-001 Airframe INSPECTION 120M #1367	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z330-002 Airframe INSPECTION 120M #994	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z340-001 Airframe INSPECTION 60M #416	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
79 Z340-002 Airframe INSPECTION 120M #1786	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z410-001 Airframe INSPECTION 120M #1490	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z410-002 Airframe INSPECTION 120M #73	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 Z430-001 Airframe INSPECTION 120M #655	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE	18-JUL-2022 H: 2611.00 L: 2496	M: 120	M: 1		18-JUL-2032	M: 83 D: 19
79 Z500-001 Airframe INSPECTION 60M #182	ZONAL INSPECTION - EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
79 Z500-002 Airframe INSPECTION 60M #1636	ZONAL INSPECTION - INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS	18-JUL-2022 H: 2611.00 L: 2496	M: 60	M: 1		18-JUL-2027	M: 23 D: 19
SIL PW500-077 Engine 1 SIL - Open #447	SERVICE INFO LETTERS - GAS GENERATOR TO TURBINE SUPPORT CASE RETAINING BOLTS - AIRWORTHINESS DIRECTIVE CF-2023-60 - VALID UNTIL SUPERSEDED OR CANCELLED BY REVISION						
SIL PW500-077 Engine 2 SIL - Open #446	SERVICE INFO LETTERS - GAS GENERATOR TO TURBINE SUPPORT CASE RETAINING BOLTS - AIRWORTHINESS DIRECTIVE CF-2023-60 - VALID UNTIL SUPERSEDED OR CANCELLED BY REVISION						
SL 505-00-0007 R9 Airframe SL - Open #2288	LABOR FEES FOR IN-SERVICE TECHNICAL SUPPORT						
SL 505-00-0041 R41 Airframe SL - Open #2274	SERVICE LETTER - CHANGES IN ACCESS TO THE ELEB CMMS PUBLISHED IN TECHPUBS						
SL 505-00-0042 Airframe SL - Open #2275	SERVICE LETTER - EMBRAER'S TECHPUBS APP MIGRATION ON GOOGLE PLAY						
SL 505-00-0043 Airframe SL - Open #2280	SERVICE LETTER - NON-EMBRAER SOFTWARE FOR OPENING AND READING EMBRAER DOCUMENTS IN PDF FORMAT						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 505-21-0005 R1 Airframe SL - Open #2262	SERVICE LETTER - VCS PRESSURE FAULT - SPURIOUS EVENTS						
SL 505-21-0005 R2 Airframe SL - Open #2271	SERVICE LETTER - VCS PRESSURE FAULT - SPURIOUS EVENTS AND TROUBLESHOOTING TIPS						
SL 505-21-0006 R1 Airframe SL - Open #2261	SERVICE LETTER - COMPRESSOR DRIVE MODULE (CDM) REPLACEMENT - BEST PRACTICES						
ASB A003 Airframe SB - N/A #1627	ICE AND RAIN PROTECTION - INSPECTION OF THE PICCOLO TUBE INSTALLATION (SUPERSEDED BY SB 505-30-A003 REV 01), ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE						
ASB A003 R01 Airframe SB - N/A #1041	ICE AND RAIN PROTECTION - INSPECTION OF THE PICCOLO TUBE INSTALLATION (SUPERSEDED BY SB 505-30-A003 REV 02), ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE						
ASB A003 R02 Airframe SB - N/A #487	ICE AND RAIN PROTECTION - INSPECTION OF THE PICCOLO TUBE INSTALLATION, ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE						
ASB A005 PART I Airframe SB - Complied With #1966	ELECTRICAL POWER ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 505-24-0005), ALERT SERVICE BULLETIN LEFT-HAND (LH) STARTER GENERATOR REPLACEMENT						
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A005 PART II Airframe SB - Complied With #265	ELECTRICAL POWER ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 505-24-0005), ALERT SERVICE BULLETIN RIGHT-HAND (RH) STARTER GENERATOR REPLACEMENT	23-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH						
ASB A005 Airframe SB - Complied With #896	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 505-24-0005), ALERT SERVICE BULLETIN	23-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH						
ASB A011 Airframe SB - Complied With #502	LANDING GEAR - PRECAUTIONARY INSPECTION IN THE STATOR PRESSURE PLATE OF THE MLG BRAKE ASSEMBLY (SUPERSEDED BY SB 505-32-0011 REV 01), ALERT SERVICE BULLETIN	12-JAN-2014 H: 519.00 L: 571					
	Notes COMPLIED WITH						
ASB A011 R01 Airframe SB - Complied With #1032	LANDING GEAR - PRECAUTIONARY INSPECTION IN THE STATOR PRESSURE PLATE OF THE MLG BRAKE ASSEMBLY (SUPERSEDED BY SB 505-32-0011 REV 01), ALERT SERVICE BULLETIN						
	Notes COMPLIED WITH - ON ORIGINAL SB						
ASB A011 R02 PART I Airframe SB - Complied With #349	INSPECTION LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE ASSEMBLY (SUPERSEDED BY SB 505-32-0011 REV 01), ALERT SERVICE BULLETIN TO BE DONE IN THE PRESSURE STATOR ON THE BRAKE ASSEMBLY OF LH AND RH MAIN LANDING GEARS (MLG) FOR CRACKS BEYOND ACCEPTABLE LIMITS	28-MAY-2014 H: 659.40 L: 714					
	Notes COMPLIED WITH						
ASB A011 R02 Airframe SB - Complied With #1058	LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE ASSEMBLY (SUPERSEDED BY SB 505-32-0011 REV 01), ALERT SERVICE BULLETIN	28-MAY-2014 H: 659.40 L: 714					
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A011 R02 PART II Airframe SB - Complied With #511	VISUAL INSPECTION LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE ASSEMBLY (SUPERSEDED BY SB 505-32-0011 REV 01), ALERT SERVICE BULLETIN TO BE DONE ON THE THRUST STATOR, DOUBLE STATOR AND ROTORS OF THE LH AND RH BRAKE ASSEMBLIES	28-MAY-2014 H: 659.40 L: 714					
	Notes COMPLIED WITH						
ASB A028 R01 PART II Airframe SB - N/A #226	ACCOMPLISH FLIGHT CONTROLS - AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB INSPECTION AND TORQUE, ALERT SERVICE BULLETIN AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB COTTER PIN INSTALLATION AND TORQUE						
	Notes NOT APPLICABLE						
ASB A028 R01 PART I Airframe SB - N/A #958	ACCOMPLISH FLIGHT CONTROLS - AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB INSPECTION AND TORQUE, ALERT SERVICE BULLETIN INSPECTION OF AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB						
	Notes NOT APPLICABLE						
ASB A028 R01 Airframe SB - N/A #1815	FLIGHT CONTROLS - AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB INSPECTION AND TORQUE, ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE						
ASB A028 R02 PART II Airframe SB - N/A #1106	ACCOMPLISH, ALERT SERVICE BULLETIN AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB COTTER PIN INSTALLATION AND TORQUE						
	Notes NOT APPLICABLE						
ASB A028 R02 PART I Airframe SB - N/A #1316	ACCOMPLISH, ALERT SERVICE BULLETIN INSPECTION OF AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
ASB A028 R02 Airframe SB - N/A #554	FLIGHT CONTROLS - AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB INSPECTION AND TORQUE, ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE						
ASB A30477 Engine 1 SB - Open #18	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF ENGINE MOUNT HEAT SHIELD NUTS, ALERT SERVICE BULLETIN						
	Notes CATEGORY 3						
ASB A30477 Engine 2 SB - Open #320	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF ENGINE MOUNT HEAT SHIELD NUTS, ALERT SERVICE BULLETIN						
	Notes CATEGORY 3						
ASB A30477 R1 Engine 1 SB - N/A #209	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF ENGINE MOUNT HEAT SHIELD NUTS, ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE - NOT APPLICABLE BY ENGINE S/N CATEGORY 3				11-MAR-2013 H: 268.80 C: 292		
ASB A30477 R1 Engine 2 SB - N/A #226	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF ENGINE MOUNT HEAT SHIELD NUTS, ALERT SERVICE BULLETIN						
	Notes NOT APPLICABLE - NOT APPLICABLE BY ENGINE S/N CATEGORY 3				11-MAR-2013 H: 268.80 C: 292		
SB 30000 Engine 1 SB - Open #321	NO. 1 ENGINE - OMNIBUS SERVICE BULLETIN - FOR INFORMATIONAL RECORD PURPOSES, SERVICE BULLETIN						
	Notes CATEGORY 11						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30000 Engine 2 SB - Open #227	NO. 2 ENGINE - OMNIBUS SERVICE BULLETIN - FOR INFORMATIONAL RECORD PURPOSES, SERVICE BULLETIN Notes CATEGORY 11						
SB 30000 R1 Engine 1 SB - Open #189	NO. 1 ENGINE - OMNIBUS SERVICE BULLETIN - FOR INFORMATIONAL RECORD PURPOSES, SERVICE BULLETIN Notes CATEGORY 11						
SB 30000 R1 Engine 2 SB - Open #196	NO. 2 ENGINE - OMNIBUS SERVICE BULLETIN - FOR INFORMATIONAL RECORD PURPOSES, SERVICE BULLETIN Notes CATEGORY 11						
SB 30403 Engine 1 SB - Open #136	NO. 1 ENGINE - TURBOFAN ENGINE TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN Notes CATEGORY 6						
SB 30403 Engine 2 SB - Open #230	NO. 2 ENGINE - TURBOFAN ENGINE TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN Notes CATEGORY 6						
SB 30403 R02 Engine 1 SB - Open #319	NO. 1 ENGINE - REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES, SERVICE BULLETIN Notes CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30403 R02 Engine 2 SB - Open #13	NO. 2 ENGINE - REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES, SERVICE BULLETIN Notes CATEGORY 6						
SB 30403 R1 Engine 1 SB - Complied With #359	NO. 1 ENGINE - TURBOFAN ENGINE TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 6	30-DEC-2011					
SB 30403 R1 Engine 2 SB - Complied With #346	NO. 2 ENGINE - TURBOFAN ENGINE TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 6	20-JAN-2012					
SB 30404 Engine 1 SB - Open #108	NO. 1 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN						
SB 30404 Engine 2 SB - Open #57	NO. 2 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN						
SB 30404 R1 Engine 1 SB - Open #190	NO. 1 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN						
SB 30404 R1 Engine 2 SB - Open #130	NO. 2 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN						
SB 30404 R2 Engine 1 SB - Open #115	NO. 1 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30404 R2 Engine 2 SB - Open #343	NO. 2 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN Notes CATEGORY 7						
SB 30404 R3 Engine 1 SB - Complied With #73	NO. 1 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	30-DEC-2011					
SB 30404 R3 Engine 2 SB - Complied With #155	NO. 2 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	20-JAN-2012					
SB 30406 Engine 1 SB - Open #12	NO. 1 ENGINE - REPLACEMENT OF FUEL SHUT-OFF VALVE PIN, SERVICE BULLETIN Notes CATEGORY 7						
SB 30406 Engine 2 SB - Open #65	NO. 2 ENGINE - REPLACEMENT OF FUEL SHUT-OFF VALVE PIN, SERVICE BULLETIN Notes CATEGORY 7						
SB 30410 Engine 1 SB - Complied With #244	NO. 1 ENGINE - REPLACEMENT OF HARNESS SUPPORT BRACKET, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30410 Engine 2 SB - Complied With #113	NO. 2 ENGINE - REPLACEMENT OF HARNESS SUPPORT BRACKET, SERVICE BULLETIN	20-JAN-2012					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						
SB 30412 Engine 1 SB - Open #19	NO. 1 ENGINE - REPLACEMENT FAN ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30412 Engine 2 SB - Open #283	NO. 2 ENGINE - REPLACEMENT FAN ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30415 R1 Engine 1 SB - Open #360	NO. 1 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30415 R1 Engine 2 SB - Open #73	NO. 2 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30415 R2 Engine 1 SB - Open #274	NO. 1 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN						
	Notes CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30415 R2 Engine 2 SB - Open #286	NO. 2 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN Notes CATEGORY 6						
SB 30415 R3 Engine 1 SB - Open #51	NO. 1 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN Notes CATEGORY 6						
SB 30415 R3 Engine 2 SB - Open #333	NO. 2 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN Notes CATEGORY 6						
SB 30415 R4 Engine 1 SB - Open #410	TURBOFAN ENGINE NO. 4 ROLLER BEARING - REPLACEMENT OF						
SB 30415 R4 Engine 2 SB - Open #409	TURBOFAN ENGINE NO. 4 ROLLER BEARING - REPLACEMENT OF						
SB 30420 Engine 1 SB - Open #276	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30420 Engine 2 SB - Open #12	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30420 R1 Engine 1 SB - Open #239	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30420 R1 Engine 2 SB - Open #80	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30420 R2 Engine 1 SB - Complied With #262	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 3	30-DEC-2011					
SB 30420 R2 Engine 2 SB - Complied With #76	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 3	20-JAN-2012					
SB 30420 R3 Engine 1 SB - Open #269	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30420 R3 Engine 2 SB - Open #359	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30420 R4 Engine 1 SB - Open #60	NO. 1 ENGINE - REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30420 R4 Engine 2 SB - Open #126	NO. 2 ENGINE - REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30420R6 Engine 1 SB - Open #407	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF - CATEGORY 3, 6						
SB 30420R6 Engine 2 SB - Open #406	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF - CATEGORY 3, 6						
SB 30423 Engine 1 SB - Complied With #168	NO. 1 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 6	30-DEC-2011					
SB 30423 Engine 2 SB - Complied With #236	NO. 2 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 6	20-JAN-2012					
SB 30423 R1 Engine 1 SB - Open #145	NO. 1 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30423 R1 Engine 2 SB - Open #106	NO. 2 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 6						
SB 30431 Engine 1 SB - Complied With #252	NO. 1 ENGINE - CARBON SEAL NO. 4 BEARING - REPLACEMENT OF , SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	30-DEC-2011					
SB 30431 Engine 2 SB - Complied With #11	NO. 2 ENGINE - CARBON SEAL NO. 4 BEARING - REPLACEMENT OF , SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	20-JAN-2012					
SB 30432 Engine 1 SB - Open #54	NO. 1 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN Notes CATEGORY 7						
SB 30432 Engine 2 SB - Open #27	NO. 2 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN Notes CATEGORY 7						
SB 30432 R1 Engine 1 SB - Complied With #205	NO. 1 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	30-DEC-2011					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30432 R1 Engine 2 SB - Complied With #297	NO. 2 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF , SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	20-JAN-2012					
SB 30433 Engine 1 SB - Open #236	NO. 1 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN Notes CATEGORY 7						
SB 30433 Engine 2 SB - Open #336	NO. 2 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN Notes CATEGORY 7						
SB 30435 Engine 1 SB - Complied With #365	NO. 1 ENGINE - TURBINE EXHAUST DUCT - MODIFICATION/REPLACEMENT OF , SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	30-DEC-2011					
SB 30435 Engine 2 SB - Complied With #234	NO. 2 ENGINE - TURBINE EXHAUST DUCT - MODIFICATION/REPLACEMENT OF , SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	20-JAN-2012					
SB 30435 R1 Engine 1 SB - Open #123	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF TURBINE EXHAUST DUCT, SERVICE BULLETIN Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30435 R1 Engine 2 SB - Open #153	NO. 2 ENGINE - MODIFICATION/REPLACEMENT OF TURBINE EXHAUST DUCT, SERVICE BULLETIN Notes CATEGORY 7						
SB 30437 Engine 1 SB - Open #287	NO. 1 ENGINE - INSPECTION OF FUEL MANIFOLD AND NOZZLES, SERVICE BULLETIN Notes CATEGORY 3						
SB 30437 Engine 2 SB - Open #311	NO. 2 ENGINE - INSPECTION OF FUEL MANIFOLD AND NOZZLES, SERVICE BULLETIN Notes CATEGORY 3						
SB 30437 R1 Engine 1 SB - Open #130	NO. 1 ENGINE - FUEL MANIFOLD AND NOZZLES - INSPECTION OF, SERVICE BULLETIN Notes CATEGORY 3						
SB 30437 R1 Engine 2 SB - Open #190	NO. 2 ENGINE - FUEL MANIFOLD AND NOZZLES - INSPECTION OF, SERVICE BULLETIN Notes CATEGORY 3						
SB 30437 R2 Engine 1 SB - N/A #88	NO. 1 ENGINE - INSPECTION OF FUEL MANIFOLD AND NOZZLES, SERVICE BULLETIN Notes NOT APPLICABLE - BULLETIN DNA BY ENG SN CATEGORY 3				08-AUG-2014 H: 726.70 C: 793		

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30437 R2 Engine 2 SB - N/A #3	NO. 2 ENGINE - INSPECTION OF FUEL MANIFOLD AND NOZZLES, SERVICE BULLETIN	08-AUG-2014 H: 726.70 C: 793					
	Notes NOT APPLICABLE - BULLETIN DNA BY ENG SN CATEGORY 3						
SB 30438 Engine 1 SB - N/A #181	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 7						
SB 30438 Engine 2 SB - N/A #291	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 7						
SB 30438 R1 Engine 1 SB - N/A #92	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 7						
SB 30438 R1 Engine 2 SB - N/A #15	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 7						
SB 30438 R2 Engine 1 SB - N/A #65	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 5						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30438 R2 Engine 2 SB - N/A #157	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 5						
SB 30438 R3 Engine 1 SB - N/A #290	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 5						
SB 30438 R3 Engine 2 SB - N/A #345	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes NOT APPLICABLE CATEGORY 5						
SB 30438 R4 Engine 1 SB - Complied With #318	NO. 1 ENGINE - TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	30-DEC-2011					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 3						
SB 30438 R4 Engine 2 SB - Complied With #273	NO. 2 ENGINE - TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	20-JAN-2012					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 3						
SB 30438 R5 Engine 1 SB - Open #106	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R3), SERVICE BULLETIN						
	Notes CATEGORY 10						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30438 R5 Engine 2 SB - Open #121	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R3), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30439 Engine 1 SB - Complied With #116	NO. 1 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN	30-DEC-2011					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						
SB 30439 Engine 2 SB - Complied With #281	NO. 2 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN	20-JAN-2012					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						
SB 30439 R1 Engine 1 SB - Open #134	NO. 1 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30439 R1 Engine 2 SB - Open #72	NO. 2 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30445 Engine 1 SB - Complied With #294	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	30-DEC-2011					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30445 Engine 2 SB - Complied With #110	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	20-JAN-2012					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						
SB 30446 R1 Engine 1 SB - Complied With #31	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN	30-DEC-2011					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						
SB 30446 R1 Engine 2 SB - Complied With #249	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN	20-JAN-2012					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7						
SB 30446 R2 Engine 1 SB - Open #139	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30446 R2 Engine 2 SB - Open #39	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30447 Engine 1 SB - Complied With #237	NO. 1 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN	30-DEC-2011					
	Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30447 Engine 2 SB - Complied With #41	NO. 2 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 6	20-JAN-2012					
SB 30447 R1 Engine 1 SB - Open #229	NO. 1 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN Notes CATEGORY 6						
SB 30447 R1 Engine 2 SB - Open #328	NO. 2 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN Notes CATEGORY 6						
SB 30451 Engine 1 SB - Complied With #44	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	30-DEC-2011					
SB 30451 Engine 2 SB - Complied With #310	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE CATEGORY 7	20-JAN-2012					
SB 30453 Engine 1 SB - Open #254	NO. 1 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30453 Engine 2 SB - Open #97	NO. 2 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30453 R03 Engine 1 SB - Open #68	NO. 1 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30453 R03 Engine 2 SB - Open #177	NO. 2 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30453 R1 Engine 1 SB - Open #129	NO. 1 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30453 R1 Engine 2 SB - Open #225	NO. 2 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30453 R2 Engine 1 SB - Open #128	NO. 1 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30453 R2 Engine 2 SB - Open #197	NO. 2 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30454 Engine 1 SB - Open #59	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR INLET VANE RING, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30454 Engine 2 SB - Open #165	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR INLET VANE RING, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30454 R1 Engine 1 SB - Open #100	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET VANE RING, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30454 R1 Engine 2 SB - Open #277	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET VANE RING, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30459 Engine 1 SB - Open #285	NO. 1 ENGINE - REPLACEMENT OF NUT OPTION (IC), SERVICE BULLETIN						
	Notes CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30459 Engine 2 SB - Open #229	NO. 2 ENGINE - REPLACEMENT OF NUT OPTION (IC), SERVICE BULLETIN Notes CATEGORY 6						
SB 30459 R1 Engine 1 SB - Open #336	NO. 1 ENGINE - REPLACEMENT OF NUT OPTION (IC), SERVICE BULLETIN Notes CATEGORY 6						
SB 30459 R1 Engine 2 SB - Open #162	NO. 2 ENGINE - REPLACEMENT OF NUT OPTION (IC), SERVICE BULLETIN Notes CATEGORY 6						
SB 30460 Engine 1 SB - Open #216	NO. 1 ENGINE - RE-PROGRAMMING / REPLACEMENT-MODIFICATION ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN Notes CATEGORY 5						
SB 30460 Engine 2 SB - Open #191	NO. 2 ENGINE - RE-PROGRAMMING / REPLACEMENT-MODIFICATION ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN Notes CATEGORY 5						
SB 30460 R1 Engine 1 SB - Open #7	NO. 1 ENGINE - RE-PROGRAMMING / REPLACEMENT-MODIFICATION OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN Notes CATEGORY 5						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30460 R1 Engine 2 SB - Open #175	NO. 2 ENGINE - RE-PROGRAMMING / REPLACEMENT-MODIFICATION OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN						
	Notes CATEGORY 5						
SB 30460 R2 Engine 1 SB - Complied With #56	NO. 1 ENGINE - RE-PROGRAMMING / REPLACEMENT-MODIFICATION OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN						
	Notes COMPLIED WITH - ASSISTED BY JIM ROBBINS. PRAH & WHITNEY CANADA FIELD REP. CATEGORY 5	28-MAY-2013 H: 330.50 C: 349					
SB 30460 R2 Engine 2 SB - Complied With #62	NO. 2 ENGINE - RE-PROGRAMMING / REPLACEMENT-MODIFICATION OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN						
	Notes COMPLIED WITH - ASSISTED BY JIM ROBBINS. PRAH & WHITNEY CANADA FIELD REP. CATEGORY 5	28-MAY-2013 H: 330.50 C: 349					
SB 30463 Engine 1 SB - Open #11	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30463 Engine 2 SB - Open #44	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30463 R1 Engine 1 SB - Open #164	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30463 R1 Engine 2 SB - Open #32	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30463 R2 Engine 1 SB - Open #286	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30463 R2 Engine 2 SB - Open #47	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30465 Engine 1 SB - Open #296	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30465 Engine 2 SB - Open #156	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30465 R1 Engine 1 SB - Open #304	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30465 R1 Engine 2 SB - Open #207	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30465 R2 Engine 1 SB - Open #364	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30465 R2 Engine 2 SB - Open #23	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30470 Engine 1 SB - Open #124	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30470 Engine 2 SB - Open #344	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30470 R1 Engine 1 SB - Open #58	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30470 R1 Engine 2 SB - Open #172	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30474 Engine 1 SB - Open #207	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30474 Engine 2 SB - Open #262	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30474 R1 Engine 1 SB - Open #184	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30474 R1 Engine 2 SB - Open #154	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30474 R2 Engine 1 SB - Open #170	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30474 R2 Engine 2 SB - Open #321	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN Notes CATEGORY 7						
SB 30474 R3 Engine 1 SB - Open #373	REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS						
SB 30474 R3 Engine 2 SB - Open #373	REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS						
SB 30475 R1 PART B Engine 1 SB - Open #191	NO. 1 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE ACCESSORY DRIVE GEARSHAFT Notes CATEGORY 7						
SB 30475 R1 PART A Engine 1 SB - Open #343	NO. 1 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT Notes CATEGORY 7						
SB 30475 R1 Engine 1 SB - Open #95	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30475 R1 PART B Engine 2 SB - Open #82	NO. 2 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE ACCESSORY DRIVE GEARSHAFT Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30475 R1 PART A Engine 2 SB - Open #8	NO. 2 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT Notes CATEGORY 7						
SB 30475 R1 Engine 2 SB - Open #88	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30475 R2 PART B Engine 1 SB - Open #197	NO. 1 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE ACCESSORY DRIVE GEARSHAFT Notes CATEGORY 7						
SB 30475 R2 PART A Engine 1 SB - Open #257	NO. 1 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT Notes CATEGORY 7						
SB 30475 R2 Engine 1 SB - Open #140	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30475 R2 PART B Engine 2 SB - Open #307	NO. 2 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE ACCESSORY DRIVE GEARSHAFT Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30475 R2 PART A Engine 2 SB - Open #332	NO. 2 ENGINE - REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT						
	Notes CATEGORY 7						
SB 30475 R2 Engine 2 SB - Open #222	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30475 R3 PART A Engine 1 SB - Open #153	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT						
	Notes CATEGORY 7						
SB 30475 R3 PART B Engine 1 SB - Open #242	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT						
	Notes CATEGORY 7						
SB 30475 R3 Engine 1 SB - Open #263	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30475 R3 PART A Engine 2 SB - Open #357	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30475 R3 PART B Engine 2 SB - Open #313	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT Notes CATEGORY 7						
SB 30475 R3 Engine 2 SB - Open #84	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30478 Engine 1 SB - Open #368	NO. 1 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN Notes CATEGORY 5						
SB 30478 Engine 2 SB - Open #269	NO. 2 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN Notes CATEGORY 5						
SB 30478 R1 Engine 1 SB - Open #218	NO. 1 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN Notes CATEGORY 5						
SB 30478 R1 Engine 2 SB - Open #46	NO. 2 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN Notes CATEGORY 5						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30478 R2 Engine 1 SB - Complied With #163	NO. 1 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN	18-APR-2014 H: 623.30 C: 675					
	Notes COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN NO. PW500-72-30478, NO DEFECTS NOTED. CATEGORY 5						
SB 30478 R2 Engine 2 SB - Complied With #60	NO. 2 ENGINE - REPLACEMENT/FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN	18-APR-2014 H: 623.30 C: 675					
	Notes COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN NO. PW500-72-30478, NO DEFECTS NOTED. CATEGORY 5						
SB 30478 R3 Engine 1 SB - Open #162	NO. 1 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30478 R3 Engine 2 SB - Open #361	NO. 2 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30478 R4 Engine 1 SB - N/A #298	NO. 1 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN	24-AUG-2016 H: 1227.30 C: 1304					
	Notes NOT APPLICABLE CATEGORY 3						
SB 30478 R4 Engine 2 SB - N/A #100	NO. 2 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN	24-AUG-2016 H: 1227.30 C: 1304					
	Notes NOT APPLICABLE CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30480 Engine 1 SB - Open #81	NO. 1 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS, SERVICE BULLETIN Notes CATEGORY 7						
SB 30480 Engine 2 SB - Open #200	NO. 2 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS, SERVICE BULLETIN Notes CATEGORY 7						
SB 30482 Engine 1 SB - Open #253	NO. 1 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT, SERVICE BULLETIN Notes CATEGORY 3						
SB 30482 Engine 2 SB - Open #334	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT, SERVICE BULLETIN Notes CATEGORY 3						
SB 30482 R1 Engine 1 SB - Open #273	NO. 1 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT, SERVICE BULLETIN Notes CATEGORY 3						
SB 30482 R1 Engine 2 SB - Open #38	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT, SERVICE BULLETIN Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30482 R2 Engine 1 SB - Complied With #171	NO. 1 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT, SERVICE BULLETIN	17-APR-2014 H: 623.30 C: 675					
	Notes COMPLIED WITH - C/W BY PRATT AND WHITNEY ENGINE SERVICES INC CRS L2QR166Y REF SALES ORDER 182019 CATEGORY 3						
SB 30482 R2 Engine 2 SB - Complied With #119	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT, SERVICE BULLETIN	17-APR-2014 H: 623.30 C: 675					
	Notes COMPLIED WITH - C/W BY PRATT AND WHITNEY ENGINE SERVICES INC CRS L2QR166Y REF SALES ORDER 182019 CATEGORY 3						
SB 30482 R3 Engine 1 SB - Open #38	NO. 1 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30482 R3 Engine 2 SB - Open #161	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30483 Engine 1 SB - Open #137	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30483 Engine 2 SB - Open #75	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30483 R1 Engine 1 SB - Open #1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30483 R1 Engine 2 SB - Open #56	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30483 R2 Engine 1 SB - Open #25	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30483 R2 Engine 2 SB - Open #331	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30483 R3 Engine 1 SB - Open #235	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2), SERVICE BULLETIN Notes CATEGORY 10						
SB 30483 R3 Engine 2 SB - Open #171	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2), SERVICE BULLETIN Notes CATEGORY 10						
SB 30487 Engine 1 SB - Open #144	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30487 Engine 2 SB - Open #117	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
SB 30487 R1 Engine 1 SB - Open #223	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
SB 30487 R1 Engine 2 SB - Open #49	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
SB 30487 R2 Engine 1 SB - Open #327	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
SB 30487 R2 Engine 2 SB - Open #290	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN						
SB 30487 R3 Engine 1 SB - Open #208	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30487 R3 Engine 2 SB - Open #271	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30488 Engine 1 SB - Open #3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 5						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30488 Engine 2 SB - Open #17	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R1 Engine 1 SB - Open #109	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R1 Engine 2 SB - Open #55	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R2 Engine 1 SB - Open #2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R2 Engine 2 SB - Open #246	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R3 Engine 1 SB - Open #71	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30488 R3 Engine 2 SB - Open #79	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R4 Engine 1 SB - Open #75	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R4 Engine 2 SB - Open #5	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R5 Engine 1 SB - Open #118	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30488 R5 Engine 2 SB - Open #114	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 5						
SB 30491 Engine 1 SB - Open #127	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30491 Engine 2 SB - Open #26	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30491 R1 Engine 1 SB - Open #50	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30491 R1 Engine 2 SB - Open #231	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30491 R2 Engine 1 SB - Open #154	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30491 R2 Engine 2 SB - Open #43	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30492 Engine 1 SB - Open #172	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30492 Engine 2 SB - Open #260	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30492 R1 Engine 1 SB - Open #250	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30492 R1 Engine 2 SB - Open #267	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30492 R2 Engine 1 SB - Open #183	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30492 R2 Engine 2 SB - Open #198	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30492 R3 Engine 1 SB - Open #238	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30492 R3 Engine 2 SB - Open #66	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 6						
SB 30492 R4 Engine 1 SB - Open #157	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 6						
SB 30492 R4 Engine 2 SB - Open #215	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN Notes CATEGORY 6						
SB 30494 Engine 1 SB - Open #326	NO. 1 ENGINE - REPLACEMENT OF FAN CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30494 Engine 2 SB - Open #127	NO. 2 ENGINE - REPLACEMENT OF FAN CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30495 Engine 1 SB - Open #143	NO. 1 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498), SERVICE BULLETIN Notes CATEGORY 10						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30495 Engine 2 SB - Open #354	NO. 2 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30495 R1 Engine 1 SB - Open #63	NO. 1 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE, SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30495 R1 Engine 2 SB - Open #241	NO. 2 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE, SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30497 Engine 1 SB - Open #198	NO. 1 ENGINE - CONVERSION OF PW535E ENGINE BUILD SPECIFICATION 1229 TO 1348 (NETJETS SPECIFIC MAINTENANCE PROGRAM), SERVICE BULLETIN						
	Notes CATEGORY 8						
SB 30497 Engine 2 SB - Open #188	NO. 2 ENGINE - CONVERSION OF PW535E ENGINE BUILD SPECIFICATION 1229 TO 1348 (NETJETS SPECIFIC MAINTENANCE PROGRAM), SERVICE BULLETIN						
	Notes CATEGORY 8						
SB 30498 Engine 1 SB - Open #240	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30498 Engine 2 SB - Open #94	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30498 R02 Engine 1 SB - Open #101	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30498 R02 Engine 2 SB - Open #136	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30498 R03 Engine 1 SB - Open #284	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30498 R03 Engine 2 SB - Open #211	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						
SB 30498 R1 Engine 1 SB - Open #220	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30498 R1 Engine 2 SB - Open #338	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30500 Engine 1 SB - Complied With #152	NO. 1 ENGINE - REPLACEMENT OF PREFORMED PACKING, SERVICE BULLETIN						
	Notes COMPLIED WITH CATEGORY 7	02-JUN-2015 H: 850.20 C: 933					
SB 30500 Engine 2 SB - Complied With #138	NO. 2 ENGINE - REPLACEMENT OF PREFORMED PACKING, SERVICE BULLETIN						
	Notes COMPLIED WITH CATEGORY 7	02-JUN-2015 H: 850.20 C: 933					
SB 30502 Engine 1 SB - Open #74	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 Engine 2 SB - Open #69	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R1 Engine 1 SB - Open #300	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30502 R1 Engine 2 SB - Open #141	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R2 PART B Engine 1 SB - Open #331	NO. 1 ENGINE - ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN ACCESSORY GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R2 PART A Engine 1 SB - Open #270	NO. 1 ENGINE - ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN FUEL CONTROL GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R2 Engine 1 SB - Open #96	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R2 PART B Engine 2 SB - Open #284	NO. 2 ENGINE - ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN ACCESSORY GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R2 PART A Engine 2 SB - Open #218	NO. 2 ENGINE - ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN FUEL CONTROL GEARSHAFT SEAL						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30502 R2 Engine 2 SB - Open #252	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R3 PART B Engine 1 SB - Open #112	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACE ACCESSORY GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R3 PART A Engine 1 SB - Open #14	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACE FUEL CONTROL GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R3 Engine 1 SB - Open #241	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R3 PART B Engine 2 SB - Open #102	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACE ACCESSORY GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R3 PART A Engine 2 SB - Open #105	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACE FUEL CONTROL GEARSHAFT SEAL						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30502 R3 Engine 2 SB - Open #251	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R4 PART B Engine 1 SB - Open #305	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN ACCESSORY GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R4 PART A Engine 1 SB - Open #43	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN FUEL CONTROL GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R4 Engine 1 SB - Open #350	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30502 R4 PART B Engine 2 SB - Open #299	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN ACCESSORY GEARSHAFT SEAL						
	Notes CATEGORY 7						
SB 30502 R4 PART A Engine 2 SB - Open #248	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN FUEL CONTROL GEARSHAFT SEAL						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30502 R4 Engine 2 SB - Open #288	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30503 Engine 1 SB - Open #367	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30503 Engine 2 SB - Open #295	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30504 Engine 1 SB - Open #224	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30504 Engine 2 SB - Open #169	NO. 2 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30504 R1 Engine 1 SB - Open #361	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30504 R1 Engine 2 SB - Open #61	NO. 2 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30504 R2 Engine 1 SB - Open #62	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30504 R2 Engine 2 SB - Open #296	NO. 2 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30505 Engine 1 SB - Open #272	NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30505 Engine 2 SB - Open #125	NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30505 R1 Engine 1 SB - Open #219	NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30505 R1 Engine 2 SB - Open #183	NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30505 R2 Engine 1 SB - Complied With #289	NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN	02-JUN-2015 H: 850.20 C: 933					
	Notes COMPLIED WITH CATEGORY 3						
SB 30505 R2 Engine 2 SB - Complied With #364	NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN	02-JUN-2015 H: 850.20 C: 933					
	Notes COMPLIED WITH CATEGORY 3						
SB 30505 R4 Engine 1 SB - Open #441	TURBOFAN ENGINE BLEED OFF VALVE (BOV) GASKETS - REPLACEMENT OF						
SB 30505 R4 Engine 2 SB - Open #440	TURBOFAN ENGINE BLEED OFF VALVE (BOV) GASKETS - REPLACEMENT OF						
SB 30505R3 Engine 1 SB - Open #408	TURBOFAN ENGINE BLEED OFF VALVE (BOV) GASKETS - REPLACEMENT OF - CATEGORY 3						
SB 30505R3 Engine 2 SB - Open #407	TURBOFAN ENGINE BLEED OFF VALVE (BOV) GASKETS - REPLACEMENT OF - CATEGORY 3						
SB 30506 Engine 1 SB - Open #156	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30506 Engine 2 SB - Open #9	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30506 R1 Engine 1 SB - Open #55	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30506 R1 Engine 2 SB - Open #335	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30506 R2 Engine 1 SB - Open #126	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30506 R2 Engine 2 SB - Open #18	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30509 Engine 1 SB - Open #160	NO. 1 ENGINE - INSPECTION OF WIRING HARNESS T6 CONNECTION, SERVICE BULLETIN						
	Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30509 Engine 2 SB - Open #298	NO. 2 ENGINE - INSPECTION OF WIRING HARNESS T6 CONNECTION, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30511 Engine 1 SB - Open #357	NO. 1 ENGINE - RE-TORQUEING OF AGB COVER BOLTS OR NUTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30511 Engine 2 SB - Open #53	NO. 2 ENGINE - RE-TORQUEING OF AGB COVER BOLTS OR NUTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30511 R1 Engine 1 SB - Open #266	NO. 1 ENGINE - RE-TORQUEING OF AGB COVER BOLTS OR NUTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30511 R1 Engine 2 SB - Open #329	NO. 2 ENGINE - RE-TORQUEING OF AGB COVER BOLTS OR NUTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30511 R2 Engine 1 SB - Open #422	TURBOFAN ENGINE - AGB COVER BOLTS OR NUTS- RE-TORQUEING OF						
SB 30511 R2 Engine 2 SB - Open #421	TURBOFAN ENGINE - AGB COVER BOLTS OR NUTS- RE-TORQUEING OF						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30516 Engine 1 SB - Open #76	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30516 Engine 2 SB - Open #7	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30516 R1 Engine 1 SB - Open #66	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30516 R1 Engine 2 SB - Open #122	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30516 R2 Engine 1 SB - Open #141	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30516 R2 Engine 2 SB - Open #21	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30517 Engine 1 SB - Open #77	NO. 1 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30517 Engine 2 SB - Open #68	NO. 2 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30517 R1 Engine 1 SB - Open #9	NO. 1 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30517 R1 Engine 2 SB - Open #194	NO. 2 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30519 Engine 1 SB - Open #105	NO. 1 ENGINE - INSPECTION OF IGNITION LEAD, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30519 Engine 2 SB - Open #59	NO. 2 ENGINE - INSPECTION OF IGNITION LEAD, SERVICE BULLETIN						
	Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30519 R1 Engine 1 SB - N/A #195	NO. 1 ENGINE - INSPECTION OF IGNITION LEAD, SERVICE BULLETIN	24-AUG-2016 H: 1227.30 C: 1304					
	Notes NOT APPLICABLE CATEGORY 3						
SB 30519 R1 Engine 2 SB - N/A #263	NO. 2 ENGINE - INSPECTION OF IGNITION LEAD, SERVICE BULLETIN	24-AUG-2016 H: 1227.30 C: 1304					
	Notes NOT APPLICABLE CATEGORY 3						
SB 30521 Engine 1 SB - Open #175	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30521 Engine 2 SB - Open #342	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30521 R1 Engine 1 SB - Open #335	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30521 R1 Engine 2 SB - Open #349	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30522 Engine 1 SB - Open #278	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30522 Engine 2 SB - Open #116	NO. 2 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30522 R1 Engine 1 SB - Open #159	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30522 R1 Engine 2 SB - Open #294	NO. 2 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30522 R2 Engine 1 SB - Open #94	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY SB PW500-72-30529 R1), SERVICE BULLETIN						
	Notes CATEGORY 10						
SB 30522 R2 Engine 2 SB - Open #348	NO. 2 ENGINE - REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY SB PW500-72-30529 R1), SERVICE BULLETIN						
	Notes CATEGORY 10						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30523 Engine 1 SB - Open #206	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN Notes CATEGORY 7						
SB 30523 Engine 2 SB - Open #35	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN Notes CATEGORY 7						
SB 30523 R1 Engine 1 SB - Open #347	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN Notes CATEGORY 7						
SB 30523 R1 Engine 2 SB - Open #166	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN Notes CATEGORY 7						
SB 30524 Engine 1 SB - Open #35	NO. 1 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30524 Engine 2 SB - Open #302	NO. 2 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30524 R1 Engine 1 SB - Open #64	NO. 1 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes CATEGORY 7						
SB 30524 R1 Engine 2 SB - Open #257	NO. 2 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes CATEGORY 7						
SB 30524 R2 Engine 1 SB - Open #234	NO. 1 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30524 R2 Engine 2 SB - Open #365	NO. 2 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes CATEGORY 3						
SB 30524 R3 Engine 1 SB - Complied With #307	NO. 1 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes COMPLIED WITH CATEGORY 3					21-APR-2016 H: 1156.20 C: 1221	
SB 30524 R3 Engine 2 SB - Complied With #173	NO. 2 ENGINE - REPLACEMENT OF FMU TO FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN Notes COMPLIED WITH CATEGORY 3					21-APR-2016 H: 1156.20 C: 1221	

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30525 Engine 1 SB - Open #142	NO. 1 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30525 Engine 2 SB - Open #25	NO. 2 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN Notes CATEGORY 7						
SB 30525 R1 Engine 1 SB - Open #230	NO. 1 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN Notes CATEGORY 8						
SB 30525 R1 Engine 2 SB - Open #147	NO. 2 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN Notes CATEGORY 8						
SB 30525R2 Engine 1 SB - Open #420	TURBOFAN ENGINE - ENGINE SHIPPING CONTAINER - REPLACEMENT OF						
SB 30525R2 Engine 2 SB - Open #419	TURBOFAN ENGINE - ENGINE SHIPPING CONTAINER - REPLACEMENT OF						
SB 30527 Engine 1 SB - Open #299	NO. 1 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN Notes CATEGORY 9						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30527 Engine 2 SB - Open #152	NO. 2 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN						
	Notes CATEGORY 9						
SB 30528 Engine 1 SB - Open #349	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30528 Engine 2 SB - Open #242	NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30528 R1 Engine 1 SB - Open #204	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30528 R1 Engine 2 SB - Open #16	NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30528 R2 Engine 1 SB - Open #222	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30528 R2 Engine 2 SB - Open #163	NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30529 Engine 1 SB - Open #138	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30529 Engine 2 SB - Open #144	NO. 2 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30529 R1 Engine 1 SB - Complied With #322	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes COMPLIED WITH CATEGORY 3				19-APR-2016 H: 1156.20 C: 1221		
SB 30529 R1 Engine 2 SB - Complied With #235	NO. 2 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN						
	Notes COMPLIED WITH CATEGORY 3				18-APR-2016 H: 1156.20 C: 1221		
SB 30530 Engine 1 SB - Complied With #334	NO. 1 ENGINE - REPLACEMENT OF ADAPTER FOR THE FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN						
	Notes COMPLIED WITH CATEGORY 3				21-APR-2016 H: 1156.20 C: 1221		

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30530 Engine 2 SB - Complied With #6	NO. 2 ENGINE - REPLACEMENT OF ADAPTER FOR THE FLOWMETER FUEL PRESSURE TUBE, SERVICE BULLETIN	21-APR-2016 H: 1156.20 C: 1221					
	Notes COMPLIED WITH CATEGORY 3						
SB 30531 Engine 1 SB - Open #174	NO. 1 ENGINE - INSPECTION OF FUEL SHUT OFF VALVE AIR GAP, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30531 Engine 2 SB - Open #98	NO. 2 ENGINE - INSPECTION OF FUEL SHUT OFF VALVE AIR GAP, SERVICE BULLETIN						
	Notes CATEGORY 3						
SB 30532 Engine 1 SB - Open #232	NO. 1 ENGINE - REPLACEMENT OF RETAINING RINGS, SERVICE BULLETIN						
	Notes CATEGORY 9						
SB 30532 Engine 2 SB - Open #253	NO. 2 ENGINE - REPLACEMENT OF RETAINING RINGS, SERVICE BULLETIN						
	Notes CATEGORY 9						
SB 30534 Engine 1 SB - Open #151	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30534 Engine 2 SB - Open #210	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30534 R1 Engine 1 SB - Open #27	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30534 R1 Engine 2 SB - Open #95	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30534 R2 Engine 1 SB - Open #99	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30534 R2 Engine 2 SB - Open #339	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30536 Engine 1 SB - Open #40	NO. 1 ENGINE - REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS AND BUS BARS, SERVICE BULLETIN						
	Notes CATEGORY 6						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30536 Engine 2 SB - Open #71	NO. 2 ENGINE - REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS AND BUS BARS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30538 Engine 1 SB - Open #114	NO. 1 ENGINE - REPLACEMENT OF ENGINE WIRING HARNESS BOLTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30538 Engine 2 SB - Open #264	NO. 2 ENGINE - REPLACEMENT OF ENGINE WIRING HARNESS BOLTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30538 R1 Engine 1 SB - Open #280	NO. 1 ENGINE - REPLACEMENT OF ENGINE WIRING HARNESS BOLTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30538 R1 Engine 2 SB - Open #186	NO. 2 ENGINE - REPLACEMENT OF ENGINE WIRING HARNESS BOLTS, SERVICE BULLETIN						
	Notes CATEGORY 6						
SB 30539 Engine 1 SB - Open #317	NO. 1 ENGINE - REPLACEMENT OF FUEL SUPPLY PAD, SERVICE BULLETIN						
	Notes CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30539 Engine 2 SB - Open #170	NO. 2 ENGINE - REPLACEMENT OF FUEL SUPPLY PAD, SERVICE BULLETIN						
	Notes CATEGORY 7						
SB 30539R1 Engine 1 SB - Open #405	TURBOFAN ENGINE FUEL SUPPLY PAD - REPLACEMENT OF						
SB 30539R1 Engine 2 SB - Open #405	TURBOFAN ENGINE FUEL SUPPLY PAD - REPLACEMENT OF						
SB 30549 Engine 1 SB - Open #374	REPLACEMENT OF LPT VANE FIBER PACKING						
SB 30549 Engine 2 SB - Open #374	REPLACEMENT OF LPT VANE FIBER PACKING						
SB 30551 Engine 1 SB - Open #375	REPLACEMENT OF NO. 3 BEARING						
SB 30551 Engine 2 SB - Open #375	REPLACEMENT OF NO. 3 BEARING						
SB 30553 Engine 1 SB - Open #377	TURBOFAN ENGINE INTERMEDIATE CASE - REPLACEMENT OF IC NUMBER						
SB 30553 Engine 2 SB - Open #377	TURBOFAN ENGINE INTERMEDIATE CASE - REPLACEMENT OF IC NUMBER						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30554 Engine 1 SB - Open #417	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30554 Engine 2 SB - Open #416	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30554 R1 Engine 1 SB - Open #421	TURBOFAN ENGINE - INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30554 R1 Engine 2 SB - Open #420	TURBOFAN ENGINE - INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30554R2 Engine 1 SB - Open #427	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30554R2 Engine 2 SB - Open #426	TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE - REPLACEMENT OF						
SB 30555 Engine 1 SB - Open #423	TURBOFAN ENGINE HYDRAULIC PUMP DRIVE GEARSHAFT SPLINES - INSPECTION OF						
SB 30555 Engine 2 SB - Open #422	TURBOFAN ENGINE HYDRAULIC PUMP DRIVE GEARSHAFT SPLINES - INSPECTION OF						
SB 30559 Engine 1 SB - Open #409	TURBOFAN ENGINE NO. 3 BEARING - REPLACEMENT OF - CATEGORY 7						
SB 30559 Engine 2 SB - Open #408	TURBOFAN ENGINE NO. 3 BEARING - REPLACEMENT OF - CATEGORY 7						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30559 R1 Engine 1 SB - Open #411	TURBOFAN ENGINE NO. 3 BEARING - REPLACEMENT OF CATEGORY 7						
SB 30559 R1 Engine 2 SB - Open #410	TURBOFAN ENGINE NO. 3 BEARING - REPLACEMENT OF CATEGORY 7						
SB 30559 R2 Engine 1 SB - Open #413	NO. 3 BEARING - REPLACEMENT OF - CATEGORY 7						
SB 30559 R2 Engine 2 SB - Open #412	NO. 3 BEARING - REPLACEMENT OF - CATEGORY 7						
SB 30559R3 Engine 1 SB - Open #415	TURBOFAN ENGINE-NO. 3 BEARING - REPLACEMENT OF - CATEGORY 7						
SB 30559R3 Engine 2 SB - Open #414	TURBOFAN ENGINE-NO. 3 BEARING - REPLACEMENT OF - CATEGORY 7						
SB 30559R4 Engine 1 SB - Open #424	TURBOFAN ENGINE - NO. 3 BEARING - REPLACEMENT OF						
SB 30559R4 Engine 2 SB - Open #423	TURBOFAN ENGINE - NO. 3 BEARING - REPLACEMENT OF						
SB 30560 Engine 1 SB - Open #412	TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL - INSPECTION/REPAIR OF CATEGORY 3						
SB 30560 Engine 2 SB - Open #411	TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL - INSPECTION/REPAIR OF CATEGORY 3						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30560 R1 Engine 1 SB - Open #435	TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL - INSPECTION/REPAIR OF (CATEGORY 3)						
SB 30560 R1 Engine 2 SB - Open #434	TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL - INSPECTION/REPAIR OF (CATEGORY 3)						
SB 30560R2 Engine 1 SB - N/A #446	SERVICE BULLETIN - TURBOFAN ENGINE - ELECTRONIC ENGINE CONTROL - INSPECTION/REPAIR OF	22-SEP-2023					
	Notes FOUND TO BE N/A DUE TO EEC S/N: 2011050012 INSTALLED AND IS NOT APPLICABLE TO AFFECTED EEC'S						
SB 30560R2 Engine 2 SB - N/A #445	SERVICE BULLETIN - TURBOFAN ENGINE - ELECTRONIC ENGINE CONTROL - INSPECTION/REPAIR OF	22-SEP-2023					
	Notes FOUND TO BE N/A DUE TO EEC S/N: 2011070024 INSTALLED AND IS NOT APPLICABLE TO AFFECTED EEC'S						
SB 30563 Engine 1 SB - Open #425	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563 Engine 2 SB - Open #424	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563 R10 Engine 1 SB - Open #440	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563 R10 Engine 2 SB - Open #439	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563 R4 Engine 1 SB - Open #430	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30563 R4 Engine 2 SB - Open #429	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R5 Engine 1 SB - Open #433	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R5 Engine 2 SB - Open #432	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R6 Engine 1 SB - Open #434	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R6 Engine 2 SB - Open #433	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R7 Engine 1 SB - Open #436	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R7 Engine 2 SB - Open #435	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF (CATEGORY 7)						
SB 30563 R8 Engine 1 SB - Open #437	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563 R8 Engine 2 SB - Open #436	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563 R9 Engine 1 SB - Open #438	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30563 R9 Engine 2 SB - Open #437	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563R1 Engine 1 SB - Open #426	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563R1 Engine 2 SB - Open #425	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563R2 Engine 1 SB - Open #428	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563R2 Engine 2 SB - Open #427	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563R3 Engine 1 SB - Open #429	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30563R3 Engine 2 SB - Open #428	TURBOFAN ENGINE TURBINE SUPPORT CASE - REPLACEMENT OF						
SB 30568 Engine 1 SB - Open #439	TURBOFAN ENGINE NO. 4 BEARING FRONT AND REAR SEAL RUNNERS - REPLACEMENT OF						
SB 30568 Engine 2 SB - Open #438	TURBOFAN ENGINE NO. 4 BEARING FRONT AND REAR SEAL RUNNERS - REPLACEMENT OF						
SB 30571 Engine 1 SB - Open #444	SERVICE BULLETIN - TURBOFAN ENGINE - GAS GENERATOR TO TURBINE SUPPORT CASE BOLTS - INSPECTION OF						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30571 Engine 2 SB - Open #443	SERVICE BULLETIN - TURBOFAN ENGINE - GAS GENERATOR TO TURBINE SUPPORT CASE BOLTS - INSPECTION OF						
SB 500-34-0020 IN01 Airframe SB - Open #2118	NAVIGATION - NXT-600 NACV PARAMETER ADJUSTMENT						
SB 505-00-0001 Airframe SB - N/A #1370	GENERAL - REMOVAL OF ICING LIMITATION ABOVE 30,000 FT (SUPERSEDED BY SB 505-00-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-00-0001 R01 Airframe SB - Complied With #1781	GENERAL - REMOVAL OF ICING LIMITATION ABOVE 30,000 FT, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-00-0002 Airframe SB - N/A #1637	GENERAL - FAA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-00-0003 Airframe SB - N/A #650	GENERAL - ANAC CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-00-0004 Airframe SB - N/A #582	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS (SUPERSEDED BY SB 505-00-0004 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0004 R01 Airframe SB - N/A #221	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-00-0005 Airframe SB - Open #193	GENERAL - INSPECTION OF THE TURNBUCKLES (SUPERSEDED BY SB 505-00-0005 REV 01), SERVICE BULLETIN						
SB 505-00-0005 R01 Airframe SB - N/A #95	GENERAL - INSPECTION OF THE TURNBUCKLES, SERVICE BULLETIN	11-JUN-2012 H: 32.80 L: 37					
	Notes NOT APPLICABLE - N/A PER AIRCRAFT S/N						
SB 505-00-0005 R01 PART II Airframe SB - N/A #528	INSPECTION GENERAL - INSPECTION OF THE TURNBUCKLES, SERVICE BULLETIN OF THE FREE FALL SYSTEM	11-JUN-2012 H: 32.80 L: 37					
	Notes NOT APPLICABLE - N/A PER AIRCRAFT S/N						
SB 505-00-0005 R01 PART I Airframe SB - N/A #565	INSPECTION GENERAL - INSPECTION OF THE TURNBUCKLES, SERVICE BULLETIN OF THE TURNBUCKLES ALL SYSTEM	11-JUN-2012 H: 32.80 L: 37					
	Notes NOT APPLICABLE - N/A PER AIRCRAFT S/N						
SB 505-00-0006 Airframe SB - Open #1943	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0006 REV 01), SERVICE BULLETIN						
SB 505-00-0006 R02 Airframe SB - Open #2174	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G1000 AVIONICS						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0006 R03 Airframe SB - Open #2177	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G1000 AVIONICS						
SB 505-00-0007 Airframe SB - Open #989	GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL (SUPERSEDED BY SB 505-00-0007 REV 01), SERVICE BULLETIN						
SB 505-00-0007 PART I Airframe SB - Open #334	INSTALLATION GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL (SUPERSEDED BY SB 505-00-0007 REV 01), SERVICE BULLETIN OF INSTRUMENTS						
SB 505-00-0007 PART II Airframe SB - Open #1430	REMOVAL GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL (SUPERSEDED BY SB 505-00-0007 REV 01), SERVICE BULLETIN OF INSTRUMENTS.						
SB 505-00-0007 R01 Airframe SB - N/A #1354	GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL (SUPERSEDED BY SB 505-00-0007 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-00-0007 R01 PART I Airframe SB - N/A #836	INSTALLATION GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL (SUPERSEDED BY SB 505-00-0007 REV 02), SERVICE BULLETIN OF INSTRUMENTS						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-00-0007 R01 PART II Airframe SB - N/A #986	REMOVAL GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL (SUPERSEDED BY SB 505-00-0007 REV 02), SERVICE BULLETIN OF INSTRUMENTS						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0007 R02 Airframe SB - N/A #319	GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL, SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-00-0007 R02 PART I Airframe SB - N/A #1671	INSTALLATION GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL, SERVICE BULLETIN OF INSTRUMENTS						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-00-0007 R02 PART II Airframe SB - N/A #1745	REMOVAL GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL, SERVICE BULLETIN OF INSTRUMENTS						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-00-0008 Airframe SB - N/A #162	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0008 R01 Airframe SB - N/A #1880	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0008 R02 Airframe SB - N/A #1397	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0008 R03 Airframe SB - N/A #588	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0008 R04 Airframe SB - N/A #829	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0008 R05 Airframe SB - N/A #1504	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0008 R06 Airframe SB - N/A #1188	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 07), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0008 R07 Airframe SB - Open #1624	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY SB 505-00-0008 REV 08), SERVICE BULLETIN						
SB 505-00-0008 R08 Airframe SB - Open #1537	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY 505-00-0008 REV 09), SERVICE BULLETIN						
SB 505-00-0008 R09 Airframe SB - Open #1294	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE, SERVICE BULLETIN						
SB 505-00-0008 R10 Airframe SB - Open #1160	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (SUPERSEDED BY 505-00-0008 REV 11), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0008 R11 Airframe SB - Open #1255	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE, SERVICE BULLETIN						
SB 505-00-0008 R12 Airframe SB - Open #1989	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (REV. 12)						
SB 505-00-0008 R13 Airframe SB - Open #2008	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (REV. 13)						
SB 505-00-0008 R14 Airframe SB - Open #2015	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE (REV. 14)						
SB 505-00-0008 R15 Airframe SB - Open #2066	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R16 Airframe SB - Open #2093	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R17 Airframe SB - Open #2109	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R18 Airframe SB - Open #2112	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R19 Airframe SB - Open #2161	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R20 Airframe SB - Open #2167	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0008 R21 Airframe SB - Open #2201	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R22 Airframe SB - Open #2203	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R23 Airframe SB - Open #2213	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R24 Airframe SB - Open #2217	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R25 Airframe SB - Open #2218	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R26 Airframe SB - Open #2225	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R28 Airframe SB - Open #2242	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0009 Airframe SB - N/A #1644	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS (SUPERSEDED BY SB 505-00-0009 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0009 R01 Airframe SB - N/A #350	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS (SUPERSEDED BY SB 505-00-0009 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0009 R02 Airframe SB - N/A #1571	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-00-0009 R03 Airframe SB - Open #2012	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS (REV. 3)						
SB 505-00-0010 Airframe SB - Open #158	GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0010 REV 01), SERVICE BULLETIN						
SB 505-00-0010 PART I Airframe SB - Open #1281	PERFORM GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0010 REV 01), SERVICE BULLETIN THE ELECTRICAL MODIFICATION ON W201 TO CHANGE THE LOGIC OF THE QUICK-DISCONNECT BUTTON						
SB 505-00-0010 PART II Airframe SB - Open #1679	PERFORM GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0010 REV 01), SERVICE BULLETIN THE THE ELECTRICAL MODIFICATION ON W207 TO CHANGE THE LOGIC OF THE QUICK-DISCONNECT BUTTON						
SB 505-00-0010 R01 Airframe SB - Open #1321	GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0010 REV 02), SERVICE BULLETIN						
SB 505-00-0010 R01 PART I Airframe SB - Open #1385	PERFORM GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0010 REV 02), SERVICE BULLETIN THE ELECTRICAL MODIFICATION ON W201 TO CHANGE THE LOGIC OF THE QUICK-DISCONNECT BUTTON						
SB 505-00-0010 R01 PART II Airframe SB - Open #407	PERFORM GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0010 REV 02), SERVICE BULLETIN THE ELECTRICAL MODIFICATION ON W207 TO CHANGE THE LOGIC OF THE QUICK-DISCONNECT BUTTON						
SB 505-00-0010 R02 Airframe SB - Open #1610	GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0010 R02 PART I Airframe SB - Open #135	PERFORM GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN THE ELECTRICAL MODIFICATION ON W201 TO CHANGE THE LOGIC OF THE QUICK-DISCONNECT BUTTON						
SB 505-00-0010 R02 PART II Airframe SB - Open #122	PERFORM GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN THE ELECTRICAL MODIFICATION ON W207 TO CHANGE THE LOGIC OF THE QUICK-DISCONNECT BUTTON						
SB 505-00-0011 Airframe SB - Open #1473	GENERAL - CONVERSION FROM FAA TO ANAC CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
SB 505-00-0012 Airframe SB - N/A #1033	GENERAL - G3000 - CUSTOMIZED UNITS CONFIGURATION (IMPERIAL UNITS), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0013 Airframe SB - N/A #78	GENERAL - G1000 - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0013 R01 Airframe SB - Open #2086	GENERAL - G1000 - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS						
SB 505-00-0013 R02 IN01 Airframe SB - Open #2153	GENERAL - G1000 - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS						
SB 505-00-0014 Airframe SB - N/A #12	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0014 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0014 R01 Airframe SB - N/A #1669	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0014 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0014 R02 Airframe SB - N/A #185	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0014 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-00-0014 R03 Airframe SB - Open #70	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY SB 505-00-0014 REV 04), SERVICE BULLETIN						
SB 505-00-0014 R04 Airframe SB - N/A #1322	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0015 Airframe SB - N/A #144	GENERAL - G3000 - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0016 Airframe SB - Superseded #298	GENERAL - G3000 - CONVERSION FROM FAA TO TCCA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0016 R01 Airframe SB - Open #2181	GENERAL - G3000 - CONVERSION FROM FAA TO TCCA CERTIFICATION BASIS REQUIREMENTS						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0017 Airframe SB - N/A #308	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY 505-00-0017 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-00-0017 R01 Airframe SB - N/A #1141	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (SUPERSEDED BY 505-00-0017 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0017 R03 PART II Airframe SB - N/A #1453	ACCOMPLISH, SERVICE BULLETIN ADDITIONAL ACTION						
	Notes NOT APPLICABLE						
SB 505-00-0017 R03 PART I Airframe SB - N/A #1941	ACCOMPLISH, SERVICE BULLETIN CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS						
	Notes NOT APPLICABLE						
SB 505-00-0017 R03 Airframe SB - N/A #640	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0017 R04 Airframe SB - Open #2003	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS (REV. 4)						
SB 505-00-0017 R05 Airframe SB - Open #2146	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0017 R06 Airframe SB - Open #2191	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS						
SB 505-00-0018 Airframe SB - N/A #5	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0018 R01 Airframe SB - Open #2020	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS (REV. 1)						
SB 505-00-0018 R02 Airframe SB - Open #2087	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0018 R05 Airframe SB - Open #2187	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0019 Airframe SB - Open #1701	GENERAL - INSPECTION OF THE TURNBUCKLES, SERVICE BULLETIN						
SB 505-00-0020 Airframe SB - N/A #1110	GENERAL - G1000 - CONVERSION FROM EASA TO ANAC CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-00-0020 R01 Airframe SB - Open #1983	GENERAL - G1000 - CONVERSION FROM EASA TO ANAC CERTIFICATION BASIS REQUIREMENTS (REV. 1)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-006 R01 Airframe SB - N/A #230	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G1000 AVIONICS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-21-0001 Airframe SB - Complied With #1708	AIR CONDITIONING - CPCS CONTROLLER (ECMU) HARDWARE CORRECTION, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-21-0002 Airframe SB - N/A #1095	AIR CONDITIONING - INSPECTION/CORRECTION OF THE BAGGAGE HEATING WIRING, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-21-0002 PART I Airframe SB - N/A #1752	INSPECTION AIR CONDITIONING - INSPECTION/CORRECTION OF THE BAGGAGE HEATING WIRING, SERVICE BULLETIN OF THE BAGGAGE HEATING WIRING	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-21-0002 PART II Airframe SB - N/A #665	MODIFICATION AIR CONDITIONING - INSPECTION/CORRECTION OF THE BAGGAGE HEATING WIRING, SERVICE BULLETIN OF THE BAGGAGE HEATING WIRING	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-21-0003 Airframe SB - Complied With #800	AIR CONDITIONING - PRESSURE RELIEF VALVE (PRV) REPLACEMENT, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-21-0004 Airframe SB - Complied With #1223	AIR CONDITIONING - REPLACEMENT OF THE CABIN EVAPORATOR, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-21-0005 Airframe SB - Complied With #583	AIR CONDITIONING - REPLACEMENT OF FLOW CONTROL SHUT OFF VALVE (FCSOV) (SUPERSEDED BY SB 505-21-0005 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-21-0005 R01 Airframe SB - N/A #1868	AIR CONDITIONING - REPLACEMENT OF FLOW CONTROL SHUT OFF VALVE (FCSOV), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-21-0006 Airframe SB - N/A #661	AIR CONDITIONING - COCKPIT AIR DISTRIBUTION IMPROVEMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-21-0007 Airframe SB - Complied With #1629	AIR CONDITIONING - REPLACEMENT OF ECS TEMPERATURE CONTROLLER TC-6 (SUPERSEDED BY SB 505-21-0007 REV 01), SERVICE BULLETIN	06-SEP-2012 H: 114.00 L: 135					
	Notes COMPLIED WITH - R & RD ECS CONTROLLER PER EMBRAER SB 505-21-0007						
SB 505-21-0007 R02 Airframe SB - Open #632	AIR CONDITIONING - REPLACEMENT OF ECS TEMPERATURE CONTROLLER TC-6, SERVICE BULLETIN						
SB 505-21-0007/01 Airframe SB - Open #916	AIR CONDITIONING - REPLACEMENT OF ECS TEMPERATURE CONTROLLER TC-6 (SUPERSEDED BY SB 505-21-0007 REV 02), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-21-0008 Airframe SB - Open #1228	AIR CONDITIONING - WATER DRAIN INSTALLATION TO THE BLEED LINE (SUPERSEDED BY SB 505-21-0008 REV 01), SERVICE BULLETIN						
SB 505-21-0008 R02 Airframe SB - Complied With #8	AIR CONDITIONING - WATER DRAIN INSTALLATION TO THE BLEED LINE, SERVICE BULLETIN	22-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - AIRCRAFT WEIGHT AND BALANCE HAS BEEN CORRECTED IAW SB 505-21-0008 REV 2						
SB 505-21-0008/01 Airframe SB - Complied With #1567	AIR CONDITIONING - WATER DRAIN INSTALLATION TO THE BLEED LINE (SUPERSEDED BY SB 505-21-0008 REV 02), SERVICE BULLETIN	16-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - C/W SB 505-21-0008 REV 1 AIR CONDITIONING - WATER DRAIN INSTALLATION TO THE BLEED LINE SERVICE BULLETIN1. IAW SB 505-21-0008 REV 1. NO DEFECTS						
SB 505-21-0009 Airframe SB - Complied With #961	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION SYSTEM, SERVICE BULLETIN	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-21-0009 PART III Airframe SB - Complied With #714	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION SYSTEM, SERVICE BULLETIN COMPLEMENTARY ACTION - WINDOW REVEAL REPLACEMENT AND MUFFLER INSTALLATION ON THE LH SIDE	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-21-0009 PART I Airframe SB - Complied With #512	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION SYSTEM, SERVICE BULLETIN WINDOW SUPPORTS AND MIXER DUCT INSTALLATION, WINDOW REVEAL REPLACEMENT	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-21-0009 PART II Airframe SB - Complied With #1373	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION SYSTEM, SERVICE BULLETIN WINDOW SUPPORTS AND MUFFLER INSTALLATION, WINDOW REVEAL REPLACEMENT Notes COMPLIED WITH	19-MAY-2016 H: 1156.90 L: 1222					
SB 505-21-0010 Airframe SB - N/A #1216	AIR CONDITIONING - WATER DRIPPING PROTECTION (SUPERSEDED BY SB 505-21-0010 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-21-0010 R01 Airframe SB - N/A #1508	AIR CONDITIONING - WATER DRIPPING PROTECTION (SUPERSEDED BY 505-21-0010 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-21-0010 R02 Airframe SB - N/A #1638	AIR CONDITIONING - WATER DRIPPING PROTECTION, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-21-0010 R03 Airframe SB - N/A #1166	AIR CONDITIONING - WATER DRIPPING PROTECTION, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-21-0010 R04 Airframe SB - Open #2190	AIR CONDITIONING - WATER DRIPPING PROTECTION						
SB 505-21-0011 Airframe SB - N/A #1948	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT, SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-21-0012 Airframe SB - N/A #689	AIR CONDITIONING - AFT CARGO COMPARTMENT HEATING SYSTEM - INSTALLATION (SUPERSEDED BY 505-21-0012 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-21-0012 R01 Airframe SB - N/A #1709	AIR CONDITIONING - AFT CARGO COMPARTMENT HEATING SYSTEM - INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-21-0012 R02 Airframe SB - N/A #1466	AIR CONDITIONING - AFT CARGO COMPARTMENT HEATING SYSTEM - INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-21-0012 R03 Airframe SB - Open #2016	AIR CONDITIONING - AFT CARGO COMPARTMENT HEATING SYSTEM - INSTALLATION (REV. 3)						
SB 505-21-0014 Airframe SB - Open #2241	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT						
SB 505-22-0001 Airframe SB - Complied With #740	AUTO FLIGHT - VENTRAL RUDDER - WATER DEFLECTOR INSTALLATION AND SERVO ACTUATORS MOUNTING BOLTS REPLACEMENT, SERVICE BULLETIN				28-JUL-2015 H: 892.10 L: 968		
	Notes COMPLIED WITH						
SB 505-22-0001 PART II Airframe SB - Complied With #1148	AUTO FLIGHT - VENTRAL RUDDER - WATER DEFLECTOR INSTALLATION AND SERVO ACTUATORS MOUNTING BOLTS REPLACEMENT, SERVICE BULLETIN SERVO ACTUATORS MOUNTING BOLTS REPLACEMENT				28-JUL-2015 H: 892.10 L: 968		
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-22-0001 PART I Airframe SB - Complied With #1419	AUTO FLIGHT - VENTRAL RUDDER - WATER DEFLECTOR INSTALLATION AND SERVO ACTUATORS MOUNTING BOLTS REPLACEMENT, SERVICE BULLETIN WATER DEFLECTOR INSTALLATION AND SERVO ACTUATORS OUNTING BOLTS REPLACEMENT Notes COMPLIED WITH	28-JUL-2015 H: 892.10 L: 968					
SB 505-22-0002 Airframe SB - N/A #131	AUTO FLIGHT - AUTOPILOT SERVOS CONTROL-CABLES INSPECTION, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-22-0004 R01 Airframe SB - Open #2226	AUTO FLIGHT - REPLACEMENT OF THE AILERON SERVO ASSEMBLY BOLT						
SB 505-22-0004 R02 Airframe SB - Open #2227	AUTO FLIGHT - REPLACEMENT OF THE AILERON SERVO ASSEMBLY BOLT						
SB 505-22-0004 R03 Airframe SB - Open #2228	AUTO FLIGHT - REPLACEMENT OF THE AILERON SERVO ASSEMBLY BOLT						
SB 505-22-0004 R04 Airframe SB - Recurring #2232	AUTO FLIGHT - REPLACEMENT OF THE AILERON SERVO ASSEMBLY BOLT	22-SEP-2023 H: 2833.90 L: 2664	M: 36			22-SEP-2026	M: 13 D: 24
SB 505-23-0001 Airframe SB - N/A #910	COMMUNICATIONS - PROTECTION TO HF (HIGH FREQUENCY COMMUNICATION SYSTEM) WIRES, SERVICE BULLETIN Notes NOT APPLICABLE	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0001 PART I Airframe SB - N/A #1729	INSTALLATION COMMUNICATIONS - PROTECTION TO HF (HIGH FREQUENCY COMMUNICATION SYSTEM) WIRES, SERVICE BULLETIN HF WIRES PROTECTION - AIRCRAFT WITH HF SYSTEM Notes NOT APPLICABLE	07-MAY-2012					
SB 505-23-0001 PART II Airframe SB - N/A #711	INSTALLATION COMMUNICATIONS - PROTECTION TO HF (HIGH FREQUENCY COMMUNICATION SYSTEM) WIRES, SERVICE BULLETIN HF WIRES PROTECTION AND CB0177 LOCKING - AIRCRAFT WITH HF PROVISION Notes NOT APPLICABLE	07-MAY-2012					
SB 505-23-0002 Airframe SB - N/A #1329	INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (DLMS), SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION	07-MAY-2012					
SB 505-23-0003 Airframe SB - N/A #1290	COMMUNICATIONS - INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (DLMS) WITH IN-FLIGHT PHONE (SUPERSEDED BY SB 505-23-0003 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.						
SB 505-23-0003 R01 Airframe SB - N/A #605	COMMUNICATIONS - INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (DLMS) WITH IN-FLIGHT PHONE (SUPERSEDED BY SB 505-23-0003 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0003 R02 Airframe SB - N/A #1973	COMMUNICATIONS - INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (DLMS) WITH IN-FLIGHT PHONE, SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0004 PART I Airframe SB - N/A #1246	ACTIVATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 01), SERVICE BULLETIN OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0004 Airframe SB - N/A #116	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER - TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0004 PART II Airframe SB - N/A #1241	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 01), SERVICE BULLETIN OF THE LRUS AND ACTIVATION Notes NOT APPLICABLE						
SB 505-23-0004 PART III Airframe SB - N/A #444	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 01), SERVICE BULLETIN OF THE VHF ANTENNA CABLE, LRUS AND ACTIVATION Notes NOT APPLICABLE						
SB 505-23-0004 R01 PART I Airframe SB - N/A #1666	ACTIVATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 02), SERVICE BULLETIN OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0004 R01 Airframe SB - N/A #508	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER - TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0004 R01 PART II Airframe SB - N/A #1047	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 02), SERVICE BULLETIN OF THE LRUS AND ACTIVATION						
	Notes NOT APPLICABLE						
SB 505-23-0004 R01 PART III Airframe SB - N/A #1774	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 02), SERVICE BULLETIN OF THE VHF ANTENNA CABLE, LRUS AND ACTIVATION						
	Notes NOT APPLICABLE						
SB 505-23-0004 R02 PART I Airframe SB - N/A #1043	ACTIVATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 03), SERVICE BULLETIN OF THE CPDLC SYSTEM						
	Notes NOT APPLICABLE						
SB 505-23-0004 R02 Airframe SB - N/A #280	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-23-0004 R02 PART II Airframe SB - N/A #1189	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 03), SERVICE BULLETIN OF THE LRUS, AND ACTIVATION OF THE CPDLC SYSTEM						
	Notes NOT APPLICABLE						
SB 505-23-0004 R02 PART III Airframe SB - N/A #1695	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNICATION) SYSTEM (SUPERSEDED BY SB 505-23-0004 REV 03), SERVICE BULLETIN OF THE VHF ANTENNA CABLE, LRUS, AND ACTIVATION OF THE CPDLC SYSTEM						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0004 R03 PART I Airframe SB - N/A #581	ACCOMPLISH, SERVICE BULLETIN ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0004 R03 PART IV Airframe SB - N/A #922	ACCOMPLISH, SERVICE BULLETIN ADDITIONAL ACTION Notes NOT APPLICABLE						
SB 505-23-0004 R03 PART II Airframe SB - N/A #274	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF THE LRUS, AND ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0004 R03 PART III Airframe SB - N/A #229	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF THE VHF ANTENNA CABLE, LRUS, AND ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0004 R03 Airframe SB - N/A #1939	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER - TO-PILOT DATA LINK COMMUNICATION) SYSTEM, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0005 Airframe SB - N/A #540	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0005 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0005 R01 Airframe SB - N/A #695	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0005 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-23-0005 R02 Airframe SB - N/A #698	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0005 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-23-0005 R03 PART II Airframe SB - N/A #1585	ACCOMPLISH COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0005 REV 04), SERVICE BULLETIN ADDITIONAL ACTION						
	Notes NOT APPLICABLE						
SB 505-23-0005 R03 PART I Airframe SB - N/A #535	ACCOMPLISH COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0005 REV 04), SERVICE BULLETIN INSTALLATION OF THE CPDLC SYSTEM						
	Notes NOT APPLICABLE						
SB 505-23-0005 R03 Airframe SB - N/A #1598	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0005 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-23-0005 R04 PART II Airframe SB - N/A #1773	ACCOMPLISH, SERVICE BULLETIN ADDITIONAL ACTION						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0005 R04 PART I Airframe SB - N/A #1611	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0005 R04 Airframe SB - N/A #501	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0006 PART I Airframe SB - N/A #1821	ACTIVATION COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0006 REV 01), SERVICE BULLETIN OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 Airframe SB - N/A #1702	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0006 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0006 PART II Airframe SB - N/A #999	INSTALLATION COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0006 REV 01), SERVICE BULLETIN OF THE LRUS, AND ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 R01 Airframe SB - N/A #629	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0006 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0006 R01 PART I Airframe SB - N/A #934	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0006 REV 02), SERVICE BULLETIN ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 R01 PART II Airframe SB - N/A #40	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY SB 505-23-0006 REV 02), SERVICE BULLETIN INSTALLATION OF THE LRUS AND ACTIVATION Notes NOT APPLICABLE						
SB 505-23-0006 R02 PART I Airframe SB - N/A #51	ACCOMPLISH COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0006 REV 03), SERVICE BULLETIN ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 R02 PART III Airframe SB - N/A #1392	ACCOMPLISH COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0006 REV 03), SERVICE BULLETIN ADDITIONAL ACTION Notes NOT APPLICABLE						
SB 505-23-0006 R02 PART II Airframe SB - N/A #1182	ACCOMPLISH COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0006 REV 03), SERVICE BULLETIN INSTALLATION OF THE LRUS, AND ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 R02 Airframe SB - N/A #369	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION) (SUPERSEDED BY 505-23-0006 REV 03), SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-23-0006 R03 PART I Airframe SB - N/A #1171	ACCOMPLISH, SERVICE BULLETIN ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 R03 PART III Airframe SB - N/A #236	ACCOMPLISH, SERVICE BULLETIN ADDITIONAL ACTION Notes NOT APPLICABLE						
SB 505-23-0006 R03 PART II Airframe SB - N/A #1589	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF THE LRUS, AND ACTIVATION OF THE CPDLC SYSTEM Notes NOT APPLICABLE						
SB 505-23-0006 R03 Airframe SB - N/A #1086	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0007 Airframe SB - N/A #1393	COMMUNICATIONS - NEW STATIC DISCHARGER ON AILERON - INSTALLATION (SUPERSEDED BY SB 505-23-0007 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-23-0007 R01 Airframe SB - Complied With #326	COMMUNICATIONS - NEW STATIC DISCHARGER ON AILERON - INSTALLATION, SERVICE BULLETIN Notes COMPLIED WITH OPERATORS DISCRETION					19-MAY-2016 H: 1156.90 L: 1222	

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0001 Airframe SB - Complied With #138	ELECTRICAL POWER - AC ELECTRICAL OUTLET CONNECTOR PROTECTION, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	07-MAY-2012					
SB 505-24-0003 Airframe SB - Complied With #862	ELECTRICAL POWER - NEW ATTACHMENT FOR THE AP AILERON SERVO ACTUATOR ELECTRICAL CABLE, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	07-MAY-2012					
SB 505-24-0004 Airframe SB - Complied With #1012	ELECTRICAL POWER - REPLACEMENT OF THE ELECTRICAL BONDING JUMPER, SERVICE BULLETIN Notes COMPLIED WITH	12-MAY-2017 H: 1452.20 L: 1499					
SB 505-24-0004 PART I Airframe SB - Complied With #1492	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE ELECTRICAL BONDING JUMPER, SERVICE BULLETIN OF THE ELECTRICAL BONDING JUMPER Notes COMPLIED WITH	12-MAY-2017 H: 1452.20 L: 1499					
SB 505-24-0004 PART II Airframe SB - N/A #559	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE ELECTRICAL BONDING JUMPER, SERVICE BULLETIN OF THE ELECTRICAL BONDING JUMPER ATTACHMENTS Notes NOT APPLICABLE	12-MAY-2017 H: 1452.20 L: 1499					
SB 505-24-0005 Airframe SB - Complied With #170	ELECTRICAL POWER - REPLACEMENT OF THE STARTERS GENERATORS, SERVICE BULLETIN Notes COMPLIED WITH - C/W BY PREVIOUS INSTALLATION OF P/N MG103C-4	23-APR-2014 H: 623.30 L: 675					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0006 PART III Airframe SB - Open #1063	ELECTRICAL POWER ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN REPLACEMENT OF THE CONTACTORS PN SM400D117 IN THE EPDU						
SB 505-24-0006 PART I Airframe SB - Open #233	ELECTRICAL POWER ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN REPLACEMENT OF THE CONTACTORS PN SM400D117 IN THE LPDU						
SB 505-24-0006 PART II Airframe SB - Open #601	ELECTRICAL POWER ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN REPLACEMENT OF THE CONTACTORS PN SM400D117 IN THE RPDU						
SB 505-24-0006 Airframe SB - Complied With #1824	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-24-0007 Airframe SB - N/A #1098	ELECTRICAL POWER - MODIFICATION OF THE EMERGENCY BUS CONTRACTOR (EBC) 1 GROUND WIRE (SUPERSEDED BY SB 505-24-0007 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0007 R01 Airframe SB - N/A #1173	ELECTRICAL POWER - MODIFICATION OF THE EMERGENCY BUS CONTACTOR (EBC) 1 GROUND WIRE, SERVICE BULLETIN						
	Notes NOT APPLICABLE - C/W EQUIVALENT MODIFICATION FACTORY-INCORPORATED						
SB 505-24-0008 Airframe SB - Complied With #179	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN	15-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - REMOVED & REPLACED LPDU, RPDU, EPDU IAW SB 505-24-0008 PERFORMED OPERATIONAL CHECKS IAW AMM TASK 24-65-01-400-801-A/400, 24-65-02-400-801-A/400 & 24-65-03-400-801-A/400						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0008 PART III Airframe SB - Complied With #915	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN OF THE EPDU PN SX7EG22-1 OR SX7EG22-1A	14-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - REMOVED EPDU P/N SX7EG22-1A S/N 0123 WITH P/N SX7EG22-1B S/N 0081. APPROPRIATE OPS CHECKS COMPLETED. SYSTEM FUNCTION NORMALLY						
SB 505-24-0008 PART I Airframe SB - Complied With #777	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN OF THE LPDU PN SX7EG20-1 OR SX7EG20-1A	15-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - REMOVED LPDU PART SX7EG20-1A S/N 0116 REPLACED WITH P/N SX7EG20-1B S/N 0107. COMPLETED APPROPRIATE OPS CHECK. ALL SYSTEMS CHECK GOOD.						
SB 505-24-0008 PART II Airframe SB - Complied With #634	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU (SUPERSEDED BY SB 505-24-0008 REV 01), SERVICE BULLETIN OF THE RPDU PN SX7EG21-1 OR SX7EG21-1A	15-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - REMOVED RPDU PART SX7EG21-1A S/N 0111 & REPLACED WITH P/N SX7EG21-1B S/N 0129. COMPLETED APPROPRIATE OPS CHECKS. SYSTEMS FUNCTIONS NORMALLY.						
SB 505-24-0008 R01 Airframe SB - Open #825	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN						
SB 505-24-0008 R01 PART III Airframe SB - Open #1096	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN OF THE EPDU PN SX7EG22-1 OR SX7EG22-1A						
SB 505-24-0008 R01 PART I Airframe SB - Open #1854	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN OF THE LPDU PN SX7EG20-1 OR SX7EG20-1A						
SB 505-24-0008 R01 PART II Airframe SB - Open #188	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN OF THE RPDU PN SX7EG21-1 OR SX7EG21-1A						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0009 Airframe SB - Open #788	ELECTRICAL POWER - BATTERIES AND GPU RECEPTACLE POWER CABLES - INSPECTION AND SPACER INSTALLATION (SUPERSEDED BY SB 505-24-0009 REV 01), SERVICE BULLETIN						
SB 505-24-0009 R01 Airframe SB - Open #468	ELECTRICAL POWER - BATTERIES AND GPU RECEPTACLE POWER CABLES - INSPECTION AND SPACER INSTALLATION, SERVICE BULLETIN						
SB 505-24-0010 Airframe SB - Complied With #1129	ELECTRICAL POWER - INSTALLATION OF SPACER BETWEEN HARNESS W111 AND STRUCTURE (SUPERSEDED BY SB 505-24-0010 REV 01), SERVICE BULLETIN				23-APR-2014 H: 623.30 L: 675		
	Notes COMPLIED WITH						
SB 505-24-0010 R01 Airframe SB - Complied With #32	ELECTRICAL POWER - INSTALLATION OF SPACER BETWEEN HARNESS W111 AND STRUCTURE, SERVICE BULLETIN				03-APR-2014 H: 623.30 L: 675		
	Notes COMPLIED WITH - C/W INSTALLING SPACER BTEWEEN HARNESS W111 AND STRUCTURE PER SERVICE BULLETINE 505-24-0010						
SB 505-24-0011 Airframe SB - Complied With #21	ELECTRICAL POWER - INSTALLATION OF BRACKET TO REMOVE CHAFING BETWEEN W207 AND PEDAL MECHANISM, SERVICE BULLETIN				19-MAY-2016 H: 1156.90 L: 1222		
	Notes COMPLIED WITH						
SB 505-24-0012 Airframe SB - Complied With #1249	ELECTRICAL POWER - CHANGE IN W201 HARNESS ROUTING IN THE COCKPIT, SERVICE BULLETIN				19-MAY-2016 H: 1156.90 L: 1222		
	Notes COMPLIED WITH						
SB 505-24-0014 Airframe SB - Open #1639	ELECTRICAL POWER - GCU (GENERATOR CONTROL UNIT) REPLACEMENT (SUPERSEDED BY SB 505-24-0014 REV 01), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0014 R01 Airframe SB - Complied With #1417	ELECTRICAL POWER - GCU (GENERATOR CONTROL UNIT) REPLACEMENT, SERVICE BULLETIN Notes COMPLIED WITH	02-JUN-2015 H: 850.20 L: 933					
SB 505-24-0015 Airframe SB - Open #1882	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY_2 (SUPERSEDED BY SB 505-24-0015 REV 01), SERVICE BULLETIN Notes OPERATORS DISCRETION						
SB 505-24-0015 R01 Airframe SB - Open #1591	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY_2 (SUPERSEDED BY SB 505-24-0015 REV 02), SERVICE BULLETIN Notes OPERATORS DISCRETION						
SB 505-24-0015 R02 Airframe SB - Open #681	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY_2 (SUPERSEDED BY SB 505-24-0015 REV 03), SERVICE BULLETIN Notes OPERATORS DISCRETION						
SB 505-24-0015 R03 Airframe SB - Complied With #281	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY_2 (SUPERSEDED BY SB 505-24-0015 REV 04), SERVICE BULLETIN Notes COMPLIED WITH OPERATORS DISCRETION	12-JUN-2015 H: 850.20 L: 933					
SB 505-24-0015 R04 Airframe SB - Open #59	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY_2, SERVICE BULLETIN Notes OPERATORS DISCRETION						
SB 505-24-0015 R05 Airframe SB - Open #2197	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY 2						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0017 Airframe SB - N/A #1366	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R01 Airframe SB - N/A #430	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R02 Airframe SB - N/A #375	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R03 Airframe SB - N/A #1842	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R04 Airframe SB - N/A #108	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R05 Airframe SB - N/A #1954	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-24-0017 R06 Airframe SB - N/A #562	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 07), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R07 Airframe SB - N/A #1386	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 08), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R08 Airframe SB - N/A #1301	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 09), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R09 Airframe SB - N/A #1900	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 10), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-24-0017 R10 Airframe SB - Open #676	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION (SUPERSEDED BY SB 505-24-0017 REV 11), SERVICE BULLETIN						
SB 505-24-0017 R11 Airframe SB - Complied With #506	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION, SERVICE BULLETIN						
	Notes COMPLIED WITH	19-MAY-2016 H: 1156.90 L: 1222					
SB 505-25-0001 Airframe SB - Complied With #203	EQUIPMENT/FURNISHINGS - LAVATORY TOILET LID IMPROVEMENT, SERVICE BULLETIN						
	Notes COMPLIED WITH - AT MANUFACTURE	07-MAY-2012					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0002 Airframe SB - N/A #1170	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS (SUPERSEDED BY SB 505-25-0002 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-25-0002 R01 Airframe SB - N/A #164	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS (SUPERSEDED BY SB 505-25-0010 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0003 Airframe SB - N/A #192	EQUIPMENT/FURNISHINGS - INSPECTION OF THE FASTEN SEAT BELTS PLACARDS, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-25-0004 Airframe SB - N/A #1224	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R01 Airframe SB - N/A #771	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R02 Airframe SB - N/A #103	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0004 R03 Airframe SB - N/A #611	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R04 Airframe SB - N/A #928	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R05 Airframe SB - N/A #1575	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R06 Airframe SB - N/A #1265	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 07), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R07 Airframe SB - N/A #885	EQUIPMENT / FURNISHINGS - BELTED TOILET INSTALLATION (SUPERSEDED BY SB 505-25-0004 REV 08), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0004 R08 Airframe SB - Open #1348	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN						
SB 505-25-0005 Airframe SB - N/A #1860	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE RH/LH SIDEEDGE LOWER PANEL (SUPERSEDED BY SB 505-25-0005 REV 01), SERVICE BULLETIN					07-MAY-2012	
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0005 R01 Airframe SB - N/A #180	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE RH/LH SIDELEDGE LOWER PANEL (SUPERSEDED BY SB 505-25-0010 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0006 Airframe SB - Complied With #82	EQUIPMENT/FURNISHINGS - COCKPIT CURTAIN IMPROVEMENT, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-25-0007 Airframe SB - Open #456	EQUIPMENT/FURNISHINGS - LH FORWARD CABINET - INSTALLATION OF ARM LINK ON THE TRAY COMPARTMENT DOOR, SERVICE BULLETIN						
SB 505-25-0008 Airframe SB - Complied With #1558	EQUIPMENT/FURNISHINGS - CURTAIN PLACARD INSTALLATION IN THE COCKPIT, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE OPERATORS DISCRETION						
SB 505-25-0009 Airframe SB - N/A #1899	EQUIPMENT/FURNISHINGS - PLACARDS AND EXTERNAL INSCRIPTIONS REPLACEMENT - CZECH/ENGLISH LANGUAGE, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-25-0010 Airframe SB - N/A #589	EQUIPMENT/FURNISHINGS - INTERIOR CONFIGURATION CONVERSION FROM WENGUE TO SAPELE PATTERN (SUPERSEDED BY SB 505-25-0010 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-25-0010 R01 Airframe SB - N/A #1691	EQUIPMENT/FURNISHINGS - INTERIOR CONFIGURATION CONVERSION FROM WENGUE TO SAPELE PATTERN, SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0011 Airframe SB - N/A #286	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT (SUPERSEDED BY SB 505-25-0011 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0011 R01 Airframe SB - N/A #1213	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT (SUPERSEDED BY SB 505-25-0011 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0011 R02 Airframe SB - N/A #1467	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT (SUPERSEDED BY SB 505-25-0011 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0011 R03 Airframe SB - N/A #1026	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT (SUPERSEDED BY 505-25-0011 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0011 R04 Airframe SB - N/A #1006	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0012 Airframe SB - N/A #702	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS (SUPERSEDED BY SB 505-25-0012 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0012 R01 Airframe SB - N/A #1489	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS (SUPERSEDED BY SB 505-25-0012 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0012 R02 Airframe SB - N/A #603	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0014 Airframe SB - N/A #1779	EQUIPMENT/FURNISHINGS - LEFT HAND FORWARD CABINET - REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-25-0015 Airframe SB - N/A #864	EQUIPMENT/FURNISHINGS - STOP INSTALLATION TO THE LH FORWARD CABINET, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0016 Airframe SB - N/A #1088	EQUIPMENT/FURNISHINGS - ENHANCED SEAT INSTALLATION (SUPERSEDED BY SB 505-25-0016 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0016 R01 Airframe SB - N/A #1462	EQUIPMENT/FURNISHINGS - ENHANCED SEAT INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0017 Airframe SB - N/A #6	EQUIPMENT/FURNISHINGS - CARPET REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0018 Airframe SB - N/A #1307	EQUIPMENT/FURNISHINGS - FULL FUNCTION SEAT INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0019 Airframe SB - N/A #288	EQUIPMENT/FURNISHINGS - AFT LAVATORY CABINET REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0020 Airframe SB - Complied With #1183	EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION, SERVICE BULLETIN						
	Notes COMPLIED WITH - SB 505-25-0025 PREVIOUSLY COMPLIED WITH ON 20-MAY-2016				01-DEC-2016 H: 1300.00 L: 1383		
SB 505-25-0020 PART I Airframe SB - Complied With #1175	INSPECTION EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION, SERVICE BULLETIN OF FLOOR FITTINGS						
	Notes COMPLIED WITH				01-DEC-2016 H: 1300.00 L: 1383		
SB 505-25-0020 PART II Airframe SB - Complied With #383	REPOSITION EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION, SERVICE BULLETIN OF FLOOR FITTING						
	Notes COMPLIED WITH				01-DEC-2016 H: 1300.00 L: 1383		

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0021 Airframe SB - N/A #648	EQUIPMENT/FURNISHINGS - DECAL AND TECHNICAL INSCRIPTION - PORTUGUESE/ENGLISH, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0021 PART I Airframe SB - N/A #1967	EQUIPMENT/FURNISHINGS - DECAL AND TECHNICAL INSCRIPTION - PORTUGUESE/ENGLISH, SERVICE BULLETIN NEW INSCRIPTION ON THE MAIN DOOR HANDLE						
	Notes NOT APPLICABLE						
SB 505-25-0021 PART II Airframe SB - N/A #1479	EQUIPMENT/FURNISHINGS - DECAL AND TECHNICAL INSCRIPTION - PORTUGUESE/ENGLISH, SERVICE BULLETIN NEW INSCRIPTION ON THE MAIN DOOR HANDLE AND REPLACEMENT DECAL ON THE FWD /AFT BAGGAGE						
	Notes NOT APPLICABLE						
SB 505-25-0022 Airframe SB - N/A #840	EQUIPMENT/FURNISHINGS - PASSENGER CABIN CARPET REPLACEMENT (SUPERSEDED BY SB 505-25-0022 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0022 R01 Airframe SB - N/A #357	EQUIPMENT/FURNISHINGS - PASSENGER CABIN CARPET REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0023 Airframe SB - N/A #353	EQUIPMENT/FURNISHINGS - INSTALLATION OF THE ELT (EMERGENCY LOCATOR TRANSMITTER) / NAV (NAVIGATION) (SUPERSEDED BY 505-25-0023 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0023 R01 Airframe SB - N/A #1334	EQUIPMENT / FURNISHINGS - INSTALLATION OF THE ELT (EMERGENCY LOCATOR TRANSMITTER) / NAV (NAVIGATION), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0024 Airframe SB - N/A #352	EQUIPMENT/FURNISHINGS - REPOSITIONING OF THE HATCHET, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0025 Airframe SB - N/A #997	EQUIPMENT/FURNISHINGS - REPLACEMENT OF CUSHION OF BELTED TOILET AND DIVAN (SUPERSEDED BY SB 505-25-0025 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-25-0025 R01 PART I Airframe SB - N/A #139	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH BELTED TOILET						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-25-0025 R01 PART II Airframe SB - N/A #1830	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH BELTED TOILET AND DIVAN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-25-0025 R01 Airframe SB - N/A #1323	EQUIPMENT/FURNISHINGS - REPLACEMENT OF CUSHION OF BELTED TOILET AND DIVAN, SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0027 Airframe SB - N/A #1859	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION (SUPERSEDED BY SB 505-25-0027 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0027 R01 Airframe SB - N/A #1794	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION (SUPERSEDED BY SB 505-25-0027 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0027 R02 Airframe SB - Open #578	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION (SUPERSEDED BY SB 505-25-0027 REV 03), SERVICE BULLETIN						
SB 505-25-0027 R03 Airframe SB - N/A #855	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0027 R04 Airframe SB - Open #1986	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION (REV. 4)						
SB 505-25-0027 R05 Airframe SB - Open #2017	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION (REV. 5)						
SB 505-25-0028 Airframe SB - N/A #1064	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0029 Airframe SB - N/A #128	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - FRENCH/ENGLISH LANGUAGE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0030 Airframe SB - N/A #807	EQUIPMENT/FURNISHINGS - HATCHET INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0030 R01 Airframe SB - N/A #367	EQUIPMENT/FURNISHINGS - HATCHET INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0030 R02 Airframe SB - Open #2004	EQUIPMENT/FURNISHINGS - HATCHET INSTALLATION (REV. 2)						
SB 505-25-0031 Airframe SB - N/A #20	EQUIPMENT/FURNISHINGS - PROTECTIVE BREATHING EQUIPMENT INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0031 R02 Airframe SB - Open #1988	EQUIPMENT/FURNISHINGS - PROTECTIVE BREATHING EQUIPMENT INSTALLATION						
SB 505-25-0031 R03 Airframe SB - Open #2171	EQUIPMENT/FURNISHINGS - PROTECTIVE BREATHING EQUIPMENT INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0032 Airframe SB - N/A #1109	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT (SUPERSEDED BY 505-25-0032 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0032 R01 Airframe SB - N/A #1451	EQUIPMENT / FURNISHINGS - FIRST AID KIT REPLACEMENT (SUPERSEDED BY 505-25-0032 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0032 R02 Airframe SB - N/A #1378	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0032 R03 Airframe SB - Open #2005	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT (REV. 3)						
SB 505-25-0032 R04 Airframe SB - Open #2147	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT						
SB 505-25-0033 Airframe SB - N/A #789	EQUIPMENT / FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS - POLISH/ENGLISH LANGUAGE (SUPERSEDED BY 505-25-0033 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0033 R01 Airframe SB - N/A #127	EQUIPMENT / FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS - POLISH / ENGLISH LANGUAGE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0034 Airframe SB - N/A #14	EQUIPMENT / FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - HINDI/ENGLISH LANGUAGE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0035 Airframe SB - N/A #101	EQUIPMENT/FURNISHINGS - IDENTIFICATION PLATE INSTALLATION AT THE MAIN ENTRY DOOR (SUPERSEDED BY 505-25-0035 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0035 R01 Airframe SB - N/A #1384	EQUIPMENT/FURNISHINGS - IDENTIFICATION PLATE INSTALLATION AT THE MAIN ENTRY DOOR, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0035 R02 Airframe SB - Open #2010	EQUIPMENT/FURNISHINGS - IDENTIFICATION PLATE INSTALLATION AT THE MAIN ENTRY DOOR (REV. 2)						
SB 505-25-0036 Airframe SB - N/A #1423	EQUIPMENT / FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - GERMAN / ENGLISH LANGUAGE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-25-0036 R02 Airframe SB - Open #2148	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - GERMAN/ENGLISH LANGUAGE						
SB 505-25-0037 Airframe SB - Open #1982	EQUIPMENT/FURNISHINGS - LH FWD REFRESHMENT CENTER INSTALLATION						
SB 505-25-0038 Airframe SB - N/A #1987	EQUIPMENT/FURNISHINGS - DIVAN INSTALLATION				03-APR-2018 H: 1753.90 L: 1770		

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0039 Airframe SB - Open #1984	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS SPANISH - ENGLISH						
SB 505-25-0040 Airframe SB - Open #2044	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - PORTUGUESE/ENGLISH LANGUAGE						
SB 505-25-0041 Airframe SB - Open #2043	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT - ANAC						
SB 505-25-0043 Airframe SB - Open #2088	EQUIPMENT/FURNISHINGS - FLOOR SILL CARPET INSTALLATION						
SB 505-25-0044 Airframe SB - Open #2145	EQUIPMENT/FURNISHINGS - LH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION						
SB 505-25-0044 IN01 Airframe SB - Open #2165	EQUIPMENT/FURNISHINGS - LH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION						
SB 505-25-0045 IN01 Airframe SB - Open #2154	EQUIPMENT/FURNISHINGS - LATERAL LONGITUDINAL SHAFTS OF THE SEAT - INSPECTION						
SB 505-25-0046 Airframe SB - Open #2162	EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION						
SB 505-26-0001 Airframe SB - N/A #969	FIRE PROTECTION - INSPECTION/REPLACEMENT OF THE BAGGAGE-COMPARTMENT SMOKE DETECTOR (SUPERSEDED BY SB 505-26-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-26-0001 R01 Airframe SB - N/A #167	FIRE PROTECTION - INSPECTION/REPLACEMENT OF THE BAGGAGE-COMPARTMENT SMOKE DETECTOR, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-26-0002 Airframe SB - Open #904	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN						
SB 505-26-0002 R01 Airframe SB - Open #1934	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN						
SB 505-26-0003 Airframe SB - N/A #1118	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-26-0003 R01 Airframe SB - Open #2006	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT (REV. 1)						
SB 505-26-0004 Airframe SB - Open #2078	FIRE PROTECTION - PORTABLE HALON FIRE EXTINGUISHER REPLACEMENT						
SB 505-27-0001 Airframe SB - Open #154	FLIGHT CONTROLS - CONTROL YOKE MAP HOLDER REPLACEMENT (SUPERSEDED BY SB 505-27-0001 REV 01), SERVICE BULLETIN						
SB 505-27-0001 R01 Airframe SB - Complied With #1483	FLIGHT CONTROLS - CONTROL YOKE MAP HOLDER REPLACEMENT, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0002 Airframe SB - Superseded #1187	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE) (SUPERSEDED BY SB 505-27-0002 REV 01), SERVICE BULLETIN						
SB 505-27-0002 R01 Airframe SB - Complied With #415	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE) (SUPERSEDED BY SB 505-27-0009 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-27-0003 Airframe SB - Open #776	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS (SUPERSEDED BY SB 505-27-0003 REV 01), SERVICE BULLETIN						
SB 505-27-0003 R01 Airframe SB - Open #563	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS (SUPERSEDED BY SB 505-27-0003 REV 02), SERVICE BULLETIN						
SB 505-27-0003 R02 Airframe SB - Complied With #1574	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS (SUPERSEDED BY SB 505-27-0003 REV 03), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE OPERATORS DISCRETION						
SB 505-27-0003 R03 Airframe SB - Complied With #767	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS, SERVICE BULLETIN	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SB 505-27-0003 ON THE MODIFICATION OF PEDAL TRANSDUCER STOPS, NO DEFECTS NOTED OPERATORS DISCRETION						
SB 505-27-0004 Airframe SB - N/A #747	FLIGHT CONTROLS - REPLACEMENT OF THE MULTIFUNCTION SPOILER-SURFACE SENSOR, CONTROL WHEEL, AND PCU, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0005 Airframe SB - Complied With #57	FLIGHT CONTROLS - REPLACEMENT OF THE TRIM ACTUATOR CONTROLLER (TAC), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-27-0006 Airframe SB - N/A #530	FLIGHT CONTROLS - RUDDER GUST LOCK ACTUATOR INSPECTION/REPLACEMENT, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-27-0007 Airframe SB - N/A #29	FLIGHT CONTROLS - ELECTRICAL WIRING MODIFICATION IN THE COPILOT CONTROL WHEEL CONNECTOR 2J0505, SERVICE BULLETIN						
	Notes NOT APPLICABLE - C/W EQUIVALENT MODIFICATION FACTORY-INCORPORATED						
SB 505-27-0008 Airframe SB - N/A #1360	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK (SUPERSEDED BY SB 505-27-0008 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-27-0008 R01 Airframe SB - Open #169	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK (SUPERSEDED BY SB 505-27-0008 REV 02), SERVICE BULLETIN						
SB 505-27-0008 R01 PART II Airframe SB - Open #149	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK (SUPERSEDED BY SB 505-27-0008 REV 02), SERVICE BULLETIN OF ADJUSTABLE STOP SCREW ASSEMBLY						
SB 505-27-0008 R01 PART I Airframe SB - Open #742	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK (SUPERSEDED BY SB 505-27-0008 REV 02), SERVICE BULLETIN OF BOLT PIN ASSEMBLY						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0008 R02 Airframe SB - Complied With #1234	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SB 505-27-0008						
SB 505-27-0008 R02 PART II Airframe SB - Complied With #1770	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF ADJUSTABLE STOP SCREW ASSEMBLY	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SB 505-27-0008 ON THE ADJUSTABLE STOP SCREW ASSEMBLY. NO DEFECTS NOTED						
SB 505-27-0008 R02 PART I Airframe SB - Complied With #835	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF STOP PIN ASSEMBLY	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SB 505-27-0008 ON THE STOP PIN ASSEMBLY. NO DEFECTS NOTED						
SB 505-27-0009 Airframe SB - N/A #292	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007 TO FCE 462900-1009) (SUPERSEDED BY SB 505-27-0009 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-27-0009 R01 Airframe SB - Complied With #527	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007 TO FCE 462900-1009), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-27-0010 Airframe SB - Open #155	FLIGHT CONTROLS - INSPECTION / REPLACEMENT OF THE FLAP SYSTEM LEVER, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0011 PART II Airframe SB - N/A #621	- FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 01), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT EQUIPPED WITH THE STRUCTURAL PROVISION						
	Notes NOT APPLICABLE						
SB 505-27-0011 PART I Airframe SB - N/A #737	- FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 01), SERVICE BULLETIN FLAP FULL ACTIVATION TO AIRCRAFT NOT EQUIPPED WITH THE STRUCTURAL PROVISION						
	Notes NOT APPLICABLE						
SB 505-27-0011 Airframe SB - N/A #414	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-27-0011 R01 PART II Airframe SB - Open #312	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 02), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT EQUIPPED WITH THE STRUCTURAL PROVISION						
SB 505-27-0011 R01 PART I Airframe SB - Complied With #1748	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 02), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT NOT EQUIPPED WITH THE STRUCTURAL PROVISION					27-MAR-2014 H: 623.30 L: 675	
	Notes COMPLIED WITH						
SB 505-27-0011 R01 Airframe SB - Complied With #526	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 02), SERVICE BULLETIN					22-APR-2014 H: 623.30 L: 675	
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0011 R02 PART II Airframe SB - N/A #1029	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 03), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT EQUIPPED WITH THE STRUCTURAL PROVISION	24-MAR-2015					
	Notes NOT APPLICABLE						
SB 505-27-0011 R02 PART I Airframe SB - Complied With #671	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 03), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT NOT EQUIPPED WITH THE STRUCTURAL PROVISION	24-MAR-2015					
	Notes COMPLIED WITH						
SB 505-27-0011 R02 Airframe SB - Complied With #124	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 03), SERVICE BULLETIN	24-MAR-2015					
	Notes COMPLIED WITH						
SB 505-27-0011 R03 PART II Airframe SB - Open #662	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 04), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT EQUIPPED WITH STRUCTURAL PROVISION						
SB 505-27-0011 R03 PART I Airframe SB - Open #1675	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 04), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT NOT EQUIPPED WITH STRUCTURAL PROVISION						
SB 505-27-0011 R03 PART III Airframe SB - Open #1557	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 04), SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT WITH STOPPER ON THE FLAP SELECTOR LEVER UNDER TCCA CERTIFICATION.						
SB 505-27-0011 R03 Airframe SB - Open #1706	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION (SUPERSEDED BY SB 505-27-0011 REV 04), SERVICE BULLETIN						
SB 505-27-0011 R04 PART II Airframe SB - Open #803	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION, SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT EQUIPPED WITH STRUCTURAL PROVISION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0011 R04 PART I Airframe SB - Open #159	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION, SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT NOT EQUIPPED WITH STRUCTURAL PROVISION						
SB 505-27-0011 R04 PART III Airframe SB - Open #479	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION, SERVICE BULLETIN FLAP FULL ACTIVATION FOR AIRCRAFT WITH STOPPER ON THE FLAP SELECTOR LEVER UNDER TCCA/CAAC CERTIFICATION						
SB 505-27-0011 R04 Airframe SB - Open #1969	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION, SERVICE BULLETIN						
SB 505-27-0012 PART I Airframe SB - Open #1151	CHECK FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING (SUPERSEDED BY SB 505-27-0012 REV 01), SERVICE BULLETIN FOR LOCK WIRE PROPER ROUTING						
SB 505-27-0012 Airframe SB - Open #768	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING (SUPERSEDED BY SB 505-27-0012 REV 01), SERVICE BULLETIN						
SB 505-27-0012 PART IV Airframe SB - Open #1016	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING (SUPERSEDED BY SB 505-27-0012 REV 01), SERVICE BULLETIN LOCK WIRE REINSTALLATION - PITCH TRIM ACTUATOR						
SB 505-27-0012 PART II Airframe SB - Open #1259	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING (SUPERSEDED BY SB 505-27-0012 REV 01), SERVICE BULLETIN LOCK WIRE REINSTALLATION - ROLL TRIM ACTUATOR						
SB 505-27-0012 PART III Airframe SB - Open #636	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING (SUPERSEDED BY SB 505-27-0012 REV 01), SERVICE BULLETIN LOCK WIRE REINSTALLATION - YAW TRIM ACTUATOR						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0012 R01 PART I Airframe SB - Complied With #435	CHECK FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN FOR LOCK WIRE PROPER ROUTING ON ROLL TRIM ACTUATOR, YAW TRIM ACTUATOR AND PITCH TRIM ACTUATOR	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SB NO 505-27-0012 OF THE CHECK OF LOCK WIRE FOR PROPER ROUTING ON THE TRIM ACTUATOR, YAW TRIM ACTUATOR AND PITCH TRIM ACTUATOR . NO DEFECTS FOUND						
SB 505-27-0012 R01 Airframe SB - Complied With #370	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SB N 505-27-0012 ON THE CHECK OF LOCK WIRE FOR PROPER FOUTING.NO DEFECTS FOUND						
SB 505-27-0012 R01 PART IV Airframe SB - Complied With #204	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN LOCK WIRE REINSTALLATION - PITCH TRIM ACTUATOR	04-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - C/W SERVICE BULLETINE NO 505-27-0012 ON THE LOCK WIRE REINSTALLATION ON THE PITCH TRIM ACTUATOR. NO DEFECTS NOTED						
SB 505-27-0012 R01 PART II Airframe SB - Complied With #18	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN LOCK WIRE REINSTALLATION - ROLL TRIM ACTUATOR	03-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - CHECKED LOCK WIRE, NO DISCREPANCY FOUND						
SB 505-27-0012 R01 PART III Airframe SB - Complied With #687	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN LOCK WIRE REINSTALLATION - YAW TRIM ACTUATOR	03-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - CHECKED LOCK WIRE FOR CORED INSTAL, NO DISCREPANCYS NOTED						
SB 505-27-0013 Airframe SB - Open #813	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007/ 462900-1009 TO FCE 462900-1011) (SUPERSEDED BY SB 505-27-0013 REV 01), SERVICE BULLETIN						
SB 505-27-0013 R01 Airframe SB - Open #102	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007/ 462900-1009 TO FCE 462900-1011) (SUPERSEDED BY SB 505-27-0013 REV 02), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0013 R02 Airframe SB - Complied With #1977	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007/ 462900-1009 TO FCE 462900-1011) (SUPERSEDED BY SB 505-27-0013 REV 03), SERVICE BULLETIN	23-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH						
SB 505-27-0013 R03 Airframe SB - Open #1435	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007/ 462900-1009 TO FCE 462900-1011) (SUPERSEDED BY SB 505-27-0013 REV 04), SERVICE BULLETIN						
SB 505-27-0013 R04 Airframe SB - Complied With #94	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007/ 462900-1009 TO FCE 462900-1011) (SUPERSEDED BY SB 505-27-0022), SERVICE BULLETIN	07-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - SERVICE BULLETIN 505-27-0013. NO DEFECTS NOTED						
SB 505-27-0014 Airframe SB - Open #552	FLIGHT CONTROLS - CHECK OF LOCK WASHERS OF THE TOGGLE LINKS FOR INSTALLATION DAMAGE (SUPERSEDED BY SB 505-27-0014 REV 01), SERVICE BULLETIN						
SB 505-27-0014 R01 Airframe SB - Open #1516	FLIGHT CONTROLS - CHECK OF LOCK WASHERS OF THE TOGGLE LINKS FOR INSTALLATION DAMAGE (SUPERSEDED BY SB 505-27-0014 REV 02), SERVICE BULLETIN						
	Notes OPERATORS DISCRETION						
SB 505-27-0014 R02 Airframe SB - Complied With #1582	FLIGHT CONTROLS - CHECK OF LOCK WASHERS OF THE TOGGLE LINKS FOR INSTALLATION DAMAGE (SUPERSEDED BY SB 505-27-0014 REV 03), SERVICE BULLETIN	08-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH - LOCK WASHER FOUND TO BE BROKEN, INSTALLED NEW LOCK WASHER AND TOGGLE LINE PER SB 505-27-0014						
SB 505-27-0014 R03 Airframe SB - Open #1652	FLIGHT CONTROLS - CHECK OF LOCK WASHERS OF THE TOGGLE LINKS FOR INSTALLATION DAMAGE, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0017 Airframe SB - Complied With #1643	FLIGHT CONTROLS - RUDDER GUST LOCK SYSTEM - REPLACEMENT OF GUST LOCK LEVER AND ACTUATOR, SERVICE BULLETIN	28-JUL-2015 H: 892.10 L: 968					
	Notes COMPLIED WITH						
SB 505-27-0017 IN02 Airframe SB - Open #2169	FLIGHT CONTROLS - RUDDER GUST LOCK SYSTEM - REPLACEMENT OF GUST LOCK LEVER AND ACTUATOR						
SB 505-27-0018 Airframe SB - Superseded #302	FLIGHT CONTROLS - G3000 - ACTIVATION OF THE STEEP APPROACH MODE (SUPERSEDED BY SB 505-27-0018 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-27-0018 R01 PART II Airframe SB - Superseded #431	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE, SERVICE BULLETIN G1000						
	Notes NOT APPLICABLE						
SB 505-27-0018 R01 PART I Airframe SB - Superseded #200	ACCOMPLISH FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE, SERVICE BULLETIN G3000						
	Notes NOT APPLICABLE						
SB 505-27-0018 R01 Airframe SB - Superseded #625	FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0018 R02 PART II Airframe SB - Superseded #1493	ACCOMPLISH, SERVICE BULLETIN G1000 Notes NOT APPLICABLE						
SB 505-27-0018 R02 PART I Airframe SB - Superseded #1945	ACCOMPLISH, SERVICE BULLETIN G3000 Notes NOT APPLICABLE						
SB 505-27-0018 R02 Airframe SB - Superseded #1480	FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-27-0018 R03 IN01 Airframe SB - Superseded #2168	FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE - ATTACH THIS IN TO SB 505-27-0018, REV 03 DATED APRIL 27, 2021						
SB 505-27-0018 R04 Airframe SB - Open #2185	FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE						
SB 505-27-0019 Airframe SB - N/A #109	FLIGHT CONTROLS - G3000 - REMOVAL OF THE STALL WARNING DISCRETE SIGNAL FROM THE REMOTE AUDIO CONTROLLER, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-27-0022 Airframe SB - Complied With #1897	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE1 AND FCE2), SERVICE BULLETIN Notes COMPLIED WITH					13-JUL-2016 H: 1201.40 L: 1270	

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0022 R01 Airframe SB - Open #2199	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE1 AND FCE2)						
SB 505-27-0023 PART I Airframe SB - Complied With #666	ACCOMPLISH FLIGHT CONTROLS - PROVISIONING OF THE ELECTRICAL HARNESS TO RUDDER GUST LOCK ANNUNCIATION SYSTEM (SUPERSEDED BY 505-27-0023 REV 01), SERVICE BULLETIN AIRCRAFT CONFIGURED WITH G1000 AVIONICS SYSTEM						
	Notes COMPLIED WITH				12-MAY-2017 H: 1452.20 L: 1499		
SB 505-27-0023 PART II Airframe SB - N/A #1482	ACCOMPLISH FLIGHT CONTROLS - PROVISIONING OF THE ELECTRICAL HARNESS TO RUDDER GUST LOCK ANNUNCIATION SYSTEM (SUPERSEDED BY 505-27-0023 REV 01), SERVICE BULLETIN AIRCRAFT CONFIGURED WITH G3000 AVIONICS SYSTEM						
	Notes NOT APPLICABLE				12-MAY-2017 H: 1452.20 L: 1499		
SB 505-27-0023 Airframe SB - Complied With #423	FLIGHT CONTROLS - PROVISIONING OF THE ELECTRICAL HARNESS TO RUDDER GUST LOCK ANNUNCIATION SYSTEM (SUPERSEDED BY 505-27-0023 REV 01), SERVICE BULLETIN						
	Notes COMPLIED WITH				12-MAY-2017 H: 1452.20 L: 1499		
SB 505-27-0023 R01 PART I Airframe SB - Open #1051	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT CONFIGURED WITH G1000 AVIONICS SYSTEM						
SB 505-27-0023 R01 PART II Airframe SB - Open #1715	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT CONFIGURED WITH G3000 AVIONICS SYSTEM						
SB 505-27-0023 R01 Airframe SB - Open #1277	FLIGHT CONTROLS - PROVISIONING OF THE ELECTRICAL HARNESS TO RUDDER GUST LOCK ANNUNCIATION SYSTEM, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-0024 Airframe SB - N/A #436	FLIGHT CONTROLS - REPLACEMENT OF HORIZONTAL-STABILIZER PITCH TRIM ACTUATOR, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-27-0024 R01 Airframe SB - Open #2188	FLIGHT CONTROLS - REPLACEMENT OF HORIZONTAL-STABILIZER PITCH TRIM ACTUATOR						
SB 505-27-0025 PART II Airframe SB - N/A #1790	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE BARREL SELF-LOCKING NUTS OF THE CONTROL YOKE MECHANISM AND ITS ATTACHMENT PARTS	13-SEP-2017 H: 1567.40					
	Notes NOT APPLICABLE - NOT APPLICABLE.						
SB 505-27-0025 PART I Airframe SB - Complied With #1345	ACCOMPLISH, SERVICE BULLETIN VISUAL INSPECTION OF THE BARREL SELF-LOCKING NUT INSTALLATION	12-MAY-2017 H: 1452.20 L: 1499					
	Notes COMPLIED WITH						
SB 505-27-0025 Airframe SB - Complied With #568	FLIGHT CONTROLS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, SERVICE BULLETIN	12-MAY-2017 H: 1452.20 L: 1499					
	Notes COMPLIED WITH						
SB 505-27-0026 Airframe SB - N/A #1411	FLIGHT CONTROLS - CABLES INSPECTION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-27-A028 PART II Airframe SB - N/A #445	ACCOMPLISH, SERVICE BULLETIN AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB COTTER PIN INSTALLATION AND TORQUE						
	Notes NOT APPLICABLE						
SB 505-27-A028 PART I Airframe SB - N/A #1327	ACCOMPLISH, SERVICE BULLETIN INSPECTION OF AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB						
	Notes NOT APPLICABLE						
SB 505-27-A028 Airframe SB - N/A #525	FLIGHT CONTROLS - AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB INSPECTION AND TORQUE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-28-0001 Airframe SB - N/A #489	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC (SUPERSEDED BY SB 505-28-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.						
SB 505-28-0001 R01 Airframe SB - Open #425	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC (SUPERSEDED BY SB 505-28-0001 REV 02), SERVICE BULLETIN						
SB 505-28-0001 R02 Airframe SB - Complied With #240	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC (SUPERSEDED BY SB 505-28-0001 REV 03), SERVICE BULLETIN					07-MAY-2012	
	Notes COMPLIED WITH - AT MANUFACTURE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-28-0001 R03 Airframe SB - N/A #56	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC, SERVICE BULLETIN						
	Notes NOT APPLICABLE - C/W EQUIVALENT MODIFICATION FACTORY INCORPORATED						
SB 505-28-0001 R03 PART I Airframe SB - N/A #1013	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC, SERVICE BULLETIN APPLICABLE TO AIRCRAFT EQUIPPED WITH EMERGENCY BATTERY PN 3400-22-10						
	Notes NOT APPLICABLE						
SB 505-28-0001 R03 PART II Airframe SB - N/A #1809	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC, SERVICE BULLETIN APPLICABLE TO AIRCRAFT NOT EQUIPPED WITH EMERGENCY BATTERY PN 3400-22-10						
	Notes NOT APPLICABLE						
SB 505-28-0002 Airframe SB - N/A #405	FUEL - INSTALLATION OF THE FUEL PUMP DC CONTACTOR, SERVICE BULLETIN					19-MAY-2016 H: 1156.90 L: 1222	
	Notes NOT APPLICABLE - NOT APPLICABLE TO THIS S/N A/C, VISUALLY NOTED CONTACTORS INSTALLED						
SB 505-28-0003 Airframe SB - Open #1599	FUEL - MOTIVE FLOW LINE AND FEED LINE FUEL TUBES INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
SB 505-28-0003 PART I Airframe SB - Complied With #878	FUEL - MOTIVE FLOW LINE AND FEED LINE FUEL TUBES INSPECTION AND REPLACEMENT, SERVICE BULLETIN MOTIVE FLOW LINE AND FEED LINE FUEL TUBES INSPECTION					04-JUN-2015 H: 850.20 L: 933	
	Notes COMPLIED WITH - NO CORROSION FOUND						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-28-0003 PART II Airframe SB - Complied With #1269	FUEL - MOTIVE FLOW LINE AND FEED LINE FUEL TUBES INSPECTION AND REPLACEMENT, SERVICE BULLETIN MOTIVE FLOW LINE AND FEED LINE FUEL TUBES REPLACEMENT Notes COMPLIED WITH	19-MAY-2016 H: 1156.90 L: 1222					
SB 505-29-0001 Airframe SB - Complied With #344	HYDRAULIC POWER - HYDRAULIC RESERVOIR REPLACEMENT, SERVICE BULLETIN Notes COMPLIED WITH - AT MANUFACTURE	07-MAY-2012					
SB 505-29-0002 Airframe SB - N/A #1233	HYDRAULIC POWER - INSPECTION/FLUSHING OF THE HYDRAULIC SYSTEM LINE, SERVICE BULLETIN Notes NOT APPLICABLE	07-MAY-2012					
SB 505-29-0003 Airframe SB - Open #638	HYDRAULIC POWER - HYDRAULIC RESERVOIR INSPECTION / REPLACEMENT, SERVICE BULLETIN						
SB 505-29-0003 PART I Airframe SB - Open #1797	INSPECTION HYDRAULIC POWER - HYDRAULIC RESERVOIR INSPECTION / REPLACEMENT, SERVICE BULLETIN OF THE SERIAL NUMBER OF HYDRAULIC RESERVOIR						
SB 505-29-0003 PART II Airframe SB - Open #1857	REPLACE HYDRAULIC POWER - HYDRAULIC RESERVOIR INSPECTION / REPLACEMENT, SERVICE BULLETIN THE HYDRAULIC RESERVOIR						
SB 505-29-0005 Airframe SB - Open #613	HYDRAULIC POWER - HYDRAULIC ACCUMULATOR REPLACEMENT, SERVICE BULLETIN Notes OPERATORS DISCRETION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-29-0006 Airframe SB - Complied With #1495	HYDRAULIC POWER - INSPECTION OF ENGINE DRIVEN PUMP ASSEMBLY (SUPERSEDED BY SB 505-29-0006 REV 01), SERVICE BULLETIN	08-JUN-2015 H: 850.20 L: 933					
	Notes COMPLIED WITH						
SB 505-29-0006 R01 Airframe SB - Complied With #341	HYDRAULIC POWER - INSPECTION OF ENGINE DRIVEN PUMP ASSEMBLY, SERVICE BULLETIN	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH - HAS BEEN PREVIOUSLY COMPLIED WITH. PUMPS DATA PLATE MARKED WITH "C" MODIFICATION. NO FURTHER ACTION TAKEN						
SB 505-29-0007 Airframe SB - Open #1455	HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT (SUPERSEDED BY SB 505-29-0007 REV 01), SERVICE BULLETIN						
SB 505-29-0007 PART II Airframe SB - Open #1735	REPLACEMENT HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT (SUPERSEDED BY SB 505-29-0007 REV 01), SERVICE BULLETIN OF TUBES						
SB 505-29-0007 PART I Airframe SB - Open #81	VISUAL INSPECTION HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT (SUPERSEDED BY SB 505-29-0007 REV 01), SERVICE BULLETIN						
SB 505-29-0007 R01 Airframe SB - Complied With #1670	HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT, SERVICE BULLETIN	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-29-0007 R01 PART II Airframe SB - Complied With #481	REPLACEMENT HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT, SERVICE BULLETIN OF TUBES	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-29-0007 R01 PART I Airframe SB - Complied With #1922	VISUAL INSPECTION HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT, SERVICE BULLETIN	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-30-0001 Airframe SB - N/A #1407	ICE AND RAIN PROTECTION - INSPECTION / UPLOAD OF ICE DETECTOR FUNCTION, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-30-0002 Airframe SB - Open #490	ICE AND RAIN PROTECTION - RH PITOT STANDBY HEATER - SIGNAL RESISTORS - REMOVAL (SUPERSEDED BY SB 505-30-0002 REV 01), SERVICE BULLETIN						
SB 505-30-0002 R01 Airframe SB - Open #263	ICE AND RAIN PROTECTION - RH PITOT STANDBY HEATER - SIGNAL RESISTORS - REMOVAL (SUPERSEDED BY SB 505-30-0002 REV 02), SERVICE BULLETIN						
SB 505-30-0002 R02 Airframe SB - Complied With #1426	ICE AND RAIN PROTECTION - RH PITOT STANDBY HEATER - SIGNAL RESISTORS - REMOVAL, SERVICE BULLETIN	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-30-0004 Airframe SB - Open #2098	ICE AND RAIN PROTECTION - ICE DETECTOR INSTALLATION						
SB 505-31-0001 Airframe SB - Open #1805	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43 AVIONICS SOFTWARE AND CMC LOAD 9 SOFTWARE (SUPERSEDED BY SB 505-31-0001 REV 01), SERVICE BULLETIN						
SB 505-31-0001 R01 Airframe SB - Complied With #65	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43 AVIONICS SOFTWARE AND CMC LOAD 9 SOFTWARE, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0002 Airframe SB - Open #1299	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 01), SERVICE BULLETIN						
SB 505-31-0002 R01 Airframe SB - Open #905	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 02), SERVICE BULLETIN						
SB 505-31-0002 R02 Airframe SB - Open #97	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 03), SERVICE BULLETIN						
SB 505-31-0002 R03 Airframe SB - Open #486	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 04), SERVICE BULLETIN						
SB 505-31-0002 R04 Airframe SB - Open #668	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 05), SERVICE BULLETIN						
SB 505-31-0002 R05 Airframe SB - Open #1832	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 06), SERVICE BULLETIN						
SB 505-31-0002 R06 Airframe SB - Open #1961	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 07), SERVICE BULLETIN						
SB 505-31-0002 R07 Airframe SB - Complied With #1898	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 08), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-31-0002 R08 Airframe SB - Open #163	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 09), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0002 R09 Airframe SB - Open #1540	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 10), SERVICE BULLETIN						
SB 505-31-0002 R10 Airframe SB - N/A #1017	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 11), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R11 Airframe SB - N/A #1252	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 12), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R12 Airframe SB - N/A #566	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 13), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R13 Airframe SB - N/A #283	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 14), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R14 Airframe SB - N/A #1291	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 15), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R15 Airframe SB - N/A #451	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 16), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0002 R16 Airframe SB - N/A #1758	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 17), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R17 Airframe SB - N/A #1270	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 18), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R18 Airframe SB - N/A #1563	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 19), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R19 Airframe SB - N/A #90	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 20), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R20 Airframe SB - N/A #968	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 21), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R21 Airframe SB - N/A #1775	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 22), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0002 R22 Airframe SB - N/A #1421	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY SB 505-31-0002 REV 23), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R23 Airframe SB - N/A #1320	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R24 Airframe SB - N/A #1700	INDICATING / RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (SUPERSEDED BY 505-31-0002 REV 25), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R25 Airframe SB - N/A #1844	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0002 R26 Airframe SB - Open #1995	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (REV. 26)						
SB 505-31-0002 R27 Airframe SB - Open #2025	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM (REV. 27)						
SB 505-31-0002 R30 Airframe SB - Open #2092	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM						
SB 505-31-0002 R31 Airframe SB - Open #2110	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0003 Airframe SB - Open #1949	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 01), SERVICE BULLETIN						
SB 505-31-0003 R01 Airframe SB - Open #261	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 02), SERVICE BULLETIN						
SB 505-31-0003 R02 Airframe SB - Open #1946	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 03), SERVICE BULLETIN						
SB 505-31-0003 R03 Airframe SB - Complied With #1870	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 04), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-31-0003 R04 Airframe SB - N/A #1607	INDICATING/RECORDING SYSTEM - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0003 R05 Airframe SB - N/A #573	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0003 R06 Airframe SB - N/A #715	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL) (SUPERSEDED BY SB 505-31-0003 REV 07), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0003 R07 Airframe SB - N/A #1192	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0003 R08 Airframe SB - Open #2094	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL)						
SB 505-31-0004 Airframe SB - Open #275	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 54 AVIONICS SOFTWARE AND CMC LOAD 10 SOFTWARE (SUPERSEDED BY SB 505-31-0004 REV 01), SERVICE BULLETIN						
SB 505-31-0004 R01 Airframe SB - Open #975	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 54 AVIONICS SOFTWARE AND CMC LOAD 10 SOFTWARE (SUPERSEDED BY SB 505-31-0004 REV 02), SERVICE BULLETIN						
SB 505-31-0004 R02 Airframe SB - Complied With #505	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 54 AVIONICS SOFTWARE AND CMC LOAD 10 SOFTWARE, SERVICE BULLETIN					29-MAY-2013 H: 330.50 L: 349	
	Notes COMPLIED WITH - INSTALLED LOAD 54 AND CMC VERSION 10 IAW SB 505-31-0004						
SB 505-31-0005 Airframe SB - Open #1820	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 (SUPERSEDED BY SB 505-31-0005 REV 01), SERVICE BULLETIN						
SB 505-31-0005 R01 Airframe SB - Open #546	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 (SUPERSEDED BY SB 505-31-0005 REV 02), SERVICE BULLETIN						
SB 505-31-0005 R02 PART II Airframe SB - Open #64	ADDITIONAL ACTION INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 (SUPERSEDED BY SB 505-31-0005 REV 03), SERVICE BULLETIN - DATA LINK FOLDERS CONFIGURATION AND LOG FILES ERASURE						
SB 505-31-0005 R02 Airframe SB - Open #995	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 (SUPERSEDED BY SB 505-31-0005 REV 03), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0005 R02 PART I Airframe SB - Open #522	INSTALLATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 (SUPERSEDED BY SB 505-31-0005 REV 03), SERVICE BULLETIN OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11						
SB 505-31-0005 R03 PART II Airframe SB - Open #417	ADDITIONAL ACTION INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN - DATA LINK FOLDERS CONFIGURATION AND LOG FILES ERASURE						
SB 505-31-0005 R03 Airframe SB - Open #1944	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN						
SB 505-31-0005 R03 PART I Airframe SB - Open #745	INSTALLATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11						
SB 505-31-0006 Airframe SB - N/A #390	INDICATING/RECORDING SYSTEMS - FDR - FLIGHT DATA RECORDER SYSTEM INSTALLATION (SUPERSEDED BY 505-31-0006 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0006 R01 Airframe SB - N/A #699	INDICATING/RECORDING SYSTEMS - FDR - FLIGHT DATA RECORDER SYSTEM INSTALLATION (SUPERSEDED BY 505-31-0006 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0006 R02 Airframe SB - N/A #946	INDICATING / RECORDING SYSTEMS - FDR - FLIGHT DATA RECORDER SYSTEM INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0007 Airframe SB - N/A #750	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.16 AVIONICS SOFTWARE, CMC LOAD 0.98 AND DEFAULT PILOT PROFILE FILES, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0008 Airframe SB - N/A #544	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.42 AVIONICS SOFTWARE, CMC LOAD 1.0 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505-31-0008 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0008 R01 Airframe SB - N/A #252	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.42 AVIONICS SOFTWARE, CMC LOAD 1.0 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505-31-0012), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0009 Airframe SB - N/A #608	INDICATING/RECORDING SYSTEMS - FDR (FLIGHT DATA RECORDER) AND IMPACT SWITCH INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0010 Airframe SB - N/A #157	INDICATING/RECORDING SYSTEMS - G1000 - DOWNGRADE FROM LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 SOFTWARE TO LOAD 54 AVIONICS SOFTWARE AND CMC LOAD 10 SOFTWARE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0011 Airframe SB - N/A #1858	INDICATING/RECORDING SYSTEMS - CONVERSION OF PROVISIONED AIRCRAFT FROM G1000 AVIONICS CONFIGURATION TO G3000 AVIONICS CONFIGURATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0012 Airframe SB - N/A #731	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.51 AVIONICS SOFTWARE, CMC LOAD 3.02 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505-31-0008 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0013 Airframe SB - Complied With #1845	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.4, SERVICE BULLETIN					01-MAY-2015 H: 839.20 L: 922	
	Notes COMPLIED WITH - INSTALLED AVIONICS SOFTWARE VERSION 72.1 AND CMC SOFTWARE 12.4						
SB 505-31-0014 Airframe SB - N/A #1134	INDICATING/RECORDING SYSTEMS - FDR (FLIGHT DATA RECORDER) AND FDR IMPACT SWITCH REMOVAL (SUPERSEDED BY SB 505-31-0014 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0014 R01 Airframe SB - N/A #1554	INDICATING/RECORDING SYSTEMS - FDR (FLIGHT DATA RECORDER) AND FDR IMPACT SWITCH REMOVAL, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0015 Airframe SB - N/A #63	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.60 AVIONICS SOFTWARE, CMC LOAD 3.03 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505-31-0017 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-31-0015 R01 Airframe SB - N/A #1568	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.60 AVIONICS SOFTWARE, CMC LOAD 3.03 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505-31-0017 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0016 Airframe SB - N/A #1856	INDICATING/RECORDING SYSTEMS - REPLACEMENT OF THE GTC 570 COOLING FAN (SUPERSEDED BY SB 505-31-0016 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-31-0016 R01 Airframe SB - N/A #1260	INDICATING/RECORDING SYSTEMS - REPLACEMENT OF THE GTC 570 COOLING FAN, SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-31-0017 Airframe SB - N/A #672	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 13.25 AVIONICS SOFTWARE, CMC LOAD V4.04 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505- 31-0017 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-31-0017 R01 Airframe SB - N/A #828	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 13.25 AVIONICS SOFTWARE, CMC LOAD V4.04 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY SB 505- 31-0017 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-31-0017 R02 Airframe SB - N/A #1001	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 13.25 AVIONICS SOFTWARE, CMC LOAD V4.04 AND DEFAULT PILOT PROFILE FILES, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-31-0018 Airframe SB - Complied With #1045	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 83.25 AVIONICS SOFTWARE AND CMC LOAD 13.3, SERVICE BULLETIN Notes COMPLIED WITH					12-MAY-2017 H: 1452.20 L: 1499	

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0019 Airframe SB - N/A #1474	INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT (SUPERSEDED BY SB 505-31-0019 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-31-0019 R01 Airframe SB - N/A #1198	INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT (SUPERSEDED BY 505-31-0019 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-31-0019 R02 Airframe SB - N/A #1542	INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-31-0019 R03 Airframe SB - Open #1992	INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT (REV. 3)						
SB 505-31-0019 R04 Airframe SB - Open #2034	INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT						
SB 505-31-002 R29 Airframe SB - Open #2089	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM						
SB 505-31-0020 Airframe SB - N/A #1283	INDICATING/RECORDING SYSTEMS - DEACTIVATION OF CVDR BULK ERASE, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0021 PART I Airframe SB - N/A #1847	ACCOMPLISH INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY 505-31-0021 REV 01), SERVICE BULLETIN AIRCRAFT WITH GUST LOCK ANNUNCIATION SYSTEM INSTALLED OR POST-MOD SB505-27-0023 Notes NOT APPLICABLE						
SB 505-31-0021 PART II Airframe SB - N/A #1015	ACCOMPLISH INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY 505-31-0021 REV 01), SERVICE BULLETIN AIRCRAFT WITHOUT GUST LOCK ANNUNCIATION SYSTEM INSTALLED OR PRE-MOD SB505-27-0023 Notes NOT APPLICABLE						
SB 505-31-0021 PARTS I & II Airframe SB - N/A #597	ACCOMPLISH INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY 505-31-0021 REV 01), SERVICE BULLETIN SOFTWARE IMPROVEMENTS AND MODIFICATIONS Notes NOT APPLICABLE						
SB 505-31-0021 Airframe SB - N/A #1548	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3 AND DEFAULT PILOT PROFILE FILES (SUPERSEDED BY 505-31-0021 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-31-0021 R01 PART I Airframe SB - N/A #342	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT WITH GUST LOCK ANNUNCIATION SYSTEM INSTALLED OR POST-MOD SB505-27-0023 Notes NOT APPLICABLE						
SB 505-31-0021 R01 PART II Airframe SB - N/A #774	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT WITHOUT GUST LOCK ANNUNCIATION SYSTEM INSTALLED OR PRE-MOD SB505-27-0023 Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0021 R01 PARTS I & I Airframe SB - N/A #1759	ACCOMPLISH, SERVICE BULLETIN SOFTWARE IMPROVEMENTS AND MODIFICATIONS Notes NOT APPLICABLE						
SB 505-31-0021 R01 Airframe SB - N/A #332	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3 AND DEFAULT PILOT PROFILE FILES, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-31-0022 PART I Airframe SB - Open #948	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT CONFIGURED WITH AVIONICS SOFTWARE LOAD VERSION 72.1 OR LOWER.						
SB 505-31-0022 PART II Airframe SB - Open #1878	ACCOMPLISH, SERVICE BULLETIN AIRCRAFT CONFIGURED WITH AVIONICS SOFTWARE LOAD VERSION 83.25 FACTORY INCORPORATED OR POST-MOD SB505-31-0018.						
SB 505-31-0022 Airframe SB - Open #1497	INDICATING / RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.00 AVIONICS SOFTWARE AND CMC LOAD 14.20, SERVICE BULLETIN						
SB 505-31-0023 Airframe SB - Open #1996	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.10 AVIONICS SOFTWARE AND CMC LOAD V5.20						
SB 505-31-0023 R01 Airframe SB - Open #2014	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.10 AVIONICS SOFTWARE AND CMC LOAD V5.20 (REV. 1)						
SB 505-31-0023 R02 Airframe SB - Open #2023	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.10 AVIONICS SOFTWARE AND CMC LOAD V5.20 (REV. 2)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-31-0024 Airframe SB - Open #1994	INDICATING/RECORDING SYSTEMS - CVDR - DATA RATE CORRECTION						
SB 505-31-0025 Airframe SB - Complied With #2028	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.10 AVIONICS SOFTWARE AND CMC LOAD 15.0	26-SEP-2018 H: 1868.60 L: 1880					
SB 505-32-0001 Airframe SB - N/A #38	LANDING GEAR - REPLACEMENT OF THE NLG SHOCK STRUT PLACARD, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-32-0002 Airframe SB - N/A #125	LANDING GEAR - BRAKE SYSTEM TROUBLESHOOTING (SUPERSEDED BY SB 505-32-0002 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-32-0002 R01 Airframe SB - N/A #380	LANDING GEAR - BRAKE SYSTEM TROUBLESHOOTING, SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-32-0003 Airframe SB - N/A #716	LANDING GEAR - BRAKE CONTROL UNIT NEW SOFTWARE INSTALLATION (SUPERSEDED BY SB 505-32-0003 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-32-0003 R01 Airframe SB - N/A #844	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT (SUPERSEDED BY SB 505-32-0003 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0003 R02 Airframe SB - Complied With #1767	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT (SUPERSEDED BY SB 505-32-0005 REV 02), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-32-0004 Airframe SB - N/A #561	LANDING GEAR - RETURN AIRCRAFT HYDRAULIC LINE TO ORIGINAL CONFIGURATION, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-32-0005 Airframe SB - Open #1710	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT (BCU DAP00100-03/-04/-05 TO BCU DAP00100-06) (SUPERSEDED BY SB 505-32-0005 REV 01), SERVICE BULLETIN						
SB 505-32-0005 R01 Airframe SB - Open #941	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT (BCU DAP00100-03/-04/-05 TO BCU DAP00100-06) (SUPERSEDED BY SB 505-32-0005 REV 02), SERVICE BULLETIN						
SB 505-32-0005 R02 Airframe SB - Complied With #1071	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT (BCU DAP00100-03/-04/-05 TO BCU DAP00100-06) (SUPERSEDED BY SB 505-32-0006 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-32-0006 Airframe SB - Complied With #1309	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT (SUPERSEDED BY SB 505-32-0015 REV 01), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-32-0006 R01 Airframe SB - N/A #86	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT (SUPERSEDED BY SB 505-32-0015 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0008 Airframe SB - Complied With #1512	LANDING GEAR - CORRECTION OF THE WHEEL AXLE TORQUE OF MLG AND NLG, SERVICE BULLETIN Notes COMPLIED WITH	27-MAR-2014 H: 623.30 L: 675					
SB 505-32-0011 Airframe SB - Open #808	LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE (SUPERSEDED BY SB 505-32-0011 REV 01), SERVICE BULLETIN						
SB 505-32-0011 PART I Airframe SB - Open #609	VISUAL INSPECTION LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE (SUPERSEDED BY SB 505-32-0011 REV 01), SERVICE BULLETIN TO BE DONE ON THE PRESSURE STATOR OF THE LH AND RH BRAKE ASSEMBLIES FOR CRACKS BEYOND ACCEPTABLE LIMITS						
SB 505-32-0011 PART II Airframe SB - Open #1440	VISUAL INSPECTION LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE (SUPERSEDED BY SB 505-32-0011 REV 01), SERVICE BULLETIN TO BE DONE ON THE THRUST STATOR, DOUBLE STATOR AND ROTORS OF THE LH AND RH BRAKE ASSEMBLIES						
SB 505-32-0011 R01 Airframe SB - N/A #336	LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE, SERVICE BULLETIN Notes NOT APPLICABLE	20-AUG-2014 H: 739.30 L: 813					
SB 505-32-0011 R01 PART I Airframe SB - N/A #1901	VISUAL INSPECTION LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE, SERVICE BULLETIN TO BE DONE ON THE PRESSURE STATOR OF THE LH AND RH BRAKE ASSEMBLIES FOR CRACKS BEYOND ACCEPTABLE LIMITS Notes NOT APPLICABLE	20-AUG-2014 H: 739.30 L: 813					
SB 505-32-0011 R01 PART II Airframe SB - N/A #1076	VISUAL INSPECTION LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE, SERVICE BULLETIN TO BE DONE ON THE THRUST STATOR, DOUBLE STATOR AND ROTORS OF THE LH AND RH BRAKE ASSEMBLIES Notes NOT APPLICABLE	20-AUG-2014 H: 739.30 L: 813					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0012 Airframe SB - Terminated #1862	LANDING GEAR - MAIN LANDING GEAR LOCKING ACTUATOR INSPECTION, SERVICE BULLETIN	30-JUN-2014 H: 691.20 L: 752					
	Notes DECLINED						
SB 505-32-0013 Airframe SB - Complied With #796	LANDING GEAR - REPLACEMENT OF THE BRAKE ASSEMBLY (SUPERSEDED BY SB 505-32-0013 REV 01), SERVICE BULLETIN	28-MAY-2014 H: 659.40 L: 714					
	Notes COMPLIED WITH - C/W THIS SB IS THE FINAL ACTION FOR AD 2013-22-20. AD LONGER APPLIES BY PN OPERATORS DISCRETION						
SB 505-32-0013 R01 Airframe SB - Open #348	LANDING GEAR - REPLACEMENT OF THE BRAKE ASSEMBLY, SERVICE BULLETIN						
	Notes OPERATORS DISCRETION						
SB 505-32-0014 Airframe SB - Open #1962	LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT (SUPERSEDED BY SB 505-32-0014 REV 01), SERVICE BULLETIN						
SB 505-32-0014 PART I Airframe SB - Open #1085	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT (SUPERSEDED BY SB 505-32-0014 REV 01), SERVICE BULLETIN NUT P/N MS14145L16 AND REDUCTION OF LENGTH AT EXTENDED POSITION, REWORK AND REIDENTIFY THE LH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO PN 2117-3000-601						
SB 505-32-0014 PART I Airframe SB - Open #174	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT (SUPERSEDED BY SB 505-32-0014 REV 01), SERVICE BULLETIN NUT P/N MS14145L16 AND REDUCTION OF LENGTH AT EXTENDED POSITION, REWORK AND REIDENTIFY THE RH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO PN 2117-3000-601						
SB 505-32-0014 PART II Airframe SB - Open #93	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT (SUPERSEDED BY SB 505-32-0014 REV 01), SERVICE BULLETIN THE LH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO NEW LOCKING ACTUATOR PN 2117-3000-409 OR A REWORKED AND REIDENTIFIED LOCKING ACTUATOR PN 2117-3000-601						
SB 505-32-0014 PART II Airframe SB - Open #660	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT (SUPERSEDED BY SB 505-32-0014 REV 01), SERVICE BULLETIN THE RH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO NEW LOCKING ACTUATOR PN 2117-3000-409 OR A REWORKED AND REIDENTIFIED LOCKING ACTUATOR PN 2117-3000-601						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0014 R01 Airframe SB - Complied With #1263	LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT, SERVICE BULLETIN	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-32-0014 R01 PART I Airframe SB - Complied With #1436	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT, SERVICE BULLETIN NUT P/N MS14145L16 AND REDUCTION OF LENGTH AT EXTENDED POSITION, REWORK AND REIDENTIFY THE LH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO PN 2117-3000-601	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-32-0014 R01 PART I Airframe SB - Complied With #1785	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT, SERVICE BULLETIN NUT P/N MS14145L16 AND REDUCTION OF LENGTH AT EXTENDED POSITION, REWORK AND REIDENTIFY THE RH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO PN 2117-3000-601	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-32-0014 R01 PART II Airframe SB - Complied With #1539	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT, SERVICE BULLETIN THE LH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO NEW LOCKING ACTUATOR PN 2117-3000-409 OR A REWORKED AND REIDENTIFIED LOCKING ACTUATOR PN 2117-3000-601	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-32-0014 R01 PART II Airframe SB - Complied With #1179	REPLACE LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT, SERVICE BULLETIN THE RH MLG LOCKING ACTUATOR FROM PN 2117-3000-405 OR PN 2117-3000-407 TO NEW LOCKING ACTUATOR PN 2117-3000-409 OR A REWORKED AND REIDENTIFIED LOCKING ACTUATOR PN 2117-3000-601	19-MAY-2016 H: 1156.90 L: 1222					
	Notes COMPLIED WITH						
SB 505-32-0015 Airframe SB - Complied With #412	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT (SUPERSEDED BY SB 505-32-0019), SERVICE BULLETIN	02-JUN-2015 H: 850.20 L: 933					
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0016 Airframe SB - Open #1039	LANDING GEAR - SPIN BRAKE PAD REMOVAL (SUPERSEDED BY SB 505-32-0016 REV 01), SERVICE BULLETIN						
	Notes OPERATORS DISCRETION						
SB 505-32-0016 R01 Airframe SB - Complied With #1595	LANDING GEAR - SPIN BRAKE PAD REMOVAL, SERVICE BULLETIN						
	Notes COMPLIED WITH OPERATORS DISCRETION	08-JUN-2015 H: 850.20 L: 933					
SB 505-32-0017 PART II Airframe SB - N/A #1273	INSPECTION LANDING GEAR - EMERGENCY AND NORMAL BRAKE, DOWNLOCK ACTUATOR, RETRACTION AND EXTENSION HYDRAULIC HOSES - INSPECTION / REPLACEMENT, SERVICE BULLETIN OF THE EMERGENCY AND NORMAL BRAKE UPPER HYDRAULIC HOSES OF MLG AND DOWNLOCK ACTUATOR, RETRACTION AND EXTENSION HYDRAULIC HOSES OF NLG						
	Notes NOT APPLICABLE						
SB 505-32-0017 Airframe SB - N/A #1374	LANDING GEAR - EMERGENCY AND NORMAL BRAKE, DOWNLOCK ACTUATOR, RETRACTION AND EXTENSION HYDRAULIC HOSES - INSPECTION / REPLACEMENT, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-32-0017 PART I Airframe SB - N/A #400	REPLACEMENT LANDING GEAR - EMERGENCY AND NORMAL BRAKE, DOWNLOCK ACTUATOR, RETRACTION AND EXTENSION HYDRAULIC HOSES - INSPECTION / REPLACEMENT, SERVICE BULLETIN OF EMERGENCY AND NORMAL BRAKE SYSTEMS HYDRAULIC HOSES OF MLG						
	Notes NOT APPLICABLE						
SB 505-32-0017 PART III Airframe SB - N/A #269	REPLACEMENT LANDING GEAR - EMERGENCY AND NORMAL BRAKE, DOWNLOCK ACTUATOR, RETRACTION AND EXTENSION HYDRAULIC HOSES - INSPECTION / REPLACEMENT, SERVICE BULLETIN OF THE EMERGENCY AND/OR NORMAL BRAKE UPPER HOSES OF MLG, AND/OR DOWNLOCK ACTUATOR, RETRACTION AND/OR EXTENSION HYDRAULIC HOSES OF NLG						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0018 Airframe SB - Open #1843	LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM (SUPERSEDED BY SB 505-32-0018 REV 01), SERVICE BULLETIN						
SB 505-32-0018 PART II Airframe SB - Open #684	REPLACEMENT LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM (SUPERSEDED BY SB 505-32-0018 REV 01), SERVICE BULLETIN OF MLG TRAILING ARM						
SB 505-32-0018 PART I Airframe SB - Complied With #794	VISUAL INSPECTION LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM (SUPERSEDED BY SB 505-32-0018 REV 01), SERVICE BULLETIN					19-MAY-2016 H: 1156.90 L: 1222	
	Notes COMPLIED WITH						
SB 505-32-0018 R01 PART I Airframe SB - Open #1404	ACCOMPLISH LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM, SERVICE BULLETIN MLG TRAILING ARM INSPECTION						
SB 505-32-0018 R01 PART II Airframe SB - Open #1425	ACCOMPLISH LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM, SERVICE BULLETIN MLG TRAILING ARM REPLACEMENT						
SB 505-32-0018 R01 Airframe SB - Open #826	LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM, SERVICE BULLETIN						
SB 505-32-0019 Airframe SB - Complied With #1437	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT (SUPERSEDED BY 505-32-0019 REV 01), SERVICE BULLETIN					12-MAY-2017 H: 1452.20 L: 1499	
	Notes COMPLIED WITH						
SB 505-32-0019 R01 Airframe SB - N/A #1190	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT (SUPERSEDED BY 505-32-0019 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-32-0019 R02 Airframe SB - Open #153	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT, SERVICE BULLETIN						
SB 505-33-0002 Airframe SB - Complied With #1286	LIGHTS - REPLACEMENT OF LIGHTS CONTROL PANEL, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-33-0003 Airframe SB - N/A #1398	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH (SUPERSEDED BY SB 505-33-0003 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-33-0003 R01 Airframe SB - N/A #1699	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH (SUPERSEDED BY SB 505-33-0003 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-33-0003 R02 Airframe SB - Open #1812	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH, SERVICE BULLETIN						
	Notes DEFERRED - 6/8/2016, 1168.2, 1242						
SB 505-33-0003 R02 PART II Airframe SB - Open #893	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH THE INERTIAL SWITCH PROVISION						
	Notes DEFERRED - 6/8/2016, 1168.2, 1242						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-33-0003 R02 PART I Airframe SB - Open #1580	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH, SERVICE BULLETIN AIRCRAFT NOT EQUIPPED WITH THE INERTIAL SWITCH PROVISION Notes DEFERRED - 6/8/2016, 1168.2, 1242						
SB 505-33-0004 Airframe SB - N/A #388	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION (SUPERSEDED BY SB 505-33-0004 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0004 R01 Airframe SB - N/A #428	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION (SUPERSEDED BY SB 505-33-0004 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0004 R01 PART II Airframe SB - N/A #1444	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION (SUPERSEDED BY SB 505-33-0004 REV 02), SERVICE BULLETIN ADDITIONAL ACTION: REPLACEMENT OF EMERGENCY LIGHTING SYSTEM BATTERIES Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0004 R01 PART I Airframe SB - N/A #831	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION (SUPERSEDED BY SB 505-33-0004 REV 02), SERVICE BULLETIN EMERGENCY LIGHTING SYSTEM INSTALLATION Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0004 R02 Airframe SB - N/A #1806	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION, SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-33-0004 R02 PART II Airframe SB - N/A #805	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION, SERVICE BULLETIN ADDITIONAL ACTION: REPLACEMENT OF EMERGENCY LIGHTING SYSTEM BATTERIES Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0004 R02 PART I Airframe SB - N/A #1107	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION, SERVICE BULLETIN EMERGENCY LIGHTING SYSTEM INSTALLATION Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0005 Airframe SB - Complied With #703	LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 TO PN 6434-00 (SUPERSEDED BY SB 505-33-0007), SERVICE BULLETIN Notes COMPLIED WITH				13-FEB-2015 H: 802.00 L: 884		
SB 505-33-0005 R01 Airframe SB - Open #1229	LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 TO PN 6434-00 (SUPERSEDED BY SB 505-33-0007 REV 01), SERVICE BULLETIN						
SB 505-33-0006 Airframe SB - N/A #1036	LIGHTS - EXIT SIGN REPLACEMENT - CZECH/ENGLISH LANGUAGE, SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0007 Airframe SB - Open #1057	LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 TO PN 6450LS-00 (SUPERSEDED BY SB 505-33-0007 REV 01), SERVICE BULLETIN						
SB 505-33-0007 R01 Airframe SB - Complied With #121	LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 OR PN 6434-00 TO PN 6450LS-00, SERVICE BULLETIN Notes COMPLIED WITH				12-MAY-2017 H: 1452.20 L: 1499		

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-33-0007 R01 GROUP 1 Airframe SB - N/A #1617	REPLACEMENT LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 OR PN 6434-00 TO PN 6450LS-00, SERVICE BULLETIN BATTERY PN 5434-00 WITH PN 6450LS-00	12-MAY-2017 H: 1452.20 L: 1499					
	Notes NOT APPLICABLE						
SB 505-33-0007 R01 GROUP 2 Airframe SB - N/A #44	REPLACEMENT LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 OR PN 6434-00 TO PN 6450LS-00, SERVICE BULLETIN BATTERY PN 6434-00 WITH PN 6450LS-00	12-MAY-2017 H: 1452.20 L: 1499					
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-33-0008 Airframe SB - N/A #1584	LIGHTS - EXIT SIGN REPLACEMENT - HINDI/ENGLISH LANGUAGE, SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-34-0002 Airframe SB - Complied With #1600	NAVIGATION - INTERFERENCE BETWEEN AHRS UNIT2 AND HARNESS W102, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-34-0003 Airframe SB - Complied With #356	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS) (SUPERSEDED BY SB 505-34-0003 REV 01), SERVICE BULLETIN	13-JUN-2012 H: 43.40 L: 49					
	Notes COMPLIED WITH - C/W BY MANUFACTURER						
SB 505-34-0003 R01 Airframe SB - Complied With #898	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS) (SUPERSEDED BY SB 505-34-0003 REV 02), SERVICE BULLETIN	13-JUN-2012 H: 43.40 L: 49					
	Notes COMPLIED WITH - C/W BY MANUFACTURER						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0003 R02 Airframe SB - Complied With #1947	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS) (SUPERSEDED BY SB 505-34-0003 REV 03), SERVICE BULLETIN	13-JUN-2012 H: 43.40 L: 49					
	Notes COMPLIED WITH - C/W BY MANUFACTURER						
SB 505-34-0003 R03 Airframe SB - N/A #54	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS) (SUPERSEDED BY SB 505-34-0003 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0003 R04 Airframe SB - N/A #615	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS) (SUPERSEDED BY SB 505-34-0003 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0003 R05 Airframe SB - N/A #785	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0003 R05 PART I Airframe SB - N/A #664	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS), SERVICE BULLETIN AIRCRAFT WITH G1000 CONFIGURATION						
	Notes NOT APPLICABLE						
SB 505-34-0003 R05 PART II Airframe SB - N/A #576	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS), SERVICE BULLETIN AIRCRAFT WITH G3000 CONFIGURATION						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0003 R06 Airframe SB - Open #2019	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS (REV. 6)						
SB 505-34-0003 R08 Airframe SB - Open #2175	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS)						
SB 505-34-0006 Airframe SB - Open #419	NAVIGATION - IASP (INTEGRATED AIR DATA AND STALL PROTECTION PROBE) REPLACEMENT, SERVICE BULLETIN						
	Notes OPERATORS DISCRETION						
SB 505-34-0006 R01 Airframe SB - Open #2200	NAVIGATION - IASP (INTEGRATED AIR DATA AND STALL PROTECTION PROBE) REPLACEMENT						
SB 505-34-0007 Airframe SB - N/A #1359	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - INSTALLATION (SUPERSEDED BY SB 505-34-0007 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0007 R01 Airframe SB - N/A #89	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - INSTALLATION (SUPERSEDED BY SB 505-34-0007 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0007 R02 Airframe SB - N/A #28	NAVIGATION - INSTALLATION OF ADF (AUTOMATIC DIRECTION FINDER) SYSTEM (SUPERSEDED BY 505-34-0007 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0007 R03 Airframe SB - N/A #669	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0007 R04 Airframe SB - N/A #421	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0008 Airframe SB - N/A #457	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - REMOVAL, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0009 Airframe SB - N/A #1406	NAVIGATION - INSTALLATION OF THE TCAS (TRAFFIC CREW ALERT SYSTEM) II AND RADAR ALTIMETER SYSTEMS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0010 Airframe SB - N/A #1576	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0010 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0010 R01 Airframe SB - N/A #1784	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0010 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0010 R02 Airframe SB - N/A #448	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0010 R03 Airframe SB - Open #1985	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 3)						
SB 505-34-0010 R04 Airframe SB - Open #2007	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 4)						
SB 505-34-0010 R05 Airframe SB - Open #2021	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 5)						
SB 505-34-0010 R06 Airframe SB - Open #2027	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 6)						
SB 505-34-0010 R07 Airframe SB - Complied With #2031	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 7)					26-SEP-2018 H: 1868.60 L: 1880	
SB 505-34-0010 R08 Airframe SB - Open #2032	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 8)						
SB 505-34-0010 R09 Airframe SB - Open #2039	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R11 Airframe SB - Open #2080	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0010 R12 Airframe SB - Open #2096	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R14 Airframe SB - Open #2111	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R15 Airframe SB - Open #2122	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R16 Airframe SB - Open #2143	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R17 Airframe SB - Open #2157	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R18 Airframe SB - Open #2204	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R19 Airframe SB - Open #2206	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R20 Airframe SB - Open #2229	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R21 Airframe SB - Open #2243	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST)						
SB 505-34-0011 Airframe SB - Open #827	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY SB 505-34-0011 REV 01), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0011 R01 PART I Airframe SB - N/A #1104	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 02), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 DUAL TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R01 PART III Airframe SB - N/A #1717	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 02), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R01 PART II Airframe SB - N/A #1646	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 02), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 SINGLE TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R01 Airframe SB - N/A #384	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0011 R02 PART I Airframe SB - N/A #663	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 03), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 DUAL TRANSPONDER TO NXT- 600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R02 PART III Airframe SB - N/A #553	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 03), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0011 R02 PART II Airframe SB - N/A #1938	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 03), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 SINGLE TRANSPONDER Notes NOT APPLICABLE						
SB 505-34-0011 R02 Airframe SB - N/A #211	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 03), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-34-0011 R03 PART I Airframe SB - N/A #361	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 04), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 DUAL TRANSPONDER TO NXT-600 DUAL TRANSPONDER Notes NOT APPLICABLE						
SB 505-34-0011 R03 PART III Airframe SB - N/A #311	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 04), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 DUAL TRANSPONDER Notes NOT APPLICABLE						
SB 505-34-0011 R03 PART II Airframe SB - N/A #1541	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 04), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 SINGLE TRANSPONDER Notes NOT APPLICABLE						
SB 505-34-0011 R03 Airframe SB - N/A #1428	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 04), SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0011 R04 PART IV Airframe SB - N/A #1556	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 05), SERVICE BULLETIN ADDITIONAL ACTION						
	Notes NOT APPLICABLE						
SB 505-34-0011 R04 PART I Airframe SB - N/A #1024	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 05), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 DUAL TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R04 PART III Airframe SB - N/A #1811	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 05), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R04 PART II Airframe SB - N/A #3	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 05), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 SINGLE TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R04 Airframe SB - N/A #1272	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0011 R05 PART IV Airframe SB - N/A #256	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 06), SERVICE BULLETIN ADDITIONAL ACTION						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0011 R05 PART I Airframe SB - N/A #869	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 06), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 DUAL TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R05 PART III Airframe SB - N/A #1722	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 06), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R05 PART II Airframe SB - N/A #513	ACCOMPLISH NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 06), SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 SINGLE TRANSPONDER						
	Notes NOT APPLICABLE						
SB 505-34-0011 R05 Airframe SB - N/A #846	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY 505-34-0011 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0011 R06 PART IV Airframe SB - N/A #92	ACCOMPLISH, SERVICE BULLETIN ADDITIONAL ACTION						
	Notes NOT APPLICABLE						
SB 505-34-0011 R06 PART I Airframe SB - N/A #510	ACCOMPLISH, SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 DUAL TRANSPONDER TO NXT-600 DUAL TRANSPONDER						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0011 R06 PART III Airframe SB - N/A #42	ACCOMPLISH, SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 DUAL TRANSPONDER Notes NOT APPLICABLE						
SB 505-34-0011 R06 PART II Airframe SB - N/A #284	ACCOMPLISH, SERVICE BULLETIN RECONFIGURATION FROM RCZ-852 SINGLE TRANSPONDER TO NXT-600 SINGLE TRANSPONDER Notes NOT APPLICABLE						
SB 505-34-0011 R06 Airframe SB - N/A #296	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-34-0011 R07 Airframe SB - Open #1990	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 7)						
SB 505-34-0011 R08 Airframe SB - Open #2024	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (REV. 8)						
SB 505-34-0011 R10 Airframe SB - Open #2040	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R11 Airframe SB - Open #2047	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R14 Airframe SB - Open #2090	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0011 R16 Airframe SB - Open #2113	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R17 Airframe SB - Open #2116	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R17 IN01 Airframe SB - Open #2117	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R17 IN03 Airframe SB - Open #2155	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R18 Airframe SB - Open #2179	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0012 Airframe SB - N/A #863	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM (SUPERSEDED BY SB 505-34-0012 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0012 R01 Airframe SB - N/A #1097	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM (SUPERSEDED BY SB 505-34-0012 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0012 R02 Airframe SB - Open #679	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM (SUPERSEDED BY SB 505-34-0012 REV 03), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0012 R03 Airframe SB - N/A #1960	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM (SUPERSEDED BY 505-34-0012 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0012 R05 Airframe SB - N/A #1822	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0012 R06 Airframe SB - Open #2180	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM - SURFACE WATCH FUNCTION						
SB 505-34-0013 Airframe SB - N/A #309	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (SUPERSEDED BY SB 505-34-0013 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0013 R01 Airframe SB - N/A #1055	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (SUPERSEDED BY SB 505-34-0013 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0013 R02 Airframe SB - Open #550	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (SUPERSEDED BY SB 505-34-0013 REV 03), SERVICE BULLETIN						
SB 505-34-0013 R03 Airframe SB - N/A #1206	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (SUPERSEDED BY 505-34-0013 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0013 R04 Airframe SB - N/A #595	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (SUPERSEDED BY 505-34-0013 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0013 R05 Airframe SB - N/A #1254	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0013 R06 Airframe SB - Open #1991	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (REV. 6)						
SB 505-34-0013 R07 Airframe SB - Open #2011	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM (REV. 7)						
SB 505-34-0014 Airframe SB - N/A #1485	NAVIGATION - GROUND CLUTTER SUPPRESSION/TURBULENCE DETECTION SYSTEM ACTIVATION (SUPERSEDED BY SB 505-34-0014 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0014 R01 Airframe SB - N/A #1131	NAVIGATION - GROUND CLUTTER SUPPRESSION/TURBULENCE DETECTION SYSTEM ACTIVATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0014 R02 Airframe SB - N/A #1449	NAVIGATION - GROUND CLUTTER SUPPRESSION/TURBULENCE DETECTION SYSTEM ACTIVATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-34-0015 Airframe SB - N/A #887	NAVIGATION - INSTALLATION OF THE TCAS (TRAFFIC CREW ALERT SYSTEM) II AND XPDR (TRANSPONDER) 1/2 SYSTEMS, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-34-0019 Airframe SB - Open #2085	NAVIGATION - REPLACEMENT OF THE WEATHER RADAR						
SB 505-34-0019 R01 Airframe SB - Open #2105	NAVIGATION - REPLACEMENT OF THE WEATHER RADAR						
SB 505-34-0020 Airframe SB - Superseded #2097	NAVIGATION - NXT-600 NACV PARAMETER ADJUSTMENT						
SB 505-34-0020 IN03 Airframe SB - Superseded #2156	NAVIGATION - NXT-600 NACV PARAMETER ADJUSTMENT						
SB 505-34-0020 R01 Airframe SB - Open #2182	NAVIGATION - NXT-600 NACV PARAMETER ADJUSTMENT						
SB 505-34-0021 Airframe SB - Open #2106	NAVIGATION - G1000-GROUND CLUTTER SUPPRESSION/TURBULENCE DETECTION SYSTEM ACTIVATION - S/N: 50500239						
SB 505-34-0022 Airframe SB - Open #2184	NAVIGATION - PREDICTIVE WINDSHEAR ACTIVATION						
SB 505-34-0024 Airframe SB - Open #2244	NAVIGATION - RADIO ALTIMETER SYSTEM - BAND-PASS FILTER INSTALLATION - G1000 SYSTEM						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-35-0001 Airframe SB - Complied With #967	OXYGEN - REPLACEMENT OF THE OXYGEN CYLINDER BRACKETS, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-35-0002 Airframe SB - N/A #75	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR) (SUPERSEDED BY SB 505-35-0002 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - TO AIRCRAFT SERIAL NUMBER						
SB 505-35-0002 R01 Airframe SB - Open #467	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR) (SUPERSEDED BY SB 505-35-0002 REV 02), SERVICE BULLETIN						
SB 505-35-0002 R02 Airframe SB - Complied With #238	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-35-0003 Airframe SB - Open #424	OXYGEN - INSTALLATION OF BLEED VENT VALVE TO THE OXYGEN LINE (SUPERSEDED BY SB 505-35-0003 REV 01), SERVICE BULLETIN						
SB 505-35-0003 R01 Airframe SB - Complied With #210	OXYGEN - INSTALLATION OF BLEED VENT VALVE TO THE OXYGEN LINE, SERVICE BULLETIN	12-MAY-2017 H: 1452.20 L: 1499					
	Notes COMPLIED WITH						
SB 505-36-0001 Airframe SB - N/A #1163	PNEUMATIC - REPLACEMENT OF THE AMS CONTROLLER (SUPERSEDED BY SB 505-36-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - TO AIRCRAFT SERIAL NUMBER						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-36-0001 R01 Airframe SB - Complied With #1350	PNEUMATIC - REPLACEMENT OF THE AMS CONTROLLER, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-36-0002 Airframe SB - Open #842	PNEUMATIC - AMS CONTROLLER SOFTWARE UPDATE GE AVIATION SYSTEM S.B. SYLZ-53632 -36-175 (SUPERSEDED BY SB 505-36-0002 REV 01) , SERVICE BULLETIN						
SB 505-36-0002 R01 Airframe SB - Complied With #216	PNEUMATIC - AMS CONTROLLER SOFTWARE UPDATE, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-36-0004 Airframe SB - Complied With #1659	PNEUMATIC - FAN AIR LINE REPLACEMENT, SERVICE BULLETIN	01-JUN-2015 H: 850.20 L: 933					
	Notes COMPLIED WITH - R7R TUBES 2EA						
SB 505-36-0005 Airframe SB - Complied With #932	PNEUMATIC - INSPECTION AND INSTALLATION OF A NEW FIXATION POINT TO THE BLEED LEAK 1 DETECTOR SYSTEM HARNESS, SERVICE BULLETIN	10-JUN-2015 H: 850.20 L: 933					
	Notes COMPLIED WITH						
SB 505-36-0006 Airframe SB - Open #1083	PNEUMATIC - AMS CONTROLLER (-204) SOFTWARE UPDATE, SERVICE BULLETIN						
SB 505-36-0007 Airframe SB - Open #35	PNEUMATIC - AMS CONTROLLER (-202 AND -203) SOFTWARE UPDATE, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-38-0001 Airframe SB - N/A #1855	WATER/WASTE - LAVATORY WATER SYSTEM AND SINK CABINET INSTALLATION (SUPERSEDED BY SB 505-38-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0001 R01 Airframe SB - N/A #723	WATER/WASTE - LAVATORY WATER SYSTEM AND SINK CABINET INSTALLATION (SUPERSEDED BY SB 505-38-0001 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0001 R02 Airframe SB - N/A #1510	WATER/WASTE - LAVATORY WATER SYSTEM AND SINK CABINET INSTALLATION (SUPERSEDED BY 505-38-0001 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0001 R03 Airframe SB - N/A #1886	WATER / WASTE - LAVATORY WATER SYSTEM AND SINK CABINET INSTALLATION, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0002 Airframe SB - N/A #988	WATER/WASTE - WASTE TANK DRAIN LINE MODIFICATION (SUPERSEDED BY SB 505-38-0002 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0002 R01 Airframe SB - N/A #315	WATER/WASTE - WASTE TANK DRAIN LINE MODIFICATION (SUPERSEDED BY SB 505-38-0002 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-38-0002 R02 Airframe SB - N/A #1090	WATER/WASTE - WASTE TANK DRAIN LINE MODIFICATION (SUPERSEDED BY SB 505-38-0002 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0002 R03 Airframe SB - Complied With #1829	WATER/WASTE - WASTE TANK DRAIN LINE MODIFICATION (SUPERSEDED BY SB 505-38-0002 REV 04), SERVICE BULLETIN						
	Notes COMPLIED WITH	10-APR-2014 H: 623.30 L: 675					
SB 505-38-0002 R04 Airframe SB - Open #1626	WATER/WASTE - WASTE TANK DRAIN LINE MODIFICATION, SERVICE BULLETIN						
SB 505-38-0003 Airframe SB - N/A #718	WATER/WASTE - REWORK OF THE WASTE TANK - MODIFICATION TO RECIRCULATING TOILET ASSEMBLY P/N RTA9147-00 (SUPERSEDED BY SB 505-38-0003 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-38-0003 R01 Airframe SB - Open #450	WATER/WASTE - REWORK OF THE WASTE TANK - MODIFICATION TO RECIRCULATING TOILET ASSEMBLY P/N RTA9147-00 (SUPERSEDED BY SB 505-38-0003 REV 02), SERVICE BULLETIN						
SB 505-38-0003 R02 Airframe SB - Open #1768	WATER/WASTE - REWORK OF THE WASTE TANK - MODIFICATION TO RECIRCULATING TOILET ASSEMBLY P/N RTA9147-00 (SUPERSEDED BY SB 505-38-0003 REV 03), SERVICE BULLETIN						
SB 505-38-0003 R03 Airframe SB - Complied With #1780	WATER/WASTE - REWORK OF THE WASTE TANK - MODIFICATION TO RECIRCULATING TOILET ASSEMBLY P/N RTA9147-00, SERVICE BULLETIN						
	Notes COMPLIED WITH	19-MAY-2016 H: 1156.90 L: 1222					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-38-0004 Airframe SB - N/A #1358	WATER/WASTE - WASTE TANK REPLACEMENT (SUPERSEDED BY SB 505-38-0004 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-38-0004 R01 Airframe SB - Open #1099	WATER/WASTE - WASTE TANK REPLACEMENT (SUPERSEDED BY SB 505-38-0004 REV 02), SERVICE BULLETIN Notes OPERATORS DISCRETION						
SB 505-38-0004 R02 Airframe SB - Open #1586	WATER/WASTE - WASTE TANK REPLACEMENT, SERVICE BULLETIN Notes OPERATORS DISCRETION						
SB 505-44-0001 Airframe SB - N/A #1850	CABIN SYSTEMS - 7" LCD (LIQUID CRYSTAL LIQUID) MONITORS INSTALLATION, SERVICE BULLETIN Notes NOT APPLICABLE	07-MAY-2012					
SB 505-44-0003 Airframe SB - N/A #1147	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-44-0003 R01 Airframe SB - N/A #1917	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0003 R02 Airframe SB - N/A #60	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R03 Airframe SB - N/A #883	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R04 Airframe SB - N/A #1853	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R05 Airframe SB - N/A #1144	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R06 Airframe SB - N/A #1288	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 07), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R07 Airframe SB - N/A #1801	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 08), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0003 R08 Airframe SB - N/A #129	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 09), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R09 Airframe SB - N/A #49	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 10), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R10 Airframe SB - N/A #868	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 11), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R11 Airframe SB - N/A #1930	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 12), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R12 Airframe SB - N/A #756	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 13), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R13 Airframe SB - N/A #654	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 14), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0003 R14 Airframe SB - N/A #783	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 15), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R15 Airframe SB - N/A #1448	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 16), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R16 Airframe SB - N/A #1498	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 17), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R17 Airframe SB - N/A #371	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 18), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R18 Airframe SB - N/A #1399	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 19), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R20 Airframe SB - N/A #1328	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 21), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0003 R21 Airframe SB - N/A #1264	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 22), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R22 Airframe SB - N/A #1167	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 23), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R23 Airframe SB - N/A #950	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 24), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R24 Airframe SB - N/A #2	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 25), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R25 Airframe SB - N/A #471	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 26), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R26 Airframe SB - N/A #338	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 27), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0003 R27 Airframe SB - N/A #1524	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 28), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R28 Airframe SB - N/A #1981	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 29), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R29 Airframe SB - Open #1152	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 30), SERVICE BULLETIN						
SB 505-44-0003 R30 Airframe SB - Open #1484	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS), SERVICE BULLETIN						
SB 505-44-0003 R31 Airframe SB - N/A #91	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY 505-44-0003 REV 32), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R32 Airframe SB - N/A #899	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS),, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0003 R33 Airframe SB - Open #2018	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (REV. 33)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0003/19 Airframe SB - N/A #1942	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS) (SUPERSEDED BY SB 505-44-0003 REV 20), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-44-0004 PART I Airframe SB - N/A #1863	ACCOMPLISH CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) EQUIPMENT INSTALLATION (SUPERSEDED BY SB 505-44-0004 REV 01), SERVICE BULLETIN FOR SUBWOOFER HOUSING INSTALLED						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-44-0004 PART II Airframe SB - N/A #1848	ACCOMPLISH CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) EQUIPMENT INSTALLATION (SUPERSEDED BY SB 505-44-0004 REV 01), SERVICE BULLETIN SUBWOOFER HOUSING NOT INSTALLED						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-44-0004 Airframe SB - N/A #347	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) EQUIPMENT INSTALLATION (SUPERSEDED BY SB 505-44-0004 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-44-0004 R01 PART I Airframe SB - N/A #360	ACCOMPLISH, SERVICE BULLETIN SUBWOOFER HOUSING INSTALLED						
	Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-44-0004 R01 PART II Airframe SB - N/A #1199	ACCOMPLISH, SERVICE BULLETIN SUBWOOFER HOUSING NOT INSTALLED						
	Notes NOT APPLICABLE OPERATORS DISCRETION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0004 R01 Airframe SB - N/A #1034	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) EQUIPMENT INSTALLATION, SERVICE BULLETIN Notes NOT APPLICABLE OPERATORS DISCRETION						
SB 505-44-0005 Airframe SB - N/A #482	CABIN SYSTEMS - VIP CONTROL PANEL REPLACEMENT, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-44-0006 Airframe SB - Open #592	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) WIRELESS EQUIPMENT INSTALLATION, SERVICE BULLETIN						
SB 505-44-0006 R01 Airframe SB - Open #2189	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) WIRELESS EQUIPMENT INSTALLATION						
SB 505-44-0007 Airframe SB - N/A #1831	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT EQUIPMENT) WIRED AUDIO FEATURE - INSTALLATION (SUPERSEDED BY 505-44-0007 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-44-0007 R01 Airframe SB - N/A #614	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT EQUIPMENT) WIRED AUDIO FEATURE - INSTALLATION (SUPERSEDED BY 505-44-0007 REV 02), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-44-0007 R02 Airframe SB - N/A #1782	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT EQUIPMENT) WIRED AUDIO FEATURE - INSTALLATION, SERVICE BULLETIN Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-44-0008 Airframe SB - Open #2048	CABIN SYSTEMS - AVIATOR 300 HSD SYSTEM INSTALLATION						
SB 505-44-0008 R01 Airframe SB - Open #2064	CABIN SYSTEMS - AVIATOR 300 HSD SYSTEM INSTALLATION						
SB 505-44-0009 Airframe SB - Open #2091	CABIN SYSTEMS - AVIATOR 300 HSD SYSTEM INSTALLATION						
SB 505-45-0001 Airframe SB - N/A #1194	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER (CMC) LOAD V2.0 SOFTWARE UPLOAD (SUPERSEDED BY SB 505-45-0002), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-45-0002 Airframe SB - N/A #1622	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER (CMC) LOAD V2.01A SOFTWARE UPLOAD, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-45-0003 Airframe SB - Open #2079	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER(CMC) LOAD v5.30 SOFTWARE UPLOAD						
SB 505-45-0003 R01 Airframe SB - Open #2102	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER (CMC) LOAD v5.30 SOFTWARE UPLOAD						
SB 505-50-0001 Airframe SB - Open #2104	BAGGAGE AND ACCESSORY COMPARTMENTS - TOWBAR HEAD STORAGE INSTALLATION						
SB 505-52-0001 Airframe SB - Open #213	DOORS - IMPROVEMENT ON THE BATTERY AND AFT BAGGAGE DOOR LOCK CAM (SUPERSEDED BY SB 505-52-0001 REV 01), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-52-0001 R01 Airframe SB - Complied With #593	DOORS - IMPROVEMENT ON THE BATTERY AND AFT BAGGAGE DOOR LOCK CAM (SUPERSEDED BY SB 505-52-0001 REV 02), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-52-0001 R02 Airframe SB - N/A #1478	DOORS - IMPROVEMENT ON THE BATTERY AND AFT BAGGAGE DOOR LOCK CAM, SERVICE BULLETIN	17-MAY-2013 H: 330.50 L: 349					
	Notes NOT APPLICABLE - S/N 50500055 AN EQUIVALENT MODIFICATION FACTORY - INCORPORATED						
SB 505-52-0002 Airframe SB - Complied With #693	DOORS - RH WING-TO-FUSELAGE AFT FAIRING ACCESS DOOR IMPROVEMENT (SUPERSEDED BY SB 505-52-0002 REV 02), SERVICE BULLETIN	15-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - COMPLIED WITH SB 505-52-0002						
SB 505-52-0002 R01 Airframe SB - Open #37	DOORS - RH WING-TO-FUSELAGE AFT FAIRING ACCESS DOOR IMPROVEMENT, SERVICE BULLETIN						
SB 505-52-0002 R02 Airframe SB - Open #2069	DOORS - RH WING-TO-FUSELAGE AFT FAIRING ACCESS DOOR IMPROVEMENT						
SB 505-52-0003 Airframe SB - N/A #1885	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT (SUPERSEDED BY SB 505-52- 0003 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-52-0003 PART II Airframe SB - N/A #1469	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT (SUPERSEDED BY SB 505-52- 0003 REV 01), SERVICE BULLETIN MAIN DOOR AFT AND FORWARD LINING REPLACEMENT						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-52-0003 PART I Airframe SB - N/A #1351	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT (SUPERSEDED BY SB 505-52-0003 REV 01), SERVICE BULLETIN MAIN DOOR REWORK, AFT AND FORWARD LINING REPLACEMENT Notes NOT APPLICABLE						
SB 505-52-0003 R01 Airframe SB - Open #1239	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT, SERVICE BULLETIN						
SB 505-52-0003 R01 PART II Airframe SB - N/A #1776	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT, SERVICE BULLETIN MAIN DOOR AFT AND FORWARD LINING REPLACEMENT Notes NOT APPLICABLE						
SB 505-52-0003 R01 PART I Airframe SB - Open #633	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT, SERVICE BULLETIN MAIN DOOR REWORK, AFT AND FORWARD LINING REPLACEMENT						
SB 505-52-0003 R02 Airframe SB - Open #2029	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT (REV. 2)						
SB 505-52-0004 Airframe SB - N/A #1714	DOORS - MOVABLE FLOOR TRIM INSTALLATION, SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-52-0004 R01 Airframe SB - Open #2095	DOORS - MOVABLE FLOOR TRIM INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-52-0005 PART II Airframe SB - N/A #177	ACCOMPLISH DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 01), SERVICE BULLETIN MAIN DOOR BALANCING MECHANISM CABLE AND GEAR SECTOR REPLACEMENT	12-MAY-2017 H: 1452.20 L: 1499					
	Notes NOT APPLICABLE						
SB 505-52-0005 PART I Airframe SB - Complied With #1087	ACCOMPLISH DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 01), SERVICE BULLETIN MAIN DOOR BALANCING MECHANISM CABLE REPLACEMENT	12-MAY-2017 H: 1452.20 L: 1499					
	Notes COMPLIED WITH						
SB 505-52-0005 Airframe SB - Complied With #320	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 01), SERVICE BULLETIN	12-MAY-2017 H: 1452.20 L: 1499					
	Notes COMPLIED WITH						
SB 505-52-0005 R01 PART III Airframe SB - Open #1230	ACCOMPLISH DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 02), SERVICE BULLETIN ADDITIONAL ACTION - INSTALLATION OF DECAL						
SB 505-52-0005 R01 PART II Airframe SB - Open #1377	ACCOMPLISH DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 02), SERVICE BULLETIN MAIN DOOR BALANCING MECHANISM CABLE AND GEAR SECTOR REPLACEMENT						
SB 505-52-0005 R01 PART I Airframe SB - Open #770	ACCOMPLISH DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 02), SERVICE BULLETIN MAIN DOOR BALANCING MECHANISM CABLE REPLACEMENT						
SB 505-52-0005 R01 Airframe SB - Open #1827	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION (SUPERSEDED BY 505-52-0005 REV 02), SERVICE BULLETIN						
SB 505-52-0005 R02 PART III Airframe SB - Open #547	ACCOMPLISH, SERVICE BULLETIN ADDITIONAL ACTION - INSTALLATION OF DECAL						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-52-0005 R02 PART II Airframe SB - Open #901	ACCOMPLISH, SERVICE BULLETIN MAIN DOOR BALANCING MECHANISM CABLE AND GEAR SECTOR REPLACEMENT						
SB 505-52-0005 R02 PART I Airframe SB - Open #1137	ACCOMPLISH, SERVICE BULLETIN MAIN DOOR BALANCING MECHANISM CABLE REPLACEMENT						
SB 505-52-0005 R02 Airframe SB - Open #834	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION, SERVICE BULLETIN						
SB 505-52-0006 Airframe SB - Open #1092	DOORS - MAIN DOOR - METALLIC SILL INSTALLATION, SERVICE BULLETIN						
SB 505-53-0001 Airframe SB - N/A #538	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE (SUPERSEDED BY SB 505-53-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-53-0001 R01 Airframe SB - N/A #810	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE (SUPERSEDED BY SB 505-53-0001 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-53-0001 R02 Airframe SB - N/A #454	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE (SUPERSEDED BY SB 505-53-0001 REV 03), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-53-0001 R03 Airframe SB - N/A #1464	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE (SUPERSEDED BY SB 505-53-0001 REV 04), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-53-0001 R04 Airframe SB - N/A #1940	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE (SUPERSEDED BY SB 505-53-0001 REV 05), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-53-0001 R05 Airframe SB - N/A #1121	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE (SUPERSEDED BY SB 505-53-0001 REV 06), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-53-0001 R06 Airframe SB - Open #569	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE, SERVICE BULLETIN						
SB 505-53-0002 Airframe SB - Complied With #965	FUSELAGE - RADOME BONDING PLATE INSTALLATION, SERVICE BULLETIN					19-MAY-2016 H: 1156.90 L: 1222	
	Notes COMPLIED WITH						
SB 505-53-0003 Airframe SB - Open #555	FUSELAGE - AFT FUSELAGE GRATE REPLACEMENT (SUPERSEDED BY SB 505-53-0005), SERVICE BULLETIN						
SB 505-53-0003 R01 Airframe SB - Open #1257	FUSELAGE - AFT FUSELAGE GRATE REPLACEMENT (SUPERSEDED BY SB 505-53-0005 REV 01), SERVICE BULLETIN						
SB 505-53-0003 R02 Airframe SB - Open #938	FUSELAGE - AFT FUSELAGE GRATE REPLACEMENT (SUPERSEDED BY SB 505-53-0005 REV 01), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-53-0004 Airframe SB - Open #1530	FUSELAGE - POLYURETHANE FILM INSTALLATION, SERVICE BULLETIN						
SB 505-53-0005 Airframe SB - Open #1604	FUSELAGE - AFT FUSELAGE GRATE - TO RETURN TO PREVIOUS CONFIGURATION (SUPERSEDED BY SB 505-53-0005 REV 01), SERVICE BULLETIN						
SB 505-53-0005 R01 Airframe SB - Open #943	FUSELAGE - AFT FUSELAGE GRATE - TO RETURN TO PREVIOUS CONFIGURATION, SERVICE BULLETIN						
SB 505-53-0006 Airframe SB - Open #2178	FUSELAGE - INSTALLATION OF RIVETS ON FRAME 19						
SB 505-54-0001 Airframe SB - Complied With #294	NACELLES/PYLONS - REINFORCEMENTS IN YOKE GUSSETS, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-54-0002 PART I Airframe SB - Open #293	INSPECTION NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2 (SUPERSEDED BY SB 505-54-0002 REV 01), SERVICE BULLETIN - FIXED BUSHING OF THE YOKE 2						
SB 505-54-0002 PART II Airframe SB - Open #358	INSTALLATION NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2 (SUPERSEDED BY SB 505-54-0002 REV 01), SERVICE BULLETIN OF AXIAL LOCK						
SB 505-54-0002 Airframe SB - Open #717	NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2 (SUPERSEDED BY SB 505-54-0002 REV 01), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-54-0002 R01 PART II Airframe SB - Complied With #282	INSTALLATION NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2, SERVICE BULLETIN AXIAL LOCK INSTALLATION	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-54-0002 R01 Airframe SB - Complied With #1799	NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-54-0002 R01 PART I Airframe SB - Complied With #1826	VISUAL INSPECTION NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2, SERVICE BULLETIN YOKE 2 FIXED BUSHING INSPECTION	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-54-0003 Airframe SB - N/A #1655	NACELLES/PYLONS - REPLACEMENT OF THE FIXED BUSHING RIVETS, SERVICE BULLETIN						
	Notes NOT APPLICABLE - C/W EQUIVALENT MODIFICATION FACTORY-INCORPORATED						
SB 505-55-0001 Airframe SB - N/A #1565	STABILIZERS - REPLACEMENT OF THE BOLTS OF THE RUDDER MASS BALANCE (SUPERSEDED BY SB 505-55-0001 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-55-0001 R01 Airframe SB - Complied With #464	STABILIZERS - REPLACEMENT OF THE BOLTS OF THE RUDDER MASS BALANCE, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-55-0002 Airframe SB - Complied With #1588	STABILIZERS - REPLACEMENT OF THE BOLTS OF ELEVATOR MASS BALANCE, SERVICE BULLETIN	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
SB 505-55-0003 Airframe SB - Open #879	STABILIZERS - ELIMINATION OF INTERFERENCE BETWEEN THE BOLTS THAT ATTACH VERTICAL STABILIZER AND AFT FUSELAGE FRAME 43 (SUPERSEDED BY SB 505-55-0003 REV 01), SERVICE BULLETIN						
SB 505-55-0003 R01 Airframe SB - Complied With #1343	STABILIZERS - ELIMINATION OF INTERFERENCE BETWEEN THE BOLTS THAT ATTACH VERTICAL STABILIZER AND AFT FUSELAGE FRAME 43, SERVICE BULLETIN	13-JUL-2016 H: 1201.40 L: 1270					
	Notes COMPLIED WITH						
SB 505-55-0004 IN01 Airframe SB - Open #2119	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT						
SB 505-55-0004 IN02 Airframe SB - Open #2151	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT						
SB 505-55-0004 R01 PART II Airframe SB - Complied With #2224	AILERON MASS BALANCE AND ATTACHMENT PARTS REPLACEMENT	18-JUL-2022 H: 2611.00 L: 2496					
SB 505-55-0004 R01 PART I Airframe SB - Open #2223	ELEVATOR MASS BALANCE AND ATTACHMENT PARTS REPLACEMENT						
SB 505-55-0004 R01 PART III Airframe SB - Complied With #2222	RUDDER MASS BALANCE AND ATTACHMENT PARTS REPLACEMENT	18-JUL-2022 H: 2611.00 L: 2496					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-55-0004 R01 Airframe SB - Complied With #2121	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT	04-MAY-2021 H: 2376.70 L: 2304					
SB 505-55-0004 R01 IN01 Airframe SB - Open #2142	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT						
SB 505-55-A004 Airframe SB - Superseded #2114	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT						
SB 505-55-A004 R02 Airframe SB - Superseded #2099	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT						
SB 505-55-A004 R03 Airframe SB - Superseded #2100	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT						
SB 505-55-A004 R04 Airframe SB - Complied With #2101	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT	13-DEC-2019 H: 2125.00 L: 2121					
SB 505-55-A004 R05 Airframe SB - Open #2103	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT						
SB 505-55-A004 R06 Airframe SB - Open #2115	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT REV. 06						
SB 505-56-0001 Airframe SB - Open #66	WINDOWS - PASSENGER CABIN WINDOWS IMPROVEMENTS (SUPERSEDED BY SB 505-56-0001 REV 01), SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-56-0001 R01 Airframe SB - N/A #1139	WINDOWS - PASSENGER CABIN WINDOWS IMPROVEMENTS (SUPERSEDED BY SB 505-56-0001 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-56-0001 R02 PART II Airframe SB - N/A #845	ACCOMPLISH PASSENGER CABIN WINDOWS IMPROVEMENTS, SERVICE BULLETIN - ADDITIONAL ACTION; CORRECTION OF ACCOMPLISHMENT INSTRUCTIONS						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-56-0001 R02 PART I Airframe SB - N/A #323	ACCOMPLISH PASSENGER CABIN WINDOWS IMPROVEMENTS, SERVICE BULLETIN - IMPROVEMENT OF CABIN WINDOWS						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-56-0001 R02 Airframe SB - N/A #724	PASSENGER CABIN WINDOWS IMPROVEMENTS, SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-56-0002 Airframe SB - Open #496	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 01), SERVICE BULLETIN						
SB 505-56-0002 PART II Airframe SB - N/A #223	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 01), SERVICE BULLETIN 6 PAX CABIN CONFIGURATION						
	Notes NOT APPLICABLE						
SB 505-56-0002 PART I Airframe SB - Open #769	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 01), SERVICE BULLETIN 7 PAX CABIN CONFIGURATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-56-0002 R01 Airframe SB - Open #560	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 02), SERVICE BULLETIN						
SB 505-56-0002 R01 PART II Airframe SB - N/A #1807	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 02), SERVICE BULLETIN 6 PAX CABIN CONFIGURATION						
	Notes NOT APPLICABLE						
SB 505-56-0002 R01 PART I Airframe SB - Open #971	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 02), SERVICE BULLETIN 7 PAX CABIN CONFIGURATION						
SB 505-56-0002 R01 PART III Airframe SB - N/A #856	WINDOWS - PASSENGER CABIN WINDOWS REWORK (SUPERSEDED BY SB 505-56-0002 REV 02), SERVICE BULLETIN 7 PAX CABIN CONFIGURATION WITH LIFE VEST						
	Notes NOT APPLICABLE						
SB 505-56-0002 R02 PART II Airframe SB - Open #1566	ACCOMPLISH WINDOWS - PASSENGER CABIN WINDOWS REWORK, SERVICE BULLETIN 6 PAX CABIN CONFIGURATION						
SB 505-56-0002 R02 PART I Airframe SB - Open #624	ACCOMPLISH WINDOWS - PASSENGER CABIN WINDOWS REWORK, SERVICE BULLETIN 7 PAX CABIN CONFIGURATION						
SB 505-56-0002 R02 PART III Airframe SB - Open #944	ACCOMPLISH WINDOWS - PASSENGER CABIN WINDOWS REWORK, SERVICE BULLETIN 7 PAX CABIN CONFIGURATION WITH LIFE VEST						
SB 505-56-0002 R02 Airframe SB - Open #429	WINDOWS - PASSENGER CABIN WINDOWS REWORK, SERVICE BULLETIN						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-56-0003 Airframe SB - N/A #1457	WINDOWS - NEW PAX WINDOW TRANSPARENCIES (SUPERSEDED BY SB 505-56-0003 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-56-0003 R01 Airframe SB - N/A #924	WINDOWS - NEW PAX WINDOW TRANSPARENCIES (SUPERSEDED BY SB 505-56-0003 REV 02), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-56-0003 R01 PART II Airframe SB - N/A #1046	WINDOWS - NEW PAX WINDOW TRANSPARENCIES (SUPERSEDED BY SB 505-56-0003 REV 02), SERVICE BULLETIN TRANSPARENCIES REPLACEMENT						
	Notes NOT APPLICABLE						
SB 505-56-0003 R01 PART I Airframe SB - N/A #1648	WINDOWS - NEW PAX WINDOW TRANSPARENCIES (SUPERSEDED BY SB 505-56-0003 REV 02), SERVICE BULLETIN TRANSPARENCIES REPLACEMENT, WATER DRAIN REROUTING AND PROTECTION INSTALLATION TO THE ELECTRICAL HARNESS						
	Notes NOT APPLICABLE						
SB 505-56-0003 R02 PART II Airframe SB - N/A #556	ACCOMPLISH WINDOWS - NEW PAX WINDOW TRANSPARENCIES, SERVICE BULLETIN TRANSPARENCIES REPLACEMENT						
	Notes NOT APPLICABLE						
SB 505-56-0003 R02 PART I Airframe SB - N/A #1835	ACCOMPLISH WINDOWS - NEW PAX WINDOW TRANSPARENCIES, SERVICE BULLETIN TRANSPARENCIES REPLACEMENT, WATER DRAIN REROUTING AND PROTECTION INSTALLATION TO THE ELECTRICAL HARNESS						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-56-0003 R02 Airframe SB - N/A #406	WINDOWS - NEW PAX WINDOW TRANSPARENCIES, SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-57-0001 Airframe SB - Open #1614	WINGS - BOLTS REPLACEMENT OF THE AILERON TAB MECHANISM FITTING (SUPERSEDED BY SB 505-57-0001 REV 01), SERVICE BULLETIN						
SB 505-57-0001 R01 Airframe SB - Complied With #606	WINGS - BOLTS REPLACEMENT OF THE AILERON TAB MECHANISM FITTING, SERVICE BULLETIN						
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW	17-MAY-2013 H: 330.50 L: 349					
SB 505-57-0002 Airframe SB - Complied With #1278	WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES (SUPERSEDED BY SB 505-57-0002 REV 01), SERVICE BULLETIN						
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW	17-MAY-2013 H: 330.50 L: 349					
SB 505-57-0002 R01 PART I Airframe SB - Complied With #1382	ACCOMPLISH WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES (SUPERSEDED BY SB 505-57-0002 REV 02), SERVICE BULLETIN ADDING NEW DRAIN HOLES TO THE CONTROL SURFACES						
	Notes COMPLIED WITH - THIS ITEM HAS BEEN P/C/W	17-MAY-2013 H: 330.50 L: 349					
SB 505-57-0002 R01 PART II Airframe SB - Complied With #691	ACCOMPLISH WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES (SUPERSEDED BY SB 505-57-0002 REV 02), SERVICE BULLETIN ADDING NEW DRAIN HOLES TO THE CONTROL SURFACES						
	Notes COMPLIED WITH - THIS ITEM HAS BEEN P/C/W	17-MAY-2013 H: 330.50 L: 349					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-57-0002 R01 Airframe SB - Complied With #574	WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES (SUPERSEDED BY SB 505-57-0002 REV 02), SERVICE BULLETIN	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN P/C/W						
SB 505-57-0002 R02 PART I Airframe SB - Complied With #627	ACCOMPLISH WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES, SERVICE BULLETIN AILERON, AILERON TRIM-TAB, AILERON HORN COVER, RUDDER, RUDDER TRIM-TAB, ELEVATOR, ELEVATOR AUTOTAB	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
SB 505-57-0002 R02 PART II Airframe SB - Complied With #1056	ACCOMPLISH WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES, SERVICE BULLETIN RUDDER, RUDDER TRIM-TAB, ELEVATOR, ELEVATOR AUTOTAB	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
SB 505-57-0002 R02 Airframe SB - Complied With #653	WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES, SERVICE BULLETIN						
	Notes COMPLIED WITH - BY PREVIOUS SB						
SB 505-57-0003 Airframe SB - Complied With #1460	WINGS - AILERON DRAIN HOLES INSPECTION, SERVICE BULLETIN	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
SB 505-57-0004 PART I Airframe SB - Complied With #641	INSPECTION WINGS - INSPECTION AND DRILLING OF DRAIN HOLES TO THE CONTROL SURFACES , SERVICE BULLETIN AND DRILLING OF DRAIN HOLES TO CONTROL SURFACES (AILERON, ELEVATOR AND RUDDER)	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN P/C/W						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-57-0004 PART II Airframe SB - Complied With #515	INSPECTION WINGS - INSPECTION AND DRILLING OF DRAIN HOLES TO THE CONTROL SURFACES , SERVICE BULLETIN AND DRILLING OF DRAIN HOLES TO CONTROL SURFACE (AILERON) Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW	17-MAY-2013 H: 330.50 L: 349					
SB 505-57-0004 Airframe SB - Complied With #728	WINGS - INSPECTION AND DRILLING OF DRAIN HOLES TO THE CONTROL SURFACES , SERVICE BULLETIN Notes COMPLIED WITH - THIS ITEM HAS BEEN P/C/W	17-MAY-2013 H: 330.50 L: 349					
SB 505-57-0005 Airframe SB - Complied With #1927	ELIMINATION OF THE AILERON TAB FITTING BOLT INTERFERENCE (SUPERSEDED BY SB 505-57-0005 REV 01), SERVICE BULLETIN Notes COMPLIED WITH - FOUND PWC	30-MAY-2013 H: 330.50 L: 349					
SB 505-57-0005 R01 Airframe SB - Complied With #426	WINGS - ELIMINATION OF THE AILERON TAB FITTING BOLT INTERFERENCE, SERVICE BULLETIN Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW	17-MAY-2013 H: 330.50 L: 349					
SB 505-57-0007 Airframe SB - N/A #1957	WINGS - ELECTRICAL BONDING CORRECTION FOR SEAL REINFORCEMENT AND LOCK STOPPER (SUPERSEDED BY SB 505-57-0007 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-57-0007 R01 Airframe SB - Open #1368	WINGS - ELECTRICAL BONDING CORRECTION FOR SEAL REINFORCEMENT AND LOCK STOPPER (SUPERSEDED BY SB 505-57-0007 REV 02), SERVICE BULLETIN						
SB 505-57-0007 R02 Airframe SB - Complied With #1818	WINGS - ELECTRICAL BONDING CORRECTION FOR SEAL REINFORCEMENT AND LOCK STOPPER, SERVICE BULLETIN Notes COMPLIED WITH	19-MAY-2016 H: 1156.90 L: 1222					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-57-0008 Airframe SB - Complied With #1665	WINGS - OUTBOARD-FLAP LOWER SHROUD SEAL REPLACEMENT, SERVICE BULLETIN	11-JUN-2015 H: 850.20 L: 933					
	Notes COMPLIED WITH						
SB 505-71-0001 Airframe SB - Open #410	ENGINE #1 POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET (SUPERSEDED BY 505-71-0006), SERVICE BULLETIN						
SB 505-71-0001 Airframe SB - Open #465	ENGINE #2 POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET SERVICE BULLETIN (SUPERSEDED BY 505-71-0006), SERVICE BULLETIN						
SB 505-71-0001 R01 Airframe SB - Complied With #1102	ENGINE #1 POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0006), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-71-0001 R01 Airframe SB - Complied With #889	ENGINE #2 POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0006), SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-71-0001 R02 Airframe SB - N/A #1232	ENGINE #1 POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0006), SERVICE BULLETIN						
	Notes NOT APPLICABLE						
SB 505-71-0001 R02 Airframe SB - N/A #832	ENGINE #2 POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0006), SERVICE BULLETIN						
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-71-0001 R03 Airframe SB - Open #2198	POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET						
SB 505-71-0002 Airframe SB - N/A #1642	POWERPLANT - REPLACEMENT OF THE RH ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0002 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT S/N.						
SB 505-71-0002 R01 Airframe SB - Open #250	POWERPLANT - ASSISTANCE TO REPLACE RH ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0002 REV 02), SERVICE BULLETIN						
SB 505-71-0002 R02 Airframe SB - N/A #212	POWERPLANT - ASSISTANCE TO REPLACE RH ENGINE AIR INLET, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-71-0003 Airframe SB - Complied With #1979	POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET, SERVICE BULLETIN	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-71-0003 PART II Airframe SB - Complied With #1609	REPLACE POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET, SERVICE BULLETIN THE LH ENGINE AIR INLET FROM PN 505-36900-401 OR PN 505-36900-403 OR PN 505-36920-403 TO PN 505-36920-405.	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						
SB 505-71-0003 PART I Airframe SB - Complied With #379	REPLACE POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET, SERVICE BULLETIN THE RH ENGINE AIR INLET PN 505-36910-401 OR 505-36910-403 OR PN 505-36930-403 WITH PN 505-36930-405.	07-MAY-2012					
	Notes COMPLIED WITH - AT MANUFACTURE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-71-0004 Airframe SB - N/A #1111	POWERPLANT - INSPECTION OF ENGINE FORWARD MOUNT ASSEMBLY, SERVICE BULLETIN	07-MAY-2012					
	Notes NOT APPLICABLE						
SB 505-71-0005 Airframe SB - N/A #492	POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 01), SERVICE BULLETIN						
	Notes NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER						
SB 505-71-0005 R01 Airframe SB - Open #1494	POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 02), SERVICE BULLETIN						
SB 505-71-0005 R01 PART I Airframe SB - Open #1475	REINFORCEMENT POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 02), SERVICE BULLETIN - OF THE NACELLE MID COWLS						
SB 505-71-0005 R01 PART II Airframe SB - Open #586	REPLACEMENT POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 02), SERVICE BULLETIN - OF THE LOCK STOPPER ON THE PYLON FAIRING						
SB 505-71-0005 R02 Airframe SB - Open #1133	POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 03), SERVICE BULLETIN						
SB 505-71-0005 R02 PART I Airframe SB - Open #1873	REINFORCEMENT POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 03), SERVICE BULLETIN - OF THE NACELLE MID COWLS						
SB 505-71-0005 R02 PART II Airframe SB - Open #1331	REPLACEMENT POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS (SUPERSEDED BY SB 505-71-0005 REV 03), SERVICE BULLETIN - OF THE LOCK STOPPER ON THE PYLON FAIRING						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-71-0005 R03 PART II Airframe SB - Complied With #324	ADDITIONAL ACTION POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS, SERVICE BULLETIN - REPLACEMENT OF THE LOCK STOPPER ON THE PYLON FAIRING	18-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH						
SB 505-71-0005 R03 Airframe SB - Complied With #1215	POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS, SERVICE BULLETIN	18-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH						
SB 505-71-0005 R03 PART I Airframe SB - Complied With #806	REINFORCEMENT POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS, SERVICE BULLETIN OF THE NACELLE MID COWLS	18-APR-2014 H: 623.30 L: 675					
	Notes COMPLIED WITH						
SB 505-71-0006 PART I Airframe SB - N/A #644	ACCOMPLISH POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET, SERVICE BULLETIN	26-AUG-2015 H: 909.40 L: 989					
	Notes NOT APPLICABLE - APPLIED SB505-71-0008 INSTALLED P/N:505-43420-403 AND 505-43430-403						
SB 505-71-0006 PART II Airframe SB - N/A #483	ACCOMPLISH POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET, SERVICE BULLETIN	26-AUG-2015 H: 909.40 L: 989					
	Notes NOT APPLICABLE - APPLIED SB505-71-0008 INSTALLED P/N:505-43420-403 AND 505-43430-403						
SB 505-71-0006 Airframe SB - N/A #343	POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET, SERVICE BULLETIN	26-AUG-2015 H: 909.40 L: 989					
	Notes NOT APPLICABLE - APPLIED SB505-71-0008 INSTALLED P/N:505-43420-403 AND 505-43430-403						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-71-0007 Airframe SB - N/A #897	POWERPLANT - DRAIN MAST REPLACEMENT (SUPERSEDED BY SB 505-71-0007 REV 01), SERVICE BULLETIN Notes NOT APPLICABLE						
SB 505-71-0007 R01 Airframe SB - Complied With #119	POWERPLANT - DRAIN MAST REPLACEMENT (SUPERSEDED BY SB 505-71-0007 REV 02), SERVICE BULLETIN Notes COMPLIED WITH					18-APR-2014 H: 623.30 L: 675	
SB 505-71-0007 R02 Airframe SB - Open #977	POWERPLANT - DRAIN MAST REPLACEMENT (SUPERSEDED BY SB 505-71-0007 REV 03), SERVICE BULLETIN						
SB 505-71-0007 R03 Airframe SB - Open #1918	POWERPLANT - DRAIN MAST REPLACEMENT, SERVICE BULLETIN						
SB 505-71-0008 Airframe SB - Complied With #1511	POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET (SUPERSEDED BY SB 505-71-0008 REV 01), SERVICE BULLETIN Notes COMPLIED WITH					26-AUG-2015 H: 909.40 L: 989	
SB 505-71-0008 R01 Airframe SB - Open #397	POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET (SUPERSEDED BY 505-71-0008 REV 02), SERVICE BULLETIN						
SB 505-71-0008 R02 PART I Airframe SB - Open #1248	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF ENGINE AIR INLETS PN 505-43420-403 AND 505-43430-403						
SB 505-71-0008 R02 PART II Airframe SB - Open #1840	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF ENGINE AIR INLETS PN 505-43420-405 AND 505-43430-405						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-71-0008 R02 Airframe SB - Open #921	POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET, SERVICE BULLETIN						
SB 505-71-0009 PART I Airframe SB - Open #1921	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF LH ENGINE UPPER AND LOWER MID COWLS STUD ASSEMBLY						
	Notes OPERATORS DISCRETION						
SB 505-71-0009 PART II Airframe SB - Open #631	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF RH ENGINE UPPER AND LOWER MID COWLS STUD ASSEMBLY						
	Notes OPERATORS DISCRETION						
SB 505-71-0009 Airframe SB - Open #1515	POWERPLANT - REPLACEMENT OF LH/RH ENGINE UPPER AND LOWER MID COWLS STUD ASSEMBLY, SERVICE BULLETIN						
	Notes OPERATORS DISCRETION						

Maintenance Items

N204WC

Make & Model (Serial) EMBRAER EMB 505 (Phenom 300) (50500098)		Operator Sun Aviation LLC	Reported Date 03-May-2025	Hours 3043.40	Landings 2816
- Major Components					
Component	Model (Serial)	Hours	Cycles		
Engine 1	PW535E (PCE-DG0190)	3043.40	2816.00		
Engine 2	PW535E (PCE-DG0194)	3043.40	2816.00		

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-73-0001 Airframe SB - Open #333	NEW FADEC (FULL-AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE - VERSION 4.3 (SUPERSEDED BY SB 505-73-0001 REV 01), SERVICE BULLETIN						
SB 505-73-0001 R01 Airframe SB - Open #1740	ENGINE FUEL AND CONTROL - NEW FADEC (FULL-AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE - VERSION 4.3, SERVICE BULLETIN						
SB 505-73-0002 Airframe SB - Open #491	ENGINE FUEL AND CONTROL - ENGINE FUEL PRESSURE TUBE REPLACEMENT (SUPERSEDED BY SB 505-73-0002 REV 01), SERVICE BULLETIN						
SB 505-73-0002 R01 PART II Airframe SB - Complied With #393	ACCOMPLISH ENGINE FUEL AND CONTROL - ENGINE FUEL PRESSURE TUBE REPLACEMENT, SERVICE BULLETIN ADDITIONAL ACTION - ADAPTER REPLACEMENT	21-APR-2016 H: 1156.20 L: 1221					
	Notes COMPLIED WITH						
SB 505-73-0002 R01 PART I Airframe SB - Complied With #1705	ACCOMPLISH ENGINE FUEL AND CONTROL - ENGINE FUEL PRESSURE TUBE REPLACEMENT, SERVICE BULLETIN FUEL PRESSURE TUBE AND ADAPTER REPLACEMENT	21-APR-2016 H: 1156.20 L: 1221					
	Notes COMPLIED WITH						
SB 505-73-0002 R01 Airframe SB - Complied With #1022	ENGINE FUEL AND CONTROL - ENGINE FUEL PRESSURE TUBE REPLACEMENT, SERVICE BULLETIN	21-APR-2016 H: 1156.20 L: 1221					
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB PW300-72-30446 Engine 1 SB - N/A #48	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN Notes NOT APPLICABLE - BY ENGINE SERIAL NUMBER (PCE-DG0190) CATEGORY 7						
SB PW300-72-30446 Engine 2 SB - N/A #244	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN Notes NOT APPLICABLE - BY ENGINE SERIAL NUMBER (PCE-DG0194) CATEGORY 7						
SIL GEN-055 R10 Engine 1 SB - Open #376	GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES						
SIL GEN-055 R10 Engine 2 SB - Open #376	GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES						
SIL GEN-153R6 Engine 1 SB - Open #416	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						
SIL GEN-153R6 Engine 2 SB - Open #415	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						
SIL GEN-156 Engine 1 SB - Open #404	KATHON™ FP 1.5 FUEL BIOCIDES MANUFACTURED BY DUPONT						
SIL GEN-156 Engine 2 SB - Open #404	KATHON™ FP 1.5 FUEL BIOCIDES MANUFACTURED BY DUPONT						
SIL PW500-066R1 Engine 1 SB - Open #380	CANCELLED - LIMITED TIME OFFER FOR DATA TRANSMISSION UNIT (DTU) 3G UPGRADE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SIL PW500-066R1 Engine 2 SB - Open #380	CANCELLED - LIMITED TIME OFFER FOR DATA TRANSMISSION UNIT (DTU) 3G UPGRADE						
SIL PW500-073 Engine 1 SB - Open #381	OIL ANALYSIS TECHNOLOGY SOLUTION NOW AVAILABLE						
SIL PW500-073 Engine 2 SB - Open #381	OIL ANALYSIS TECHNOLOGY SOLUTION NOW AVAILABLE						
SL 505-00-0002 Airframe SB - Open #306	EMBRAER SOCIOENVIRONMENTAL RESPONSABILITY, SERVICE LETTER						
SL 505-00-0013 R02 Airframe SB - Open #2196	GENERAL - RECOMMENDATION FOR NOISE OR VIBRATION ISSUES						
SL 505-00-0027 Airframe SB - Open #2152	NEW PLATFORM FOR EMBRAER TECHNICAL PUBLICATIONS						
SL 505-00-0028 Airframe SB - Open #2160	COVID-19 VACCINES TRANSPORTATION - DRY ICE LOAD LIMITS GUIDELINES						
SL 505-00-0029 Airframe SB - Open #2164	CHANGE IN THE TECHNICAL PUBLICATION PART NUMBER						
SL 505-00-0030 Airframe SB - Open #2202	MODIFICATIONS IN THE LAYOUT OF STANDARD MANUAL (SM-2680) DUE TO EMBRAER EDITION SYSTEM CHANGES						
SL 505-00-0032 Airframe SB - Open #2208	NEW AMM PART IV - AIRWORTHINESS LIMITATIONS (AWL)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 505-00-007 R03 Airframe SB - Open #2149	LABOR FEES FOR IN-SERVICE TECHNICAL SUPPORT						
SL 505-12-0004 Airframe SB - Open #189	SERVICING - OPERATION IN WINTER - EMB-505 AIRCRAFT, SERVICE LETTER						
SL 505-12-0005 Airframe SB - Open #2186	WINDSHIELD CLEANING						
SL 505-21-0005 Airframe SB - Open #2183	VCS PRESSURE FAULT - SPURIOUS EVENTS						
SL 505-23-0002 Airframe SB - Open #987	COMMUNICATIONS - REMOTE AUDIO CONTROLLER GMA 36 MOD 3 AVAILABILITY, SERVICE LETTER						
SL 505-24-0002 Airframe SB - Open #516	ELECTRICAL POWER - BATTERIES - BEST PRACTICES MANUAL (SUPERSEDED BY SL505-24-0002 REV 01), SERVICE LETTER						
SL 505-24-0002 R01 Airframe SB - Open #227	ELECTRICAL POWER - BATTERIES - BEST PRACTICES MANUAL (SUPERSEDED BY SL505-24-0002 REV 02), SERVICE LETTER						
SL 505-24-0002 R02 Airframe SB - Open #1672	ELECTRICAL POWER - BATTERIES - BEST PRACTICES MANUAL, SERVICE LETTER						
SL 505-25-0003 Airframe SB - Open #2170	EQUIPMENT/FURNISHINGS - COCKPIT CURTAIN - FABRIC OBSOLESCENCE						
SL 505-27-0002 R01 Airframe SB - Open #2176	FLIGHT CONTROL SYSTEM - ADDITIONAL RECOMMENDATIONS FOR SPOILER FAIL						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SL 505-30-0001 Airframe SB - Open #25	ICE AND RAIN PROTECTION - INSPECTION / UPLOAD OF ICE DETECTOR FUNCTION (SUPERSEDED BY SL505-30-0001 REV 01), SERVICE LETTER						
SL 505-30-0001 R01 Airframe SB - Open #196	ICE AND RAIN PROTECTION - INSPECTION / UPLOAD OF ICE DETECTOR FUNCTION, SERVICE LETTER						
SL 505-32-0012 R01 Airframe SB - Open #2150	LANDING GEAR - WHEEL ASSEMBLY OVERHAUL						
SL 505-34-0003 Airframe SB - N/A #1578	NAVIGATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM - WARRANTY COVERAGE FOR ACSS SB, SERVICE LETTER					13-JUN-2012 H: 43.40 L: 49	
	Notes NOT APPLICABLE - N/A PER P/N.						
SL 505-35-0005 R01 Airframe SB - Open #2159	O2 CONTROL CABLE INSTALLATION CHECK						
SL 505-44-0001 R05 Airframe SB - Open #2042	LUFTHANSA TECHNIK CABIN MANAGEMENT SYSTEM SOFTWARE UPDATE						
SL 505-44-0001 R08 Airframe SB - Open #2158	LUFTHANSA TECHNIK CABIN MANAGEMENT SYSTEM SOFTWARE UPDATE						
SB 30470 R2 Engine 1 SB - Open #490	SERVICE BULLETIN - TURBOFAN ENGINE - DATA COLLECTION UNIT - REPLACEMENT OF						
SB 30470 R2 Engine 2 SB - Open #488	SERVICE BULLETIN - TURBOFAN ENGINE - DATA COLLECTION UNIT - REPLACEMENT OF						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30556R2 Engine 1 SB - Open #448	SERVICE BULLETIN - TURBOFAN ENGINE - GAS GENERATOR CASE - REPLACEMENT OF						
SB 30556R2 Engine 2 SB - Open #447	SERVICE BULLETIN - TURBOFAN ENGINE - GAS GENERATOR CASE - REPLACEMENT OF						
SB 30568 R1 Engine 1 SB - Open #442	TURBOFAN ENGINE - NO. 4 BEARING FRONT AND REAR SEAL RUNNERS - REPLACEMENT OF						
SB 30568 R1 Engine 2 SB - Open #441	TURBOFAN ENGINE - NO. 4 BEARING FRONT AND REAR SEAL RUNNERS - REPLACEMENT OF						
SB 30570 Engine 1 SB - Open #445	SERVICE BULLETIN - TURBOFAN ENGINE - FUEL CONTROL UNIT DRIVE SPUR GEAR SHAFT - REPLACEMENT OF						
SB 30570 Engine 2 SB - Open #444	SERVICE BULLETIN - TURBOFAN ENGINE - FUEL CONTROL UNIT DRIVE SPUR GEAR SHAFT - REPLACEMENT OF						
SB 30570 R1 Engine 1 SB - Open #481	SERVICE BULLETIN - TURBOFAN ENGINE - FUEL CONTROL UNIT DRIVE SPUR GEAR SHAFT - REPLACEMENT OF						
SB 30570 R1 Engine 2 SB - Open #480	SERVICE BULLETIN - TURBOFAN ENGINE - FUEL CONTROL UNIT DRIVE SPUR GEAR SHAFT - REPLACEMENT OF						
SB 30570 R2 Engine 1 SB - Open #487	SERVICE BULLETIN - TURBOFAN ENGINE - FUEL CONTROL UNIT DRIVE SPUR GEARSHAFT - REPLACEMENT OF						
SB 30570 R2 Engine 2 SB - Open #485	SERVICE BULLETIN - TURBOFAN ENGINE - FUEL CONTROL UNIT DRIVE SPUR GEARSHAFT - REPLACEMENT OF						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30573 Engine 1 SB - Open #443	SERVICE BULLETIN - TURBOFAN ENGINE - INTERMEDIATE CASE ASSEMBLY WALL THICKNESS - INSPECTION OF						
SB 30573 Engine 2 SB - Open #442	SERVICE BULLETIN - TURBOFAN ENGINE - INTERMEDIATE CASE ASSEMBLY WALL THICKNESS - INSPECTION OF						
SB 30576 Engine 1 SB - Open #482	SERVICE BULLETIN - TURBOFAN ENGINE - LP COMPRESSOR BOOST ROTOR - INSPECTION/REPLACEMENT OF						
SB 30576 Engine 2 SB - Open #481	SERVICE BULLETIN - TURBOFAN ENGINE - LP COMPRESSOR BOOST ROTOR - INSPECTION/REPLACEMENT OF						
SB 30578 Engine 1 SB - Open #484	SERVICE BULLETIN - TURBOFAN ENGINE - HIGH-PRESSURE COMPRESSOR SECOND-STAGE ROTOR - INSPECTION OF						
SB 30578 Engine 2 SB - Open #483	SERVICE BULLETIN - TURBOFAN ENGINE - HIGH-PRESSURE COMPRESSOR SECOND-STAGE ROTOR - INSPECTION OF						
SB 30579 Engine 1 SB - Open #483	SERVICE BULLETIN - TURBOFAN ENGINE - SHIPPING CONTAINER - REPLACEMENT/MODIFICATION OF						
SB 30579 Engine 2 SB - Open #482	SERVICE BULLETIN - TURBOFAN ENGINE - SHIPPING CONTAINER - REPLACEMENT/MODIFICATION OF						
SB 30580 Engine 1 SB - Open #485	SERVICE BULLETIN - TURBOFAN ENGINE - ENGINE SHIPPING CONTAINER - REPLACEMENT/MODIFICATION OF						
SB 30580 Engine 2 SB - Open #484	SERVICE BULLETIN - TURBOFAN ENGINE - ENGINE SHIPPING CONTAINER - REPLACEMENT/MODIFICATION OF						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 30581 Engine 1 SB - Open #488	SERVICE BULLETIN - TURBOFAN ENGINE - FIRST AND SECOND-STAGE LOW-PRESSURE-TURBINE BLADES - INSPECTION/REPLACEMENT OF						
SB 30581 Engine 2 SB - Open #486	SERVICE BULLETIN - TURBOFAN ENGINE - FIRST AND SECOND-STAGE LOW-PRESSURE-TURBINE BLADES - INSPECTION/REPLACEMENT OF						
SB 505-00-0008 R27 Airframe SB - Open #2233	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R29 Airframe SB - Open #2292	SERVICE BULLETIN - GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R30 Airframe SB - Open #2295	SERVICE BULLETIN - GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0008 R31 Airframe SB - Open #2309	SERVICE BULLETIN - GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE						
SB 505-00-0016 R4 Airframe SB - Open #2272	SERVICE BULLETIN - GENERAL - G3000 - CONVERSION FROM FAA TO TCCA CERTIFICATION BASIS REQUIREMENTS						
SB 505-00-0018 R15 Airframe SB - Open #2264	SERVICE BULLETIN - GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0018 R16 Airframe SB - Open #2286	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0018 R17 Airframe SB - Open #2305	SERVICE BULLETIN - GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-00-0018 R18 Airframe SB - Open #2307	SERVICE BULLETIN - GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0021 R3 Airframe SB - Open #2268	SERVICE BULLETIN - GENERAL - CONVERSION FROM FAA TO ANAC CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0021 R4 Airframe SB - Open #2273	SERVICE BULLETIN - GENERAL - CONVERSION FROM FAA TO ANAC CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH G3000 AVIONICS						
SB 505-00-0022 R1 Airframe SB - Open #2270	SERVICE BULLETIN - GENERAL - G3000 - CONVERSION FROM TCCA TO FAA CERTIFICATION BASIS REQUIREMENTS						
SB 505-00-0022 R2 Airframe SB - Open #2298	SERVICE BULLETIN - GENERAL - G3000 - CONVERSION FROM TCCA TO FAA CERTIFICATION BASIS REQUIREMENTS						
SB 505-00-0023 R1 Airframe SB - Open #2303	SERVICE BULLETIN - GENERAL - INSTALLATION OF FUSELAGE REGISTRATION PLACARD						
SB 505-00-0026 Airframe SB - Open #2236	GENERAL - W201 HARNESS ROUTING IMPROVEMENT						
SB 505-00-0027 Airframe SB - Open #2230	GENERAL - W302 HARNESS ROUTING IMPROVEMENT						
SB 505-00-0030 Airframe SB - Open #2263	SERVICE BULLETIN - GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT)						
SB 505-00-0031 Airframe SB - Open #2269	SERVICE BULLETIN - GENERAL - CONVERSION FROM ANAC TO EASA CERTIFICATION BASIS REQUIREMENTS						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-21-0013 R1 Airframe SB - Open #2294	SERVICE BULLETIN - AIR CONDITIONING - CHECK VALVE AND MUFFLER MODIFICATION						
SB 505-21-0015 R3 Airframe SB - Open #2255	SERVICE BULLETIN - AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT						
SB 505-21-0015 R4 Airframe SB - Open #2284	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT						
SB 505-22-0001 R01 Airframe SB - Open #2234	AUTO FLIGHT - VENTRAL RUDDER - WATER DEFLECTOR INSTALLATION AND SERVO ACTUATORS MOUNTING BOLTS REPLACEMENT						
SB 505-22-0004 R05 Airframe SB - Open #2254	SERVICE BULLETIN - AUTO FLIGHT - REPLACEMENT OF THE AILERON SERVO ASSEMBLY BOLT						
SB 505-22-0006 Airframe SB - Open #2265	SERVICE BULLETIN - AUTO FLIGHT - AILERON SERVO ASSEMBLY - PARTS REPLACEMENT						
SB 505-22-0006 R1 Airframe SB - Open #2290	SERVICE BULLETIN - AUTO FLIGHT -AILERON SERVO ASSEMBLY· PARTS REPLACEMENT						
SB 505-22-0007 Airframe SB - Open #2287	AUTO FLIGHT - AUTOTHROTTLE INSTALLATION						
SB 505-22-0007 R2 Airframe SB - Open #2300	SERVICE BULLETIN - AUTO FLIGHT - AUTOTHROTTLE INSTALLATION						
SB 505-22-0007 R3 Airframe SB - Open #2304	SERVICE BULLETIN - AUTO FLIGHT - AUTOTHROTTLE INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-22-0007 R4 Airframe SB - Open #2306	SERVICE BULLETIN - AUTO FLIGHT - AUTOTHROTTLE INSTALLATION						
SB 505-22-0007 R1 Airframe SB - Open #2293	SERVICE BULLETIN - AUTO FLIGHT - AUTOTHROTTLE INSTALLATION						
SB 505-23-0005 R5 Airframe SB - Open #2260	SERVICE BULLETIN - COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION)						
SB 505-23-0006 R6 Airframe SB - Open #2310	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION)						
SB 505-25-0011 R6 Airframe SB - Open #2258	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT						
SB 505-25-0046 R01 Airframe SB - Open #2237	EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION						
SB 505-25-0046 R02 Airframe SB - Open #2249	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION					19-FEB-2027	M: 18 D: 21
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						
SB 505-25-0046 R03 Airframe SB - Open #2253	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION						
SB 505-25-0046 R4 Airframe SB - Open #2291	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS • RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-25-0048 R4 Airframe SB - Open #2277	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS - INSTALLATION OF DNA SEATS						
SB 505-25-0055 Airframe SB - Open #2281	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS - COCKPIT SUN VISOR (BLUE FILM) - INSTALLATION						
SB 505-25-0059 Airframe SB - Open #2299	SERVICE BULLETIN - EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - ENGLISH/PORTUGUESE LANGUAGE						
SB 505-27-0030 Airframe SB - Open #2231	FLIGHT CONTROLS - PTA POSITION SENSOR FILTER INSTALLATION						
SB 505-27-0031 R4 Airframe SB - Open #2256	SERVICE BULLETIN - FLIGHT CONTROLS - FLIGHT CONTROL ELECTRONICS (FCE) CONTROL PANEL INSTALLATION						
SB 505-27-0034 Airframe SB - Open #2266	SERVICE BULLETIN - FLIGHT CONTROLS - INSPECTION AND ADJUSTMENT OF THE BACKLASH OF THE HORIZONTAL STABILIZER						
SB 505-27-0034 R2 Airframe SB - Open #2279	SERVICE BULLETIN - FLIGHT CONTROLS - INSPECTION AND ADJUSTMENT OF THE BACKLASH OF THE HORIZONTAL STABILIZER						
SB 505-31-0019 R5 Airframe SB - Open #2259	SERVICE BULLETIN - INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT						
SB 505-31-0025 R01 Airframe SB - Open #2235	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.10 AVIONICS SOFTWARE AND CMC LOAD 15.0						
SB 505-33-0010 Airframe SB - Open #2278	SERVICE BULLETIN - LIGHTS - LANDING AND TAXI LED LIGHTING - INSTALLATION						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 505-33-0010 R1 Airframe SB - Open #2308	SERVICE BULLETIN - LIGHTS LANDING AND TAXI LED LIGHTING - INSTALLATION						
SB 505-34-0010 R22 Airframe SB - Open #2251	SERVICE BULLETIN - NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R23 Airframe SB - Open #2276	SERVICE BULLETIN - NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R24 Airframe SB - Open #2283	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0010 R25 Airframe SB - Open #2301	SERVICE BULLETIN - NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0011 R21 Airframe SB - Open #2257	SERVICE BULLETIN - NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION						
SB 505-34-0028 Airframe SB - Open #2302	SERVICE BULLETIN - NAVIGATION - PITOT-STATIC PROBE HARNESS REPLACEMENT						
SB 505-46-0001 R3 Airframe SB - Open #2296	SERVICE BULLETIN - INFORMATION SYSTEMS - FLIGHT STREAM SYSTEM ACTIVATION						
SB 505-46-0001R2 Airframe SB - Open #2285	INFORMATION SYSTEMS - FLIGHT STREAM SYSTEM ACTIVATION						
SB 505-55-0004 R1 Airframe SB - Open #2297	SERVICE BULLETIN - STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1974-08-09 R3 Airframe AD - Recurring FAA #859	APPLIANCE AD - LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	03-MAY-2023 H: 2749.10 L: 2607	H: 1000.00			H: 3749.10	H: 705.70
AD 2003-26-14 Airframe AD - N/A FAA #387	APPLIANCE AD - TO REMOVE FROM SERVICE FIRE EXTINGUISHERS THAT HAVE THIS INCOMPLETE CRIMPING OF THE SIPHON TUBE	08-MAY-2012					
	Notes NOT APPLICABLE - DUE TO P/N INSTALLED, P/N RT-A1200 AND 33000073-1 EQUIPPED.						
AD 2005-01-19 Airframe AD - N/A FAA #1477	APPLIANCE AD - TO PREVENT INTERROGATING A/C FROM POSSIBLY RECEIVING INACCURATE REPLIES FROM A/C EQUIPPED WITH GARMIN GTX33/33D/330/330D MODE S TRANSPONDERS	08-MAY-2012					
	Notes NOT APPLICABLE - DUE TO SOFTWARE VERSION						
AD 2010-01-03 Airframe AD - N/A FAA #1687	APPLIANCE AD - REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS	08-MAY-2012					
	Notes NOT APPLICABLE - DUE TO P/N INSTALLED, P/N RT-A1200 AND 33000073-1 EQUIPPED.						
AD 2010-04-16 Airframe AD - N/A FAA #1725	APPLIANCE AD - REPLACE ALL TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI, HAVING P/N 1708337B4	08-MAY-2012					
	Notes NOT APPLICABLE - DUE TO P/N INSTALLED, P/N RT-A1200 AND 33000073-1 EQUIPPED.						
AD 2011-01-09 Airframe AD - Open FAA #917	APPLIANCE AD - TO PREVENT PBE UNITS FROM IGNITING						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2011-04-09 Airframe AD - N/A FAA #1236	APPLIANCE AD - OXYGEN GENERATOR DEACTIVATION (SUPERSEDED BY FAA AD 2012-11-09) Notes NOT APPLICABLE - OXYGEN GENERATOR NOT INSTALL IN THIS AIRCRAFT	11-JUN-2012 H: 32.80 L: 37					
AD 2011-14-08 Airframe AD - Complied With FAA #1875	APPLIANCE AD - AN INSPECTION/RECORDS CHECK TO DETERMINE THE MANUFACTURER AND PART NUMBER OF OXYGEN MASK ASSEMBLIES Notes COMPLIED WITH - DATE OF MFG IS AFTER MAR 1,2006	01-AUG-2014 H: 718.70 L: 784					
AD 2011-20-01 Airframe AD - Complied With FAA #532	REPLACE THE BOLTS THAT ATTACH THE BALANCE MASS WEIGHTS TO THE ELEVATOR STRUCTURE Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW	17-MAY-2013 H: 330.50 L: 349					
AD 2012-02-08 Airframe AD - N/A FAA #1651	APPLIANCE AD - PREVENT TCAS UNITS FROM DROPPING TRACKS Notes NOT APPLICABLE - DETERMINED TO BE NOT APPLICABLE AT DELIVERY P/N INSTALLED 9003500-55904	10-FEB-2015					
AD 2012-08-04 AMD (C) Airframe AD - N/A FAA #317	ACTIVATE RE-ESTABLISHMENT OF NON-HAZARDOUS SUPPLEMENTAL OXYGEN SUPPLY IN LAVATORIES ALL CHEMICAL OXYGEN GENERATORS IN THE LAVATORIES UNTIL OXYGEN SUPPLY IS EXPENDED. Notes NOT APPLICABLE - AIRCRAFT NOT BRAZILIAN REGISTERED, PARA (C) NOT INSTALLED EQUIPED, PARA(F) SUPP, O2 INSTALLED IN LAV.	06-NOV-2012 H: 167.90 L: 194					
AD 2012-08-04 AMD (F) Airframe AD - N/A FAA #1738	INSTALL RE-ESTABLISHMENT OF NON-HAZARDOUS SUPPLEMENTAL OXYGEN SUPPLY IN LAVATORIES A SUPPLEMENTAL OXYGEN SYSTEM Notes NOT APPLICABLE - AIRCRAFT NOT BRAZILIAN REGISTERED, PARA (C) NOT INSTALLED EQUIPED, PARA(F) SUPP, O2 INSTALLED IN LAV.	06-NOV-2012 H: 167.90 L: 194					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-08-04 Airframe AD - N/A FAA #459	RE-ESTABLISHMENT OF NON-HAZARDOUS SUPPLEMENTAL OXYGEN SUPPLY IN LAVATORIES	06-NOV-2012 H: 167.90 L: 194					
	Notes NOT APPLICABLE - AIRCRAFT NOT BRAZILIAN REGISTERED, PARA (C) NOT INSTALLED EQUIPED, PARA(F) SUPP, O2 INSTALLED IN LAV.						
AD 2012-11-09 AMD PARA (G) Airframe AD - N/A FAA #156	DISCHARGE ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES ALL CHEMICAL OXYGEN GENERATORS	24-AUG-2012 H: 100.20 L: 121					
	Notes NOT APPLICABLE - NOT INSTALLED ON OUR AIRCRAFT						
AD 2012-11-09 Airframe AD - N/A FAA #1608	ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES	24-AUG-2012 H: 100.20 L: 121					
	Notes NOT APPLICABLE - NOT INSTALLED ON OUR AIRCRAFT						
AD 2012-11-09 AMD PARA (L) Airframe AD - N/A FAA #797	INSTALL ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY	24-AUG-2012 H: 100.20 L: 121					
	Notes NOT APPLICABLE - NOT INSTALLED ON OUR AIRCRAFT						
AD 2012-13-04 Airframe AD - Complied With FAA #1891	FLIGHT CONTROLS - DRAIN HOLE INSUFFICIENCY FOR PRIMARY CONTROL SURFACES - VISUAL INSPECTION / REWORK	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-13-04 AMD PARA F(3V) Airframe AD - Complied With FAA #1004	INSPECT FLIGHT CONTROLS - DRAIN HOLE INSUFFICIENCY FOR PRIMARY CONTROL SURFACES - VISUAL INSPECTION / REWORK REWORK, IF NECESSARY, THE AILERONS DRAIN HOLES IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF PART II OF EMBRAER SB 505-57-0004	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
AD 2012-13-04 AMD PARA F(4) Airframe AD - Complied With FAA #1956	INSPECT FLIGHT CONTROLS - DRAIN HOLE INSUFFICIENCY FOR PRIMARY CONTROL SURFACES - VISUAL INSPECTION / REWORK REWORK, IF NECESSARY, THE AILERONS, ELEVATORS, AND RUDDER DRAIN HOLES IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF PART I OF EMBRAER SB 505-57-0004	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS SB HAS BEEN PREVIOUSLY COMPLIED WITH						
AD 2012-13-04 AMD PARA F(2) Airframe AD - Complied With FAA #696	REWORK FLIGHT CONTROLS - DRAIN HOLE INSUFFICIENCY FOR PRIMARY CONTROL SURFACES - VISUAL INSPECTION / REWORK AILERONS, AILERONS TRIM-TABS, AILERONS HORN COVER, RUDDER, RUDDER TRIM-TAB, ELEVATORS AND ELEVATORS AUTO-TABS SURFACES BY DRILLING ADDITIONAL DRAIN HOLES IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF PART I OF EMBRAER SB 505-57-0002	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
AD 2012-13-04 AMD PARA F(3) Airframe AD - Complied With FAA #1128	REWORK FLIGHT CONTROLS - DRAIN HOLE INSUFFICIENCY FOR PRIMARY CONTROL SURFACES - VISUAL INSPECTION / REWORK RUDDER, RUDDER TRIM-TAB, ELEVATORS AND ELEVATORS AUTO-TABS SURFACES BY DRILLING ADDITIONAL DRAIN HOLES IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF PART II OF EMBRAER SB 505-57-0002	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						
AD 2012-13-04 AMD PARA F(1) Airframe AD - Complied With FAA #1235	VISUAL INSPECT FLIGHT CONTROLS - DRAIN HOLE INSUFFICIENCY FOR PRIMARY CONTROL SURFACES - VISUAL INSPECTION / REWORK RH AND LH AILERONS LOWER SKIN IN ORDER TO VERIFY IF THE DRAIN HOLES ARE MISSING AND IF SO, TO DRILL THEM IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTION OF EMBRAER SERVICE BULLETIN (SB) 505-57-0003	17-MAY-2013 H: 330.50 L: 349					
	Notes COMPLIED WITH - THIS ITEM HAS BEEN PCW						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2013-09-01-E AMD PARA(D) Airframe AD - Open FAA #1315	DO NOT INSTALL INSPECTION AND REWORK OF THE STATOR PRESSURE PLATE OF THE LEFT HAND (LH) AND RIGHT HAND (RH) BRAKE ASSEMBLIES (SUPERSEDED BY ANAC AD 2014-04-01) BRAKE ASSEMBLY, P/N DAP00097-01 OR DAP00097-02, HAVING CRACKS BEYOND THE LIMIT DEFINED IN THE FIGURE 3 (SHEET 02 OF 02) OF THE EMBRAER ALERT SERVICE BULLETIN NO. 505-32-A011.						
	Notes - AD NOTE 2013-22-20 NOV 08,2013 SUPERCEDES THIS ITEM. REMOVE FROM CASMP RUN.						
AD 2013-09-01-E Airframe AD - Open FAA #992	EMERGENCY AD - INSPECTION AND REWORK OF THE STATOR PRESSURE PLATE OF THE LEFT HAND (LH) AND RIGHT HAND (RH) BRAKE ASSEMBLIES (SUPERSEDED BY ANAC AD 2014-04-01)						
	Notes - AD NOTE 2013-22-20 NOV 08,2013 SUPERCEDES THIS ITEM. REMOVE FROM CASMP RUN.						
AD 2013-09-01-E AMD PARA(B)(C) Airframe AD - Open FAA #146	GENERAL VISUAL INSPECTION INSPECTION AND REWORK OF THE STATOR PRESSURE PLATE OF THE LEFT HAND (LH) AND RIGHT HAND (RH) BRAKE ASSEMBLIES (SUPERSEDED BY ANAC AD 2014-04-01) FOR CRACKS IN THE STATOR PRESSURE PLATE ON LH BRAKE ASSEMBLY. REMOVE THE WHEEL AND PERFORM A DETAILED INSPECTION, IF ANY CRACK WAS FOUND IN THE STATOR PRESSURE PLATE						
	Notes - AD NOTE 2013-22-20 NOV 08,2013 SUPERCEDES THIS ITEM. REMOVE FROM CASMP RUN.						
AD 2013-09-01-E AMD PARA(B)(C) Airframe AD - Open FAA #1028	GENERAL VISUAL INSPECTION INSPECTION AND REWORK OF THE STATOR PRESSURE PLATE OF THE LEFT HAND (LH) AND RIGHT HAND (RH) BRAKE ASSEMBLIES (SUPERSEDED BY ANAC AD 2014-04-01) FOR CRACKS IN THE STATOR PRESSURE PLATE ON RH BRAKE ASSEMBLY. REMOVE THE WHEEL AND PERFORM A DETAILED INSPECTION, IF ANY CRACK WAS FOUND IN THE STATOR PRESSURE PLATE						
	Notes - AD NOTE 2013-22-20 NOV 08,2013 SUPERCEDES THIS ITEM. REMOVE FROM CASMP RUN.						
AD 2013-22-20 Airframe AD - Complied With FAA #719	LANDING GEAR - STATOR PRESSURE PLATE ON BOTH LH AND RH BRAKE ASSEMBLIES - GENERAL VISUAL INSPECTION (SUPERSEDED BY FAA AD 2014-19-01)						
	Notes COMPLIED WITH - -3 BRAKE INSTALLED AT THIS TIME AND THE FINAL ACTION FOR THIS AD	28-MAY-2014 H: 659.40 L: 714					

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-18-01 Airframe AD - N/A FAA #1631	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	01-DEC-2014 H: 768.90 L: 854					
	Notes NOT APPLICABLE - ROCKWELL COLLINS TRNSPONDERS NOT INSTALLED ON THIS AIRCRAFT						
AD 2014-19-01 AMD PARA(F)(01)(LH) Airframe AD - Open FAA #1159	CALCULATE THE COMPLIANCE TIMES FOR FLIGHT CYCLES ON THE BRAKE ASSEMBLY						
AD 2014-19-01 AMD PARA(F)(01)(RH) Airframe AD - Open FAA #22	CALCULATE THE COMPLIANCE TIMES FOR FLIGHT CYCLES ON THE BRAKE ASSEMBLY						
AD 2014-19-01 AMD PARA(F)(07)(RH) Airframe AD - N/A FAA #1337	DET FOR CRACKS ON THE EXTERNAL VISIBLE SURFACE OF THE THRUST STATOR, DOUBLE STATOR, AND ROTORS / REPEAT THE INSPECTION (IF NO CRACK IS DETECTED OR IF ANY CRACK WITHIN THE ACCEPTABLE LIMITS)	14-NOV-2014 H: 767.20 L: 848					
	Notes NOT APPLICABLE - P/N NOT INSTALLED						
AD 2014-19-01 AMD PARA(F)(07)(LH) Airframe AD - N/A FAA #1357	DET FOR CRACKS ON THE EXTERNAL VISIBLE SURFACE OF THE THRUST STATOR, DOUBLE STATOR, AND ROTORS / REPEAT THE INSPECTION (IF NO CRACK IS DETECTED OR IF ANY CRACK WITHIN THE ACCEPTABLE LIMITS)	14-NOV-2014 H: 767.20 L: 848					
	Notes NOT APPLICABLE - P/N NOT INSTALLED						
AD 2014-19-01 AMD PARA(F)(04)(LH) Airframe AD - Open FAA #1931	DETAILED INSPECTION (DET) (IF ANY CRACK IS FOUND IN THE STATOR PRESSURE PLATE DURING ANY OF THE INSPECTIONS REQUIRED IN PARAGRAPH (F)(2) OF THIS AD)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-19-01 AMD PARA(F)(04)(RH) Airframe AD - Open FAA #843	DETAILED INSPECTION (DET) (IF ANY CRACK IS FOUND IN THE STATOR PRESSURE PLATE DURING ANY OF THE INSPECTIONS REQUIRED IN PARAGRAPH (F)(2) OF THIS AD)						
AD 2014-19-01 AMD PARA(F)(02)(RH) Airframe AD - N/A FAA #1721	GENERAL VISUAL INSPECTION (GVI) FOR CRACKS IN THE STATOR PRESSURE PLATE ON RH BRAKE ASSEMBLIES		14-NOV-2014 H: 767.20 L: 848				
	Notes NOT APPLICABLE - P/N NOT INSTALLED						
AD 2014-19-01 AMD PARA(F)(02)(LH) Airframe AD - N/A FAA #814	GENERAL VISUAL INSPECTION (GVI) FOR CRACKS IN THE STATOR PRESSURE PLATE ON THE LH BRAKE ASSEMBLIES		14-NOV-2014 H: 767.20 L: 848				
	Notes NOT APPLICABLE - P/N NOT INSTALLED						
AD 2014-19-01 Airframe AD - Open FAA #732	LANDING GEAR - STATOR PRESSURE PLATE ON BOTH LH AND RH BRAKE ASSEMBLIES - GENERAL VISUAL INSPECTION						
AD 2014-19-01 AMD PARA(F)(06)(LH) Airframe AD - Open FAA #61	REPAIR THE BRAKE ASSEMBLY (IF CRACKS THAT EXCEED THE ACCEPTABLE LIMITS ARE FOUND DURING THE DET REQUIRED IN PARAGRAPH (F)(4) OF THIS AD) OR REPLACE THE BRAKE ASSEMBLY WITH A BRAKE ASSEMBLY THAT HAS BEEN INSPECTED AND FOUND FREE OF CRACKS THAT EXCEED THE ACCEPTABLE LIMITS						
AD 2014-19-01 AMD PARA(F)(06)(RH) Airframe AD - Open FAA #1195	REPAIR THE BRAKE ASSEMBLY (IF CRACKS THAT EXCEED THE ACCEPTABLE LIMITS ARE FOUND DURING THE DET REQUIRED IN PARAGRAPH (F)(4) OF THIS AD) OR REPLACE THE BRAKE ASSEMBLY WITH A BRAKE ASSEMBLY THAT HAS BEEN INSPECTED AND FOUND FREE OF CRACKS THAT EXCEED THE ACCEPTABLE LIMITS						
AD 2014-19-01 AMD PARA(F)(10)(RH) Airframe AD - Open FAA #432	REPLACE THE AFFECTED BRAKE ASSEMBLY (IF ANY CRACK BEYOND THE ACCEPTABLE LIMITS SHOWN IN FIGURE 4 DETAIL H OF SB 505-32-0011 R1 IS DETECTED)						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-19-01 AMD PARA(F)(10)(LH) Airframe AD - Open FAA #295	REPLACE THE AFFECTED BRAKE ASSEMBLY (IF ANY CRACK BEYOND THE ACCEPTABLE LIMITS SHOWN IN FIGURE 4 DETAIL H OF SB 505-32-0011 R1 IS DETECTED)						
AD 2014-19-01 AMD PARA(F)(09)(RH) Airframe AD - Open FAA #557	REPLACE THE AFFECTED BRAKE ASSEMBLY (IF ANY CRACK WITHIN THE ACCEPTABLE LIMITS SHOWN IN FIGURE 4 DETAIL H OF SB 505-32-0011 R1 IS DETECTED IN THE INSPECTION REQUIRED IN PARAGRAPH (F)(7) OF THIS AD)						
AD 2014-19-01 AMD PARA(F)(09)(LH) Airframe AD - Open FAA #551	REPLACE THE AFFECTED BRAKE ASSEMBLY (IF ANY CRACK WITHIN THE ACCEPTABLE LIMITS SHOWN IN FIGURE 4 DETAIL H OF SB 505-32-0011 R1 IS DETECTED IN THE INSPECTION REQUIRED IN PARAGRAPH (F)(7) OF THIS AD)						
AD 2015-08-07 Airframe AD - N/A FAA #478	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					02-JUN-2015 H: 850.20 L: 933	
	Notes NOT APPLICABLE - BE AEROSPACE MASKS INSTALLED						
AD 2015-08-07 AMD PARA (G) Airframe AD - N/A FAA #1867	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011					02-JUN-2015 H: 850.20 L: 933	
	Notes NOT APPLICABLE - BE AEROSPACE MASKS INSTALLED						
AD 2015-08-07 AMD PARA (H) Airframe AD - N/A FAA #966	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES					02-JUN-2015 H: 850.20 L: 933	
	Notes NOT APPLICABLE - BE AEROSPACE MASKS INSTALLED						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-10-02 Airframe AD - Open FAA #1861	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT						
AD 2015-10-02 AMD PARA (H) Airframe AD - Open FAA #980	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK						
AD 2015-10-02 AMD PARA (G) Airframe AD - Open FAA #881	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2						
AD 2015-10-02 AMD PARA (I) Airframe AD - Open FAA #673	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS						
AD 2015-10-51 Airframe AD - Open FAA #1007	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS						
AD 2015-10-51-E Airframe AD - Open FAA #1884	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS						
AD 2015-23-09 Airframe AD - N/A FAA #466	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS					11-DEC-2015 H: 1027.50 L: 1107	
	Notes NOT APPLICABLE - BE AEROSPACE MASKS INSTALLED						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-23-09 AMD PARA (G) Airframe AD - N/A FAA #739	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	11-DEC-2015 H: 1027.50 L: 1107					
	Notes NOT APPLICABLE						
AD 2015-23-09 AMD PARA (I) Airframe AD - N/A FAA #1502	REGULATOR REPLACEMENT	11-DEC-2015 H: 1027.50 L: 1107					
	Notes NOT APPLICABLE						
AD 2015-23-09 PARA AMD (H.2.II) Airframe AD - N/A FAA #579	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	11-DEC-2015 H: 1027.50 L: 1107					
	Notes NOT APPLICABLE						
AD 2015-23-09 PARA AMD PARA(H.1) Airframe AD - N/A FAA #1837	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	11-DEC-2015 H: 1027.50 L: 1107					
	Notes NOT APPLICABLE						
AD 2015-23-09 PARA AMD PARA(H.2.I) Airframe AD - N/A FAA #1470	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	11-DEC-2015 H: 1027.50 L: 1107					
	Notes NOT APPLICABLE						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-11-20 Airframe AD - N/A FAA #652	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. (SUPERSEDED BY 2017-18-12) SUPERSEDED BY FAA AD 2017-18-12	11-JUL-2016 H: 1201.40 L: 1270					
	Notes NOT APPLICABLE - BY MANUFACTURER						
AD 2016-11-20 AMD PARA (G) Airframe AD - N/A FAA #1694	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	11-JUL-2016 H: 1201.40 L: 1270					
	Notes NOT APPLICABLE - NOT APPLICABLE BY MANUFACTURER						
AD 2016-11-20 PARA AMD PARA(H.1) Airframe AD - N/A FAA #871	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	11-JUL-2016 H: 1201.40 L: 1270					
	Notes NOT APPLICABLE						
AD 2016-11-20 PARA AMD PARA(H.2) Airframe AD - N/A FAA #1120	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	11-JUL-2016 H: 1201.40 L: 1270					
	Notes NOT APPLICABLE						
AD 2016-22-02 Airframe AD - Complied With FAA #1657	EQUIPMENT / FURNISHING - INSPECT EACH APPLICABLE PASSENGER SEAT FOR THE CORRECT INSTALLATION OF ATTACHMENT FITTINGS AND CORRECT THE DISCREPANCY (IF ANY DISCREPANCY IS FOUND)	01-DEC-2016 H: 1300.00 L: 1383					
	Notes COMPLIED WITH						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-16-01 Airframe AD - N/A FAA #991	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						
AD 2017-16-01 AMD PARA (J) Airframe AD - N/A FAA #194	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						
AD 2017-16-01 AMD PARA (G) Airframe AD - N/A FAA #1852	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						
AD 2017-18-12 Airframe AD - N/A FAA #1339	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						
AD 2017-18-12 AMD PARA (G) Airframe AD - N/A FAA #837	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-18-12 AMD PARA (H) Airframe AD - N/A FAA #1839	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						
AD 2017-18- 12+AA24AAA35:AA71 AMD PARA (I) & (J) Airframe AD - N/A FAA #1021	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	26-SEP-2017 H: 1579.20 L: 1613					
	Notes NOT APPLICABLE - EQUIPMENT NOT INSTALLED.						
AD 2018-03-04 AMD 39 -19177 Airframe AD - N/A FAA #1993	ROSEMOUNT AEROSPACE 851AK PITOT PROBES - TO PREVENT INCORRECT AIRSPEED INDICATIONS DURING FLIGHT (EFFECTIVE 16 MARCH 2018)	09-MAR-2018 H: 1740.70 L: 1753					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-07-10 AMD 39 -19241 Airframe AD - N/A FAA #2013	TO INSPECT THE AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR TRIM TAB (OR AUTOTAB) AND CORRECT ANY DISCREPANCY (EFFECTIVE 15 MAY 2018)	17-APR-2018 H: 1765.70 L: 1775					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-16-01 AMD 39 -19341 Airframe AD - N/A FAA #2026	TO PREVENT MALFUNCTION OF THE EA ON THE SEAT (EFFECTIVE 31 AUGUST 2018)	21-AUG-2018 H: 1850.00 L: 1865					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-16-13 AMD 39 -19353 Airframe AD - N/A FAA #2030	TO PREVENT FAILURE OF THESE ATTENDANT SEATS (EFFECTIVE 26 OCTOBER 2018)	03-OCT-2018 H: 1875.10 L: 1883					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-19-15 AMD 39 -19415 Airframe AD - N/A FAA #2033	TO PREVENT FAILURE OF THE SEATS TO PERFORM THEIR INTENDED FUNCTION GEVEN TYPE D1-02 AND D1-03 (EFFECTIVE 14 NOVEMBER 2018)	07-NOV-2018 H: 1905.30 L: 1911					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-21-14 AMD 39 -19472 Airframe AD - N/A FAA #2046	JOINT AIRCRAFT SERVICE COMPONENT (JASC) CODE: 3510, CREW OXYGEN SYSTEM (EFFECTIVE 03-27-2019)	15-MAR-2019 H: 2019.00 L: 2014					
AD 2018-23-01 AMD 39 -19487 Airframe AD - N/A FAA #2037	TO PREVENT FAILURE OF AFFECTED SEATS. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN INJURY TO THE SEAT OCCUPANTS (EFFECTIVE 28 DECEMBER 2018)	13-DEC-2018 H: 1928.30 L: 1936					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2018-23-12 AMD 39 -19499 Airframe AD - N/A FAA #2038	TO ADDRESS FUSIBLE PLUGS THAT MIGHT ACTIVATE BELOW THE RATED TEMPERATURE AND RENDER THE EVACUATION SYSTEM UNUSABLE (EFFECTIVE 28 DECEMBER 2018)	13-DEC-2018 H: 1928.30 L: 1936					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2019-01-02 AMD 39 -19541 Airframe AD - N/A FAA #2041	JOINT AIRCRAFT SYSTEM COMPONENT (JASC): 3410, FLIGHT ENVIRONMENT DATA; AND 3420, ATTITUDE AND DIRECTION DATA SYSTEM (7, FEBRUARY 2019)	24-JAN-2019 H: 1960.50 L: 1972					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2019-07-03 AMD 39 -19614 Airframe AD - N/A FAA #2065	UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN FAILURE OF THE SEAT OCCUPIED BY THE CABIN ATTENDANT, AND POSSIBLE INJURY TO THE CABIN ATTENDANT (EFFECTIVE 16 MAY 2019)	29-APR-2019 H: 2052.70 L: 2048					
AD 2019-07-10 AMD 39 -19621 Airframe AD - N/A FAA #2070	NORTHROP GRUMMAN LITEF GMBH LCR-100 ATTITUDE AND HEADING REFERENCE SYSTEM (EFFECTIVE 29 MAY 2019)	29-APR-2019 H: 2052.70 L: 2048					
AD 2019-08-01 AMD 39 -19622 Airframe AD - N/A FAA #2074	JOINT AIRCRAFT SYSTEM COMPONENT (JASC) CODE 2520, PASSENGER COMPARTMENT EQUIPMENT (EFFECTIVE 21 MAY 2019)	16-MAY-2019 H: 2054.20 L: 2050					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						
AD 2019-12-09 AMD 39 -19664 Airframe AD - N/A FAA #2083	TO PREVENT CONFLICTING TCAS INFORMATION (EFFECTIVE 23 JULY 2019)	16-JUL-2019 H: 2081.60 L: 2076					
AD 2020-12-08 AMD 39 -21143 Airframe AD - Superseded FAA #2120	TO ADDRESS CORROSION IN THE MASS-BALANCE WEIGHTS OF THE FLIGHT CONTROL SURFACES. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN LOSS OF MASS OR THE DETACHMENT OF THE MASS-BALANCE WEIGHTS, RESULTING IN AN UNBALANCED CONTROL SURFACE, WHICH COULD LEAD TO FLUTTER AND LOSS OF AIRPLANE CONTROL (EFFECTIVE 1 JULY 2020)						
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2020-18-51 AMD 39 -21249 Airframe AD - N/A FAA #2144	ISSUING THIS EMERGENCY AD TO PREVENT AERONAUTICAL DECISION-MAKING BASED ON ERRONEOUS ATTITUDE INFORMATION, WHICH MAY RESULT IN LOSS OF CONTROL OF THE AIRCRAFT (EFFECTIVE 28 AUGUST 2020)	04-MAY-2021					
	Notes N/A - EQUIPMENT NOT INSTALLED ON AIRCRAFT						
AD 2021-08-07 AMD 39 -21501 Airframe AD - N/A FAA #2163	ISSUING THIS AD TO PREVENT A MISLEADING GPS POSITION ON AN LPV APPROACH. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN A MISLEADING GPS POSITION ON AN LPV APPROACH RESULTING IN CONTROLLED FLIGHT INTO TERRAIN (EFFECTIVE 12 MAY 2021)	18-JUL-2022					
	Notes N/A DUE AIRCRAFT HAVING GARMIN GPS RECEIVER P/N: 011-01105-20.						
AD 2022-05-12 AMD 39 -21964 Airframe AD - Complied With FAA #2207	THIS AD RETAINS THE ACTIONS REQUIRED BY AD 2020-12-08 AND REQUIRES, FOR CERTAIN AIRPLANES, CLEANING AND WEIGHING CERTAIN MASS-BALANCES AND INSTALLATION OR REPLACEMENT, AS APPLICABLE; AND FOR CERTAIN OTHER MASS-BALANCES FOR CERTAIN AIRPLANES, REPLACEMENT OF THOSE MASS-BALANCES (EFFECTIVE 13 APRIL 2022)	18-JUL-2022 H: 2611.00 L: 2496					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						
AD 2023-10-02 AMD 39 -22438 Airframe AD - Complied With FAA #2240	THE FAA IS ISSUING THIS AD BECAUSE RADIO ALTIMETER ANOMALIES THAT ARE UNDETECTED BY THE AUTOMATION OR PILOT, PARTICULARLY CLOSE TO THE GROUND (E.G., LANDING FLARE), COULD LEAD TO LOSS OF CONTINUED SAFE FLIGHT AND LANDING. ADDITIONALLY, RADIO ALTIMETER ANOMALIES COULD LEAD TO INCREASED FLIGHTCREW WORKLOAD AND FLIGHTCREW DESENSITIZATION TO WARNINGS. (EFFECTIVE 30 JUNE 2023)	22-SEP-2023 H: 2833.90 L: 2664					
	Notes REVISED THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 4 PARAGRAPH (I) OF THIS AD. THIS IS A TERMINATING ACTION.						
AD 2023-21-04 AMD 39 -22576 Airframe AD - N/A FAA #2245	THE FAA IS ISSUING THIS AD TO ADDRESS THE UNCOMMANDED CHANGE IN THE SETTING OF THE BAROMETRIC PRESSURE IN BOTH PFDS. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN ALTITUDE MISMANAGEMENT OR SPATIAL DISORIENTATION OF THE FLIGHT CREW, WITH CONSEQUENT DEVIATION FROM THE INTENDED ALTITUDE AND LOSS OF CONTROL OF THE AIRPLANE, RISK OF AIR COLLISION, CONT'D. (EFFECTIVE 11 DECEMBER 2023)	14-DEC-2023					
	Notes N/A DUE TO THIS AD BEING APPLICABLE TO ONLY G3000 AIRCRAFT.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-21-06 AMD 39 -22578 Airframe AD - Open FAA #2246	THE FAA IS ISSUING THIS AD TO ADDRESS THE UNSAFE CONDITION. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN A MONUMENT NOT WITHSTANDING THE LOADS EXPECTED FOR SPECIFIC EMERGENCY LANDING CONDITIONS, WHICH MAY CAUSE THE DETACHMENT OF MASS ITEMS AND RESULT IN INJURIES TO THE AIRPLANE OCCUPANTS. (EFFECTIVE 11 DECEMBER 2023)					02-JUN-2026	M: 10 D: 4
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						
AD 2023-22-11 AMD 39 -22595 Airframe AD - Recurring FAA #2247	THE FAA IS ISSUING THIS AD TO ADDRESS THE CORROSION IN THE CLUTCH RETAINING BOLT OF THE AILERON AUTOPILOT SERVO MOUNT. THE UNSAFE CONDITION COULD RESULT IN FAILURE OF THE CLUTCH RETAINING BOLT OF THE AILERON AUTOPILOT SERVO MOUNT, WHICH COULD DISENGAGE THE CLUTCH FROM THE DRIVE PIN AND JAM THE AILERON CONTROLS, RESULTING IN REDUCED CONTROLLABILITY OF THE AIRPLANE. (EFFECTIVE 26 DECEMBER 2023)	22-SEP-2023 H: 2833.90 L: 2664	M: 36			22-SEP-2026	M: 13 D: 24
	Notes COMPLIED WITH BY COMPLETION OF SB 505-22-0004. AD HAS A 36 MONTH REOCCURRING REPLACEMENT.						
AD 2024-17-09 AMD 39 -22834 Airframe AD - N/A FAA #2267	TO ADDRESS THE POSSIBILITY OF DETACHMENT OF MASS ITEMS DURING SPECIFIC EMERGENCY LANDING CONDITIONS. THE UNSAFE CONDITION, IF NOT ADDRESSED, COULD RESULT IN INJURIES TO THE AIRPLANE OCCUPANTS	H: 2974.90 L: 2767					
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						
AD 2024-22-06 AMD 39 -22877 Airframe AD - Open FAA #2282	THIS AD WAS PROMPTED BY THE ANALYSIS OF CERTAIN MONUMENTS (THE RIGHT-HAND REFRESHMENT CENTER AND LEFT-HAND FORWARD CABINET) THAT IDENTIFIED THE NEED FOR INSTALLING STRUCTURAL REINFORCEMENTS AND REPLACING APPLICABLE FLOOR SUPPORT RIVETS.					02-JUN-2026	M: 10 D: 4
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						
AD 2025-05-13 AMD 39 -22985 Engine 1 AD - Recurring FAA #489	[RECURRING] FAA IS ISSUING THIS AD TO PREVENT CRACK, FRACTURE, MISSING, OR LOOSENING OF THE GAS GENERATOR CASE TO TURBINE SUPPORT CASE RETAINING BOLTS. IF NOT ADDRESSED, COULD RESULT IN UNCONTAINED ENGINE DEBRIS, DAMAGE TO THE ENGINE AND AIRPLANE.					23-APR-2025	M: -3 D: -6
	Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.						

Maintenance Items

N204WC

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2025-05-13 AMD 39 -22985 Engine 2 AD - Recurring FAA #487	[RECURRING] FAA IS ISSUING THIS AD TO PREVENT CRACK, FRACTURE, MISSING, OR LOOSENING OF THE GAS GENERATOR CASE TO TURBINE SUPPORT CASE RETAINING BOLTS. IF NOT ADDRESSED, COULD RESULT IN UNCONTAINED ENGINE DEBRIS, DAMAGE TO THE ENGINE AND AIRPLANE.					23-APR-2025	M: -3 D: -6
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ADDITIONALLY, INCLUDE ANY INSTRUCTIONS FOR THE CONTROL OF CORRELATED SUB PARTS.							