



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FXT-6	PERFORM AIRWORTHINESS REVIEW INSPECTION AND RECOMMENDATION (ARC)				MTH 11-Oct-2023		36		11-Oct-2026	12 m 18 d
FXT-7	PERFORM 1ST EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE				MTH 08-Oct-2024 HRS 1427:29 LDG 980		36		11-Oct-2025	18 d
FXT-8	PERFORM 2ND EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE				MTH		36		11-Oct-2025	18 d
PPPP1	PAINT AIRCRAFT				MTH 27-Apr-2022 HRS 991:24 LDG 731		O/C			
PPPP1	PAINT AIRCRAFT						-			
055001	ACCOMPLISH CHECK HARD/OVERWEIGHT LANDINGS				MTH 16-Nov-2015		O/C			
055002	ACCOMPLISH CHECK OVERSPEED				MTH 16-Nov-2015		O/C			
055003	ACCOMPLISH CHECK SEVERE AIR TURBULANCE OR SEVERE MANEUVERS				MTH 16-Nov-2015		O/C			
055004	ACCOMPLISH CHECK LIGHTING STRIKE				MTH 16-Nov-2015		O/C			
055005	ACCOMPLISH CHECK FOREIGN OBJECT DAMAGE				MTH 16-Nov-2015		O/C			
055006	ACCOMPLISH CHECK TOWING WITH A LARGE FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS DUE TO GROUND HANDLING				MTH 10-Jan-2024 HRS 1272:51 LDG 868		O/C			
5-12-01	INSPECTION DOCUMENT 01				MTH 05-Feb-2025 HRS 1519:42 LDG 1047		300		1819:42	167:55
5-12-02	INSPECTION DOCUMENT 02				MTH 05-Feb-2025 HRS 1519:42 LDG 1047		12		28-Feb-2026	5 m 5 d
B262201 CABIN	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 2				MTH 05-Feb-2025 HRS 1519:42 LDG 1047		12		28-Feb-2026	5 m 5 d
Weight Check Date: 05-Feb-2025										
5-12-06	INSPECTION DOCUMENT 06 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 11-Feb-2021 HRS 633:54 LDG 505		72			
A262201 CABIN	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 06				MTH 14-May-2024 HRS 1347:50 LDG 918		72		31-May-2030	56 m 8 d
5-12-08	INSPECTION DOCUMENT 08				MTH 19-Sep-2024 HRS 1411:13 LDG 965		24 300		30-Sep-2026 1711:13	12 m 7 d 59:26
5-12-09	INSPECTION DOCUMENT 09 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 05-Feb-2025 HRS 1519:42 LDG 1047		4 200			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
B243603	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-36-15-720									
	EKBI	RG-380E/44LA5 - S3597-8 41238130	MTH	07-Jun-2025		4		31-Oct-2025	1 m 8 d	
			HRS	1606:16		200		1806:16	154:29	
			LDG	1104						
5-12-10	INSPECTION DOCUMENT 10		MTH	05-Feb-2025		36		29-Feb-2028	29 m 6 d	
	LFPB		HRS	1519:42		1200		2719:42	1067:55	
			LDG	1047						
5-12-11	INSPECTION DOCUMENT 11		MTH	26-Sep-2024		36		30-Sep-2027	24 m 7 d	
	EDDL		HRS	1418:18		1200		2618:18	966:31	
			LDG	968						
5-12-12	INSPECTION DOCUMENT 12 (14 CFR 91.207)		MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d	
	LFPB		HRS	1519:42						
			LDG	1047						
A256201	DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER ARTEX (ELT): INSPECTION DOCUMENT 12									
	LFPB	453-5060	MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d	
		16014	HRS	1519:42						
			LDG	1047						
B256203	OPERATIONAL CHECK ARTEX C406-N EMERGENCY LOCATOR TRANSMITTER: INSPECTION DOCUMENT 12									
	LFPB		MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d	
			HRS	1519:42						
			LDG	1047						
5-12-13	INSPECTION DOCUMENT 13 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)		MTH	05-Feb-2025		24				
	LFPB		HRS	1519:42						
			LDG	1047						
B341101	FUNCTIONAL CHECK PITOT-STATIC SYSTEM: INSPECTION DOCUMENT 13									
LEFT	LFPB		MTH	05-Feb-2025		24		28-Feb-2027	17 m 5 d	
			HRS	1519:42						
			LDG	1047						
B341101	CALIBRATION TEST NO. 1 GDC 7400 RVSM AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 13									
NO. 1	LFPB	011-02337-01	MTH	05-Feb-2025		24		31-Jan-2027	16 m 8 d	
		1U6100844	HRS	1519:42						
			LDG	1047						
Calibration Date: 24-Jan-2025										
B341101	CALIBRATION TEST NO. 2 GDC 7400 RVSM AIR DATA COMPUTER (FAR 91.411): INSPECTION DOCUMENT 13									
NO. 2	LFPB	011-02337-01	MTH	05-Feb-2025		24		31-Jan-2027	16 m 8 d	
		1U6100842	HRS	1519:42						
			LDG	1047						
Calibration Date: 24-Jan-2025										
B341101	FUNCTIONAL CHECK PITOT-STATIC SYSTEM: INSPECTION DOCUMENT 13									
RIGHT	LFPB		MTH	05-Feb-2025		24		28-Feb-2027	17 m 5 d	
			HRS	1519:42						
			LDG	1047						
B341101	CALIBRATION TEST ELECTRONIC STANDBY INDICATOR (4-IN-1) DISPLAY : INSPECTION DOCUMENT 13									
	LFPB	9200-32100-0201	MTH	05-Feb-2025		24		31-Jan-2027	16 m 8 d	
		2777	HRS	1519:42						
			LDG	1047						
Calibration Date: 24-Jan-2025										
B345701	CALIBRATION CHECK GTX 3000 MODE S TCAS II TRANSPONDER ATC SYSTEM: INSPECTION DOCUMENT 13									
LEFT	LFPB	011-01997-00	MTH	05-Feb-2025		24		31-Jan-2027	16 m 8 d	
		20S007092	HRS	1519:42						
			LDG	1047						
Calibration Date: 24-Jan-2025										
B345701	CALIBRATION CHECK GTX 3000 MODE S TCAS II TRANSPONDER ATC SYSTEM: INSPECTION DOCUMENT 13									
RIGHT	LFPB	011-01997-00	MTH	05-Feb-2025		24		31-Jan-2027	16 m 8 d	
		20S007124	HRS	1519:42						
			LDG	1047						
Calibration Date: 24-Jan-2025										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-14	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
				MTH	16-Nov-2015		T/C			
				HRS	0					
				LDG	0					
A324201 LEFT	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14	EDDL		3-1527-2 2058	MTH		T/C			
A324201 NOSE	SPECIAL DETAIL INSPECT LANDING GEAR WHEEL ASSY (NDI): INSPECTION DOCUMENT 14	KMQJ		3-1418 9221	MTH	15-Oct-2019	T/C			
				HRS	451:42					
				LDG	390					
A324201 RIGHT	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14	EKRK		3-1527-2 1745	MTH	03-Jan-2024	T/C			
				HRS	1273:39					
				LDG	869					
5-12-17	INSPECTION DOCUMENT 17 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)									
		KMQJ		MTH	14-Oct-2020		12			
				HRS	546		100			
				LDG	471					
5-12-21	INSPECTION DOCUMENT 21	EGHH		MTH	14-May-2024		24		31-May-2026	8 m 8 d
				HRS	1347:50		600		1947:50	296:03
				LDG	918					
5-12-29	INSPECTION DOCUMENT 29			MTH	16-Nov-2015					
				HRS	0		7200		7200	5548:13
A530003	ZONAL INSPECTION COCKPIT AND CABIN ABOVE AND BELOW FLOORBOARD: INSPECTION DOCUMENT 29									
				MTH	16-Nov-2015					
				HRS	0		7200		7200	5548:13
5-12-33	INSPECTION DOCUMENT 33	LFPB		MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
				HRS	1519:42		300		1819:42	167:55
				LDG	1047					
5-12-36	INSPECTION DOCUMENT 36	EKBI		MTH	07-Jun-2025		6		31-Dec-2025	3 m 8 d
				HRS	1606:16					
				LDG	1104					
5-12-37	INSPECTION DOCUMENT 37			MTH	10-Jul-2023					
				HRS	1222:12					
				LDG	825					
				ACH	497:12		500		997:12	500
5-12-MA	INSPECTION DOCUMENT MA	LFPB		MTH	05-Feb-2025					
				HRS	1519:42		300		1819:42	167:55
				LDG	1047					
5-12-MD	INSPECTION DOCUMENT MD			MTH	16-Nov-2015					
				LDG	0		5000		5000	3864
5-12-MF	INSPECTION DOCUMENT MF			MTH	16-Nov-2015					
				HRS	0		6000		6000	4348:13
5-12-MG	INSPECTION DOCUMENT MG			MTH	16-Nov-2015					
				HRS	0		6000		6000	4348:13
5-12-MH	INSPECTION DOCUMENT MH			MTH	16-Nov-2015					
				HRS	0		6000		6000	4348:13
5-12-MI	INSPECTION DOCUMENT MI			MTH	16-Nov-2015					
				HRS	0		7200		7200	5548:13
5-12-MJ	INSPECTION DOCUMENT MJ			MTH	16-Nov-2015					
				HRS	0		7200		7200	5548:13
5-12-MK	INSPECTION DOCUMENT MK			MTH	16-Nov-2015					
				HRS	0		7900		7900	6248:13
5-12-MM	INSPECTION DOCUMENT MM			MTH	16-Nov-2015					
				HRS	0		12000		12000	10348:13



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-MN	INSPECTION DOCUMENT MN				MTH 16-Nov-2015					
					HRS 0		12000		12000	10348:13
5-12-MO	INSPECTION DOCUMENT MO				MTH 16-Nov-2015					
					HRS 0		15200		15200	13548:13
5-12-MP	INSPECTION DOCUMENT MP				MTH 05-Feb-2025		12		28-Feb-2026	5 m 5 d
	LFPB				HRS 1519:42		250		1769:42	117:55
					LDG 1047					
5-12-MQ	INSPECTION DOCUMENT MQ				MTH 16-Nov-2015					
					HRS 0		14000		14000	12348:13
05-50-00-870-803-01	POLISH FAN ROTOR				MTH 16-Nov-2015		A/R			
E1										
05-50-00-870-803-01	POLISH FAN ROTOR				MTH 16-Nov-2015		A/R			
E2										
052001	FJ44 CHECK 1	LFPB			MTH 05-Feb-2025					
E1					HRS 1519:42		300		(1819:42)1819:42	167:55
					LDG 1047					
052001	FJ44 CHECK 1	LFPB			MTH 05-Feb-2025					
E2					HRS 1519:42		300		(1819:42)1819:42	167:55
					LDG 1047					
052002	FJ44 CHECK 2	KSAT			MTH 20-Jul-2023					
E1					HRS 1222:12		600		(1822:20)1822:20	170:33
					LDG 825					
052002	FJ44 CHECK 2	KSAT			MTH 20-Jul-2023					
E2					HRS 1222:12		600		(1822:20)1822:20	170:33
					LDG 825					
723003	CLEAN FAN ROTOR AND VISUALLY INSPECT FOR DEFECTS				MTH 20-Jul-2023					
E1	KSAT			117810	HRS 1222:12		600		(1822:20)1822:20	170:33
				HW40851	LDG 825					
723003	CLEAN FAN ROTOR AND VISUALLY INSPECT FOR DEFECTS				MTH 20-Jul-2023					
E2	KSAT			117810	HRS 1222:12		600		(1822:20)1822:20	170:33
				HW40850	LDG 825					
052003	FJ44 CHECK 3				MTH 16-Nov-2015					
E1					HRS 0		1750		(1750)1750	98:13
052003	FJ44 CHECK 3				MTH 16-Nov-2015					
E2					HRS 0		1750		(1750)1750	98:13
052004	FJ44 CHECK 4				MTH 16-Nov-2015					
E1					HRS 0		3500		(3500)3500	1848:13
052004	FJ44 CHECK 4				MTH 16-Nov-2015					
E2					HRS 0		3500		(3500)3500	1848:13
052005	FJ44 CHECK 5				MTH 16-Nov-2015					
E1					HRS 0		5250		(5250)5250	3598:13
052005	FJ44 CHECK 5				MTH 16-Nov-2015					
E2					HRS 0		5250		(5250)5250	3598:13
052006	FJ44 CHECK 6				MTH 16-Nov-2015					
E1					HRS 0		7000		(7000)7000	5348:13
052006	FJ44 CHECK 6				MTH 16-Nov-2015					
E2					HRS 0		7000		(7000)7000	5348:13
052007	FJ44 CHECK 7				MTH 16-Nov-2015					
E1					HRS 0		8750		(8750)8750	7098:13
052007	FJ44 CHECK 7				MTH 16-Nov-2015					
E2					HRS 0		8750		(8750)8750	7098:13
052008	FJ44 CHECK 8				MTH 16-Nov-2015					
E1					HRS 0		10500		(10500)10500	8848:13
052008	FJ44 CHECK 8				MTH 16-Nov-2015					
E2					HRS 0		10500		(10500)10500	8848:13



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052009 E1	FJ44 CHECK 9			MTH	16-Nov-2015 HRS 0		12250		(12250)12250	10598:13
052009 E2	FJ44 CHECK 9			MTH	16-Nov-2015 HRS 0		12250		(12250)12250	10598:13
052010 E1	FJ44 CHECK 10			MTH	16-Nov-2015 HRS 0		14000		(14000)14000	12348:13
052010 E2	FJ44 CHECK 10			MTH	16-Nov-2015 HRS 0		14000		(14000)14000	12348:13
052011 E1	FJ44 CHECK 11			MTH	16-Nov-2015 HRS 0		15750		(15750)15750	14098:13
052011 E2	FJ44 CHECK 11			MTH	16-Nov-2015 HRS 0		15750		(15750)15750	14098:13
052012 E1	FJ44 CHECK 12			MTH	16-Nov-2015 HRS 0		17500		(17500)17500	15848:13
052012 E2	FJ44 CHECK 12			MTH	16-Nov-2015 HRS 0		17500		(17500)17500	15848:13
052013 E1	FJ44 CHECK 13			MTH	16-Nov-2015 HRS 0		19250		(19250)19250	17598:13
052013 E2	FJ44 CHECK 13			MTH	16-Nov-2015 HRS 0		19250		(19250)19250	17598:13
052014 E1	FJ44 CHECK 14			MTH	16-Nov-2015 HRS 0		21000		(21000)21000	19348:13
052014 E2	FJ44 CHECK 14			MTH	16-Nov-2015 HRS 0		21000		(21000)21000	19348:13
12-28-05-600	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH	KMQJ		DAYS	15-Jul-2020 HRS 525:18 LDG 446		O/C			
12-28-05-601	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH	KMQJ		DAYS	05-Oct-2023	10	45		29-Nov-2023	-21 m 25 d
Over Due										
12-28-05-602	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS	21-Jun-2023 HRS 1219:24 LDG 826		O/C			
052500	PERFORM FXT-13 AIRCRAFT WEIGHT CHECK	EKBI		MTH	05-Oct-2023 HRS 1247:02 LDG 840		48		31-Oct-2027	25 m 8 d
26-20-00-961	ENGINE FIRE EXTINGUISHER BOTTLES (HYDROSTATIC TEST) FUNCTIONAL CHECK	UNK		30401102-2 60847B1	MTH 19-Sep-2024 HRS 1411:13 LDG 965		60		30-Jun-2029	45 m 7 d
Hydro Check Date: 05-Jun-2024										
26-20-00-962 NO. 1	NO. 1 ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (TOTAL LIFE)	UNK		13083-5 LOTESD23L959-001	MTH 01-Nov-2024		72		30-Nov-2030	62 m 7 d
Manufacture Date: 01-Nov-2024										
26-20-00-962 NO. 2	NO. 2 ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (TOTAL LIFE)	UNK		13083-5 LOTESD23L959-001	MTH 01-Nov-2024		72		30-Nov-2030	62 m 7 d
Manufacture Date: 01-Nov-2024										
26-22-00-961 CABIN	CABIN PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK	EGHH		C352CS I-27696359	MTH 11-Mar-2024 HRS 1347:50 LDG 918		144		31-Mar-2036	126 m 8 d
Hydro Check Date: 11-Mar-2024										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
					MTH 23-Nov-2023 HRS 633:54 LDG 505		O/C			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
					MTH 16-Nov-2015		O/C			
32-32-05-720	EMERGENCY PNEUMATIC STORAGE BOTTLE (HYDROSTATIC TEST) FUNCTIONAL CHECK									
	EDDL			40005320-2 7547	MTH 26-Sep-2024 HRS 1418:18 LDG 968		36		31-Aug-2027	23 m 8 d
Hydro Check Date: 21-Aug-2024										
35-00-00-780	OXYGEN BOTTLE RESTORATION (HYDROSTATIC TEST)									
	EGHH			176276-50 590399503	MTH 01-Dec-2023 HRS 1347:50 LDG 918		60		31-Dec-2028	39 m 8 d
Hydro Check Date: 01-Dec-2023										
551010	EXAMINE HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS 4.78									
					MTH 16-Nov-2015 HRS 0		14000		14000	12348:13
571010	EXAMINE LOWER MAIN SPAR SPLICE AT WS 93.00									
					MTH 16-Nov-2015 HRS 0		13200		13200	11548:13
571015	EXAMINE LOWER REAR SPAR SPLICE AT WS 93.00									
					MTH 16-Nov-2015 HRS 0		15600		15600	13948:13
571020	EXAMINE MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0)									
					MTH 16-Nov-2015 HRS 0		15000		15000	13348:13
571025	EXAMINE REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0)									
					MTH 16-Nov-2015 HRS 0		15000		15000	13348:13
571030	EXAMINE MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00)									
					MTH 16-Nov-2015 HRS 0		15000		15000	13348:13
710015 E1	COMPRESSOR CLEANING									
					MTH 16-Nov-2015		A/R			
710015 E2	COMPRESSOR CLEANING									
					MTH 16-Nov-2015		A/R			
731025 E1	FUEL FILTER REPLACEMENT KSAT									
					MTH 20-Jul-2023 HRS 1222:12 LDG 825		1200		(2422:12)2422:12	770:25
731025 E2	FUEL FILTER REPLACEMENT KSAT									
					MTH 20-Jul-2023 HRS 1222:12 LDG 825		1200		(2422:12)2422:12	770:25
850004	RENEW INSURANCE CERTIFICATE									
					MTH					



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
211003	HEAT PRESSURE EXCHANGER	10840A 1352	MTH 16-Nov-2015		O/C	0		
211004	HEAT EXCHANGER SHUTOFF VALVE	27241287-24 5BM23	MTH 16-Nov-2015		O/C	0		
211005	EMERGENCY PRESS SHUTOFF VALVE	2601-23 1258	MTH 16-Nov-2015		O/C	0		
212001	UNDERFLOOR INLET AIR BLOWER	0113-12 2389	MTH 16-Nov-2015		O/C	0		
212003	TEMP PRESS COMPRESSION SWITCH	1173T42-3 4301	MTH 16-Nov-2015		O/C	0		
212011 AFT	TEMPERATURE WINDSHIELD BLEED AIR SENSOR	27221274 6BM131	MTH 16-Nov-2015		O/C	0		
212202	OVERHEAD AIR VALVE SOLENOID	D113204 NSN	MTH 16-Nov-2015		O/C	0		
212302	BLOWER - WINDSHIELD AIR MOTOR	7003-200 2023	MTH 16-Nov-2015		O/C	0		
213003	PRESSURIZATION CONTROLLER	52811-103 05162	MTH 16-Nov-2015		O/C	0		
213004 LEFT	KAPS II OUTFLOW VALVE	52812-102 05178	MTH 16-Nov-2015		O/C	0		
213004 RIGHT	KAPS II OUTFLOW VALVE	52812-102 05120	MTH 16-Nov-2015		O/C	0		
215001 FORWARD	EVAPORATOR	1134820-13 345	MTH 16-Nov-2015		O/C	0		
215002 AFT	EVAPORATOR	1134820-14 439	MTH 16-Nov-2015		O/C	0		
215003 AFT	EVAPORATOR MOTOR	1250211-7 NSN	MTH 16-Nov-2015		O/C	0		
215003 FORWARD	EVAPORATOR MOTOR	1250211-7 NSN	MTH 16-Nov-2015		O/C	0		
215004	COMPRESSOR CONDENSOR MODULE ASSEMBLY	9912459-8 1134400-31 453A	MTH 16-Nov-2015		O/C	0		
215006	DRIVE MOTOR ASSEMBLY	1134104-5 5569	MTH 16-Nov-2015		O/C	0		
215010	FREON A/C-BAROMETRIC SWITCH	GBC300-82 1503803	MTH 16-Nov-2015		O/C	0		
215013 AFT	EXPANSION VALVE	1250218 NSN	MTH 16-Nov-2015		O/C	0		
215013 FORWARD	EXPANSION VALVE	1250218 NSN	MTH 16-Nov-2015		O/C	0		
216002	TEMPERATURE CONTROLLER	1E86-1 4BM153	MTH 16-Nov-2015		O/C	0		
216004	TEMPERATURE BLEED AIR INSTALL SENSOR	27221274 5BM98	MTH 16-Nov-2015		O/C	0		
A215004	COMPRESSOR DRIVE MOTOR BRUSHES	1251171 NSN	MTH 10-Jul-2023 HRS 1222:12 LDG 825 ACH 497:12			0 0 0 0	997:12	500
221003 AILERON	SERVO	011-00877-20 19Z008897	MTH 16-Nov-2015		O/C	0		
221004 RUDDER	SERVO	011-00877-20 19Z008899	MTH 16-Nov-2015		O/C	0		
221009	GMC 710 AFCS MODE CONTROLLER	011-01020-10 22007638	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
221010 ELEVATOR	GSA 81 SERVO IND	011-00878-20 1A1013659	MTH 19-May-2016 HRS 72:12 LDG 50		O/C	0 0		
221011 AILERON	GSM 86 SERVO MOUNT	011-02490-14 1GK014083	MTH 16-Nov-2015		O/C	0		
221012 RUDDER	GSM 86 SERVO MOUNT	011-02490-15 1GK014343	MTH 16-Nov-2015		O/C	0		
221013 ELEVATOR	GSM 86 SERVO MOUNT	011-02490-16 1GK014492	MTH 16-Nov-2015		O/C	0		
221014	GSM 86 SERVO (ELEVATOR TRIM) MOUNT	011-02490-17 1GJ005725	MTH 16-Nov-2015		O/C	0		
231008	GDR 66 VHF DATALINK RADIO	011-02303-00 222005307	MTH 16-Nov-2015		O/C	0		
232008 BOTTOM	COMM 2 ANTENNA	VHF10-829 2129	MTH 16-Nov-2015		O/C	0		
232008 LWR	TCAS ANTENNA	S72-1735-26 874-0631	MTH 16-Nov-2015		O/C	0		
232008 NO. 3	VHF-COM ANTENNA	VHF10-829 2109	MTH 16-Nov-2015		O/C	0		
232008 TOP	COMM 1 ANTENNA	VHF10-829 2085	MTH 16-Nov-2015		O/C	0		
232008 UPPER	TCAS ANTENNA	S72-1735-26 874-0653	MTH 16-Nov-2015		O/C	0		
232014 LH	GSD 41 DATA CONCENTRATOR	011-01457-01 2JH005611	MTH 16-Nov-2015		O/C	0		
232014 RH	GSD 41 DATA CONCENTRATOR	011-01457-01 2JH005556	MTH 16-Nov-2015		O/C	0		
232023 AFT	WIFI ANTENNA	TRAB24/49003P 07311215	MTH 16-Nov-2015		O/C	0		
232033 FWD	WIFI ANTENNA	TRAB24/49003P 07311215	MTH 16-Nov-2015		O/C	0		
235001 NO. 1	GPS/XM ANTENNA	CI428-410 493761	MTH 16-Nov-2015		O/C	0		
235001 NO. 2	GPS/XM ANTENNA KMQJ	CI428-410 546909	MTH 19-Jan-2018 HRS 268 LDG 231		O/C	0 0 0		
235006 LEFT	GMA 36 REMOTE AUDIO PROCESSOR	011-01793-00 1HF006372	MTH 16-Nov-2015		O/C	0		
235006 RIGHT	GMA 36 REMOTE AUDIO PROCESSOR	011-01793-00 1HF006374	MTH 16-Nov-2015		O/C	0		
235009	PA AMPLIFIER	102025-1 4800515	MTH 16-Nov-2015		O/C	0		
344404	GRAPHICAL WEATHER SYSTEM DATA LINK	011-00987-00 47768884	MTH 16-Nov-2015		O/C	0		
242001 AUX	AC CONVERTER	SS50 7234	MTH 16-Nov-2015		O/C	0		
242003	STATIC INVERTER (230 VOLT)	PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
243002 LEFT	GENERATOR CONTROL UNIT	51525-001F P7002	MTH 16-Nov-2015		O/C	0		
243002 RIGHT	GENERATOR CONTROL UNIT	51525-001F P7014	MTH 16-Nov-2015		O/C	0		
243003	MAIN BATTERY EKBI	RG-380E/44LA5 - S3597-8 41238130	MTH 07-Jun-2025 HRS 1606:16 LDG 1104		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
243007	14 AHR BATTERY ASSEMBLY LFPB			7243-16T G03296685	MTH 05-Feb-2025 HRS 1519:42 LDG 1047		O/C	1 0 0		
243012	STANDBY BATTERY	LFPB		501-1712-01 80344	MTH 05-Feb-2025 HRS 1519:42 LDG 1047		O/C			
245001	PRESSURIZATION PCB ASSY			6318349-26 0461	MTH 16-Nov-2015		O/C	0		
245002 LEFT	ASSEMBLY-FUEL CONTROL PCB			6318037-6 1329	MTH 16-Nov-2015		O/C	0		
245002 RIGHT	ASSEMBLY-FUEL CONTROL PCB			6318037-6 1328	MTH 16-Nov-2015		O/C	0		
245003 LEFT	ASSEMBLY-IGNITOR PCB KIND			6318388-7 0816	MTH 19-Jul-2017 HRS 222:30 LDG 192		O/C	20 222:30 192		
245003 RIGHT	ASSEMBLY-IGNITOR PCB KIND			6318388-7 0817	MTH 19-Jul-2017 HRS 222:30 LDG 192		O/C	20 222:30 192		
245004 LEFT	ANTI ICE PCB ASSY			6318390-1 0509	MTH 16-Nov-2015		O/C	0		
245004 RIGHT	ANTI ICE PCB ASSY			6318390-1 0511	MTH 16-Nov-2015		O/C	0		
245005	PRINTED CIRCUIT BOARD (PCB) ASSEMBLY - DIAGNOSTICS NZ115				6318046-9 0455	MTH 16-Nov-2015	O/C	0		
245006	ENVIRONMENTAL PCB ASSY			6318358-20 0561	MTH 16-Nov-2015		O/C	0		
245007 LEFT	PCB-START LOGIC ASSY			6318038-1 1506	MTH 16-Nov-2015		O/C	0		
245007 RIGHT	PCB-START LOGIC ASSY			6318038-1 1502	MTH 16-Nov-2015		O/C	0		
245011	FUEL FLOW XMITTER PCB ASSY			85-230-2 1346050	MTH 16-Nov-2015		O/C	0		
245012	SPEEDBRAKE CONTROL PCB ASSY			6318034-6 0715	MTH 16-Nov-2015		O/C	0		
245013	TAIL DEICE MONITOR PCB ASSY			6318043-1 0785	MTH 16-Nov-2015		O/C	0		
245014	TAIL DEICE CONTROL PCB ASSY			6318044-1 0787	MTH 16-Nov-2015		O/C	0		
245015	HYDRAULIC PCB ASSY			6318035-7 0703	MTH 16-Nov-2015		O/C	0		
245020	FADEC INTERFACE NZ116 ASSY			6318387-11 0664	MTH 16-Nov-2015		O/C	0		
245022	FADEC INTERFACE NZ117 ASSY			6318387-11 0663	MTH 16-Nov-2015		O/C	0		
245023	LANDING GEAR MONITOR PCB ASSY			6318397-21 0805	MTH 16-Nov-2015		O/C	0		
245026 NO. 1	LANDING GEAR PCB	EGHH		6318398-6 33663360-3	MTH 14-May-2024 HRS 1347:50 LDG 918		O/C	0 0 0		
245027 NO. 2	LANDING GEAR PCB			6318399-11 0700	MTH 16-Nov-2015		O/C	0		
245200 CABIN	ALT MODULE ASSY			7018119-1 1535	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
25-62-00-960	ELT BEACON BATTERY PACK LFPB	452-0133 1013859-015	MTH 05-Feb-2025 HRS 1519:42 LDG 1047		DUE DUE DUE DUE	3 0 0 0	31-Jan-2030	52 m 8 d
Expiration Date: 31-Jan-2030								
251001 LEFT HAND	LEFT HAND CREW SEAT WITH CUTOUT	PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
251001 RIGHT HAND	RIGHT HAND CREW SEAT WITH CUTOUT	PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
256001	EMERGENCY LOCATOR TRANSMITTER	453-5060 16014	MTH 16-Nov-2015		O/C	0		
256004	ELT ANTENNA	110-340 457355	MTH 16-Nov-2015		O/C	0		
256006 CO-PILOT	LIFE VEST	P01074-207 24091730306	MTH 20-Jan-2025 HRS 1520:06 LDG 1047		120	4 0 0	30-Sep-2034	108 m 7 d
256006 LAVATORY	LIFE VEST	P01074-207 24091730303	MTH 20-Jan-2025 HRS 1520:06 LDG 1047		120	4 0 0	30-Sep-2034	108 m 7 d
256006 NO. 3	LIFE VEST	P01074-207 24091730309	MTH 20-Jan-2025 HRS 1520:06 LDG 1047		120	4 0 0	30-Sep-2034	108 m 7 d
256006 NO. 4	LIFE VEST	P01074-207 24091730307	MTH 20-Jan-2025 HRS 1520:06 LDG 1047		120	4 1520:06 5	30-Sep-2034	108 m 7 d
256006 NO. 5	LIFE VEST	P01074-207 24091730308	MTH 20-Jan-2025 HRS 1520:06 LDG 1047		120	4 0 5	30-Sep-2034	108 m 7 d
256006 NO. 6	LIFE VEST	P01074-207 24091730304	MTH 20-Jan-2025 LDG 1042		120	4 0	30-Sep-2034	108 m 7 d
256006 PILOT	LIFE VEST	P01074-207 24091730305	MTH 20-Jan-2025 HRS 1520:06 LDG 1047		120	4 1520:06 5	30-Sep-2034	108 m 7 d
256006 SFS	LIFE VEST	P01074-207 24091730310	MTH 20-Jan-2025 LDG 1042		120	4 0	30-Sep-2034	108 m 7 d
256055	FIRST AID KIT	BR8524 MX597	MTH 05-Feb-2025 HRS 1519:42 LDG 1047		O/C	0 0 0		
261002 LEFT	FIRE DETECT SENSOR	3001-212-1004/455-9 214263	MTH 16-Nov-2015		O/C	0		
261002 RIGHT	FIRE DETECT SENSOR	3001-212-1004/455-9 214246	MTH 16-Nov-2015		O/C	0		
262001	ENGINE FIRE EXTINGUISHER BOTTLE UNK	30401102-2 60847B1	MTH 19-Sep-2024 HRS 1411:13 LDG 965		O/C	190 0 0		
262002 NO. 1	FIRE EXTINGUISHER CARTRIDGE UNK	13083-5 LOTESD23L959-001	MTH 19-Sep-2024 HRS 1411:13 LDG 965		H/T H/T H/T H/T			
262002 NO. 2	FIRE EXTINGUISHER CARTRIDGE UNK	13083-5 LOTESD23L959-001	MTH 19-Sep-2024 HRS 1411:13 LDG 965		H/T H/T H/T H/T			



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262003 CABIN	PORTABLE FIRE EXTINGUISHER EGHH			C352CS I-27696359	MTH 14-May-2024 HRS 1347:50 LDG 918		O/C	0 0 0		
271001 LH	CONTROL WHEEL ASSY			6360115-1 1087C	MTH 16-Nov-2015		O/C	0		
271001 RH	CONTROL WHEEL ASSY			6360115-2 1056C	MTH 16-Nov-2015		O/C	0		
273001 LEFT	SHAKER CONTROL			201 163041-09	MTH 16-Nov-2015		O/C	0		
273004 LEFT	ELEVATOR TRIM ACTUATOR			6396022-3 NSN	MTH 16-Nov-2015		O/C	0		
273004 RIGHT	ELEVATOR TRIM ACTUATOR			6396022-4 NSN	MTH 16-Nov-2015		O/C	0		
273005	RUDDER TRIM ACTUATOR			6396022-2 NSN	MTH 16-Nov-2015		O/C	0		
273006 LEFT HAND	ACTUATOR ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
273006 RIGHT HAND	ACTUATOR ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
273006 RUDDER	ACTUATOR ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
273006	AILERON TRIM ACTUATOR			6396022-5 NSN	MTH 16-Nov-2015		O/C	0		
275001	SHUTOFF VALVE			4083-1 1310	MTH 16-Nov-2015		O/C	0		
275002 LEFT	FLAP HYD ACTUATOR			1542000-9 2579	MTH 16-Nov-2015		O/C	0		
275002 RIGHT	FLAP HYD ACTUATOR			1542000-9 2569	MTH 16-Nov-2015		O/C	0		
276001 LEFT	SPEEDBRAKE ACTUATOR			1542100-5 2550A	MTH 16-Nov-2015		O/C	0		
276001 RIGHT	SPEEDBRAKE ACTUATOR			1542100-5 2551A	MTH 16-Nov-2015		O/C	0		
281001 LEFT	FUEL SURGE VALVE			35C10D 6175	MTH 16-Nov-2015		O/C	0		
281001 RIGHT	FUEL SURGE VALVE			35C10D 6184	MTH 16-Nov-2015		O/C	0		
282001 LEFT	ELECTRIC FUEL PUMP			1C7-13 6BM37	MTH 16-Nov-2015		O/C	0		
282001 RIGHT	ELECTRIC FUEL PUMP			1C7-13 3BM8	MTH 16-Nov-2015		O/C	0		
282002 LEFT	FUEL TRANSFER PUMP			RG45880 B4245	MTH 16-Nov-2015		O/C	0		
282002 RIGHT	FUEL TRANSFER PUMP			RG45880 B4242	MTH 16-Nov-2015		O/C	0		
282004 LEFT	FUEL MOTOR ACTUATED VALVE			AV24B1507 AA518386	MTH 16-Nov-2015		O/C	0		
282004 RIGHT	FUEL MOTOR ACTUATED VALVE			AV24B1507 AA529344	MTH 16-Nov-2015		O/C	0		
282005 LEFT	FUEL TRANSFER EJECTOR			RG45310 C3841	MTH 16-Nov-2015		O/C	0		
282005 RIGHT	FUEL TRANSFER EJECTOR			RG45310 C3844	MTH 16-Nov-2015		O/C	0		
282006	TRANSFER VALVE			ZSV57 15-071451	MTH 16-Nov-2015		O/C	0		
284001 LH	NO.5 TRANSMITTER FUEL PROBE			10307T01Y00 MN36064	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
284001 RH	NO.5 TRANSMITTER FUEL PROBE	10307T01Y00 MN35378	MTH 16-Nov-2015		O/C	0		
284003	FUEL QUANTITY SIGNAL CONDITIONER EGHH	10310B01Y02 01080604	MTH 14-May-2024 HRS 1347:50 LDG 918		O/C	4 0 0		
284004 LH	NO.3 TRANSMITTER FUEL PROBE	10305T01Y00 MN35373	MTH 16-Nov-2015		O/C	0		
284004 RH	NO.3 TRANSMITTER FUEL PROBE	10305T01Y00 MN33836	MTH 16-Nov-2015		O/C	0		
284005 LH	NO.4 TRANSMITTER FUEL PROBE	10306T01Y00 MN35698	MTH 16-Nov-2015		O/C	0		
284005 RH	NO.4 TRANSMITTER FUEL PROBE	10306T01Y00 MN35843	MTH 16-Nov-2015		O/C	0		
284006 LH	NO.2 TRANSMITTER FUEL PROBE	10304T01Y00 MN36049	MTH 16-Nov-2015		O/C	0		
284006 RH	NO.2 TRANSMITTER FUEL PROBE	10304T01Y00 MN36046	MTH 16-Nov-2015		O/C	0		
284007 LH	NO.1 TRANSMITTER FUEL PROBE	10303T01Y00 MN35148	MTH 16-Nov-2015		O/C	0		
284007 RH	NO.1 TRANSMITTER FUEL PROBE	10303T01Y00 MN34858	MTH 16-Nov-2015		O/C	0		
284008 LEFT	FUEL LOW LEVEL SWITCH	L16H-14 NSN	MTH 16-Nov-2015		O/C	0		
284008 RIGHT	FUEL LOW LEVEL SWITCH	GIF5400-40 NSN	MTH 16-Nov-2015		O/C	0		
284010 LH	NO.6 TRANSMITTER FUEL PROBE	10309T03Y00 MN35744	MTH 16-Nov-2015		O/C	0		
284010 RH	NO.6 TRANSMITTER FUEL PROBE	10309T03Y00 MN36304	MTH 16-Nov-2015		O/C	0		
291003	HYDRAULIC CHECK VALVE	CV02-193 NSN	MTH 16-Nov-2015		O/C	0		
291008	HYDRAULIC MANIFOLD ASSEMBLY	8250-3 0897	MTH 16-Nov-2015		O/C	0		
291009 LEFT	ENGINE DRIVEN HYDRAULIC PUMP	4120-046000 0409	MTH 16-Nov-2015		O/C	0		
291009 RIGHT	ENGINE DRIVEN HYDRAULIC PUMP	4120-046000 0410	MTH 16-Nov-2015		O/C	0		
291010 LEFT	HYDRAULIC SHUTOFF VALVE ASSY	AV24B1388-2 AA529154	MTH 16-Nov-2015		O/C	0		
291010 RIGHT	HYDRAULIC SHUTOFF VALVE ASSY	AV24B1388-2 AA529338	MTH 16-Nov-2015		O/C	0		
291011 LEFT	FLOW SWITCH/CHECK HYD VALVE	V10F75 1837A	MTH 16-Nov-2015		O/C	0		
291011 RIGHT	FLOW SWITCH/CHECK HYD VALVE	V10F75 1841A	MTH 16-Nov-2015		O/C	0		
291014	LANDING GEAR VALVE SOLENOID	4051-4 1296	MTH 16-Nov-2015		O/C	0		
291020	SPEEDBRAKE VALVE SOLENOID	4052-3 1365	MTH 16-Nov-2015		O/C	0		
291021	FLAP VALVE SOLENOID	4052-4 1390	MTH 16-Nov-2015		O/C	0		
301001	SHUTOFF ISOLATION VALVE	2602-36 2531	MTH 16-Nov-2015		O/C	0		
301002 LEFT	PNEUMATIC DEICE SWITCH	1106P55-1 10714A	MTH 16-Nov-2015		O/C	0		
301002 RIGHT	PNEUMATIC DEICE SWITCH	1106P55-1 10709A	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301003 LEFT	BLEED AIR PRESSURE REGULATOR SHUTOFF VALVE 5285-00-3 3227	MTH	16-Nov-2015		O/C	0		
301003 RIGHT	BLEED AIR PRESSURE REGULATOR SHUTOFF VALVE 5285-00-3 2758	MTH	16-Nov-2015		O/C	0		
301004 LEFT	TEMPERATURE DEICE SWITCH 1173T42-4 5058	MTH	16-Nov-2015		O/C	0		
301004 RIGHT	TEMPERATURE DEICE SWITCH 1173T42-4 5061	MTH	16-Nov-2015		O/C	0		
301010 LEFT	HORIZONTAL STABILIZER BOOT 29S4D5244-11 NGQ3240	MTH HRS LDG	10-Jul-2023 1222:12 825		O/C	0 0 0		
301010 RIGHT	HORIZONTAL STABILIZER BOOT 29S4D5244-12 NCP7190	MTH	16-Nov-2015		O/C	0		
301012 LEFT	WING SHUTOFF PRESSURE REGULATING VALVE 9912402-9 1H127-4 4BM27	MTH	16-Nov-2015		O/C	0		
301012 RIGHT	WING SHUTOFF PRESSURE REGULATING VALVE 9912402-9 1H127-4 5BM42	MTH	16-Nov-2015		O/C	0		
303002 LEFT	HEATED PITOT TUBE PH502 A1879	MTH	16-Nov-2015		O/C	0		
303002 RIGHT	HEATED PITOT TUBE PH502 1411310	MTH	16-Nov-2015		O/C	0		
304001 LH	B/A TEMP MONITOR- 4824	MTH	16-Nov-2015		O/C	0		
304002	HEAT EXCHANGER 10653A 2400	MTH	16-Nov-2015		O/C	0		
304003	WINDSHIELD S/O VALVE 1H127-4 3BM22	MTH	16-Nov-2015		O/C	0		
304004 AFT	AFT PITOT STATIC CURRENT SENSOR 76250-6 12129	MTH	16-Nov-2015		O/C	0		
304004 FORWARD	FORWARD PITOT STATIC CURRENT SENSOR 76250-6 121111	MTH	16-Nov-2015		O/C	0		
304005 AFT	AFT SENSOR 76552-1 10727	MTH	16-Nov-2015		O/C	0		
304005 FORWARD	FORWARD SENSOR 76552-1 10711	MTH	16-Nov-2015		O/C	0		
304006	TEMP BLEED AIR CONTROLLER 1E58-1 5BM32	MTH	16-Nov-2015		O/C	0		
304007	TEMP CONTROL BLEED AIR VALVE 27241287 6BM33P	MTH	16-Nov-2015		O/C	0		
304009 LEFT	SOLENOID DEICE VALVE 3D2353-06 N150101	MTH	16-Nov-2015		O/C	0		
304009 RIGHT	SOLENOID DEICE VALVE 3D2353-06 N151430	MTH	16-Nov-2015		O/C	0		
304010	ALCOHOL PUMP ASSEMBLY 6508092-4 NSN	MTH	16-Nov-2015		O/C	0		
304012 LEFT	WINDSHIELD BLEED AIR VALVE 1403-25 5773	MTH	16-Nov-2015		O/C	0		
304012 RIGHT	WINDSHIELD BLEED AIR VALVE 1403-25 5796	MTH	16-Nov-2015		O/C	0		
304013	PRESSURE WINDSHIELD SWITCH 1115P25 5299AB	MTH	16-Nov-2015		O/C	0		
304014 AFT	TEMPERATURE EVAPORATOR SENSOR 27221274 4BM70	MTH	16-Nov-2015		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
313001	FLIGHT HOUR METER			C664503-0104 NSN	MTH 16-Nov-2015		O/C	0		
313003	ARES II 24-CH FLIGHT DATA RECORDER			6918236-20 1312	MTH 16-Nov-2015		O/C	0		
32-32-05-960	EMERGENCY PNEUMATIC STORAGE BOTTLE DISCARD 9912368-2	EDDL		40005320-2 7547	MTH 26-Sep-2024 HRS 1418:18 LDG 968		288		30-Sep-2035	120 m 7 d
Manufacture Date: 01-Sep-2011										
321001 NOSE LANDING	NOSE LANDING GEAR STRUT ASSEMBLY (PART NUMBER 6342000-43, -45, -49), EXCEPT THE FORK AND PISTON ASSEMBLY									
				6342000-43 25129286	MTH 16-Nov-2015 LDG 0			0 0		21364
321003 LEFT MAIN LANDING GEAR	TRUNNION ASSEMBLY			6341007-11 25057437	MTH 16-Nov-2015 LDG 0		22500 9310	0 0	22500 9310	8174
321004 RIGHT MAIN LANDING GEAR	TRUNNION ASSEMBLY			6341007-12 24883930	MTH 16-Nov-2015 LDG 0		9310	0	9310	8174
321005 LEFT	TRAILING LINK AND AXLE ASSEMBLY			6341002-17 24998564	MTH 16-Nov-2015 LDG 0		21100	0	21100	19964
321006 RIGHT	TRAILING LINK AND AXLE ASSEMBLY			6341002-18 24098561	MTH 16-Nov-2015 LDG 0		21100	0	21100	19964
321007	SHIMMY DAMPER ASSEMBLY			6343001-10 24119741H	MTH 16-Nov-2015		O/C	0		
321008 LEFT	OLEO ASSEMBLY			6341130-12 25026376	MTH 16-Nov-2015 LDG 0		21100	0	21100	19964
321008 RIGHT	OLEO ASSEMBLY			6341130-12 25022285	MTH 16-Nov-2015 LDG 0		21100	0	21100	19964
321009	FORK AND PISTON ASSEMBLY			6342000-39 25129206	MTH 16-Nov-2015 LDG 0		12500	0	12500	11364
321013 LEFT	LEFT MAIN LANDING GEAR ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		H/T H/T	0		
321013 RIGHT	RIGHT MAIN LANDING GEAR ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		H/T H/T	0		
323000 NOSE LANDING GEAR	ACTUATOR ASSEMBLY 9912370-5			1541900-7 1862	MTH 16-Nov-2015 LDG 0		7500	0	7500	6364
323001 LEFT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912397-8			1541800-13 1654	MTH 16-Nov-2015 LDG 0		8952	0	8952	7816
323002 RIGHT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912397-8			1541800-13 1651	MTH 16-Nov-2015 LDG 0		8952	0	8952	7816
323003	NG UPLOCK ACTUATOR			6327504-7 1824	MTH 16-Nov-2015		O/C	0		
323005 LEFT	MLG UPLOCK ACTUATOR			6327504-6 3745	MTH 16-Nov-2015		O/C	0		
323005 RIGHT	MLG UPLOCK ACTUATOR			6327504-6 3738	MTH 16-Nov-2015		O/C	0		
323006	HYD SHUTTLE VALVE			95784 5059A	MTH 16-Nov-2015		O/C	0		
324001 LEFT	MAIN LANDING GEAR WHEEL 9912398-7			3-1527-2 2058	MTH 26-Sep-2024 HRS 1418:18 LDG 968		O/C	106 1418:18 968		
324001 RIGHT	MAIN LANDING GEAR WHEEL 9912398-7	EK RK		3-1527-2 1745	MTH 03-Jan-2024 HRS 1273:39 LDG 869		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324002 NOSE	LANDING GEAR WHEEL ASSY			3-1418 9221	MTH 16-Nov-2015		O/C	0		
324005 LEFT	MLG TIRE	EDDL		277K08-1 40170145	MTH 26-Sep-2024 HRS 1418:18 LDG 968		O/C	0 0 0		
324005 RIGHT	MLG TIRE	EKRK		277K08-1 922992097	MTH 10-Jan-2024 HRS 1273:39 LDG 869		O/C	0 0 0		
324007 NOSE	LANDING GEAR TIRE			030-611-0 2016T00379	MTH 16-Sep-2022 HRS 1085:30 LDG 779		O/C	0 0 0		
324016 LEFT MAIN LANDING GEAR	BRAKE ASSY	KDEN		2-1559-3 1386	MTH 01-Jul-2021 HRS 730:36 LDG 573		O/C	1 0 0		
324016 RIGHT MAIN LANDING GEAR	BRAKE ASSY			2-1599-3 0165	MTH 11-Jun-2021 HRS 713:24 LDG 562		O/C	0 0 0		
324102 LEFT	ANTISKID TRANSDUCER ASSEMBLY			40-955 10095	MTH 16-Nov-2015		O/C	0		
324102 RIGHT	ANTISKID TRANSDUCER ASSEMBLY			40-955 10457	MTH 16-Nov-2015		O/C	0		
324103	BRAKE CONTROL BOX			42-707-1 1617	MTH 16-Nov-2015		O/C	0		
324111 LEFT	MLG UP & LOCK SWITCH			65-430087 NSN	MTH 16-Nov-2015		O/C	0		
324111 RIGHT	MLG UP & LOCK SWITCH			65-430087 NSN	MTH 16-Nov-2015		O/C	0		
324111	NLG UP & LOCK SWITCH			65-430087 NSN	MTH 16-Nov-2015		O/C	0		
324112	PRESSURE ANTISKID SWITCH			38-747502 1013	MTH 16-Nov-2015		O/C	0		
325001	NOSE LANDING GEAR ASSEMBLY			6342000-42 NSN	MTH 16-Nov-2015		O/C	0		
326001 LEFT	M/G DOWN&LOCK SWITCH			1EN118-6 NSN	MTH 16-Nov-2015		O/C	0		
326001 RIGHT	M/G DOWN&LOCK SWITCH			1EN118-6 NSN	MTH 16-Nov-2015		O/C	0		
326002	N/G DOWN&LOCK SWITCH			1EN118-6 NSN	MTH 16-Nov-2015		O/C	0		
331003	INDIRECT LIGHTING CONTROL BOX			CLC500-01 500005281	MTH 16-Nov-2015		O/C	0		
332009 L4	21" LIGHT ASSY			CLE221-02 221003817	MTH 16-Nov-2015		O/C	0		
332009 R4	21" LIGHT ASSY			CLE221-02 221003821	MTH 16-Nov-2015		O/C	0		
332010 L1	36" LIGHT ASSY			CLE236-02 236027162	MTH 16-Nov-2015		O/C	0		
332010 L2	36" LIGHT ASSY			CLE236-02 236027129	MTH 16-Nov-2015		O/C	0		
332010 L3	36" LIGHT ASSY			CLE236-02 236026901	MTH 16-Nov-2015		O/C	0		
332010 R1	36" LIGHT ASSY			CLE236-02 236026917	MTH 16-Nov-2015		O/C	0		
332010 R2	36" LIGHT ASSY			CLE236-02 236027213	MTH 16-Nov-2015		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
332010 R3	36" LIGHT ASSY			CLE236-02 236027175	MTH 16-Nov-2015		O/C	0		
334001	GROUND RECOGNITION LIGHT			84003-3 000615	MTH 16-Nov-2015		O/C	0		
334007	TAIL LIGHT ASSEMBLY			01-0770966-00 05469A	MTH 16-Nov-2015		O/C	0		
334008 LEFT	PTA WINGTIP LIGHT			87-03916-001 00120	MTH 16-Nov-2015		O/C	0		
334008 RIGHT	PTA WINGTIP LIGHT			87-03917-001 00131	MTH 16-Nov-2015		O/C	0		
334009 LH	OVER WING LIGHT			OWL100-03 115007662	MTH 16-Nov-2015		O/C	0		
334009 RH	OVER WING LIGHT			OWL100-03 115007666	MTH 16-Nov-2015		O/C	0		
334010 LEFT	LED LANDING LIGHT			LDL100-01 206001133	MTH 16-Nov-2015		O/C	0		
334010 RIGHT	LED LANDING LIGHT			LDL100-01 206001130	MTH 16-Nov-2015		O/C	0		
341009	AOA SENSOR			C12417-2 161661-01	MTH 16-Nov-2015		O/C	0		
341010 AFT	RADIO ALTIMETER ANTENNA			S67-2002 543-75978	MTH 16-Nov-2015		O/C	0		
341010 FORWARD	RADIO ALTIMETER ANTENNA			S67-2002 543-74910	MTH 16-Nov-2015		O/C	0		
341601	ELECTRONIC FLIGHT DISPLAY EFD - 750 MOD UI013			PN SN-UNKNOWN	MTH 16-Nov-2015		H/T H/T	0		
342015 LEFT	AHRS COMPUTER			011-00868-10 42030613	MTH 16-Nov-2015		O/C	0		
342015 RIGHT	AHRS COMPUTER			011-00868-10 42030612	MTH 16-Nov-2015		O/C	0		
342056	MULTI-FUNCTION MODULE			9118009-4 0450	MTH 16-Nov-2015		O/C	0		
342061 LEFT	GTC 570 PORTRAIT-ORIENTED TOUCHSCREEN CONTROLLER			011-01924-10 1MB506356	MTH 20-Jul-2021 HRS 743:06 LDG 579		O/C			
342061 RIGHT	GTC 570 PORTRAIT-ORIENTED TOUCHSCREEN CONTROLLER			011-01924-10 1MB505580	MTH 16-Nov-2015		O/C	0		
342062 LEFT	GEA 71 ENGINE & AIRFRAME IO UNIT			011-00831-05 1Z1005745	MTH 16-Nov-2015		O/C	0		
342062 RIGHT	GEA 71 ENGINE & AIRFRAME IO UNIT			011-00831-05 1Z1005740	MTH 16-Nov-2015		O/C	0		
342077 LEFT	GIA 63W INTEGRATED AVIONICS, NAV, COM, GPS/WAAS, FD UNIT			011-01105-40 2DC001981	MTH 16-Nov-2015		O/C	0		
342077 RIGHT	GIA 63W INTEGRATED AVIONICS, NAV, COM, GPS/WAAS, FD UNIT			011-01105-40 2DC001975	MTH 16-Nov-2015		O/C	0		
342079	GWX 70 WEATHER RADAR			011-01768-00 1DP006248	MTH 16-Nov-2015		O/C	0		
342082	ELECTRONIC STANDBY INDICATOR (4-IN-1) DISPLAY			9200-32100-0201 2777	MTH 16-Nov-2015		O/C	0		
342084 CENTER	GDU 1400W (MFD) MULTIFUNCTION FLIGHT DISPLAY	KIWA		011-01910-00 1F1005230	MTH 26-Apr-2021 HRS 691:18 LDG 574		O/C	691:18		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342084 COPILOT	GDU 1400W (PFD) PRIMARY FLIGHT DISPLAY KIWA			011-01910-00 1F1003173	MTH 26-Apr-2021 HRS 691:18 LDG 574		O/C	691:18		
342084 PILOT	GDU 1400W (PFD) PRIMARY FLIGHT DISPLAY			011-01910-00 1F1005172	MTH 16-Nov-2015		O/C	0		
342085 NO. 1	NO. 1 GDC7400 RVSM AIR DATA COMPUTER			011-02337-01 1U6100844	MTH 16-Nov-2015		O/C	0		
342085 NO. 2	NO. 2 GDC7400 RVSM AIR DATA COMPUTER			011-02337-01 1U6100842	MTH 16-Nov-2015		O/C	0		
342090	GWX70 ANTENNA			117-00254-01 900	MTH 16-Nov-2015		O/C	0		
342800 LEFT	GMU 44 MAGNETOMETER			011-00870-10 1CM015776	MTH 16-Nov-2015		O/C	0		
342800 RIGHT	GMU 44 MAGNETOMETER			011-00870-10 1CM015775	MTH 16-Nov-2015		O/C	0		
343010	MARKER BEACON COUPLER			DMB20-20 4650	MTH 16-Nov-2015		O/C	0		
344001	ANTENNA GLIDESLOPE COUPLER			DGSC20-02 7712	MTH 16-Nov-2015		O/C	0		
344024	RADIO ALTIMETER INDICATOR			822-0615-206 4PT1M	MTH 16-Nov-2015		O/C	0		
344403 NOSE	MAINTENANCE ANTENNA			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
345001 LOWER AFT	DME #2 ANTENNA			L10-611-14 6631	MTH 16-Nov-2015		O/C	0		
345001 LOWER FORWARD	DME #1 ANTENNA			L10-611-14 6631	MTH 16-Nov-2015		O/C	0		
345004 L/H LOWER	TRANSPONDER ANTENNA			L10-611-14 6748	MTH 16-Nov-2015		O/C	0		
345004 L/H UPPER	TRANSPONDER ANTENNA			L10-611-14 7143	MTH 16-Nov-2015		O/C	0		
345004 R/H LOWER	TRANSPONDER ANTENNA			L10-611-14 6908	MTH 16-Nov-2015		O/C	0		
345004 R/H UPPER	TRANSPONDER ANTENNA			L10-611-14 7140	MTH 16-Nov-2015		O/C	0		
345005	MARKER BEACON ANTENNA			MB10-754 1990	MTH 16-Nov-2015		O/C	0		
345006	GLIDESLOPE ANTENNA			RGS10-48 18336	MTH 16-Nov-2015		O/C	0		
345008 LEFT	DME 1 RECEIVER			822-1466-001 44V6C6	MTH 16-Nov-2015		O/C	0		
345022 LEFT	NAVIGATION(VOR/LOC/GS) ANTENNA			S65-247-38 180-10468	MTH 16-Nov-2015		O/C	0		
345022 RIGHT	NAVIGATION(VOR/LOC/GS) ANTENNA			S65-247-38 180-10469	MTH 16-Nov-2015		O/C	0		
345070 LEFT	GTX 3000 MODE S TCAS II TRANSPONDER			011-01997-00 20S007092	MTH 16-Nov-2015		O/C	0		
345070 RIGHT	GTX 3000 MODE S TCAS II TRANSPONDER			011-01997-00 20S007124	MTH 16-Nov-2015		O/C	0		
346030	TCAS PROCESSOR			011-02571-00 28P006056	MTH 16-Nov-2015		O/C	0		
346102 LH	GCU 275 PFD CONTROLLER			011-01983-01 1U7105875	MTH 16-Nov-2015		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
346102 RH	GCU 275 PFD CONTROLLER	011-01983-01 1U7105876	MTH 16-Nov-2015		O/C	0		
35-00-00-960	OXYGEN BOTTLE EGHH	176276-50 590399503	MTH 14-May-2024 HRS 1347:50 LDG 918		180		31-Aug-2028	35 m 8 d
Manufacture Date: 01-Aug-2013								
35-10-05-960 COPILOT	COPILOT OXYGEN MASK OVERHAUL 9914771-1 KIND	174252-96 37730	MTH 15-Feb-2017 HRS 178:36 LDG 149		O/C	22 178:36 149		
35-10-05-960 PILOT	PILOT OXYGEN MASK OVERHAUL 9914771-1 KIND	174252-96 36478	MTH 15-Feb-2017 HRS 178:36 LDG 149		O/C	22 178:36 149		
350008	PORTABLE BOTTLE - OXYGEN SYSTEM	PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
351008	OXYGEN 3 POSITION VALVE	P21007 2740	MTH 16-Nov-2015		O/C	0		
36-10-00-960 LEFT	LEFT BLEED AIR PRECOOLER 9914402-2	8161-1 4883T2005	MTH 08-Nov-2022 HRS 1126:06 LDG 807		84 2000	0 0 0	30-Nov-2029 3126:06	50 m 7 d 1474:19
36-10-00-960 RIGHT	RIGHT BLEED AIR PRECOOLER 9914402-2	8161-1 S4883T1381	MTH 08-Nov-2022 HRS 1126:06 LDG 807		84 2000	0 0 0	30-Nov-2029 3126:06	50 m 7 d 1474:19
361001 LEFT	TEMPERATURE SENSOR	27431501-10 7BM101	MTH 16-Nov-2015		O/C	0		
361001 RIGHT	TEMPERATURE SENSOR	27431501-10 7BM102	MTH 16-Nov-2015		O/C	0		
361003	PNEUMATIC REGULATOR 9912510-1	1H75-25 2BM15	MTH 16-Nov-2015		O/C	0		
361004 LEFT	PNEUMATIC SHUTOFF VALVE ASSY	2601-21 1826	MTH 16-Nov-2015		O/C	0		
361004 RIGHT	PNEUMATIC SHUTOFF VALVE ASSY	2601-21 1825	MTH 16-Nov-2015		O/C	0		
361007 LEFT	OVER TEMP BLEED AIR SWITCH	1173T181-2 7865	MTH 16-Nov-2015		O/C	0		
361007 RIGHT	OVER TEMP BLEED AIR SWITCH	1173T181-2 7864	MTH 16-Nov-2015		O/C	0		
361008 LEFT	PRECOOLER DOOR VALVE	5060-00-1 4573	MTH 16-Nov-2015		O/C	0		
361008 RIGHT	PRECOOLER DOOR VALVE	5060-00-1 4580	MTH 16-Nov-2015		O/C	0		
361010 LEFT	CHECK VALVE	1553-00-18 3714	MTH 16-Nov-2015		O/C	0		
361010 RIGHT	CHECK VALVE	1553-00-18 3711	MTH 16-Nov-2015		O/C	0		
361011 LEFT	PRECOOLER ACTUATOR	1H139-1 6BM54	MTH 16-Nov-2015		O/C	0		
361011 RIGHT	PRECOOLER ACTUATOR	1H139-2 3BM26	MTH 16-Nov-2015		O/C	0		
361012	DOOR SEAL CONTROL VALVE	MJV3 NSN	MTH 16-Nov-2015		O/C	0		
383001	FLUSHING TOILET ASSEMBLY LFPB	17000-457 10242235	MTH 05-Feb-2025 HRS 1519:42 LDG 1047		O/C	4 0 0		
442000	WIRELESS MEDIA SERVER	PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
521000	CABIN ENTRY DOOR			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
522001	DOOR INFLATABLE SEAL			S15501-4 NSN	MTH 16-Nov-2015		O/C	0		
522004	PRESSURE SWITCH			P18M30 5772	MTH 16-Nov-2015		O/C	0		
522007	ESCAPE HATCH SKIN BAND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
523001	TAILCONE BAGGAGE DOOR BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
523002 LEFT	NOSE BAGGAGE DOOR BOND ASSEMBLY - LEFT			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
523002 RIGHT	NOSE BAGGAGE DOOR BOND ASSEMBLY - RIGHT			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
531000 LEFT	TRUNNION SUPPORT FITTING			5513056-7 47309-21	MTH 16-Nov-2015 LDG 0		22500	0	22500	21364
531000 RIGHT	TRUNNION SUPPORT FITTING			5513056-8 43972-12	MTH 16-Nov-2015 LDG 0		22500	0	22500	21364
531001	NOSE LANDING GEAR (NLG) ACTUATOR SUPPORT FITTING			6511105-1 24604152T	MTH 16-Nov-2015 LDG 0		22500	0	22500	21364
531201	RADOME ASSEMBLY			6313101-47 NSN	MTH 16-Nov-2015		O/C	0		
532001 FORWARD	FORWARD PRESSURE BULKHEAD WEB BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532002 AFT	AFT CABIN STRUCTURE DOUBLER BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532003 LOWER	AFT PRESSURE BULKHEAD LOWER WEB BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532004 AFT	AFT CABIN STRUCTURE FRAME BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532401 LEFT HAND	LEFT CABIN SKIN BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532401 RIGHT HAND	RIGHT CABIN SKIN BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532402 LOWER	LOWER CABIN SKIN BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532403	FUSELAGE SKIN BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532404 LEFT	LEFT COCKPIT FUSELAGE SKIN BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
532404 RIGHT	RIGHT COCKPIT FUSELAGE SKIN BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
534001 AFT	AFT CANTED BULKHEAD ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
534002 AFT 1	AFT 1 TAILCONE BONDED WEB ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
534002 FORWARD 1	FORWARD 1 TAILCONE BONDED WEB ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
534003 AFT 1	AFT 2 TAILCONE BONDED WEB ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
534003 FORWARD 2	FORWARD 2 TAILCONE BONDED WEB ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535001 LEFT	LEFT FAIRING PANEL BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535001 RIGHT	RIGHT FAIRING PANEL BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535002 LEFT HAND	LEFT HAND AFT FAIRING SKIN			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535002 RIGHT HAND	RIGHT HAND AFT FAIRING SKIN			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535003 LEFT HAND	LEFT HAND FUSELAGE FAIRING PANEL ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535003 RIGHT HAND	RIGHT HAND FUSELAGE FAIRING PANEL ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535004 AFT	AFT FUSELAGE FAIRING BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535004 FORWARD	FORWARD FUSELAGE FAIRING BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535005 AFT	AFT FUSELAGE FAIRING ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535005 FORWARD	FORWARD FUSELAGE FAIRING ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535006 LEFT HAND FORWARD	LEFT HAND FORWARD FUSELAGE FAIRING BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535006 RIGHT HAND FORWARD	RIGHT HAND FORWARD FUSELAGE FAIRING BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535007 LEFT HAND AFT	LEFT HAND AFT FUSELAGE FAIRING BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
535007 RIGHT HAND AFT	RIGHT HAND AFT FUSELAGE FAIRING BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
551011	HORIZONTAL STABILIZER DOUBLER BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
551012 LOWER	HORIZONTAL STABILIZER LOWER DOUBLER BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
551012 UPPER	HORIZONTAL STABILIZER UPPER DOUBLER BOND ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
551013 LEFT HAND	LEFT HAND HORIZONTAL STABILIZER WEB ASSEMBLY			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
551013 RIGHT HAND	RIGHT HAND HORIZONTAL STABILIZER WEB ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
551014 LEFT LOWER	LEFT LOWER HORIZONTAL STABILIZER SKIN BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
551014 RIGHT LOWER	RIGHT LOWER HORIZONTAL STABILIZER SKIN BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
551015 LEFT UPPER	LEFT UPPER HORIZONTAL STABILIZER SKIN BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
551015 RIGHT UPPER	RIGHT UPPER HORIZONTAL STABILIZER SKIN BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
552003 UPPER	AFT PRESSURE BULKHEAD UPPER WEB BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
553002	VERTICAL STABILIZER SPAR BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
553003 NO. 1	NO.1 VERTICAL STABILIZER WEB BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
553003 NO. 2	NO. 2 VERTICAL STABILIZER WEB BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
553004 LEFT HAND	LEFT HAND VERTICAL STABILIZER SKIN BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
553005 RIGHT HAND	RIGHT HAND VERTICAL STABILIZER SKIN BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		
561001 LEFT	WINDSHIELD ASSY, (LH) 93200-15 3615			MTH	16-Nov-2015		O/C	0		
561001 RIGHT	WINDSHIELD ASSY, (LH) 93200-16 3418			MTH	16-Nov-2015		O/C	0		
561002 L1	CABIN DOOR WINDOW 6311123-11-1 2115			MTH	16-Nov-2015		O/C	0		
561002 L2	CABIN WINDOW 6311123-11-1 2159			MTH	16-Nov-2015		O/C	0		
561002 L3	CABIN WINDOW 6311123-11-1 2123			MTH	16-Nov-2015		O/C	0		
561002 R1	CABIN WINDOW 6311123-11-1 1980			MTH	16-Nov-2015		O/C	0		
561002 R2	CABIN WINDOW 6311123-11-1 1991			MTH	16-Nov-2015		O/C	0		
561002 R3	CABIN WINDOW 6311123-11-1 2019			MTH	16-Nov-2015		O/C	0		
561002 R4	CABIN WINDOW 6311123-11-1 1809			MTH	16-Nov-2015		O/C	0		
561003 PILOT	SIDE WINDOW 6311263-1 2621			MTH	16-Nov-2015		O/C	0		
561004 COPILLOT	SIDE WINDOW 6311263-2 2648			MTH	16-Nov-2015		O/C	0		
561005 LEFT HAND	LEFT HAND DOUBLER BOND ASSEMBLY PN SN-UNKNOWN			MTH	16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
561005 RIGHT HAND	RIGHT HAND DOUBLER BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
571000 LEFT AFT	TRUNNION ATTACH FITTING 6322070-21 24958056C	MTH LDG	16-Nov-2015 0			0 0		19964
571000 RIGHT AFT	TRUNNION ATTACH FITTING 6322070-20 24031805J	MTH LDG	16-Nov-2015 0			0 0	21100	19964
571001 LEFT FORWARD	TRUNNION ATTACH FITTING 6322060-19 24360217M	MTH LDG	16-Nov-2015 0		21100	0 0	21100	19964
571001 RIGHT FORWARD	TRUNNION ATTACH FITTING 6322060-20 24970717J	MTH LDG	16-Nov-2015 0		21100	0 0	21100	19964
571002 LEFT	SIDE BRACE FITTING 6322080-25 24550395F	MTH LDG	16-Nov-2015 0		21100	0 0	21100	19964
571002 RIGHT	SIDE BRACE FITTING 6322080-24 24924586J	MTH LDG	16-Nov-2015 0		21100	0 0	21100	19964
571003 LEFT HAND	LEFT HAND WS 30 FORWARD WEB PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
571003 RIGHT HAND	RIGHT HAND WS 30 FORWARD WEB PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
572001 LH LOWER	LEFT HAND LOWER OUTBOARD SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
572001 LH UPPER	LEFT HAND UPPER OUTBOARD SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
572001 RH LOWER	RIGHT HAND LOWER OUTBOARD SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
572001 RH UPPER	RIGHT HAND UPPER OUTBOARD SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573004 LEFT	LEFT CENTER TRAILING EDGE SKIN BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573004 RIGHT	RIGHT CENTER TRAILING EDGE SKIN BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573005 LEFT	LEFT AFT LOWER BONDED SKIN PANEL PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573005 RIGHT	RIGHT AFT LOWER BONDED SKIN PANEL PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573006 LEFT	LEFT INBOARD TRAILING EDGE SKIN BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573006 RIGHT	RIGHT INBOARD TRAILING EDGE SKIN BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573007 LEFT	LEFT SKIN PANEL BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573007 RIGHT	RIGHT SKIN PANEL BOND ASSEMBLY PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573008 LEFT HAND	LEFT HAND LOWER OUTBOARD SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573008 RIGHT HAND	RIGHT HAND LOWER OUTBOARD SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573009 LH LOWER	LEFT HAND FORWARD LOWER SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573009 LH UPPER	LEFT HAND FORWARD UPPER SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		
573009 RH LOWER	RIGHT HAND FORWARD LOWER SKIN PN SN-UNKNOWN	MTH	16-Nov-2015		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
573009 RH UPPER	RIGHT HAND FORWARD UPPER SKIN			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
71-20-00-960 LEFT ENGINE AFT	ISOLATOR MOUNT			LM601SA4 LK3537	MTH 16-Nov-2015 HRS 0		3500	0	3500	1848:13
71-20-00-960 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT			LM601SA5 5333	MTH 16-Nov-2015 HRS 0		3500	0	3500	1848:13
71-20-00-960 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT			LM601SA5 5332	MTH 16-Nov-2015 HRS 0		3500	0	3500	1848:13
71-20-00-960 RIGHT ENGINE AFT	ISOLATOR MOUNT			LM601SA4 LK3636	MTH 16-Nov-2015 HRS 0		3500	0	3500	1848:13
71-20-00-960 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT			LM601SA5 5323	MTH 16-Nov-2015 HRS 0		3500	0	3500	1848:13
71-20-00-960 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT			LM601SA5 5254	MTH 16-Nov-2015 HRS 0		3500	0	3500	1848:13
716000 LH	TEMPERATURE SWITCH			1173T0759 7440	MTH 16-Nov-2015		O/C	0		
716000 RH	TEMPERATURE SWITCH			1173T0759 7442	MTH 16-Nov-2015		O/C	0		
71EN1 NO. 1	ENGINE			72100-201 290191			E/C			
71EN2 NO. 2	ENGINE			72100-201 290192			E/C			
720001	STD GEAR BOX			011-00878-20 1A1013659	MTH 16-Nov-2015		O/C	0		
720005 E1	#4 INNER RACE BEARING			79029 JT-106650	MTH 16-Nov-2015		O/C	0		
720005 E2	#4 INNER RACE BEARING			79029 JT-115120	MTH 16-Nov-2015		O/C	0		
720007 E1	1ST LP TURBINE NOZZLE			122141 AU22331	MTH 16-Nov-2015		O/C	0		
720007 E2	1ST LP TURBINE NOZZLE			122141 AU22309	MTH 16-Nov-2015		O/C	0		
720010 E1	BALL, DEEP GROOVE - 103 BEARING			78321 JT-111918	MTH 16-Nov-2015		O/C	0		
720010 E2	BALL, DEEP GROOVE - 103 BEARING			78321 JT-111913	MTH 16-Nov-2015		O/C	0		
720015 E1	BEARING, ROLLER - OUTER GDR ASSEMBLY			78301 JT-114097	MTH 16-Nov-2015		O/C	0		
720015 E2	BEARING, ROLLER - OUTER GDR ASSEMBLY			78301 JT-116475	MTH 16-Nov-2015		O/C	0		
720020 E1	BEVEL GEAR, 1ST RED PINION			56278 BG3614	MTH 16-Nov-2015		O/C	0		
720020 E2	BEVEL GEAR, 1ST RED PINION			56278 BG3561	MTH 16-Nov-2015		O/C	0		
720025 E1	BRG, 1ST RDCN RVL GEAR SUPPORT			110433 AU22437	MTH 16-Nov-2015		O/C	0		
720025 E2	BRG, 1ST RDCN RVL GEAR SUPPORT			110433 AU22443	MTH 16-Nov-2015		O/C	0		
720030 E1	COMBUSTOR ASSEMBLY			119448 AU20321	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720030 E2	COMBUSTOR ASSEMBLY			119448 AU20315	MTH 16-Nov-2015		O/C	0		
720035 E1	DAMPED 1ST RDCN BEVEL GEAR			50349 BG5686	MTH 16-Nov-2015		O/C	0		
720035 E2	DAMPED 1ST RDCN BEVEL GEAR			50349 BG5684	MTH 16-Nov-2015		O/C	0		
720040 E1	HP SHAFT SEAL, FRONT RUNNER			78640 SBC216B3	MTH 16-Nov-2015		O/C	0		
720040 E2	HP SHAFT SEAL, FRONT RUNNER			78640 SBC213B3	MTH 16-Nov-2015		O/C	0		
720045 E1	LP TURBINE MODULE ASSY KIT			111748 AU20481	MTH 16-Nov-2015		O/C	0		
720045 E2	LP TURBINE MODULE ASSY KIT			111748 AU20491	MTH 16-Nov-2015		O/C	0		
720050 E1	OIL TANK COVER			54879 WL22382	MTH 16-Nov-2015		O/C	0		
720050 E2	OIL TANK COVER			54879 WL22396	MTH 16-Nov-2015		O/C	0		
720055 E1	REAR, FUEL SLINGER,SEAL ASSEMBLY			116184 AU20194	MTH 16-Nov-2015		O/C	0		
720055 E2	REAR, FUEL SLINGER,SEAL ASSEMBLY			116184 AU20200	MTH 16-Nov-2015		O/C	0		
720060 E1	ACCESSORY DRIVE SHAFT			123069 GG271	MTH 16-Nov-2015		O/C	0		
720060 E2	ACCESSORY DRIVE SHAFT			123069 GG090	MTH 16-Nov-2015		O/C	0		
720065 E1	RETAINER, AXIAL CPRSR NUT			45785 AU20530	MTH 16-Nov-2015		O/C	0		
720065 E2	RETAINER, AXIAL CPRSR NUT			45785 AU20578	MTH 16-Nov-2015		O/C	0		
720070 E1 NO. 1	RING SEAL ASSEMBLY			45075 SBC258B3	MTH 16-Nov-2015		O/C	0		
720070 E2 NO. 1	RING SEAL ASSEMBLY			45075 SBC260B7	MTH 16-Nov-2015		O/C	0		
720075 E1 NO. 2	RING SEAL ASSEMBLY			45075 SBC264B9	MTH 16-Nov-2015		O/C	0		
720075 E2 NO. 2	RING SEAL ASSEMBLY			45075 SBC297B0	MTH 16-Nov-2015		O/C	0		
720080 E1 NO. 3	RING SEAL ASSEMBLY			64771 SBC244B1	MTH 16-Nov-2015		O/C	0		
720080 E2 NO. 3	RING SEAL ASSEMBLY			64771 SBC246B8	MTH 16-Nov-2015		O/C	0		
720090 E1	ROLLER, INNER GUIDED BEARING			79027 JT-116204	MTH 16-Nov-2015		O/C	0		
720090 E2	ROLLER, INNER GUIDED BEARING			79027 JT-116202	MTH 16-Nov-2015		O/C	0		
720095 E1	STATOR, IP COMPRESSOR VANE			115576 AU20407	MTH 16-Nov-2015		O/C	0		
720095 E2	STATOR, IP COMPRESSOR VANE			115576 AU20552	MTH 16-Nov-2015		O/C	0		
720100 E1	VANE, FAN STATOR ASSEMBLY			72439 MX20209	MTH 16-Nov-2015		O/C	0		
720100 E2	VANE, FAN STATOR ASSEMBLY			72439 MX20210	MTH 16-Nov-2015		O/C	0		
723001 E1	FAN ROTOR			117810 HW40851	MTH 16-Nov-2015 LDG 0		10000	0	(10000)10000	8864



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723001 E2	FAN ROTOR			117810 HW40850	MTH 16-Nov-2015 LDG 0			0 10000		8864
723010 E1	HP COMPRESSOR ROTOR			122723 HW40767	MTH 16-Nov-2015 LDG 0			0 10000	(10000)10000	8864
723010 E2	HP COMPRESSOR ROTOR			122723 HW40770	MTH 16-Nov-2015 LDG 0			0 10000	(10000)10000	8864
723015 E1	IP COMPRESSOR ROTOR			66032 HW41344	MTH 16-Nov-2015 LDG 0			0 10000	(10000)10000	8864
723015 E2	IP COMPRESSOR ROTOR			66032 HW41341	MTH 16-Nov-2015 LDG 0			0 10000	(10000)10000	8864
723022 E1	DIFFUSER CASE ASSEMBLY			114614 AU22231	MTH 16-Nov-2015		O/C	0		
723022 E2	DIFFUSER CASE ASSEMBLY			114614 AU22214	MTH 16-Nov-2015		O/C	0		
723061 E1	HIGH PRESSURE SHAFT			118924 RX15RT2974	MTH 16-Nov-2015		O/C	0		
723061 E2	HIGH PRESSURE SHAFT			118924 RX15RT3011	MTH 16-Nov-2015		O/C	0		
723092 E1	COMPLETE LP SHAFT ASSEMBLY			121728 RX14NG0627	MTH 16-Nov-2015		O/C	0		
723092 E2	COMPLETE LP SHAFT ASSEMBLY			121728 RX15NG0658	MTH 16-Nov-2015		O/C	0		
723149 E1	HP COMPRESSOR COVER ASSY			69885 AU22236	MTH 16-Nov-2015		O/C	0		
723149 E2	HP COMPRESSOR COVER ASSY			69885 AU22239	MTH 16-Nov-2015		O/C	0		
723205 E1	CASE AND INSERT ASSEMBLY			78267 MX3886	MTH 16-Nov-2015		O/C	0		
723205 E2	CASE AND INSERT ASSEMBLY			78267 MX3890	MTH 16-Nov-2015		O/C	0		
723505 E1	BEARING, SPLIT INNER-014 BALL			72107-700 JT-116011	MTH 16-Nov-2015		O/C	0		
723505 E2	BEARING, SPLIT INNER-014 BALL			72107-700 JT-115985	MTH 16-Nov-2015		O/C	0		
723510 E1 FRONT	BRG HSG, BRG LP SHFT ASSEMBLY			50242 FL1940	MTH 16-Nov-2015		O/C	0		
723510 E2 FRONT	BRG HSG, BRG LP SHFT ASSEMBLY			50242 FL1933	MTH 16-Nov-2015		O/C	0		
723515 E1	CARBON RING SEAL & BRG RETNR HOUSING			76881 AU20620	MTH 16-Nov-2015		O/C	0		
723515 E2	CARBON RING SEAL & BRG RETNR HOUSING			76881 AU20628	MTH 16-Nov-2015		O/C	0		
723520 E1 NO. 1	FACE,CARBON SEAL ASSEMBLY			57657 SBC163B8	MTH 16-Nov-2015		O/C	0		
723520 E2 NO. 1	FACE,CARBON SEAL ASSEMBLY			57657 SBC150B4	MTH 16-Nov-2015		O/C	0		
723525 E1 NO. 2	FACE,CARBON SEAL ASSEMBLY			68937 SBC314B5	MTH 16-Nov-2015		O/C	0		
723525 E2 NO. 2	FACE,CARBON SEAL ASSEMBLY			68937 SBC316B1	MTH 16-Nov-2015		O/C	0		
723530 E1	RUNNER, LP SHAFT, FRONT SEAL			79855 SBC253B1	MTH 16-Nov-2015		O/C	0		
723530 E2	RUNNER, LP SHAFT, FRONT SEAL			79855 SBC256B3	MTH 16-Nov-2015		O/C	0		
723535 E1	SPLIT INNER RING, BALL BEARING			118017 JT-116398	MTH 16-Nov-2015		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723535 E2	SPLIT INNER RING, BALL BEARING			118017 JT-116406	MTH 16-Nov-2015		O/C	0		
723540 E1	HOUSING,BEARING,TURBINE			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
723540 E2	HOUSING,BEARING,TURBINE			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
724035 E1	HP TURBINE ROTOR ASSEMBLY			111386 HW40903	MTH 16-Nov-2015		O/C	0		
724035 E2	HP TURBINE ROTOR ASSEMBLY			111386 HW41375	MTH 16-Nov-2015		O/C	0		
724045 E1	SEAL AND FUEL SLINGER ASSEMBLY			115471 AU200870	MTH 16-Nov-2015		O/C	0		
724045 E2	SEAL AND FUEL SLINGER ASSEMBLY			115471 AU200934	MTH 16-Nov-2015		O/C	0		
725010 E1	HP TURBINE DISK			73853 HW40903	MTH 16-Nov-2015 LDG 0		8000	0	(8000)8000	6864
725010 E2	HP TURBINE DISK			73853 HW41375	MTH 16-Nov-2015 LDG 0		8000	0	(8000)8000	6864
725020 E1	1ST LP TURBINE DISK 411			72704 HW40154	MTH 16-Nov-2015 LDG 0		10000	0	(10000)10000	8864
725020 E2	1ST LP TURBINE DISK 411			72704 HW40912	MTH 16-Nov-2015 LDG 0		10000	0	(10000)10000	8864
725030 E1	2ND LP TURBINE DISK			66993 HW40078	MTH 16-Nov-2015 LDG 0		10000	0	(10000)10000	8864
725030 E2	2ND LP TURBINE DISK			66993 HW40060	MTH 16-Nov-2015 LDG 0		10000	0	(10000)10000	8864
726011 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY			120746 MX21396	MTH 16-Nov-2015		O/C	0		
726011 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY			120746 MX21405	MTH 16-Nov-2015		O/C	0		
726012 E1	GEARBOX ACCESS DRIVE HOUSING			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
726012 E2	GEARBOX ACCESS DRIVE HOUSING			PN SN-UNKNOWN	MTH 16-Nov-2015		O/C	0		
730001 LEFT ENGINE	FUEL PRESSURE SWITCH			1103P0448 10740	MTH 16-Nov-2015		O/C	0		
730001 RIGHT ENGINE	FUEL PRESSURE SWITCH			1103P0448 10777	MTH 16-Nov-2015		O/C	0		
732301 NO. 1	ELECTRIC IND-FUEL FILTER			57847 GE5626	MTH 16-Nov-2015		O/C	0		
732301 NO. 2	ELECTRIC IND-FUEL FILTER			57847 GE5641	MTH 16-Nov-2015		O/C	0		
732500 LEFT ENGINE	FADEC	KMIE		117779 CL14AW2592	MTH 02-Jun-2017 HRS 215 LDG 180		O/C	215 215		
732500 RIGHT ENGINE	FADEC	KMIE		117779 CL14AW2590	MTH 02-Jun-2017 HRS 215 LDG 180		O/C	215 215		
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER			1573-4 AAT1196	MTH 16-Nov-2015		O/C	0		
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER			1573-4 AAT1415	MTH 16-Nov-2015		O/C	0		
730002 E1	FUEL NOZZLE ASSEMBLY 115	KSAT		50817 BCC-1AEC2555	MTH 20-Jul-2023 HRS 1222:12 LDG 825		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
730002 E2	FUEL NOZZLE ASSEMBLY 115	KSAT		50817 BCC-AAA14399	MTH 20-Jul-2023 HRS 1222:12 LDG 825		O/C			
731040 E1	FUEL MANIFOLD ASSEMBLY			121784 AU22365	MTH 16-Nov-2015		O/C	0		
731040 E2	FUEL MANIFOLD ASSEMBLY			121784 AU22352	MTH 16-Nov-2015		O/C	0		
732301 E1	ELEC FUEL FILTER INDICATOR			57847 GE5626	MTH 16-Nov-2015		O/C	0		
732301 E2	ELEC FUEL FILTER INDICATOR			57847 GE5641	MTH 16-Nov-2015		O/C	0		
732401 E1	FUEL DELIVERY UNIT			119148 CL4ATW0889	MTH 16-Nov-2015 HRS 0			0	(8000)8000	6348:13
732401 E2	FUEL DELIVERY UNIT			119148 CL4ATW0900	MTH 16-Nov-2015 HRS 0		8000	0	(8000)8000	6348:13
741010 E1 INBOARD	IGNITION EXCITER			68145 CK1500342	MTH 16-Nov-2015		O/C	0		
741010 E2 INBOARD	IGNITION EXCITER			68145 CK1402555	MTH 16-Nov-2015		O/C	0		
741020 E1 OUTBOARD	IGNITION EXCITER			68145 CK1500503	MTH 16-Nov-2015		O/C	0		
741020 E2 OUTBOARD	IGNITION EXCITER			68145 CK1500042	MTH 16-Nov-2015		O/C	0		
742201 E1 INBOARD	IGNITOR	KSAT		68032 CK-1903120	MTH 20-Jul-2023 HRS 1222:12 LDG 825		O/C			
742201 E1 OUTBOARD	IGNITOR	KSAT		68032 CK-1400842	MTH 20-Jul-2023 HRS 1222:12 LDG 825		O/C			
742201 E2 INBOARD	IGNITOR	KSAT		68032 CK-1500291	MTH 20-Jul-2023 HRS 1222:12 LDG 825		O/C			
742201 E2 OUTBOARD	IGNITOR	KSAT		68032 CK-1702334	MTH 20-Jul-2023 HRS 1222:12 LDG 825		O/C			
762005 E1	FRT BRG, HP SHAFT HOUSING ASSEMBLY			55684 JDM-1348	MTH 16-Nov-2015		O/C	0		
762005 E2	FRT BRG, HP SHAFT HOUSING ASSEMBLY			55684 JDM-1351	MTH 16-Nov-2015		O/C	0		
771005 E1	N1 DUAL MAGNETIC SPEED SENSOR			57355 MD-0180896	MTH 16-Nov-2015		O/C	0		
771005 E2	N1 DUAL MAGNETIC SPEED SENSOR			57355 MD-0180903	MTH 16-Nov-2015		O/C	0		
771005A E1	TT2 SENSOR			114944 AXT0201530	MTH 16-Nov-2015		O/C	0		
771005A E2	TT2 SENSOR			114944 AXT0201593	MTH 16-Nov-2015		O/C	0		
771015 E1	N2 DUAL MAGNETIC SPEED SENSOR			54831 MD-0179664	MTH 16-Nov-2015		O/C	0		
771015 E2	N2 DUAL MAGNETIC SPEED SENSOR			54831 MD-0179845	MTH 16-Nov-2015		O/C	0		
772002 E1	ITT HARNESS			75378 YYF003180	MTH 16-Nov-2015		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
772002 E2	ITT HARNESS			75378 YYF003166	MTH 16-Nov-2015		O/C	0		
772205 E1	PT2 PRESSURE DUAL SENSOR			113762 AXT0101188	MTH 16-Nov-2015		O/C	0		
772205 E2	PT2 PRESSURE DUAL SENSOR			113762 AXT0101197	MTH 16-Nov-2015		O/C	0		
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER			MS28034-3 193400	MTH 16-Nov-2015		O/C	0		
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER			MS28034-3 193383	MTH 16-Nov-2015		O/C	0		
793006 LEFT ENGINE	OIL PRESSURE SWITCH			S1103P89-3 3892	MTH 16-Nov-2015		O/C	0		
793006 RIGHT ENGINE	OIL PRESSURE SWITCH			S1103P89-3 3771	MTH 16-Nov-2015		O/C	0		
793008 LEFT	OIL TRANSDUCER			S2800-1128 8172-11-300	MTH 16-Nov-2015		O/C	0		
793008 RIGHT	OIL TRANSDUCER			S2800-1128 8236-9-244	MTH 16-Nov-2015		O/C	0		
792201 E1	LUBE OIL COOLER			121535 PP1764	MTH 16-Nov-2015		O/C	0		
792201 E2	LUBE OIL COOLER			121535 PP1787	MTH 16-Nov-2015		O/C	0		
792401 E1	LUBE AND SCAVENGE PUMP			120932 MX30311	MTH 16-Nov-2015 HRS 0		6000	0	(6000)6000	4348:13
792401 E2	LUBE AND SCAVENGE PUMP			120932 MX30359	MTH 16-Nov-2015 HRS 0		6000	0	(6000)6000	4348:13
793311 E1	INTERSTAGE HOUSING ASSEMBLY			117626 AU43979	MTH 16-Nov-2015		O/C	0		
793311 E2	INTERSTAGE HOUSING ASSEMBLY			117626 AU43986	MTH 16-Nov-2015		O/C	0		
80-10-00-960 LEFT ENGINE	LEFT ENGINE STARTER-GENERATOR RESTORATION			MG94D-4 0647A	MTH 08-Apr-2022 HRS 974:54 LDG 722		1000	3 0 0	1974:54	323:07
80-10-00-960 RIGHT ENGINE	RIGHT ENGINE STARTER-GENERATOR RESTORATION			MG94D-4 0609A	MTH 08-Apr-2022 HRS 974:54 LDG 722		1000	3 0 0	1974:54	323:07



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525-99-08 R01	MISCELLANEOUS - GARMIN G3000 COCKPIT REFERENCE GUIDE EFFECTIVITY	KMQJ		RECOMMENDED	MTH 06-Feb-2019 HRS 365:12 LDG 316		-			Complete
	MOC : COMPLIED WITH - COMPLETED SL525-99-08 R01 PER THE INSTRUCTIONS.									
SB FJ44-05-002 R01 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL	MTH		-			
	MOC :									
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL	MTH		-			
	MOC :									
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-05-1000 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R06 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R06 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1003 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 R02 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 R02 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 R03 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 R03 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
PSID WI-05-1003 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS						-			
	MOC :									
SL WI-05-1009-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-05-1009-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-05-1009 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-05-1009 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1095-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-05-1095-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-05-1095 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1095 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-05-1173-CN E1	CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-05-1173-CN E2	CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-05-1184-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-05-1184-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									
SL WI-05-1189-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
				CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-05-1189-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1189 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1189 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1194-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1194-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1198 R01-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1198 R01-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1198 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1198 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1198 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1198 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1208 R01-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1208 R01-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED									
MOC :										
SL WI-05-1208 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										
SL WI-05-1208 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL									
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-05-1208 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							
	-							
	MOC :							
SL WI-05-1208 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							
	-							
	MOC :							
SL WI-05-1209 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							
	-							
	MOC :							
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL CANCELLED							
	-							
	MOC :							
SL 525-20-06	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL INFORMATIONAL							
	-							
	MOC :							
SB 525-21-21	AIR CONDITIONING - SECURE EVAPORATOR DRAIN LINE TO PREVENT POTENTIAL CHAFING KMQJ	RECOMMENDED	MTH 20-Mar-2020 HRS 495:54 LDG 422		-			Complete
	MOC : COMPLIED WITH - COMPLETED SB525-21-21 PER THE INSTRUCTIONS.							
SL 525-21-03	AIR CONDITIONING - COMPRESSOR/CONDENSER ASSEMBLY FUSE REPLACEMENT RECOMMENDED				-			
	MOC :							
SL 525-21-04	AIR CONDITIONING - DIVERTER DUCT AIR CYLINDER VERIFICATION KMQJ	RECOMMENDED	MTH 15-Jul-2020 HRS 525:18 LDG 446		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL 525-21-04 IN ACCORDANCE WITH SERVICE LETTER INSTRUCTIONS. FOUND CORRECT DIVERTER SOLENOIDS INSTALLED AT THIS TIME. NO FURTHER ACTION REQUIRED.							
SL 525-21-06	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT RECOMMENDED	MTH			-			
	MOC :							
SB 525-23-21	COMMUNICATIONS - AVIATOR 300 SATCOM ANTENNA REPLACEMENT OPTIONAL				-			
	MOC :							
SB 525-23-22 R01	COMMUNICATIONS - AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM (ACARS) OPTION OPTIONAL				-			
	MOC :							
SB 525-23-22 R02	COMMUNICATIONS - AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM (ACARS) OPTION OPTIONAL				-			
	MOC :							
SB 525-23-22	COMMUNICATIONS - AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM (ACARS) OPTION OPTIONAL				-			
	MOC :							
SB 525-23-23 R01	COMMUNICATIONS - LINK 2000+ CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION OPTIONAL				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 525-23-23	COMMUNICATIONS - LINK 2000+ CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-23-24 R01	COMMUNICATIONS - FAA DATACOMM INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-23-24	COMMUNICATIONS - FAA DATACOMM INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-23-25	COMMUNICATIONS - GARMIN GDR 66 VHF DATA LINK RADIO INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-23-26	COMMUNICATIONS - AUDIO WIRING MODIFICATION			OPTIONAL			-			
	MOC :									
SL 525-23-08 R01	COMMUNICATIONS - GARMIN GMA 36 MODIFICATION LEVEL VERIFICATION			RECOMMENDED	MTH		-			
	MOC :									
SL 525-23-08	COMMUNICATIONS - GARMIN GMA 36 MODIFICATION LEVEL VERIFICATION	IND		RECOMMENDED	MTH 23-Feb-2016 HRS 35:48 LDG 29		-			N/A
	MOC :									
SL 525-23-09	COMMUNICATIONS - LINK 2000+ CPDLC AND VHF ACARS CONFIGURATION VERIFICATION			RECOMMENDED			-			
	MOC :									
SL 525-23-11	COMMUNICATIONS - ATG 5000 SOFTWARE UPGRADE			OPTIONAL			-			
	MOC :									
SL 525-23-12	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8			OPTIONAL			-			
	MOC :									
SB 525-24-19 R02	ELECTRICAL POWER - CONCORDE LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH 16-Sep-2022 HRS 1085:30 LDG 779		-			Complete
	MOC :									
SB 525-24-31 R01	ELECTRICAL POWER - POWER J-BOX START RELAY MODIFICATION	KMQJ		RECOMMENDED	MTH 06-Feb-2019 HRS 365:12 LDG 316		-			Complete
	MOC :									
SB 525-24-32	ELECTRICAL POWER - RG24-15M CONCORDE LEAD ACID AUXILIARY BATTERY INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-24-33	ELECTRICAL POWER - GENERATOR CONTROL UNIT (GCU) DIODE MODIFICATION			DISCRETIONARY			-			
	MOC :									
COM MC 525-007 R01	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES			INFORMATIONAL	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
COM MC M2-006 R01	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES									
				INFORMATIONAL	MTH		-			
	MOC :									
COM MC M2-006	ATA 24 - GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES									
				INFORMATIONAL			-			
	MOC :									
SL 525-24-09	ELECTRICAL POWER - INSPECT THE AILERON, SPEED BRAKE AND FLAP BOND JUMPERS FOR PROPER GROUNDING									
				RECOMMENDED			-			
	MOC :									
SB 525-25-30 R01	EXTENDED RECLINE RIGHT FORWARD DIVIDER INSTALLATION									
				OPTIONAL	MTH		-			
	MOC :									
SB 525-25-34	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK									
				OPTIONAL			-			
	MOC :									
SB 525-25-35 R01	EQUIPMENT/FURNISHINGS - GARMIN FLIGHT STREAM 510 INSTALLATION									
				OPTIONAL	MTH 10-Jul-2023		-			Complete
					HRS 1222:12					
					LDG 825					
	MOC : COMPLIED WITH - COMPLIED WITH SB525-25-35 R1, IAW SERVICE BULLETINS ACCOMPLISHMENT INSTRUCTIONS, DATED AUGUST 27, 2021.									
SB 525-25-35	EQUIPMENT/FURNISHINGS - GARMIN FLIGHT STREAM 510 INSTALLATION									
				OPTIONAL			-			
	MOC :									
SB 525-25-36	EQUIPMENT/FURNISHINGS - CABIN ACOUSTIC NOISE IMPROVEMENT INSTALLATION									
				OPTIONAL			-			
	MOC :									
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION									
				OPTIONAL			-			
	MOC :									
SB CIB-25-02	EQUIPMENT/FURNISHINGS - BELTED TOILET SEAT INERTIA REEL MODIFICATION									
				RECOMMENDED			-			
	MOC :									
SL CIL-25-02	EQUIPMENT/FURNISHINGS - MEDAIRE AIRCRAFT FIRST AID KITS WITH MEDICATION SUBJECT TO RECALL NOTICE									
				INFORMATIONAL			-			
	MOC :									
SL CIL-25-03 R01	EQUIPMENT/FURNISHINGS - SEAT PAN TILT BLOCKING TAB INSTALLATION									
				INFORMATIONAL			-			
	MOC :									
SL 525-25-06	EQUIPMENT/FURNISHINGS - HEADREST BEARING IMPROVEMENT									
				DISCRETIONARY			-			
	MOC :									
SL 525-25-07	EQUIPMENT/FURNISHINGS - TOILET DRIP TRAY INSTALLATION									
				OPTIONAL			-			
	MOC :									
SL 525-25-08	EQUIPMENT/FURNISHINGS - MODIFICATION OF THE PASSENGER SEATS									
				OPTIONAL			-			
	MOC :									
SL 525-25-09 R01	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE SEAT PAN TILT SNAP RINGS (MILLENNIUM SERVICE BULLETIN SB2049-25-20-02B)									
				RECOMMENDED			-			
	MOC :									
SL 525-25-10	EQUIPMENT/FURNISHINGS - INSPECT FOR MISSING RIVETS IN THE CLIPS COMMON TO THE LEFT AND RIGHT WINDOW LONGERON									
				RECOMMENDED	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525-25-12	EQUIPMENT/FURNISHINGS - INSPECTION OF THE FLIGHT CREW SEAT HARDWARE									
	RECOMMENDED						-			
	MOC :									
SB 525-26-03	FIRE PROTECTION - REPLACEMENT OF THE HALON TYPE 1211 PORTABLE FIRE EXTINGUISHERS									
	OPTIONAL						-			
	MOC :									
SB 525-26-04 R01	FIRE PROTECTION - FIRE LOOP WIRING IMPROVEMENT	MTH	26-Sep-2024				-			Complete
	EDDL	MANDATORY	HRS 1418:18							
			LDG 968							
	MOC : COMPLIED WITH									
SB 525-26-04	FIRE PROTECTION - FIRE LOOP WIRING IMPROVEMENT (ON ENGINEERING HOLD PER EMAIL OCT 12,2023)									
	KSAT	MANDATORY	MTH 10-Jul-2023				-			Complete
			HRS 1222:12							
			LDG 825							
	MOC : COMPLIED WITH - COMPLIED WITH SB 525-26-04 FIRE PROTECTION FIRE LOOP WIRING IMPROVEMENT.									
COM MC M2-009	HYDRAULIC FIREWALL SHUTOFF VALVES									
	INFORMATIONAL						-			
	MOC :									
SL 525-26-01 R01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE ORIENTATION VERIFICATION									
	RECOMMENDED						-			
	MOC :									
SL 525-26-01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE ORIENTATION VERIFICATION									
	RECOMMENDED MTH						-			
	MOC :									
SB 525-27-25 R01	FLIGHT CONTROLS - GARMIN GSM 86 ELEVATOR TRIM MODIFICATION									
	DISCRETIONARY						-			
	MOC :									
SB 525-27-25	FLIGHT CONTROLS - GARMIN GSM 86 ELEVATOR TRIM MODIFICATION									
	OPTIONAL						-			
	MOC :									
SB 525-27-26 R01	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION									
	RECOMMENDED MTH						-			
	MOC :									
SB 525-27-26	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION									
	RECOMMENDED MTH						-			
	MOC :									
SB 525-27-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION									
	RECOMMENDED MTH						-			
	MOC :									
SL 525-27-06 R01	FLIGHT CONTROLS - ELEVATOR HARDWARE INSPECTION					MTH		-		
	MANDATORY									
	MOC :									
SL 525-27-07 R02	FLIGHT CONTROLS - AFT ELEVATOR CABLE INSPECTION/REPLACEMENT									
	MANDATORY MTH						-			
	MOC :									
SL 525-27-08	FLIGHT CONTROLS - RUDDER RIG PIN HOLE INSTALLATION									
	KMQJ	RECOMMENDED	MTH 06-Feb-2019				-			Complete
			HRS 365:12							
			LDG 316							
	MOC : COMPLIED WITH - COMPLETED SL525-27-08 PER THE INSTRUCTIONS.									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525-27-10	FLIGHT CONTROLS - ELEVATOR RIGGING TENSION CHECK AND CORRECT AS NEEDED			RECOMMENDED			DUE			
	MOC :									
SL 525-27-11	FLIGHT CONTROLS - CONTROL WHEEL ADAPTER AND SHAFT INSPECTION			RECOMMENDED MTH			-			
	MOC :									
SL 525-27-12 R01	FLIGHT CONTROLS - TRIM ACTUATOR GREASE INSTALLATION			RECOMMENDED DAYS			-			
	MOC :									
SL 525-27-13	FLIGHT CONTROLS - AILERON PUSHROD ATTACH BOLT NUT TORQUE VERIFICATION			RECOMMENDED			-			
	MOC :									
SL 525-27-14 R01	FLIGHT CONTROLS - SPEED BRAKE ASSEMBLY FASTENER INSPECTION	LFPB		RECOMMENDED	MTH 05-Feb-2025 HRS 1519:42 LDG 1047		-			Complete
	MOC :	COMPLIED WITH								
SL 525-27-14	FLIGHT CONTROLS - SPEED BRAKE ASSEMBLY FASTENER INSPECTION			RECOMMENDED			-			
	MOC :									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
	MOC :									
COM ME-P-003	MULTI-ENGINE PISTON COMMUNIQUE - FUEL			RECOMMENDED			-			
	MOC :									
SL 525-28-06	FUEL - FUEL LOW LEVEL FLOAT SWITCH (SL001, LEFT; SR001, RIGHT) MOUNTING NUT TORQUE INSPECTION	KMQJ			MTH 20-Mar-2020 HRS 495:54 LDG 422		-			Complete
	MOC :	COMPLIED WITH - COMPLETED SL525-28-06 PER THE INSTRUCTIONS.								
COM MC M2-005	"HYD FLOW SENSE L (OR) R" CAS MESSAGE AT ENGINE SHUTDOWN			INFORMATIONAL			-			
	MOC :									
SL 525-29-04	HYDRAULIC POWER - CV02-193 CHECK VALVE INSPECTION			RECOMMENDED			DUE			
	MOC :									
SL 525-29-05	HYDRAULIC POWER - INSTALLATION OF THE CONICAL SEALS IN HYDRAULIC LINES			RECOMMENDED			-			
	MOC :									
SL 525-30-05 R02	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE SENSOR INSPECTION			MANDATORY MTH			-			
	MOC :									
SL 525-30-05	WINDSHIELD TEMPERATURE SENSOR INSPECTION	IND		MANDATORY	MTH 23-Feb-2016 HRS 35:48 LDG 29		-			Complete
	MOC :	COMPLIED WITH								
SL 525-30-06	ICE AND RAIN PROTECTION - WINDSHIELD BLEED AIR SHROUD SEALING	IND		MANDATORY	MTH 23-Feb-2016 HRS 35:48 LDG 29		-			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525-30-07	ICE AND RAIN PROTECTION - ENGINE ANTI-ICE VALVE CONNECTOR SAFETY WIRE INSTALLATION	IND		MANDATORY	MTH 19-May-2016 HRS 72:12 LDG 50		-			Complete
	MOC : COMPLIED WITH									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
	MOC :									
COM MC 525-003	AIRCRAFT RECORDING SYSTEM SOFTWARE			INFORMATIONAL			-			
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL	MTH		-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL			-			
	MOC :									
SL 525-32-26	LANDING GEAR - EMERGENCY BRAKE VALVE ASSEMBLY INSPECTION			RECOMMENDED			-			
	MOC :									
SL 525-32-27	LANDING GEAR - MAIN LANDING GEAR REPAIR			INFORMATIONAL			-			
	MOC :									
SB 525-34-100 R01	NAVIGATION - FUTURE AIR NAVIGATION SYSTEM (FANS) 1/A INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-100	NAVIGATION - FUTURE AIR NAVIGATION SYSTEM (FANS) 1/A INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-101 R01	NAVIGATION - GARMIN SURFACEWATCH INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-101	NAVIGATION - GARMIN SURFACEWATCH INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-102 R01	NAVIGATION - SYNTHETIC VISION SYSTEM INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-102	NAVIGATION - SYNTHETIC VISION SYSTEM INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-103 R01	NAVIGATION - TERRAIN AWARENESS WARNING SYSTEM (TAWS) CLASS A INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-103	NAVIGATION - TERRAIN AWARENESS WARNING SYSTEM (TAWS) CLASS A INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-104 R01	NAVIGATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS II) INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-104	NAVIGATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS II) INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-34-105 R01	NAVIGATION - REACTIVE WINDSHEAR INSTALLATION			OPTIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 525-34-105 R02	NAVIGATION - REACTIVE WINDSHEAR INSTALLATION									
				OPTIONAL			-			
	MOC :									
SB 525-34-105	NAVIGATION - REACTIVE WINDSHEAR INSTALLATION						-			
				OPTIONAL						
	MOC :									
SB 525-34-106	NAVIGATION - GDL 69 SXM DATA LINK INSTALLATION						-			
				OPTIONAL						
	MOC :									
SB 525-34-107 R01	NAVIGATION - GARMIN HARDWARE AND SOFTWARE UPDATE TO VERSION 4.8.9						-			
				OPTIONAL						
	MOC :									
SB 525-34-108	NAVIGATION - GARMIN HARDWARE AND SOFTWARE UPDATE TO VERSION 4.8.16 (4.8 PRIME)(ON HOLD)						-			
				OPTIONAL						
	MOC :									
SB 525-34-109	NAVIGATION - ENHANCED VISION SYSTEM (EVS) INSTALLATION						-			
				OPTIONAL						
	MOC :									
SB 525-34-110	NAVIGATION - PREDICTIVE WINDSHEAR INSTALLATION						-			
				OPTIONAL						
	MOC :									
SB 525-34-111	NAVIGATION - TOLD DATABASE UPDATE				MTH		-			
				RECOMMENDED						
	MOC :									
SB 525-34-89	NAVIGATION - GARMIN G3000 3.2 SOFTWARE UPGRADE				MTH 23-Feb-2016		-			Complete
		IND		RECOMMENDED	HRS 35:48					
					LDG 29					
	MOC :	COMPLIED WITH								
SB 525-34-91	NAVIGATION - STORMSCOPE SYSTEM INSTALLATION						-			
				OPTIONAL						
	MOC :									
SB 525-34-92	NAVIGATION - GARMIN G3000 SURFACEWATCH INSTALLATION						-			
				OPTIONAL						
	MOC :									
SB 525-34-93	NAVIGATION - RADAR GROUND CLUTTER SUPPRESSION INSTALLATION						-			
				DISCRETIONARY						
	MOC :									
SB 525-34-97 R01	NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11				MTH 21-Jun-2023		-			N/A
				MANDATORY	HRS 1219:24					
					LDG 826					
	MOC :	NOT APPLICABLE - SOFTWARE VERSION 4.8.11 IS INSTALLED								
SB 525-34-97 R02	NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11						-			
				MANDATORY						
	MOC :									
SB 525-34-97	NAVIGATION - GARMIN SOFTWARE UPDATE TO VERSION 4.8.11				MTH 21-Jun-2023		-			Complete
				MANDATORY	HRS 1219:24					
					LDG 826					
	MOC :	COMPLIED WITH - PCW								
SB 525-34-99 R01	NAVIGATION - GROUND CLUTTER SUPPRESSION (GCS) AND TURBULENCE DETECTION SYSTEM (TDS) OPTION						-			
				OPTIONAL						
	MOC :									
SB 525-34-99	NAVIGATION - GROUND CLUTTER SUPPRESSION (GCS) AND TURBULENCE DETECTION SYSTEM (TDS) OPTION						-			
				OPTIONAL						
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-34-05 R01	TRANSMITTAL OF GARMIN SERVICE ALERT 1478, LP AND LPV APPROACHES			CANCELLED	MTH		-			
	MOC :									
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
	MOC :									
SL CIL-34-08	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ATL-4000-34-D, NAVIGATION - ALT-4000 - EVALUATION OF SURFACE MOUNT FERRITE BEAD USED ON THE POWER SUPPLY			RECOMMENDED			-			
	MOC :									
SL CIL-34-10	NAVIGATION - TRANSMITTAL OF GARMIN SB 19102 GSR 56 MOD 1			INFORMATIONAL			-			
	MOC :									
SB CIL-34-11	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS IMPROVEMENT			OPTIONAL			-			
	MOC :									
COM MC 525-005	M2 GARMIN 4.8 SOFTWARE AND LRU UPDATE			INFORMATIONAL			-			
	MOC :									
COM MC M2-002	ATA 34 - LOSS OF GPS SIGNAL			INFORMATIONAL			-			
	MOC :									
COM MC M2-003	ATA 34 - GARMIN G3000 VERSION 4.8.9 DATABASE LOADING GUIDANCE			INFORMATIONAL			-			
	MOC :									
COM MC M2-004	ATA 34 - GARMIN G3000 VERSION 4.8.11 DATABASE LOADING GUIDANCE			INFORMATIONAL			-			
	MOC :									
SL 525-34-28	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1433 POTENTIAL GWX 70 POWER AMPLIFIER FAILURE IN GROUND MAP MODE			INFORMATIONAL	MTH		-			
	MOC :									
SL 525-34-29	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1529, PROCEDURE LEGS IN TERMINAL PROCEDURES			INFORMATIONAL	MTH		-			
	MOC :									
SL 525-34-30	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1514, POTENTIAL ERRONEOUS LATERAL GUIDANCE			INFORMATIONAL	MTH		-			
	MOC :									
SL 525-34-31	NAVIGATION - VOR ANTENNA GASKET INSTALLATION				MTH	23-Feb-2016	-			Complete
	IND			RECOMMENDED	HRS	35:48				
					LDG	29				
	MOC :									
	COMPLIED WITH									
SL 525-34-33 R01	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1612 REVISION F, 2020 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL						-			
				INFORMATIONAL						
	MOC :									
SL 525-34-33	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL						-			
				INFORMATIONAL						
	MOC :									
	MOC :									
SL 525-34-34	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG AND SERVICE ADVISORY 1822 DME/DME NAVIGATION						-			
				INFORMATIONAL						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525-34-36	NAVIGATION - TRANSMITTAL OF GARMIN SB 1994, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE									
	INFORMATIONAL									
	MOC :									
SL 525-34-37	NAVIGATION - DISABLE FMS TEMPERATURE COMPENSATION AND IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES FOR LNAV/VNAV									
	EKRK	MANDATORY	MTH 06-Sep-2023			-			N/A	
			HRS 1222:30							
			LDG 826							
	MOC : NOT APPLICABLE - AIRCRAFT MODEL 525 M2 /SN IS NOT AFFECTED									
SL 525-34-38	NAVIGATION - STORMSCOPE PROCESSOR MODIFICATION (MOD) LEVEL INSPECTION									
		RECOMMENDED	MTH			-				
	MOC :									
SL 525-34-39	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY LETTER NO. 22037 REV A FALSE GPS NEEDS SERVICE SYSTEM MESSAGE									
	INFORMATIONAL									
	MOC :									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001									
	IND	MANDATORY	MTH			-			N/A	
			DAYS 23-Feb-2016							
			HRS 35:48							
			LDG 29							
	MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.									
COM MC M2-008	LIFE LIMITED PRECOOLERS									
	MOC :									
SL 525-36-03	PNEUMATIC - CAP INSPECTION		RECOMMENDED			-				
	MOC :									
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION									
	INFORMATIONAL									
	MOC :									
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION			MTH 23-Nov-2021		-		Complete		
		MANDATORY		HRS 846:12						
				LDG 642						
	MOC : COMPLIED WITH									
SL 525-52-02	DOORS - CABIN ENTRY DOOR HEATER DUCT INSTALLATION									
	KMQJ	RECOMMENDED	MTH 06-Feb-2019			-		Complete		
			HRS 365:12							
			LDG 316							
	MOC : COMPLIED WITH - COMPLETED SL525-52-02 PER THE INSTRUCTIONS.									
SL 525-52-04	DOORS - MAIN CABIN DOOR GROMMET INSTALLATION			MTH		-				
		RECOMMENDED								
	MOC :									
SB 525-53-21	FUSELAGE - RADOME LATCH IMPROVEMENT									
		OPTIONAL				-				
	MOC :									
SL CIL-53-01 R01	FUSELAGE - NOSE RADOME GUIDE PIN REPLACMENT									
		RECOMMENDED				-				
	MOC :									
SL 525-53-09 R01	FUSELAGE - NOSE WHEEL WELL RIVET INSPECTION/INSTALLATION									
		MANDATORY	MTH			-				
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 525-53-10 R01	FUSELAGE - WIRE BUNDLE ANCHOR INSPECTION ON FORWARD FAIRING									
			MANDATORY	DAYS			-			
	MOC :									
SL 525-53-12	FUSELAGE - CONTROL PEDESTAL WIRE HARNESS ANCHOR VERIFICATION									
			RECOMMENDED	MTH			-			
	MOC :									
SL 525-55-03 R01	STABILIZERS - HORIZONTAL STABILIZER FASTENER INSPECTION									
			MANDATORY	DAYS			-			
	MOC :									
SL 525-55-04 R01	STABILIZERS - LOWER HINGE BRACKET IN VERTICAL STABILIZER FASTENER INSPECTION									
			RECOMMENDED				DUE			
	MOC :									
SL WI-70-1008-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
			CANCELLED				-			
	MOC :									
SL WI-70-1008-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
			CANCELLED				-			
	MOC :									
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-70-1010-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
			CANCELLED				-			
	MOC :									
SL WI-70-1010-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
			CANCELLED				-			
	MOC :									
SL WI-70-1010 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-70-1010 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-70-1011-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
			CANCELLED				-			
	MOC :									
SL WI-70-1011-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
			CANCELLED				-			
	MOC :									
SL WI-70-1011 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL WI-70-1011 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
							-			
	MOC :									
SL 525-71-07 R01	POWER PLANT - OIL PRESSURE TRANSMITTER TUBE ASSEMBLY INSPECTION/REPLACEMENT									
			MANDATORY	MTH			-			
	MOC :									
SL 525-71-08 R01	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL									
			RECOMMENDED	MTH			-			
	MOC :									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 525-71-08 R02	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL			RECOMMENDED			-			
	MOC :									
SL 525-71-08	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL			RECOMMENDED MTH			-			
	MOC :									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1274 E1	POWER PLANT - TAKEOFF THROTTLE EXCEEDANCE - ACCEPTABLE FOR CONTINUED USE						-			
	MOC :									
SL WI-71-1274 E2	POWER PLANT - TAKEOFF THROTTLE EXCEEDANCE - ACCEPTABLE FOR CONTINUED USE						-			
	MOC :									
SL WI-71-1287 R01 E1	POWER PLANT - TAKEOFF THROTTLE EXCEEDANCE - ACCEPTABLE FOR CONTINUED USE						-			
	MOC :									
SL WI-71-1287 R01 E2	POWER PLANT - TAKEOFF THROTTLE EXCEEDANCE - ACCEPTABLE FOR CONTINUED USE						-			
	MOC :									
SL WI-71-1319-CN E1	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1319-CN E2	CANCELED - POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1319 E1	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1319 E2	POWER PLANT - ENGINE SHIPPING - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1540 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1540 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-71-1601-CN E1	CANCELED - POWER PLANT - VIBRATION SURVEY - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-71-1601-CN E2	CANCELED - POWER PLANT – VIBRATION SURVEY – REVISION TO LINE MAINTENANCE MANUAL									
	CANCELLED						-			
	MOC :									
SL WI-71-1601 E1	POWER PLANT - VIBRATION SURVEY - REVISION TO LINE MAINTENANCE MANUAL							-		
	MOC :									
SL WI-71-1601 E2	POWER PLANT - VIBRATION SURVEY - REVISION TO LINE MAINTENANCE MANUAL							-		
	MOC :									
SL WI-71-1606 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL							-		
	MOC :									
SL WI-71-1606 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL							-		
	MOC :									
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-72-076 R02 E1	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 R02 E2	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-080 R02 E1	2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE							-		
	RECOMMENDED									
	MOC :									
SB FJ44-72-080 R02 E2	2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE							-		
	RECOMMENDED									
	MOC :									
SB FJ44-72-103 R02 E1	LP SHAFT ASSEMBLY - IDENTIFICATION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-103 R02 E2	LP SHAFT ASSEMBLY - IDENTIFICATION			RECOMMENDED			-			
	MOC :									
SB FJ44-72-105 R03 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)							-		
	OPTIONAL									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-105 R03 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04) OPTIONAL						-			
	MOC :									
SB FJ44-72-105 R05 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION						-			
	MOC :									
SB FJ44-72-105 R05 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION						-			
	MOC :									
SB FJ44-72-105 R06 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION OPTIONAL MTH						-			
	MOC :									
SB FJ44-72-105 R06 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION OPTIONAL MTH						-			
	MOC :									
SB FJ44-72-107 R05 E1	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-107 R05 E2	2ND REDUCTION PINION BEARING HOUSING - REPLACE RECOMMENDED						-			
	MOC :									
SB FJ44-72-108 R01-CN E1	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED						-			
	MOC :									
SB FJ44-72-108 R01-CN E2	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED						-			
	MOC :									
SB FJ44-72-129 R01-CN E1	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE CANCELLED						-			
	MOC :									
SB FJ44-72-129 R01-CN E2	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE CANCELLED						-			
	MOC :									
SB FJ44-72-133 R01 E1	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED						-			
	MOC :									
SB FJ44-72-133 R01 E2	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED						-			
	MOC :									
SB FJ44-72-133 R02 E1	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED						-			
	MOC :									
SB FJ44-72-133 R02 E2	REPLACE 1ST LP TURBINE NOZZLE RECOMMENDED						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-72-133 E1	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-133 E2	REPLACE 1ST LP TURBINE NOZZLE (SUPERSEDED BY FJ44-72-133 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-140 R01 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			RECOMMENDED	MTH		CSI CSI			
	MOC :									
SB FJ44-72-140 R01 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			RECOMMENDED	MTH		CSI CSI			
	MOC :									
SB FJ44-72-143 R02 E1	BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-143 R02 E2	BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-143 R03 E1	BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-143 R03 E2	BLEED VALVE SHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 R03 E1	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-150 R03 E2	LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SL 44-72-325 R06 E1	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R06 E2	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R07 E1	1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R07 E2	1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
PSID WI-05-1000 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-05-1000 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R07 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R07 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-72-1022 R01 E1	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1022 R01 E2	OPERATING IN AREAS OF SMOKE						-			
	MOC :									
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS						-			
	MOC :									
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS						-			
	MOC :									
SB WI-72-1033 E1	HP TURBINE ROTOR BLADES - INSPECTION			RECOMMENDED			-			
	MOC :									
SB WI-72-1033 E2	HP TURBINE ROTOR BLADES - INSPECTION			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R01 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R01 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R02 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1037 R02 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1037 R03 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R03 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1037 R04 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-72-1037 R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2					MTH		-			
MOC :										
SB WI-72-1037 R05 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1							-			
RECOMMENDED										
MOC :										
SB WI-72-1037 R05 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2							-			
RECOMMENDED										
MOC :										
SB WI-72-1037 R06 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1					MTH		-			
MOC :										
SB WI-72-1037 R06 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2					MTH		-			
MOC :										
SB WI-72-1037 R07 ACCESSORY DRIVE TOWERSHAFT - REPLACE E1					MTH		-			
MOC :										
SB WI-72-1037 R07 ACCESSORY DRIVE TOWERSHAFT - REPLACE E2					MTH		-			
MOC :										
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1							-			
RECOMMENDED										
MOC :										
SB WI-72-1041 R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2							-			
RECOMMENDED										
MOC :										
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1					MTH		-			
RECOMMENDED										
MOC :										
SB WI-72-1041 R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2					MTH		-			
RECOMMENDED										
MOC :										
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1							-			
RECOMMENDED										
MOC :										
SB WI-72-1041 R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2							-			
RECOMMENDED										
MOC :										
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1							MPI			
RECOMMENDED										
MOC :										
SB WI-72-1041 R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2							MPI			
RECOMMENDED										
MOC :										
SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E1							-			
RECOMMENDED										
MOC :										
SB WI-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE E2							-			
RECOMMENDED										
MOC :										
SB WI-72-1044 R01 BALANCE PISTON - REPLACE E1							-			
RECOMMENDED										
MOC :										
SB WI-72-1044 R01 BALANCE PISTON - REPLACE E2							-			
RECOMMENDED										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-72-1044 E1	R02 BALANCE PISTON - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1044 E2	R02 BALANCE PISTON - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-72-1044 E1	R03 BALANCE PISTON - REPLACE			RECOMMENDED			CSI			
	MOC :									
SB WI-72-1044 E2	R03 BALANCE PISTON - REPLACE			RECOMMENDED			CSI			
	MOC :									
SB WI-72-1044 E1	ENGINE - BALANCE PISTON - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1044 E2	ENGINE - BALANCE PISTON - REPLACE			RECOMMENDED	MTH		-			
	MOC :									
SB WI-72-1172 E1	HIGH PRESSURE TURBINE BLADES - REPLACE				MTH		-			
	MOC :									
SB WI-72-1172 E2	HIGH PRESSURE TURBINE BLADES - REPLACE				MTH		-			
	MOC :									
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-72-1132-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
	MOC :									
SL WI-72-1262-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-72-1262-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
	MOC :									
SL WI-72-1262 E1	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL WI-72-1262 E2	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :						-			
SL WI-72-1332-CN E1	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS									
	CANCELLED						-			
	MOC :									
SL WI-72-1332-CN E2	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS									
	CANCELLED						-			
	MOC :									
SL WI-72-1418-CN E1	CANCELED-ENGINE – REAR HOUSING ASSEMBLY – REVISION TO ENGINE MANUAL									
	CANCELLED						-			
	MOC :									
SL WI-72-1418-CN E2	CANCELED-ENGINE – REAR HOUSING ASSEMBLY – REVISION TO ENGINE MANUAL									
	CANCELLED						-			
	MOC :									
SB 525-73-03	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT (FCU) FIELD REPLACEMENT									
	OPTIONAL						-			
	MOC :									
SB 525-73-04	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT (FDU) FIELD REPLACEMENT									
	OPTIONAL						-			
	MOC :									
SB FJ44-73-044 R08 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE									
	MANDATORY						-			
	MOC :									
SB FJ44-73-044 R08 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE									
	MANDATORY						-			
	MOC :									
SB FJ44-73-044 R09 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE									
	MANDATORY						-			
	MOC :									
SB FJ44-73-044 R09 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE									
	MANDATORY						-			
	MOC :									
SB FJ44-73-044 R10 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE									
	MANDATORY						-			
	MOC :									
SB FJ44-73-044 R10 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE									
	MANDATORY						-			
	MOC :									
SB FJ44-73-044 R11 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE					MTH				
							-			
	MOC :									
SB FJ44-73-044 R11 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE					MTH				
							-			
	MOC :									
SB FJ44-73-044 R12 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE					MTH				
							-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-73-044 R12 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE MTH				-			
MOC :								
SB FJ44-73-061 E1	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) CANCELLED				-			
MOC :								
SB FJ44-73-061 E2	CANCELLED - FUEL DELIVERY UNIT (FDU) - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) CANCELLED				-			
MOC :								
PSID WI-73-1001 R09 E1	ENGINE FUEL AND CONTROL - ENGINE CONTROL UNIT AND FUEL CONTROL UNIT - VALIDATION				-			
MOC :								
PSID WI-73-1001 R09 E2	ENGINE FUEL AND CONTROL - ENGINE CONTROL UNIT AND FUEL CONTROL UNIT - VALIDATION				-			
MOC :								
PSID WI-73-1001 E1	CANCELED - ENGINE FUEL AND CONTROL - ENGINE CONTROL UNIT AND FUEL CONTROL UNIT - VALIDATION CANCELLED				-			
MOC :								
PSID WI-73-1001 E2	CANCELED - ENGINE FUEL AND CONTROL - ENGINE CONTROL UNIT AND FUEL CONTROL UNIT - VALIDATION CANCELLED				-			
MOC :								
PSID WI-73-1004- CN E1	CANCELED - ENGINE AND FUEL CONTROL - FUEL DELIVERY UNIT - REVISION TO ILLUSTRATED PARTS CATALOG CANCELLED				-			
MOC :								
PSID WI-73-1004- CN E2	CANCELED - ENGINE AND FUEL CONTROL - FUEL DELIVERY UNIT - REVISION TO ILLUSTRATED PARTS CATALOG CANCELLED				-			
MOC :								
PSID WI-73-1004 E1	ENGINE AND FUEL CONTROL - FUEL DELIVERY UNIT - REVISION TO ILLUSTRATED PARTS CATALOG				-			
MOC :								
PSID WI-73-1004 E2	ENGINE AND FUEL CONTROL - FUEL DELIVERY UNIT - REVISION TO ILLUSTRATED PARTS CATALOG				-			
MOC :								
PSID WI-73-1008 R01 E1	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG				-			
MOC :								
PSID WI-73-1008 R01 E2	FUEL CONTROL UNIT - REVISION TO ILLUSTRATED PARTS CATALOG				-			
MOC :								
PSID WI-73-1031 R02 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION				-			
MOC :								
PSID WI-73-1031 R02 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION				-			
MOC :								
PSID WI-73-1031 R03 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION INFORMATIONAL				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
PSID WI-73-1031 R03 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION			INFORMATIONAL			-			
MOC :										
PSID WI-73-1031 R04 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION			MTH			-			
MOC :										
PSID WI-73-1031 R04 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT TO FUEL CONTROL UNIT CONVERSION			MTH			-			
MOC :										
SB WI-73-1002 R02 -CN E1	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
MOC :										
SB WI-73-1002 R02 -CN E2	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			CANCELLED			-			
MOC :										
SB WI-73-1002 R02 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)			MANDATORY			-			
MOC :										
SB WI-73-1002 R02 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (CANCELLED)			MANDATORY			-			
MOC :										
SB WI-73-1002 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)			MANDATORY			-			
MOC :										
SB WI-73-1002 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE (SUPERSEDED BY WISB-73-1002 R01)			MANDATORY			-			
MOC :										
SB WI-73-1007 R01 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)						-			
MOC :										
SB WI-73-1007 R01 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.10.02 (CANCELLED)						-			
MOC :										
SB WI-73-1008 R01 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED MTH			-			
MOC :										
SB WI-73-1008 R01 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED MTH			-			
MOC :										
SB WI-73-1008 R02 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1008 R02 E2	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1008 R03 E1	ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1009 R05 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE LFPB	RECOMMENDED	MTH 05-Feb-2025 HRS 1519:42 LDG 1047			-				Complete
	MOC : COMPLIED WITH									
SB WI-73-1009 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE RECOMMENDED					-				
	MOC :									
SB WI-73-1009 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE RECOMMENDED					-				
	MOC :									
SB WI-73-1016 E1	ENGINE FUEL AND CONTROL - FADEC - UPDATE AIRCRAFT SERIAL NUMBER					-				
	MOC :									
SB WI-73-1016 E2	ENGINE FUEL AND CONTROL - FADEC - UPDATE AIRCRAFT SERIAL NUMBER					-				
	MOC :									
SB WI-73-1019-CN E1	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022)	SUPERSEDED				-				
	MOC :									
SB WI-73-1019-CN E2	SUPERSEDED - ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY SB WISB-73-1022)	SUPERSEDED				-				
	MOC :									
SB WI-73-1019 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)					-				
	MOC :									
SB WI-73-1019 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 (SUPERSEDED BY WISB-73-1022)					-				
	MOC :									
SB WI-73-1022 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 NOT APPLICABLE					-				
	MOC :									
SB WI-73-1022 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01 NOT APPLICABLE					-				
	MOC :									
SB WI-73-1023 R01 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE RECOMMENDED					-				
	MOC :									
SB WI-73-1023 R01 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE RECOMMENDED					-				
	MOC :									
SB WI-73-1023 R02 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE RECOMMENDED					-				
	MOC :									
SB WI-73-1023 R02 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE RECOMMENDED					-				
	MOC :									
SB WI-73-1023 R03 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE					-				
	MOC :									
SB WI-73-1023 R03 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE					-				
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1023 R04 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE										
E1							-			
MOC :										
SB WI-73-1023 R04 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE										
E2							-			
MOC :										
SB WI-73-1023	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
E1				RECOMMENDED	MTH		-			
MOC :										
SB WI-73-1023	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
E2				RECOMMENDED	MTH		-			
MOC :										
SB WI-73-1027 R01 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE										
-CN				CANCELLED			-			
E1										
MOC :										
SB WI-73-1027 R01 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE										
-CN				CANCELLED			-			
E2										
MOC :										
SB WI-73-1027 R01 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE										
E1				MANDATORY			-			
MOC :										
SB WI-73-1027 R01 ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE										
E2				MANDATORY			-			
MOC :										
SB WI-73-1027	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
E1				MANDATORY			-			
MOC :										
SB WI-73-1027	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE									
E2				MANDATORY			-			
MOC :										
SB WI-73-1031 ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01										
E1							-			
MOC :										
SB WI-73-1031 ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.12.01										
E2							-			
MOC :										
SB WI-73-1032-CN ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01 (SUPERSEDED BY WISB-73-1042)										
E1				SUPERSEDED			-			
MOC :										
SB WI-73-1032-CN ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01 (SUPERSEDED BY WISB-73-1042)										
E2				SUPERSEDED			-			
MOC :										
SB WI-73-1032 ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01										
E1							-			
MOC :										
SB WI-73-1032 ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01										
E2							-			
MOC :										
SB WI-73-1040 R01 ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE										
E1					MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1040 R01 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH		-			
MOC :										
SB WI-73-1040 R02 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH		-			
MOC :										
SB WI-73-1040 R02 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH		-			
MOC :										
SB WI-73-1040 R03 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH HRS		DUE DUE DUE		(8000)8000	6348:13
MOC :										
SB WI-73-1040 R03 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH HRS		DUE DUE DUE		(8000)8000	6348:13
MOC :										
SB WI-73-1040 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH		-			
MOC :										
SB WI-73-1040 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE				MTH		-			
MOC :										
SB WI-73-1042 R01 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01				MTH		-			
MOC :										
SB WI-73-1042 R01 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01				MTH		-			
MOC :										
SB WI-73-1042 E1	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01						-			
MOC :										
SB WI-73-1042 E2	ENGINE FUEL AND CONTROL - ENGINE MAINTENANCE TERMINAL (EMT) SOFTWARE UPGRADE TO CP356.13.01						-			
MOC :										
SB WI-73-1043 E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE						-			
MOC :										
SB WI-73-1043 E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE						-			
MOC :										
SL WI-73-1016-CN E1	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG CANCELLED						-			
MOC :										
SL WI-73-1016-CN E2	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG CANCELLED						-			
MOC :										
SL WI-73-1016 E1	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL WI-73-1016 E2	ENGINE FUEL AND CONTROL - REVISION TO ILLUSTRATED PARTS CATALOG					-			
	MOC :								
SL WI-73-1026 E1	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1026 E2	ENGINE CONTROLS - EMT COMMUNICATION TOOLING - REVISION TO THE LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1037 E1	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1037 E2	ENGINE FUEL AND CONTROL - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1084-CN E1	CANCELED - ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-73-1084-CN E2	CANCELED - ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED			-			
	MOC :								
SL WI-73-1084 E1	ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1084 E2	ENGINE AND FUEL CONTROL - FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) AND ENGINE CONTROL UNIT (ECU) - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1095 E1	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-73-1095 E2	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SB WI-74-1000 R01 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT			MTH		-			
	MOC :								
SB WI-74-1000 R01 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT			MTH		-			
	MOC :								
SB WI-74-1000 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	APF	MANDATORY	MTH 29-May-2018 HRS 301:06 LDG 243		-			Complete
	MOC :								
SB WI-74-1000 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	APF	MANDATORY	MTH 29-May-2018 HRS 301:06 LDG 243		-			Complete
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-74-1004 R02 IGNITION - IGNITER LEAD - REPLACE E1				RECOMMENDED			DUE			
MOC :										
SB WI-74-1004 R02 IGNITION - IGNITER LEAD - REPLACE E2				RECOMMENDED			DUE			
MOC :										
SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-75-1001 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1				RECOMMENDED	MTH HRS		-		(3500)3500	1848:13
MOC :										
SB WI-75-1001 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2				RECOMMENDED	MTH HRS		-		(3500)3500	1848:13
MOC :										
SB WI-75-1001 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1001 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB 525-76-10	ENGINE CONTROLS - UPDATED FJ44-1AP FULL AUTHORITY ENGINE CONTROL (FADEC) FIELD REPLACEMENT			OPTIONAL			-			
MOC :										
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
MOC :										
SB FJ44-77-011 R16 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R17)			MANDATORY			-			
MOC :										
SB FJ44-77-011 R16 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - INSPECTION (SUPERSEDED BY FJ44-77-011 R17)			MANDATORY			-			
MOC :										
SB FJ44-77-013 R10 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-77-013 R10 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK					-			
	MOC :								
SB FJ44-77-013 R11 E1	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK RECOMMENDED					-			
	MOC :								
SB FJ44-77-013 R11 E2	ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK RECOMMENDED					-			
	MOC :								
COM ME-P-002	EXHAUST - MULTI-ENGINE PISTON COMMUNIQUE					-			
	MOC :								
SB FJ44-79-009 R09 E1	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST RECOMMENDED					-			
	MOC :								
SB FJ44-79-009 R09 E2	LUBRICATION - OIL PRESSURE RELIEF VALVE - ADJUST RECOMMENDED					-			
	MOC :								
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE MANDATORY					-			
	MOC :								
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE MANDATORY					-			
	MOC :								
SB FJ44-79-013 R01 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02) OPTIONAL					-			
	MOC :								
SB FJ44-79-013 R01 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R02) OPTIONAL					-			
	MOC :								
SB FJ44-79-013 R02 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03) RECOMMENDED					-			
	MOC :								
SB FJ44-79-013 R02 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03) RECOMMENDED					-			
	MOC :								
SB FJ44-79-013 R03 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04) RECOMMENDED					-			
	MOC :								
SB FJ44-79-013 R03 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R04) RECOMMENDED					-			
	MOC :								
SB FJ44-79-013 R04 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05) RECOMMENDED					-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-013 R04 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R05)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-013 R05 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH 04-Feb-2025		-			
	MOC : DECLINED - POSTPONED BY WILLIAMS									
SB FJ44-79-013 R05 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE			RECOMMENDED	MTH 04-Feb-2025		-			
	MOC : DECLINED - POSTPONED BY WILLIAMS									
SB FJ44-79-013 E1	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-79-013 E2	OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R01 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R01 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R02 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R02 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R03 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R03 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-016 R04 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE	APF		RECOMMENDED	MTH 29-May-2018 HRS 301:06 LDG 243		-			Complete
	MOC : COMPLIED WITH - REMOVED RELIEF VALVE PN: 120931, INSTALLED NEW RELIEF VALVE PN: 124540. WORK I.A.W. SB FJ44-79-016 R4.									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB FJ44-79-016 R04 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE	APF		RECOMMENDED	MTH 29-May-2018 HRS 301:06 LDG 243		-			Complete
MOC : COMPLIED WITH - REMOVED RELIEF VALVE, PN: 120931, INSTALLED NEW RELIEF VALVE, PN: 124540. WORK I.A.W. SB FJ44-79-016 R4.										
SB FJ44-79-016 R05 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R05 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R06 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R06 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 R07 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			RPI			
MOC :										
SB FJ44-79-016 R07 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE			RECOMMENDED			RPI			
MOC :										
SB FJ44-79-016 E1	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-79-016 E2	OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R01)			RECOMMENDED			-			
MOC :										
SL 525-80-02 R01	STARTING - STARTER GENERATOR MAIN POWER TERMINAL INSPECTION FOR CORRECT INSTALLATION OF WASHER AND NUT			RECOMMENDED			-			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2003-21-07	FLIGHT CONTROLS - ELECTRIC PITCH TRIM FAILURE CAUSING RUN AWAY PITCH TRIM CONDITION, LARGE PITCH MISTRIM AND EXCESSIVE CONTROL FORCES (SUPERSEDED BY FAA AD 2004-14-20)									
			MANDATORY	MTH			-			
MOC :										
FAA 2013-08-05	INSPECTION A/C COMPRESSOR HOUR METER			DAYS	14-Sep-2025		-			N/A
PARA (G)	EKBI		MANDATORY	HRS	1651:47					
				LDG	1136					
MOC : NOT APPLICABLE										
FAA 2013-08-05	REPLACE THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES			MTH	14-Sep-2025		-			N/A
PARA (H)	EKBI		MANDATORY	HRS	1651:47					
				LDG	1136					
MOC : NOT APPLICABLE										
FAA 2013-08-05	DEACTIVATION OF THE AIR CONDITIONING			MTH	14-Sep-2025		A/R			N/A
PARA (I)	EKBI		MANDATORY	HRS	1651:47					
				LDG	1136					
MOC : NOT APPLICABLE										
FAA 2013-08-05	RETURN OF REPLACED PARTS AND REPORTING REQUIREMENT			DAYS	14-Sep-2025		-			N/A
PARA (J)	EKBI		MANDATORY	HRS	1651:47					
				LDG	1136					
MOC : NOT APPLICABLE										
FAA 2013-08-05	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM			MTH	14-Sep-2025		-			N/A
	EKBI		MANDATORY	HRS	1651:47					
				LDG	1136					
MOC : NOT APPLICABLE - AIRCRAFT SN										
CAA UK G-2021-0003	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE JACKET - INSPECTION			MTH	08-Sep-2023		-			N/A
	UNK		MANDATORY	HRS	1222:30					
				LDG	826					
MOC : NOT APPLICABLE - EAM VESTS PN:P01074-207 IS INST										
CAA UK G-2022-0009	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFEJACKETS - INSPECTION			MTH	08-Sep-2023		-			N/A
	UNK		MANDATORY	HRS	1222:30					
				LDG	826					
MOC : NOT APPLICABLE - EAM VEST PN:P01074-207 IS INST										
EASA 2016-0163	MODIFY AND RE-IDENTIFY EACH AFFECTED CABIN ATTENDANT SEAT			MTH	08-Sep-2023		-			N/A
PARA (1)	UNK		MANDATORY	HRS	1222:30					
				LDG	826					
MOC : NOT APPLICABLE - NO CABIN ATENDAND SEAT IS INSTALLED										
EASA 2016-0163	DO NOT INSTALL AN AFFECTED CABIN ATTENDANT SEAT ON ANY AEROPLANE			MTH	08-Sep-2023		-			N/A
PARA (2)	UNK		MANDATORY	HRS	1222:30					
				LDG	826					
MOC : NOT APPLICABLE - NO CABIN ATENDAND SEAT IS INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
EASA 2016-0163	APPLIANCE AD - EQUIPMENT / FURNISHINGS – CABIN ATTENDANT SEAT – MODIFICATION / REPLACEMENT	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - NO CABIN ATENDAND SEAT IS INSTALLED										
EASA 2016-0167 R01 (CORR)	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01 PARA (1)	REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION (DVI)	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01 PARA (2)	DETAILED VISUAL INSPECTION (DVI)	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01 PARA (3)	ACCOMPLISH THE APPLICABLE TEMPORARY CORRECTIVE ACTIONS (IF, DURING ANY INSPECTION AS REQUIRED BY PARAS (1) OR (2) OF THIS AD, AS APPLICABLE, CORROSION OR OTHER DAMAGE IS FOUND)	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01 PARA (4)	TEMPORARILY STOWING AND SECURING A DAMAGED ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARA (3) OF THIS AD.	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01 PARA (5)	IT IS ALLOWED TO INSTALL (SEE NOTE 2 OF THIS AD) ON ANY AEROPLANE AN AFFECTED SEAT, HAVING ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON AN AEROPLANE, PROVIDED THAT, BEFORE (RE)INSTALLATION, IT HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2, SUBPART B, OF ZODIAC SEATS FRANCE SB NO. 536-25-002	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01 PARA (6)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE INSTRUCTIONS OF ZODIAC SEATS FRANCE SB NO. 536-25-004 CONSTITUTE TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AS REQUIRED BY PARAS (1) AND (2) OF THIS AD FOR THAT SEAT	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										
EASA 2016-0167 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SEAT IS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0210 PARA (1)	REPLACE THE EA ASSEMBLIES ON EACH AFFECTED SEAT WITH SERVICEABLE ASSEMBLIES IN ACCORDANCE WITH THE INSTRUCTIONS OF B/E AEROSPACE FISCHER SB 9911-001	UNK	MANDATORY	DAYS 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SEAT MODEL IS NOT INSTALLED									
EASA 2016-0210 PARA (2)	INSTALLATION OF AN AFFECTED SEAT ON AN AIRCRAFT IS ALLOWED, PROVIDED THAT, PRIOR TO INSTALLATION, IT IS DETERMINED THAT THE EA ASSEMBLIES HAVE BEEN REPLACED IN ACCORDANCE WITH THE INSTRUCTIONS OF B/E AEROSPACE FISCHER SB 9911-001	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SEAT MODEL IS NOT INSTALLED									
EASA 2016-0210	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SEAT MODEL IS NOT INSTALLED									
EASA 2018-0223	EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - MODIFICATION	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SEAT MODEL IS NOT INSTALLED									
EASA 2018-0264 R01	EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SEAT MODEL IS NOT INSTALLED									
EASA 2019-0010 PARA (1)	REMOVE EACH AFFECTED PART FROM SERVICE AND REPLACE IT WITH A SERVICEABLE PART	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EAM PN:P01074-207 IS INSTALLED									
EASA 2019-0010 PARA (2)	DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EAM PN:P01074-207 IS INSTALLED									
EASA 2019-0010 PARA (3)	DO NOT RELEASE TO SERVICE ANY AFFECTED PART, UNLESS IT HAS BEEN REPAIRED AND RE-IDENTIFIED	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EAM PN:P01074-207 IS INSTALLED									
EASA 2019-0010	EQUIPMENT/FURNISHING - LIFE JACKET - REMOVAL/REPAIR	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EAM PN:P01074-207 IS INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - ELT IS ONG INSTALLED HAVE NOT BEEN INSTALLED IN HELICOPTER										
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - ELT IS ONG INSTALLED HAVE NOT BEEN INSTALLED IN HELICOPTER										
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - ELT IS ONG INSTALLED HAVE NOT BEEN INSTALLED IN HELICOPTER										
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - ELT IS ONG INSTALLED HAVE NOT BEEN INSTALLED IN HELICOPTER										
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - ELT IS ONG INSTALLED HAVE NOT BEEN INSTALLED IN HELICOPTER										
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SEAT MODEL IS NOT INSTALLED										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS									
		MQJ			MTH 06-Dec-2018 HRS 348:48 LDG 303		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY. AIRCRAFT IS NOT EQUIPPED WITH AN AMERIKING ELT.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT									
		MQJ		MANDATORY	MTH 06-Dec-2018 HRS 348:48 LDG 303		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY. AIRCRAFT IS NOT EQUIPPED WITH AN AMERIKING ELT.										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS									
		MQJ		MANDATORY	MTH 06-Dec-2018 HRS 348:48 LDG 303		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY. AIRCRAFT IS NOT EQUIPPED WITH AN AMERIKING ELT.										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2018-23-12 PARA (G)	ACCOMPLISH AN INSPECTION TO DETERMINE IF ANY PLUG HAS PART NUMBER (P/N) B13984-3, STAMPED WITH LOT PA-21 OR PA-22	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SYSTEM IS NOT INSTALLED										
FAA 2018-23-12 PARA (H)	REPLACE FUSIBLE PLUG WITH A SERVICEABLE FUSIBLE PLUG P/N B13984-3 THAT IS NOT STAMPED WITH LOT PA-21 OR PA-22	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SYSTEM IS NOT INSTALLED										
FAA 2018-23-12 PARA (I)	NO PERSON SHAL INSTALL ON ANY AIRPLANE ANY FUSIBLE PLUG HAVING P/N B13984-3, STAMPED WITH LOT PA-21 OR PA-22	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SYSTEM IS NOT INSTALLED										
FAA 2018-23-12	APPLIANCE AD - EQUIPMENT / FURNISHINGS - INSPECTION AND REPLACEMENT OF ZODIAC AERO (ALSO KNOWN AS AIR CRUISERS COMPANY) EVACUATION SYSTEMS FUSIBLE PLUGS	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SYSTEM IS NOT INSTALLED										
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION	EKRK	MANDATORY	MTH 06-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - VEST PN INSTALLED IS NOT AFFECTED										
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA	EKRK	MANDATORY	MTH 06-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - VEST PN INSTALLED IS NOT AFFECTED										
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR		MANDATORY	MTH 06-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - VEST PN INSTALLED IS NOT AFFECTED										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INST										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INST										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INST										
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INST										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH 09-May-2025 HRS 1585:48 LDG 1092		-			N/A
MOC : NOT APPLICABLE										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH 09-May-2025 HRS 1585:48 LDG 1092		-			N/A
MOC : NOT APPLICABLE										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY	MTH 09-May-2025 HRS 1585:48 LDG 1092		-			N/A
MOC : NOT APPLICABLE										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY	MTH 09-May-2025 HRS 1585:48 LDG 1092		-			N/A
MOC : NOT APPLICABLE										
LBA D-2018-234	APPLIANCE AD - EQUIPMENT / FURNISHINGS - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REMOVAL FROM SERVICE			MANDATORY			-			
MOC :										
EASA 2021-0185 R02	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION/REPLACEMENT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - FIREX BOTTLE PN IS NOT INST										
FAA 2005-17-11	FIRE PROTECTION - INSTALL IDENTIFICATION SLEEVES ON THE WIRING FOR BOTH ENGINE FIRE EXTINGUISHER BOTTLES	EK RK		MANDATORY	DAYS 08-Sep-2023 HRS 1222:30 LDG 826		-			Complete
MOC : COMPLIED WITH - CW AT AIRCRAFT BUILD 2015 REFF CESSNA AD-SB STATEMENT										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2020-21-02 PARA (H) & (I)	DO AN INSPECTION TO DETERMINE THE PART NUMBER AND SERIAL NUMBER OF THE CARGO FIRE EXTINGUISHER HALON BOTTLES INSTALLED IN THE CARGO COMPARTMENT AND REPLACE WITH A SERVICEABLE PART AS REQUIRED									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - NO CARGO FIREX INSTALLED										
FAA 2020-21-02 PARA (J)	NO PERSON MAY INSTALL ON ANY AIRPLANE AN AFFECTED PART AS IDENTIFIED IN PARAGRAPH (G)(3) OF THIS AD UNLESS THAT PART HAS A CIRCLED LETTER "G" STAMPED AT A DISTANCE 8 OF APPROXIMATELY ONE INCH FROM THE LEFT EDGE OF THE PLACARD, INDICATING THAT THE CARGO FIRE EXTINGUISHER HALON BOTTLE HAS BEEN TESTED AND REFILLED									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - NO CARGO FIREX INSTALLED										
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT									
		UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - NO CARGO FIREX INSTALLED										
EASA 2019-0086 R01 PARA (1)	DEACTIVATE THE ATLAS AND MODIFY THE TACS TO RESTRICT THEIR MOVEMENT, AMEND THE APPLICABLE AFMS, AMEND ITEM 27-60-01 "ATLAS INOPERATIVE" OF THE MMEL SUPPLEMENT TO REMOVE THE 10 FLIGHT HOURS (FH) TIME LIMIT,INFORM ALL FLIGHT CREWS AND, THEREAFTER, OPERATE THE AEROPLANE ACCORDINGLY									
				MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - STC IS NOT INSTALLED ON AIRCRAFT										
EASA 2019-0086 R01 PARA (4)	MODIFY THE AEROPLANE IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 7 OF THE MODIFICATION SB.									
		EKRK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - STC IS NOT INSTALLED ON AIRCRAFT										
EASA 2019-0086 R01 PARA (5)	MODIFICATION OF AN AEROPLANE AS REQUIRED BY PARAGRAPH (4) OF THIS AD CONSTITUTES TERMINATING ACTION FOR THE DEACTIVATION, LIMITATIONS AND REPETITIVE PRE-FLIGHT INSPECTIONS AS REQUIRED BY THIS AD FOR THAT AEROPLANE.									
		EKRK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - STC IS NOT INSTALLED ON AIRCRAFT										
EASA 2019-0086 R01	FLIGHT CONTROLS – ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM – DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT – AMENDMENT									
				MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - STC IS NOT INSTALLED ON AIRCRAFT										
FAA 2004-14-20	FLIGHT CONTROLS - REMOVE AND REPLACE AN OLD TRIM PCB ASSEMBLY WITH A NEW DESIGN ASSEMBLY OR MODIFY AN OLD TRIM PCB ASSEMBLY TO THE NEW DESIGN									
				MANDATORY	MTH 14-Sep-2025 HRS 1651:47 LDG 1136		-			N/A
MOC : NOT APPLICABLE - AC SN										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06)									
			MANDATORY	MTH	10-Jul-2023		-			N/A
	KSAT			HRS	1222:12					
				LDG	825					
	MOC : NOT APPLICABLE - AD2019-08-13 DOES NOT APPLY DUE TO THE EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT.									
FAA 2020-24-06	FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM – DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT									
			MANDATORY	MTH	06-Sep-2023		-			N/A
	EKRK			HRS	1222:30					
				LDG	826					
	MOC : NOT APPLICABLE - AIRCRAFT DO NOT HAVE STC INSTALLED									
FAA 2024-15-09	GUST LOCK/DAMPER SYSTEM - INSTALL PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) AND REVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE									
			MANDATORY				-			N/A
	MOC : NOT APPLICABLE - NA DUE TO NO TAMARACK WINGLETS INSTALLED									
FAA 2022-03-15	FUEL QUANTITY INDICATOR - RESISTIVE FUEL PROBE INTERFACE - MODIFICATION									
	UNK		MANDATORY	MTH	08-Sep-2023		-			N/A
				HRS	1222:30					
				LDG	826					
	MOC : NOT APPLICABLE - AFFECTED STC IS NOT INSTALLED									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS									
			MANDATORY	MTH	02-Feb-2022		-			Complete
				HRS	907:24					
				LDG	671					
	MOC : COMPLIED WITH - BY INSTALLING A COPY OF THE AD FIGURE 1 PARAGRAPH GIN THE POH LIMITATIONS SECTION									
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)									
	KSAT		MANDATORY	MTH	10-Jul-2023		-			N/A
				HRS	1222:12					
				LDG	825					
	MOC : NOT APPLICABLE - AD2023-10-02 PARA (H) DOES NOT APPLY DUE TO THE CATEGORY OF THE AIRCRAFT. THE AIRCRAFT IS A NORMAL CATEGORY AIRCRAFT.									
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)									
	KSAT		MANDATORY	MTH	10-Jul-2023		-			N/A
				HRS	1222:12					
				LDG	825					
	MOC : NOT APPLICABLE - AD2023-10-02 PARA (I) DOES NOT APPLY DUE TO THE CATEGORY OF THE AIRCRAFT. THE AIRCRAFT IS A NORMAL CATEGORY AIRCRAFT.									
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION									
	KSAT		MANDATORY	MTH	10-Jul-2023		-			N/A
				HRS	1222:12					
				LDG	825					
	MOC : NOT APPLICABLE - AD2023-10-02 DOES NOT APPLY DUE TO THE CATEGORY OF THE AIRCRAFT. THE AIRCRAFT IS A NORMAL CATEGORY AIRCRAFT.									
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)									
	UNK		MANDATORY	MTH	08-Sep-2023		-			N/A
				HRS	1222:30					
				LDG	826					
	MOC : NOT APPLICABLE - EQUIPMENT IS NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT IS NOT INSTALLED										
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT IS NOT INSTALLED										
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT IS NOT INSTALLED										
EASA 2015-0093	APPLIANCE AD - NAVIGATION & ATTITUDE HEADING REFERENCE SYSTEM & MODIFICATION / REPLACEMENT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT IS NOT INSTALLED										
EASA 2018-0247 PARA (1)	INSPECT THE INSTALLATION OF THE AFFECTED PART ON THE AIRCRAFT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - TRIG SYST IS NOT INSTALLED										
EASA 2018-0247 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, IT IS DETERMINED THAT THE INSTALLATION IS NOT A CONVENTIONAL INSTALLATION, AS DEFINED IN THIS AD, BEFORE NEXT FLIGHT, REMOVE THE TRANSPONDER FROM SERVICE FOR IN-SHOP MODIFICATION.	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - TRIG SYST IS NOT INSTALLED										
EASA 2018-0247 PARA (3)	RETURNING AN AFFECTED PART, REMOVED FROM AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, TO TRIG AVIONICS FOR MODIFICATION, AND RE-INSTALLATION OF THAT MODIFIED TRANSPONDER ON THAT AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENTS OF THIS AD FOR THAT AIRCRAFT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - TRIG SYST IS NOT INSTALLED										
EASA 2018-0247 PARA (4)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT, UNLESS THE INSTALLATION IS CONVENTIONAL, AS DEFINED IN THIS AD	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - TRIG SYST IS NOT INSTALLED										
EASA 2018-0247	NAVIGATION - TRANSPONDERS - INSPECTION / MODIFICATION	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - TRIG SYST IS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
EASA 2019-0004	NAVIGATION - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS	UNK	MANDATORY	DAYS 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - GARMIN SYST IS INSTALLED										
EASA 2022-0024	APPLIANCE AD - ATA 34 - NAVIGATION - FLIGHT MANAGEMENT COMPUTER 2 / NAVIGATION MODULES - OPERATIONAL LIMITATIONS / AMENDMENT	UNK	MANDATORY	DAYS 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - EQUIPMENT IS NOT INSTALLED										
EASA 2025-0088	APPLIANCE AD - NAVIGATION - SATELLITE BASED AUGMENTATION SYSTEMS / GLOBAL POSITIONING SYSTEM RECEIVER - REPLACEMENT		MANDATORY	MTH 28-Mar-2025 HRS 1564:51 LDG 1076		-				N/A
MOC : NOT APPLICABLE - MODEL IS NOT INSTALLED										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - NOT INSTALLED										
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC, AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - MODEL IS NOT INSTALLED										
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - SYSTEM IS NOT INSTALLED										
FAA 2019-01-02 PARA (G)(1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - GARMIN SYST IS INSTALLED										
FAA 2019-01-02 PARA (G)(2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - GARMIN SYST IS INSTALLED										
FAA 2019-01-02	APPLIANCE AD - NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE	UNK	MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-				N/A
MOC : NOT APPLICABLE - GARMIN SYST IS INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK	EK RK		MANDATORY	DAYS 06-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH TRIG TRANSPONDER										
FAA 2019-13-03 PARA (H)	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK AS DEFINED IN THIS AD	EK RK		MANDATORY	MTH 06-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH TRIG TRANSPONDERS										
FAA 2019-13-03	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION	EK RK		MANDATORY	MTH 06-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH TRIG TRANSPONDER										
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - AIRCRAFT IS NOT EQUIPPED WITH PROLINE										
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED										
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SYSTEM NOT INSTALLED										
FAA 2021-05-17 PARA (G)(1) & (G) (2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAAAD 2019-12-09)	UNK		MANDATORY	DAYS 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SYST IS NOT INSTALLED										
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SYST IS NOT INSTALLED										
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - SYST IS NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITATIONS / SOFTWARE UPGRADE			MANDATORY	MTH 08-Sep-2023	-				N/A
		UNK			HRS 1222:30					
					LDG 826					
MOC : NOT APPLICABLE - SYST IS NOT INSTALLED										
FAA 2021-08-07	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100			MANDATORY	MTH 08-Sep-2023	-				N/A
PARA (G)(1)		UNK			HRS 1222:30					
					LDG 826					
MOC : NOT APPLICABLE - GPS MODEL IS NOT INST										
FAA 2021-08-07	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE			MANDATORY	MTH 08-Sep-2023	-				N/A
PARA (G)(2)		UNK			HRS 1222:30					
					LDG 826					
MOC : NOT APPLICABLE - GPS MODEL IS NOT INST										
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE			MANDATORY	MTH 08-Sep-2023	-				N/A
		UNK			HRS 1222:30					
					LDG 826					
MOC : NOT APPLICABLE - GPS MODEL IS NOT INST										
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE			MANDATORY	MTH 08-Sep-2023	-				N/A
		UNK			HRS 1222:30					
					LDG 826					
MOC : NOT APPLICABLE - REF CAMP SW VERSION 3.14.1 IS INSTALLED										
FAA 2015-23-09	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER			MANDATORY	MTH	-				N/A
PARA (G)		IND			DAYS 23-Feb-2016					
					HRS 35:48					
					LDG 29					
MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.										
FAA 2015-23-09	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).			MANDATORY	MTH	-				N/A
PARA (H.1)		IND			DAYS 23-Feb-2016					
MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.										
FAA 2015-23-09	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1			MANDATORY	MTH	-				N/A
PARA (H.2.I)		IND			DAYS 23-Feb-2016					
MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.										
FAA 2015-23-09	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."			MANDATORY	MTH	-				N/A
PARA (H.2.II)		IND			DAYS 23-Feb-2016					
MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.										
FAA 2015-23-09	REGULATOR REPLACEMENT			MANDATORY	MTH 23-Feb-2016	-				N/A
PARA (I)		IND								
MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	IND		MANDATORY	MTH 23-Feb-2016 HRS 35:48 LDG 29		-			N/A
MOC : NOT APPLICABLE - N/A BY BE AEROSPACE EQUIPMENT IS INSTALLED.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	ICT		MANDATORY	MTH 04-Aug-2016		-			N/A
MOC : NOT APPLICABLE - PART NUMBER NOT INSTALLED IN AIRCRAFT										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	ICT		MANDATORY	MTH 04-Aug-2016		-			N/A
MOC : NOT APPLICABLE - PART NUMBER NOT INSTALLED IN AIRCRAFT										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	ICT		MANDATORY	MTH 04-Aug-2016		-			N/A
MOC : NOT APPLICABLE - PART NUMBER NOT INSTALLED IN AIRCRAFT										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	ICT		MANDATORY	MTH 04-Aug-2016 HRS 87:48 LDG 73		-			N/A
MOC : NOT APPLICABLE - PART NUMBER NOT INSTALLED IN AIRCRAFT										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INSTALLED										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INSTALLED										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INSTALLED										
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	UNK		MANDATORY	MTH 08-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - REFF CAMP LIST EQUIP NOT INSTALLED										
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS	EKRK		MANDATORY	MTH 06-Sep-2023 HRS 1222:30 LDG 826		-			N/A
MOC : NOT APPLICABLE - BE MASKS IS INSTALLED IN AIRCRAFT										



CESCOM 10 - Aircraft Status Report

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1651:47	1136	14-Sep-2025	0:27
ENG 1	1651:47	1136	14-Sep-2025	0:27
ENG 2	1651:47	1136	14-Sep-2025	0:27
AIR COND	497:12		14-Sep-2025	0:54

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD									
	EKRK	MANDATORY	MTH	06-Sep-2023	-			N/A		
			HRS	1222:30						
			LDG	826						
MOC : NOT APPLICABLE - AIRCRAFT IS EQUIPED WITH BE MASKS										
FAA 2018-21-14	OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT									
	EKRK	MANDATORY	MTH	06-Sep-2023	-			N/A		
			HRS	1222:30						
			LDG	826						
MOC : NOT APPLICABLE - AIRCRAFT IS EQUIPED WITH BE MASKS										
FAA 2023-13-11 PARA (H)	INSPECT THE OXYGEN VALVE ASSEMBLIES AND OXYGEN CYLINDER AND VALVE ASSEMBLIES									
	EKRK	MANDATORY	DAYS	06-Sep-2023	-			N/A		
			HRS	1222:30						
			LDG	826						
MOC : NOT APPLICABLE - BOTTLE PN IS NOT INSTALED										
FAA 2023-13-11 PARA (J)	REPORT THE RESULTS OF THE INSPECTION AND RETURN PARTS (AS REQUIRED)									
	EKRK	MANDATORY	DAYS	06-Sep-2023	-			N/A		
			HRS	1222:30						
			LDG	826						
MOC : NOT APPLICABLE - BOTTLE PN IS NOT INSTALLED										
FAA 2023-13-11	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT									
	EKRK	MANDATORY	MTH	06-Sep-2023	-			N/A		
			HRS	1222:30						
			LDG	826						
MOC : NOT APPLICABLE - BOTTLE PN IS NOT INSTALLED										
FAA 2008-12-01	POWER PLANT - INSPECT FOR MISSING FIREWALL SEALANT BETWEEN THE AFT FIREWALL ASSEMBLY AND SEAL ASSEMBLY									
	EKRK	MANDATORY	DAYS	08-Sep-2023	-			Complete		
			HRS	1222:30						
			LDG	826						
MOC : COMPLIED WITH - CW AT AIRCRAFT BUILD 2015 REFF CESSNA AD-SB STATEMENT										