



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Program Types

AIRCRAFT	SERIAL/REGNO: 510-0348 / N681AN	MODEL: 510 - CITATION MUSTANG	MANUFACTURER: TEXTRON AVIATION INC.
-----------------	--	--------------------------------------	--

UTILIZATION: MODERATE OR SEVERE CORROSION ENVIRONMENT
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

ENGINE NO. 1	SERIAL/PART: PCE-LB0715 / 35C0510 -01	MODEL: PW615F-A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	--	------------------------	---

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

ENGINE NO. 2	SERIAL/PART: PCE-LB0714 / 35C0510 -01	MODEL: PW615F-A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	--	------------------------	---

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

These program types are defined in the OEM manual and can differ from your other settings. These selections will impact the active OEM interval defined on the aircraft status.

As an example,

1. Your aircraft might be EASA registered but you choose to follow the OEM recommended interval for Transport Canada. In that case the operating regulation would be TCCA and can be set to EASA if OEM did not specify intervals for EASA operation.
2. Region of Operation is driven from the OEM manual and the selection between Airframe, Engine and APU can differ since the OEM manual can have requirements dependent on different regions of operation.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (XPONDER 91.413)	KMCO		MTH 05-Jan-2025 HRS 1895.2 LDG 1467		24		31-Jan-2027	6 m 8 d
0534NXIV	VISUAL INSPECTION G1000 NXI EQUIPMENT/ACCESSORIES/WIRING HARNESS	KSAT		MTH 19-Mar-2019 HRS 1265.6 LDG 1045		1350		2615.6	538
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK					A/R			
055002	ACCOMPLISH OVERSPEED CHECK					A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK					A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK					A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK					A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK					A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK					A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK					A/R			
5-12-01	INSPECTION DOCUMENT 01	KMCO		MTH 05-Apr-2023 HRS 1730.8 LDG 1353		450		2180.8	103.2
5-12-02	INSPECTION DOCUMENT 02	KMCO		MTH 05-Apr-2023 HRS 1730.8 LDG 1353		900		2630.8	553.2
5-12-03	INSPECTION DOCUMENT 03	KMCO		MTH 07-Jun-2019 HRS 1338.8 LDG 1085		1350		2688.8	611.2
5-12-04	INSPECTION DOCUMENT 04	KMCO		MTH 05-Apr-2023 HRS 1730.8 LDG 1353		1800		3530.8	1453.2
5-12-05	INSPECTION DOCUMENT 05			MTH 23-Dec-2010 HRS 0		3150		3150	1072.4
5-12-06	INSPECTION DOCUMENT 06	KHII		MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12		30-Apr-2027	9 m 7 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK)	KHII	C352TS H-35472072	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12		30-Apr-2027	9 m 7 d
5-12-07	INSPECTION DOCUMENT 07	KMCO		MTH 06-Apr-2025 HRS 1918 LDG 1483		24		30-Apr-2027	9 m 7 d
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMCO		MTH 05-Jan-2025 HRS 1895.2 LDG 1467		60			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262004	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)	KMCO		30401102-2 77951B1	MTH 05-Jan-2025 HRS 1895.2 LDG 1467		60		30-Nov-2029	40 m 7 d
Hydro Check Date: 05-Nov-2024										
5-12-11	INSPECTION DOCUMENT 11	KMCO			MTH 05-Apr-2023 HRS 1730.8 LDG 1353		72		30-Apr-2029	33 m 7 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)	KMCO		C352TS H-35472072	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		72		30-Apr-2029	33 m 7 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 23-Dec-2010		144			
B262101	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)	KMCO		C352TS H-35472072	MTH 01-Jan-2023		144		31-Jan-2035	102 m 8 d
Hydro Check Date: 01-Jan-2023										
5-12-13	INSPECTION DOCUMENT 13	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12 450		30-Apr-2027 2473.9	9 m 7 d 396.3
5-12-14	INSPECTION DOCUMENT 14	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12 900		30-Apr-2027 2923.9	9 m 7 d 846.3
5-12-15	INSPECTION DOCUMENT 15	KMCO			MTH 06-Apr-2025 HRS 1918 LDG 1483		24 1350		30-Apr-2027 3268	9 m 7 d 1190.4
5-12-16	INSPECTION DOCUMENT 16	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		36 1350		30-Apr-2029 3373.9	33 m 7 d 1296.3
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK 29-10-00-720	KHII		HM50C-3 408B	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		36 1350		30-Apr-2029 3373.9	33 m 7 d 1296.3
5-12-17	INSPECTION DOCUMENT 17	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		36 1800		30-Apr-2029 3823.9	33 m 7 d 1746.3
5-12-18	INSPECTION DOCUMENT 18	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		36 2250		30-Apr-2029 4273.9	33 m 7 d 2196.3
5-12-20	INSPECTION DOCUMENT 20	KMCO			MTH 05-Apr-2023 HRS 1730.8 LDG 1353		48 2700		30-Apr-2027 4430.8	9 m 7 d 2353.2
5-12-21	INSPECTION DOCUMENT 21	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12		30-Apr-2027	9 m 7 d
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMCO			MTH 05-Jan-2025 HRS 1895.2 LDG 1467		24			
B341001 AIRSPEED	CALIBRATION TEST INDICATOR 14 CFR PART 91.411	KMCO		261440-1143 295495A	MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
Calibration Date: 23-Dec-2024										
B341001 NO. 1	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KMCO		011-01110-00 43806221	MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
Calibration Date: 23-Dec-2024										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KMCO		011-01110-00 43806227	MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
Calibration Date: 23-Dec-2024										
B341001 STANDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411	KMCO		162350-1161 179985C	MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
Calibration Date: 23-Dec-2024										
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)	KMCO			MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
B345000 LEFT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KMCO		011-00779-21 84810087	MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
Calibration Date: 23-Dec-2024										
B345000 RIGHT	G1000 NXI UPGRADE STC SA01896WI (XPNDR 91.413)	KMCO		011-03303-00 3EH023527	MTH 23-Dec-2024		24		31-Dec-2026	5 m 8 d
Calibration Date: 23-Dec-2024										
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KMCO		3-1640 0249	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)	KMCO		3-1642 0154	MTH 27-Dec-2023 HRS 1803.5 LDG 1404		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)	KMCO		3-1640 0354	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		A/R			
5-12-30	INSPECTION DOCUMENT 30	KMCO			MTH 05-Apr-2023 HRS 1730.8 LDG 1353		48 1800		30-Apr-2027 3530.8	9 m 7 d 1453.2
5-12-31	INSPECTION DOCUMENT 31	KMCO			MTH 05-Apr-2023 HRS 1730.8 LDG 1353		450		2180.8	103.2
5-12-32	INSPECTION DOCUMENT 32	KMCO			MTH 05-Apr-2023 HRS 1730.8 LDG 1353		72 1800		30-Apr-2029 3153	33 m 7 d 1566
5-12-35	INSPECTION DOCUMENT 35	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		6		31-Oct-2026	3 m 8 d
5-12-37	INSPECTION DOCUMENT 37				MTH 23-Dec-2010 HRS 0		7200		8096.4	6018.8
5-12-38	INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		6			
B243000	CONCORDE (RG-390E) LEAD-ACID BATTERY FUNCTIONALCHECK (CAPACITY CHECK)	KHII		RG-390E 41390274	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		6		31-Oct-2026	3 m 8 d
5-12-MA	INSPECTION DOCUMENT MA	KMCO			MTH 30-Jul-2025 HRS 1945.1 LDG 1500		500		2445.1	367.5

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MB	INSPECTION DOCUMENT MB	KMCO		MTH 14-Jul-2024 HRS 1847.1 LDG 1433			950		2797.1	719.5
5-12-MC	INSPECTION DOCUMENT MC			MTH 23-Dec-2010 HRS 0			4000		4000	1922.4
5-12-MD	INSPECTION DOCUMENT MD	KHII		MTH 20-Apr-2026 HRS 2023.9 LDG 1554			12		30-Apr-2027	9 m 7 d
5-12-ME	INSPECTION DOCUMENT ME	KHII		MTH 20-Apr-2026 HRS 2023.9 LDG 1554			36 1400		30-Apr-2029 3423.9	33 m 7 d 1346.3
5-12-MF	INSPECTION DOCUMENT MF			MTH 23-Dec-2010 HRS 0			12000		12000	9922.4
A551001	INSPECT/SURFACE EDDY CURRENT HORIZONTAL STABILIZER FRONT SPAR UPPER FLANGE AND SPLICE STRAPS (BL 0.00 - BL 6.00)			MTH 23-Dec-2010 HRS 0			12000		12000	9922.4
5-12-MG	INSPECTION DOCUMENT MG			MTH 23-Dec-2010 HRS 0			5000		5000	2922.4
5-12-MH	INSPECTION DOCUMENT MH			MTH 23-Dec-2010 HRS 0			8250		8250	6172.4
5-12-MI	INSPECTION DOCUMENT MI			MTH 23-Dec-2010 HRS 0			12000		12000	9922.4
5-12-MJ	INSPECTION DOCUMENT MJ			MTH 23-Dec-2010 HRS 0			10600		10600	8522.4
5-12-MK	INSPECTION DOCUMENT MK			MTH 23-Dec-2010 HRS 0			10400		10400	8322.4
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE	GSO		MTH 17-Jul-2016 HRS 800.9 LDG 707			A/R			
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS 23-Dec-2010			A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH			DAYS 23-Dec-2010			A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS 23-Dec-2010			A/R			
0521009	ENVIRO SYSTEMS 500 HOUR INSPECTION	KMCO		MTH 07-Jan-2020 HRS 1449.8 LDG 1155 ACH 479.4			500		979.4	330.9
0521009A	ENVIRO SYSTEMS 12 MONTH INSPECTION	KHII		MTH 20-Apr-2026 HRS 2023.9 LDG 1554			12		30-Apr-2027	9 m 7 d
262003A LEFT	REPLACE FIRE EXT CARTRIDGE		13083-5 11/23	MTH 05-Jan-2025 HRS 1895.2 LDG 1467			72	14	30-Nov-2029	40 m 7 d
262003A RIGHT	REPLACE FIRE EXT CARTRIDGE		13083-5 11/23	MTH 05-Jan-2025 HRS 1895.2 LDG 1467			72	14	30-Nov-2029	40 m 7 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)			MTH 23-Dec-2010			A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)			MTH 23-Dec-2010			A/R			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
32-30-40-960	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KHII		9912478-3 11590	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		36		31-Mar-2029	32 m 8 d
Hydro Check Date: 31-Mar-2026										
32-40-00-960	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KHII		40005399-1 7582	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		36		31-Mar-2029	32 m 8 d
Hydro Check Date: 31-Mar-2026										
0534NXISU	- GARMIN NXI SOFTWARE UPGRADE VERSION 413.46	KMCO			MTH 09-Jan-2026 HRS 1984.8 LDG 1527		-			
35-00-00-960	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST	KMCO		4441073-040 0660-164	MTH 28-Feb-2024 HRS 1847.1 LDG 1433		60		28-Feb-2029	31 m 5 d
Hydro Check Date: 28-Feb-2024										
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12 450		30-Apr-2027 (2473.9)2473.9	9 m 7 d 396.3
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KHII			MTH 20-Apr-2026 HRS 2023.9 LDG 1554		12 450		30-Apr-2027 (2473.9)2473.9	9 m 7 d 396.3
710010 E1	COMPRESSOR DESALINATION WASH	KMCO			MTH 06-Apr-2025 HRS 1918 LDG 1483		A/R			
710010 E2	COMPRESSOR DESALINATION WASH	KMCO			MTH 06-Apr-2025 HRS 1918 LDG 1483		A/R			
710010A E1	DESALINATION WASH / RINSE	KMCO			MTH 09-Jan-2026 HRS 1984.8 LDG 1527		A/R			
710010A E2	DESALINATION WASH / RINSE	KMCO			MTH 09-Jan-2026 HRS 1984.8 LDG 1527		A/R			
72-00-00-620-804- 01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 23-Dec-2010		A/R			
72-00-00-620-804- 01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 23-Dec-2010		A/R			
72-00-00-620-804- 02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 23-Dec-2010		A/R			
72-00-00-620-804- 02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 23-Dec-2010		A/R			
72-00-00-620-804- 03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 23-Dec-2010		A/R			
72-00-00-620-804- 03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 23-Dec-2010		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-620-805-01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-620-805-01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-620-805-02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-620-805-02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-620-806-01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-620-806-01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-620-806-02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	23-Dec-2010		A/R			
72-00-00-620-806-02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	23-Dec-2010		A/R			
72-00-00-630-804-01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	23-Dec-2010		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	23-Dec-2010		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	23-Dec-2010		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	23-Dec-2010		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	23-Dec-2010		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	23-Dec-2010		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY		MTH	23-Dec-2010		A/R			
720000 E1	PERFORM ENGINE OVERHAUL		MTH	23-Dec-2010					
720000 E2	PERFORM ENGINE OVERHAUL		MTH	23-Dec-2010		3500		(3500)3500	1422.4
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION		MTH	23-Dec-2010		3500		(3500)3500	1422.4
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION	UNK	MTH	30-Dec-2022					
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION	UNK	HRS	1730.8		1750		(3480.8)3480.8	1403.2
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION		MTH	13-Mar-2023					
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION	UNK	MTH	13-Mar-2023					
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION	UNK	HRS	1730.8		1750		(3480.8)3480.8	1403.2
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION	UNK	LDG	1353					



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
720003 E1	INSPECT LOW UTILIZATION ENGINE	KMCO		MTH HRS LDG	06-Apr-2025 1918 1483		24		30-Apr-2027	9 m 7 d
720003 E2	INSPECT LOW UTILIZATION ENGINE	KMCO		MTH HRS LDG	06-Apr-2025 1918 1483		24		30-Apr-2027	9 m 7 d
721030 E1	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS			1750		(3480.8)3480.8	1403.2
721030 E2	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER			MTH HRS			1750		(3480.8)3480.8	1403.2
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	UNK		MTH HRS	30-Dec-2022 1730.8		1750		(3480.8)3480.8	1403.2
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	UNK		MTH HRS LDG	13-Mar-2023 1730.8 1353		1750		(3480.8)3480.8	1403.2
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT	KHII		MTH HRS LDG	20-Apr-2026 2023.9 1554		12 900		30-Apr-2027 (2923.9)2923.9	9 m 7 d 846.3
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT	KHII		MTH HRS LDG	20-Apr-2026 2023.9 1554		12 900		30-Apr-2027 (2923.9)2923.9	9 m 7 d 846.3
731055 E1	REPLACE FUEL MANIFOLD	UNK		35C6160-01 DEAAAA78506 MTH HRS	30-Dec-2022 1730.8		1750		(3480.8)3480.8	1403.2
731055 E2	REPLACE FUEL MANIFOLD	UNK		35C6160-01 DEAAAA78507 MTH HRS LDG	13-Mar-2023 1730.8 1353		1750		(3480.8)3480.8	1403.2
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH	UNK		PN SN-UNKNOWN MTH HRS	30-Dec-2022 1730.8		1750		(3480.8)3480.8	1403.2
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH	UNK		PN SN-UNKNOWN MTH HRS LDG	13-Mar-2023 1730.8 1353		1750		(3480.8)3480.8	1403.2
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY	UNK		PN SN-UNKNOWN MTH HRS	30-Dec-2022 1730.8		1750		(3480.8)3480.8	1403.2
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY	UNK		PN SN-UNKNOWN MTH HRS LDG	13-Mar-2023 1730.8 1353		1750		(3480.8)3480.8	1403.2
790015 E1	REPLACE OIL FILTER ELEMENT	UNK		MTH HRS	30-Dec-2022 1730.8		900		(2630.8)2630.8	553.2
790015 E2	REPLACE OIL FILTER ELEMENT	KMCO		MTH HRS LDG	05-Apr-2023 1730.8 1353		900		(2630.8)2630.8	553.2
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KHII		PN SN-UNKNOWN MTH HRS LDG	20-Apr-2026 2023.9 1554		6 100		31-Oct-2026 (2123.9)2123.9	3 m 8 d 46.3

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY.			0113-12 1900	MTH 23-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
213001	KAPS II CONTROLLER	KMCO		9912661-12 1183A	MTH 07-Apr-2023 HRS 1730.8 LDG 1353		O/C	0 0 0		
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7			52812-102 1439	MTH 23-Dec-2010		O/C	0		
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7			52812-102 1445	MTH 23-Dec-2010		O/C	0		
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14			1133610-4 452	MTH 23-Dec-2010		O/C	0		
215002	CONDENSOR ASSEMBLY 9912660-3			1134620-5 423	MTH 23-Dec-2010		O/C	0		
215003	RECEIVER DRYER ASSY	KMCO		9912660-18 N/A	MTH 07-Jan-2020 HRS 1449.8 LDG 1155		O/C			
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7			1133300-1 823	MTH 23-Dec-2010		O/C	0		
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7			1133300-1 824	MTH 23-Dec-2010		O/C	0		
215005	VANE AXIAL BLOWER ASSY.			PN SN-UNKNOWN	MTH 23-Dec-2010		O/C	0		
215005A	COMPRESSOR FAN	KMCO		K1134608-3 NSN	MTH 07-Jan-2020 HRS 1449.8 LDG 1155 ACH 479.4		O/C	0 0 0 0		
215006A	COMPRESSOR DRIVE BELT	KMCO		5MR535-25 NSN	MTH 27-Apr-2023 HRS 1737.9 LDG 1359		O/C	0 0 0		
215007A	AIRCONDITIONER BINARY SWITCH	KMCO		1250232-10 217	MTH 07-Jan-2020 HRS 1449.8 LDG 1155		O/C	0 0 0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD	KMCO		1251171-6 NSN	MTH 07-Jan-2020 HRS 1449.8 LDG 1155 ACH 479.4			0 0 0 0	1279.4	630.9
221001 AILERON	GSA 80 TORQUE SERVO			011-00877-00 66306891	MTH 23-Dec-2010		O/C	0		
221001 RUDDER	GSA 80 TORQUE SERVO	SWF		011-00877-00 66306163	MTH 06-Nov-2011 HRS 189.7 LDG 148		O/C			
221002 ELEVATOR	GSA 81 TORQUE SERVO	KPHF		011-00878-10 71308305	MTH 24-Aug-2022 HRS 1707.6		O/C			
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO	KSAT		011-00878-10 71305122	MTH 14-Jun-2018 HRS 1130.6 LDG 957		O/C			
221003 AILERON	GSM 85A SERVO MOUNT	GSO		011-01436-A2 10905159	MTH 03-Jan-2014 HRS 512.7 LDG 441		O/C			
221003 ELEVATOR	GSM 85A SERVO MOUNT			011-01436-A0 11205324	MTH 23-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT			011-01436-A1 5058	MTH 23-Dec-2010		O/C	0		
221003 RUDDER	GSM 85 SERVO MOUNT	SWF		011-01436-A3 11005038	MTH 16-Dec-2011 HRS 211.6 LDG 166		O/C	6		
221004	GMC 710 AFCS CONTROLLER			011-01020-10 22005757	MTH 23-Dec-2010		O/C	0		
231002 NO. 1	GMA 1347D AUDIO PANEL	KSAT		011-03568-20 4QF105212	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		O/C	0 0 0		
231002 NO. 2	GMA 1347D AUDIO PANEL	KSAT		011-03568-20 4QF105205	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		O/C	0 0 0		
231003 NO. 1	VHF COMM ANTENNA			VHF10-829 0850	MTH 23-Dec-2010		O/C	0		
231003 NO. 2	VHF COMM ANTENNA			VHF10-829 0874	MTH 23-Dec-2010		O/C	0		
231011	SAT PHONE ANTENNA			S67-1575-109 9129	MTH 23-Dec-2010		O/C	0		
231101	HIGH FREQUENCY CONTROLLER			S3100-470 NSN	MTH 23-Dec-2010		O/C	0		
231102	HIGH FREQUENCY RECEIVER/ EXCITER			S3100-449 064-01073-0102 NSN	MTH 23-Dec-2010		O/C	0		
231103	HIGH FREQUENCY ANTENNA			16390 NSN	MTH 23-Dec-2010		O/C	0		
231104	HIGH FREQUENCY POWER AMPLIFIER			064-01072-0101 NSN	MTH 23-Dec-2010		O/C	0		
243001 LEFT	DIGITAL GCU	GAI		51525-001F 9912682-1 OR 9912682-3 97386	MTH 04-Aug-2011 HRS 105.6 LDG 79		O/C			
243001 RIGHT	DIGITAL GCU	OXB		51525-001F 9912682-3 OR 9912682-3 Y1633	MTH 20-Jul-2011 HRS 100.9 LDG 73		O/C			
243002	EMER INST BATTERY	KMCO		CBS24 00928	MTH 29-Jul-2024 HRS 1852 LDG 1437		O/C			
243007	MAIN SHIP BATTERY	KMCO		RG-390E 41390274	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		O/C	0 0 0		
243015	RELAY DISCONNECT BATTERY			A-931F S3155-1 CR-69547	MTH 23-Dec-2010		O/C	0		
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	KSAT		7018920-5 1223	MTH 06-Dec-2017 HRS 1046.5 LDG 892 ACH 365.8		O/C	0 0 0		
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	KMCO		7018920-8 36217922-1	MTH 28-Jan-2026 HRS 1984.8 LDG 1527		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0348**
 Unit: **0348** Reg No: **N681AN**
 Airworthiness: **23-Dec-2010**
 Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245003	FLAP CONTROL MODULE			7018916-9 0522	MTH 23-Dec-2010		O/C	0		
245005 LEFT	ICE PROTECTION CONTROL			7018917-9 0462	MTH 23-Dec-2010		O/C	0		
245005 RIGHT	ICE PROTECTION CONTROL			7018918-13 0486	MTH 23-Dec-2010		O/C	0		
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL			7018919-13 0706	MTH 23-Dec-2010		O/C	0		
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL			7018919-13 0709	MTH 23-Dec-2010		O/C	0		
245008	DOOR MONITOR-			7018921-8 0427	MTH 23-Dec-2010		O/C	0		
245009	LANDING GEAR MONITOR-			7018923-12 0426	MTH 23-Dec-2010		O/C	0		
245010 LEFT	START CONTROL	GSO		7018924-12 0290	MTH 07-Dec-2014 HRS 620.2 LDG 546		O/C	0 0 0		
245010 RIGHT	START CONTROL	OXB		7018924-12 0295	MTH 20-Jul-2011 HRS 100.9 LDG 73		O/C	0 0 0		
245011	FLAP MONITOR-			7018925-11 0453	MTH 23-Dec-2010		O/C	0		
245013	DIAGNOSTIC UNIT			7018927-7 0487	MTH 23-Dec-2010		O/C	0		
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3			85-230-0 0943002M2	MTH 23-Dec-2010		O/C	0		
245015	MASTER INTERIOR SSR UNIT UZ100			10747P03E25 10047266	MTH 23-Dec-2010		O/C	0		
245016 RIGHT	AVN BUS #1 SENSOR UZ102			10747P03E25 10047270	MTH 23-Dec-2010		O/C	0		
245017 LEFT	AVN SENSOR	GSO		10747P03E25 07092566	MTH 03-Jan-2014 HRS 512.7 LDG 441		O/C	0 0 0		
245018 RIGHT	AVN BUS #2 SENSOR UZ104			10747P03E25 10047287	MTH 23-Dec-2010		O/C	0		
245019 LEFT	IGN #1 SENSOR UZ105			10747P03E10 10057441	MTH 23-Dec-2010		O/C	0		
245019 RIGHT	IGN #1 SENSOR UZ106			10747P03E10 10057451	MTH 23-Dec-2010		O/C	0		
245020 LEFT	IGN #2 SENSOR UZ107			10747P03E10 10057442	MTH 23-Dec-2010		O/C	0		
245020 RIGHT	IGN #2 SENSOR UZ108			10747P03E10 10057440	MTH 23-Dec-2010		O/C	0		
245021	COCKPIT FAN SENSOR UZ109			10747P03E25 10057384	MTH 23-Dec-2010		O/C	0		
245022	CABIN FAN SENSOR UZ110			10747P03E25 10047276	MTH 23-Dec-2010		O/C	0		
245023 LEFT	LH BOOST PUMP SENSOR UZ114			10747P03E25 10047265	MTH 23-Dec-2010		O/C	0		
245023 RIGHT	RH BOOST PUMP SENSOR UZ111			10747P03E25 10057344	MTH 23-Dec-2010		O/C	0		
245024	CONDENSER FAN SENSOR UZ112			10747P03E25 10047260	MTH 23-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245025	DC-DC CONVERTER UZ116			10747P03E10 10057448	MTH 23-Dec-2010		O/C	0		
245026	AVN EMERG SENSOR UZ200			10747P03E25 10047277	MTH 23-Dec-2010		O/C	0		
245201 LEFT	CABIN ALTITUDE MODULE			7018119-1 784	MTH 23-Dec-2010		O/C	0		
245201 RIGHT	CABIN ALTITUDE MODULE			7018119-1 786	MTH 23-Dec-2010		O/C	0		
246030 RIGHT	MULTI FUNCTION DISPLAY HND			7018929-1 0302	MTH 12-Sep-2011 HRS 137.3 LDG 97		O/C	0 0 0		
251001	GLARESHIELD ASSEMBLY			4319027-17 SN-UNKNOWN	MTH 23-Dec-2010		O/C	0		
256001 NO. 1	LIFE VEST	KMCO		P01074-101 25011890063	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		60	6 0 0	31-Jan-2030	42 m 8 d
256001 NO. 2	LIFE VEST	KMCO		P01074-101 25011890042	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		60	6 0 0	31-Jan-2030	42 m 8 d
256001 NO. 3	LIFE VEST	KMCO		P01074-101 25011890041	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		60	6 0 0	31-Jan-2030	42 m 8 d
256001 NO. 4	LIFE VEST	KMCO		P01074-101 25011890046	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		60	6 0 0	31-Jan-2030	42 m 8 d
256001 NO. 5	LIFE VEST	KMCO		P01074-101 25011890043	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		60	6 0 0	31-Jan-2030	42 m 8 d
256001 NO. 6	LIFE VEST	KMCO		P01074-101 25011890047	MTH 30-Jul-2025 HRS 1945.1 LDG 1500		60	0 0 0	31-Jul-2030	48 m 8 d
256002	ELT BATTERY	KMCO		452-0133 1009768-024	MTH 14-Jul-2024 HRS 1847.1 LDG 1433	1	60	0 0 0	31-Aug-2029	37 m 8 d
256004	ELT ANTENNA			110-340 310589	MTH 23-Dec-2010		O/C	0		
256004A	C406N ELT PROGRAMMING ADAPTER KGSO			453-5068 352248-060	MTH 24-Apr-2020 HRS 1488 LDG 1186		O/C			
256007	ELT PROCESSOR C406N			453-5060 09416	MTH 23-Dec-2010		O/C	0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 211189	MTH 23-Dec-2010		O/C	0		
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 211077	MTH 23-Dec-2010		O/C	0		
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	KMCO		30401102-2 77951B1	MTH 05-Jan-2025 HRS 1895.2 LDG 1467		O/C	0 0 0		
262003 LEFT	FIRE EXT CARTRIDGE	KMCO		13083-5 11/23	MTH 05-Jan-2025 HRS 1895.2 LDG 1467		72	0 0 0	30-Nov-2029	40 m 7 d

Manufacture Date: 30-Nov-2023



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262003 RIGHT	FIRE EXT CARTRIDGE	KMCO		13083-5 11/23	MTH 05-Jan-2025 HRS 1895.2 LDG 1467		72	0 0 0	30-Nov-2029	40 m 7 d
Manufacture Date: 30-Nov-2023										
262004	PORTABLE FIRE EXTINGUISHER	KMCO		C352TS H-35472072	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C	0 0 0		
271001 LEFT	CONTROL WHEEL ASSY			4319065-1 1837	MTH 23-Dec-2010		O/C	0		
271001 RIGHT	CONTROL WHEEL ASSY			4319065-2 1774	MTH 23-Dec-2010		O/C	0		
271002 --	ELEVATOR TRIM TAB ACTUATOR			PN SN-UNKNOWN	MTH 23-Dec-2010		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR			SYLC-53361-1 551	MTH 23-Dec-2010		O/C	0		
273002	AILERON TRIM ACTUATOR			SYLC-53361-1 375	MTH 23-Dec-2010		O/C	0		
275001	FLAP PDU (POWER DRIVE UNIT) UNIT			MP50Y-1 376AB	MTH 23-Dec-2010		O/C	0		
275002 LEFT	FLAP ACTUATOR			41013930-105 0442	MTH 23-Dec-2010		O/C	0		
275002 RIGHT	FLAP ACTUATOR			41013930-106 0804	MTH 23-Dec-2010		O/C	0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY	KMCO		9914344-59 0966	MTH 22-Jul-2020 HRS 1510.6 LDG 1202		O/C	0 0 0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY	SWF		140527-5900 0182	MTH 16-Nov-2012 HRS 344.7 LDG 287		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR			2R5211A 0006	MTH 23-Dec-2010		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR			2R5212A 0114	MTH 23-Dec-2010		O/C	0		
282001 LEFT	PRIMARY EJECTOR			LR45300A C1924	MTH 23-Dec-2010		O/C	0		
282001 RIGHT	PRIMARY EJECTOR			LR45300A C1988	MTH 23-Dec-2010		O/C	0		
282002	TRANSFER VALVE			ZSV57 10-0521381	MTH 23-Dec-2010		O/C	0		
282003 LEFT	DC FUEL PUMP			1C7-23 5BF146	MTH 23-Dec-2010		O/C	0		
282003 RIGHT	DC FUEL PUMP	GSO		1C7-23 1BE28	MTH 17-Jul-2016 HRS 800.9 LDG 707 ACH 130.1		O/C			
282004 L1	SCAVENGE EJECTOR			RG45310 C2417	MTH 23-Dec-2010		O/C	0		
282004 L2	SCAVENGE EJECTOR			RG45310 C2418	MTH 23-Dec-2010		O/C	0		
282004 R1	SCAVENGE EJECTOR			RG45310 C2386	MTH 23-Dec-2010		O/C	0		
282004 R2	SCAVENGE EJECTOR			RG45310 C2363	MTH 23-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282005 LEFT	VALVE-FUEL MOTOR 9912014-3			AV24B1507 232752	MTH 23-Dec-2010		O/C	0		
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3			AV24B1507 232745	MTH 23-Dec-2010		O/C	0		
284001 L1	FUEL PROBE 9912664-1			020-251-001 0948	MTH 23-Dec-2010		O/C	0		
284001 L2	FUEL PROBE 9912664-2			020-251-002 0950	MTH 23-Dec-2010		O/C	0		
284001 L3	FUEL PROBE 9912664-3			020-251-003 0950	MTH 23-Dec-2010		O/C	0		
284001 L4	FUEL PROBE 9912664-4			020-251-004 0943	MTH 23-Dec-2010		O/C	0		
284001 L5	FUEL PROBE 9912664-5			020-251-005 0943	MTH 23-Dec-2010		O/C	0		
284001 R1	FUEL PROBE 9912664-1			020-251-001 0947	MTH 23-Dec-2010		O/C	0		
284001 R2	FUEL PROBE 9912664-2			020-251-002 0953	MTH 23-Dec-2010		O/C	0		
284001 R3	FUEL PROBE 9912664-3			020-251-003 0951	MTH 23-Dec-2010		O/C	0		
284001 R4	FUEL PROBE 9912664-4			020-251-004 0942	MTH 23-Dec-2010		O/C	0		
284001 R5	FUEL PROBE 9912664-5			020-251-005 0942	MTH 23-Dec-2010		O/C	0		
284002	SIGNAL CONDITIONER 9912664-6			367-350-001 1361	MTH 23-Dec-2010		O/C	0		
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2			HM50C-3 408B	MTH 23-Dec-2010		O/C	0		
291002	HYDRAULIC CHECK VALVE			4001-20 5671A	MTH 23-Dec-2010		O/C	0		
291003	HYDRAULIC SYS PRESSURE GAUGE			19940933-1 032323	MTH 23-Dec-2010		O/C	0		
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4			80665 366	MTH 23-Dec-2010		O/C	0		
291007	HYDRAULIC MANIFOLD 9912657-14			8257-3 355	MTH 23-Dec-2010		O/C	0		
291008	HYDRAULIC RELIEF VALVE 9912657-2			2672 352	MTH 23-Dec-2010		O/C	0		
291009	BRAKE PRESSURE SWITCH 9912657-3	KMCO		80664 610	MTH 06-Apr-2025 HRS 1918 LDG 1483		O/C	0 0 0		
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5			4251 358	MTH 23-Dec-2010		O/C	0		
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7			4252 353	MTH 23-Dec-2010		O/C	0		
291011	HYDRAULIC DUMP VALVE 9912657-15			9625-1 358	MTH 23-Dec-2010		O/C	0		
291012	HYDRAULIC RESERVOIR ASSEMBLY KMCO			7017005-28 NSN	MTH 07-Jan-2020 HRS 1449.8 LDG 1155		O/C			
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2			7550-2 0788	MTH 23-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301001 LEFT	WING DE-ICE BOOT 9912662-17	GSO		P35-4D5317-17 NDY2950	MTH 17-Jul-2016 HRS 800.9 LDG 707 ACH 130.1		O/C	0 0 0		
301001 RIGHT	WING DE-ICE BOOT	KMCO		9912662-18 NFU3730	MTH 03-Aug-2021 HRS 1598.5 LDG 1266		O/C	0 0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT	KMCO		9912662-3 NGH6720	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C	0 0 0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT	KMCO		9912662-4 NFT9270	MTH 03-Aug-2021 HRS 1598.5 LDG 1266		O/C	0 0 0		
301004 L1	DE-ICE PRESSURE SWITCH			1106P55-1 8520A	MTH 23-Dec-2010		O/C	0		
301004 L2	DE-ICE PRESSURE SWITCH			1106P55-1 8522A	MTH 23-Dec-2010		O/C	0		
301004 L3	DE-ICE PRESSURE SWITCH			1106P55-1 8567A	MTH 23-Dec-2010		O/C	0		
301004 R1	DE-ICE PRESSURE SWITCH			1106P55-1 8535A	MTH 23-Dec-2010		O/C	0		
301004 R2	DE-ICE PRESSURE SWITCH			1106P55-1 8555A	MTH 23-Dec-2010		O/C	0		
301004 R3	DE-ICE PRESSURE SWITCH			1106P55-1 8519A	MTH 23-Dec-2010		O/C	0		
301004	VERT DE-ICE BOOT 9912662-13	KMCO		P29S4D5317-13 NGL6370	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C	0 0 0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY			5285-00-3 2560	MTH 23-Dec-2010		O/C	0		
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY			5285-00-3 2541	MTH 23-Dec-2010		O/C	0		
302002 LEFT	TEMP SWITCH			1173T0759 6062	MTH 23-Dec-2010		O/C	0		
302002 RIGHT	TEMP SWITCH	KMCO		1173T0759 9791	MTH 05-Jan-2025 HRS 1895.2 LDG 1467		O/C	0 0 0		
304001 L1	DE-ICE VALVE			3D2353-06 N101044	MTH 23-Dec-2010		O/C	0		
304001 L2	DE-ICE VALVE			3D2353-06 N101049	MTH 23-Dec-2010		O/C	0		
304002 LEFT	WINDSHIELD CONTROLLER	SWF		7018108-26 0107A	MTH 13-Jul-2012 HRS 319.6 LDG 250		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER	SWF		7018108-26 0199	MTH 13-Jul-2012 HRS 319.6 LDG 250		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY			7041020-5 346	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY			7041020-6 347	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
321001	NOSE LANDING GEAR TRUNNION			7042020-1 339	MTH 23-Dec-2010		O/C	0		
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY OXB			7041050-5 35	MTH 20-Jul-2011 HRS 100.9 LDG 73		12000	0	12073	10486
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY			7041050-5 34	MTH 23-Dec-2010 LDG 0		12000	0	12000	10413
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY			7041030-3 13	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY KMCO			7041030-4 13	MTH 06-Jul-2023 HRS 1755.8 LDG 1377		20000	1730.8 1353	20024	18437
COMMENTS: REMOVED RENTAL RH MLG TRAILING LINK ASSEMBLY PN.7041030-4 SN.30252616 WITH 90 CSN. INSTALLED CUSTOMER REPAIRED (BY TEXTRON AVIATION, OF WICHITA, KS, CRS#CNQR918C) RH MLG TRAILING LINK ASSEMBLY PN.7041030-4 SN.13 WITH 1730 HOURS AND 1353 CYCLES. WORK DONE IAW CESSNA510 MAINTENANCE MANUAL 32-42-00. OPS AND CLEARANCE CHECKS GOOD.										
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK			6327504-6 2901	MTH 23-Dec-2010		O/C	0		
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK			6327504-6 2829	MTH 23-Dec-2010		O/C	0		
322002	NOSE GEAR FORK & PISTON ASSEMBLY			7042040-1 341	MTH 23-Dec-2010		O/C	0		
322003 NOSE GEAR	UPLOCK ACTUATOR			6327504-7 1499	MTH 23-Dec-2010		O/C	0		
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR			9912655-1 FA100036-001 0406	MTH 23-Dec-2010 LDG 0		12000	0	12000	10413
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR			9912653-5 FA100104-001 FA100104-1-0363	MTH 23-Dec-2010 LDG 0		12000	0	12000	10413
322010 RIGHT	MAIN LANDING GEAR HYDRAULIC ACTUATOR			9912653-6 FA100105-001 FA100105-1-0359	MTH 23-Dec-2010 LDG 0		12000	0	12000	10413
322011	NOSE LANDING GEAR ACTUATOR			9912654-2 0359	MTH 23-Dec-2010 LDG 0		12000	0	12000	10413
322202	SHIMMY DAMPER			7042030-2 TSKC00102	MTH 23-Dec-2010		O/C	0		
322205 NOSE	LANDING GEAR STRUT ASSEMBLY			7042010-4 336	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
322206 NOSE	LANDING GEAR DRAG BRACE ASSY CHP 4			7042120-5 102	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
323001 LEFT	LANDING GEAR ASSEMBLY			7041010-5 NSN	MTH 23-Dec-2010		O/C	0		
323001 RIGHT	LANDING GEAR ASSEMBLY			7041010-6 NSN	MTH 23-Dec-2010		O/C	0		
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE KHII			9912478-3 11590	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		288	33	31-Jul-2047	252 m 8 d

Manufacture Date: 31-Jul-2023



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE 9914678-4	KHII		40005399-1 7582	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		288	175	30-Sep-2035	110 m 7 d
Manufacture Date: 30-Sep-2011										
323003	EMER BLOW DOWN BTL PRESSURE GAUGE 9914678-4	KGSO		19940931-1 74694	MTH 04-May-2021 HRS 1575.7 LDG 1251		O/C	0 0 0		
324001 LEFT	MAIN LANDING GEAR TIRE 9912646-1	KHII		021-523-0 2200T00100	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		O/C	0 0 0		
324001 RIGHT	MAIN LANDING GEAR TIRE 9912646-1	KMCO		021-523-0 2199T00351	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C	0 0 0		
324002	NOSE LANDING GEAR TIRE 9912649-1	KMCO		079-606-0 3048T00523	MTH 27-Dec-2023 HRS 1803.5 LDG 1404		O/C	0 0 0		
324003 LEFT	MAIN LANDING GEAR WHEEL 9912645-1	KMCO		3-1640 0249	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C	141 1629.9 1280		
324003 RIGHT	MAIN LANDING GEAR WHEEL 9912645-1	KMCO		3-1640 0354	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C	141 1629.9 1280		
324004 NOSE	NOSE LANDING GEAR WHEEL 9912648-1			3-1642 0154	MTH 27-Dec-2023 HRS 1803.5 LDG 1404		O/C	149 1702.6 1331		
324005 LEFT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KMCO		2-1706-1 0715A	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C			
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KMCO		2-1706-1 0541A	MTH 05-Apr-2023 HRS 1730.8 LDG 1353		O/C			
324006 LEFT	SHUTTLE VALVE 9914689-4			5145-1 0741	MTH 23-Dec-2010		O/C	0		
324006 RIGHT	SHUTTLE VALVE 9914689-4			5145-1 0761	MTH 23-Dec-2010		O/C	0		
324007	BRAKE METERING VALVE 9912650-9			84-75 373	MTH 23-Dec-2010		O/C	0		
324101 LEFT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0727	MTH 23-Dec-2010		O/C	0		
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0758	MTH 23-Dec-2010		O/C	0		
324101	PARKING BRAKE VALVE 9912388-10			98433-1 0377	MTH 23-Dec-2010		O/C	0		
324102	ANTISKID CONTROL UNIT 9912650-1			556-3 302829468	MTH 23-Dec-2010		O/C	0		
324103	ANTISKID CONTROL VALVE 9912650-6			211-134-1 0075	MTH 23-Dec-2010		O/C	0		
324104	EMERGENCY BRAKE VALVE 9912651-1			72298 0286	MTH 23-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324105	EMER BRAKE BOTTLE PRESSURE GAUGE			19940931-1 031701	MTH 23-Dec-2010		O/C	0		
325001	BUNGE ASSEMBLY			7042072-9 NSN	MTH 23-Dec-2010		O/C	0		
334001 LEFT	POWER SUPPLY 9912677-3	KSAT		82004-1 001096	MTH 05-Dec-2018 HRS 1221.4 LDG 1016		O/C	0 0 0		
334001 RIGHT	POWER SUPPLY 9912677-3			82004-1 000845	MTH 23-Dec-2010		O/C	0		
334002	GROUND RECOGNITION LIGHT 9912679-3			84003-2 000572	MTH 23-Dec-2010		O/C	0		
334003 LEFT	ANTI-COLLISION LIGHT	KMCO		9912679-7 001440	MTH 03-Aug-2021 HRS 1598.5 LDG 1266		8000	0 0 0	9598.5	7520.9
334003 RIGHT	ANTI-COLLISION LIGHT	KMCO		9912679-8 000893	MTH 03-Aug-2021 HRS 1598.5 LDG 1266		8000	0 0 0	9598.5	7520.9
341001	SWAAT UNIT 9912689-1			0863B2 427	MTH 23-Dec-2010		O/C	0		
341002 NO. 1	GDC 74B AIRDATA SYSTEM			011-01110-00 43806221	MTH 23-Dec-2010		O/C	0		
341002 NO. 2	GDC 74B AIRDATA SYSTEM			011-01110-00 43806227	MTH 23-Dec-2010		O/C	0		
341003 NO. 1	GTP 59 OAT PROBE SYSTEM			011-00978-00 47914673	MTH 23-Dec-2010		O/C	0		
341003 NO. 2	GTP 59 OAT PROBE SYSTEM			011-00978-00 47914509	MTH 23-Dec-2010		O/C	0		
341004 LEFT	PITOT PROBE 9912678-1			0851LN 275980	MTH 23-Dec-2010		O/C	0		
341004 RIGHT	PITOT PROBE 9912678-1			0851LN 275481	MTH 23-Dec-2010		O/C	0		
342001 STANDBY	ALTIMETER S3100-465			162350-1161 179985C	MTH 23-Dec-2010		O/C	0		
342002 AIRSPEED	INDICATOR			261440-1143 295495A	MTH 23-Dec-2010		O/C	0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE	KCRG		011-00831-00 46714469	MTH 12-Aug-2020 HRS 1511.1 LDG 1203		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE	KGSO		011-00831-00 46715212	MTH 21-Aug-2020 HRS 1514.5 LDG 1206		O/C			
342003	MAGNETIC COMPASS			S2800-821 NSN	MTH 23-Dec-2010		O/C	0		
342004 NO. 1	GDU 1040A DISPLAY	KSAT		011-03470-10 494102306	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		O/C	0 0 0		
342004 NO. 2	GDU 1040A DISPLAY	KMCO		011-03470-10 494105352	MTH 31-Oct-2019 HRS 1398.1 LDG 1125		O/C	2 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517			011-00868-10 42014604	MTH 23-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517			011-00868-10 42014605	MTH 23-Dec-2010		O/C	0		
342006 NO. 1	GMU 44 MAGNETOMETER			011-00870-00 47510009	MTH 27-Jan-2020 HRS 1470.1 LDG 1173		O/C			
342006 NO. 2	GMU 44 MAGNETOMETER KCRG			011-00870-00 47517918	MTH 04-Sep-2023 HRS 1770.4 LDG 1380		O/C	0 0 0		
342007	GDU 1500 MFD UNIT KSAT			011-03472-00 496001344	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513			4200-21 B10-10400	MTH 23-Dec-2010		O/C	0		
3420SD	FLIGHT STREAM 510 SOFTWARE SD VERSION 2.72 CARD KMCO			G1000 NXI VERSION 2.72	MTH 09-Jan-2026 HRS 1984.8 LDG 1527		O/C	0 0 0		
344001	GWX 75 12" WEATHER RADAR KMCO			010-01589-01 4RR002625	MTH 04-Jan-2022 HRS 1652.1 LDG 1301		O/C	0 0 0		
344002	GARMIN GDL-69A DATA LINK			011-00987-00 47763338	MTH 23-Dec-2010		O/C	0		
344003	RADAR ANTENNA, GWAX/GSX, 12" -- KMCO			117-00254-01 4739	MTH 04-Jan-2022 HRS 1652.1 LDG 1301		O/C	0 0 0		
345001	GPS/WAAS/XM ANTENNA			013-00245-00 8071	MTH 23-Dec-2010		O/C	0		
345002 RIGHT	TRANSPONDER KSAT			011-03303-00 3EH023527	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		O/C	0 0 0		
345003 LEFT	TRANSPONDER KSAT			011-00779-21 84810087	MTH 13-Jan-2017 HRS 896.4 LDG 789 ACH 325.3		O/C			
345004	GCU 475 FLIGHT MGMT CONTROL UNIT KSAT			011-04475-00 48V000347	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		O/C	0 0 0		
345005	ADF RECEIVER			013-00166-00 NSN	MTH 23-Dec-2010		O/C	0		
345006	ADF ANTENNA			013-00165-00 NSN	MTH 23-Dec-2010		O/C	0		
345007	MARKER BEACON ANTENNA			MB10-754-2 0397	MTH 23-Dec-2010		O/C	0		
345008	GLIDE SLOPE ANTENNA			RGS10-48 15070	MTH 23-Dec-2010		O/C	0		
345009 LEFT	L-BAND TRANSPONDER ANTENNA			L10-611-14 3112	MTH 23-Dec-2010		O/C	0		
345009 RIGHT	L-BAND TRANSPONDER ANTENNA			L10-611-14 3161	MTH 23-Dec-2010		O/C	0		
345009 UPPER	L-BAND TRANSPONDER ANTENNA			L10-611-14 3170	MTH 23-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA			L10-611-14 3175	MTH 23-Dec-2010		O/C	0		
345010 LEFT	NAV ANTENNA			VT11-767-3 1824	MTH 23-Dec-2010		O/C	0		
345010 RIGHT	NAV ANTENNA			VT11-767-3 1823	MTH 23-Dec-2010		O/C	0		
345011	KN63 DME TRANSCEIVER			066-01070-0001 34012	MTH 23-Dec-2010		O/C	0		
345013	RMI CONVERTER			013-00167-00 NSN	MTH 23-Dec-2010		O/C	0		
345014	GPS/WAAS/ ANTENNA			013-00244-00 6899	MTH 23-Dec-2010		O/C	0		
345015	DME ANTENNA			L10-611-14 3169	MTH 23-Dec-2010		O/C	0		
346010	TAS PROCESSOR			066-01152-0101 KTA810-2929	MTH 23-Dec-2010		O/C	0		
346011 BOTTOM	TAS ANTENNA			L10-611-14 3173	MTH 23-Dec-2010		O/C	0		
346011 TOP	TAS ANTENNA			071-01599-0100 22547	MTH 23-Dec-2010		O/C	0		
346012	CONFIGURATION MODULE			071-00112-0200 16132	MTH 23-Dec-2010		O/C	0		
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT KSAT			011-01105-01 15W012381	MTH 14-Jun-2018 HRS 1130.6 LDG 957		O/C	90 1130.6 957		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT KSAT			011-01105-01 15W012374	MTH 14-Jun-2018 HRS 1130.6 LDG 957		O/C	90 1130.6 957		
350001	OXYGEN BOTTLE	KMCO		4441073-040 0660-164	MTH 14-Jul-2024 HRS 1847.1 LDG 1433		180		30-Nov-2036	124 m 7 d
Manufacture Date: 01-Nov-2021										
350002	OXYGEN PRESSURE GAUGE C668512-0101			MD97-1 D10-10401	MTH 23-Dec-2010		O/C	0		
351001 LEFT	CREW OXYGEN MASK 9914067-41	KMCO		MC10-15-109 31082	MTH 04-Jan-2022 HRS 1652.1 LDG 1301		72	6 0 0	31-Jul-2027	12 m 8 d
351001 RIGHT	CREW OXYGEN MASK	KMCO		9914067-41 77612	MTH 11-Apr-2024 HRS 1828.5 LDG 1420		72	2 0 0	28-Feb-2030	43 m 5 d
361001 LEFT	PRECOOLER 9914402-7	KMCO		8315-2 T1267	MTH 05-Mar-2022 HRS 1667.6 LDG 1311		O/C	0 0 0		
361001 RIGHT	PRECOOLER 9914402-7			8315-2 TO716	MTH 23-Dec-2010		O/C	0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY			2601-34 0740A	MTH 23-Dec-2010		O/C	0		
361002 RIGHT	VARIABLE VENTURI VALVE ASSY			2601-34 0741A	MTH 23-Dec-2010		O/C	0		
361003	SERVICE AIR REGULATOR ASSY 9912510-2			1H75-23 2BF15	MTH 23-Dec-2010		O/C	0		
361004 LEFT	B/A SHUTOFF VALVE			5253-00-3 3034	MTH 23-Dec-2010		O/C	0		
361004 RIGHT	B/A SHUTOFF VALVE			5253-00-3 3054	MTH 23-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
361101 R1	DE-ICE VALVE			3D2353-06 N094208	MTH 23-Dec-2010		O/C	0		
361101 R2	DE-ICE VALVE			3D2353-06 N101133	MTH 23-Dec-2010		O/C	0		
522001	CABIN DOOR SEAL 9912674-3			S-22560-3 404	MTH 23-Dec-2010		O/C	0		
522002	ESCAPE HATCH SEAL 9912675-1			S-22561 563	MTH 23-Dec-2010		O/C	0		
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY			7013022-3 510-00348	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY			7013022-4 510-00348	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY			7013022-11 510-00348	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY			7013022-10 510-00348	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
534101 FWD	ENGINE BEAM			7012061-3 352	MTH 23-Dec-2010		O/C	0		
552001 LEFT	ELEVATOR ASSEMBLY			7034001-9 49	MTH 23-Dec-2010		O/C	0		
552001 RIGHT	ELEVATOR ASSEMBLY			7034001-10 49	MTH 23-Dec-2010		O/C	0		
553001	VERTICAL STABILIZER ASSY			7031001-1 324	MTH 23-Dec-2010		O/C	0		
561001 LEFT	WINDSHIELD ASSY, (LH) 9912745-9			NP-188601-1 10161H8538	MTH 23-Dec-2010		O/C	0		
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-10			NP-188601-2 10153H7882	MTH 23-Dec-2010		O/C	0		
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1			93310-1 1821	MTH 23-Dec-2010		O/C	0		
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2			93310-2 1800	MTH 23-Dec-2010		O/C	0		
562003 L1	CABIN WINDOW 9912747-10			93320-10 3258	MTH 23-Dec-2010		O/C	0		
562003 L2	CABIN WINDOW 9912747-10	SWF		93320-10 1724	MTH 29-Aug-2012 HRS 330.3 LDG 273		O/C	0 0 0		
562003 L3	CABIN WINDOW 9912747-10			93320-10 3249	MTH 23-Dec-2010		O/C	0		
562003 R1	CABIN WINDOW 9912747-10			93320-10 3256	MTH 23-Dec-2010		O/C	0		
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-10			93320-10 3276	MTH 23-Dec-2010		O/C	0		
562003 R3	CABIN WINDOW 9912747-10			93320-10 3248	MTH 23-Dec-2010		O/C	0		
572001 LEFT WING	FWD SPAR			7022022-1 77174	MTH 23-Dec-2010		O/C	0		
572001 RIGHT WING	FWD SPAR			7022022-2 78236	MTH 23-Dec-2010		O/C	0		
572002 LEFT WING	REAR SPAR			7022032-3 78243	MTH 23-Dec-2010		O/C	0		
572002 RIGHT WING	REAR SPAR			7022032-4 77696	MTH 23-Dec-2010		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
572003 LEFT WING	MAIN SPAR			7022027-1 78220	MTH 23-Dec-2010		O/C	0		
572003 RIGHT WING	MAIN SPAR			7022027-2 77683	MTH 23-Dec-2010		O/C	0		
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY			7041165-5 335	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY			7041165-6 345	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY			7041155-9 345	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY			7041155-10 335	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY			7041175-5 371	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY			7041175-6 372	MTH 23-Dec-2010 LDG 0		20000	0	20000	18413
712001 LEFT	ENG CHANNEL-FWD MOUNT			7051001-1 00332	MTH 23-Dec-2010		O/C	0		
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12 9912647-1 1773	MTH 23-Dec-2010 HRS 0		4000	0	4000	1922.4
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12 9912647-1 1778	MTH 23-Dec-2010 HRS 0		4000	0	4000	1922.4
712001 RIGHT	ENG CHANNEL-FWD MOUNT			7051001-2 00311	MTH 23-Dec-2010		O/C	0		
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12 9912647-1 1746	MTH 23-Dec-2010 HRS 0		4000	0	4000	1922.4
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM			LM-471-SA12 9912647-1 1753	MTH 23-Dec-2010 HRS 0		4000	0	4000	1922.4
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY			LM-471-SA4 9912647-3 LK2440	MTH 23-Dec-2010 HRS 0		8000	0	8000	5922.4
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY			LM-471-SA4 9912647-3 LK2470	MTH 23-Dec-2010 HRS 0		8000	0	8000	5922.4
712003 AFT	ENGINE BEAM			7012066-2 0348	MTH 23-Dec-2010		O/C	0		
712003 LEFT	AFT ENGINE MOUNT CHANNEL			7051001-3 00349	MTH 23-Dec-2010		O/C	0		
712003 RIGHT	AFT ENGINE MOUNT CHANNEL			7051001-4 00402	MTH 23-Dec-2010		O/C	0		
71EN1 NO. 1	ENGINE			35C0510-01 PCE-LB0715			E/C			
71EN2 NO. 2	ENGINE			35C0510-01 PCE-LB0714			E/C			
720010 E1	FAN ROTOR			35C1940-01 FRAEPLLN15	MTH 23-Dec-2010 LDG 6 ACCC YC		10500	0 0	(10500)10506	8919 8921
720010 E2	FAN ROTOR			35C1940-01 FRAEPLHD9	MTH 23-Dec-2010 LDG 6 ACCC YC		10500	0 0	(10500)10506	8919 8921
721010 E1	HP TURBINE DISK			35C2311-01 CRAZADMB165	MTH 23-Dec-2010 LDG 6 ACCC YC		5250	0 0	(5250)5256	3669 3671
721010 E2	HP TURBINE DISK			35C2311-01 CRAZADMB166	MTH 23-Dec-2010 LDG 6 ACCC YC		5250	0 0	(5250)5256	3669 3671

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
721020 E1	LP TURBINE DISK			35C2372-01 FRAEPLKA54	MTH 23-Dec-2010 LDG 6			0 0	(10500)10506	8919 8921
					ACCC YC		10500			
721020 E2	LP TURBINE DISK			35C2372-01 CRAZADPL269	MTH 23-Dec-2010 LDG 6			0 0	(10500)10506	8919 8921
					ACCC YC		10500			
723010 E1	IMPELLER AND SHAFT ASSEMBLY			35C4888-01 AAPPIAEX2008	MTH 23-Dec-2010 LDG 6			0 0	(10500)10506	8919 8921
					ACCC YC		10500			
723010 E2	IMPELLER AND SHAFT ASSEMBLY			35C4888-01 AAPPIAEX2005	MTH 23-Dec-2010 LDG 6			0 0	(10500)10506	8919 8921
					ACCC YC		10500			
725010 E1	HP COMPRESSOR ROTOR			35C3661-01 FRAEPLHT66	MTH 23-Dec-2010 LDG 6			0 0	(10500)10506	8919 8921
					ACCC YC		10500			
725010 E2	HP COMPRESSOR ROTOR			35C3661-01 FRAEPLHT61	MTH 23-Dec-2010 LDG 6			0 0	(10500)10506	8919 8921
					ACCC YC		10500			
726010 E1	AGB STARTER MAGNETIC SEAL UNK			35C1022-01 SN-UNKNOWN	MTH 30-Dec-2022 HRS 1730.8		1750	1 0	(3480.8)3480.8	1403.2
726010 E2	AGB STARTER MAGNETIC SEAL UNK			35C1022-01 N/A	MTH 13-Mar-2023 HRS 1730.8 LDG 1353		1750	0 0 0	(3480.8)3480.8	1403.2
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2			1103P0448 9454	MTH 23-Dec-2010		O/C	0		
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2			1103P0448 9475	MTH 23-Dec-2010		O/C	0		
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1 SWF			TFF1573-4 AAA7021	MTH 11-Feb-2012 HRS 235.7 LDG 190		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER KMCO			9912417-1 0043	MTH 22-Jul-2020 HRS 1510.6 LDG 1202		O/C	0 0 0		
731050 E1	FUEL MANIFOLD UNK			35C6160-01 DEAAAA78506	MTH 30-Dec-2022 HRS 1730.8		O/C	1 0		
731050 E2	FUEL MANIFOLD UNK			35C6160-01 DEAAAA78507	MTH 13-Mar-2023 HRS 1730.8 LDG 1353		O/C	0 0 0		
732101 E1	FUEL METERING UNIT (F.M.U.)			35C0794-04 17006304	MTH 23-Dec-2010		H/T H/T	0		
732101 E2	FUEL METERING UNIT (F.M.U.)			35C0794-04 16981647	MTH 23-Dec-2010		H/T H/T	0		
741001 E1	IGNITION EXCITER			35C5472-01 WDA111667	MTH 23-Dec-2010		O/C	0		
741001 E2	IGNITION EXCITER			35C5472-01 WDA111666	MTH 23-Dec-2010		O/C	0		
741002 E1 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 23-Dec-2010		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
741002 E2 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 23-Dec-2010		O/C	0		
741003 E1 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 23-Dec-2010		O/C	0		
741003 E2 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 23-Dec-2010		O/C	0		
741004 E1 INBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 23-Dec-2010		O/C	0		
741004 E2 INBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 23-Dec-2010		O/C	0		
741005 E1 OUTBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 23-Dec-2010		O/C	0		
741005 E2 OUTBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 23-Dec-2010		O/C	0		
751003 E1	BLEED VALVE ACTUATOR			35C2851-02 16914535	MTH 23-Dec-2010		H/T H/T	0		
751003 E2	BLEED VALVE ACTUATOR			35C2851-02 16971944	MTH 23-Dec-2010		H/T H/T	0		
761001 E1	FADEC 9912637-2			35C4035-04 10-905	MTH 23-Dec-2010		O/C	0		
761001 E2	FADEC 9912637-2			35C4035-04 10-906	MTH 23-Dec-2010		O/C	0		
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-04 WA39851	MTH 23-Dec-2010		H/T H/T	0		
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-04 WA39855	MTH 23-Dec-2010		H/T H/T	0		
793001 E1	OIL TEMP SENSOR			102-00083 07628	MTH 23-Dec-2010		O/C	0		
793001 E2	OIL TEMP SENSOR			102-00083 07552	MTH 23-Dec-2010		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER GSO			S2800-1267 8892-4-562	MTH 04-May-2024 HRS 1831.7 LDG 1423		O/C	0 0 0		
793002 E2	OIL PRESSURE TRANSMITER KPHF			S2800-1267 9005-8-491	MTH 18-Apr-2024 HRS 1830.9 LDG 1422		O/C	0 0 0		
793010 E1	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 23-Dec-2010		O/C	0		
793010 E2	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 23-Dec-2010		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1	KORL		MG94E-1 1067D	MTH 28-Oct-2022 HRS 1726 LDG 1349		1500	0 0 0	3226	1148.4
801000 RIGHT	STARTER GENERATOR 9912676-1	KSAT		MG94E-1 196D	MTH 13-Jan-2017 HRS 896.4 LDG 789 ACH 325.3		1500	0	2396.4	318.8

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)									
	INFORMATIONAL									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 510-99-02 REV 01	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 02)			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SL 510-99-02	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 01)			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 510-05-02	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS INTERVALS UPDATE			MANDATORY	MTH		12		16-Jul-2027	New Req
	MOC :				HRS		150		2230.55	
SL 510-11-03	PLACARDS AND MARKINGS - BRAKE ACCUMULATOR PLACARD INSPECTION	SWF		RECOMMENDED	MTH 29-Aug-2012		A/R			Complete
	MOC :				HRS 330.3					
					LDG 273					
	MOC :									
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH		-			
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01) INFORMATIONAL									
MOC :										
SL 510-20-01 REV 01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 02) INFORMATIONAL									
MOC :										
SL 510-20-01 REV 02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 03) INFORMATIONAL									
MOC :										
SL 510-20-01 REV 03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 04) INFORMATIONAL									
MOC :										
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05) INFORMATIONAL									
MOC :										
SL 510-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 01) INFORMATIONAL									
MOC :										
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL INFORMATIONAL									
MOC :										
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT	KMCO	RECOMMENDED	MTH 07-Jan-2020 HRS 1449.8 LDG 1155			-			N/A
MOC : NOT APPLICABLE - SERVICE LETTER SL510-21-04 IS NOT APPLICABLE DUE TO SERIAL NUMBER INSTALLED. {P/N: 52811-102, S/N: 1315}										
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT OPTIONAL									
MOC :										
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT	SWF	OPTIONAL	MTH 16-Dec-2011 HRS 211.6 LDG 166			A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-23-02 ENABLE XM RADIO IN COCKPIT. ENABLED XM RADIO IN COCKPIT PER ACCOMPLISHMENT INSTRUCTIONS.										
SL 510-23-01	LIGHTNING RELATED ANOMALIES OF THE GARMIN GMA 1347[D] AUDIO PANEL INFORMATIONAL									
MOC :										
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION	KSAT	MANDATORY	DAYS 13-Jan-2017 HRS 896.4 LDG 789			-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-24-14 REVISION 1 DATED SEPT 28,2016. "PRINTED CIRCUIT BOARD VERIFICATION".										
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01) MANDATORY									
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT OPTIONAL						A/R			
	MOC :									
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS OPTIONAL						-			
	MOC :									
SB 510-28-02	LOCKING FUEL CAP INSTALLATION			OPTIONAL			A/R			
	MOC :									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS INFORMATIONAL						-			
	MOC :									
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT DISCRETIONARY						-			
	MOC :									
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01)	SWF		DISCRETIONARY	MTH 13-Jul-2012 HRS 319.6 LDG 250		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WIRH SB510-30-02 PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT. INSTALLED WIRING, SWITCHES AND TEMPERATURE CONTROL UNITS PER ACCOMPLISHMENT INSTRUCTIONS.									
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION	SWF		MANDATORY	MTH 13-Jul-2012 HRS 319.6 LDG 250		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB510-30-05 WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION. TEMPERATURE CONTROL UNITS REPLACED DURING SB510-30-02 PER ACCOMPLISHMENT INSTRUCTIONS.									
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT RECOMMENDED			MTH 21-Feb-2017			-			
	MOC :									
	DEFERRED									
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)			RECOMMENDED	MTH		-			
	MOC :									
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES INFORMATIONAL						-			
	MOC :									
SL 510-30-01 REV 01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 02)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01 REV 02	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 03)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 01)			INFORMATIONAL			A/R			
	MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL						-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION INFORMATIONAL						-			
	MOC :									
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	SWF		RECOMMENDED	MTH 13-Jul-2012 HRS 319.6 LDG 250		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-32-05 NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION PER ACCOMPLISHMENT INSTRUCTIONS. ADDED SPLICES AND EXTENSION.									
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	MTO		MANDATORY	DAYS 02-Mar-2017 HRS 916 LDG 808		-			N/A
	MOC : NOT APPLICABLE - C/W SL510-32-07 "LANDING GEAR-MAIN LANDING GEAR BRAKE VERIFICATION" NOT APPLICABLE DUE THE PART NUMBER OF LANDING GEAR BRAKES IS NOT AFFECTED.									
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY	MMTO		MANDATORY	DAYS 04-Aug-2017 HRS 976.4 LDG 847		-			Complete
	MOC : COMPLIED WITH - LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY. NOTE: LEFT ASSY BRAKE P/N 2-1706-1 S/N 0384 AND RH ASSY BRAKE P/N 2-1706-1 S/N 0376 WAS PAINT THE END OF THE TWO WEAR INDICATOR PINS YELLOW IAW ACCOMPLISHMENT INSTRUCTIONS OF THIS SB 2-1706-1-32-1 UTC AEROSPACE SYSTEMS GOODRIC CORPORATIONS									
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT OPTIONAL						-			
	MOC :									
SB 510-34-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION	KSAT		OPTIONAL	MTH 19-Mar-2019 HRS 1265.6 LDG 1045		A/R			Complete
	MOC : COMPLIED WITH - DURING THE INSTALLATION OF THE GARMIN G1000 NXI INTEGRATED AVIONICS SYSTEM- FOUND THAT SB510-34-10, GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION, HAD BEEN PREVIOUSLY INSTALLED. OPS CHECKED SATISFACTORY.									
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	SWF		MANDATORY	MTH 26-Jul-2011 HRS 101.4 LDG 74		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB 510-34-11 REV. 1 IN ACCORDANCE WITH BULLETIN INSTRUCTIONS									
SB 510-34-11	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE (SUPERSEDED BY 510-34-11 REV 01)	SWF		MANDATORY	MTH 22-Jun-2011 HRS 99.9 LDG 72		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-34-11 GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE. UPGRADED GARMIN G1000 PER ACCOMPLISHMENT INSTRUCTIONS.									
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT			MANDATORY	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)	SWF		MANDATORY	MTH 11-Feb-2012 HRS 235.7 LDG 190		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB510-34-12 PER THE SERVICE BULLETINS ACCOMPLISHMENT INSTRUCTIONS. OPERATIONAL CHECK IS GOOD.										
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	SWF		MANDATORY	MTH 13-Jul-2012 HRS 319.6 LDG 250		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-14 GARMIN G1000 SOFTWARE VERSION 010-00435-24 PER ACCOMPLISHMENT INSTRUCTIONS. UPGRADED GARMIN G1000 TO VERSION 010-000435-24.										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRs SOFTWARE UPDATE	KSAT		MANDATORY	MTH 13-Jan-2017 HRS 896.4 LDG 789		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-16 REVISION 1 DATED SEPT 30, 2016, BY COMPLYING WITH SB510-34-17.										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)	KSAT		OPTIONAL	MTH 13-Jan-2017 HRS 896.4 LDG 789		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-17 REVISION 1 DATED SEPT 28,2016. "GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE".										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)			OPTIONAL			-			
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE			OPTIONAL			-			
MOC :										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE	KMCO		RECOMMENDED	MTH 07-Jan-2020 HRS 1449.8 LDG 1155		-			N/A
MOC : NOT APPLICABLE - SERVICE BULLETIN SB510-34-18 IS NOT APPLICABLE DUE TO AIRCRAFT HAS G1000 NXI STC INSTALLED.										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
MOC :										
COM MC ALL - 007	GPS/SBAS APPROACH DOWNGRADES DUE TO GEOMAGNETIC ACTIVITY			INFORMATIONAL	MTH		-			
MOC :										
SL 510-34-01	TRANSMITTAL OF GARMIN SERVICE ALERT 070424-00			INFORMATIONAL			A/R			
MOC :										
SL 510-34-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING			INFORMATIONAL			A/R			
MOC :										
SL 510-34-05	GARMIN G1000 TRANSPONDER OPERATION CHANGE			INFORMATIONAL			A/R			
MOC :										
SL 510-34-06	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0811, G1000 SERIES FLIGHT PLAN SEQUENCING ISSUE			INFORMATIONAL			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-07	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 0825 LPV AND LNAV/VNAV APPROACHES WITH THREE-CHARACTER AIRPORT IDENTIFIERS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-08	GPS/WAAS LOSS OF RECEPTION IN ALASKA, NORTHWEST CANADA, AND EASTERN RUSSIA			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-10	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0915 REVISION A, G1000 SERIES NAVIGATION SUSPENDING DURING NON-PRECISION APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-12	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0933 REVISION A, SYSTEM MAY SELECT NAV 2 AS A NAVIGATION SOURCE DURING APPROACH			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-13	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0922 REVISION A, VOR OR LOC/ILS APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION			INFORMATIONAL			-			
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL			-			
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT	KMCO		RECOMMENDED	MTH 22-Jun-2017 HRS 959.9 LDG 840		-			Complete
	MOC :			COMPLIED WITH						
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL			-			
	MOC :									
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)			INFORMATIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG INFORMATIONAL						-			
MOC :										
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)						-			
MOC :										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	GSO		MANDATORY	MTH DAYS 13-Apr-2016 HRS 770.1 LDG 678		-			N/A
MOC : NOT APPLICABLE - CIL-35-05 NOT APPLICABLE DUE TO P/N OF INSTALLED O2 MASKS.										
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02)			MANDATORY			-			
MOC :										
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	SWF		MANDATORY	MTH 16-Dec-2011 HRS 211.6 LDG 166		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH SL510-35-01 PER ACCOMPLISHMENT INSTRUCTIONS AND FOUND BOTH O2 MASKS NOT APPLICABLE BY SERIAL NUMBERS.										
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	KGSO		MANDATORY	DAYS 21-Feb-2020 HRS 1473.4 LDG 1176		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-52-06.										
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR						A/R			
MOC :										
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT	KMCO		MANDATORY	DAYS 07-Jan-2020 HRS 1449.8 LDG 1155		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER BY TORQUING THE BOLT ON EMERGENCY ESCAPE HATCH IAW SL510-52-06 ACCOMPLISHMENT INSTRUCTIONS.										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS			DISCRETIONARY			-			
MOC :										
SL 510-55-02 REV 02	HORIZONTAL STABILIZER SEALANT INSPECTION			MANDATORY	DAYS		A/R			
MOC :										
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH 23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH 23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) CATEGORY 6			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7						-			
	MOC :									
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS CATEGORY 7						-			
	MOC :									
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01) CATEGORY 9			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01) CATEGORY 9			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R2 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 R2 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)			CATEGORY 8	MTH 23-Dec-2010		-			Complete
	MOC :									
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)			CATEGORY 8	MTH 23-Dec-2010		-			Complete
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63028 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)			CATEGORY 5	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)			CATEGORY 5	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63034 R01 E1	REPLACEMENT OF OIL PUMP PLATE			CATEGORY 6			-			
	MOC :									
SB PW600-72-63034 R01 E2	REPLACEMENT OF OIL PUMP PLATE			CATEGORY 6			-			
	MOC :									
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE			CATEGORY 8	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE			CATEGORY 8	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63037 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63037 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63043 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01) CATEGORY 6			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63043 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01) CATEGORY 6			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
	MOC :									
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW600-72-63051 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63051 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)			CATEGORY 6	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER			CATEGORY 7	MTH 23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
	MOC :									
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)			CATEGORY 7	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63074 R02 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			
MOC :										
SB PW600-72-63074 R02 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			
MOC :										
SB PW600-72-63074 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63074 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
MOC :										
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6						-			
MOC :										
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01) CATEGORY 6			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7						A/R			
MOC :										
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7						A/R			
MOC :										
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
MOC :										
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			
MOC :										
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01) CATEGORY 5			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7	MTH 23-Dec-2010		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63087 R01 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02)	SWF		CATEGORY 3	MTH 29-Aug-2012 HRS 330.3 LDG 273		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 R1. UPDATED FADEC SOFTWARE AS PER ACCOMPLISHMENT INSTRUCTIONS.									
SB PW600-72-63087 R01 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02)	SWF		CATEGORY 3	MTH 29-Aug-2012 HRS 330.3 LDG 273		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 R1. UPDATED FADEC SOFTWARE AS PER ACCOMPLISHMENT INSTRUCTIONS.									
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL			CATEGORY 3	MTH		-			
	MOC :									
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL			CATEGORY 3	MTH		-			
	MOC :									
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
	MOC :									
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6			-			
	MOC :									
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS	UNK		CATEGORY 6	MTH 30-Dec-2022 HRS 1730.8		-			Complete
	MOC :									
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS	UNK		CATEGORY 6	MTH 13-Mar-2023 HRS 1730.8		-			Complete
	MOC :									
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
	MOC :									
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
	MOC :									
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7						-			
	MOC :									
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7						-			
	MOC :									
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7						-			
	MOC :									
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)						-			
	MOC :									
SB PW600-72-63097 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 6						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63097 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 6						-			
	MOC :									
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)						-			
	MOC :									
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3						-			
	MOC :									
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3						-			
	MOC :									
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY CATEGORY 5						-			
	MOC :									
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY CATEGORY 5						-			
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7						-			
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7						-			
	MOC :									
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 5						-			
	MOC :									
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 5						-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY UNK RECOMMENDED				MTH 30-Dec-2022 HRS 1730.8		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY UNK RECOMMENDED				MTH 13-Mar-2023 HRS 1730.8		-			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL RECOMMENDED						-			
	MOC :									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01) CATEGORY 7						-			
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER CATEGORY 5						-			
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01) CATEGORY 5						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5			-			
MOC :										
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
MOC :										
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
MOC :										
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
MOC :										
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING	UNK		CATEGORY 7	MTH 13-Mar-2023 HRS 1730.8 LDG 1353		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
MOC :										
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
MOC :										
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE	UNK		CATEGORY 5	MTH 30-Dec-2022 HRS 1730.8		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE	UNK		CATEGORY 5	MTH 13-Mar-2023 HRS 1730.8		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE			CATEGORY 5			-			
MOC :										
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE	UNK		CATEGORY 5	MTH 13-Mar-2023 HRS 1730.8		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	KSAT		CATEGORY 3	MTH 05-Dec-2018 HRS 1221.4 LDG 1017		-			N/A
MOC : NOT APPLICABLE - PRATT & WHITNEY SERVICE BULLETIN PW600-72-63111, DOES NOT APPLY DUE TO EFFECTED SERIAL NUMBER IS NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	KSAT		CATEGORY 3	MTH 05-Dec-2018 HRS 1221.4 LDG 1017		-			N/A
MOC : NOT APPLICABLE - PRATT & WHITNEY SERVICE BULLETIN PW600-72-63111, DOES NOT APPLY DUE TO EFFECTED SERIAL NUMBER IS NOT INSTALLED.										
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL			CATEGORY 3	MTH 31-Oct-2021 HRS 1631.3 LDG 1288		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AGB SEAL WAS NOT REPLACED BETWEEN JANUARY 01 2018 AND FEBRUARY 01 2021.										
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL			CATEGORY 3	MTH 31-Oct-2021 HRS 1631.3 LDG 1288		-			N/A
MOC : NOT APPLICABLE - N/A DUE TO AGB SEAL WAS NOT REPLACED BETWEEN JANUARY 01 2018 AND FEBRUARY 01 2021.										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	UNK		CATEGORY 7	MTH 30-Dec-2022 HRS 1730.8		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	UNK		CATEGORY 7	MTH 13-Mar-2023 HRS 1730.8 LDG 1353		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5			-			
MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW600-72-63116 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63116 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63116 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63116 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63117 E1	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER CATEGORY 9						-			
MOC :										
SB PW600-72-63117 E2	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER CATEGORY 9						-			
MOC :										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						A/R			
MOC :										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						A/R			
MOC :										
ASL 510-73-01 LEFT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			MANDATORY			A/R			
MOC :										
ASL 510-73-01 RIGHT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			MANDATORY			-			
MOC :										
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-1007-63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E1	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01) CATEGORY 6			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01) CATEGORY 6			MTH	23-Dec-2010		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01) CATEGORY 3			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01) CATEGORY 3			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63071 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R01) SUPERSEDED			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63071 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R01) SUPERSEDED			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) CATEGORY 8			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63115 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL CATEGORY 7			MTH			-			
	MOC :									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63115 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7 MTH			-			
MOC :										
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7			-			
MOC :										
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7			-			
MOC :										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01)			CATEGORY 7 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01)			CATEGORY 7 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB 510-76-01 REV 01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETINPW600-72-63087 (SUPERSEDED BY 510-76-01 REV 02)	SWF		MANDATORY MTH	29-Aug-2012		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 R1. UPDATED FADEC SOFTWARE AS PER ACCOMPLISHMENT INSTRUCTIONS.										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087			MANDATORY MTH			-			
MOC :										
SB 510-76-02 REV 01	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT			RECOMMENDED MTH			-			
MOC :										
SB 510-76-02	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT			RECOMMENDED MTH			-			
MOC :										
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8 MTH	23-Dec-2010		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT KPHF			MTH HRS LDG	18-Apr-2024 1830.9 1422		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB 510-79-03									
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION SWF			DAYS HRS LDG	03-Nov-2011 186 145		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-79-02 OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION. APPLIED COATING AND ADDED INSULATING TAPE PER ACCOMPLISHMENT INSTRUCTIONS.									
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06) INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION INFORMATIONAL						-			
	MOC :									
SB PW600-72-63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63068 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01) RECOMMENDED			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63068 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63068 R01) RECOMMENDED			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63047 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)			MTH	23-Dec-2010		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SL 510-80-01	ENGINE STARTING			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM	KMCO		RECOMMENDED	MTH 07-Jan-2020 HRS 1449.8 LDG 1155		-			N/A
MOC : NOT APPLICABLE - SERVICE LETTER SL510-80-02 START/GENERATORS IS NOT APPLICABLE. LEFT & RIGHT STARTER/GENERATORS ARE MOD LEVEL D.										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										
SL CIL-99-05 REV 1	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL	MTH		-			
MOC :										
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
MOC :										

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-10-02 DOES NOT APPLY DUE TO SICMA AERO SEATS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-10-02 DOES NOT APPLY DUE TO SICMA AERO SEATS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-10-02 DOES NOT APPLY DUE TO SICMA AERO SEATS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-10-02 DOES NOT APPLY DUE TO SICMA AERO SEATS NOT INSTALLED IN THIS AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KMCO		MTH 23-Jun-2018 HRS 1139.7 LDG 964			-			N/A
MOC : NOT APPLICABLE - AD 2017-16-01 PARA (G) DATED 24 OCT 2017 IS NOT APPLICABLE DUE TO EFFECTED EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT IAW AD INSTRUCTIONS.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KMCO		MANDATORY MTH 23-Jun-2018 HRS 1139.7 LDG 964			-			N/A
MOC : NOT APPLICABLE - AD 2017-16-01 PARA (J) DATED 24 OCT 2017 IS NOT APPLICABLE DUE TO EFFECTED EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT IAW AD INSTRUCTIONS.										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KMCO		MANDATORY MTH 23-Jun-2018 HRS 1139.7 LDG 964			-			N/A
MOC : NOT APPLICABLE - AD 2017-16-01 DATED 24 OCT 2017 IS NOT APPLICABLE DUE TO EFFECTED EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT IAW AD INSTRUCTIONS.										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KMCO		MANDATORY MTH 03-Aug-2021 HRS 1598.5 LDG 1266			-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA 2021-07-13 APPLIANCE AD (EFFECTIVE DATE MAY 11,2021) - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT PARA(E)(1). DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOTINSTALLED ON THIS AIRCRAFT.										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KMCO		MANDATORY MTH 03-Aug-2021 HRS 1598.5 LDG 1266			-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA 2021-07-13 APPLIANCE AD (EFFECTIVE DATE MAY 11,2021) - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT PARA(E)(2). DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	KMCO		MANDATORY MTH 03-Aug-2021 HRS 1598.5 LDG 1266			-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA 2021-07-13 APPLIANCE AD (EFFECTIVE DATE MAY 11,2021) - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT PARA(E)(3) DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	KMCO		MANDATORY MTH 03-Aug-2021 HRS 1598.5 LDG 1266			-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA 2021-07-13 APPLIANCE AD (EFFECTIVE DATE MAY 11,2021) - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT. DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH 06-Feb-2025		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH 06-Feb-2025		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY	MTH 06-Feb-2025		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY	MTH 06-Feb-2025		-			N/A
MOC : NOT APPLICABLE - AD DOES NOT APPLY DUE TO AFFECTED PART NUMBER SEAT BELTS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS			MANDATORY			-			
MOC :										
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	MMTO		MANDATORY	DAYS 12-Apr-2018 HRS 1087.7 LDG 923		-			Complete
MOC : COMPLIED WITH - ADRESSED WITH SL-510-32-08										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KMCO		MANDATORY	MTH 07-Jun-2019 HRS 1338.8 LDG 1085		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2014-18-01 BY INSPECTING IAW PARAGRAPH G, ROCKWELL COLLINS TRANSPONDER NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-10-51-E DOES NOT APPLY DUE TO AVIDYNE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-10-51-E DOES NOT APPLY DUE TO AVIDYNE NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-08-07 DOES NOT APPLY TO PILOTS OXYGEN MASK DUE TO PART NUMBER INSTALLED IS MC10-15-109 OR SERIAL NUMBER 57792. CO-PILOTS MASK DOES NOT APPLY DUE TO MASK SERIAL NUMBER SE29623.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-08-07 DOES NOT APPLY TO PILOTS OXYGEN MASK DUE TO PART NUMBER INSTALLED IS MC10-15-109 OR SERIAL NUMBER 57792. CO-PILOTS MASK DOES NOT APPLY DUE TO MASK SERIAL NUMBER SE29623.										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	GSO		MANDATORY	MTH 05-Aug-2015 HRS 701.6 LDG 617		-			N/A
MOC : NOT APPLICABLE - AD2015-08-07 DOES NOT APPLY TO PILOTS OXYGEN MASK DUE TO PART NUMBER INSTALLED IS MC10-15-109 OR SERIAL NUMBER 57792. CO-PILOTS MASK DOES NOT APPLY DUE TO MASK SERIAL NUMBER SE29623.										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KGSO		MANDATORY	MTH DAYS 21-Dec-2015 HRS 748.5 LDG 659		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 PER ACCOMPLISHMENT INSTRUCTIONS. AD2015-23-09 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KGSO		MANDATORY	MTH DAYS 21-Dec-2015 HRS 748.5 LDG 659		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 PER ACCOMPLISHMENT INSTRUCTIONS. AD2015-23-09 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KGSO		MANDATORY	MTH DAYS 21-Dec-2015 HRS 748.5 LDG 659		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 PER ACCOMPLISHMENT INSTRUCTIONS. AD2015-23-09 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KGSO		MANDATORY	MTH DAYS 21-Dec-2015 HRS 748.5 LDG 659		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 PER ACCOMPLISHMENT INSTRUCTIONS. AD2015-23-09 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KGSO		MANDATORY	MTH 21-Dec-2015 HRS 748.5 LDG 659		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 PER ACCOMPLISHMENT INSTRUCTIONS. AD2015-23-09 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS									
		KGSO		MANDATORY	MTH 21-Dec-2015 HRS 748.5 LDG 659		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 PER ACCOMPLISHMENT INSTRUCTIONS. AD2015-23-09 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12									
		KSAT		MANDATORY	MTH 13-Jan-2017 HRS 896.4 LDG 789		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 DOES NOT APPLY DUE TO NO B/E AEROSPACE EQUIPMENT IS ON BOARD.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12									
		KSAT		MANDATORY	MTH 13-Jan-2017 HRS 896.4 LDG 789		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 DOES NOT APPLY DUE TO NO B/E AEROSPACE EQUIPMENT IS ON BOARD.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12									
		KSAT		MANDATORY	MTH 13-Jan-2017 HRS 896.4 LDG 789		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 DOES NOT APPLY DUE TO NO B/E AEROSPACE EQUIPMENT IS ON BOARD.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12									
		KSAT		MANDATORY	MTH 13-Jan-2017 HRS 896.4 LDG 789		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 DOES NOT APPLY DUE TO NO B/E AEROSPACE EQUIPMENT IS ON BOARD.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
				MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED									
				MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.									
		MMTO		MANDATORY	MTH 12-Apr-2018 HRS 1087.7 LDG 923		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED										
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
				MANDATORY			-			
MOC :										
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS									
				MANDATORY	DAYS 11-Dec-2025		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE PART NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0348**
Unit: **0348** Reg No: **N681AN**
Airworthiness: **23-Dec-2010**
Print Date: **23-Jul-2026 10:54AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1587	23-Jul-2026	.55
ENG 1	2077.6	1581	23-Jul-2026	.55
ENG 2	2077.6	1581	23-Jul-2026	.55
AIR COND	648.5		23-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT	KMCO		MANDATORY	DAYS 09-Jan-2026 HRS 1984.8 LDG 1527		-			N/A
MOC : NOT APPLICABLE - AD2025-26-06 EFFECTIVE DATE: JANUARY 14-2026 THIS AD IS NOT APPLICABLE. TYPE EQUIPMENT NOT INSTALLED.										
FAA 2026-03-09 PARA (G) EASA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD	KHII		MANDATORY	DAYS 20-Apr-2026 HRS 2023.9 LDG 1554		-			N/A
MOC : NOT APPLICABLE										
FAA 2026-03-09 PARA (G) EASA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD	KHII		MANDATORY	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		-			N/A
MOC : NOT APPLICABLE										
FAA 2026-03-09 PARA (G) EASA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT	KHII		MANDATORY	DAYS 20-Apr-2026 HRS 2023.9 LDG 1554		-			N/A
MOC : NOT APPLICABLE										
FAA 2026-03-09 PARA (G) EASA (4)	LIFE LIMIT: REMOVE FROM SERVICE	KHII		MANDATORY	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		-			N/A
MOC : NOT APPLICABLE										
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE	KHII		MANDATORY	MTH 20-Apr-2026 HRS 2023.9 LDG 1554		-			N/A
MOC : NOT APPLICABLE										
TCCA CF-2010-03 E1	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR			MANDATORY	MTH 23-Dec-2010		-			N/A
MOC : NOT APPLICABLE - BY PART NUMBER										
TCCA CF-2010-03 E2	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR			MANDATORY	MTH 23-Dec-2010		-			N/A
MOC : NOT APPLICABLE - BY PART NUMBER										