



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Program Types

AIRCRAFT	SERIAL/REGNO: 510-0448 / N448SJ	MODEL: 510 - CITATION MUSTANG	MANUFACTURER: TEXTRON AVIATION INC.
-----------------	--	--------------------------------------	--

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

ENGINE NO. 1	SERIAL/PART: PCE-LB0919 / 35C0510 -01	MODEL: PW615F-A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	--	------------------------	---

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

ENGINE NO. 2	SERIAL/PART: PCE-LB0918 / 35C0510 -01	MODEL: PW615F-A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	--	------------------------	---

UTILIZATION: N/A
OPERATING REGULATION: N/A
REGION OF OPERATION: N/A
OPTIONAL EQUIPMENT: N/A

These program types are defined in the OEM manual and can differ from your other settings. These selections will impact the active OEM interval defined on the aircraft status.

As an example,

1. Your aircraft might be EASA registered but you choose to follow the OEM recommended interval for Transport Canada. In that case the operating regulation would be TCCA and can be set to EASA if OEM did not specify intervals for EASA operation.
2. Region of Operation is driven from the OEM manual and the selection between Airframe, Engine and APU can differ since the OEM manual can have requirements dependent on different regions of operation.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (XPNDR 91.413)	KIWA	MTH	28-Jun-2026		24		30-Jun-2028	23 m 16 d
			HRS	1983.5					
			LDG	1713					
0534NXIV	VISUAL INSPECTION G1000 NXI EQUIPMENT/ACCESSORIES/WIRING HARNESS	KIWA	MTH	01-Jul-2026					
			HRS	1983.5		1350		3333.5	1348.4
			LDG	1713					
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK		MTH	14-Mar-2014		A/R			
055002	ACCOMPLISH OVERSPEED CHECK		MTH	14-Mar-2014		A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK		MTH	14-Mar-2014		A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK		MTH	14-Mar-2014		A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK		MTH	14-Mar-2014		A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK		MTH	14-Mar-2014		A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK		MTH	14-Mar-2014		A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK		MTH	14-Mar-2014		A/R			
5-12-01	INSPECTION DOCUMENT 01		MTH	04-Nov-2024		450		2250.8	265.7
			HRS	1800.8					
			LDG	1575					
5-12-02	INSPECTION DOCUMENT 02		MTH	04-Nov-2024		900		2700.8	715.7
			HRS	1800.8					
			LDG	1575					
5-12-03	INSPECTION DOCUMENT 03		MTH	03-Nov-2022		1350		2652.1	667
			HRS	1302.1					
			LDG	1185					
5-12-04	INSPECTION DOCUMENT 04		MTH	19-Jul-2024		1800		3527.28	1542.18
			HRS	1727.28					
			LDG	1487					
5-12-05	INSPECTION DOCUMENT 05		MTH	14-Mar-2014		3150		3150	1164.9
			HRS	0					
5-12-06	INSPECTION DOCUMENT 06		MTH	28-Oct-2025		12		31-Oct-2026	3 m 17 d
			HRS	1959.33					
			LDG	1704					
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK)		MTH	28-Oct-2025		12		31-Oct-2026	3 m 17 d
		339TS	HRS	1959.33					
		I-77193023	LDG	1704					
5-12-07	INSPECTION DOCUMENT 07		MTH	04-Nov-2024		24		30-Nov-2026	4 m 16 d
			HRS	1800.8					
			LDG	1575					
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK	MTH	05-Jun-2018		60			
			HRS	273					
			LDG	301					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262004	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)			30401102-2 59585B1	MTH 22-Feb-2023		60		29-Feb-2028	19 m 15 d
Hydro Check Date: 22-Feb-2023										
5-12-11	INSPECTION DOCUMENT 11				MTH 03-Nov-2022 HRS 1302.1 LDG 1185		72		30-Nov-2028	28 m 16 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)			339TS I-77193023	MTH 27-Aug-2025		72		31-Aug-2031	61 m 17 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 14-Mar-2014		144			
B262101	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)			339TS I-77193023	MTH 28-Oct-2025 HRS 1959.33 LDG 1704		144		31-Oct-2037	135 m 17 d
5-12-13	INSPECTION DOCUMENT 13				MTH 28-Oct-2025 HRS 1959.33 LDG 1704		12 450		31-Oct-2026 2409.33	3 m 17 d 424.23
5-12-14	INSPECTION DOCUMENT 14				MTH 28-Oct-2025 HRS 1959.33 LDG 1704		12 900		31-Oct-2026 2859.33	3 m 17 d 874.23
5-12-15	INSPECTION DOCUMENT 15				MTH 04-Nov-2024 HRS 1800.8 LDG 1575		24 1350		30-Nov-2026 3150.8	4 m 16 d 1165.7
5-12-16	INSPECTION DOCUMENT 16				MTH 04-Nov-2024 HRS 1800.8 LDG 1575		36 1350		30-Nov-2027 3150.8	16 m 16 d 1165.7
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK			HM50C-3 451B	29-10-00-720 MTH 04-Nov-2024 HRS 1800.8 LDG 1575		36 1350		30-Nov-2027 3150.8	16 m 16 d 1165.7
5-12-17	INSPECTION DOCUMENT 17				MTH 04-Nov-2024 HRS 1800.8 LDG 1575		36 1800		30-Nov-2027 3600.8	16 m 16 d 1615.7
5-12-18	INSPECTION DOCUMENT 18				MTH 04-Nov-2024 HRS 1800.8 LDG 1575		36 2250		30-Nov-2027 4050.8	16 m 16 d 2065.7
5-12-20	INSPECTION DOCUMENT 20				MTH 04-Nov-2024 HRS 1800.8 LDG 1575		48 2700		30-Nov-2028 4500.8	28 m 16 d 2515.7
5-12-21	INSPECTION DOCUMENT 21				MTH 28-Oct-2025 HRS 1959.33 LDG 1704		12		31-Oct-2026	3 m 17 d
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KIWA			MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24			
B341001	CALIBRATION TEST INDICATOR 14 CFR PART 91.411	KIWA		261440-1143 289921A	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
Calibration Date: 29-Jun-2026										
B341001	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KIWA		011-01110-01 1SW005906	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
Calibration Date: 29-Jun-2026										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 2	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411	KIWA		011-01110-01 1SW005943	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
Calibration Date: 29-Jun-2026										
B341001 STANDBY	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411	KIWA		162350-1161 1000310C	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
Calibration Date: 29-Jun-2026										
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)	KIWA			MTH 29-Jun-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
B345000 LEFT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KIWA		011-00779-21 84813624	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
Calibration Date: 29-Jun-2026										
B345000 RIGHT	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413	KIWA		010-01776-03 51Y003431	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		24		30-Jun-2028	23 m 16 d
Calibration Date: 29-Jun-2026										
5-12-28	INSPECTION DOCUMENT 28 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 14-Mar-2014 HRS 0 LDG 0		A/R			
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)			3-1640 1047	MTH 19-Jul-2024 HRS 1727.28 LDG 1487		A/R			
B324000 NOSE	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)			3-1642 0551	MTH 14-Mar-2014		A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)			3-1640 1046	MTH 19-Jul-2024 HRS 1727.28 LDG 1487		A/R			
5-12-30	INSPECTION DOCUMENT 30				MTH 25-May-2022 HRS 1146.9 LDG 1073		48 1800		31-May-2026 2946.9	-1 m 14 d 961.8
Over Due										
5-12-31	INSPECTION DOCUMENT 31				MTH 04-Nov-2024 HRS 1800.8 LDG 1575		450		2250.8	265.7
5-12-32	INSPECTION DOCUMENT 32	LFPB			MTH 16-Mar-2020 HRS 405.55 LDG 459		72 1800		31-Mar-2026 2259	-3 m 14 d 545
Over Due										
5-12-34	INSPECTION DOCUMENT 34 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 28-Oct-2025 HRS 1959.33 LDG 1704		12 900			
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY TELEDYNE GILL LEAD-ACID BATTERY (CAPACITY CHECK)			S4324-1 G03301022	MTH 28-Oct-2025 HRS 1959.33 LDG 1704		12 900		31-Oct-2026 2859.33	3 m 17 d 874.23



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-35	INSPECTION DOCUMENT 35			MTH HRS LDG	28-Oct-2025 1959.33 1704		6		30-Apr-2026	-2 m 14 d
										Over Due
5-12-37	INSPECTION DOCUMENT 37			MTH HRS	14-Mar-2014 0		7200		7200	5214.9
5-12-MA	INSPECTION DOCUMENT MA			MTH HRS	12-Apr-2023 1579.6		500		2079.6	94.5
5-12-MB	INSPECTION DOCUMENT MB			MTH HRS LDG	04-Nov-2024 1800.8 1575		950		2750.8	765.7
5-12-MC	INSPECTION DOCUMENT MC			MTH HRS	14-Mar-2014 0		4000		4000	2014.9
5-12-MD	INSPECTION DOCUMENT MD			MTH HRS LDG	28-Oct-2025 1959.33 1704		12		31-Oct-2026	3 m 17 d
5-12-ME	INSPECTION DOCUMENT ME			MTH HRS LDG	22-Feb-2023 1463.8 1295		36 1400		28-Feb-2026 2863.8	-4 m 14 d 878.7
										Over Due
5-12-MF	INSPECTION DOCUMENT MF			MTH HRS	14-Mar-2014 0		12000		12000	10014.9
5-12-MG	INSPECTION DOCUMENT MG			MTH HRS	14-Mar-2014 0		5000		5000	3014.9
5-12-MH	INSPECTION DOCUMENT MH			MTH HRS	14-Mar-2014 0		8250		8250	6264.9
5-12-MI	INSPECTION DOCUMENT MI			MTH HRS	14-Mar-2014 0		12000		12000	10014.9
5-12-MJ	INSPECTION DOCUMENT MJ			MTH HRS	14-Mar-2014 0		10600		10600	8614.9
5-12-MK	INSPECTION DOCUMENT MK			MTH HRS	14-Mar-2014 0		10400		10400	8414.9
SIB_AIR22-10	CRITICAL - DETAILED VISUAL INSPECTION OF COWL QUARTER-TURN FASTENERS			MTH HRS LDG	28-Oct-2025 1959.33 1704		12		31-Oct-2026	3 m 17 d
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE			MTH HRS LDG	22-Apr-2024 1644.6 1437		A/R			
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS	14-Mar-2014		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH			DAYS	14-Mar-2014		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS HRS LDG	10-Nov-2021 1108.63 1047		A/R			
262003A LEFT	REPLACE FIRE EXT CARTRIDGE			13083-5 ESD221886-001	MTH HRS	12-Apr-2023 1579.6	72	5	30-Nov-2028	28 m 16 d
262003A RIGHT	REPLACE FIRE EXT CARTRIDGE			13083-5 ESD221886-001	MTH HRS	12-Apr-2023 1579.6	72	5	30-Nov-2028	28 m 16 d



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
C273000 --	LUBRICATION -- ELEVATOR TRIM TAB ACTUATOR			MTH PN SN-UNKNOWN	04-Nov-2024 1800.8 1575		N/A			
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)			MTH HRS LDG	10-Nov-2021 1108.6 1047		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)			MTH HRS LDG	20-Oct-2020 603.4 599		A/R			
32-30-40-960	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)			9914678-3 8420	MTH HRS LDG	30-May-2025 1907 1660	36		31-Mar-2028	20 m 17 d
Hydro Check Date: 25-Mar-2025										
32-40-00-960	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)	LFPB		9914678-4 6892	MTH HRS LDG	24-Mar-2025 1873.95 1629	36		30-Nov-2027	16 m 16 d
Hydro Check Date: 07-Nov-2024										
35-00-00-960	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST			4441073-040 552367102	MTH	15-Dec-2022	60		30-Nov-2027	16 m 16 d
Hydro Check Date: 15-Dec-2022										
711000 2623 NO. 1	NO.1 ENGINE - DETAILED VISUAL INSPECTION OF THE COWL QUARTER-TURN FASTENER WHENEVER OPENING AND CLOSING OF ENGINE COWLINGS (TO BE ACTIVATED WHENEVER THERE IS OPENING AND CLOSING OF THE ENGINE COWLINGS)			MTH			A/R			
711000 2623 NO. 2	NO.2 ENGINE - DETAILED VISUAL INSPECTION OF THE COWL QUARTER-TURN FASTENER WHENEVER OPENING AND CLOSING OF ENGINE COWLINGS (TO BE ACTIVATED WHENEVER THERE IS OPENING AND CLOSING OF THE ENGINE COWLINGS)			MTH			A/R			
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION			MTH HRS LDG	28-Oct-2025 1959.33 1704		12 450		31-Oct-2026 (2409.33)2409.33	3 m 17 d 424.23
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION			MTH HRS LDG	30-May-2025 1907 1660		12 450		31-May-2026 (2265.78)2357	-1 m 14 d 371.9
Over Due										
71-00-00-760-813 E1	CHECK NO.5 POWER ASSURANCE TEST			MTH HRS LDG	21-Nov-2025 1959.33 1704		A/R			
71-00-00-760-813 E2	CHECK NO.5 POWER ASSURANCE TEST			MTH HRS LDG	21-Nov-2025 1959.33 1704		A/R			
710010 E1	COMPRESSOR DESALINATION WASH			MTH HRS LDG	10-Nov-2021 1108.63 1047		A/R			
710010 E2	COMPRESSOR DESALINATION WASH			MTH HRS LDG	10-Nov-2021 1199.83 1120		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
710020 E1	COMPRESSOR PERFORMANCE RECOVERY WASH		MTH HRS LDG	21-Nov-2025 1959.33 1704		A/R			
710020 E2	COMPRESSOR PERFORMANCE RECOVERY WASH		MTH HRS LDG	21-Nov-2025 1959.33 1704		A/R			
72-00-00-620-804- 01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-804- 01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-804- 02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	14-Mar-2014		A/R			
72-00-00-620-804- 02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	14-Mar-2014		A/R			
72-00-00-620-804- 03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	14-Mar-2014		A/R			
72-00-00-620-804- 03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)		MTH	14-Mar-2014		A/R			
72-00-00-620-805- 01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-805- 01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-805- 02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-805- 02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-806- 01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-806- 01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-620-806- 02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	14-Mar-2014		A/R			
72-00-00-620-806- 02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER		MTH	14-Mar-2014		A/R			
72-00-00-630-804- 01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-630-804- 01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS		MTH	14-Mar-2014		A/R			
72-00-00-630-804- 02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)		MTH	14-Mar-2014		A/R			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)								
			MTH	14-Mar-2014		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)								
			MTH	14-Mar-2014		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)								
			MTH	14-Mar-2014		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY								
			MTH	14-Mar-2014		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY								
			MTH	14-Mar-2014		A/R			
720000 E1	PERFORM ENGINE OVERHAUL		MTH	14-Mar-2014					
			HRS	0		3500		(3500)3500	1514.9
720000 E2	PERFORM ENGINE OVERHAUL		MTH	14-Mar-2014					
			HRS	91.2		3500		(3500)3591.2	1606.1
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION		MTH	09-Nov-2023					
			HRS	1644.57		1750		(3394.57)3394.57	1409.47
			LDG	1437					
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION		MTH	18-Jun-2024					
			HRS	1735.8		1750		(3394.6)3485.8	1500.7
			LDG	1510					
720003 E1	INSPECT LOW UTILIZATION ENGINE		MTH	14-Mar-2014		144		31-Mar-2026	-3 m 14 d
									Over Due
720003 E2	INSPECT LOW UTILIZATION ENGINE		MTH	14-Mar-2014		144		31-Mar-2026	-3 m 14 d
									Over Due
720020 E1	MONITORING OIL CONSUMPTION TREND		MTH	14-Mar-2014		A/R			
720020 E2	MONITORING OIL CONSUMPTION TREND		MTH	14-Mar-2014		A/R			
721030 E1	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER								
			MTH	06-Nov-2023					
			HRS	1644.6		1750		(3394.6)3394.6	1409.5
			LDG	1437					
721030 E2	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER								
			MTH	18-Jun-2024					
			HRS	1735.8		1750		(3394.6)3485.8	1500.7
			LDG	1510					
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER								
			MTH	09-Nov-2023					
			HRS	1644.57		1750		(3394.57)3394.57	1409.47
			LDG	1437					
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER								
			MTH	27-Jan-2023					
			HRS	1496.3		1750		(3155.1)3246.3	1261.2
			LDG	1329					
731020 E1	CHECK AND REPLACE FUEL FILTER ELEMENT								
			MTH	28-Oct-2025		12		31-Oct-2026	3 m 17 d
			HRS	1959.33		900		(2859.33)2859.33	874.23
			LDG	1704					



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731020 E2	CHECK AND REPLACE FUEL FILTER ELEMENT			MTH HRS LDG	30-May-2025 1906.98 1660		12 900		31-May-2026 (2715.78)2806.98	-1 m 14 d 821.88
Over Due										
731055 E1	REPLACE FUEL MANIFOLD			35C6160-01 DEAAAA99274	MTH HRS LDG		1750		(3394.57)3394.57	1409.47
731055 E2	REPLACE FUEL MANIFOLD			35C6160-01 DEAAAB04749	MTH HRS LDG		1750		(3394.6)3485.8	1500.7
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN	MTH HRS LDG		1750		(3394.57)3394.57	1409.47
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			35C3388-01 WDA102586	MTH HRS LDG		1750		(3394.6)3485.8	1500.7
772001 E1	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			PN SN-UNKNOWN	MTH HRS LDG		1750		(3394.57)3394.57	1409.47
772001 E2	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY			35C4518-01 WDAAD001233	MTH HRS LDG		1750		(3394.6)3485.8	1500.7
790010 E1	CHANGE ENGINE OIL/MONITOR /ANALYZE OIL QUALITY			MTH HRS LDG	28-Oct-2025 1959.33 1704		O/C			
790010 E2	CHANGE ENGINE OIL/MONITOR /ANALYZE OIL QUALITY			MTH HRS LDG	28-Oct-2025 1959.33 1704		O/C			
790015 E1	REPLACE OIL FILTER ELEMENT			MTH HRS LDG	19-Jul-2024 1727.28 1487	72.72	900		(2700)2700	714.9
790015 E2	REPLACE OIL FILTER ELEMENT			MTH HRS LDG	18-Jun-2024 1735.8 1510		900		(2544.6)2635.8	650.7
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL			MTH HRS LDG	06-Nov-2023 1644.6 1437		1750		(3394.6)3394.6	1409.5
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL			MTH HRS LDG	18-Jun-2024 1735.8 1510		1750		(3394.6)3485.8	1500.7

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY.			0113-12 2175	MTH 14-Mar-2014		O/C	0		
213001	KAPS II CONTROLLER			9912661-6 1403	MTH 14-Mar-2014		O/C	0		
213002 NO. 1	KAPS II OUTFLOW VALVE			9912661-7 1665	MTH 14-Mar-2014		O/C	0		
213002 NO. 2	KAPS II OUTFLOW VALVE			9912661-7 1666	MTH 14-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14			1133610-4 555	MTH 14-Mar-2014		O/C	0		
215002	CONDENSOR ASSEMBLY 9912660-3			1134620-5 687	MTH 14-Mar-2014		O/C	0		
215003	RECEIVER DRYER ASSY 9912660-18			1134275-13 154	MTH 14-Mar-2014		O/C	0		
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7			9912660-7 414A	MTH 21-Nov-2025 HRS 1959.33 LDG 1704		O/C	0 0 0		
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7			1133300-1 1032	MTH 14-Mar-2014		O/C	0		
215005	VANE AXIAL BLOWER ASSY.			1250435-10 1581B	MTH 29-Jul-2024 HRS 1735.8 LDG 1494		O/C	0 0 0		
215007	FREON COMPRESSOR DRIVE MODULE ASSEMBLY 1134146-6 927A				MTH 11-Jul-2020 HRS 488.9 LDG 518		O/C	11 0 0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD 1251171-12 NSN				MTH 04-Nov-2024 HRS 1800.8 LDG 1575 ACH 774.9			0 0 0 0	1574.9	745.3
216000 LH	THERMAL ACTUATOR 74S235H6F255 NSN				MTH 28-Mar-2019 HRS 305.4 LDG 367		O/C	0 0 0		
216000 RH	THERMAL ACTUATOR 74S235H6F255 NSN				MTH 02-Jan-2019		O/C	0		
221001 AILERON	GSA 80 TORQUE SERVO 011-00877-00 66307994				MTH 03-May-2023 HRS 1608.8 LDG 1391		O/C			
221001 RUDDER	GSA 80 TORQUE SERVO 011-00877-00 66307411				MTH 03-May-2023 HRS 1608.8 LDG 1391		O/C			
221002 ELEVATOR	GSA 81 TORQUE SERVO 011-00878-10 71308805				MTH 14-Mar-2014		O/C	0		
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO 011-00878-10 71308681				MTH 05-Sep-2021 HRS 994.5 LDG 942		O/C			
221003 AILERON	GSM 85A SERVO MOUNT 011-01436-A2 10905402				MTH 14-Mar-2014		O/C	0		
221003 ELEVATOR	GSM 85A SERVO MOUNT 011-01436-A0 11205420				MTH 14-Mar-2014		O/C	0		
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT 011-01436-A1 11305405				MTH 14-Mar-2014		O/C	0		
221003 RUDDER	GSM 85 SERVO MOUNT 011-01436-A3 11005489				MTH 14-Mar-2014		O/C	0		
221004	GMC 710 AFCS CONTROLLER 011-01020-10 22006744				MTH 14-Mar-2014		O/C	0		
231002 NO. 1	GMA 1347D AUDIO PANEL 011-01257-20 17107533				MTH 14-Mar-2014		O/C	0		
231002 NO. 2	GMA 1347D AUDIO PANEL 011-01257-20 17107536				MTH 14-Mar-2014		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
231003 NO. 1	VHF COMM ANTENNA			VHF10-829 1479	MTH 14-Mar-2014		O/C	0		
231003 NO. 2	VHF COMM ANTENNA			VHF10 - 829 4394	MTH 27-Jan-2023 HRS 1405.1 LDG 1256		O/C	0 0 0		
231011	SAT PHONE ANTENNA			S67-1575-109 13059	MTH 14-Mar-2014		O/C	0		
231101	HIGH FREQUENCY CONTROLLER S3100-470			071-01605-0201 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
231102	HIGH FREQUENCY RECEIVER/ EXCITER S3100-449			064-01073-0102 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
231103	HIGH FREQUENCY ANTENNA			16390 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
231104	HIGH FREQUENCY POWER AMPLIFIER			064-01072-0101 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
243001 LEFT	DIGITAL GCU 9912682-1 OR 9912682-3			51525-001F P6219	MTH 14-Mar-2014		O/C	0		
243001 RIGHT	DIGITAL GCU 9912682-3 OR 9912682-3			51525-001F Y1113	MTH 28-Aug-2024 HRS 1758.68 LDG 1544		O/C			
243002	EMER INST BATTERY			CBS24 01033	MTH 30-May-2025 HRS 1907 LDG 1660		O/C			
243007	MAIN SHIP BATTERY TELEDYNE GILL LEAD ACID			S4324-1 G03301022	MTH 28-Oct-2025 HRS 1959.33 LDG 1704		O/C	0 0 0		
243015	RELAY DISCONNECT BATTERY S3155-1			A-931F CT-42724	MTH 14-Mar-2014		O/C	0		
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY ZPPP			7018920-5 1174	MTH 13-Aug-2016 HRS 90.4 LDG 119		O/C	0 0 0		
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY			7018920-5 1090	MTH 14-Mar-2014		O/C	0		
245003	FLAP CONTROL MODULE EHAM			7018916-9 0687	MTH 10-Nov-2017 HRS 221.13 LDG 271		O/C	0 0 0		
245005 LEFT	ICE PROTECTION CONTROL ICT			7018917-9 0586	MTH 07-Jul-2014 HRS 10.1 LDG 18		O/C	0 0 0		
245005 RIGHT	ICE PROTECTION CONTROL			7018918-13 0596	MTH 14-Mar-2014		O/C	0		
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL			7018919-13 1035	MTH 28-Mar-2019 HRS 305.4 LDG 367		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL			7018919-13 0952	MTH 28-Mar-2019 HRS 305.4 LDG 367		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245008	DOOR MONITOR-			7018921-8 0546	MTH 14-Mar-2014		O/C	0		
245009	LANDING GEAR MONITOR-			7018923-12 0556	MTH 14-Mar-2014		O/C	0		
245010 LEFT	START CONTROL	KGSO		7018924-12 0557	MTH 28-Sep-2016 HRS 100.4 LDG 105 ACH 80.4		O/C	0 0 0		
245010 RIGHT	START CONTROL	KGSO		7018924-12 0556	MTH 28-Sep-2016 HRS 100.4 LDG 105 ACH 80.4		O/C	0 0		
245011	FLAP MONITOR-			7018925-11 0589	MTH 14-Mar-2014		O/C	0		
245012 LEFT	SPEEDBRAKE ASSY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
245012 RIGHT	SPEEDBRAKE ASSY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
245013	DIAGNOSTIC UNIT			7018927-7 0634	MTH 14-Mar-2014		O/C	0		
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3			85-230-2 1233006	MTH 14-Mar-2014		O/C	0		
245015	MASTER INTERIOR SSR UNIT UZ100			10747P03E25 13058834	MTH 14-Mar-2014		O/C	0		
245016 RIGHT	AVN BUS #1 SENSOR UZ102			10747P03E25 13048831	MTH 14-Mar-2014		O/C	0		
245017 LEFT	AVN SENSOR UZ103			10747P03E25 13058846	MTH 14-Mar-2014		O/C	0		
245018 RIGHT	AVN BUS #2 SENSOR UZ104			10747P03E25 13058837	MTH 14-Mar-2014		O/C	0		
245019 LEFT	IGN #1 SENSOR UZ105			10747P03E10 12078642	MTH 14-Mar-2014		O/C	0		
245019 RIGHT	IGN #1 SENSOR UZ106			10747P03E10 12078652	MTH 14-Mar-2014		O/C	0		
245020 LEFT	IGN #2 SENSOR UZ107			10747P03E10 12058537	MTH 14-Mar-2014		O/C	0		
245020 RIGHT	IGN #2 SENSOR UZ108			10747P03E10 12078650	MTH 14-Mar-2014		O/C	0		
245021	COCKPIT FAN SENSOR UZ109			10747P03E25 13058836	MTH 14-Mar-2014		O/C	0		
245022	CABIN FAN SENSOR UZ110			10747P03E25 13058841	MTH 14-Mar-2014		O/C	0		
245023 LEFT	LH BOOST PUMP SENSOR UZ114			10747P03E25 13058847	MTH 14-Mar-2014		O/C	0		
245023 RIGHT	RH BOOST PUMP SENSOR UZ111			10747P03E25 13048829	MTH 14-Mar-2014		O/C	0		
245024	CONDENSER FAN SENSOR UZ112			10747P03E25 13058840	MTH 14-Mar-2014		O/C	0		
245025	DC-DC CONVERTER UZ116			10747P03E10 12078651	MTH 14-Mar-2014		O/C	0		
245026	AVN EMERG SENSOR UZ200			10747P03E25 13058838	MTH 14-Mar-2014		O/C	0		
245201 LEFT	CABIN ALTITUDE MODULE			7018119-1 1245	MTH 14-Mar-2014		O/C	0		
245201 RIGHT	CABIN ALTITUDE MODULE			7018119-1 1247	MTH 14-Mar-2014		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
246030 LEFT	MULTI FUNCTION DISPLAY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
246030 RIGHT	MULTI FUNCTION DISPLAY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
251001	GLARESHIELD ASSEMBLY			4319027-17 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
256001 NO. 1	LIFE VEST	LEVC		P01074-207 23051200269	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		60	0 0 0	01-May-2028	21 m 17 d
Manufacture Date: 01-May-2023										
256001 NO. 2	LIFE VEST	LEVC		P01074-207 23051200270	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		60	0 0 0	01-May-2028	21 m 17 d
Manufacture Date: 01-May-2023										
256001 NO. 3	LIFE VEST	LEVC		P01074-207 23051200268	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		60	0 0 0	01-May-2028	21 m 17 d
Manufacture Date: 01-May-2023										
256001 NO. 4	LIFE VEST	LEVC		P01074-207 23051200279	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		60	0 0 0	01-May-2028	21 m 17 d
Manufacture Date: 01-May-2023										
256001 NO. 5	LIFE VEST	LEVC		P01074-207 23051200272	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		60	0 0 0	31-Dec-2028	29 m 17 d
256001 NO. 6	LIFE VEST	LEVC		P01074-207 23051200275	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		60	0 0 0	31-Dec-2028	29 m 17 d
256002	ELT BATTERY			452-0133 395797-003	MTH 27-Jan-2023 HRS 1405.1 LDG 1256		60	0 0 0	01-Jul-2027	11 m 17 d
256004	ELT ANTENNA			110-340 395570	MTH 14-Mar-2014		O/C	0		
256007	ELT PROCESSOR C406N			453-5060 13913	MTH 14-Mar-2014		O/C	0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 213153	MTH 14-Mar-2014		O/C	0		
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1			3001-212-1004/455-9 213187	MTH 14-Mar-2014		O/C	0		
262001	FIRE EXTINGUISHER BOTTLE 9912048-6			30401102-2 59585B1	MTH 12-Apr-2023 HRS 1579.6		O/C	0 0		
262003 LEFT	FIRE EXT CARTRIDGE			13083-5 ESD221886-001	MTH 12-Apr-2023 HRS 1579.6 LDG 1385		72	5 0 0	30-Nov-2028	28 m 16 d
Manufacture Date: 01-Nov-2022										
262003 RIGHT	FIRE EXT CARTRIDGE			13083-5 ESD221886-001	MTH 12-Apr-2023 HRS 1579.6		72	5 0	30-Nov-2028	28 m 16 d
Manufacture Date: 01-Nov-2022										
262004	PORTABLE FIRE EXTINGUISHER			339TS I-77193023	MTH 28-Oct-2025 HRS 1959.33 LDG 1704		O/C	0 0 0		
271001 LEFT	CONTROL WHEEL ASSY			4319065-3 2021	MTH 14-Mar-2014		O/C	0		
271001 RIGHT	CONTROL WHEEL ASSY			4319065-4 2056	MTH 14-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
271002 --	ELEVATOR TRIM TAB ACTUATOR			PN SN-UNKNOWN	MTH 14-Mar-2014		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR 9912639-2			SYLC-53361-1 0761	MTH 14-Mar-2014		O/C	0		
273002	AILERON TRIM ACTUATOR 9912639-2			SYLC-53361-1 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1			MP50Y-1 462AC	MTH 14-Mar-2014		O/C	0		
275002 LEFT	FLAP ACTUATOR 9912640-1			41013930-105 0930	MTH 14-Mar-2014		O/C	0		
275002 RIGHT	FLAP ACTUATOR 9912640-2			41013930-106 1059	MTH 14-Mar-2014		O/C	0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-59	KGSO		140527-5900 0635	MTH 28-Sep-2016 HRS 100.4 LDG 105 ACH 80.4		O/C	0 0 0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY 9914344.59			140527-5900 0591	MTH 14-Mar-2014		O/C	0		
276001 LEFT	SPEED BRAKE ACTUATOR			2R5211A 0146	MTH 14-Mar-2014		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR			2R5212A 0152	MTH 14-Mar-2014		O/C	0		
282001 LEFT	PRIMARY EJECTOR 9912190-5			LR45300A C2175	MTH 14-Mar-2014		O/C	0		
282001 RIGHT	PRIMARY EJECTOR 9912190-5			LR45300A C2174	MTH 14-Mar-2014		O/C	0		
282002	TRANSFER VALVE 9914103-6			ZSV57 13-0423251	MTH 14-Mar-2014		O/C	0		
282003 LEFT	DC FUEL PUMP 9912553-1			1C7-23 10BH79	MTH 14-Mar-2014		O/C	0		
282003 RIGHT	DC FUEL PUMP 9912553-1			1C7-23 10BH81	MTH 14-Mar-2014		O/C	0		
282004 L1	SCAVENGE EJECTOR 9912190-2			RG45310 C3435	MTH 14-Mar-2014		O/C	0		
282004 L2	SCAVENGE EJECTOR 9912190-2			RG45310 C3432	MTH 14-Mar-2014		O/C	0		
282004 R1	SCAVENGE EJECTOR 9912190-2			RG45310 C3293	MTH 14-Mar-2014		O/C	0		
282004 R2	SCAVENGE EJECTOR 9912190-2			RG45310 C3436	MTH 14-Mar-2014		O/C	0		
282005 LEFT	VALVE-FUEL MOTOR 9912014-3			AV24B1507 AA421081	MTH 14-Mar-2014		O/C	0		
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3			AV24B1507 AA421076	MTH 14-Mar-2014		O/C	0		
284001 L1	FUEL PROBE 9912664-1			020-251-001 1098	MTH 14-Mar-2014		O/C	0		
284001 L2	FUEL PROBE 9912664-2			020-251-002 1073	MTH 14-Mar-2014		O/C	0		
284001 L3	FUEL PROBE 9912664-3			020-251-003 1083	MTH 14-Mar-2014		O/C	0		
284001 L4	FUEL PROBE 9912664-4			020-251-004 1100	MTH 14-Mar-2014		O/C	0		
284001 L5	FUEL PROBE 9912664-5			020-251-005 1086	MTH 14-Mar-2014		O/C	0		
284001 R1	FUEL PROBE 9912664-1			020-251-001 1099	MTH 14-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
284001 R2	FUEL PROBE 9912664-2			020-251-002 1099	MTH 14-Mar-2014		O/C	0		
284001 R3	FUEL PROBE 9912664-3			020-251-003 0933	MTH 14-Mar-2014		O/C	0		
284001 R4	FUEL PROBE 9912664-4			020-251-004 1085	MTH 14-Mar-2014		O/C	0		
284001 R5	FUEL PROBE 9912664-5			020-251-005 1085	MTH 14-Mar-2014		O/C	0		
284002	SIGNAL CONDITIONER 9912664-6			367-350-001 1460	MTH 14-Mar-2014		O/C	0		
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2			HM50C-3 451B	MTH 04-Nov-2024 HRS 1800.8 LDG 1575		O/C	128 1800.8 1575		
291002	HYDRAULIC CHECK VALVE			4001-20 6171A	MTH 14-Mar-2014		O/C	0		
291003	HYDRAULIC SYS PRESSURE GAUGE			19940933-1 041630	MTH 14-Mar-2014		O/C	0		
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4			80665 NSN	MTH 14-Mar-2014		O/C	0		
291007	HYDRAULIC MANIFOLD 9912657-14			8257-3 0451	MTH 14-Mar-2014		O/C	0		
291008	HYDRAULIC RELIEF VALVE 9912657-2			2672 0456	MTH 14-Mar-2014		O/C	0		
291009	BRAKE PRESSURE SWITCH 9912657-3			80664 0464	MTH 14-Mar-2014		O/C	0		
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5			4251 0449	MTH 14-Mar-2014		O/C	0		
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7			4252 0445	MTH 14-Mar-2014		O/C	0		
291011	HYDRAULIC DUMP VALVE 9912657-15			9625-1 0454	MTH 14-Mar-2014		O/C	0		
291012	HYDRAULIC RESERVOIR ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2			7550-2 1093	MTH 14-Mar-2014		O/C	0		
301001 LEFT	WING DE-ICE BOOT 9912662-17			P35-4D5317-17 NBM8810	MTH 14-Mar-2014		O/C	0		
301001 RIGHT	WING DE-ICE BOOT EGKB			9912662-18 NGF9720	MTH 11-Sep-2022 HRS 1255.4 LDG 1163		O/C	0 0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3			P29S4D5317-05 NBB4820	MTH 14-Mar-2014		O/C	0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4			P29S4D5317-06 NBA3110	MTH 14-Mar-2014		O/C	0		
301004 L1	DE-ICE PRESSURE SWITCH			1106P55-1 9830A	MTH 14-Mar-2014		O/C	0		
301004 L2	DE-ICE PRESSURE SWITCH			1106P55-1 9843A	MTH 14-Mar-2014		O/C	0		
301004 L3	DE-ICE PRESSURE SWITCH			1106P55-1 9844A	MTH 14-Mar-2014		O/C	0		
301004 R1	DE-ICE PRESSURE SWITCH			1106P55-1 9842A	MTH 14-Mar-2014		O/C	0		
301004 R2	DE-ICE PRESSURE SWITCH			1106P55-1 9845A	MTH 14-Mar-2014		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301004 R3	DE-ICE PRESSURE SWITCH			1106P55-1 9835A	MTH 14-Mar-2014		O/C	0		
301004	VERT DE-ICE BOOT 9912662-13			P29S4D5317-13 NBA3328	MTH 14-Mar-2014		O/C	0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY			5285-00-3 2963	MTH 14-Mar-2014		O/C	0		
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY			5285-00-3 2908	MTH 14-Mar-2014		O/C	0		
302002 LEFT	TEMP SWITCH			1173T0759 6912	MTH 14-Mar-2014		O/C	0		
302002 RIGHT	TEMP SWITCH			1173T0759 6829	MTH 14-Mar-2014		O/C	0		
304001 L1	DE-ICE VALVE			3D2353-06 N131009	MTH 14-Mar-2014		O/C	0		
304001 L2	DE-ICE VALVE			3D2353-06 N131006	MTH 14-Mar-2014		O/C	0		
304002 LEFT	WINDSHIELD CONTROLLER KMCO			7018108-30 0258	MTH 17-Feb-2017 HRS 106.2 LDG 125 ACH 80.4		O/C	3 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER KMCO			7018108-30 0263	MTH 17-Feb-2017 HRS 106.2 LDG 125 ACH 80.4		O/C	2 0 0		
313000	CVDR - COCKPIT VOICE/DATA RECORDER EQUIPMENT 2100-3083-51 879318				MTH 14-Mar-2014		O/C	0		
314105	GSD41 SOFTWARE CONFIGURATION --			011-01457-00 16905674	MTH 29-Apr-2020 HRS 405.55 LDG 459		O/C	1		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY 7041020-5 23606315				MTH 14-Mar-2014 LDG 0		20000	0 0	20000	18286
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY 7041020-6 23606316				MTH 14-Mar-2014 LDG 0		20000	0 0	20000	18286
321001	NOSE LANDING GEAR TRUNNION 7042020-1 23254940				MTH 14-Mar-2014		O/C	0		
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY 7041050-5 23573588C				MTH 14-Mar-2014 LDG 0		12000	0 0	12000	10286
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY 7041050-5 23573588A				MTH 14-Mar-2014 LDG 0		12000	0 0	12000	10286
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY KGSO 7041030-3 23606315				MTH 28-Sep-2016 HRS 100.4 LDG 105 ACH 80.4		20000	30 100.4 105	20000	18286
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY KGSO 7041030-4 23606316				MTH 28-Sep-2016 HRS 100.4 LDG 105 ACH 80.4		20000	30 100.4 105	20000	18286
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK 6327504-6 3425				MTH 14-Mar-2014		O/C	0		
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK 6327504-6 3447				MTH 14-Mar-2014		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
322002	NOSE GEAR FORK & PISTON ASSEMBLY			7042040-6 23532841C	MTH 14-Mar-2014		O/C	0		
322003	UPLOCK ACTUATOR			6327504-7 1678	MTH 14-Mar-2014		O/C	0		
NOSE GEAR										
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR			9912655-1 FA100036-001 0466	MTH 14-Mar-2014 LDG 0		12000	0	12000	10286
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR			9912653-5 FA100104-001 FA100104-1-0454	MTH 14-Mar-2014 LDG 0		12000	0	12000	10286
LEFT										
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR			9912653-6 FA100105-001 FA100105-1-0459	MTH 14-Mar-2014 LDG 0		12000	0	12000	10286
RIGHT										
322011	NOSE LANDING GEAR ACTUATOR			9912654-2 FA100087-001 0456	MTH 14-Mar-2014 LDG 0		12000	0	12000	10286
322202	SHIMMY DAMPER			7042030-2 NSN	MTH 14-Mar-2014		O/C	0		
322205	LANDING GEAR STRUT ASSEMBLY			7042010-6 23591940	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
NOSE										
322206	LANDING GEAR DRAG BRACE ASSY			7042120-5 23620131	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
NOSE	CHP 4									
323001	LANDING GEAR ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
LEFT										
323001	LANDING GEAR ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
RIGHT										
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE			9914678-3 8420	MTH 30-May-2025 HRS 1907 LDG 1660		288	130	31-Jul-2038	144 m 17 d
Manufacture Date: 01-Jul-2014										
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE			9914678-4	MTH 24-Mar-2025		288	4	31-Aug-2033	85 m 17 d
	LFPB			6892	HRS 1873.95 LDG 1629			0 0		
Manufacture Date: 01-Aug-2009										
323003	EMER BLOW DOWN BTL PRESSURE GAUGE			19940931-1 041381	MTH 14-Mar-2014		O/C	0		
324001	MAIN LANDING GEAR TIRE			021-523-0	MTH 19-Jul-2024		O/C	0		
LEFT	9912646-1			3060T00484	HRS 1727.28 LDG 1487			0 0		
324001	MAIN LANDING GEAR TIRE			021-523-0	MTH 19-Jul-2024		O/C	0		
RIGHT	9912646-1			3059T00465	HRS 1727.28 LDG 1487			0 0		
324002	NOSE LANDING GEAR TIRE			079-606-0	MTH 22-Feb-2023		O/C	0		
	9912649-1			1201T00199	HRS 1463.5 LDG 1295			0 0		
324003	MAIN LANDING GEAR WHEEL			3-1640	MTH 19-Jul-2024		O/C	0		
LEFT	9912645-1			1047	HRS 1727.28 LDG 1487			0 0		
324003	MAIN LANDING GEAR WHEEL			3-1640	MTH 19-Jul-2024		O/C	0		
RIGHT	9912645-1			1046	HRS 1727.28 LDG 1487			0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324004 NOSE	NOSE LANDING GEAR WHEEL 9912648-1	LFPB		3-1642 0551	MTH 02-Jul-2021 HRS 906.98 LDG 872		O/C	88 906.98 872		
324005 LEFT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	LEVC		2-1706-1 1045	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		O/C	0 0 0		
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-2	LEVC		2-1706 1106	MTH 18-Dec-2023 HRS 1644.6 LDG 1437		O/C	0 0 0		
324006 LEFT	SHUTTLE VALVE 9914689-4			5145-1 0921	MTH 14-Mar-2014		O/C	0		
324006 RIGHT	SHUTTLE VALVE			3S1172 0255	MTH 30-May-2025 HRS 1907 LDG 1660		O/C			
324007	BRAKE METERING VALVE 9912650-9			84-75 0480	MTH 14-Mar-2014		O/C	0		
324101 LEFT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0017	MTH 14-Mar-2014		O/C	0		
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5			466-23-1 0957	MTH 14-Mar-2014		O/C	0		
324101	PARKING BRAKE VALVE 9912388-10			98433-1 0465	MTH 14-Mar-2014		O/C	0		
324102	ANTISKID CONTROL UNIT 9912650-1			556-3 302829558	MTH 14-Mar-2014		O/C	0		
324103	ANTISKID CONTROL VALVE 9912650-6			211-134-1 0482	MTH 14-Mar-2014		O/C	0		
324104	EMERGENCY BRAKE VALVE 9912651-1			72298 0497	MTH 14-Mar-2014		O/C	0		
324105	EMER BRAKE BOTTLE PRESSURE GAUGE			19940931-1 041608	MTH 14-Mar-2014		O/C	0		
325001	BUNGE ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
334001 LEFT	POWER SUPPLY	UNK		9912677-3 001191	MTH 27-Jul-2020 HRS 512.6 LDG 528		O/C	5 0 0		
334001 RIGHT	POWER SUPPLY			9912677-3 001016	MTH 14-Mar-2014		O/C	0		
334002	GROUND RECOGNITION LIGHT			84003-4 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
334003 LEFT	ANTI-COLLISION LIGHT			84056-1 000268	MTH 14-Mar-2014 HRS 0		8000	0	8000	6014.9
334003 RIGHT	ANTI-COLLISION LIGHT			84056-2 000253	MTH 14-Mar-2014 HRS 0		8000	0	8000	6014.9
341001	SWAAT UNIT 9912689-1	ICT		0863B2 67	MTH 07-Jul-2014 HRS 10.1 LDG 18		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM KFXE			011-01110-01 1SW005906	MTH 31-Oct-2016 HRS 102.3 LDG 119 ACH 80.4		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341002 NO. 2	GDC 74B AIRDATA SYSTEM			011-01110-01 1SW005943	MTH 14-Mar-2014		O/C	0		
341003 NO. 1	GTP 59 OAT PROBE SYSTEM			011-00978-00 47922558	MTH 14-Mar-2014		O/C	0		
341003 NO. 2	GTP 59 OAT PROBE SYSTEM			011-00978-00 47922566	MTH 14-Mar-2014		O/C	0		
341004 LEFT	PITOT PROBE 9912678-1			0851LN 300909	MTH 14-Mar-2014		O/C	0		
341004 RIGHT	PITOT PROBE 9912678-1			0851LN 300908	MTH 14-Mar-2014		O/C	0		
342001 STANDBY	ALTIMETER S3100-465			162350-1161 1000310C	MTH 14-Mar-2014		O/C	0		
342002 AIRSPEED	INDICATOR	KGSO		261440-1143 289921A	MTH 28-Sep-2016 HRS 100.4 LDG 105 ACH 80.4		O/C	2 0 0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE			011-00831-00 46716630	MTH 14-Mar-2014		O/C	0		
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE			011-00831-00 46716629	MTH 14-Mar-2014		O/C	0		
342003	MAGNETIC COMPASS			S2800-821 NSN	MTH 14-Mar-2014		O/C	0		
342004 NO. 1	NO. 1 GDU 1050A DISPLAY	KIWA		011-03470-10 494108981	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		O/C	0 0 0		
342004 NO. 2	NO. 2 GDU 1050A DISPLAY	KIWA		011-03470-10 494109005	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517			011-00868-10 42023370	MTH 14-Mar-2014		O/C	0		
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517			011-00868-10 42023368	MTH 14-Mar-2014		O/C	0		
342006 NO. 1	GMU 44 MAGNETOMETER	EGKB		011-00870-00 47511272	MTH 11-Sep-2022 HRS 1255.4 LDG 1163		O/C	0 0 0		
342006 NO. 2	GMU 44 MAGNETOMETER			011-00870-00 47524511	MTH 30-May-2025 HRS 1907 LDG 1660		O/C			
342007	GDU 1550 MFD UNIT	KIWA		010-01310-00 496003038	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513			4200-21 C13-11164	MTH 14-Mar-2014		O/C	0		
3420SD	FLIGHT STREAM 510 SOFTWARE SD CARD	KIWA		010-01322-05 59Q007250	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		O/C	0 0 0		
344001	GWX 68 WEATHER RADAR			011-00883-20 47202258	MTH 14-Mar-2014		O/C	0		
344002	GARMIN GDL-69A DATA LINK			011-00987-00 47766734	MTH 14-Mar-2014		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
344005 LEFT	(KRA-405B) RADAR ALTIMETER ANTENNA			S67-2002-4 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
344005 RIGHT	(KRA-405B) RADAR ALTIMETER ANTENNA			S67-2002-4 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
344006	(KRA-405B) RADAR ALTIMETER			066-01153-0202 KRA405B-14790	MTH 14-Mar-2014		O/C	0		
345001	GPS/WAAS/XM ANTENNA			013-00245-00 10877	MTH 14-Mar-2014		O/C	0		
345002 RIGHT	RIGHT GTX345 TRANSPONDER KIWA			010-01776-03 51Y003431	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		O/C	0 0 0		
345003 LEFT	TRANSPONDER	LFPB		011-00779-21 84813624	MTH 29-Apr-2020 HRS 405.55 LDG 459		O/C	7 0 0		
345004	GCU 475 FLIGHT MGMT CONTROL UNIT KIWA			011-04475-00 48V001593	MTH 01-Jul-2026 HRS 1983.5 LDG 1713		O/C	0 0 0		
345006	ADF ANTENNA			013-00165-00 3809	MTH 14-Mar-2014		O/C	0		
345007	MARKER BEACON ANTENNA			MB10-754-2 0633	MTH 14-Mar-2014		O/C	0		
345008	GLIDE SLOPE ANTENNA			RGS10-48 17295	MTH 14-Mar-2014		O/C	0		
345009 LEFT	L-BAND TRANSPONDER ANTENNA			L10-611-14 5227	MTH 14-Mar-2014		O/C	0		
345009 RIGHT	L-BAND TRANSPONDER ANTENNA			L10-611-14 5440	MTH 14-Mar-2014		O/C	0		
345009 UPPER	L-BAND TRANSPONDER ANTENNA			L10-611-14 5171	MTH 14-Mar-2014		O/C	0		
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA			L10-611-14 20397	MTH 05-Nov-2025 HRS 1959.33 LDG 1704		O/C	0 0 0		
345010 LEFT	NAV ANTENNA			VT11-767-3 1448	MTH 14-Mar-2014		O/C	0		
345010 RIGHT	NAV ANTENNA			VT11-767-3 1448	MTH 14-Mar-2014		O/C	0		
345011	KN63 DME TRANSCEIVER			066-01070-0001 36648	MTH 14-Mar-2014		O/C	0		
345014	GPS/WAAS/ ANTENNA			013-00244-00 9765	MTH 14-Mar-2014		O/C	0		
345015	DME ANTENNA			L10-611-14 5166	MTH 14-Mar-2014		O/C	0		
345080	SURVEILLANCE PROCESSOR 4 MCU -- LFPB			066-01152-0101 KTA810-3068	MTH 29-Apr-2020 HRS 405.55 LDG 459		O/C	2 0 0		
346011 BOTTOM	TAS ANTENNA			L10-611-14 5255	MTH 14-Mar-2014		O/C	0		
346011 TOP	TAS ANTENNA	LFPB		071-01599-0100 32357	MTH 29-Apr-2020 HRS 405.55 LDG 459		O/C	2 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
346012	CONFIGURATION MODULE			071-00112-0200 18845	MTH 14-Mar-2014		O/C	0		
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT			011-01105-20 1HQ008382	MTH 14-Mar-2014		O/C	0		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT			011-01105-20 1HQ005810	MTH 14-Mar-2014		O/C	0		
350001	OXYGEN BOTTLE			4441073-040 552367102	MTH 27-Jan-2023 HRS 1405.17 LDG 1256		180	1	30-Nov-2027	16 m 16 d
Manufacture Date: 01-Apr-2013										
350002	OXYGEN PRESSURE GAUGE C668512-0101			MD97-1 J12-11166	MTH 14-Mar-2014		O/C	0		
351001 LEFT	CREW OXYGEN MASK 9914067-41	LIPR		MC10-16-101 119486	MTH 06-Sep-2024 HRS 1768.93 LDG 1552		72	0 0 0	31-Aug-2030	49 m 17 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41			MC10-16-101 99760	MTH 30-May-2025 HRS 1907 LDG 1660		72	3 0 0	28-Feb-2031	55 m 14 d
353000	PROTECTIVE BREATHING EQUIPMENT - REPLACE (DISCARD)			MR10051N E2002603	MTH 07-Feb-2021 HRS 678.9 LDG 675		120	0 0 0	01-Feb-2031	54 m 18 d
Manufacture Date: 01-Aug-2020										
361001 LEFT	PRECOOLER 9914402-7			8315-2 T0912	MTH 14-Mar-2014		O/C	0		
361001 RIGHT	PRECOOLER 9914402-7			8315-2 T0911	MTH 14-Mar-2014		O/C	0		
361002 LEFT	VARIABLE VENTURI VALVE ASSY			2601-34 0918A	MTH 14-Mar-2014		O/C	0		
361002 RIGHT	VARIABLE VENTURI VALVE ASSY			2601-34 0917A	MTH 14-Mar-2014		O/C	0		
361003	SERVICE AIR REGULATOR ASSY 9912510-2			1H75-23 5BJ3	MTH 14-Mar-2014		O/C	0		
361004 LEFT	B/A SHUTOFF VALVE			5253-00-3 SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
361004 RIGHT	B/A SHUTOFF VALVE			5253-00-3 3464	MTH 14-Mar-2014		O/C	0		
361101 R1	DE-ICE VALVE			3D2353-06 N132598	MTH 14-Mar-2014		O/C	0		
361101 R2	DE-ICE VALVE			3D2353-06 N132601	MTH 14-Mar-2014		O/C	0		
522001	CABIN DOOR SEAL 9912674-3			S-22560-3 581	MTH 14-Mar-2014		O/C	0		
522002	ESCAPE HATCH SEAL 9912675-1			S-22561 625	MTH 14-Mar-2014		O/C	0		
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY			7013022-15 123	MTH 14-Mar-2014 LDG 0		20000	0 0	20000	18286
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY			7013022-16 TSW0116	MTH 14-Mar-2014 LDG 0		20000	0 0	20000	18286
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY CHP 4			7013022-17 TSW0063A	MTH 14-Mar-2014 LDG 0		20000	0 0	20000	18286
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY CHP 4			7013022-18 TSW0099	MTH 14-Mar-2014 LDG 0		20000	0 0	20000	18286



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
533100	AFT PRESSURE BULKHEAD WEB BOND ASSEMBLY			7011190-1-1 23211915	MTH 14-Mar-2014		O/C	0		
534101 FWD	ENGINE BEAM			7012061-3 23134397	MTH 14-Mar-2014		O/C	0		
552001 LEFT	ELEVATOR ASSEMBLY			7034001-9 23655728	MTH 14-Mar-2014		O/C	0		
552001 RIGHT	ELEVATOR ASSEMBLY			7034001-10 23655728	MTH 26-Jul-2024 HRS 1735.8 LDG 1494		O/C			
553001	VERTICAL STABILIZER ASSY			7031001-801-17 23681199	MTH 14-Mar-2014		O/C	0		
561001 LEFT	WINDSHIELD ASSY, (LH)			NP-188601-13 12363H1059	MTH 14-Mar-2014		O/C	0		
561001 RIGHT	WINDSHIELD ASSY, (RH)			NP-188601-14 12272H1747	MTH 14-Mar-2014		O/C	0		
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW			93310-1 2009	MTH 14-Mar-2014		O/C	0		
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW			93310-2 2018	MTH 14-Mar-2014		O/C	0		
562003 L1	CABIN WINDOW			93320-13 1636	MTH 14-Mar-2014		O/C	0		
562003 L2	CABIN WINDOW			93320-13 1710	MTH 14-Mar-2014		O/C	0		
562003 L3	CABIN WINDOW			93320-13 1706	MTH 14-Mar-2014		O/C	0		
562003 R1	CABIN WINDOW			93320-13 1716	MTH 14-Mar-2014		O/C	0		
562003 R2	CABIN (ESCAPE HATCH) WINDOW			93320-13 1666	MTH 14-Mar-2014		O/C	0		
562003 R3	CABIN WINDOW			93320-13 1746	MTH 14-Mar-2014		O/C	0		
572001 LEFT WING	FWD SPAR			7022022-1 92910	MTH 14-Mar-2014		O/C	0		
572001 RIGHT WING	FWD SPAR			7022022-2 90943	MTH 14-Mar-2014		O/C	0		
572002 LEFT WING	REAR SPAR			7022032-3 91096	MTH 14-Mar-2014		O/C	0		
572002 RIGHT WING	REAR SPAR			7022032-4 92049	MTH 14-Mar-2014		O/C	0		
572003 LEFT WING	MAIN SPAR			7022027-1 91029	MTH 14-Mar-2014		O/C	0		
572003 RIGHT WING	MAIN SPAR			7022027-2 93827	MTH 14-Mar-2014		O/C	0		
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY			7041165-5 427	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY			7041165-6 443	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY			7041155-9 23170124F	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY			7041155-10 23170121C	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY			7041175-5 23170140K	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY			7041175-6 458	MTH 14-Mar-2014 LDG 0		20000	0	20000	18286



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1			7051001-1 00435	MTH 14-Mar-2014		O/C	0		
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1			LM-471-SA11 2194	MTH 14-Mar-2014 HRS 0		4000	0	4000	2014.9
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1			LM-471-SA11 2193	MTH 14-Mar-2014 HRS 0		4000	0	4000	2014.9
712001 RIGHT	ENG CHANNEL-FWD MOUNT 7051001-2			7051001-2 00457	MTH 14-Mar-2014		O/C	0		
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1			LM-471-SA11 2192	MTH 14-Mar-2014 HRS 0		4000	0	4000	2014.9
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1			LM-471-SA11 2189	MTH 14-Mar-2014 HRS 0		4000	0	4000	2014.9
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3			LM-471-SA4 LK2635	MTH 14-Mar-2014 HRS 0		8000	0	8000	6014.9
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3			LM-471-SA4 LK2630	MTH 14-Mar-2014 HRS 0		8000	0	8000	6014.9
712003 AFT	ENGINE BEAM 7012066-802-1			7012066-802-1 00448	MTH 14-Mar-2014		O/C	0		
712003 LEFT	AFT ENGINE MOUNT CHANNEL 7051001-3			7051001-3 00437	MTH 14-Mar-2014		O/C	0		
712003 RIGHT	AFT ENGINE MOUNT CHANNEL 7051001-4			7051001-4 00455	MTH 14-Mar-2014		O/C	0		
71EN1 NO. 1	ENGINE 35C0510-01			PCE-LB0919			E/C			
71EN2 NO. 2	ENGINE 35C0510-01			PCE-LB0918	MTH 26-Jul-2024 HRS 1735.8 LDG 1494		E/C			
72-30-03-900-801 E2	DIFFUSER EXIT DUCTS			35C5534-01 SN-UNKNOWN	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C	0 0 0		
72-40-01-900-801 E2	COMBUSTION CHAMBER LINER			35C4281-01 SN-UNKNOWN	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C	0 0 0		
72-50-02-900-801 E2	HP TURBINE VANE RING			35C2581CL01 SN-UNKNOWN	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
720010 E1	FAN ROTOR			35C1940-01 FRAEPNWN2	MTH 14-Mar-2014 LDG 0 ACCC YC		10500	0 0	(10500)10500	8786 8787
720010 E2	FAN ROTOR			35C1940-01 FRAEPNWN9	MTH 14-Mar-2014 LDG 73 ACCC YC		10500	0 0	(10500)10573	8859 8860
721010 E1	HP TURBINE DISK			35C2311-01 FRAEPPBU23	MTH 14-Mar-2014 LDG 0 ACCC YC		5250	0 0	(5250)5250	3536 3537
721010 E2	HP TURBINE DISK			35C2311-01 CRAZAEIX072	MTH 14-Mar-2014 LDG 73 ACCC YC		5250	0 0	(5250)5323	3609 3610
721015 E1	HP TURBINE DISK BALANCING ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
721015 E2	HP TURBINE DISK BALANCING ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
721020 E1	LP TURBINE DISK			35C2372-01 CRAZAEJW149	MTH 14-Mar-2014 LDG 0			0	(10500)10500	8786 8787
721020 E2	LP TURBINE DISK			35C2372-01 CRAZAEFT106	MTH 14-Mar-2014 LDG 73		10500	0	(10500)10573	8859 8860
721025 E1	LP TURBINE DISK BALANCING ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
721025 E2	LP TURBINE DISK BALANCING ASSEMBLY			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
723010 E1	IMPELLER AND SHAFT ASSEMBLY			35C5663-01 AAPPIDIO2061	MTH 14-Mar-2014 LDG 0		10500	0	(10500)10500	8786 8787
723010 E2	IMPELLER AND SHAFT ASSEMBLY			35C5663-01 AAPPIKSP2059	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		10500	0	(11937)12010	10296 10297
725010 E1	HP COMPRESSOR ROTOR			35C3661-01 FRAEPNTE12	MTH 14-Mar-2014 LDG 0		10500	0	(10500)10500	8786 8787
725010 E2	HP COMPRESSOR ROTOR			35C3661-01 FRAEPNTE5	MTH 14-Mar-2014 LDG 73		10500	0	(10500)10573	8859 8860
726010 E1	AGB STARTER MAGNETIC SEAL			35C1022-01 A005073	MTH 09-Nov-2023 HRS 1644.57 LDG 1437		1750	0	(3394.57)3394.57	1409.47
726010 E2	AGB STARTER MAGNETIC SEAL			35C1022-01 SN-UNKNOWN	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		1750	0	(3394.6)3485.8	1500.7
730001 LEFT	ENGINE FUEL PRESSURE SWITCH			1103P0448 10329	MTH 14-Mar-2014		O/C	0		
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH			1103P0448 10328	MTH 14-Mar-2014		O/C	0		
733001 LEFT	FUEL FLOW TRANSMITTER	LEVC		TFF1573-4 0827-004	MTH 23-Oct-2017 HRS 215.47 LDG 248 ACH 81.4		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER			TFF1573-4 AAF5362	MTH 14-Mar-2014		O/C	0		
73-20-02-900-801 E1	ELECTRICAL WIRING HARNESS			35C3943-03 WDAAL001101	MTH 07-Feb-2021 HRS 678.9 LDG 675		H/T H/T H/T H/T			
73-20-02-900-801 E2	ELECTRICAL WIRING HARNESS			35C3943-03 WDAAL001595	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		H/T H/T H/T H/T			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
73-20-03-900-801 E2	ENGINE ELECTRONIC CONTROL (EEC)			8237-1219-1 12-1102	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
731050 E1	FUEL MANIFOLD			35C6160-01 DEAAAA99274	MTH 09-Nov-2023 HRS 1644.57 LDG 1437		O/C	0 0 0		
731050 E2	FUEL MANIFOLD			35C6160-01 DEAAAB04749	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C	0 0 0		
732101 E1	FUEL METERING UNIT (F.M.U.)			35C0794-05 18620498	MTH 14-Mar-2014		H/T	0		
732101 E2	FUEL METERING UNIT (F.M.U.)			35C0794-05 17561117	MTH 14-Mar-2014		H/T	0		
733010 E1	FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
733010 E2	FUEL FILTER IMPENDING BYPASS SWITCH			35C3388-01 WDA102586	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
741001 E1	IGNITION EXCITER			35C5472-02 WDA119743	MTH 14-Mar-2014		O/C	0		
741001 E2	IGNITION EXCITER			35C5472-02 WDA119819	MTH 14-Mar-2014		O/C	0		
741002 E1 LEFT	IGNITER CABLE			35C0844-01 NSN	MTH 14-Mar-2014		O/C	0		
741002 E2 LEFT	IGNITER CABLE			35C0844-01 WDA113489	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
741003 E1 RIGHT	IGNITER CABLE			35C0799-01 NSN	MTH 14-Mar-2014		O/C	0		
741003 E2 RIGHT	IGNITER CABLE			35C0799-01 WDA118973	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
741004 E1 INBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 14-Mar-2014		O/C	0		
741004 E2 INBOARD	SPARK IGNITER			PN SN-UNKNOWN	MTH 03-Nov-2022 HRS 1393.3 LDG 1258		O/C			
741005 E1 OUTBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 14-Mar-2014		O/C	0		
741005 E2 OUTBOARD	SPARK IGNITER			35C2353-01 NSN	MTH 14-Mar-2014		O/C	0		
751003 E1	BLEED VALVE ACTUATOR			35C2851-02 18710405	MTH 14-Mar-2014		H/T	0		
751003 E2	BLEED VALVE ACTUATOR			35C2851-02 18310065	MTH 14-Mar-2014		H/T	0		
761001 E1	FADEC			35C4035-07 12-1106	MTH 14-Mar-2014		O/C	0		
761001 E2	FADEC	LEV		35C4035-04 09-589	MTH 18-Dec-2023 HRS 1735.8 LDG 1510		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
77-20-02-900-801 E2	T6 THERMOCOUPLE WIRING HARNESS			35C4518-01 WDAAD001233	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-04 WA46288	MTH 14-Mar-2014		H/T H/T	0		
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-04 WA46285	MTH 14-Mar-2014		H/T H/T	0		
792010 E1	LP COMPRESSOR CASE NOS. 1,2,3 BEARINGS OIL TUBE			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
792010 E2	LP COMPRESSOR CASE NOS. 1,2,3 BEARINGS OIL TUBE			PN SN-UNKNOWN	MTH 14-Mar-2014		O/C	0		
792030 E2	AIR COOLED OIL COOLER			10941J WA41362	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		H/T H/T H/T H/T			
793001 E1	OIL TEMP SENSOR			102-00083 08098	MTH 14-Mar-2014		O/C	0		
793001 E2	OIL TEMP SENSOR			102-00083 08091	MTH 14-Mar-2014		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER			APTE-598-1000-250G 8021-10-208	MTH 14-Mar-2014		O/C	0		
793002 E2	OIL PRESSURE TRANSMITER			APTE-598-1000-250G 8021-9-128	MTH 14-Mar-2014		O/C	0		
793010 E2	CHIP COLLECTOR			35C0412-01 AB1011	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C			
793050 E1	OIL FILTER IMPENDING BYPASS INDICATOR			PN SN-UNKNOWN	MTH 04-Nov-2024 HRS 1800.8 LDG 1575		O/C			
793050 E2	OIL FILTER IMPENDING BYPASS INDICATOR			35C4333-01 WDA02322	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		O/C	0 0 0		
801000 LEFT	STARTER GENERATOR			9912676-1 618D	MTH 27-Jan-2023 HRS 1405.1 LDG 1256		1500	0 0 0	2905.1	920
801000 RIGHT	STARTER GENERATOR	LFPB		9912676-1 857D	MTH 16-Aug-2024 HRS 1752.15 LDG 1536		1500	0 0 0	3252.15	1267.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW INFORMATIONAL						-			
MOC :										
SL 510-99-02 REV 01	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 02) INFORMATIONAL						-			
MOC :										
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01) INFORMATIONAL						-			
MOC :										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-99-02	CESCOM PRICES (SUPERSEDED BY SL510-99-02 REV 01)			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED			-			
	MOC :									
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL MTH			-			
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL 510-20-01 REV 01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL 510-20-01 REV 02	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 03)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-01 REV 03	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 04)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-01 REV 05	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 02)			INFORMATIONAL			-			
	MOC :									
SL 510-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL MTH			-			
	MOC :									
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT			RECOMMENDED MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: A/C not equipped with Cabin Pressurization Controller P/N 9912661-12									
SL 510-23-01	LIGHTNING RELATED ANOMALIES OF THE GARMIN GMA 1347[D] AUDIO PANEL			INFORMATIONAL			A/R			
	MOC :									
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION			MANDATORY DAYS			-			N/A
	MOC : NOT APPLICABLE - THE SL 510-24-14 WAS PREVIOUSLY COMPLIED WITH. THE R01 OF THE SL510-24-14 HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)	GSO		MANDATORY	DAYS 28-Sep-2016		-			Complete
					HRS 100.4					
					LDG 119					
	MOC : COMPLIED WITH - COMPLIED WITH SL510-24-14 PER ACCOMPLISHMENT INSTRUCTIONS. OPERATION CHECKS GOOD.									
SB 510-28-02	LOCKING FUEL CAP INSTALLATION			OPTIONAL			A/R			
	MOC :									
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT	KMCO		RECOMMENDED	MTH 17-Feb-2017		-			Complete
					HRS 106.2					
					LDG 125					
					ACH 80.4					
	MOC : COMPLIED WITH - COMPLIED WITH SB510-30-06 REVISION 1 DATED AUGUST 3, 2016 BY REPLACEMENT OF WINDSHIELD CONTROLLERS WITH IMPROVED UNITS PER SERVICE BULLETIN INSTRUCTIONS.									
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)	KMCO		RECOMMENDED	MTH 17-Feb-2017		-			Complete
					HRS 106.2					
					LDG 125					
					ACH 80.4					
	MOC : COMPLIED WITH - COMPLIED WITH BY PERFORMING REVISION 1 OF THIS SERVICE BULLETIN.									
SL 510-30-01 REV 01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 02)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01 REV 02	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 03)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01 REV 04	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 05)			INFORMATIONAL			A/R			
	MOC :									
SL 510-30-01 REV 05	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 06)			INFORMATIONAL			-			
	MOC :									
SL 510-30-01 REV 06	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY CIL-30-01)			INFORMATIONAL			-			
	MOC :									
SL 510-30-01	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL510-30-01 REV 01)			INFORMATIONAL			A/R			
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	MOC :									
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	LESU		MANDATORY	DAYS 08-Jan-2018		-			N/A
					HRS 228					
					LDG 278					
					ACH 81.4					
	MOC : NOT APPLICABLE - SL510-32-07 NOT APPLICABLE FOR THE MAIN LANDING GEAR BRAKES SERIAL NUMBERS INSTALLED IN THE AIRCRAFT									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY	LESU		MANDATORY	DAYS 08-Jan-2018 HRS 228 LDG 278 ACH 81.4		-			N/A
MOC : NOT APPLICABLE - SL510-32-08 NOT APPLICABLE BECAUSE THE MAIN LANDING GEAR BRAKES ARE NOT INCLUDED ON TABLE 1. BRAKE SERIAL NUMBER INSTALLED ON THE LEFT MLG IS 1068 AND ON THE RH IS 1052.										
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT			OPTIONAL			-			
MOC :										
SB 510-34-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION	KMCO		OPTIONAL	MTH 17-Feb-2017 HRS 106.2 LDG 125 ACH 80.4		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-10 DATED MARCH 18, 2009 BY UPLOADING NEW SOFTWARE TO ENABLE THE SYNTHETIC VISION FUNCTION OF THE GARMIN G1000 SYSTEM PER SERVICE BULLETIN INSTRUCTIONS.										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE	LEVC		MANDATORY	MTH 23-Oct-2017 HRS 215.47 LDG 248 ACH 81.4		-			Complete
MOC : COMPLIED WITH - PERFORMED SB 510-34-16 REV 01, TEST ARCHITECTURE TEST, AFCS CHECKED AND FOUND PROBLEMS ON NAV 1 AND AFCS, RE-INSTALLED SB 510-34-16 REV 01 GIA 1 PARAMETERS, TCAS 2 CONFIGURATION AND TESTED AGAIN IS WORKING PROPERLY.WORK DONE IAW SB 510-34-16 REV 01 30 SEP 2016 AND 510 MM REV 13 CH-34-60-00.										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)			OPTIONAL			-			
MOC :										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)			N/A BY PART NUMBER			-			
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE			OPTIONAL	MTH 12-Apr-2020		-			Complete
MOC : COMPLIED WITH - THROUGH WO DB002/2020										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE			RECOMMENDED	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG Not equipped with Garmin G1000 ADS-B Out										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
MOC :										
COM MC ALL - 007	GPS/SBAS APPROACH DOWNGRADES DUE TO GEOMAGNETIC ACTIVITY			INFORMATIONAL	MTH		-			
MOC :										
SL 510-34-01	TRANSMITTAL OF GARMIN SERVICE ALERT 070424-00			INFORMATIONAL			A/R			
MOC :										
SL 510-34-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING			INFORMATIONAL			A/R			
MOC :										
SL 510-34-05	GARMIN G1000 TRANSPONDER OPERATION CHANGE			INFORMATIONAL			A/R			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-34-06	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0811, G1000 SERIES FLIGHT PLAN SEQUENCING ISSUE			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-07	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO.: 0825 LPV AND LNAV/VNAV APPROACHES WITH THREE-CHARACTER AIRPORT IDENTIFIERS			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-08	GPS/WAAS LOSS OF RECEPTION IN ALASKA, NORTHWEST CANADA, AND EASTERN RUSSIA			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-10	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0915 REVISION A, G1000 SERIES NAVIGATION SUSPENDING DURING NON-PRECISION APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-12	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0933 REVISION A, SYSTEM MAY SELECT NAV 2 AS A NAVIGATION SOURCE DURING APPROACH			INFORMATIONAL			-			
	MOC :									
SL 510-34-13	TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 0922 REVISION A, VOR OR LOC/ILS APPROACHES			INFORMATIONAL			A/R			
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL			-			
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT			RECOMMENDED	MTH		-			
	MOC :									
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL			-			
	MOC :									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	MCO		MANDATORY	DAYS 04-Nov-2016		-			Complete
					HRS 102.8					
					LDG 120					
					ACH 80.4					
	MOC :									
	MOC :									
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	LFPB		MANDATORY	DAYS 16-Mar-2020		-			Complete
					HRS 405.55					
					LDG 459					
	MOC :									
	MOC :									
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT			MANDATORY	DAYS 18-Dec-2019		-			Complete
					HRS 388.5					
					LDG 444					
	MOC :									
	MOC :									
SL 510-57-02	WINGS - FLAP ACTUATOR BOLT REPLACEMENT	GSO		MANDATORY	MTH 28-Sep-2016		-			Complete
					HRS 100.4					
					LDG 119					
	MOC :									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS CATEGORY 5	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE CATEGORY 9	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING CATEGORY 5	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE CATEGORY 9	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY CATEGORY 7	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 8	MTH		14-Mar-2014		-				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7	MTH		14-Mar-2014		A/R				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY CATEGORY 7	MTH		14-Mar-2014		A/R				Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)			CATEGORY 7 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6 MTH			-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63019 was complied with at engine manufacture. The R01 of the SB has no effect. No further actions required.									
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6 MTH			-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63019 was complied with at engine manufacture. The R01 of the SB has no effect. No further actions required.									
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9 MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7 MTH			-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63022 was complied with at engine manufacture. The R01 of the SB has no effect. No further actions required.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02) CATEGORY 7 MTH - N/A									
	MOC : NOT APPLICABLE - The SB PW600-72-63022 was complied with at engine manufacture. The R01 of the SB has no effect. No further actions required.									
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7 MTH - N/A									
	MOC : NOT APPLICABLE - The SB PW600-72-63022 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.									
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY CATEGORY 7 MTH - N/A									
	MOC : NOT APPLICABLE - The SB PW600-72-63022 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.									
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01) CATEGORY 7 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01) CATEGORY 7 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING CATEGORY 7 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING CATEGORY 7 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER CATEGORY 7 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER CATEGORY 7 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY CATEGORY 9 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63027 R01 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63027 R01 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 8 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63028 R01 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 5 MTH 14-Mar-2014 - Complete									
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63028 R01 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY CATEGORY 5			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63034 R01 E1	REPLACEMENT OF OIL PUMP PLATE CATEGORY 6						-			
	MOC :									
SB PW600-72-63034 R01 E2	REPLACEMENT OF OIL PUMP PLATE CATEGORY 6						-			
	MOC :									
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE CATEGORY 8			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63037 R01 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63037 R01 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63043 R02 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63043 R02 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63051 R02 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03) CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63051 R02 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03) CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES CATEGORY 6						-			N/A
	MOC : NOT APPLICABLE - THE SB PW600-72-63051 WAS COMPLIED WITH AT ENGINE MANUFACTURE. THE R03 OF THE SB HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.									
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES CATEGORY 6						-			N/A
	MOC : NOT APPLICABLE - THE SB PW600-72-63051 WAS COMPLIED WITH AT ENGINE MANUFACTURE. THE R03 OF THE SB HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST CATEGORY 9						-			
	MOC :									
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST CATEGORY 9						-			
	MOC :									
SB PW600-72-63059 R01 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02) CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63059 R01 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02) CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY			MTH			-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63059 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY			MTH			-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63059 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.									
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET CATEGORY 8			MTH	18-Apr-2022		-			N/A
	MOC : NOT APPLICABLE - THE ENGINE IS POST SB PW600-72-63052									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET CATEGORY 8			MTH	18-Apr-2022		-			N/A
	MOC : NOT APPLICABLE - THE ENGINE IS POST SB PW600-72-63052									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02) CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02) CATEGORY 6			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			N/A
MOC : NOT APPLICABLE - The SB PW600-72-63074 was complied with at engine manufacture. The R01 of the SB has no effect. No further actions required.										
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			N/A
MOC : NOT APPLICABLE - The SB PW600-72-63074 was complied with at engine manufacture. The R01 of the SB has no effect. No further actions required.										
SB PW600-72-63074 R02 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			
MOC :										
SB PW600-72-63074 R02 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			
MOC :										
SB PW600-72-63074 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63074 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02) CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6			MTH			-			N/A
MOC : NOT APPLICABLE - The SB PW600-72-63077 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.										
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR CATEGORY 6			MTH			-			N/A
MOC : NOT APPLICABLE - The SB PW600-72-63077 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.										
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			N/A
	MOC : NOT APPLICABLE - THE SB PW600-72-63080 WAS COMPLIED WITH AT ENGINE MANUFACTURE. THE R02 OF THE SB HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.									
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) CATEGORY 6						-			N/A
	MOC : NOT APPLICABLE - THE SB PW600-72-63080 WAS COMPLIED WITH AT ENGINE MANUFACTURE. THE R02 OF THE SB HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.									
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 5			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC) CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL CATEGORY 3			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL CATEGORY 3			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF CATEGORY 6			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF CATEGORY 6			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6						-			N/A
MOC : NOT APPLICABLE - THE SB PW600-72-63091 WAS COMPLIED WITH AT ENGINE MANUFACTURE. THE R01 OF THE SB HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.										
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02) CATEGORY 6						-			N/A
MOC : NOT APPLICABLE - THE SB PW600-72-63091 WAS COMPLIED WITH AT ENGINE MANUFACTURE. THE R01 OF THE SB HAS NO EFFECT. NO FURTHER ACTIONS REQUIRED.										
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6						-			
MOC :										
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS CATEGORY 6						-			
MOC :										
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01) CATEGORY 6			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7						-			
	MOC :									
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3			MTH	23-Feb-2021		-			N/A
	MOC : NOT APPLICABLE - BY SERIAL:									
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3			MTH	23-Feb-2021		-			N/A
	MOC : NOT APPLICABLE - BY SERIAL:									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT						-			
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			MTH	14-Mar-2014		-			Complete
	CATEGORY 7									
	MOC :									
	COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			MTH	14-Mar-2014		-			Complete
	CATEGORY 7									
	MOC :									
	COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			MTH	14-Mar-2014		-			Complete
	CATEGORY 7									
	MOC :									
	COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			MTH	14-Mar-2014		-			Complete
	CATEGORY 7									
	MOC :									
	COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH			MTH	14-Mar-2014		-			Complete
	MOC :									
	COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH			MTH	14-Mar-2014		-			Complete
	MOC :									
	COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE						-			
	CATEGORY 7									
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE						-			
	CATEGORY 7									
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			MTH			-			
	CATEGORY 7									
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			MTH			-			
	CATEGORY 7									
	MOC :									
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			MTH			-			
	CATEGORY 7									
	MOC :									
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			MTH			-			
	CATEGORY 7									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7			-			
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5			-			
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5			-			
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5			-			
	MOC :									
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5			-			
	MOC :									
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
	MOC :									
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5	MTH 09-Nov-2023 HRS 1644.57 LDG 1437		-			Complete
	MOC :	COMPLIED WITH								
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5	MTH 18-Jun-2024 HRS 1735.8 LDG 1510		-			Complete
	MOC :	COMPLIED WITH								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5			MTH	23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - BY SERIAL:										
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE CATEGORY 5			MTH	23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - BY SERIAL:										
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING CATEGORY 3			MTH			-			N/A
MOC : NOT APPLICABLE - By Part: Due to this SB is only applicable to engines PW615F-A which have post-SB 63105 FOHE P/N 35C3778-05 installed.										
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING CATEGORY 3			MTH			-			N/A
MOC : NOT APPLICABLE - By Part: Due to this SB is only applicable to engines PW615F-A which have post-SB 63105 FOHE P/N 35C3778-05 installed.										
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL CATEGORY 3			MTH	03-Feb-2021		-			N/A
MOC : NOT APPLICABLE - BY EFFECTIVITY: ENGINE IS NOT POST-SB63062 CONFIGURATION BETWEEN JANUARY 01, 2018 AND PRIOR TO FEBRUARY 01, 2021										
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL CATEGORY 3			MTH	03-Feb-2021		-			N/A
MOC : NOT APPLICABLE - BY EFFECTIVITY: ENGINE IS NOT POST-SB63062 CONFIGURATION BETWEEN JANUARY 01, 2018 AND PRIOR TO FEBRUARY 01, 2021										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL CATEGORY 3			MTH			A/R			
MOC :										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL CATEGORY 3			MTH	18-Jun-2024		-			Complete
HRS 1735.8 LDG 1510										
MOC : COMPLIED WITH										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 5			MTH	18-Jun-2024		-			Complete
HRS 1735.8 LDG 1510										
MOC : COMPLIED WITH										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL CATEGORY 7			MTH	09-Nov-2023		-			Complete
HRS 1644.57 LDG 1437										
MOC : COMPLIED WITH										
SB PW600-72-63116 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63116 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63116 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY CATEGORY 7						-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63116 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW600-72-63117 E1	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER CATEGORY 9						-			
MOC :										
SB PW600-72-63117 E2	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER CATEGORY 9						-			
MOC :										
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02) CATEGORY 3			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63071 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02) CATEGORY 3			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE CATEGORY 3			MTH			-			N/A
MOC : NOT APPLICABLE - The SB PW600-72-A63071 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.										
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE CATEGORY 3			MTH			-			N/A
MOC : NOT APPLICABLE - The SB PW600-72-A63071 was complied with at engine manufacture. The R02 of the SB has no effect. No further actions required.										
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
ASL 510-73-01 LEFT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE MANDATORY						A/R			
MOC :										
ASL 510-73-01 RIGHT	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE MANDATORY						-			
MOC :										
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-1007-63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63067 E1	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63067 E2	REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 3			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 3			MTH	14-Mar-2014		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 8			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT CATEGORY 7			MTH	14-Mar-2014		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS CATEGORY 6			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 R01 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) CATEGORY 7			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB 510-76-02 REV 01	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT RECOMMENDED			MTH			-			
MOC :										
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS CATEGORY 8			MTH	14-Mar-2014		-			Complete
MOC : COMPLIED WITH - AT MANUFACTURE										
SL 510-79-03 REV 01	OIL - OIL TRANSDUCER AND CONNECTOR REPLACEMENT MCO MANDATORY			MTH HRS	09-Nov-2016 103.5		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY VISUAL INSPECTION OF THE OIL PRESSURE TRANSDUCERS PER SERVICE LETTER INSTRUCTIONS. PART NUMBER APTE-598-1000-250G TRANSDUCERS WERE FOUND TO BE INSTALLED ON BOTH THE LEFT AND RIGHT ENGINES. NO FURTHER ACTION REQUIRED.										
SL 510-79-03	OIL - OIL TRANSDUCER AND CONNECTOR REPLACEMENT (SUPERSEDED BY SL510-79-03 REV 01) GSO MANDATORY			MTH HRS LDG	28-Sep-2016 100.4 119		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-79-03 PER ACCOMPLISHMENT INSTRUCTIONS. OPERATION CHECKS GOOD.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01) CATEGORY 7	MTH	14-Mar-2014				A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01) CATEGORY 7	MTH	14-Mar-2014				A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63008 R02 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS CATEGORY 5	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63008 R02 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS CATEGORY 5	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63047 R02 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03) CATEGORY 3	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63047 R02 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03) CATEGORY 3	MTH	14-Mar-2014				-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE									
SB PW600-79-63047 R03 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS CATEGORY 3	MTH					-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63047 was complied with at engine manufacture. The R03 of the SB has no effect. No further actions required.									
SB PW600-79-63047 R03 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS CATEGORY 3	MTH					-			N/A
	MOC : NOT APPLICABLE - The SB PW600-72-63047 was complied with at engine manufacture. The R03 of the SB has no effect. No further actions required.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 510-80-01	ENGINE STARTING			INFORMATIONAL			-			
MOC :										
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM			RECOMMENDED MTH			-			N/A
MOC : NOT APPLICABLE - Not adopted due to the starter generator installed in the aircraft only having 120 Hrs of time accrued										
SL CIL-99-05 REV 1	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL MTH			-			
MOC :										

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2007-0256-CN	APPLIANCE AD - ATA 25 - CANCELLED: EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION / REPLACEMENT			MTH	28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - CANCELLED										
EASA 2013-0020 R04 (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER			MANDATORY MTH	25-Nov-2014		-			N/A
MOC : NOT APPLICABLE - OPERATING UNDER CCAR-135.										
EASA 2013-0020 R04 (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD			MANDATORY MTH	25-Nov-2014		-			N/A
MOC : NOT APPLICABLE - OPERATING UNDER CCAR-135.										
EASA 2013-0020 R04 (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE			MANDATORY MTH	25-Nov-2014		-			N/A
MOC : NOT APPLICABLE - OPERATING UNDER CCAR-135.										
EASA 2013-0020 R04 (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD			MANDATORY MTH	25-Nov-2014		-			N/A
MOC : NOT APPLICABLE - OPERATING UNDER CCAR-135.										
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT			MANDATORY MTH	25-Nov-2014		-			N/A
MOC : NOT APPLICABLE - OPERATING UNDER CCAR-135.										
EASA 2014-0187 PARA (1)	INSPECT THE SAFETY BELT ATTACHMENT BOLTS	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2014-0187 DATED 20 AUGUST 2014, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (1), (2), (3) AND (4). NO FURTHER ACTION REQUIRED.										
EASA 2014-0187 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2.	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2014-0187 DATED 20 AUGUST 2014, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (1), (2), (3) AND (4). NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0187 PARA (3)	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2.								
		KMCO	MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2014-0187 DATED 20 AUGUST 2014, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (1), (2), (3) AND (4). NO FURTHER ACTION REQUIRED.									
EASA 2014-0187 PARA (4)	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S).								
		KMCO	MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2014-0187 DATED 20 AUGUST 2014, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (1), (2), (3) AND (4). NO FURTHER ACTION REQUIRED.									
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS – SAFETY BELT ATTACHMENT BOLTS – INSPECTION / REPLACEMENT								
		KMCO	MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125 ACH 80.4		-			N/A
MOC : NOT APPLICABLE - EASA AD 2014-0187 DATED 20 AUGUST 2014, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (1), (2), (3) AND (4). NO FURTHER ACTION REQUIRED.									
EASA 2016-0167 R01 (CORR)	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2016-0167 R01 PARA (1)	REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION (DVI)								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2016-0167 R01 PARA (2)	DETAILED VISUAL INSPECTION (DVI)								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2016-0167 R01 PARA (3)	ACCOMPLISH THE APPLICABLE TEMPORARY CORRECTIVE ACTIONS (IF, DURING ANY INSPECTION AS REQUIRED BY PARAS (1) OR (2) OF THIS AD, AS APPLICABLE, CORROSION OR OTHER DAMAGE IS FOUND)								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2016-0167 R01 PARA (4)	TEMPORARILY STOWING AND SECURING A DAMAGED ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARA (3) OF THIS AD.								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2016-0167 R01 PARA (5)	IT IS ALLOWED TO INSTALL (SEE NOTE 2 OF THIS AD) ON ANY AEROPLANE AN AFFECTED SEAT, HAVING ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON AN AEROPLANE, PROVIDED THAT, BEFORE (RE)INSTALLATION, IT HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2, SUBPART B, OF ZODIAC SEATS FRANCE SB NO. 536-25-002								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2016-0167 R01 PARA (6)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE INSTRUCTIONS OF ZODIAC SEATS FRANCE SB NO. 536- 25-004 CONSTITUTE TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AS REQUIRED BY PARAS (1) AND (2) OF THIS AD FOR THAT SEAT								
			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0167 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with CAS 536 Cabin Attendant Seats.									
EASA 2018-0195	EQUIPMENT / FURNISHINGS - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REMOVAL FROM SERVICE		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with Torso Restraint System model 358									
EASA 2018-0223	EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - MODIFICATION		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Common Seats 170/260 H160.									
EASA 2018-0262 PARA (1)	MODIFY AND RE-IDENTIFY EACH PRE-MOD SEAT (FOR GROUP 1 AEROPLANES) (RESTATEMENT OF EASA AD 2016-0256 (1))		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0262 PARA (2)	DO NOT INSTALL A PRE-MOD SEAT ON ANY AEROPLANE (RESTATEMENT OF EASA AD 2016-0256 PARA (2))		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0262 PARA (3)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0262 PARA (5)	IT IS ALLOWED TO DEFER ACCOMPLISHMENT OF CORRECTIVE ACTIONS REQUIRED BT PARA (4) OF THIS AD FOR THAT SEAT, PROVIDED A COPY OF THE ATR OEB IS INCLUDED IN THE APPLICABLE AFM, PILOTS ARE INFORMED, AND THE AEROPLANE IS OPERATED IAW THE INSTRUCTIONS OF THAT OEB (IF, DURING ANY INSPECTION AS REQ BY PARA (3) OF THIS AD, ANY DAMAGE OR INCORRECT INSTALLATION OF ONLY ONE AFFECTED SPRING IS FOUND ON THE PILOT OR CO-PILOT SEAT) (FOR ATR AEROPLANES)		MTH MANDATORY DAYS			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0262 PARA (8)	IT IS ALLOWED TO INSTALL AN AFFECTED SPRING ON A SEAT INSTALLED ON AN AEROPLANE PROVIDED THAT, AFTER INSTALLATION, THAT SPRING PASSES AN INSPECTION (NO DEFECT FOUND)		MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0262 PARA (9) & (10)	REPORTING		MANDATORY MTH DAYS			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0262	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOTS SEATS - MODIFICATION / INSPECTION		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
EASA 2018-0264 R01	EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Centaurus passenger seats.									
EASA 2018-0264	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: Not Equipped: CS-DOG is not equipped with Centaurus passenger seats.									
EASA 2019-0010 PARA (1)	REMOVE EACH AFFECTED PART FROM SERVICE AND REPLACE IT WITH A SERVICEABLE PART		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.									
EASA 2019-0010 PARA (2)	DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.									
EASA 2019-0010 PARA (3)	DO NOT RELEASE TO SERVICE ANY AFFECTED PART, UNLESS IT HAS BEEN REPAIRED AND RE-IDENTIFIED		MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2019-0010	APPLIANCE AD - EQUIPMENT/FURNINSHING - LIFE JACKET - REMOVAL/REPAIR			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.										
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)	UNK			MTH 26-Oct-2020 HRS 603.4 LDG 599		-			N/A
MOC : NOT APPLICABLE										
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION	UNK		MANDATORY	MTH 26-Oct-2020 HRS 603.4 LDG 599		-			N/A
MOC : NOT APPLICABLE										
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART	UNK		MANDATORY	MTH 26-Oct-2020 HRS 603.4 LDG 599		-			N/A
MOC : NOT APPLICABLE										
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE	UNK		MANDATORY	MTH 26-Oct-2020 HRS 603.4 LDG 599		-			N/A
MOC : NOT APPLICABLE										
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT	UNK		MANDATORY	MTH 26-Oct-2020 HRS 603.4 LDG 599		-			N/A
MOC : NOT APPLICABLE										
EASA 2020-0272 PARA (1)	MODIFY EACH AFFECTED BUCKLE OR REPLACE THE AFFECTED BUCKLE WITH A SERVICEABLE BUCKLE			MANDATORY	MTH 23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH 4 POINT HARNESS RESTRAINT SYSTEMS, HAVING PART NUMBER 18-()-().										
EASA 2020-0272 PARA (2)	REPLACE EACH AFFECTED BUCKLE WITH A SERVICEABLE BUCKLE (IF POST-MODIFICATION AND PRE-REPLACEMENT PER PARA (1))			MANDATORY	MTH 23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH 4 POINT HARNESS RESTRAINT SYSTEMS, HAVING PART NUMBER 18-()-().										
EASA 2020-0272	APPLIANCE AD - EQUIPMENT / FURNISHINGS - BUCKLE - MODIFICATION / REPLACEMENT			MANDATORY	MTH 23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH 4 POINT HARNESS RESTRAINT SYSTEMS, HAVING PART NUMBER 18-()-().										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	UNK			MTH 15-Oct-2018		-			Complete
MOC : COMPLIED WITH										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS		MANDATORY			-			
	MOC :								
FAA 2018-16-01 PARA (G)	REVIEW EACH AFFECTED ATTENDANT SEAT NG AND PILOT SEAT 120/335, REMOVE AND REPLACE THE EA ASSEMBLIES ON EACH AFFECTED PILOT SEAT, AND REMOVE EACH AFFECTED ATTENDANT SEAT AND REPLACE WITH A REWORKED SEAT IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016		MANDATORY	MTH DAYS		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with attendant seats NG and pilot seats 120/335.								
FAA 2018-16-01 PARA (H)	DO NOT INSTALL AN AFFECTED SEAT ON AN AIRCRAFT UNLESS, PRIOR TO INSTALLATION, THE EA ASSEMBLIES ON THE SEAT HAVE BEEN REPLACED IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with attendant seats NG and pilot seats 120/335.								
FAA 2018-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with attendant seats NG and pilot seats 120/335.								
FAA 2018-16-13 PARA (G)	INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: This AD is not applicable to CS-DOG due is not equipped with the Zodiac Seats France, 537-Series Cabin Attendant Seats.								
FAA 2018-16-13 PARA (H)	DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: This AD is not applicable to CS-DOG due is not equipped with the Zodiac Seats France, 537-Series Cabin Attendant Seats.								
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: This AD is not applicable to CS-DOG due is not equipped with the Zodiac Seats France, 537-Series Cabin Attendant Seats.								
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Geven Type D1-03 seats.								
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.								
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.								
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.								
FAA 2018-23-12 PARA (G)	ACCOMPLISH AN INSPECTION TO DETERMINE IF ANY PLUG HAS PART NUMBER (P/N) B13984-3, STAMPED WITH LOT PA-21 OR PA-22		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Aero Evacuation Systems fusible plugs installed on emergency evacuation.								



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2018-23-12 PARA (H)	REPLACE FUSIBLE PLUG WITH A SERVICEABLE FUSIBLE PLUG P/N B13984-3 THAT IS NOT STAMPED WITH LOT PA-21 OR PA-22			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Aero Evacuation Systems fusible plugs installed on emergency evacuation.										
FAA 2018-23-12 PARA (I)	NO PERSON SHAL INSTALL ON ANY AIRPLANE ANY FUSIBLE PLUG HAVING P/N B13984-3, STAMPED WITH LOT PA-21 OR PA-22			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Aero Evacuation Systems fusible plugs installed on emergency evacuation.										
FAA 2018-23-12	APPLIANCE AD - EQUIPMENT / FURNISHINGS - INSPECTION AND REPLACEMENT OF ZODIAC AERO (ALSO KNOWN AS AIR CRUISERS COMPANY) EVACUATION SYSTEMS FUSIBLE PLUGS			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Aero Evacuation Systems fusible plugs installed on emergency evacuation.										
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.										
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.										
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.										
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Zodiac Seats France 536-Series Cabin Attendant Seats.										
FAA 2019-08-01 PARA (G)	MODIFY THE AFFECTED PASSENGER SEAT AND RE-IDENTIFY EACH MODIFIED PASSENGER SEAT			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with RECARO Model 3510A and 3510D passenger seats.										
FAA 2019-08-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED RECARO MODEL PASSENGER SEAT ON ANY AIRCRAFT, UNLESS THE SEAT HAS BEEN MODIFIED AND RE-IDENTIFIED IN ACCORDANCE WITH PARAGRAPH (G)(2), (3), OR (4) OF THIS AD			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with RECARO Model 3510A and 3510D passenger seats.										
FAA 2019-08-01	APPLIANCE AD - EQUIPEMENT AND FURNISHINGS - MODIFICATION AND RE-IDENTIFICATION OF ALL AFFECTED RECARO AIRCRAFT SEATING GMBH & CO. KG MODEL PASSENGER SEATS			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with RECARO Model 3510A and 3510D passenger seats.										
FAA 2019-14-05 PARA (G)	REVIEW EACH AFFECTED B/E AEROSPACE FISCHER COMMON SEAT TO DETERMINE IF REWORK HAS ALREADY BEEN PERFORMED. IF THE REWORK HAS NOT BEEN PERFORMED REWORK THE AFFECTED SEATS AND MARK THE SEAT BY INSTALLING A PLACARD			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with B/E Aerospace Common Seats 170/260 H160.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-14-05 PARA (H)	DO NOT INSTALL ANY SEAT AFFECTED BY THIS AD ONTO ANY AIRCRAFT UNLESS THE SEAT IS MARKED WITH A PLACARD STATING COMPLETION OF B/E AEROSPACE FISCHER ASB NO. SB0718-004, ISSUE A, DATED JUNE 26, 2018			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with B/E Aerospace Common Seats 170/260 H160.									
FAA 2019-14-05	APPLIANCE AD - EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with B/E Aerospace Common Seats 170/260 H160.									
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: Not Equipped: CS-DOG is not equipped with Safran Aerosystems Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.									
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: Not Equipped: CS-DOG is not equipped with Safran Aerosystems Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.									
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: Not Equipped: CS-DOG is not equipped with Safran Aerosystems Life Jackets, having P/N 210225-2, 216200-0 or 216203-0.									
FAA 2019-21-06 PARA (G)(1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (RESTATEMENT OF FAA 2017-22-02)			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
FAA 2019-21-06 PARA (G)(2)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
FAA 2019-21-06 PARA (G)(3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO AT TECHNICALSUPPORT@IPECO.COM			MANDATORY MTH DAYS			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
FAA 2019-21-06 PARA (H)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C)(1)(I) OF THIS AD UNLESS THE SEAT IS MODIFIED AND RE-IDENTIFIED AS SPECIFIED IN PARAGRAPH (G)(1) OF THIS AD			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
FAA 2019-21-06	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Type 3A063 flight crew seats.									
FAA 2019-21-09 PARA (G)	INSPECT THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY; IF, DURING THE INSPECTION A LIFE VEST POUCH VELCRO STRIP IS FOUND DAMAGED OR WORN OR A LIFE VEST POUCH INSTALLATION IS NOT FOUND ACCEPTABLE, BEFORE FURTHER FLIGHT, REMOVE THE LIFE VEST POUCH FROM SERVICE AND REPLACE IT WITH A PART ELIGIBLE FOR INSTALLATION			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Centaurus passengers seats.									
FAA 2019-21-09 PARA (I)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AVIOINTERIORS CENTAURUS ECONOMY CLASS PASSENGER SEAT WITH A P/N IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY HAS BEEN INSPECTED IN ACCORDANCE WITH PARAGRAPH (G)(1) OF THIS AD			MANDATORY MTH			-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Centaurus passengers seats.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-21-09	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION / REPLACEMENT			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Centaurus passengers seats.										
FAA 2020-09-02 PARA (G)(1)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY (FOR THE RESTRAINT SYSTEMS LISTED IN THE EFFECTIVITY OF ANJOU AERO SB 358SB-14-101 R01, EXCEPT FOR S/NS 1038-1048 (INCLUSIVE), 1050-1055 (INCLUSIVE), AND 1062-1073 (INCLUSIVE))			MANDATORY	MTH	23-Feb-2021	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS.										
FAA 2020-09-02 PARA (G)(2)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE RESTRAINT SYSTEM FROM SERVICE (FOR RESTRAINT SYSTEMS, P/N 358XX-XXX-YY-ZZZ (WHERE 358XX-XXX-YY-ZZZ CAN BE ANY COMBINATION OF NUMBERS AND/OR LETTERS)), HAVING S/NS 738-1619 (INCLUSIVE))			MANDATORY	MTH	23-Feb-2021	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS.										
FAA 2020-09-02 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN ANJOU AERONAUTIQUE RESTRAINT SYSTEM, P/N 358XX-XXX-YY-ZZZ, HAVING S/NS 738-1619 (INCLUSIVE), EVEN IF THE RESTRAINT SYSTEM IS LABELED IN COMPLIANCE WITH ANJOU AERO SB 358SB-14-101 R01, DATED DECEMBER 12, 2014			MANDATORY	MTH	23-Feb-2021	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS.										
FAA 2020-09-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REPLACEMENT			MANDATORY	MTH	23-Feb-2021	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS.										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH	28-Mar-2022	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH PACIFIC SCIENTIFIC SEAT RESTRAINT SYSTEM.										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH	28-Mar-2022	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH PACIFIC SCIENTIFIC SEAT RESTRAINT SYSTEM.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY	MTH	28-Mar-2022	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH PACIFIC SCIENTIFIC SEAT RESTRAINT SYSTEM.										
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY	MTH	28-Mar-2022	-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH PACIFIC SCIENTIFIC SEAT RESTRAINT SYSTEM.										
FAA 2022-05-10 PARA (G)(2)	INSTALL PLACARDS AND REVIS THE EXISTING RFM			MANDATORY			BF/F			
MOC :										
FAA 2022-05-10 PARA (G)(3)	DEACTIVATE OR REMOVE THE HOIST IF PARTIAL PEEL OUT OCCURS			MANDATORY			BF/F			
MOC :										
FAA 2022-05-10 PARA (G)(4)	REVIEW THE HELICOPTER'S HOIST SLIP LAOD TEST RECORDS			MANDATORY			-			N/A
MOC : NOT APPLICABLE - BY EFFECTIVITY: AD APPLICABLE ONLY TO HELICOPTERS										
FAA 2022-05-10 PARA (G)(5)	INSPECT CABLE FROM THE HOOK ASSEMBLY, PERFORM CABLE CONDITIONING AND HOIST SLIP LOAD TEST			MANDATORY			-			N/A
MOC : NOT APPLICABLE - BY EFFECTIVITY: AD APPLICABLE ONLY TO HELICOPTERS										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2022-05-10 PARA (G)(6)	REPORT HOIST SLIP LOAD TEST INFORMATION REQUESTED IN APPENDIX 1			MANDATORY	DAYS		30			
MOC :										
FAA 2022-05-10	APPLIANCE AD - CABIN EQUIPMENT/FURNISHINGS - GOODRICH HOIST ASSEMBLY - INSPECT/REPLACE			MANDATORY	MTH 16-Mar-2022		-			N/A
MOC : NOT APPLICABLE - BY EFFECTIVITY: AD APPLICABLE ONLY TO HELICOPTERS										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	UNK		MANDATORY	MTH 28-Jan-2026 HRS 1959.33 LDG 1704		-			N/A
MOC : NOT APPLICABLE - 2024-26-02 IS NOT APPLICABLE AS WE DO NOT HAVE THAT SEATBELT										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	UNK		MANDATORY	MTH 28-Jan-2026 HRS 1959.33 LDG 1704		-			N/A
MOC : NOT APPLICABLE - 2024-26-02 IS NOT APPLICABLE AS WE DO NOT HAVE THAT SEATBELT										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	UNK		MANDATORY	MTH 28-Jan-2026 HRS 1959.33 LDG 1704		-			N/A
MOC : NOT APPLICABLE - 2024-26-02 IS NOT APPLICABLE AS WE DO NOT HAVE THAT SEATBELT										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	UNK		MANDATORY	MTH 28-Jan-2026 HRS 1959.33 LDG 1704		-			N/A
MOC : NOT APPLICABLE - 2024-26-02 IS NOT APPLICABLE AS WE DO NOT HAVE THAT SEATBELT										
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0024 DATED 26 JANUARY, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0024 DATED 26 JANUARY, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0024 DATED 26 JANUARY, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0024 DATED 26 JANUARY, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0024 DATED 26 JANUARY, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125 ACH 80.4		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0024 DATED 26 JANUARY, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0044 DATED 08 MARCH, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0044 DATED 08 MARCH, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2016-0044 DATED 08 MARCH, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL			MANDATORY	MTH 17-Feb-2017		-			N/A
		KMCO			HRS 106.2					
					LDG 125					
					ACH 80.4					
MOC : NOT APPLICABLE - EASA AD 2016-0044 DATED 08 MARCH, 2016, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2021-0185 R01	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT				MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED:										
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with cargo fire extinguisher halon bottles.										
FAA 2021-22-07	FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT			MANDATORY	MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH UMLAUT HALON FREE FIRE EXTINGUISHERS										
FAA 2022-01-03	APPLIANCE AD - FIRE PROTECTION - HAND-HELD FIRE EXTINGUISHERS - REPLACEMENT			MANDATORY	MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH UMLAUT HALON FREE FIRE EXTINGUISHERS										
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	UNK		MANDATORY	MTH 06-Feb-2026		-			Complete
					LDG 1704					
MOC : COMPLIED WITH - PERFORMED										
FAA 2023-10-02	INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	UNK		MANDATORY	MTH 06-Feb-2026		-			Complete
					LDG 1704					
MOC : COMPLIED WITH - PERFORMED										
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH			MANDATORY	MTH		-			N/A
					DAYS					
MOC : NOT APPLICABLE - Not Equipped: Not Applicable due CS-DOG is not equipped with the affected Brake Assembly Serial Numbers.										
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)	KMCO		MANDATORY	MTH 17-Feb-2017		-			N/A
					HRS 106.2					
					LDG 125					
MOC : NOT APPLICABLE - EASA AD 2015-0093 DATED 27 MAY, 2015, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHSR UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD	KMCO		MANDATORY	MTH 17-Feb-2017		-			N/A
					HRS 106.2					
					LDG 125					
MOC : NOT APPLICABLE - EASA AD 2015-0093 DATED 27 MAY, 2015, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2015-0093 DATED 27 MAY, 2015, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRN UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125		-			N/A
MOC : NOT APPLICABLE - EASA AD 2015-0093 DATED 27 MAY, 2015, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2015-0093	APPLIANCE AD - NAVIGATION & ATTITUDE HEADING REFERENCE SYSTEM & MODIFICATION / REPLACEMENT	KMCO		MANDATORY	MTH 17-Feb-2017 HRS 106.2 LDG 125 ACH 80.4		-			N/A
MOC : NOT APPLICABLE - EASA AD 2015-0093 DATED 27 MAY, 2015, DOES NOT APPLY. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
EASA 2018-0247	APPLIANCE AD - NAVIGATION - TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with TT31, AXP340 and KT74 mode S transponders.										
EASA 2019-0004	NAVIGATION - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS			MANDATORY	MTH DAYS		-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with GPS/SBAS receivers Topstar 200 LPV.										
EASA 2019-0179 PARA (1)	AMEND THE APPLICABLE AFM(S) IN ACCORDANCE WITH THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED AND INTRODUCE PRE-FLIGHT CHECKS			MANDATORY	MTH DAYS		-			N/A
MOC : NOT APPLICABLE - Not Equipped: The A/C is not equipped with Collins FDSA-6500 Flight Display System (P/N mentioned).										
EASA 2019-0179 PARA (2)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION ADDRESSED BY THIS AD; BEFORE NEXT FLIGHT AFTER MODIFICATION REMOVE THE AFM CHANGES AND PLACARD AND CONCURRENT WITH REMOVAL OF THE AFM(S) CHANGE AND PLACARD INSERT THE APPLICABLE POST-SB MTB 34-02 AFM TC			MANDATORY	MTH		-			N/A
MOC : NOT APPLICABLE - Not Equipped: The A/C is not equipped with Collins FDSA-6500 Flight Display System (P/N mentioned).										
EASA 2019-0179 R01 PARA (1)	AMEND THE APPLICABLE AFM(S) IAW THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED; AND INTRODUCE PRE-FLIGHT CHECKS			MANDATORY	DAYS 23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM (P/N MENTIONED).										
EASA 2019-0179 R01 PARA (2) & (4)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION THEN REMOVE THE AFM(S) CHANGES AND PLACARD, AS REQUIRED BY PARA (1) OF THIS AD. CONCURRENTLY, FOR CERTAIN TEXTRON AVIATION AEROPLANES, INSERT THE THE APPLICABLE POST-SB MTB-34-02 AFM TC OR POST-MOD AFMS, AS IDENTIFIED IN APPENDIX 2 OF THIS AD			MANDATORY	MTH 23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM (P/N MENTIONED).										
EASA 2019-0179 R01	APPLIANCE AD - NAVIGATION - AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE - UPDATE			MANDATORY	MTH 23-Feb-2021		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: WITH COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM (P/N MENTIONED).										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2019-0179	APPLIANCE AD - NAVIGATION - AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE - UPDATE			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: The A/C is not equipped with Collins FDSA-6500 Flight Display System (P/N mentioned).										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	MCO		MANDATORY MTH	04-Nov-2016		-			Complete
					HRS 102.8					
					LDG 120					
					ACH 80.4					
MOC : COMPLIED WITH - COMPLIED WITH AD2014-18-01 APPLIANCE AD BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MCO		MANDATORY MTH	04-Nov-2016		-			Complete
					HRS 102.8					
					LDG 120					
					ACH 80.4					
MOC : COMPLIED WITH - COMPLIED WITH AD2015-10-51-E APPLIANCE AD BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	MCO		MANDATORY MTH	04-Nov-2016		-			Complete
					HRS 102.8					
					LDG 120					
					ACH 80.4					
MOC : COMPLIED WITH - COMPLIED WITH AD2015-10-51 APPLIANCE AD BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.										
FAA 2019-01-02 PARA (G)(1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with Aspen Avionics Evolution Flight Display (EFD) EFD1000 Primary Flight Display, EFD1000 Multi-Function Display (MFD), EFD1000 Emergency Backup Display, or EFD500 MFD units.										
FAA 2019-01-02 PARA (G)(2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with Aspen Avionics Evolution Flight Display (EFD) EFD1000 Primary Flight Display, EFD1000 Multi-Function Display (MFD), EFD1000 Emergency Backup Display, or EFD500 MFD units.										
FAA 2019-01-02	APPLIANCE AD - NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG not equipped with Aspen Avionics Evolution Flight Display (EFD) EFD1000 Primary Flight Display, EFD1000 Multi-Function Display (MFD), EFD1000 Emergency Backup Display, or EFD500 MFD units.										
FAA 2019-07-10 PARA (F)(1)	REMOVE THE AHRS UNIT FROM SERVICE			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Northrop Grumman LITEF AHRS units (P/N mentioned)										
FAA 2019-07-10 PARA (F)(2)	REMOVAL FROM SERVICE OF P/N 145130-7100 TERMINATES THE REQUIREMENTS OF AD 2010-26-09 (75 FR 81424, DECEMBER 28, 2010)			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Northrop Grumman LITEF AHRS units (P/N mentioned)										
FAA 2019-07-10 PARA (F)(3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Northrop Grumman LITEF AHRS units (P/N mentioned)										
FAA 2019-07-10	APPLIANCE AD - NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL			MANDATORY MTH			-			N/A
MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with Northrop Grumman LITEF AHRS units (P/N mentioned)										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2019-12-09	NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)			MANDATORY	MTH		-			N/A
					DAYS					
	MOC : NOT APPLICABLE - Not Equipped: The A/C is not equipped with Collins FDSA-6500 Flight Display System (P/N mentioned).									
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK			MANDATORY	MTH		-			N/A
					DAYS					
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with TT31, AXP340 and KT74 mode S transponders.									
FAA 2019-13-03 PARA (H)	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK AS DEFINED IN THIS AD			MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with TT31, AXP340 and KT74 mode S transponders.									
FAA 2019-13-03	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION			MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE - Not Equipped: CS-DOG is not equipped with TT31, AXP340 and KT74 mode S transponders.									
FAA 2020-08-02	APPLIANCE AD - NAVIGATION - THALES AVS FRANCE SAS - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS			MANDATORY	MTH	23-Feb-2021	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: WITH THALES (GPS/SBAS) RECEIVERS P/NS C17149JA02 AND C17149HA01.									
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS			MANDATORY	MTH	23-Feb-2021	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS. THE FMS INSTALLED ON CS-DOG IS GARMIN.									
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION			MANDATORY	MTH	23-Feb-2021	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ASPEN AVIONICS EVOLUTION FLIGHT DISPLAY (EFD).									
FAA 2020-18-51-E	APPLIANCE/EMERGENCY AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT			MANDATORY	MTH	23-Feb-2021	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ATTITUDE INDICATOR P/NS MENTIONED.									
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT			MANDATORY	MTH	23-Feb-2021	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: WITH ATTITUDE INDICATOR P/NS MENTIONED.									
FAA 2021-05-17 PARA (G)(1) & (G) (2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)			MANDATORY	MTH	28-Mar-2022	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS FDSA-6500 P/N MENTIONED.									
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE			MANDATORY	MTH	28-Mar-2022	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS FDSA-6500 P/N MENTIONED.									
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE				MTH	28-Mar-2022	-			N/A
				MANDATORY						
	MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS FDSA-6500 P/N MENTIONED.									
FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITATIONS / SOFTWARE UPGRADE			MANDATORY	MTH	28-Mar-2022	-			N/A
	MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS FDSA-6500 P/N MENTIONED.									



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-08-07 PARA (G)(1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100			MANDATORY	MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS GPS - 4000S P/N 822-2189-100.										
FAA 2021-08-07 PARA (G)(2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE			MANDATORY	MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS GPS - 4000S P/N 822-2189-100.										
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE			MANDATORY	MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH ROCKWELL COLLINS GPS - 4000S P/N 822-2189-100.										
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE			MANDATORY	MTH 28-Mar-2022		-			N/A
MOC : NOT APPLICABLE - NOT EQUIPPED: CS-DOG IS NOT EQUIPPED WITH GMN-00962 GTS P/N 011-02571-0().										
EASA 2025-0297 R01 PARA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD			MANDATORY	DAYS		14			
MOC :										
EASA 2025-0297 R01 PARA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD				MTH		-			
MOC :										
EASA 2025-0297 R01 PARA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT			MANDATORY	DAYS		14			
MOC :										
EASA 2025-0297 R01 PARA (4)	LIFE LIMIT: REMOVE FROM SERVICE			MANDATORY	MTH		120			
MOC :										
EASA 2025-0297 R01	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE			MANDATORY	MTH		-			New Req
MOC :										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 28-Sep-2016		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE. B/E AEROSPACE PBE 119003-11 NOT INSTALLED.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 28-Sep-2016		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE. B/E AEROSPACE PBE 119003-11 NOT INSTALLED.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12			MANDATORY	MTH 28-Sep-2016		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE. B/E AEROSPACE PBE 119003-11 NOT INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	GSO	MANDATORY	MTH 28-Sep-2016 HRS 100.4 LDG 119		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE. B/E AEROSPACE PBE 119003-11 NOT INSTALLED.								
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED		MANDATORY			-			
	MOC :								
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED		MANDATORY			-			
	MOC :								
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.			MTH 08-Jan-2018		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE. B/E AEROSPACE PBE 119003-21 NOT INSTALLED.								
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES		MANDATORY			-			
	MOC :								
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS		MANDATORY	MTH		-			N/A
	MOC : NOT APPLICABLE								
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD		MANDATORY	MTH		-			
	MOC :								
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT		MANDATORY	MTH		-			
	MOC :								
FAA 2022-04-09 PARA (H) & (I)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF AN EFFECTED PART INSTALLED; IF INSTALLED, BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY AND PERFORM CORRECTIVE ACTIONS		MANDATORY	MTH 10-Jul-2022		-			N/A
	MOC : NOT APPLICABLE - BY PART:								
FAA 2022-04-09 PARA (J)	REPORT THE RESULTS OF THE INSPECTION		MANDATORY	MTH 10-Jul-2022		-			N/A
	MOC : NOT APPLICABLE - BY PART:								
FAA 2022-04-09	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECT / REPLACE		MANDATORY	MTH 28-Feb-2022		-			N/A
	MOC : NOT APPLICABLE - BY PART:								
FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT		MANDATORY	DAYS 31-Jan-2026 HRS 1959.33 LDG 1704		-			N/A
	MOC : NOT APPLICABLE - SAFRAN PBE SYSTEMS IS NOT INSTALLED.								
FAA 2026-03-09 PARA (G) EASA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD		MANDATORY	DAYS		14		26-Mar-2026	-3 m 18 d Over Due
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **SOLJETS**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0448**
Unit: **-0448** Reg No: **N448SJ**
Airworthiness: **14-Mar-2014**
Print Date: **14-Jul-2026 1:54PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1985.1	1714	14-Jul-2026	.02
ENG 1	1985.1	1714	14-Jul-2026	.02
ENG 2	1893.9	1641	14-Jul-2026	.02
AIR COND	829.6		14-Jul-2026	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2026-03-09 PARA (G) EASA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD									
				MTH			-			
				MANDATORY						
	MOC :									
FAA 2026-03-09 PARA (G) EASA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT									
				MANDATORY	DAYS		14			
	MOC :									
FAA 2026-03-09 PARA (G) EASA (4)	LIFE LIMIT: REMOVE FROM SERVICE			MANDATORY	MTH		120			
	MOC :									
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE									
				MANDATORY	MTH		-			
	MOC :									
TCCA CF-2010-03 E1	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR									
				MANDATORY	MTH	23-Jul-2013	-			N/A
	MOC : NOT APPLICABLE - DUE TO PART NUMBER OF FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE									
TCCA CF-2010-03 E2	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR									
				MANDATORY	MTH	16-Jul-2013	-			N/A
	MOC : NOT APPLICABLE - DUE TO PART NUMBER OF FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE									
FAA 2010-17-06 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				MANDATORY	MTH	23-Jul-2013	-			N/A
	MOC : NOT APPLICABLE - DUE TO PART NUMBER OF FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE									
FAA 2010-17-06 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				MANDATORY	MTH	16-Jul-2013	-			N/A
	MOC : NOT APPLICABLE - DUE TO PART NUMBER OF FUEL OIL HEAT EXCHANGER INSTALLED AT MANUFACTURE									