



## Status Report

PHENOM 300

S/N 50500559 N303TG

OWNER: CRASEL CORP.  
ADDRESS: 299 SOUTH MAIN STREET  
SALT LAKE CITY UT 84111-2580  
OFFICE:  
FAX:

OPERATOR: CRASEL CORP.  
ADDRESS: 299 SOUTH MAIN STREET  
SALT LAKE CITY UT 84111-2580  
OFFICE:  
FAX:

ANALYST: BRYAN STIKA  
EMAIL: BSTIKA@CAMPSYSTEMS.COM

+1-316-462-2408 (DIRECT)  
+1-631-588-3200 (MAIN)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO  
RECORD CHANGES TO ADDRESS, LAST ACTUALS  
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT SERIAL/REGNO: 50500559/N303TG MODEL: PHENOM 300 MANUFACTURER: EMBRAER

CERTIFICATION DATE: 23-APR-2020

LAST ACTUALS:  
1295:24 A/C HRS as of 01-JUN-2026  
598 AFL as of 01-JUN-2026

ENGINE NO. 1 SERIAL/PART: PCE-DG1117/3072913-01 MODEL: PW535E MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 23-APR-2020

0 ENG. HRS 0 A/C HRS  
0 ENC

LAST ACTUALS:  
1295:24 ENG. HRS as of 01-JUN-2026  
598 ENC as of 01-JUN-2026

ENGINE NO. 2 SERIAL/PART: PCE-DG1116/3072913-01 MODEL: PW535E MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 23-APR-2020

0 ENG. HRS 0 A/C HRS  
0 ENC

LAST ACTUALS:  
1295:24 ENG. HRS as of 01-JUN-2026  
598 ENC as of 01-JUN-2026



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                                        | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|----------------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA GENERAL                                    |              |                                                                            |               |          |                           |           |           |                |
| Z210-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION    |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                                  | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                          |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                          |               |          |                           |           |           |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                           |           |           | PKG:87         |
| Z210-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION    |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                                  | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                          |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                          |               |          |                           |           |           |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                           |           |           | PKG:87         |
| Z220-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 31-Mar-25                                                                  | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                | HRS          | 987:24                                                                     |               |          |                           |           |           |                |
|                                                | AFL          | 456                                                                        |               |          |                           |           |           |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                           |           |           | PKG:84         |
| Z220-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                                  | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                          |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                          |               |          |                           |           |           |                |
| PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00 |              |                                                                            |               |          |                           |           |           | PKG:87         |
| Z230-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION    |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                                  | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                          |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                          |               |          |                           |           |           |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                            |               |          |                           |           |           | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                                     | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|-------------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA GENERAL                                    |              |                                                                         |               |          |                           |           |           |                |
| Z230-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                               | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                       |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                       |               |          |                           |           |           |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                         |               |          |                           |           |           | PKG:87         |
| Z240-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION  |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                               | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                       |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                       |               |          |                           |           |           |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                         |               |          |                           |           |           | PKG:87         |
| Z240-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION  |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 31-Mar-25                                                               | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                | HRS          | 987:24                                                                  |               |          |                           |           |           |                |
|                                                | AFL          | 456                                                                     |               |          |                           |           |           |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |              |                                                                         |               |          |                           |           |           | PKG:84         |
| Z310-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION    |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                               | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                       |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                       |               |          |                           |           |           |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                         |               |          |                           |           |           | PKG:87         |
| Z310-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION    |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                               | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                       |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                       |               |          |                           |           |           |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                         |               |          |                           |           |           | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                                 | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|---------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA GENERAL                                    |              |                                                                     |               |          |                           |           |           |                |
| Z320-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                           | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                   |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                   |               |          |                           |           |           |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                     |               |          |                           |           |           | PKG:87         |
| Z320-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                           | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                   |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                   |               |          |                           |           |           |                |
| PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00 |              |                                                                     |               |          |                           |           |           | PKG:87         |
| Z330-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER       |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                           | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                   |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                   |               |          |                           |           |           |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                     |               |          |                           |           |           | PKG:87         |
| Z330-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER       |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                           | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                                   |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                                   |               |          |                           |           |           |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                     |               |          |                           |           |           | PKG:87         |
| Z340-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER     |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 31-Mar-25                                                           | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                | HRS          | 987:24                                                              |               |          |                           |           |           |                |
|                                                | AFL          | 456                                                                 |               |          |                           |           |           |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                     |               |          |                           |           |           | PKG:84         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                             | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|-----------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA GENERAL                                    |              |                                                                 |               |          |                           |           |           |                |
| Z340-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                       | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                               |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                               |               |          |                           |           |           |                |
| PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00 |              |                                                                 |               |          |                           |           |           | PKG:87         |
| Z410-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON                 |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                       | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                               |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                               |               |          |                           |           |           |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                           |           |           | PKG:87         |
| Z410-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON                 |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                       | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                               |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                               |               |          |                           |           |           |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                           |           |           | PKG:87         |
| Z430-001                                       | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE               |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                       | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                               |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                               |               |          |                           |           |           |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                           |           |           | PKG:87         |
| Z430-002                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE               |               |          |                           |           |           | Service ATA:-- |
|                                                | MOS          | 23-Apr-20                                                       | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 0                                                               |               |          |                           |           |           |                |
|                                                | AFL          | 0                                                               |               |          |                           |           |           |                |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00 |              |                                                                 |               |          |                           |           |           | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit         | C/W                                                             | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------------|--------------|-----------------------------------------------------------------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA GENERAL                                        |              |                                                                 |              |          |                           |           |           |                |
| Z500-001                                           | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS                 |              |          |                           |           |           | Service ATA:-- |
|                                                    | MOS          | 31-Mar-25                                                       | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                    | HRS          | 987:24                                                          |              |          |                           |           |           |                |
|                                                    | AFL          | 456                                                             |              |          |                           |           |           |                |
| PROC. REF: AMM 05-45-00PROC. REF: AMM 05-45-00     |              |                                                                 |              |          |                           |           |           | PKG:84         |
| Z500-002                                           | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS                 |              |          |                           |           |           | Service ATA:-- |
|                                                    | MOS          | 31-Mar-25                                                       | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                    | HRS          | 987:24                                                          |              |          |                           |           |           |                |
|                                                    | AFL          | 456                                                             |              |          |                           |           |           |                |
| PROC. REF: AMM 05-45-00PROC. REF: AMM 05-45-00     |              |                                                                 |              |          |                           |           |           | PKG:84         |
| Z700-001                                           | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY |              |          |                           |           |           | Service ATA:-- |
|                                                    | MOS          | 31-Mar-25                                                       | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                    | HRS          | 987:24                                                          |              |          |                           |           |           |                |
|                                                    | AFL          | 456                                                             |              |          |                           |           |           |                |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00     |              |                                                                 |              |          |                           |           |           | PKG:84         |
| ATA 00 - INFORMATION                               |              |                                                                 |              |          |                           |           |           |                |
| 00001                                              |              | NO. 1 ENGINE - ADD CERT DATE                                    |              |          |                           |           |           | Service ATA:00 |
|                                                    | MOS/MSC      | 06-Dec-19                                                       | -            |          |                           |           |           |                |
|                                                    | HRS          | 0                                                               |              |          |                           |           |           |                |
|                                                    | ENC          | 0                                                               |              |          |                           |           |           |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                 |              |          |                           |           |           |                |
| 00001                                              |              | NO. 2 ENGINE - ADD CERT DATE                                    |              |          |                           |           |           | Service ATA:00 |
|                                                    | MOS/MSC      | 05-Dec-19                                                       | -            |          |                           |           |           |                |
|                                                    | HRS          | 0                                                               |              |          |                           |           |           |                |
|                                                    | ENC          | 0                                                               |              |          |                           |           |           |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                 |              |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                            | Unit                                                                         | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|------------------------------------|------------------------------------------------------------------------------|-----|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION               |                                                                              |     |          |          |                           |           |           |                          |
| EM55-210514-ALS                    | REVIEW EMBRAER PHENOM 300 - AMM - CHAPTER 04- REV. 14, DATED MAY 14TH, 2021  |     |          |          |                           |           |           | Service ATA:00           |
|                                    | MOS/MSC                                                                      |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                                    | HRS                                                                          |     |          |          |                           |           |           |                          |
|                                    | AFL                                                                          |     |          |          |                           |           |           |                          |
| PROC. REF: RCF 00PROC. REF: RCF 00 |                                                                              |     |          |          |                           |           |           |                          |
| EM55-211103-SMR                    | REVIEW EMBRAER PHENOM 300 - AMM 2757, SMR REV. 04, DATED NOV 3, 2021         |     |          |          |                           |           |           | Service ATA:00           |
|                                    | MOS/MSC                                                                      |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                                    | HRS                                                                          |     |          |          |                           |           |           |                          |
|                                    | AFL                                                                          |     |          |          |                           |           |           |                          |
| EM55-220505-CAMP ADJUSTMENT        | REVIEW CAMP ADJUSTMENT FORM DATED MAY 05/2022 FOR EMBRAER PHENOM 300         |     |          |          |                           |           |           | Service ATA:00           |
|                                    | MOS/MSC                                                                      |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                                    | HRS                                                                          |     |          |          |                           |           |           |                          |
|                                    | AFL                                                                          |     |          |          |                           |           |           |                          |
| PROC. REF: RCF 00PROC. REF: RCF 00 |                                                                              |     |          |          |                           |           |           |                          |
| EM55-220630-CAMP ADJUSTMENT        | REVIEW EMBRAER EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED JUN 30, 2022      |     |          |          |                           |           |           | Service ATA:00           |
|                                    | MOS/MSC                                                                      |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                                    | HRS                                                                          |     |          |          |                           |           |           |                          |
|                                    | AFL                                                                          |     |          |          |                           |           |           |                          |
| PROC. REF: RCF -PROC. REF: RCF -   |                                                                              |     |          |          |                           |           |           |                          |
| EM55-220812-CAMP ADJUSTMENT        | REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-505 - PHENOM 300 |     |          |          |                           |           |           | Service ATA:00           |
|                                    | MOS/MSC                                                                      |     | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                                    | HRS                                                                          |     |          |          |                           |           |           |                          |
|                                    | AFL                                                                          |     |          |          |                           |           |           |                          |
| PROC. REF: RCF 00PROC. REF: RCF 00 |                                                                              |     |          |          |                           |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                                                                         | C/W       | Interval      | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition              |
|------------------------------------------------|--------------------------------------------------------------------------------------------------------------|-----------|---------------|-----------|---------------------------|-----------|--------------|--------------------------|
| ATA 00 - INFORMATION                           |                                                                                                              |           |               |           |                           |           |              |                          |
| EM55-221017-AWL                                | REVIEW EMB-505 - PHENOM 300 AMM - PART IV - AIRWORTHINESS LIMITATIONS (AWL) REV 1 DATED OCT 17/2022          |           |               |           |                           |           |              | Service ATA:00           |
|                                                | MOS/MSC                                                                                                      |           | -             |           |                           |           |              | REQUIREMENT CHANGE FORMS |
|                                                | HRS                                                                                                          |           |               |           |                           |           |              |                          |
|                                                | AFL                                                                                                          |           |               |           |                           |           |              |                          |
| PROC. REF: RCF 00PROC. REF: RCF 00             |                                                                                                              |           |               |           |                           |           |              |                          |
| EM55-221103-SMR                                | REVIEW EMB-505 - PHENOM 300 AMM - PART III - SCHEDULE MAINTENANCE REQUIREMENTS (SMR) REV 5 DATED NOV 03/2022 |           |               |           |                           |           |              | Service ATA:00           |
|                                                | MOS/MSC                                                                                                      |           | -             |           |                           |           |              | REQUIREMENT CHANGE FORMS |
|                                                | HRS                                                                                                          |           |               |           |                           |           |              |                          |
|                                                | AFL                                                                                                          |           |               |           |                           |           |              |                          |
| PROC. REF: RCF 00PROC. REF: RCF 00             |                                                                                                              |           |               |           |                           |           |              |                          |
| EM55-230201-CAMP ADJUSTMENT                    | REVIEW EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED FEB 01, 2023                                              |           |               |           |                           |           |              | Service ATA:00           |
|                                                | MOS/MSC                                                                                                      |           | -             |           |                           |           |              | REQUIREMENT CHANGE FORMS |
|                                                | HRS                                                                                                          |           |               |           |                           |           |              |                          |
|                                                | AFL                                                                                                          |           |               |           |                           |           |              |                          |
| EM55-230216-CAMP ADJUSTMENT                    | REVIEW CAMP ADJUSTMENT FORM DATED FEB 16/2023 FOR EMB-505 - PHENOM 300                                       |           |               |           |                           |           |              | Service ATA:00           |
|                                                | MOS/MSC                                                                                                      |           | -             |           |                           |           |              | REQUIREMENT CHANGE FORMS |
|                                                | HRS                                                                                                          |           |               |           |                           |           |              |                          |
|                                                | AFL                                                                                                          |           |               |           |                           |           |              |                          |
| PROC. REF: RCF 00PROC. REF: RCF 00             |                                                                                                              |           |               |           |                           |           |              |                          |
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                                              |           |               |           |                           |           |              |                          |
| 05-30-01                                       | 800 FH MAINTENANCE PACKAGE                                                                                   |           |               |           |                           |           |              | Package ATA:05           |
|                                                | MOS                                                                                                          | 19-Mar-24 |               |           |                           |           |              |                          |
|                                                | HRS                                                                                                          | 781:30    | 800 (+30/-30) | Adj 18:30 | 1600                      | 1630      | 304:36 (+30) |                          |
|                                                | AFL                                                                                                          | 364       |               |           |                           |           |              |                          |
| PROC. REF: SMR 05-30-01PROC. REF: SMR 05-30-01 |                                                                                                              |           |               |           |                           |           |              |                          |
|                                                |                                                                                                              |           |               |           |                           |           |              | PKG:1                    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|------------------------------------------------|------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                |           |                |          |                           |           |               |                |
| 051254                                         | NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                                            | 13-Mar-26 | 12 (+30d)      |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30)   |                |
|                                                | HRS                                            | 1221:24   | 800 (+10%)     |          | (2021:24)<br>2021:24      | 2101:24   | 726 (+80)     |                |
|                                                | ENC                                            | 564       |                |          |                           |           |               |                |
| PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00   |                                                |           |                |          |                           |           |               | PKG:1          |
| 051254                                         | NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                                            | 13-Mar-26 | 12 (+30d)      |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30)   |                |
|                                                | HRS                                            | 1221:24   | 800 (+10%)     |          | (2021:24)<br>2021:24      | 2101:24   | 726 (+80)     |                |
|                                                | ENC                                            | 564       |                |          |                           |           |               |                |
| PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00   |                                                |           |                |          |                           |           |               | PKG:1          |
| 05-30-10                                       | 1600 FH MAINTENANCE PACKAGE                    |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                                            | 23-Apr-20 |                |          |                           |           |               |                |
|                                                | HRS                                            | 0         | 1600 (+30/-30) |          | 1600                      | 1630      | 304:36 (+30)  |                |
|                                                | AFL                                            | 0         |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-10PROC. REF: SMR 05-30-10 |                                                |           |                |          |                           |           |               | PKG:10         |
| 05-30-20                                       | 2400 FH MAINTENANCE PACKAGE                    |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                                            | 23-Apr-20 |                |          |                           |           |               |                |
|                                                | HRS                                            | 0         | 2400 (+30/-30) |          | 2400                      | 2430      | 1104:36 (+30) |                |
|                                                | AFL                                            | 0         |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-20PROC. REF: SMR 05-30-20 |                                                |           |                |          |                           |           |               | PKG:20         |
| 05-30-40                                       | 3200 FH MAINTENANCE PACKAGE                    |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                                            | 23-Apr-20 |                |          |                           |           |               |                |
|                                                | HRS                                            | 0         | 3200 (+30/-30) |          | 3200                      | 3230      | 1904:36 (+30) |                |
|                                                | AFL                                            | 0         |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-40PROC. REF: SMR 05-30-40 |                                                |           |                |          |                           |           |               | PKG:40         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                              | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|------------------------------------------------|-----------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                   |           |                |          |                           |           |               |                |
| 05-30-42                                       | 3200 FH/60 MO MAINTENANCE PACKAGE |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                               | 31-Mar-25 | 60 (+1m/-1m)   |          | 31-Mar-30                 | 30-Apr-30 | 1341 d (+30)  |                |
|                                                | HRS                               | 987:24    | 3200 (+30/-30) |          | 4187:24                   | 4217:24   | 2892 (+30)    |                |
|                                                | AFL                               | 456       |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-42PROC. REF: SMR 05-30-42 |                                   |           |                |          |                           |           |               | PKG:42         |
| 05-30-50                                       | 5600 FH MAINTENANCE PACKAGE       |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                               | 23-Apr-20 |                |          |                           |           |               |                |
|                                                | HRS                               | 0         | 5600 (+30/-30) |          | 5600                      | 5630      | 4304:36 (+30) |                |
|                                                | AFL                               | 0         |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-50PROC. REF: SMR 05-30-50 |                                   |           |                |          |                           |           |               | PKG:50         |
| 05-30-60                                       | 6400 FH MAINTENANCE PACKAGE       |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                               | 23-Apr-20 |                |          |                           |           |               |                |
|                                                | HRS                               | 0         | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                |
|                                                | AFL                               | 0         |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-60PROC. REF: SMR 05-30-60 |                                   |           |                |          |                           |           |               | PKG:60         |
| 05-30-80                                       | 12 MO MAINTENANCE PACKAGE         |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                               | 13-Mar-26 | 12 (+1m/-1m)   | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30)   |                |
|                                                | HRS                               | 1221:24   |                |          |                           |           |               |                |
|                                                | AFL                               | 564       |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-80PROC. REF: SMR 05-30-80 |                                   |           |                |          |                           |           |               | PKG:80         |
| 05-30-81                                       | 24 MO MAINTENANCE PACKAGE         |           |                |          |                           |           |               | Package ATA:05 |
|                                                | MOS                               | 13-Mar-26 | 24 (+1m/-1m)   | Adj 6d   | 19-Mar-28                 | 19-Apr-28 | 599 d (+31)   |                |
|                                                | HRS                               | 1221:24   |                |          |                           |           |               |                |
|                                                | AFL                               | 564       |                |          |                           |           |               |                |
| PROC. REF: SMR 05-30-81PROC. REF: SMR 05-30-81 |                                   |           |                |          |                           |           |               | PKG:81         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                        | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|------------------------------------------------|---------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                             |           |                 |          |                           |           |              |                |
| 05-30-82                                       | 36 MO MAINTENANCE PACKAGE                   |           |                 |          |                           |           |              | Package ATA:05 |
|                                                | MOS                                         | 13-Mar-26 | 36 (+1m/-1m)    | Adj 4d   | 17-Mar-29                 | 17-Apr-29 | 962 d (+31)  |                |
|                                                | HRS                                         | 1221:24   |                 |          |                           |           |              |                |
|                                                | AFL                                         | 564       |                 |          |                           |           |              |                |
| PROC. REF: SMR 05-30-82PROC. REF: SMR 05-30-82 |                                             |           |                 |          |                           |           |              | PKG:82         |
| 05-30-83                                       | 48 MO MAINTENANCE PACKAGE                   |           |                 |          |                           |           |              | Package ATA:05 |
|                                                | MOS                                         | 19-Mar-24 | 48 (+1m/-1m)    |          | 19-Mar-28                 | 19-Apr-28 | 599 d (+31)  |                |
|                                                | HRS                                         | 781:30    |                 |          |                           |           |              |                |
|                                                | AFL                                         | 364       |                 |          |                           |           |              |                |
| PROC. REF: SMR 05-30-83PROC. REF: SMR 05-30-83 |                                             |           |                 |          |                           |           |              | PKG:83         |
| 05-30-84                                       | 60 MO MAINTENANCE PACKAGE                   |           |                 |          |                           |           |              | Package ATA:05 |
|                                                | MOS                                         | 31-Mar-25 | 60 (+1m/-1m)    | Adj 23d  | 23-Apr-30                 | 23-May-30 | 1364 d (+30) |                |
|                                                | HRS                                         | 987:24    |                 |          |                           |           |              |                |
|                                                | AFL                                         | 456       |                 |          |                           |           |              |                |
| PROC. REF: SMR 05-30-84PROC. REF: SMR 05-30-84 |                                             |           |                 |          |                           |           |              | PKG:84         |
| 05-30-87                                       | 120 MO MAINTENANCE PACKAGE                  |           |                 |          |                           |           |              | Package ATA:05 |
|                                                | MOS                                         | 23-Apr-20 | 120 (+1m/-1m)   |          | 23-Apr-30                 | 23-May-30 | 1364 d (+30) |                |
|                                                | HRS                                         | 0         |                 |          |                           |           |              |                |
|                                                | AFL                                         | 0         |                 |          |                           |           |              |                |
| PROC. REF: SMR 05-30-87PROC. REF: SMR 05-30-87 |                                             |           |                 |          |                           |           |              | PKG:87         |
| 05-30-90                                       | 120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE |           |                 |          |                           |           |              | Package ATA:05 |
|                                                | MOS                                         | 23-Apr-20 | T:120 (+1m/-1m) |          | 23-Apr-30                 | 23-May-30 | 1364 d (+30) |                |
|                                                | HRS                                         | 0         |                 |          |                           |           |              |                |
|                                                | AFL                                         | 0         |                 |          |                           |           |              |                |
| PROC. REF: SMR 05-30-90PROC. REF: SMR 05-30-90 |                                             |           |                 |          |                           |           |              | PKG:90         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                       |           |          |          |                           |           |           |                |
| 05-50-00-210-802                             | NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                               | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                   | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                   | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                           |           |           |                |
| 05-50-00-210-802                             | NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                               | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                   | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                   | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                           |           |           |                |
| 05-50-00-210-803                             | NO. 1 ENGINE - ENGINE OVERTEMPERATURE                 |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                               | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                   | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                   | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                           |           |           |                |
| 05-50-00-210-803                             | NO. 2 ENGINE - ENGINE OVERTEMPERATURE                 |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                               | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                   | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                   | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                           |           |           |                |
| 05-50-00-210-804                             | NO. 1 ENGINE - ENGINE OVERSPEED                       |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                               | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                   | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                   | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                           |           |           |                |
| 05-50-00-210-804                             | NO. 2 ENGINE - ENGINE OVERSPEED                       |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                               | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                   | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                   | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                       |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|----------------------------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                            |           |          |          |                           |           |           |                                  |
| 05-50-00-210-805                             | NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD) |           |          |          |                           |           |           | Service ATA:05                   |
|                                              | MOS/MSC                                    | 06-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                                  |
| 05-50-00-210-805                             | NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD) |           |          |          |                           |           |           | Service ATA:05                   |
|                                              | MOS/MSC                                    | 05-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                                  |
| 05-50-00-210-806                             | NO. 1 ENGINE - LIGHTNING STRIKE            |           |          |          |                           |           |           | Service ATA:05                   |
|                                              | MOS/MSC                                    | 06-Dec-19 | A/R      |          |                           |           |           |                                  |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                                  |
| 05-50-00-210-806                             | NO. 2 ENGINE - LIGHTNING STRIKE            |           |          |          |                           |           |           | Service ATA:05                   |
|                                              | MOS/MSC                                    | 05-Dec-19 | A/R      |          |                           |           |           |                                  |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                                  |
| 05-50-00-210-807                             | NO. 1 ENGINE - DROPPED ENGINE              |           |          |          |                           |           |           | Service ATA:05                   |
|                                              | MOS/MSC                                    | 06-Dec-19 | A/R      |          |                           |           |           |                                  |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                                  |
| 05-50-00-210-807                             | NO. 2 ENGINE - DROPPED ENGINE              |           |          |          |                           |           |           | Service ATA:05                   |
|                                              | MOS/MSC                                    | 05-Dec-19 | A/R      |          |                           |           |           |                                  |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                             |           |          |          |                           |           |           |                |
| 05-50-00-210-808                             | NO. 1 ENGINE - HEAVY LANDING                |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                     | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                         | 0         |          |          |                           |           |           |                |
|                                              | ENC                                         | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                           |           |           |                |
| 05-50-00-210-808                             | NO. 2 ENGINE - HEAVY LANDING                |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                     | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                         | 0         |          |          |                           |           |           |                |
|                                              | ENC                                         | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                           |           |           |                |
| 05-50-00-210-809                             | NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                     | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                         | 0         |          |          |                           |           |           |                |
|                                              | ENC                                         | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                           |           |           |                |
| 05-50-00-210-809                             | NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                     | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                         | 0         |          |          |                           |           |           |                |
|                                              | ENC                                         | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                           |           |           |                |
| 05-50-00-210-810                             | NO. 1 ENGINE - ENGINE IMMERSION IN WATER    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                     | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                         | 0         |          |          |                           |           |           |                |
|                                              | ENC                                         | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                           |           |           |                |
| 05-50-00-210-810                             | NO. 2 ENGINE - ENGINE IMMERSION IN WATER    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                     | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                         | 0         |          |          |                           |           |           |                |
|                                              | ENC                                         | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                             |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                               |           |          |          |                           |           |           |                |
| 05-50-00-210-811                             | NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT     |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                                       | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                           | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                           |           |           |                |
| 05-50-00-210-811                             | NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT     |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                                       | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                           | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                           |           |           |                |
| 05-50-00-210-812                             | NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                                       | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                           | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                           |           |           |                |
| 05-50-00-210-812                             | NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                                       | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                           | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                           |           |           |                |
| 05-50-00-210-813                             | NO. 1 ENGINE - LOSS OF OIL                                    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                                       | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                           | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                           |           |           |                |
| 05-50-00-210-813                             | NO. 2 ENGINE - LOSS OF OIL                                    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                                       | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                           | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                               |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit    | C/W                                                | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|---------|----------------------------------------------------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |         |                                                    |          |          |                           |           |           |                |
| 05-50-00-210-814                             | U       | NO. 1 ENGINE - CHIP DETECTOR LIGHT "ON"            |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC | 06-Dec-19                                          | A/R      |          |                           |           |           |                |
|                                              | HRS     | 0                                                  |          |          |                           |           |           |                |
|                                              | ENC     | 0                                                  |          |          |                           |           |           |                |
| 05-50-00-210-814                             | U       | NO. 2 ENGINE - CHIP DETECTOR LIGHT "ON"            |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC | 05-Dec-19                                          | A/R      |          |                           |           |           |                |
|                                              | HRS     | 0                                                  |          |          |                           |           |           |                |
|                                              | ENC     | 0                                                  |          |          |                           |           |           |                |
| 05-50-00-210-815                             |         | NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS      |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC | 06-Dec-19                                          | A/R      |          |                           |           |           |                |
|                                              | HRS     | 0                                                  |          |          |                           |           |           |                |
|                                              | ENC     | 0                                                  |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |         |                                                    |          |          |                           |           |           |                |
| 05-50-00-210-815                             |         | NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS      |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC | 05-Dec-19                                          | A/R      |          |                           |           |           |                |
|                                              | HRS     | 0                                                  |          |          |                           |           |           |                |
|                                              | ENC     | 0                                                  |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |         |                                                    |          |          |                           |           |           |                |
| 05-50-00-210-816                             |         | NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC | 06-Dec-19                                          | A/R      |          |                           |           |           |                |
|                                              | HRS     | 0                                                  |          |          |                           |           |           |                |
|                                              | ENC     | 0                                                  |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |         |                                                    |          |          |                           |           |           |                |
| 05-50-00-210-816                             |         | NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC | 05-Dec-19                                          | A/R      |          |                           |           |           |                |
|                                              | HRS     | 0                                                  |          |          |                           |           |           |                |
|                                              | ENC     | 0                                                  |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |         |                                                    |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                            |           |          |          |                           |           |           |                |
| 05-50-00-210-817                             | NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                    | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                |
| 05-50-00-210-817                             | NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                    | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                |
| 05-50-00-210-818                             | NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                    | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                |
| 05-50-00-210-818                             | NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                    | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                |
| 05-50-00-210-819                             | NO. 1 ENGINE - FUEL FILTER CONTAMINATION   |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                    | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                |
| 05-50-00-210-819                             | NO. 2 ENGINE - FUEL FILTER CONTAMINATION   |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                    | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                        | 0         |          |          |                           |           |           |                |
|                                              | ENC                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                            |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS      |                                                      |           |          |          |                           |           |           |                |
| 05-50-00-210-820                             | NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN            |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                              | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                  | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                  | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                           |           |           |                |
| 05-50-00-210-820                             | NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN            |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                              | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                  | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                  | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                           |           |           |                |
| 05-50-00-210-821                             | NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                              | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                  | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                  | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                           |           |           |                |
| 05-50-00-210-821                             | NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                              | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                  | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                  | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                           |           |           |                |
| 05-50-00-210-822                             | NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                              | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                  | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                  | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                           |           |           |                |
| 05-50-00-210-822                             | NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL    |           |          |          |                           |           |           | Service ATA:05 |
|                                              | MOS/MSC                                              | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                  | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                  | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00 |                                                      |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|------------------------------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                               |           |          |          |                           |           |           |                                  |
| 05-50-00-210-823                               | NO. 1 ENGINE - FUEL CONTAMINATION             |           |          |          |                           |           |           | Service ATA:05                   |
|                                                | MOS/MSC                                       | 06-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                           | 0         |          |          |                           |           |           |                                  |
|                                                | ENC                                           | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                               |           |          |          |                           |           |           |                                  |
| 05-50-00-210-823                               | NO. 2 ENGINE - FUEL CONTAMINATION             |           |          |          |                           |           |           | Service ATA:05                   |
|                                                | MOS/MSC                                       | 05-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                           | 0         |          |          |                           |           |           |                                  |
|                                                | ENC                                           | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                               |           |          |          |                           |           |           |                                  |
| 05-50-00-210-824                               | NO. 1 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE |           |          |          |                           |           |           | Service ATA:05                   |
|                                                | MOS/MSC                                       | 06-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                           | 0         |          |          |                           |           |           |                                  |
|                                                | ENC                                           | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                               |           |          |          |                           |           |           |                                  |
| 05-50-00-210-824                               | NO. 2 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE |           |          |          |                           |           |           | Service ATA:05                   |
|                                                | MOS/MSC                                       | 05-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                           | 0         |          |          |                           |           |           |                                  |
|                                                | ENC                                           | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00   |                                               |           |          |          |                           |           |           |                                  |
| 05-50-01-210-801                               | LIGHTNING STRIKE - GENERAL VISUAL INSPECTION  |           |          |          |                           |           |           | Service ATA:05                   |
|                                                | MOS/MSC                                       | 23-Apr-20 | A/R      |          |                           |           |           |                                  |
|                                                | HRS                                           | 0         |          |          |                           |           |           |                                  |
|                                                | AFL                                           | 0         |          |          |                           |           |           |                                  |
| PROC. REF: AMM 05-50-01PROC. REF: AMM 05-50-01 |                                               |           |          |          |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                          |           |          |          |                           |           |           |                |
| 05-50-01-210-802                               | FORWARD FUSELAGE LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION                            |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-01PROC. REF: AMM 05-50-01 |                                                                                          |           |          |          |                           |           |           |                |
| 05-50-01-210-803                               | CENTER FUSELAGE AND WING-TO-FUSELAGE FARING LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-01PROC. REF: AMM 05-50-01 |                                                                                          |           |          |          |                           |           |           |                |
| 05-50-01-210-804                               | WINGS LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION                                       |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-01PROC. REF: AMM 05-50-01 |                                                                                          |           |          |          |                           |           |           |                |
| 05-50-01-210-805                               | AFT FUSELAGE, TAIL CONE AND EMPENNAGE LIGHTNING-STRIKE - GENERAL VISUAL INSPECTION       |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-01PROC. REF: AMM 05-50-01 |                                                                                          |           |          |          |                           |           |           |                |
| 05-50-01-210-806                               | ENGINE NACELLE LIGHTNING STRIKE - GENERAL VISUAL INSPECTION                              |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-01PROC. REF: AMM 05-50-01 |                                                                                          |           |          |          |                           |           |           |                |
| 05-50-02-200-801                               | HARD LANDING OR OFF-TEMPERATURE - INSPECTION                                             |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-02PROC. REF: AMM 05-50-02 |                                                                                          |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                          |           |          |          |                           |           |           |                |
| 05-50-04-200-801                               | OVERSPEED - INSPECTION                   |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-04PROC. REF: AMM 05-50-04 |                                          |           |          |          |                           |           |           |                |
| 05-50-06-200-801                               | LANDING GEAR DOWN OVERSPEED - INSPECTION |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-06PROC. REF: AMM 05-50-06 |                                          |           |          |          |                           |           |           |                |
| 05-50-07-200-801                               | FLAP EXTENDED OVERSPEED - INSPECTION     |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-07PROC. REF: AMM 05-50-07 |                                          |           |          |          |                           |           |           |                |
| 05-50-08-200-801                               | CABIN DEPRESSURIZATION - INSPECTION      |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-08PROC. REF: AMM 05-50-08 |                                          |           |          |          |                           |           |           |                |
| 05-50-09-200-801                               | ICE OR SNOW CONDITION - INSPECTION       |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-09PROC. REF: AMM 05-50-09 |                                          |           |          |          |                           |           |           |                |
| 05-50-10-200-801                               | HIGH-ENERGY STOP CONDITION - INSPECTION  |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                  | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                      | 0         |          |          |                           |           |           |                |
|                                                | AFL                                      | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-10PROC. REF: AMM 05-50-10 |                                          |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|-----------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                           |           |          |          |                           |           |           |                |
| 05-50-11-200-801                               | LANDING GEAR FREE-FALL CONDITION - INSPECTION             |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                   | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                       | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                       | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-11PROC. REF: AMM 05-50-11 |                                                           |           |          |          |                           |           |           |                |
| 05-50-12-200-801                               | OVERHEATED WHEELS - INSPECTION                            |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                   | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                       | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                       | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-12PROC. REF: AMM 05-50-12 |                                                           |           |          |          |                           |           |           |                |
| 05-50-13-200-801                               | WHEEL OVERSPEED - INSPECTION                              |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                   | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                       | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                       | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-13PROC. REF: AMM 05-50-13 |                                                           |           |          |          |                           |           |           |                |
| 05-50-14-200-801                               | TIRE TREAD FAILURE - INSPECTION                           |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                   | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                       | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                       | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-14PROC. REF: AMM 05-50-14 |                                                           |           |          |          |                           |           |           |                |
| 05-50-15-200-801                               | TIRE BURST WITH LANDING GEAR FULLY RETRACTED - INSPECTION |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                   | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                       | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                       | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-15PROC. REF: AMM 05-50-15 |                                                           |           |          |          |                           |           |           |                |
| 05-50-16-200-801                               | ON-GROUND GALE EVENTS - INSPECTION                        |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                   | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                                       | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                       | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-16PROC. REF: AMM 05-50-16 |                                                           |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                     |           |          |          |                           |           |           |                |
| 05-50-17-200-801                               | VOLCANIC ASH CONDITION - INSPECTION |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                             | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                 | 0         |          |          |                           |           |           |                |
|                                                | AFL                                 | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-17PROC. REF: AMM 05-50-17 |                                     |           |          |          |                           |           |           |                |
| 05-50-18-200-801                               | LOAD FACTOR EXCEEDANCE - INSPECTION |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                             | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                 | 0         |          |          |                           |           |           |                |
|                                                | AFL                                 | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-18PROC. REF: AMM 05-50-18 |                                     |           |          |          |                           |           |           |                |
| 05-50-19-200-801                               | TOILET OVERSERVICING - INSPECTION   |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                             | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                 | 0         |          |          |                           |           |           |                |
|                                                | AFL                                 | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-19PROC. REF: AMM 05-50-19 |                                     |           |          |          |                           |           |           |                |
| 05-50-20-200-801                               | SEVERE TURBULENCE - INSPECTION      |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                             | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                 | 0         |          |          |                           |           |           |                |
|                                                | AFL                                 | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-20PROC. REF: AMM 05-50-20 |                                     |           |          |          |                           |           |           |                |
| 05-50-21-200-801                               | LANDING OVERWEIGHT - INSPECTION     |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                             | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                 | 0         |          |          |                           |           |           |                |
|                                                | AFL                                 | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-21PROC. REF: AMM 05-50-21 |                                     |           |          |          |                           |           |           |                |
| 05-50-26-200-801                               | SANDSTORM CONDITION - INSPECTION    |           |          |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                             | 23-Apr-20 | A/R      |          |                           |           |           |                |
|                                                | HRS                                 | 0         |          |          |                           |           |           |                |
|                                                | AFL                                 | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 05-50-26PROC. REF: AMM 05-50-26 |                                     |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                                                   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|----------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS        |                                                                                        |           |               |          |                           |           |           |                |
| 05-50-27-200-801                               | AIRCRAFT NOISE AND VIBRATION- INSPECTION                                               |           |               |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                | 23-Apr-20 | A/R           |          |                           |           |           |                |
|                                                | HRS                                                                                    | 0         |               |          |                           |           |           |                |
|                                                | AFL                                                                                    | 0         |               |          |                           |           |           |                |
| PROC. REF: AMM 05-50-27PROC. REF: AMM 05-50-27 |                                                                                        |           |               |          |                           |           |           |                |
| 05-50-28-200-801                               | NLG INCORRECT TOWING - INSPECTION                                                      |           |               |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                | 23-Apr-20 | A/R           |          |                           |           |           |                |
|                                                | HRS                                                                                    | 0         |               |          |                           |           |           |                |
|                                                | AFL                                                                                    | 0         |               |          |                           |           |           |                |
| PROC. REF: AMM 05-50-28PROC. REF: AMM 05-50-28 |                                                                                        |           |               |          |                           |           |           |                |
| 05-50-29-200-801                               | FIRE EXTINGUISHING FOAM - INSPECTION                                                   |           |               |          |                           |           |           | Service ATA:05 |
|                                                | MOS/MSC                                                                                | 23-Apr-20 | A/R           |          |                           |           |           |                |
|                                                | HRS                                                                                    | 0         |               |          |                           |           |           |                |
|                                                | AFL                                                                                    | 0         |               |          |                           |           |           |                |
| PROC. REF: AMM 05-50-29PROC. REF: AMM 05-50-29 |                                                                                        |           |               |          |                           |           |           |                |
| H140-001 <sup>S</sup>                          | EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE |           |               |          |                           |           |           | Service ATA:05 |
|                                                | MOS                                                                                    | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS                                                                                    |           |               |          |                           |           |           |                |
|                                                | AFL                                                                                    |           |               |          |                           |           |           |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |                                                                                        |           |               |          |                           |           |           | PKG:87         |
| H242-001 <sup>S</sup>                          | INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE |           |               |          |                           |           |           | Service ATA:05 |
|                                                | MOS                                                                                    | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS                                                                                    | 0         |               |          |                           |           |           |                |
|                                                | AFL                                                                                    | 0         |               |          |                           |           |           |                |
| PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00 |                                                                                        |           |               |          |                           |           |           | PKG:87         |
| H430-001 <sup>S</sup>                          | INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS  |           |               |          |                           |           |           | Service ATA:05 |
|                                                | MOS                                                                                    | 31-Mar-25 | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                | HRS                                                                                    | 987:24    |               |          |                           |           |           |                |
|                                                | AFL                                                                                    | 456       |               |          |                           |           |           |                |
|                                                |                                                                                        |           |               |          |                           |           |           | PKG:84         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                                             | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                    |                                                                                                                  |           |              |          |                           |           |           |                  |
| PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00                             |                                                                                                                  |           |              |          |                           |           |           |                  |
| H700-001 <sup>S</sup>                                                      | EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS |           |              |          |                           |           |           | Service ATA:05   |
|                                                                            | MOS                                                                                                              | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                              | 987:24    |              |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                              | 456       |              |          |                           |           |           |                  |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00                             |                                                                                                                  |           |              |          |                           |           |           | PKG:84           |
| H700-002 <sup>S</sup>                                                      | EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS |           |              |          |                           |           |           | Service ATA:05   |
|                                                                            | MOS                                                                                                              | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                              | 987:24    |              |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                              | 456       |              |          |                           |           |           |                  |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00                             |                                                                                                                  |           |              |          |                           |           |           | PKG:84           |
| H700-003 <sup>S</sup>                                                      | EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING                                            |           |              |          |                           |           |           | Service ATA:05   |
|                                                                            | MOS                                                                                                              | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                              | 987:24    |              |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                              | 456       |              |          |                           |           |           |                  |
| PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00                             |                                                                                                                  |           |              |          |                           |           |           | PKG:84           |
| ATA 21 - AIR CONDITIONING                                                  |                                                                                                                  |           |              |          |                           |           |           |                  |
| 21-01-01                                                                   | RH INSC ILLUM PANEL                                                                                              |           |              |          |                           |           |           | Component ATA:21 |
| PN:441-44279-002                                                           | MOS/MSC                                                                                                          | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:1401                                                                    | HRS                                                                                                              | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                              | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-01-01, AMM 21-01-01PROC. REF: AMM 21-01-01, AMM 21-01-01 |                                                                                                                  |           |              |          |                           |           |           |                  |
| 21-20-03                                                                   | NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY                                                                  |           |              |          |                           |           |           | Component ATA:21 |
| PN:1300250-9                                                               | MOS/MSC                                                                                                          | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:1396                                                                    | HRS                                                                                                              | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                              | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-21-01, AMM 21-21-01PROC. REF: AMM 21-21-01, AMM 21-21-01 |                                                                                                                  |           |              |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                                 |           |                |          |                           |           |           |                  |
| 21-20-03                                                                   | NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY |           |                |          |                           |           |           | Component ATA:21 |
| PN:1300250-9                                                               | MOS/MSC                                         | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:1397                                                                    | HRS                                             | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-21-01, AMM 21-21-01PROC. REF: AMM 21-21-01, AMM 21-21-01 |                                                 |           |                |          |                           |           |           |                  |
| 21-20-05                                                                   | GROUND COOLING FAN                              |           |                |          |                           |           |           | Component ATA:21 |
| PN:1133660-3                                                               | MOS/MSC                                         | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:698                                                                     | HRS                                             | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-23-05, AMM 21-23-05PROC. REF: AMM 21-23-05, AMM 21-23-05 |                                                 |           |                |          |                           |           |           |                  |
| 21-21-02-001 <sup>S</sup>                                                  | OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE   |           |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS                                             | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                             | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-21-02PROC. REF: AMM 21-21-02                             |                                                 |           |                |          |                           |           |           |                  |
| 21-21-02-001 <sup>S</sup>                                                  | OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE   |           |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS                                             | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                             | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-21-02PROC. REF: AMM 21-21-02                             |                                                 |           |                |          |                           |           |           |                  |
| 21-23-01                                                                   | ELECTROMECHANICAL LINEAR ACTUATOR               |           |                |          |                           |           |           | Component ATA:21 |
| PN:100000-77                                                               | MOS/MSC                                         | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:41139                                                                   | HRS                                             | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-23-03, AMM 21-23-03PROC. REF: AMM 21-23-03, AMM 21-23-03 |                                                 |           |                |          |                           |           |           |                  |
| 21-23-03                                                                   | RAM AIR VALVE                                   |           |                |          |                           |           |           | Component ATA:21 |
| PN:505-17170-401                                                           | MOS/MSC                                         | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:0001049408                                                              | HRS                                             | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-23-03, AMM 21-23-03PROC. REF: AMM 21-23-03, AMM 21-23-03 |                                                 |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                             | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|-------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 21 - AIR CONDITIONING                      |              |                                                 |                |          |                           |           |           |                |
| 21-23-03-002                                   | <sup>S</sup> | OPERATIONAL CHECK OF RAM AIR VALVE              |                |          |                           |           |           | Service ATA:21 |
|                                                | MOS          | 23-Apr-20                                       |                |          |                           |           |           |                |
|                                                | HRS          | 0                                               | 6400 (+30/-30) |          |                           |           |           |                |
|                                                | AFL          | 0                                               |                |          |                           |           |           |                |
| PROC. REF: AMM 21-23-03PROC. REF: AMM 21-23-03 |              |                                                 |                |          |                           |           |           | PKG:60         |
| 21-23-03-003                                   | <sup>S</sup> | OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION    |                |          |                           |           |           | Service ATA:21 |
|                                                | MOS          | 19-Mar-24                                       |                |          |                           |           |           |                |
|                                                | HRS          | 781:30                                          | 800 (+30/-30)  |          |                           |           |           |                |
|                                                | AFL          | 364                                             |                |          |                           |           |           |                |
| PROC. REF: AMM 21-23-03PROC. REF: AMM 21-23-03 |              |                                                 |                |          |                           |           |           | PKG:1          |
| 21-23-04-001                                   | <sup>S</sup> | OPERATIONAL CHECK OF RAM AIR CHECK VALVES       |                |          |                           |           |           | Service ATA:21 |
|                                                | MOS          | 23-Apr-20                                       |                |          |                           |           |           |                |
|                                                | HRS          | 0                                               | 6400 (+30/-30) |          |                           |           |           |                |
|                                                | AFL          | 0                                               |                |          |                           |           |           |                |
| PROC. REF: AMM 21-23-04PROC. REF: AMM 21-23-04 |              |                                                 |                |          |                           |           |           | PKG:60         |
| 21-23-05-001                                   | <sup>S</sup> | GENERAL VISUAL INSPECTION OF GROUND COOLING FAN |                |          |                           |           |           | Service ATA:21 |
|                                                | MOS          | 23-Apr-20                                       |                |          |                           |           |           |                |
|                                                | HRS          | 0                                               | 1600 (+30/-30) |          |                           |           |           |                |
|                                                | AFL          | 0                                               |                |          |                           |           |           |                |
| PROC. REF: AMM 21-23-05PROC. REF: AMM 21-23-05 |              |                                                 |                |          |                           |           |           | PKG:10         |
| 21-24-01-001                                   | <sup>S</sup> | OPERATIONAL CHECK OF IFE/CMS COOLING FAN        |                |          |                           |           |           | Service ATA:21 |
|                                                | MOS          | 23-Apr-20                                       |                |          |                           |           |           |                |
|                                                | HRS          | 0                                               | 6400 (+30/-30) |          |                           |           |           |                |
|                                                | AFL          | 0                                               |                |          |                           |           |           |                |
| PROC. REF: AMM 21-24-01PROC. REF: AMM 21-24-01 |              |                                                 |                |          |                           |           |           | PKG:60         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                                | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|--------------------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |         |                                                                    |                |          |                           |           |           |                  |
| 21-31-00-002 <sup>S</sup>                                                  |         | OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE            |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS     | 19-Mar-24                                                          |                |          |                           |           |           |                  |
|                                                                            | HRS     | 781:30                                                             | 800 (+30/-30)  |          |                           |           |           |                  |
|                                                                            | AFL     | 364                                                                |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00                             |         |                                                                    |                |          |                           |           |           | PKG:1            |
| 21-31-00-003 <sup>S</sup>                                                  |         | OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)     |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS     | 19-Mar-24                                                          |                |          |                           |           |           |                  |
|                                                                            | HRS     | 781:30                                                             | 800 (+30/-30)  |          |                           |           |           |                  |
|                                                                            | AFL     | 364                                                                |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00                             |         |                                                                    |                |          |                           |           |           | PKG:1            |
| 21-31-00-004 <sup>S</sup>                                                  |         | OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS     | 23-Apr-20                                                          |                |          |                           |           |           |                  |
|                                                                            | HRS     | 0                                                                  | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL     | 0                                                                  |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00                             |         |                                                                    |                |          |                           |           |           | PKG:50           |
| 21-31-00-005 <sup>S</sup>                                                  |         | OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL                |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS     | 23-Apr-20                                                          |                |          |                           |           |           |                  |
|                                                                            | HRS     | 0                                                                  | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL     | 0                                                                  |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00                             |         |                                                                    |                |          |                           |           |           | PKG:50           |
| 21-31-01                                                                   |         | (ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT                    |                |          |                           |           |           | Component ATA:21 |
| PN:2119286-10                                                              | MOS/MSC | 23-Apr-20                                                          | O/C            | TSN 0    |                           |           |           |                  |
| SN:2119286-01650                                                           | HRS     | 0                                                                  |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                                  |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-31-01, AMM 21-31-01PROC. REF: AMM 21-31-01, AMM 21-31-01 |         |                                                                    |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                                                       |           |                |          |                           |           |               |                  |
| 21-31-01-001                                                               | RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) |           |                |          |                           |           |               | Service ATA:21   |
| PN:2119286-10                                                              | MOS                                                                   | 23-Apr-20 |                |          |                           |           |               |                  |
| SN:2119286-01650                                                           | HRS                                                                   | 0         | 5600 (+30/-30) |          | 6000 (M)                  | 6030      | 4704:36 (+30) |                  |
|                                                                            | AFL                                                                   | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01                             |                                                                       |           |                |          |                           |           |               |                  |
| 21-31-02                                                                   | OUTFLOW VALVE                                                         |           |                |          |                           |           |               | Component ATA:21 |
| PN:103922-1                                                                | MOS/MSC                                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:103922-00576                                                            | HRS                                                                   | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                   | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 21-31-02, AMM 21-31-02PROC. REF: AMM 21-31-02, AMM 21-31-02 |                                                                       |           |                |          |                           |           |               |                  |
| 21-31-02-001                                                               | RESTORATION (REPAIR) OF OUTFLOW VALVE                                 |           |                |          |                           |           |               | Service ATA:21   |
| PN:103922-1                                                                | MOS                                                                   | 23-Apr-20 |                |          |                           |           |               |                  |
| SN:103922-00576                                                            | HRS                                                                   | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                  |
|                                                                            | AFL                                                                   | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02                             |                                                                       |           |                |          |                           |           |               |                  |
| 21-31-03                                                                   | NEGATIVE PRESSURE RELIEF (NPR) VALVE                                  |           |                |          |                           |           |               | Component ATA:21 |
| PN:130664-2                                                                | MOS/MSC                                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:34163-0991                                                              | HRS                                                                   | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                   | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 21-31-03, AMM 21-31-03PROC. REF: AMM 21-31-03, AMM 21-31-03 |                                                                       |           |                |          |                           |           |               |                  |
| 21-31-03-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE                   |           |                |          |                           |           |               | Service ATA:21   |
|                                                                            | MOS                                                                   | 23-Apr-20 |                |          |                           |           |               |                  |
|                                                                            | HRS                                                                   | 0         | 5600 (+30/-30) |          |                           |           |               |                  |
|                                                                            | AFL                                                                   | 0         |                |          |                           |           |               |                  |
|                                                                            |                                                                       |           |                |          |                           |           |               | PKG:50           |
| PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03                             |                                                                       |           |                |          |                           |           |               |                  |
| 21-31-04                                                                   | PRESSURE RELIEF (PRV) VALVE                                           |           |                |          |                           |           |               | Component ATA:21 |
| PN:103918-2                                                                | MOS/MSC                                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:103918-00674                                                            | HRS                                                                   | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                   | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 21-31-04, AMM 21-31-04PROC. REF: AMM 21-31-04, AMM 21-31-04 |                                                                       |           |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                        | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |                                             |           |                |          |                           |           |              |                  |
| 21-31-04-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE   |           |                |          |                           |           |              | Service ATA:21   |
|                                                                            | MOS                                         | 23-Apr-20 |                |          |                           |           |              |                  |
|                                                                            | HRS                                         | 0         | 5600 (+30/-30) |          |                           |           |              |                  |
|                                                                            | AFL                                         | 0         |                |          |                           |           |              |                  |
| PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04                             |                                             |           |                |          |                           |           |              | PKG:50           |
|                                                                            |                                             |           |                |          |                           |           |              |                  |
| 21-41-01                                                                   | BHS SHUT-OFF VALVE                          |           |                |          |                           |           |              | Component ATA:21 |
| PN:PN                                                                      | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                                                                 | HRS                                         | 0         |                | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 21-41-01, AMM 21-41-01PROC. REF: AMM 21-41-01, AMM 21-41-01 |                                             |           |                |          |                           |           |              |                  |
|                                                                            |                                             |           |                |          |                           |           |              |                  |
| 21-52-01                                                                   | VCS COMPRESSOR DRIVE MODULE                 |           |                |          |                           |           |              | Component ATA:21 |
| PN:1133640-10                                                              | MOS/MSC                                     | 30-Aug-24 | O/C            |          |                           |           |              |                  |
| SN:520                                                                     | HRS                                         | 869:12    |                |          |                           |           |              |                  |
|                                                                            | AFL                                         | 406       |                |          |                           |           |              |                  |
| PROC. REF: AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01 |                                             |           |                |          |                           |           |              |                  |
|                                                                            |                                             |           |                |          |                           |           |              |                  |
| 21-52-01-002                                                               | DISCARD OF COMPRESSOR DRIVE MODULE BELT     |           |                |          |                           |           |              | Service ATA:21   |
| PN:PN                                                                      | MOS                                         | 23-Apr-20 |                |          |                           |           |              |                  |
| SN:UNKNOWN                                                                 | HRS                                         | 0         | 2000 (+30/-30) |          | 2000                      | 2030      | 704:36 (+30) |                  |
|                                                                            | AFL                                         | 0         |                |          |                           |           |              |                  |
|                                                                            | CDMHRS                                      |           |                |          |                           |           |              |                  |
| PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01                             |                                             |           |                |          |                           |           |              |                  |
|                                                                            |                                             |           |                |          |                           |           |              |                  |
| 21-52-01-003 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION |           |                |          |                           |           |              | Service ATA:21   |
| PN:PN                                                                      | MOS                                         | 19-Mar-24 |                |          |                           |           |              |                  |
| SN:UNKNOWN                                                                 | HRS                                         | 781:30    | 800 (+30/-30)  |          |                           |           |              |                  |
|                                                                            | AFL                                         | 364       |                |          |                           |           |              |                  |
| PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01                             |                                             |           |                |          |                           |           |              | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                               | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 21 - AIR CONDITIONING                                                                                                          |                                                    |           |                |          |                           |           |               |                  |
| 21-52-01-004                                                                                                                       | RESTORATION (OVERHAUL) OF CDM COMPRESSOR           |           |                |          |                           |           |               | Service ATA:21   |
| PN:1133640-10                                                                                                                      | MOS                                                | 30-Aug-24 |                |          |                           |           |               |                  |
| SN:520                                                                                                                             | HRS                                                | 869:12    | 2000 (+30/-30) |          | 2869:12                   | 2899:12   | 1573:48 (+30) |                  |
|                                                                                                                                    | AFL                                                | 406       |                |          |                           |           |               |                  |
|                                                                                                                                    | CDMHRS                                             |           |                |          |                           |           |               |                  |
| PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01                                                                                     |                                                    |           |                |          |                           |           |               |                  |
| 21-52-02                                                                                                                           | CDM COMPRESSOR MODULE                              |           |                |          |                           |           |               | Component ATA:21 |
| PN:PN-UNKNOWN                                                                                                                      | MOS/MSC                                            | 30-Aug-24 | O/C            |          |                           |           |               |                  |
| SN:00301                                                                                                                           | HRS                                                | 869:12    |                | TSN 0    |                           |           |               |                  |
|                                                                                                                                    | AFL                                                | 406       |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01                                                         |                                                    |           |                |          |                           |           |               |                  |
| 21-52-03                                                                                                                           | SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE       |           |                |          |                           |           |               | Component ATA:21 |
| PN:1133860-4                                                                                                                       | MOS/MSC                                            | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:718                                                                                                                             | HRS                                                | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                                                                                    | AFL                                                | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 21-52-03, AMM 21-52-03PROC. REF: AMM 21-52-03, AMM 21-52-03                                                         |                                                    |           |                |          |                           |           |               |                  |
| 21-52-03-001 <sup>S</sup>                                                                                                          | GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES    |           |                |          |                           |           |               | Service ATA:21   |
|                                                                                                                                    | MOS                                                | 19-Mar-24 |                |          |                           |           |               |                  |
|                                                                                                                                    | HRS                                                | 781:30    | 800 (+30/-30)  |          |                           |           |               |                  |
|                                                                                                                                    | AFL                                                | 364       |                |          |                           |           |               |                  |
| PROC. REF: AMM 21-52-03PROC. REF: AMM 21-52-03                                                                                     |                                                    |           |                |          |                           |           |               |                  |
| 21-52-04                                                                                                                           | FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER |           |                |          |                           |           |               | Component ATA:21 |
| PN:1133850-104                                                                                                                     | MOS/MSC                                            | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:1113                                                                                                                            | HRS                                                | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                                                                                    | AFL                                                | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04 |                                                    |           |                |          |                           |           |               |                  |
| 21-52-05                                                                                                                           | COMPRESSOR DRIVE MODULE BELT                       |           |                |          |                           |           |               | Component ATA:21 |
| PN:PN                                                                                                                              | MOS/MSC                                            | 23-Apr-20 | H/T            | TSN 0    |                           |           |               |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                                                                                    | AFL                                                | 0         |                | TSN 0    |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                        | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|--------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |              |                                            |                |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |              |                                            |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| 21-52-06-001                                                               | <sup>S</sup> | SERVICING OF VCS REFRIGERANT FLUID         |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS          | 13-Mar-26                                  | 12 (+1m/-1m)   |          |                           |           |           |                  |
|                                                                            | HRS          | 1221:24                                    |                |          |                           |           |           |                  |
|                                                                            | AFL          | 564                                        |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| PKG:80                                                                     |              |                                            |                |          |                           |           |           |                  |
| PROC. REF: AMM 12-17-00PROC. REF: AMM 12-17-00                             |              |                                            |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| 21-52-08                                                                   |              | AIR CONDITION CONDENSER ASSEMBLY           |                |          |                           |           |           | Component ATA:21 |
| PN:1133760-2                                                               | MOS/MSC      | 23-Apr-20                                  | O/C            | TSN 0    |                           |           |           |                  |
| SN:694                                                                     | HRS          | 0                                          |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                          |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-52-08, AMM 21-52-08PROC. REF: AMM 21-52-08, AMM 21-52-08 |              |                                            |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| 21-52-08-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF VCS CONDENSER |                |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS          | 23-Apr-20                                  |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                          | 1600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                          |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| PKG:10                                                                     |              |                                            |                |          |                           |           |           |                  |
| PROC. REF: AMM 21-52-08PROC. REF: AMM 21-52-08                             |              |                                            |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| 21-52-09                                                                   |              | AIR CONDITION MIX FLOW CONDENSER FAN       |                |          |                           |           |           | Component ATA:21 |
| PN:1133720-4                                                               | MOS/MSC      | 23-Apr-20                                  | O/C            | TSN 0    |                           |           |           |                  |
| SN:708                                                                     | HRS          | 0                                          |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                          |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-52-09, AMM 21-52-09PROC. REF: AMM 21-52-09, AMM 21-52-09 |              |                                            |                |          |                           |           |           |                  |
|                                                                            |              |                                            |                |          |                           |           |           |                  |
| 21-52-10                                                                   |              | AIR CONDITION BLEED AIR HEAT EXCHANGER     |                |          |                           |           |           | Component ATA:21 |
| PN:1320260-3                                                               | MOS/MSC      | 23-Apr-20                                  | O/C            | TSN 0    |                           |           |           |                  |
| SN:696                                                                     | HRS          | 0                                          |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                          |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-52-10, AMM 21-52-10PROC. REF: AMM 21-52-10, AMM 21-52-10 |              |                                            |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                    | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|--------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING                                                  |         |                                                        |               |          |                           |           |           |                  |
| 21-61-00-001 <sup>S</sup>                                                  |         | OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM |               |          |                           |           |           | Service ATA:21   |
|                                                                            | MOS     | 19-Mar-24                                              |               |          |                           |           |           |                  |
|                                                                            | HRS     | 781:30                                                 | 800 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL     | 364                                                    |               |          |                           |           |           |                  |
| PROC. REF: AMM 21-61-00PROC. REF: AMM 21-61-00                             |         |                                                        |               |          |                           |           |           | PKG:1            |
|                                                                            |         |                                                        |               |          |                           |           |           |                  |
| 21-61-01                                                                   |         | ECS TEMPERATURE CONTROLLER                             |               |          |                           |           |           | Component ATA:21 |
| PN:1300670-8                                                               | MOS/MSC | 19-Apr-24                                              | O/C           | TSR 1    |                           |           |           |                  |
| SN:00635                                                                   | HRS     | 816:14                                                 |               | TSR 0    |                           |           |           |                  |
|                                                                            | AFL     | 378                                                    |               | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 21-61-01, AMM 21-61-01PROC. REF: AMM 21-61-01, AMM 21-61-01 |         |                                                        |               |          |                           |           |           |                  |
|                                                                            |         |                                                        |               |          |                           |           |           |                  |
| 21-61-03                                                                   |         | LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH               |               |          |                           |           |           | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC | 23-Apr-20                                              | O/C           | TSN 0    |                           |           |           |                  |
| SN:4481                                                                    | HRS     | 0                                                      |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                      |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03 |         |                                                        |               |          |                           |           |           |                  |
|                                                                            |         |                                                        |               |          |                           |           |           |                  |
| 21-61-03                                                                   |         | RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH              |               |          |                           |           |           | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC | 23-Apr-20                                              | O/C           | TSN 0    |                           |           |           |                  |
| SN:4474                                                                    | HRS     | 0                                                      |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                      |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03 |         |                                                        |               |          |                           |           |           |                  |
|                                                                            |         |                                                        |               |          |                           |           |           |                  |
| 21-61-04                                                                   |         | COCKPIT DUCT TEMPERATURE SENSOR/SWITCH                 |               |          |                           |           |           | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC | 23-Apr-20                                              | O/C           | TSN 0    |                           |           |           |                  |
| SN:4577                                                                    | HRS     | 0                                                      |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                      |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-61-04, AMM 21-61-04PROC. REF: AMM 21-61-04, AMM 21-61-04 |         |                                                        |               |          |                           |           |           |                  |
|                                                                            |         |                                                        |               |          |                           |           |           |                  |
| 21-61-05                                                                   |         | CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH         |               |          |                           |           |           | Component ATA:21 |
| PN:1300450-10                                                              | MOS/MSC | 23-Apr-20                                              | O/C           | TSN 0    |                           |           |           |                  |
| SN:4420                                                                    | HRS     | 0                                                      |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                      |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 21-61-05, AMM 21-61-05PROC. REF: AMM 21-61-05, AMM 21-61-05 |         |                                                        |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                                                                       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------|----------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 21 - AIR CONDITIONING                      |              |                                                                                                           |                |          |                           |           |             |                |
| 21-61-06-001                                   | <sup>S</sup> | OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR                                                         |                |          |                           |           |             | Service ATA:21 |
|                                                | MOS          | 23-Apr-20                                                                                                 |                |          |                           |           |             |                |
|                                                | HRS          | 0                                                                                                         | 6400 (+30/-30) |          |                           |           |             |                |
|                                                | AFL          | 0                                                                                                         |                |          |                           |           |             |                |
| PROC. REF: AMM 21-61-06PROC. REF: AMM 21-61-06 |              |                                                                                                           |                |          |                           |           |             | PKG:60         |
| ATA 22 - AUTO FLIGHT                           |              |                                                                                                           |                |          |                           |           |             |                |
| 22-11-00-001                                   |              | FUNCTIONAL CHECK AILERON GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO                   |                |          |                           |           |             | Service ATA:22 |
| PN:011-01904-00                                | MOS          | 13-Mar-26                                                                                                 | 12 (+30d/-30d) | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30) | AIRWORTHINESS  |
| SN:1GK024781                                   | HRS          | 1221:24                                                                                                   |                |          |                           |           |             |                |
|                                                | AFL          | 564                                                                                                       |                |          |                           |           |             |                |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00 |              |                                                                                                           |                |          |                           |           |             |                |
| 22-11-00-001                                   |              | FUNCTIONAL CHECK ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO                  |                |          |                           |           |             | Service ATA:22 |
| PN:011-01904-00                                | MOS          | 13-Mar-26                                                                                                 | 12 (+30d/-30d) | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30) | AIRWORTHINESS  |
| SN:1GK027854                                   | HRS          | 1221:24                                                                                                   |                |          |                           |           |             |                |
|                                                | AFL          | 564                                                                                                       |                |          |                           |           |             |                |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00 |              |                                                                                                           |                |          |                           |           |             |                |
| 22-11-00-001                                   |              | FUNCTIONAL CHECK RUDDER GSM 86 AUTOPILOT SERVO MOUNT GSA 81 LOW TORQUE AUTOPILOT SERVO                    |                |          |                           |           |             | Service ATA:22 |
| PN:011-01904-00                                | MOS          | 13-Mar-26                                                                                                 | 12 (+30d/-30d) |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30) | AIRWORTHINESS  |
| SN:1GK027854                                   | HRS          | 1221:24                                                                                                   |                |          |                           |           |             |                |
|                                                | AFL          | 564                                                                                                       |                |          |                           |           |             |                |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00 |              |                                                                                                           |                |          |                           |           |             |                |
| 22-11-00-001                                   |              | FUNCTIONAL CHECK TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT GSA 80 HIGH SPEED AUTOPILOT SERVO |                |          |                           |           |             | Service ATA:22 |
| PN:011-01904-00                                | MOS          | 13-Mar-26                                                                                                 | 12 (+30d/-30d) | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30) | AIRWORTHINESS  |
| SN:1GK028239                                   | HRS          | 1221:24                                                                                                   |                |          |                           |           |             |                |
|                                                | AFL          | 564                                                                                                       |                |          |                           |           |             |                |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00 |              |                                                                                                           |                |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                          | Interval       | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|----------------------------------------------|----------------|-------------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT                                                       |         |                                              |                |             |                           |           |           |                  |
| 22-11-00-002 <sup>S</sup>                                                  |         | LUBRICATION OF SERVO ACTUATORS               |                |             |                           |           |           | Service ATA:22   |
|                                                                            | MOS     | 13-Mar-26                                    | 12 (+1m/-1m)   |             |                           |           |           |                  |
|                                                                            | HRS     | 1221:24                                      |                |             |                           |           |           |                  |
|                                                                            | AFL     | 564                                          |                |             |                           |           |           |                  |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |         |                                              |                |             |                           |           |           | PKG:80           |
| 22-11-00-003 <sup>S</sup>                                                  |         | DETAILED INSPECTION OF AUTOPILOT SERVO CABLE |                |             |                           |           |           | Service ATA:22   |
|                                                                            | MOS     | 31-Mar-25                                    | 60 (+1m/-1m)   |             |                           |           |           |                  |
|                                                                            | HRS     | 987:24                                       | 3200 (+30/-30) |             |                           |           |           |                  |
|                                                                            | AFL     | 456                                          |                |             |                           |           |           |                  |
| PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00                             |         |                                              |                |             |                           |           |           | PKG:42           |
| 22-11-01                                                                   |         | TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO  |                |             |                           |           |           | Component ATA:22 |
| PN:011-00877-21                                                            | MOS/MSC | 04-Mar-26                                    | O/C            | TSN 71      |                           |           |           |                  |
| SN:1A0007670                                                               | HRS     | 1221:24                                      |                | TSN 1221:24 |                           |           |           |                  |
|                                                                            | AFL     | 564                                          |                | TSN 564     |                           |           |           |                  |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |             |                           |           |           |                  |
| 22-11-02                                                                   |         | AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO    |                |             |                           |           |           | Component ATA:22 |
| PN:011-00878-20                                                            | MOS/MSC | 04-Mar-26                                    | O/C            | TSN 71      |                           |           |           |                  |
| SN:1A1022477                                                               | HRS     | 1221:24                                      |                | TSN 1221:24 |                           |           |           |                  |
|                                                                            | AFL     | 564                                          |                | TSN 564     |                           |           |           |                  |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |             |                           |           |           |                  |
| 22-11-02                                                                   |         | ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO   |                |             |                           |           |           | Component ATA:22 |
| PN:011-00878-20                                                            | MOS/MSC | 04-Mar-26                                    | O/C            | TSN 71      |                           |           |           |                  |
| SN:1A1025844                                                               | HRS     | 1221:24                                      |                | TSN 1221:24 |                           |           |           |                  |
|                                                                            | AFL     | 564                                          |                | TSN 564     |                           |           |           |                  |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |             |                           |           |           |                  |
| 22-11-02                                                                   |         | RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO     |                |             |                           |           |           | Component ATA:22 |
| PN:011-00878-20                                                            | MOS/MSC | 04-Mar-26                                    | O/C            | TSN 71      |                           |           |           |                  |
| SN:1A1025867                                                               | HRS     | 1221:24                                      |                | TSN 1221:24 |                           |           |           |                  |
|                                                                            | AFL     | 564                                          |                | TSN 564     |                           |           |           |                  |
| PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02 |         |                                              |                |             |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT                                                       |                                                        |           |          |          |                           |           |           |                  |
| 22-11-03                                                                   | AILERON GSM 86 AUTOPILOT SERVO MOUNT                   |           |          |          |                           |           |           | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1GK024781                                                               | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03 |                                                        |           |          |          |                           |           |           |                  |
| 22-11-03-001 <sup>S</sup>                                                  | DISCARD OF AILERON CLUTCH RETAINING BOLT AND WASHER    |           |          |          |                           |           |           | Service ATA:22   |
|                                                                            | MOS/MSC                                                | 23-Apr-20 | N/A      |          |                           |           |           |                  |
|                                                                            | HRS                                                    | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-03PROC. REF: AMM 22-11-03                             |                                                        |           |          |          |                           |           |           | PKG:82           |
| 22-11-04                                                                   | GMC 725 GUIDANCE PANEL                                 |           |          |          |                           |           |           | Component ATA:22 |
| PN:011-04214-00                                                            | MOS/MSC                                                | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:4WC000425                                                               | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 22-11-01, AMM 22-11-01PROC. REF: AMM 22-11-01, AMM 22-11-01 |                                                        |           |          |          |                           |           |           |                  |
| 22-11-06                                                                   | ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT                  |           |          |          |                           |           |           | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1GK027854                                                               | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06 |                                                        |           |          |          |                           |           |           |                  |
| 22-11-09                                                                   | RUDDER GSM 86 AUTOPILOT SERVO MOUNT                    |           |          |          |                           |           |           | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 13-Mar-26 | O/C      |          |                           |           |           |                  |
| SN:1GK027854                                                               | HRS                                                    | 1221:24   |          |          |                           |           |           |                  |
|                                                                            | AFL                                                    | 564       |          |          |                           |           |           |                  |
| PROC. REF: AMM 22-11-09, AMM 22-11-09PROC. REF: AMM 22-11-09, AMM 22-11-09 |                                                        |           |          |          |                           |           |           |                  |
| 22-11-12                                                                   | TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT |           |          |          |                           |           |           | Component ATA:22 |
| PN:011-01904-00                                                            | MOS/MSC                                                | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1GK028239                                                               | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 22 - AUTO FLIGHT                                                       |                                                       |           |          |          |                           |           |           |             |
| PROC. REF: AMM 22-11-12, AMM 22-11-12PROC. REF: AMM 22-11-12, AMM 22-11-12 |                                                       |           |          |          |                           |           |           |             |
| ATA 23 - COMMUNICATIONS                                                    |                                                       |           |          |          |                           |           |           |             |
| 23-11-02                                                                   | REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER |           |          |          |                           |           | Component | ATA:23      |
| PN:064-01073-0102                                                          | MOS/MSC                                               | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |             |
| SN:KRX1053-9770                                                            | HRS                                                   | 0         |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL                                                   | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 23-11-02, AMM 23-11-02PROC. REF: AMM 23-11-02, AMM 23-11-02 |                                                       |           |          |          |                           |           |           |             |
| 23-11-03                                                                   | KPA 1052 POWER AMPLIFIER                              |           |          |          |                           |           | Component | ATA:23      |
| PN:064-01072-0101                                                          | MOS/MSC                                               | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |             |
| SN:KPA1052-9103                                                            | HRS                                                   | 0         |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL                                                   | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 23-11-03, AMM 23-11-03PROC. REF: AMM 23-11-03, AMM 23-11-03 |                                                       |           |          |          |                           |           |           |             |
| 23-11-04                                                                   | HF ANTENNA COUPLER                                    |           |          |          |                           |           | Component | ATA:23      |
| PN:064-01074-0101                                                          | MOS/MSC                                               | 13-Mar-26 | O/C      |          |                           |           |           |             |
| SN:KAC1052-11557                                                           | HRS                                                   | 1221:24   |          |          |                           |           |           |             |
|                                                                            | AFL                                                   | 564       |          |          |                           |           |           |             |
| PROC. REF: AMM 23-11-04, AMM 23-11-04PROC. REF: AMM 23-11-04, AMM 23-11-04 |                                                       |           |          |          |                           |           |           |             |
| 23-12-01                                                                   | VHF 1 (UPPER FUSELAGE) ANTENNA                        |           |          |          |                           |           | Component | ATA:23      |
| PN:S65-8280-41                                                             | MOS/MSC                                               | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |             |
| SN:322-6577                                                                | HRS                                                   | 0         |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL                                                   | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 23-12-02, AMM 23-12-02PROC. REF: AMM 23-12-02, AMM 23-12-02 |                                                       |           |          |          |                           |           |           |             |
| 23-12-03                                                                   | VHF 3 (LOWER AFT FUSELAGE) ANTENNA                    |           |          |          |                           |           | Component | ATA:23      |
| PN:S65-8280-41                                                             | MOS/MSC                                               | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |             |
| SN:322-6581                                                                | HRS                                                   | 0         |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL                                                   | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 23-12-02, AMM 23-12-02PROC. REF: AMM 23-12-02, AMM 23-12-02 |                                                       |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                      | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS                                                    |                                                           |           |                |          |                           |           |           |                  |
| 23-34-01                                                                   | WLAN ACCESS POINT - WAP                                   |           |                |          |                           |           |           | Component ATA:23 |
| PN:WAP3212-005-002                                                         | MOS/MSC                                                   | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:000099                                                                  | HRS                                                       | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |           |                |          |                           |           |           |                  |
| 23-50-03                                                                   | LH CONSOLE COCKPIT HAND MICROPHONE                        |           |                |          |                           |           |           | Component ATA:23 |
| PN:85-03-12369-04                                                          | MOS/MSC                                                   | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:542128                                                                  | HRS                                                       | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                           |           |                |          |                           |           |           |                  |
| 23-51-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE |           |                |          |                           |           |           | Service ATA:23   |
|                                                                            | MOS                                                       | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                       | 0         | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                       | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 23-51-00PROC. REF: AMM 23-51-00                             |                                                           |           |                |          |                           |           |           |                  |
| 23-51-05                                                                   | LEFT CONTROL PANEL                                        |           |                |          |                           |           |           | Component ATA:23 |
| PN:441-40943-002                                                           | MOS/MSC                                                   | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:2009                                                                    | HRS                                                       | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05 |                                                           |           |                |          |                           |           |           |                  |
| 23-51-05                                                                   | RIGHT CONTROL PANEL                                       |           |                |          |                           |           |           | Component ATA:23 |
| PN:441-40943-002                                                           | MOS/MSC                                                   | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:2008                                                                    | HRS                                                       | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                       | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05 |                                                           |           |                |          |                           |           |           |                  |
| 23-61-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF STATIC DISCHARGERS                    |           |                |          |                           |           |           | Service ATA:23   |
|                                                                            | MOS                                                       | 19-Mar-24 | 48 (+1m/-1m)   |          |                           |           |           |                  |
|                                                                            | HRS                                                       | 781:30    |                |          |                           |           |           |                  |
|                                                                            | AFL                                                       | 364       |                |          |                           |           |           |                  |
| PROC. REF: AMM 23-61-00PROC. REF: AMM 23-61-00                             |                                                           |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                           | C/W       | Interval | TSX/Adj.      | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------|-----------|----------|---------------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS                                                    |                                |           |          |               |                           |           |           |                  |
| ATA 24 - ELECTRICAL POWER                                                  |                                |           |          |               |                           |           |           |                  |
| 24-01-01                                                                   | LEFT CONSOLE CONTROL PANEL     |           |          |               |                           |           |           | Component ATA:24 |
| PN:441-40929-002                                                           | MOS/MSC                        | 23-Apr-20 | O/C      | TSN 0         |                           |           |           |                  |
| SN:1016                                                                    | HRS                            | 0         |          | TSN 0         |                           |           |           |                  |
|                                                                            | AFL                            | 0         |          | TSN 0         |                           |           |           |                  |
| PROC. REF: AMM 24-01-01, AMM 24-01-01PROC. REF: AMM 24-01-01, AMM 24-01-01 |                                |           |          |               |                           |           |           |                  |
| 24-01-02                                                                   | 4.3 PASSENGER CONTROL UNIT     |           |          |               |                           |           |           | Component ATA:24 |
| PN:PSM2410-004-001                                                         | MOS/MSC                        | 23-Apr-20 | O/C      | TSN 0         |                           |           |           |                  |
| SN:000945                                                                  | HRS                            | 0         |          | TSN 0         |                           |           |           |                  |
|                                                                            | AFL                            | 0         |          | TSN 0         |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                |           |          |               |                           |           |           |                  |
| 24-01-03                                                                   | PCU CORE MODULE TWO            |           |          |               |                           |           |           | Component ATA:24 |
| PN:PCS3009-201-001                                                         | MOS/MSC                        | 23-Apr-20 | O/C      | TSN 0         |                           |           |           |                  |
| SN:500744                                                                  | HRS                            | 0         |          | TSN 0         |                           |           |           |                  |
|                                                                            | AFL                            | 0         |          | TSN 0         |                           |           |           |                  |
| PROC. REF: AMM 44-23-03, AMM 44-23-03PROC. REF: AMM 44-23-03, AMM 44-23-03 |                                |           |          |               |                           |           |           |                  |
| 24-31-01                                                                   | NO. 1 ENGINE STARTER/GENERATOR |           |          |               |                           |           |           | Component ATA:24 |
| PN:400SG180Q-6                                                             | MOS/MSC                        | 12-Dec-25 | O/C      | TSO 0         |                           |           |           |                  |
| SN:S00641XL                                                                | HRS                            | 1179:24   |          | TSO 0         |                           |           |           |                  |
|                                                                            | AFL                            | 546       |          | TSO 0         |                           |           |           |                  |
| PROC. REF: AMM 24-31-01, AMM 24-31-01PROC. REF: AMM 24-31-01, AMM 24-31-01 |                                |           |          |               |                           |           |           |                  |
| 24-31-01                                                                   | NO. 2 ENGINE STARTER/GENERATOR |           |          |               |                           |           |           | Component ATA:24 |
| PN:400SG180Q-6                                                             | MOS/MSC                        | 13-Mar-26 | O/C      | TSN 42, TSO 0 |                           |           |           |                  |
| SN:S04182                                                                  | HRS                            | 1221:24   |          | TSO 0         |                           |           |           |                  |
|                                                                            | AFL                            | 564       |          | TSO 0         |                           |           |           |                  |
| PROC. REF: AMM 24-31-01, AMM 24-31-01PROC. REF: AMM 24-31-01, AMM 24-31-01 |                                |           |          |               |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                                                                                                                  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER                                                  |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |
| 24-31-01-001                                                               | NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 |           |               |          |                           |           |           | Service ATA:24   |
| PN:400SG180Q-6                                                             | MOS                                                                                                                                                                                   | 12-Dec-25 |               |          |                           |           |           |                  |
| SN:S00641XL                                                                | HRS                                                                                                                                                                                   | 1179:24   | 800 (+30/-30) |          | 1979:24                   | 2009:24   | 684 (+30) |                  |
|                                                                            | AFL                                                                                                                                                                                   | 546       |               |          |                           |           |           |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |
| 24-31-01-001                                                               | NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017 |           |               |          |                           |           |           | Service ATA:24   |
| PN:400SG180Q-6                                                             | MOS                                                                                                                                                                                   | 13-Mar-26 |               |          |                           |           |           |                  |
| SN:S04182                                                                  | HRS                                                                                                                                                                                   | 1221:24   | 800 (+30/-30) |          | 2021:24                   | 2051:24   | 726 (+30) |                  |
|                                                                            | AFL                                                                                                                                                                                   | 564       |               |          |                           |           |           |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |
| 24-31-01-003                                                               | RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)                                                                           |           |               |          |                           |           |           | Service ATA:24   |
| PN:400SG180Q-6                                                             | MOS/MSC                                                                                                                                                                               |           | N/A           |          |                           |           |           |                  |
| SN:S00641XL                                                                | HRS                                                                                                                                                                                   |           |               |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                                                                                                   |           |               |          |                           |           |           |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |
| 24-31-01-003                                                               | RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)                                                                           |           |               |          |                           |           |           | Service ATA:24   |
| PN:400SG180Q-6                                                             | MOS/MSC                                                                                                                                                                               |           | N/A           |          |                           |           |           |                  |
| SN:S04182                                                                  | HRS                                                                                                                                                                                   |           |               |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                                                                                                   |           |               |          |                           |           |           |                  |
| PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01                             |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |
| 24-31-02                                                                   | LEFT 28V DC GENERATOR CONTROL UNIT                                                                                                                                                    |           |               |          |                           |           |           | Component ATA:24 |
| PN:GCSG550-12B                                                             | MOS/MSC                                                                                                                                                                               | 27-Jun-25 | O/C           |          |                           |           |           |                  |
| SN:61797                                                                   | HRS                                                                                                                                                                                   | 1046      |               |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                                                                                                   | 485       |               |          |                           |           |           |                  |
| PROC. REF: AMM 24-31-02, AMM 24-31-02PROC. REF: AMM 24-31-02, AMM 24-31-02 |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |
| 24-31-02                                                                   | RIGHT 28V DC GENERATOR CONTROL UNIT                                                                                                                                                   |           |               |          |                           |           |           | Component ATA:24 |
| PN:GCSG550-12B                                                             | MOS/MSC                                                                                                                                                                               | 27-Jun-25 | O/C           |          |                           |           |           |                  |
| SN:61970                                                                   | HRS                                                                                                                                                                                   | 1046      |               |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                                                                                                   | 485       |               |          |                           |           |           |                  |
| PROC. REF: AMM 24-31-02, AMM 24-31-02PROC. REF: AMM 24-31-02, AMM 24-31-02 |                                                                                                                                                                                       |           |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                          | Interval      | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|--------------|----------------------------------------------|---------------|-----------|---------------------------|-----------|-------------|------------------|
| ATA 24 - ELECTRICAL POWER                                                  |              |                                              |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| 24-31-07-001                                                               | <sup>S</sup> | RESTORATION (CLEANING) OF LH SHUNT GENERATOR |               |           |                           |           |             | Service ATA:24   |
|                                                                            | MOS          | 31-Mar-25                                    | 60 (+1m/-1m)  |           |                           |           |             |                  |
|                                                                            | HRS          | 987:24                                       |               |           |                           |           |             |                  |
|                                                                            | AFL          | 456                                          |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| PROC. REF: AMM 24-31-07PROC. REF: AMM 24-31-07                             |              |                                              |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| 24-31-07-001                                                               | <sup>S</sup> | RESTORATION (CLEANING) OF RH SHUNT GENERATOR |               |           |                           |           |             | Service ATA:24   |
|                                                                            | MOS          | 31-Mar-25                                    | 60 (+1m/-1m)  |           |                           |           |             |                  |
|                                                                            | HRS          | 987:24                                       |               |           |                           |           |             |                  |
|                                                                            | AFL          | 456                                          |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| PROC. REF: AMM 24-31-07PROC. REF: AMM 24-31-07                             |              |                                              |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| 24-36-01                                                                   |              | AFT MAIN BATTERY                             |               |           |                           |           |             | Component ATA:24 |
| PN:7638-48P                                                                | MOS/MSC      | 13-Mar-26                                    | H/T           |           |                           |           |             |                  |
| SN:G03307963                                                               | HRS          | 1221:24                                      |               |           |                           |           |             |                  |
|                                                                            | AFL          | 564                                          |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| PROC. REF: AMM 24-36-01, AMM 24-36-01PROC. REF: AMM 24-36-01, AMM 24-36-01 |              |                                              |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| 24-36-01                                                                   |              | FORWARD MAIN BATTERY                         |               |           |                           |           |             | Component ATA:24 |
| PN:7639-34                                                                 | MOS/MSC      | 13-Mar-26                                    | H/T           | TSN 7     |                           |           |             |                  |
| SN:G03309959                                                               | HRS          | 1221:24                                      |               | TSN 79:12 |                           |           |             |                  |
|                                                                            | AFL          | 564                                          |               | TSN 35    |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| PROC. REF: AMM 24-36-01, AMM 24-36-01PROC. REF: AMM 24-36-01, AMM 24-36-01 |              |                                              |               |           |                           |           |             |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| 24-36-01-003                                                               |              | DISCARD AFT MAIN BATTERY                     |               |           |                           |           |             | Service ATA:24   |
| PN:7638-48P                                                                | MOS          | 17-Oct-25                                    | 24 (+1m/-1m)  |           | 23-Jun-27 (M)             | 23-Jul-27 | 329 d (+30) | LIFE LIMIT       |
| SN:G03307963                                                               | HRS          | 1142:12                                      |               |           |                           |           |             |                  |
|                                                                            | AFL          | 529                                          | 600 (+30/-30) |           | 1129                      | 1159      | 531 (+30)   |                  |
|                                                                            |              |                                              |               |           |                           |           |             |                  |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01                             |              |                                              |               |           |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                              | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|------------------------------------------------|-------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 24 - ELECTRICAL POWER                      |                                                                   |           |                |          |                           |           |             |                |
| 24-36-01-003                                   | DISCARD FORWARD MAIN BATTERY                                      |           |                |          |                           |           |             | Service ATA:24 |
| PN:7639-34                                     | MOS                                                               | 17-Oct-25 | 24 (+1m/-1m)   |          | 17-Oct-27                 | 17-Nov-27 | 445 d (+31) | LIFE LIMIT     |
| SN:G03309959                                   | HRS                                                               | 1142:12   |                |          |                           |           |             |                |
|                                                | AFL                                                               | 529       | 600 (+30/-30)  |          | 1129                      | 1159      | 531 (+30)   |                |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01 |                                                                   |           |                |          |                           |           |             |                |
| 24-36-01-004                                   | FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015)      |           |                |          |                           |           |             | Service ATA:24 |
| PN:7638-48P                                    | MOS/MSC                                                           |           | N/A            |          |                           |           |             |                |
| SN:G03307963                                   | HRS                                                               |           |                |          |                           |           |             |                |
|                                                | AFL                                                               |           |                |          |                           |           |             |                |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01 |                                                                   |           |                |          |                           |           |             |                |
| 24-36-01-004                                   | FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015)  |           |                |          |                           |           |             | Service ATA:24 |
| PN:7639-34                                     | MOS/MSC                                                           |           | N/A            |          |                           |           |             |                |
| SN:G03309959                                   | HRS                                                               |           |                |          |                           |           |             |                |
|                                                | AFL                                                               |           |                |          |                           |           |             |                |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01 |                                                                   |           |                |          |                           |           |             |                |
| 24-36-01-005                                   | FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)     |           |                |          |                           |           |             | Service ATA:24 |
| PN:7638-48P                                    | MOS                                                               | 13-Mar-26 | 6 (+1m/-1m)    |          | 13-Sep-26                 | 13-Oct-26 | 46 d (+30)  |                |
| SN:G03307963                                   | HRS                                                               | 1221:24   |                |          |                           |           |             |                |
|                                                | AFL                                                               | 564       |                |          |                           |           |             |                |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01 |                                                                   |           |                |          |                           |           |             |                |
| 24-36-01-005                                   | FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015) |           |                |          |                           |           |             | Service ATA:24 |
| PN:7639-34                                     | MOS                                                               | 13-Mar-26 | 6 (+1m/-1m)    |          | 13-Sep-26                 | 13-Oct-26 | 46 d (+30)  |                |
| SN:G03309959                                   | HRS                                                               | 1221:24   |                |          |                           |           |             |                |
|                                                | AFL                                                               | 564       |                |          |                           |           |             |                |
| PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01 |                                                                   |           |                |          |                           |           |             |                |
| 24-36-02-001 <sup>S</sup>                      | OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)                 |           |                |          |                           |           |             | Service ATA:24 |
|                                                | MOS                                                               | 23-Apr-20 |                |          |                           |           |             |                |
|                                                | HRS                                                               | 0         | 6400 (+30/-30) |          |                           |           |             |                |
|                                                | AFL                                                               | 0         |                |          |                           |           |             |                |
| PROC. REF: AMM 24-36-02PROC. REF: AMM 24-36-02 |                                                                   |           |                |          |                           |           |             |                |

PKG:60

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                      | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|----------------------------------------------------------------------------|---------|------------------------------------------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 24 - ELECTRICAL POWER                                                  |         |                                          |          |          |                           |           |           |             |
| 24-50-01                                                                   |         | PAX CAB DC/AC POWER SUPPLY 28VD INVERTER |          |          |                           |           | Component | ATA:24      |
| PN:1215-30                                                                 | MOS/MSC | 23-Apr-20                                | O/C      | TSN 0    |                           |           |           |             |
| SN:003200                                                                  | HRS     | 0                                        |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL     | 0                                        |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 24-54-05, AMM 24-54-05PROC. REF: AMM 24-54-05, AMM 24-54-05 |         |                                          |          |          |                           |           |           |             |
| 24-50-02                                                                   |         | PAX CAB DC/AC POWER SUPPLY 28VD INVERTER |          |          |                           |           | Component | ATA:24      |
| PN:1215-30                                                                 | MOS/MSC | 23-Apr-20                                | O/C      | TSN 0    |                           |           |           |             |
| SN:003399                                                                  | HRS     | 0                                        |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL     | 0                                        |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 24-54-05, AMM 24-54-05PROC. REF: AMM 24-54-05, AMM 24-54-05 |         |                                          |          |          |                           |           |           |             |
| 24-50-03                                                                   |         | PAX CAB DC/AC POWER SUPPLY 28VD INVERTER |          |          |                           |           | Component | ATA:24      |
| PN:1215-30                                                                 | MOS/MSC | 23-Apr-20                                | O/C      | TSN 0    |                           |           |           |             |
| SN:003398                                                                  | HRS     | 0                                        |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL     | 0                                        |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 24-54-05, AMM 24-54-05PROC. REF: AMM 24-54-05, AMM 24-54-05 |         |                                          |          |          |                           |           |           |             |
| 24-65-01                                                                   |         | LEFT POWER DISTRIBUTION BOX              |          |          |                           |           | Component | ATA:24      |
| PN: SX7EG20-3                                                              | MOS/MSC | 23-Apr-20                                | O/C      | TSN 0    |                           |           |           |             |
| SN:0610                                                                    | HRS     | 0                                        |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL     | 0                                        |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 24-65-01, AMM 24-65-01PROC. REF: AMM 24-65-01, AMM 24-65-01 |         |                                          |          |          |                           |           |           |             |
| 24-65-02                                                                   |         | RIGHT POWER DISTRIBUTION BOX             |          |          |                           |           | Component | ATA:24      |
| PN: SX7EG21-3                                                              | MOS/MSC | 23-Apr-20                                | O/C      | TSN 0    |                           |           |           |             |
| SN:0595                                                                    | HRS     | 0                                        |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL     | 0                                        |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 24-65-02, AMM 24-65-02PROC. REF: AMM 24-65-02, AMM 24-65-02 |         |                                          |          |          |                           |           |           |             |
| 24-65-04                                                                   |         | NOSE POWER DISTRIBUTION BOX              |          |          |                           |           | Component | ATA:24      |
| PN: SX7EG22-3                                                              | MOS/MSC | 23-Apr-20                                | O/C      | TSN 0    |                           |           |           |             |
| SN:0603                                                                    | HRS     | 0                                        |          | TSN 0    |                           |           |           |             |
|                                                                            | AFL     | 0                                        |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 24-65-04, AMM 24-65-04PROC. REF: AMM 24-65-04, AMM 24-65-04 |         |                                          |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                             | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                  |           |                |          |                           |           |           |                  |
| 25-11-01                                                                   | COPILOT SEAT                                     |           |                |          |                           |           |           | Component ATA:25 |
| PN:1419-04HM                                                               | MOS/MSC                                          | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:1469-1419                                                               | HRS                                              | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-11-01, AMM 25-11-01PROC. REF: AMM 25-11-01, AMM 25-11-01 |                                                  |           |                |          |                           |           |           |                  |
| 25-11-01                                                                   | PILOT SEAT                                       |           |                |          |                           |           |           | Component ATA:25 |
| PN:1419-03HM                                                               | MOS/MSC                                          | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:1468-1419                                                               | HRS                                              | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-11-01, AMM 25-11-01PROC. REF: AMM 25-11-01, AMM 25-11-01 |                                                  |           |                |          |                           |           |           |                  |
| 25-11-01-001 <sup>S</sup>                                                  | DETAILED INSPECTION COPILOT SEAT                 |           |                |          |                           |           |           | Service ATA:25   |
|                                                                            | MOS                                              | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                              | 0         | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01                             |                                                  |           |                |          |                           |           |           |                  |
| 25-11-01-001 <sup>S</sup>                                                  | DETAILED INSPECTION PILOT SEAT                   |           |                |          |                           |           |           | Service ATA:25   |
|                                                                            | MOS                                              | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                              | 0         | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01                             |                                                  |           |                |          |                           |           |           |                  |
| 25-11-01-002 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION OF COCKPIT SEAT BELTS |           |                |          |                           |           |           | Service ATA:25   |
|                                                                            | MOS                                              | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                              | 0         | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01                             |                                                  |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                         | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|---------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |              |                                             |                |          |                           |           |           |                  |
| 25-21-01-001                                                               | <sup>S</sup> | DETAILED INSPECTION OF PASSENGER SEATS      |                |          |                           |           |           | Service ATA:25   |
|                                                                            | MOS          | 23-Apr-20                                   |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                           | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                           |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01                             |              |                                             |                |          |                           |           |           | PKG:20           |
| 25-21-01-002                                                               | <sup>S</sup> | DETAILED INSPECTION OF PASSENGER SEAT BELTS |                |          |                           |           |           | Service ATA:25   |
|                                                                            | MOS          | 23-Apr-20                                   |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                           | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                           |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01                             |              |                                             |                |          |                           |           |           | PKG:20           |
| 25-21-02                                                                   |              | DIVAN                                       |                |          |                           |           |           | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC      | 23-Apr-20                                   | O/C            | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                           |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                           |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-21-02, AMM 25-21-02PROC. REF: AMM 25-21-02, AMM 25-21-02 |              |                                             |                |          |                           |           |           |                  |
| 25-21-02-001                                                               | <sup>S</sup> | DETAILED INSPECTION OF DIVAN                |                |          |                           |           |           | Service ATA:25   |
| PN:PN                                                                      | MOS          | 23-Apr-20                                   |                |          |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                           | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                           |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-21-02PROC. REF: AMM 25-21-02                             |              |                                             |                |          |                           |           |           | PKG:40           |
| 25-21-02-002                                                               | <sup>S</sup> | DETAILED INSPECTION OF DIVAN SEAT BELTS     |                |          |                           |           |           | Service ATA:25   |
| PN:PN                                                                      | MOS          | 23-Apr-20                                   |                |          |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS          | 0                                           | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                           |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-21-02PROC. REF: AMM 25-21-02                             |              |                                             |                |          |                           |           |           | PKG:40           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                      | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                                           |           |              |          |                           |           |             |                  |
| 25-21-04                                                                   | (DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY                               |           |              |          |                           |           |             | Component ATA:25 |
| PN:508358-415                                                              | MOS/MSC                                                                   | 13-Mar-26 | O/C          | TSN 3    |                           |           |             |                  |
| SN:A04DEC25-17                                                             | HRS                                                                       | 1221:24   |              | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                                       | 564       |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 25-21-04, AMM 25-21-04PROC. REF: AMM 25-21-04, AMM 25-21-04 |                                                                           |           |              |          |                           |           |             |                  |
| 25-21-04-001                                                               | RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) |           |              |          |                           |           |             | Service ATA:25   |
| PN:508358-415                                                              | MOS                                                                       | 13-Mar-26 | 84           |          | 01-Dec-32                 |           | 2317 d      |                  |
| SN:A04DEC25-17                                                             | HRS                                                                       | 1221:24   |              |          |                           |           |             |                  |
|                                                                            | AFL                                                                       | 564       |              |          |                           |           |             |                  |
| OverHaul Date:: 01-Dec-25                                                  |                                                                           |           |              |          |                           |           |             |                  |
| PROC. REF: AMM 25-21-04, AMM 25-21-04PROC. REF: AMM 25-21-04, AMM 25-21-04 |                                                                           |           |              |          |                           |           |             |                  |
| 25-21-04-002                                                               | DISCARD OF SEAT BELT AIRBAG INFLATOR GAS CYLINDER                         |           |              |          |                           |           |             | Service ATA:25   |
| PN:PN                                                                      | MOS                                                                       | 01-Jul-19 | 120          |          | 01-Jul-29                 |           | 1068 d      | LIFE LIMIT       |
| SN:UNKNOWN                                                                 | HRS                                                                       |           |              |          |                           |           |             |                  |
|                                                                            | AFL                                                                       |           |              |          |                           |           |             |                  |
| Manufacture Date:: 01-Jul-19                                               |                                                                           |           |              |          |                           |           |             |                  |
| PROC. REF: AMM 25-21-04PROC. REF: AMM 25-21-04                             |                                                                           |           |              |          |                           |           |             |                  |
| 25-21-04-003                                                               | DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG ASSEMBLY                   |           |              |          |                           |           |             | Service ATA:25   |
|                                                                            | MOS                                                                       | 19-Mar-24 | 48 (+1m/-1m) |          | 19-Mar-28                 | 19-Apr-28 | 599 d (+31) |                  |
|                                                                            | HRS                                                                       | 781:30    |              |          |                           |           |             |                  |
|                                                                            | AFL                                                                       | 364       |              |          |                           |           |             |                  |
| PROC. REF: AMM 25-21-04PROC. REF: AMM 25-21-04                             |                                                                           |           |              |          |                           |           |             |                  |
| 25-21-04-004                                                               | OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY                            |           |              |          |                           |           |             | Service ATA:25   |
|                                                                            | MOS                                                                       | 19-Mar-24 | 48 (+1m/-1m) |          | 19-Mar-28                 | 19-Apr-28 | 599 d (+31) |                  |
|                                                                            | HRS                                                                       | 781:30    |              |          |                           |           |             |                  |
|                                                                            | AFL                                                                       | 364       |              |          |                           |           |             |                  |
| PROC. REF: AMM 25-21-04PROC. REF: AMM 25-21-04                             |                                                                           |           |              |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval       | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------------|------------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                       |           |                |            |                           |           |           |                  |
| 25-21-05 <sup>U</sup>                                                      | LH FWD PAX SEAT GOLD LUGANO CARBON THIGH DRAWER       |           |                |            |                           |           |           | Component ATA:25 |
| PN:71203-11-107-<br>ADBDSRQAIA                                             | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0      |                           |           |           |                  |
| SN:10392                                                                   | HRS                                                   | 0         |                | TSN 0      |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0      |                           |           |           |                  |
|                                                                            |                                                       |           |                |            |                           |           |           |                  |
| 25-21-05 <sup>U</sup>                                                      | RH FWD PAX SEAT GOLD LUGANO CARBON THIGH DRAWER       |           |                |            |                           |           |           | Component ATA:25 |
| PN:71204-12-207-<br>ADBDSRQAIA                                             | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0      |                           |           |           |                  |
| SN:10212                                                                   | HRS                                                   | 0         |                | TSN 0      |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0      |                           |           |           |                  |
|                                                                            |                                                       |           |                |            |                           |           |           |                  |
| 25-43-01-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION OF BELTED TOILET UNIT      |           |                |            |                           |           |           | Service ATA:25   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |            |                           |           |           |                  |
|                                                                            | HRS                                                   | 0         | 3200 (+30/-30) |            |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                |            |                           |           |           |                  |
| PROC. REF: AMM 25-43-02PROC. REF: AMM 25-43-02                             |                                                       |           |                |            |                           |           |           | PKG:40           |
|                                                                            |                                                       |           |                |            |                           |           |           |                  |
| 25-43-01-002 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION OF BELTED TOILET SEAT BELT |           |                |            |                           |           |           | Service ATA:25   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |            |                           |           |           |                  |
|                                                                            | HRS                                                   | 0         | 3200 (+30/-30) |            |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                |            |                           |           |           |                  |
| PROC. REF: AMM 25-43-02PROC. REF: AMM 25-43-02                             |                                                       |           |                |            |                           |           |           | PKG:40           |
|                                                                            |                                                       |           |                |            |                           |           |           |                  |
| 25-60-01                                                                   | EMERGENCY LOCATOR TRANSMITTER                         |           |                |            |                           |           |           | Component ATA:25 |
| PN:S1821502-02                                                             | MOS/MSC                                               | 31-Mar-25 | O/C            | TSN 59     |                           |           |           |                  |
| SN:LX1100843446                                                            | HRS                                                   | 987:24    |                | TSN 987:24 |                           |           |           |                  |
|                                                                            | AFL                                                   | 456       |                | TSN 456    |                           |           |           |                  |
| PROC. REF: AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01 |                                                       |           |                |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                        | Interval | TSX/Adj.                 | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|----------------------------------------------------------------------------|---------|------------------------------------------------------------|----------|--------------------------|---------------------------|-----------|-----------|-------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |         |                                                            |          |                          |                           |           |           |             |
| 25-60-03                                                                   |         | ELT ANTENNA                                                |          |                          |                           |           | Component | ATA:25      |
| PN:S65-8282-406                                                            | MOS/MSC | 23-Apr-20                                                  | O/C      | TSN 0                    |                           |           |           |             |
| SN:401-3899                                                                | HRS     | 0                                                          |          | TSN 0                    |                           |           |           |             |
|                                                                            | AFL     | 0                                                          |          | TSN 0                    |                           |           |           |             |
| PROC. REF: AMM 25-61-03, AMM 25-61-03PROC. REF: AMM 25-61-03, AMM 25-61-03 |         |                                                            |          |                          |                           |           |           |             |
| 25-60-11                                                                   |         | EMERGENCY LOCATOR TRANSMITTER BATTERY                      |          |                          |                           |           | Component | ATA:25      |
| PN:S1820506-01                                                             | MOS/MSC | 13-Mar-26                                                  | H/T      | TSN 6                    |                           |           |           |             |
| SN:2513 0337                                                               | HRS     | 1221:24                                                    |          | TSN 0                    |                           |           |           |             |
|                                                                            | AFL     | 564                                                        |          | TSN 0                    |                           |           |           |             |
| PROC. REF: AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01 |         |                                                            |          |                          |                           |           |           |             |
| 25-61-00-001                                                               |         | OPERATIONAL CHECK OF ELT SYSTEM                            |          |                          |                           |           | Service   | ATA:25      |
| PN:S1821502-02                                                             | MOS     | 13-Mar-26                                                  | 12       |                          | 13-Mar-27                 |           | 227 d     |             |
| SN:LX1100843446                                                            | HRS     | 1221:24                                                    |          |                          |                           |           |           |             |
|                                                                            | AFL     | 564                                                        |          |                          |                           |           |           |             |
| PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00                             |         |                                                            |          |                          |                           |           |           |             |
| 25-61-00-002                                                               |         | GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER |          |                          |                           |           | Service   | ATA:25      |
| PN:S1821502-02                                                             | MOS     | 13-Mar-26                                                  | 12       |                          | 13-Mar-27                 |           | 227 d     |             |
| SN:LX1100843446                                                            | HRS     | 1221:24                                                    |          |                          |                           |           |           |             |
|                                                                            | AFL     | 564                                                        |          |                          |                           |           |           |             |
| PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00                             |         |                                                            |          |                          |                           |           |           |             |
| 25-61-04-001                                                               |         | DISCARD OF ELT BATTERY                                     |          |                          |                           |           | Service   | ATA:25      |
| PN:S1820506-01                                                             | MOS/MSC | 13-Mar-26                                                  | DUE      |                          | 30-Mar-32 (M)             |           | 2071 d    | LIFE LIMIT  |
| SN:2513 0337                                                               | HRS     | 1221:24                                                    |          |                          |                           |           |           |             |
|                                                                            | AFL     | 564                                                        |          |                          |                           |           |           |             |
|                                                                            |         |                                                            |          | Expiry Date: : 30-Mar-32 |                           |           |           |             |
| PROC. REF: AMM 25-61-04PROC. REF: AMM 25-61-04                             |         |                                                            |          |                          |                           |           |           |             |
| 25-61-05                                                                   |         | CS144-A ELT/NAV INTERFACE MODULE                           |          |                          |                           |           | Component | ATA:25      |
| PN:S1825502-02                                                             | MOS/MSC | 23-Apr-20                                                  | O/C      | TSN 0                    |                           |           |           |             |
| SN:TM0000175887                                                            | HRS     | 0                                                          |          | TSN 0                    |                           |           |           |             |
|                                                                            | AFL     | 0                                                          |          | TSN 0                    |                           |           |           |             |
| PROC. REF: AMM 25-61-05, AMM 25-61-05PROC. REF: AMM 25-61-05, AMM 25-61-05 |         |                                                            |          |                          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                 |           |          |          |                           |           |           |                  |
| 25-61-05-001                                                               | RESTORATION (REPAIR) OF ELT/NAV INTERFACEMODULE |           |          |          |                           |           |           | Service ATA:25   |
| PN:S1825502-02                                                             | MOS                                             | 01-May-19 | 120      |          | 01-May-29                 |           | 1007 d    |                  |
| SN:TM0000175887                                                            | HRS                                             | 0         | 16000    |          | 16000                     |           | 14704:36  |                  |
|                                                                            | AFL                                             |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-61-07PROC. REF: AMM 25-61-07                             |                                                 |           |          |          |                           |           |           |                  |
| 25-62-01                                                                   | #1 FIRST AID KIT                                |           |          |          |                           |           |           | Component ATA:25 |
| PN:39N814                                                                  | MOS/MSC                                         | 18-Sep-25 | H/T      | TSN 0    |                           |           |           |                  |
| SN:2251285                                                                 | HRS                                             | 1117:18   |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 518       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                 |           |          |          |                           |           |           |                  |
| 25-62-01-001                                                               | VISUAL CHECK #1 FIRST AID KIT                   |           |          |          |                           |           |           | Service ATA:25   |
| PN:39N814                                                                  | MOS/MSC                                         | 12-Dec-25 | DUE      |          | 31-Aug-27 (M)             |           | 398 d     |                  |
| SN:2251285                                                                 | HRS                                             | 1179:24   |          |          |                           |           |           |                  |
|                                                                            | AFL                                             | 546       |          |          |                           |           |           |                  |
| Expiry Date: : 31-Aug-27                                                   |                                                 |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01                             |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | COPILOT LIFE VEST                               |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-505                                                               | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4899811                                                                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | DIVAN NO. 1 LIFE VEST                           |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | DIVAN NO. 2 LIFE VEST                           |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                                                                      | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                           |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 1 PASSENGER LIFE VEST |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4996441                                                                | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 2 PASSENGER LIFE VEST |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4996440                                                                | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 3 PASSENGER LIFE VEST |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4996439                                                                | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 4 PASSENGER LIFE VEST |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4886624                                                                | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 5 PASSENGER LIFE VEST |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4998222                                                                | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 6 PASSENGER LIFE VEST |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                   | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4998236                                                                | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                           |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 7 PASSENGER LIFE VEST                       |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4998235                                                                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | NO. 8 PASSENGER LIFE VEST                       |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4998231                                                                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | PILOT LIFE VEST                                 |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-505                                                               | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4899810                                                                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02                                                                   | TOILET PAX LIFE VEST                            |           |          |          |                           |           |           | Component ATA:25 |
| PN:66601-105                                                               | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L4998227                                                                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02 |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02-001                                                               | RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST    |           |          |          |                           |           |           | Service ATA:25   |
| PN:66601-505                                                               | MOS                                             | 01-Oct-19 | 120      |          | 01-Oct-29                 |           | 1160 d    | OVERHAUL         |
| SN:L4899811                                                                | HRS                                             |           |          |          |                           |           |           |                  |
|                                                                            | AFL                                             |           |          |          |                           |           |           |                  |
| OverHaul Date:: 01-Oct-19                                                  |                                                 |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02                             |                                                 |           |          |          |                           |           |           |                  |
| 25-62-02-001                                                               | RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST |           |          |          |                           |           |           | Service ATA:25   |
| PN:PN                                                                      | MOS/MSC                                         |           | N/A      |          |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                             |           |          |          |                           |           |           |                  |
|                                                                            | AFL                                             |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02                             |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                            | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|-------------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                 |                                                 |           |                           |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST |           |                           |          |                           |           |           | Service ATA:25 |
| PN:PN                                          | MOS/MSC                                         |           | N/A                       |          |                           |           |           | OVERHAUL       |
| SN:UNKNOWN                                     | HRS                                             |           |                           |          |                           |           |           |                |
|                                                | AFL                                             |           |                           |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                                 |           |                           |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST       |           |                           |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                             | 01-Jan-20 | 120                       |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4996441                                    | HRS                                             |           |                           |          |                           |           |           |                |
|                                                | AFL                                             |           |                           |          |                           |           |           |                |
|                                                |                                                 |           | OverHaul Date:: 01-Jan-20 |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                                 |           |                           |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST       |           |                           |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                             | 01-Jan-20 | 120                       |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4996440                                    | HRS                                             |           |                           |          |                           |           |           |                |
|                                                | AFL                                             |           |                           |          |                           |           |           |                |
|                                                |                                                 |           | OverHaul Date:: 01-Jan-20 |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                                 |           |                           |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST       |           |                           |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                             | 01-Jan-20 | 120                       |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4996439                                    | HRS                                             |           |                           |          |                           |           |           |                |
|                                                | AFL                                             |           |                           |          |                           |           |           |                |
|                                                |                                                 |           | OverHaul Date:: 01-Jan-20 |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                                 |           |                           |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST       |           |                           |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                             | 01-Sep-19 | 120                       |          | 01-Sep-29                 |           | 1130 d    | OVERHAUL       |
| SN:L4886624                                    | HRS                                             |           |                           |          |                           |           |           |                |
|                                                | AFL                                             |           |                           |          |                           |           |           |                |
|                                                |                                                 |           | OverHaul Date:: 01-Sep-19 |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                                 |           |                           |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                 |                                           |           |          |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST |           |          |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                       | 01-Jan-20 | 120      |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4998222                                    | HRS                                       |           |          |          |                           |           |           |                |
|                                                | AFL                                       |           |          |          |                           |           |           |                |
|                                                | OverHaul Date:: 01-Jan-20                 |           |          |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                           |           |          |          |                           |           |           |                |
|                                                |                                           |           |          |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST |           |          |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                       | 01-Jan-20 | 120      |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4998236                                    | HRS                                       |           |          |          |                           |           |           |                |
|                                                | AFL                                       |           |          |          |                           |           |           |                |
|                                                | OverHaul Date:: 01-Jan-20                 |           |          |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                           |           |          |          |                           |           |           |                |
|                                                |                                           |           |          |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST |           |          |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                       | 01-Jan-20 | 120      |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4998235                                    | HRS                                       |           |          |          |                           |           |           |                |
|                                                | AFL                                       |           |          |          |                           |           |           |                |
|                                                | OverHaul Date:: 01-Jan-20                 |           |          |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                           |           |          |          |                           |           |           |                |
|                                                |                                           |           |          |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST |           |          |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                       | 01-Jan-20 | 120      |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4998231                                    | HRS                                       |           |          |          |                           |           |           |                |
|                                                | AFL                                       |           |          |          |                           |           |           |                |
|                                                | OverHaul Date:: 01-Jan-20                 |           |          |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                           |           |          |          |                           |           |           |                |
|                                                |                                           |           |          |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF PILOT LIFE VEST |           |          |          |                           |           |           | Service ATA:25 |
| PN:66601-505                                   | MOS                                       | 01-Oct-19 | 120      |          | 01-Oct-29                 |           | 1160 d    | OVERHAUL       |
| SN:L4899810                                    | HRS                                       |           |          |          |                           |           |           |                |
|                                                | AFL                                       |           |          |          |                           |           |           |                |
|                                                | OverHaul Date:: 01-Oct-19                 |           |          |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                           |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                       | C/W       | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------------------------------------|-----------|---------------------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                 |                                            |           |                           |          |                           |           |           |                |
| 25-62-02-001                                   | RESTORATION (OVERHAUL) OF TOILET LIFE VEST |           |                           |          |                           |           |           | Service ATA:25 |
| PN:66601-105                                   | MOS                                        | 01-Jan-20 | 120                       |          | 01-Jan-30                 |           | 1252 d    | OVERHAUL       |
| SN:L4998227                                    | HRS                                        |           |                           |          |                           |           |           |                |
|                                                | AFL                                        |           |                           |          |                           |           |           |                |
|                                                |                                            |           | OverHaul Date:: 01-Jan-20 |          |                           |           |           |                |
| PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02 |                                            |           |                           |          |                           |           |           |                |

|                           |                    |           |     |  |  |  |  |                |
|---------------------------|--------------------|-----------|-----|--|--|--|--|----------------|
| 25-62-02-003 <sup>U</sup> | DISCARD NO. 8 VEST |           |     |  |  |  |  | Service ATA:25 |
| PN:66601-105              | MOS/MSC            | 01-Jan-20 | O/C |  |  |  |  |                |
| SN:L4998231               | HRS                |           |     |  |  |  |  |                |
|                           | AFL                |           |     |  |  |  |  |                |

|                           |                          |           |     |  |  |  |  |                |
|---------------------------|--------------------------|-----------|-----|--|--|--|--|----------------|
| 25-62-02-003 <sup>U</sup> | DISCARD TOILET LIFE VEST |           |     |  |  |  |  | Service ATA:25 |
| PN:66601-105              | MOS/MSC                  | 01-Jan-20 | O/C |  |  |  |  |                |
| SN:L4998227               | HRS                      |           |     |  |  |  |  |                |
|                           | AFL                      |           |     |  |  |  |  |                |

|                                                |                                                  |           |              |  |  |  |  |                |
|------------------------------------------------|--------------------------------------------------|-----------|--------------|--|--|--|--|----------------|
| 25-62-04-001 <sup>S</sup>                      | DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER |           |              |  |  |  |  | Service ATA:25 |
|                                                | MOS                                              | 13-Mar-26 | 24 (+1m/-1m) |  |  |  |  |                |
|                                                | HRS                                              | 1221:24   |              |  |  |  |  |                |
|                                                | AFL                                              | 564       |              |  |  |  |  |                |
|                                                |                                                  |           |              |  |  |  |  | PKG:81         |
| PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04 |                                                  |           |              |  |  |  |  |                |

|                                                    |           |           |     |       |  |  |  |                  |
|----------------------------------------------------|-----------|-----------|-----|-------|--|--|--|------------------|
| 25-66-01                                           | LIFE RAFT |           |     |       |  |  |  | Component ATA:25 |
| PN:913FASA-690-1-103                               | MOS/MSC   | 22-Jan-24 | O/C | TSO 0 |  |  |  |                  |
| SN:9UL-00895                                       | HRS       |           |     | TSO 0 |  |  |  |                  |
|                                                    | AFL       |           |     | TSO 0 |  |  |  |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |           |           |     |       |  |  |  |                  |

|                              |                                     |           |    |  |           |  |       |                |
|------------------------------|-------------------------------------|-----------|----|--|-----------|--|-------|----------------|
| 25-66-01-001                 | RESTORATION (OVERHAUL) OF LIFE RAFT |           |    |  |           |  |       | Service ATA:25 |
| PN:913FASA-690-1-103         | MOS                                 | 22-Jan-24 | 36 |  | 22-Jan-27 |  | 177 d |                |
| SN:9UL-00895                 | HRS                                 |           |    |  |           |  |       |                |
|                              | AFL                                 |           |    |  |           |  |       |                |
| Restoration Date:: 22-Jan-24 |                                     |           |    |  |           |  |       |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                             |                                                       |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 25-66-01PROC. REF: AMM 25-66-01                             |                                                       |           |                |          |                           |           |           |                  |
| 25-99-01                                                                   | REAR FUS INTERCONNECTION CABLE                        |           |                |          |                           |           |           | Component ATA:25 |
| PN:S1825503-01                                                             | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:TM0000153795                                                            | HRS                                                   | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                       |           |                |          |                           |           |           |                  |
| ATA 26 - FIRE PROTECTION                                                   |                                                       |           |                |          |                           |           |           |                  |
| 26-11-01                                                                   | LEFT ENGINE FIRE DETECTOR                             |           |                |          |                           |           |           | Component ATA:26 |
| PN:3951-51-565/215C-5.1M                                                   | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:55658                                                                   | HRS                                                   | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-11-01, AMM 26-11-01PROC. REF: AMM 26-11-01, AMM 26-11-01 |                                                       |           |                |          |                           |           |           |                  |
| 26-11-01                                                                   | RIGHT ENGINE FIRE DETECTOR                            |           |                |          |                           |           |           | Component ATA:26 |
| PN:3951-51-565/215C-5.1M                                                   | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:56035                                                                   | HRS                                                   | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-11-01, AMM 26-11-01PROC. REF: AMM 26-11-01, AMM 26-11-01 |                                                       |           |                |          |                           |           |           |                  |
| 26-11-01-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR  |           |                |          |                           |           |           | Service ATA:26   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                   | 0         | 1600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |                                                       |           |                |          |                           |           |           | PKG:10           |
| 26-11-01-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR |           |                |          |                           |           |           | Service ATA:26   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                   | 0         | 1600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |                                                       |           |                |          |                           |           |           | PKG:10           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                 | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|--------------|-----------------------------------------------------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 26 - FIRE PROTECTION                                                   |              |                                                     |                |          |                           |           |               |                  |
| 26-11-01-002                                                               | <sup>S</sup> | OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR         |                |          |                           |           |               | Service ATA:26   |
|                                                                            | MOS          | 19-Mar-24                                           |                |          |                           |           |               |                  |
|                                                                            | HRS          | 781:30                                              | 800 (+30/-30)  |          |                           |           |               |                  |
|                                                                            | AFL          | 364                                                 |                |          |                           |           |               |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |              |                                                     |                |          |                           |           |               | PKG:1            |
| 26-11-01-002                                                               | <sup>S</sup> | OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR        |                |          |                           |           |               | Service ATA:26   |
|                                                                            | MOS          | 19-Mar-24                                           |                |          |                           |           |               |                  |
|                                                                            | HRS          | 781:30                                              | 800 (+30/-30)  |          |                           |           |               |                  |
|                                                                            | AFL          | 364                                                 |                |          |                           |           |               |                  |
| PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01                             |              |                                                     |                |          |                           |           |               | PKG:1            |
| 26-15-01                                                                   |              | MODEL 602 SMOKE DETECTOR                            |                |          |                           |           |               | Component ATA:26 |
| PN:8930-223B60L014                                                         | MOS/MSC      | 23-Apr-20                                           | O/C            | TSN 0    |                           |           |               |                  |
| SN:28582                                                                   | HRS          | 0                                                   |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL          | 0                                                   |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 26-15-01, AMM 26-15-01PROC. REF: AMM 26-15-01, AMM 26-15-01 |              |                                                     |                |          |                           |           |               |                  |
| 26-21-01                                                                   |              | ENGINE FIRE EXTINGUISHER BOTTLE                     |                |          |                           |           |               | Component ATA:26 |
| PN:33000073-1                                                              | MOS/MSC      | 23-Apr-20                                           | O/C            | TSN 0    |                           |           |               |                  |
| SN:92968A1                                                                 | HRS          | 0                                                   |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL          | 0                                                   |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 26-21-03, AMM 26-21-03PROC. REF: AMM 26-21-03, AMM 26-21-03 |              |                                                     |                |          |                           |           |               |                  |
| 26-21-01-001                                                               |              | FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL |                |          |                           |           |               | Service ATA:26   |
|                                                                            | MOS          | 23-Apr-20                                           |                |          |                           |           |               | AIRWORTHINESS    |
|                                                                            | HRS          | 0                                                   | 2400 (+30/-30) |          | 2400                      | 2430      | 1104:36 (+30) |                  |
|                                                                            | AFL          | 0                                                   |                |          |                           |           |               |                  |
| PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00                             |              |                                                     |                |          |                           |           |               |                  |
| 26-21-01A                                                                  |              | FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL             |                |          |                           |           |               | Component ATA:26 |
| PN:441-44278-001                                                           | MOS/MSC      | 23-Apr-20                                           | O/C            | TSN 0    |                           |           |               |                  |
| SN:1442                                                                    | HRS          | 0                                                   |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL          | 0                                                   |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 26-21-01, AMM 26-21-01PROC. REF: AMM 26-21-01, AMM 26-21-01 |              |                                                     |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION                                                   |                                                                     |           |                |          |                           |           |           |                  |
| 26-21-03-001                                                               | FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE                 |           |                |          |                           |           |           | Service ATA:26   |
| PN:33000073-1                                                              | MOS                                                                 | 01-Sep-19 | 120            |          | 01-Sep-29                 |           | 1130 d    | AIRWORTHINESS    |
| SN:92968A1                                                                 | HRS                                                                 |           |                |          |                           |           |           |                  |
|                                                                            | AFL                                                                 |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03                             |                                                                     |           |                |          |                           |           |           |                  |
| 26-21-05-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) |           |                |          |                           |           |           | Service ATA:26   |
|                                                                            | MOS                                                                 | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                 | 0         | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                 | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05                             |                                                                     |           |                |          |                           |           |           |                  |
| 26-21-07                                                                   | NO. 1 CARTRIDGE                                                     |           |                |          |                           |           |           | Component ATA:26 |
| PN:30903962-1                                                              | MOS/MSC                                                             | 23-Apr-20 | H/T            | TSN 0    |                           |           |           |                  |
| SN:1893YC                                                                  | HRS                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-21-07, AMM 26-21-07PROC. REF: AMM 26-21-07, AMM 26-21-07 |                                                                     |           |                |          |                           |           |           |                  |
| 26-21-07                                                                   | NO. 2 CARTRIDGE                                                     |           |                |          |                           |           |           | Component ATA:26 |
| PN:30903963-1                                                              | MOS/MSC                                                             | 23-Apr-20 | H/T            | TSN 0    |                           |           |           |                  |
| SN:0235YG                                                                  | HRS                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-21-07, AMM 26-21-07PROC. REF: AMM 26-21-07, AMM 26-21-07 |                                                                     |           |                |          |                           |           |           |                  |
| 26-21-07-001                                                               | DISCARD NO. 1 CARTRIDGE                                             |           |                |          |                           |           |           | Service ATA:26   |
| PN:30903962-1                                                              | MOS                                                                 | 01-Oct-19 | 120            |          | 01-Oct-29                 |           | 1160 d    | LIFE LIMIT       |
| SN:1893YC                                                                  | HRS                                                                 |           |                |          |                           |           |           |                  |
|                                                                            | AFL                                                                 |           |                |          |                           |           |           |                  |
| Manufacture Date:: 01-Oct-19                                               |                                                                     |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-21-07PROC. REF: AMM 26-21-07                             |                                                                     |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                     | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION                                                   |                                                                          |           |                |          |                           |           |           |                  |
| 26-21-07-001                                                               | DISCARD NO. 2 CARTRIDGE                                                  |           |                |          |                           |           |           | Service ATA:26   |
| PN:30903963-1                                                              | MOS                                                                      | 01-Oct-19 | 120            |          | 01-Oct-29                 |           | 1160 d    | LIFE LIMIT       |
| SN:0235YG                                                                  | HRS                                                                      |           |                |          |                           |           |           |                  |
|                                                                            | AFL                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-21-07PROC. REF: AMM 26-21-07                             |                                                                          |           |                |          |                           |           |           |                  |
| 26-21-09-001 <sup>S</sup>                                                  | DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING |           |                |          |                           |           |           | Service ATA:26   |
|                                                                            | MOS                                                                      | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                      | 0         | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                      | 0         |                |          |                           |           |           |                  |
| PKG:20                                                                     |                                                                          |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-21-09PROC. REF: AMM 26-21-09                             |                                                                          |           |                |          |                           |           |           |                  |
| 26-24-01                                                                   | CABIN PORTABLE FIRE EXTINGUISHER                                         |           |                |          |                           |           |           | Component ATA:26 |
| PN:P3APP003010D                                                            | MOS/MSC                                                                  | 19-Mar-24 | H/T            | TSN 12   |                           |           |           |                  |
| SN:064491                                                                  | HRS                                                                      | 781:30    |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                      | 364       |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-24-01, AMM 26-24-01PROC. REF: AMM 26-24-01, AMM 26-24-01 |                                                                          |           |                |          |                           |           |           |                  |
| 26-24-01                                                                   | COCKPIT PORTABLE FIRE EXTINGUISHER                                       |           |                |          |                           |           |           | Component ATA:26 |
| PN:P3APP003010A                                                            | MOS/MSC                                                                  | 23-Apr-20 | H/T            | TSN 0    |                           |           |           |                  |
| SN:017954                                                                  | HRS                                                                      | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                      | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-24-01, AMM 26-24-01PROC. REF: AMM 26-24-01, AMM 26-24-01 |                                                                          |           |                |          |                           |           |           |                  |
| 26-24-01-001                                                               | WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER                            |           |                |          |                           |           |           | Service ATA:26   |
| PN:P3APP003010D                                                            | MOS/MSC                                                                  |           | N/A            |          |                           |           |           |                  |
| SN:064491                                                                  | HRS                                                                      |           |                |          |                           |           |           |                  |
|                                                                            | AFL                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01                             |                                                                          |           |                |          |                           |           |           |                  |
| 26-24-01-001                                                               | WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER                       |           |                |          |                           |           |           | Service ATA:26   |
| PN:P3APP003010A                                                            | MOS/MSC                                                                  |           | N/A            |          |                           |           |           |                  |
| SN:017954                                                                  | HRS                                                                      |           |                |          |                           |           |           |                  |
|                                                                            | AFL                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01                             |                                                                          |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit    | C/W                                                | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|---------|----------------------------------------------------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 26 - FIRE PROTECTION                       |         |                                                    |          |          |                           |           |           |                |
| 26-24-01-002                                   |         | DISCARD CABIN PORTABLE FIRE EXTINGUISHER           |          |          |                           |           |           | Service ATA:26 |
| PN:P3APP003010D                                | MOS     | 01-Mar-23                                          | 144      |          | 01-Mar-35                 |           | 3137 d    | LIFE LIMIT     |
| SN:064491                                      | HRS     | 781:30                                             |          |          |                           |           |           |                |
|                                                | AFL     | 364                                                |          |          |                           |           |           |                |
| Manufacture Date:: 01-Mar-23                   |         |                                                    |          |          |                           |           |           |                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |         |                                                    |          |          |                           |           |           |                |
| 26-24-01-002                                   |         | DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER      |          |          |                           |           |           | Service ATA:26 |
| PN:P3APP003010A                                | MOS     | 01-Sep-19                                          | 144      |          | 01-Sep-31                 |           | 1860 d    | LIFE LIMIT     |
| SN:017954                                      | HRS     |                                                    |          |          |                           |           |           |                |
|                                                | AFL     |                                                    |          |          |                           |           |           |                |
| Manufacture Date:: 01-Sep-19                   |         |                                                    |          |          |                           |           |           |                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |         |                                                    |          |          |                           |           |           |                |
| 26-24-01-003                                   |         | DISCARD CABIN PORTABLE FIRE EXTINGUISHER           |          |          |                           |           |           | Service ATA:26 |
| PN:P3APP003010D                                | MOS/MSC |                                                    | N/A      |          |                           |           |           |                |
| SN:064491                                      | HRS     |                                                    |          |          |                           |           |           |                |
|                                                | AFL     |                                                    |          |          |                           |           |           |                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |         |                                                    |          |          |                           |           |           |                |
| 26-24-01-003                                   |         | DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER      |          |          |                           |           |           | Service ATA:26 |
| PN:P3APP003010A                                | MOS/MSC |                                                    | N/A      |          |                           |           |           |                |
| SN:017954                                      | HRS     |                                                    |          |          |                           |           |           |                |
|                                                | AFL     |                                                    |          |          |                           |           |           |                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |         |                                                    |          |          |                           |           |           |                |
| 26-24-01-004                                   |         | WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER   |          |          |                           |           |           | Service ATA:26 |
| PN:P3APP003010D                                | MOS     | 31-Mar-25                                          | 24       |          | 31-Mar-27                 |           | 245 d     |                |
| SN:064491                                      | HRS     | 987:24                                             |          |          |                           |           |           |                |
|                                                | AFL     | 456                                                |          |          |                           |           |           |                |
| PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01 |         |                                                    |          |          |                           |           |           |                |
| 26-24-01-004                                   |         | WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER |          |          |                           |           |           | Service ATA:26 |
| PN:P3APP003010A                                | MOS     | 31-Mar-25                                          | 24       |          | 31-Mar-27                 |           | 245 d     |                |
| SN:017954                                      | HRS     | 987:24                                             |          |          |                           |           |           |                |
|                                                | AFL     | 456                                                |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---------|------|-----|----------|----------|---------------------------|-----------|-----------|-------------|
|---------|------|-----|----------|----------|---------------------------|-----------|-----------|-------------|

### ATA 26 - FIRE PROTECTION

PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01

### ATA 27 - FLIGHT CONTROLS

|                                                                            |                                           |           |     |  |  |  |         |        |
|----------------------------------------------------------------------------|-------------------------------------------|-----------|-----|--|--|--|---------|--------|
| 27-001                                                                     | DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR |           |     |  |  |  | Service | ATA:27 |
| PN:475100-1013                                                             | MOS/MSC                                   | 23-Apr-20 | N/A |  |  |  |         |        |
| SN:1210                                                                    | HRS                                       | 0         |     |  |  |  |         |        |
|                                                                            | AFL                                       | 0         |     |  |  |  |         |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                           |           |     |  |  |  |         |        |

|                                                                            |                                            |           |     |  |  |  |         |        |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|-----|--|--|--|---------|--------|
| 27-001                                                                     | DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR |           |     |  |  |  | Service | ATA:27 |
| PN:475100-1013                                                             | MOS/MSC                                    | 23-Apr-20 | N/A |  |  |  |         |        |
| SN:1216                                                                    | HRS                                        | 0         |     |  |  |  |         |        |
|                                                                            | AFL                                        | 0         |     |  |  |  |         |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |     |  |  |  |         |        |

|                                                                            |                                           |           |     |  |  |  |         |        |
|----------------------------------------------------------------------------|-------------------------------------------|-----------|-----|--|--|--|---------|--------|
| 27-002                                                                     | DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR |           |     |  |  |  | Service | ATA:27 |
| PN:475000-2013                                                             | MOS/MSC                                   | 23-Apr-20 | N/A |  |  |  |         |        |
| SN:2425                                                                    | HRS                                       | 0         |     |  |  |  |         |        |
|                                                                            | AFL                                       | 0         |     |  |  |  |         |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                           |           |     |  |  |  |         |        |

|                                                                            |                                            |           |     |  |  |  |         |        |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|-----|--|--|--|---------|--------|
| 27-002                                                                     | DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |           |     |  |  |  | Service | ATA:27 |
| PN:475000-2013                                                             | MOS/MSC                                    | 23-Apr-20 | N/A |  |  |  |         |        |
| SN:2426                                                                    | HRS                                        | 0         |     |  |  |  |         |        |
|                                                                            | AFL                                        | 0         |     |  |  |  |         |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |     |  |  |  |         |        |

|                                                                            |                                          |           |     |  |  |  |         |        |
|----------------------------------------------------------------------------|------------------------------------------|-----------|-----|--|--|--|---------|--------|
| 27-003                                                                     | DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR |           |     |  |  |  | Service | ATA:27 |
| PN:475000-1013                                                             | MOS/MSC                                  | 23-Apr-20 | N/A |  |  |  |         |        |
| SN:2432                                                                    | HRS                                      | 0         |     |  |  |  |         |        |
|                                                                            | AFL                                      | 0         |     |  |  |  |         |        |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                          |           |     |  |  |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                                                                           |                                           |           |          |          |                           |           |           |                  |
| 27-003                                                                                                                             | DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR |           |          |          |                           |           |           | Service ATA:27   |
| PN:475000-1013                                                                                                                     | MOS/MSC                                   | 23-Apr-20 | N/A      |          |                           |           |           |                  |
| SN:2430                                                                                                                            | HRS                                       | 0         |          |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |                                           |           |          |          |                           |           |           |                  |
| 27-004                                                                                                                             | ROLL TRIM ACTUATOR                        |           |          |          |                           |           |           | Component ATA:27 |
| PN:470500-1005                                                                                                                     | MOS                                       | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:0590                                                                                                                            | HRS                                       | 0         | 12000    | TSN 0    | 12000                     |           | 10704:36  |                  |
|                                                                                                                                    | AFL                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-14-02, AMM 27-14-02PROC. REF: AMM 27-14-02, AMM 27-14-02                                                         |                                           |           |          |          |                           |           |           |                  |
| 27-005                                                                                                                             | YAW TRIM ACTUATOR                         |           |          |          |                           |           |           | Component ATA:27 |
| PN:470600-1005                                                                                                                     | MOS                                       | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:0593                                                                                                                            | HRS                                       | 0         | 12000    | TSN 0    | 12000                     |           | 10704:36  |                  |
|                                                                                                                                    | AFL                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-24-02, AMM 27-24-02PROC. REF: AMM 27-24-02, AMM 27-24-02                                                         |                                           |           |          |          |                           |           |           |                  |
| 27-006                                                                                                                             | PITCH TRIM ACTUATOR                       |           |          |          |                           |           |           | Component ATA:27 |
| PN:467500-1003                                                                                                                     | MOS                                       | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:0605                                                                                                                            | HRS                                       | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                                                                                    | AFL                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-41-01, AMM 27-41-01PROC. REF: AMM 27-41-01, AMM 27-41-01                                                         |                                           |           |          |          |                           |           |           |                  |
| 27-007                                                                                                                             | LEFT SPOILER ACTUATOR                     |           |          |          |                           |           |           | Component ATA:27 |
| PN:456800-1003                                                                                                                     | MOS                                       | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1156                                                                                                                            | HRS                                       | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                                                                                    | AFL                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02 |                                           |           |          |          |                           |           |           |                  |
| 27-007                                                                                                                             | RIGHT SPOILER ACTUATOR                    |           |          |          |                           |           |           | Component ATA:27 |
| PN:456800-1003                                                                                                                     | MOS                                       | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1157                                                                                                                            | HRS                                       | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                                                                                    | AFL                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02 |                                           |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                     |           |              |          |                           |           |           |                  |
| 27-008                                                                     | ELECTRO - RUDDER GUST LOCK ACTUATOR |           |              |          |                           |           |           | Component ATA:27 |
| PN:SYLC-53058                                                              | MOS/MSC                             | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:1991                                                                    | HRS                                 | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                 | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-70-01, AMM 27-70-01PROC. REF: AMM 27-70-01, AMM 27-70-01 |                                     |           |              |          |                           |           |           |                  |
| 27-009                                                                     | RUDDER BOOSTER ACTUATOR             |           |              |          |                           |           |           | Component ATA:27 |
| PN:9125-3                                                                  | MOS                                 | 23-Apr-20 |              | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:0567T                                                                   | HRS                                 | 0         | 35000        | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                                 | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-23-02, AMM 27-23-02PROC. REF: AMM 27-23-02, AMM 27-23-02 |                                     |           |              |          |                           |           |           |                  |
| 27-01-01                                                                   | LEFT CONTROL WHEEL                  |           |              |          |                           |           |           | Component ATA:27 |
| PN:83912139                                                                | MOS/MSC                             | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:01261                                                                   | HRS                                 | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                 | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-01-01, AMM 27-01-01PROC. REF: AMM 27-01-01, AMM 27-01-01 |                                     |           |              |          |                           |           |           |                  |
| 27-01-01                                                                   | RIGHT CONTROL WHEEL                 |           |              |          |                           |           |           | Component ATA:27 |
| PN:83912141                                                                | MOS/MSC                             | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:01206                                                                   | HRS                                 | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                 | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-01-01, AMM 27-01-01PROC. REF: AMM 27-01-01, AMM 27-01-01 |                                     |           |              |          |                           |           |           |                  |
| 27-01-02                                                                   | LH PEDAL ASSEMBLY                   |           |              |          |                           |           |           | Component ATA:27 |
| PN:505-15420-427                                                           | MOS/MSC                             | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:0001047479                                                              | HRS                                 | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                 | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-01-02, AMM 27-01-02PROC. REF: AMM 27-01-02, AMM 27-01-02 |                                     |           |              |          |                           |           |           |                  |
| 27-01-03-001 <sup>S</sup>                                                  | LUBRICATION OF ROTARY BALL SPLINE   |           |              |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS                                 | 13-Mar-26 | 24 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                 | 1221:24   |              |          |                           |           |           |                  |
|                                                                            | AFL                                 | 564       |              |          |                           |           |           |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00                             |                                     |           |              |          |                           |           |           |                  |
| PKG:81                                                                     |                                     |           |              |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                 |           |          |          |                           |           |           |                  |
| 27-010                                                                     | LEFT TOGGLE LINK                |           |          |          |                           |           |           | Component ATA:27 |
| PN:456870-1001                                                             | MOS                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1273                                                                    | HRS                             | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-65-02, AMM 27-65-02PROC. REF: AMM 27-65-02, AMM 27-65-02 |                                 |           |          |          |                           |           |           |                  |
| 27-010                                                                     | RIGHT TOGGLE LINK               |           |          |          |                           |           |           | Component ATA:27 |
| PN:456870-1001                                                             | MOS                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1274                                                                    | HRS                             | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-65-02, AMM 27-65-02PROC. REF: AMM 27-65-02, AMM 27-65-02 |                                 |           |          |          |                           |           |           |                  |
| 27-011                                                                     | STICK PUSHER ACTUATOR           |           |          |          |                           |           |           | Component ATA:27 |
| PN:9124-1                                                                  | MOS                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:0545T                                                                   | HRS                             | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-36-02, AMM 27-36-02PROC. REF: AMM 27-36-02, AMM 27-36-02 |                                 |           |          |          |                           |           |           |                  |
| 27-012                                                                     | POWER DRIVE UNIT                |           |          |          |                           |           |           | Component ATA:27 |
| PN:467700-1003                                                             | MOS                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:0619                                                                    | HRS                             | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-07, AMM 27-51-07PROC. REF: AMM 27-51-07, AMM 27-51-07 |                                 |           |          |          |                           |           |           |                  |
| 27-013                                                                     | LEFT FLAP POSITION SENSOR UNIT  |           |          |          |                           |           |           | Component ATA:27 |
| PN:457310-1001                                                             | MOS                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1218                                                                    | HRS                             | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-53-03, AMM 27-53-03PROC. REF: AMM 27-53-03, AMM 27-53-03 |                                 |           |          |          |                           |           |           |                  |
| 27-013                                                                     | RIGHT FLAP POSITION SENSOR UNIT |           |          |          |                           |           |           | Component ATA:27 |
| PN:457310-1001                                                             | MOS                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1220                                                                    | HRS                             | 0         | 35000    | TSN 0    | 35000                     |           | 33704:36  |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-53-03, AMM 27-53-03PROC. REF: AMM 27-53-03, AMM 27-53-03 |                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                              |           |          |          |                           |           |           |                |
| 27-014                                                                     | DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT    |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1007                                                             | MOS/MSC                                      | 23-Apr-20 | N/A      |          |                           |           |           |                |
| SN:SSW1147                                                                 | HRS                                          | 0         |          |          |                           |           |           |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-014                                                                     | DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT   |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 19-Mar-24 |          |          |                           |           |           | LIFE LIMIT     |
| SN:SSW3513                                                                 | HRS                                          | 781:30    | 35000    |          | 35781:30                  |           | 34486:06  |                |
|                                                                            | AFL                                          | 364       |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-014                                                                     | DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:SSW2329                                                                 | HRS                                          | 0         | 35000    |          | 35000                     |           | 33704:36  |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-014                                                                     | DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT   |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1007                                                             | MOS/MSC                                      | 23-Apr-20 | N/A      |          |                           |           |           |                |
| SN:SSW1167                                                                 | HRS                                          | 0         |          |          |                           |           |           |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-014                                                                     | DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 19-Mar-24 |          |          |                           |           |           | LIFE LIMIT     |
| SN:SSW3541                                                                 | HRS                                          | 781:30    | 35000    |          | 35781:30                  |           | 34486:06  |                |
|                                                                            | AFL                                          | 364       |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-014                                                                     | DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS                                          | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:SSW2336                                                                 | HRS                                          | 0         | 35000    |          | 35000                     |           | 33704:36  |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                              |           |          |          |                           |           |           |                |
| 27-015                                                                     | DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT    |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1007                                                             | MOS                                          | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:SSW1147                                                                 | HRS                                          | 0         | 35000    |          | 35000                     |           | 33704:36  |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-015                                                                     | DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT   |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      |           | N/A      |          |                           |           |           |                |
| SN:SSW3513                                                                 | HRS                                          |           |          |          |                           |           |           |                |
|                                                                            | AFL                                          |           |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-015                                                                     | DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      | 23-Apr-20 | N/A      |          |                           |           |           |                |
| SN:SSW2329                                                                 | HRS                                          | 0         |          |          |                           |           |           |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-015                                                                     | DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT   |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1007                                                             | MOS                                          | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:SSW1167                                                                 | HRS                                          | 0         | 35000    |          | 35000                     |           | 33704:36  |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-015                                                                     | DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT  |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      |           | N/A      |          |                           |           |           |                |
| SN:SSW3541                                                                 | HRS                                          |           |          |          |                           |           |           |                |
|                                                                            | AFL                                          |           |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |
| 27-015                                                                     | DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT |           |          |          |                           |           |           | Service ATA:27 |
| PN:457360-1005                                                             | MOS/MSC                                      | 23-Apr-20 | N/A      |          |                           |           |           |                |
| SN:SSW2336                                                                 | HRS                                          | 0         |          |          |                           |           |           |                |
|                                                                            | AFL                                          | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                              |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                            |           |          |          |                           |           |           |                |
| 27-016                                                                     | DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR  |           |          |          |                           |           |           | Service ATA:27 |
| PN:475100-1013                                                             | MOS                                        | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:1210                                                                    | HRS                                        | 0         | 7200     |          | 7200                      |           | 5904:36   |                |
|                                                                            | AFL                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                           |           |           |                |
| 27-016                                                                     | DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR |           |          |          |                           |           |           | Service ATA:27 |
| PN:475100-1013                                                             | MOS                                        | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:1216                                                                    | HRS                                        | 0         | 7200     |          | 7200                      |           | 5904:36   |                |
|                                                                            | AFL                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                           |           |           |                |
| 27-017                                                                     | DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR  |           |          |          |                           |           |           | Service ATA:27 |
| PN:475000-2013                                                             | MOS                                        | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:2425                                                                    | HRS                                        | 0         | 7200     |          | 7200                      |           | 5904:36   |                |
|                                                                            | AFL                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                           |           |           |                |
| 27-017                                                                     | DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |           |          |          |                           |           |           | Service ATA:27 |
| PN:475000-2013                                                             | MOS                                        | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:2426                                                                    | HRS                                        | 0         | 7200     |          | 7200                      |           | 5904:36   |                |
|                                                                            | AFL                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                           |           |           |                |
| 27-018                                                                     | DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR   |           |          |          |                           |           |           | Service ATA:27 |
| PN:475000-1013                                                             | MOS                                        | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:2432                                                                    | HRS                                        | 0         | 7200     |          | 7200                      |           | 5904:36   |                |
|                                                                            | AFL                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                           |           |           |                |
| 27-018                                                                     | DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR  |           |          |          |                           |           |           | Service ATA:27 |
| PN:475000-1013                                                             | MOS                                        | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT     |
| SN:2430                                                                    | HRS                                        | 0         | 7200     |          | 7200                      |           | 5904:36   |                |
|                                                                            | AFL                                        | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                            |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                       |           |                |          |                           |           |               |                  |
| 27-03-01                                                                   | NO. 1 ELECTRONICS FLIGHT CONTROL                      |           |                |          |                           |           |               | Component ATA:27 |
| PN:462900-1017                                                             | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:2039                                                                    | HRS                                                   | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-03-01, AMM 27-03-01PROC. REF: AMM 27-03-01, AMM 27-03-01 |                                                       |           |                |          |                           |           |               |                  |
| 27-03-01                                                                   | NO. 2 ELECTRONICS FLIGHT CONTROL                      |           |                |          |                           |           |               | Component ATA:27 |
| PN:462900-1017                                                             | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:2041                                                                    | HRS                                                   | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-03-01, AMM 27-03-01PROC. REF: AMM 27-03-01, AMM 27-03-01 |                                                       |           |                |          |                           |           |               |                  |
| 27-03-01-002 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP        |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |          |                           |           |               |                  |
|                                                                            | HRS                                                   | 0         | 5600 (+30/-30) |          |                           |           |               |                  |
|                                                                            | AFL                                                   | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-03-01PROC. REF: AMM 27-03-01                             |                                                       |           |                |          |                           |           |               |                  |
| 27-03-01-003 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |          |                           |           |               |                  |
|                                                                            | HRS                                                   | 0         | 5600 (+30/-30) |          |                           |           |               |                  |
|                                                                            | AFL                                                   | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-03-01PROC. REF: AMM 27-03-01                             |                                                       |           |                |          |                           |           |               |                  |
| 27-03-01-004                                                               | OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                   | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS    |
|                                                                            | HRS                                                   | 0         | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                  |
|                                                                            | AFL                                                   | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-03-01PROC. REF: AMM 27-03-01                             |                                                       |           |                |          |                           |           |               |                  |
| 27-04-01                                                                   | TRIM ACTUATOR CONTROLLER                              |           |                |          |                           |           |               | Component ATA:27 |
| PN:475200-1009                                                             | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:2116                                                                    | HRS                                                   | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-04-01, AMM 27-04-01PROC. REF: AMM 27-04-01, AMM 27-04-01 |                                                       |           |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                              | Unit    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|----------------------------------------------------------------------------------------------------------------------|---------|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|
| ATA 27 - FLIGHT CONTROLS                                                                                             |         |           |                |          |                           |           |           |             |
| 27-04-01-001 <sup>S</sup> FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER Service ATA:27                   |         |           |                |          |                           |           |           |             |
|                                                                                                                      | MOS     | 23-Apr-20 |                |          |                           |           |           |             |
|                                                                                                                      | HRS     | 0         | 5600 (+30/-30) |          |                           |           |           |             |
|                                                                                                                      | AFL     | 0         |                |          |                           |           |           |             |
| PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01                                                                       |         |           |                |          |                           |           |           | PKG:50      |
| 27-04-01-002 <sup>S</sup> FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP Service ATA:27                     |         |           |                |          |                           |           |           |             |
|                                                                                                                      | MOS     | 23-Apr-20 |                |          |                           |           |           |             |
|                                                                                                                      | HRS     | 0         | 5600 (+30/-30) |          |                           |           |           |             |
|                                                                                                                      | AFL     | 0         |                |          |                           |           |           |             |
| PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01                                                                       |         |           |                |          |                           |           |           | PKG:50      |
| 27-11-00 AILERON CABLES ASSY. Component ATA:27                                                                       |         |           |                |          |                           |           |           |             |
| PN:PN                                                                                                                | MOS/MSC | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |             |
| SN:UNKNOWN                                                                                                           | HRS     | 0         |                | TSN 0    |                           |           |           |             |
|                                                                                                                      | AFL     | 0         |                | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-11-02, AMM 27-11-02PROC. REF: AMM 27-11-02, AMM 27-11-02                                           |         |           |                |          |                           |           |           |             |
| 27-11-00-001 <sup>S</sup> GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS Service ATA:27 |         |           |                |          |                           |           |           |             |
|                                                                                                                      | MOS     | 31-Mar-25 | 60 (+1m/-1m)   |          |                           |           |           |             |
|                                                                                                                      | HRS     | 987:24    | 3200 (+30/-30) |          |                           |           |           |             |
|                                                                                                                      | AFL     | 456       |                |          |                           |           |           |             |
| PROC. REF: AMM 27-11-00PROC. REF: AMM 27-11-00                                                                       |         |           |                |          |                           |           |           | PKG:42      |
| 27-11-01 LEFT AILERON Component ATA:27                                                                               |         |           |                |          |                           |           |           |             |
| PN:505-14721-405                                                                                                     | MOS/MSC | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |             |
| SN:0001054077                                                                                                        | HRS     | 0         |                | TSN 0    |                           |           |           |             |
|                                                                                                                      | AFL     | 0         |                | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-11-01, AMM 27-11-01PROC. REF: AMM 27-11-01, AMM 27-11-01                                           |         |           |                |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                         |           |                |          |                           |           |               |                  |
| 27-11-01                                                                   | RIGHT AILERON                                                           |           |                |          |                           |           |               | Component ATA:27 |
| PN:505-14719-409                                                           | MOS/MSC                                                                 | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:0001056342                                                              | HRS                                                                     | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                     | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-11-01, AMM 27-11-01PROC. REF: AMM 27-11-01, AMM 27-11-01 |                                                                         |           |                |          |                           |           |               |                  |
| 27-11-02-001                                                               | FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION                      |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                                     | 31-Mar-25 | 60 (+1m/-1m)   | Adj 23d  | 23-Apr-30                 | 23-May-30 | 1364 d (+30)  |                  |
|                                                                            | HRS                                                                     | 987:24    | 3200 (+30/-30) |          | 4187:24                   | 4217:24   | 2892 (+30)    |                  |
|                                                                            | AFL                                                                     | 456       |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02                             |                                                                         |           |                |          |                           |           |               |                  |
| 27-11-02-001(INITIAL)                                                      | FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS/MSC                                                                 | 02-May-21 | -              | Adj -9d  |                           |           |               |                  |
|                                                                            | HRS                                                                     | 115:30    |                |          |                           |           |               |                  |
|                                                                            | AFL                                                                     | 57        |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02                             |                                                                         |           |                |          |                           |           |               |                  |
| 27-11-02-002 <sup>S</sup>                                                  | DETAILED INSPECTION OF AILERON CONTROL CABLES                           |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                                     | 31-Mar-25 | 60 (+1m/-1m)   |          |                           |           |               |                  |
|                                                                            | HRS                                                                     | 987:24    | 3200 (+30/-30) |          |                           |           |               |                  |
|                                                                            | AFL                                                                     | 456       |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02                             |                                                                         |           |                |          |                           |           |               |                  |
| PKG:42                                                                     |                                                                         |           |                |          |                           |           |               |                  |
| 27-14-02-001                                                               | FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY                    |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                                     | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS    |
|                                                                            | HRS                                                                     | 0         | 6000 (+30/-30) |          | 6000                      | 6030      | 4704:36 (+30) |                  |
|                                                                            | AFL                                                                     | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-14-03PROC. REF: AMM 27-14-03                             |                                                                         |           |                |          |                           |           |               |                  |
| 27-14-02-002                                                               | DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM                    |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                                                     | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS    |
|                                                                            | HRS                                                                     | 0         | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                  |
|                                                                            | AFL                                                                     | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-14-02PROC. REF: AMM 27-14-02                             |                                                                         |           |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                       | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                            |           |                |          |                           |           |              |                  |
| 27-14-03                                                                   | LEFT AILERON TAB                                                           |           |                |          |                           |           |              | Component ATA:27 |
| PN:505-14720-405                                                           | MOS/MSC                                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |              |                  |
| SN:0001054068                                                              | HRS                                                                        | 0         |                | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                                        | 0         |                | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 27-14-03, AMM 27-14-03PROC. REF: AMM 27-14-03, AMM 27-14-03 |                                                                            |           |                |          |                           |           |              |                  |
| 27-14-04                                                                   | LEFT BALANCED AILERON ASSY                                                 |           |                |          |                           |           |              | Component ATA:27 |
| PN:505-14735-641                                                           | MOS/MSC                                                                    | 31-Mar-25 | O/C            |          |                           |           |              |                  |
| SN:0001057854                                                              | HRS                                                                        | 987:24    |                |          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 456       |                |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                            |           |                |          |                           |           |              |                  |
| 27-21-00                                                                   | RUDDER CABLES ASSY.                                                        |           |                |          |                           |           |              | Component ATA:27 |
| PN:PN                                                                      | MOS/MSC                                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                                                                 | HRS                                                                        | 0         |                | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                                        | 0         |                | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 27-21-02, AMM 27-21-02PROC. REF: AMM 27-21-02, AMM 27-21-02 |                                                                            |           |                |          |                           |           |              |                  |
| 27-21-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS |           |                |          |                           |           |              | Service ATA:27   |
|                                                                            | MOS                                                                        | 31-Mar-25 | 60 (+1m/-1m)   |          |                           |           |              |                  |
|                                                                            | HRS                                                                        | 987:24    | 3200 (+30/-30) |          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 456       |                |          |                           |           |              |                  |
|                                                                            |                                                                            |           |                |          |                           |           |              | PKG:42           |
| PROC. REF: AMM 27-21-00PROC. REF: AMM 27-21-00                             |                                                                            |           |                |          |                           |           |              |                  |
| 27-21-01                                                                   | RUDDER ASSEMBLY                                                            |           |                |          |                           |           |              | Component ATA:27 |
| PN:505-39061-623                                                           | MOS/MSC                                                                    | 31-Mar-25 | O/C            |          |                           |           |              |                  |
| SN:0001062099                                                              | HRS                                                                        | 987:24    |                |          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 456       |                |          |                           |           |              |                  |
| PROC. REF: AMM 27-21-01, AMM 27-21-01PROC. REF: AMM 27-21-01, AMM 27-21-01 |                                                                            |           |                |          |                           |           |              |                  |
| 27-21-02-001                                                               | FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION                          |           |                |          |                           |           |              | Service ATA:27   |
|                                                                            | MOS                                                                        | 31-Mar-25 | 60 (+1m/-1m)   | Adj 23d  | 23-Apr-30                 | 23-May-30 | 1364 d (+30) |                  |
|                                                                            | HRS                                                                        | 987:24    | 3200 (+30/-30) |          | 4187:24                   | 4217:24   | 2892 (+30)   |                  |
|                                                                            | AFL                                                                        | 456       |                |          |                           |           |              |                  |
| PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02                             |                                                                            |           |                |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit    | C/W                                                                      | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|------------------------------------------------|---------|--------------------------------------------------------------------------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                       |         |                                                                          |                |          |                           |           |               |                  |
| 27-21-02-001(INITIAL)                          |         | FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK |                |          |                           |           |               | Service ATA:27   |
|                                                | MOS/MSC | 02-May-21                                                                | -              | Adj -9d  |                           |           |               |                  |
|                                                | HRS     | 115:30                                                                   |                |          |                           |           |               |                  |
|                                                | AFL     | 57                                                                       |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02 |         |                                                                          |                |          |                           |           |               |                  |
| 27-21-02-002 <sup>S</sup>                      |         | DETAILED INSPECTION OF RUDDER CONTROL CABLES                             |                |          |                           |           |               | Service ATA:27   |
|                                                | MOS     | 31-Mar-25                                                                | 60 (+1m/-1m)   |          |                           |           |               |                  |
|                                                | HRS     | 987:24                                                                   | 3200 (+30/-30) |          |                           |           |               |                  |
|                                                | AFL     | 456                                                                      |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02 |         |                                                                          |                |          |                           |           |               |                  |
| 27-23-00-001 <sup>S</sup>                      |         | OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM                   |                |          |                           |           |               | Service ATA:27   |
|                                                | MOS     | 23-Apr-20                                                                |                |          |                           |           |               |                  |
|                                                | HRS     | 0                                                                        | 1600 (+30/-30) |          |                           |           |               |                  |
|                                                | AFL     | 0                                                                        |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-23-00PROC. REF: AMM 27-23-00 |         |                                                                          |                |          |                           |           |               |                  |
| 27-24-02-001                                   |         | FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH                                 |                |          |                           |           |               | Service ATA:27   |
|                                                | MOS     | 23-Apr-20                                                                |                |          |                           |           |               | AIRWORTHINESS    |
|                                                | HRS     | 0                                                                        | 6000 (+30/-30) |          | 6000                      | 6030      | 4704:36 (+30) |                  |
|                                                | AFL     | 0                                                                        |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-24-03PROC. REF: AMM 27-24-03 |         |                                                                          |                |          |                           |           |               |                  |
| 27-24-02-002                                   |         | DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM                      |                |          |                           |           |               | Service ATA:27   |
|                                                | MOS     | 23-Apr-20                                                                |                |          |                           |           |               | AIRWORTHINESS    |
|                                                | HRS     | 0                                                                        | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                  |
|                                                | AFL     | 0                                                                        |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-24-02PROC. REF: AMM 27-24-02 |         |                                                                          |                |          |                           |           |               |                  |
| 27-24-03                                       |         | RUDDER TRIM TAB                                                          |                |          |                           |           |               | Component ATA:27 |
| PN:505-10450-409                               | MOS/MSC | 23-Apr-20                                                                | O/C            | TSN 0    |                           |           |               |                  |
| SN:0001060101                                  | HRS     | 0                                                                        |                | TSN 0    |                           |           |               |                  |
|                                                | AFL     | 0                                                                        |                | TSN 0    |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                              |           |                |          |                           |           |              |                  |
| PROC. REF: AMM 27-24-03, AMM 27-24-03PROC. REF: AMM 27-24-03, AMM 27-24-03 |                                                                              |           |                |          |                           |           |              |                  |
| 27-26-01                                                                   | VENTRAL RUDDER                                                               |           |                |          |                           |           |              | Component ATA:27 |
| PN:505-07540-417                                                           | MOS/MSC                                                                      | 23-Apr-20 | O/C            | TSN 0    |                           |           |              |                  |
| SN:0001060961                                                              | HRS                                                                          | 0         |                | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                                          | 0         |                | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 27-26-01, AMM 27-26-01PROC. REF: AMM 27-26-01, AMM 27-26-01 |                                                                              |           |                |          |                           |           |              |                  |
| 27-31-00                                                                   | ELEVATOR CABLES ASSY                                                         |           |                |          |                           |           |              | Component ATA:27 |
| PN:PN                                                                      | MOS/MSC                                                                      | 23-Apr-20 | O/C            | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                                                                 | HRS                                                                          | 0         |                | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                                          | 0         |                | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 27-31-02, AMM 27-31-02PROC. REF: AMM 27-31-02, AMM 27-31-02 |                                                                              |           |                |          |                           |           |              |                  |
| 27-31-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS |           |                |          |                           |           |              | Service ATA:27   |
|                                                                            | MOS                                                                          | 31-Mar-25 | 60 (+1m/-1m)   |          |                           |           |              |                  |
|                                                                            | HRS                                                                          | 987:24    | 3200 (+30/-30) |          |                           |           |              |                  |
|                                                                            | AFL                                                                          | 456       |                |          |                           |           |              |                  |
| PKG:42                                                                     |                                                                              |           |                |          |                           |           |              |                  |
| PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00                             |                                                                              |           |                |          |                           |           |              |                  |
| 27-31-02-001                                                               | FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION                          |           |                |          |                           |           |              | Service ATA:27   |
|                                                                            | MOS                                                                          | 31-Mar-25 | 60 (+1m/-1m)   | Adj 23d  | 23-Apr-30                 | 23-May-30 | 1364 d (+30) |                  |
|                                                                            | HRS                                                                          | 987:24    | 3200 (+30/-30) |          | 4187:24                   | 4217:24   | 2892 (+30)   |                  |
|                                                                            | AFL                                                                          | 456       |                |          |                           |           |              |                  |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02                             |                                                                              |           |                |          |                           |           |              |                  |
| 27-31-02-001(INITIAL)                                                      | FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK   |           |                |          |                           |           |              | Service ATA:27   |
|                                                                            | MOS/MSC                                                                      | 02-May-21 | -              | Adj -9d  |                           |           |              |                  |
|                                                                            | HRS                                                                          | 115:30    |                |          |                           |           |              |                  |
|                                                                            | AFL                                                                          | 57        |                |          |                           |           |              |                  |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02                             |                                                                              |           |                |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|----------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |              |                                                    |                |          |                           |           |           |                  |
| 27-31-02-002                                                               | <sup>S</sup> | DETAILED INSPECTION OF ELEVATOR CONTROL CABLES     |                |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS          | 31-Mar-25                                          | 60 (+1m/-1m)   |          |                           |           |           |                  |
|                                                                            | HRS          | 987:24                                             | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 456                                                |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02                             |              |                                                    |                |          |                           |           |           | PKG:42           |
| 27-31-03                                                                   |              | LEFT HAND ELEVATOR ASSEMBLY                        |                |          |                           |           |           | Component ATA:27 |
| PN:505-11083-403                                                           | MOS/MSC      | 31-Mar-25                                          | O/C            |          |                           |           |           |                  |
| SN:0001057103                                                              | HRS          | 987:24                                             |                |          |                           |           |           |                  |
|                                                                            | AFL          | 456                                                |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-31-03, AMM 27-31-03PROC. REF: AMM 27-31-03, AMM 27-31-03 |              |                                                    |                |          |                           |           |           |                  |
| 27-31-03                                                                   |              | RIGHT HAND ELEVATOR ASSEMBLY                       |                |          |                           |           |           | Component ATA:27 |
| PN:505-11083-404                                                           | MOS/MSC      | 31-Mar-25                                          | O/C            |          |                           |           |           |                  |
| SN:0001057105                                                              | HRS          | 987:24                                             |                |          |                           |           |           |                  |
|                                                                            | AFL          | 456                                                |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-31-03, AMM 27-31-03PROC. REF: AMM 27-31-03, AMM 27-31-03 |              |                                                    |                |          |                           |           |           |                  |
| 27-31-03-001                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH    |                |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS          | 23-Apr-20                                          |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                                  | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                  |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03                             |              |                                                    |                |          |                           |           |           | PKG:50           |
| 27-31-03-002                                                               | <sup>S</sup> | DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM |                |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS          | 23-Apr-20                                          |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                                  | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                  |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03                             |              |                                                    |                |          |                           |           |           | PKG:50           |
| 27-31-05                                                                   |              | MID CONTROL PANEL                                  |                |          |                           |           |           | Component ATA:27 |
| PN:441-44280-001                                                           | MOS/MSC      | 23-Apr-20                                          | O/C            | TSN 0    |                           |           |           |                  |
| SN:1353                                                                    | HRS          | 0                                                  |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                  |                | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                               | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------|----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 27 - FLIGHT CONTROLS                                                   |              |                                                   |                |          |                           |           |               |                |
| PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05 |              |                                                   |                |          |                           |           |               |                |
| 27-36-03-001                                                               | <sup>S</sup> | OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH         |                |          |                           |           |               | Service ATA:27 |
|                                                                            | MOS          | 23-Apr-20                                         |                |          |                           |           |               |                |
|                                                                            | HRS          | 0                                                 | 1600 (+30/-30) |          |                           |           |               |                |
|                                                                            | AFL          | 0                                                 |                |          |                           |           |               |                |
| PROC. REF: AMM 27-36-03PROC. REF: AMM 27-36-03                             |              |                                                   |                |          |                           |           |               | PKG:10         |
| 27-41-01-001                                                               |              | DETAILED INSPECTION OF PITCH TRIM ACTUATOR        |                |          |                           |           |               | Service ATA:27 |
|                                                                            | MOS          | 23-Apr-20                                         |                |          |                           |           |               | AIRWORTHINESS  |
|                                                                            | HRS          | 0                                                 | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                |
|                                                                            | AFL          | 0                                                 |                |          |                           |           |               |                |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01                             |              |                                                   |                |          |                           |           |               |                |
| 27-41-01-002                                                               |              | FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH  |                |          |                           |           |               | Service ATA:27 |
|                                                                            | MOS          | 23-Apr-20                                         |                |          |                           |           |               | AIRWORTHINESS  |
|                                                                            | HRS          | 0                                                 | 6000 (+30/-30) |          | 6000                      | 6030      | 4704:36 (+30) |                |
|                                                                            | AFL          | 0                                                 |                |          |                           |           |               |                |
| PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00                             |              |                                                   |                |          |                           |           |               |                |
| 27-41-01-003                                                               | <sup>S</sup> | LUBRICATION OF PITCH TRIM ACTUATOR                |                |          |                           |           |               | Service ATA:27 |
|                                                                            | MOS          | 19-Mar-24                                         | 48 (+1m/-1m)   |          |                           |           |               |                |
|                                                                            | HRS          | 781:30                                            |                |          |                           |           |               |                |
|                                                                            | AFL          | 364                                               |                |          |                           |           |               |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00                             |              |                                                   |                |          |                           |           |               | PKG:83         |
| 27-41-01-004                                                               |              | OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK |                |          |                           |           |               | Service ATA:27 |
|                                                                            | MOS          | 23-Apr-20                                         |                |          |                           |           |               | AIRWORTHINESS  |
|                                                                            | HRS          | 0                                                 | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                |
|                                                                            | AFL          | 0                                                 |                |          |                           |           |               |                |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01                             |              |                                                   |                |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                        | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|--------------------------------------------------------------|--------------|----------------------------------------------------------------------------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                     |              |                                                                            |                |          |                           |           |               |                  |
| 27-41-01-005                                                 | <sup>S</sup> | SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES                                |                |          |                           |           |               | Service ATA:27   |
|                                                              | MOS          | 19-Mar-24                                                                  | 48 (+1m/-1m)   |          |                           |           |               |                  |
|                                                              | HRS          | 781:30                                                                     |                |          |                           |           |               |                  |
|                                                              | AFL          | 364                                                                        |                |          |                           |           |               |                  |
| PROC. REF: AMM 12-18-00PROC. REF: AMM 12-18-00               |              |                                                                            |                |          |                           |           |               | PKG:83           |
| 27-41-01-006                                                 | <sup>S</sup> | FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP                    |                |          |                           |           |               | Service ATA:27   |
|                                                              | MOS          | 23-Apr-20                                                                  |                |          |                           |           |               |                  |
|                                                              | HRS          | 0                                                                          | 5600 (+30/-30) |          |                           |           |               |                  |
|                                                              | AFL          | 0                                                                          |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01               |              |                                                                            |                |          |                           |           |               | PKG:50           |
| 27-43-02                                                     |              | COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL                                  |                |          |                           |           |               | Component ATA:27 |
| PN:441-44422-001                                             | MOS/MSC      | 23-Apr-20                                                                  | O/C            | TSN 0    |                           |           |               |                  |
| SN:1430                                                      | HRS          | 0                                                                          |                | TSN 0    |                           |           |               |                  |
|                                                              | AFL          | 0                                                                          |                | TSN 0    |                           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |              |                                                                            |                |          |                           |           |               |                  |
| 27-50-01-01-901                                              |              | DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL |                |          |                           |           |               | Service ATA:27   |
|                                                              | MOS          | 23-Apr-20                                                                  |                |          |                           |           | AIRWORTHINESS |                  |
|                                                              | HRS          | 0                                                                          | T:17500        |          | 17500                     |           | 16204:36      |                  |
|                                                              | AFL          | 0                                                                          | T:14000        |          | 14000                     |           | 13402         |                  |
| PROC. REF: NDT PART 5 27-51-00PROC. REF: NDT PART 5 27-51-00 |              |                                                                            |                |          |                           |           |               |                  |
| 27-51-01-001                                                 | <sup>S</sup> | LUBRICATION OF FLAP ACTUATORS BALL SCREWS                                  |                |          |                           |           |               | Service ATA:27   |
|                                                              | MOS          | 19-Mar-24                                                                  | 48 (+1m/-1m)   |          |                           |           |               |                  |
|                                                              | HRS          | 781:30                                                                     |                |          |                           |           |               |                  |
|                                                              | AFL          | 364                                                                        |                |          |                           |           |               |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00               |              |                                                                            |                |          |                           |           |               | PKG:83           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|------------------------------------------------|--------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 27 - FLIGHT CONTROLS                       |                                                        |           |                |          |                           |           |               |                |
| 27-51-01-002                                   | DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR   |           |                |          |                           |           |               | Service ATA:27 |
|                                                | MOS                                                    | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                |
|                                                | AFL                                                    | 0         |                |          |                           |           |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01 |                                                        |           |                |          |                           |           |               |                |
| 27-51-01-002                                   | DETAILED INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR  |           |                |          |                           |           |               | Service ATA:27 |
|                                                | MOS                                                    | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                |
|                                                | AFL                                                    | 0         |                |          |                           |           |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01 |                                                        |           |                |          |                           |           |               |                |
| 27-51-01-002                                   | DETAILED INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR  |           |                |          |                           |           |               | Service ATA:27 |
|                                                | MOS                                                    | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                |
|                                                | AFL                                                    | 0         |                |          |                           |           |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01 |                                                        |           |                |          |                           |           |               |                |
| 27-51-01-002                                   | DETAILED INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR  |           |                |          |                           |           |               | Service ATA:27 |
|                                                | MOS                                                    | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                |
|                                                | AFL                                                    | 0         |                |          |                           |           |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01 |                                                        |           |                |          |                           |           |               |                |
| 27-51-01-002                                   | DETAILED INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR |           |                |          |                           |           |               | Service ATA:27 |
|                                                | MOS                                                    | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                |
|                                                | AFL                                                    | 0         |                |          |                           |           |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01 |                                                        |           |                |          |                           |           |               |                |
| 27-51-01-002                                   | DETAILED INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR |           |                |          |                           |           |               | Service ATA:27 |
|                                                | MOS                                                    | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS                                                    | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                |
|                                                | AFL                                                    | 0         |                |          |                           |           |               |                |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01 |                                                        |           |                |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                             | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                  |           |                |          |                           |           |               |                  |
| 27-51-01-004                                                               | FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                              | 23-Apr-20 |                |          |                           |           |               | AIRWORTHINESS    |
|                                                                            | HRS                                              | 0         | 7200 (+30/-30) |          | 7200                      | 7230      | 5904:36 (+30) |                  |
|                                                                            | AFL                                              | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01                             |                                                  |           |                |          |                           |           |               |                  |
| 27-51-01-005 <sup>S</sup>                                                  | SERVICING OF FLAP ACTUATOR GEAR BOXES            |           |                |          |                           |           |               | Service ATA:27   |
|                                                                            | MOS                                              | 19-Mar-24 | 48 (+1m/-1m)   |          |                           |           |               |                  |
|                                                                            | HRS                                              | 781:30    |                |          |                           |           |               |                  |
|                                                                            | AFL                                              | 364       |                |          |                           |           |               |                  |
| PKG:83                                                                     |                                                  |           |                |          |                           |           |               |                  |
| PROC. REF: AMM 12-18-00PROC. REF: AMM 12-18-00                             |                                                  |           |                |          |                           |           |               |                  |
| 27-51-01-900-801-01                                                        | LEFT NO. 3 OUTBOARD FLAP ACTUATOR                |           |                |          |                           |           |               | Component ATA:27 |
| PN:475100-1013                                                             | MOS/MSC                                          | 23-Apr-20 | H/T            | TSN 0    |                           |           |               |                  |
| SN:1210                                                                    | HRS                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                                  |           |                |          |                           |           |               |                  |
| 27-51-01-900-801-02                                                        | RIGHT NO. 3 OUTBOARD FLAP ACTUATOR               |           |                |          |                           |           |               | Component ATA:27 |
| PN:475100-1013                                                             | MOS/MSC                                          | 23-Apr-20 | H/T            | TSN 0    |                           |           |               |                  |
| SN:1216                                                                    | HRS                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                                  |           |                |          |                           |           |               |                  |
| 27-51-01-900-801-03                                                        | LEFT NO. 2 OUTBOARD FLAP ACTUATOR                |           |                |          |                           |           |               | Component ATA:27 |
| PN:475000-2013                                                             | MOS/MSC                                          | 23-Apr-20 | H/T            | TSN 0    |                           |           |               |                  |
| SN:2425                                                                    | HRS                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                                  |           |                |          |                           |           |               |                  |
| 27-51-01-900-801-04                                                        | RIGHT NO. 2 OUTBOARD FLAP ACTUATOR               |           |                |          |                           |           |               | Component ATA:27 |
| PN:475000-2013                                                             | MOS/MSC                                          | 23-Apr-20 | H/T            | TSN 0    |                           |           |               |                  |
| SN:2426                                                                    | HRS                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01 |                                                  |           |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit    | C/W                               | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------------------------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 27 - FLIGHT CONTROLS                                                                                                           |         |                                   |          |          |                           |           |           |             |
| 27-51-01-900-801-05                                                                                                                |         | LEFT NO. 1 INBOARD FLAP ACTUATOR  |          |          |                           |           | Component | ATA:27      |
| PN:475000-1013                                                                                                                     | MOS/MSC | 23-Apr-20                         | H/T      | TSN 0    |                           |           |           |             |
| SN:2432                                                                                                                            | HRS     | 0                                 |          | TSN 0    |                           |           |           |             |
|                                                                                                                                    | AFL     | 0                                 |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                   |          |          |                           |           |           |             |
| 27-51-01-900-801-06                                                                                                                |         | RIGHT NO. 1 INBOARD FLAP ACTUATOR |          |          |                           |           | Component | ATA:27      |
| PN:475000-1013                                                                                                                     | MOS/MSC | 23-Apr-20                         | H/T      | TSN 0    |                           |           |           |             |
| SN:2430                                                                                                                            | HRS     | 0                                 |          | TSN 0    |                           |           |           |             |
|                                                                                                                                    | AFL     | 0                                 |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01                                                         |         |                                   |          |          |                           |           |           |             |
| 27-51-05                                                                                                                           |         | LEFT INBOARD FLAP                 |          |          |                           |           | Component | ATA:27      |
| PN:505-14358-405                                                                                                                   | MOS/MSC | 23-Apr-20                         | O/C      | TSN 0    |                           |           |           |             |
| SN:0001072637                                                                                                                      | HRS     | 0                                 |          | TSN 0    |                           |           |           |             |
|                                                                                                                                    | AFL     | 0                                 |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |         |                                   |          |          |                           |           |           |             |
| 27-51-05                                                                                                                           |         | LEFT OUTBOARD FLAP                |          |          |                           |           | Component | ATA:27      |
| PN:505-14349-405                                                                                                                   | MOS/MSC | 23-Apr-20                         | O/C      | TSN 0    |                           |           |           |             |
| SN:0001061926                                                                                                                      | HRS     | 0                                 |          | TSN 0    |                           |           |           |             |
|                                                                                                                                    | AFL     | 0                                 |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |         |                                   |          |          |                           |           |           |             |
| 27-51-05                                                                                                                           |         | RIGHT INBOARD FLAP                |          |          |                           |           | Component | ATA:27      |
| PN:505-14358-406                                                                                                                   | MOS/MSC | 23-Apr-20                         | O/C      | TSN 0    |                           |           |           |             |
| SN:0001066746                                                                                                                      | HRS     | 0                                 |          | TSN 0    |                           |           |           |             |
|                                                                                                                                    | AFL     | 0                                 |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |         |                                   |          |          |                           |           |           |             |
| 27-51-05                                                                                                                           |         | RIGHT OUTBOARD FLAP               |          |          |                           |           | Component | ATA:27      |
| PN:505-14349-406                                                                                                                   | MOS/MSC | 23-Apr-20                         | O/C      | TSN 0    |                           |           |           |             |
| SN:0001065571                                                                                                                      | HRS     | 0                                 |          | TSN 0    |                           |           |           |             |
|                                                                                                                                    | AFL     | 0                                 |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05 |         |                                   |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                           | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|-----------------------------------------------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 27 - FLIGHT CONTROLS                       |              |                                               |              |          |                           |           |           |                |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT   |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                     | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                        |              |          |                           |           |           |                |
|                                                | AFL          | 364                                           |              |          |                           |           |           |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                               |              |          |                           |           |           | PKG:83         |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                     | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                        |              |          |                           |           |           |                |
|                                                | AFL          | 364                                           |              |          |                           |           |           |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                               |              |          |                           |           |           | PKG:83         |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT    |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                     | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                        |              |          |                           |           |           |                |
|                                                | AFL          | 364                                           |              |          |                           |           |           |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                               |              |          |                           |           |           | PKG:83         |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT    |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                     | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                        |              |          |                           |           |           |                |
|                                                | AFL          | 364                                           |              |          |                           |           |           |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                               |              |          |                           |           |           | PKG:83         |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT  |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                     | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                        |              |          |                           |           |           |                |
|                                                | AFL          | 364                                           |              |          |                           |           |           |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                               |              |          |                           |           |           | PKG:83         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                          | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------|--------------------------------------------------------------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 27 - FLIGHT CONTROLS                       |              |                                                              |              |          |                           |           |           |                |
| 27-51-06-001                                   | <sup>S</sup> | LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT               |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                                    | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                                       |              |          |                           |           |           |                |
|                                                | AFL          | 364                                                          |              |          |                           |           |           |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                                              |              |          |                           |           |           | PKG:83         |
| 27-51-06-002                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT   |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                                    | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                                       |              |          |                           |           |           |                |
|                                                | AFL          | 364                                                          |              |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06 |              |                                                              |              |          |                           |           |           | PKG:83         |
| 27-51-06-002                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                                    | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                                       |              |          |                           |           |           |                |
|                                                | AFL          | 364                                                          |              |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06 |              |                                                              |              |          |                           |           |           | PKG:83         |
| 27-51-06-002                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT    |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                                    | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                                       |              |          |                           |           |           |                |
|                                                | AFL          | 364                                                          |              |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06 |              |                                                              |              |          |                           |           |           | PKG:83         |
| 27-51-06-002                                   | <sup>S</sup> | DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT    |              |          |                           |           |           | Service ATA:27 |
|                                                | MOS          | 19-Mar-24                                                    | 48 (+1m/-1m) |          |                           |           |           |                |
|                                                | HRS          | 781:30                                                       |              |          |                           |           |           |                |
|                                                | AFL          | 364                                                          |              |          |                           |           |           |                |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06 |              |                                                              |              |          |                           |           |           | PKG:83         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                           | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |         |                                                               |              |          |                           |           |           |                  |
| 27-51-06-002 <sup>S</sup>                                                  |         | DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT   |              |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS     | 19-Mar-24                                                     | 48 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS     | 781:30                                                        |              |          |                           |           |           |                  |
|                                                                            | AFL     | 364                                                           |              |          |                           |           |           |                  |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06                             |         |                                                               |              |          |                           |           |           | PKG:83           |
| 27-51-06-002 <sup>S</sup>                                                  |         | DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT |              |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS     | 19-Mar-24                                                     | 48 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS     | 781:30                                                        |              |          |                           |           |           |                  |
|                                                                            | AFL     | 364                                                           |              |          |                           |           |           |                  |
| PROC. REF: AMM 27-51-06PROC. REF: AMM 27-51-06                             |         |                                                               |              |          |                           |           |           | PKG:83           |
| 27-51-06-900-801-01                                                        |         | RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT                          |              |          |                           |           |           | Component ATA:27 |
| PN:457360-1005                                                             | MOS/MSC | 23-Apr-20                                                     | H/T          | TSN 0    |                           |           |           |                  |
| SN:SSW2336                                                                 | HRS     | 0                                                             |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                             |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |         |                                                               |              |          |                           |           |           |                  |
| 27-51-06-900-801-02                                                        |         | RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT                           |              |          |                           |           |           | Component ATA:27 |
| PN:457360-1005                                                             | MOS/MSC | 19-Mar-24                                                     | H/T          | TSN 0    |                           |           |           |                  |
| SN:SSW3541                                                                 | HRS     | 781:30                                                        |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 364                                                           |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |         |                                                               |              |          |                           |           |           |                  |
| 27-51-06-900-801-03                                                        |         | LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT                           |              |          |                           |           |           | Component ATA:27 |
| PN:457360-1005                                                             | MOS/MSC | 23-Apr-20                                                     | H/T          | TSN 0    |                           |           |           |                  |
| SN:SSW2329                                                                 | HRS     | 0                                                             |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                             |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |         |                                                               |              |          |                           |           |           |                  |
| 27-51-06-900-801-04                                                        |         | LEFT INBOARD FLAP FLEXIBLE 1 SHAFT                            |              |          |                           |           |           | Component ATA:27 |
| PN:457360-1005                                                             | MOS/MSC | 19-Mar-24                                                     | H/T          | TSN 0    |                           |           |           |                  |
| SN:SSW3513                                                                 | HRS     | 781:30                                                        |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 364                                                           |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |         |                                                               |              |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                                                                       |           |          |          |                           |           |           |                  |
| 27-51-06-900-801-05                                                        | LEFT CENTER FLAP FLEXIBLE 2 SHAFT                                                                                     |           |          |          |                           |           |           | Component ATA:27 |
| PN:457360-1007                                                             | MOS/MSC                                                                                                               | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                  |
| SN:SSW1147                                                                 | HRS                                                                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                                                                                                       |           |          |          |                           |           |           |                  |
| 27-51-06-900-801-06                                                        | RIGHT CENTER FLAP FLEXIBLE 2 SHAFT                                                                                    |           |          |          |                           |           |           | Component ATA:27 |
| PN:457360-1007                                                             | MOS/MSC                                                                                                               | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                  |
| SN:SSW1167                                                                 | HRS                                                                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-51-06, AMM 27-51-06PROC. REF: AMM 27-51-06, AMM 27-51-06 |                                                                                                                       |           |          |          |                           |           |           |                  |
| 27-53-01                                                                   | FLAP SELECTOR, PRODUCTION, LEVER                                                                                      |           |          |          |                           |           |           | Component ATA:27 |
| PN:780501-9                                                                | MOS/MSC                                                                                                               | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1972                                                                    | HRS                                                                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-53-01, AMM 27-53-01PROC. REF: AMM 27-53-01, AMM 27-53-01 |                                                                                                                       |           |          |          |                           |           |           |                  |
| 27-64-01-01-901                                                            | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS-INTERNAL |           |          |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                                            | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                  |
|                                                                            | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 6 27-64-00PROC. REF: NDT PART 6 27-64-00               |                                                                                                                       |           |          |          |                           |           |           |                  |
| 27-64-01-01-902                                                            | DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL               |           |          |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                                            | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                  |
|                                                                            | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 27-64-00PROC. REF: NDT PART 5 27-64-00               |                                                                                                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                                                                                                |           |                |          |                           |           |           |                  |
| 27-64-01-02-901                                                            | SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL |           |                |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS                                                                                                                            | 23-Apr-20 |                |          |                           |           |           | AIRWORTHINESS    |
|                                                                            | HRS                                                                                                                            | 0         | T:17500        |          | 17500                     |           | 16204:36  |                  |
|                                                                            | AFL                                                                                                                            | 0         | T:14000        |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 7 27-64-00PROC. REF: NDT PART 7 27-64-00               |                                                                                                                                |           |                |          |                           |           |           |                  |
| 27-65-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM                                                                               |           |                |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS                                                                                                                            | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                                            | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                                            | 0         |                |          |                           |           |           |                  |
| PKG:60                                                                     |                                                                                                                                |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00                             |                                                                                                                                |           |                |          |                           |           |           |                  |
| 27-65-01-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)                                                    |           |                |          |                           |           |           | Service ATA:27   |
|                                                                            | MOS                                                                                                                            | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                                            | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                                            | 0         |                |          |                           |           |           |                  |
| PKG:60                                                                     |                                                                                                                                |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 27-65-00PROC. REF: AMM 27-65-00                             |                                                                                                                                |           |                |          |                           |           |           |                  |
| 27-66-01                                                                   | NO. 1 CONTROL WHEEL POSITION SENSOR                                                                                            |           |                |          |                           |           |           | Component ATA:27 |
| PN:456896-1001                                                             | MOS/MSC                                                                                                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:387082                                                                  | HRS                                                                                                                            | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                                            | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-66-01, AMM 27-66-01PROC. REF: AMM 27-66-01, AMM 27-66-01 |                                                                                                                                |           |                |          |                           |           |           |                  |
| 27-66-01                                                                   | NO. 2 CONTROL WHEEL POSITION SENSOR                                                                                            |           |                |          |                           |           |           | Component ATA:27 |
| PN:456896-1001                                                             | MOS/MSC                                                                                                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:387084                                                                  | HRS                                                                                                                            | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                                            | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-66-01, AMM 27-66-01PROC. REF: AMM 27-66-01, AMM 27-66-01 |                                                                                                                                |           |                |          |                           |           |           |                  |
| 27-66-02                                                                   | LEFT SPOILER SURFACE POSITION SENSOR                                                                                           |           |                |          |                           |           |           | Component ATA:27 |
| PN:456897-1001                                                             | MOS/MSC                                                                                                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:405299                                                                  | HRS                                                                                                                            | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                                            | 0         |                | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                              | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS                                                   |                                                   |           |              |          |                           |           |           |                  |
| PROC. REF: AMM 27-66-02, AMM 27-66-02PROC. REF: AMM 27-66-02, AMM 27-66-02 |                                                   |           |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |
| 27-66-02                                                                   | RIGHT SPOILER SURFACE POSITION SENSOR             |           |              |          |                           |           |           | Component ATA:27 |
| PN:456897-1001                                                             | MOS/MSC                                           | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:405300                                                                  | HRS                                               | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 27-66-02, AMM 27-66-02PROC. REF: AMM 27-66-02, AMM 27-66-02 |                                                   |           |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |
| ATA 28 - FUEL                                                              |                                                   |           |              |          |                           |           |           |                  |
| 28-11-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS |           |              |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS                                               | 13-Mar-26 | 12 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                               | 1221:24   |              |          |                           |           |           |                  |
|                                                                            | AFL                                               | 564       |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |
| PKG:80                                                                     |                                                   |           |              |          |                           |           |           |                  |
| PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00                             |                                                   |           |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |
| 28-11-01                                                                   | LH WING ASSEMBLY - EQUIPED                        |           |              |          |                           |           |           | Component ATA:28 |
| PN:505-11984-405                                                           | MOS/MSC                                           | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:0001063275                                                              | HRS                                               | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                   |           |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |
| 28-11-03                                                                   | LEFT WING HALF ASSEMBLY                           |           |              |          |                           |           |           | Component ATA:28 |
| PN:505-12200-439                                                           | MOS/MSC                                           | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:0001055762                                                              | HRS                                               | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                   |           |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |
| 28-11-03                                                                   | RIGHT WING HALF ASSEMBLY                          |           |              |          |                           |           |           | Component ATA:28 |
| PN:505-12200-440                                                           | MOS/MSC                                           | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:0001056769                                                              | HRS                                               | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                   |           |              |          |                           |           |           |                  |
|                                                                            |                                                   |           |              |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                                  | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|----------------------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |              |                                                                      |                |          |                           |           |           |                  |
| 28-11-03-001                                                               | <sup>S</sup> | FUNCTIONAL CHECK (TORQUE) OF WING TANK SPAR 1 COVERS ATTACHING BOLTS |                |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS          | 23-Apr-20                                                            | 60 (+1m/-1m)   |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                                                    | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                    |                |          |                           |           |           |                  |
| PROC. REF: AMM 28-11-03PROC. REF: AMM 28-11-03                             |              |                                                                      |                |          |                           |           |           | PKG:42           |
| 28-11-05                                                                   |              | LEFT WING WATER DRAIN VALVE                                          |                |          |                           |           |           | Component ATA:28 |
| PN:L83A13-628                                                              | MOS/MSC      | 23-Apr-20                                                            | O/C            | TSN 0    |                           |           |           |                  |
| SN:M29895                                                                  | HRS          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05 |              |                                                                      |                |          |                           |           |           |                  |
| 28-11-05                                                                   |              | RIGHT WING WATER DRAIN VALVE                                         |                |          |                           |           |           | Component ATA:28 |
| PN:L83A13-628                                                              | MOS/MSC      | 23-Apr-20                                                            | O/C            | TSN 0    |                           |           |           |                  |
| SN:M37649                                                                  | HRS          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05 |              |                                                                      |                |          |                           |           |           |                  |
| 28-11-07                                                                   |              | LEFT WING DUMP VALVE                                                 |                |          |                           |           |           | Component ATA:28 |
| PN:V98A32-001                                                              | MOS/MSC      | 23-Apr-20                                                            | O/C            | TSN 0    |                           |           |           |                  |
| SN:M29419                                                                  | HRS          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-11-07, AMM 28-11-07PROC. REF: AMM 28-11-07, AMM 28-11-07 |              |                                                                      |                |          |                           |           |           |                  |
| 28-11-07                                                                   |              | RIGHT WING DUMP VALVE                                                |                |          |                           |           |           | Component ATA:28 |
| PN:V98A32-001                                                              | MOS/MSC      | 23-Apr-20                                                            | O/C            | TSN 0    |                           |           |           |                  |
| SN:M29418                                                                  | HRS          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-11-07, AMM 28-11-07PROC. REF: AMM 28-11-07, AMM 28-11-07 |              |                                                                      |                |          |                           |           |           |                  |
| 28-11-09                                                                   |              | RIGHT WING JUNCTION                                                  |                |          |                           |           |           | Component ATA:28 |
| PN:505-12066-401                                                           | MOS/MSC      | 23-Apr-20                                                            | O/C            | TSN 0    |                           |           |           |                  |
| SN:0001056931                                                              | HRS          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                    |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |              |                                                                      |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                    | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|--------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |              |                                                        |                |          |                           |           |           |                  |
| 28-12-01-001                                                               | <sup>S</sup> | SPECIAL DETAILED INSPECTION OF FUEL VENT NACA          |                |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS          | 19-Mar-24                                              |                |          |                           |           |           |                  |
|                                                                            | HRS          | 781:30                                                 | 800 (+30/-30)  |          |                           |           |           |                  |
|                                                                            | AFL          | 364                                                    |                |          |                           |           |           |                  |
| PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01                             |              |                                                        |                |          |                           |           |           | PKG:1            |
| 28-12-03                                                                   |              | LEFT FUEL TANK FLOAT VENT VALVE                        |                |          |                           |           |           | Component ATA:28 |
| PN:L87-19-001P2                                                            | MOS/MSC      | 23-Apr-20                                              | O/C            | TSN 0    |                           |           |           |                  |
| SN:M31231                                                                  | HRS          | 0                                                      |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                      |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-12-03, AMM 28-12-03PROC. REF: AMM 28-12-03, AMM 28-12-03 |              |                                                        |                |          |                           |           |           |                  |
| 28-12-03                                                                   |              | RIGHT FUEL TANK FLOAT VENT VALVE                       |                |          |                           |           |           | Component ATA:28 |
| PN:L87-19-001P2                                                            | MOS/MSC      | 23-Apr-20                                              | O/C            | TSN 0    |                           |           |           |                  |
| SN:M31217                                                                  | HRS          | 0                                                      |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                      |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-12-03, AMM 28-12-03PROC. REF: AMM 28-12-03, AMM 28-12-03 |              |                                                        |                |          |                           |           |           |                  |
| 28-12-03-001                                                               | <sup>S</sup> | OPERATIONAL CHECK LEFT FLOAT VENT VALVE                |                |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS          | 23-Apr-20                                              |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                                      | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                      |                |          |                           |           |           |                  |
| PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03                             |              |                                                        |                |          |                           |           |           | PKG:60           |
| 28-12-03-001                                                               | <sup>S</sup> | OPERATIONAL CHECK RIGHT FLOAT VENT VALVE               |                |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS          | 23-Apr-20                                              |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                                      | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                      |                |          |                           |           |           |                  |
| PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03                             |              |                                                        |                |          |                           |           |           | PKG:60           |
| 28-21-01                                                                   |              | LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE |                |          |                           |           |           | Component ATA:28 |
| PN:L96-19-007P4                                                            | MOS/MSC      | 23-Apr-20                                              | O/C            | TSN 0    |                           |           |           |                  |
| SN:M27671                                                                  | HRS          | 0                                                      |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                      |                | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01 |         |           |          |          |                           |           |           |                  |
| 28-21-01 RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE           |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:L96-19-007P4                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:M27190                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01 |         |           |          |          |                           |           |           |                  |
| 28-21-02 RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE                      |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:P99C25-606P2                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L38541                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |         |           |          |          |                           |           |           |                  |
| 28-21-03 LEFT WING DC AUXILIARY BOOST PUMP CANISTER                        |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:C93R25-606P2                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L49368                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |         |           |          |          |                           |           |           |                  |
| 28-21-03 RIGHT WING DC AUXILIARY BOOST PUMP CANISTER                       |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:C93R25-606P2                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L49363                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03 |         |           |          |          |                           |           |           |                  |
| 28-21-05 LEFT WING JET PUMP FEED LINE                                      |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:T99A19-602                                                              | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L44415                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-05, AMM 28-21-05PROC. REF: AMM 28-21-05, AMM 28-21-05 |         |           |          |          |                           |           |           |                  |
| 28-21-05 RIGHT WING JET PUMP FEED LINE                                     |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:T99A19-602                                                              | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L44412                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W       | Interval      | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|---------|-----------|---------------|-----------|---------------------------|-----------|--------------|------------------|
| ATA 28 - FUEL                                                              |         |           |               |           |                           |           |              |                  |
| PROC. REF: AMM 28-21-05, AMM 28-21-05PROC. REF: AMM 28-21-05, AMM 28-21-05 |         |           |               |           |                           |           |              |                  |
|                                                                            |         |           |               |           |                           |           |              |                  |
| 28-21-07 LEFT 0.75 SHUTOFF VALVE                                           |         |           |               |           |                           |           |              | Component ATA:28 |
| PN:B97-15-601                                                              | MOS/MSC | 23-Apr-20 | O/C           | TSN 0     |                           |           |              |                  |
| SN:M29665                                                                  | HRS     | 0         |               | TSN 0     |                           |           |              |                  |
|                                                                            | AFL     | 0         |               | TSN 0     |                           |           |              |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |         |           |               |           |                           |           |              |                  |
|                                                                            |         |           |               |           |                           |           |              |                  |
| 28-21-07 RIGHT 0.75 SHUTOFF VALVE                                          |         |           |               |           |                           |           |              | Component ATA:28 |
| PN:B97-15-601                                                              | MOS/MSC | 23-Apr-20 | O/C           | TSN 0     |                           |           |              |                  |
| SN:M29661                                                                  | HRS     | 0         |               | TSN 0     |                           |           |              |                  |
|                                                                            | AFL     | 0         |               | TSN 0     |                           |           |              |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |         |           |               |           |                           |           |              |                  |
|                                                                            |         |           |               |           |                           |           |              |                  |
| 28-21-07-001 OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM                 |         |           |               |           |                           |           |              | Service ATA:28   |
|                                                                            | MOS     | 19-Mar-24 |               |           |                           |           |              | AIRWORTHINESS    |
|                                                                            | HRS     | 781:30    | 800 (+30/-30) | Adj 18:30 | 1600                      | 1630      | 304:36 (+30) |                  |
|                                                                            | AFL     | 364       |               |           |                           |           |              |                  |
| PROC. REF: AMM 28-21-07PROC. REF: AMM 28-21-07                             |         |           |               |           |                           |           |              |                  |
|                                                                            |         |           |               |           |                           |           |              |                  |
| 28-21-07-001 OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM                |         |           |               |           |                           |           |              | Service ATA:28   |
|                                                                            | MOS     | 19-Mar-24 |               |           |                           |           |              | AIRWORTHINESS    |
|                                                                            | HRS     | 781:30    | 800 (+30/-30) | Adj 18:30 | 1600                      | 1630      | 304:36 (+30) |                  |
|                                                                            | AFL     | 364       |               |           |                           |           |              |                  |
| PROC. REF: AMM 28-21-07PROC. REF: AMM 28-21-07                             |         |           |               |           |                           |           |              |                  |
|                                                                            |         |           |               |           |                           |           |              |                  |
| 28-21-08 FORWARD LEFT 28 VDC SOV ACTUATOR                                  |         |           |               |           |                           |           |              | Component ATA:28 |
| PN:D97C00-644P2                                                            | MOS/MSC | 23-Apr-20 | O/C           | TSN 0     |                           |           |              |                  |
| SN:C703131                                                                 | HRS     | 0         |               | TSN 0     |                           |           |              |                  |
|                                                                            | AFL     | 0         |               | TSN 0     |                           |           |              |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |         |           |               |           |                           |           |              |                  |
|                                                                            |         |           |               |           |                           |           |              |                  |
| 28-21-08 LEFT WING 28 VDC SOV ACTUATOR                                     |         |           |               |           |                           |           |              | Component ATA:28 |
| PN:D97C00-644P2                                                            | MOS/MSC | 23-Apr-20 | O/C           | TSN 0     |                           |           |              |                  |
| SN:C703122                                                                 | HRS     | 0         |               | TSN 0     |                           |           |              |                  |
|                                                                            | AFL     | 0         |               | TSN 0     |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                  | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------|-----------|-----------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 28 - FUEL                                                              |                                       |           |                 |          |                           |           |                |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                       |           |                 |          |                           |           |                |                  |
|                                                                            |                                       |           |                 |          |                           |           |                |                  |
| 28-21-08                                                                   | REAR RIGHT 28 VDC SOV ACTUATOR        |           |                 |          |                           |           |                | Component ATA:28 |
| PN:D97C00-644P2                                                            | MOS/MSC                               | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:C703117                                                                 | HRS                                   | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07 |                                       |           |                 |          |                           |           |                |                  |
|                                                                            |                                       |           |                 |          |                           |           |                |                  |
| 28-21-09                                                                   | LEFT WING SCAVENGER JET PUMP          |           |                 |          |                           |           |                | Component ATA:28 |
| PN:T99A19-603                                                              | MOS/MSC                               | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:L42734                                                                  | HRS                                   | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 28-21-09, AMM 28-21-09PROC. REF: AMM 28-21-09, AMM 28-21-09 |                                       |           |                 |          |                           |           |                |                  |
|                                                                            |                                       |           |                 |          |                           |           |                |                  |
| 28-21-09                                                                   | RIGHT WING SCAVENGER JET PUMP         |           |                 |          |                           |           |                | Component ATA:28 |
| PN:T99A19-603                                                              | MOS/MSC                               | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:L40077                                                                  | HRS                                   | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 28-21-09, AMM 28-21-09PROC. REF: AMM 28-21-09, AMM 28-21-09 |                                       |           |                 |          |                           |           |                |                  |
|                                                                            |                                       |           |                 |          |                           |           |                |                  |
| 28-21-10                                                                   | 3/4" (CROSSFEED) SHUT OFF VALVE       |           |                 |          |                           |           |                | Component ATA:28 |
| PN:B97H19-608P2                                                            | MOS/MSC                               | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:L42542                                                                  | HRS                                   | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 28-21-10, AMM 28-21-10PROC. REF: AMM 28-21-10, AMM 28-21-10 |                                       |           |                 |          |                           |           |                |                  |
|                                                                            |                                       |           |                 |          |                           |           |                |                  |
| 28-21-10-001                                                               | OPERATIONAL CHECK OF FUEL XFEED VALVE |           |                 |          |                           |           |                | Service ATA:28   |
|                                                                            | MOS                                   | 23-Apr-20 |                 |          |                           |           |                |                  |
|                                                                            | HRS                                   | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                  |
|                                                                            | AFL                                   | 0         |                 |          |                           |           |                |                  |
| PROC. REF: AMM 28-21-10PROC. REF: AMM 28-21-10                             |                                       |           |                 |          |                           |           |                |                  |
|                                                                            |                                       |           |                 |          |                           |           |                |                  |
| 28-21-11                                                                   | LEFT WING 1/2 INCH CHECK VALVE VALVE  |           |                 |          |                           |           |                | Component ATA:28 |
| PN:L96-13-001                                                              | MOS/MSC                               | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:M33061                                                                  | HRS                                   | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                   | 0         |                 | TSN 0    |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 28-21-11 RIGHT WING 1/2 INCH CHECK VALVE VALVE                             |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:L96-13-001                                                              | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:M33067                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 28-21-13 INSC ILLUM PANEL                                                  |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:441-42621-003                                                           | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1084                                                                    | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-21-13, AMM 28-21-13PROC. REF: AMM 28-21-13, AMM 28-21-13 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 28-23-01 REFUEL CONTROL PANEL                                              |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:742388-1-2                                                              | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:742388IN00697                                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-23-01, AMM 28-23-01PROC. REF: AMM 28-23-01, AMM 28-23-01 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 28-23-03 LEFT WING PRESSURE REFUELING SOLENOID VALVE                       |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:L94E31-653P3                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:M31702                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-23-03, AMM 28-23-03PROC. REF: AMM 28-23-03, AMM 28-23-03 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 28-23-03 RIGHT WING PRESSURE REFUELING SOLENOID VALVE                      |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:L94E31-653P3                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:M31697                                                                  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-23-03, AMM 28-23-03PROC. REF: AMM 28-23-03, AMM 28-23-03 |         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                     | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |              |                                                         |                |          |                           |           |           |                  |
| 28-23-04-001                                                               | <sup>S</sup> | GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER |                |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS          | 23-Apr-20                                               |                |          |                           |           |           |                  |
|                                                                            | HRS          | 0                                                       | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                       |                |          |                           |           |           |                  |
| PROC. REF: AMM 28-23-05PROC. REF: AMM 28-23-05                             |              |                                                         |                |          |                           |           |           | PKG:40           |
| 28-23-07                                                                   |              | LEFT HIGH LEVEL SENSOR                                  |                |          |                           |           |           | Component ATA:28 |
| PN:722860-2-0                                                              | MOS/MSC      | 23-Apr-20                                               | O/C            | TSN 0    |                           |           |           |                  |
| SN:2537                                                                    | HRS          | 0                                                       |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-23-07, AMM 28-23-07PROC. REF: AMM 28-23-07, AMM 28-23-07 |              |                                                         |                |          |                           |           |           |                  |
| 28-23-07                                                                   |              | RIGHT HIGH LEVEL SENSOR                                 |                |          |                           |           |           | Component ATA:28 |
| PN:722860-2-0                                                              | MOS/MSC      | 23-Apr-20                                               | O/C            | TSN 0    |                           |           |           |                  |
| SN:2545                                                                    | HRS          | 0                                                       |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-23-07, AMM 28-23-07PROC. REF: AMM 28-23-07, AMM 28-23-07 |              |                                                         |                |          |                           |           |           |                  |
| 28-23-09                                                                   |              | FUEL PORT AND CAP                                       |                |          |                           |           |           | Component ATA:28 |
| PN:K97-63-613                                                              | MOS/MSC      | 23-Apr-20                                               | O/C            | TSN 0    |                           |           |           |                  |
| SN:M39259                                                                  | HRS          | 0                                                       |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-23-09, AMM 28-23-09PROC. REF: AMM 28-23-09, AMM 28-23-09 |              |                                                         |                |          |                           |           |           |                  |
| 28-41-01                                                                   |              | NO. 1 LEFT PROBE                                        |                |          |                           |           |           | Component ATA:28 |
| PN:765896-1-0                                                              | MOS/MSC      | 23-Apr-20                                               | O/C            | TSN 0    |                           |           |           |                  |
| SN:765896IN01285                                                           | HRS          | 0                                                       |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |              |                                                         |                |          |                           |           |           |                  |
| 28-41-01                                                                   |              | NO. 1 RIGHT PROBE                                       |                |          |                           |           |           | Component ATA:28 |
| PN:765896-1-0                                                              | MOS/MSC      | 23-Apr-20                                               | O/C            | TSN 0    |                           |           |           |                  |
| SN:765896IN01282                                                           | HRS          | 0                                                       |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                       |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |              |                                                         |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |                   |           |          |          |                           |           |           |                  |
| 28-41-01                                                                   | NO. 2 LEFT PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:765873-1-0                                                              | MOS/MSC           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:765873IN01318                                                           | HRS               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                           |           |           |                  |
| 28-41-01                                                                   | NO. 2 RIGHT PROBE |           |          |          |                           |           |           | Component ATA:28 |
| PN:765873-1-0                                                              | MOS/MSC           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:765873IN01333                                                           | HRS               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                           |           |           |                  |
| 28-41-01                                                                   | NO. 3 LEFT PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:765874-1-0                                                              | MOS/MSC           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:765874IN01293                                                           | HRS               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                           |           |           |                  |
| 28-41-01                                                                   | NO. 3 RIGHT PROBE |           |          |          |                           |           |           | Component ATA:28 |
| PN:765874-1-0                                                              | MOS/MSC           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:765874IN01298                                                           | HRS               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                           |           |           |                  |
| 28-41-01                                                                   | NO. 4 LEFT PROBE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:765875-1-0                                                              | MOS/MSC           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:765875IN01293                                                           | HRS               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                           |           |           |                  |
| 28-41-01                                                                   | NO. 4 RIGHT PROBE |           |          |          |                           |           |           | Component ATA:28 |
| PN:765875-1-0                                                              | MOS/MSC           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:765875IN01290                                                           | HRS               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01 |                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                       | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                                              |                                                            |           |                |          |                           |           |           |                  |
| 28-41-05                                                                   | EFCU ELECTRICAL FUEL CONTROL UNIT                          |           |                |          |                           |           |           | Component ATA:28 |
| PN:738742-1-4                                                              | MOS/MSC                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:738790IN01430                                                           | HRS                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-41-05, AMM 28-41-05PROC. REF: AMM 28-41-05, AMM 28-41-05 |                                                            |           |                |          |                           |           |           |                  |
| 28-43-01                                                                   | TEMPERATURE SENSOR                                         |           |                |          |                           |           |           | Component ATA:28 |
| PN:798840-1-0                                                              | MOS/MSC                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:05741                                                                   | HRS                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-43-01, AMM 28-43-01PROC. REF: AMM 28-43-01, AMM 28-43-01 |                                                            |           |                |          |                           |           |           |                  |
| 28-43-01-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR                |           |                |          |                           |           |           | Service ATA:28   |
|                                                                            | MOS                                                        | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                        | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 28-43-01PROC. REF: AMM 28-43-01                             |                                                            |           |                |          |                           |           |           |                  |
| 28-45-01                                                                   | LEFT PRESSURE SWITCH                                       |           |                |          |                           |           |           | Component ATA:28 |
| PN:D98C07-611                                                              | MOS/MSC                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:2268                                                                    | HRS                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-45-01, AMM 28-45-01PROC. REF: AMM 28-45-01, AMM 28-45-01 |                                                            |           |                |          |                           |           |           |                  |
| 28-45-01                                                                   | RIGHT PRESSURE SWITCH                                      |           |                |          |                           |           |           | Component ATA:28 |
| PN:D98C07-611                                                              | MOS/MSC                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:2269                                                                    | HRS                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-45-01, AMM 28-45-01PROC. REF: AMM 28-45-01, AMM 28-45-01 |                                                            |           |                |          |                           |           |           |                  |
| ATA 29 - HYDRAULIC POWER                                                   |                                                            |           |                |          |                           |           |           |                  |
| 29-12-02                                                                   | CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR |           |                |          |                           |           |           | Component ATA:29 |
| PN:3032763-003                                                             | MOS/MSC                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:MX827783                                                                | HRS                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |                | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 29 - HYDRAULIC POWER                                                                                                           |                                         |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02 |                                         |           |                |          |                           |           |           |                  |
| 29-12-02                                                                                                                           | LEFT ENGINE DRIVEN HYDRAULIC PUMP       |           |                |          |                           |           |           | Component ATA:29 |
| PN:3032249-002                                                                                                                     | MOS/MSC                                 | 13-Mar-26 | O/C            | TSO 3    |                           |           |           |                  |
| SN:MX858527                                                                                                                        | HRS                                     | 1221:24   |                | TSO 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                     | 564       |                | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02 |                                         |           |                |          |                           |           |           |                  |
| 29-12-02                                                                                                                           | RIGHT ENGINE DRIVEN HYDRAULIC PUMP      |           |                |          |                           |           |           | Component ATA:29 |
| PN:3032249-002                                                                                                                     | MOS/MSC                                 | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:MX829338                                                                                                                        | HRS                                     | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                     | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02 |                                         |           |                |          |                           |           |           |                  |
| 29-12-02-001 <sup>S</sup>                                                                                                          | VISUAL CHECK OF MANIFOLD/ RESERVOIR     |           |                |          |                           |           |           | Service ATA:29   |
|                                                                                                                                    | MOS                                     | 13-Mar-26 | 12 (+1m/-1m)   |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                     | 1221:24   |                |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                     | 564       |                |          |                           |           |           |                  |
| PROC. REF: AMM 29-12-02PROC. REF: AMM 29-12-02                                                                                     |                                         |           |                |          |                           |           |           | PKG:80           |
| 29-12-02-002 <sup>S</sup>                                                                                                          | OPERATIONAL CHECK LEFT EDP CHECK VALVE  |           |                |          |                           |           |           | Service ATA:29   |
|                                                                                                                                    | MOS                                     | 01-Nov-19 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                     | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                     |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00                                                                                     |                                         |           |                |          |                           |           |           | PKG:50           |
| 29-12-02-002 <sup>S</sup>                                                                                                          | OPERATIONAL CHECK RIGHT EDP CHECK VALVE |           |                |          |                           |           |           | Service ATA:29   |
|                                                                                                                                    | MOS                                     | 01-Nov-19 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                     | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                     |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 29-10-00PROC. REF: AMM 29-10-00                                                                                     |                                         |           |                |          |                           |           |           | PKG:50           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                             | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 29 - HYDRAULIC POWER                                                   |                                                                                  |           |                |          |                           |           |               |                  |
| 29-15-03                                                                   | HYDRAULIC ACCUMULATOR                                                            |           |                |          |                           |           |               | Component ATA:29 |
| PN:11172-2                                                                 | MOS/MSC                                                                          | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:11172-0477                                                              | HRS                                                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 29-15-03, AMM 29-15-03PROC. REF: AMM 29-15-03, AMM 29-15-03 |                                                                                  |           |                |          |                           |           |               |                  |
| 29-15-03-001 <sup>S</sup>                                                  | SERVICING OF HYDRAULIC ACCUMULATOR                                               |           |                |          |                           |           |               | Service ATA:29   |
| PN:11172-2                                                                 | MOS                                                                              | 13-Mar-26 | 12 (+1m/-1m)   |          |                           |           |               |                  |
| SN:11172-0477                                                              | HRS                                                                              | 1221:24   |                |          |                           |           |               |                  |
|                                                                            | AFL                                                                              | 564       |                |          |                           |           |               |                  |
| PROC. REF: AMM 12-13-00PROC. REF: AMM 12-13-00                             |                                                                                  |           |                |          |                           |           |               |                  |
| 29-15-04                                                                   | NO. 1 FSOV FIRE SHUT OFF VALVE                                                   |           |                |          |                           |           |               | Component ATA:29 |
| PN:3032428-001                                                             | MOS/MSC                                                                          | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:AA729491                                                                | HRS                                                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 29-15-04, AMM 29-15-04PROC. REF: AMM 29-15-04, AMM 29-15-04 |                                                                                  |           |                |          |                           |           |               |                  |
| 29-15-04                                                                   | NO. 2 FSOV FIRE SHUT OFF VALVE                                                   |           |                |          |                           |           |               | Component ATA:29 |
| PN:3032428-001                                                             | MOS/MSC                                                                          | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:AA729480                                                                | HRS                                                                              | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                            | AFL                                                                              | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 29-15-04, AMM 29-15-04PROC. REF: AMM 29-15-04, AMM 29-15-04 |                                                                                  |           |                |          |                           |           |               |                  |
| 29-15-04-001                                                               | OPERATIONAL CHECK NO. 1 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE |           |                |          |                           |           |               | Service ATA:29   |
| PN:3032428-001                                                             | MOS                                                                              | 17-Nov-23 | 48 (+30d/-30d) | Adj 14d  | 01-Dec-27                 | 31-Dec-27 | 490 d (+30)   | AIRWORTHINESS    |
| SN:AA729491                                                                | HRS                                                                              | 673:54    | 3200 (+30/-30) |          | 3873:54                   | 3903:54   | 2578:30 (+30) |                  |
|                                                                            | AFL                                                                              | 316       |                |          |                           |           |               |                  |
| PROC. REF: AMM 29-15-04PROC. REF: AMM 29-15-04                             |                                                                                  |           |                |          |                           |           |               |                  |
| 29-15-04-001                                                               | OPERATIONAL CHECK NO. 2 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE |           |                |          |                           |           |               | Service ATA:29   |
| PN:3032428-001                                                             | MOS                                                                              | 17-Nov-23 | 48 (+30d/-30d) | Adj 14d  | 01-Dec-27                 | 31-Dec-27 | 490 d (+30)   | AIRWORTHINESS    |
| SN:AA729480                                                                | HRS                                                                              | 673:54    | 3200 (+30/-30) |          | 3873:54                   | 3903:54   | 2578:30 (+30) |                  |
|                                                                            | AFL                                                                              | 316       |                |          |                           |           |               |                  |
| PROC. REF: AMM 29-15-04PROC. REF: AMM 29-15-04                             |                                                                                  |           |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 29 - HYDRAULIC POWER                                                   |                                                                                                     |           |                |          |                           |           |           |                  |
| 29-15-05                                                                   | PRIORITY VALVE                                                                                      |           |                |          |                           |           |           | Component ATA:29 |
| PN:2217-0030-401                                                           | MOS/MSC                                                                                             | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:00128                                                                   | HRS                                                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-15-05, AMM 29-15-05PROC. REF: AMM 29-15-05, AMM 29-15-05 |                                                                                                     |           |                |          |                           |           |           |                  |
| 29-31-02-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE |           |                |          |                           |           |           | Service ATA:29   |
|                                                                            | MOS                                                                                                 | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                 | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                 | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 29-31-02PROC. REF: AMM 29-31-02                             |                                                                                                     |           |                |          |                           |           |           |                  |
| PKG:50                                                                     |                                                                                                     |           |                |          |                           |           |           |                  |
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                                                                     |           |                |          |                           |           |           |                  |
| 30-01-01                                                                   | MD INSC ILLUM PANEL                                                                                 |           |                |          |                           |           |           | Component ATA:30 |
| PN:441-45072-001                                                           | MOS/MSC                                                                                             | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:1099                                                                    | HRS                                                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                 | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-01-01, AMM 30-01-01PROC. REF: AMM 30-01-01, AMM 30-01-01 |                                                                                                     |           |                |          |                           |           |           |                  |
| 30-12-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM                                                  |           |                |          |                           |           |           | Service ATA:30   |
|                                                                            | MOS                                                                                                 | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                 | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                 | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00                             |                                                                                                     |           |                |          |                           |           |           |                  |
| PKG:60                                                                     |                                                                                                     |           |                |          |                           |           |           |                  |
| 30-12-01-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS                               |           |                |          |                           |           |           | Service ATA:30   |
|                                                                            | MOS                                                                                                 | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                                                                                 | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                                                                 | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 30-12-01PROC. REF: AMM 30-12-01                             |                                                                                                     |           |                |          |                           |           |           |                  |
| PKG:60                                                                     |                                                                                                     |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                                                                                   |                                                          |           |          |          |                           |           |           |                  |
| 30-12-02                                                                                                                           | LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE       |           |          |          |                           |           |           | Component ATA:30 |
| PN:RYLB-53534-3                                                                                                                    | MOS/MSC                                                  | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0750                                                                                                                            | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-02, AMM 30-12-02PROC. REF: AMM 30-12-02, AMM 30-12-02                                                         |                                                          |           |          |          |                           |           |           |                  |
| 30-12-02                                                                                                                           | RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE      |           |          |          |                           |           |           | Component ATA:30 |
| PN:RYLB-53534-4                                                                                                                    | MOS/MSC                                                  | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0751                                                                                                                            | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-02, AMM 30-12-02PROC. REF: AMM 30-12-02, AMM 30-12-02                                                         |                                                          |           |          |          |                           |           |           |                  |
| 30-12-05                                                                                                                           | LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER  |           |          |          |                           |           |           | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                  | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8496-2-426                                                                                                                      | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                          |           |          |          |                           |           |           |                  |
| 30-12-05                                                                                                                           | LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER                  |           |          |          |                           |           |           | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                  | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8496-2-451                                                                                                                      | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                          |           |          |          |                           |           |           |                  |
| 30-12-05                                                                                                                           | LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER               |           |          |          |                           |           |           | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                  | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8496-2-181                                                                                                                      | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                          |           |          |          |                           |           |           |                  |
| 30-12-05                                                                                                                           | RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER |           |          |          |                           |           |           | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                  | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8496-2-441                                                                                                                      | HRS                                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                                                       | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                                                                                   |                                                                            |           |                |          |                           |           |           |                  |
| 30-12-05                                                                                                                           | RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER                                   |           |                |          |                           |           |           | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:8496-2-461                                                                                                                      | HRS                                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                                        | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                                            |           |                |          |                           |           |           |                  |
| 30-12-05                                                                                                                           | RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER                                |           |                |          |                           |           |           | Component ATA:30 |
| PN:APTE-485F-1000-50G                                                                                                              | MOS/MSC                                                                    | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:8496-2-180                                                                                                                      | HRS                                                                        | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                                        | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05 |                                                                            |           |                |          |                           |           |           |                  |
| 30-12-05-001 <sup>S</sup>                                                                                                          | FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER              |           |                |          |                           |           |           | Service ATA:30   |
|                                                                                                                                    | MOS                                                                        | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                                        | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                                        | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                                                                                     |                                                                            |           |                |          |                           |           |           |                  |
| 30-12-05-001 <sup>S</sup>                                                                                                          | FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER             |           |                |          |                           |           |           | Service ATA:30   |
|                                                                                                                                    | MOS                                                                        | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                                        | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                                        | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                                                                                     |                                                                            |           |                |          |                           |           |           |                  |
| 30-12-05-002 <sup>S</sup>                                                                                                          | FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER |           |                |          |                           |           |           | Service ATA:30   |
|                                                                                                                                    | MOS                                                                        | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                                        | 0         | 6400 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                                        | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                                                                                     |                                                                            |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                        | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                                             |           |                 |          |                           |           |                |                  |
| 30-12-05-002 <sup>S</sup>                                                  | FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER |           |                 |          |                           |           |                | Service ATA:30   |
|                                                                            | MOS                                                                         | 23-Apr-20 |                 |          |                           |           |                |                  |
|                                                                            | HRS                                                                         | 0         | 6400 (+30/-30)  |          |                           |           |                |                  |
|                                                                            | AFL                                                                         | 0         |                 |          |                           |           |                |                  |
| PROC. REF: AMM 30-12-05PROC. REF: AMM 30-12-05                             |                                                                             |           |                 |          |                           |           |                | PKG:60           |
|                                                                            |                                                                             |           |                 |          |                           |           |                |                  |
| 30-21-01                                                                   | LEFT ENGINE ANTI-ICE PRESUURE VALVE                                         |           |                 |          |                           |           |                | Component ATA:30 |
| PN:CW30-10040-1                                                            | MOS/MSC                                                                     | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:0000272                                                                 | HRS                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 30-21-01, AMM 30-21-01PROC. REF: AMM 30-21-01, AMM 30-21-01 |                                                                             |           |                 |          |                           |           |                |                  |
|                                                                            |                                                                             |           |                 |          |                           |           |                |                  |
| 30-21-01                                                                   | RIGHT ENGINE ANTI-ICE PRESUURE VALVE                                        |           |                 |          |                           |           |                | Component ATA:30 |
| PN:CW30-10040-1                                                            | MOS/MSC                                                                     | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:0266                                                                    | HRS                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 30-21-01, AMM 30-21-01PROC. REF: AMM 30-21-01, AMM 30-21-01 |                                                                             |           |                 |          |                           |           |                |                  |
|                                                                            |                                                                             |           |                 |          |                           |           |                |                  |
| 30-21-02                                                                   | LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER                                    |           |                 |          |                           |           |                | Component ATA:30 |
| PN:APTE-477F-1000-100GMOS/MSC                                              |                                                                             | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:8613-12-179                                                             | HRS                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 30-21-02, AMM 30-21-02PROC. REF: AMM 30-21-02, AMM 30-21-02 |                                                                             |           |                 |          |                           |           |                |                  |
|                                                                            |                                                                             |           |                 |          |                           |           |                |                  |
| 30-21-02                                                                   | RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER                                   |           |                 |          |                           |           |                | Component ATA:30 |
| PN:APTE-477F-1000-100GMOS/MSC                                              |                                                                             | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:8613-12-175                                                             | HRS                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                         | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 30-21-02, AMM 30-21-02PROC. REF: AMM 30-21-02, AMM 30-21-02 |                                                                             |           |                 |          |                           |           |                |                  |
|                                                                            |                                                                             |           |                 |          |                           |           |                |                  |
| 30-21-02-001                                                               | FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER              |           |                 |          |                           |           |                | Service ATA:30   |
|                                                                            | MOS                                                                         | 23-Apr-20 |                 |          |                           |           |                |                  |
|                                                                            | HRS                                                                         | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                  |
|                                                                            | AFL                                                                         | 0         |                 |          |                           |           |                |                  |
| PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02                             |                                                                             |           |                 |          |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                                                                | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition                      |
|------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|----------------|----------------------------------|
| ATA 30 - ICE AND RAIN PROTECTION               |                                                                                                     |           |                 |          |                           |           |                |                                  |
| 30-21-02-001                                   | FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER                                     |           |                 |          |                           |           |                | Service ATA:30                   |
|                                                | MOS                                                                                                 | 23-Apr-20 |                 |          |                           |           |                |                                  |
|                                                | HRS                                                                                                 | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                                  |
|                                                | AFL                                                                                                 | 0         |                 |          |                           |           |                |                                  |
| PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02 |                                                                                                     |           |                 |          |                           |           |                |                                  |
| 30-21-02-720-801-A                             | TROUBLE SHOOTING ENGINE OPERATING PROBLEMS - ENGINE ANTI-ICING PRESSURE TRANSDUCER FUNCTIONAL CHECK |           |                 |          |                           |           |                | Service ATA:30                   |
|                                                | MOS/MSC                                                                                             | 23-Apr-20 | A/R             |          |                           |           |                | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                                                                                 | 0         |                 |          |                           |           |                |                                  |
|                                                | AFL                                                                                                 | 0         |                 |          |                           |           |                |                                  |
| PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02 |                                                                                                     |           |                 |          |                           |           |                |                                  |
| 30-21-03-001 <sup>S</sup>                      | BORESCOPE INSPECTION OF PICCOLO TUBE                                                                |           |                 |          |                           |           |                | Service ATA:30                   |
|                                                | MOS                                                                                                 | 23-Apr-20 |                 |          |                           |           |                |                                  |
|                                                | HRS                                                                                                 | 0         | 5600 (+30/-30)  |          |                           |           |                |                                  |
|                                                | AFL                                                                                                 | 0         |                 |          |                           |           |                |                                  |
| PROC. REF: AMM 30-21-03PROC. REF: AMM 30-21-03 |                                                                                                     |           |                 |          |                           |           |                |                                  |
| PKG:50                                         |                                                                                                     |           |                 |          |                           |           |                |                                  |
| 30-21-04-001 <sup>S</sup>                      | DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS                                                        |           |                 |          |                           |           |                | Service ATA:30                   |
|                                                | MOS                                                                                                 | 23-Apr-20 |                 |          |                           |           |                |                                  |
|                                                | HRS                                                                                                 | 0         | 2400 (+30/-30)  |          |                           |           |                |                                  |
|                                                | AFL                                                                                                 | 0         |                 |          |                           |           |                |                                  |
| PROC. REF: AMM 30-21-00PROC. REF: AMM 30-21-00 |                                                                                                     |           |                 |          |                           |           |                |                                  |
| PKG:20                                         |                                                                                                     |           |                 |          |                           |           |                |                                  |
| 30-31-00-002                                   | OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING                                               |           |                 |          |                           |           |                | Service ATA:30                   |
|                                                | MOS                                                                                                 | 13-Mar-26 | 24 (+1m/-1m)    | Adj 6d   | 19-Mar-28                 | 19-Apr-28 | 599 d (+31)    |                                  |
|                                                | HRS                                                                                                 | 1221:24   |                 |          |                           |           |                |                                  |
|                                                | AFL                                                                                                 | 564       |                 |          |                           |           |                |                                  |
| PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00 |                                                                                                     |           |                 |          |                           |           |                |                                  |
| PKG:81                                         |                                                                                                     |           |                 |          |                           |           |                |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                                          | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|------------------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |              |                                                                              |               |          |                           |           |           |                  |
| 30-41-01-002                                                               | <sup>S</sup> | DISCARD OF WINDSHIELD RAIN REPELLENT COATING (RRC)                           |               |          |                           |           |           | Service ATA:30   |
|                                                                            | MOS          | 13-Mar-26                                                                    | 12 (+1m/-1m)  |          |                           |           |           |                  |
|                                                                            | HRS          | 1221:24                                                                      |               |          |                           |           |           |                  |
|                                                                            | AFL          | 564                                                                          |               |          |                           |           |           |                  |
| PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01                             |              |                                                                              |               |          |                           |           |           | PKG:80           |
| 30-41-01-003                                                               | <sup>S</sup> | FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE |               |          |                           |           |           | Service ATA:30   |
|                                                                            | MOS          | 13-Mar-26                                                                    | 12 (+1m/-1m)  |          |                           |           |           |                  |
|                                                                            | HRS          | 1221:24                                                                      |               |          |                           |           |           |                  |
|                                                                            | AFL          | 564                                                                          |               |          |                           |           |           |                  |
| PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01                             |              |                                                                              |               |          |                           |           |           | PKG:80           |
| 30-42-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM                               |               |          |                           |           |           | Service ATA:30   |
|                                                                            | MOS          | 19-Mar-24                                                                    |               |          |                           |           |           |                  |
|                                                                            | HRS          | 781:30                                                                       | 800 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 364                                                                          |               |          |                           |           |           |                  |
| PROC. REF: AMM 30-42-00PROC. REF: AMM 30-42-00                             |              |                                                                              |               |          |                           |           |           | PKG:1            |
| 30-42-01                                                                   |              | LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL                              |               |          |                           |           |           | Component ATA:30 |
| PN:EPM-112-4                                                               | MOS/MSC      | 23-Apr-20                                                                    | O/C           | TSN 0    |                           |           |           |                  |
| SN:03311                                                                   | HRS          | 0                                                                            |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                            |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-42-01, AMM 30-42-01PROC. REF: AMM 30-42-01, AMM 30-42-01 |              |                                                                              |               |          |                           |           |           |                  |
| 30-42-01                                                                   |              | RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL                              |               |          |                           |           |           | Component ATA:30 |
| PN:EPM-112-4                                                               | MOS/MSC      | 23-Apr-20                                                                    | O/C           | TSN 0    |                           |           |           |                  |
| SN:03260                                                                   | HRS          | 0                                                                            |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                            |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 30-42-01, AMM 30-42-01PROC. REF: AMM 30-42-01, AMM 30-42-01 |              |                                                                              |               |          |                           |           |           |                  |
| 30-81-02                                                                   |              | LEFT NOSE ICE DETECTOR                                                       |               |          |                           |           |           | Component ATA:30 |
| PN:0871LM3-1                                                               | MOS/MSC      | 23-Apr-20                                                                    | O/C           | TSN 0    |                           |           |           |                  |
| SN:2353                                                                    | HRS          | 0                                                                            |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                            |               | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                         | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                                           |                                                              |           |              |          |                           |           |             |                  |
| PROC. REF: AMM 30-81-02, AMM 30-81-02PROC. REF: AMM 30-81-02, AMM 30-81-02 |                                                              |           |              |          |                           |           |             |                  |
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                              |           |              |          |                           |           |             |                  |
| 31-30-02                                                                   | CVDR ACCELEROMETER                                           |           |              |          |                           |           |             | Component ATA:31 |
| PN:3001-01-111                                                             | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:0419-DT1793N                                                            | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 31-31-05, AMM 31-31-05PROC. REF: AMM 31-31-05, AMM 31-31-05 |                                                              |           |              |          |                           |           |             |                  |
| 31-31-00-002                                                               | OPERATIONAL CHECK OF CVDR (COCKPIT VOICE RECORDER)           |           |              |          |                           |           |             | Service ATA:31   |
|                                                                            | MOS                                                          | 13-Mar-26 | 12 (+1m/-1m) | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30) |                  |
|                                                                            | HRS                                                          | 1221:24   |              |          |                           |           |             |                  |
|                                                                            | AFL                                                          | 564       |              |          |                           |           |             |                  |
| PROC. REF: AMM 31-31-00PROC. REF: AMM 31-31-00                             |                                                              |           |              |          |                           |           |             |                  |
| 31-31-01                                                                   | (CVR / CVDR) COCKPIT VOICE RECORDER                          |           |              |          |                           |           |             | Component ATA:31 |
| PN:5013-6100-50                                                            | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:002013549                                                               | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 31-31-01, AMM 31-31-01PROC. REF: AMM 31-31-01, AMM 31-31-01 |                                                              |           |              |          |                           |           |             |                  |
| 31-31-02-001                                                               | FUNCTIONAL CHECK OF RIPS (RECORDER INDEPENDENT POWER SUPPLY) |           |              |          |                           |           |             | Service ATA:31   |
|                                                                            | MOS/MSC                                                      | 23-Apr-20 | N/A          |          |                           |           |             |                  |
|                                                                            | HRS                                                          | 0         |              |          |                           |           |             |                  |
|                                                                            | AFL                                                          | 0         |              |          |                           |           |             |                  |
| PROC. REF: AMM 31-31-02PROC. REF: AMM 31-31-02                             |                                                              |           |              |          |                           |           |             |                  |
| 31-31-03                                                                   | CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON  |           |              |          |                           |           |             | Component ATA:31 |
| PN:DK120/90                                                                | MOS/MSC                                                      | 12-Dec-25 | H/T          | TSN 8    |                           |           |             |                  |
| SN:AT222913                                                                | HRS                                                          | 1179:24   |              | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                          | 546       |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 31-31-03, AMM 31-31-03PROC. REF: AMM 31-31-03, AMM 31-31-03 |                                                              |           |              |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                          | C/W       | Interval                 | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------------|-----------|--------------------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                               |           |                          |          |                           |           |           |                  |
| 31-31-03-001                                                               | DISCARD OF CVDR/ULB BATTERY                                   |           |                          |          |                           |           |           | Service ATA:31   |
| PN:DK120/90                                                                | MOS/MSC                                                       | 12-Dec-25 | DUE                      |          | 30-Apr-32 (M)             |           | 2102 d    | LIFE LIMIT       |
| SN:AT222913                                                                | HRS                                                           | 1179:24   |                          |          |                           |           |           |                  |
|                                                                            | AFL                                                           | 546       |                          |          |                           |           |           |                  |
|                                                                            |                                                               |           | Expiry Date: : 30-Apr-32 |          |                           |           |           |                  |
| PROC. REF: AMM 31-31-03PROC. REF: AMM 31-31-03                             |                                                               |           |                          |          |                           |           |           |                  |
| 31-33-03                                                                   | FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON      |           |                          |          |                           |           |           | Component ATA:31 |
| PN:PN                                                                      | MOS/MSC                                                       | 23-Apr-20 | H/T                      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-33-03, AMM 31-33-03PROC. REF: AMM 31-33-03, AMM 31-33-03 |                                                               |           |                          |          |                           |           |           |                  |
| 31-33-04                                                                   | FORWARD CVDR IMPACT SWITCH                                    |           |                          |          |                           |           |           | Component ATA:31 |
| PN:5930-4-000                                                              | MOS/MSC                                                       | 23-Apr-20 | O/C                      | TSN 0    |                           |           |           |                  |
| SN:8192                                                                    | HRS                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-33-04, AMM 31-33-04PROC. REF: AMM 31-33-04, AMM 31-33-04 |                                                               |           |                          |          |                           |           |           |                  |
| 31-33-05                                                                   | ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER |           |                          |          |                           |           |           | Component ATA:31 |
| PN:3K2222B                                                                 | MOS/MSC                                                       | 23-Apr-20 | O/C                      | TSN 0    |                           |           |           |                  |
| SN:C1447                                                                   | HRS                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-33-05, AMM 31-33-05PROC. REF: AMM 31-33-05, AMM 31-33-05 |                                                               |           |                          |          |                           |           |           |                  |
| 31-33-05                                                                   | RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER   |           |                          |          |                           |           |           | Component ATA:31 |
| PN:3K2222B                                                                 | MOS/MSC                                                       | 23-Apr-20 | O/C                      | TSN 0    |                           |           |           |                  |
| SN:C1486                                                                   | HRS                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |                          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-33-05, AMM 31-33-05PROC. REF: AMM 31-33-05, AMM 31-33-05 |                                                               |           |                          |          |                           |           |           |                  |
| 31-33-05-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF RUDDER FDR RVDT                           |           |                          |          |                           |           |           | Service ATA:31   |
| PN:3K2222B                                                                 | MOS                                                           | 13-Mar-26 | 12 (+1m/-1m)             |          |                           |           |           |                  |
| SN:C1486                                                                   | HRS                                                           | 1221:24   |                          |          |                           |           |           |                  |
|                                                                            | AFL                                                           | 564       |                          |          |                           |           |           |                  |
| PROC. REF: AMM 31-33-05PROC. REF: AMM 31-33-05                             |                                                               |           |                          |          |                           |           |           |                  |

PKG:80

PKG:80

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit                                   | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------------------------------------------------|----------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                                                  |                                        |           |              |          |                           |           |           |                  |
|                                                                                                        |                                        |           |              |          |                           |           |           |                  |
| 31-33-05-002 <sup>S</sup>                                                                              | FUNCTIONAL CHECK OF ELEVATOR FDR RVDT  |           |              |          |                           |           |           | Service ATA:31   |
| PN:3K2222B                                                                                             | MOS                                    | 13-Mar-26 | 12 (+1m/-1m) |          |                           |           |           |                  |
| SN:C1447                                                                                               | HRS                                    | 1221:24   |              |          |                           |           |           |                  |
|                                                                                                        | AFL                                    | 564       |              |          |                           |           |           |                  |
|                                                                                                        |                                        |           |              |          |                           |           |           |                  |
| PROC. REF: AMM 31-33-05PROC. REF: AMM 31-33-05                                                         |                                        |           |              |          |                           |           |           |                  |
|                                                                                                        |                                        |           |              |          |                           |           |           |                  |
| 31-40-01                                                                                               | LH DCU UNIT                            |           |              |          |                           |           |           | Component ATA:31 |
| PN:011-01457-00                                                                                        | MOS/MSC                                | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:16907464                                                                                            | HRS                                    | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL                                    | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-41-01, AMM 31-41-01PROC. REF: AMM 31-41-01, AMM 31-41-01                             |                                        |           |              |          |                           |           |           |                  |
|                                                                                                        |                                        |           |              |          |                           |           |           |                  |
| 31-40-01                                                                                               | RH DCU UNIT                            |           |              |          |                           |           |           | Component ATA:31 |
| PN:011-01457-00                                                                                        | MOS/MSC                                | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:16907565                                                                                            | HRS                                    | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL                                    | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-41-01, AMM 31-41-01PROC. REF: AMM 31-41-01, AMM 31-41-01                             |                                        |           |              |          |                           |           |           |                  |
|                                                                                                        |                                        |           |              |          |                           |           |           |                  |
| 31-40-02                                                                                               | LEFT GIA 63W INTEGRATED AVIONICS UNIT  |           |              |          |                           |           |           | Component ATA:31 |
| PN:011-03711-40                                                                                        | MOS/MSC                                | 03-Mar-22 | O/C          | TSN 16   |                           |           |           |                  |
| SN:4SM005739                                                                                           | HRS                                    | 278:18    |              | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL                                    | 139       |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05 |                                        |           |              |          |                           |           |           |                  |
|                                                                                                        |                                        |           |              |          |                           |           |           |                  |
| 31-40-02                                                                                               | RIGHT GIA 63W INTEGRATED AVIONICS UNIT |           |              |          |                           |           |           | Component ATA:31 |
| PN:011-03711-40                                                                                        | MOS/MSC                                | 10-Jul-25 | O/C          | TSR 0    |                           |           |           |                  |
| SN:4SM006830                                                                                           | HRS                                    | 1062:18   |              | TSR 0    |                           |           |           |                  |
|                                                                                                        | AFL                                    | 493       |              | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05 |                                        |           |              |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                              | C/W       | Interval       | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------|----------------|-------------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                                                   |           |                |             |                           |           |           |                  |
| 31-42-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF HSDB SWITCH REVERSION                                        |           |                |             |                           |           |           | Service ATA:31   |
|                                                                            | MOS                                                                               | 23-Apr-20 |                |             |                           |           |           |                  |
|                                                                            | HRS                                                                               | 0         | 6400 (+30/-30) |             |                           |           |           |                  |
|                                                                            | AFL                                                                               | 0         |                |             |                           |           |           |                  |
| PROC. REF: AMM 31-42-00PROC. REF: AMM 31-42-00                             |                                                                                   |           |                |             |                           |           |           | PKG:60           |
| 31-42-01                                                                   | COCKPIT PARTITION MAINTENANCE SYSTEM INSC ILLUM                                   |           |                |             |                           |           |           | Component ATA:31 |
| PN:441-5430-000                                                            | MOS/MSC                                                                           | 23-Apr-20 | O/C            | TSN 0       |                           |           |           |                  |
| SN:1010                                                                    | HRS                                                                               | 0         |                | TSN 0       |                           |           |           |                  |
|                                                                            | AFL                                                                               | 0         |                | TSN 0       |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                   |           |                |             |                           |           |           |                  |
| 31-50-01                                                                   | 1 (GEA) ENGINE AIRFRAME INTERFACE UNIT                                            |           |                |             |                           |           |           | Component ATA:31 |
| PN:011-03682-00                                                            | MOS/MSC                                                                           | 13-Mar-26 | O/C            |             |                           |           |           |                  |
| SN:497003170                                                               | HRS                                                                               | 1221:24   |                |             |                           |           |           |                  |
|                                                                            | AFL                                                                               | 564       |                |             |                           |           |           |                  |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                   |           |                |             |                           |           |           |                  |
| 31-50-01                                                                   | 2 (GEA) ENGINE AIRFRAME INTERFACE UNIT                                            |           |                |             |                           |           |           | Component ATA:31 |
| PN:011-03682-00                                                            | MOS/MSC                                                                           | 13-Mar-26 | O/C            | TSN 71      |                           |           |           |                  |
| SN:497003316                                                               | HRS                                                                               | 1221:24   |                | TSN 1221:24 |                           |           |           |                  |
|                                                                            | AFL                                                                               | 564       |                | TSN 564     |                           |           |           |                  |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                   |           |                |             |                           |           |           |                  |
| 31-50-01                                                                   | 3 (GEA) ENGINE AIRFRAME INTERFACE UNIT                                            |           |                |             |                           |           |           | Component ATA:31 |
| PN:011-03682-00                                                            | MOS/MSC                                                                           | 23-Apr-20 | O/C            | TSN 0       |                           |           |           |                  |
| SN:497003170                                                               | HRS                                                                               | 0         |                | TSN 0       |                           |           |           |                  |
|                                                                            | AFL                                                                               | 0         |                | TSN 0       |                           |           |           |                  |
| PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03 |                                                                                   |           |                |             |                           |           |           |                  |
| 31-61-00-001 <sup>S</sup>                                                  | OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) |           |                |             |                           |           |           | Service ATA:31   |
| PN:011-04187-10                                                            | MOS                                                                               | 23-Apr-20 |                |             |                           |           |           |                  |
| SN:4VS105036                                                               | HRS                                                                               | 0         | 3200 (+30/-30) |             |                           |           |           |                  |
|                                                                            | AFL                                                                               | 0         |                |             |                           |           |           |                  |
| PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00                             |                                                                                   |           |                |             |                           |           |           | PKG:40           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                                                 | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |              |                                                                                     |                |          |                           |           |           |                  |
|                                                                            |              |                                                                                     |                |          |                           |           |           |                  |
| 31-61-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) |                |          |                           |           |           | Service ATA:31   |
| PN:011-04187-10                                                            | MOS          | 23-Apr-20                                                                           |                |          |                           |           |           |                  |
| SN:4VS105037                                                               | HRS          | 0                                                                                   | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                                   |                |          |                           |           |           |                  |
| PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00                             |              |                                                                                     |                |          |                           |           |           | PKG:40           |
|                                                                            |              |                                                                                     |                |          |                           |           |           |                  |
| 31-61-00-001                                                               | <sup>S</sup> | OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) |                |          |                           |           |           | Service ATA:31   |
| PN:011-04187-10                                                            | MOS          | 23-Apr-20                                                                           |                |          |                           |           |           |                  |
| SN:4VS105042                                                               | HRS          | 0                                                                                   | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                                   |                |          |                           |           |           |                  |
| PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00                             |              |                                                                                     |                |          |                           |           |           | PKG:40           |
|                                                                            |              |                                                                                     |                |          |                           |           |           |                  |
| 31-61-01                                                                   |              | MFD (MULTI-FUNCTION FLIGHT DISPLAY)                                                 |                |          |                           |           |           | Component ATA:31 |
| PN:011-04187-10                                                            | MOS/MSC      | 23-Apr-20                                                                           | O/C            | TSN 0    |                           |           |           |                  |
| SN:4VS105036                                                               | HRS          | 0                                                                                   |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01 |              |                                                                                     |                |          |                           |           |           |                  |
|                                                                            |              |                                                                                     |                |          |                           |           |           |                  |
| 31-61-01                                                                   |              | PFD 1 (PRIMARY FLIGHT DISPLAY)                                                      |                |          |                           |           |           | Component ATA:31 |
| PN:011-04187-10                                                            | MOS/MSC      | 23-Apr-20                                                                           | O/C            | TSN 0    |                           |           |           |                  |
| SN:4VS105037                                                               | HRS          | 0                                                                                   |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01 |              |                                                                                     |                |          |                           |           |           |                  |
|                                                                            |              |                                                                                     |                |          |                           |           |           |                  |
| 31-61-01                                                                   |              | PFD 2 (PRIMARY FLIGHT DISPLAY)                                                      |                |          |                           |           |           | Component ATA:31 |
| PN:011-04187-10                                                            | MOS/MSC      | 23-Apr-20                                                                           | O/C            | TSN 0    |                           |           |           |                  |
| SN:4VS105042                                                               | HRS          | 0                                                                                   |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL          | 0                                                                                   |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01 |              |                                                                                     |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                              | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS                                      |                                                                   |           |               |          |                           |           |           |                  |
| 31-61-06                                                                   | NO. 1 BARO INSC ILLUMINATED PANEL                                 |           |               |          |                           |           |           | Component ATA:31 |
| PN:441-44282-001                                                           | MOS/MSC                                                           | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:1859                                                                    | HRS                                                               | 0         |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                               | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-06, AMM 31-61-06PROC. REF: AMM 31-61-06, AMM 31-61-06 |                                                                   |           |               |          |                           |           |           |                  |
| 31-61-06                                                                   | NO. 2 BARO INSC ILLUMINATED PANEL                                 |           |               |          |                           |           |           | Component ATA:31 |
| PN:441-44282-001                                                           | MOS/MSC                                                           | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:1861                                                                    | HRS                                                               | 0         |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                               | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-06, AMM 31-61-06PROC. REF: AMM 31-61-06, AMM 31-61-06 |                                                                   |           |               |          |                           |           |           |                  |
| 316104-0101                                                                | PAX NO.1 GTC570 TOUCHSCREEN CONTROLLER                            |           |               |          |                           |           |           | Component ATA:31 |
| PN:011-03759-01                                                            | MOS/MSC                                                           | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:4MT101786                                                               | HRS                                                               | 0         |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                               | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-04, AMM 31-61-04PROC. REF: AMM 31-61-04, AMM 31-61-04 |                                                                   |           |               |          |                           |           |           |                  |
| 316104-0101                                                                | PAX NO.2 GTC570 TOUCHSCREEN CONTROLLER                            |           |               |          |                           |           |           | Component ATA:31 |
| PN:011-03759-01                                                            | MOS/MSC                                                           | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:4MT101905                                                               | HRS                                                               | 0         |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                               | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 31-61-04, AMM 31-61-04PROC. REF: AMM 31-61-04, AMM 31-61-04 |                                                                   |           |               |          |                           |           |           |                  |
| ATA 32 - LANDING GEAR                                                      |                                                                   |           |               |          |                           |           |           |                  |
| 32-00-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR POLYURETHANE FILMS |           |               |          |                           |           |           | Service ATA:32   |
|                                                                            | MOS                                                               | 19-Mar-24 |               |          |                           |           |           |                  |
|                                                                            | HRS                                                               | 781:30    | 800 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                                               | 364       |               |          |                           |           |           |                  |
| PROC. REF: AMM 32-00-20PROC. REF: AMM 32-00-20                             |                                                                   |           |               |          |                           |           |           |                  |
| PKG:1                                                                      |                                                                   |           |               |          |                           |           |           |                  |
| 32-001                                                                     | LEFT MLG SHOCK STRUT LEFT MAIN FITTING                            |           |               |          |                           |           |           | Component ATA:32 |
| PN:2317-1201-503                                                           | MOS                                                               | 23-Apr-20 |               | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1765086/001                                                             | HRS                                                               | 0         |               | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                               | 0         | 16800         | TSN 0    | 16800                     |           | 16202     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |      |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |      |           |          |          |                           |           |           |                  |
|                                                                            |      |           |          |          |                           |           |           |                  |
| 32-002 RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING                            |      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1201-504                                                           | MOS  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1758922/001                                                             | HRS  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL  | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |      |           |          |          |                           |           |           |                  |
|                                                                            |      |           |          |          |                           |           |           |                  |
| 32-003 LEFT PINTLE PIN                                                     |      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1101-003                                                           | MOS  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1765799/007                                                             | HRS  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL  | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |      |           |          |          |                           |           |           |                  |
|                                                                            |      |           |          |          |                           |           |           |                  |
| 32-003 RIGHT PINTLE PIN                                                    |      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1101-003                                                           | MOS  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1765799/009                                                             | HRS  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL  | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |      |           |          |          |                           |           |           |                  |
|                                                                            |      |           |          |          |                           |           |           |                  |
| 32-004 LEFT PINTLE PIN                                                     |      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1102-001                                                           | MOS  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1762708/002                                                             | HRS  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL  | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |      |           |          |          |                           |           |           |                  |
|                                                                            |      |           |          |          |                           |           |           |                  |
| 32-004 RIGHT PINTLE PIN                                                    |      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1102-001                                                           | MOS  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1762708/004                                                             | HRS  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL  | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                       |           |          |          |                           |           |           |                  |
| 32-005                                                                     | LEFT MLG SHOCK STRUT (MF - AS) AXLE                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1103-003                                                           | MOS                                                   | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1765873/005                                                             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                       |           |          |          |                           |           |           |                  |
| 32-005                                                                     | RIGHT MLG SHOCK STRUT (MF - AS) AXLE                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1103-003                                                           | MOS                                                   | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1765873/008                                                             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                       |           |          |          |                           |           |           |                  |
| 32-006                                                                     | LEFT MLG SHOCK STRUT (TR - AS) AXLE                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1107-005                                                           | MOS                                                   | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1756684/010                                                             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         | 15300    | TSN 0    | 15300                     |           | 14702     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                       |           |          |          |                           |           |           |                  |
| 32-006                                                                     | RIGHT MLG SHOCK STRUT (TR - AS) AXLE                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1107-005                                                           | MOS                                                   | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1756684/002                                                             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         | 15300    | TSN 0    | 15300                     |           | 14702     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                       |           |          |          |                           |           |           |                  |
| 32-007                                                                     | LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1109-003                                                           | MOS                                                   | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770543/004                                                             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                       |           |          |          |                           |           |           |                  |
| 32-007                                                                     | RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1109-003                                                           | MOS                                                   | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770543/011                                                             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                   | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                     |           |          |          |                           |           |           |                  |
| 32-008                                                                     | LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1126-003                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1754824/015                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                     |           |          |          |                           |           |           |                  |
| 32-008                                                                     | RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1126-003                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1754678/006                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                     |           |          |          |                           |           |           |                  |
| 32-10-00                                                                   | LEFT MAIN LANDING GEAR                              |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                                             | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                     |           |          |          |                           |           |           |                  |
| 32-10-00                                                                   | RIGHT MAIN LANDING GEAR                             |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                                             | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                     |           |          |          |                           |           |           |                  |
| 32-10-01                                                                   | LEFT MAIN LANDING GEAR LEG STRUT ASSY               |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1100-405                                                           | MOS/MSC                                             | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00569                                                                   | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                     |           |          |          |                           |           |           |                  |
| 32-10-01                                                                   | RIGHT MAIN LANDING GEAR LEG STRUT ASSY              |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1100-406                                                           | MOS/MSC                                             | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00576                                                                   | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                 |           |          |          |                           |           |           |                  |
| 32-100                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM ASSY        |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1500-405                                                           | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00583                                                                   | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                           |           |           |                  |
| 32-100                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM ASSY       |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1500-406                                                           | MOS/MSC                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00585                                                                   | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                           |           |           |                  |
| 32-101                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1502-003                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1701285/001                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 15300    | TSN 0    | 15300                     |           | 14702     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                           |           |           |                  |
| 32-101                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1502-003                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1767328/009                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 15300    | TSN 0    | 15300                     |           | 14702     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                           |           |           |                  |
| 32-102                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM AXLE        |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1503-005                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1766442/003                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                           |           |           |                  |
| 32-102                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM AXLE       |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1503-005                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1764708/004                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                  |           |          |          |                           |           |           |                  |
| 32-103                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM BOLT         |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1509-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1737345/004                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                  |           |          |          |                           |           |           |                  |
| 32-103                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM BOLT        |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1509-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1737345/018                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                  |           |          |          |                           |           |           |                  |
| 32-104                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM              |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1513-501                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1754494/001                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                  |           |          |          |                           |           |           |                  |
| 32-105                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM             |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1513-502                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1759189/001                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                  |           |          |          |                           |           |           |                  |
| 32-106                                                                     | LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1505-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770264/002                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                  |           |          |          |                           |           |           |                  |
| 32-106                                                                     | RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-1505-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770264/012                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04 |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                                 | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|------------------------------------------------|--------------|---------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 32 - LANDING GEAR                          |              |                                                                     |                 |          |                           |           |              |                |
| 32-11-00-001                                   | <sup>S</sup> | GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR                      |                 |          |                           |           |              | Service ATA:32 |
|                                                | MOS          | 13-Mar-26                                                           | 12 (+1m/-1m)    |          |                           |           |              |                |
|                                                | HRS          | 1221:24                                                             |                 |          |                           |           |              |                |
|                                                | AFL          | 564                                                                 |                 |          |                           |           |              |                |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00 |              |                                                                     |                 |          |                           |           |              | PKG:80         |
| 32-11-00-003                                   |              | LUBRICATION OF MAIN LANDING GEAR                                    |                 |          |                           |           |              | Service ATA:32 |
|                                                | MOS          | 13-Mar-26                                                           | 12 (+1m/-1m)    | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30)  |                |
|                                                | HRS          | 1221:24                                                             |                 |          |                           |           |              |                |
|                                                | AFL          | 564                                                                 | 650 (+30/-30)   |          | 1214                      | 1244      | 616 (+30)    |                |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00 |              |                                                                     |                 |          |                           |           |              |                |
| 32-11-01-001                                   |              | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)       |                 |          |                           |           |              | Service ATA:32 |
| PN:2317-1100-405                               | MOS          | EFF                                                                 | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL       |
| SN:00569                                       | HRS          |                                                                     |                 |          |                           |           |              |                |
|                                                | AFL          | EFF                                                                 | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00 |              |                                                                     |                 |          |                           |           |              |                |
| 32-11-01-002                                   |              | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)       |                 |          |                           |           |              | Service ATA:32 |
| PN:2317-1100-406                               | MOS          | EFF                                                                 | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL       |
| SN:00576                                       | HRS          |                                                                     |                 |          |                           |           |              |                |
|                                                | AFL          | EFF                                                                 | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00 |              |                                                                     |                 |          |                           |           |              |                |
| 32-11-02-001                                   |              | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH) |                 |          |                           |           |              | Service ATA:32 |
| PN:2117-3000-409                               | MOS          | EFF                                                                 | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL       |
| SN:01246                                       | HRS          |                                                                     |                 |          |                           |           |              |                |
|                                                | AFL          | EFF                                                                 | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00 |              |                                                                     |                 |          |                           |           |              |                |
| 32-11-02-002                                   |              | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH) |                 |          |                           |           |              | Service ATA:32 |
| PN:2117-3000-409                               | MOS          | EFF                                                                 | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL       |
| SN:01244                                       | HRS          |                                                                     |                 |          |                           |           |              |                |
|                                                | AFL          | EFF                                                                 | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                          | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition         |
|----------------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------|
| ATA 32 - LANDING GEAR                                                            |         |           |          |          |                           |           |           |                     |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                                   |         |           |          |          |                           |           |           |                     |
|                                                                                  |         |           |          |          |                           |           |           |                     |
| 32-11-02-900-801-05      RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON |         |           |          |          |                           |           |           | Component    ATA:32 |
| PN:2117-3001-003                                                                 | MOS/MSC | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                     |
| SN:1766216/006                                                                   | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
|                                                                                  | AFL     | 0         |          | TSN 0    |                           |           |           |                     |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02       |         |           |          |          |                           |           |           |                     |
|                                                                                  |         |           |          |          |                           |           |           |                     |
| 32-11-02-900-801-06      LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON  |         |           |          |          |                           |           |           | Component    ATA:32 |
| PN:2117-3001-003                                                                 | MOS/MSC | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                     |
| SN:1766216/004                                                                   | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
|                                                                                  | AFL     | 0         |          | TSN 0    |                           |           |           |                     |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02       |         |           |          |          |                           |           |           |                     |
|                                                                                  |         |           |          |          |                           |           |           |                     |
| 32-11-02-900-801-07      LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER          |         |           |          |          |                           |           |           | Component    ATA:32 |
| PN:2117-3027-901                                                                 | MOS/MSC | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                     |
| SN:17023                                                                         | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
|                                                                                  | AFL     | 0         |          | TSN 0    |                           |           |           |                     |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02       |         |           |          |          |                           |           |           |                     |
|                                                                                  |         |           |          |          |                           |           |           |                     |
| 32-11-02-900-801-08      RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER         |         |           |          |          |                           |           |           | Component    ATA:32 |
| PN:2117-3027-901                                                                 | MOS/MSC | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                     |
| SN:17022                                                                         | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
|                                                                                  | AFL     | 0         |          | TSN 0    |                           |           |           |                     |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02       |         |           |          |          |                           |           |           |                     |
|                                                                                  |         |           |          |          |                           |           |           |                     |
| 32-11-02-900-801-13      RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN            |         |           |          |          |                           |           |           | Component    ATA:32 |
| PN:2117-3019-003                                                                 | MOS/MSC | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                     |
| SN:1754045/008                                                                   | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
|                                                                                  | AFL     | 0         |          | TSN 0    |                           |           |           |                     |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02       |         |           |          |          |                           |           |           |                     |
|                                                                                  |         |           |          |          |                           |           |           |                     |
| 32-11-02-900-801-14      LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN             |         |           |          |          |                           |           |           | Component    ATA:32 |
| PN:2117-3019-003                                                                 | MOS/MSC | 23-Apr-20 | H/T      | TSN 0    |                           |           |           |                     |
| SN:1754045/002                                                                   | HRS     | 0         |          | TSN 0    |                           |           |           |                     |
|                                                                                  | AFL     | 0         |          | TSN 0    |                           |           |           |                     |

?-Insufficient Information    S-Suppressed Requirement    \*-Estimated Due(New Requirement)    (EFF)-Effective C/W    (M)-Manual Due    U-User Task    Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                              | C/W       | Interval        | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit    | Remaining   | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|-----------------|-------------|---------------------------|--------------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                   |           |                 |             |                           |              |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |             |                           |              |             |                  |
|                                                                            |                                                                   |           |                 |             |                           |              |             |                  |
| 32-11-02-900-801-15                                                        | LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE            |           |                 |             |                           |              |             | Component ATA:32 |
| PN:2117-3007-003                                                           | MOS/MSC                                                           | 23-Apr-20 | H/T             | TSN 0       |                           |              |             |                  |
| SN:1757625/005                                                             | HRS                                                               | 0         |                 | TSN 0       |                           |              |             |                  |
|                                                                            | AFL                                                               | 0         |                 | TSN 0       |                           |              |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |             |                           |              |             |                  |
|                                                                            |                                                                   |           |                 |             |                           |              |             |                  |
| 32-11-02-900-801-16                                                        | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE           |           |                 |             |                           |              |             | Component ATA:32 |
| PN:2117-3007-003                                                           | MOS/MSC                                                           | 23-Apr-20 | H/T             | TSN 0       |                           |              |             |                  |
| SN:1757625/015                                                             | HRS                                                               | 0         |                 | TSN 0       |                           |              |             |                  |
|                                                                            | AFL                                                               | 0         |                 | TSN 0       |                           |              |             |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                   |           |                 |             |                           |              |             |                  |
|                                                                            |                                                                   |           |                 |             |                           |              |             |                  |
| 32-11-03-001                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH) |           |                 |             |                           |              |             | Service ATA:32   |
| PN:2317-3000-405                                                           | MOS                                                               | EFF       | 120 (+1m/-1m)   | 23-Apr-30 * | 23-May-30                 | 1364 d (+30) | OVERHAUL    |                  |
| SN:01294                                                                   | HRS                                                               |           |                 |             |                           |              |             |                  |
|                                                                            | AFL                                                               | EFF       | 12000 (+30/-30) | 12000 *     | 12030                     | 11402 (+30)  |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                                   |           |                 |             |                           |              |             |                  |
|                                                                            |                                                                   |           |                 |             |                           |              |             |                  |
| 32-11-03-002                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH) |           |                 |             |                           |              |             | Service ATA:32   |
| PN:2317-3000-405                                                           | MOS                                                               | EFF       | 120 (+1m/-1m)   | 23-Apr-30 * | 23-May-30                 | 1364 d (+30) | OVERHAUL    |                  |
| SN:01298                                                                   | HRS                                                               |           |                 |             |                           |              |             |                  |
|                                                                            | AFL                                                               | EFF       | 12000 (+30/-30) | 12000 *     | 12030                     | 11402 (+30)  |             |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                                   |           |                 |             |                           |              |             |                  |
|                                                                            |                                                                   |           |                 |             |                           |              |             |                  |
| 32-11-03-004                                                               | SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER                     |           |                 |             |                           |              |             | Service ATA:32   |
|                                                                            | MOS                                                               | 13-Mar-26 | 12 (+1m/-1m)    | Adj 18d     | 31-Mar-27                 | 30-Apr-27    | 245 d (+30) |                  |
|                                                                            | HRS                                                               | 1221:24   |                 |             |                           |              |             |                  |
|                                                                            | AFL                                                               | 564       | 650 (+30/-30)   |             | 1214                      | 1244         | 616 (+30)   |                  |
| PROC. REF: AMM 12-14-02PROC. REF: AMM 12-14-02                             |                                                                   |           |                 |             |                           |              |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                            | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                 |           |                 |          |                           |           |              |                  |
| 32-11-04-001                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH) |           |                 |          |                           |           |              | Service ATA:32   |
| PN:2317-1500-405                                                           | MOS                                                             | EFF       | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL         |
| SN:00583                                                                   | HRS                                                             |           |                 |          |                           |           |              |                  |
|                                                                            | AFL                                                             | EFF       | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                                 |           |                 |          |                           |           |              |                  |
| 32-11-04-002                                                               | RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH) |           |                 |          |                           |           |              | Service ATA:32   |
| PN:2317-1500-406                                                           | MOS                                                             | EFF       | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL         |
| SN:00585                                                                   | HRS                                                             |           |                 |          |                           |           |              |                  |
|                                                                            | AFL                                                             | EFF       | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                  |
| PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00                             |                                                                 |           |                 |          |                           |           |              |                  |
| 32-20-01                                                                   | NOSE LANDING GEAR                                               |           |                 |          |                           |           |              | Component ATA:32 |
| PN:PN                                                                      | MOS/MSC                                                         | 23-Apr-20 | O/C             | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                                                                 | HRS                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                                 |           |                 |          |                           |           |              |                  |
| 32-200                                                                     | LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER                       |           |                 |          |                           |           |              | Component ATA:32 |
| PN:2317-3000-405                                                           | MOS/MSC                                                         | 23-Apr-20 | O/C             | TSN 0    |                           |           |              |                  |
| SN:01294                                                                   | HRS                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                                 |           |                 |          |                           |           |              |                  |
| 32-200                                                                     | RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER                      |           |                 |          |                           |           |              | Component ATA:32 |
| PN:2317-3000-405                                                           | MOS/MSC                                                         | 23-Apr-20 | O/C             | TSN 0    |                           |           |              |                  |
| SN:01298                                                                   | HRS                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                                 |           |                 |          |                           |           |              |                  |
| 32-201                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER                  |           |                 |          |                           |           |              | Component ATA:32 |
| PN:2317-3011-001                                                           | MOS                                                             | 23-Apr-20 |                 | TSN 0    |                           |           |              | LIFE LIMIT       |
| SN:1744790/003                                                             | HRS                                                             | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                             | 0         | 16800           | TSN 0    | 16800                     |           | 16202        |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                                 |           |                 |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                     |           |          |          |                           |           |           |                  |
| 32-201                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER     |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-3011-001                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1757984/006                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                           |           |           |                  |
| 32-202                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-3021-001                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1677720/001                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                           |           |           |                  |
| 32-202                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-3021-001                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1768952/001                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                           |           |           |                  |
| 32-203                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING       |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-3001-003                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1765731/013                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                           |           |           |                  |
| 32-203                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-3001-003                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1759273/002                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                           |           |           |                  |
| 32-204                                                                     | LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT           |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-3004-001                                                           | MOS                                                 | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1759849/014                                                             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                 | 0         | 16800    | TSN 0    | 16800                     |           | 16202     |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                     | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                          |           |                 |          |                           |           |              |                  |
| 32-204                                                                     | RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT               |           |                 |          |                           |           |              | Component ATA:32 |
| PN:2317-3004-001                                                           | MOS                                                      | 23-Apr-20 |                 | TSN 0    |                           |           |              | LIFE LIMIT       |
| SN:1768437/006                                                             | HRS                                                      | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                      | 0         | 16800           | TSN 0    | 16800                     |           | 16202        |                  |
| PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03 |                                                          |           |                 |          |                           |           |              |                  |
| 32-21-00-001 <sup>S</sup>                                                  | GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR           |           |                 |          |                           |           |              | Service ATA:32   |
|                                                                            | MOS                                                      | 13-Mar-26 | 12 (+1m/-1m)    |          |                           |           |              |                  |
|                                                                            | HRS                                                      | 1221:24   |                 |          |                           |           |              |                  |
|                                                                            | AFL                                                      | 564       |                 |          |                           |           |              |                  |
| PKG:80                                                                     |                                                          |           |                 |          |                           |           |              |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                          |           |                 |          |                           |           |              |                  |
| 32-21-00-003                                                               | LUBRICATION OF NOSE LANDING GEAR                         |           |                 |          |                           |           |              | Service ATA:32   |
|                                                                            | MOS                                                      | 13-Mar-26 | 12 (+1m/-1m)    | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30)  |                  |
|                                                                            | HRS                                                      | 1221:24   |                 |          |                           |           |              |                  |
|                                                                            | AFL                                                      | 564       | 650 (+30/-30)   |          | 1214                      | 1244      | 616 (+30)    |                  |
| PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00                             |                                                          |           |                 |          |                           |           |              |                  |
| 32-21-01-001                                                               | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY |           |                 |          |                           |           |              | Service ATA:32   |
| PN:2317-5100-403                                                           | MOS                                                      | EFF       | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL         |
| SN:00592                                                                   | HRS                                                      |           |                 |          |                           |           |              |                  |
|                                                                            | AFL                                                      | EFF       | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00                             |                                                          |           |                 |          |                           |           |              |                  |
| 32-21-02                                                                   | NLG RETRACTION ACTUATOR                                  |           |                 |          |                           |           |              | Component ATA:32 |
| PN:2117-1000-401                                                           | MOS/MSC                                                  | 23-Apr-20 | O/C             | TSN 0    |                           |           |              |                  |
| SN:00587                                                                   | HRS                                                      | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                      | 0         |                 | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-21-02, AMM 32-21-02PROC. REF: AMM 32-21-02, AMM 32-21-02 |                                                          |           |                 |          |                           |           |              |                  |
| 32-21-03                                                                   | NLG DOWNLOCK ACTUATOR                                    |           |                 |          |                           |           |              | Component ATA:32 |
| PN:2117-2000-401                                                           | MOS/MSC                                                  | 23-Apr-20 | O/C             | TSN 0    |                           |           |              |                  |
| SN:00575                                                                   | HRS                                                      | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                                            | AFL                                                      | 0         |                 | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 32-21-03, AMM 32-21-03PROC. REF: AMM 32-21-03, AMM 32-21-03 |                                                          |           |                 |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                          | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------|---------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                              |                                                               |           |                 |          |                           |           |              |                  |
| 32-21-04-001                                       | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY    |           |                 |          |                           |           |              | Service ATA:32   |
| PN:2317-6500-403                                   | MOS                                                           | EFF       | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL         |
| SN:00569                                           | HRS                                                           |           |                 |          |                           |           |              |                  |
|                                                    | AFL                                                           | EFF       | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00     |                                                               |           |                 |          |                           |           |              |                  |
| 32-21-05-001                                       | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER  |           |                 |          |                           |           |              | Service ATA:32   |
| PN:2317-5170-403                                   | MOS                                                           | EFF       | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL         |
| SN:00595                                           | HRS                                                           |           |                 |          |                           |           |              |                  |
|                                                    | AFL                                                           | EFF       | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00     |                                                               |           |                 |          |                           |           |              |                  |
| 32-21-05-004                                       | SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER                 |           |                 |          |                           |           |              | Service ATA:32   |
|                                                    | MOS                                                           | 13-Mar-26 | 12 (+1m/-1m)    | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30)  |                  |
|                                                    | HRS                                                           | 1221:24   |                 |          |                           |           |              |                  |
|                                                    | AFL                                                           | 564       | 650 (+30/-30)   |          | 1214                      | 1244      | 616 (+30)    |                  |
| PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03     |                                                               |           |                 |          |                           |           |              |                  |
| 32-21-06-005 <sup>S</sup>                          | VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER               |           |                 |          |                           |           |              | Service ATA:32   |
|                                                    | MOS                                                           | 13-Mar-26 | 12 (+1m/-1m)    |          |                           |           |              |                  |
|                                                    | HRS                                                           | 1221:24   |                 |          |                           |           |              |                  |
|                                                    | AFL                                                           | 564       |                 |          |                           |           |              |                  |
|                                                    |                                                               |           |                 |          |                           |           |              | PKG:80           |
| PROC. REF: AMM 32-21-06PROC. REF: AMM 32-21-06     |                                                               |           |                 |          |                           |           |              |                  |
| 32-21-09-001                                       | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY |           |                 |          |                           |           |              | Service ATA:32   |
| PN:2317-6000-403                                   | MOS                                                           | EFF       | 120 (+1m/-1m)   |          | 23-Apr-30 *               | 23-May-30 | 1364 d (+30) | OVERHAUL         |
| SN:000578                                          | HRS                                                           |           |                 |          |                           |           |              |                  |
|                                                    | AFL                                                           | EFF       | 12000 (+30/-30) |          | 12000 *                   | 12030     | 11402 (+30)  |                  |
| PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00     |                                                               |           |                 |          |                           |           |              |                  |
| 32-23-03                                           | NLG DOOR - TORQUE TUBE ASSEMBLY                               |           |                 |          |                           |           |              | Component ATA:32 |
| PN:505-19741-403                                   | MOS/MSC                                                       | 23-Apr-20 | O/C             | TSN 0    |                           |           |              |                  |
| SN:0001064418                                      | HRS                                                           | 0         |                 | TSN 0    |                           |           |              |                  |
|                                                    | AFL                                                           | 0         |                 | TSN 0    |                           |           |              |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                               |           |                 |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                 |           |          |          |                           |           |           |                  |
| 32-300                                                                     | LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3000-409                                                           | MOS/MSC                                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01246                                                                   | HRS                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-300                                                                     | RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3000-409                                                           | MOS/MSC                                                         | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01244                                                                   | HRS                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-301                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER                |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3034-501                                                           | MOS                                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1745624/004                                                             | HRS                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-301                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER               |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3034-501                                                           | MOS                                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770309/002                                                             | HRS                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-302                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON  |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3001-003                                                           | MOS/MSC                                                         | 23-Apr-20 | N/A      |          |                           |           |           |                  |
| SN:1766216/004                                                             | HRS                                                             | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-302                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3001-003                                                           | MOS/MSC                                                         | 23-Apr-20 | N/A      |          |                           |           |           |                  |
| SN:1766216/006                                                             | HRS                                                             | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                         |           |          |          |                           |           |           |                  |
| 32-303                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER  |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3027-901                                                           | MOS/MSC                                                 | 23-Apr-20 | N/A      |          |                           |           |           |                  |
| SN:17023                                                                   | HRS                                                     | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                           |           |           |                  |
| 32-303                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3027-901                                                           | MOS/MSC                                                 | 23-Apr-20 | N/A      |          |                           |           |           |                  |
| SN:17022                                                                   | HRS                                                     | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                           |           |           |                  |
| 32-304                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD             |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3008-901                                                           | MOS                                                     | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:87006/0035                                                              | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                     | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                           |           |           |                  |
| 32-304                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD            |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3008-901                                                           | MOS                                                     | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:87006/0013                                                              | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                     | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                           |           |           |                  |
| 32-305                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3009-007                                                           | MOS                                                     | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1755710/005                                                             | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                     | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                           |           |           |                  |
| 32-305                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3009-007                                                           | MOS                                                     | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1755710/018                                                             | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                     | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                 |           |          |          |                           |           |           |                  |
| 32-306                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN             |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3019-003                                                           | MOS/MSC                                                         | 23-Apr-20 | N/A      |          |                           |           |           | LIFE LIMIT       |
| SN:1754045/002                                                             | HRS                                                             | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-306                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN            |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3019-003                                                           | MOS/MSC                                                         | 23-Apr-20 | N/A      |          |                           |           |           | LIFE LIMIT       |
| SN:1754045/008                                                             | HRS                                                             | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-307                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE  |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3007-003                                                           | MOS/MSC                                                         | 23-Apr-20 | N/A      |          |                           |           |           | LIFE LIMIT       |
| SN:1757625/005                                                             | HRS                                                             | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-307                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3007-003                                                           | MOS/MSC                                                         | 23-Apr-20 | N/A      |          |                           |           |           | LIFE LIMIT       |
| SN:1757625/015                                                             | HRS                                                             | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-308                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3011-001                                                           | MOS                                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1753671/016                                                             | HRS                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |
| 32-308                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3011-001                                                           | MOS                                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1753671/004                                                             | HRS                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                             | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                      |           |          |          |                           |           |           |                  |
| 32-309                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3013-001                                                           | MOS                                                  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1759064/002                                                             | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                  | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                      |           |          |          |                           |           |           |                  |
| 32-309                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3013-001                                                           | MOS                                                  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1759064/005                                                             | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                  | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                      |           |          |          |                           |           |           |                  |
| 32-31-01                                                                   | LANDING GEAR CONTROL LEVER                           |           |          |          |                           |           |           | Component ATA:32 |
| PN:827101-13                                                               | MOS/MSC                                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0377                                                                    | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-31-01, AMM 32-31-01PROC. REF: AMM 32-31-01, AMM 32-31-01 |                                                      |           |          |          |                           |           |           |                  |
| 32-31-04                                                                   | CENTER FUSELAGE LANDING GEAR SELECTOR VALVE          |           |          |          |                           |           |           | Component ATA:32 |
| PN:7342-1                                                                  | MOS/MSC                                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0582T                                                                   | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-31-04, AMM 32-31-04PROC. REF: AMM 32-31-04, AMM 32-31-04 |                                                      |           |          |          |                           |           |           |                  |
| 32-31-05                                                                   | LH MLG UPLOCK BOX ASSY                               |           |          |          |                           |           |           | Component ATA:32 |
| PN:2617-1000-403                                                           | MOS/MSC                                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01415                                                                   | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-31-05, AMM 32-31-05PROC. REF: AMM 32-31-05, AMM 32-31-05 |                                                      |           |          |          |                           |           |           |                  |
| 32-31-05                                                                   | NLG UPLOCK BOX ASSY                                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2617-1000-403                                                           | MOS/MSC                                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01416                                                                   | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-31-05, AMM 32-31-05PROC. REF: AMM 32-31-05, AMM 32-31-05 |                                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                        |           |          |          |                           |           |           |                  |
| 32-31-05                                                                   | RH MLG UPLOCK BOX ASSY                                 |           |          |          |                           |           |           | Component ATA:32 |
| PN:2617-1000-404                                                           | MOS/MSC                                                | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00730                                                                   | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-31-05, AMM 32-31-05PROC. REF: AMM 32-31-05, AMM 32-31-05 |                                                        |           |          |          |                           |           |           |                  |
| 32-310                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3015-001                                                           | MOS                                                    | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1768960/011                                                             | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                        |           |          |          |                           |           |           |                  |
| 32-310                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT     |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3015-001                                                           | MOS                                                    | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1759924/015                                                             | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         | 12000    | TSN 0    | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                        |           |          |          |                           |           |           |                  |
| 32-311                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END        |           |          |          |                           |           |           | Component ATA:32 |
| PN:MTMKS14ALGA1                                                            | MOS                                                    | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:01244                                                                   | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         | 10500    | TSN 0    | 10500                     |           | 9902      |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                        |           |          |          |                           |           |           |                  |
| 32-311                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END       |           |          |          |                           |           |           | Component ATA:32 |
| PN:MTMKS14ALGA1                                                            | MOS                                                    | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:01243                                                                   | HRS                                                    | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         | 10500    | TSN 0    | 10500                     |           | 9902      |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                        |           |          |          |                           |           |           |                  |
| 32-312                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3027-901                                                           | MOS                                                    | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:17023                                                                   | HRS                                                    | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                    | 0         | 12000    |          | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                |           |          |          |                           |           |           |                  |
| 32-312                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER        |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3027-901                                                           | MOS                                                            | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:17022                                                                   | HRS                                                            | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                            | 0         | 12000    |          | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |          |                           |           |           |                  |
| 32-313                                                                     | LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT         |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3029-001                                                           | MOS                                                            | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:02518                                                                   | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                            | 0         | 28000    | TSN 0    | 28000                     |           | 27402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |          |                           |           |           |                  |
| 32-313                                                                     | RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT        |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-3029-001                                                           | MOS                                                            | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:02511                                                                   | HRS                                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                            | 0         | 28000    | TSN 0    | 28000                     |           | 27402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |          |                           |           |           |                  |
| 32-314                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN            |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3019-003                                                           | MOS                                                            | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:1754045/002                                                             | HRS                                                            | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                            | 0         | 12000    |          | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |          |                           |           |           |                  |
| 32-314                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN           |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3019-003                                                           | MOS                                                            | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:1754045/008                                                             | HRS                                                            | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                            | 0         | 12000    |          | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |          |                           |           |           |                  |
| 32-315                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE |           |          |          |                           |           |           | Service ATA:32   |
| PN:2117-3007-003                                                           | MOS                                                            | 23-Apr-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:1757625/005                                                             | HRS                                                            | 0         |          |          |                           |           |           |                  |
|                                                                            | AFL                                                            | 0         | 12000    |          | 12000                     |           | 11402     |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                             | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                  |           |                |          |                           |           |             |                  |
| 32-315                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE  |           |                |          |                           |           |             | Service ATA:32   |
| PN:2117-3007-003                                                           | MOS                                                              | 23-Apr-20 |                |          |                           |           |             | LIFE LIMIT       |
| SN:1757625/015                                                             | HRS                                                              | 0         |                |          |                           |           |             |                  |
|                                                                            | AFL                                                              | 0         | 12000          |          | 12000                     |           | 11402       |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                           |           |             |                  |
| 32-316                                                                     | DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON   |           |                |          |                           |           |             | Service ATA:32   |
| PN:2117-3001-003                                                           | MOS                                                              | 23-Apr-20 |                |          |                           |           |             | LIFE LIMIT       |
| SN:1766216/004                                                             | HRS                                                              | 0         |                |          |                           |           |             |                  |
|                                                                            | AFL                                                              | 0         | 12000          |          | 12000                     |           | 11402       |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                           |           |             |                  |
| 32-316                                                                     | DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON  |           |                |          |                           |           |             | Service ATA:32   |
| PN:2117-3001-003                                                           | MOS                                                              | 23-Apr-20 |                |          |                           |           |             | LIFE LIMIT       |
| SN:1766216/006                                                             | HRS                                                              | 0         |                |          |                           |           |             |                  |
|                                                                            | AFL                                                              | 0         | 12000          |          | 12000                     |           | 11402       |                  |
| PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02 |                                                                  |           |                |          |                           |           |             |                  |
| 32-35-00-001                                                               | FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM      |           |                |          |                           |           |             | Service ATA:32   |
|                                                                            | MOS                                                              | 13-Mar-26 | 24 (+30d/-30d) | Adj 6d   | 19-Mar-28                 | 18-Apr-28 | 599 d (+30) | AIRWORTHINESS    |
|                                                                            | HRS                                                              | 1221:24   | 1600 (+30/-30) |          | 2821:24                   | 2851:24   | 1526 (+30)  |                  |
|                                                                            | AFL                                                              | 564       |                |          |                           |           |             |                  |
| PROC. REF: AMM 32-35-00PROC. REF: AMM 32-35-00                             |                                                                  |           |                |          |                           |           |             |                  |
| 32-35-00-002                                                               | GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES |           |                |          |                           |           |             | Service ATA:32   |
|                                                                            | MOS                                                              | 13-Mar-26 | 24 (+30d/-30d) | Adj 6d   | 19-Mar-28                 | 18-Apr-28 | 599 d (+30) | AIRWORTHINESS    |
|                                                                            | HRS                                                              | 1221:24   | 1600 (+30/-30) |          | 2821:24                   | 2851:24   | 1526 (+30)  |                  |
|                                                                            | AFL                                                              | 564       |                |          |                           |           |             |                  |
| PROC. REF: AMM 32-35-00PROC. REF: AMM 32-35-00                             |                                                                  |           |                |          |                           |           |             |                  |
| 32-35-02                                                                   | CENTER FUSELAGE FREE FALL VALVE                                  |           |                |          |                           |           |             | Component ATA:32 |
| PN:7343-2                                                                  | MOS/MSC                                                          | 23-Apr-20 | O/C            | TSN 0    |                           |           |             |                  |
| SN:0537T                                                                   | HRS                                                              | 0         |                | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                              | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 32-35-02, AMM 32-35-02PROC. REF: AMM 32-35-02, AMM 32-35-02 |                                                                  |           |                |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                  |           |          |          |                           |           |           |                  |
| 32-400                                                                     | NOSE LANDING GEAR SHOCK STRUT                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5100-403                                                           | MOS/MSC                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00592                                                                   | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |                                                  |           |          |          |                           |           |           |                  |
| 32-401                                                                     | NOSE LANDING GEAR SHOCK STRUT AXLE BOLT          |           |          |          |                           |           |           | Component ATA:32 |
| PN:2310-1144-005                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:00977                                                                   | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |                                                  |           |          |          |                           |           |           |                  |
| 32-402                                                                     | NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT |           |          |          |                           |           |           | Component ATA:32 |
| PN:2310-1173-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1758365/004                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-06, AMM 32-21-06PROC. REF: AMM 32-21-06, AMM 32-21-06 |                                                  |           |          |          |                           |           |           |                  |
| 32-403                                                                     | LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN    |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5105-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1743175/004                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |                                                  |           |          |          |                           |           |           |                  |
| 32-403                                                                     | RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN   |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5105-001                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1743175/016                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |                                                  |           |          |          |                           |           |           |                  |
| 32-404                                                                     | NOSE LANDING GEAR SHOCK STRUT MAIN FITTING       |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5301-503                                                           | MOS                                              | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1755200/001                                                             | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01 |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                 |           |          |          |                           |           |           |                  |
| 32-405                                                                     | NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER     |           |          |          |                           |           |           | Component ATA:32 |
| PN:2117-4000-403                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:00637                                                                   | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-06, AMM 32-21-06PROC. REF: AMM 32-21-06, AMM 32-21-06 |                                                 |           |          |          |                           |           |           |                  |
| 32-406                                                                     | NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE        |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5101-001                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1762689/001                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01 |                                                 |           |          |          |                           |           |           |                  |
| 32-407                                                                     | LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5201-001                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1774000/008                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07 |                                                 |           |          |          |                           |           |           |                  |
| 32-407                                                                     | UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5201-001                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770247/005                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07 |                                                 |           |          |          |                           |           |           |                  |
| 32-408                                                                     | NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN    |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6003-001                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1729581/010                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                                 |           |          |          |                           |           |           |                  |
| 32-409                                                                     | NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2310-1165-001                                                           | MOS                                             | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1738364/015                                                             | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                             | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07 |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                        | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                             |           |                |          |                           |           |           |                  |
| 32-41-00                                                                   | BRAKE CONTROL UNIT                          |           |                |          |                           |           |           | Component ATA:32 |
| PN:DAP00100-11                                                             | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:501760706                                                               | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-01, AMM 32-41-01PROC. REF: AMM 32-41-01, AMM 32-41-01 |                                             |           |                |          |                           |           |           |                  |
| 32-41-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM       |           |                |          |                           |           |           | Service ATA:32   |
|                                                                            | MOS                                         | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                         | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-41-00PROC. REF: AMM 32-41-00                             |                                             |           |                |          |                           |           |           |                  |
| PKG:50                                                                     |                                             |           |                |          |                           |           |           |                  |
| 32-41-01                                                                   | BRAKE CONTROL UNIT TRAY                     |           |                |          |                           |           |           | Component ATA:32 |
| PN:DAP00134-01                                                             | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:1387                                                                    | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-01, AMM 32-41-01PROC. REF: AMM 32-41-01, AMM 32-41-01 |                                             |           |                |          |                           |           |           |                  |
| 32-41-02                                                                   | LH BRAKE PEDAL TRANSDUCER                   |           |                |          |                           |           |           | Component ATA:32 |
| PN:Q3008                                                                   | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:345897                                                                  | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-02, AMM 32-41-02PROC. REF: AMM 32-41-02, AMM 32-41-02 |                                             |           |                |          |                           |           |           |                  |
| 32-41-02                                                                   | RH BRAKE PEDAL TRANSDUCER                   |           |                |          |                           |           |           | Component ATA:32 |
| PN:Q3008                                                                   | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:345898                                                                  | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-02, AMM 32-41-02PROC. REF: AMM 32-41-02, AMM 32-41-02 |                                             |           |                |          |                           |           |           |                  |
| 32-41-02-001                                                               | OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER |           |                |          |                           |           |           | Service ATA:32   |
|                                                                            | MOS/MSC                                     | 23-Apr-20 | O/C            |          |                           |           |           |                  |
|                                                                            | HRS                                         | 0         |                |          |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |                                             |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                        | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                             |           |                |          |                           |           |           |                  |
| 32-41-02-001                                                               | OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER |           |                |          |                           |           |           | Service ATA:32   |
|                                                                            | MOS/MSC                                     | 23-Apr-20 | O/C            |          |                           |           |           |                  |
|                                                                            | HRS                                         | 0         |                |          |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |                                             |           |                |          |                           |           |           |                  |
| 32-41-02-002 <sup>S</sup>                                                  | FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER  |           |                |          |                           |           |           | Service ATA:32   |
|                                                                            | MOS                                         | 01-Mar-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                         | 0         | 1600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                         |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |                                             |           |                |          |                           |           |           |                  |
| 32-41-02-002 <sup>S</sup>                                                  | FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER  |           |                |          |                           |           |           | Service ATA:32   |
|                                                                            | MOS                                         | 01-Mar-20 |                |          |                           |           |           |                  |
|                                                                            | HRS                                         | 0         | 1600 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL                                         |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02                             |                                             |           |                |          |                           |           |           |                  |
| 32-41-06                                                                   | LH MLG WHEEL SPEED TRANSDUCER               |           |                |          |                           |           |           | Component ATA:32 |
| PN:DAP00103-01                                                             | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:002TJ                                                                   | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-06, AMM 32-41-06PROC. REF: AMM 32-41-06, AMM 32-41-06 |                                             |           |                |          |                           |           |           |                  |
| 32-41-06                                                                   | RH MLG WHEEL SPEED TRANSDUCER               |           |                |          |                           |           |           | Component ATA:32 |
| PN:DAP00103-01                                                             | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:001TJ                                                                   | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-06, AMM 32-41-06PROC. REF: AMM 32-41-06, AMM 32-41-06 |                                             |           |                |          |                           |           |           |                  |
| 32-41-07                                                                   | BRAKE CONTROL MODULE                        |           |                |          |                           |           |           | Component ATA:32 |
| PN:DAP00101-02                                                             | MOS/MSC                                     | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:148TK                                                                   | HRS                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                         | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-41-07, AMM 32-41-07PROC. REF: AMM 32-41-07, AMM 32-41-07 |                                             |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                                        | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                                                                              |                                                             |           |                |          |                           |           |           |                  |
| 32-410                                                                                                                             | NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN          |           |                |          |                           |           |           | Component ATA:32 |
| PN:57675-1                                                                                                                         | MOS                                                         | 23-Apr-20 |                | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:01309                                                                                                                           | HRS                                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                         | 0         | 11200          | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07                                                         |                                                             |           |                |          |                           |           |           |                  |
| 32-411                                                                                                                             | NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT              |           |                |          |                           |           |           | Component ATA:32 |
| PN:2310-1183-001                                                                                                                   | MOS                                                         | 23-Apr-20 |                | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:00788                                                                                                                           | HRS                                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                         | 0         | 11200          | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07                                                         |                                                             |           |                |          |                           |           |           |                  |
| 32-412                                                                                                                             | NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK            |           |                |          |                           |           |           | Component ATA:32 |
| PN:2317-5191-001                                                                                                                   | MOS                                                         | 23-Apr-20 |                | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1770668/004                                                                                                                     | HRS                                                         | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                         | 0         | 11200          | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03 |                                                             |           |                |          |                           |           |           |                  |
| 32-43-00-001 <sup>S</sup>                                                                                                          | FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM         |           |                |          |                           |           |           | Service ATA:32   |
|                                                                                                                                    | MOS                                                         | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                         | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                         | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00                                                                                     |                                                             |           |                |          |                           |           |           | PKG:50           |
| 32-43-01-001 <sup>S</sup>                                                                                                          | GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM |           |                |          |                           |           |           | Service ATA:32   |
|                                                                                                                                    | MOS                                                         | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                         | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                         | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00                                                                                     |                                                             |           |                |          |                           |           |           | PKG:50           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                  |           |          |          |                           |           |           |                  |
| 32-43-02                                                                   | PRESSURE SWITCH                                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00108-01                                                             | MOS/MSC                                          | 12-Dec-25 | O/C      | TSN 6    |                           |           |           |                  |
| SN:183ZA                                                                   | HRS                                              | 1179:24   |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 546       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-12-03, AMM 29-12-03PROC. REF: AMM 29-12-03, AMM 29-12-03 |                                                  |           |          |          |                           |           |           |                  |
| 32-43-04                                                                   | EMERGENCY/PARKING BRAKE ACCUMULATOR              |           |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00106-01                                                             | MOS/MSC                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:609                                                                     | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-43-04, AMM 32-43-04PROC. REF: AMM 32-43-04, AMM 32-43-04 |                                                  |           |          |          |                           |           |           |                  |
| 32-43-05                                                                   | EMERGENCY/PARKING BRAKE VALVE                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00107-01                                                             | MOS/MSC                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:100TD                                                                   | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-43-02PROC. REF: AMM 32-43-02                             |                                                  |           |          |          |                           |           |           |                  |
| 32-43-08                                                                   | THERMAL RELIEF VALVE                             |           |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00110-01                                                             | MOS/MSC                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:737                                                                     | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-43-08, AMM 32-43-08PROC. REF: AMM 32-43-08, AMM 32-43-08 |                                                  |           |          |          |                           |           |           |                  |
| 32-43-10                                                                   | EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE       |           |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00202-01                                                             | MOS/MSC                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:596                                                                     | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-43-02, AMM 32-43-02PROC. REF: AMM 32-43-02, AMM 32-43-02 |                                                  |           |          |          |                           |           |           |                  |
| 32-43-11                                                                   | FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE |           |          |          |                           |           |           | Component ATA:32 |
| PN:2216-0001-401                                                           | MOS/MSC                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00980                                                                   | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-43-11, AMM 32-43-11PROC. REF: AMM 32-43-11, AMM 32-43-11 |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                       | C/W       | Interval      | TSX/Adj.       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------|-----------|---------------|----------------|---------------------------|-----------|--------------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                                            |           |               |                |                           |           |              |                  |
| 32-43-11-001                                                               | OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE |           |               |                |                           |           |              | Service ATA:32   |
|                                                                            | MOS                                                                        | 19-Mar-24 |               |                |                           |           |              | AIRWORTHINESS    |
|                                                                            | HRS                                                                        | 781:30    | 800 (+30/-30) | Adj 18:30      | 1600                      | 1630      | 304:36 (+30) |                  |
|                                                                            | AFL                                                                        | 364       |               |                |                           |           |              |                  |
| PROC. REF: AMM 32-43-11PROC. REF: AMM 32-43-11                             |                                                                            |           |               |                |                           |           |              |                  |
| 32-45-00                                                                   | LH MAIN WHEEL AND TIRE ASSY                                                |           |               |                |                           |           |              | Component ATA:32 |
| PN:505-19517-611                                                           | MOS/MSC                                                                    | 19-Mar-24 | O/C           | TSO 0          |                           |           |              |                  |
| SN:5080RK                                                                  | HRS                                                                        | 781:30    |               | TSO 0          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 364       |               | TSO 0          |                           |           |              |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |                                                                            |           |               |                |                           |           |              |                  |
| 32-45-00                                                                   | NOSE WHEEL AND TIRE ASSY                                                   |           |               |                |                           |           |              | Component ATA:32 |
| PN:505-19601-607                                                           | MOS/MSC                                                                    | 10-Dec-24 | O/C           | TSR 2          |                           |           |              |                  |
| SN:5038XL                                                                  | HRS                                                                        | 915:06    |               | TSR 0          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 425       |               | TSN 0, TSR 0   |                           |           |              |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |                                                                            |           |               |                |                           |           |              |                  |
| 32-45-00                                                                   | RH MAIN WHEEL AND TIRE ASSY                                                |           |               |                |                           |           |              | Component ATA:32 |
| PN:505-19517-611                                                           | MOS/MSC                                                                    | 12-Dec-25 | O/C           | TSR 0          |                           |           |              |                  |
| SN:5117YF                                                                  | HRS                                                                        | 1179:24   |               | TSR 0          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 546       |               | TSN 282, TSR 0 |                           |           |              |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |                                                                            |           |               |                |                           |           |              |                  |
| 32-45-01                                                                   | LEFT MAIN WHEEL                                                            |           |               |                |                           |           |              | Component ATA:32 |
| PN:PN-UNKNOWN                                                              | MOS/MSC                                                                    | 19-Mar-24 | O/C           | TSO 0          |                           |           |              |                  |
| SN:5080RK                                                                  | HRS                                                                        | 781:30    |               | TSO 0          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 364       |               | TSO 0          |                           |           |              |                  |
| PROC. REF: AMM 32-45-01, AMM 32-45-01PROC. REF: AMM 32-45-01, AMM 32-45-01 |                                                                            |           |               |                |                           |           |              |                  |
| 32-45-01                                                                   | RIGHT MAIN WHEEL                                                           |           |               |                |                           |           |              | Component ATA:32 |
| PN:DAP00098-02                                                             | MOS/MSC                                                                    | 12-Dec-25 | O/C           | TSR 0          |                           |           |              |                  |
| SN:5117YF                                                                  | HRS                                                                        | 1179:24   |               | TSR 0          |                           |           |              |                  |
|                                                                            | AFL                                                                        | 546       |               | TSN 282, TSR 0 |                           |           |              |                  |
| PROC. REF: AMM 32-45-01, AMM 32-45-01PROC. REF: AMM 32-45-01, AMM 32-45-01 |                                                                            |           |               |                |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                           | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |         |                                                               |          |          |                           |           |           |                  |
| 32-45-01-003                                                               |         | RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY |          |          |                           |           |           | Service ATA:32   |
| PN:PN-UNKNOWN                                                              | MOS     | 19-Mar-24                                                     |          |          |                           |           |           |                  |
| SN:5080RK                                                                  | HRS     | 781:30                                                        |          |          |                           |           |           |                  |
|                                                                            | AFL     | 364                                                           | 1500     |          | 1864                      |           | 1266      |                  |
| PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00                             |         |                                                               |          |          |                           |           |           |                  |
| 32-45-01-003                                                               |         | RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY |          |          |                           |           |           | Service ATA:32   |
| PN:DAP00098-02                                                             | MOS     | 12-Dec-25                                                     |          |          |                           |           |           |                  |
| SN:5117YF                                                                  | HRS     | 1179:24                                                       |          |          |                           |           |           |                  |
|                                                                            | AFL     | 546                                                           | 1500     | TAC 282  | 1764                      |           | 1166      |                  |
| PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00                             |         |                                                               |          |          |                           |           |           |                  |
| 32-45-02                                                                   |         | LEFT MAIN WHEEL TIRE                                          |          |          |                           |           |           | Component ATA:32 |
| PN:258K63-2                                                                | MOS/MSC | 19-Mar-24                                                     | O/C      | TSN 0    |                           |           |           |                  |
| SN:30050592                                                                | HRS     | 781:30                                                        |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 364                                                           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |         |                                                               |          |          |                           |           |           |                  |
| 32-45-02                                                                   |         | RIGHT MAIN WHEEL TIRE                                         |          |          |                           |           |           | Component ATA:32 |
| PN:258K63-2                                                                | MOS/MSC | 12-Dec-25                                                     | O/C      | TSN 0    |                           |           |           |                  |
| SN:50760555                                                                | HRS     | 1179:24                                                       |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 546                                                           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02 |         |                                                               |          |          |                           |           |           |                  |
| 32-45-03                                                                   |         | LH MLG HUB CAP                                                |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00131-02                                                             | MOS/MSC | 23-Apr-20                                                     | O/C      | TSN 0    |                           |           |           |                  |
| SN:086TB                                                                   | HRS     | 0                                                             |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                             |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-45-03, AMM 32-45-03PROC. REF: AMM 32-45-03, AMM 32-45-03 |         |                                                               |          |          |                           |           |           |                  |
| 32-45-03                                                                   |         | RH MLG HUB CAP                                                |          |          |                           |           |           | Component ATA:32 |
| PN:DAP00131-02                                                             | MOS/MSC | 23-Apr-20                                                     | O/C      | TSN 0    |                           |           |           |                  |
| SN:087TB                                                                   | HRS     | 0                                                             |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0                                                             |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-45-03, AMM 32-45-03PROC. REF: AMM 32-45-03, AMM 32-45-03 |         |                                                               |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                        | Interval | TSX/Adj.     | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|----------------------------------------------------------------------------|---------|------------------------------------------------------------|----------|--------------|---------------------------|-----------|-----------|-------------|
| ATA 32 - LANDING GEAR                                                      |         |                                                            |          |              |                           |           |           |             |
| 32-45-11                                                                   |         | NOSE WHEEL                                                 |          |              |                           |           | Component | ATA:32      |
| PN:DAP00099-02                                                             | MOS/MSC | 10-Dec-24                                                  | O/C      | TSR 2        |                           |           |           |             |
| SN:5038XL                                                                  | HRS     | 915:06                                                     |          | TSR 0        |                           |           |           |             |
|                                                                            | AFL     | 425                                                        |          | TSN 0, TSR 0 |                           |           |           |             |
| PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11 |         |                                                            |          |              |                           |           |           |             |
| 32-45-11-003                                                               |         | RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY |          |              |                           |           | Service   | ATA:32      |
| PN:DAP00099-02                                                             | MOS     | 10-Dec-24                                                  |          |              |                           |           |           |             |
| SN:5038XL                                                                  | HRS     | 915:06                                                     |          |              |                           |           |           |             |
|                                                                            | AFL     | 425                                                        | 1500     |              | 1925                      |           | 1327      |             |
| PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00                             |         |                                                            |          |              |                           |           |           |             |
| 32-45-12                                                                   |         | NOSE TIRE                                                  |          |              |                           |           | Component | ATA:32      |
| PN:156E23-1                                                                | MOS/MSC | 10-Dec-24                                                  | O/C      | TSN 0        |                           |           |           |             |
| SN:33180656                                                                | HRS     | 915:06                                                     |          | TSN 0        |                           |           |           |             |
|                                                                            | AFL     | 425                                                        |          | TSN 0        |                           |           |           |             |
| PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11 |         |                                                            |          |              |                           |           |           |             |
| 32-45-21                                                                   |         | LH MLG CARBON BRAKE ASSY                                   |          |              |                           |           | Component | ATA:32      |
| PN:DAP00097-04                                                             | MOS/MSC | 23-Apr-20                                                  | O/C      | TSN 0        |                           |           |           |             |
| SN:5036TF                                                                  | HRS     | 0                                                          |          | TSN 0        |                           |           |           |             |
|                                                                            | AFL     | 0                                                          |          | TSN 0        |                           |           |           |             |
| PROC. REF: AMM 32-45-21, AMM 32-45-21PROC. REF: AMM 32-45-21, AMM 32-45-21 |         |                                                            |          |              |                           |           |           |             |
| 32-45-21                                                                   |         | RH MLG CARBON BRAKE ASSY                                   |          |              |                           |           | Component | ATA:32      |
| PN:DAP00097-04                                                             | MOS/MSC | 23-Apr-20                                                  | O/C      | TSN 0        |                           |           |           |             |
| SN:5037TF                                                                  | HRS     | 0                                                          |          | TSN 0        |                           |           |           |             |
|                                                                            | AFL     | 0                                                          |          | TSN 0        |                           |           |           |             |
| PROC. REF: AMM 32-45-21, AMM 32-45-21PROC. REF: AMM 32-45-21, AMM 32-45-21 |         |                                                            |          |              |                           |           |           |             |
| 32-500                                                                     |         | NOSE LANDING GEAR SHOCK ABSORBER                           |          |              |                           |           | Component | ATA:32      |
| PN:2317-5170-403                                                           | MOS/MSC | 23-Apr-20                                                  | O/C      | TSN 0        |                           |           |           |             |
| SN:00595                                                                   | HRS     | 0                                                          |          | TSN 0        |                           |           |           |             |
|                                                                            | AFL     | 0                                                          |          | TSN 0        |                           |           |           |             |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |                                                            |          |              |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                   |           |          |          |                           |           |           |                  |
| 32-501                                                                     | NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK       |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5227-501                                                           | MOS                                               | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1755953/001                                                             | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                   |           |          |          |                           |           |           |                  |
| 32-502                                                                     | NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING    |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5113-005                                                           | MOS                                               | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1768337/004                                                             | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                   |           |          |          |                           |           |           |                  |
| 32-503                                                                     | NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-5237-501                                                           | MOS                                               | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1724654/001                                                             | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                   |           |          |          |                           |           |           |                  |
| 32-600                                                                     | NOSE LANDING GEAR DRAG BRACE                      |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6000-403                                                           | MOS/MSC                                           | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000578                                                                  | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                                   |           |          |          |                           |           |           |                  |
| 32-601                                                                     | NOSE LANDING GEAR UPPER DRAG BRACE                |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6114-501                                                           | MOS                                               | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1769028/001                                                             | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                                   |           |          |          |                           |           |           |                  |
| 32-602                                                                     | NOSE LANDING GEAR LOWER DRAG BRACE                |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6201-001                                                           | MOS                                               | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1650822/007                                                             | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                               | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                               |           |          |          |                           |           |           |                  |
| 32-603                                                                     | LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN  |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6001-001                                                           | MOS                                           | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1739860/006                                                             | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                           |           |           |                  |
| 32-603                                                                     | RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6001-001                                                           | MOS                                           | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1739860/007                                                             | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                           |           |           |                  |
| 32-604                                                                     | NOSE LANDING GEAR DRAG BRACE PIN              |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6003-001                                                           | MOS                                           | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1729581/012                                                             | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                           | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09 |                                               |           |          |          |                           |           |           |                  |
| 32-61-01                                                                   | LH WING PROXIMITY SWITCH                      |           |          |          |                           |           |           | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:51542                                                                   | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                               |           |          |          |                           |           |           |                  |
| 32-61-01                                                                   | NO. 1 LEFT MLG PROXIMITY SWITCH               |           |          |          |                           |           |           | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:51553                                                                   | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                               |           |          |          |                           |           |           |                  |
| 32-61-01                                                                   | NO. 1 NLG PROXIMITY SWITCH                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:52284                                                                   | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                      |           |          |          |                           |           |           |                  |
| 32-61-01                                                                   | NO. 1 RIGHT MLG PROXIMITY SWITCH     |           |          |          |                           |           |           | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:51549                                                                   | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                           |           |           |                  |
| 32-61-01                                                                   | NO. 2 NLG PROXIMITY SWITCH           |           |          |          |                           |           |           | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:51871                                                                   | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                           |           |           |                  |
| 32-61-01                                                                   | RH WING PROXIMITY SWITCH             |           |          |          |                           |           |           | Component ATA:32 |
| PN:80-057-01                                                               | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:51547                                                                   | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                           |           |           |                  |
| 32-700                                                                     | NOSE LANDING GEAR LOCKING STAY       |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6500-403                                                           | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:00569                                                                   | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                      |           |          |          |                           |           |           |                  |
| 32-701                                                                     | NOSE LANDING GEAR UPPER LOCKING STAY |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6521-003                                                           | MOS                                  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1756699/003                                                             | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                      |           |          |          |                           |           |           |                  |
| 32-702                                                                     | NOSE LANDING GEAR LOWER LOCKING STAY |           |          |          |                           |           |           | Component ATA:32 |
| PN:2317-6531-001                                                           | MOS                                  | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1769845/005                                                             | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                      |                                                               |           |          |          |                           |           |           |                  |
| 32-703                                                                     | LOWER NOSE LANDING GEAR LOCKING STAY BOLT                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:2310-1734-001                                                           | MOS                                                           | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1744779/009                                                             | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                                               |           |          |          |                           |           |           |                  |
| 32-703                                                                     | UPPER NOSE LANDING GEAR LOCKING STAY BOLT                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:2310-1734-001                                                           | MOS                                                           | 23-Apr-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:1744779/006                                                             | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         | 11200    | TSN 0    | 11200                     |           | 10602     |                  |
| PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04 |                                                               |           |          |          |                           |           |           |                  |
| ATA 33 - LIGHTS                                                            |                                                               |           |          |          |                           |           |           |                  |
| 33-01-01                                                                   | OVERHEAD LIGHTS CONTROL PANEL                                 |           |          |          |                           |           |           | Component ATA:33 |
| PN:441-45393-001                                                           | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1086                                                                    | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-01-01, AMM 33-01-01PROC. REF: AMM 33-01-01, AMM 33-01-01 |                                                               |           |          |          |                           |           |           |                  |
| 33-12-01                                                                   | COCKPIT DIMMER                                                |           |          |          |                           |           |           | Component ATA:33 |
| PN:81-01760-002                                                            | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1068                                                                    | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-12-01, AMM 33-12-01PROC. REF: AMM 33-12-01, AMM 33-12-01 |                                                               |           |          |          |                           |           |           |                  |
| 33-12-02                                                                   | INSC ILLUM - TEST PANEL                                       |           |          |          |                           |           |           | Component ATA:33 |
| PN:441-42631-003                                                           | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1590                                                                    | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-12-02, AMM 33-12-02PROC. REF: AMM 33-12-02, AMM 33-12-02 |                                                               |           |          |          |                           |           |           |                  |
| 33-13-01                                                                   | LH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY |           |          |          |                           |           |           | Component ATA:33 |
| PN:84075-1                                                                 | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000556                                                                  | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS                                                                                                                    |                                                               |           |          |          |                           |           |           |                  |
| 33-13-01                                                                                                                           | RH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY |           |          |          |                           |           |           | Component ATA:33 |
| PN:84075-2                                                                                                                         | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000587                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                                               |           |          |          |                           |           |           |                  |
| 33-42-01                                                                                                                           | LH LWR FWD TAXI LIGHT ASSY                                    |           |          |          |                           |           |           | Component ATA:33 |
| PN:81017-3                                                                                                                         | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000788                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01 |                                                               |           |          |          |                           |           |           |                  |
| 33-42-01                                                                                                                           | RH LWR FWD TAXI LIGHT ASSY                                    |           |          |          |                           |           |           | Component ATA:33 |
| PN:81017-4                                                                                                                         | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000803                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01PROC. REF: AMM 33-42-01, AMM 33-42-01, AMM 33-42-01, AMM 33-42-01 |                                                               |           |          |          |                           |           |           |                  |
| 33-47-01                                                                                                                           | LEFT LANDING LIGHT ASSY                                       |           |          |          |                           |           |           | Component ATA:33 |
| PN:81017-5                                                                                                                         | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000756                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01 |                                                               |           |          |          |                           |           |           |                  |
| 33-47-01                                                                                                                           | RIGHT LANDING LIGHT ASSY                                      |           |          |          |                           |           |           | Component ATA:33 |
| PN:81017-6                                                                                                                         | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000752                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01PROC. REF: AMM 33-47-01, AMM 33-47-01, AMM 33-47-01, AMM 33-47-01 |                                                               |           |          |          |                           |           |           |                  |
| 33-48-00                                                                                                                           | LEFT WING AFT NAVIGATION LIGHT                                |           |          |          |                           |           |           | Component ATA:33 |
| PN:84004-7                                                                                                                         | MOS/MSC                                                       | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:001343                                                                                                                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                   | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|-----------|-----------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 33 - LIGHTS                                                                                                                    |                                        |           |                 |          |                           |           |                |                  |
| 33-48-00                                                                                                                           | LEFT WING FWD NAVIGATION LIGHT         |           |                 |          |                           |           |                | Component ATA:33 |
| PN:PN                                                                                                                              | MOS/MSC                                | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                    | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                                                                                    | AFL                                    | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                        |           |                 |          |                           |           |                |                  |
| 33-48-00                                                                                                                           | RIGHT WING AFT NAVIGATION LIGHT        |           |                 |          |                           |           |                | Component ATA:33 |
| PN:84004-7                                                                                                                         | MOS/MSC                                | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:001351                                                                                                                          | HRS                                    | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                                                                                    | AFL                                    | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                        |           |                 |          |                           |           |                |                  |
| 33-48-00                                                                                                                           | RIGHT WING FWD NAVIGATION LIGHT        |           |                 |          |                           |           |                | Component ATA:33 |
| PN:PN                                                                                                                              | MOS/MSC                                | 23-Apr-20 | O/C             | TSN 0    |                           |           |                |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                    | 0         |                 | TSN 0    |                           |           |                |                  |
|                                                                                                                                    | AFL                                    | 0         |                 | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02 |                                        |           |                 |          |                           |           |                |                  |
| 33-48-00-001                                                                                                                       | DISCARD LEFT WING AFT NAVIGATION LIGHT |           |                 |          |                           |           |                | Service ATA:33   |
| PN:84004-7                                                                                                                         | MOS                                    | 23-Apr-20 |                 |          |                           |           |                |                  |
| SN:001343                                                                                                                          | HRS                                    | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                  |
|                                                                                                                                    | AFL                                    | 0         |                 |          |                           |           |                |                  |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00                                                                                     |                                        |           |                 |          |                           |           |                |                  |
| 33-48-00-001                                                                                                                       | LEFT WING FWD NAVIGATION LIGHT         |           |                 |          |                           |           |                | Service ATA:33   |
| PN:PN                                                                                                                              | MOS                                    | 23-Apr-20 |                 |          |                           |           |                |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                    | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                  |
|                                                                                                                                    | AFL                                    | 0         |                 |          |                           |           |                |                  |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00                                                                                     |                                        |           |                 |          |                           |           |                |                  |
| 33-48-00-001                                                                                                                       | RIGHT WING AFT NAVIGATION LIGHT        |           |                 |          |                           |           |                | Service ATA:33   |
| PN:84004-7                                                                                                                         | MOS                                    | 23-Apr-20 |                 |          |                           |           |                |                  |
| SN:001351                                                                                                                          | HRS                                    | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                  |
|                                                                                                                                    | AFL                                    | 0         |                 |          |                           |           |                |                  |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00                                                                                     |                                        |           |                 |          |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                      | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|------------------------------------------------|-----------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 33 - LIGHTS                                |                                                           |           |                 |          |                           |           |                |                |
| 33-48-00-001                                   | RIGHT WING FWD NAVIGATION LIGHT                           |           |                 |          |                           |           |                | Service ATA:33 |
| PN:PN                                          | MOS                                                       | 23-Apr-20 |                 |          |                           |           |                |                |
| SN:UNKNOWN                                     | HRS                                                       | 0         | 12000 (+30/-30) |          | 12000                     | 12030     | 10704:36 (+30) |                |
|                                                | AFL                                                       | 0         |                 |          |                           |           |                |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                           |           |                 |          |                           |           |                |                |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION LEFT WING AFT NAVIGATION LIGHT  |           |                 |          |                           |           |                | Service ATA:33 |
|                                                | MOS                                                       | 13-Mar-26 |                 |          |                           |           |                |                |
|                                                | HRS                                                       | 1221:24   | 2400 (+30/-30)  |          |                           |           |                |                |
|                                                | AFL                                                       | 564       |                 |          |                           |           |                |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                           |           |                 |          |                           |           |                |                |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION LEFT WING FWD NAVIGATION LIGHT  |           |                 |          |                           |           |                | Service ATA:33 |
|                                                | MOS                                                       | 13-Mar-26 |                 |          |                           |           |                |                |
|                                                | HRS                                                       | 1221:24   | 2400 (+30/-30)  |          |                           |           |                |                |
|                                                | AFL                                                       | 564       |                 |          |                           |           |                |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                           |           |                 |          |                           |           |                |                |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION RIGHT WING AFT NAVIGATION LIGHT |           |                 |          |                           |           |                | Service ATA:33 |
|                                                | MOS                                                       | 13-Mar-26 |                 |          |                           |           |                |                |
|                                                | HRS                                                       | 1221:24   | 2400 (+30/-30)  |          |                           |           |                |                |
|                                                | AFL                                                       | 564       |                 |          |                           |           |                |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                           |           |                 |          |                           |           |                |                |
| 33-48-00-002 <sup>S</sup>                      | GENERAL VISUAL INSPECTION RIGHT WING FWD NAVIGATION LIGHT |           |                 |          |                           |           |                | Service ATA:33 |
|                                                | MOS                                                       | 13-Mar-26 |                 |          |                           |           |                |                |
|                                                | HRS                                                       | 1221:24   | 2400 (+30/-30)  |          |                           |           |                |                |
|                                                | AFL                                                       | 564       |                 |          |                           |           |                |                |
| PROC. REF: AMM 33-48-00PROC. REF: AMM 33-48-00 |                                                           |           |                 |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                                                                                                                                            | Unit                                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 33 - LIGHTS                                                                                                                                                                                                                                    |                                              |           |                |          |                           |           |               |                  |
| 33-49-00                                                                                                                                                                                                                                           | NO. 1 STROBE LIGHT                           |           |                |          |                           |           |               | Component ATA:33 |
| PN:84036-3                                                                                                                                                                                                                                         | MOS/MSC                                      | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:000703                                                                                                                                                                                                                                          | HRS                                          | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                                                                                                                                                                                                    | AFL                                          | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02 |                                              |           |                |          |                           |           |               |                  |
| 33-49-00                                                                                                                                                                                                                                           | NO. 2 STROBE LIGHT                           |           |                |          |                           |           |               | Component ATA:33 |
| PN:84036-4                                                                                                                                                                                                                                         | MOS/MSC                                      | 23-Apr-20 | O/C            | TSN 0    |                           |           |               |                  |
| SN:001277                                                                                                                                                                                                                                          | HRS                                          | 0         |                | TSN 0    |                           |           |               |                  |
|                                                                                                                                                                                                                                                    | AFL                                          | 0         |                | TSN 0    |                           |           |               |                  |
| PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02, AMM 33-49-02 |                                              |           |                |          |                           |           |               |                  |
| 33-49-00-001                                                                                                                                                                                                                                       | DISCARD NO. 1 STROBE LIGHT                   |           |                |          |                           |           |               | Service ATA:33   |
| PN:84036-3                                                                                                                                                                                                                                         | MOS                                          | 23-Apr-20 |                |          |                           |           |               |                  |
| SN:000703                                                                                                                                                                                                                                          | HRS                                          | 0         | 8000 (+30/-30) |          | 8000                      | 8030      | 6704:36 (+30) |                  |
|                                                                                                                                                                                                                                                    | AFL                                          | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                                                                                                                                                                                                     |                                              |           |                |          |                           |           |               |                  |
| 33-49-00-001                                                                                                                                                                                                                                       | DISCARD NO. 2 STROBE LIGHT                   |           |                |          |                           |           |               | Service ATA:33   |
| PN:84036-4                                                                                                                                                                                                                                         | MOS                                          | 23-Apr-20 |                |          |                           |           |               |                  |
| SN:001277                                                                                                                                                                                                                                          | HRS                                          | 0         | 8000 (+30/-30) |          | 8000                      | 8030      | 6704:36 (+30) |                  |
|                                                                                                                                                                                                                                                    | AFL                                          | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                                                                                                                                                                                                     |                                              |           |                |          |                           |           |               |                  |
| 33-49-00-002 <sup>S</sup>                                                                                                                                                                                                                          | GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT |           |                |          |                           |           |               | Service ATA:33   |
|                                                                                                                                                                                                                                                    | MOS                                          | 23-Apr-20 |                |          |                           |           |               |                  |
|                                                                                                                                                                                                                                                    | HRS                                          | 0         | 2400 (+30/-30) |          |                           |           |               |                  |
|                                                                                                                                                                                                                                                    | AFL                                          | 0         |                |          |                           |           |               |                  |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                                                                                                                                                                                                     |                                              |           |                |          |                           |           |               |                  |

PKG:20

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W                                                                                                     | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|---------------------------------------------------------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS                                                            |         |                                                                                                         |                |          |                           |           |           |                  |
| 33-49-00-002 <sup>S</sup>                                                  |         | GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT                                                            |                |          |                           |           |           | Service ATA:33   |
|                                                                            | MOS     | 23-Apr-20                                                                                               |                |          |                           |           |           |                  |
|                                                                            | HRS     | 0                                                                                                       | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                            | AFL     | 0                                                                                                       |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-49-00PROC. REF: AMM 33-49-00                             |         |                                                                                                         |                |          |                           |           |           | PKG:20           |
|                                                                            |         |                                                                                                         |                |          |                           |           |           |                  |
| 33-52-01                                                                   |         | EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR)                                                          |                |          |                           |           |           | Component ATA:33 |
| PN:7450LS-00                                                               | MOS/MSC | 05-Jun-25                                                                                               | O/C            | TSR 1    |                           |           |           |                  |
| SN:005514                                                                  | HRS     | 1036:06                                                                                                 |                | TSR 0    |                           |           |           |                  |
|                                                                            | AFL     | 481                                                                                                     |                | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 33-52-01, AMM 33-52-01PROC. REF: AMM 33-52-01, AMM 33-52-01 |         |                                                                                                         |                |          |                           |           |           |                  |
|                                                                            |         |                                                                                                         |                |          |                           |           |           |                  |
| 33-52-01                                                                   |         | EMERGENCY LIGHT BATTERY 2 (CENTER COMPT)                                                                |                |          |                           |           |           | Component ATA:33 |
| PN:7450LS-00                                                               | MOS/MSC | 10-Dec-24                                                                                               | O/C            | TSR 1    |                           |           |           |                  |
| SN:005277                                                                  | HRS     | 915:06                                                                                                  |                | TSR 0    |                           |           |           |                  |
|                                                                            | AFL     | 425                                                                                                     |                | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 33-52-01, AMM 33-52-01PROC. REF: AMM 33-52-01, AMM 33-52-01 |         |                                                                                                         |                |          |                           |           |           |                  |
|                                                                            |         |                                                                                                         |                |          |                           |           |           |                  |
| 33-52-01-001                                                               |         | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH BE AEROSPACE BATTERY) |                |          |                           |           |           | Service ATA:33   |
| PN:7450LS-00                                                               | MOS     | 13-Mar-26                                                                                               | 12             |          | 13-Mar-27                 |           | 227 d     |                  |
| SN:005514                                                                  | HRS     | 1221:24                                                                                                 |                |          |                           |           |           |                  |
|                                                                            | AFL     | 564                                                                                                     |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01                             |         |                                                                                                         |                |          |                           |           |           |                  |
|                                                                            |         |                                                                                                         |                |          |                           |           |           |                  |
| 33-52-01-001                                                               |         | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH BE AEROSPACE BATTERY)       |                |          |                           |           |           | Service ATA:33   |
| PN:7450LS-00                                                               | MOS     | 13-Mar-26                                                                                               | 12             |          | 13-Mar-27                 |           | 227 d     |                  |
| SN:005277                                                                  | HRS     | 1221:24                                                                                                 |                |          |                           |           |           |                  |
|                                                                            | AFL     | 564                                                                                                     |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01                             |         |                                                                                                         |                |          |                           |           |           |                  |
|                                                                            |         |                                                                                                         |                |          |                           |           |           |                  |
| 33-52-01-002                                                               |         | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) (AIRCRAFT WITH DLE BATTERY)          |                |          |                           |           |           | Service ATA:33   |
| PN:7450LS-00                                                               | MOS/MSC |                                                                                                         | N/A            |          |                           |           |           |                  |
| SN:005514                                                                  | HRS     |                                                                                                         |                |          |                           |           |           |                  |
|                                                                            | AFL     |                                                                                                         |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01                             |         |                                                                                                         |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                                     | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS                                    |                                                                                          |           |                |          |                           |           |           |                  |
| 33-52-01-002                                       | FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) (AIRCRAFT WITH DLE BATTERY) |           |                |          |                           |           |           | Service ATA:33   |
| PN:7450LS-00                                       | MOS/MSC                                                                                  |           | N/A            |          |                           |           |           |                  |
| SN:005277                                          | HRS                                                                                      |           |                |          |                           |           |           |                  |
|                                                    | AFL                                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01     |                                                                                          |           |                |          |                           |           |           |                  |
| 33-52-01-003                                       | DISCARD OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR)                                |           |                |          |                           |           |           | Service ATA:33   |
| PN:7450LS-00                                       | MOS/MSC                                                                                  |           | N/A            |          |                           |           |           |                  |
| SN:005514                                          | HRS                                                                                      |           |                |          |                           |           |           |                  |
|                                                    | AFL                                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01     |                                                                                          |           |                |          |                           |           |           |                  |
| 33-52-01-003                                       | DISCARD OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT)                                      |           |                |          |                           |           |           | Service ATA:33   |
| PN:7450LS-00                                       | MOS/MSC                                                                                  |           | N/A            |          |                           |           |           |                  |
| SN:005277                                          | HRS                                                                                      |           |                |          |                           |           |           |                  |
|                                                    | AFL                                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-01PROC. REF: AMM 33-52-01     |                                                                                          |           |                |          |                           |           |           |                  |
| 33-52-17                                           | EMERGENCY LIGHTING IMPACT SWITCH                                                         |           |                |          |                           |           |           | Component ATA:33 |
| PN:7212-4-000                                      | MOS/MSC                                                                                  | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:0470                                            | HRS                                                                                      | 0         |                | TSN 0    |                           |           |           |                  |
|                                                    | AFL                                                                                      | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                          |           |                |          |                           |           |           |                  |
| 33-52-17-001 <sup>S</sup>                          | OPERATIONAL CHECK OF INERTIAL SWITCH                                                     |           |                |          |                           |           |           | Service ATA:33   |
|                                                    | MOS                                                                                      | 01-Nov-19 |                |          |                           |           |           |                  |
|                                                    | HRS                                                                                      | 0         | 1600 (+30/-30) |          |                           |           |           |                  |
|                                                    | AFL                                                                                      |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 33-52-17PROC. REF: AMM 33-52-17     |                                                                                          |           |                |          |                           |           |           |                  |
| PKG:10                                             |                                                                                          |           |                |          |                           |           |           |                  |
| ATA 34 - NAVIGATION                                |                                                                                          |           |                |          |                           |           |           |                  |
| 34-00-03                                           | NO.1 IASP SMART PROBE                                                                    |           |                |          |                           |           |           | Component ATA:34 |
| PN:2015L-4B                                        | MOS/MSC                                                                                  | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:1374                                            | HRS                                                                                      | 0         |                | TSN 0    |                           |           |           |                  |
|                                                    | AFL                                                                                      | 0         |                | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                                         | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                                                                                |                                                              |           |              |          |                           |           |             |                  |
| PROC. REF: AMM 34-15-07, AMM 34-15-07PROC. REF: AMM 34-15-07, AMM 34-15-07                                                         |                                                              |           |              |          |                           |           |             |                  |
|                                                                                                                                    |                                                              |           |              |          |                           |           |             |                  |
| 34-00-03                                                                                                                           | NO.2 IASP SMART PROBE                                        |           |              |          |                           |           |             | Component ATA:34 |
| PN:2015L-4B                                                                                                                        | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:1375                                                                                                                            | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                                                                                    | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-15-07, AMM 34-15-07PROC. REF: AMM 34-15-07, AMM 34-15-07                                                         |                                                              |           |              |          |                           |           |             |                  |
|                                                                                                                                    |                                                              |           |              |          |                           |           |             |                  |
| 34-10-01                                                                                                                           | RADIO ALTIMETER                                              |           |              |          |                           |           |             | Component ATA:34 |
| PN:066-01153-0101                                                                                                                  | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:KRA405B-21396                                                                                                                   | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                                                                                    | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-31-01, AMM 34-31-01, AMM 34-31-01, AMM 34-31-01PROC. REF: AMM 34-31-01, AMM 34-31-01, AMM 34-31-01, AMM 34-31-01 |                                                              |           |              |          |                           |           |             |                  |
|                                                                                                                                    |                                                              |           |              |          |                           |           |             |                  |
| 34-10-02                                                                                                                           | LEFT RADIO ALTIMETER TRANSMIT ANTENNA                        |           |              |          |                           |           |             | Component ATA:34 |
| PN:S67-2002-45                                                                                                                     | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:553-12353                                                                                                                       | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                                                                                    | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-31-02, AMM 34-31-02PROC. REF: AMM 34-31-02, AMM 34-31-02                                                         |                                                              |           |              |          |                           |           |             |                  |
|                                                                                                                                    |                                                              |           |              |          |                           |           |             |                  |
| 34-10-02                                                                                                                           | RIGHT RADIO ALTIMETER RECEIVE ANTENNA                        |           |              |          |                           |           |             | Component ATA:34 |
| PN:S67-2002-45                                                                                                                     | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:553-11970                                                                                                                       | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                                                                                    | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-31-02, AMM 34-31-02PROC. REF: AMM 34-31-02, AMM 34-31-02                                                         |                                                              |           |              |          |                           |           |             |                  |
|                                                                                                                                    |                                                              |           |              |          |                           |           |             |                  |
| 34-11-00                                                                                                                           | IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT              |           |              |          |                           |           |             | Component ATA:34 |
| PN:C16786DA01                                                                                                                      | MOS/MSC                                                      | 23-Apr-20 | O/C          | TSN 0    |                           |           |             |                  |
| SN:C16786031446                                                                                                                    | HRS                                                          | 0         |              | TSN 0    |                           |           |             |                  |
|                                                                                                                                    | AFL                                                          | 0         |              | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-11-01, AMM 34-11-01PROC. REF: AMM 34-11-01, AMM 34-11-01                                                         |                                                              |           |              |          |                           |           |             |                  |
|                                                                                                                                    |                                                              |           |              |          |                           |           |             |                  |
| 34-11-00-001                                                                                                                       | FUNCTIONAL CHECK OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT |           |              |          |                           |           |             | Service ATA:34   |
| PN:C16786DA01                                                                                                                      | MOS                                                          | 13-Mar-26 | 24 (+1m/-1m) |          | 13-Mar-28                 | 13-Apr-28 | 593 d (+31) |                  |
| SN:C16786031446                                                                                                                    | HRS                                                          | 1221:24   |              |          |                           |           |             |                  |
|                                                                                                                                    | AFL                                                          | 564       |              |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                    | C/W       | Interval     | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------------------------|-----------|--------------|------------|---------------------------|-----------|--------------|------------------|
| ATA 34 - NAVIGATION                                                        |                                                                         |           |              |            |                           |           |              |                  |
| PROC. REF: AMM 34-11-00PROC. REF: AMM 34-11-00                             |                                                                         |           |              |            |                           |           |              |                  |
| 34-11-02                                                                   | PITOT/STATIC PROBE                                                      |           |              |            |                           |           |              | Component ATA:34 |
| PN:0856UT4                                                                 | MOS/MSC                                                                 | 03-Mar-22 | O/C          | TSN 23     |                           |           |              |                  |
| SN:313286                                                                  | HRS                                                                     | 278:18    |              | TSN 278:18 |                           |           |              |                  |
|                                                                            | AFL                                                                     | 139       |              | TSN 139    |                           |           |              |                  |
| PROC. REF: AMM 34-11-02, AMM 34-11-02PROC. REF: AMM 34-11-02, AMM 34-11-02 |                                                                         |           |              |            |                           |           |              |                  |
| 34-11-02-001                                                               | RESTORATION (CLEANING) OF PITOT-STATIC PROBE                            |           |              |            |                           |           |              | Service ATA:34   |
| PN:0856UT4                                                                 | MOS                                                                     | 12-Dec-25 | 24 (+1m/-1m) |            | 12-Dec-27                 | 12-Jan-28 | 501 d (+31)  |                  |
| SN:313286                                                                  | HRS                                                                     | 1179:24   |              |            |                           |           |              |                  |
|                                                                            | AFL                                                                     | 546       |              |            |                           |           |              |                  |
| PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02                             |                                                                         |           |              |            |                           |           |              |                  |
| 34-15-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF AIR DATA SYSTEM                                     |           |              |            |                           |           |              | Service ATA:34   |
|                                                                            | MOS                                                                     | 13-Mar-26 | 24 (+1m/-1m) |            |                           |           |              |                  |
|                                                                            | HRS                                                                     | 1221:24   |              |            |                           |           |              |                  |
|                                                                            | AFL                                                                     | 564       |              |            |                           |           |              |                  |
| PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00                             |                                                                         |           |              |            |                           |           |              |                  |
| 34-15-00-002                                                               | SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS |           |              |            |                           |           |              | Service ATA:34   |
|                                                                            | MOS                                                                     | 31-Mar-25 | 60 (+1m/-1m) | Adj 23d    | 23-Apr-30                 | 23-May-30 | 1364 d (+30) |                  |
|                                                                            | HRS                                                                     | 987:24    |              |            |                           |           |              |                  |
|                                                                            | AFL                                                                     | 456       |              |            |                           |           |              |                  |
| PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00                             |                                                                         |           |              |            |                           |           |              |                  |
| 34-15-00-003                                                               | DETAILED INSPECTION OF IASP                                             |           |              |            |                           |           |              | Service ATA:34   |
|                                                                            | MOS                                                                     | 13-Mar-26 | 24 (+1m/-1m) | Adj 6d     | 19-Mar-28                 | 19-Apr-28 | 599 d (+31)  |                  |
|                                                                            | HRS                                                                     | 1221:24   |              |            |                           |           |              |                  |
|                                                                            | AFL                                                                     | 564       |              |            |                           |           |              |                  |
| PROC. REF: AMM 34-15-07PROC. REF: AMM 34-15-07                             |                                                                         |           |              |            |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                     | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                                        |                                                                          |           |              |          |                           |           |           |                  |
| 34-20-01                                                                   | LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM                          |           |              |          |                           |           |           | Component ATA:34 |
| PN:011-03732-00                                                            | MOS/MSC                                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:45T002935                                                               | HRS                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-21-01, AMM 34-21-01PROC. REF: AMM 34-21-01, AMM 34-21-01 |                                                                          |           |              |          |                           |           |           |                  |
| 34-20-01                                                                   | RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM                          |           |              |          |                           |           |           | Component ATA:34 |
| PN:011-03732-00                                                            | MOS/MSC                                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:45T002997                                                               | HRS                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-21-01, AMM 34-21-01PROC. REF: AMM 34-21-01, AMM 34-21-01 |                                                                          |           |              |          |                           |           |           |                  |
| 34-20-02                                                                   | LEFT MAGNETOMETER                                                        |           |              |          |                           |           |           | Component ATA:34 |
| PN:011-00870-10                                                            | MOS/MSC                                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:1CM026387                                                               | HRS                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-21-02, AMM 34-21-02PROC. REF: AMM 34-21-02, AMM 34-21-02 |                                                                          |           |              |          |                           |           |           |                  |
| 34-20-02                                                                   | RIGHT MAGNETOMETER                                                       |           |              |          |                           |           |           | Component ATA:34 |
| PN:011-00870-10                                                            | MOS/MSC                                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:1CM026290                                                               | HRS                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-21-02, AMM 34-21-02PROC. REF: AMM 34-21-02, AMM 34-21-02 |                                                                          |           |              |          |                           |           |           |                  |
| 34-21-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER |           |              |          |                           |           |           | Service ATA:34   |
| PN:011-00870-10                                                            | MOS                                                                      | 13-Mar-26 | 36 (+1m/-1m) |          |                           |           |           |                  |
| SN:1CM026387                                                               | HRS                                                                      | 1221:24   |              |          |                           |           |           |                  |
|                                                                            | AFL                                                                      | 564       |              |          |                           |           |           |                  |
| PROC. REF: AMM 34-21-02PROC. REF: AMM 34-21-02                             |                                                                          |           |              |          |                           |           |           | PKG:82           |
| 34-21-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER |           |              |          |                           |           |           | Service ATA:34   |
| PN:011-00870-10                                                            | MOS                                                                      | 13-Mar-26 | 36 (+1m/-1m) |          |                           |           |           |                  |
| SN:1CM026290                                                               | HRS                                                                      | 1221:24   |              |          |                           |           |           |                  |
|                                                                            | AFL                                                                      | 564       |              |          |                           |           |           |                  |
| PROC. REF: AMM 34-21-02PROC. REF: AMM 34-21-02                             |                                                                          |           |              |          |                           |           |           | PKG:82           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                     | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                                        |                                                          |           |              |          |                           |           |           |                  |
| 34-23-00                                                                   | MAGNETIC COMPASS                                         |           |              |          |                           |           |           | Component ATA:34 |
| PN:KCA0120W                                                                | MOS/MSC                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:BU9940919                                                               | HRS                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-23-01, AMM 34-23-01PROC. REF: AMM 34-23-01, AMM 34-23-01 |                                                          |           |              |          |                           |           |           |                  |
| 34-23-00-001 <sup>S</sup>                                                  | FUNCTIONAL CHECK OF STANDBY COMPASS                      |           |              |          |                           |           |           | Service ATA:34   |
| PN:KCA0120W                                                                | MOS                                                      | 13-Mar-26 | 36 (+1m/-1m) |          |                           |           |           |                  |
| SN:BU9940919                                                               | HRS                                                      | 1221:24   |              |          |                           |           |           |                  |
|                                                                            | AFL                                                      | 564       |              |          |                           |           |           |                  |
| PROC. REF: AMM 34-23-00PROC. REF: AMM 34-23-00                             |                                                          |           |              |          |                           |           |           |                  |
| PKG:82                                                                     |                                                          |           |              |          |                           |           |           |                  |
| 34-30-01                                                                   | LEFT VOR/LOC 2 & 3 BLADE ANTENNA                         |           |              |          |                           |           |           | Component ATA:34 |
| PN:S65-247170                                                              | MOS/MSC                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:173-6397                                                                | HRS                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-32-03, AMM 34-32-03PROC. REF: AMM 34-32-03, AMM 34-32-03 |                                                          |           |              |          |                           |           |           |                  |
| 34-30-01                                                                   | RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE                      |           |              |          |                           |           |           | Component ATA:34 |
| PN:S65-247170                                                              | MOS/MSC                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:173-6402                                                                | HRS                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-32-03, AMM 34-32-03PROC. REF: AMM 34-32-03, AMM 34-32-03 |                                                          |           |              |          |                           |           |           |                  |
| 34-40-01                                                                   | GDL-69A SATELLITE WEATHER AND RADIO RECEIVER             |           |              |          |                           |           |           | Component ATA:34 |
| PN:011-03177-10                                                            | MOS/MSC                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:3NV004606                                                               | HRS                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                      | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-57-01, AMM 34-57-01PROC. REF: AMM 34-57-01, AMM 34-57-01 |                                                          |           |              |          |                           |           |           |                  |
| 34-40-02                                                                   | AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA |           |              |          |                           |           |           | Component ATA:34 |
| PN:013-00245-00                                                            | MOS/MSC                                                  | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:20203                                                                   | HRS                                                      | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                      | 0         |              | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                                                                    |         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02 |         |           |          |          |                           |           |           |                  |
|                                                                                                        |         |           |          |          |                           |           |           |                  |
| 34-40-02 FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA                                      |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:013-00245-00                                                                                        | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:19903                                                                                               | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02 |         |           |          |          |                           |           |           |                  |
|                                                                                                        |         |           |          |          |                           |           |           |                  |
| 34-40-03 WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA                                                    |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-03997-00                                                                                        | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:4RR001351                                                                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-42-01, AMM 34-42-01PROC. REF: AMM 34-42-01, AMM 34-42-01                             |         |           |          |          |                           |           |           |                  |
|                                                                                                        |         |           |          |          |                           |           |           |                  |
| 34-40-07 NOSE WEATHER RADAR ANTENNA                                                                    |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:117-00254-01                                                                                        | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:3656                                                                                                | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-42-01, AMM 34-42-01PROC. REF: AMM 34-42-01, AMM 34-42-01                             |         |           |          |          |                           |           |           |                  |
|                                                                                                        |         |           |          |          |                           |           |           |                  |
| 34-43-01 TRAFFIC PROCESSOR UNIT - GTS 8XXX                                                             |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-01997-00                                                                                        | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:20S011160                                                                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-43-01, AMM 34-43-01PROC. REF: AMM 34-43-01, AMM 34-43-01                             |         |           |          |          |                           |           |           |                  |
|                                                                                                        |         |           |          |          |                           |           |           |                  |
| 34-43-02 LOWER TCAS L BAND ANTENNA                                                                     |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-01346-00                                                                                        | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:124016041                                                                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-43-02, AMM 34-43-02PROC. REF: AMM 34-43-02, AMM 34-43-02                             |         |           |          |          |                           |           |           |                  |
|                                                                                                        |         |           |          |          |                           |           |           |                  |
| 34-43-05 TOP TCAS DIRECTIONAL ANTENNA                                                                  |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-01346-00                                                                                        | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:124015963                                                                                           | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL     | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                                        |                                              |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-43-05, AMM 34-43-05PROC. REF: AMM 34-43-05, AMM 34-43-05 |                                              |           |          |          |                           |           |           |                  |
|                                                                            |                                              |           |          |          |                           |           |           |                  |
| 34-50-02                                                                   | BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-5366-7L                                                             | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:261-133858                                                              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-52-02, AMM 34-52-02PROC. REF: AMM 34-52-02, AMM 34-52-02 |                                              |           |          |          |                           |           |           |                  |
|                                                                            |                                              |           |          |          |                           |           |           |                  |
| 34-50-02                                                                   | TOP XPDR L BAND ANTENNA                      |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-5366-7L                                                             | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:261-133756                                                              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-52-02, AMM 34-52-02PROC. REF: AMM 34-52-02, AMM 34-52-02 |                                              |           |          |          |                           |           |           |                  |
|                                                                            |                                              |           |          |          |                           |           |           |                  |
| 34-50-03                                                                   | KN 63 DISTANCE MEASURING UNIT                |           |          |          |                           |           |           | Component ATA:34 |
| PN:066-01070-0001                                                          | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:43761                                                                   | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-51-01, AMM 34-51-01PROC. REF: AMM 34-51-01, AMM 34-51-01 |                                              |           |          |          |                           |           |           |                  |
|                                                                            |                                              |           |          |          |                           |           |           |                  |
| 34-50-05                                                                   | PHASING COUPLER                              |           |          |          |                           |           |           | Component ATA:34 |
| PN:SSPD-113-10                                                             | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:9967                                                                    | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-32-01, AMM 34-32-01PROC. REF: AMM 34-32-01, AMM 34-32-01 |                                              |           |          |          |                           |           |           |                  |
|                                                                            |                                              |           |          |          |                           |           |           |                  |
| 34-50-06                                                                   | MARKER BEACON ANTENNA                        |           |          |          |                           |           |           | Component ATA:34 |
| PN:S35-1000-2                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:102-13714                                                               | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-32-04, AMM 34-32-04PROC. REF: AMM 34-32-04, AMM 34-32-04 |                                              |           |          |          |                           |           |           |                  |
|                                                                            |                                              |           |          |          |                           |           |           |                  |
| 34-50-10                                                                   | GSR 56 IRIDIUM UNIT                          |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-02268-00                                                            | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1NZ008425                                                               | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                                                                                                                                                        |         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-15-01, AMM 23-15-01PROC. REF: AMM 23-15-01, AMM 23-15-01                                                                                                                 |         |           |          |          |                           |           |           |                  |
|                                                                                                                                                                                            |         |           |          |          |                           |           |           |                  |
| 34-50-11IRIDIUM SATCOM ANTENNA                                                                                                                                                             |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-1575-109                                                                                                                                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:430-16381                                                                                                                                                                               | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-15-03, AMM 23-15-03PROC. REF: AMM 23-15-03, AMM 23-15-03                                                                                                                 |         |           |          |          |                           |           |           |                  |
|                                                                                                                                                                                            |         |           |          |          |                           |           |           |                  |
| 34-50-12GDL 59 DATALINK MANAGEMENT UNIT                                                                                                                                                    |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-01746-03                                                                                                                                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:57F000207                                                                                                                                                                               | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-23-01, AMM 23-23-01PROC. REF: AMM 23-23-01, AMM 23-23-01                                                                                                                 |         |           |          |          |                           |           |           |                  |
|                                                                                                                                                                                            |         |           |          |          |                           |           |           |                  |
| 34-50-13WI-FI - DATALINK ANTENNA                                                                                                                                                           |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-5366-71S                                                                                                                                                                            | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:258-6654                                                                                                                                                                                | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11 |         |           |          |          |                           |           |           |                  |
|                                                                                                                                                                                            |         |           |          |          |                           |           |           |                  |
| 34-51-02NO. 1 DME L BAND ANTENNA                                                                                                                                                           |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-5366-7L                                                                                                                                                                             | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:261-133859                                                                                                                                                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-51-02, AMM 34-51-02PROC. REF: AMM 34-51-02, AMM 34-51-02                                                                                                                 |         |           |          |          |                           |           |           |                  |
|                                                                                                                                                                                            |         |           |          |          |                           |           |           |                  |
| 34-52-00NO. 1 TRANSPONDER                                                                                                                                                                  |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-01997-00                                                                                                                                                                            | MOS/MSC | 19-Mar-24 | O/C      |          |                           |           |           |                  |
| SN:20S011204                                                                                                                                                                               | HRS     | 781:30    |          |          |                           |           |           |                  |
|                                                                                                                                                                                            | AFL     | 364       |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-52-01, AMM 34-52-01PROC. REF: AMM 34-52-01, AMM 34-52-01                                                                                                                 |         |           |          |          |                           |           |           |                  |
|                                                                                                                                                                                            |         |           |          |          |                           |           |           |                  |
| 34-52-00NO. 2 TRANSPONDER                                                                                                                                                                  |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:011-01997-00                                                                                                                                                                            | MOS/MSC | 19-Mar-24 | O/C      |          |                           |           |           |                  |
| SN:20S011160                                                                                                                                                                               | HRS     | 781:30    |          |          |                           |           |           |                  |
|                                                                                                                                                                                            | AFL     | 364       |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 34 - NAVIGATION                                                        |                                                              |           |                |          |                           |           |             |                  |
| PROC. REF: AMM 34-52-01, AMM 34-52-01PROC. REF: AMM 34-52-01, AMM 34-52-01 |                                                              |           |                |          |                           |           |             |                  |
|                                                                            |                                                              |           |                |          |                           |           |             |                  |
| 34-52-00-001                                                               | FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM                 |           |                |          |                           |           |             | Service ATA:34   |
| PN:011-01997-00                                                            | MOS                                                          | 13-Mar-26 | 24             |          | 04-Mar-28                 |           | 584 d       |                  |
| SN:20S011204                                                               | HRS                                                          | 1221:24   |                |          |                           |           |             |                  |
|                                                                            | AFL                                                          | 564       |                |          |                           |           |             |                  |
| Calibration Date: : 04-Mar-26                                              |                                                              |           |                |          |                           |           |             |                  |
| PROC. REF: AMM 34-52-00PROC. REF: AMM 34-52-00                             |                                                              |           |                |          |                           |           |             |                  |
|                                                                            |                                                              |           |                |          |                           |           |             |                  |
| 34-52-00-001                                                               | FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM                 |           |                |          |                           |           |             | Service ATA:34   |
| PN:011-01997-00                                                            | MOS                                                          | 13-Mar-26 | 24             |          | 04-Mar-28                 |           | 584 d       |                  |
| SN:20S011160                                                               | HRS                                                          | 1221:24   |                |          |                           |           |             |                  |
|                                                                            | AFL                                                          | 564       |                |          |                           |           |             |                  |
| Calibration Date: : 04-Mar-26                                              |                                                              |           |                |          |                           |           |             |                  |
| PROC. REF: AMM 34-52-00PROC. REF: AMM 34-52-00                             |                                                              |           |                |          |                           |           |             |                  |
|                                                                            |                                                              |           |                |          |                           |           |             |                  |
| 34-52-04                                                                   | LOWER COAXIAL UNIT                                           |           |                |          |                           |           |             | Component ATA:34 |
| PN:D2-729B005                                                              | MOS/MSC                                                      | 23-Apr-20 | O/C            | TSN 0    |                           |           |             |                  |
| SN:595411                                                                  | HRS                                                          | 0         |                | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                          | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-52-04, AMM 34-52-04PROC. REF: AMM 34-52-04, AMM 34-52-04 |                                                              |           |                |          |                           |           |             |                  |
|                                                                            |                                                              |           |                |          |                           |           |             |                  |
| 34-52-04                                                                   | UPPER COAXIAL UNIT                                           |           |                |          |                           |           |             | Component ATA:34 |
| PN:D2-729B005                                                              | MOS/MSC                                                      | 23-Apr-20 | O/C            | TSN 0    |                           |           |             |                  |
| SN:595398                                                                  | HRS                                                          | 0         |                | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                          | 0         |                | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 34-52-04, AMM 34-52-04PROC. REF: AMM 34-52-04, AMM 34-52-04 |                                                              |           |                |          |                           |           |             |                  |
|                                                                            |                                                              |           |                |          |                           |           |             |                  |
| ATA 35 - OXYGEN                                                            |                                                              |           |                |          |                           |           |             |                  |
| 35-00-00-001                                                               | FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE |           |                |          |                           |           |             | Service ATA:35   |
|                                                                            | MOS                                                          | 13-Mar-26 | 36 (+30d/-30d) | Adj 4d   | 17-Mar-29                 | 16-Apr-29 | 962 d (+30) | AIRWORTHINESS    |
|                                                                            | HRS                                                          | 1221:24   | 2400 (+30/-30) |          | 3621:24                   | 3651:24   | 2326 (+30)  |                  |
|                                                                            | AFL                                                          | 564       |                |          |                           |           |             |                  |
| PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00                             |                                                              |           |                |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                   | C/W                                                 | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------------------------------------|----------------------------------------|-----------------------------------------------------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 35 - OXYGEN                                                            |                                        |                                                     |              |          |                           |           |           |                |
| 35-01-00-001                                                               | <sup>S</sup>                           | FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION |              |          |                           |           |           | Service ATA:35 |
|                                                                            | MOS                                    | 31-Mar-25                                           | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                                            | HRS                                    | 987:24                                              |              |          |                           |           |           |                |
|                                                                            | AFL                                    | 456                                                 |              |          |                           |           |           |                |
| PROC. REF: AMM 35-01-02PROC. REF: AMM 35-01-02                             |                                        |                                                     |              |          |                           |           |           | PKG:84         |
| 35-01-02                                                                   | OXYGEN CYLINDER TRANSDUCER             |                                                     |              |          |                           |           | Component | ATA:35         |
| PN:4441125-000                                                             | MOS/MSC                                | 23-Apr-20                                           | O/C          | TSN 0    |                           |           |           |                |
| SN:8527-4-5                                                                | HRS                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
|                                                                            | AFL                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
| PROC. REF: AMM 35-01-02, AMM 35-01-02PROC. REF: AMM 35-01-02, AMM 35-01-02 |                                        |                                                     |              |          |                           |           |           |                |
| 35-01-05                                                                   | CREW OXYGEN SYSTEM LOW PRESSURE SWITCH |                                                     |              |          |                           |           | Component | ATA:35         |
| PN:P24151                                                                  | MOS/MSC                                | 23-Apr-20                                           | O/C          | TSN 0    |                           |           |           |                |
| SN:0733                                                                    | HRS                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
|                                                                            | AFL                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
| PROC. REF: AMM 35-01-05, AMM 35-01-05PROC. REF: AMM 35-01-05, AMM 35-01-05 |                                        |                                                     |              |          |                           |           |           |                |
| 35-01-06                                                                   | OXYGEN SYSTEM CONTROL PANEL            |                                                     |              |          |                           |           | Component | ATA:35         |
| PN:441-40945-002                                                           | MOS/MSC                                | 23-Apr-20                                           | O/C          | TSN 0    |                           |           |           |                |
| SN:1012                                                                    | HRS                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
|                                                                            | AFL                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
| PROC. REF: AMM 35-01-06, AMM 35-01-06PROC. REF: AMM 35-01-06, AMM 35-01-06 |                                        |                                                     |              |          |                           |           |           |                |
| 35-01-07                                                                   | COCKPIT SENSOR                         |                                                     |              |          |                           |           | Component | ATA:35         |
| PN:P24099                                                                  | MOS/MSC                                | 23-Apr-20                                           | O/C          | TSN 0    |                           |           |           |                |
| SN:D19082237                                                               | HRS                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
|                                                                            | AFL                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
| PROC. REF: AMM 35-01-07, AMM 35-01-07PROC. REF: AMM 35-01-07, AMM 35-01-07 |                                        |                                                     |              |          |                           |           |           |                |
| 35-01-09                                                                   | ALTITUDE COMPENSATING REGULATOR        |                                                     |              |          |                           |           | Component | ATA:35         |
| PN:4421135-001                                                             | MOS/MSC                                | 23-Apr-20                                           | O/C          | TSN 0    |                           |           |           |                |
| SN:00578                                                                   | HRS                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
|                                                                            | AFL                                    | 0                                                   |              | TSN 0    |                           |           |           |                |
| PROC. REF: AMM 35-01-09, AMM 35-01-09PROC. REF: AMM 35-01-09, AMM 35-01-09 |                                        |                                                     |              |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                              | C/W       | Interval | TSX/Adj.      | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------|-----------|----------|---------------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN                                                            |                                                   |           |          |               |                           |           |           |                  |
| 35-01-10                                                                   | LOW PRESSURE OXYGEN VALVE                         |           |          |               |                           |           |           | Component ATA:35 |
| PN:4421132-109                                                             | MOS/MSC                                           | 23-Apr-20 | O/C      | TSN 0         |                           |           |           |                  |
| SN:01129                                                                   | HRS                                               | 0         |          | TSN 0         |                           |           |           |                  |
|                                                                            | AFL                                               | 0         |          | TSN 0         |                           |           |           |                  |
| PROC. REF: AMM 35-01-10, AMM 35-01-10PROC. REF: AMM 35-01-10, AMM 35-01-10 |                                                   |           |          |               |                           |           |           |                  |
| 35-02-01                                                                   | OXYGEN CYLINDER                                   |           |          |               |                           |           |           | Component ATA:35 |
| PN:4441122-077                                                             | MOS/MSC                                           | 19-Mar-24 | H/T      | TSN 96, TSO 1 |                           |           |           |                  |
| SN:788632601                                                               | HRS                                               | 781:30    |          | TSO 0         |                           |           |           |                  |
|                                                                            | AFL                                               | 364       |          | TSO 0         |                           |           |           |                  |
| PROC. REF: AMM 35-02-01, AMM 35-02-01PROC. REF: AMM 35-02-01, AMM 35-02-01 |                                                   |           |          |               |                           |           |           |                  |
| 35-02-01-001                                                               | FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR     |           |          |               |                           |           |           | Service ATA:35   |
| PN:4441122-077                                                             | MOS                                               | 01-Jan-24 | 60       |               | 01-Jan-29                 |           | 887 d     |                  |
| SN:788632601                                                               | HRS                                               | 781:30    |          |               |                           |           |           |                  |
|                                                                            | AFL                                               | 364       |          |               |                           |           |           |                  |
| HydroCheck Date: : 01-Jan-24                                               |                                                   |           |          |               |                           |           |           |                  |
| PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01                             |                                                   |           |          |               |                           |           |           |                  |
| 35-02-01-003                                                               | DISCARD OF OXYGEN CYLINDER                        |           |          |               |                           |           |           | Service ATA:35   |
| PN:4441122-077                                                             | MOS                                               | 01-Mar-16 | 180      |               | 01-Mar-31                 |           | 1676 d    | LIFE LIMIT       |
| SN:788632601                                                               | HRS                                               | 781:30    |          |               |                           |           |           |                  |
|                                                                            | AFL                                               | 364       |          |               |                           |           |           |                  |
| Manufacture Date:: 01-Mar-16                                               |                                                   |           |          |               |                           |           |           |                  |
| PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01                             |                                                   |           |          |               |                           |           |           |                  |
| 35-02-01-004                                                               | RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER |           |          |               |                           |           |           | Service ATA:35   |
| PN:4441122-077                                                             | MOS                                               | 01-Jan-24 | 60       |               | 01-Jan-29                 |           | 887 d     |                  |
| SN:788632601                                                               | HRS                                               | 781:30    |          |               |                           |           |           |                  |
|                                                                            | AFL                                               | 364       |          |               |                           |           |           |                  |
| HydroCheck Date: : 01-Jan-24                                               |                                                   |           |          |               |                           |           |           |                  |
| PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01                             |                                                   |           |          |               |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                  | C/W       | Interval       | TSX/Adj.       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------|-----------|----------------|----------------|---------------------------|-----------|-------------|------------------|
| ATA 35 - OXYGEN                                                            |                                                       |           |                |                |                           |           |             |                  |
| 35-02-05                                                                   | OXYGEN PRESSURE REGULATOR                             |           |                |                |                           |           |             | Component ATA:35 |
| PN:2421-14                                                                 | MOS/MSC                                               | 19-Mar-24 | O/C            |                |                           |           |             |                  |
| SN:0938                                                                    | HRS                                                   | 781:30    |                |                |                           |           |             |                  |
|                                                                            | AFL                                                   | 364       |                |                |                           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                       |           |                |                |                           |           |             |                  |
| 35-11-00-001                                                               | OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX |           |                |                |                           |           |             | Service ATA:35   |
|                                                                            | MOS                                                   | 13-Mar-26 | 12 (+30d/-30d) | Adj 18d        | 31-Mar-27                 | 30-Apr-27 | 245 d (+30) | AIRWORTHINESS    |
|                                                                            | HRS                                                   | 1221:24   | 800 (+30/-30)  |                | 2021:24                   | 2051:24   | 726 (+30)   |                  |
|                                                                            | AFL                                                   | 564       |                |                |                           |           |             |                  |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02                             |                                                       |           |                |                |                           |           |             |                  |
| 35-11-01                                                                   | COPILOT OXYGEN MASK STOWAGE BOX                       |           |                |                |                           |           |             | Component ATA:35 |
| PN:MXP603                                                                  | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0          |                           |           |             |                  |
| SN:SE110426                                                                | HRS                                                   | 0         |                | TSN 0          |                           |           |             |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0          |                           |           |             |                  |
| PROC. REF: AMM 35-11-01, AMM 35-11-01PROC. REF: AMM 35-11-01, AMM 35-11-01 |                                                       |           |                |                |                           |           |             |                  |
| 35-11-01                                                                   | PILOT OXYGEN MASK STOWAGE BOX                         |           |                |                |                           |           |             | Component ATA:35 |
| PN:MXP603                                                                  | MOS/MSC                                               | 23-Apr-20 | O/C            | TSN 0          |                           |           |             |                  |
| SN:SE110423                                                                | HRS                                                   | 0         |                | TSN 0          |                           |           |             |                  |
|                                                                            | AFL                                                   | 0         |                | TSN 0          |                           |           |             |                  |
| PROC. REF: AMM 35-11-01, AMM 35-11-01PROC. REF: AMM 35-11-01, AMM 35-11-01 |                                                       |           |                |                |                           |           |             |                  |
| 35-11-02                                                                   | LEFT CREW OXYGEN MASK                                 |           |                |                |                           |           |             | Component ATA:35 |
| PN:MC40-011                                                                | MOS/MSC                                               | 31-Mar-25 | O/C            | TSN 79, TSO 6  |                           |           |             |                  |
| SN:918                                                                     | HRS                                                   | 987:24    |                | TSO 0          |                           |           |             |                  |
|                                                                            | AFL                                                   | 456       |                | TSO 0          |                           |           |             |                  |
| PROC. REF: AMM 35-11-02, AMM 35-11-02PROC. REF: AMM 35-11-02, AMM 35-11-02 |                                                       |           |                |                |                           |           |             |                  |
| 35-11-02                                                                   | RIGHT CREW OXYGEN MASK                                |           |                |                |                           |           |             | Component ATA:35 |
| PN:MC40-011                                                                | MOS/MSC                                               | 31-Mar-25 | O/C            | TSN 105, TSO 5 |                           |           |             |                  |
| SN:1542                                                                    | HRS                                                   | 987:24    |                | TSO 0          |                           |           |             |                  |
|                                                                            | AFL                                                   | 456       |                | TSO 0          |                           |           |             |                  |
| PROC. REF: AMM 35-11-02, AMM 35-11-02PROC. REF: AMM 35-11-02, AMM 35-11-02 |                                                       |           |                |                |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                 | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|------------------------------------------------|------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 35 - OXYGEN                                |                                                      |           |                |          |                           |           |              |                |
| 35-11-02-001                                   | DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK  |           |                |          |                           |           |              | Service ATA:35 |
| PN:MC40-011                                    | MOS/MSC                                              |           | N/A            |          |                           |           |              |                |
| SN:918                                         | HRS                                                  |           |                |          |                           |           |              |                |
|                                                | AFL                                                  |           |                |          |                           |           |              |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                           |           |              |                |
| 35-11-02-001                                   | DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK |           |                |          |                           |           |              | Service ATA:35 |
| PN:MC40-011                                    | MOS/MSC                                              |           | N/A            |          |                           |           |              |                |
| SN:1542                                        | HRS                                                  |           |                |          |                           |           |              |                |
|                                                | AFL                                                  |           |                |          |                           |           |              |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                           |           |              |                |
| 35-11-02-002                                   | RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK      |           |                |          |                           |           |              | Service ATA:35 |
| PN:MC40-011                                    | MOS                                                  | 31-Mar-25 | 72 (+1m/-1m)   | TAC 6    | 30-Sep-30                 | 31-Oct-30 | 1524 d (+31) |                |
| SN:918                                         | HRS                                                  | 987:24    | 3600 (+30/-30) | TAC 0    | 4587:24                   | 4617:24   | 3292 (+30)   |                |
|                                                | AFL                                                  | 456       |                | TAC 0    |                           |           |              |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                           |           |              |                |
| 35-11-02-002                                   | RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK     |           |                |          |                           |           |              | Service ATA:35 |
| PN:MC40-011                                    | MOS                                                  | 31-Mar-25 | 72 (+1m/-1m)   | TAC 5    | 31-Oct-30                 | 30-Nov-30 | 1555 d (+30) |                |
| SN:1542                                        | HRS                                                  | 987:24    | 3600 (+30/-30) | TAC 0    | 4587:24                   | 4617:24   | 3292 (+30)   |                |
|                                                | AFL                                                  | 456       |                | TAC 0    |                           |           |              |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                           |           |              |                |
| 35-11-02-003                                   | DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK  |           |                |          |                           |           |              | Service ATA:35 |
| PN:MC40-011                                    | MOS                                                  | 13-Mar-26 | 12 (+1m/-1m)   | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30)  |                |
| SN:918                                         | HRS                                                  | 1221:24   |                |          |                           |           |              |                |
|                                                | AFL                                                  | 564       |                |          |                           |           |              |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                           |           |              |                |
| 35-11-02-003                                   | DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK |           |                |          |                           |           |              | Service ATA:35 |
| PN:MC40-011                                    | MOS                                                  | 13-Mar-26 | 12 (+1m/-1m)   | Adj 18d  | 31-Mar-27                 | 30-Apr-27 | 245 d (+30)  |                |
| SN:1542                                        | HRS                                                  | 1221:24   |                |          |                           |           |              |                |
|                                                | AFL                                                  | 564       |                |          |                           |           |              |                |
| PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02 |                                                      |           |                |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                        | C/W       | Interval       | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit   | Remaining     | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------------|-----------|----------------|-----------|---------------------------|-------------|---------------|------------------|
| ATA 35 - OXYGEN                                                            |                                                             |           |                |           |                           |             |               |                  |
| 35-11-04                                                                   | #1 CREW GOGGLES                                             |           |                |           |                           |             |               | Component ATA:35 |
| PN:MXG14001                                                                | MOS/MSC                                                     | 23-Apr-20 | O/C            | TSN 0     |                           |             |               |                  |
| SN:NSN                                                                     | HRS                                                         | 0         |                | TSN 0     |                           |             |               |                  |
|                                                                            | AFL                                                         | 0         |                | TSN 0     |                           |             |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                             |           |                |           |                           |             |               |                  |
| 35-11-04                                                                   | #2 CREW GOGGLES                                             |           |                |           |                           |             |               | Component ATA:35 |
| PN:MXG14001                                                                | MOS/MSC                                                     | 23-Apr-20 | O/C            | TSN 0     |                           |             |               |                  |
| SN:NSN                                                                     | HRS                                                         | 0         |                | TSN 0     |                           |             |               |                  |
|                                                                            | AFL                                                         | 0         |                | TSN 0     |                           |             |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                             |           |                |           |                           |             |               |                  |
| 35-11-04-001 <sup>S</sup>                                                  | DETAILED INSPECTION OF CREW GOGGLES                         |           |                |           |                           |             |               | Service ATA:35   |
|                                                                            | MOS                                                         | 13-Mar-26 | 36 (+1m/-1m)   |           |                           |             |               |                  |
|                                                                            | HRS                                                         | 1221:24   |                |           |                           |             |               |                  |
|                                                                            | AFL                                                         | 564       |                |           |                           |             |               |                  |
| PROC. REF: AMM 35-11-04PROC. REF: AMM 35-11-04                             |                                                             |           |                |           |                           |             |               |                  |
| 35-21-00-001                                                               | FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE    |           |                |           |                           |             |               | Service ATA:35   |
|                                                                            | MOS                                                         | 31-Mar-25 | 36 (+30d/-30d) | 31-Mar-28 | 30-Apr-28                 | 611 d (+30) | AIRWORTHINESS |                  |
|                                                                            | HRS                                                         | 987:24    | 2400 (+30/-30) | 3387:24   | 3417:24                   | 2092 (+30)  |               |                  |
|                                                                            | AFL                                                         | 456       |                |           |                           |             |               |                  |
| PROC. REF: AMM 35-21-00PROC. REF: AMM 35-21-00                             |                                                             |           |                |           |                           |             |               |                  |
| 35-21-00-002                                                               | OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE |           |                |           |                           |             |               | Service ATA:35   |
|                                                                            | MOS                                                         | 31-Mar-25 | 36 (+30d/-30d) | 31-Mar-28 | 30-Apr-28                 | 611 d (+30) | AIRWORTHINESS |                  |
|                                                                            | HRS                                                         | 987:24    | 2400 (+30/-30) | 3387:24   | 3417:24                   | 2092 (+30)  |               |                  |
|                                                                            | AFL                                                         | 456       |                |           |                           |             |               |                  |
| PROC. REF: AMM 35-21-00PROC. REF: AMM 35-21-00                             |                                                             |           |                |           |                           |             |               |                  |
| 35-21-01                                                                   | AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER                    |           |                |           |                           |             |               | Component ATA:35 |
| PN:EB1-421048                                                              | MOS/MSC                                                     | 23-Apr-20 | O/C            | TSN 0     |                           |             |               |                  |
| SN:D19090649                                                               | HRS                                                         | 0         |                | TSN 0     |                           |             |               |                  |
|                                                                            | AFL                                                         | 0         |                | TSN 0     |                           |             |               |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                                             |           |                |           |                           |             |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN                                                            |                                            |           |          |          |                           |           |           |                  |
| 35-21-01                                                                   | CENTER FUSELAGE ONE MASK DEPLOYMENT SYSTEM |           |          |          |                           |           |           | Component ATA:35 |
| PN:EB1-421048                                                              | MOS/MSC                                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19090658                                                               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                            |           |          |          |                           |           |           |                  |
| 35-21-01                                                                   | FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER   |           |          |          |                           |           |           | Component ATA:35 |
| PN:EB1-421048                                                              | MOS/MSC                                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19090657                                                               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                            |           |          |          |                           |           |           |                  |
| 35-21-01                                                                   | NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:EB2-421048                                                              | MOS/MSC                                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19101494                                                               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                            |           |          |          |                           |           |           |                  |
| 35-21-01                                                                   | NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:EB2-421048                                                              | MOS/MSC                                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19101492                                                               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                            |           |          |          |                           |           |           |                  |
| 35-21-01                                                                   | NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:EB2-421048                                                              | MOS/MSC                                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19110778                                                               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                            |           |          |          |                           |           |           |                  |
| 35-21-01                                                                   | NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:EB2-421048                                                              | MOS/MSC                                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:D19101491                                                               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01 |                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit                                                                         | C/W                                                    | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|--------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|--------------------------------------------------------|---------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 35 - OXYGEN                                                                                        |                                                                              |                                                        |               |          |                           |           |              |                  |
| 35-21-01-001                                                                                           | <sup>S</sup>                                                                 | DETAILED INSPECTION OF PASSENGER OXYGEN-MASKS ASSEMBLY |               |          |                           |           |              | Service ATA:35   |
|                                                                                                        | MOS                                                                          | 13-Mar-26                                              | 36 (+1m/-1m)  |          |                           |           |              |                  |
|                                                                                                        | HRS                                                                          | 1221:24                                                |               |          |                           |           |              |                  |
|                                                                                                        | AFL                                                                          | 564                                                    |               |          |                           |           |              |                  |
| PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01                                                         |                                                                              |                                                        |               |          |                           |           |              | PKG:82           |
|                                                                                                        |                                                                              |                                                        |               |          |                           |           |              |                  |
| 35-31-01                                                                                               | PBE - PROTECTIVE BREATHING EQUIPMENT                                         |                                                        |               |          |                           |           |              | Component ATA:35 |
| PN:MR-10022NEMB                                                                                        | MOS/MSC                                                                      | 01-Apr-19                                              | H/T           | TSN 0    |                           |           |              |                  |
| SN:E1900850                                                                                            | HRS                                                                          |                                                        |               | TSN 0    |                           |           |              |                  |
|                                                                                                        | AFL                                                                          |                                                        |               | TSN 0    |                           |           |              |                  |
| Manufacture Date:: 01-Apr-19                                                                           |                                                                              |                                                        |               |          |                           |           |              |                  |
| PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01 |                                                                              |                                                        |               |          |                           |           |              |                  |
|                                                                                                        |                                                                              |                                                        |               |          |                           |           |              |                  |
| 35-31-01-001                                                                                           | DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)                              |                                                        |               |          |                           |           |              | Service ATA:35   |
| PN:MR-10022NEMB                                                                                        | MOS                                                                          | 01-Apr-19                                              | 126 (+1m/-1m) |          | 01-Oct-29                 | 01-Nov-29 | 1160 d (+31) | LIFE LIMIT       |
| SN:E1900850                                                                                            | HRS                                                                          |                                                        |               |          |                           |           |              |                  |
|                                                                                                        | AFL                                                                          |                                                        |               |          |                           |           |              |                  |
| PROC. REF: AMM 35-31-01PROC. REF: AMM 35-31-01                                                         |                                                                              |                                                        |               |          |                           |           |              |                  |
|                                                                                                        |                                                                              |                                                        |               |          |                           |           |              |                  |
| ATA 36 - PNEUMATIC                                                                                     |                                                                              |                                                        |               |          |                           |           |              |                  |
| 36-00-00-710-801-A                                                                                     | TROUBLE SHOOT ENGINE OPERATING PROBLEMS - PNEUMATIC SYSTEM OPERATIONAL CHECK |                                                        |               |          |                           |           |              | Service ATA:36   |
|                                                                                                        | MOS/MSC                                                                      | 23-Apr-20                                              | A/R           |          |                           |           |              |                  |
|                                                                                                        | HRS                                                                          | 0                                                      |               |          |                           |           |              |                  |
|                                                                                                        | AFL                                                                          | 0                                                      |               |          |                           |           |              |                  |
| PROC. REF: AMM 36-00-00PROC. REF: AMM 36-00-00                                                         |                                                                              |                                                        |               |          |                           |           |              |                  |
|                                                                                                        |                                                                              |                                                        |               |          |                           |           |              |                  |
| 36-01-01                                                                                               | PNEUMATIC INSC ILLUM PANEL                                                   |                                                        |               |          |                           |           |              | Component ATA:36 |
| PN:441-42633-002                                                                                       | MOS/MSC                                                                      | 23-Apr-20                                              | O/C           | TSN 0    |                           |           |              |                  |
| SN:1584                                                                                                | HRS                                                                          | 0                                                      |               | TSN 0    |                           |           |              |                  |
|                                                                                                        | AFL                                                                          | 0                                                      |               | TSN 0    |                           |           |              |                  |
| PROC. REF: AMM 36-01-01, AMM 36-01-01PROC. REF: AMM 36-01-01, AMM 36-01-01                             |                                                                              |                                                        |               |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|------------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                                                                        |           |                |          |                           |           |            |                  |
| 36-11-01                                                                   | LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE                                     |           |                |          |                           |           |            | Component ATA:36 |
| PN:RYLB-53505-5                                                            | MOS/MSC                                                                                | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:0841                                                                    | HRS                                                                                    | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                                                                    | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-01, AMM 36-11-01PROC. REF: AMM 36-11-01, AMM 36-11-01 |                                                                                        |           |                |          |                           |           |            |                  |
| 36-11-01                                                                   | RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE                                    |           |                |          |                           |           |            | Component ATA:36 |
| PN:RYLB-53505-6                                                            | MOS/MSC                                                                                | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:0834                                                                    | HRS                                                                                    | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                                                                    | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-01, AMM 36-11-01PROC. REF: AMM 36-11-01, AMM 36-11-01 |                                                                                        |           |                |          |                           |           |            |                  |
| 36-11-01-001 <sup>S</sup>                                                  | RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) INLET FILTER |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                                                                    | 23-Apr-20 |                |          |                           |           |            |                  |
|                                                                            | HRS                                                                                    | 0         | 2400 (+30/-30) |          |                           |           |            |                  |
|                                                                            | AFL                                                                                    | 0         |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01                             |                                                                                        |           |                |          |                           |           |            |                  |
| 36-11-01-002 <sup>S</sup>                                                  | OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION                                    |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                                                                    | 19-Mar-24 |                |          |                           |           |            |                  |
|                                                                            | HRS                                                                                    | 781:30    | 800 (+30/-30)  |          |                           |           |            |                  |
|                                                                            | AFL                                                                                    | 364       |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-00PROC. REF: AMM 36-11-00                             |                                                                                        |           |                |          |                           |           |            |                  |
| 36-11-01-003 <sup>S</sup>                                                  | DISCARD OF PRESSURE REGULATING SHUTOFF VALVE (PRSOV) VENT FILTER                       |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                                                                    | 23-Apr-20 |                |          |                           |           | LIFE LIMIT |                  |
|                                                                            | HRS                                                                                    | 0         | 2400 (+30/-30) |          |                           |           |            |                  |
|                                                                            | AFL                                                                                    | 0         |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-01PROC. REF: AMM 36-11-01                             |                                                                                        |           |                |          |                           |           |            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|------------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                                |           |                |          |                           |           |            |                  |
| 36-11-02-001 <sup>S</sup>                                                  | DETAILED INSPECTION OF BLEED LINE WATER DRAINS |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                            | 13-Mar-26 | 24 (+1m/-1m)   |          |                           |           |            |                  |
|                                                                            | HRS                                            | 1221:24   |                |          |                           |           |            |                  |
|                                                                            | AFL                                            | 564       |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02                             |                                                |           |                |          |                           |           |            | PKG:81           |
| 36-11-03                                                                   | AMS CONTROLLER                                 |           |                |          |                           |           |            | Component ATA:36 |
| PN:SYLZ-53632-205                                                          | MOS/MSC                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:0660A                                                                   | HRS                                            | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-03, AMM 36-11-03PROC. REF: AMM 36-11-03, AMM 36-11-03 |                                                |           |                |          |                           |           |            |                  |
| 36-11-04                                                                   | NO. 1 ENGINE FAN AIR VALVE                     |           |                |          |                           |           |            | Component ATA:36 |
| PN:RYLB-53527-2                                                            | MOS/MSC                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:1178                                                                    | HRS                                            | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-04, AMM 36-11-04PROC. REF: AMM 36-11-04, AMM 36-11-04 |                                                |           |                |          |                           |           |            |                  |
| 36-11-04                                                                   | NO. 2 ENGINE FAN AIR VALVE                     |           |                |          |                           |           |            | Component ATA:36 |
| PN:RYLB-53527-2                                                            | MOS/MSC                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:1214                                                                    | HRS                                            | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-04, AMM 36-11-04PROC. REF: AMM 36-11-04, AMM 36-11-04 |                                                |           |                |          |                           |           |            |                  |
| 36-11-04-001 <sup>S</sup>                                                  | DISCARD OF FAN-AIR VALVE (FAV) VENT FILTER     |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                            | 23-Apr-20 |                |          |                           |           | LIFE LIMIT |                  |
|                                                                            | HRS                                            | 0         | 2400 (+30/-30) |          |                           |           |            |                  |
|                                                                            | AFL                                            | 0         |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-04PROC. REF: AMM 36-11-04                             |                                                |           |                |          |                           |           |            | PKG:20           |
| 36-11-05                                                                   | LH INCONEL 625 BLEED PRE-COOLER                |           |                |          |                           |           |            | Component ATA:36 |
| PN:381256000                                                               | MOS/MSC                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:T0687                                                                   | HRS                                            | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                            | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-05, AMM 36-11-05PROC. REF: AMM 36-11-05, AMM 36-11-05 |                                                |           |                |          |                           |           |            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|------------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                                                |           |                |          |                           |           |            |                  |
| 36-11-05                                                                   | RH INCONEL 625 BLEED PRE-COOLER                                |           |                |          |                           |           |            | Component ATA:36 |
| PN:381257000                                                               | MOS/MSC                                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:T0695                                                                   | HRS                                                            | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                                            | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-05, AMM 36-11-05PROC. REF: AMM 36-11-05, AMM 36-11-05 |                                                                |           |                |          |                           |           |            |                  |
| 36-11-06                                                                   | CROSS BLEED VALVE                                              |           |                |          |                           |           |            | Component ATA:36 |
| PN:RYLB-53506-1                                                            | MOS/MSC                                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |            |                  |
| SN:0530                                                                    | HRS                                                            | 0         |                | TSN 0    |                           |           |            |                  |
|                                                                            | AFL                                                            | 0         |                | TSN 0    |                           |           |            |                  |
| PROC. REF: AMM 36-11-06, AMM 36-11-06PROC. REF: AMM 36-11-06, AMM 36-11-06 |                                                                |           |                |          |                           |           |            |                  |
| 36-11-06-001 <sup>S</sup>                                                  | OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION      |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                                            | 19-Mar-24 |                |          |                           |           |            |                  |
|                                                                            | HRS                                                            | 781:30    | 800 (+30/-30)  |          |                           |           |            |                  |
|                                                                            | AFL                                                            | 364       |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-06PROC. REF: AMM 36-11-06                             |                                                                |           |                |          |                           |           |            | PKG:1            |
| 36-11-06-002 <sup>S</sup>                                                  | RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) INLET FILTER |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                                            | 23-Apr-20 |                |          |                           |           |            |                  |
|                                                                            | HRS                                                            | 0         | 6400 (+30/-30) |          |                           |           |            |                  |
|                                                                            | AFL                                                            | 0         |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-06PROC. REF: AMM 36-11-06                             |                                                                |           |                |          |                           |           |            | PKG:60           |
| 36-11-06-003 <sup>S</sup>                                                  | DISCARD OF CROSS-BLEED VALVE (XBV) VENT FILTER                 |           |                |          |                           |           |            | Service ATA:36   |
|                                                                            | MOS                                                            | 23-Apr-20 |                |          |                           |           | LIFE LIMIT |                  |
|                                                                            | HRS                                                            | 0         | 6400 (+30/-30) |          |                           |           |            |                  |
|                                                                            | AFL                                                            | 0         |                |          |                           |           |            |                  |
| PROC. REF: AMM 36-11-06PROC. REF: AMM 36-11-06                             |                                                                |           |                |          |                           |           |            | PKG:60           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 36 - PNEUMATIC                                                         |                                 |           |          |          |                           |           |           |                  |
| 36-11-07                                                                   | NO. 1 BLEED PRESSURE TRANSDUCER |           |          |          |                           |           |           | Component ATA:36 |
| PN:APTE-479F-1000-200GMOS/MS                                               |                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8613-7-185                                                              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-11-07, AMM 36-11-07PROC. REF: AMM 36-11-07, AMM 36-11-07 |                                 |           |          |          |                           |           |           |                  |
| 36-11-07                                                                   | NO. 2 BLEED PRESSURE TRANSDUCER |           |          |          |                           |           |           | Component ATA:36 |
| PN:APTE-479F-1000-200GMOS/MS                                               |                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:8448-10-724                                                             | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-11-07, AMM 36-11-07PROC. REF: AMM 36-11-07, AMM 36-11-07 |                                 |           |          |          |                           |           |           |                  |
| 36-11-08                                                                   | NO. 1 BLEED TEMPERATURE SENSOR  |           |          |          |                           |           |           | Component ATA:36 |
| PN:103-00264                                                               | MOS/MS                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01674                                                                   | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |                                 |           |          |          |                           |           |           |                  |
| 36-11-08                                                                   | NO. 2 BLEED TEMPERATURE SENSOR  |           |          |          |                           |           |           | Component ATA:36 |
| PN:103-00264                                                               | MOS/MS                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01631                                                                   | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |                                 |           |          |          |                           |           |           |                  |
| 36-11-08                                                                   | NO. 3 BLEED TEMPERATURE SENSOR  |           |          |          |                           |           |           | Component ATA:36 |
| PN:103-00264                                                               | MOS/MS                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01629                                                                   | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |                                 |           |          |          |                           |           |           |                  |
| 36-11-08                                                                   | NO. 4 BLEED TEMPERATURE SENSOR  |           |          |          |                           |           |           | Component ATA:36 |
| PN:103-00264                                                               | MOS/MS                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:01673                                                                   | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 36-11-08, AMM 36-11-08PROC. REF: AMM 36-11-08, AMM 36-11-08 |                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit         | C/W                                                 | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|------------------------------------------------|--------------|-----------------------------------------------------|----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 36 - PNEUMATIC                             |              |                                                     |                |          |                           |           |               |                |
| 36-11-08-001                                   | <sup>S</sup> | FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR |                |          |                           |           |               | Service ATA:36 |
|                                                | MOS          | 23-Apr-20                                           |                |          |                           |           |               |                |
|                                                | HRS          | 0                                                   | 6400 (+30/-30) |          |                           |           |               |                |
|                                                | AFL          | 0                                                   |                |          |                           |           |               |                |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08 |              |                                                     |                |          |                           |           |               | PKG:60         |
| 36-11-08-001                                   | <sup>S</sup> | FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR |                |          |                           |           |               | Service ATA:36 |
|                                                | MOS          | 23-Apr-20                                           |                |          |                           |           |               |                |
|                                                | HRS          | 0                                                   | 6400 (+30/-30) |          |                           |           |               |                |
|                                                | AFL          | 0                                                   |                |          |                           |           |               |                |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08 |              |                                                     |                |          |                           |           |               | PKG:60         |
| 36-11-08-001                                   | <sup>S</sup> | FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR |                |          |                           |           |               | Service ATA:36 |
|                                                | MOS          | 23-Apr-20                                           |                |          |                           |           |               |                |
|                                                | HRS          | 0                                                   | 6400 (+30/-30) |          |                           |           |               |                |
|                                                | AFL          | 0                                                   |                |          |                           |           |               |                |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08 |              |                                                     |                |          |                           |           |               | PKG:60         |
| 36-11-08-001                                   | <sup>S</sup> | FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR |                |          |                           |           |               | Service ATA:36 |
|                                                | MOS          | 23-Apr-20                                           |                |          |                           |           |               |                |
|                                                | HRS          | 0                                                   | 6400 (+30/-30) |          |                           |           |               |                |
|                                                | AFL          | 0                                                   |                |          |                           |           |               |                |
| PROC. REF: AMM 36-11-08PROC. REF: AMM 36-11-08 |              |                                                     |                |          |                           |           |               | PKG:60         |
| 36-21-01-001                                   |              | OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS          |                |          |                           |           |               | Service ATA:36 |
|                                                | MOS          | 23-Apr-20                                           |                |          |                           |           |               | AIRWORTHINESS  |
|                                                | HRS          | 0                                                   | 6400 (+30/-30) |          | 6400                      | 6430      | 5104:36 (+30) |                |
|                                                | AFL          | 0                                                   |                |          |                           |           |               |                |
| PROC. REF: AMM 36-21-01PROC. REF: AMM 36-21-01 |              |                                                     |                |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 38 - WATER/WASTE                                                       |                                      |           |          |          |                           |           |           |                  |
| 38-33-07                                                                   | WASTE DRAIN VALVE                    |           |          |          |                           |           |           | Component ATA:38 |
| PN:0218-0032-1                                                             | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:310858                                                                  | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 38-33-07, AMM 38-33-07PROC. REF: AMM 38-33-07, AMM 38-33-07 |                                      |           |          |          |                           |           |           |                  |
| ATA 44 - CABIN SYSTEMS                                                     |                                      |           |          |          |                           |           |           |                  |
| 44-21-09                                                                   | IFE INSC ILLUM PANEL                 |           |          |          |                           |           |           | Component ATA:44 |
| PN:441-44843-001                                                           | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1374                                                                    | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-21-09, AMM 44-21-09PROC. REF: AMM 44-21-09, AMM 44-21-09 |                                      |           |          |          |                           |           |           |                  |
| 44-21-12                                                                   | HDMI / USB CABIN JACK MODULE         |           |          |          |                           |           |           | Component ATA:44 |
| PN:ADT-1810-007-000                                                        | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000838                                                                  | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-23-15, AMM 44-23-15PROC. REF: AMM 44-23-15, AMM 44-23-15 |                                      |           |          |          |                           |           |           |                  |
| 44-21-14                                                                   | RJ45 / USB CABIN JACK MODULE         |           |          |          |                           |           |           | Component ATA:44 |
| PN:ADT-1810-005-000                                                        | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000854                                                                  | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-23-07, AMM 44-23-07PROC. REF: AMM 44-23-07, AMM 44-23-07 |                                      |           |          |          |                           |           |           |                  |
| 44-21-15                                                                   | AUDIO VOLUME CONTROLLER              |           |          |          |                           |           |           | Component ATA:44 |
| PN:APA3009-001-001                                                         | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:500315                                                                  | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-21-15, AMM 44-21-15PROC. REF: AMM 44-21-15, AMM 44-21-15 |                                      |           |          |          |                           |           |           |                  |
| 44-21-16                                                                   | PAX 1 GMA 36 REMOTE AUDIO CONTROLLER |           |          |          |                           |           |           | Component ATA:44 |
| PN:011-04093-00                                                            | MOS/MSC                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:4RK110586                                                               | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 44 - CABIN SYSTEMS                                                     |                                                |           |          |          |                           |           |           |                  |
| 44-21-16                                                                   | PAX 2 GMA 36 REMOTE AUDIO CONTROLLER           |           |          |          |                           |           |           | Component ATA:44 |
| PN:011-04093-00                                                            | MOS/MSC                                        | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:4RK111413                                                               | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                |           |          |          |                           |           |           |                  |
| 44-21-18 <sup>U</sup>                                                      | AUDIO POWER AMPLIFIER / APA                    |           |          |          |                           |           |           | Component ATA:44 |
| PN:APA3009-001-001                                                         | MOS/MSC                                        |           | O/C      |          |                           |           |           |                  |
| SN:500315                                                                  | HRS                                            |           |          |          |                           |           |           |                  |
|                                                                            | AFL                                            |           |          |          |                           |           |           |                  |
|                                                                            |                                                |           |          |          |                           |           |           |                  |
| 44-21-23                                                                   | NO. 1 WIRELESS HEADPHONE                       |           |          |          |                           |           |           | Component ATA:44 |
| PN:ADT1810-013-001                                                         | MOS/MSC                                        | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000164                                                                  | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                |           |          |          |                           |           |           |                  |
| 44-21-23                                                                   | NO. 2 WIRELESS HEADPHONE                       |           |          |          |                           |           |           | Component ATA:44 |
| PN:ADT1810-013-001                                                         | MOS/MSC                                        | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000161                                                                  | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                |           |          |          |                           |           |           |                  |
| 44-22-01                                                                   | CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER |           |          |          |                           |           |           | Component ATA:44 |
| PN:BDP3009-203-001                                                         | MOS/MSC                                        | 31-Mar-25 | O/C      | TSR 0    |                           |           |           |                  |
| SN:500582                                                                  | HRS                                            | 987:24    |          | TSR 0    |                           |           |           |                  |
|                                                                            | AFL                                            | 456       |          | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 44-22-01, AMM 44-22-01PROC. REF: AMM 44-22-01, AMM 44-22-01 |                                                |           |          |          |                           |           |           |                  |
| 44-22-02                                                                   | LEFT AFT CABIN SPEAKER                         |           |          |          |                           |           |           | Component ATA:44 |
| PN:SPK4615-001-000                                                         | MOS/MSC                                        | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000364                                                                  | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-12-01, AMM 44-12-01PROC. REF: AMM 44-12-01, AMM 44-12-01 |                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 44 - CABIN SYSTEMS                                                     |                                         |           |          |          |                           |           |           |                  |
| 44-22-02                                                                   | LEFT FORWARD CABIN SPEAKER              |           |          |          |                           |           |           | Component ATA:44 |
| PN:SPK4615-001-000                                                         | MOS/MSC                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000368                                                                  | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-12-01, AMM 44-12-01PROC. REF: AMM 44-12-01, AMM 44-12-01 |                                         |           |          |          |                           |           |           |                  |
| 44-22-02                                                                   | RIGHT AFT CABIN SPEAKER                 |           |          |          |                           |           |           | Component ATA:44 |
| PN:SPK4615-001-000                                                         | MOS/MSC                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000361                                                                  | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-12-01, AMM 44-12-01PROC. REF: AMM 44-12-01, AMM 44-12-01 |                                         |           |          |          |                           |           |           |                  |
| 44-22-02                                                                   | RIGHT FORWARD CABIN SPEAKER             |           |          |          |                           |           |           | Component ATA:44 |
| PN:SPK4615-001-000                                                         | MOS/MSC                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000358                                                                  | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-12-01, AMM 44-12-01PROC. REF: AMM 44-12-01, AMM 44-12-01 |                                         |           |          |          |                           |           |           |                  |
| 44-22-03                                                                   | NO. 1 10.4 INCH FOLD DOWN MONITOR-      |           |          |          |                           |           |           | Component ATA:44 |
| PN:DIS0716-002-001                                                         | MOS/MSC                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:000185                                                                  | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-22-03, AMM 44-22-03PROC. REF: AMM 44-22-03, AMM 44-22-03 |                                         |           |          |          |                           |           |           |                  |
| 44-23-13                                                                   | PASSENGER CABIN FOLD-DOWN MONITOR / FDM |           |          |          |                           |           |           | Component ATA:44 |
| PN:DIS0716-002-001                                                         | MOS/MSC                                 | 12-Dec-25 | O/C      | TSN 36   |                           |           |           |                  |
| SN:000443                                                                  | HRS                                     | 1179:24   |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                     | 546       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-23-13, AMM 44-23-13PROC. REF: AMM 44-23-13, AMM 44-23-13 |                                         |           |          |          |                           |           |           |                  |
| 44-60-01                                                                   | ETHERNET INTERFACE UNIT                 |           |          |          |                           |           |           | Component ATA:44 |
| PN:EIU3009-201-001                                                         | MOS/MSC                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:500151                                                                  | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-23-01, AMM 44-23-01PROC. REF: AMM 44-23-01, AMM 44-23-01 |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                       | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 44 - CABIN SYSTEMS                                                     |                                                            |           |              |          |                           |           |           |                  |
| 44-60-02                                                                   | ETHERNET ENCODER UNIT                                      |           |              |          |                           |           |           | Component ATA:44 |
| PN:EEU0910-201-001                                                         | MOS/MSC                                                    | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:500803                                                                  | HRS                                                        | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-23-05, AMM 44-23-05PROC. REF: AMM 44-23-05, AMM 44-23-05 |                                                            |           |              |          |                           |           |           |                  |
| 442321-0101                                                                | XM RADIO (2-CHANNEL) RECEIVER                              |           |              |          |                           |           |           | Component ATA:44 |
| PN:PN                                                                      | MOS/MSC                                                    | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 44-23-21, AMM 44-23-21PROC. REF: AMM 44-23-21, AMM 44-23-21 |                                                            |           |              |          |                           |           |           |                  |
| ATA 52 - DOORS                                                             |                                                            |           |              |          |                           |           |           |                  |
| 52-10-00-001 <sup>S</sup>                                                  | INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE |           |              |          |                           |           |           | Service ATA:52   |
|                                                                            | MOS                                                        | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                                        | 987:24    |              |          |                           |           |           |                  |
|                                                                            | AFL                                                        | 456       |              |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00               |                                                            |           |              |          |                           |           |           |                  |
| 52-10-00-01A                                                               | PAX DOOR EQUIPPED MAIN DOOR ASSY                           |           |              |          |                           |           |           | Component ATA:52 |
| PN:505-09910-469                                                           | MOS/MSC                                                    | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:0001059395                                                              | HRS                                                        | 0         |              | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                        | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 52-10-00, AMM 52-10-00PROC. REF: AMM 52-10-00, AMM 52-10-00 |                                                            |           |              |          |                           |           |           |                  |
| 52-10-01-001 <sup>S</sup>                                                  | EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE |           |              |          |                           |           |           | Service ATA:52   |
|                                                                            | MOS                                                        | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                  |
|                                                                            | HRS                                                        | 987:24    |              |          |                           |           |           |                  |
|                                                                            | AFL                                                        | 456       |              |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00               |                                                            |           |              |          |                           |           |           |                  |

PKG:84

PKG:84

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 52 - DOORS                                               |                                                                                                                                     |           |              |          |                           |           |           |                |
| 52-10-01-01-901                                              | GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL                                    |           |              |          |                           |           |           | Service ATA:52 |
|                                                              | MOS                                                                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                           |           |           |                |
| 52-10-01-02-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL                                         |           |              |          |                           |           |           | Service ATA:52 |
|                                                              | MOS                                                                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                           |           |           |                |
| 52-10-01-02-902                                              | DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL |           |              |          |                           |           |           | Service ATA:52 |
|                                                              | MOS                                                                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                           |           |           |                |
| 52-10-02-01-901                                              | GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL                                         |           |              |          |                           |           |           | Service ATA:52 |
|                                                              | MOS                                                                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 52-10-00PROC. REF: NDT PART 5 52-10-00 |                                                                                                                                     |           |              |          |                           |           |           |                |
| 52-10-20-001 <sup>S</sup>                                    | GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL                                                                                  |           |              |          |                           |           |           | Service ATA:52 |
|                                                              | MOS                                                                                                                                 | 13-Mar-26 | 12 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                 | 1221:24   |              |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                 | 564       |              |          |                           |           |           |                |
| PROC. REF: AMM 52-10-20PROC. REF: AMM 52-10-20               |                                                                                                                                     |           |              |          |                           |           |           | PKG:80         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit         | C/W                                                                             | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|--------------|---------------------------------------------------------------------------------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 52 - DOORS                                     |              |                                                                                 |                |          |                           |           |           |                  |
| 52-11-00-001                                       | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM |                |          |                           |           |           | Service ATA:52   |
|                                                    | MOS          | 19-Mar-24                                                                       | 48 (+1m/-1m)   |          |                           |           |           |                  |
|                                                    | HRS          | 781:30                                                                          |                |          |                           |           |           |                  |
|                                                    | AFL          | 364                                                                             |                |          |                           |           |           |                  |
| PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00     |              |                                                                                 |                |          |                           |           |           | PKG:83           |
| 52-11-00-003                                       | <sup>S</sup> | FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH                          |                |          |                           |           |           | Service ATA:52   |
|                                                    | MOS          | 19-Mar-24                                                                       |                |          |                           |           |           |                  |
|                                                    | HRS          | 781:30                                                                          | 800 (+30/-30)  |          |                           |           |           |                  |
|                                                    | AFL          | 364                                                                             |                |          |                           |           |           |                  |
| PROC. REF: AMM 52-11-23PROC. REF: AMM 52-11-23     |              |                                                                                 |                |          |                           |           |           | PKG:1            |
| 52-13-00                                           |              | MAIN DOOR BALANCE ASSY. GEAR SECTOR                                             |                |          |                           |           |           | Component ATA:52 |
| PN:PN                                              | MOS/MSC      | 23-Apr-20                                                                       | H/T            | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS          | 0                                                                               |                | TSN 0    |                           |           |           |                  |
|                                                    | AFL          | 0                                                                               |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                 |                |          |                           |           |           |                  |
| 52-13-01                                           |              | MAIN DOOR BALANCE ASSY. PINION SHAFT                                            |                |          |                           |           |           | Component ATA:52 |
| PN:PN                                              | MOS/MSC      | 23-Apr-20                                                                       | H/T            | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS          | 0                                                                               |                | TSN 0    |                           |           |           |                  |
|                                                    | AFL          | 0                                                                               |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                 |                |          |                           |           |           |                  |
| 52-13-21-001                                       | <sup>S</sup> | DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR                            |                |          |                           |           |           | Service ATA:52   |
| PN:PN                                              | MOS          | 23-Apr-20                                                                       |                |          |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS          | 0                                                                               | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                    | AFL          | 0                                                                               |                |          |                           |           |           |                  |
| PROC. REF: AMM 52-13-21PROC. REF: AMM 52-13-21     |              |                                                                                 |                |          |                           |           |           | PKG:50           |
| 52-13-22                                           |              | MAIN DOOR BALANCING MECHANISM                                                   |                |          |                           |           |           | Component ATA:52 |
| PN:PN                                              | MOS/MSC      | 23-Apr-20                                                                       | O/C            | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS          | 0                                                                               |                | TSN 0    |                           |           |           |                  |
|                                                    | AFL          | 0                                                                               |                | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                            | Unit                                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 52 - DOORS                                                                                                                     |                                                                |           |                |          |                           |           |           |                  |
| PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22 |                                                                |           |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           |                  |
| 52-13-22-001 <sup>S</sup>                                                                                                          | DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE                 |           |                |          |                           |           |           | Service ATA:52   |
| PN:PN                                                                                                                              | MOS/MSC                                                        | 19-Mar-24 | O/C            |          |                           |           |           |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                            | 781:30    |                |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                            | 364       |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           | PKG:1            |
| PROC. REF: AMM 52-13-22PROC. REF: AMM 52-13-22                                                                                     |                                                                |           |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           |                  |
| 52-13-22-004 <sup>S</sup>                                                                                                          | DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES                |           |                |          |                           |           |           | Service ATA:52   |
|                                                                                                                                    | MOS                                                            | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                            | 0         | 3200 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                            | 0         |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           | PKG:40           |
| PROC. REF: AMM 52-13-22PROC. REF: AMM 52-13-22                                                                                     |                                                                |           |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           |                  |
| 52-13-23-001 <sup>S</sup>                                                                                                          | DISCARD OF MAIN DOOR BALANCING MECHANISM PINION SHAFT          |           |                |          |                           |           |           | Service ATA:52   |
| PN:PN                                                                                                                              | MOS                                                            | 23-Apr-20 |                |          |                           |           |           |                  |
| SN:UNKNOWN                                                                                                                         | HRS                                                            | 0         | 5600 (+30/-30) |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                            | 0         |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           | PKG:50           |
| PROC. REF: AMM 52-13-23PROC. REF: AMM 52-13-23                                                                                     |                                                                |           |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           |                  |
| 52-20-00                                                                                                                           | EMERGENCY DOOR                                                 |           |                |          |                           |           |           | Component ATA:52 |
| PN:505-09700-405                                                                                                                   | MOS/MSC                                                        | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:0001059540                                                                                                                      | HRS                                                            | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                                                    | AFL                                                            | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                                 |                                                                |           |                |          |                           |           |           |                  |
|                                                                                                                                    |                                                                |           |                |          |                           |           |           |                  |
| 52-20-01-001                                                                                                                       | EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE |           |                |          |                           |           |           | Service ATA:52   |
|                                                                                                                                    | MOS/MSC                                                        | 23-Apr-20 | O/C            |          |                           |           |           |                  |
|                                                                                                                                    | HRS                                                            | 0         |                |          |                           |           |           |                  |
|                                                                                                                                    | AFL                                                            | 0         |                |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00                                                                       |                                                                |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit         | C/W                                                                                  | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------------------------------------------------|--------------|--------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 52 - DOORS                                                                                         |              |                                                                                      |                 |          |                           |           |               |                |
| 52-20-01-002                                                                                           | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE                       |                 |          |                           |           |               | Service ATA:52 |
|                                                                                                        | MOS          | 23-Apr-20                                                                            | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                                                                        | HRS          | 0                                                                                    |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 0                                                                                    |                 |          |                           |           |               |                |
|                                                                                                        |              |                                                                                      |                 |          |                           |           |               | PKG:90         |
| PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00 |              |                                                                                      |                 |          |                           |           |               |                |
| 52-20-01-01-901                                                                                        |              | GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL    |                 |          |                           |           |               | Service ATA:52 |
|                                                                                                        | MOS          | 23-Apr-20                                                                            |                 |          |                           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                    | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                                                                        | AFL          | 0                                                                                    | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00                                           |              |                                                                                      |                 |          |                           |           |               |                |
| 52-20-01-01-902                                                                                        |              | DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL  |                 |          |                           |           |               | Service ATA:52 |
|                                                                                                        | MOS          | 23-Apr-20                                                                            |                 |          |                           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                    | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                                                                        | AFL          | 0                                                                                    | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 52-20-00PROC. REF: NDT PART 5 52-20-00                                           |              |                                                                                      |                 |          |                           |           |               |                |
| 52-20-20-001                                                                                           | <sup>S</sup> | INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM |                 |          |                           |           |               | Service ATA:52 |
|                                                                                                        | MOS          | 19-Mar-24                                                                            | 48 (+1m/-1m)    |          |                           |           |               |                |
|                                                                                                        | HRS          | 781:30                                                                               |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 364                                                                                  |                 |          |                           |           |               |                |
|                                                                                                        |              |                                                                                      |                 |          |                           |           |               | PKG:83         |
| PROC. REF: AMM 52-20-20PROC. REF: AMM 52-20-20                                                         |              |                                                                                      |                 |          |                           |           |               |                |
| 52-20-21-001                                                                                           | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL                     |                 |          |                           |           |               | Service ATA:52 |
|                                                                                                        | MOS          | 13-Mar-26                                                                            | 24 (+1m/-1m)    |          |                           |           |               |                |
|                                                                                                        | HRS          | 1221:24                                                                              |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 564                                                                                  |                 |          |                           |           |               |                |
|                                                                                                        |              |                                                                                      |                 |          |                           |           |               | PKG:81         |
| PROC. REF: AMM 52-20-21PROC. REF: AMM 52-20-21                                                         |              |                                                                                      |                 |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                               | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 52 - DOORS                                               |              |                                                                                   |                 |          |                           |           |           |                |
| 52-31-20-001                                                 | <sup>S</sup> | GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM |                 |          |                           |           |           | Service ATA:52 |
|                                                              | MOS          | 19-Mar-24                                                                         | 48 (+1m/-1m)    |          |                           |           |           |                |
|                                                              | HRS          | 781:30                                                                            |                 |          |                           |           |           |                |
|                                                              | AFL          | 364                                                                               |                 |          |                           |           |           |                |
| PROC. REF: AMM 52-31-20PROC. REF: AMM 52-31-20               |              |                                                                                   |                 |          |                           |           |           | PKG:83         |
| 52-32-20-001                                                 | <sup>S</sup> | GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM         |                 |          |                           |           |           | Service ATA:52 |
|                                                              | MOS          | 19-Mar-24                                                                         | 48 (+1m/-1m)    |          |                           |           |           |                |
|                                                              | HRS          | 781:30                                                                            |                 |          |                           |           |           |                |
|                                                              | AFL          | 364                                                                               |                 |          |                           |           |           |                |
| PROC. REF: AMM 52-32-20PROC. REF: AMM 52-32-20               |              |                                                                                   |                 |          |                           |           |           | PKG:83         |
| ATA 53 - FUSELAGE                                            |              |                                                                                   |                 |          |                           |           |           |                |
| 53-00-00-001                                                 | <sup>S</sup> | GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS                          |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 19-Mar-24                                                                         |                 |          |                           |           |           |                |
|                                                              | HRS          | 781:30                                                                            | 800 (+30/-30)   |          |                           |           |           |                |
|                                                              | AFL          | 364                                                                               |                 |          |                           |           |           |                |
| PROC. REF: AMM 53-00-20PROC. REF: AMM 53-00-20               |              |                                                                                   |                 |          |                           |           |           | PKG:1          |
| 53-05-00-001                                                 | <sup>S</sup> | DETAILED INSPECTION OF FUSELAGE DRAINS                                            |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 31-Mar-25                                                                         | 60 (+1m/-1m)    |          |                           |           |           |                |
|                                                              | HRS          | 987:24                                                                            |                 |          |                           |           |           |                |
|                                                              | AFL          | 456                                                                               |                 |          |                           |           |           |                |
| PROC. REF: AMM 53-05-00PROC. REF: AMM 53-05-00               |              |                                                                                   |                 |          |                           |           |           | PKG:84         |
| 53-10-00-001                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES                |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                         | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 0                                                                                 |                 |          |                           |           |           |                |
|                                                              | AFL          | 0                                                                                 |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                   |                 |          |                           |           |           | PKG:90         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                              | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                   |           |               |          |                           |           |               |                |
| 53-10-00-002                                                 | EXTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES                                               |           |               |          |                           |           |               | Service ATA:53 |
|                                                              | MOS/MSC                                                                                                                           | 23-Apr-20 | O/C           |          |                           |           |               |                |
|                                                              | HRS                                                                                                                               | 0         |               |          |                           |           |               |                |
|                                                              | AFL                                                                                                                               | 0         |               |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                                   |           |               |          |                           |           |               |                |
| 53-10-00-003 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE                                                      |           |               |          |                           |           |               | Service ATA:53 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS                                                                                                                               | 0         |               |          |                           |           |               |                |
|                                                              | AFL                                                                                                                               | 0         |               |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PKG:87                         |                                                                                                                                   |           |               |          |                           |           |               |                |
| 53-10-01-01-901                                              | DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL |           |               |          |                           |           |               | Service ATA:53 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |               |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                               | 0         | T:17500       |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000       |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                                   |           |               |          |                           |           |               |                |
| 53-10-01-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL                     |           |               |          |                           |           |               | Service ATA:53 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |               |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                               | 0         | T:17500       |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000       |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                                   |           |               |          |                           |           |               |                |
| 53-10-02-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL      |           |               |          |                           |           |               | Service ATA:53 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |               |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS                                                                                                                               | 0         | T:17500       |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000       |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                                   |           |               |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                       |           |          |          |                           |           |           |                |
| 53-10-02-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL         |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                       |           |          |          |                           |           |           |                |
| 53-10-03-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL              |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                       |           |          |          |                           |           |           |                |
| 53-10-03-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL                               |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                       |           |          |          |                           |           |           |                |
| 53-10-04-01-901                                              | DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                       |           |          |          |                           |           |           |                |
| 53-10-04-01-902                                              | DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |                                                                                                                       |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                                | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                                                    |                 |          |                           |           |               |                |
| 53-10-05-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD                                                                                   |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                          | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS          | 0                                                                                                                                                  |                 |          |                           |           |               |                |
|                                                              | AFL          | 0                                                                                                                                                  |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                    |                 |          |                           |           |               | PKG:90         |
| 53-10-05-01-901                                              |              | DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL                                                     |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                          |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                                  | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL          | 0                                                                                                                                                  | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                    |                 |          |                           |           |               |                |
| 53-10-07-001                                                 | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE                                                                        |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 31-Mar-25                                                                                                                                          | 60 (+1m/-1m)    |          |                           |           |               |                |
|                                                              | HRS          | 987:24                                                                                                                                             |                 |          |                           |           |               |                |
|                                                              | AFL          | 456                                                                                                                                                |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                    |                 |          |                           |           |               | PKG:84         |
| 53-10-07-01-901                                              |              | SPECIAL DETAILED INSPECTION (BOREScope) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WELL METALLIC STRUCTURE - INTERNAL |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                          |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                                  | T:15000         |          | 15000                     |           | 13704:36      |                |
|                                                              | AFL          | 0                                                                                                                                                  | T:12000         |          | 12000                     |           | 11402         |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                    |                 |          |                           |           |               |                |
| 53-10-07-02-901                                              |              | DETAILED INSPECTION OF WHEEL WEEL STRUCTURE. NOSE LANDING GEAR WHEEL WELL METALLIC STRUCTURE - EXTERNAL                                            |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                          |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                                                  | T:15000         |          | 15000                     |           | 13704:36      |                |
|                                                              | AFL          | 0                                                                                                                                                  | T:12000         |          | 12000                     |           | 11402         |                |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00 |              |                                                                                                                                                    |                 |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 53 - FUSELAGE                                                          |                                                                                                         |           |          |          |                           |           |           |                  |
| 53-10-07-02-902                                                            | DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WELL STRUCTURE. |           |          |          |                           |           |           | Service ATA:53   |
|                                                                            | MOS                                                                                                     | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                                            | HRS                                                                                                     | 0         | T:15000  |          | 15000                     |           | 13704:36  |                  |
|                                                                            | AFL                                                                                                     | 0         | T:12000  |          | 12000                     |           | 11402     |                  |
| PROC. REF: NDT PART 5 53-10-00PROC. REF: NDT PART 5 53-10-00               |                                                                                                         |           |          |          |                           |           |           |                  |
| 53-11-00                                                                   | FORWARD FUSELAGE ASSEMBLY                                                                               |           |          |          |                           |           |           | Component ATA:53 |
| PN:507-01000-405                                                           | MOS/MSC                                                                                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0001060037                                                              | HRS                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                         |           |          |          |                           |           |           |                  |
| 53-14-00                                                                   | NOSE RADOME                                                                                             |           |          |          |                           |           |           | Component ATA:53 |
| PN:5190-102-1                                                              | MOS/MSC                                                                                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1034                                                                    | HRS                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 53-14-00, AMM 53-14-00PROC. REF: AMM 53-14-00, AMM 53-14-00 |                                                                                                         |           |          |          |                           |           |           |                  |
| 53-20-00                                                                   | CENTER FUSELAGE JUNCTION ASSY                                                                           |           |          |          |                           |           |           | Component ATA:53 |
| PN:507-03600-415                                                           | MOS/MSC                                                                                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0001056732                                                              | HRS                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                         |           |          |          |                           |           |           |                  |
| 53-20-00                                                                   | CENTRAL FUSELAGE ASSY                                                                                   |           |          |          |                           |           |           | Component ATA:53 |
| PN:507-03500-415                                                           | MOS/MSC                                                                                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0001059142                                                              | HRS                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                         |           |          |          |                           |           |           |                  |
| 53-20-00                                                                   | COMPLETE FUSELAGE ASSY                                                                                  |           |          |          |                           |           |           | Component ATA:53 |
| PN:507-09001-435                                                           | MOS/MSC                                                                                                 | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0001060036                                                              | HRS                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 53 - FUSELAGE                                            |                                                                                                            |           |                 |          |                           |           |           |                  |
| 53-20-00                                                     | FUSELAGE JUNCTION ALIGNMENT                                                                                |           |                 |          |                           |           |           | Component ATA:53 |
| PN:507-08700-417                                             | MOS/MSC                                                                                                    | 23-Apr-20 | O/C             | TSN 0    |                           |           |           |                  |
| SN:0001059141                                                | HRS                                                                                                        | 0         |                 | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                                        | 0         |                 | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                            |           |                 |          |                           |           |           |                  |
| 53-20-00-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES                                          |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                        | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                                        | 0         |                 |          |                           |           |           |                  |
|                                                              | AFL                                                                                                        | 0         |                 |          |                           |           |           |                  |
| PKG:90                                                       |                                                                                                            |           |                 |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                            |           |                 |          |                           |           |           |                  |
| 53-20-00-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES                                          |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                        | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                                        | 0         |                 |          |                           |           |           |                  |
|                                                              | AFL                                                                                                        | 0         |                 |          |                           |           |           |                  |
| PKG:90                                                       |                                                                                                            |           |                 |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                            |           |                 |          |                           |           |           |                  |
| 53-20-01-01-901                                              | DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                        | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                        | 0         | T:17500         |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                        | 0         | T:14000         |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                            |           |                 |          |                           |           |           |                  |
| 53-20-01-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL                     |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                        | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                        | 0         | T:17500         |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                        | 0         | T:14000         |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                            |           |                 |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-20-02-01-901                                              | DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL                                 |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-20-02-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL                                                                  |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-20-03-01-901                                              | DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL                                |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-20-03-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL                                                                 |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-20-04-01-901                                              | DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                        |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                          | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-20-04-01-902                                              | DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL                                    |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-20-04-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 53-20-00PROC. REF: NDT PART 6 53-20-00 |                                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-20-04-02-902                                              | GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL                                                        |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-20-05-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE                                               |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                           | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              |                                                                                                                                                                               |           |                 |          |                           |           |           | PKG:90         |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-20-05-003 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE                                                |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                           | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              |                                                                                                                                                                               |           |                 |          |                           |           |           | PKG:90         |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                               |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                                                            |           |          |          |                           |           |           |                |
| 53-20-05-01-901                                              | GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                        | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                           |           |           |                |
| 53-20-05-02-901                                              | DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL              |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                        | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                           |           |           |                |
| 53-20-05-03-901                                              | DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL          |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                        | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                           |           |           |                |
| 53-20-05-04-901                                              | DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL                    |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                        | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                           |           |           |                |
| 53-20-05-05-901                                              | GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL                     |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                                                        | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                        | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                        | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                                                                            |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                          | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                                              |                 |          |                           |           |           |                |
| 53-20-06-001                                                 | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE                                                                             |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 31-Mar-25                                                                                                                                    | 60 (+1m/-1m)    |          |                           |           |           |                |
|                                                              | HRS          | 987:24                                                                                                                                       |                 |          |                           |           |           |                |
|                                                              | AFL          | 456                                                                                                                                          |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |                 |          |                           |           |           | PKG:84         |
| 53-20-06-002                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE                                                                            |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                    | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 0                                                                                                                                            |                 |          |                           |           |           |                |
|                                                              | AFL          | 0                                                                                                                                            |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |                 |          |                           |           |           | PKG:90         |
| 53-20-06-01-901                                              |              | DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL                                               |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                    |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                                            | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                                            | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |                 |          |                           |           |           |                |
| 53-20-06-01-902                                              |              | DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                    |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                                            | T:8750          |          | 8750                      |           | 7454:36   |                |
|                                                              | AFL          | 0                                                                                                                                            | T:7000          |          | 7000                      |           | 6402      |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |                 |          |                           |           |           |                |
| 53-20-07-01-901                                              |              | DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL             |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                    |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                                            | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                                            | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |              |                                                                                                                                              |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                         | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                              |           |                 |          |                           |           |           |                |
| 53-20-07-01-902                                              | DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |                 |          |                           |           |           |                |
| 53-20-08-002 <sup>S</sup>                                    | INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE                                                      |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                          | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                          | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |                 |          |                           |           |           |                |
| PKG:90                                                       |                                                                                                                              |           |                 |          |                           |           |           |                |
| 53-20-08-01-901                                              | GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL                      |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |                 |          |                           |           |           |                |
| 53-20-08-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL                       |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |                 |          |                           |           |           |                |
| 53-20-10-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS                                                    |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                          | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                          | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                              |           |                 |          |                           |           |           |                |
| PKG:90                                                       |                                                                                                                              |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                     | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                          |           |                 |          |                           |           |           |                  |
| 53-20-10-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                                      | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                      | 0         | T:17500         |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                      | 0         | T:14000         |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                          |           |                 |          |                           |           |           |                  |
| 53-20-10-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL                                |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                                      | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                      | 0         | T:17500         |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                      | 0         | T:14000         |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                          |           |                 |          |                           |           |           |                  |
| 53-20-10-02-901                                              | GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL                    |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                                      | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                      | 0         | T:17500         |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                      | 0         | T:14000         |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 53-20-00PROC. REF: NDT PART 5 53-20-00 |                                                                                                                          |           |                 |          |                           |           |           |                  |
| 53-30-00                                                     | REAR FUSELAGE ASSY                                                                                                       |           |                 |          |                           |           |           | Component ATA:53 |
| PN:507-06000-409                                             | MOS/MSC                                                                                                                  | 23-Apr-20 | O/C             | TSN 0    |                           |           |           |                  |
| SN:0001059145                                                | HRS                                                                                                                      | 0         |                 | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                                                      | 0         |                 | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                                          |           |                 |          |                           |           |           |                  |
| 53-30-00-001 <sup>S</sup>                                    | EXTERNAL GENERAL VISUAL INSPECTION OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE                               |           |                 |          |                           |           |           | Service ATA:53   |
|                                                              | MOS                                                                                                                      | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                                                      | 0         |                 |          |                           |           |           |                  |
|                                                              | AFL                                                                                                                      | 0         |                 |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                          |           |                 |          |                           |           |           | PKG:90           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                         | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                             |                 |          |                           |           |               |                |
| 53-30-00-002                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES                                                              |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                   | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS          | 0                                                                                                                           |                 |          |                           |           |               |                |
|                                                              | AFL          | 0                                                                                                                           |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                             |                 |          |                           |           |               | PKG:90         |
| 53-30-01-01-901                                              |              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                   |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                           | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL          | 0                                                                                                                           | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                             |                 |          |                           |           |               |                |
| 53-30-01-01-902                                              |              | DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL                                         |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                   |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                           | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL          | 0                                                                                                                           | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                             |                 |          |                           |           |               |                |
| 53-30-02-002                                                 |              | INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL                                                         |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS/MSC      | 23-Apr-20                                                                                                                   | O/C             |          |                           |           |               |                |
|                                                              | HRS          | 0                                                                                                                           |                 |          |                           |           |               |                |
|                                                              | AFL          | 0                                                                                                                           |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                             |                 |          |                           |           |               |                |
| 53-30-02-01-901                                              |              | DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL                       |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                   |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                           | T:12500         |          | 12500                     |           | 11204:36      |                |
|                                                              | AFL          | 0                                                                                                                           | T:10000         |          | 10000                     |           | 9402          |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                             |                 |          |                           |           |               |                |
| 53-30-02-01-902                                              |              | GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL                   |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                                   |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                           | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL          | 0                                                                                                                           | T:14000         |          | 14000                     |           | 13402         |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                          | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                               |           |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-30-02-01-903                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL                                                            |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-30-03-01-901                                              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL                              |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-30-03-01-902                                              | DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL                                                           |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 53-30-04-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES                                                                              |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                           | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |                 |          |                           |           |           | PKG:90         |
| 53-30-04-01-901                                              | DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL |           |                 |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                            |                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-30-04-01-902                                              | DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-30-05-02-901                                              | DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL                            |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                    | 0         | T:10000  |          | 10000                     |           | 8704:36   |                |
|                                                              | AFL                                                                                                                                    | 0         | T:8000   |          | 8000                      |           | 7402      |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-30-06-01-901                                              | DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL                      |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                    | 0         | T:12500  |          | 12500                     |           | 11204:36  |                |
|                                                              | AFL                                                                                                                                    | 0         | T:10000  |          | 10000                     |           | 9402      |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-30-06-01-902                                              | GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL                   |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                        |           |          |          |                           |           |           |                |
| 53-30-06-01-903                                              | DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL                            |           |          |          |                           |           |           | Service ATA:53 |
|                                                              | MOS                                                                                                                                    | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                    | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                    | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |                                                                                                                                        |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                     | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                            |              |                                                                                                                         |                 |          |                           |           |               |                |
| 53-30-07-001                                                 | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION                                     |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                               | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS          | 0                                                                                                                       |                 |          |                           |           |               |                |
|                                                              | AFL          | 0                                                                                                                       |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                         |                 |          |                           |           |               | PKG:90         |
|                                                              |              |                                                                                                                         |                 |          |                           |           |               |                |
| 53-30-07-002                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION                                     |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                               | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS          | 0                                                                                                                       |                 |          |                           |           |               |                |
|                                                              | AFL          | 0                                                                                                                       |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                         |                 |          |                           |           |               | PKG:90         |
|                                                              |              |                                                                                                                         |                 |          |                           |           |               |                |
| 53-30-07-01-901                                              |              | GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                               |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                       | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL          | 0                                                                                                                       | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                         |                 |          |                           |           |               |                |
|                                                              |              |                                                                                                                         |                 |          |                           |           |               |                |
| 53-30-07-01-902                                              |              | DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL         |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                               |                 |          |                           |           | AIRWORTHINESS |                |
|                                                              | HRS          | 0                                                                                                                       | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                              | AFL          | 0                                                                                                                       | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                         |                 |          |                           |           |               |                |
|                                                              |              |                                                                                                                         |                 |          |                           |           |               |                |
| 53-30-08-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46                                                                         |                 |          |                           |           |               | Service ATA:53 |
|                                                              | MOS          | 23-Apr-20                                                                                                               | 120 (+1m/-1m)   |          |                           |           |               |                |
|                                                              | HRS          | 0                                                                                                                       |                 |          |                           |           |               |                |
|                                                              | AFL          | 0                                                                                                                       |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00 |              |                                                                                                                         |                 |          |                           |           |               | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit         | C/W                                                                                                 | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 53 - FUSELAGE                                                                                      |              |                                                                                                     |                 |          |                           |           |               |                |
| 53-30-08-002                                                                                           | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46                                                     |                 |          |                           |           |               | Service ATA:53 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                           | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                                                                        | HRS          | 0                                                                                                   |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 0                                                                                                   |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 53-30-00PROC. REF: NDT PART 5 53-30-00                                           |              |                                                                                                     |                 |          |                           |           |               | PKG:90         |
| ATA 54 - NACELLES/PYLONS                                                                               |              |                                                                                                     |                 |          |                           |           |               |                |
| 54-00-00-001                                                                                           | <sup>S</sup> | GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS                                               |                 |          |                           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 19-Mar-24                                                                                           |                 |          |                           |           |               |                |
|                                                                                                        | HRS          | 781:30                                                                                              | 800 (+30/-30)   |          |                           |           |               |                |
|                                                                                                        | AFL          | 364                                                                                                 |                 |          |                           |           |               |                |
| PROC. REF: AMM 54-51-20PROC. REF: AMM 54-51-20                                                         |              |                                                                                                     |                 |          |                           |           |               | PKG:1          |
| 54-50-00-001                                                                                           | <sup>S</sup> | INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE                                  |                 |          |                           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                           | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                                                                        | HRS          | 0                                                                                                   |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 0                                                                                                   |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 54-50-00PROC. REF: NDT PART 5 54-50-00                                           |              |                                                                                                     |                 |          |                           |           |               | PKG:90         |
| 54-50-00-002                                                                                           | <sup>S</sup> | INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX                                                      |                 |          |                           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                           | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                                                                        | HRS          | 0                                                                                                   |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 0                                                                                                   |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00 |              |                                                                                                     |                 |          |                           |           |               | PKG:90         |
| 54-50-01-01-901                                                                                        |              | GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL |                 |          |                           |           |               | Service ATA:54 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                           |                 |          |                           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                   | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                                                                        | AFL          | 0                                                                                                   | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 54-50-00PROC. REF: NDT PART 5 54-50-00                                           |              |                                                                                                     |                 |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 54 - NACELLES/PYLONS                                     |                                                                                                     |           |               |          |                           |           |           |                |
| 54-50-02-01-901                                              | GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL            |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                                 | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                 | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                 | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 54-50-00PROC. REF: NDT PART 5 54-50-00 |                                                                                                     |           |               |          |                           |           |           |                |
| 54-50-03-001 <sup>S</sup>                                    | EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.                                  |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                                 | 31-Mar-25 | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                              | HRS                                                                                                 | 987:24    |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                 | 456       |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                     |           |               |          |                           |           |           |                |
| 54-50-03-01-901                                              | GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                                 | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                 | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                 | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                     |           |               |          |                           |           |           |                |
| 54-50-03-01-902                                              | DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL                            |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                                 | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                 | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                 | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                     |           |               |          |                           |           |           |                |
| 54-50-04-01-901                                              | GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL    |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                                 | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                 | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                 | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 54-52-00PROC. REF: NDT PART 5 54-52-00 |                                                                                                     |           |               |          |                           |           |           |                |
| 54-50-05-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES                                                  |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                                 | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                 | 0         |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                 | 0         |               |          |                           |           |           |                |

PKG:87

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                        | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 54 - NACELLES/PYLONS                                     |                                                                                             |           |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                             |           |               |          |                           |           |           |                |
| 54-50-05-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL             |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                         | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                         | 0         | T:15000       |          | 15000                     |           | 13704:36  |                |
|                                                              | AFL                                                                                         | 0         | T:12000       |          | 12000                     |           | 11402     |                |
| PROC. REF: NDT PART 6 54-55-00PROC. REF: NDT PART 6 54-55-00 |                                                                                             |           |               |          |                           |           |           |                |
| 54-50-05-02-901                                              | DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                         | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                         | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                         | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                             |           |               |          |                           |           |           |                |
| 54-50-06-01-901                                              | DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL                     |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                         | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                         | 0         | T:15000       |          | 15000                     |           | 13704:36  |                |
|                                                              | AFL                                                                                         | 0         | T:12000       |          | 12000                     |           | 11402     |                |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                             |           |               |          |                           |           |           |                |
| 54-50-06-01-902                                              | DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL                     |           |               |          |                           |           |           | Service ATA:54 |
|                                                              | MOS                                                                                         | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                         | 0         | T:15000       |          | 15000                     |           | 13704:36  |                |
|                                                              | AFL                                                                                         | 0         | T:12000       |          | 12000                     |           | 11402     |                |
| PROC. REF: NDT PART 5 54-55-00PROC. REF: NDT PART 5 54-55-00 |                                                                                             |           |               |          |                           |           |           |                |
| ATA 55 - STABILIZERS                                         |                                                                                             |           |               |          |                           |           |           |                |
| 55-00-00-001 <sup>S</sup>                                    | GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS                                  |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                         | 19-Mar-24 |               |          |                           |           |           |                |
|                                                              | HRS                                                                                         | 781:30    | 800 (+30/-30) |          |                           |           |           |                |
|                                                              | AFL                                                                                         | 364       |               |          |                           |           |           |                |
| PROC. REF: AMM 55-00-20PROC. REF: AMM 55-00-20               |                                                                                             |           |               |          |                           |           |           |                |
| PKG:1                                                        |                                                                                             |           |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                           | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 55 - STABILIZERS                                         |                                                                                                |           |               |          |                           |           |           |                  |
| 55-03-00                                                     | HORIZONTAL TAIL - EQUIPED                                                                      |           |               |          |                           |           |           | Component ATA:55 |
| PN:505-10983-403                                             | MOS/MSC                                                                                        | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:0001062622                                                | HRS                                                                                            | 0         |               | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                            | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                |           |               |          |                           |           |           |                  |
| 55-10-00                                                     | HORIZONTAL STABILIZER (COMPLETION)                                                             |           |               |          |                           |           |           | Component ATA:55 |
| PN:505-10700-421                                             | MOS/MSC                                                                                        | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:0001059745                                                | HRS                                                                                            | 0         |               | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                            | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                |           |               |          |                           |           |           |                  |
| 55-10-00-001 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS         |           |               |          |                           |           |           | Service ATA:55   |
|                                                              | MOS                                                                                            | 31-Mar-25 | 120 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                            | 987:24    |               |          |                           |           |           |                  |
|                                                              | AFL                                                                                            | 456       |               |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                |           |               |          |                           |           |           |                  |
| 55-10-00-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING         |           |               |          |                           |           |           | Service ATA:55   |
|                                                              | MOS                                                                                            | 31-Mar-25 | 60 (+1m/-1m)  |          |                           |           |           |                  |
|                                                              | HRS                                                                                            | 987:24    |               |          |                           |           |           |                  |
|                                                              | AFL                                                                                            | 456       |               |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                |           |               |          |                           |           |           |                  |
| 55-10-01-001 <sup>S</sup>                                    | EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS |           |               |          |                           |           |           | Service ATA:55   |
|                                                              | MOS                                                                                            | 31-Mar-25 | 120 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                            | 987:24    |               |          |                           |           |           |                  |
|                                                              | AFL                                                                                            | 456       |               |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                |           |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                              | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                   |           |               |          |                           |           |           |                |
| 55-10-01-01-901                                              | DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                               | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                   |           |               |          |                           |           |           |                |
| 55-10-02-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                               | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                   |           |               |          |                           |           |           |                |
| 55-10-02-01-902                                              | DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL                      |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                               | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                   |           |               |          |                           |           |           |                |
| 55-10-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN                                                 |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                               | 0         |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                               | 0         |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                   |           |               |          |                           |           |           | PKG:87         |
| 55-10-03-002 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN                                      |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 31-Mar-25 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                               | 987:24    |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                               | 456       |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                   |           |               |          |                           |           |           | PKG:87         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                  | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                       |           |                 |          |                           |           |           |                |
| 55-10-03-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                   | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                   | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                   | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                       |           |                 |          |                           |           |           |                |
| 55-10-03-01-902                                              | DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL                           |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                   | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                   | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                   | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                       |           |                 |          |                           |           |           |                |
| 55-10-04-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL                      |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                   | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                   | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                   | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                       |           |                 |          |                           |           |           |                |
| 55-10-05-001 <sup>S</sup>                                    | INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS                                                                   |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                   | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                   | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                   | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                       |           |                 |          |                           |           |           | PKG:90         |
| 55-10-05-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                     |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                   | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                   | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                   | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                                       |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                              |           |          |          |                           |           |           |                |
| 55-10-05-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 55-10-00PROC. REF: NDT PART 6 55-10-00 |                                                                                                                              |           |          |          |                           |           |           |                |
| 55-10-05-02-902                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                 |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                              |           |          |          |                           |           |           |                |
| 55-10-05-03-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                           |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                              |           |          |          |                           |           |           |                |
| 55-10-05-04-901                                              | DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL                      |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |                                                                                                                              |           |          |          |                           |           |           |                |
| 55-10-05-05-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL              |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 55-10-00PROC. REF: NDT PART 6 55-10-00 |                                                                                                                              |           |          |          |                           |           |           |                |
| 55-10-07-01-901                                              | GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL                                 |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000  |          | 14000                     |           | 13402     |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                                             | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                                                 |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                                 |               |          |                           |           |           |                |
| 55-10-08-001                                                 | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS                                                      |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 31-Mar-25                                                                                                                                       | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 987:24                                                                                                                                          |               |          |                           |           |           |                |
|                                                              | AFL          | 456                                                                                                                                             |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                                 |               |          |                           |           |           | PKG:87         |
| 55-10-08-01-901                                              |              | DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                       |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                                 |               |          |                           |           |           |                |
| 55-10-09-001                                                 |              | EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT                                                     |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS/MSC      | 23-Apr-20                                                                                                                                       | O/C           |          |                           |           |           |                |
|                                                              | HRS          | 0                                                                                                                                               |               |          |                           |           |           |                |
|                                                              | AFL          | 0                                                                                                                                               |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                                 |               |          |                           |           |           |                |
| 55-10-09-01-901                                              |              | DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL                                |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                       |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                                 |               |          |                           |           |           |                |
| 55-10-09-01-902                                              |              | DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL                                |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                                                       |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                                               | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                                               | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00 |              |                                                                                                                                                 |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit         | C/W                                                                                                                      | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------------------------------------------------|--------------|--------------------------------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 55 - STABILIZERS                                                                                   |              |                                                                                                                          |                 |          |                           |           |               |                |
| 55-10-10-001                                                                                           | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR TRIM-TAB FITTINGS                                                         |                 |          |                           |           |               | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                                                                        | HRS          | 0                                                                                                                        |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 0                                                                                                                        |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00                                           |              |                                                                                                                          |                 |          |                           |           |               | PKG:90         |
| 55-10-10-01-901                                                                                        |              | DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL           |                 |          |                           |           |               | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                |                 |          |                           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                                        | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                                                                        | AFL          | 0                                                                                                                        | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 55-10-00PROC. REF: NDT PART 5 55-10-00                                           |              |                                                                                                                          |                 |          |                           |           |               |                |
| 55-20-01-002                                                                                           | <sup>S</sup> | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX                                                      |                 |          |                           |           |               | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                | 120 (+1m/-1m)   |          |                           |           |               |                |
|                                                                                                        | HRS          | 0                                                                                                                        |                 |          |                           |           |               |                |
|                                                                                                        | AFL          | 0                                                                                                                        |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00 |              |                                                                                                                          |                 |          |                           |           |               | PKG:87         |
| 55-20-01-01-901                                                                                        |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL                 |                 |          |                           |           |               | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                |                 |          |                           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                                        | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                                                                        | AFL          | 0                                                                                                                        | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00                                           |              |                                                                                                                          |                 |          |                           |           |               |                |
| 55-20-01-01-902                                                                                        |              | DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL |                 |          |                           |           |               | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                |                 |          |                           |           | AIRWORTHINESS |                |
|                                                                                                        | HRS          | 0                                                                                                                        | T:17500         |          | 17500                     |           | 16204:36      |                |
|                                                                                                        | AFL          | 0                                                                                                                        | T:14000         |          | 14000                     |           | 13402         |                |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00                                           |              |                                                                                                                          |                 |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit                                                                                                            | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                                                                   |                                                                                                                 |           |               |          |                           |           |           |                |
| 55-20-02-01-901                                                                                        | DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL                                  |           |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS                                                                                                             | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                                                                        | HRS                                                                                                             | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                                                                        | AFL                                                                                                             | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00                                           |                                                                                                                 |           |               |          |                           |           |           |                |
| 55-20-02-02-901                                                                                        | GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL                                |           |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS                                                                                                             | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                                                                        | HRS                                                                                                             | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                                                                        | AFL                                                                                                             | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00                                           |                                                                                                                 |           |               |          |                           |           |           |                |
| 55-20-03-001 <sup>S</sup>                                                                              | EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY                                            |           |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS                                                                                                             | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                                                                        | HRS                                                                                                             | 0         |               |          |                           |           |           |                |
|                                                                                                        | AFL                                                                                                             | 0         |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00                                           |                                                                                                                 |           |               |          |                           |           |           | PKG:87         |
| 55-20-03-01-901                                                                                        | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL |           |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS                                                                                                             | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                                                                        | HRS                                                                                                             | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                                                                        | AFL                                                                                                             | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 55-20-00PROC. REF: NDT PART 6 55-20-00                                           |                                                                                                                 |           |               |          |                           |           |           |                |
| 55-20-03-02-901                                                                                        | SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL       |           |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS                                                                                                             | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                                                                        | HRS                                                                                                             | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                                                                        | AFL                                                                                                             | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 8 55-20-00PROC. REF: NDT PART 8 55-20-00                                           |                                                                                                                 |           |               |          |                           |           |           |                |
| 55-20-04-001                                                                                           | INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS                              |           |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS                                                                                                             | 31-Mar-25 | 60            |          | 31-Mar-30                 |           | 1341 d    | ALI            |
|                                                                                                        | HRS                                                                                                             | 987:24    |               |          |                           |           |           |                |
|                                                                                                        | AFL                                                                                                             | 456       |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00 |                                                                                                                 |           |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                          | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 55-20-04-002                                                 | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS                                                                             |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                           | 31-Mar-25 | 60              |          | 31-Mar-30                 |           | 1341 d    | ALI            |
|                                                              | HRS                                                                                                                                                           | 987:24    |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                           | 456       |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-20-00PROC. REF: NDT PART 5 55-20-00 |                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 55-22-00-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB                                                                                                      |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-22-00PROC. REF: NDT PART 5 55-22-00 |                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 55-30-01-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER                                                 |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                           | 31-Mar-25 | 120 (+1m/-1m)   |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                           | 987:24    |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                           | 456       |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 55-30-01-002 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER                                                     |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                           | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                               |           |                 |          |                           |           |           |                |
| 55-30-01-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 55-30-00PROC. REF: NDT PART 6 55-30-00 |                                                                                                                                                               |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                                        |           |               |          |                           |           |           |                |
| 55-30-01-02-901                                              | DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                   |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                        |           |               |          |                           |           |           |                |
| 55-30-01-03-901                                              | DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                                             |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                        |           |               |          |                           |           |           |                |
| 55-30-01-04-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 55-30-00PROC. REF: NDT PART 6 55-30-00 |                                                                                                                                                        |           |               |          |                           |           |           |                |
| 55-30-02-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER                                 |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                    | 31-Mar-25 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                    | 987:24    |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                    | 456       |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                        |           |               |          |                           |           |           | PKG:87         |
| 55-30-02-01-901                                              | DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL        |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                    | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                    | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                    | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                        |           |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                                                       |           |          |          |                           |           |           |                |
| 55-30-02-03-901                                              | DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                                                 |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |          |          |                           |           |           |                |
| 55-30-02-04-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                       |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 55-30-00PROC. REF: NDT PART 6 55-30-00 |                                                                                                                                                                       |           |          |          |                           |           |           |                |
| 55-30-02-05-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                          |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |          |          |                           |           |           |                |
| 55-30-02-06-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL                |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |          |          |                           |           |           |                |
| 55-30-02-07-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL |           |          |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                                                                   | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                                   | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                                   | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                                                       |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit         | C/W                                                                                                                               | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------------------------------------------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                                                                   |              |                                                                                                                                   |               |          |                           |           |           |                |
| 55-30-03-001                                                                                           | <sup>S</sup> | INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS                                                |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                         | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                                                                        | HRS          | 0                                                                                                                                 |               |          |                           |           |           |                |
|                                                                                                        | AFL          | 0                                                                                                                                 |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00                                           |              |                                                                                                                                   |               |          |                           |           |           | PKG:87         |
| 55-30-03-002                                                                                           | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX                                                               |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                         | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                                                                        | HRS          | 0                                                                                                                                 |               |          |                           |           |           |                |
|                                                                                                        | AFL          | 0                                                                                                                                 |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00, NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00, NDT PART 5 55-30-00 |              |                                                                                                                                   |               |          |                           |           |           | PKG:87         |
| 55-30-03-01-901                                                                                        |              | DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL                                        |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                         |               |          |                           |           |           | AIRWORTHINESS  |
|                                                                                                        | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                                                                        | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00                                           |              |                                                                                                                                   |               |          |                           |           |           |                |
| 55-30-03-01-902                                                                                        |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS          | 23-Apr-20                                                                                                                         |               |          |                           |           |           | AIRWORTHINESS  |
|                                                                                                        | HRS          | 0                                                                                                                                 | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                                                                        | AFL          | 0                                                                                                                                 | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00                                           |              |                                                                                                                                   |               |          |                           |           |           |                |
| 55-30-04-001                                                                                           | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING                                                |               |          |                           |           |           | Service ATA:55 |
|                                                                                                        | MOS          | 31-Mar-25                                                                                                                         | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                                                                        | HRS          | 987:24                                                                                                                            |               |          |                           |           |           |                |
|                                                                                                        | AFL          | 456                                                                                                                               |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00                                           |              |                                                                                                                                   |               |          |                           |           |           | PKG:90         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                              | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                                   |           |                 |          |                           |           |           |                |
| 55-30-04-01-901                                              | GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL                                         |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                               | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |                 |          |                           |           |           |                |
| 55-30-05-002 <sup>S</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER                      |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 31-Mar-25 | 60 (+1m/-1m)    |          |                           |           |           |                |
|                                                              | HRS                                                                                                                               | 987:24    |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                               | 456       |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |                 |          |                           |           |           |                |
| 55-30-05-01-901                                              | DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL  |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                               | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |                 |          |                           |           |           |                |
| 55-30-06-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING                                                           |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                               | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                               | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |                 |          |                           |           |           |                |
| 55-30-06-01-901                                              | DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL |           |                 |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                               | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                               | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                               | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-30-00PROC. REF: NDT PART 5 55-30-00 |                                                                                                                                   |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                                    | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------------------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |              |                                                                                                                        |               |          |                           |           |           |                |
| 55-40-01-002                                                 | <sup>S</sup> | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX                                                      |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                              | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 0                                                                                                                      |               |          |                           |           |           |                |
|                                                              | AFL          | 0                                                                                                                      |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                        |               |          |                           |           |           | PKG:87         |
| 55-40-01-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL                 |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                              |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                      | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                      | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                        |               |          |                           |           |           |                |
| 55-40-01-01-902                                              |              | DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                              |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                      | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                      | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                        |               |          |                           |           |           |                |
| 55-40-02-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS                                                           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                              | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 0                                                                                                                      |               |          |                           |           |           |                |
|                                                              | AFL          | 0                                                                                                                      |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                        |               |          |                           |           |           | PKG:87         |
| 55-40-02-01-901                                              |              | DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL                                         |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS          | 23-Apr-20                                                                                                              |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                                      | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                                      | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |              |                                                                                                                        |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                         | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 55 - STABILIZERS                                         |                                                                                                                              |           |               |          |                           |           |           |                |
| 55-40-02-02-901                                              | GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL                                        |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |                                                                                                                              |           |               |          |                           |           |           |                |
| 55-40-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY                                                           |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                          | 0         |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                          | 0         |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |                                                                                                                              |           |               |          |                           |           |           |                |
| 55-40-03-01-901                                              | GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                          | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                          | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |                                                                                                                              |           |               |          |                           |           |           |                |
| 55-40-04-002                                                 | INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS                                  |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 31-Mar-25 | 60            |          | 31-Mar-30                 |           | 1341 d    | ALI            |
|                                                              | HRS                                                                                                                          | 987:24    |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                          | 456       |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |                                                                                                                              |           |               |          |                           |           |           |                |
| 55-40-04-003                                                 | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS                           |           |               |          |                           |           |           | Service ATA:55 |
|                                                              | MOS                                                                                                                          | 31-Mar-25 | 60            |          | 31-Mar-30                 |           | 1341 d    | ALI            |
|                                                              | HRS                                                                                                                          | 987:24    |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                          | 456       |               |          |                           |           |           |                |
| PROC. REF: NDT PART 5 55-40-00PROC. REF: NDT PART 5 55-40-00 |                                                                                                                              |           |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                                  | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit     | Remaining | Disposition      |
|----------------------------------------------------------------------------|--------------|----------------------------------------------------------------------|-----------------|----------|---------------------------|---------------|-----------|------------------|
| ATA 55 - STABILIZERS                                                       |              |                                                                      |                 |          |                           |               |           |                  |
| 55-42-00-001                                                               | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB               |                 |          |                           |               |           | Service ATA:55   |
|                                                                            | MOS          | 23-Apr-20                                                            | T:120 (+1m/-1m) |          |                           |               |           |                  |
|                                                                            | HRS          | 0                                                                    |                 |          |                           |               |           |                  |
|                                                                            | AFL          | 0                                                                    |                 |          |                           |               |           |                  |
| PROC. REF: NDT PART 5 55-42-00PROC. REF: NDT PART 5 55-42-00               |              |                                                                      |                 |          |                           |               |           | PKG:90           |
| ATA 56 - WINDOWS                                                           |              |                                                                      |                 |          |                           |               |           |                  |
| 56-10-00                                                                   |              | COPILOT HEATED GLASS WINDSHIELD ASSY                                 |                 |          |                           |               |           | Component ATA:56 |
| PN:NP-195301-6                                                             | MOS/MSC      | 23-Apr-20                                                            | O/C             | TSN 0    |                           |               |           |                  |
| SN:19068H6151                                                              | HRS          | 0                                                                    | TSN 0           |          |                           |               |           |                  |
|                                                                            | AFL          | 0                                                                    | TSN 0           |          |                           |               |           |                  |
| PROC. REF: AMM 56-11-00, AMM 56-11-00PROC. REF: AMM 56-11-00, AMM 56-11-00 |              |                                                                      |                 |          |                           |               |           |                  |
| 56-10-00                                                                   |              | PILOT HEATED GLASS WINDSHIELD ASSY                                   |                 |          |                           |               |           | Component ATA:56 |
| PN:NP-195301-5                                                             | MOS/MSC      | 23-Apr-20                                                            | O/C             | TSN 0    |                           |               |           |                  |
| SN:19098H9247                                                              | HRS          | 0                                                                    | TSN 0           |          |                           |               |           |                  |
|                                                                            | AFL          | 0                                                                    | TSN 0           |          |                           |               |           |                  |
| PROC. REF: AMM 56-11-00, AMM 56-11-00PROC. REF: AMM 56-11-00, AMM 56-11-00 |              |                                                                      |                 |          |                           |               |           |                  |
| 56-10-01-001                                                               | <sup>S</sup> | EXTERNAL GENERAL VISUAL INSPECTION OF SIDE WINDOWS PANE (BOTH SIDES) |                 |          |                           |               |           | Service ATA:56   |
|                                                                            | MOS          | 31-Mar-25                                                            | 120 (+1m/-1m)   |          |                           |               |           |                  |
|                                                                            | HRS          | 987:24                                                               |                 |          |                           |               |           |                  |
|                                                                            | AFL          | 456                                                                  |                 |          |                           |               |           |                  |
| PROC. REF: NDT PART 5 56-12-00PROC. REF: NDT PART 5 56-12-00               |              |                                                                      |                 |          |                           |               |           | PKG:87           |
| 56-10-01-002                                                               |              | FUNCTIONAL CHECK (TORQUE) OF COPILOT SIDE WINDOW ATTACHING BOLTS     |                 |          |                           |               |           | Service ATA:56   |
| PN:NP-195302-4                                                             | MOS          | 19-Mar-24                                                            |                 |          |                           |               |           |                  |
| SN:19155H4636                                                              | HRS          | 781:30                                                               | 1600 (+30/-30)  | 2381:30  | 2411:30                   | 1086:06 (+30) |           |                  |
|                                                                            | AFL          | 364                                                                  |                 |          |                           |               |           |                  |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00                             |              |                                                                      |                 |          |                           |               |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                  | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 56 - WINDOWS                                             |                                                                       |           |                 |          |                           |           |               |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF COPILOT WINDSHIELD ATTACHING BOLTS       |           |                 |          |                           |           |               | Service ATA:56 |
| PN:NP-195301-6                                               | MOS                                                                   | 19-Mar-24 |                 |          |                           |           |               |                |
| SN:19068H6151                                                | HRS                                                                   | 781:30    | 1600 (+30/-30)  |          | 2381:30                   | 2411:30   | 1086:06 (+30) |                |
|                                                              | AFL                                                                   | 364       |                 |          |                           |           |               |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                 |          |                           |           |               |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF PILOT SIDE WINDOW ATTACHING BOLTS        |           |                 |          |                           |           |               | Service ATA:56 |
| PN:NP-195302-3                                               | MOS                                                                   | 19-Mar-24 |                 |          |                           |           |               |                |
| SN:19135H2809                                                | HRS                                                                   | 781:30    | 1600 (+30/-30)  |          | 2381:30                   | 2411:30   | 1086:06 (+30) |                |
|                                                              | AFL                                                                   | 364       |                 |          |                           |           |               |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                 |          |                           |           |               |                |
| 56-10-01-002                                                 | FUNCTIONAL CHECK (TORQUE) OF PILOT WINDSHIELD ATTACHING BOLTS         |           |                 |          |                           |           |               | Service ATA:56 |
| PN:NP-195301-5                                               | MOS                                                                   | 19-Mar-24 |                 |          |                           |           |               |                |
| SN:19098H9247                                                | HRS                                                                   | 781:30    | 1600 (+30/-30)  |          | 2381:30                   | 2411:30   | 1086:06 (+30) |                |
|                                                              | AFL                                                                   | 364       |                 |          |                           |           |               |                |
| PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00               |                                                                       |           |                 |          |                           |           |               |                |
| 56-10-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE |           |                 |          |                           |           |               | Service ATA:56 |
|                                                              | MOS                                                                   | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS                                                                   | 0         |                 |          |                           |           |               |                |
|                                                              | AFL                                                                   | 0         |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00 |                                                                       |           |                 |          |                           |           |               | PKG:90         |
| 56-10-03-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE |           |                 |          |                           |           |               | Service ATA:56 |
|                                                              | MOS                                                                   | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |               |                |
|                                                              | HRS                                                                   | 0         |                 |          |                           |           |               |                |
|                                                              | AFL                                                                   | 0         |                 |          |                           |           |               |                |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00 |                                                                       |           |                 |          |                           |           |               | PKG:90         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit         | C/W                                                                                                           | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|----------------------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------------|-----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 56 - WINDOWS                                                           |              |                                                                                                               |                 |          |                           |           |               |                  |
| 56-10-03-001                                                               | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE                                                 |                 |          |                           |           |               | Service ATA:56   |
|                                                                            | MOS          | 23-Apr-20                                                                                                     | T:120 (+1m/-1m) |          |                           |           |               |                  |
|                                                                            | HRS          | 0                                                                                                             |                 |          |                           |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |                 |          |                           |           |               |                  |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00               |              |                                                                                                               |                 |          |                           |           |               | PKG:90           |
| 56-10-03-001                                                               | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE                                                |                 |          |                           |           |               | Service ATA:56   |
|                                                                            | MOS          | 23-Apr-20                                                                                                     | T:120 (+1m/-1m) |          |                           |           |               |                  |
|                                                                            | HRS          | 0                                                                                                             |                 |          |                           |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |                 |          |                           |           |               |                  |
| PROC. REF: NDT PART 5 56-10-00PROC. REF: NDT PART 5 56-10-00               |              |                                                                                                               |                 |          |                           |           |               | PKG:90           |
| 56-10-03-01-901                                                            |              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL |                 |          |                           |           |               | Service ATA:56   |
|                                                                            | MOS          | 23-Apr-20                                                                                                     |                 |          |                           |           | AIRWORTHINESS |                  |
|                                                                            | HRS          | 0                                                                                                             | T:17500         |          | 17500                     |           | 16204:36      |                  |
|                                                                            | AFL          | 0                                                                                                             | T:14000         |          | 14000                     |           | 13402         |                  |
| PROC. REF: NDT PART 6 56-10-00PROC. REF: NDT PART 6 56-10-00               |              |                                                                                                               |                 |          |                           |           |               |                  |
| 56-12-00                                                                   |              | COPILOT ACRYLIC SIDE WINDOW                                                                                   |                 |          |                           |           |               | Component ATA:56 |
| PN:NP-195302-4                                                             | MOS/MSC      | 23-Apr-20                                                                                                     | O/C             | TSN 0    |                           |           |               |                  |
| SN:19155H4636                                                              | HRS          | 0                                                                                                             |                 |          | TSN 0                     |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |                 |          | TSN 0                     |           |               |                  |
| PROC. REF: AMM 56-12-00, AMM 56-12-00PROC. REF: AMM 56-12-00, AMM 56-12-00 |              |                                                                                                               |                 |          |                           |           |               |                  |
| 56-12-00                                                                   |              | PILOT ACRYLIC SIDE WINDOW                                                                                     |                 |          |                           |           |               | Component ATA:56 |
| PN:NP-195302-3                                                             | MOS/MSC      | 23-Apr-20                                                                                                     | O/C             | TSN 0    |                           |           |               |                  |
| SN:19135H2809                                                              | HRS          | 0                                                                                                             |                 |          | TSN 0                     |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |                 |          | TSN 0                     |           |               |                  |
| PROC. REF: AMM 56-12-00, AMM 56-12-00PROC. REF: AMM 56-12-00, AMM 56-12-00 |              |                                                                                                               |                 |          |                           |           |               |                  |
| 56-20-00                                                                   |              | NO. 1 WINDOW TRANSPARENCY                                                                                     |                 |          |                           |           |               | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC      | 23-Apr-20                                                                                                     | O/C             | TSN 0    |                           |           |               |                  |
| SN:842643                                                                  | HRS          | 0                                                                                                             |                 |          | TSN 0                     |           |               |                  |
|                                                                            | AFL          | 0                                                                                                             |                 |          | TSN 0                     |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS                                                           |                            |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                           |           |           |                  |
| 56-20-00                                                                   | NO. 10 WINDOW TRANSPARENCY |           |          |          |                           |           |           | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:868189                                                                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                           |           |           |                  |
| 56-20-00                                                                   | NO. 11 WINDOW TRANSPARENCY |           |          |          |                           |           |           | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:856007                                                                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                           |           |           |                  |
| 56-20-00                                                                   | NO. 2 WINDOW TRANSPARENCY  |           |          |          |                           |           |           | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:842640                                                                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                           |           |           |                  |
| 56-20-00                                                                   | NO. 3 WINDOW TRANSPARENCY  |           |          |          |                           |           |           | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:856004                                                                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                           |           |           |                  |
| 56-20-00                                                                   | NO. 4 WINDOW TRANSPARENCY  |           |          |          |                           |           |           | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:856005                                                                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                            |           |          |          |                           |           |           |                  |
| 56-20-00                                                                   | NO. 5 WINDOW TRANSPARENCY  |           |          |          |                           |           |           | Component ATA:56 |
| PN:14024                                                                   | MOS/MSC                    | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:856006                                                                  | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN | Unit | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---------|------|-----|----------|----------|---------------------------|-----------|-----------|-------------|
|---------|------|-----|----------|----------|---------------------------|-----------|-----------|-------------|

### ATA 56 - WINDOWS

PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00

|                                                                            |                           |           |     |       |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 6 WINDOW TRANSPARENCY |           |     |       |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 23-Apr-20 | O/C | TSN 0 |  |  |           |        |
| SN:888685                                                                  | HRS                       | 0         |     | TSN 0 |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |           |        |

|                                                                            |                           |           |     |       |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 7 WINDOW TRANSPARENCY |           |     |       |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 23-Apr-20 | O/C | TSN 0 |  |  |           |        |
| SN:856010                                                                  | HRS                       | 0         |     | TSN 0 |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |           |        |

|                                                                            |                           |           |     |       |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 8 WINDOW TRANSPARENCY |           |     |       |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 23-Apr-20 | O/C | TSN 0 |  |  |           |        |
| SN:856013                                                                  | HRS                       | 0         |     | TSN 0 |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |           |        |

|                                                                            |                           |           |     |       |  |  |           |        |
|----------------------------------------------------------------------------|---------------------------|-----------|-----|-------|--|--|-----------|--------|
| 56-20-00                                                                   | NO. 9 WINDOW TRANSPARENCY |           |     |       |  |  | Component | ATA:56 |
| PN:14024                                                                   | MOS/MSC                   | 23-Apr-20 | O/C | TSN 0 |  |  |           |        |
| SN:868187                                                                  | HRS                       | 0         |     | TSN 0 |  |  |           |        |
|                                                                            | AFL                       | 0         |     | TSN 0 |  |  |           |        |
| PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00 |                           |           |     |       |  |  |           |        |

|                                                              |                                                                   |           |               |  |  |  |         |        |
|--------------------------------------------------------------|-------------------------------------------------------------------|-----------|---------------|--|--|--|---------|--------|
| 56-20-01-001 <sup>S</sup>                                    | EXTERNAL GENERAL VISUAL INSPECTION OF THE PASSENGER WINDOW PANELS |           |               |  |  |  | Service | ATA:56 |
|                                                              | MOS                                                               | 31-Mar-25 | 120 (+1m/-1m) |  |  |  |         |        |
|                                                              | HRS                                                               | 987:24    |               |  |  |  |         |        |
|                                                              | AFL                                                               | 456       |               |  |  |  |         |        |
| PROC. REF: NDT PART 5 56-20-00PROC. REF: NDT PART 5 56-20-00 |                                                                   |           |               |  |  |  |         |        |

PKG:87

### ATA 57 - WINGS

|                           |                                                         |           |  |  |  |  |         |        |
|---------------------------|---------------------------------------------------------|-----------|--|--|--|--|---------|--------|
| 57-00-00-001 <sup>S</sup> | GENERAL VISUAL INSPECTION OF WINGLET POLYURETHANE FILMS |           |  |  |  |  | Service | ATA:57 |
|                           | MOS                                                     | 19-Mar-24 |  |  |  |  |         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                             | Unit    | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---------------------------------------------------------------------------------------------------------------------|---------|-----------|-----------------|----------|---------------------------|-----------|-----------|-------------|
| ATA 57 - WINGS                                                                                                      |         |           |                 |          |                           |           |           |             |
|                                                                                                                     | HRS     | 781:30    | 800 (+30/-30)   |          |                           |           |           |             |
|                                                                                                                     | AFL     | 364       |                 |          |                           |           |           |             |
| PROC. REF: AMM 57-35-21PROC. REF: AMM 57-35-21                                                                      |         |           |                 |          |                           |           |           | PKG:1       |
| 57-10-00-001 <sup>S</sup> INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX Service ATA:57                       |         |           |                 |          |                           |           |           |             |
|                                                                                                                     | MOS     | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |             |
|                                                                                                                     | HRS     | 0         |                 |          |                           |           |           |             |
|                                                                                                                     | AFL     | 0         |                 |          |                           |           |           |             |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00                                                        |         |           |                 |          |                           |           |           | PKG:90      |
| 57-10-00-002 <sup>S</sup> SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN Service ATA:57   |         |           |                 |          |                           |           |           |             |
|                                                                                                                     | MOS     | 23-Apr-20 | 120 (+1m/-1m)   |          |                           |           |           |             |
|                                                                                                                     | HRS     | 0         |                 |          |                           |           |           |             |
|                                                                                                                     | AFL     | 0         |                 |          |                           |           |           |             |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00                                                        |         |           |                 |          |                           |           |           | PKG:87      |
| 57-10-01 LEFT WING LOWER SKIN Component ATA:57                                                                      |         |           |                 |          |                           |           |           |             |
| PN:505-12400-419                                                                                                    | MOS/MSC | 23-Apr-20 | O/C             | TSN 0    |                           |           |           |             |
| SN:0001050561                                                                                                       | HRS     | 0         |                 | TSN 0    |                           |           |           |             |
|                                                                                                                     | AFL     | 0         |                 | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                  |         |           |                 |          |                           |           |           |             |
| 57-10-01 RIGHT WING LOWER SKIN Component ATA:57                                                                     |         |           |                 |          |                           |           |           |             |
| PN:505-12400-420                                                                                                    | MOS/MSC | 23-Apr-20 | O/C             | TSN 0    |                           |           |           |             |
| SN:0001050391                                                                                                       | HRS     | 0         |                 | TSN 0    |                           |           |           |             |
|                                                                                                                     | AFL     | 0         |                 | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                  |         |           |                 |          |                           |           |           |             |
| 57-10-01-001 <sup>S</sup> EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS Service ATA:57 |         |           |                 |          |                           |           |           |             |
|                                                                                                                     | MOS     | 23-Apr-20 | 120 (+1m/-1m)   |          |                           |           |           |             |
|                                                                                                                     | HRS     | 0         |                 |          |                           |           |           |             |
|                                                                                                                     | AFL     | 0         |                 |          |                           |           |           |             |
| PROC. REF: NDT PART 5 57-00-00PROC. REF: NDT PART 5 57-00-00                                                        |         |           |                 |          |                           |           |           | PKG:87      |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                  | C/W       | Interval        | TSX/Adj.     | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|-----------|-----------------|--------------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                                               |                                                                                                       |           |                 |              |                           |           |           |                  |
| 57-10-01-01-901                                              | DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL         |           |                 |              |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                   | 23-Apr-20 |                 |              |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                   | 0         | T:17500         |              | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                   | 0         | T:14000         |              | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                       |           |                 |              |                           |           |           |                  |
| 57-10-02 <sup>U</sup>                                        | SKIN LOWER, MACHINED-WING, AL                                                                         |           |                 |              |                           |           |           | Component ATA:57 |
| PN:505-37111-901                                             | MOS/MSC                                                                                               |           | O/C             | TSO 0        |                           |           |           |                  |
| SN:RA-0041552-1                                              | HRS                                                                                                   |           |                 | TSN 0, TSO 0 |                           |           |           |                  |
|                                                              | AFL                                                                                                   |           |                 | TSO 0        |                           |           |           |                  |
|                                                              |                                                                                                       |           |                 |              |                           |           |           |                  |
| 57-10-02-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR                                                |           |                 |              |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                   | 23-Apr-20 | T:120 (+1m/-1m) |              |                           |           |           |                  |
|                                                              | HRS                                                                                                   | 0         |                 |              |                           |           |           |                  |
|                                                              | AFL                                                                                                   | 0         |                 |              |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                       |           |                 |              |                           |           |           | PKG:90           |
| 57-10-02-01-901                                              | DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL |           |                 |              |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                   | 23-Apr-20 |                 |              |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                   | 0         | T:17500         |              | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                   | 0         | T:14000         |              | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                       |           |                 |              |                           |           |           |                  |
| 57-10-03 <sup>U</sup>                                        | SKIN-LOWER, MACHINED-WING, AL                                                                         |           |                 |              |                           |           |           | Component ATA:57 |
| PN:505-37111-902                                             | MOS/MSC                                                                                               |           | O/C             | TSO 0        |                           |           |           |                  |
| SN:RA-0041877-2                                              | HRS                                                                                                   |           |                 | TSN 0, TSO 0 |                           |           |           |                  |
|                                                              | AFL                                                                                                   |           |                 | TSO 0        |                           |           |           |                  |
|                                                              |                                                                                                       |           |                 |              |                           |           |           |                  |
| 57-10-03-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR                                                 |           |                 |              |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                   | 23-Apr-20 | T:120 (+1m/-1m) |              |                           |           |           |                  |
|                                                              | HRS                                                                                                   | 0         |                 |              |                           |           |           |                  |
|                                                              | AFL                                                                                                   | 0         |                 |              |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                       |           |                 |              |                           |           |           | PKG:90           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                           | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |                                                                                                                |           |               |          |                           |           |           |                |
| 57-10-03-01-901                                              | DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                            | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                            | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                            | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |               |          |                           |           |           |                |
| 57-10-04-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR                                                          |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                            | 31-Mar-25 | 60 (+1m/-1m)  |          |                           |           |           |                |
|                                                              | HRS                                                                                                            | 987:24    |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                            | 456       |               |          |                           |           |           |                |
|                                                              |                                                                                                                |           |               |          |                           |           |           | PKG:84         |
| PROC. REF: NDT PART 5 57-20-00PROC. REF: NDT PART 5 57-20-00 |                                                                                                                |           |               |          |                           |           |           |                |
| 57-10-04-01-901                                              | DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL                                               |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                            | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                            | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                            | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |               |          |                           |           |           |                |
| 57-10-05-01-901                                              | GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL                 |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                            | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                            | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                            | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |               |          |                           |           |           |                |
| 57-10-06-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL                                                        |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                            | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                            | 0         |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                            | 0         |               |          |                           |           |           |                |
|                                                              |                                                                                                                |           |               |          |                           |           |           | PKG:87         |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                |           |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------|----------------------------------------------------------------------------------------------------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |              |                                                                                                    |              |          |                           |           |           |                |
| 57-10-07-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL                                            |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 31-Mar-25                                                                                          | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 987:24                                                                                             |              |          |                           |           |           |                |
|                                                              | AFL          | 456                                                                                                |              |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |              |          |                           |           |           | PKG:84         |
| 57-10-07-01-901                                              |              | GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                          |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                  | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                  | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |              |          |                           |           |           |                |
| 57-10-07-01-902                                              |              | DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL                                 |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                          |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                  | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                  | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |              |          |                           |           |           |                |
| 57-10-08-01-901                                              |              | DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL                                         |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                          |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                  | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                  | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |              |          |                           |           |           |                |
| 57-10-08-02-901                                              |              | DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL                                |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                          |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                  | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                  | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |              |                                                                                                    |              |          |                           |           |           |                |
| 57-10-11-001                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE                                          |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 31-Mar-25                                                                                          | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 987:24                                                                                             |              |          |                           |           |           |                |
|                                                              | AFL          | 456                                                                                                |              |          |                           |           |           |                |
|                                                              |              |                                                                                                    |              |          |                           |           |           | PKG:84         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                                               |                                                                                                                     |           |              |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                           |           |           |                  |
| 57-10-11-01-901                                              | DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL       |           |              |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                           |           |           |                  |
| 57-10-11-01-902                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL |           |              |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                           |           |           |                  |
| 57-10-12-01-901                                              | DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL                         |           |              |          |                           |           |           | Service ATA:57   |
|                                                              | MOS/MSC                                                                                                             | 23-Apr-20 | N/A          |          |                           |           |           |                  |
|                                                              | HRS                                                                                                                 | 0         |              |          |                           |           |           |                  |
|                                                              | AFL                                                                                                                 | 0         |              |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-10-00PROC. REF: NDT PART 5 57-10-00 |                                                                                                                     |           |              |          |                           |           |           |                  |
| 57-10-30                                                     | LEFT WING ASSEMBLY                                                                                                  |           |              |          |                           |           |           | Component ATA:57 |
| PN:505-11900-459                                             | MOS/MSC                                                                                                             | 23-Apr-20 | O/C          | TSN 0    |                           |           |           |                  |
| SN:0001059112                                                | HRS                                                                                                                 | 0         |              | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                                                 | 0         |              | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                                     |           |              |          |                           |           |           |                  |
| 57-50-01-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS                  |           |              |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                 | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                                                 | 987:24    |              |          |                           |           |           |                  |
|                                                              | AFL                                                                                                                 | 456       |              |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                     |           |              |          |                           |           |           | PKG:84           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |                                                                                                                                                               |           |          |          |                           |           |           |                |
| 57-50-01-01-901                                              | DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES<br>SUPPORT FITTINGS - INTERNAL                  |           |          |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                           | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                           | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                               |           |          |          |                           |           |           |                |
| 57-50-01-01-902                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES<br>SUPPORT FITTINGS - INTERNAL                 |           |          |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                           | 0         | T:11250  |          | 11250                     |           | 9954:36   |                |
|                                                              | AFL                                                                                                                                                           | 0         | T:9000   |          | 9000                      |           | 8402      |                |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                               |           |          |          |                           |           |           |                |
| 57-50-01-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND<br>CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL |           |          |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                           | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                           | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                               |           |          |          |                           |           |           |                |
| 57-50-01-03-901                                              | DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES<br>SUPPORT FITTINGS - EXTERNAL                   |           |          |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                           | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                           | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                               |           |          |          |                           |           |           |                |
| 57-50-01-04-901                                              | DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES<br>SUPPORT FITTINGS - EXTERNAL                    |           |          |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                           | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                           | 0         | T:17500  |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                           | 0         | T:14000  |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                               |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                         | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |                                                                                                                                                              |           |              |          |                           |           |           |                |
| 57-50-01-05-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL      |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                          | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                              |           |              |          |                           |           |           |                |
| 57-50-01-05-902                                              | DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL                             |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                          | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                              |           |              |          |                           |           |           |                |
| 57-50-02-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK                                                         |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                          | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                                          | 987:24    |              |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                                          | 456       |              |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-20-00PROC. REF: NDT PART 5 57-20-00 |                                                                                                                                                              |           |              |          |                           |           |           | PKG:84         |
| 57-50-02-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                          | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                                              |           |              |          |                           |           |           |                |
| 57-50-02-01-902                                              | DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL                        |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                                          | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                                          | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                                          | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                                              |           |              |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                          | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 57-50-02-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL |           |                 |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 57-50-00PROC. REF: NDT PART 6 57-50-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 57-50-02-02-902                                              | DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL                        |           |                 |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-50-00PROC. REF: NDT PART 5 57-50-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |
| 57-52-00-001 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP                                                                            |           |                 |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 | T:120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                           | 0         |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                           | 0         |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                                               |           |                 |          |                           |           |           | PKG:90         |
| 57-52-00-002 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP                                                                                       |           |                 |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                           | 31-Mar-25 | 60 (+1m/-1m)    |          |                           |           |           |                |
|                                                              | HRS                                                                                                                                           | 987:24    |                 |          |                           |           |           |                |
|                                                              | AFL                                                                                                                                           | 456       |                 |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                                               |           |                 |          |                           |           |           | PKG:84         |
| 57-52-01-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL                                     |           |                 |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                                           | 23-Apr-20 |                 |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                                           | 0         | T:17500         |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                                           | 0         | T:14000         |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                                               |           |                 |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |                                                                                                                       |           |               |          |                           |           |           |                |
| 57-52-01-01-902                                              | DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL                                 |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                       |           |               |          |                           |           |           |                |
| 57-52-02-01-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL                                    |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                       |           |               |          |                           |           |           |                |
| 57-52-03-01-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL                             |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:11250       |          | 11250                     |           | 9954:36   |                |
|                                                              | AFL                                                                                                                   | 0         | T:9000        |          | 9000                      |           | 8402      |                |
| PROC. REF: NDT PART 6 57-52-00PROC. REF: NDT PART 6 57-52-00 |                                                                                                                       |           |               |          |                           |           |           |                |
| 57-52-04-01-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL    |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-52-00PROC. REF: NDT PART 5 57-52-00 |                                                                                                                       |           |               |          |                           |           |           |                |
| 57-52-04-02-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                                                   | 0         | T:17500       |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                                                   | 0         | T:14000       |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 6 57-52-00PROC. REF: NDT PART 6 57-52-00 |                                                                                                                       |           |               |          |                           |           |           |                |
| 57-53-00-001 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE OUTBOARD FLAP                                                   |           |               |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                                                   | 23-Apr-20 | 120 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                                                   | 0         |               |          |                           |           |           |                |
|                                                              | AFL                                                                                                                   | 0         |               |          |                           |           |           |                |

PKG:87

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit         | C/W                                                                                                        | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|--------------|------------------------------------------------------------------------------------------------------------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |              |                                                                                                            |              |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |              |                                                                                                            |              |          |                           |           |           |                |
| 57-53-00-002                                                 | <sup>S</sup> | EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP                                                   |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 31-Mar-25                                                                                                  | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS          | 987:24                                                                                                     |              |          |                           |           |           |                |
|                                                              | AFL          | 456                                                                                                        |              |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |              |                                                                                                            |              |          |                           |           |           | PKG:84         |
| 57-53-01-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                                  |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                          | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                          | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |              |                                                                                                            |              |          |                           |           |           |                |
| 57-53-01-01-902                                              |              | DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL                     |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                                  |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                          | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                          | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |              |                                                                                                            |              |          |                           |           |           |                |
| 57-53-02-01-901                                              |              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL                        |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                                  |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                          | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL          | 0                                                                                                          | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |              |                                                                                                            |              |          |                           |           |           |                |
| 57-53-03-01-901                                              |              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL                 |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS          | 23-Apr-20                                                                                                  |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS          | 0                                                                                                          | T:11250      |          | 11250                     |           | 9954:36   |                |
|                                                              | AFL          | 0                                                                                                          | T:9000       |          | 9000                      |           | 8402      |                |
| PROC. REF: NDT PART 6 57-53-00PROC. REF: NDT PART 6 57-53-00 |              |                                                                                                            |              |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                                                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                                               |                                                                                                                                                                  |           |          |          |                           |           |           |                  |
| 57-53-04-01-901                                              | DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL                         |           |          |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                                                              | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                                                                  |           |          |          |                           |           |           |                  |
| 57-53-04-02-901                                              | DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL                         |           |          |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                                                              | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                                                                  |           |          |          |                           |           |           |                  |
| 57-53-04-03-901                                              | SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL |           |          |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                                                              | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-53-00PROC. REF: NDT PART 5 57-53-00 |                                                                                                                                                                  |           |          |          |                           |           |           |                  |
| 57-53-04-04-901                                              | SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL |           |          |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                                                                              | 23-Apr-20 |          |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                                                                              | 0         | T:17500  |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                                                                              | 0         | T:14000  |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 6 57-53-00PROC. REF: NDT PART 6 57-53-00 |                                                                                                                                                                  |           |          |          |                           |           |           |                  |
| 57-56-00                                                     | LEFT HAND INBOARD FLAP ASSEMBLY                                                                                                                                  |           |          |          |                           |           |           | Component ATA:57 |
| PN:505-14334-405                                             | MOS/MSC                                                                                                                                                          | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0001067523                                                | HRS                                                                                                                                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                                                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                                                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                                    | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 57 - WINGS                                               |                                                                                                         |           |               |          |                           |           |           |                  |
| 57-56-00                                                     | RIGHT HAND INBOARD FLAP ASSEMBLY                                                                        |           |               |          |                           |           |           | Component ATA:57 |
| PN:505-14334-406                                             | MOS/MSC                                                                                                 | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:0001061930                                                | HRS                                                                                                     | 0         |               | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                                     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                         |           |               |          |                           |           |           |                  |
| 57-60-00                                                     | RIGHT HAND WING AUTO 0% AILERON                                                                         |           |               |          |                           |           |           | Component ATA:57 |
| PN:505-14718-409                                             | MOS/MSC                                                                                                 | 23-Apr-20 | O/C           | TSN 0    |                           |           |           |                  |
| SN:0001061364                                                | HRS                                                                                                     | 0         |               | TSN 0    |                           |           |           |                  |
|                                                              | AFL                                                                                                     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF           |                                                                                                         |           |               |          |                           |           |           |                  |
| 57-60-00-001                                                 | EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON                                                      |           |               |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                     | 31-Mar-25 | 60            |          | 31-Mar-30                 |           | 1341 d    | ALI              |
|                                                              | HRS                                                                                                     | 987:24    |               |          |                           |           |           |                  |
|                                                              | AFL                                                                                                     | 456       |               |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                                         |           |               |          |                           |           |           |                  |
| 57-60-00-002 <sup>S</sup>                                    | SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON AND TAB                                       |           |               |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                     | 31-Mar-25 | 120 (+1m/-1m) |          |                           |           |           |                  |
|                                                              | HRS                                                                                                     | 987:24    |               |          |                           |           |           |                  |
|                                                              | AFL                                                                                                     | 456       |               |          |                           |           |           |                  |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                                         |           |               |          |                           |           |           |                  |
| 57-60-01-01-901                                              | SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL |           |               |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                     | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                     | 0         | T:17500       |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                     | 0         | T:14000       |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                                         |           |               |          |                           |           |           |                  |
| 57-60-01-01-902                                              | DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL                     |           |               |          |                           |           |           | Service ATA:57   |
|                                                              | MOS                                                                                                     | 23-Apr-20 |               |          |                           |           |           | AIRWORTHINESS    |
|                                                              | HRS                                                                                                     | 0         | T:17500       |          | 17500                     |           | 16204:36  |                  |
|                                                              | AFL                                                                                                     | 0         | T:14000       |          | 14000                     |           | 13402     |                  |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                                         |           |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                      | Unit                                                                                | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 57 - WINGS                                               |                                                                                     |           |              |          |                           |           |           |                |
| 57-60-01-02-901                                              | DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL               |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                     |           |              |          |                           |           |           |                |
| 57-60-02-01-901                                              | DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL       |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                     |           |              |          |                           |           |           |                |
| 57-60-02-02-901                                              | DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL   |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                 | 23-Apr-20 |              |          |                           |           |           | AIRWORTHINESS  |
|                                                              | HRS                                                                                 | 0         | T:17500      |          | 17500                     |           | 16204:36  |                |
|                                                              | AFL                                                                                 | 0         | T:14000      |          | 14000                     |           | 13402     |                |
| PROC. REF: NDT PART 5 57-60-00PROC. REF: NDT PART 5 57-60-00 |                                                                                     |           |              |          |                           |           |           |                |
| 57-60-04-001 <sup>U</sup>                                    | INTERNAL DETAILED VISUAL INSPECTION OF AILERON MASS-BALANCE WEIGHTS AND ATTACHMENTS |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS/MSC                                                                             | 23-Apr-20 | O/C          |          |                           |           |           |                |
|                                                              | HRS                                                                                 | 0         |              |          |                           |           |           |                |
|                                                              | AFL                                                                                 | 0         |              |          |                           |           |           |                |
| 57-70-02-001 <sup>S</sup>                                    | EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS                       |           |              |          |                           |           |           | Service ATA:57 |
|                                                              | MOS                                                                                 | 31-Mar-25 | 60 (+1m/-1m) |          |                           |           |           |                |
|                                                              | HRS                                                                                 | 987:24    |              |          |                           |           |           |                |
|                                                              | AFL                                                                                 | 456       |              |          |                           |           |           |                |
| PROC. REF: NDT PART 5 57-70-00PROC. REF: NDT PART 5 57-70-00 |                                                                                     |           |              |          |                           |           |           | PKG:84         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|-----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 70 - STANDARD PRACTICES - ENGINES        |                                                                 |           |          |          |                           |           |           |                |
| 700010                                       | NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION                    |           |          |          |                           |           |           | Service ATA:70 |
|                                              | MOS/MSC                                                         | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                             | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                             | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00 |                                                                 |           |          |          |                           |           |           |                |
| 700010                                       | NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION                    |           |          |          |                           |           |           | Service ATA:70 |
|                                              | MOS/MSC                                                         | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                             | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                             | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00 |                                                                 |           |          |          |                           |           |           |                |
| ATA 71 - POWER PLANT                         |                                                                 |           |          |          |                           |           |           |                |
| 70-00-00-200-801                             | NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                         | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                             | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                             | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00 |                                                                 |           |          |          |                           |           |           |                |
| 70-00-00-200-801                             | NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                         | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                             | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                             | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 70-00-00PROC. REF: MM 70-00-00 |                                                                 |           |          |          |                           |           |           |                |
| 71-00-00-160-805                             | NO. 1 ENGINE - COMPRESSOR WASH                                  |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                         | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                             | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                             | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                 |           |          |          |                           |           |           |                |
| 71-00-00-160-805                             | NO. 2 ENGINE - COMPRESSOR WASH                                  |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                         | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                             | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                             | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                 |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|----------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 71 - POWER PLANT                         |                                                                                        |           |          |          |                           |           |           |                |
| 71-00-00-160-806                             | NO. 1 ENGINE - PERFORMANCE RECOVERY WASH                                               |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                                                    | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                                                    | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                           |           |           |                |
| 71-00-00-160-806                             | NO. 2 ENGINE - PERFORMANCE RECOVERY WASH                                               |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                                                    | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                                                    | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                           |           |           |                |
| 71-00-00-760-810                             | NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN                                   |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                                                    | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                                                    | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                           |           |           |                |
| 71-00-00-760-810                             | NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN                                   |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                                                    | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                                                    | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                           |           |           |                |
| 71-00-00-760-814                             | NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                                                    | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                                                    | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                           |           |           |                |
| 71-00-00-760-814                             | NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK |           |          |          |                           |           |           | Service ATA:71 |
|                                              | MOS/MSC                                                                                | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                                                    | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                                                    | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00 |                                                                                        |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                      |
|------------------------------------------------|-----------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|----------------------------------|
| ATA 71 - POWER PLANT                           |                                                     |           |                |          |                           |           |             |                                  |
| 71-00-00-760-817                               | NO. 1 ENGINE - DOWNLOAD ENGINE DCU DATA             |           |                |          |                           |           |             | Service ATA:71                   |
|                                                | MOS/MSC                                             | 06-Dec-19 | A/R            |          |                           |           |             | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                                 | 0         |                |          |                           |           |             |                                  |
|                                                | ENC                                                 | 0         |                |          |                           |           |             |                                  |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00   |                                                     |           |                |          |                           |           |             |                                  |
| 71-00-00-760-817                               | NO. 2 ENGINE - DOWNLOAD ENGINE DCU DATA             |           |                |          |                           |           |             | Service ATA:71                   |
|                                                | MOS/MSC                                             | 05-Dec-19 | A/R            |          |                           |           |             | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                | HRS                                                 | 0         |                |          |                           |           |             |                                  |
|                                                | ENC                                                 | 0         |                |          |                           |           |             |                                  |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00   |                                                     |           |                |          |                           |           |             |                                  |
| 71-00-00-760-823                               | NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH) |           |                |          |                           |           |             | Service ATA:71                   |
|                                                | MOS                                                 | 13-Mar-26 | 12 (+30d)      |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30) |                                  |
|                                                | HRS                                                 | 1221:24   | 630 (+10%)     |          | (1851:24)<br>1851:24      | 1914:24   | 556 (+63)   |                                  |
|                                                | ENC                                                 | 564       |                |          |                           |           |             |                                  |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00   |                                                     |           |                |          |                           |           |             |                                  |
| 71-00-00-760-823                               | NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH) |           |                |          |                           |           |             | Service ATA:71                   |
|                                                | MOS                                                 | 13-Mar-26 | 12 (+30d)      |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30) |                                  |
|                                                | HRS                                                 | 1221:24   | 630 (+10%)     |          | (1851:24)<br>1851:24      | 1914:24   | 556 (+63)   |                                  |
|                                                | ENC                                                 | 564       |                |          |                           |           |             |                                  |
| PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00   |                                                     |           |                |          |                           |           |             |                                  |
| 71-11-00-001 <sup>S</sup>                      | GENERAL VISUAL INSPECTION OF UPPER MID COWL         |           |                |          |                           |           |             | Service ATA:71                   |
|                                                | MOS                                                 | 23-Apr-20 |                |          |                           |           |             |                                  |
|                                                | HRS                                                 | 0         | 5600 (+30/-30) |          |                           |           |             |                                  |
|                                                | AFL                                                 | 0         |                |          |                           |           |             |                                  |
| PROC. REF: AMM 71-11-00PROC. REF: AMM 71-11-00 |                                                     |           |                |          |                           |           |             |                                  |
|                                                |                                                     |           |                |          |                           |           |             | PKG:50                           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 71 - POWER PLANT                                                       |                                              |           |          |          |                           |           |           |                  |
| 71-20-00                                                                   | LEFT AFT ENGINE MOUNT ISOLATOR               |           |          |          |                           |           |           | Component ATA:71 |
| PN:LM-475-SA4                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LK1525                                                                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-22-00, AMM 71-22-00PROC. REF: AMM 71-22-00, AMM 71-22-00 |                                              |           |          |          |                           |           |           |                  |
| 71-20-00                                                                   | LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR   |           |          |          |                           |           |           | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LK2957                                                                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |                                              |           |          |          |                           |           |           |                  |
| 71-20-00                                                                   | LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR  |           |          |          |                           |           |           | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LK2984                                                                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |                                              |           |          |          |                           |           |           |                  |
| 71-20-00                                                                   | RIGHT AFT ENGINE MOUNT ISOLATOR              |           |          |          |                           |           |           | Component ATA:71 |
| PN:LM-475-SA4                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LK1533                                                                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-22-00, AMM 71-22-00PROC. REF: AMM 71-22-00, AMM 71-22-00 |                                              |           |          |          |                           |           |           |                  |
| 71-20-00                                                                   | RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR  |           |          |          |                           |           |           | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LK2939                                                                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |                                              |           |          |          |                           |           |           |                  |
| 71-20-00                                                                   | RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR |           |          |          |                           |           |           | Component ATA:71 |
| PN:LM-475-SA3                                                              | MOS/MSC                                      | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LK2969                                                                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00 |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                        | Unit                                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|------------------------------------------------|--------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 71 - POWER PLANT                           |                                                                                |           |          |          |                           |           |           |                |
| 71-20-00-001                                   | RESTORATION (OVERHAUL) OF ENGINE LEFT AFT MOUNT ASSEMBLY AND ATTACHMENTS       |           |          |          |                           |           |           | Service ATA:71 |
| PN:LM-475-SA4                                  | MOS/MSC                                                                        | 23-Apr-20 | O/C      |          |                           |           |           |                |
| SN:LK1525                                      | HRS                                                                            | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                            | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                |           |          |          |                           |           |           |                |
| 71-20-00-001                                   | RESTORATION (OVERHAUL) OF ENGINE LEFT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS   |           |          |          |                           |           |           | Service ATA:71 |
| PN:LM-475-SA3                                  | MOS/MSC                                                                        | 23-Apr-20 | O/C      |          |                           |           |           |                |
| SN:LK2957                                      | HRS                                                                            | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                            | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                |           |          |          |                           |           |           |                |
| 71-20-00-001                                   | RESTORATION (OVERHAUL) OF ENGINE LEFT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS  |           |          |          |                           |           |           | Service ATA:71 |
| PN:LM-475-SA3                                  | MOS/MSC                                                                        | 23-Apr-20 | O/C      |          |                           |           |           |                |
| SN:LK2984                                      | HRS                                                                            | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                            | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                |           |          |          |                           |           |           |                |
| 71-20-00-001                                   | RESTORATION (OVERHAUL) OF ENGINE RIGHT AFT MOUNT ASSEMBLY AND ATTACHMENTS      |           |          |          |                           |           |           | Service ATA:71 |
| PN:LM-475-SA4                                  | MOS/MSC                                                                        | 23-Apr-20 | O/C      |          |                           |           |           |                |
| SN:LK1533                                      | HRS                                                                            | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                            | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                |           |          |          |                           |           |           |                |
| 71-20-00-001                                   | RESTORATION (OVERHAUL) OF ENGINE RIGHT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS  |           |          |          |                           |           |           | Service ATA:71 |
| PN:LM-475-SA3                                  | MOS/MSC                                                                        | 23-Apr-20 | O/C      |          |                           |           |           |                |
| SN:LK2939                                      | HRS                                                                            | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                            | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                |           |          |          |                           |           |           |                |
| 71-20-00-001                                   | RESTORATION (OVERHAUL) OF ENGINE RIGHT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS |           |          |          |                           |           |           | Service ATA:71 |
| PN:LM-475-SA3                                  | MOS/MSC                                                                        | 23-Apr-20 | O/C      |          |                           |           |           |                |
| SN:LK2969                                      | HRS                                                                            | 0         |          |          |                           |           |           |                |
|                                                | AFL                                                                            | 0         |          |          |                           |           |           |                |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00 |                                                                                |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                | Unit                                                                                                                                                                                                                  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 71 - POWER PLANT                                                                                   |                                                                                                                                                                                                                       |           |                |          |                           |           |           |                  |
| 71-21-01-01-901                                                                                        | RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY |           |                |          |                           |           |           | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 23-Apr-20 |                |          |                           |           |           | AIRWORTHINESS    |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | T:7500         |          | 7500                      |           | 6204:36   |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         | T:6000         |          | 6000                      |           | 5402      |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                         |                                                                                                                                                                                                                       |           |                |          |                           |           |           |                  |
| 71-22-01-01-901                                                                                        | DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL                                                                                                                                                            |           |                |          |                           |           |           | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 23-Apr-20 |                |          |                           |           |           | AIRWORTHINESS    |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | T:4500         |          | 4500                      |           | 3204:36   |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         | T:3600         |          | 3600                      |           | 3002      |                  |
| PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00 |                                                                                                                                                                                                                       |           |                |          |                           |           |           |                  |
| 71-22-01-01-902                                                                                        | RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY                                     |           |                |          |                           |           |           | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 23-Apr-20 |                |          |                           |           |           | AIRWORTHINESS    |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | T:7500         |          | 7500                      |           | 6204:36   |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         | T:6000         |          | 6000                      |           | 5402      |                  |
| PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00                                                         |                                                                                                                                                                                                                       |           |                |          |                           |           |           |                  |
| 71-31-00-001 <sup>S</sup>                                                                              | DETAILED INSPECTION OF PYLON FIREWALL SEAL                                                                                                                                                                            |           |                |          |                           |           |           | Service ATA:71   |
|                                                                                                        | MOS                                                                                                                                                                                                                   | 23-Apr-20 |                |          |                           |           |           |                  |
|                                                                                                        | HRS                                                                                                                                                                                                                   | 0         | 2400 (+30/-30) |          |                           |           |           |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         |                |          |                           |           |           |                  |
| PROC. REF: AMM 71-31-00PKG:20                                                                          |                                                                                                                                                                                                                       |           |                |          |                           |           |           |                  |
| 71-60-01                                                                                               | LEFT ENGINE AIR INLET                                                                                                                                                                                                 |           |                |          |                           |           |           | Component ATA:71 |
| PN:505-43420-405                                                                                       | MOS/MSC                                                                                                                                                                                                               | 23-Apr-20 | O/C            | TSN 0    |                           |           |           |                  |
| SN:CPI563                                                                                              | HRS                                                                                                                                                                                                                   | 0         |                | TSN 0    |                           |           |           |                  |
|                                                                                                        | AFL                                                                                                                                                                                                                   | 0         |                | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01                             |                                                                                                                                                                                                                       |           |                |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|----------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 71 - POWER PLANT                                                       |                                                                      |           |          |          |                           |           |           |                  |
| 71-60-01                                                                   | RIGHT ENGINE AIR INLET                                               |           |          |          |                           |           |           | Component ATA:71 |
| PN:505-43430-405                                                           | MOS/MSC                                                              | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:CPI562                                                                  | HRS                                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL                                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01 |                                                                      |           |          |          |                           |           |           |                  |
| 71EN1                                                                      | NO. 1 ENGINE                                                         |           |          |          |                           |           |           | Component ATA:71 |
| PN:3072913-01                                                              | MOS/MSC                                                              |           | E/C      |          |                           |           |           |                  |
| SN:PCE-DG1117                                                              | HRS                                                                  |           |          |          |                           |           |           |                  |
| WC#: 71.EN1                                                                | AFL                                                                  |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00 |                                                                      |           |          |          |                           |           |           |                  |
| 71EN2                                                                      | NO. 2 ENGINE                                                         |           |          |          |                           |           |           | Component ATA:71 |
| PN:3072913-01                                                              | MOS/MSC                                                              |           | E/C      |          |                           |           |           |                  |
| SN:PCE-DG1116                                                              | HRS                                                                  |           |          |          |                           |           |           |                  |
| WC#: 71.EN2                                                                | AFL                                                                  |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00 |                                                                      |           |          |          |                           |           |           |                  |
| 72-00-02-810-801                                                           | NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION |           |          |          |                           |           |           | Service ATA:71   |
|                                                                            | MOS                                                                  | 13-Mar-26 | 12       |          | 13-Mar-27                 |           | 227 d     |                  |
|                                                                            | HRS                                                                  | 1221:24   | 630      |          | (1851:24)<br>1851:24      |           | 556       |                  |
|                                                                            | ENC                                                                  | 564       |          |          |                           |           |           |                  |
| PROC. REF: MM 72-00-02PROC. REF: MM 72-00-02                               |                                                                      |           |          |          |                           |           |           |                  |
| 72-00-02-810-801                                                           | NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION |           |          |          |                           |           |           | Service ATA:71   |
|                                                                            | MOS                                                                  | 13-Mar-26 | 12       |          | 13-Mar-27                 |           | 227 d     |                  |
|                                                                            | HRS                                                                  | 1221:24   | 630      |          | (1851:24)<br>1851:24      |           | 556       |                  |
|                                                                            | ENC                                                                  | 564       |          |          |                           |           |           |                  |
| PROC. REF: MM 72-00-02PROC. REF: MM 72-00-02                               |                                                                      |           |          |          |                           |           |           |                  |
| ATA 72 - ENGINE                                                            |                                                                      |           |          |          |                           |           |           |                  |
| 72-00-00-000-802                                                           | NO. 1 ENGINE - LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL   |           |          |          |                           |           |           | Service ATA:72   |
| PN:3073356-01                                                              | MOS/MSC                                                              | 06-Dec-19 | A/R      |          |                           |           |           |                  |
| SN:PKAAA838946                                                             | HRS                                                                  | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                      | C/W       | Interval                                            | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------------|---------------------------------------------------------------------------|-----------|-----------------------------------------------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 72 - ENGINE                                    |                                                                           |           |                                                     |          |                           |           |           |                |
|                                                    | ENC                                                                       | 0         |                                                     |          |                           |           |           |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                           |           |                                                     |          |                           |           |           |                |
| 72-00-00-000-802                                   | NO. 2 ENGINE -                                                            |           | LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL |          |                           |           |           | Service ATA:72 |
| PN:3073356-01                                      | MOS/MSC                                                                   | 05-Dec-19 | A/R                                                 |          |                           |           |           |                |
| SN:PKAAA838944                                     | HRS                                                                       | 0         |                                                     |          |                           |           |           |                |
|                                                    | ENC                                                                       | 0         |                                                     |          |                           |           |           |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                           |           |                                                     |          |                           |           |           |                |
| 72-00-00-212-801 <sup>S</sup>                      | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA         |           |                                                     |          |                           |           | Service   | ATA:72         |
|                                                    | MOS                                                                       | 13-Mar-26 | 12 (+30d)                                           |          |                           |           |           |                |
|                                                    | HRS                                                                       | 1221:24   | 800 (+10%)                                          |          |                           |           |           |                |
|                                                    | ENC                                                                       | 564       |                                                     |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                           |           |           | PKG:1          |
| 72-00-00-212-801 <sup>S</sup>                      | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA         |           |                                                     |          |                           |           | Service   | ATA:72         |
|                                                    | MOS                                                                       | 13-Mar-26 | 12 (+30d)                                           |          |                           |           |           |                |
|                                                    | HRS                                                                       | 1221:24   | 800 (+10%)                                          |          |                           |           |           |                |
|                                                    | ENC                                                                       | 564       |                                                     |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                           |           |           | PKG:1          |
| 72-00-00-212-802 <sup>S</sup>                      | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB |           |                                                     |          |                           |           | Service   | ATA:72         |
|                                                    | MOS                                                                       | 13-Mar-26 | 12 (+30d)                                           |          |                           |           |           |                |
|                                                    | HRS                                                                       | 1221:24   | 800 (+10%)                                          |          |                           |           |           |                |
|                                                    | ENC                                                                       | 564       |                                                     |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                           |           |           | PKG:1          |
| 72-00-00-212-802 <sup>S</sup>                      | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB |           |                                                     |          |                           |           | Service   | ATA:72         |
|                                                    | MOS                                                                       | 13-Mar-26 | 12 (+30d)                                           |          |                           |           |           |                |
|                                                    | HRS                                                                       | 1221:24   | 800 (+10%)                                          |          |                           |           |           |                |
|                                                    | ENC                                                                       | 564       |                                                     |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                           |           |                                                     |          |                           |           |           | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit         | C/W                                                                      | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|--------------|--------------------------------------------------------------------------|------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 72 - ENGINE                              |              |                                                                          |            |          |                           |           |           |                |
| 72-00-00-212-803                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT              |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                  | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                      |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-803                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT              |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                  | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                      |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-804                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE     |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                  | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                      |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-804                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE     |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                  | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                      |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-805                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                  | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                      |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                          |            |          |                           |           |           | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit         | C/W                                                                            | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|--------------|--------------------------------------------------------------------------------|------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 72 - ENGINE                              |              |                                                                                |            |          |                           |           |           |                |
| 72-00-00-212-805                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM       |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                      | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                        | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                            |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-806                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM        |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                      | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                        | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                            |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-806                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM        |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                      | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                        | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                            |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-807                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                      | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                        | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                            |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-807                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                      | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                        | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                            |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                |            |          |                           |           |           | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit         | C/W                                                                               | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|--------------|-----------------------------------------------------------------------------------|------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 72 - ENGINE                              |              |                                                                                   |            |          |                           |           |           |                |
| 72-00-00-212-808                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM  |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                         | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                           | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                               |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-808                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM  |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                         | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                           | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                               |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-809                             | <sup>S</sup> | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                         | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                           | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                               |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                           |           |           | PKG:1          |
| 72-00-00-212-809                             | <sup>S</sup> | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS          | 13-Mar-26                                                                         | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                                           | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                               |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                           |           |           | PKG:1          |
| 72-00-00-280-802                             |              | NO. 1 ENGINE - BORESCOPE INSPECT HP COMPRESSOR AND DIFFUSER EXIT DUCTS            |            |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC      | 06-Dec-19                                                                         | A/R        |          |                           |           |           |                |
|                                              | HRS          | 0                                                                                 |            |          |                           |           |           |                |
|                                              | ENC          | 0                                                                                 |            |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |              |                                                                                   |            |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                                     | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|----------------------------------------------|--------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 72 - ENGINE                              |                                                                          |           |             |          |                           |           |              |                |
| 72-00-00-280-802                             | NO. 2 ENGINE - BORESCOPE INSPECT HP COMPRESSOR AND DIFFUSER EXIT DUCTS   |           |             |          |                           |           |              | Service ATA:72 |
|                                              | MOS/MSC                                                                  | 05-Dec-19 | A/R         |          |                           |           |              |                |
|                                              | HRS                                                                      | 0         |             |          |                           |           |              |                |
|                                              | ENC                                                                      | 0         |             |          |                           |           |              |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                          |           |             |          |                           |           |              |                |
| 72-00-00-280-818                             | NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) |           |             |          |                           |           |              | Service ATA:72 |
|                                              | MOS                                                                      | 06-Dec-19 | T:120 (+1m) |          | 06-Dec-29                 | 06-Jan-30 | 1226 d (+31) |                |
|                                              | HRS                                                                      | 0         |             |          |                           |           |              |                |
|                                              | ENC                                                                      | 0         |             |          |                           |           |              |                |
| PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00 |                                                                          |           |             |          |                           |           |              |                |
| 72-00-00-280-818                             | NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) |           |             |          |                           |           |              | Service ATA:72 |
|                                              | MOS                                                                      | 05-Dec-19 | T:120 (+1m) |          | 05-Dec-29                 | 05-Jan-30 | 1225 d (+31) |                |
|                                              | HRS                                                                      | 0         |             |          |                           |           |              |                |
|                                              | ENC                                                                      | 0         |             |          |                           |           |              |                |
| PROC. REF: MM 05-20-00PROC. REF: MM 05-20-00 |                                                                          |           |             |          |                           |           |              |                |
| 72-00-00-280-820 <sup>S</sup>                | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES         |           |             |          |                           |           |              | Service ATA:72 |
|                                              | MOS                                                                      | 13-Mar-26 | 12 (+30d)   |          |                           |           |              |                |
|                                              | HRS                                                                      | 1221:24   | 800 (+10%)  |          |                           |           |              |                |
|                                              | ENC                                                                      | 564       |             |          |                           |           |              |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                          |           |             |          |                           |           |              | PKG:1          |
| 72-00-00-280-820 <sup>S</sup>                | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES         |           |             |          |                           |           |              | Service ATA:72 |
|                                              | MOS                                                                      | 13-Mar-26 | 12 (+30d)   |          |                           |           |              |                |
|                                              | HRS                                                                      | 1221:24   | 800 (+10%)  |          |                           |           |              |                |
|                                              | ENC                                                                      | 564       |             |          |                           |           |              |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                          |           |             |          |                           |           |              | PKG:1          |
| 72-00-00-640-802                             | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL         |           |             |          |                           |           |              | Service ATA:72 |
|                                              | MOS/MSC                                                                  | 04-Mar-24 | BF/F        |          |                           |           |              |                |
|                                              | HRS                                                                      |           |             |          |                           |           |              |                |
|                                              | ENC                                                                      |           |             |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|----------------------------------------------|-----------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------------------------|
| ATA 72 - ENGINE                              |                                                                                         |           |          |          |                           |           |           |                                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                           |           |           |                                  |
| 72-00-00-640-802                             | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL                        |           |          |          |                           |           |           | Service ATA:72                   |
|                                              | MOS/MSC                                                                                 | 04-Mar-24 | BF/F     |          |                           |           |           |                                  |
|                                              | HRS                                                                                     |           |          |          |                           |           |           |                                  |
|                                              | ENC                                                                                     |           |          |          |                           |           |           |                                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                           |           |           |                                  |
| 72-00-00-640-806                             | NO. 1 ENGINE - OIL ANALYSIS                                                             |           |          |          |                           |           |           | Service ATA:72                   |
|                                              | MOS/MSC                                                                                 | 19-Mar-24 | A/R      |          |                           |           |           |                                  |
|                                              | HRS                                                                                     | 781:30    |          |          |                           |           |           |                                  |
|                                              | ENC                                                                                     | 364       |          |          |                           |           |           |                                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                           |           |           |                                  |
| 72-00-00-640-806                             | NO. 2 ENGINE - OIL ANALYSIS                                                             |           |          |          |                           |           |           | Service ATA:72                   |
|                                              | MOS/MSC                                                                                 | 19-Mar-24 | A/R      |          |                           |           |           |                                  |
|                                              | HRS                                                                                     | 781:30    |          |          |                           |           |           |                                  |
|                                              | ENC                                                                                     | 364       |          |          |                           |           |           |                                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                                                         |           |          |          |                           |           |           |                                  |
| 72-00-01-810-822                             | NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115) |           |          |          |                           |           |           | Service ATA:72                   |
|                                              | MOS/MSC                                                                                 | 06-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                              | HRS                                                                                     | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                                                                     | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 72-00-01PROC. REF: MM 72-00-01 |                                                                                         |           |          |          |                           |           |           |                                  |
| 72-00-01-810-822                             | NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115) |           |          |          |                           |           |           | Service ATA:72                   |
|                                              | MOS/MSC                                                                                 | 05-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                              | HRS                                                                                     | 0         |          |          |                           |           |           |                                  |
|                                              | ENC                                                                                     | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 72-00-01PROC. REF: MM 72-00-01 |                                                                                         |           |          |          |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|------------------------------------------------------------------------|-----------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 72 - ENGINE                                                        |                                                     |           |             |          |                           |           |                |                  |
| 72-00-34-030-802                                                       | NO. 1 ENGINE - DISCARD GAS GENERATOR CASE           |           |             |          |                           |           |                | Service ATA:72   |
| PN:3136412                                                             | MOS                                                 | 06-Dec-19 |             |          |                           |           |                |                  |
| SN:RWA84F423                                                           | HRS                                                 | 0         |             |          |                           |           |                |                  |
|                                                                        | ENC                                                 | 0         | 10000       |          | (10000)<br>10000          |           | 9402           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |             |          |                           |           |                |                  |
| 72-00-34-030-802                                                       | NO. 2 ENGINE - DISCARD GAS GENERATOR CASE           |           |             |          |                           |           |                | Service ATA:72   |
| PN:3136412                                                             | MOS                                                 | 05-Dec-19 |             |          |                           |           |                |                  |
| SN:RWA84F217                                                           | HRS                                                 | 0         |             |          |                           |           |                |                  |
|                                                                        | ENC                                                 | 0         | 10000       |          | (10000)<br>10000          |           | 9402           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |             |          |                           |           |                |                  |
| 72-00-51-030-002                                                       | NO. 1 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER |           |             |          |                           |           |                | Service ATA:72   |
|                                                                        | MOS                                                 | 06-Dec-19 |             |          |                           |           |                | LIFE LIMIT       |
|                                                                        | HRS                                                 | 0         | 5000 (+100) |          | (5000)<br>5000 (M)        | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                 | 0         |             |          |                           |           |                |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                                     |           |             |          |                           |           |                |                  |
| 72-00-51-030-002                                                       | NO. 2 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER |           |             |          |                           |           |                | Service ATA:72   |
|                                                                        | MOS                                                 | 05-Dec-19 |             |          |                           |           |                | LIFE LIMIT       |
|                                                                        | HRS                                                 | 0         | 5000 (+100) |          | (5000)<br>5000 (M)        | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                 | 0         |             |          |                           |           |                |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                                     |           |             |          |                           |           |                |                  |
| 72-34-01-040-801                                                       | NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR        |           |             |          |                           |           |                | Component ATA:72 |
| PN:3056210-01                                                          | MOS                                                 | 06-Dec-19 |             | TSN 0    |                           |           |                | LIFE LIMIT       |
| SN:EAAE000W527                                                         | HRS                                                 | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                        | ENC                                                 | 0         |             | TSN 0    | (13500)<br>13500 (M)      |           | 12902          |                  |
|                                                                        | ACCCYC                                              | 0         | 13500       | TSN 0    |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                     |           |             |          |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------|------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 72 - ENGINE                                    |                                                                        |           |             |          |                           |           |             |                  |
| 72-34-01-040-801                                   | NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR                           |           |             |          |                           |           |             | Component ATA:72 |
| PN:3056210-01                                      | MOS                                                                    | 05-Dec-19 |             | TSN 0    |                           |           |             | LIFE LIMIT       |
| SN:EAAE000W864                                     | HRS                                                                    | 0         |             | TSN 0    |                           |           |             |                  |
|                                                    | ENC                                                                    | 0         |             | TSN 0    | (13500)<br>13500 (M)      |           | 12902       |                  |
|                                                    | ACCCYC                                                                 | 0         | 13500       | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                        |           |             |          |                           |           |             |                  |
| 72-60-01-212-801                                   | NO. 1 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES        |           |             |          |                           |           |             | Service ATA:72   |
|                                                    | MOS                                                                    | 12-Dec-25 |             |          |                           |           |             |                  |
|                                                    | HRS                                                                    | 1179:24   | 1200 (+100) |          | (2379:24)<br>2379:24      | 2479:24   | 1084 (+100) |                  |
|                                                    | ENC                                                                    | 546       |             |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                        |           |             |          |                           |           |             |                  |
| 72-60-01-212-801                                   | NO. 2 ENGINE - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES        |           |             |          |                           |           |             | Service ATA:72   |
|                                                    | MOS                                                                    | 12-Dec-25 |             |          |                           |           |             |                  |
|                                                    | HRS                                                                    | 1179:24   | 1200 (+100) |          | (2379:24)<br>2379:24      | 2479:24   | 1084 (+100) |                  |
|                                                    | ENC                                                                    | 546       |             |          |                           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                        |           |             |          |                           |           |             |                  |
| 72-60-02-212-801 <sup>U</sup>                      | NO. 1 ENGINE - DO AN INSPECTION OF ENGINE HYDRAULIC PUMP SHAFT SPLINES |           |             |          |                           |           |             | Service ATA:72   |
|                                                    | MOS/MSC                                                                | 23-Apr-20 | N/A         |          |                           |           |             |                  |
|                                                    | HRS                                                                    | 0         |             |          |                           |           |             |                  |
|                                                    | ENC                                                                    | 0         |             |          |                           |           |             |                  |
| 72-60-02-212-801 <sup>U</sup>                      | NO. 2 ENGINE - DO AN INSPECTION OF ENGINE HYDRAULIC PUMP SHAFT SPLINES |           |             |          |                           |           |             | Service ATA:72   |
|                                                    | MOS/MSC                                                                | 23-Apr-20 | N/A         |          |                           |           |             |                  |
|                                                    | HRS                                                                    | 0         |             |          |                           |           |             |                  |
|                                                    | ENC                                                                    | 0         |             |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 72 - ENGINE                              |                                                    |           |          |          |                           |           |           |                |
| 720001                                       | NO. 1 ENGINE - ENGINE PRESERVATION - 0 TO 7 DAYS   |           |          |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC                                            | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                    |           |          |          |                           |           |           |                |
| 720001                                       | NO. 2 ENGINE - ENGINE PRESERVATION - 0 TO 7 DAYS   |           |          |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC                                            | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                    |           |          |          |                           |           |           |                |
| 720002                                       | NO. 1 ENGINE - ENGINE PRESERVATION - 8 TO 28 DAYS  |           |          |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC                                            | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                    |           |          |          |                           |           |           |                |
| 720002                                       | NO. 2 ENGINE - ENGINE PRESERVATION - 8 TO 28 DAYS  |           |          |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC                                            | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                    |           |          |          |                           |           |           |                |
| 720003                                       | NO. 1 ENGINE - ENGINE PRESERVATION - 29 TO 90 DAYS |           |          |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC                                            | 06-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                    |           |          |          |                           |           |           |                |
| 720003                                       | NO. 2 ENGINE - ENGINE PRESERVATION - 29 TO 90 DAYS |           |          |          |                           |           |           | Service ATA:72 |
|                                              | MOS/MSC                                            | 05-Dec-19 | A/R      |          |                           |           |           |                |
|                                              | HRS                                                | 0         |          |          |                           |           |           |                |
|                                              | ENC                                                | 0         |          |          |                           |           |           |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00 |                                                    |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                  | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|----------------------------------------------------|-------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 72 - ENGINE                                    |                                                       |           |             |          |                           |           |                |                |
| 720004                                             | NO. 1 ENGINE - ENGINE PRESERVATION - 90 DAYS AND OVER |           |             |          |                           |           |                | Service ATA:72 |
|                                                    | MOS/MSC                                               | 06-Dec-19 | A/R         |          |                           |           |                |                |
|                                                    | HRS                                                   | 0         |             |          |                           |           |                |                |
|                                                    | ENC                                                   | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                       |           |             |          |                           |           |                |                |
| 720004                                             | NO. 2 ENGINE - ENGINE PRESERVATION - 90 DAYS AND OVER |           |             |          |                           |           |                | Service ATA:72 |
|                                                    | MOS/MSC                                               | 05-Dec-19 | A/R         |          |                           |           |                |                |
|                                                    | HRS                                                   | 0         |             |          |                           |           |                |                |
|                                                    | ENC                                                   | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                       |           |             |          |                           |           |                |                |
| 720005                                             | NO. 1 ENGINE - ENGINE DEPRESERVATION                  |           |             |          |                           |           |                | Service ATA:72 |
|                                                    | MOS/MSC                                               | 06-Dec-19 | A/R         |          |                           |           |                |                |
|                                                    | HRS                                                   | 0         |             |          |                           |           |                |                |
|                                                    | ENC                                                   | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                       |           |             |          |                           |           |                |                |
| 720005                                             | NO. 2 ENGINE - ENGINE DEPRESERVATION                  |           |             |          |                           |           |                | Service ATA:72 |
|                                                    | MOS/MSC                                               | 05-Dec-19 | A/R         |          |                           |           |                |                |
|                                                    | HRS                                                   | 0         |             |          |                           |           |                |                |
|                                                    | ENC                                                   | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                       |           |             |          |                           |           |                |                |
| 720010                                             | NO. 1 ENGINE - OVERHAUL                               |           |             |          |                           |           |                | Service ATA:72 |
|                                                    | MOS                                                   | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                   | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                   | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                       |           |             |          |                           |           |                |                |
| 720010                                             | NO. 2 ENGINE - OVERHAUL                               |           |             |          |                           |           |                | Service ATA:72 |
|                                                    | MOS                                                   | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                   | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                   | 0         |             |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                  | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|------------------------------------------------------------------------|---------------------------------------|-----------|------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 72 - ENGINE                                                        |                                       |           |            |          |                           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                       |           |            |          |                           |           |               |                  |
| 720060                                                                 | NO. 1 ENGINE - HOT SECTION INSPECTION |           |            |          |                           |           |               | Service ATA:72   |
|                                                                        | MOS                                   | 23-Apr-20 |            |          |                           |           |               |                  |
|                                                                        | HRS                                   | 0         | 2500 (+50) |          | (2500)<br>2500            | 2550      | 1204:36 (+50) |                  |
|                                                                        | ENC                                   | 0         |            |          |                           |           |               |                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00                           |                                       |           |            |          |                           |           |               |                  |
| 720060                                                                 | NO. 2 ENGINE - HOT SECTION INSPECTION |           |            |          |                           |           |               | Service ATA:72   |
|                                                                        | MOS                                   | 23-Apr-20 |            |          |                           |           |               |                  |
|                                                                        | HRS                                   | 0         | 2500 (+50) |          | (2500)<br>2500            | 2550      | 1204:36 (+50) |                  |
|                                                                        | ENC                                   | 0         |            |          |                           |           |               |                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00                           |                                       |           |            |          |                           |           |               |                  |
| 722001                                                                 | NO. 1 ENGINE - OIL PUMP               |           |            |          |                           |           |               | Component ATA:72 |
| PN:3073477-02                                                          | MOS/MSC                               | 06-Dec-19 | O/C        | TSN 0    |                           |           |               |                  |
| SN:EC01A006A593                                                        | HRS                                   | 0         |            | TSN 0    |                           |           |               |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    |                           |           |               |                  |
| PROC. REF: MM 79-20-02, MM 79-20-02PROC. REF: MM 79-20-02, MM 79-20-02 |                                       |           |            |          |                           |           |               |                  |
| 722001                                                                 | NO. 2 ENGINE - OIL PUMP               |           |            |          |                           |           |               | Component ATA:72 |
| PN:3073477-02                                                          | MOS/MSC                               | 05-Dec-19 | O/C        | TSN 0    |                           |           |               |                  |
| SN:EC01A006A592                                                        | HRS                                   | 0         |            | TSN 0    |                           |           |               |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    |                           |           |               |                  |
| PROC. REF: MM 79-20-02, MM 79-20-02PROC. REF: MM 79-20-02, MM 79-20-02 |                                       |           |            |          |                           |           |               |                  |
| 723004                                                                 | NO. 1 ENGINE - LP SHAFT ASSEMBLY      |           |            |          |                           |           |               | Component ATA:72 |
| PN:3073356-01                                                          | MOS                                   | 06-Dec-19 |            | TSN 0    |                           |           |               | LIFE LIMIT       |
| SN:PKAAA838946                                                         | HRS                                   | 0         |            | TSN 0    |                           |           |               |                  |
|                                                                        | ENC                                   | 0         |            | TSN 0    | (30000)<br>30000 (M)      |           | 29402         |                  |
|                                                                        | ACCCYC                                | 0         | 30000      | TSN 0    |                           |           |               |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                       |           |            |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                                        |                                          |           |          |          |                           |           |           |                  |
| 723004                                                                 | NO. 2 ENGINE - LP SHAFT ASSEMBLY         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073356-01                                                          | MOS                                      | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:PKAAA838944                                                         | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                      | 0         |          | TSN 0    | (30000)<br>30000 (M)      |           | 29402     |                  |
|                                                                        | ACCCYC                                   | 0         | 30000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                          |           |          |          |                           |           |           |                  |
| 723010                                                                 | NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR   |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073311-01                                                          | MOS                                      | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004L72X                                                            | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                      | 0         |          | TSN 0    | (15000)<br>15000 (M)      |           | 14402     |                  |
|                                                                        | ACCCYC                                   | 0         | 15000    | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-30-01, MM 72-30-01PROC. REF: MM 72-30-01, MM 72-30-01 |                                          |           |          |          |                           |           |           |                  |
| 723010                                                                 | NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR   |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073311-01                                                          | MOS                                      | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004LARW                                                            | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                      | 0         |          | TSN 0    | (15000)<br>15000 (M)      |           | 14402     |                  |
|                                                                        | ACCCYC                                   | 0         | 15000    | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-30-01, MM 72-30-01PROC. REF: MM 72-30-01, MM 72-30-01 |                                          |           |          |          |                           |           |           |                  |
| 723020                                                                 | NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073292-01                                                          | MOS                                      | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:TXA1D7550                                                           | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                      | 0         |          | TSN 0    | (15000)<br>15000 (M)      |           | 14402     |                  |
|                                                                        | ACCCYC                                   | 0         | 15000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                                        |                                              |           |          |          |                           |           |           |                  |
| 723020                                                                 | NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR     |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073292-01                                                          | MOS                                          | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:TXA1D7549                                                           | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (15000)<br>15000 (M)      |           | 14402     |                  |
|                                                                        | ACCCYC                                       | 0         | 15000    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 723030                                                                 | NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072981-01                                                          | MOS                                          | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004KTNP                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                       | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 723030                                                                 | NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072981-01                                                          | MOS                                          | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004HRAE                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                       | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 723050                                                                 | NO. 1 ENGINE - FAN CASE ASSEMBLY             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3075221-01                                                          | MOS/MSC                                      | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:EDA1823H                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-30-02, MM 72-30-02PROC. REF: MM 72-30-02, MM 72-30-02 |                                              |           |          |          |                           |           |           |                  |
| 723050                                                                 | NO. 2 ENGINE - FAN CASE ASSEMBLY             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3075221-01                                                          | MOS/MSC                                      | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:EDA1822W                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-30-02, MM 72-30-02PROC. REF: MM 72-30-02, MM 72-30-02 |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|---------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                                        |                                                                                 |           |          |          |                           |           |           |                  |
| 723051                                                                 | NO. 1 ENGINE - FAN CASE                                                         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074676-01                                                          | MOS/MSC                                                                         | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:EDA1823H                                                            | HRS                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-30-02, MM 72-30-02PROC. REF: MM 72-30-02, MM 72-30-02 |                                                                                 |           |          |          |                           |           |           |                  |
| 723051                                                                 | NO. 2 ENGINE - FAN CASE                                                         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074676-01                                                          | MOS/MSC                                                                         | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:EDA1822W                                                            | HRS                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-30-02, MM 72-30-02PROC. REF: MM 72-30-02, MM 72-30-02 |                                                                                 |           |          |          |                           |           |           |                  |
| 723060                                                                 | NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3079044-01                                                          | MOS/MSC                                                                         | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN519533                                                           | HRS                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                           |           |           |                  |
| 723060                                                                 | NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3079044-01                                                          | MOS/MSC                                                                         | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN519531                                                           | HRS                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                           |           |           |                  |
| 723070                                                                 | NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY                                       |           |          |          |                           |           |           | Component ATA:72 |
| PN:3079507-01                                                          | MOS/MSC                                                                         | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HBA0489                                                             | HRS                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                           |           |           |                  |
| 723070                                                                 | NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY                                       |           |          |          |                           |           |           | Component ATA:72 |
| PN:3079617-01                                                          | MOS/MSC                                                                         | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004LXBT                                                            | HRS                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                             | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                      |           |          |          |                           |           |           |                  |
| 723080                                             | NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3136412                                         | MOS/MSC                                              | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:RWA84F423                                       | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                           |           |           |                  |
| 723080                                             | NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3136412                                         | MOS/MSC                                              | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:RWA84F217                                       | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                           |           |           |                  |
| 723090                                             | NO. 1 ENGINE - GAS GENERATOR DIFFUSER                |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073236-01                                      | MOS/MSC                                              | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004L5BE                                        | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                           |           |           |                  |
| 723090                                             | NO. 2 ENGINE - GAS GENERATOR DIFFUSER                |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073236-01                                      | MOS/MSC                                              | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004LDRK                                        | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                           |           |           |                  |
| 723095                                             | NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052673-01                                      | MOS/MSC                                              | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA851978                                     | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                           |           |           |                  |
| 723095                                             | NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052673-01                                      | MOS/MSC                                              | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA851981                                     | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                |           |          |          |                           |           |           |                  |
| 723110                                             | NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER       |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052668-01                                      | MOS/MSC                                        | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AFD01E503                                       | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 723110                                             | NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER       |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052668-01                                      | MOS/MSC                                        | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AFD01E724                                       | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 723120                                             | NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072571-01                                      | MOS/MSC                                        | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:MDA18005814                                     | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 723120                                             | NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072571-01                                      | MOS/MSC                                        | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:MDA18005801                                     | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 723130                                             | NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072572-01                                      | MOS/MSC                                        | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:MDA18004886                                     | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |
| 723130                                             | NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072572-01                                      | MOS/MSC                                        | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:MDA18004900                                     | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                            | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-----------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                                         |           |          |          |                           |           |           |                  |
| 723140                                             | NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING                                                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052737-01                                      | MOS/MSC                                                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LPA000026412                                    | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 723140                                             | NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING                                                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052737-01                                      | MOS/MSC                                                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:LPA000026374                                    | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 723150                                             | NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR                                           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072574-01                                      | MOS/MSC                                                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:EAAE000T806                                     | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 723150                                             | NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR                                           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072574-01                                      | MOS/MSC                                                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:EAAE000T704                                     | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 723160                                             | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052670-02                                      | MOS/MSC                                                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN521105                                       | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |
| 723160                                             | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052670-02                                      | MOS/MSC                                                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN522694                                       | HRS                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                         |           |          |          |                           |           |           |                  |
| 723161                                             | NO. 1 ENGINE - LOW PRESSURE SHAFT ASSEMBLY - ANNULAR BALL BEARING       |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052634-01                                      | MOS/MSC                                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN515418                                       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 723161                                             | NO. 2 ENGINE - LOW PRESSURE SHAFT ASSEMBLY - ANNULAR BALL BEARING       |           |          |          |                           |           |           | Component ATA:72 |
| PN:3071046-01                                      | MOS/MSC                                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FAA1801302                                      | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 723170                                             | NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072280-01                                      | MOS/MSC                                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA846383                                     | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 723170                                             | NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072280-01                                      | MOS/MSC                                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA846370                                     | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 723180                                             | NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052616-01                                      | MOS/MSC                                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN518765                                       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 723180                                             | NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052616-01                                      | MOS/MSC                                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN518759                                       | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                                        |                                                    |           |          |          |                           |           |           |                  |
| 723705                                                                 | NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053812-01                                                          | MOS                                                | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004KX4T                                                            | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                           |           |           |                  |
| 723705                                                                 | NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053812-01                                                          | MOS                                                | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004KKN5                                                            | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                           |           |           |                  |
| 723706                                                                 | NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053743-01                                                          | MOS                                                | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004KWBB                                                            | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                           |           |           |                  |
| 723706                                                                 | NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053743-01                                                          | MOS                                                | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004EYTA                                                            | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                             | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                    |           |          |          |                           |           |           |                  |
| 724001                                                                 | NO. 1 ENGINE - INNER COMBUSTION LINER              |           |          |          |                           |           |           | Component ATA:72 |
| PN:3123695-01                                                          | MOS/MSC                                            | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004LTL5                                                            | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                                        |                                              |           |          |          |                           |           |           |                  |
| 724001                                                                 | NO. 2 ENGINE - INNER COMBUSTION LINER        |           |          |          |                           |           |           | Component ATA:72 |
| PN:3123695-01                                                          | MOS/MSC                                      | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004LTA1                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                              |           |          |          |                           |           |           |                  |
| 724002                                                                 | NO. 1 ENGINE - OUTER COMBUSTION LINER        |           |          |          |                           |           |           | Component ATA:72 |
| PN:3079976-01                                                          | MOS/MSC                                      | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004L84K                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                              |           |          |          |                           |           |           |                  |
| 724002                                                                 | NO. 2 ENGINE - OUTER COMBUSTION LINER        |           |          |          |                           |           |           | Component ATA:72 |
| PN:3079976-01                                                          | MOS/MSC                                      | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:A004L607                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-40-01, MM 72-40-01PROC. REF: MM 72-40-01, MM 72-40-01 |                                              |           |          |          |                           |           |           |                  |
| 724003                                                                 | NO. 1 ENGINE - HP TURBINE AIR SEAL           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052756-01                                                          | MOS/MSC                                      | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:ECB8504                                                             | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 724003                                                                 | NO. 2 ENGINE - HP TURBINE AIR SEAL           |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052756-01                                                          | MOS/MSC                                      | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:ECB8501                                                             | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 724010                                                                 | NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:3075468-01                                                          | MOS/MSC                                      | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:ACM222195735                                                        | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                                        |                                              |           |          |          |                           |           |           |                  |
| 724010                                                                 | NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:3075468-01                                                          | MOS/MSC                                      | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:ACM222205612                                                        | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 724706                                                                 | NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053331-01                                                          | MOS                                          | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004KW91                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (10000)<br>10000 (M)      |           | 9402      |                  |
|                                                                        | ACCCYC                                       | 0         | 10000    | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                              |           |          |          |                           |           |           |                  |
| 724706                                                                 | NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053331-01                                                          | MOS                                          | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004KKR8                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (10000)<br>10000 (M)      |           | 9402      |                  |
|                                                                        | ACCCYC                                       | 0         | 10000    | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-50-01, MM 72-50-01PROC. REF: MM 72-50-01, MM 72-50-01 |                                              |           |          |          |                           |           |           |                  |
| 724825                                                                 | NO. 1 ENGINE - CENTRIFUGAL IMPELLER          |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052661-01                                                          | MOS                                          | 06-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004LPT2                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                       | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |
| 724825                                                                 | NO. 2 ENGINE - CENTRIFUGAL IMPELLER          |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052661-01                                                          | MOS                                          | 05-Dec-19 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:A004FT72                                                            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                          | 0         |          | TSN 0    | (13500)<br>13500 (M)      |           | 12902     |                  |
|                                                                        | ACCCYC                                       | 0         | 13500    | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXN0658                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY7710                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY7711                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY7724                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY7725                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY7729                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0131                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0137                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0139                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0341                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0345                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXN1173                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0420                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0423                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0424                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0430                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0432                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0437                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0496                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0510                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0519                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0535                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3157                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0536                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0539                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0544                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0640                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0890                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0894                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0901                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0902                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA1055                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA1063                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3162                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA1084                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA1086                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA1110                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2427                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2431                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2441                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2497                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2500                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2507                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2509                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3198                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2574                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2586                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2589                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2597                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2686                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2701                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA2843                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA3813                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA3816                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA4665                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3200                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5037                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3221                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3405                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY7708                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5039                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5056                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5059                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5096                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5101                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5117                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5187                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5193                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5242                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA5250                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXR9575                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9149                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9202                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9208                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9210                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9221                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9226                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9229                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9234                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9235                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9238                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX0468                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9240                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9243                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9507                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9508                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9524                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9528                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9529                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9587                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9589                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9596                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9119                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY2967                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY2978                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3018                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3022                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3029                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3035                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3040                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3050                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3053                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3106                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9122                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3132                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3135                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3189                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3204                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3208                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3210                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3220                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY3422                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9229                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9231                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9128                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9252                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9462                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9472                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9488                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9579                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9582                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9587                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9652                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9654                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9660                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9133                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9668                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9134                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9135                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXX9138                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9675                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9797                                        | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9801                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9802                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9803                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9811                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWXY9974                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0176                                        | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                               |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE                              |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                                                       | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0237                                        | HRS                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                           |           |           |                  |
| 725010                                             | NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE                              |           |          |          |                           |           |           | Component ATA:72 |
| PN:3077471-01                                      | MOS/MSC                                                                       | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:HWYA0248                                        | HRS                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                           |           |           |                  |
| 725015                                             | NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073355-01                                      | MOS/MSC                                                                       | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN518846                                       | HRS                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                           |           |           |                  |
| 725015                                             | NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073355-01                                      | MOS/MSC                                                                       | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN518849                                       | HRS                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                               |           |          |          |                           |           |           |                  |
| 725020                                             | NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY                                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3076552-01                                      | MOS/MSC                                                                       | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:RWA86F923                                       | HRS                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-50-03PROC. REF: MM 72-50-03       |                                                                               |           |          |          |                           |           |           |                  |
| 725020                                             | NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY                                  |           |          |          |                           |           |           | Component ATA:72 |
| PN:3076552-01                                      | MOS/MSC                                                                       | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:RWA86F496                                       | HRS                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-50-03PROC. REF: MM 72-50-03       |                                                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                         |           |          |          |                           |           |           |                  |
| 725025                                             | NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073353-01                                      | MOS/MSC                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:MDA19008252                                     | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 725025                                             | NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073353-01                                      | MOS/MSC                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:MDA19008246                                     | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 725030                                             | NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053163CL01                                     | MOS/MSC                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PDAMW3TP01                                      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 725030                                             | NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053163CL01                                     | MOS/MSC                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PDAMX27W01                                      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 725035                                             | NO. 1 ENGINE - TURBINE (CASTING) VANE RING              |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073821CL01                                     | MOS/MSC                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PDAM294M01                                      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |
| 725035                                             | NO. 2 ENGINE - TURBINE (CASTING) VANE RING              |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073821CL01                                     | MOS/MSC                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PDAM4L9M01                                      | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                   |           |          |          |                           |           |           |                  |
| 725040                                             | NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073262CL02                                     | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:BHAMBRHP01                                      | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725040                                             | NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073262CL02                                     | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:BHAMCMYB01                                      | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725041                                             | NO. 1 ENGINE - LP TURBINE VANE RING               |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053173CL01                                     | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PDAMW3TP01                                      | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 725041                                             | NO. 2 ENGINE - LP TURBINE VANE RING               |           |          |          |                           |           |           | Component ATA:72 |
| PN:3053173CL01                                     | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PDAMX27W01                                      | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 726010                                             | NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052549-01                                      | MOS/MSC                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN517275                                       | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 726010                                             | NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052549-01                                      | MOS/MSC                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FCN517281                                       | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|--------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                    |           |          |          |                           |           |           |                  |
| 726020                                             | NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320218                                      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 726020                                             | NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320170                                      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 726030                                             | NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320219                                      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 726030                                             | NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320173                                      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 726040                                             | NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING   |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320221                                      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |
| 726040                                             | NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING   |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                            | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320177                                      | HRS                                                                | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-----------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                       |           |          |          |                           |           |           |                  |
| 726050                                             | NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                               | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320225                                      | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 726050                                             | NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                               | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320178                                      | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 726051                                             | NO. 1 ENGINE - FUEL CONTROL DRIVE GEARSHAFT SPUR                      |           |          |          |                           |           |           | Component ATA:72 |
| PN:3078182-01                                      | MOS/MSC                                                               | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA846475                                     | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 726051                                             | NO. 2 ENGINE - FUEL CONTROL DRIVE GEARSHAFT SPUR                      |           |          |          |                           |           |           | Component ATA:72 |
| PN:3078182-01                                      | MOS/MSC                                                               | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA836552                                     | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 726060                                             | NO. 1 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                               | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320228                                      | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |
| 726060                                             | NO. 2 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073908-01                                      | MOS/MSC                                                               | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:AEB0320179                                      | HRS                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                   |           |          |          |                           |           |           |                  |
| 726070                                             | NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY                 |           |          |          |                           |           |           | Component ATA:72 |
| PN:3078183-01                                      | MOS/MSC                                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA838160                                     | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726070                                             | NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY                 |           |          |          |                           |           |           | Component ATA:72 |
| PN:3078183-01                                      | MOS/MSC                                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA838155                                     | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726080                                             | NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT                      |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072279-01                                      | MOS/MSC                                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA844367                                     | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726080                                             | NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT                      |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072279-01                                      | MOS/MSC                                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA844372                                     | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726090                                             | NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072235-01                                      | MOS/MSC                                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FAA1905521                                      | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726090                                             | NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072235-01                                      | MOS/MSC                                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FAA1905517                                      | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                   |           |          |          |                           |           |           |                  |
| 726110                                             | NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052605-01                                      | MOS/MSC                                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FAA1912984                                      | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726110                                             | NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052605-01                                      | MOS/MSC                                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:FAA1912987                                      | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726120                                             | NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052550-01                                      | MOS/MSC                                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:BB0317747                                       | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726120                                             | NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3052550-01                                      | MOS/MSC                                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:BB0305352                                       | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726130                                             | NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072282-01                                      | MOS/MSC                                                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA842408                                     | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |
| 726130                                             | NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072282-01                                      | MOS/MSC                                                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:PKAAA842405                                     | HRS                                                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                                          | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                                    |                                                                                               |           |            |          |                           |           |           |                  |
| 727010                                             | NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY                                               |           |            |          |                           |           |           | Component ATA:72 |
| PN:3075013-01                                      | MOS/MSC                                                                                       | 06-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:KYAA028A047                                     | HRS                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                               |           |            |          |                           |           |           |                  |
| 727010                                             | NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY                                               |           |            |          |                           |           |           | Component ATA:72 |
| PN:3075013-01                                      | MOS/MSC                                                                                       | 05-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:KYAA026A033                                     | HRS                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                               |           |            |          |                           |           |           |                  |
| 727020                                             | NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY                                                      |           |            |          |                           |           |           | Component ATA:72 |
| PN:3074835-01                                      | MOS/MSC                                                                                       | 06-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:KYAA028A316                                     | HRS                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-70-01PROC. REF: MM 72-70-01       |                                                                                               |           |            |          |                           |           |           |                  |
| 727020                                             | NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY                                                      |           |            |          |                           |           |           | Component ATA:72 |
| PN:3074835-01                                      | MOS/MSC                                                                                       | 05-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:KYAA028A305                                     | HRS                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                                           | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 72-70-01PROC. REF: MM 72-70-01       |                                                                                               |           |            |          |                           |           |           |                  |
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                                                                               |           |            |          |                           |           |           |                  |
| 72-00-00-280-819 <sup>S</sup>                      | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY |           |            |          |                           |           |           | Service ATA:73   |
|                                                    | MOS                                                                                           | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
|                                                    | HRS                                                                                           | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                    | ENC                                                                                           | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                                               |           |            |          |                           |           |           |                  |
|                                                    |                                                                                               |           |            |          |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                                          | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                                                                               |           |             |          |                           |           |                |                |
| 72-00-00-280-819 <sup>S</sup>                      | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                           | 13-Mar-26 | 12 (+30d)   |          |                           |           |                |                |
|                                                    | HRS                                                                                           | 1221:24   | 800 (+10%)  |          |                           |           |                |                |
|                                                    | ENC                                                                                           | 564       |             |          |                           |           |                |                |
| PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00       |                                                                                               |           |             |          |                           |           |                | PKG:1          |
|                                                    |                                                                                               |           |             |          |                           |           |                |                |
| 73-10-01-212-801                                   | NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES                                         |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                           | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                           | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                           | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                               |           |             |          |                           |           |                |                |
|                                                    |                                                                                               |           |             |          |                           |           |                |                |
| 73-10-01-212-801                                   | NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES                                         |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                           | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                           | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                           | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                               |           |             |          |                           |           |                |                |
|                                                    |                                                                                               |           |             |          |                           |           |                |                |
| 73-10-04-000-801                                   | NO. 1 ENGINE - DISCARD THE FUEL MANIFOLD PAD                                                  |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                           | 06-Dec-19 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                           | 0         |             |          |                           |           |                |                |
|                                                    | ENC                                                                                           | 0         | 9900        |          | (9900)<br>9900            |           | 9302           |                |
| PROC. REF: MM 73-10-04PROC. REF: MM 73-10-04       |                                                                                               |           |             |          |                           |           |                |                |
|                                                    |                                                                                               |           |             |          |                           |           |                |                |
| 73-10-04-000-801                                   | NO. 2 ENGINE - DISCARD THE FUEL MANIFOLD PAD                                                  |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                           | 05-Dec-19 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                           | 0         |             |          |                           |           |                |                |
|                                                    | ENC                                                                                           | 0         | 9900        |          | (9900)<br>9900            |           | 9302           |                |
| PROC. REF: MM 73-10-04PROC. REF: MM 73-10-04       |                                                                                               |           |             |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                                      | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|------------------------------------------------------------------------|---------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                       |                                                                           |           |            |          |                           |           |              |                |
| 73-10-05-212-801                                                       | NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT |           |            |          |                           |           |              | Service ATA:73 |
|                                                                        | MOS                                                                       | 13-Mar-26 | 12 (+30d)  |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30)  |                |
|                                                                        | HRS                                                                       | 1221:24   |            |          |                           |           |              |                |
|                                                                        | ENC                                                                       | 564       |            |          |                           |           |              |                |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                           |                                                                           |           |            |          |                           |           |              |                |
| 73-10-05-212-801                                                       | NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT |           |            |          |                           |           |              | Service ATA:73 |
|                                                                        | MOS                                                                       | 13-Mar-26 | 12 (+30d)  |          | 13-Mar-27                 | 12-Apr-27 | 227 d (+30)  |                |
|                                                                        | HRS                                                                       | 1221:24   |            |          |                           |           |              |                |
|                                                                        | ENC                                                                       | 564       |            |          |                           |           |              |                |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                           |                                                                           |           |            |          |                           |           |              |                |
| 73-10-05-960-801                                                       | NO. 1 ENGINE - DISCARD THE FUEL FILTER                                    |           |            |          |                           |           |              | Service ATA:73 |
| PN:3052624-01                                                          | MOS                                                                       | 19-Mar-24 |            |          |                           |           |              |                |
| SN:N/A                                                                 | HRS                                                                       | 781:30    | 800 (+10%) |          | (1581:30)<br>1581:30      | 1661:30   | 286:06 (+80) |                |
|                                                                        | ENC                                                                       | 364       |            |          |                           |           |              |                |
| PROC. REF: MM 73-10-05, MM 73-10-05PROC. REF: MM 73-10-05, MM 73-10-05 |                                                                           |           |            |          |                           |           |              |                |
| 73-10-05-960-801                                                       | NO. 2 ENGINE - DISCARD THE FUEL FILTER                                    |           |            |          |                           |           |              | Service ATA:73 |
| PN:3052624-01                                                          | MOS                                                                       | 19-Mar-24 |            |          |                           |           |              |                |
| SN:N/A                                                                 | HRS                                                                       | 781:30    | 800 (+10%) |          | (1581:30)<br>1581:30      | 1661:30   | 286:06 (+80) |                |
|                                                                        | ENC                                                                       | 364       |            |          |                           |           |              |                |
| PROC. REF: MM 73-10-05, MM 73-10-05PROC. REF: MM 73-10-05, MM 73-10-05 |                                                                           |           |            |          |                           |           |              |                |
| 73-10-07-212-801 <sup>S</sup>                                          | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE                |           |            |          |                           |           |              | Service ATA:73 |
|                                                                        | MOS                                                                       | 13-Mar-26 | 12 (+30d)  |          |                           |           |              |                |
|                                                                        | HRS                                                                       | 1221:24   | 800 (+10%) |          |                           |           |              |                |
|                                                                        | ENC                                                                       | 564       |            |          |                           |           |              |                |
| PROC. REF: MM 73-10-07PROC. REF: MM 73-10-07                           |                                                                           |           |            |          |                           |           |              |                |
|                                                                        |                                                                           |           |            |          |                           |           |              | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit                                                                                      | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|----------------------------------------------|-------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL             |                                                                                           |           |             |          |                           |           |                |                |
| 73-10-07-212-801 <sup>S</sup>                | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE                                |           |             |          |                           |           |                | Service ATA:73 |
|                                              | MOS                                                                                       | 13-Mar-26 | 12 (+30d)   |          |                           |           |                |                |
|                                              | HRS                                                                                       | 1221:24   | 800 (+10%)  |          |                           |           |                |                |
|                                              | ENC                                                                                       | 564       |             |          |                           |           |                |                |
| PROC. REF: MM 73-10-07PROC. REF: MM 73-10-07 |                                                                                           |           |             |          |                           |           |                | PKG:1          |
|                                              |                                                                                           |           |             |          |                           |           |                |                |
| 73-20-01-212-801                             | NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT |           |             |          |                           |           |                | Service ATA:73 |
| PN:3071682-05                                | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
| SN:F85602                                    | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                              | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 73-20-01PROC. REF: MM 73-20-01 |                                                                                           |           |             |          |                           |           |                |                |
|                                              |                                                                                           |           |             |          |                           |           |                |                |
| 73-20-01-212-801                             | NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT |           |             |          |                           |           |                | Service ATA:73 |
| PN:3071682-05                                | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
| SN:F85863                                    | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                              | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 73-20-01PROC. REF: MM 73-20-01 |                                                                                           |           |             |          |                           |           |                |                |
|                                              |                                                                                           |           |             |          |                           |           |                |                |
| 73-20-02-212-801 <sup>S</sup>                | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS                     |           |             |          |                           |           |                | Service ATA:73 |
|                                              | MOS                                                                                       | 13-Mar-26 | 12 (+30d)   |          |                           |           |                |                |
|                                              | HRS                                                                                       | 1221:24   | 800 (+10%)  |          |                           |           |                |                |
|                                              | ENC                                                                                       | 564       |             |          |                           |           |                |                |
| PROC. REF: MM 73-20-02PROC. REF: MM 73-20-02 |                                                                                           |           |             |          |                           |           |                | PKG:1          |
|                                              |                                                                                           |           |             |          |                           |           |                |                |
| 73-20-02-212-801 <sup>S</sup>                | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS                     |           |             |          |                           |           |                | Service ATA:73 |
|                                              | MOS                                                                                       | 13-Mar-26 | 12 (+30d)   |          |                           |           |                |                |
|                                              | HRS                                                                                       | 1221:24   | 800 (+10%)  |          |                           |           |                |                |
|                                              | ENC                                                                                       | 564       |             |          |                           |           |                |                |
| PROC. REF: MM 73-20-02PROC. REF: MM 73-20-02 |                                                                                           |           |             |          |                           |           |                | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|----------------------------------------------------|--------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                                                                            |           |             |          |                           |           |                |                |
| 73-20-10-212-801                                   | NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS                    |           |             |          |                           |           |                | Service ATA:73 |
| PN:3073237-05                                      | MOS                                                                                        | 23-Apr-20 |             |          |                           |           |                |                |
| SN:ADXBA001698                                     | HRS                                                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                        | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                            |           |             |          |                           |           |                |                |
| 73-20-10-212-801                                   | NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS                    |           |             |          |                           |           |                | Service ATA:73 |
| PN:3073237-05                                      | MOS                                                                                        | 23-Apr-20 |             |          |                           |           |                |                |
| SN:ADXBA001677                                     | HRS                                                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                        | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                            |           |             |          |                           |           |                |                |
| 73-20-20-212-801                                   | NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES                                        |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                        | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                        | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                            |           |             |          |                           |           |                |                |
| 73-20-20-212-801                                   | NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES                                        |           |             |          |                           |           |                | Service ATA:73 |
|                                                    | MOS                                                                                        | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                        | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                            |           |             |          |                           |           |                |                |
| 73-20-30-212-801                                   | NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                           |           |                | Service ATA:73 |
| PN:PN                                              | MOS                                                                                        | 23-Apr-20 |             |          |                           |           |                |                |
| SN:UNKNOWN                                         | HRS                                                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                        | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                            |           |             |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |                                                                                            |           |             |          |                           |           |                |                  |
| 73-20-30-212-801                                                           | NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                           |           |                | Service ATA:73   |
| PN:PN                                                                      | MOS                                                                                        | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                                                 | HRS                                                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                            | ENC                                                                                        | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                                            |           |             |          |                           |           |                |                  |
| 73-21-01                                                                   | LEFT FADEC                                                                                 |           |             |          |                           |           |                | Component ATA:73 |
| PN:3073593-08                                                              | MOS/MSC                                                                                    | 23-Apr-20 | O/C         | TSN 0    |                           |           |                |                  |
| SN:2019080466                                                              | HRS                                                                                        | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                                        | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 73-21-01, AMM 73-21-01PROC. REF: AMM 73-21-01, AMM 73-21-01 |                                                                                            |           |             |          |                           |           |                |                  |
| 73-21-01                                                                   | RIGHT FADEC                                                                                |           |             |          |                           |           |                | Component ATA:73 |
| PN:3073593-08                                                              | MOS/MSC                                                                                    | 23-Apr-20 | O/C         | TSN 0    |                           |           |                |                  |
| SN:2019081373                                                              | HRS                                                                                        | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                                        | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 73-21-01, AMM 73-21-01PROC. REF: AMM 73-21-01, AMM 73-21-01 |                                                                                            |           |             |          |                           |           |                |                  |
| 73-30-02-212-801 <sup>S</sup>                                              | NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR          |           |             |          |                           |           |                | Service ATA:73   |
|                                                                            | MOS                                                                                        | 13-Mar-26 | 12 (+30d)   |          |                           |           |                |                  |
|                                                                            | HRS                                                                                        | 1221:24   | 800 (+10%)  |          |                           |           |                |                  |
|                                                                            | ENC                                                                                        | 564       |             |          |                           |           |                |                  |
| PROC. REF: MM 73-30-02PROC. REF: MM 73-30-02                               |                                                                                            |           |             |          |                           |           |                | PKG:1            |
| 73-30-02-212-801 <sup>S</sup>                                              | NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR          |           |             |          |                           |           |                | Service ATA:73   |
|                                                                            | MOS                                                                                        | 13-Mar-26 | 12 (+30d)   |          |                           |           |                |                  |
|                                                                            | HRS                                                                                        | 1221:24   | 800 (+10%)  |          |                           |           |                |                  |
|                                                                            | ENC                                                                                        | 564       |             |          |                           |           |                |                  |
| PROC. REF: MM 73-30-02PROC. REF: MM 73-30-02                               |                                                                                            |           |             |          |                           |           |                | PKG:1            |
| 73-33-01                                                                   | LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER                                   |           |             |          |                           |           |                | Component ATA:73 |
| PN:8TJ300AAB2                                                              | MOS/MSC                                                                                    | 23-Apr-20 | O/C         | TSN 0    |                           |           |                |                  |
| SN:DT6895N                                                                 | HRS                                                                                        | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                                                        | 0         |             | TSN 0    |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                           |         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 73-33-01, AMM 73-33-01PROC. REF: AMM 73-33-01, AMM 73-33-01 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 73-33-01 RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER         |         |           |          |          |                           |           |           | Component ATA:73 |
| PN:8TJ300AAB2                                                              | MOS/MSC | 23-Apr-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DT8299N                                                                 | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 73-33-01, AMM 73-33-01PROC. REF: AMM 73-33-01, AMM 73-33-01 |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 731005 NO. 1 ENGINE - FUEL FILTER                                          |         |           |          |          |                           |           |           | Component ATA:73 |
| PN:3052624-01                                                              | MOS/MSC | 19-Mar-24 | O/C      | TSN 29   |                           |           |           |                  |
| SN:N/A                                                                     | HRS     | 781:30    |          | TSN 0    |                           |           |           |                  |
|                                                                            | ENC     | 364       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                               |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 731005 NO. 2 ENGINE - FUEL FILTER                                          |         |           |          |          |                           |           |           | Component ATA:73 |
| PN:3052624-01                                                              | MOS/MSC | 19-Mar-24 | O/C      | TSN 29   |                           |           |           |                  |
| SN:N/A                                                                     | HRS     | 781:30    |          | TSN 0    |                           |           |           |                  |
|                                                                            | ENC     | 364       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-10-05PROC. REF: MM 73-10-05                               |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 731010 NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY                           |         |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                                              | MOS/MSC | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46256                                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | ENC     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 731010 NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY                          |         |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                                              | MOS/MSC | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46265                                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | ENC     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |         |           |          |          |                           |           |           |                  |
|                                                                            |         |           |          |          |                           |           |           |                  |
| 731010 NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY                          |         |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                                              | MOS/MSC | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46266                                                              | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                            | ENC     | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                           |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46257                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46258                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46259                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46260                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46261                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46262                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                            |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY  |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46263                                      | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY  |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46264                                      | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY  |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46303                                      | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB47049                                      | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB47061                                      | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY  |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                    | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46304                                      | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                        | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                           |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46305                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46306                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46307                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46308                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46309                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                           |           |          |          |                           |           |           |                  |
| 731010                                             | NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                      | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46310                                      | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                                                    | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                                                                                           |                                                         |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                         |                                                         |           |          |          |                           |           |           |                  |
| 731010                                                                                                                     | NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY               |           |          |          |                           |           |           | Component ATA:73 |
| PN:3057135-01                                                                                                              | MOS/MSC                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DEAAB46311                                                                                                              | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                                                         |                                                         |           |          |          |                           |           |           |                  |
| 732002                                                                                                                     | NO. 1 ENGINE - FUEL METERING UNIT (FMU)                 |           |          |          |                           |           |           | Component ATA:73 |
| PN:3071682-05                                                                                                              | MOS/MSC                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:F85602                                                                                                                  | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-20-01, MM 73-20-01PROC. REF: MM 73-20-01, MM 73-20-01                                                     |                                                         |           |          |          |                           |           |           |                  |
| 732002                                                                                                                     | NO. 2 ENGINE - FUEL METERING UNIT (FMU)                 |           |          |          |                           |           |           | Component ATA:73 |
| PN:3071682-05                                                                                                              | MOS/MSC                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:F85863                                                                                                                  | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-20-01, MM 73-20-01PROC. REF: MM 73-20-01, MM 73-20-01                                                     |                                                         |           |          |          |                           |           |           |                  |
| 732010                                                                                                                     | NO. 1 ENGINE - ELECTRICAL WIRING HARNESS                |           |          |          |                           |           |           | Component ATA:73 |
| PN:3073237-05                                                                                                              | MOS/MSC                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:ADXBA001698                                                                                                             | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02 |                                                         |           |          |          |                           |           |           |                  |
| 732010                                                                                                                     | NO. 2 ENGINE - ELECTRICAL WIRING HARNESS                |           |          |          |                           |           |           | Component ATA:73 |
| PN:3073237-05                                                                                                              | MOS/MSC                                                 | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:ADXBA001677                                                                                                             | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02 |                                                         |           |          |          |                           |           |           |                  |
| 732030                                                                                                                     | NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:73 |
| PN:PN                                                                                                                      | MOS/MSC                                                 | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                                                                 | HRS                                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                                                                            | ENC                                                     | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                              | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|-----------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL                   |                                                                                   |           |            |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                   |           |            |          |                           |           |           |                  |
| 732030                                             | NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH                           |           |            |          |                           |           |           | Component ATA:73 |
| PN:PN                                              | MOS/MSC                                                                           | 05-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS                                                                               | 0         |            | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                                                               | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                   |           |            |          |                           |           |           |                  |
| ATA 74 - IGNITION                                  |                                                                                   |           |            |          |                           |           |           |                  |
| 74-00-01-750-801 <sup>S</sup>                      | NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM                            |           |            |          |                           |           |           | Service ATA:74   |
|                                                    | MOS                                                                               | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
|                                                    | HRS                                                                               | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                    | ENC                                                                               | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 74-00-01PROC. REF: MM 74-00-01       |                                                                                   |           |            |          |                           |           |           | PKG:1            |
| 74-00-01-750-801 <sup>S</sup>                      | NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM                            |           |            |          |                           |           |           | Service ATA:74   |
|                                                    | MOS                                                                               | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
|                                                    | HRS                                                                               | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                    | ENC                                                                               | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 74-00-01PROC. REF: MM 74-00-01       |                                                                                   |           |            |          |                           |           |           | PKG:1            |
| 74-10-01-212-801 <sup>S</sup>                      | NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER |           |            |          |                           |           |           | Service ATA:74   |
| PN:31J2807-07                                      | MOS                                                                               | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
| SN:NNA19320003                                     | HRS                                                                               | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                    | ENC                                                                               | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 74-10-01PROC. REF: MM 74-10-01       |                                                                                   |           |            |          |                           |           |           | PKG:1            |
| 74-10-01-212-801 <sup>S</sup>                      | NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER |           |            |          |                           |           |           | Service ATA:74   |
| PN:31J2807-07                                      | MOS                                                                               | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
| SN:NNA19320005                                     | HRS                                                                               | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                    | ENC                                                                               | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 74-10-01PROC. REF: MM 74-10-01       |                                                                                   |           |            |          |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                      | Unit         | C/W                                                                | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|----------------------------------------------|--------------|--------------------------------------------------------------------|------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 74 - IGNITION                            |              |                                                                    |            |          |                           |           |           |                |
| 74-20-01-212-801                             | <sup>S</sup> | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES    |            |          |                           |           |           | Service ATA:74 |
|                                              | MOS          | 13-Mar-26                                                          | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                            | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                |            |          |                           |           |           |                |
| PROC. REF: MM 74-20-01PROC. REF: MM 74-20-01 |              |                                                                    |            |          |                           |           |           | PKG:1          |
| 74-20-01-212-801                             | <sup>S</sup> | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES    |            |          |                           |           |           | Service ATA:74 |
|                                              | MOS          | 13-Mar-26                                                          | 12 (+30d)  |          |                           |           |           |                |
|                                              | HRS          | 1221:24                                                            | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                |            |          |                           |           |           |                |
| PROC. REF: MM 74-20-01PROC. REF: MM 74-20-01 |              |                                                                    |            |          |                           |           |           | PKG:1          |
| 74-20-02-210-801                             | <sup>S</sup> | NO. 1 ENGINE - VISUAL INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR |            |          |                           |           |           | Service ATA:74 |
| PN:PN                                        | MOS          | 13-Mar-26                                                          | 12 (+30d)  |          |                           |           |           |                |
| SN:UNKNOWN                                   | HRS          | 1221:24                                                            | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                |            |          |                           |           |           |                |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02 |              |                                                                    |            |          |                           |           |           | PKG:1          |
| 74-20-02-210-801                             | <sup>S</sup> | NO. 1 ENGINE - VISUAL INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR |            |          |                           |           |           | Service ATA:74 |
| PN:PN                                        | MOS          | 13-Mar-26                                                          | 12 (+30d)  |          |                           |           |           |                |
| SN:UNKNOWN                                   | HRS          | 1221:24                                                            | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                |            |          |                           |           |           |                |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02 |              |                                                                    |            |          |                           |           |           | PKG:1          |
| 74-20-02-210-801                             | <sup>S</sup> | NO. 2 ENGINE - VISUAL INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR |            |          |                           |           |           | Service ATA:74 |
| PN:PN                                        | MOS          | 13-Mar-26                                                          | 12 (+30d)  |          |                           |           |           |                |
| SN:UNKNOWN                                   | HRS          | 1221:24                                                            | 800 (+10%) |          |                           |           |           |                |
|                                              | ENC          | 564                                                                |            |          |                           |           |           |                |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02 |              |                                                                    |            |          |                           |           |           | PKG:1          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit         | C/W                                                                | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|--------------|--------------------------------------------------------------------|------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 74 - IGNITION                                                      |              |                                                                    |            |          |                           |           |           |                  |
| 74-20-02-210-801                                                       | <sup>S</sup> | NO. 2 ENGINE - VISUAL INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR |            |          |                           |           |           | Service ATA:74   |
| PN:PN                                                                  | MOS          | 13-Mar-26                                                          | 12 (+30d)  |          |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS          | 1221:24                                                            | 800 (+10%) |          |                           |           |           |                  |
|                                                                        | ENC          | 564                                                                |            |          |                           |           |           |                  |
| PROC. REF: MM 74-20-02PROC. REF: MM 74-20-02                           |              |                                                                    |            |          |                           |           |           | PKG:1            |
| 74-20-02-960-801                                                       |              | NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER                           |            |          |                           |           |           | Service ATA:74   |
| PN:PN                                                                  | MOS/MSC      | 06-Dec-19                                                          | O/C        |          |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS          | 0                                                                  |            |          |                           |           |           |                  |
|                                                                        | ENC          | 0                                                                  |            |          |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |              |                                                                    |            |          |                           |           |           |                  |
| 74-20-02-960-801                                                       |              | NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER                            |            |          |                           |           |           | Service ATA:74   |
| PN:PN                                                                  | MOS/MSC      | 06-Dec-19                                                          | O/C        |          |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS          | 0                                                                  |            |          |                           |           |           |                  |
|                                                                        | ENC          | 0                                                                  |            |          |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |              |                                                                    |            |          |                           |           |           |                  |
| 74-20-02-960-801                                                       |              | NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER                           |            |          |                           |           |           | Service ATA:74   |
| PN:PN                                                                  | MOS/MSC      | 05-Dec-19                                                          | O/C        |          |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS          | 0                                                                  |            |          |                           |           |           |                  |
|                                                                        | ENC          | 0                                                                  |            |          |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |              |                                                                    |            |          |                           |           |           |                  |
| 74-20-02-960-801                                                       |              | NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER                            |            |          |                           |           |           | Service ATA:74   |
| PN:PN                                                                  | MOS/MSC      | 05-Dec-19                                                          | O/C        |          |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS          | 0                                                                  |            |          |                           |           |           |                  |
|                                                                        | ENC          | 0                                                                  |            |          |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |              |                                                                    |            |          |                           |           |           |                  |
| 741001                                                                 |              | NO. 1 ENGINE - EXCITER IGNITION                                    |            |          |                           |           |           | Component ATA:74 |
| PN:31J2807-07                                                          | MOS/MSC      | 06-Dec-19                                                          | O/C        | TSN 0    |                           |           |           |                  |
| SN:NNA19320003                                                         | HRS          | 0                                                                  |            | TSN 0    |                           |           |           |                  |
|                                                                        | ENC          | 0                                                                  |            | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-10-01, MM 74-10-01PROC. REF: MM 74-10-01, MM 74-10-01 |              |                                                                    |            |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 74 - IGNITION                                                      |                                           |           |          |          |                           |           |           |                  |
| 741001                                                                 | NO. 2 ENGINE - EXCITER IGNITION           |           |          |          |                           |           |           | Component ATA:74 |
| PN:31J2807-07                                                          | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NNA19320005                                                         | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-10-01, MM 74-10-01PROC. REF: MM 74-10-01, MM 74-10-01 |                                           |           |          |          |                           |           |           |                  |
| 742000                                                                 | NO. 1 ENGINE - 5 O'CLOCK IGNITER          |           |          |          |                           |           |           | Component ATA:74 |
| PN:PN                                                                  | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                           |           |           |                  |
| 742000                                                                 | NO. 2 ENGINE - 5 O'CLOCK IGNITER          |           |          |          |                           |           |           | Component ATA:74 |
| PN:PN                                                                  | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                           |           |           |                  |
| 742001                                                                 | NO. 1 ENGINE - 7 O'CLOCK IGNITER          |           |          |          |                           |           |           | Component ATA:74 |
| PN:PN                                                                  | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                           |           |           |                  |
| 742001                                                                 | NO. 2 ENGINE - 7 O'CLOCK IGNITER          |           |          |          |                           |           |           | Component ATA:74 |
| PN:PN                                                                  | MOS/MSC                                   | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-02, MM 74-20-02PROC. REF: MM 74-20-02, MM 74-20-02 |                                           |           |          |          |                           |           |           |                  |
| 742002                                                                 | NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD |           |          |          |                           |           |           | Component ATA:74 |
| PN:3127408-01                                                          | MOS/MSC                                   | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NNA17520072                                                         | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                       | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                           |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                                         | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 74 - IGNITION                                                      |                                                                              |           |            |          |                           |           |           |                  |
| 742002                                                                 | NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD                                    |           |            |          |                           |           |           | Component ATA:74 |
| PN:3127408-01                                                          | MOS/MSC                                                                      | 05-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:NNAS19130008                                                        | HRS                                                                          | 0         |            | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                          | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                                                              |           |            |          |                           |           |           |                  |
| 742003                                                                 | NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD                                    |           |            |          |                           |           |           | Component ATA:74 |
| PN:3127408-02                                                          | MOS/MSC                                                                      | 06-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:NNA17430105                                                         | HRS                                                                          | 0         |            | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                          | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                                                              |           |            |          |                           |           |           |                  |
| 742003                                                                 | NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD                                    |           |            |          |                           |           |           | Component ATA:74 |
| PN:3127408-02                                                          | MOS/MSC                                                                      | 05-Dec-19 | O/C        | TSN 0    |                           |           |           |                  |
| SN:NNA17410094                                                         | HRS                                                                          | 0         |            | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                                          | 0         |            | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 74-20-01, MM 74-20-01PROC. REF: MM 74-20-01, MM 74-20-01 |                                                                              |           |            |          |                           |           |           |                  |
| ATA 75 - AIR                                                           |                                                                              |           |            |          |                           |           |           |                  |
| 75-30-01-212-801 <sup>S</sup>                                          | NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE |           |            |          |                           |           |           | Service ATA:75   |
|                                                                        | MOS                                                                          | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
|                                                                        | HRS                                                                          | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                                        | ENC                                                                          | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                           |                                                                              |           |            |          |                           |           |           | PKG:1            |
| 75-30-01-212-801 <sup>S</sup>                                          | NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE |           |            |          |                           |           |           | Service ATA:75   |
|                                                                        | MOS                                                                          | 13-Mar-26 | 12 (+30d)  |          |                           |           |           |                  |
|                                                                        | HRS                                                                          | 1221:24   | 800 (+10%) |          |                           |           |           |                  |
|                                                                        | ENC                                                                          | 564       |            |          |                           |           |           |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                           |                                                                              |           |            |          |                           |           |           | PKG:1            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                     | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|------------------------------------------------------------------------|----------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 75 - AIR                                                           |                                                          |           |             |          |                           |           |                |                  |
| 75-30-01-212-802                                                       | NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR       |           |             |          |                           |           |                | Service ATA:75   |
| PN:PN                                                                  | MOS                                                      | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                                             | HRS                                                      | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                      | 0         |             |          |                           |           |                |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                           |                                                          |           |             |          |                           |           |                |                  |
| 75-30-01-212-802                                                       | NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR       |           |             |          |                           |           |                | Service ATA:75   |
| PN:PN                                                                  | MOS                                                      | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                                             | HRS                                                      | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                      | 0         |             |          |                           |           |                |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                           |                                                          |           |             |          |                           |           |                |                  |
| 75-30-01-212-803                                                       | NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE      |           |             |          |                           |           |                | Service ATA:75   |
| PN:3053367-01                                                          | MOS                                                      | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:AHX0501012                                                          | HRS                                                      | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                      | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                          |           |             |          |                           |           |                |                  |
| 75-30-01-212-803                                                       | NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE      |           |             |          |                           |           |                | Service ATA:75   |
| PN:3053367-01                                                          | MOS                                                      | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:AHX0501016                                                          | HRS                                                      | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                      | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                          |           |             |          |                           |           |                |                  |
| 75-30-01-900-802                                                       | NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE |           |             |          |                           |           |                | Component ATA:75 |
| PN:PN                                                                  | MOS/MSC                                                  | 06-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:UNKNOWN                                                             | HRS                                                      | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                        | ENC                                                      | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                          |           |             |          |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                      |
|------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------------------------|
| ATA 75 - AIR                                                           |                                                                                                          |           |          |          |                           |           |           |                                  |
| 75-30-01-900-802                                                       | NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE                                                 |           |          |          |                           |           |           | Component ATA:75                 |
| PN:PN                                                                  | MOS/MSC                                                                                                  | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                                  |
| SN:UNKNOWN                                                             | HRS                                                                                                      | 0         |          | TSN 0    |                           |           |           |                                  |
|                                                                        | ENC                                                                                                      | 0         |          | TSN 0    |                           |           |           |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                           |           |           |                                  |
| 75-30-01-900-803                                                       | NO. 1 ENGINE - LINEAR TRANSFORMER                                                                        |           |          |          |                           |           |           | Component ATA:75                 |
| PN:3071811-01                                                          | MOS/MSC                                                                                                  | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                                  |
| SN:117032449                                                           | HRS                                                                                                      | 0         |          | TSN 0    |                           |           |           |                                  |
|                                                                        | ENC                                                                                                      | 0         |          | TSN 0    |                           |           |           |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                           |           |           |                                  |
| 75-30-01-900-803                                                       | NO. 2 ENGINE - LINEAR TRANSFORMER                                                                        |           |          |          |                           |           |           | Component ATA:75                 |
| PN:3071811-01                                                          | MOS/MSC                                                                                                  | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                                  |
| SN:117032454                                                           | HRS                                                                                                      | 0         |          | TSN 0    |                           |           |           |                                  |
|                                                                        | ENC                                                                                                      | 0         |          | TSN 0    |                           |           |           |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                           |           |           |                                  |
| 75-30-01-960-801                                                       | NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES |           |          |          |                           |           |           | Service ATA:75                   |
|                                                                        | MOS/MSC                                                                                                  | 06-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                                        | HRS                                                                                                      | 0         |          |          |                           |           |           |                                  |
|                                                                        | ENC                                                                                                      | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                           |           |           |                                  |
| 75-30-01-960-801                                                       | NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES |           |          |          |                           |           |           | Service ATA:75                   |
|                                                                        | MOS/MSC                                                                                                  | 05-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
|                                                                        | HRS                                                                                                      | 0         |          |          |                           |           |           |                                  |
|                                                                        | ENC                                                                                                      | 0         |          |          |                           |           |           |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01 |                                                                                                          |           |          |          |                           |           |           |                                  |
| 75-30-01-960-802                                                       | NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE           |           |          |          |                           |           |           | Service ATA:75                   |
| PN:3075987-01                                                          | MOS/MSC                                                                                                  | 06-Dec-19 | A/R      |          |                           |           |           | UNSCHEDULED<br>MAINTENANCE CHECK |
| SN:TRAXY000333                                                         | HRS                                                                                                      | 0         |          |          |                           |           |           |                                  |
|                                                                        | ENC                                                                                                      | 0         |          |          |                           |           |           |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                                          | Unit                                                                                                                           | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition                      |
|--------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------------------------|
| ATA 75 - AIR                                                                                     |                                                                                                                                |           |             |          |                           |           |                |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01                           |                                                                                                                                |           |             |          |                           |           |                |                                  |
|                                                                                                  |                                                                                                                                |           |             |          |                           |           |                |                                  |
| 75-30-01-960-802                                                                                 | NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE                                 |           |             |          |                           |           |                | Service ATA:75                   |
| PN:3075987-01                                                                                    | MOS/MSC                                                                                                                        | 05-Dec-19 | A/R         |          |                           |           |                | UNSCHEDULED<br>MAINTENANCE CHECK |
| SN:TRAXY000329                                                                                   | HRS                                                                                                                            | 0         |             |          |                           |           |                |                                  |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                           |           |                |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01                           |                                                                                                                                |           |             |          |                           |           |                |                                  |
|                                                                                                  |                                                                                                                                |           |             |          |                           |           |                |                                  |
| 75-30-01-960-803                                                                                 | NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER |           |             |          |                           |           |                | Service ATA:75                   |
| PN:3071811-01                                                                                    | MOS/MSC                                                                                                                        | 06-Dec-19 | A/R         |          |                           |           |                | UNSCHEDULED<br>MAINTENANCE CHECK |
| SN:117032449                                                                                     | HRS                                                                                                                            | 0         |             |          |                           |           |                |                                  |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                           |           |                |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01 |                                                                                                                                |           |             |          |                           |           |                |                                  |
|                                                                                                  |                                                                                                                                |           |             |          |                           |           |                |                                  |
| 75-30-01-960-803                                                                                 | NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER |           |             |          |                           |           |                | Service ATA:75                   |
| PN:3071811-01                                                                                    | MOS/MSC                                                                                                                        | 05-Dec-19 | A/R         |          |                           |           |                | UNSCHEDULED<br>MAINTENANCE CHECK |
| SN:117032454                                                                                     | HRS                                                                                                                            | 0         |             |          |                           |           |                |                                  |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                           |           |                |                                  |
| PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01 |                                                                                                                                |           |             |          |                           |           |                |                                  |
|                                                                                                  |                                                                                                                                |           |             |          |                           |           |                |                                  |
| 75-30-02-212-801                                                                                 | NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER                |           |             |          |                           |           |                | Service ATA:75                   |
| PN:3071811-01                                                                                    | MOS                                                                                                                            | 23-Apr-20 |             |          |                           |           |                |                                  |
| SN:117032449                                                                                     | HRS                                                                                                                            | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                                  |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                           |           |                |                                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                               |                                                                                                                                |           |             |          |                           |           |                |                                  |
|                                                                                                  |                                                                                                                                |           |             |          |                           |           |                |                                  |
| 75-30-02-212-801                                                                                 | NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER                |           |             |          |                           |           |                | Service ATA:75                   |
| PN:3071811-01                                                                                    | MOS                                                                                                                            | 23-Apr-20 |             |          |                           |           |                |                                  |
| SN:117032454                                                                                     | HRS                                                                                                                            | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                                  |
|                                                                                                  | ENC                                                                                                                            | 0         |             |          |                           |           |                |                                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                                               |                                                                                                                                |           |             |          |                           |           |                |                                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                             | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|----------------------------------------------------|----------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 75 - AIR                                       |                                                                                  |           |             |          |                           |           |                |                  |
| 75-30-20-212-801                                   | NO. 1 ENGINE - REPLACED WITH NEW OR EXAMINE AND REFURBISH - THE BOV TORQUE MOTOR |           |             |          |                           |           |                | Service ATA:75   |
| PN:PN                                              | MOS                                                                              | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                         | HRS                                                                              | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                    | ENC                                                                              | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                  |           |             |          |                           |           |                |                  |
| 75-30-20-212-801                                   | NO. 2 ENGINE - REPLACED WITH NEW OR EXAMINE AND REFURBISH - THE BOV TORQUE MOTOR |           |             |          |                           |           |                | Service ATA:75   |
| PN:PN                                              | MOS                                                                              | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                         | HRS                                                                              | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                    | ENC                                                                              | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                  |           |             |          |                           |           |                |                  |
| 750010                                             | NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR                                         |           |             |          |                           |           |                | Component ATA:75 |
| PN:PN                                              | MOS/MSC                                                                          | 06-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:UNKNOWN                                         | HRS                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
|                                                    | ENC                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: MM 75-00-00PROC. REF: MM 75-00-00       |                                                                                  |           |             |          |                           |           |                |                  |
| 750010                                             | NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR                                         |           |             |          |                           |           |                | Component ATA:75 |
| PN:PN                                              | MOS/MSC                                                                          | 05-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:UNKNOWN                                         | HRS                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
|                                                    | ENC                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: MM 75-00-00PROC. REF: MM 75-00-00       |                                                                                  |           |             |          |                           |           |                |                  |
| 753010                                             | NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY                                   |           |             |          |                           |           |                | Component ATA:75 |
| PN:3053367-01                                      | MOS/MSC                                                                          | 06-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:AHX0501012                                      | HRS                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
|                                                    | ENC                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01       |                                                                                  |           |             |          |                           |           |                |                  |
| 753010                                             | NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY                                   |           |             |          |                           |           |                | Component ATA:75 |
| PN:3053367-01                                      | MOS/MSC                                                                          | 05-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:AHX0501016                                      | HRS                                                                              | 0         |             | TSN 0    |                           |           |                |                  |
|                                                    | ENC                                                                              | 0         |             | TSN 0    |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                              | C/W       | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|----------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|-----------|----------|---------------------------|-----------|-------------|------------------|
| ATA 75 - AIR                                                               |                                                                   |           |           |          |                           |           |             |                  |
| PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01                               |                                                                   |           |           |          |                           |           |             |                  |
| 753020                                                                     | NO. 1 ENGINE - BOV TORQUE MOTOR                                   |           |           |          |                           |           |             | Component ATA:75 |
| PN:PN                                                                      | MOS/MSC                                                           | 06-Dec-19 | O/C       | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                               | 0         |           | TSN 0    |                           |           |             |                  |
|                                                                            | ENC                                                               | 0         |           | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |           |          |                           |           |             |                  |
| 753020                                                                     | NO. 2 ENGINE - BOV TORQUE MOTOR                                   |           |           |          |                           |           |             | Component ATA:75 |
| PN:PN                                                                      | MOS/MSC                                                           | 05-Dec-19 | O/C       | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                                                                 | HRS                                                               | 0         |           | TSN 0    |                           |           |             |                  |
|                                                                            | ENC                                                               | 0         |           | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                                   |           |           |          |                           |           |             |                  |
| 753030                                                                     | NO. 1 ENGINE - INTERCOMPRESSOR BLEED VALVE - VALVE SERVO          |           |           |          |                           |           |             | Component ATA:75 |
| PN:3075987-01                                                              | MOS/MSC                                                           | 06-Dec-19 | O/C       | TSN 0    |                           |           |             |                  |
| SN:TRAXY000333                                                             | HRS                                                               | 0         |           | TSN 0    |                           |           |             |                  |
|                                                                            | ENC                                                               | 0         |           | TSN 0    |                           |           |             |                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01     |                                                                   |           |           |          |                           |           |             |                  |
| 753030                                                                     | NO. 2 ENGINE - INTERCOMPRESSOR BLEED VALVE - VALVE SERVO          |           |           |          |                           |           |             | Component ATA:75 |
| PN:3075987-01                                                              | MOS/MSC                                                           | 05-Dec-19 | O/C       | TSN 0    |                           |           |             |                  |
| SN:TRAXY000329                                                             | HRS                                                               | 0         |           | TSN 0    |                           |           |             |                  |
|                                                                            | ENC                                                               | 0         |           | TSN 0    |                           |           |             |                  |
| PROC. REF: MM 75-30-01, MM 75-30-01PROC. REF: MM 75-30-01, MM 75-30-01     |                                                                   |           |           |          |                           |           |             |                  |
| ATA 76 - ENGINE CONTROLS                                                   |                                                                   |           |           |          |                           |           |             |                  |
| 76-11-03                                                                   | THROTTLE CONTROL QUADRANT ASSEMBLY                                |           |           |          |                           |           |             | Component ATA:76 |
| PN:6990010-11                                                              | MOS/MSC                                                           | 23-Apr-20 | O/C       | TSN 0    |                           |           |             |                  |
| SN:2031                                                                    | HRS                                                               | 0         |           | TSN 0    |                           |           |             |                  |
|                                                                            | AFL                                                               | 0         |           | TSN 0    |                           |           |             |                  |
| PROC. REF: AMM 76-11-01, AMM 76-11-01PROC. REF: AMM 76-11-01, AMM 76-11-01 |                                                                   |           |           |          |                           |           |             |                  |
| ATA 77 - ENGINE INDICATING                                                 |                                                                   |           |           |          |                           |           |             |                  |
| 77-20-02-750-801                                                           | NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM |           |           |          |                           |           |             | Service ATA:77   |
|                                                                            | MOS                                                               | 13-Mar-26 | 36 (+30d) |          | 13-Mar-29                 | 12-Apr-29 | 958 d (+30) |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                                                        | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 77 - ENGINE INDICATING                                             |                                                                                             |           |             |          |                           |           |                |                  |
|                                                                        | HRS                                                                                         | 1221:24   | 1600 (+100) |          | (2821:24)<br>2821:24      | 2921:24   | 1526 (+100)    |                  |
|                                                                        | ENC                                                                                         | 564       |             |          |                           |           |                |                  |
| PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02                           |                                                                                             |           |             |          |                           |           |                |                  |
| 77-20-02-750-801                                                       | NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM                           |           |             |          |                           |           |                | Service ATA:77   |
|                                                                        | MOS                                                                                         | 13-Mar-26 | 36 (+30d)   |          | 13-Mar-29                 | 12-Apr-29 | 958 d (+30)    |                  |
|                                                                        | HRS                                                                                         | 1221:24   | 1600 (+100) |          | (2821:24)<br>2821:24      | 2921:24   | 1526 (+100)    |                  |
|                                                                        | ENC                                                                                         | 564       |             |          |                           |           |                |                  |
| PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02                           |                                                                                             |           |             |          |                           |           |                |                  |
| 77-40-01-212-801                                                       | NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT |           |             |          |                           |           |                | Service ATA:77   |
| PN:3075878-02                                                          | MOS                                                                                         | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:19072046                                                            | HRS                                                                                         | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                                                         | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                             |           |             |          |                           |           |                |                  |
| 77-40-01-212-801                                                       | NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT |           |             |          |                           |           |                | Service ATA:77   |
| PN:3075878-02                                                          | MOS                                                                                         | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:19072745                                                            | HRS                                                                                         | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                        | ENC                                                                                         | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                                                                             |           |             |          |                           |           |                |                  |
| 774001                                                                 | NO. 1 ENGINE - DATA COLLECTION UNIT                                                         |           |             |          |                           |           |                | Component ATA:77 |
| PN:3075878-02                                                          | MOS/MSC                                                                                     | 06-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:19072046                                                            | HRS                                                                                         | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                        | ENC                                                                                         | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: MM 77-40-01, MM 77-40-01PROC. REF: MM 77-40-01, MM 77-40-01 |                                                                                             |           |             |          |                           |           |                |                  |
| 774001                                                                 | NO. 2 ENGINE - DATA COLLECTION UNIT                                                         |           |             |          |                           |           |                | Component ATA:77 |
| PN:3075878-02                                                          | MOS/MSC                                                                                     | 05-Dec-19 | O/C         | TSN 0    |                           |           |                |                  |
| SN:19072745                                                            | HRS                                                                                         | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                        | ENC                                                                                         | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: MM 77-40-01, MM 77-40-01PROC. REF: MM 77-40-01, MM 77-40-01 |                                                                                             |           |             |          |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                                                                      | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|----------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 77 - ENGINE INDICATING                         |                                                                                           |           |             |          |                           |           |                |                |
| ATA 79 - OIL                                       |                                                                                           |           |             |          |                           |           |                |                |
| 79-10-02-212-801                                   | NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)                  |           |             |          |                           |           |                | Service ATA:79 |
| PN:3052640-04                                      | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
| SN:0025503117                                      | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                           |           |             |          |                           |           |                |                |
| 79-10-02-212-801                                   | NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)                  |           |             |          |                           |           |                | Service ATA:79 |
| PN:3052640-04                                      | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
| SN:0025343038                                      | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                           |           |             |          |                           |           |                |                |
| 79-20-00-212-801                                   | NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                           |           |                | Service ATA:79 |
| PN:PN                                              | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
| SN:UNKNOWN                                         | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                           |           |             |          |                           |           |                |                |
| 79-20-00-212-801                                   | NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH |           |             |          |                           |           |                | Service ATA:79 |
| PN:PN                                              | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
| SN:UNKNOWN                                         | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                                                           |           |             |          |                           |           |                |                |
| 79-20-01-210-801                                   | NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER                                           |           |             |          |                           |           |                | Service ATA:79 |
|                                                    | MOS                                                                                       | 23-Apr-20 |             |          |                           |           |                |                |
|                                                    | HRS                                                                                       | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC                                                                                       | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 79-20-01PROC. REF: MM 79-20-01       |                                                                                           |           |             |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                            | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|------------------------------------------------------------------------|-------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 79 - OIL                                                           |                                                 |           |             |          |                           |           |                |                |
| 79-20-01-210-801                                                       | NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER |           |             |          |                           |           |                | Service ATA:79 |
|                                                                        | MOS                                             | 23-Apr-20 |             |          |                           |           |                |                |
|                                                                        | HRS                                             | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                                        | ENC                                             | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 79-20-01PROC. REF: MM 79-20-01                           |                                                 |           |             |          |                           |           |                |                |
| 79-20-01-960-801                                                       | NO. 1 ENGINE - DISCARD THE OIL FILTER           |           |             |          |                           |           |                | Service ATA:79 |
| PN:3052590-01                                                          | MOS                                             | 19-Mar-24 |             |          |                           |           |                | DISCARD        |
| SN:N/A                                                                 | HRS                                             | 781:30    | 800 (+10%)  |          | (1581:30)<br>1581:30      | 1661:30   | 286:06 (+80)   |                |
|                                                                        | ENC                                             | 364       |             |          |                           |           |                |                |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01 |                                                 |           |             |          |                           |           |                |                |
| 79-20-01-960-801                                                       | NO. 2 ENGINE - DISCARD THE OIL FILTER           |           |             |          |                           |           |                | Service ATA:79 |
| PN:3052590-01                                                          | MOS                                             | 19-Mar-24 |             |          |                           |           |                | DISCARD        |
| SN:N/A                                                                 | HRS                                             | 781:30    | 800 (+10%)  |          | (1581:30)<br>1581:30      | 1661:30   | 286:06 (+80)   |                |
|                                                                        | ENC                                             | 364       |             |          |                           |           |                |                |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01 |                                                 |           |             |          |                           |           |                |                |
| 79-30-01-210-801                                                       | NO. 1 ENGINE - EXAMINE - CHIP DETECTOR          |           |             |          |                           |           |                | Service ATA:79 |
| PN:PN                                                                  | MOS                                             | 23-Apr-20 |             |          |                           |           |                |                |
| SN:UNKNOWN                                                             | HRS                                             | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                                        | ENC                                             | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01                           |                                                 |           |             |          |                           |           |                |                |
| 79-30-01-210-801                                                       | NO. 2 ENGINE - EXAMINE - CHIP DETECTOR          |           |             |          |                           |           |                | Service ATA:79 |
| PN:PN                                                                  | MOS                                             | 23-Apr-20 |             |          |                           |           |                |                |
| SN:UNKNOWN                                                             | HRS                                             | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                                        | ENC                                             | 0         |             |          |                           |           |                |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01                           |                                                 |           |             |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit         | C/W                                                                                | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition    |
|----------------------------------------------------|--------------|------------------------------------------------------------------------------------|-------------|----------|---------------------------|-----------|----------------|----------------|
| ATA 79 - OIL                                       |              |                                                                                    |             |          |                           |           |                |                |
| 79-30-01-770-801                                   | <sup>S</sup> | NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR                              |             |          |                           |           |                | Service ATA:79 |
|                                                    | MOS          | 13-Mar-26                                                                          | 12 (+30d)   |          |                           |           |                |                |
|                                                    | HRS          | 1221:24                                                                            | 800 (+10%)  |          |                           |           |                |                |
|                                                    | ENC          | 564                                                                                |             |          |                           |           |                |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01       |              |                                                                                    |             |          |                           |           |                | PKG:1          |
| 79-30-01-770-801                                   | <sup>S</sup> | NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR                              |             |          |                           |           |                | Service ATA:79 |
|                                                    | MOS          | 13-Mar-26                                                                          | 12 (+30d)   |          |                           |           |                |                |
|                                                    | HRS          | 1221:24                                                                            | 800 (+10%)  |          |                           |           |                |                |
|                                                    | ENC          | 564                                                                                |             |          |                           |           |                |                |
| PROC. REF: MM 79-30-01PROC. REF: MM 79-30-01       |              |                                                                                    |             |          |                           |           |                | PKG:1          |
| 79-30-02-210-801                                   | <sup>S</sup> | NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH |             |          |                           |           |                | Service ATA:79 |
|                                                    | MOS          | 13-Mar-26                                                                          | 12 (+30d)   |          |                           |           |                |                |
|                                                    | HRS          | 1221:24                                                                            | 800 (+10%)  |          |                           |           |                |                |
|                                                    | ENC          | 564                                                                                |             |          |                           |           |                |                |
| PROC. REF: MM 79-30-02PROC. REF: MM 79-30-02       |              |                                                                                    |             |          |                           |           |                | PKG:1          |
| 79-30-02-210-801                                   | <sup>S</sup> | NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH |             |          |                           |           |                | Service ATA:79 |
|                                                    | MOS          | 13-Mar-26                                                                          | 12 (+30d)   |          |                           |           |                |                |
|                                                    | HRS          | 1221:24                                                                            | 800 (+10%)  |          |                           |           |                |                |
|                                                    | ENC          | 564                                                                                |             |          |                           |           |                |                |
| PROC. REF: MM 79-30-02PROC. REF: MM 79-30-02       |              |                                                                                    |             |          |                           |           |                | PKG:1          |
| 79-30-03-212-801                                   |              | NO. 1 ENGINE - OVERHAUL OR REFURBISH - OIL TANK FILLER CAP                         |             |          |                           |           |                | Service ATA:79 |
| PN:PN                                              | MOS          | 23-Apr-20                                                                          |             |          |                           |           |                |                |
| SN:UNKNOWN                                         | HRS          | 0                                                                                  | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                |
|                                                    | ENC          | 0                                                                                  |             |          |                           |           |                |                |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |              |                                                                                    |             |          |                           |           |                |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                    | Unit                                                       | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition      |
|----------------------------------------------------------------------------|------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------|------------------|
| ATA 79 - OIL                                                               |                                                            |           |             |          |                           |           |                |                  |
| 79-30-03-212-801                                                           | NO. 2 ENGINE - OVERHAUL OR REFURBISH - OIL TANK FILLER CAP |           |             |          |                           |           |                | Service ATA:79   |
| PN:PN                                                                      | MOS                                                        | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                            | ENC                                                        | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |             |          |                           |           |                |                  |
| 79-30-20-212-801                                                           | NO. 1 ENGINE - INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS) |           |             |          |                           |           |                | Service ATA:79   |
| PN:PN                                                                      | MOS                                                        | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                            | ENC                                                        | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |             |          |                           |           |                |                  |
| 79-30-20-212-801                                                           | NO. 2 ENGINE - INSPECT - OIL LEVEL INDICATOR (SIGHT GLASS) |           |             |          |                           |           |                | Service ATA:79   |
| PN:PN                                                                      | MOS                                                        | 23-Apr-20 |             |          |                           |           |                |                  |
| SN:UNKNOWN                                                                 | HRS                                                        | 0         | 5000 (+100) |          | (5000)<br>5000            | 5100      | 3704:36 (+100) |                  |
|                                                                            | ENC                                                        | 0         |             |          |                           |           |                |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                         |                                                            |           |             |          |                           |           |                |                  |
| 79-31-05                                                                   | LEFT ENGINE MAIN OIL PRESSURE SENSOR                       |           |             |          |                           |           |                | Component ATA:79 |
| PN:APTE-478A-1000-270D                                                     | MOS/MSC                                                    | 23-Apr-20 | O/C         | TSN 0    |                           |           |                |                  |
| SN:01144                                                                   | HRS                                                        | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                        | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 79-31-05, AMM 79-31-05PROC. REF: AMM 79-31-05, AMM 79-31-05 |                                                            |           |             |          |                           |           |                |                  |
| 79-31-05                                                                   | RIGHT ENGINE MAIN OIL PRESSURE SENSOR                      |           |             |          |                           |           |                | Component ATA:79 |
| PN:APTE-478A-1000-270D                                                     | MOS/MSC                                                    | 23-Apr-20 | O/C         | TSN 0    |                           |           |                |                  |
| SN:01145                                                                   | HRS                                                        | 0         |             | TSN 0    |                           |           |                |                  |
|                                                                            | AFL                                                        | 0         |             | TSN 0    |                           |           |                |                  |
| PROC. REF: AMM 79-31-05, AMM 79-31-05PROC. REF: AMM 79-31-05, AMM 79-31-05 |                                                            |           |             |          |                           |           |                |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL                                                           |                                   |           |          |          |                           |           |           |                  |
| 790000                                                                 | NO. 1 ENGINE - OIL FILTER         |           |          |          |                           |           |           | Component ATA:79 |
| PN:3052590-01                                                          | MOS/MSC                           | 19-Mar-24 | O/C      | TSN 29   |                           |           |           |                  |
| SN:N/A                                                                 | HRS                               | 781:30    |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                               | 364       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01 |                                   |           |          |          |                           |           |           |                  |
| 790000                                                                 | NO. 2 ENGINE - OIL FILTER         |           |          |          |                           |           |           | Component ATA:79 |
| PN:3052590-01                                                          | MOS/MSC                           | 19-Mar-24 | O/C      | TSN 41   |                           |           |           |                  |
| SN:N/A                                                                 | HRS                               | 781:30    |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                               | 364       |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 79-20-01, MM 79-20-01PROC. REF: MM 79-20-01, MM 79-20-01 |                                   |           |          |          |                           |           |           |                  |
| 790020                                                                 | NO. 1 ENGINE - CHANGE OIL         |           |          |          |                           |           |           | Service ATA:79   |
|                                                                        | MOS/MSC                           | 19-Mar-20 | A/R      |          |                           |           |           |                  |
|                                                                        | HRS                               | 4:54      |          |          |                           |           |           |                  |
|                                                                        | ENC                               | 3         |          |          |                           |           |           |                  |
| PROC. REF: MM 72-00-00, MM 72-00-00PROC. REF: MM 72-00-00, MM 72-00-00 |                                   |           |          |          |                           |           |           |                  |
| 790020                                                                 | NO. 2 ENGINE - CHANGE OIL         |           |          |          |                           |           |           | Service ATA:79   |
|                                                                        | MOS/MSC                           | 19-Mar-20 | A/R      |          |                           |           |           |                  |
|                                                                        | HRS                               | 4:54      |          |          |                           |           |           |                  |
|                                                                        | ENC                               | 3         |          |          |                           |           |           |                  |
| PROC. REF: MM 72-00-00, MM 72-00-00PROC. REF: MM 72-00-00, MM 72-00-00 |                                   |           |          |          |                           |           |           |                  |
| 792010                                                                 | NO. 1 ENGINE - TEMPERATURE SENSOR |           |          |          |                           |           |           | Component ATA:79 |
| PN:ATS-9-800                                                           | MOS/MSC                           | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:061219-6                                                            | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                   |           |          |          |                           |           |           |                  |
| 792010                                                                 | NO. 2 ENGINE - TEMPERATURE SENSOR |           |          |          |                           |           |           | Component ATA:79 |
| PN:ATS-9-800                                                           | MOS/MSC                           | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:061219-4                                                            | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF                     |                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                                                | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------------------------------------|------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL                                                           |                                                      |           |          |          |                           |           |           |                  |
| 793001                                                                 | NO. 1 ENGINE - CHIP DETECTOR                         |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                                                  | MOS/MSC                                              | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 79-30-01, MM 79-30-01PROC. REF: MM 79-30-01, MM 79-30-01 |                                                      |           |          |          |                           |           |           |                  |
| 793001                                                                 | NO. 2 ENGINE - CHIP DETECTOR                         |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                                                  | MOS/MSC                                              | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 79-30-01, MM 79-30-01PROC. REF: MM 79-30-01, MM 79-30-01 |                                                      |           |          |          |                           |           |           |                  |
| 793003                                                                 | NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER               |           |          |          |                           |           |           | Component ATA:79 |
| PN:3052640-04                                                          | MOS/MSC                                              | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0025503117                                                          | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-10-02, MM 73-10-02PROC. REF: MM 73-10-02, MM 73-10-02 |                                                      |           |          |          |                           |           |           |                  |
| 793003                                                                 | NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER               |           |          |          |                           |           |           | Component ATA:79 |
| PN:3052640-04                                                          | MOS/MSC                                              | 30-Jan-20 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0025343038                                                          | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 73-10-02, MM 73-10-02PROC. REF: MM 73-10-02, MM 73-10-02 |                                                      |           |          |          |                           |           |           |                  |
| 793004                                                                 | NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                                                  | MOS/MSC                                              | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 79-30-02, MM 79-30-02PROC. REF: MM 79-30-02, MM 79-30-02 |                                                      |           |          |          |                           |           |           |                  |
| 793004                                                                 | NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                                                  | MOS/MSC                                              | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                             | HRS                                                  | 0         |          | TSN 0    |                           |           |           |                  |
|                                                                        | ENC                                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 79-30-02, MM 79-30-02PROC. REF: MM 79-30-02, MM 79-30-02 |                                                      |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: PHENOM 300 Serial: 50500559 RegNo: N303TG HRS: 1295:24 AFL: 598 As Of: 01-Jun-2026

29-Jul-2026 04:58 PM

| PN & SN                                            | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL                                       |                                                  |           |          |          |                           |           |           |                  |
| 793020                                             | NO. 1 ENGINE - OIL TANK FILLER CAP               |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 793020                                             | NO. 2 ENGINE - OIL TANK FILLER CAP               |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 793025                                             | NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 06-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 793025                                             | NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                                              | MOS/MSC                                          | 05-Dec-19 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                         | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                                    | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task