



DueList Report

FALCON 900

S/N 157 N328JL

OWNER: LAMON AVIATION, LLC
ADDRESS: 132 LEE DUGGAN DR. STE 3
TX 77498

OFFICE:
FAX:

OPERATOR: LAMON AVIATION, LLC
ADDRESS: 132 LEE DUGGAN DR. STE 3
TX 77498

OFFICE:
FAX:

OPERATOR: JET LINK AVIATION, LLC
ADDRESS: 132 LEE DUGAN DR
SUGAR LAND TX

OFFICE:
FAX:

CAMO: JET LINK AVIATION, LLC
ADDRESS: 132 LEE DUGAN DR
SUGAR LAND TX

OFFICE:
FAX:

ANALYST: CHRISTIAN HELLOFS
EMAIL: CHELLOFS@CAMPSYSTEMS.COM

+1-912-298-1324 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PROJECTED: 6 MOS. to 02/05/2027

AIRCRAFT	SERIAL/REGNO: 157/N328JL	MODEL: FALCON 900	MANUFACTURER: DASSAULT AVIATION S.A.
CERTIFICATION DATE: 02-FEB-1996		LAST ACTUALS: 8563.6 A/C HRS as of 24-JUL-2026 5071 AFL as of 24-JUL-2026 6488.4 APH as of 24-JUL-2026	PROJECTED: 8684.58 5131 6609
APU	SERIAL/PART: P-276/3800188-2	MODEL: GTCP36-150(F)	MANUFACTURER: HONEYWELL
INSTALLED ON: 07-OCT-2024 6368.8 APU HRS 8507.6 A/C HRS APUS		LAST ACTUALS: 6488.4 APU HRS as of 24-JUL-2026 APUS as of 03-MAR-2025	PROJECTED: 6609.38 0
ENGINE NO. 1	SERIAL/PART: P-101280/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 01-JUN-2017 6449.4 ENG. HRS 6742.8 A/C HRS 3739 ENC		LAST ACTUALS: 8274.1 ENG. HRS as of 24-JUL-2026 4932 ENC as of 24-JUL-2026	PROJECTED: 8395.08 5034
ENGINE NO. 2	SERIAL/PART: P-101279/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 11-MAR-2020 7418 ENG. HRS 7541.7 A/C HRS 4343 ENC		LAST ACTUALS: 8439.9 ENG. HRS as of 24-JUL-2026 5023 ENC as of 24-JUL-2026	PROJECTED: 8560.88 5125
ENGINE NO. 3	SERIAL/PART: P-101282/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 17-NOV-2017 6727.4 ENG. HRS 6923.9 A/C HRS 3810 ENC		LAST ACTUALS: 8367.1 ENG. HRS as of 24-JUL-2026 4889 ENC as of 24-JUL-2026	PROJECTED: 8488.08 4991



New Requirement/Flagged Items

Operator Review and Action Required

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8563.6 AFL: 5071 As Of: 24-Jul-2026 Operator: LAMON AVIATION, LLC

Report Date: 05-Aug-2026

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
FAA 2026-13-02 PARA (H)		AIRPLANE FLIGHT MANUAL (AFM) REVISION				AD	ATA:31
	01-Jul-26	MOS	T:BF/F	01-Jul-26			MANDATORY
		HRS					
		AFL					
NEW REQUIREMENT ADDED ON 02-JUL-26. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: AD		

Name: _____ Signature: _____ Cert.# _____ Date: _____

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8563.6 AFL: 5071 As Of: 24-Jul-2026 Operator: LAMON AVIATION, LLC

Report Date: 05-Aug-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
253A05 ^U		EQUIPMENT AUDIT (TPED'S) (ST11071SC) (DOC# L60-CA001)						Service ATA:25
	MOS	12		07-Oct-24	07-Oct-25		OVD	
	HRS			8507.6				
	AFL			5038				
REF:								
FAA 2025-26-06		APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT						AD ATA:35
	DAYS	T:30		EFF	13-Feb-26 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY REF: AD								
FAA 2026-03-09 PARA (G) EASA (1)		REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD						AD ATA:35
	DAYS	T:14		EFF	26-Mar-26 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY REF: AD								
32-44-00-250-801-03		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC)						Service ATA:32
PN:C20180120-2	MOS			30-Sep-21				16-Sep-2026
SN:F1106	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	14 (+12)	
REF: AMM 32-44-00-250-801								
32-44-00-250-801-04		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R540GC)						Service ATA:32
PN:C20180400	MOS			30-Sep-21				16-Sep-2026
SN:02606	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	14 (+12)	
REF: AMM 32-44-00-250-801								
28-30-00-680-803-01		DRAINING OF THE GRAVITY DEFUELING LINE						Service ATA:28
	MOS	2 (+5d)		24-Jul-26	24-Sep-26	29-Sep-26	50 d (+5)	24-Sep-2026(3)
	HRS			8563.6				
	AFL			5071				
REF: AMM 28-30-00-680-803								
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service ATA:28
	MOS	2 (+5d)		24-Jul-26	24-Sep-26	29-Sep-26	50 d (+5)	24-Sep-2026(3)
	HRS			8563.6				
	AFL			5071				
REF: AMM 28-30-00-680-804								
WO#: NOV 2022								
WO#: NOV 2022								

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8563.6 AFL: 5071 As Of: 24-Jul-2026 Operator: LAMON AVIATION, LLC

Report Date: 05-Aug-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-44-00-780-801-01		PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES						Service ATA:32
	MOS	2 (+5d)		24-Jul-26	24-Sep-26	29-Sep-26	50 d (+5)	24-Sep-2026(3)
	HRS			8563.6				
	AFL			5071				
REF: AMM 32-44-00-780-801								WO#: NOV 2022
499110		APU - SOAP CHECK OIL						Service ATA:49
	MOS			24-Jul-26				19-Oct-2026(2)
	HRS	50		6488.4	6538.4		50	
	APUS							
REF: SIL SIL APU-49								
760130		NO. 1 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			24-Jul-26				02-Nov-2026(2)
	HRS			8274.1				
	ENC	50		4932	(4982)5121		50	
REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								WO#: NOV 2022
760130		NO. 2 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			24-Jul-26				02-Nov-2026(2)
	HRS			8439.9				
	ENC	50		5023	(5073)5121		50	
REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								WO#: NOV 2022
760130		NO. 3 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			24-Jul-26				02-Nov-2026(2)
	HRS			8367.1				
	ENC	50		4889	(4939)5121		50	
REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								WO#: NOV 2022
32-44-00-250-801-05		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L565GC)						Service ATA:32
PN:C20182100	MOS			03-Aug-21				16-Dec-2026
SN:01018	HRS			7893.7				
	AFL	500 (+3%)		4615	5115	5130	44 (+15)	
REF: AMM 32-44-00-250-801								
32-44-00-250-801-06		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R565GC)						Service ATA:32
PN:C20182100	MOS			03-Aug-21				16-Dec-2026
SN:01179	HRS			7893.7				
	AFL	500 (+3%)		4615	5115	5130	44 (+15)	
REF: AMM 32-44-00-250-801								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8563.6 AFL: 5071 As Of: 24-Jul-2026 Operator: LAMON AVIATION, LLC

Report Date: 05-Aug-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
057110		NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			07-Oct-24				24-Dec-2026
	HRS	150 (+100)		8218.1	(8368.1)8657.6	8468.1	94 (+100)	
	ENC			4899				
		REF: LMM 72-00-00						
057110		NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			07-Oct-24				24-Dec-2026
	HRS	150 (+100)		8383.9	(8533.9)8657.6	8633.9	94 (+100)	
	ENC			4990				
		REF: LMM 72-00-00						
057110		NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			07-Oct-24				24-Dec-2026
	HRS	150 (+100)		8311.1	(8461.1)8657.6	8561.1	94 (+100)	
	ENC			4856				
		REF: LMM 72-00-00						
24-32-01-700-801-01		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (L1PE)						Service ATA:24
PN:4076-10	MOS	6 (+10%)		24-Jul-26	24-Jan-27	11-Feb-27	172 d (+18)	24-Jan-2027
SN:088398	HRS	250 (+25)		8563.6	8813.6	8838.6	250 (+25)	
	AFL			5071				
		REF: AMM 24-32-01-700-801						
24-32-01-700-801-02		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (R1PE)						Service ATA:24
PN:4076-10	MOS	6 (+10%)		24-Jul-26	24-Jan-27	11-Feb-27	172 d (+18)	24-Jan-2027
SN:121547	HRS	250 (+25)		8563.6	8813.6	8838.6	250 (+25)	
	AFL			5071				
		REF: AMM 24-32-01-700-801						
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION						Service ATA:38
	MOS	6 (+1m)		24-Jul-26	24-Jan-27	24-Feb-27	172 d (+31)	24-Jan-2027
	HRS			8563.6				
	AFL			5071				
		REF: AMM 38-10-00-670-801						