



Status Report

PHENOM 100

S/N 50000121 N130EC

OWNER: STE AVIATION, LLC
ADDRESS: 8810 APPALOOSA LANE
LINCOLN NE 68520

OFFICE:
FAX:

OPERATOR: STE AVIATION, LLC
ADDRESS: 8810 APPALOOSA LANE
LINCOLN NE 68520

OFFICE:
FAX:

OPERATOR: QIS AVIATION GROUP, LLC
ADDRESS: 711 COSMOPOLITAN DR NE UNIT
237
ATLANTA GA 30324

OFFICE:
FAX:

ANALYST: BRYAN STIKA
EMAIL: BSTIKA@CAMPSYSTEMS.COM

+1-316-462-2408 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 50000121/N130EC	MODEL: PHENOM 100	MANUFACTURER: EMBRAER
CERTIFICATION DATE: 23-MAR-2010		LAST ACTUALS: 2599.7 A/C HRS as of 03-AUG-2026 1870 AFL as of 03-AUG-2026	
ENGINE NO. 1	SERIAL/PART: PCE-LC0291/35C3100-01	MODEL: PW617F-E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 05-FEB-2010		LAST ACTUALS:	
0	ENG. HRS 0 A/C HRS	2599.7	ENG. HRS as of 03-AUG-2026
0	ENC	1870	ENC as of 03-AUG-2026
ENGINE NO. 2	SERIAL/PART: PCE-LC0292/35C3100-01	MODEL: PW617F-E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 05-FEB-2010		LAST ACTUALS:	
0	ENG. HRS 0 A/C HRS	2599.7	ENG. HRS as of 03-AUG-2026
0	ENC	1870	ENC as of 03-AUG-2026



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM50-160520	REVIEW EMBRAER PHENOM 100 AMM 2432 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 42 DATED MAY 20/16							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-160520PROC. REF: RCF EM50-160520								
EM50-160822	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMTIS/MAINTENANCE CHECKS (TLMC) CHAPTER -5, REVISION 43 DATED 22 AUGUST 2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-160822PROC. REF: RCF EM50-160822								
EM50-161022	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161022PROC. REF: RCF EM50-161022								
EM50-161122	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 46 DATED NOV 22/2016							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161122PROC. REF: RCF EM50-161122								
EM50-161202	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECK (CHAPTER-5) ADVANCE REVISION DATED DEC 02/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161202PROC. REF: RCF EM50-161202								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM50-161216	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/ MAINTENANCE CHECKS/CHAPTER-5 REVISION 47 DATED DEC 16/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM50-161216PROC. REF: RCF EM50-161216								
EM50-200626	REVIEW EMBRAER PHENOM 100 - AMM 2432, SMR REV. 03, DATED JUNE 26TH, 2020							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-210507-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM FOR PHENOM 100, DATED MAY 07, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-211103-SMR	REVIEW EMBRAER PHENOM 100 - AMM 2432, SMR REV. 04, DATED NOV 3, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-220812-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-500 - PHENOM 100							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM50-221017-AWL REVIEW EMB-500 - PHENOM 100 AIRWORTHINESS LIMITATIONS REV 01 DATED OCT 17, 2022								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-221103-SMR REVIEW EMB-500 - PHENOM 100 SCHEDULED MAINTENANCE REQUIREMENTS REV 05, DATED NOV 03, 2022								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-230103-CAMP ADJUSTMENT REVIEW EMB-500 - PHENOM 100 - AUDIT OF ITEM CODES 30-11-04 AND 30-11-04-001, DATED JAN 03, 2023								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-230112-CAMP ADJUSTMENT REVIEW CAMP ADJUSTMENT FOR EMB-500 - PHENOM 100 - AUDIT OF TASK CODE 32-43-11-002								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00PROC. REF: RCF 00								
EM50-230124-CAMP ADJUSTMENT REVIEW CAMP ADJUSTMENT FORM FOR EMB-500 - PHENOM 100 - AUDIT OF PN TASK 35-31-01								Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-01	800 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)		2716.8	2746.8	117.1 (+30)	
	AFL	1354						
PROC. REF: SMR 05-30-01PROC. REF: SMR 05-30-01								PKG:1
05-30-10	1600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	04-Jun-25						
	HRS	2224.4	1600 (+30/-30)		3824.4	3854.4	1224.7 (+30)	
	AFL	1614						
PROC. REF: SMR 05-30-10PROC. REF: SMR 05-30-10								PKG:10
05-30-20	2400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)	Adj -60.4	4800	4830	2200.3 (+30)	
	AFL	1778						
PROC. REF: SMR 05-30-20PROC. REF: SMR 05-30-20								PKG:20
05-30-40	3200 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)		3805.2	3835.2	1205.5 (+30)	
	AFL	428						
PROC. REF: SMR 05-30-40PROC. REF: SMR 05-30-40								PKG:40
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	04-Jun-25	60 (+1m/-1m)		04-Jun-30	04-Jul-30	1399 d (+30)	
	HRS	2224.4	3200 (+30/-30)		5424.4	5454.4	2824.7 (+30)	
	AFL	1614						
PROC. REF: SMR 05-30-42PROC. REF: SMR 05-30-42								PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-50	5600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)		5600	5630	3000.3 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-50PROC. REF: SMR 05-30-50								PKG:50
05-30-60	6400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	EFF						
	HRS	EFF	6400 (+30/-30)		6400 *	6430	3800.3 (+30)	
	AFL							
PROC. REF: SMR 05-30-60PROC. REF: SMR 05-30-60								PKG:60
05-30-80	12 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
	HRS	2523.1						
	AFL	1823						
PROC. REF: SMR 05-30-80PROC. REF: SMR 05-30-80								PKG:80
05-30-81	24 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	18-May-26	24 (+1m/-1m)	Adj -23d	25-Apr-28	25-May-28	629 d (+30)	
	HRS	2523.1						
	AFL	1823						
PROC. REF: SMR 05-30-81PROC. REF: SMR 05-30-81								PKG:81
05-30-82	36 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	04-Jun-25	36 (+1m/-1m)		04-Jun-28	04-Jul-28	669 d (+30)	
	HRS	2224.4						
	AFL	1614						
PROC. REF: SMR 05-30-82PROC. REF: SMR 05-30-82								PKG:82

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-83	48 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	18-May-26	48 (+1m/-1m)	Adj -44d	04-Apr-30	04-May-30	1338 d (+30)	
	HRS	2523.1						
	AFL	1823						
PROC. REF: SMR 05-30-83PROC. REF: SMR 05-30-83								PKG:83
05-30-84	60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	04-Jun-25	60 (+1m/-1m)		04-Jun-30	04-Jul-30	1399 d (+30)	
	HRS	2224.4						
	AFL	1614						
PROC. REF: SMR 05-30-84PROC. REF: SMR 05-30-84								PKG:84
05-30-87	120 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	05-May-20	120 (+1m/-1m)		05-May-30	05-Jun-30	1369 d (+31)	
	HRS	1467.9						
	AFL	1046						
PROC. REF: SMR 05-30-87PROC. REF: SMR 05-30-87								PKG:87
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	04-Jun-25	60 (+1m/-1m)		04-Jun-30	04-Jul-30	1399 d (+30)	
	HRS	2224.4						
	AFL	1614						
PROC. REF: SMR 05-30-90PROC. REF: SMR 05-30-90								PKG:90
05-50-00-210-805	NO. 1 ENGINE - TROUBLESHOOT - FOREIGN OBJECT DAMAGE							Service ATA:05
	MOS/MSC	19-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-805	NO. 2 ENGINE - TROUBLESHOOT - FOREIGN OBJECT DAMAGE							Service ATA:05
	MOS/MSC	20-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00PROC. REF: MM 05-50-00								
051254	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	18-May-26	12 (+30d)		18-May-27	17-Jun-27	286 d (+30)	
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PKG:1								
PROC. REF: LMM 05-20-00PROC. REF: LMM 05-20-00								
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	18-May-26	12 (+30d)		18-May-27	17-Jun-27	286 d (+30)	
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PKG:1								
PROC. REF: LMM 05-20-00PROC. REF: LMM 05-20-00								
H242-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service ATA:05
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PKG:87								
PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00								
H340-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF PITCH TRIM ACTUATOR ELECTRICAL BONDING							Service ATA:05
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PKG:87								
PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
H430-001 ^S	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS							Service ATA:05
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00								PKG:84
H700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS							Service ATA:05
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00								PKG:84
H700-002 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS							Service ATA:05
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00								PKG:84
ATA 21 - AIR CONDITIONING								
21-00-00	ELECTROMECHANICAL LINEAR ACTUATOR							Component ATA:21
PN:100000-77	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:24902	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-01-01	PRESSURIZATION AND AIR CONDITIONING CONTROL PANEL							Component ATA:21
PN:441-40931-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0128	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-01-01, AMM 21-01-01PROC. REF: AMM 21-01-01, AMM 21-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-20-02-900-801-01		COCKPIT - CONDITIONED AIR DUCT					Component	ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02, AMM 21-20-02PROC. REF: AMM 21-20-02, AMM 21-20-02								
21-20-02-900-801-02		PAX CABIN - CONDITIONED AIR DUCT					Component	ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02, AMM 21-20-02PROC. REF: AMM 21-20-02, AMM 21-20-02								
21-20-02-900-801-03		AFT CABIN - CONDITIONED AIR DUCT					Component	ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02, AMM 21-20-02PROC. REF: AMM 21-20-02, AMM 21-20-02								
21-21-01		LEFT REAR FUS FLOW CONTROL SHUT OFF VALVE ASSEMBLY					Component	ATA:21
PN:1300230-35	MOS/MSC	15-Apr-26	O/C					
SN:688	HRS	2504.7						
	AFL	1812						
PROC. REF: AMM 21-21-01, AMM 21-21-01PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-21-01		RIGHT REAR FUS FLOW CONTROL SHUT OFF VALVE ASSEMBLY					Component	ATA:21
PN:1300230-45	MOS/MSC	15-Apr-26	O/C					
SN:00221	HRS	2504.7						
	AFL	1812						
PROC. REF: AMM 21-21-01, AMM 21-21-01PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-21-02		LH AFT INLET AIR CHECK VALVE					Component	ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-02, AMM 21-21-02PROC. REF: AMM 21-21-02, AMM 21-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-21-02		RH AFT INLET AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-02, AMM 21-21-02PROC. REF: AMM 21-21-02, AMM 21-21-02								
21-21-02-001 ^S		OPERATIONAL CHECK LH AFT INLET AIR CHECK VALVE						Service ATA:21
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02PROC. REF: AMM 21-21-02								
21-21-02-001 ^S		OPERATIONAL CHECK RH AFT INLET AIR CHECK VALVE						Service ATA:21
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02PROC. REF: AMM 21-21-02								
21-23-03		RAM AIR VALVE						Component ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-23-03-002 ^S		OPERATIONAL CHECK OF RAM AIR VALVE POSITION						Service ATA:21
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-03PROC. REF: AMM 21-23-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-23-03-003 ^S		OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION						Service ATA:21
PN:PN	MOS	04-May-23						
SN:UNKNOWN	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 21-23-03PROC. REF: AMM 21-23-03								PKG:1
21-23-04		LH AFT FUSELAGE RAM AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-04, AMM 21-23-04PROC. REF: AMM 21-23-04, AMM 21-23-04								
21-23-04		LH CENTER FUSELAGE RAM AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-04, AMM 21-23-04PROC. REF: AMM 21-23-04, AMM 21-23-04								
21-23-04		RH AFT FUSELAGE RAM AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-04, AMM 21-23-04PROC. REF: AMM 21-23-04, AMM 21-23-04								
21-23-04-001 ^S		OPERATIONAL CHECK LH AFT FUSELAGE RAM AIR CHECK VALVE						Service ATA:21
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-04PROC. REF: AMM 21-23-04								PKG:50
21-23-04-001 ^S		OPERATIONAL CHECK LH CENTER FUSELAGE RAM AIR CHECK VALVE						Service ATA:21
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
								PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-23-04PROC. REF: AMM 21-23-04								
21-23-04-001	S	OPERATIONAL CHECK RH AFT FUSELAGE RAM AIR CHECK VALVE						Service ATA:21
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	5600 (+30/-30)					
	AFL	0						
PKG:50								
PROC. REF: AMM 21-23-04PROC. REF: AMM 21-23-04								
21-23-05		TAIL CONE GROUND BLOWER (COOLING FAN) ASSEMBLY						Component ATA:21
PN:1133710-5	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:321	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-05, AMM 21-23-05PROC. REF: AMM 21-23-05, AMM 21-23-05								
21-23-05-001	S	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN						Service ATA:21
PN:1133710-5	MOS	04-Jun-25						
SN:321	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PKG:10								
PROC. REF: AMM 21-23-05PROC. REF: AMM 21-23-05								
21-31-00-002	S	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE						Service ATA:21
PN:103920-1	MOS	04-May-23						
SN:103920-00220	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PKG:1								
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00								
21-31-00-003	S	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)						Service ATA:21
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PKG:1								
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-00-004 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS						Service ATA:21
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00								PKG:50
21-31-00-005 ^S		OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL						Service ATA:21
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00								PKG:50
21-31-01		ELECTRONIC CONTROL AND MONITORING UNIT						Component ATA:21
PN:2119286-5	MOS/MSC	01-Nov-11	O/C	TSN 0				
SN:2119286-00630	HRS	232.9		TSN 0				
	AFL	146		TSN 0				
PROC. REF: AMM 21-31-01, AMM 21-31-01PROC. REF: AMM 21-31-01, AMM 21-31-01								
21-31-01-001		RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU)						Service ATA:21
PN:2119286-5	MOS	01-Nov-11						
SN:2119286-00630	HRS	232.9	5600 (+30/-30)		5832.9	5862.9	3233.2 (+30)	
	AFL	146						
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
21-31-02		AFT BULKHEAD OUTFLOW (OFV) VALVE						Component ATA:21
PN:103920-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:103920-00220	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02, AMM 21-31-02PROC. REF: AMM 21-31-02, AMM 21-31-02								
21-31-02-001		RESTORATION (REPAIR) OF OUTFLOW VALVE						Service ATA:21
PN:103920-1	MOS	23-Mar-10						
SN:103920-00220	HRS	0	7200 (+30/-30)		7200	7230	4600.3 (+30)	
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02								
21-31-03 NEGATIVE PRESSURE RELIEF VALVE								Component ATA:21
PN:130664-2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:34163-0217	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03, AMM 21-31-03PROC. REF: AMM 21-31-03, AMM 21-31-03								
21-31-03-001 ^S OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE								Service ATA:21
PN:130664-2	MOS	23-Mar-10						
SN:34163-0217	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03								PKG:50
21-31-04 AFT BULKHEAD PRESSURE RELIEF (PRV) VALVE								Component ATA:21
PN:103916-2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:103916-00016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04, AMM 21-31-04PROC. REF: AMM 21-31-04, AMM 21-31-04								
21-31-04-001 ^S FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE								Service ATA:21
PN:103916-2	MOS	23-Mar-10						
SN:103916-00016	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04								PKG:50
21-52-01-001 DETAILED VISUAL INSPECTION VCS COMPRESSOR DRIVE MODULE OF VCS COMPRESSOR MOTOR DRIVE								Service ATA:21
PN:1133630-14	MOS/MSC	22-Oct-25	O/C					
SN:497	HRS	2363						
	AFL	1713						
PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-01-002		DISCARD OF COMPRESSOR DRIVE MODULE BELT						Service ATA:21
PN:1133636-7	MOS	22-Oct-25						
SN:UNKNOWN	HRS	2363	2000 (+30/-30)		4363	4393	1763.3 (+30)	
	AFL	1713						
PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01								
21-52-01-003 ^S		FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION						Service ATA:21
PN:1133636-7	MOS	22-Oct-25						
SN:UNKNOWN	HRS	2363	800 (+30/-30)					
	AFL	1713						
PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01								
21-52-01-004		RESTORATION (OVERHAUL) VCS COMPRESSOR DRIVE MODULE						Service ATA:21
PN:1133630-14	MOS	22-Oct-25						
SN:497	HRS	2363	2000 (+30/-30)		4363	4393	1763.3 (+30)	
	AFL	1713						
PROC. REF: AMM 21-52-01PROC. REF: AMM 21-52-01								
21-52-02		HEAT EXCHANGER PACK						Component ATA:21
PN:1133750-3	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:262	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-02, AMM 21-52-02PROC. REF: AMM 21-52-02, AMM 21-52-02								
21-52-02-001 ^S		GENERAL VISUAL INSPECTION OF HEAT EXCHANGER PACK						Service ATA:21
PN:1133750-3	MOS	04-Jun-25						
SN:262	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 21-52-02PROC. REF: AMM 21-52-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-03-001	^S	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES						Service ATA:21
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 21-52-03PROC. REF: AMM 21-52-03								PKG:1
21-52-04		FWD FUS VCS SYSTEM FWD EVAPORATOR BLOWER						Component ATA:21
PN:1133850-104	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:115	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-04, AMM 21-52-04PROC. REF: AMM 21-52-04, AMM 21-52-04								
21-52-06-001	^S	SERVICING OF VCS REFRIGERANT FLUID						Service ATA:21
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 12-17-00PROC. REF: AMM 12-17-00								PKG:80
21-61-00-001	^S	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM						Service ATA:21
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 21-61-00PROC. REF: AMM 21-61-00								PKG:1
21-61-01		REAR FUS ECS TEMPERATURE CONTROLLER						Component ATA:21
PN:1300650-12	MOS/MSC	14-Jun-13	O/C					
SN:548	HRS	472.6						
	AFL	320						
PROC. REF: AMM 21-61-01, AMM 21-61-01PROC. REF: AMM 21-61-01, AMM 21-61-01								
21-61-03		COCKPIT DUCT TEMPERATURE SENSOR SWITCH						Component ATA:21
PN:1300450-10	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:911	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03	LH REAR DUCT TEMPERATURE SENSOR SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:871	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03	PAX DUCT TEMPERATURE SENSOR SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:876	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03	RH REAR DUCT TEMPERATURE SENSOR SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:881	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-06-001 ^S	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR							Service ATA:21
	MOS	23-Mar-10						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-61-06PROC. REF: AMM 21-61-06								
215201-0101	VCS COMPRESSOR DRIVE MODULE							Component ATA:21
PN:1133630-14	MOS/MSC	22-Oct-25	O/C	TSN 162, TSO 0				
SN:497	HRS	2363		TSO 0				
	AFL	1713		TSO 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01, AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01, AMM 21-52-01, AMM 21-52-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215201-0102	CDM COMPRESSOR MODULE							Component ATA:21
PN:1133130-10	MOS/MSC	22-Oct-25	O/C	TSN 0				
SN:716	HRS	2363		TSN 0				
	AFL	1713		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01								
215201-0201	COMPRESSOR DRIVE MODULE BELT							Component ATA:21
PN:1133636-7	MOS/MSC	22-Oct-25	H/T	TSN 0				
SN:UNKNOWN	HRS	2363		TSN 0				
	AFL	1713		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01PROC. REF: AMM 21-52-01, AMM 21-52-01								
216102-0101	LH AFT FUSELAGE TEMPERATURE MODULATING VALVE							Component ATA:21
PN:1300330-11	MOS/MSC	04-Dec-25	O/C					
SN:285	HRS	2405.1						
	AFL	1740						
PROC. REF: AMM 21-61-02, AMM 21-61-02PROC. REF: AMM 21-61-02, AMM 21-61-02								
216102-0102	RH AFT FUSELAGE TEMPERATURE MODULATING VALVE							Component ATA:21
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-02, AMM 21-61-02PROC. REF: AMM 21-61-02, AMM 21-61-02								
Z500-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:21
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-45-00PROC. REF: AMM 05-45-00								
Z500-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:21
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-45-00PROC. REF: AMM 05-45-00								

PKG:84

PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
ATA 22 - AUTO FLIGHT								
22-11-00-001	FUNCTIONAL CHECK OF AILERON SERVO							Service ATA:22
PN:011-01436-01	MOS	18-May-26	12 (+30d/-30d)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	AIRWORTHINESS
SN:22305495	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK OF ELEVATOR SERVO							Service ATA:22
PN:011-01436-01	MOS	18-May-26	12 (+30d/-30d)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	AIRWORTHINESS
SN:22305501	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK OF RUDDER SERVO							Service ATA:22
PN:011-01436-01	MOS	18-May-26	12 (+30d/-30d)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	AIRWORTHINESS
SN:22305508	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								
22-11-00-002 ^S	LUBRICATION OF SERVO ACTUATORS							Service ATA:22
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								PKG:80
22-11-00-003 ^S	DETAILED VISUAL INSPECTION OF AUTOPILOT SERVO CABLE							Service ATA:22
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 22-11-00PROC. REF: AMM 22-11-00								PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-01 GMC 715 GUIDANCE PANEL								Component ATA:22
PN:011-01430-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:15900309	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-01, AMM 22-11-01PROC. REF: AMM 22-11-01, AMM 22-11-01								
22-11-02 AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR								Component ATA:22
PN:011-00878-10	MOS/MSC	27-Apr-12	O/C					
SN:71307441	HRS	290.98						
	AFL	180						
PROC. REF: AMM 22-11-02, AMM 22-11-02PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-03 AILERON GSM 85A MED TORQUE SERVO MOUNT								Component ATA:22
PN:011-01436-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:22305495	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03PROC. REF: AMM 22-11-03, AMM 22-11-03								
22-11-05 ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR								Component ATA:22
PN:011-00878-10	MOS/MSC	27-Apr-12	O/C					
SN:71307447	HRS	290.98						
	AFL	180						
PROC. REF: AMM 22-11-05, AMM 22-11-05PROC. REF: AMM 22-11-05, AMM 22-11-05								
22-11-06 ELEVATOR GSM 85A MED TORQUE SERVO MOUNT								Component ATA:22
PN:011-01436-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:22305501	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-08 RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR								Component ATA:22
PN:011-00878-10	MOS/MSC	27-Apr-12	O/C					
SN:71307428	HRS	290.98						
	AFL	180						
PROC. REF: AMM 22-11-08, AMM 22-11-08PROC. REF: AMM 22-11-08, AMM 22-11-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-09	RUDDER GSM 85A MED TORQUE SERVO MOUNT							Component ATA:22
PN:011-01436-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:22305508	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-09, AMM 22-11-09PROC. REF: AMM 22-11-09, AMM 22-11-09								
ATA 23 - COMMUNICATIONS								
23-12-02	BOTTOM VHF ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:322-2169	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-12-02	TOP VHF ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:322-2181	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-15-03	IRIDIUM ANTENNA							Component ATA:23
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-03, AMM 23-15-03PROC. REF: AMM 23-15-03, AMM 23-15-03								
23-23-03	WIFI - DATALINK ANTENNA							Component ATA:23
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-23-03, AMM 23-23-03PROC. REF: AMM 23-23-03, AMM 23-23-03								
23-51-00-001 ^S	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE							Service ATA:23
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)					
	AFL	428						

PKG:40

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
PROC. REF: AMM 23-51-00PROC. REF: AMM 23-51-00								
23-51-01	COPILOT GMA 1347D AUDIO PANEL							Component ATA:23
PN:011-01257-20	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:17105973	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-01, AMM 23-51-01PROC. REF: AMM 23-51-01, AMM 23-51-01								
23-51-01	PILOT GMA 1347D AUDIO PANEL							Component ATA:23
PN:011-01257-20	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:17105893	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-01, AMM 23-51-01PROC. REF: AMM 23-51-01, AMM 23-51-01								
23-51-05	LH AUDIO JACK CONTROL PANEL							Component ATA:23
PN:441-40943-002	MOS/MSC	19-Dec-24	O/C	TSN 177				
SN:0255	HRS	2047.4		TSN 2047.4				
	AFL	1478		TSN 1478				
PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-51-05	RH AUDIO JACK CONTROL PANEL							Component ATA:23
PN:441-40943-002	MOS/MSC	19-Dec-24	O/C	TSN 177				
SN:0251	HRS	2047.4		TSN 2047.4				
	AFL	1478		TSN 1478				
PROC. REF: AMM 23-51-05, AMM 23-51-05PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-51-09	LH MODEL HME 25-KA-2 HEADSET							Component ATA:23
PN:025-250-015	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:003244	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23-51-09	RH MODEL HME 25-KA-2 HEADSET							Component ATA:23
PN:025-250-015	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:003237	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23-51-11 COCKPIT ELECTRODYNAMIC MICROPHONE								Component ATA:23
PN:85-03-12369-04	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:206965	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23-61-00-001 ^S FUNCTIONAL CHECK OF STATIC DISCHARGER								Service ATA:23
	MOS	18-May-26	48 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 23-61-00PROC. REF: AMM 23-61-00								PKG:83
ATA 24 - ELECTRICAL POWER								
24-00-07 RELAY ASSEMBLY								Component ATA:24
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-01-01 ELECTRICAL CONTROL PANEL								Component ATA:24
PN:441-40929-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0212	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-01-01, AMM 24-01-01PROC. REF: AMM 24-01-01, AMM 24-01-01								
24-31-01 NO.1 ENGINE STARTER-GENERATOR								Component ATA:24
PN:MG94F-2	MOS/MSC	04-May-23	O/C	TSO 1				
SN:0830	HRS	1916.8		TSO 0				
	AFL	1354		TSO 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01PROC. REF: AMM 24-31-01, AMM 24-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-01	NO.2 ENGINE STARTER-GENERATOR							Component ATA:24
PN:MG94F-2	MOS/MSC	04-May-23	O/C	TSO 2				
SN:0786	HRS	1916.8		TSO 0				
	AFL	1354		TSO 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01PROC. REF: AMM 24-31-01, AMM 24-31-01								
24-31-01-001	NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 500 ACFT WITH STARTER GENERATOR PN MG94F-2 OR PN 400SG180Q SERIES OR POST-MOD SB 500-24-0007							Service ATA:24
PN:MG94F-2	MOS	04-May-23						
SN:0830	HRS	1916.8	800 (+30/-30)		2716.8	2746.8	117.1 (+30)	
	AFL	1354						
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
24-31-01-001	NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 500 ACFT WITH STARTER GENERATOR PN MG94F-2 OR PN 400SG180Q SERIES OR POST-MOD SB 500-24-0007							Service ATA:24
PN:MG94F-2	MOS	04-May-23						
SN:0786	HRS	1916.8	800 (+30/-30)		2716.8	2746.8	117.1 (+30)	
	AFL	1354						
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
24-31-01-003	RESTORATION (OVERHAUL) OF NO.1 ENGINE STARTER-GENERATOR (P/N MG94F-1)							Service ATA:24
PN:MG94F-2	MOS/MSC		N/A					
SN:0830	HRS							
	AFL							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
24-31-01-003	RESTORATION (OVERHAUL) OF NO.2 ENGINE STARTER-GENERATOR (P/N MG94F-1)							Service ATA:24
PN:MG94F-2	MOS/MSC		N/A					
SN:0786	HRS							
	AFL							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
24-31-02	NO.1 GENERATOR - DC, 28V CONTROL UNIT							Component ATA:24
PN:CG301A-12	MOS/MSC	28-Oct-20	O/C	TSN 47				
SN:1379	HRS	1519		TSN 0				
	AFL	1087		TSN 0				
PROC. REF: AMM 24-31-02, AMM 24-31-02PROC. REF: AMM 24-31-02, AMM 24-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-02	NO.2 GENERATOR - DC, 28V CONTROL UNIT							Component ATA:24
PN:CG301A-12	MOS/MSC	17-Oct-20	O/C					
SN:808	HRS	1517.2		TSN 1250				
	AFL	1084		TSN 1750				
PROC. REF: AMM 24-31-02, AMM 24-31-02PROC. REF: AMM 24-31-02, AMM 24-31-02								
24-31-07-001 ^S	RESTORATION (CLEANING) OF LH SHUNT GENERATOR							Service ATA:24
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 24-31-07PROC. REF: AMM 24-31-07								PKG:84
24-31-07-001 ^S	RESTORATION (CLEANING) OF RH SHUNT GENERATOR							Service ATA:24
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 24-31-07PROC. REF: AMM 24-31-07								PKG:84
24-36-01	NO.1 MAIN BATTERY							Component ATA:24
PN:RG-390E	MOS/MSC	19-Dec-25	O/C					
SN:41491670	HRS	2431.4						
	AFL	1760						
PROC. REF: AMM 24-36-01, AMM 24-36-01, AMM 24-36-01PROC. REF: AMM 24-36-01, AMM 24-36-01, AMM 24-36-01								
24-36-01	NO.2 MAIN BATTERY							Component ATA:24
PN:RG-390E	MOS/MSC	19-Dec-25	O/C					
SN:41491673	HRS	2431.4						
	AFL	1760						
PROC. REF: AMM 24-36-01, AMM 24-36-01, AMM 24-36-01PROC. REF: AMM 24-36-01, AMM 24-36-01, AMM 24-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-01-003	DISCARD NO.1 MAIN BATTERY							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41491670	HRS							
	AFL							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01								
24-36-01-003	DISCARD NO.2 MAIN BATTERY							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41491673	HRS							
	AFL							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01								
24-36-01-004	FUNCTIONAL CHECK NO.1 MAIN BATTERY OF - (PRE-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41491670	HRS							
	AFL							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01								
24-36-01-004	FUNCTIONAL CHECK NO.2 MAIN BATTERY OF - (PRE-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41491673	HRS							
	AFL							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01								
24-36-01-005	FUNCTIONAL CHECK OF NO.1 MAIN BATTERY - (POST-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41491670	HRS							
	AFL							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01								
24-36-01-005	FUNCTIONAL CHECK OF NO.2 MAIN BATTERY - (POST-MOD SB 500-24-0014)							Service ATA:24
PN:RG-390E	MOS/MSC		N/A					
SN:41491673	HRS							
	AFL							
PROC. REF: AMM 24-36-01PROC. REF: AMM 24-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-02	BATTERY CURRENT (HB2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-36-02, AMM 24-36-02PROC. REF: AMM 24-36-02, AMM 24-36-02								
24-36-02-001 ^S	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)							Service ATA:24
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 24-36-02PROC. REF: AMM 24-36-02								
PKG:60								
24-36-STC-003 ^U	DISCARD NO.1 MAIN BATTERY (CONCORDE BATTERY)							Service ATA:24
	MOS	19-Dec-25	48		19-Dec-29		1232 d	
	HRS	2431.4						
	AFL	1760						
24-36-STC-003 ^U	DISCARD NO.2 MAIN BATTERY (CONCORDE BATTERY)							Service ATA:24
	MOS	19-Dec-25	48		19-Dec-29		1232 d	
	HRS	2431.4						
	AFL	1760						
24-36-STC-005 ^U	CAPACITY CHECK NO.1 MAIN BATTERY (CONCORDE BATTERY)							Service ATA:24
	MOS	19-Dec-25	T:12 (+1m/-1m)		19-Dec-26	19-Jan-27	136 d (+31)	
	HRS	2431.4						
	AFL	1760						
24-36-STC-005 ^U	CAPACITY CHECK NO.2 MAIN BATTERY (CONCORDE BATTERY)							Service ATA:24
	MOS	19-Dec-25	T:12 (+1m/-1m)		19-Dec-26	19-Jan-27	136 d (+31)	
	HRS	2431.4						
	AFL	1760						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-54-05		28 VDC / 115 VAC STATIC INVERTER						Component ATA:24
PN:AS-24-0026-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0180	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-54-05, AMM 24-54-05PROC. REF: AMM 24-54-05, AMM 24-54-05								
24-65-00		CABLE W109 LPDU/RPDU FEEDER						Component ATA:24
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-01, AMM 24-65-01, AMM 24-65-02, AMM 24-65-02PROC. REF: AMM 24-65-01, AMM 24-65-01, AMM 24-65-02, AMM 24-65-02								
24-65-01		LEFT POWER DISTRIBUTION UNIT ASSEMBLY						Component ATA:24
PN: SX7EG16-1B	MOS/MSC	15-Mar-13	O/C					
SN:0076	HRS	428.1						
	AFL	281						
PROC. REF: AMM 24-65-01, AMM 24-65-01PROC. REF: AMM 24-65-01, AMM 24-65-01								
24-65-02		RIGHT POWER DISTRIBUTION UNIT ASSEMBLY						Component ATA:24
PN: SX7EG17-1B	MOS/MSC	15-Mar-13	O/C					
SN:0083	HRS	428.1						
	AFL	281						
PROC. REF: AMM 24-65-02, AMM 24-65-02PROC. REF: AMM 24-65-02, AMM 24-65-02								
24-65-03		CENTER POWER DISTRIBUTION UNIT ASSEMBLY						Component ATA:24
PN: SX7EG18-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0176	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-03, AMM 24-65-03PROC. REF: AMM 24-65-03, AMM 24-65-03								
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-01		COPILOT CITRINE FINISH GOODRICH SEAT						Component ATA:25
PN:1429-621AK	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:944-1429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01PROC. REF: AMM 25-11-01, AMM 25-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-01	PILOT CITRINE FINISH GOODRICH SEAT							Component ATA:25
PN:1429-521AK	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:960-1429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01-001 ^S	DETAILED VISUAL INSPECTION COPILOT CITRINE FINISH GOODRICH SEAT							Service ATA:25
PN:1429-621AK	MOS	24-Feb-26						
SN:944-1429	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PKG:20								
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01								
25-11-01-001 ^S	DETAILED VISUAL INSPECTION PILOT CITRINE FINISH GOODRICH SEAT							Service ATA:25
PN:1429-521AK	MOS	24-Feb-26						
SN:960-1429	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PKG:20								
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01								
25-11-01-002 ^S	DETAILED VISUAL INSPECTION OF COCKPIT SEAT BELTS							Service ATA:25
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PKG:20								
PROC. REF: AMM 25-11-01PROC. REF: AMM 25-11-01								
25-21-01	LH AFT PAX SEAT							Component ATA:25
PN:403176-2ABR	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:46775	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01								
25-21-01	LH FWD PAX SEAT							Component ATA:25
PN:403176-1ABR	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:46774	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01								
25-21-01	RH AFT PAX SEAT							Component ATA:25
PN:403176-4AB	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:46534	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01								
25-21-01	RH FWD PAX SEAT							Component ATA:25
PN:403176-3AB	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:46533	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01PROC. REF: AMM 25-21-00, AMM 25-21-00, AMM 25-21-01, AMM 25-21-01								
25-21-01-001 ^S	DETAILED VISUAL INSPECTION LH AFT PAX SEAT							Service ATA:25
PN:403176-2ABR	MOS	24-Feb-26						
SN:46775	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
								PKG:20
PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01								
25-21-01-001 ^S	DETAILED VISUAL INSPECTION LH FWD PAX SEAT							Service ATA:25
PN:403176-1ABR	MOS	24-Feb-26						
SN:46774	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
								PKG:20
PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01								
25-21-01-001 ^S	DETAILED VISUAL INSPECTION RH AFT PAX SEAT							Service ATA:25
PN:403176-4AB	MOS	24-Feb-26						
SN:46534	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
								PKG:20
PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-01-001	^S	DETAILED VISUAL INSPECTION RH FWD PAX SEAT						Service ATA:25
PN:403176-3AB	MOS	24-Feb-26						
SN:46533	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01								PKG:20
25-21-01-002	^S	DETAILED VISUAL INSPECTION OF PASSENGER SEAT BELTS						Service ATA:25
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 25-21-01PROC. REF: AMM 25-21-01								PKG:20
25-21-03-001	^S	DETAILED INSPECTION OF FIFTH SEAT						Service ATA:25
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 25-21-03PROC. REF: AMM 25-21-03								PKG:20
25-21-03-002	^S	DETAILED INSPECTION OF THE FIFTH SEAT BELT						Service ATA:25
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 25-21-03PROC. REF: AMM 25-21-03								PKG:20
25-43-01-001	^S	DETAILED VISUAL INSPECTION OF BELTED TOILET UNIT						Service ATA:25
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)					
	AFL	428						
PROC. REF: AMM 25-43-02PROC. REF: AMM 25-43-02								PKG:40

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-43-01-002 ^S	DETAILED VISUAL INSPECTION OF BELTED TOILET SEAT BELT							Service ATA:25
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)					
	AFL	428						
PROC. REF: AMM 25-43-02PROC. REF: AMM 25-43-02								PKG:40
25-61-00-001	OPERATIONAL CHECK OF ELT SYSTEM							Service ATA:25
PN:S1821502-02	MOS	18-May-26	12		18-May-27		286 d	
SN:2620859-0038	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00								
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:S1821502-02	MOS	18-May-26	12		18-May-27		286 d	
SN:2620859-0038	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00								
25-61-01	EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:S1821502-02	MOS/MSC	02-Mar-15	O/C					
SN:2620859-0038	HRS	769.1						
	AFL	551						
PROC. REF: AMM 25-61-01, AMM 25-61-01PROC. REF: AMM 25-61-01, AMM 25-61-01								
25-61-02	EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:S1820506-01	MOS/MSC	14-Dec-21	H/T	TSN 0				
SN:21400697	HRS	1578.2		TSN 0				
	AFL	1131		TSN 0				
PROC. REF: AMM 25-61-04PROC. REF: AMM 25-61-04								
25-61-03	ELT ANTENNA							Component ATA:25
PN:S65-8282-406	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:401-1618	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-03, AMM 25-61-03PROC. REF: AMM 25-61-03, AMM 25-61-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-04-001	DISCARD OF ELT BATTERY							Service ATA:25
PN:S1820506-01	MOS/MSC	14-Dec-21	DUE		01-Sep-28 (M)		758 d	
SN:21400697	HRS	1578.2						
	AFL	1131						
PROC. REF: AMM 25-61-04PROC. REF: AMM 25-61-04								
25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE							Service ATA:25
PN:PN	MOS/MSC		N/A					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 25-61-07PROC. REF: AMM 25-61-07								
25-61-05-01	ELT/NAV INTERFACE - CS144-A MODULE							Component ATA:25
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-05, AMM 25-61-05PROC. REF: AMM 25-61-05, AMM 25-61-05								
25-62-01	FIRST AID KIT							Component ATA:25
PN:39N831	MOS/MSC	18-May-26	H/T	TSN 0				
SN:UNKNOWN	HRS	2523.1		TSN 0				
	AFL	1823		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-62-01-001	VISUAL CHECK OF FIRST AID KIT							Service ATA:25
PN:39N831	MOS/MSC	18-May-26	DUE		01-May-27 (M)		269 d	
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
Expiry Date: : 01-May-27								
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01								
25-62-02	COPILOT CREW LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	04-Nov-19	H/T					
SN:L4720455	HRS							
	AFL							
PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02	NO.1 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	15-Aug-19	H/T	TSN 0				
SN:L4717958	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.2 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	15-Aug-19	H/T	TSN 0				
SN:L4717957	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.3 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	15-Aug-19	H/T	TSN 0				
SN:L3816488	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO.4 PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	15-Aug-19	H/T	TSN 0				
SN:L4688594	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	PILOT CREW LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	04-Nov-19	H/T					
SN:L4720454	HRS							
	AFL							
PROC. REF: AMM 25-62-02, AMM 25-62-02PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF COPILOT LIFE VEST							Service ATA:25
PN:66601-505	MOS	04-Nov-19	120		04-Nov-29		1187 d	OVERHAUL
SN:L4720455	HRS							
	AFL							
OverHaul Date:: 04-Nov-19								
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST							Service ATA:25
PN:66601-105	MOS		120		15-May-29 (M)		1014 d	OVERHAUL
SN:L4717958	HRS							
	AFL							
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST							Service ATA:25
PN:66601-105	MOS		120		15-May-29 (M)		1014 d	OVERHAUL
SN:L4717957	HRS							
	AFL							
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST							Service ATA:25
PN:66601-105	MOS		120		01-Jul-27 (M)		330 d	OVERHAUL
SN:L3816488	HRS							
	AFL							
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST							Service ATA:25
PN:66601-105	MOS		120		28-Mar-29 (M)		966 d	OVERHAUL
SN:L4688594	HRS							
	AFL							
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST							Service ATA:25
PN:66601-505	MOS	04-Nov-19	120		04-Nov-29		1187 d	OVERHAUL
SN:L4720454	HRS							
	AFL							
OverHaul Date:: 04-Nov-19								
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
25-62-04	LAV WATER BARRIER							Component ATA:25
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-04-001 ^S	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER							Service ATA:25
PN:PN	MOS	18-May-26	24 (+1m/-1m)					
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04								PKG:81
Z700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY							Service ATA:25
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-47-00PROC. REF: AMM 05-47-00								PKG:84
ATA 26 - FIRE PROTECTION								
26-11-01	LH ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-49-565/211C-3.7M	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:42806	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01PROC. REF: AMM 26-11-01, AMM 26-11-01								
26-11-01	RH ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-49-565/211C-3.7M	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:42808	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01PROC. REF: AMM 26-11-01, AMM 26-11-01								
26-11-01-001 ^S	DETAILED VISUAL INSPECTION LH ENGINE FIRE DETECTOR							Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	04-Jun-25						
SN:42806	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-11-01-001 ^S	DETAILED VISUAL INSPECTION RH ENGINE FIRE DETECTOR							Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	04-Jun-25						
SN:42808	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
								PKG:10
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01								
26-11-01-002	OPERATIONAL CHECK LH ENGINE FIRE DETECTOR							Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	01-Mar-18						AIRWORTHINESS
SN:42806	HRS	1204.2	1600 (+30/-30)		2804.2	2834.2	204.5 (+30)	
	AFL	863						
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01								
26-11-01-002	OPERATIONAL CHECK RH ENGINE FIRE DETECTOR							Service ATA:26
PN:3951-49-565/211C-3.7M	MOS	01-Mar-18						AIRWORTHINESS
SN:42808	HRS	1204.2	1600 (+30/-30)		2804.2	2834.2	204.5 (+30)	
	AFL	863						
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01								
26-21-01	FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL							Component ATA:26
PN:441-42702-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0229	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-02, AMM 26-21-02, AMM 26-21-01, AMM 26-21-01PROC. REF: AMM 26-21-02, AMM 26-21-02, AMM 26-21-01, AMM 26-21-01								
26-21-01-001	FUNCTIONAL CHECK FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL FIREX PANEL/SYSTEM							Service ATA:26
PN:441-42702-002	MOS	24-Feb-26						AIRWORTHINESS
SN:0229	HRS	2460.4	2400 (+30/-30)	Adj -60.4	4800	4830	2200.3 (+30)	
	AFL	1778						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-03	ENGINE FIRE EXTINGUISHING BOTTLE							Component ATA:26
PN:33000073-4	MOS/MSC	28-Jan-20	O/C	TSN 2				
SN:92530A1	HRS	1448.9		TSN 0				
	AFL	1031		TSN 0				
PROC. REF: AMM 26-21-03, AMM 26-21-03PROC. REF: AMM 26-21-03, AMM 26-21-03								
26-21-03-001	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHING BOTTLE							Service ATA:26
PN:33000073-4	MOS	18-Nov-19	120		18-Nov-29		1201 d	AIRWORTHINESS
SN:92530A1	HRS							
	AFL							
HydroCheck Date: : 18-Nov-19								
PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03								
26-21-05-001	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)							Service ATA:26
	MOS	24-Feb-26						AIRWORTHINESS
	HRS	2460.4	2400 (+30/-30)	Adj -60.4	4800	4830	2200.3 (+30)	
	AFL	1778						
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								
26-21-07	LEFT ENG FIREX CARTRIDGE							Component ATA:26
PN:30903962-1	MOS/MSC	28-Jan-20	O/C					
SN:1965YC	HRS	1448.9						
	AFL	1031						
PROC. REF: AMM 26-21-07, AMM 26-21-07PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07	RIGHT ENG FIREX CARTRIDGE							Component ATA:26
PN:30903963-1	MOS/MSC	28-Jan-20	O/C					
SN:0251YG	HRS	1448.9						
	AFL	1031						
PROC. REF: AMM 26-21-07, AMM 26-21-07PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07-001	DISCARD LEFT ENG FIREX CARTRIDGE							Service ATA:26
PN:30903962-1	MOS	01-Sep-19	120		01-Sep-29		1123 d	LIFE LIMIT
SN:1965YC	HRS							
	AFL							
Manufacture Date:: 01-Sep-19								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: AMM 26-21-07PROC. REF: AMM 26-21-07								
26-21-07-001	DISCARD RIGHT ENG FIREX CARTRIDGE							Service ATA:26
PN:30903963-1	MOS	01-Sep-19	120		01-Sep-29		1123 d	LIFE LIMIT
SN:0251YG	HRS							
	AFL							
Manufacture Date:: 01-Sep-19								
PROC. REF: AMM 26-21-07PROC. REF: AMM 26-21-07								
26-21-09-001 ^S	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING							Service ATA:26
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PKG:20								
PROC. REF: AMM 26-21-09PROC. REF: AMM 26-21-09								
26-24-01	COCKPIT PORTABLE EXTINGUISHER							Component ATA:26
PN:RT-A1200	MOS/MSC	05-May-20	H/T	TSN 7				
SN:Y-502378	HRS	1467.9		TSN 0				
	AFL	1046		TSN 0				
PROC. REF: AMM 26-24-01, AMM 26-24-01PROC. REF: AMM 26-24-01, AMM 26-24-01								
26-24-01-001	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	18-May-26	12		18-May-27		286 d	
SN:Y-502378	HRS	2523.1						
	AFL	1823						
WeightCheck Date : : 18-May-26								
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01								
26-24-01-002	DISCARD COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	04-Oct-19	144		04-Oct-31		1886 d	
SN:Y-502378	HRS							
	AFL							
Manufacture Date:: 04-Oct-19								
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-24-01-003	DISCARD COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS/MSC		N/A					
SN:Y-502378	HRS							
	AFL							
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01								
26-24-01-004	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER							Service ATA:26
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01								
26-24-01-004	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS/MSC		N/A					
SN:Y-502378	HRS							
	AFL							
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01								
ATA 27 - FLIGHT CONTROLS								
27-001	LEFT FLAP ACTUATOR							Component ATA:27
PN:6094A0001-05	MOS	13-Jun-13						LIFE LIMIT
SN:0181	HRS	471.9	21000	TSN 1164.7	20307.2		17707.5	
	AFL	319		TSN 1143				
PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-001	RIGHT FLAP ACTUATOR							Component ATA:27
PN:6094A0001-05	MOS	13-Jun-13						LIFE LIMIT
SN:0337	HRS	471.9	21000	TSN 771.3	20700.6		18100.9	
	AFL	319		TSN 623				
PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-002	ROLL TRIM ACTUATOR							Component ATA:27
PN:452900-1007	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:0202	HRS	0	35000	TSN 0	35000		32400.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-02, AMM 27-14-02PROC. REF: AMM 27-14-02, AMM 27-14-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-003	YAW TRIM ACTUATOR							Component ATA:27
PN:453000-1007	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:0076	HRS	0	35000	TSN 0	35000		32400.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-02, AMM 27-24-02PROC. REF: AMM 27-24-02, AMM 27-24-02								
27-004	LEFT PITCH TRIM ACTUATOR							Component ATA:27
PN:453100-1009	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:0440	HRS	0	3200	TSN 0	3200		600.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-02, AMM 27-34-02PROC. REF: AMM 27-34-02, AMM 27-34-02								
27-004	RIGHT PITCH TRIM ACTUATOR							Component ATA:27
PN:453100-1009	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:0443	HRS	0	3200	TSN 0	3200		600.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-02, AMM 27-34-02PROC. REF: AMM 27-34-02, AMM 27-34-02								
27-005	LH WING GROUND SPOILER ACTUATOR							Component ATA:27
PN:PN	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	35000	TSN 0	35000		32400.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-62-01, AMM 27-62-01PROC. REF: AMM 27-62-01, AMM 27-62-01								
27-005	RH WING GROUND SPOILER ACTUATOR							Component ATA:27
PN:PN	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	35000	TSN 0	35000		32400.3	
	AFL	0		TSN 0				
PROC. REF: AMM 27-62-01, AMM 27-62-01PROC. REF: AMM 27-62-01, AMM 27-62-01								
27-01-01	LEFT CONTROL YOKE							Component ATA:27
PN:83912039	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00287	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01PROC. REF: AMM 27-01-01, AMM 27-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-01-01	RIGHT CONTROL YOKE							Component ATA:27
PN:83912040	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00267	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01PROC. REF: AMM 27-01-01, AMM 27-01-01								
27-01-02	LH PEDAL ASSEMBLY							Component ATA:27
PN:500-15010-417	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000531882	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-02, AMM 27-01-02PROC. REF: AMM 27-01-02, AMM 27-01-02								
27-01-03-001 ^S	LUBRICATION OF ROTARY BALL SPLINE							Service ATA:27
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00								
27-04-01	NO.1 TRIM ACTUATOR CONTROLLER							Component ATA:27
PN:461600-1005	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0434	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-04-01, AMM 27-04-01PROC. REF: AMM 27-04-01, AMM 27-04-01								
27-04-01	NO.2 TRIM ACTUATOR CONTROLLER							Component ATA:27
PN:461600-1005	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0387	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-04-01, AMM 27-04-01PROC. REF: AMM 27-04-01, AMM 27-04-01								
27-04-01-001 ^S	FUNCTIONAL CHECK OF TRIM ACTUATION TIME LIMITER							Service ATA:27
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-04-01-002	^S	FUNCTIONAL CHECK OF TRIM TABS ELECTRICAL STOP						Service ATA:27
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01								PKG:50
27-04-01-003	^S	OPERATIONAL CHECK OF TRIM TAB JAM MONITORING FUNCTION						Service ATA:27
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01PROC. REF: AMM 27-04-01								PKG:50
27-11-00-001	^S	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS						Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 27-11-00PROC. REF: AMM 27-11-00								PKG:42
27-11-01		LH AILERON BALANCED ASSEMBLY						Component ATA:27
PN:500-14650-407	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000526753	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-01, AMM 27-11-01PROC. REF: AMM 27-11-01, AMM 27-11-01								
27-11-01		RH AILERON BALANCED ASSEMBLY						Component ATA:27
PN:500-14660-401	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000524634	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-01, AMM 27-11-01PROC. REF: AMM 27-11-01, AMM 27-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)		04-Jun-30	04-Jul-30	1399 d (+30)	
	HRS	2224.4	3200 (+30/-30)		5424.4	5454.4	2824.7 (+30)	
	AFL	1614						
PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02								
27-11-02-001(INITIAL)	FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	03-Aug-21	-					
	HRS	1568.6						
	AFL	1125						
PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02								
27-11-02-002 ^S	DETAILED VISUAL INSPECTION OF AILERON CONTROL CABLES							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 27-11-02PROC. REF: AMM 27-11-02								
27-14-02-001	FUNCTIONAL CHECK ROLL TRIM ACTUATOR AILERON TRIM BACKLASH/ INTEGRITY							Service ATA:27
PN:452900-1007	MOS	23-Mar-10						AIRWORTHINESS
SN:0202	HRS	0	6000 (+30/-30)		6000	6030	3400.3 (+30)	
	AFL	0						
PROC. REF: AMM 27-14-03PROC. REF: AMM 27-14-03								
27-14-03	LEFT AILERON TRIM TAB							Component ATA:27
PN:500-14630-403	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000521035	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-03, AMM 27-14-03PROC. REF: AMM 27-14-03, AMM 27-14-03								
27-21-00-001 ^S	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PKG:42								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-21-00PROC. REF: AMM 27-21-00								
27-21-01	RUDDER BALANCED ASSEMBLY							Component ATA:27
PN:500-10520-411	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000535656	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-21-01, AMM 27-21-01PROC. REF: AMM 27-21-01, AMM 27-21-01								
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)		04-Jun-30	04-Jul-30	1399 d (+30)	
	HRS	2224.4	3200 (+30/-30)		5424.4	5454.4	2824.7 (+30)	
	AFL	1614						
PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02								
27-21-02-001(INITIAL)	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	03-Aug-21	-					
	HRS	1568.6						
	AFL	1125						
PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02								
27-21-02-002 ^S	DETAILED VISUAL INSPECTION OF RUDDER CONTROL CABLES							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 27-21-02PROC. REF: AMM 27-21-02								PKG:42
27-24-02-001	FUNCTIONAL CHECK YAW TRIM ACTUATOR RUDDER TRIM BACKLASH INTEGRITY							Service ATA:27
PN:453000-1007	MOS	23-Mar-10						AIRWORTHINESS
SN:0076	HRS	0	6000 (+30/-30)		6000	6030	3400.3 (+30)	
	AFL	0						
PROC. REF: AMM 27-24-03PROC. REF: AMM 27-24-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-24-03	TAB RUDDER							Component ATA:27
PN:500-10420-407	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000530440	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-03, AMM 27-24-03PROC. REF: AMM 27-24-03, AMM 27-24-03								
27-31-00-001 ^S	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00								
27-31-01	LEFT ELEVATOR							Component ATA:27
PN:500-11085-4001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000535630	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-01	RIGHT ELEVATOR							Component ATA:27
PN:500-11085-4002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000535487	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION							Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)		04-Jun-30	04-Jul-30	1399 d (+30)	
	HRS	2224.4	3200 (+30/-30)		5424.4	5454.4	2824.7 (+30)	
	AFL	1614						
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02								
27-31-02-001(INITIAL)	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	03-Aug-21	-					
	HRS	1568.6						
	AFL	1125						
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-02-002 ^S		DETAILED VISUAL INSPECTION OF ELEVATOR CONTROL CABLES						Service ATA:27
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4	3200 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02								PKG:42
27-34-02-001		FUNCTIONAL CHECK OF PITCH TRIM BACKLASH/ INTEGRITY						Service ATA:27
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	3400.3 (+30)	
	AFL	0						
PROC. REF: AMM 27-34-05PROC. REF: AMM 27-34-05								
27-34-04		PITCH TRIM INTERCONNECTION ACTUATOR						Component ATA:27
PN:453110-1001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-04, AMM 27-34-04PROC. REF: AMM 27-34-04, AMM 27-34-04								
27-34-05		LEFT ELEVATOR TRIM TAB						Component ATA:27
PN:500-11010-4001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000525140	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-05, AMM 27-34-05PROC. REF: AMM 27-34-05, AMM 27-34-05								
27-34-05		RIGHT ELEVATOR TRIM TAB						Component ATA:27
PN:500-11010-4002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000527914	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-34-05, AMM 27-34-05PROC. REF: AMM 27-34-05, AMM 27-34-05								
27-36-01		LEFT ANGLE-OF-ATTACK SENSOR						Component ATA:27
PN:C-100117-4	MOS/MSC	29-Jun-15	O/C	TSR 0				
SN:329	HRS	820.4		TSR 0				
	AFL	586		TSR 0				
PROC. REF: AMM 27-36-01, AMM 27-36-01PROC. REF: AMM 27-36-01, AMM 27-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-36-01	RIGHT ANGLE-OF-ATTACK SENSOR							Component ATA:27
PN:C-100117-4	MOS/MSC	29-Jun-15	O/C					
SN:139222-01	HRS	820.4						
	AFL	586						
PROC. REF: AMM 27-36-01, AMM 27-36-01PROC. REF: AMM 27-36-01, AMM 27-36-01								
27-36-01-001 ^S	OPERATIONAL CHECK OF ANGLE-OF-ATTACK (AOA) SENSOR							Service ATA:27
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 27-36-01PROC. REF: AMM 27-36-01								
27-36-02	STICK PUSHER LINEAR ACTUATOR							Component ATA:27
PN:260926258-0101	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:188	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-36-02, AMM 27-36-02PROC. REF: AMM 27-36-02, AMM 27-36-02								
27-36-03-001 ^S	OPERATIONAL CHECK OF SPWS CUTOUT SWITCH							Service ATA:27
	MOS	04-Jun-25						
	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 27-36-03PROC. REF: AMM 27-36-03								
27-36-04	STALL WARNING AND PROTECTION COMPUTER							Component ATA:27
PN:C-100106-2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:182	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-36-04, AMM 27-36-04PROC. REF: AMM 27-36-04, AMM 27-36-04								
27-51-01-001 ^S	LUBRICATION OF FLAP ACTUATORS BALL SCREWS							Service ATA:27
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PKG:80								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00								
27-51-01-002 ^S	DETAILED VISUAL INSPECTION LEFT FLAP ACTUATOR							Service ATA:27
PN:6094A0001-05	MOS	13-Jun-13						
SN:0181	HRS	471.9	6400 (+30/-30)					
	AFL	319						
PKG:60								
PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-002 ^S	DETAILED VISUAL INSPECTION RIGHT FLAP ACTUATOR							Service ATA:27
PN:6094A0001-05	MOS	13-Jun-13						
SN:0337	HRS	471.9	6400 (+30/-30)					
	AFL	319						
PKG:60								
PROC. REF: AMM 27-51-01, AMM 27-51-01PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-003	RESTORE (OVERHAUL) LEFT FLAP ACTUATOR							Service ATA:27
PN:6094A0001-05	MOS	13-Jun-13						
SN:0181	HRS	471.9	4000 (+30/-30)		4471.9	4501.9	1872.2 (+30)	
	AFL	319						
PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01								
27-51-01-003	RESTORE (OVERHAUL) RIGHT FLAP ACTUATOR							Service ATA:27
PN:6094A0001-05	MOS	13-Jun-13						
SN:0337	HRS	471.9	4000 (+30/-30)		4471.9	4501.9	1872.2 (+30)	
	AFL	319						
PROC. REF: AMM 27-51-01PROC. REF: AMM 27-51-01								
27-51-03	LH WING FLAP							Component ATA:27
PN:500-14301-403	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000531442	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-03, AMM 27-51-03PROC. REF: AMM 27-51-03, AMM 27-51-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-03	RH WING FLAP							Component ATA:27
PN:500-14301-404	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000534717	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-03, AMM 27-51-03PROC. REF: AMM 27-51-03, AMM 27-51-03								
27-53-01	FLAP SELECTOR LEVER							Component ATA:27
PN:780501-9	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:1062	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01, AMM 27-53-01PROC. REF: AMM 27-53-01, AMM 27-53-01								
27-53-02	FLAP SYSTEM CONTROL UNIT							Component ATA:27
PN:8025A0001-08	MOS/MSC	15-Mar-13	O/C					
SN:434	HRS	428.1						
	AFL	281						
PROC. REF: AMM 27-53-02, AMM 27-53-02PROC. REF: AMM 27-53-02, AMM 27-53-02								
27-53-03	LH WING FLAP POSITION SENSOR UNIT							Component ATA:27
PN:7906A0001-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:KA1534	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-53-03	RH WING FLAP POSITION SENSOR UNIT							Component ATA:27
PN:7906A0001-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:KA1540	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-60-00-001	OPERATIONAL CHECK OF GROUND SPOILER SYSTEM							Service ATA:27
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	3800.3 (+30)	
	AFL	0						
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-00-001	^S	FUNCTIONAL CHECK OF FUEL TANKS FOR MICRO-ORGANISMS						Service ATA:28
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 28-11-00PROC. REF: AMM 28-11-00								PKG:80
28-11-05 LH WING WATER DRAIN VALVE Component ATA:28								
PN:L83A13-628	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E06637	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-11-05 RH WING WATER DRAIN VALVE Component ATA:28								
PN:L83A13-628	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E06660	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-11-07 LH WING DUMP VALVE Component ATA:28								
PN:V98A32-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E09883	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-11-07 RH WING DUMP VALVE Component ATA:28								
PN:V98A32-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E15603	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-12-01-001 SPECIAL DETAILED INSPECTION OF FUEL VENT NACA Service ATA:28								
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)		2716.8	2746.8	117.1 (+30)	
	AFL	1354						
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-12-03	LH WING FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E16373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03, AMM 28-12-07, AMM 28-12-07PROC. REF: AMM 28-12-03, AMM 28-12-03, AMM 28-12-07, AMM 28-12-07								
28-12-03	RH WING FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E17356	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03, AMM 28-12-07, AMM 28-12-07PROC. REF: AMM 28-12-03, AMM 28-12-03, AMM 28-12-07, AMM 28-12-07								
28-12-03-001 ^S	OPERATIONAL CHECK LH WING FUEL TANK FLOAT VENT VALVE							Service ATA:28
PN:L87-19-001P2	MOS	23-Mar-10						
SN:E16373	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03								PKG:60
28-12-03-001 ^S	OPERATIONAL CHECK RH WING FUEL TANK FLOAT VENT VALVE							Service ATA:28
PN:L87-19-001P2	MOS	23-Mar-10						
SN:E17356	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03								PKG:60
28-12-05	LH WING DRAIN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-12-05	RH WING DRAIN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-21-00	NO.1 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-00	NO.2 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-00	NO.3 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-00	NO.4 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-03	LH WING DC AUXILIARY CANISTER BOOST PUMP							Component ATA:28
PN:C93R19-601	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E17851	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-03	RH WING DC AUXILIARY CANISTER BOOST PUMP							Component ATA:28
PN:C93R19-601	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E17857	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-03-1 ^U	L H WING DC AUXILIARY CANISTER BOOST PUMP							Component ATA:28
PN:VP99-393	MOS/MSC	21-Oct-15	O/C					
SN:EN2726	HRS	855						
	AFL							
28-21-04	LH WING DC AUXILIARY CARTRIDGE BOOST PUMP							Component ATA:28
PN:P99C19-602	MOS/MSC	03-Apr-23	O/C					
SN:E55401	HRS	1908.9						
	AFL	1338						
PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-04	RH WING DC AUXILIARY CARTRIDGE BOOST PUMP							Component ATA:28
PN:P99C19-602	MOS/MSC	07-Mar-17	O/C					
SN:G94969	HRS	1054.3						
	AFL	756						
PROC. REF: AMM 28-21-03, AMM 28-21-03PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-05	LH WING MAIN EJECTOR PUMP							Component ATA:28
PN:T99A19-601	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E27446	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-05	RH WING MAIN EJECTOR PUMP							Component ATA:28
PN:T99A19-601	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E27448	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05PROC. REF: AMM 28-21-05, AMM 28-21-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-07-001	OPERATIONAL CHECK LEFT WING 0.75 IN SHUTOFF VALVE							Service ATA:28
PN:B97-15-601	MOS	24-Feb-26						AIRWORTHINESS
SN:E06074	HRS	2460.4	1200 (+30/-30)	Adj -49	3611.4	3641.4	1011.7 (+30)	
	AFL	1778						
PROC. REF: AMM 28-21-07PROC. REF: AMM 28-21-07								
28-21-07-001	OPERATIONAL CHECK RIGHT WING 0.75 IN SHUTOFF VALVE							Service ATA:28
PN:B97-15-601	MOS	24-Feb-26						AIRWORTHINESS
SN:E11747	HRS	2460.4	1200 (+30/-30)	Adj -49	3611.4	3641.4	1011.7 (+30)	
	AFL	1778						
PROC. REF: AMM 28-21-07PROC. REF: AMM 28-21-07								
28-21-07-01	LEFT WING 0.75 IN SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E06074	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-01	RIGHT WING 0.75 IN SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E11747	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-02	LH WING 28-V DC ENGINE SHUTOFF VALVE ACTUATOR ASSEMBLY							Component ATA:28
PN:D97000-644P2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:C70532	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-02	RH WING 28-V DC ENGINE SHUTOFF VALVE ACTUATOR ASSEMBLY							Component ATA:28
PN:D97000-644P2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:C70522	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07PROC. REF: AMM 28-21-07, AMM 28-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-08-001 ^S		OPERATIONAL CHECK OF FUEL TRANSFER VALVE						Service ATA:28
PN:B97-38-603P2	MOS	04-Jun-25						
SN:E19550	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 28-21-08PROC. REF: AMM 28-21-08								
PKG:10								
28-21-08-01		1.5 IN FUEL SYSTEM SHUTOFF VALVE						Component ATA:28
PN:B97-38-603P2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E19550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-08, AMM 28-21-08PROC. REF: AMM 28-21-08, AMM 28-21-08								
28-21-08-02		ENGINE 28-V DC TRANSFER VALVE ACTUATOR ASSEMBLY						Component ATA:28
PN:D97000-644P2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:C70535	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-08, AMM 28-21-08PROC. REF: AMM 28-21-08, AMM 28-21-08								
28-21-11		LH WING MOTIVE FLOW 3/8 IN CHECK VALVE						Component ATA:28
PN:L96-09-001P4	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E22299	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-11		RH WING MOTIVE FLOW 3/8 IN CHECK VALVE						Component ATA:28
PN:L96-09-001P4	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:E28466	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-13		FUEL CONTROL PANEL						Component ATA:28
PN:441-42854-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0181	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-13, AMM 28-21-13PROC. REF: AMM 28-21-13, AMM 28-21-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-01	NO. 1 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765551-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765551IN00260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 1 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765826-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765826IN00230	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765548-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765548IN00247	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765827-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765827IN00244	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 3 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765549-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765549IN00372	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 3 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765549-1-0	MOS/MSC	20-Dec-10	O/C	TSN 0				
SN:765549IN00305	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-01	NO. 4 LEFT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765550-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765550IN00408	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 RIGHT WING FUEL QUANTITY PROBE							Component ATA:28
PN:765550-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:765550IN00426	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-05	ELECTRONIC FUEL CONTROL UNIT							Component ATA:28
PN:738667-2-6	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:738790IN00285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-05, AMM 28-41-05PROC. REF: AMM 28-41-05, AMM 28-41-05								
28-43-01	FUEL TEMPERATURE SENSOR							Component ATA:28
PN:798840-1-0	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:02013	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-43-01, AMM 28-43-01PROC. REF: AMM 28-43-01, AMM 28-43-01								
28-43-01-001 ^S	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR							Service ATA:28
PN:798840-1-0	MOS	23-Mar-10						
SN:02013	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-43-01PROC. REF: AMM 28-43-01								
PKG:60								
28-45-01	NO.1 FUEL LOW PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0327	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01PROC. REF: AMM 28-45-01, AMM 28-45-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-45-01	NO.2 FUEL LOW PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01PROC. REF: AMM 28-45-01, AMM 28-45-01								
ATA 29 - HYDRAULIC POWER								
29-00-00-001 ^S	VISUAL CHECK OF HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR (DPI)							Service ATA:29
PN:PN	MOS	18-May-26	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 29-31-02PROC. REF: AMM 29-31-02								
PKG:80								
29-11-01	HYDRAULIC POWERPACK							Component ATA:29
PN:3032683-105	MOS/MSC	04-May-23	O/C	TSO 14				
SN:MX735368	HRS	1916.8		TSO 0				
	AFL	1354		TSO 0				
PROC. REF: AMM 29-11-01, AMM 29-11-01PROC. REF: AMM 29-11-01, AMM 29-11-01								
29-11-01-001	RESTORATION (OVERHAUL) OF THE HYDRAULIC POWERPACK							Service ATA:29
PN:3032683-105	MOS/MSC	04-May-23	N/A	TAC 14				
SN:MX735368	HRS	1916.8		TAC 0				
	AFL	1354		TAC 0				
PROC. REF: AMM 29-11-01PROC. REF: AMM 29-11-01								
29-11-01-002	RESTORATION (OVERHAUL) OF THE HYDRAULIC POWERPACK							Service ATA:29
PN:3032683-105	MOS	04-May-23					OVERHAUL	
SN:MX735368	HRS	1916.8	1600 (+30/-30)	3516.8	3546.8	917.1 (+30)		
	AFL	1354						
PROC. REF: AMM 29-11-01PROC. REF: AMM 29-11-01								
29-11-09	HYDRAULIC POWERPACK TEMPERATURE SWITCH							Component ATA:29
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-11-09, AMM 29-11-09PROC. REF: AMM 29-11-09, AMM 29-11-09								
29-11-09-001	S	FUNCTIONAL CHECK OF TEMPERATURE SWITCH						Service ATA:29
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 29-11-09PROC. REF: AMM 29-11-09								
29-15-01		LH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE						Component ATA:29
PN:PN	MOS/MSC	17-Mar-14	H/T	TSN 0				
SN:UNKNOWN	HRS	605.2		TSN 0				
	AFL	428		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01		LH WING - GROUND SPOILER ACTUATOR RETURN HOSE						Component ATA:29
PN:PN	MOS/MSC	17-Mar-14	H/T	TSN 0				
SN:UNKNOWN	HRS	605.2		TSN 0				
	AFL	428		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01		RH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE						Component ATA:29
PN:PN	MOS/MSC	17-Mar-14	H/T	TSN 0				
SN:UNKNOWN	HRS	605.2		TSN 0				
	AFL	428		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01PROC. REF: AMM 29-15-01, AMM 29-15-01								
29-15-01		RH WING - GROUND SPOILER ACTUATOR RETURN HOSE						Component ATA:29
PN:PN	MOS/MSC	17-Mar-14	H/T	TSN 0				
SN:UNKNOWN	HRS	605.2		TSN 0				
	AFL	428		TSN 0				
PROC. REF: AMM 29-15-01, AMM 29-15-01PROC. REF: AMM 29-15-01, AMM 29-15-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-15-01-001	^S	DISCARD LH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE						Service ATA:29
PN:PN	MOS	04-May-23						DISCARD
SN:UNKNOWN	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 29-15-01PROC. REF: AMM 29-15-01								PKG:1
29-15-01-001	^S	DISCARD LH WING - GROUND SPOILER ACTUATOR RETURN HOSE						Service ATA:29
PN:PN	MOS	04-May-23						DISCARD
SN:UNKNOWN	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 29-15-01PROC. REF: AMM 29-15-01								PKG:1
29-15-01-001	^S	DISCARD RH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE						Service ATA:29
PN:PN	MOS	04-May-23						DISCARD
SN:UNKNOWN	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 29-15-01PROC. REF: AMM 29-15-01								PKG:1
29-15-01-001	^S	DISCARD RH WING - GROUND SPOILER ACTUATOR RETURN HOSE						Service ATA:29
PN:PN	MOS	04-May-23						DISCARD
SN:UNKNOWN	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 29-15-01PROC. REF: AMM 29-15-01								PKG:1
29-15-03		HYDRAULIC ACCUMULATOR						Component ATA:29
PN:MS28797-3	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:8423-12797	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-03, AMM 29-15-03PROC. REF: AMM 29-15-03, AMM 29-15-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-15-03-001	DISCARD OF HYDRAULIC ACCUMULATOR							Service ATA:29
	MOS	23-Mar-10						DISCARD
	HRS	0						
	AFL	0	28000		28000		26130	
PROC. REF: AMM 29-15-03PROC. REF: AMM 29-15-03								
29-20-01	POWERPACK VENTILATION FAN							Component ATA:29
PN:SF9202D00	MOS/MSC	17-Mar-14	O/C	TSR 0				
SN:L00183	HRS	605.2		TSR 0				
	AFL	428		TSR 0				
PROC. REF: AMM 29-20-01, AMM 29-20-01PROC. REF: AMM 29-20-01, AMM 29-20-01								
29-20-01-001 ^S	OPERATIONAL CHECK OF POWERPACK VENTILATION FAN							Service ATA:29
PN:SF9202D00	MOS	04-May-23						
SN:L00183	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01								
29-31-02	HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR							Component ATA:29
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-02, AMM 29-31-02PROC. REF: AMM 29-31-02, AMM 29-31-02								
ATA 30 - ICE AND RAIN PROTECTION								
30-01-01	ICE PROTECTION/HEATING SYSTEM CONTROL PANEL							Component ATA:30
PN:441-43199-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0115	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-01-01, AMM 30-01-01PROC. REF: AMM 30-01-01, AMM 30-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-10-00-001 ^S	OPERATIONAL CHECK OF PNEUMATIC DE-ICING SYSTEM							Service ATA:30
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								PKG:1
30-11-01	DE-ICING SYSTEM CONTROLLER							Component ATA:30
PN:4D2037-24	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:U0205	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-01, AMM 30-11-01PROC. REF: AMM 30-11-01, AMM 30-11-01								
30-11-02	NO.1 REAR FUSELAGE CHECK VALVE							Component ATA:30
PN:3D3555-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:N091005	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02, AMM 30-11-02PROC. REF: AMM 30-11-02, AMM 30-11-02								
30-11-02	NO.2 REAR FUSELAGE CHECK VALVE							Component ATA:30
PN:3D3555-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:N092287	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02, AMM 30-11-02PROC. REF: AMM 30-11-02, AMM 30-11-02								
30-11-03	REAR FUS PRESSURE REGULATOR/RELIEVER VALVE							Component ATA:30
PN:4D2095-2011	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:N100077	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03, AMM 30-11-03PROC. REF: AMM 30-11-03, AMM 30-11-03								
30-11-03-001 ^S	RESTORATION (CLEANING) OF PRESSURE REGULATOR/RELIEVER							Service ATA:30
PN:4D2095-2011	MOS	23-Mar-10						
SN:N100077	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-04	AFT WATER SEPARATOR							Component ATA:30
PN:44E13-5A	MOS/MSC	15-Mar-13	O/C	TSN 0				
SN:N120198	HRS	428.1		TSN 0				
	AFL	281		TSN 0				
PROC. REF: AMM 30-11-04, AMM 30-11-04PROC. REF: AMM 30-11-04, AMM 30-11-04								
30-11-04	FORWARD WATER SEPARATOR							Component ATA:30
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-04, AMM 30-11-04PROC. REF: AMM 30-11-04, AMM 30-11-04								
30-11-04-001	RESTORATION (CLEANING) OF THE AFT WATER SEPARATOR							Service ATA:30
PN:44E13-5A	MOS/MSC	23-Mar-10	O/C					
SN:N120198	HRS	0						
	AFL	0						
PROC. REF: AMM 30-11-04PROC. REF: AMM 30-11-04								
30-11-04-001	RESTORATION (CLEANING) OF THE FORWARD WATER SEPARATOR							Service ATA:30
PN:PN	MOS/MSC	23-Mar-10	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 30-11-04PROC. REF: AMM 30-11-04								
30-11-05	REAR FUS LOW PRESSURE SWITCH							Component ATA:30
PN:3D3552-02	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0214	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-05, AMM 30-11-05PROC. REF: AMM 30-11-05, AMM 30-11-05								
30-11-05-001 ^S	FUNCTIONAL CHECK OF DE-ICING LOW PRESSURE SWITCH							Service ATA:30
PN:3D3552-02	MOS	23-Mar-10						
SN:0214	HRS	0	5600 (+30/-30)					
	AFL	0						

PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-11-05PROC. REF: AMM 30-11-05								
30-13-01	INBOARD WING FLOW CONTROL VALVE							Component ATA:30
PN:3D2376-07	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:N092498	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-01, AMM 30-13-01PROC. REF: AMM 30-13-01, AMM 30-13-01								
30-13-01	OUTBOARD WING FLOW CONTROL VALVE							Component ATA:30
PN:3D2376-07	MOS/MSC	14-Jan-15	O/C	TSN 0				
SN:N710046	HRS	755.7		TSN 0				
	AFL	540		TSN 0				
PROC. REF: AMM 30-13-01, AMM 30-13-01PROC. REF: AMM 30-13-01, AMM 30-13-01								
30-13-02	NO.1 L/H WING DE ICE PRESSURE SWITCH							Component ATA:30
PN:3D3533-04	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0598	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02	NO.1 R/H WING DE ICE PRESSURE SWITCH							Component ATA:30
PN:3D3533-04	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0699	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02	NO.2 L/H WING DE ICE PRESSURE SWITCH							Component ATA:30
PN:3D3533-04	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0734	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-02, AMM 30-13-02PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02	NO.2 R/H WING DE ICE PRESSURE SWITCH							Component ATA:30
PN:3D3533-04	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0788	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-13-02, AMM 30-13-02PROC. REF: AMM 30-13-02, AMM 30-13-02								
30-13-02-001 ^S FUNCTIONAL CHECK NO.1 L/H WING DE ICE PRESSURE SWITCH Service ATA:30								
PN:3D3533-04	MOS	23-Mar-10						
SN:0598	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02PROC. REF: AMM 30-13-02								
30-13-02-001 ^S FUNCTIONAL CHECK NO.1 R/H WING DE ICE PRESSURE SWITCH Service ATA:30								
PN:3D3533-04	MOS	23-Mar-10						
SN:0699	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02PROC. REF: AMM 30-13-02								
30-13-02-001 ^S FUNCTIONAL CHECK NO.2 L/H WING DE ICE PRESSURE SWITCH Service ATA:30								
PN:3D3533-04	MOS	23-Mar-10						
SN:0734	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02PROC. REF: AMM 30-13-02								
30-13-02-001 ^S FUNCTIONAL CHECK NO.2 R/H WING DE ICE PRESSURE SWITCH Service ATA:30								
PN:3D3533-04	MOS	23-Mar-10						
SN:0788	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-13-02PROC. REF: AMM 30-13-02								
30-13-03 LH WING DE-ICER BOOT Component ATA:30								
PN:PS29S4D5321-23	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:MCAH010	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-03, AMM 30-13-03PROC. REF: AMM 30-13-03, AMM 30-13-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-13-03	RH WING DE-ICER BOOT							Component ATA:30
PN:PS29S4D5321-24	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:MBZY690	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-13-03, AMM 30-13-03PROC. REF: AMM 30-13-03, AMM 30-13-03								
30-13-03-001 ^S	GENERAL VISUAL INSPECTION LH WING DE-ICER BOOT							Service ATA:30
PN:PS29S4D5321-23	MOS	18-May-26	12 (+1m/-1m)					
SN:MCAH010	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 30-13-03PROC. REF: AMM 30-13-03								
30-13-03-001 ^S	GENERAL VISUAL INSPECTION RH WING DE-ICER BOOT							Service ATA:30
PN:PS29S4D5321-24	MOS	18-May-26	12 (+1m/-1m)					
SN:MBZY690	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 30-13-03PROC. REF: AMM 30-13-03								
30-15-01	REAR FUS FLOW CONTROL VALVE							Component ATA:30
PN:3D2376-07	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:N093847	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-01, AMM 30-15-01PROC. REF: AMM 30-15-01, AMM 30-15-01								
30-15-02	REAR FUS DE ICE PRESSURE SWITCH							Component ATA:30
PN:3D3533-04	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0926	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-02, AMM 30-15-02PROC. REF: AMM 30-15-02, AMM 30-15-02								
30-15-02-001 ^S	FUNCTIONAL CHECK OF HORIZONTAL STABILIZER DE-ICER PRESSURE SWITCH							Service ATA:30
PN:3D3533-04	MOS	23-Mar-10						
SN:0926	HRS	0	5600 (+30/-30)					
	AFL	0						
PKG:50								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-15-02PROC. REF: AMM 30-15-02								
30-15-03	LH TAIL DE-ICER BOOT							Component ATA:30
PN:PS29S4D5321-21	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:MBMA230	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-03, AMM 30-15-03PROC. REF: AMM 30-15-03, AMM 30-15-03								
30-15-03	RH TAIL DE-ICER BOOT							Component ATA:30
PN:PS29S4D5321-22	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:MBKT130	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-15-03, AMM 30-15-03PROC. REF: AMM 30-15-03, AMM 30-15-03								
30-15-03-001 ^S	GENERAL VISUAL INSPECTION OF LH TAIL DE-ICER BOOT							Service ATA:30
PN:PS29S4D5321-21	MOS	18-May-26	12 (+1m/-1m)					
SN:MBMA230	HRS	2523.1						
	AFL	1823						
								PKG:80
PROC. REF: AMM 30-15-03PROC. REF: AMM 30-15-03								
30-15-03-001 ^S	GENERAL VISUAL INSPECTION OF RH TAIL DE-ICER BOOT							Service ATA:30
PN:PS29S4D5321-22	MOS	18-May-26	12 (+1m/-1m)					
SN:MBKT130	HRS	2523.1						
	AFL	1823						
								PKG:80
PROC. REF: AMM 30-15-03PROC. REF: AMM 30-15-03								
30-21-00-900-801-01	LH ENGINE ANTI ICING DUCT							Component ATA:30
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-00, AMM 30-21-00PROC. REF: AMM 30-21-00, AMM 30-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-21-00-900-801-02		RH ENGINE ANTI ICING DUCT						Component ATA:30
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-00, AMM 30-21-00PROC. REF: AMM 30-21-00, AMM 30-21-00								
30-21-01		LEFT ENGINE ANTI-ICE SYSTEM SHUTOFF VALVE						Component ATA:30
PN:5727-00-5	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0328A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01, AMM 30-21-01PROC. REF: AMM 30-21-01, AMM 30-21-01								
30-21-01		RIGHT ENGINE ANTI-ICE SYSTEM SHUTOFF VALVE						Component ATA:30
PN:5727-00-5	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0343A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01, AMM 30-21-01PROC. REF: AMM 30-21-01, AMM 30-21-01								
30-21-02		LH ENG ANTI-ICE PRESSURE TRANSDUCER						Component ATA:30
PN:APTE-473A-1000-50G	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:7585-9-247	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02, AMM 30-21-02PROC. REF: AMM 30-21-02, AMM 30-21-02								
30-21-02		RH ENG ANTI-ICE PRESSURE TRANSDUCER						Component ATA:30
PN:APTE-473A-1000-50G	MOS/MSC	10-May-17	O/C					
SN:8178-6-223	HRS	1066.15						
	AFL	770						
PROC. REF: AMM 30-21-02, AMM 30-21-02PROC. REF: AMM 30-21-02, AMM 30-21-02								
30-21-02-001		FUNCTIONAL CHECK OF LH ENG ANTI-ICE PRESSURE TRANSDUCER						Service ATA:30
PN:APTE-473A-1000-50G	MOS	23-Mar-10						
SN:7585-9-247	HRS	0	12000 (+30/-30)	12000	12030	9400.3 (+30)		
	AFL	0						
PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-21-02-001	FUNCTIONAL CHECK OF RH ENG ANTI-ICE PRESSURE TRANSDUCER							Service ATA:30
PN:APTE-473A-1000-50G	MOS	10-May-17						
SN:8178-6-223	HRS	1066.15	12000 (+30/-30)		13066.15	13096.15	10466.5 (+30)	
	AFL	770						
PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02								
30-21-03-001	^S	BORESCOPE INSPECTION OF PICCOLO TUBE						Service ATA:30
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PKG:50								
PROC. REF: AMM 30-21-03PROC. REF: AMM 30-21-03								
30-21-04-001	^S	DETAILED VISUAL INSPECTION OF ENGINE ANTI-ICE DUCTS						Service ATA:30
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PKG:20								
PROC. REF: AMM 30-21-00PROC. REF: AMM 30-21-00								
30-31-00-001	^S	OPERATIONAL CHECK OF PITOT, STATIC, AOA AND P-STATIC HEATING						Service ATA:30
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PKG:81								
PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00								
30-31-01	AIR DATA PROBES HEATER CURRENT MONITOR-							Component ATA:30
PN:C-100131-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:258	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-31-01, AMM 30-31-01PROC. REF: AMM 30-31-01, AMM 30-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-41-01-001	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING							Service ATA:30
	MOS/MSC	23-Mar-18	O/C					
	HRS	1211.4						
	AFL	870						
PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01								
30-41-01-002 ^S	DISCARD OF WINDSHIELD RAIN REPELLENT COATING (RRC)							Service ATA:30
	MOS	18-May-26	12 (+1m/-1m)					DISCARD
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 30-41-01PKG:80								
30-41-01-003 ^S	FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE							Service ATA:30
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 30-41-01PKG:80								
30-42-00-001 ^S	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM							Service ATA:30
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 30-42-00PKG:1								
30-42-01	LH WINDSHIELD HEATER CONTROL UNIT							Component ATA:30
PN:EPM-112-4	MOS/MSC	17-Jun-23	O/C	TSN 0				
SN:04059	HRS	1942.5		TSN 0				
	AFL	1373		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-42-01	RH WINDSHIELD HEATER CONTROL UNIT							Component ATA:30
PN:EPM-112-3	MOS/MSC	09-May-22	O/C					
SN:01310	HRS	1718.4						
	AFL	1217						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-42-01, AMM 30-42-01PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-81-01	CREW CABIN LIGHT ICING INDICATOR							Component ATA:30
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-81-02, AMM 30-81-02PROC. REF: AMM 30-81-02, AMM 30-81-02								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-00-002 ^S	OPERATIONAL CHECK OF COCKPIT VOICE AND DATA RECORDER SYSTEM							Service ATA:31
PN:2100-3083-50	MOS	18-May-26	12 (+1m/-1m)					
SN:000608843	HRS	2523.1						
	AFL	1823						
PKG:80								
PROC. REF: AMM 31-31-00PROC. REF: AMM 31-31-00								
31-31-01	CVDR - COCKPIT VOICE AND DATA RECORDER							Component ATA:31
PN:2100-3083-50	MOS/MSC	16-Apr-15	O/C					
SN:000608843	HRS	791.7						
	AFL	568						
PROC. REF: AMM 31-31-01, AMM 31-31-01PROC. REF: AMM 31-31-01, AMM 31-31-01								
31-31-03	CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY							Component ATA:31
PN:PN-UNKNOWN	MOS/MSC	18-May-26	H/T					
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 31-31-03, AMM 31-31-03PROC. REF: AMM 31-31-03, AMM 31-31-03								
31-31-03-001	DISCARD CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY							Service ATA:31
PN:PN-UNKNOWN	MOS/MSC	18-May-26	DUE		01-Mar-33 (M)		2400 d	DISCARD
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
Expiry Date: : 01-Mar-33								
PROC. REF: AMM 31-31-03PROC. REF: AMM 31-31-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-04 IMPACT SWITCH								Component ATA:31
PN:5930-4-000	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:4246	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-04, AMM 31-31-04PROC. REF: AMM 31-31-04, AMM 31-31-04								
31-31-09 CVDR INSC ILLUM PANEL								Component ATA:31
PN:441-42635-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0201	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-09, AMM 31-31-09PROC. REF: AMM 31-31-09, AMM 31-31-09								
31-31-13 CVDR/UNDERWATER LOCATOR BEACON								Component ATA:31
PN:DK120/90	MOS/MSC	18-May-26	A/R	TSN 3				
SN:AT240152	HRS	2523.1		TSN 0				
	AFL	1823		TSN 0				
PROC. REF: AMM 31-31-03, AMM 31-31-03PROC. REF: AMM 31-31-03, AMM 31-31-03								
31-41-01 GSD 41 DATA CONCENTRATOR UNIT								Component ATA:31
PN:011-01457-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:16905173	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01, AMM 31-41-01PROC. REF: AMM 31-41-01, AMM 31-41-01								
31-41-03 NO.1 ENGINE/AIRFRAME INTERFACE UNIT								Component ATA:31
PN:011-00831-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:46711149	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-41-03 NO.2 ENGINE/AIRFRAME INTERFACE UNIT								Component ATA:31
PN:011-00831-00	MOS/MSC	04-Aug-15	O/C					
SN:46708474	HRS	835.4						
	AFL	596						
PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-41-03	NO.3 ENGINE/AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:46711224	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-41-05	NO.1 GIA63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-01105-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:15W010211	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05PROC. REF: AMM 31-41-05, AMM 31-41-05								
31-41-05	NO.2 GIA63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-01105-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:15W010223	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05PROC. REF: AMM 31-41-05, AMM 31-41-05								
31-42-00-001 ^S	OPERATIONAL CHECK OF HSDB SWITCH REVERSION							Service ATA:31
	MOS	23-Mar-10						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PKG:60								
PROC. REF: AMM 31-42-00PROC. REF: AMM 31-42-00								
31-42-01	MAINTENANCE CONTROL PANEL							Component ATA:31
PN:441-40947-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0138	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-42-01, AMM 31-42-01PROC. REF: AMM 31-42-01, AMM 31-42-01								
31-61-00-001 ^S	OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)					
	AFL	428						
PKG:40								
PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-61-00-001	^S	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)						Service ATA:31
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)					
	AFL	428						
PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00								PKG:40
31-61-00-001	^S	OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)						Service ATA:31
	MOS	17-Mar-14						
	HRS	605.2	3200 (+30/-30)					
	AFL	428						
PROC. REF: AMM 31-61-00PROC. REF: AMM 31-61-00								PKG:40
31-61-01		MFD (MULTI-FUNCTION FLIGHT DISPLAY)						Component ATA:31
PN:011-01440-10	MOS/MSC	24-Feb-26	O/C					
SN:18T006047	HRS	2460.4						
	AFL	1778						
PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01								
31-61-01		PFD 1 (PRIMARY FLIGHT DISPLAY)						Component ATA:31
PN:011-01440-10	MOS/MSC	24-Feb-26	O/C					
SN:18T005090	HRS	2460.4						
	AFL	1778						
PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01								
31-61-01		PFD 2 (PRIMARY FLIGHT DISPLAY)						Component ATA:31
PN:011-01440-10	MOS/MSC	23-Mar-19	O/C	TSR 0				
SN:18T006047	HRS	1336.4		TSR 0				
	AFL	956		TSR 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01PROC. REF: AMM 31-61-01, AMM 31-61-01								
ATA 32 - LANDING GEAR								
32-00-00-001	^S	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR POLYURETHANE FILMS						Service ATA:32
	MOS	04-May-23						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 32-00-20PROC. REF: AMM 32-00-20								PKG:1
32-000 LEFT MAIN GEAR ASSEMBLY Component ATA:32								
PN:PN	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:UNKNOWN	HRS	1568.6		TSO 0				
	AFL	1125		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-000 RIGHT MAIN GEAR ASSEMBLY Component ATA:32								
PN:PN	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:UNKNOWN	HRS	1568.6		TSO 0				
	AFL	1125		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-001 LEFT MAIN GEAR SHOCK STRUT - MAIN FITTING Component ATA:32								
PN:2310-2206-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1318820/001	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-002 RIGHT MAIN GEAR SHOCK STRUT - MAIN FITTING Component ATA:32								
PN:2310-2206-502	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1315892/001	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-005 NO.1 LEFT MAIN GEAR PINTLE PIN Component ATA:32								
PN:2310-2107-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1302128/012	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-005	NO.1 RIGHT MAIN GEAR PINTLE PIN							Component ATA:32
PN:2310-2107-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1302128/004	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-005	NO.2 LEFT MAIN GEAR PINTLE PIN							Component ATA:32
PN:2310-2107-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1302128/013	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-005	NO.2 RIGHT MAIN GEAR PINTLE PIN							Component ATA:32
PN:2310-2107-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1302128/006	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-006	LEFT MAIN GEAR UPPER AXLE							Component ATA:32
PN:2310-2104-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1302126/010	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-006	RIGHT MAIN GEAR UPPER AXLE							Component ATA:32
PN:2310-2104-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1302139/011	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-007	LEFT MAIN GEAR LOWER AXLE							Component ATA:32
PN:2310-2108-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1290116/004	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-007	RIGHT MAIN GEAR LOWER AXLE							Component ATA:32
PN:2310-2108-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1296600/012	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-008	LEFT MAIN GEAR JACKING PIN							Component ATA:32
PN:2310-2109-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1310141/011	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-008	RIGHT MAIN GEAR JACKING PIN							Component ATA:32
PN:2310-2109-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1310141/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-009	LEFT MAIN GEAR PIN							Component ATA:32
PN:2310-2103-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1287343/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-009	RIGHT MAIN GEAR PIN							Component ATA:32
PN:2310-2103-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1287343/010	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-010	LEFT MAIN GEAR PIN							Component ATA:32
PN:2310-2113-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304704/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-010	RIGHT MAIN GEAR PIN							Component ATA:32
PN:2310-2113-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1290111/004	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-100	LEFT MAIN GEAR TRAILING ARM ASSEMBLY							Component ATA:32
PN:2310-3000-401	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00158	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-100	RIGHT MAIN GEAR TRAILING ARM ASSEMBLY							Component ATA:32
PN:2310-3000-402	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00151	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-101	LEFT MAIN GEAR TRAILING ARM AXLE							Component ATA:32
PN:2310-2102-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1289984/009	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-101	RIGHT MAIN GEAR TRAILING ARM AXLE							Component ATA:32
PN:2310-2102-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1277672/012	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-102	LEFT MAIN GEAR TRAILING ARM							Component ATA:32
PN:2310-3002-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1296608/001	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-103	RIGHT MAIN GEAR TRAILING ARM							Component ATA:32
PN:2310-3002-502	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1299605/004	HRS	2.22		TSN 0				
	AFL	2	19000	TSN 0	19002		17132	
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	LEFT MAIN GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:2310-3010-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1296606/008	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	RIGHT MAIN GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:2310-3010-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1299601/009	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: AMM 32-11-04, AMM 32-11-04PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-11-00-001 ^S	GENERAL VISUAL INSPECTION LEFT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	18-May-26	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
								PKG:80
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-00-001 ^S	GENERAL VISUAL INSPECTION RIGHT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	18-May-26	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
								PKG:80
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-00-002	RESTORE (OVERHAUL) LEFT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	03-Aug-21	O/C					
SN:UNKNOWN	HRS	1568.6						
	AFL	1125						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-00-002	RESTORE (OVERHAUL) RIGHT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	03-Aug-21	O/C					
SN:UNKNOWN	HRS	1568.6						
	AFL	1125						
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-00-003	LUBRICATION OF LEFT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
SN:UNKNOWN	HRS	2523.1						
	AFL	1823	650 (+30/-30)		2473	2503	603 (+30)	
PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00								
32-11-00-003	LUBRICATION OF RIGHT MAIN GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
SN:UNKNOWN	HRS	2523.1						
	AFL	1823	650 (+30/-30)		2473	2503	603 (+30)	
PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00								
32-11-01	LEFT MAIN GEAR SHOCK STRUT							Component ATA:32
PN:2310-2000-601	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00155	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-11-01	RIGHT MAIN GEAR SHOCK STRUT							Component ATA:32
PN:2310-2000-602	MOS/MSC	03-Aug-21	O/C	TSN 137, TSO 0				
SN:00148	HRS	1568.6		TSN 1566.38, TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01PROC. REF: AMM 32-11-01, AMM 32-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-01-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)							Service ATA:32
PN:2310-2000-601	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00155	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-01-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)							Service ATA:32
PN:2310-2000-602	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00148	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-02-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH)							Service ATA:32
PN:2136-1000-405	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00577	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-02-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH)							Service ATA:32
PN:2136-1000-405	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00562	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)							Service ATA:32
PN:2310-4000-407	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00451	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)							Service ATA:32
PN:2310-4000-407	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00444	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-03-004	SERVICING LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Service ATA:32
PN:2310-4000-407	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
SN:00451	HRS	2523.1						
	AFL	1823	650 (+30/-30)		2473	2503	603 (+30)	
PROC. REF: AMM 12-14-02PROC. REF: AMM 12-14-02								
32-11-03-004	SERVICING RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Service ATA:32
PN:2310-4000-407	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
SN:00444	HRS	2523.1						
	AFL	1823	650 (+30/-30)		2473	2503	603 (+30)	
PROC. REF: AMM 12-14-02PROC. REF: AMM 12-14-02								
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)							Service ATA:32
PN:2310-3000-401	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00158	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)							Service ATA:32
PN:2310-3000-402	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00151	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
32-200	LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Component ATA:32
PN:2310-4000-407	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00451	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-200	RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY							Component ATA:32
PN:2310-4000-407	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00444	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1123, TSO 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03PROC. REF: AMM 32-11-03, AMM 32-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-201	LEFT MAIN GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:2310-4102-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1307218/007	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-201	RIGHT MAIN GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:2310-4102-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1307223/005	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-204	LEFT MAIN GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:2310-4201-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1312117/004	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-204	RIGHT MAIN GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:2310-4201-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1298838/008	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-206	LEFT MAIN GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2310-4006-007	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1321038/001	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-206	RIGHT MAIN GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2310-4006-007	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1321038/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-207	LEFT MAIN GEAR SHOCK ABSORBER BEARING CAP							Component ATA:32
PN:2310-4014-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1310157/020	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-207	RIGHT MAIN GEAR SHOCK ABSORBER BEARING CAP							Component ATA:32
PN:2310-4014-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1310157/012	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-00-001 ^S	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR							Service ATA:32
PN:PN	MOS	18-May-26	12 (+1m/-1m)					
SN:UNKNOWN	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
PKG:80								
32-21-00-002	RESTORE (OVERHAUL) NOSE LANDING GEAR ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	03-Aug-21	O/C					
SN:UNKNOWN	HRS	1568.6						
	AFL	1125						
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
32-21-00-003	LUBRICATION OF NOSE LANDING GEAR							Service ATA:32
PN:PN	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
SN:UNKNOWN	HRS	2523.1						
	AFL	1823	650 (+30/-30)		2473	2503	603 (+30)	
PROC. REF: AMM 12-21-00PROC. REF: AMM 12-21-00								
32-21-01	NOSE LANDING GEAR SHOCK STRUT							Component ATA:32
PN:2310-1000-403	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00052	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1496, TSO 0				
PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-01-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY							Service ATA:32
PN:2310-1000-403	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00052	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
32-21-02	NOSE LANDING GEAR RETRACT ACTUATOR ASSEMBLY							Component ATA:32
PN:2135-1000-403	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00168	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-02, AMM 32-21-02PROC. REF: AMM 32-21-02, AMM 32-21-02								
32-21-03	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR ASSEMBLY							Component ATA:32
PN:2137-1000-401	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00162	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-03, AMM 32-21-03PROC. REF: AMM 32-21-03, AMM 32-21-03								
32-21-04-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY							Service ATA:32
PN:2310-1700-403	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00153	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
32-21-05-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER							Service ATA:32
PN:2310-1100-403	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00054	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
32-21-05-004	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER							Service ATA:32
PN:2310-1100-403	MOS	18-May-26	12 (+1m/-1m)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	
SN:00054	HRS	2523.1						
	AFL	1823	650 (+30/-30)		2473	2503	603 (+30)	
PROC. REF: AMM 12-14-03PROC. REF: AMM 12-14-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-06-005 ^S		VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER						Service ATA:32
PN:2310-1500-403	MOS	18-May-26	12 (+1m/-1m)					
SN:00062	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 32-21-06PROC. REF: AMM 32-21-06								PKG:80
32-21-09-001		RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY						Service ATA:32
PN:2310-1400-403	MOS	03-Aug-21	120 (+1m/-1m)		03-Aug-31	03-Sep-31	1824 d (+31)	OVERHAUL
SN:00157	HRS	1568.6						
	AFL	1125	12000 (+30/-30)		13125	13155	11255 (+30)	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
32-300		LEFT MAIN GEAR LOCKING ACTUATOR ASSEMBLY						Component ATA:32
PN:2136-1000-405	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00577	HRS	1568.6		TSO 0				
	AFL	1125		TSN 904, TSO 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-300		RIGHT MAIN GEAR LOCKING ACTUATOR ASSEMBLY						Component ATA:32
PN:2136-1000-405	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00562	HRS	1568.6		TSO 0				
	AFL	1125		TSN 904, TSO 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-301		LEFT MAIN GEAR LOCKING ACTUATOR CYLINDER						Component ATA:32
PN:2136-1013-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1312207/010	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-301		RIGHT MAIN GEAR LOCKING ACTUATOR CYLINDER						Component ATA:32
PN:2136-1013-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1293053/006	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-304	LEFT MAIN GEAR LOCKING ACTUATOR PISTON							Component ATA:32
PN:2136-1035-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304670/010	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-304	RIGHT MAIN GEAR LOCKING ACTUATOR PISTON							Component ATA:32
PN:2136-1035-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304670/001	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-305	LEFT MAIN GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:2136-1050-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305306/007	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-305	RIGHT MAIN GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:2136-1050-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305307/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-306	LEFT MAIN GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:2136-1020-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304426/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-306	RIGHT MAIN GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:2136-1020-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1306099/006	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-307	LEFT MAIN GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:2136-1046-007	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1303530/007	HRS	2.22		TSN 0				
	AFL	2	19500	TSN 0	19502		17632	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-307	RIGHT MAIN GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:2136-1046-007	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1303530/004	HRS	2.22		TSN 0				
	AFL	2	19500	TSN 0	19502		17632	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-309	LEFT MAIN GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:2136-1049-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305262/002	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-309	RIGHT MAIN GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:2136-1049-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305262/006	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-31-01	LANDING GEAR CONTROL LEVER PANEL							Component ATA:32
PN:827101-5	MOS/MSC	10-Nov-16	O/C	TSR 30				
SN:1077	HRS	1010.6		TSR 0				
	AFL	726		TSR 0				
PROC. REF: AMM 32-31-01, AMM 32-31-01PROC. REF: AMM 32-31-01, AMM 32-31-01								
32-31-02	LANDING GEAR HYDRAULIC SYSTEM (MANIFOLD) ASSEMBLY							Component ATA:32
PN:72375-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0168	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-02, AMM 32-31-02PROC. REF: AMM 32-31-02, AMM 32-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-310	LEFT MAIN GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:2136-1036-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305286/006	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-310	RIGHT MAIN GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:2136-1036-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305289/007	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-311	LEFT MAIN GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:2136-1005-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304668/012	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-311	RIGHT MAIN GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:2136-1005-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304668/007	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-312	LEFT MAIN GEAR LOCKING ACTUATOR NUT							Component ATA:32
PN:2136-1042-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305298/005	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-312	RIGHT MAIN GEAR LOCKING ACTUATOR NUT							Component ATA:32
PN:2136-1042-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1305298/001	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-313	LEFT MAIN GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:2136-1008-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1299578/013	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-313	RIGHT MAIN GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:2136-1008-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1306948/003	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-314	LEFT MAIN GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:MEKS12EL	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:13	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-314	RIGHT MAIN GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:MEKS12EL	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:29	HRS	2.22		TSN 0				
	AFL	2	21000	TSN 0	21002		19132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-35-00-001 ^S	FUNCTIONAL CHECK OF EMERGENCY EXTENSION SYSTEM							Service ATA:32
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 32-35-00PROC. REF: AMM 32-35-00								PKG:81
32-35-00-002 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES							Service ATA:32
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-35-00PROC. REF: AMM 32-35-00								
32-400	NOSE LANDING GEAR ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:UNKNOWN	HRS	1568.6		TSO 0				
	AFL	1125		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-401	LEFT SIDE NLG SIDE PINTLE PIN							Component ATA:32
PN:2310-1137-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1294216/007	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-401	RIGHT SIDE NLG SIDE PINTLE PIN							Component ATA:32
PN:2310-1137-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1294216/008	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-402	NOSE LANDING GEAR MAIN FITTING							Component ATA:32
PN:2310-1204-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1294311/002	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-404 (1)	NOSE LANDING GEAR TORQUE LINK							Component ATA:32
PN:2310-1124-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304696/001	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-07, AMM 32-21-07PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-406	NOSE LANDING GEAR SHOCK STRUT PIN							Component ATA:32
PN:2310-1407-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1262075/012	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-21-01, AMM 32-21-01PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-407 NOSE LANDING GEAR AXLE								Component ATA:32
PN:2310-1165-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1264806/002	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-408 NOSE LANDING GEAR STEERING BELLCRANK								Component ATA:32
PN:2310-1131-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1296498/003	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-409 NOSE LANDING GEAR SHIMMY DAMPER								Component ATA:32
PN:2310-1500-403	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00062	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1496, TSO 0				
PROC. REF: AMM 32-21-06, AMM 32-21-06PROC. REF: AMM 32-21-06, AMM 32-21-06								
32-41-01 DIGITAL BRAKE CONTROL UNIT								Component ATA:32
PN:90005034-7	MOS/MSC	05-May-20	O/C					
SN:MAY09-1055	HRS	1467.9		TSN 1516				
	AFL	1046		TSN 1532				
PROC. REF: AMM 32-41-01, AMM 32-41-01PROC. REF: AMM 32-41-01, AMM 32-41-01								
32-41-02 LH BRAKE PEDAL TRANSDUCER								Component ATA:32
PN:Q3008	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:832950	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02PROC. REF: AMM 32-41-02, AMM 32-41-02								
32-41-02 RH BRAKE PEDAL TRANSDUCER								Component ATA:32
PN:Q3008	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:832951	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-02, AMM 32-41-02PROC. REF: AMM 32-41-02, AMM 32-41-02								
32-41-02-001	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS/MSC	23-Mar-18	O/C					
SN:832950	HRS	1211.4						
	AFL	870						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								
32-41-02-001	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS/MSC	23-Mar-18	O/C					
SN:832951	HRS	1211.4						
	AFL	870						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								
32-41-02-002 ^S	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS	04-Jun-25						
SN:832950	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:10
32-41-02-002 ^S	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER							Service ATA:32
PN:Q3008	MOS	04-Jun-25						
SN:832951	HRS	2224.4	1600 (+30/-30)					
	AFL	1614						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:10
32-41-03	MAIN BRAKE SHUT-OFF VALVE							Component ATA:32
PN:90005027	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:MAR09-0150	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-03PROC. REF: AMM 32-41-03, AMM 32-41-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-04	LH BRAKE CONTROL VALVE							Component ATA:32
PN:90005035-2	MOS/MSC	01-Nov-11	O/C					
SN:09-12-0444	HRS	232.9						
	AFL	146						
PROC. REF: AMM 32-41-04, AMM 32-41-04PROC. REF: AMM 32-41-04, AMM 32-41-04								
32-41-04	RH BRAKE CONTROL VALVE							Component ATA:32
PN:90005035-2	MOS/MSC	01-Nov-11	O/C					
SN:09-10-0425	HRS	232.9						
	AFL	146						
PROC. REF: AMM 32-41-04, AMM 32-41-04PROC. REF: AMM 32-41-04, AMM 32-41-04								
32-41-05	LH MAIN BRAKE SYSTEM PRESSURE TRANSDUCER							Component ATA:32
PN:90005191-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:AUG09-0371	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-05, AMM 32-41-05PROC. REF: AMM 32-41-05, AMM 32-41-05								
32-41-05	RH MAIN BRAKE SYSTEM PRESSURE TRANSDUCER							Component ATA:32
PN:90005191-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:JUL09-0366	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-05, AMM 32-41-05PROC. REF: AMM 32-41-05, AMM 32-41-05								
32-41-06	LEFT MAIN GEAR WHEEL SPEED TRANSDUCER							Component ATA:32
PN:90005036	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:APR09-0326	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06PROC. REF: AMM 32-41-06, AMM 32-41-06								
32-41-06	RIGHT MAIN GEAR WHEEL SPEED TRANSDUCER							Component ATA:32
PN:90005036	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:APR09-0327	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06PROC. REF: AMM 32-41-06, AMM 32-41-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-11-001	^S	FUNCTIONAL CHECK OF BRAKE HYDRAULIC ACCUMULATOR						Service ATA:32
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-11PROC. REF: AMM 32-41-11								PKG:50
32-410	NOSE LANDING GEAR WHEEL AXLE							Component ATA:32
PN:2317-5101-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1294382/006	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-411	NOSE LANDING GEAR LOCK PIN							Component ATA:32
PN:57675-1	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:144	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-412	NOSE LANDING GEAR AXLE BOLT							Component ATA:32
PN:2310-1144-005	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1299619/006	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-413	NOSE LANDING GEAR BOLT							Component ATA:32
PN:2310-1172-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1293334/009	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-414	NOSE LANDING GEAR PIN							Component ATA:32
PN:2310-1173-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1280867/011	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-415	NOSE LANDING GEAR BOLT							Component ATA:32
PN:2310-1183-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1275188/004	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-43-00-001	FUNCTIONAL CHECK OF EMERGENCY/PARKING BRAKE SYSTEM							Service ATA:32
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)		2716.8	2746.8	117.1 (+30)	
	AFL	1354						
PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00								PKG:1
32-43-01-001	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM							Service ATA:32
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)		2716.8	2746.8	117.1 (+30)	
	AFL	1354						
PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00								PKG:1
32-43-02	EMERGENCY/PARKING BRAKE VALVE							Component ATA:32
PN:11056-7	MOS/MSC	03-Aug-21	O/C	TSO 5				
SN:0794	HRS	1568.6		TSO 0				
	AFL	1125		TSO 0				
PROC. REF: AMM 32-43-02, AMM 32-43-02PROC. REF: AMM 32-43-02, AMM 32-43-02								
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR							Component ATA:32
PN:0860231003	MOS/MSC	03-Aug-21	O/C	TSN 0				
SN:60231-2413	HRS	1568.6		TSN 0				
	AFL	1125		TSN 0				
PROC. REF: AMM 32-43-04, AMM 32-43-04PROC. REF: AMM 32-43-04, AMM 32-43-04								
32-43-05	EMERGENCY/PARKING BRAKE PRESSURE SWITCH							Component ATA:32
PN:15H0126PH	MOS/MSC	03-Aug-21	O/C	TSN 26				
SN:0673	HRS	1568.6		TSN 0				
	AFL	1125		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-43-05, AMM 32-43-05PROC. REF: AMM 32-43-05, AMM 32-43-05								
32-43-06 EMERGENCY/PARKING BRAKE PRESSURE- TRANSDUCER								Component ATA:32
PN:APT-218A-1000-3000AMOS/MSC		23-Mar-10	O/C	TSN 0				
SN:7539-9-46	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-06, AMM 32-43-06PROC. REF: AMM 32-43-06, AMM 32-43-06								
32-43-11 EMERGENCY/PARKING BRAKE SHUT OFF VALVE								Component ATA:32
PN:2216-0001-401	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00153	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-11, AMM 32-43-11PROC. REF: AMM 32-43-11, AMM 32-43-11								
32-43-11-001 OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE								Service ATA:32
PN:2216-0001-401	MOS	18-May-26	12 (+30d/-30d)	Adj 17d	04-Jun-27	04-Jul-27	303 d (+30)	AIRWORTHINESS
SN:00153	HRS	2523.1	800 (+30/-30)		3323.1	3353.1	723.4 (+30)	
	AFL	1823						
PROC. REF: AMM 32-43-11PROC. REF: AMM 32-43-11								
32-43-11-002 OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE								Service ATA:32
PN:2216-0001-401	MOS/MSC	23-Mar-10	N/A					
SN:00153	HRS	0						
	AFL	0						
PROC. REF: AMM 32-43-11PROC. REF: AMM 32-43-11								
32-45-01 LH MLG. 21X6.5-10 12PR TIRE								Component ATA:32
PN:215K26-2	MOS/MSC	14-Oct-25	O/C	TSN 8				
SN:33410113	HRS	2356.1		TSN 0				
	AFL	1707		TSN 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-01 RH MLG 21X6.5-10 12PR TIRE								Component ATA:32
PN:215K26-2	MOS/MSC	14-Oct-25	O/C	TSN 8				
SN:33410111	HRS	2356.1		TSN 0				
	AFL	1707		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-01-001	RESTORATION (OVERHAUL) OF LH MLG. WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	17-Oct-20	T/C					
SN:NOV16-1151	HRS	1517.2						
	AFL	1084	1500 (+30/-30)		2584	2614	714 (+30)	
PROC. REF: SMR 500-32-0012, AMM 32-45-00PROC. REF: SMR 500-32-0012, AMM 32-45-00								
32-45-01-001	RESTORATION (OVERHAUL) OF RH MLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	23-Mar-18	T/C					
SN:AUG09-0403	HRS	1211.4						
	AFL	870	1500 (+30/-30)		2370	2400	500 (+30)	
PROC. REF: SMR 500-32-0012, AMM 32-45-00PROC. REF: SMR 500-32-0012, AMM 32-45-00								
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LH MLG. WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	17-Oct-20	O/C					
SN:NOV16-1151	HRS	1517.2						
	AFL	1084						
PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00								
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RH MLG WHEEL ASSEMBLY							Service ATA:32
PN:500-19026-605	MOS/MSC	22-Sep-20	O/C					
SN:AUG09-0403	HRS	1508.9						
	AFL	1078						
PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00								
32-45-02	LH MLG. 21X6.5-10, AL WHEEL							Component ATA:32
PN:90005024	MOS/MSC	14-Oct-25	O/C	TSO 61				
SN:NOV16-1151	HRS	2356.1		TSO 838.9				
	AFL	1707		TSO 623				
PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-02	RH MLG 21X6.5-10, AL WHEEL							Component ATA:32
PN:90005116	MOS/MSC	14-Oct-25	O/C					
SN:AUG09-0403	HRS	2356.1						
	AFL	1707						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-45-02, AMM 32-45-02PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-03 LH MLG. WHEEL ASSEMBLY								Component ATA:32
PN:500-19026-605	MOS/MSC	14-Oct-25	O/C	TSO 61				
SN:NOV16-1151	HRS	2356.1		TSO 838.9				
	AFL	1707		TSO 623				
PROC. REF: AMM 32-45-01, AMM 32-45-01PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-03 RH MLG WHEEL ASSEMBLY								Component ATA:32
PN:500-19026-605	MOS/MSC	14-Oct-25	O/C	TSN 102				
SN:AUG09-0403	HRS	2356.1		TSN 1144.7				
	AFL	1707		TSN 837				
PROC. REF: AMM 32-45-01, AMM 32-45-01PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-10 NLG 15X6.0-6 10PR TIRE								Component ATA:32
PN:156E06B1	MOS/MSC	04-Jun-25	O/C	TSN 0				
SN:41790269	HRS	2224.4		TSN 0				
	AFL	1614		TSN 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-11 NLG WHEEL ASSEMBLY								Component ATA:32
PN:500-19001-601	MOS/MSC	04-Jun-25	O/C	TSO 5				
SN:JUN09-0226	HRS	2224.4		TSO 0				
	AFL	1614		TSO 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-11-001 RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY								Service ATA:32
PN:500-19001-601	MOS/MSC	04-Jun-25	T/C					
SN:JUN09-0226	HRS	2224.4						
	AFL	1614	1500 (+30/-30)	3114	3144	1244 (+30)		
PROC. REF: SMR 500-32-0012, AMM 32-45-00PROC. REF: SMR 500-32-0012, AMM 32-45-00								
32-45-11-002 SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NLG WHEEL ASSEMBLY								Service ATA:32
PN:500-19001-601	MOS/MSC	04-Jun-25	O/C					
SN:JUN09-0226	HRS	2224.4						
	AFL	1614						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-45-00PROC. REF: AMM 32-45-00								
32-45-12 NLG 15X6.0-6, AL WHEEL								Component ATA:32
PN:90005023-1	MOS/MSC	04-Jun-25	O/C	TSO 5				
SN:JUN09-0226	HRS	2224.4		TSO 0				
	AFL	1614		TSO 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-21 LH MLG. STEEL BRAKE ASSEMBLY								Component ATA:32
PN:90005025-3	MOS/MSC	24-Feb-26	O/C	TSO 4				
SN:JUN08-0050	HRS	2460.4		TSO 0				
	AFL	1778		TSO 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-45-21 RH MLG STEEL BRAKE ASSEMBLY								Component ATA:32
PN:90005025-3	MOS/MSC	25-Apr-24	O/C	TSO 2				
SN:AUG10-0555	HRS	2034.9		TSO 0				
	AFL	1464		TSO 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-45-21-20 LH MLG. SHUTTLE VALVE								Component ATA:32
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-45-21-20 RH MLG SHUTTLE VALVE								Component ATA:32
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-500 NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER								Component ATA:32
PN:2310-1100-403	MOS/MSC	03-Aug-21	O/C	TSO 0				
SN:00054	HRS	1568.6		TSO 0				
	AFL	1125		TSN 1496, TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-501	NOSE LANDING GEAR SHOCK ABSORBER PISTON TUBE							Component ATA:32
PN:2310-1225-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1262111/004	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-502	NOSE LANDING GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2310-1221-009	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1296655/003	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-504	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER							Component ATA:32
PN:2310-1241-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1311063/003	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-506	NOSE LANDING GEAR SHOCK ABSORBER FORK							Component ATA:32
PN:2310-1308-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1301542/002	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-600	NLG DRAG BRACE ASSEMBLY							Component ATA:32
PN:2310-1400-403	MOS/MSC	03-Aug-21	O/C	TSN 137, TSO 0				
SN:00157	HRS	1568.6		TSN 1566.38, TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-601	NOSE LANDING GEAR UPPER DRAG BRACE							Component ATA:32
PN:2310-1424-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1301544/002	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-603	NOSE LANDING GEAR LOWER DRAG BRACE							Component ATA:32
PN:2310-1451-005	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1287414/007	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-605	LEFT SIDE NLG DRAG BRACE PINTLE PIN							Component ATA:32
PN:2310-1415-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1294218/008	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-605	RIGHT SIDE NLG DRAG BRACE PINTLE PIN							Component ATA:32
PN:2310-1415-003	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1280255/003	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-606	NOSE LANDING GEAR DRAG BRACE PIN							Component ATA:32
PN:2310-1407-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1262075/009	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-09, AMM 32-21-09PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-61-01	LH MLG. PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:21770	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-61-01	NO. 1 NLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:23424	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-61-01	RH MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:23389	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-61-02	LH MLG. PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-61-02	RH MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-700	NLG LOCKING STAY ASSEMBLY							Component ATA:32
PN:2310-1700-403	MOS/MSC	03-Aug-21	O/C	TSN 137, TSO 0				
SN:00153	HRS	1568.6		TSN 1566.38, TSO 0				
	AFL	1125		TSN 1125, TSO 0				
PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-701	LOWER NLG LOCKING STAY							Component ATA:32
PN:2310-1712-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304697/006	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-703	UPPER NLG LOCKING STAY							Component ATA:32
PN:2310-1722-501	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1294178/003	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-706	LOWER NLG LOCKING STAY BOLT							Component ATA:32
PN:2310-1734-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304715/003	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-706	UPPER NLG LOCKING STAY BOLT							Component ATA:32
PN:2310-1734-001	MOS	23-Mar-10		TSN 0				LIFE LIMIT
SN:1304715/002	HRS	2.22		TSN 0				
	AFL	2	35000	TSN 0	35002		33132	
PROC. REF: AMM 32-21-04, AMM 32-21-04PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-801	BRAKE SYSTEM ACCUMULATOR							Component ATA:32
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-11, AMM 32-41-11PROC. REF: AMM 32-41-11, AMM 32-41-11								
ATA 33 - LIGHTS								
33-01-01	UPPER COCKPIT LIGHTING SYSTEM CONTROL PANEL							Component ATA:33
PN:441-40941-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0169	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-01-01, AMM 33-01-01PROC. REF: AMM 33-01-01, AMM 33-01-01								
33-12-01	FORWARD FUSELAGE BOTTOM DIMMER							Component ATA:33
PN:81-01760-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0205	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-01, AMM 33-12-01PROC. REF: AMM 33-12-01, AMM 33-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-12-02	MAIN TEST ANUNCIATOR/FIRE PANEL ASSEMBLY							Component ATA:33
PN:441-43213-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0166	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02, AMM 33-12-02PROC. REF: AMM 33-12-02, AMM 33-12-02								
33-21-05	PASSENGER-CABIN LED LIGHT DIMMER							Component ATA:33
PN:AS-33-0038-001	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0045	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-21-05, AMM 33-21-05PROC. REF: AMM 33-21-05, AMM 33-21-05								
33-31-02	W001 ELECTRICAL NOSE HARNESS							Component ATA:33
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-41-01	LEFT LANDING/TAXI LIGHT							Component ATA:33
PN:81012-3	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:000179	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-01, AMM 33-41-01PROC. REF: AMM 33-41-01, AMM 33-41-01								
33-41-01	RIGHT LANDING/TAXI LIGHT							Component ATA:33
PN:81012-4	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:000174	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-01, AMM 33-41-01PROC. REF: AMM 33-41-01, AMM 33-41-01								
33-43-01	LH WING NAVIGATION/STROBE LIGHTS							Component ATA:33
PN:84016-1	MOS/MSC	04-Apr-22	O/C	TSN 86				
SN:000214	HRS	1682.2		TSN 0				
	AFL	1192		TSN 0				
PROC. REF: AMM 33-43-01, AMM 33-43-01PROC. REF: AMM 33-43-01, AMM 33-43-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-43-01	RH WING NAVIGATION/STROBE LIGHTS							Component ATA:33
PN:84016-2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:000197	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01, AMM 33-43-01PROC. REF: AMM 33-43-01, AMM 33-43-01								
33-43-01-001	DISCARD LH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-1	MOS	04-Apr-22						
SN:000214	HRS	1682.2	8000 (+30/-30)		9682.2	9712.2	7082.5 (+30)	
	AFL	1192						
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
33-43-01-001	DISCARD RH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-2	MOS	23-Mar-10						
SN:000197	HRS	0	8000 (+30/-30)		8000	8030	5400.3 (+30)	
	AFL	0						
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
33-43-01-002 ^S	GENERAL VISUAL INSPECTION OF LH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-1	MOS	24-Feb-26						
SN:000214	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
PKG:20								
33-43-01-002 ^S	GENERAL VISUAL INSPECTION OF RH WING NAVIGATION/STROBE LIGHTS							Service ATA:33
PN:84016-2	MOS	24-Feb-26						
SN:000197	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
PKG:20								
ATA 34 - NAVIGATION								
34-11-00-001	FUNCTIONAL CHECK OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT							Service ATA:34
PN:011-04489-30	MOS	18-May-26	24 (+1m/-1m)		01-Apr-28 (M)	01-May-28	605 d (+30)	
SN:5MZ125532	HRS	2523.1						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
	AFL	1823						
PROC. REF: AMM 34-11-00PROC. REF: AMM 34-11-00								
34-11-01	INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT							Component ATA:34
PN:011-04489-30	MOS/MSC	18-May-26	O/C	TSN 10				
SN:5MZ125532	HRS	2523.1		TSN 0				
	AFL	1823		TSN 0				
PROC. REF: AMM 34-11-01, AMM 34-11-01PROC. REF: AMM 34-11-01, AMM 34-11-01								
34-11-02	PITOT-STATIC PROBE							Component ATA:34
PN:101469-4-004	MOS/MSC	05-May-20	O/C	TSN 10				
SN:ER1293	HRS	1467.9		TSN 0				
	AFL	1046		TSN 0				
PROC. REF: AMM 34-11-02, AMM 34-11-02PROC. REF: AMM 34-11-02, AMM 34-11-02								
34-11-02-001	RESTORATION (CLEANING) OF PITOT-STATIC PROBE							Service ATA:34
PN:101469-4-004	MOS	29-Apr-26	24 (+1m/-1m)	Adj -4d	25-Apr-28	25-May-28	629 d (+30)	
SN:ER1293	HRS	2510.7						
	AFL	1815						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
34-15-00-001	FUNCTIONAL CHECK OF AIR DATA SYSTEM							Service ATA:34
	MOS	29-Apr-26	24 (+1m/-1m)	Adj -11d	18-Apr-28	18-May-28	622 d (+30)	
	HRS	2510.7						
	AFL	1815						
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00								
34-15-00-002 ^S	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS							Service ATA:34
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00								

PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-15-00-003 ^S	SPECIAL DETAILED INSPECTION OF STATIC PORT SURROUNDING PLATE FOR FLUSHNESS							Service ATA:34
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 34-15-00PROC. REF: AMM 34-15-00								PKG:81
34-15-01	NO. 1 GDC 74B AIR DATA COMPUTER UNIT							Component ATA:34
PN:011-01110-00	MOS/MSC	17-Mar-14	O/C					
SN:43805877	HRS	605.2						
	AFL	428						
PROC. REF: AMM 34-15-01, AMM 34-15-01PROC. REF: AMM 34-15-01, AMM 34-15-01								
34-15-01	NO. 2 GDC 74B AIR DATA COMPUTER UNIT							Component ATA:34
PN:011-01110-00	MOS/MSC	17-Mar-14	O/C					
SN:43805878	HRS	605.2						
	AFL	428						
PROC. REF: AMM 34-15-01, AMM 34-15-01PROC. REF: AMM 34-15-01, AMM 34-15-01								
34-15-03	LH FWD PITOT TUBE							Component ATA:34
PN:1851LW	MOS/MSC	31-Mar-17	O/C	TSN 0				
SN:318530	HRS	1059.8		TSN 0				
	AFL	760		TSN 0				
PROC. REF: AMM 34-15-03, AMM 34-15-03PROC. REF: AMM 34-15-03, AMM 34-15-03								
34-15-03	RH FWD PITOT TUBE							Component ATA:34
PN:0851LW	MOS/MSC	31-Mar-17	O/C	TSN 0				
SN:318531	HRS	1059.8		TSN 0				
	AFL	760		TSN 0				
PROC. REF: AMM 34-15-03, AMM 34-15-03PROC. REF: AMM 34-15-03, AMM 34-15-03								
34-15-03-001 ^S	RESTORATION (CLEANING) OF PITOT PROBE							Service ATA:34
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 34-15-03PROC. REF: AMM 34-15-03								PKG:81

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-15-05	LH FWD DUAL STATIC PORT							Component ATA:34
PN:100442-106	MOS/MSC	12-May-11	O/C	TSN 0				
SN:867710	HRS	169.4		TSN 0				
	AFL	106		TSN 0				
PROC. REF: AMM 34-15-05, AMM 34-15-05PROC. REF: AMM 34-15-05, AMM 34-15-05								
34-15-05	RH FWD DUAL STATIC PORT							Component ATA:34
PN:100442-107	MOS/MSC	12-May-11	O/C	TSN 0				
SN:867720	HRS	169.4		TSN 0				
	AFL	106		TSN 0				
PROC. REF: AMM 34-15-05, AMM 34-15-05PROC. REF: AMM 34-15-05, AMM 34-15-05								
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER							Service ATA:34
PN:011-00870-00	MOS	04-Jun-25	36 (+1m/-1m)					
SN:47512342	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 34-21-02PROC. REF: AMM 34-21-02								PKG:82
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER							Service ATA:34
PN:011-00870-10	MOS	04-Jun-25	36 (+1m/-1m)					
SN:1CM010008	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 34-21-02PROC. REF: AMM 34-21-02								PKG:82
34-21-01	LH ATTITUDE AND HEADING REFERENCE UNIT							Component ATA:34
PN:011-00870-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:42011544	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-01, AMM 34-21-01PROC. REF: AMM 34-21-01, AMM 34-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-01	RH ATTITUDE AND HEADING REFERENCE UNIT							Component ATA:34
PN:011-00868-10	MOS/MSC	14-Jun-12	O/C					
SN:42011258	HRS	313.8						
	AFL	197						
PROC. REF: AMM 34-21-01, AMM 34-21-01PROC. REF: AMM 34-21-01, AMM 34-21-01								
34-21-02	LH WING MAGNETOMETER							Component ATA:34
PN:011-00870-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:47512342	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-02, AMM 34-21-02PROC. REF: AMM 34-21-02, AMM 34-21-02								
34-21-02	RH WING MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	03-Aug-23	O/C					
SN:1CM010008	HRS	1983.5						
	AFL	1391						
PROC. REF: AMM 34-21-02, AMM 34-21-02PROC. REF: AMM 34-21-02, AMM 34-21-02								
34-23-00-001 ^S	FUNCTIONAL CHECK OF STANDBY COMPASS							Service ATA:34
PN:KCA0120W	MOS	04-Jun-25	36 (+1m/-1m)					
SN:BD7091009	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 34-23-00PROC. REF: AMM 34-23-00								
34-23-01	MAGNETIC COMPASS							Component ATA:34
PN:KCA0120W	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:BD7091009	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01, AMM 34-23-01PROC. REF: AMM 34-23-01, AMM 34-23-01								
34-32-01	TAIL PHASING COUPLER							Component ATA:34
PN:SSPD-113-10	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:6217	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-01, AMM 34-32-01PROC. REF: AMM 34-32-01, AMM 34-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-32-03	LEFT VOR/LOC 2&3 ANTENNA BLADE							Component ATA:34
PN:S65-247170	MOS/MSC	23-Mar-19	O/C	TSN 11				
SN:173-6065	HRS	1336.4		TSN 0				
	AFL	956		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03PROC. REF: AMM 34-32-03, AMM 34-32-03								
34-32-03	RIGHT VOR/LOC 2&3 ANTENNA BLADE							Component ATA:34
PN:S65-247170	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:173-2160	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03PROC. REF: AMM 34-32-03, AMM 34-32-03								
34-32-04	LW FWR MARKER BEACON ANTENNA							Component ATA:34
PN:S35-1000-2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:102-8304	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-04, AMM 34-32-04PROC. REF: AMM 34-32-04, AMM 34-32-04								
34-42-01	WEATHER RADAR ANTENNA							Component ATA:34
PN:011-00883-20	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:47203058	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-43-00	BAGGAGE COMPARTMENT GTS 850 TRAFFIC PROCESSOR UNIT							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-43-02	TRC899 TRANSMITTER RECEIVER COMPUTER							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-43-05	LOWER DIRECTIONAL ANTENNA							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-05, AMM 34-43-05PROC. REF: AMM 34-43-05, AMM 34-43-05								
34-43-05	UPPER DIRECTIONAL ANTENNA							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-05, AMM 34-43-05PROC. REF: AMM 34-43-05, AMM 34-43-05								
34-43-08	LOW NOISE (TCAS) POWER AMPLIFIER							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-08, AMM 34-43-08PROC. REF: AMM 34-43-08, AMM 34-43-08								
34-51-01	NO.1 CENTER DISTANCE MEASURING EQUIP UNIT							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01, AMM 34-51-01PROC. REF: AMM 34-51-01, AMM 34-51-01								
34-51-01	NO.2 CENTER DISTANCE MEASURING EQUIP UNIT							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01, AMM 34-51-01PROC. REF: AMM 34-51-01, AMM 34-51-01								
34-51-02	NO. 1 DME L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:261-86020	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02, AMM 34-51-02PROC. REF: AMM 34-51-02, AMM 34-51-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-51-02	NO. 2 DME L BAND ANTENNA							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02, AMM 34-51-02PROC. REF: AMM 34-51-02, AMM 34-51-02								
34-52-00-001	FUNCTIONAL CHECK LH TRANSPONDER MODULE TRANSPONDER SYSTEM							Service ATA:34
PN:011-00779-30	MOS	29-Apr-26	24	Adj -11d	18-Apr-28		622 d	
SN:89107089	HRS	2510.7						
	AFL	1815						
PROC. REF: AMM 34-52-00PROC. REF: AMM 34-52-00								
34-52-00-001	FUNCTIONAL CHECK RH TRANSPONDER MODULE TRANSPONDER SYSTEM							Service ATA:34
PN:011-00779-01	MOS/MSC	06-Apr-20	N/A					
SN:UNKNOWN	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 34-52-00PROC. REF: AMM 34-52-00								
34-52-01	LH TRANSPONDER MODULE							Component ATA:34
PN:011-00779-30	MOS/MSC	31-Mar-17	O/C					
SN:89107089	HRS	1059.8						
	AFL	760						
PROC. REF: AMM 34-52-01, AMM 34-52-01PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-01	RH TRANSPONDER MODULE							Component ATA:34
PN:011-00779-01	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-01, AMM 34-52-01PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-02	BOTTOM TRANSPONDOR 1 L BAND ANTENNA							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02PROC. REF: AMM 34-52-02, AMM 34-52-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-52-02	TOP TRANSPONDOR 2 L BAND ANTENNA							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02PROC. REF: AMM 34-52-02, AMM 34-52-02								
34-52-04	COAXIAL SWITCH							Component ATA:34
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-04, AMM 34-52-04PROC. REF: AMM 34-52-04, AMM 34-52-04								
34-56-02	LH TOP CENTER GPS WAAS - GA 36 ANTENNA							Component ATA:34
PN:010-107200-00	MOS/MSC	27-May-10	O/C					
SN:UNKNOWN	HRS	23.4						
	AFL							
PROC. REF: AMM 34-56-02, AMM 34-56-02PROC. REF: AMM 34-56-02, AMM 34-56-02								
34-56-02	RH TOP CENTER WAAS & SATELLITE WEATHER AND RADAR ANTENNA							Component ATA:34
PN:010-107200-00	MOS/MSC	27-May-10	O/C					
SN:UNKNOWN	HRS	23.4						
	AFL							
PROC. REF: AMM 34-56-02, AMM 34-56-02PROC. REF: AMM 34-56-02, AMM 34-56-02								
34-57-01	SATELLITE WEATHER AND RADIO RECIEVER							Component ATA:34
PN:011-00987-00	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:47762588	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01, AMM 34-57-01PROC. REF: AMM 34-57-01, AMM 34-57-01								
34-61-01	FLIGHT MANAGEMENT SYSTEM PANEL							Component ATA:34
PN:011-01054-10	MOS/MSC	05-May-20	O/C	TSR 2				
SN:21805097	HRS	1467.9		TSR 0				
	AFL	1046		TSR 0				
PROC. REF: AMM 34-61-01, AMM 34-61-01PROC. REF: AMM 34-61-01, AMM 34-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341101-001 ^U	INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT BACKUP BATTERY CHECK PER ICA 190-02246-11							Service ATA:34
PN:011-04489-30	MOS	18-May-26	12		18-May-27		286 d	ICA
SN:5MZ125532	HRS							
	AFL							
341101-002 ^U	INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT AHRS MAGNETIC FIELD UPDATE PER ICA 190-2246-11							Service ATA:34
PN:011-04489-30	MOS/MSC	18-May-26	DUE		01-Jan-30 (M)		1245 d	
SN:5MZ125532	HRS							
	AFL							
Expiry Date: : 01-Jan-30								
34FAR01 ^U	FUNCTIONAL CHECK INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT (FAR 91.411)							Service ATA:34
PN:011-04489-30	MOS	18-May-26	24		01-Apr-28 (M)		605 d	FAR
SN:5MZ125532	HRS	2523.1						
	AFL	1823						
34FAR02 ^U	FUNCTIONAL CHECK OF AIR DATA SYSTEM (FAR 91.411)							Service ATA:34
	MOS	29-Apr-26	24		29-Apr-28		633 d	FAR
	HRS	2510.7						
	AFL	1815						
34FAR04 ^U	FUNCTIONAL CHECK NO. 1 TRANSPONDER SYSTEM (FAR 91.413)							Service ATA:34
	MOS	29-Apr-26	24		29-Apr-28		633 d	FAR
	HRS	2510.7						
	AFL	1815						
ATA 35 - OXYGEN								
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE							Service ATA:35
	MOS	04-Jun-25	36 (+30d/-30d)		04-Jun-28	04-Jul-28	669 d (+30)	AIRWORTHINESS
	HRS	2224.4	1800 (+30/-30)		4024.4	4054.4	1424.7 (+30)	
	AFL	1614						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-01-00-001	^S	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION						Service ATA:35
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 35-01-02PROC. REF: AMM 35-01-02								
35-01-02		OXYGEN CYLINDER PRESSURE AND TEMPERATURE TRANSDUCER						Component ATA:35
PN:4441125-000	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:7536-8-87	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-02, AMM 35-01-02PROC. REF: AMM 35-01-02, AMM 35-01-02								
35-01-05		OXYGEN SYSTEM LOW PRESSURE SWITCH						Component ATA:35
PN:4421134-000	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0224	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-05, AMM 35-01-05PROC. REF: AMM 35-01-05, AMM 35-01-05								
35-01-06		LH CSL OXYGEN SYSTEM CONTROL PANEL						Component ATA:35
PN:441-40945-002	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0148	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-06, AMM 35-01-06PROC. REF: AMM 35-01-06, AMM 35-01-06								
35-01-07		OXYGEN SYSTEM CABIN ALTITUDE SWITCH						Component ATA:35
PN:4421133-000	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0850205	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-07, AMM 35-01-07PROC. REF: AMM 35-01-07, AMM 35-01-07								
35-01-09		CENTER FUSELAGE ALTITUDE COMPENSATING REGULATOR						Component ATA:35
PN:4421135-001	MOS/MSC	12-May-11	O/C	TSN 0				
SN:00183	HRS	169.4		TSN 0				
	AFL	106		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-01-09, AMM 35-01-09PROC. REF: AMM 35-01-09, AMM 35-01-09								
35-01-10	OXYGEN LOW PRESSURE 3 POSITION VALVE							Component ATA:35
PN:4421132-109	MOS/MSC	09-Jun-10	O/C					
SN:00049	HRS	32.2						
	AFL							
PROC. REF: AMM 35-01-10, AMM 35-01-10PROC. REF: AMM 35-01-10, AMM 35-01-10								
35-02-01	50 CU.FT OXYGEN CYLINDER							Component ATA:35
PN:4441122-050	MOS/MSC	18-Jan-24	O/C	TSO 0				
SN:0086-887	HRS	2011.6		TSO 0				
	AFL	1437		TSO 0				
PROC. REF: AMM 35-02-01, AMM 35-02-01PROC. REF: AMM 35-02-01, AMM 35-02-01								
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR							Service ATA:35
PN:4441122-050	MOS	09-Dec-23	60		09-Dec-28		857 d	
SN:0086-887	HRS	2011.6						
	AFL	1437						
HydroCheck Date: : 09-Dec-23								
PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01								
35-02-01-003	DISCARD OF OXYGEN CYLINDER							Service ATA:35
PN:4441122-050	MOS	09-Dec-23	180		09-Dec-38		4509 d	
SN:0086-887	HRS	2011.6						
	AFL	1437						
Manufacture Date:: 09-Dec-23								
PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01								
35-02-01-004	RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER							Service ATA:35
PN:4441122-050	MOS	09-Dec-23	60		09-Dec-28		857 d	
SN:0086-887	HRS	2011.6						
	AFL	1437						
HydroCheck Date: : 09-Dec-23								
PROC. REF: AMM 35-02-01PROC. REF: AMM 35-02-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-02-05	OXYGEN PRESSURE REGULATOR							Component ATA:35
PN:PN	MOS/MSC	18-Sep-19	O/C	TSR 0				
SN:UNKNOWN	HRS	1403.8		TSR 0				
	AFL	998		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-11-00-001	OPERATIONAL CHECK OF LH CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	18-May-26	24 (+1m/-1m)	Adj -23d	25-Apr-28	25-May-28	629 d (+30)	
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-00-001	OPERATIONAL CHECK OF RH CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	18-May-26	24 (+1m/-1m)	Adj -23d	25-Apr-28	25-May-28	629 d (+30)	
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-01	LH CREW OXYGEN-MASK STOWAGE BOX							Component ATA:35
PN:1186F6-23	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-01	RH CREW OXYGEN-MASK STOWAGE BOX							Component ATA:35
PN:1186F6-23	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-02	LH CREW OXYGEN MASK							Component ATA:35
PN:174232-93	MOS/MSC	04-Apr-22	O/C	TSO 1				
SN:28522	HRS	1682.2		TSO 0				
	AFL	1192		TSO 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02PROC. REF: AMM 35-11-02, AMM 35-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-02	RH CREW OXYGEN MASK							Component ATA:35
PN:174232-93	MOS/MSC	04-May-23	O/C	TSO 1				
SN:28361	HRS	1916.8		TSO 0				
	AFL	1354		TSO 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02PROC. REF: AMM 35-11-02, AMM 35-11-02								
35-11-02-001	DETAILED VISUAL INSPECTION OF LH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	18-May-26	24 (+1m/-1m)	Adj -23d	25-Apr-28	25-May-28	629 d (+30)	
SN:28522	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-02-001	DETAILED VISUAL INSPECTION OF RH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	04-Jun-25	24 (+1m/-1m)		04-Jun-27	04-Jul-27	303 d (+30)	
SN:28361	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-02-002	RESTORATION (OVERHAUL) OF LH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	09-Mar-22	72 (+1m/-1m)		09-Mar-28	09-Apr-28	582 d (+31)	
SN:28522	HRS	1682.2	3600 (+30/-30)		5282.2	5312.2	2682.5 (+30)	
	AFL	1192						
Restoration Date:: 09-Mar-22								
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								
35-11-02-002	RESTORATION (OVERHAUL) OF RH CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS	06-Apr-23	72 (+1m/-1m)	TAC 7	06-Sep-28	06-Oct-28	763 d (+30)	
SN:28361	HRS	1916.8	3600 (+30/-30)	TAC 0	5516.8	5546.8	2917.1 (+30)	
	AFL							
Restoration Date:: 06-Apr-23								
PROC. REF: AMM 35-11-02PROC. REF: AMM 35-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-04-001	^S	DETAILED VISUAL INSPECTION OF CREW GOGGLES						Service ATA:35
	MOS	04-Jun-25	36 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 35-11-04PROC. REF: AMM 35-11-04								PKG:82
35-21-00-001		FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE						Service ATA:35
	MOS	04-Jun-25	36 (+30d/-30d)		04-Jun-28	04-Jul-28	669 d (+30)	AIRWORTHINESS
	HRS	2224.4	1800 (+30/-30)		4024.4	4054.4	1424.7 (+30)	
	AFL	1614						
PROC. REF: AMM 35-21-00PROC. REF: AMM 35-21-00								
35-21-00-002		OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE						Service ATA:35
	MOS	04-Jun-25	36 (+30d/-30d)		04-Jun-28	04-Jul-28	669 d (+30)	AIRWORTHINESS
	HRS	2224.4	1800 (+30/-30)		4024.4	4054.4	1424.7 (+30)	
	AFL	1614						
PROC. REF: AMM 35-21-00PROC. REF: AMM 35-21-00								
35-21-01		PAX 1 OXYGEN MASK						Component ATA:35
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01		PAX 2 OXYGEN MASK						Component ATA:35
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01		PAX 3 OXYGEN MASK						Component ATA:35
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-01	PAX 4 OXYGEN MASK							Component ATA:35
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER OXYGEN-MASKS ASSEMBLY							Service ATA:35
	MOS	04-Jun-25	36 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 35-21-01PROC. REF: AMM 35-21-01								
35-21-02	CABIN OXYGEN THREE MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411072-111	MOS/MSC	06-Sep-19	O/C	TSN 3				
SN:4411072-111-00240	HRS	1399.3		TSN 0				
	AFL	996		TSN 0				
PROC. REF: AMM 35-21-02, AMM 35-21-02PROC. REF: AMM 35-21-02, AMM 35-21-02								
35-21-02	LH OXYGEN TWO MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411072-00	MOS/MSC	09-Jun-10	O/C					
SN:NSN	HRS	32.2						
	AFL							
PROC. REF: AMM 35-21-02, AMM 35-21-02PROC. REF: AMM 35-21-02, AMM 35-21-02								
35-21-02	RH OXYGEN TWO MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411073-00	MOS/MSC	09-Jun-10	O/C					
SN:NSN	HRS	32.2						
	AFL							
PROC. REF: AMM 35-21-02, AMM 35-21-02PROC. REF: AMM 35-21-02, AMM 35-21-02								
35-31-01	PROTECTIVE BREATHING EQUIPMENT (PBE)							Component ATA:35
PN:PN	MOS/MSC	23-Mar-10	N/A	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-31-01, AMM 35-31-01PROC. REF: AMM 35-31-01, AMM 35-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-31-01-001	DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)							Service ATA:35
PN:PN	MOS/MSC		N/A					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 35-31-01PROC. REF: AMM 35-31-01								
ATA 36 - PNEUMATIC								
36-11-00-001 ^S	OPERATIONAL CHECK LH BLEED SHUT-OFF FUNCTION							Service ATA:36
PN:1330310-5	MOS	04-May-23						
SN:0504	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 36-11-00PROC. REF: AMM 36-11-00								PKG:1
36-11-00-001 ^S	OPERATIONAL CHECK RH BLEED SHUT-OFF FUNCTION							Service ATA:36
PN:1330310-5	MOS	04-May-23						
SN:0610	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 36-11-00PROC. REF: AMM 36-11-00								PKG:1
36-11-01	LH PYLON PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:1330310-5	MOS/MSC	31-Mar-17	O/C					
SN:0504	HRS	1059.8						
	AFL	760						
PROC. REF: AMM 36-11-01, AMM 36-11-01PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-01	RH PYLON PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:1330310-5	MOS/MSC	31-Mar-17	O/C					
SN:0610	HRS	1059.8						
	AFL	760						
PROC. REF: AMM 36-11-01, AMM 36-11-01PROC. REF: AMM 36-11-01, AMM 36-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-02-001	DETAILED INSPECTION OF BLEED LINE WATER DRAINS							Service ATA:36
	MOS/MSC	05-May-20	N/A					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 36-11-02PROC. REF: AMM 36-11-02								
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS							Service ATA:36
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	3800.3 (+30)	
	AFL	0						
PROC. REF: AMM 36-21-01PROC. REF: AMM 36-21-01								
ATA 44 - CABIN SYSTEMS								
24-21-03	DC CONVERTER							Component ATA:44
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-03, AMM 44-21-03PROC. REF: AMM 44-21-03, AMM 44-21-03								
ATA 52 - DOORS								
52-10-00	OPTIONAL DOOR EQUIPPED STEP ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR STRUCTURE							Service ATA:52
PN:500-09910-445	MOS	04-Jun-25	60 (+1m/-1m)					
SN:0000533218	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00								
PKG:84								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-01-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR STRUCTURE							Service ATA:52
PN:500-09910-445	MOS	04-Jun-25	60 (+1m/-1m)					
SN:0000533218	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00								PKG:90
52-10-01-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE UPPER EXTERNAL FRAME, UPPER HORIZONTAL STRINGER, EXTERNAL VERTICAL FRAME, AND LOWER HORIZONTAL FRAME.							Service ATA:52
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00								
52-10-01-01-902	EXTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.							Service ATA:52
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00								
52-10-02-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR LATCH MECHANISM LATCH PINS.							Service ATA:52
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 52-10-00PROC. REF: NDT 52-10-00								
52-10-20-001 ^S	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL							Service ATA:52
PN:500-09910-445	MOS	18-May-26	12 (+1m/-1m)					
SN:0000533218	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-10-20PROC. REF: AMM 52-10-20								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-00	MAIN PAX DOOR ASSEMBLY							Component ATA:52
PN:500-09910-445	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000533218	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00, AMM 52-10-00PROC. REF: AMM 52-10-00, AMM 52-10-00								
52-11-00-001 ^S	GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
PN:500-09910-445	MOS	18-May-26	48 (+1m/-1m)					
SN:0000533218	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-11-00PROC. REF: AMM 52-11-00								
52-11-00-002 ^S	LUBRICATION OF MAIN DOOR LATCH PINS							Service ATA:52
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-11-21PROC. REF: AMM 52-11-21								
52-11-01	DOOR KEY LOCK KIT							Component ATA:52
PN:500-38850-901	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:100142-10142	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-13-00	MAIN DOOR BALANCE ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-00, AMM 52-13-00PROC. REF: AMM 52-13-00, AMM 52-13-00								
52-13-01	MAIN DOOR BALANCE ASSY GEAR SECTOR							Component ATA:52
PN:PN	MOS/MSC	23-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-21, AMM 52-13-21PROC. REF: AMM 52-13-21, AMM 52-13-21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-13-02	MAIN DOOR BALANCE ASSY PINION SHAFT							Component ATA:52
PN:PN	MOS/MSC	23-Mar-10	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-23, AMM 52-13-23PROC. REF: AMM 52-13-23, AMM 52-13-23								
52-13-21-001 ^S	DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR							Service ATA:52
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-21PROC. REF: AMM 52-13-21								PKG:60
52-13-22-002 ^S	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE							Service ATA:52
PN:PN	MOS	04-May-23						
SN:UNKNOWN	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 52-13-22PROC. REF: AMM 52-13-22								PKG:1
52-13-22-004	DETAILED VISUAL INSPECTION OF MAIN DOOR BALANCING MECHANISM CABLES							Service ATA:52
	MOS/MSC	23-Mar-10	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 52-13-22PROC. REF: AMM 52-13-22								
52-13-23-001 ^S	DISCARD OF MAIN DOOR BALANCING MECHANISM PINION SHAFT							Service ATA:52
PN:PN	MOS	23-Mar-10						
SN:UNKNOWN	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-23PROC. REF: AMM 52-13-23								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-01-01-901	INTERNAL DETAILED VISUAL INSPECTION EMERGENCY DOOR STRUCTURE SPAR AND FRAMES.							Service ATA:52
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 52-20-00PROC. REF: NDT 52-20-00								
52-20-01-01-902	EXTERNAL - DETAILED INSPECTION EMERGENCY DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.							Service ATA:52
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 52-20-00PROC. REF: NDT 52-20-00								
52-20-20-001 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
PN:500-09700-427	MOS	18-May-26	48 (+1m/-1m)					
SN:0000533225	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-20-20PROC. REF: AMM 52-20-20								PKG:83
52-20-21	CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY							Component ATA:52
PN:500-09700-427	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000533225	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52-20-21-001 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL							Service ATA:52
PN:500-09700-427	MOS	18-May-26	24 (+1m/-1m)					
SN:0000533225	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-20-21PROC. REF: AMM 52-20-21								PKG:81

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-31-20-001	^S	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM						Service ATA:52
	MOS	18-May-26	48 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-31-20PROC. REF: AMM 52-31-20								PKG:83
52-32-20-001	^S	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM						Service ATA:52
	MOS	18-May-26	48 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: AMM 52-32-20PROC. REF: AMM 52-32-20								PKG:83
52-71-20		LOWER DOOR MICRO SWITCH						Component ATA:52
PN:500-38876-401	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000537777	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-71-20, AMM 52-71-20PROC. REF: AMM 52-71-20, AMM 52-71-20								
52-71-20		UPPER DOOR MICRO SWITCH						Component ATA:52
PN:500-38876-401	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000537778	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-71-20, AMM 52-71-20PROC. REF: AMM 52-71-20, AMM 52-71-20								
ATA 53 - FUSELAGE								
53-00-00-001	^S	GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS						Service ATA:53
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 53-00-20PROC. REF: AMM 53-00-20								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-05-00-001	^S	DETAILED VISUAL INSPECTION OF FUSELAGE DRAINS						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 53-05-00PROC. REF: AMM 53-05-00								PKG:84
53-10-00-001	^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE LOWER SKIN PANEL AND COCKPIT FLOOR STRUCTURES						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								PKG:90
53-10-00-002	^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS, SKIN SPLICES AND WINDSHIELD CUTOUT STRUCTURE						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								PKG:90
53-10-01-01-901		INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:6300		6300		4430	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-01-01-902		INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:14000		14000		12130	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-01-01-903	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE SKIN PANEL AND FASTENERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-02-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS FRAMES AND SPLICES.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-02-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-FRAMES AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-02-02-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS STRINGERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-02-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-STRINGERS AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-03-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL FRAMES AND STRINGERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-03-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL SKIN-TO-FRAME/STRINGERS AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-04-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES LONGITUDINAL SPLICE							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-04-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES - SKIN-TO-LONGITUDINAL SPLICE AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-04-02-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES CIRCUMFERENTIAL SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-04-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES SKIN-TO-CIRCUMFERENTIAL-SPLICE AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-05-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE PRESSURE BULKHEAD						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								PKG:90
53-10-05-002	^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE PRESSURE BULKHEAD						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								PKG:90
53-10-05-01-901		INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE PRESSURE BULKHEAD.						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-06-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE FORWARD SKIN PANELS						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								PKG:90
53-10-07-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL METALLIC STRUCTURE						Service ATA:53
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								PKG:81

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-07-01-901	EXTERNAL SPECIAL DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE (EDDY CURRENT) TRUNION.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-07-02-901	EXTERNAL - DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-07-02-902	EXTERNAL SPECIAL DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE (EDDY CURRENT) DRAG LOCKING STRUTS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-08-002	INTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL COMPOSITE STRUCTURE							Service ATA:53
	MOS/MSC	05-May-20	O/C					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-10-08-01-901	EXTERNAL - DETAILED INSPECTION NOSE LANDING GEAR WHEEL COMPOSITE STRUCTURE UPPER PANEL AND SIDE SKIN.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-10-00PROC. REF: NDT 53-10-00								
53-14-00	NOSE RADOME							Component ATA:53
PN:5190-102-1	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:167	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-14-00, AMM 53-14-00PROC. REF: AMM 53-14-00, AMM 53-14-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS AND SKIN SPLICES						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90
53-20-00-002	^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS, SKIN SPLICES, AND FLOOR STRUCTURE						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90
53-20-00-003	^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TO-WING LATERAL AND CENTER LINKS						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90
53-20-01-01-901		INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) FRAMES.						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-01-01-902		EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) SKIN TO FRAMES AREA.						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-01-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) STRINGERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-01-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-02-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) FRAMES.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-02-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) SKIN TO FRAMES AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-02-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) STRINGERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-02-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-03-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) CUT-OUT REINFORCEMENT (SKIN DOUBLER).							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-03-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO CUT-OUT AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-03-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) FRAMES AND STRINGERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-03-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO FRAMES AND STRINGERS AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-04-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-04-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-04-02-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPLICE CIRCUNFERENTIAL SKIN SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-04-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAPJOINT SKIN SPLICE AND CIRCUMFERENTIALSKIN SPICESKIN AT CIRCUMFERENTIAL SKIN SPLICE AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-05-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES ANDEND FITTINGS SKIN (FROM STRINGER 12L TO 12R).							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-05-01-902	EXTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES ANDEND FITTINGS (EDDY CURRENT) SPLICE (1ST AND 3RD ROWS) (FROM STRINGER 01R TO 01L, FROM STINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-05-01-903	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGECIRCUMFERENTIAL SKIN SPLICES ANDEND FITTINGS SKIN (FROM STRINGER 01R TO 01L, FROM STRINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	00	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-05-01-904	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES END FITTINGS							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-06-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-06-002	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90
53-20-06-01-901	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE DOUBLER 1 AT CORNERS OF MAIN DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-06-01-902	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE SKIN AT CORNERS OF THE MAIN DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-06-01-903	EXTERNAL - DETAILED INSPECTION THE MAIN DOOR CUTOUT STRUCTURE SKIN TO DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-06-01-904	INTERNAL GENERAL VISUAL INSPECTION THE MAIN DOOR CUT-OUT STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-06-01-905	INTERNAL DETAILED INSPECTION MAIN DOOR CUTOUT STRUCTURE MACHINED FRAME AT LATCH PIN BOX AREA .							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-07-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR CUTOUT STRUCTURE						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:84
53-20-07-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR CUTOUT STRUCTURE						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90
53-20-07-01-901		INTERNAL GENERAL VISUAL INSPECTION EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-07-01-902		EXTERNAL - DETAILED INSPECTION THE SKIN TO EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)						Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-08-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUT-OUT STRUCTURE						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-08-01-901	INTERNAL GENERAL VISUAL INSPECTION PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER WINDOW FRAME (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18)							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-08-01-902	EXTERNAL - DETAILED INSPECTION PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18) SKIN AT WINDOW AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-10-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING LATERAL LINKS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-10-01-902	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING LATERAL LINKSMACHINED FRAME (FRAME 14 AND FRAME 18) AND FASTENERS							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-11-01-901	INTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING CONNECTION LINK(EDDY CURRENT) CONNECTION LINK FITTING (LUG AND INNER CAP).							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-11-01-902	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING CONNECTION LINK FITTING.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-20-12-01-901	INTERNAL DETAILED INSPECTION AFT PRESSURE BULKHEAD.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	00	T:17500		17500		15630	
PROC. REF: NDT 53-20-00PROC. REF: NDT 53-20-00								
53-30-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN AND ATTACHMENTS							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								PKG:90
53-30-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER SKIN, JUNCTIONS AND ATTACHMENTS							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								PKG:90
53-30-00-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN, CUTOUTS AND ATTACHMENTS							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-01-01-901	INTERNAL DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANELBEDPLATE AND ITS ATTACHMENTS, BEDPLATES TO STRINGER ATTACHMENTS AND SKIN TO BEDPLATE AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-01-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANEL SKIN TO BEDPLATE AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-02-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL FORWARD MACHINED FRAME (FRAME 22 AND FRAME 23)							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-02-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL SKIN TO FRAME AREA							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-02-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL AFT MACHINED FRAME (FRAME 25 AND FR25A)							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-02-02-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL - SKIN TO FRAME AREA							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-04-01-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES AFT FUSELAGE SKIN TO LONGITUDINAL SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-04-01-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES LONGITUDINAL SPLICE							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-04-02-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES TO CIRCUMFERENTIAL SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-04-02-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIALSKIN SPLICES TO CIRCUMFERENTIAL SPLICE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-05-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-05-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-05-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUTSTRUCTUREAFT FUSELAGE THE SKIN TO BAGGAGE DOOR CUTOUT STRUCTURE.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-06-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE CUTOUT STRUCTURES -INTERNALFRAMES, STRINGER, REINFORCEMENT, AND DOUBLER OF AFT FUSELAGE CUTOUT STRUCTURES.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-07-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER FRAMES 29 TO 32							Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								PKG:90
53-30-07-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) MACHINED FRAMES.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-07-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) SKIN TO FRAME AREA.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-07-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) BEDPLATES AND FASTENERS.							Service ATA:53
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								
53-30-08-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE MACHINED FRAME 32							Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 53-30-00PROC. REF: NDT 53-30-00								PKG:87
Z210-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00								PKG:87
Z210-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Z220-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00								PKG:84
Z220-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-41-00PROC. REF: AMM 05-41-00								PKG:87
Z230-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00								PKG:87
Z230-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00								PKG:87
Z240-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Z240-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION						Service ATA:53
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: AMM 05-42-00PROC. REF: AMM 05-42-00								PKG:84
Z310-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00								PKG:87
Z310-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00								PKG:87
Z320-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00								PKG:87
Z320-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION						Service ATA:53
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-43-00PROC. REF: AMM 05-43-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-00-00-001	^S	GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS						Service ATA:54
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 54-51-20PROC. REF: AMM 54-51-20								PKG:1
54-50-00-001	^S	INTERNAL DETAILED VISUAL INSPECTION OF PYLON MAIN BOX						Service ATA:54
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								PKG:90
54-50-00-002	^S	INTERNAL DETAILED VISUAL INSPECTION OF PYLON FORWARD BEAM						Service ATA:54
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								PKG:90
54-50-01-01-901		INTERNAL DETAILED INSPECTION PYLON FORWARD BEAM PYLON SPARS 1 AND 2, UPPER AND LOWER SKIN AND FASTENERS.						Service ATA:54
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								
54-50-02-01-901		INTERNAL DETAILED INSPECTION PYLON AFT BEAMPYLON SPARS 3 AND 4 AND FASTENERS.						Service ATA:54
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	00	T:17500		17500		15630	
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-03-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF PYLON MAIN BOX						Service ATA:54
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								PKG:90
54-50-03-01-901		EXTERNAL GENERAL VISUAL INSPECTION OF PYLON MAIN BOX MAIN BOX SKIN AND FASTENERS.						Service ATA:54
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								
54-50-04-01-901		INTERNAL DETAILED INSPECTION PYLON-TO-FUSELAGE CONNECTIONS OF BOLTS.						Service ATA:54
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								
54-50-05-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES						Service ATA:54
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								PKG:87
54-50-05-01-901		INTERNAL DETAILED INSPECTION PYLON YOKESLUG HOLES AT YOKES, YOKES, GUSSETS AND SHIELD.						Service ATA:54
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-06-001	^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT MOUNT FITTINGS						Service ATA:54
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								PKG:84
54-50-06-01-901		INTERNAL DETAILED INSPECTION PYLON AFT FITTINGAFT MOUNT FITTING AND FASTENERS.						Service ATA:54
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 54-50-00PROC. REF: NDT 54-50-00								
410-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON						Service ATA:54
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00								PKG:87
410-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON						Service ATA:54
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00								PKG:87
430-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE						Service ATA:54
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
Z430-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE						Service ATA:54
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-46-00PROC. REF: AMM 05-46-00								PKG:87
ATA 55 - STABILIZERS								
55-00-00-001	^S	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS						Service ATA:55
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 55-00-20PROC. REF: AMM 55-00-20								PKG:1
55-10-00		HORIZONTAL STABILIZER						Component ATA:55
PN:500-10700-409	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000534564	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-10-00-001	^S	EXTERNAL - DETAILED INSPECTION OF HORIZONTAL-STABILIZER SPARS						Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:87
55-10-00-002	^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF HORIZONTAL-STABILIZER MAIN BOX						Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-01-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL-TO-HORIZONTAL STABILIZER ATTACHMENTS						Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:87
55-10-01-01-901		INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER AND FASTENERS.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-02-01-901		INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR (BORESCOPIC) FRONT SPAR AND FASTENERS.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-02-01-902		EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR FRONT SPAR AND FASTENERS.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-03-01-901		INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR(BORESCOPIC) REAR SPAR.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-03-01-902		EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR				REAR SPAR AND FASTENERS.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN					(BORESCOPIC) STRINGERS.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-04-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN					UPPER SKIN AND		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-05-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN - LOWER SKIN.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-05-01-902	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN					LOWER SKIN AT FIN TO		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-06-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER COMPOSITE RIBS					(BORESCOPIC) COMPOSITE RIBS		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-07-001	^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER TIP RIBS						Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:90
55-10-07-01-901		INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER METALLIC RIBS INCLUDING FASTENERS.				ROOT AND TIP METALLIC RIBS,		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-08-001	^S	EXTERNAL - DETAILED INSPECTION ON HORIZONTAL STABILIZER ROOT RIBS						Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:90
55-10-08-01-901		INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER LEADING EDGE HORIZONTAL STABILIZER LEADING EDGE SKIN AND SPAR.				(BORESCOPIC)		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-08-01-902		EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER LEADING EDGE EDGE SKIN AND FASTENERS.				HORIZONTAL STABILIZER LEADING		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-09-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL STABILIZER LEADING EDGE							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:87
55-10-09-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING					HINGE FITTINGS, AND FASTENERS.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-09-02-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING (EDDY CURRENT) LUGS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-09-03-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING TORQUE BOX AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-10-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION ON HORIZONTAL-STABILIZER HINGE FITTINGS							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-10-01-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS TAB SUPPORTING FITTING AND FASTENERS.						TRIM	Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-10-02-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS TAB LINK SUPPORT FITTING AND FASTENERS.						TRIM	Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								
55-10-11-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF TRIM-TAB SUPPORT FITTINGS							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-10-00PROC. REF: NDT 55-10-00								PKG:84
55-20-00-001 ^S	EXTERNAL - DETAILED INSPECTION OF ELEVATOR FITTINGS AND TORQUE-TUBE ATTACHMENTS							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								PKG:84
55-20-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) SKIN, SPARS, RIBS AND FASTENERS.					(BORESCOPIC)		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-20-01-01-902	EXTERNAL - DETAILED INSPECTION ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE AND HORN.					SKIN AND FASTENERS,		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-20-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS					(DYE PENETRANT) ELEVATOR HINGE PINS.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-20-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS					(EDDY CURRENT) ELEVATOR HINGE FITTINGS.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-20-02-02-902	INTERNAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS					ELEVATOR HINGE FITTINGS.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-20-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR TORQUE TUBE ASSY (EDDY CURRENT)					ELEVATOR TORQUE TUBE FLANGE.		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-20-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR TORQUE TUBE ASSY (DYE PENETRANT) ELEVATOR TORQUE TUBE.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-20-00PROC. REF: NDT 55-20-00								
55-22-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TAB PIANO HINGE							Service ATA:55
	MOS/MSC	05-May-20	O/C					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-22-00PROC. REF: NDT 55-22-00								
55-22-02-001 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR TAB BOX							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-22-00PROC. REF: NDT 55-22-00								PKG:90
55-30-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER TO AFT FUSELAGE CONNECTIONS AT VERTICAL STABILIZER							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								PKG:87
55-30-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-REAR FUSELAGE CONNECTIONS AT VERTICAL STABILIZER							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER FITTING, PINS AND SPARS ATTACHMENTS (UPPER PART OF CONNECTIONS).					(BORESCOPIC)		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-01-01-902	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER SPAR ATTACHMENTS (LOWER PART OF CONNECTIONS), NUT, SEAL AND FASTENERS.					FITTING, PINS AND		Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-01-02-901	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER L SHAPE, RIB AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-02-002 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								PKG:90
55-30-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) DOUBLER AND TIP RIB.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-02-01-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (EDDY CURRENT) DOUBLER AND TIP RIB AT FRONT AND REAR FITTING AREA.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-02-02-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER L SHAPE AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-02-02-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) L SHAPE AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-02-03-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER FITTINGS AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-02-04-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER COMPOSITE PLATES AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-03-001	^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL STABILIZER MAIN BOX						Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								PKG:87
55-30-03-01-901		EXTERNAL - DETAILED INSPECTION VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) SKIN AND SPAR.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-03-01-902		INTERNAL SPECIAL DETAILED INSPECTION VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) (BORESCOPIC) SPAR.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-05-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER FITTING						Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								PKG:84
55-30-05-01-901		EXTERNAL - DETAILED INSPECTION RUDDER HINGE FITTINGS HINGE FITTING 1 AND FASTENERS.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-05-02-901		INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS (EDDY CURRENT) HINGE FITTING 2 FLANGES.						Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-05-03-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS				(EDDY CURRENT) RUDDER LUG HINGE FITTINGS 1 AND 2.		Service	ATA:55
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TAB ACTUATOR FITTING AND SUPPORT FITTINGS						Service	ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
								PKG:90
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-30-06-01-901	EXTERNAL - DETAILED INSPECTION VERTICAL STABILIZER TAB ACTUATOR AND SUPPORT FITTINGS FITTINGS, LUGS AND FASTENERS.						Service	ATA:55
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-30-00PROC. REF: NDT 55-30-00								
55-33-00	VERTICAL STABILIZER						Component	ATA:55
PN:500-10100-417	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0000534473	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-40-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF OF RUDDER ASSEMBLY						Service	ATA:55
	MOS/MSC	05-May-20	O/C					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER ASSEMBLY							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								PKG:87
55-40-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER MAIN BOX (BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								
55-40-01-01-902	EXTERNAL - DETAILED INSPECTION RUDDER MAIN BOX MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								
55-40-02-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF RUDDER HINGE FITTINGS							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								PKG:87
55-40-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS (DYE PENETRANT) RUDDER HINGE FITTINGS PINS.							Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS				(EDDY CURRENT) RUDDER HINGE FITTINGS.			Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								
55-40-02-02-902	INTERNAL DETAILED INSPECTION RUDDER HINGE FITTINGS				RUDDER HINGE FITTINGS.			Service ATA:55
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								
55-40-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE-TUBE ASSEMBLY							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								PKG:87
55-40-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER TORQUE TUBE ASSEMBLY				(EDDY CURRENT) RUDDER TORQUE			Service ATA:55
	TUBE FLANGE.							
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								
55-40-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER TORQUE TUBE ASSEMBLY				(DYE PENETRANT) RUDDER TORQUE			Service ATA:55
	TUBE.							
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 55-40-00PROC. REF: NDT 55-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-41-00	RUDDER ASSEMBLY							Component ATA:55
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-42-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TAB PIANO HINGE							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PKG:90								
PROC. REF: NDT 55-42-00PROC. REF: NDT 55-42-00								
Z330-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PKG:84								
PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00								
Z330-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PKG:87								
PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00								
Z340-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PKG:84								
PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
Z340-002	^S	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER						Service ATA:55
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: AMM 05-44-00PROC. REF: AMM 05-44-00								PKG:87
ATA 56 - WINDOWS								
56-10-01-001	^S	EXTERNAL GENERAL VISUAL INSPECTION OF COCKPIT SIDE-WINDOWS PANE (BOTH SIDES)						Service ATA:56
	MOS	04-Jun-25	120 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 56-10-00PROC. REF: NDT 56-10-00								PKG:87
56-10-01-002		FUNCTIONAL CHECK (TORQUE) OF COPILOT SIDE WINDOW ATTACHING BOLTS						Service ATA:56
PN:NP-195302-4	MOS	24-Feb-26						
SN:09194H5334	HRS	2460.4	1600 (+30/-30)		4060.4	4090.4	1460.7 (+30)	
	AFL	1778						
PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00								
56-10-01-002		FUNCTIONAL CHECK (TORQUE) OF COPILOT WINDSHIELD ATTACHING BOLTS						Service ATA:56
PN:NP195301-3	MOS	24-Feb-26						
SN:160322H1713	HRS	2460.4	1600 (+30/-30)	Adj -91.8	3968.6	3998.6	1368.9 (+30)	
	AFL	1778						
PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00								
56-10-01-002		FUNCTIONAL CHECK (TORQUE) OF PILOT SIDE WINDOW ATTACHING BOLTS						Service ATA:56
PN:NP-195302-3	MOS	24-Feb-26						
SN:09197H5723	HRS	2460.4	1600 (+30/-30)		4060.4	4090.4	1460.7 (+30)	
	AFL	1778						
PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-01-002	FUNCTIONAL CHECK (TORQUE) OF PILOT WINDSHIELD ATTACHING BOLTS							Service ATA:56
PN:NP195301-3	MOS	24-Feb-26						
SN:16020H8792	HRS	2460.4	1600 (+30/-30)	Adj -91.8	3968.6	3998.6	1368.9 (+30)	
	AFL	1778						
PROC. REF: AMM 56-10-00PROC. REF: AMM 56-10-00								
56-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WINDSHIELD AND COCKPIT SIDE WINDOW FRAMES AND FASTENERS							Service ATA:56
	MOS	18-May-26	24 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						
PKG:81								
PROC. REF: NDT 56-10-00PROC. REF: NDT 56-10-00								
56-10-03-01-901	EXTERNAL SPECIAL DETAILED INSPECTION WINDSHIELD FRAME AND FASTENERS					(EDDY CURRENT) FRAMES AND	Service ATA:56	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 56-10-00PROC. REF: NDT 56-10-00								
56-11-00	COPILOT HEATED GLASS WINDSHIELD ASSY							Component ATA:56
PN:NP195301-3	MOS/MSC	03-Aug-21	O/C	TSN 22				
SN:160322H1713	HRS	1568.6		TSN 0				
	AFL	1125		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-11-00	PILOT HEATED GLASS WINDSHIELD ASSY							Component ATA:56
PN:NP195301-3	MOS/MSC	03-Aug-21	O/C	TSN 60				
SN:16020H8792	HRS	1568.6		TSN 0				
	AFL	1125		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-12-00	COPILOT ACRYLIC SIDE WINDOW							Component ATA:56
PN:NP-195302-4	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:09194H5334	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-12-00, AMM 56-12-00PROC. REF: AMM 56-12-00, AMM 56-12-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-12-00	PILOT ACRYLIC SIDE WINDOW							Component ATA:56
PN:NP-195302-3	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:09197H5723	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-12-00, AMM 56-12-00PROC. REF: AMM 56-12-00, AMM 56-12-00								
56-20-00	LEFT NO.1 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:00447	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	LEFT NO.2 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01357	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	LEFT NO.3 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01358	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	LEFT NO.4 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01360	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 1 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01361	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-00	RIGHT NO. 2 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01362	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 3 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01414	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	RIGHT NO. 4 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01584	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF PASSENGER CABIN WINDOWS							Service ATA:56
	MOS	04-Jun-25	120 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 56-20-00PROC. REF: NDT 56-20-00								PKG:87
ATA 57 - WINGS								
57-00-00-001 ^S	GENERAL VISUAL INSPECTION OF WING POLYURETHANE FILMS							Service ATA:57
	MOS	04-May-23						
	HRS	1916.8	800 (+30/-30)					
	AFL	1354						
PROC. REF: AMM 57-30-20PROC. REF: AMM 57-30-20								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-FUSELAGE LINKS						Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:90
57-10-00-002	^S	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX						Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:90
57-10-00-003	^S	INTERNAL DETAILED VISUAL INSPECTION OF WING MIDDLE AND REAR SPARS						Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:84
57-10-01-01-901		INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE SEAL.				FRONT FITTING, BOLT, NUT AND		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-01-02-901		INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE SEAL.				REAR FITTING, BOLT, NUT AND		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE CENTER FITTING AND LUG.					(EDDY CURRENT) WING		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-02-01-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE					WING CENTER FITTING.		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE CENTER LINK LUGS.					(EDDY CURRENT)		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-02-02-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE NUT AND SEAL.					CENTER LINK FITTING, BOLT,		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-02-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE HORIZONTAL LINK BOLTS.					(MAGNETIC PARTICLE)		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-03-01-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR ACCESS FRAMES, INCLUDING FASTENERS.			FRONT SPAR LOWER CAP BETWEEN RIB 1 AND 3 AND WINDOW			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-03-02-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR ACCESS FRAMES, INCLUDING FASTENERS.			FRONT SPAR LOWER CAP BETWEEN RIB 3 AND 6 AND WINDOW			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-03-03-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR			LOWER SKIN BETWEEN RIB 6 AND 7, INCLUDING FASTENER.			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-03-04-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR ACCESS FRAMES, INCLUDING FASTENERS.			FRONT SPAR LOWER CAP BETWEEN RIB 7 AND 10 AND WINDOW			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-03-05-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR			LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING FASTENERS.			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-04-01-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR FASTENERS.			MIDDLE SPAR LOWER CAP BETWEEN RIB 1 AND 3, INCLUDING			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-04-02-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR FASTENERS .			MIDDLE SPAR LOWER CAP BETWEEN RIB 3 AND 7, INCLUDING			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-04-03-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR SPAR-STRINGER-SPLICE AND FASTENERS.			MIDDLE SPAR LOWER CAP BETWEEN RIB 7 AND 9, INCLUDING			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-04-04-901	INTERNAL SPECIAL DETAILED INSPECTION WING MIDDLE SPAR AND RADIUS).			(EDDY CURRENT) MLG FRONT TRUNNION (LUG, SURFACE			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-04-04-902	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR			MLG FRONT TRUNNION AND FASTENERS.			Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-04-05-901	INTERNAL SPECIAL DETAILED INSPECTION WING MIDDLE SPAR (EDDY CURRENT) MLG ACTUATOR FITTING (SURFACE AND RADIUS).							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-04-05-902	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR MLG ACTUATOR FITTING AND FASTENERS.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-05-01-901	INTERNAL DETAILED INSPECTION WING REAR SPAR FRAME.				REAR SPAR LOWER CAP BETWEEN RIB 1 AND 3 AND WINDOW ACCESS			Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-05-02-901	EXTERNAL - DETAILED INSPECTION WING REAR SPAR FASTENERS.				REAR SPAR LOWER CAP BETWEEN RIB 3 AND 7, INCLUDING			Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-05-03-901	INTERNAL DETAILED INSPECTION WING REAR SPAR FASTENERS.				REAR SPAR LOWER CAP BETWEEN RIB 7 AND 10, INCLUDING			Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-05-04-901	EXTERNAL - DETAILED INSPECTION WING REAR SPAR			LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING FASTENERS.			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-05-05-901	EXTERNAL SPECIAL DETAILED INSPECTION WING REAR SPAR AND MACHINED RADIUS).			(EDDY CURRENT) MLG REAR TRUNNION (LUG, SURFACE			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-05-05-902	EXTERNAL - DETAILED INSPECTION WING REAR SPAR			MLG REAR TRUNNION AND FASTENERS.			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL						Service	ATA:57
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:87
57-10-07-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL						Service	ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-07-002	^S	INTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL						Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:90
57-10-07-01-901		INTERNAL DETAILED INSPECTION WING LOWER PANEL STRINGER 5 AND SHEAR CLIPS FASTENERS.		STRINGER 2 AND 3 BETWEEN RIB 1 AND 3 AND SHEAR CLIPS OF			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-07-02-901		INTERNAL DETAILED INSPECTION WING LOWER PANEL WINDOW ACCESS PANEL 9 FRAMES.		STRINGER 2 RUN-OUT, STRINGER SHEAR CLIPS AT RIB 8 AND			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-07-03-901		EXTERNAL - DETAILED INSPECTION WING LOWER PANEL INCLUDING DOU-BLER AND ITS FASTENERS.		LOWER PANEL AND FASTENERS BETWEEN RIB 2 AND RIB 10,			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-08-01-901		INTERNAL DETAILED INSPECTION WING LOWER PANEL 8R).		MACHINED RIBS (RIB 1, RIB 3, RIB 3A, RIB 5R, RIB 6R, RIB 7R, RIB			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-08-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL			WING FORMED RIBS (RIB 2, RIB 4F, RIB 5F, RIB 6F, RIB 7F, RIB 8F, RIB 9, RIB 10, RIB11, RIB 12, RIB 13, RIB 14, RIB 15 AND RIB 16).				Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-08-03-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL			DRY BAY WALLS AND FASTENERS.				Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-10-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
PKG:90								
57-10-10-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF WING CENTRAL SPLICE							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
PKG:90								
57-10-10-003 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTRAL SPLICE							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
PKG:90								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-10-01-901	EXTERNAL - DETAILED INSPECTION WING CENTRAL SPLICES INCLUDING FASTENERS.			FRONT SPAR SPLICE, LOWER SKIN SPLICES, REAR SPAR SPLICES,				Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-10-01-902	INTERNAL DETAILED INSPECTION WING CENTRAL SPLICES FRONT , REAR AND MIDDLE SPAR ON SPLICE AREA AND MIDDLE SPAR SPLICE, INCLUDING FASTENERS.			WING LOWER SKIN ON SPLICE AREA, BETWEEN RIB1 AND RIB 2,				Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								
57-10-11-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON TAB ACTUATOR SUPPORT FITTINGS AND TAB HINGE FITTINGS							Service ATA:57
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 57-10-00PROC. REF: NDT 57-10-00								PKG:87
57-50-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE INBOARD AND OUTBOARD TORQUE BOXES							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								PKG:84
57-50-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS (EDDY CURRENT) WING ROOT TRACK.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-01-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS WING ROOT TRACK.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-01-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS (DYE PENETRANT) WING ROOT ROLLER.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:8875		8875		7005	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-01-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS (EDDY CURRENT) RIB 1.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-01-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUEBOX AND FLAP TRACK # 1 SUPPORTS RIB 1 AND FASTENERS.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS WING CENTER TRACK.					(EDDY CURRENT)		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-02-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS					WING CENTER TRACK.		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS WING CENTER TRACK SUPPORT.					(EDDY CURRENT)		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-02-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS SUPPORT.					WING CENTER TRACK		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-02-03-901	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2SUPPORTS ATTACHMENTS, PIN AND FASTENERS).					FITTINGS (LUG,		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) WING TIP TRACK.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-03-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS WING TIP TRACK.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS (DYE PENETRANT) WING TIP ROLLER.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:8875		8875		7005	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) RIBS 13 AND 13A WEB AND FLANGE.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-03-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS RIBS 13 AND 13A.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-03-04-901	EXTERNAL - DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUEBOX AND FLAP TRACK # 3 SUPPORTS TORQUE BOX SKIN AND FASTENERS.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-04-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE AILERON HINGE FITTINGS						Service ATA:57
	MOS	04-Jun-25	120 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								PKG:87
57-50-04-01-901		INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS CURRENT) AILERON HINGE FITTING 01.				(EDDY		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-04-02-901		INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS CURRENT) AILERON HINGE FITTING 02 .				(EDDY		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-04-02-902		INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS FITTING 02.				AILERON HINGE		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-50-04-03-901		INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS CURRENT) AILERON HINGE FITTING 03.				(EDDY		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-04-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORTFITTINGS FITTING 03.					AILERON HINGE		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-50-00PROC. REF: NDT 57-50-00								
57-51-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP ASSEMBLY							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								PKG:90
57-51-01-01-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS				FLAP UPPER SKIN FROM RIB 7 TO RIB 9.			Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-02-002 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE FLAP MAIN BOX							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								PKG:90
57-51-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS 5B.				(BOREScope) FLAP FRONT SPAR BETWEEN RIB 5A AND RIB			Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7049		7049		5179	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-02-03-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS RIB 10.			FLAP LOWER SKIN FROM RIB 1 TO RIB 5A AND FROM RIB 5B TO			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-02-04-901	EXTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS AND FROM RIB 5B TO RIB 6 AT FRONT SPAR AREA.			(EDDY CURRENT) FLAP LOWER SKIN FROM RIB 4 TO RIB 5A			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-02-05-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS ROLLERS FITTING TO RIB 5A AND RIB 5B			(BORESCOPIC) AROUND FASTENERS THAT CONNECT CENTER			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-02-06-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS			(EDDY CURRENT) FRONT SPAR FROM RIB 5A TO RIB 5B.			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-02-07-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS			(EDDY CURRENT) RIB 1 AND RIB 10.			Service	ATA:57
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-03-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP TRACK FITTINGS AND ACTUATOR FITTING						Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								PKG:84
57-51-03-01-901		INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP ROOT TRACK.						Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-03-01-902		INTERNAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS FLAP ROOT TRACK.						Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-03-02-901		INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP TIP TRACK.						Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-03-02-902		INTERNAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS FLAP TIP TRACK.						Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-03-03-901		INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) FLAP ROOT AND TIP ROLLERS.						Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-03-04-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) CENTER ROLLERS EXTERNAL PINS.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-03-05-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) CENTER ROLLERS FITTING AROUND FASTENERS.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-04-01-901	INTERNAL DETAILED INSPECTION FLAP ACTUATOR SUPPORT FITTING					FLAP ACTUATOR SUPPORT PIN.		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-51-04-02-901	INTERNAL DETAILED INSPECTION FLAP ACTUATOR SUPPORT FITTING AND FASTENERS.					FLAP ACTUATOR SUPPORT FITTING		Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-51-00PROC. REF: NDT 57-51-00								
57-60-00	LH AILERON ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-60-00	RH AILERON ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-60-00-001	^S	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON ASSEMBLY AND AILERON TAB BOX						Service ATA:57
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								PKG:87
57-60-01-002	^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON MAIN BOX						Service ATA:57
	MOS	05-May-20	120 (+1m/-1m)					
	HRS	1467.9						
	AFL	1046						
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								PKG:87
57-60-01-01-901		INTERNAL SPECIAL DETAILED INSPECTION AILERON MAIN BOX		(BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								
57-60-01-01-902		EXTERNAL - DETAILED INSPECTION AILERON MAIN BOX		SKIN, SPARS, RIBS AND FASTENERS.			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								
57-60-02-01-901		INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS		(DYE PENETRANT) AILERON HINGE FITTINGS PINS.			Service ATA:57	
	MOS	23-Mar-10					AIRWORTHINESS	
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS (EDDY CURRENT) AILERON HINGE FITTINGS (LUGS, STIFFENERS RADIUS).						Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								
57-60-02-02-902	INTERNAL DETAILED INSPECTION AILERON HINGE FITTINGS AILERON HINGE FITTINGS.						Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								
57-60-03-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF AILERON ACTUATOR FITTING, HINGE FITTINGS AND PINS						Service	ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								PKG:84
57-60-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN AILERON ACTUATOR HINGE FITTINGS PINS.					(DYE PENETRANT)	Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								
57-60-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN ACTUATOR HINGE FITTINGS (LUGS, STIFFEN-ERS RADIUS).					(EDDY CURRENT) AILERON	Service	ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-03-02-902	INTERNAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN AILERON ACTUATOR HINGE FITTINGS.							Service ATA:57
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:17500		17500		15630	
PROC. REF: NDT 57-60-00PROC. REF: NDT 57-60-00								
57-63-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF AILERON TAB ASSEMBLY							Service ATA:57
	MOS	04-Jun-25	60 (+1m/-1m)					
	HRS	2224.4						
	AFL	1614						
PROC. REF: NDT 57-63-00PKG:90 PROC. REF: NDT 57-63-00								
ATA 71 - POWER PLANT								
71-00-00-760-812	NO. 1 ENGINE - PERFORM PW617F-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	13-May-26	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	2522						
	ENC	1824						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-812	NO. 2 ENGINE - PERFORM PW617F-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	13-May-26	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	2522						
	ENC	1824						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-812-A	NO. 1 ENGINE - PERFORM PW617F1-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	19-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-760-812-A	NO. 2 ENGINE - PERFORM PW617F1-E ENGINE CALIBRATION (FIVE POINT CALIBRATION)							Service ATA:71
	MOS/MSC	20-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-813	NO. 1 ENGINE - PERFORM PW617F-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	13-May-26	A/R					
	HRS	2522						
	ENC	1824						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-813	NO. 2 ENGINE - PERFORM PW617F-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	13-May-26	A/R					
	HRS	2522						
	ENC	1824						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-813-A	NO. 1 ENGINE - PERFORM PW617F1-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	03-Aug-21	A/R					
	HRS	1568.6						
	ENC	1125						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-813-A	NO. 2 ENGINE - PERFORM PW617F1-E POWER ASSURANCE TEST							Service ATA:71
	MOS/MSC	03-Aug-21	A/R					
	HRS	1568.6						
	ENC	1125						
PROC. REF: MM 71-00-00PROC. REF: MM 71-00-00								
71-00-00-760-822	NO. 1 ENGINE - TLD CLEAR PROCEDURE (LONG DISPATCH)							Service ATA:71
	MOS/MSC	19-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 71-00-00PROC. REF: LMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-760-822	NO. 2 ENGINE - TLD CLEAR PROCEDURE (LONG DISPATCH)							Service ATA:71
	MOS/MSC	20-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 71-00-00PROC. REF: LMM 71-00-00								
71-11-00-001 ^S	GENERAL VISUAL INSPECTION OF UPPER MID COWL							Service ATA:71
	MOS	23-Mar-10						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 71-11-00PROC. REF: AMM 71-11-00								
71-20-00-001	DISCARD LEFT ENGINE AFT MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA2	MOS	23-Mar-10	240 (+1m/-1m)		23-Mar-30	23-Apr-30	1326 d (+31)	
SN:LK0464	HRS	0	4800 (+30/-30)		4800	4830	2200.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	23-Mar-10	240 (+1m/-1m)		23-Mar-30	23-Apr-30	1326 d (+31)	
SN:LK0612	HRS	0	4800 (+30/-30)		4800	4830	2200.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	23-Mar-10	240 (+1m/-1m)		23-Mar-30	23-Apr-30	1326 d (+31)	
SN:LK0773	HRS	0	4800 (+30/-30)		4800	4830	2200.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD RIGHT ENGINE AFT MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA2	MOS	23-Mar-10	240 (+1m/-1m)		23-Mar-30	23-Apr-30	1326 d (+31)	
SN:LK0458	HRS	0	4800 (+30/-30)		4800	4830	2200.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00-001	DISCARD RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	23-Mar-10	240 (+1m/-1m)		23-Mar-30	23-Apr-30	1326 d (+31)	
SN:LK0864	HRS	0	4800 (+30/-30)		4800	4830	2200.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
71-20-00-001	DISCARD RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR							Service ATA:71
PN:LM-474-SA11	MOS	23-Mar-10	240 (+1m/-1m)		23-Mar-30	23-Apr-30	1326 d (+31)	
SN:LK0873	HRS	0	4800 (+30/-30)		4800	4830	2200.3 (+30)	
	AFL	0						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
71-21-01	LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:LK0612	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01	LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:LK0773	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01	RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:LK0864	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-21-01	RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA11	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:LK0873	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00PROC. REF: AMM 71-21-00, AMM 71-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-21-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.							Service ATA:71
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:5000		5000		3130	
PROC. REF: NDT 71-21-00PROC. REF: NDT 71-21-00								
71-21-01-01-902	INTERNAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY ENGINE BOLT AND SLEEVE BOLT.							Service ATA:71
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:5000		5000		3130	
PROC. REF: NDT 71-21-00PROC. REF: NDT 71-21-00								
71-22-01	LEFT ENGINE AFT MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:LK0464	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00PROC. REF: AMM 71-22-00, AMM 71-22-00								
71-22-01	RIGHT ENGINE AFT MOUNT ISOLATOR							Component ATA:71
PN:LM-474-SA2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:LK0458	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00PROC. REF: AMM 71-22-00, AMM 71-22-00								
71-22-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.							Service ATA:71
	MOS	23-Mar-10						AIRWORTHINESS
	HRS	0						
	AFL	0	T:5000		5000		3130	
PROC. REF: NDT 71-22-00PROC. REF: NDT 71-22-00								
71-22-01-01-902	INTERNAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLYPYLON BOLTS, ENGINE BOLTS AND SLEEVE BOLTS.							Service ATA:71
	MOS	25-Apr-24						AIRWORTHINESS
	HRS	2034.9						
	AFL	1464	1500		2964		1094	
PROC. REF: NDT 71-22-00PROC. REF: NDT 71-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-31-00-001	^S	DETAILED VISUAL INSPECTION OF PYLON FIREWALL SEAL						Service ATA:71
	MOS	24-Feb-26						
	HRS	2460.4	2400 (+30/-30)					
	AFL	1778						
PROC. REF: AMM 71-31-00PROC. REF: AMM 71-31-00								PKG:20
71-50-00 LH ENG W403 HARNESS Component ATA:71								
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-50-00, AMM 71-50-00PROC. REF: AMM 71-50-00, AMM 71-50-00								
71-50-00 RH ENG W404 HARNESS Component ATA:71								
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-50-00, AMM 71-50-00PROC. REF: AMM 71-50-00, AMM 71-50-00								
71-60-01 LH ENG NACELLE AIR INLET ASSEMBLY Component ATA:71								
PN:500-36000-407	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01267	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01								
71-60-01 RH ENG NACELLE AIR INLET ASSEMBLY Component ATA:71								
PN:500-36000-407	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:01268	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01PROC. REF: AMM 71-60-01, AMM 71-60-01								
710010 NO. 1 ENGINE - COMPRESSOR DESALINATION WASH Service ATA:71								
	MOS/MSC	04-May-23	A/R					
	HRS	1916.8						
	ENC	1354						
PROC. REF: LMM 71-00-00, LMM 71-00-00PROC. REF: LMM 71-00-00, LMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710010	NO. 2 ENGINE - COMPRESSOR DESALINATION WASH							Service ATA:71
	MOS/MSC	04-May-23	A/R					
	HRS	1916.8						
	ENC	1354						
PROC. REF: LMM 71-00-00, LMM 71-00-00PROC. REF: LMM 71-00-00, LMM 71-00-00								
710011	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	04-May-23	A/R					
	HRS	1916.8						
	ENC	1354						
PROC. REF: LMM 71-00-00PROC. REF: LMM 71-00-00								
710011	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	23-Mar-19	A/R					
	HRS	1336.4						
	ENC	956						
PROC. REF: LMM 71-00-00PROC. REF: LMM 71-00-00								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:35C3100-01	MOS/MSC	05-Feb-10	E/C					
SN:PCE-LC0291	HRS	0						
WC#: 71.EN1	AFL	0						
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:35C3100-01	MOS/MSC	05-Feb-10	E/C					
SN:PCE-LC0292	HRS	0						
WC#: 71.EN2	AFL	0						
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								
ATA 72 - ENGINE								
72-00-00-001 ^S	VISUAL CHECK OF ENGINE MAINTENANCE PAGE FOR ENGINE DISPATCH AND EXCEEDANCE INFORMATION							Service ATA:72
	MOS	18-May-26	12 (+1m/-1m)					
	HRS	2523.1						
	AFL	1823						

PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: AMM 72-00-00PROC. REF: AMM 72-00-00								
72-00-00-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-802 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-802 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-803 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-803	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-804	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-804	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-805	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-805	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-806	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-212-806	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-215-801	^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-215-801	^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA						Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
72-00-00-215-802		NO. 1 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY						Service ATA:72
	MOS	18-May-26						
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-215-802	NO. 2 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY							Service ATA:72
	MOS	18-May-26						
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:2
72-00-00-215-803	NO. 1 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA							Service ATA:72
	MOS	18-May-26						
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:2
72-00-00-215-803	NO. 2 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA							Service ATA:72
	MOS	18-May-26						
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:2
72-00-00-280-802	NO. 1 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS							Service ATA:72
	MOS/MSC	19-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-280-802	NO. 2 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS							Service ATA:72
	MOS/MSC	20-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-290-804	NO. 1 ENGINE - PERFORM BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	25-Apr-24	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	2034.9						
	ENC	1464						
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00								
72-00-00-290-804	NO. 2 ENGINE - PERFORM BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	25-Apr-24	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	2034.9						
	ENC	1464						
PROC. REF: MM 72-00-00PROC. REF: MM 72-00-00								
72-00-00-290-815	NO. 1 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:72
	MOS	18-May-26						
	HRS	2522	1750 (+50)		(4272) 4272	4322	1672.3 (+50)	
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-290-815	NO. 2 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:72
	MOS	18-May-26						
	HRS	2522	1750 (+50)		(4272) 4272	4322	1672.3 (+50)	
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 1 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 4 DAYS							Service ATA:72
	MOS/MSC	-						
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-620-804	NO. 1 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED IN A HANGAR)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 1 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED OUTSIDE)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 2 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 4 DAYS							Service ATA:72
	MOS/MSC		-					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 2 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED IN A HANGAR)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-804	NO. 2 ENGINE - ALTERNATIVE PRESERVATION - IN-SERVICE ENGINES INACTIVE 1 - 28 DAYS (STORED OUTSIDE)							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-805	NO. 1 ENGINE - ENGINE UNPRESERVED - ENGINE INACTIVE ON-WING 1 - 28 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-620-805	NO. 1 ENGINE - PRESERVATION RECOMMENDATIONS FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-805	NO. 2 ENGINE - ENGINE UNPRESERVED - ENGINE INACTIVE ON-WING 1 - 28 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-805	NO. 2 ENGINE - PRESERVATION RECOMMENDATIONS FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-806	NO. 1 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 - 90 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-806	NO. 1 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-620-806	NO. 2 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 - 90 DAYS							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-620-806	NO. 2 ENGINE - PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00-640-803 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
								PKG:1
72-00-00-640-803 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
								PKG:1
72-00-01-810-822	NO. 1 ENGINE - TROUBLESHOOT ENGINE PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	19-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-01PROC. REF: MM 72-00-01								
72-00-01-810-822	NO. 2 ENGINE - TROUBLESHOOT ENGINE PERFORMANCE DETERIORATION							Service ATA:72
	MOS/MSC	20-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-01PROC. REF: MM 72-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-02-810-801	NO. 1 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM							Service ATA:72
	MOS/MSC	19-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-02PROC. REF: LMM 72-00-02								
72-00-02-810-801	NO. 2 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM							Service ATA:72
	MOS/MSC	20-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-02PROC. REF: LMM 72-00-02								
72-30-04-000-803	NO. 1 ENGINE - REPLACE FRONT NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	19-Oct-22		TSN 0				LIFE LIMIT
SN:RXA278G8	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								
72-30-04-000-803	NO. 2 ENGINE - REPLACE FRONT NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	19-Oct-22		TSN 0				LIFE LIMIT
SN:RXA499G6	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								
72-30-04-000-804	NO. 1 ENGINE - REPLACE REAR NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	19-Oct-22		TSN 0				LIFE LIMIT
SN:RXA866F4	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-30-04-000-804	NO. 2 ENGINE - REPLACE REAR NO. 4 BEARING CARBON SEAL							Component ATA:72
PN:35C6516	MOS	19-Oct-22		TSN 0				LIFE LIMIT
SN:RXA446G0	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04PROC. REF: MM 72-30-04, MM 72-30-04, LMM 72-30-04, LMM 72-30-04								
72-50-02-000-801	NO. 1 ENGINE - DISCARD HP TURBINE VANE RETAINING RING							Service ATA:72
	MOS	19-Oct-22						
	HRS	1799.9	1750 (+50)		(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-50-02-000-801	NO. 1 ENGINE - DISCARD HP TURBINE VANE RETAINING RING BOLTS							Service ATA:72
	MOS/MSC	19-Oct-22	A/R					
	HRS	1799.9						
	ENC	1273						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-50-02-000-801	NO. 2 ENGINE - DISCARD HP TURBINE VANE RETAINING RING							Service ATA:72
	MOS	19-Oct-22						
	HRS	1799.9	1750 (+50)		(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								
72-50-02-000-801	NO. 2 ENGINE - DISCARD HP TURBINE VANE RETAINING RING BOLTS							Service ATA:72
	MOS/MSC	19-Oct-22	A/R					
	HRS	1799.9						
	ENC	1273						
PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02PROC. REF: MM 72-50-02, MM 72-50-02, MM 72-50-02, LMM 72-50-02, LMM 72-50-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-01-000-805	NO. 1 ENGINE - DISCARD THE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER							Component ATA:72
PN:ST3983-01	MOS	19-Oct-22		TSN 0				DISCARD
SN:UNKNOWN	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: LMM 72-60-01, LMM 72-60-01PROC. REF: LMM 72-60-01, LMM 72-60-01								
72-60-01-000-805	NO. 2 ENGINE - DISCARD THE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER							Component ATA:72
PN:ST3983-01	MOS	19-Oct-22		TSN 0				DISCARD
SN:UNKNOWN	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: LMM 72-60-01, LMM 72-60-01PROC. REF: LMM 72-60-01, LMM 72-60-01								
720000	NO. 1 ENGINE - PERFORM ENGINE OVERHAUL							Service ATA:72
	MOS	19-Jan-10						OVERHAUL
	HRS	0	3500 (+100)		(3500) 3500	3600	900.3 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720000	NO. 2 ENGINE - PERFORM ENGINE OVERHAUL							Service ATA:72
	MOS	20-Jan-10						OVERHAUL
	HRS	0	3500 (+100)		(3500) 3500	3600	900.3 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720001	NO. 1 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION							Service ATA:72
	MOS	19-Oct-22						
	HRS	1799.9	1750 (+50)		(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273						
PROC. REF: MM 72-00-00, LMM 72-00-00PROC. REF: MM 72-00-00, LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720001	NO. 2 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION							Service ATA:72
	MOS	19-Oct-22						
	HRS	1799.9	1750 (+50)		(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273						
PROC. REF: MM 72-00-00, LMM 72-00-00PROC. REF: MM 72-00-00, LMM 72-00-00								
720003	NO. 1 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	18-May-26	24 (+1m)		18-May-28	18-Jun-28	652 d (+31)	
	HRS	2522						
	ENC	1824						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720003	NO. 2 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	18-May-26	24 (+1m)		18-May-28	18-Jun-28	652 d (+31)	
	HRS	2522						
	ENC	1824						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720010	NO. 1 ENGINE - FAN ROTOR							Component ATA:72
PN:35C3881-01	MOS	19-Jan-10		TSN 0				LIFE LIMIT
SN:AATPWACR048	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720010	NO. 2 ENGINE - FAN ROTOR							Component ATA:72
PN:35C3881-01	MOS	20-Jan-10		TSN 0				LIFE LIMIT
SN:AATPWACS019	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720030 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXTERIOR OF THE ENGINE FOR EVIDENCE OF OIL LEAKS							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
720030 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXTERIOR OF THE ENGINE FOR EVIDENCE OF OIL LEAKS							Service ATA:72
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
721010	NO. 1 ENGINE - HP TURBINE DISK							Component ATA:72
PN:35C3091-01	MOS	19-Jan-10		TSN 0				LIFE LIMIT
SN:CRAZADQG010	HRS	0		TSN 0				
	ENC	0		TSN 0	(5250) 5250 (M)		3380	
	ACCCYC	0	5250	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
721010	NO. 2 ENGINE - HP TURBINE DISK							Component ATA:72
PN:35C3091-01	MOS	20-Jan-10		TSN 0				LIFE LIMIT
SN:CRAZADQG039	HRS	0		TSN 0				
	ENC	0		TSN 0	(5250) 5250 (M)		3380	
	ACCCYC	0	5250	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
721015	NO. 1 ENGINE - HP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
721015	NO. 2 ENGINE - HP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
721020	NO. 1 ENGINE - LP TURBINE DISK							Component ATA:72
PN:35C5392-01	MOS	19-Jan-10		TSN 0				LIFE LIMIT
SN:CRAZADOZ308	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
721020	NO. 2 ENGINE - LP TURBINE DISK							Component ATA:72
PN:35C5392-01	MOS	20-Jan-10		TSN 0				LIFE LIMIT
SN:CRAZADOZ328	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
721025	NO. 1 ENGINE - LP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
721025	NO. 2 ENGINE - LP TURBINE DISK BALANCING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723010	NO. 1 ENGINE - IMPELLER AND SHAFT ASSEMBLY							Component ATA:72
PN:35C4716-01	MOS	19-Jan-10		TSN 0				LIFE LIMIT
SN:AAPPHZXP2010	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723010	NO. 2 ENGINE - IMPELLER AND SHAFT ASSEMBLY							Component ATA:72
PN:35C4716-01	MOS	20-Jan-10		TSN 0				LIFE LIMIT
SN:AAPPIAPC2070	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723015	NO. 1 ENGINE - LP COMPRESSOR SHAFT							Component ATA:72
PN:35C4620-01	MOS	19-Jan-10		TSN 0				LIFE LIMIT
SN:KWA5190821	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723015	NO. 2 ENGINE - LP COMPRESSOR SHAFT							Component ATA:72
PN:35C4620-01	MOS	20-Jan-10		TSN 0				LIFE LIMIT
SN:KWA5190814	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723020	NO. 1 ENGINE - TOWERSHAFT ANNULAR BALL BEARING							Component ATA:72
PN:35C2168-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN216746	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723020	NO. 2 ENGINE - TOWERSHAFT ANNULAR BALL BEARING							Component ATA:72
PN:35C2168-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN216744	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723025	NO. 1 ENGINE - HIGH COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:35C4832-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN308153	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723025	NO. 2 ENGINE - HIGH COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:35C4832-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN308150	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723030	NO. 1 ENGINE - LP SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:35C5051-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN310885	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723030	NO. 2 ENGINE - LP SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:35C5051-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN310890	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723035	NO. 1 ENGINE - LP SHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C4831-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN310396	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723035	NO. 2 ENGINE - LP SHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C4831-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN312347	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723040	NO. 1 ENGINE - TOWERSHAFT ROLLER BEARING							Component ATA:72
PN:3107496-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN310062	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - TOWERSHAFT ROLLER BEARING							Component ATA:72
PN:3107496-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN310071	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723045	NO. 1 ENGINE - HIGH COMPRESSOR ROTOR ROLLER BEARING							Component ATA:72
PN:35C4534-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN308841	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723045	NO. 2 ENGINE - HIGH COMPRESSOR ROTOR ROLLER BEARING							Component ATA:72
PN:35C4534-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN308840	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:35C5325-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:NYAB00005382	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-02, LMM 72-30-02PROC. REF: LMM 72-30-02, LMM 72-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:35C5325-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:NYAB00005356	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-02, LMM 72-30-02PROC. REF: LMM 72-30-02, LMM 72-30-02								
723055	NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY							Component ATA:72
PN:35C4935-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:RWA72C895	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723055	NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY							Component ATA:72
PN:35C4935-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:RWA72C626	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723060	NO. 1 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY							Component ATA:72
PN:35C4860-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:RWA73C559	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723060	NO. 2 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY							Component ATA:72
PN:35C4860-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:RWA73C687	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723065	NO. 1 ENGINE - LOWER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C5334-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:PKAAA282437	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723065	NO. 2 ENGINE - LOWER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C5334-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:PKAAA282442	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723070	NO. 1 ENGINE - UPPER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C3627-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:PKAAA290311	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723070	NO. 2 ENGINE - UPPER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:35C3627-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:PKAAA290307	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723075	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR							Component ATA:72
PN:35C3628-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:PKAAA251938	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723075	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR							Component ATA:72
PN:35C3628-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:PKAAA296386	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723080	NO. 1 ENGINE - IMPELLER CENTRIFUGAL ASSEMBLY							Component ATA:72
PN:35C4714-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:AAPPHZXP2010	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723080	NO. 2 ENGINE - IMPELLER CENTRIFUGAL ASSEMBLY							Component ATA:72
PN:35C4714-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:AAPPIAPC2070	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723085	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C5326-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:EYA19170	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723085	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C5326-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:EYA18715	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723090	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C4623-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:EYA19630	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723090	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:35C4623-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:EYA19632	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723095	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLY							Component ATA:72
PN:35C5330-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:PKAAA297255	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723095	NO. 2 ENGINE - COMPRESSOR STATOR ASSEMBLY							Component ATA:72
PN:35C5330-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:PKAAA297261	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723110	NO. 1 ENGINE - HOUSING IMPELLER ASSEMBLY							Component ATA:72
PN:35C5211-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:RWA72C243	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723110	NO. 2 ENGINE - HOUSING IMPELLER ASSEMBLY							Component ATA:72
PN:35C5211-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:RWA72C241	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724010	NO. 1 ENGINE - INNER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5050-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:A002NCFL	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724010	NO. 2 ENGINE - INNER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5050-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:A002NB2K	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724015	NO. 1 ENGINE - OUTER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5053-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:A002NEH7	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724015	NO. 2 ENGINE - OUTER COMBUSTOR CHAMBER LINER ASSEMBLY							Component ATA:72
PN:35C5053-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:A002NCFM	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - HP COMPRESSOR ROTOR							Component ATA:72
PN:35C4781-01	MOS	19-Jan-10		TSN 0				LIFE LIMIT
SN:AATPWACQ059	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - HP COMPRESSOR ROTOR							Component ATA:72
PN:35C4781-01	MOS	20-Jan-10		TSN 0				LIFE LIMIT
SN:AATPWACQ003	HRS	0		TSN 0				
	ENC	0		TSN 0	(10500) 10500 (M)		8630	
	ACCCYC	0	10500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725015	NO. 1 ENGINE - BALL ROLLER ANNULAR BEARING							Component ATA:72
PN:35C0590-02	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN308961	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725015	NO. 2 ENGINE - BALL ROLLER ANNULAR BEARING							Component ATA:72
PN:35C0590-02	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN308929	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725020	NO. 1 ENGINE - HIGH PRESSURE TURBINE CASE ASSEMBLY							Component ATA:72
PN:35C4726-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:RWA68C594	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725020	NO. 2 ENGINE - HIGH PRESSURE TURBINE CASE ASSEMBLY							Component ATA:72
PN:35C4726-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:RWA75C364	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725025	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:35C5563-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:DYA346053	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725025	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:35C5563-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:DYA346225	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725030	NO. 1 ENGINE - NO. 5 SEAL BEARING RUNNER							Component ATA:72
PN:35C4886-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:EYA19518	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725030	NO. 2 ENGINE - NO. 5 SEAL BEARING RUNNER							Component ATA:72
PN:35C4886-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:EYA19512	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725035	NO. 1 ENGINE - HIGH PRESSURE TURBINE TIE SHAFT							Component ATA:72
PN:35C5798-01	MOS/MSC	19-Oct-22	O/C	TSN 0				
SN:UNAA23211	HRS	1799.9		TSN 0				
	ENC	1273		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725035	NO. 2 ENGINE - HIGH PRESSURE TURBINE TIE SHAFT							Component ATA:72
PN:35C5798-01	MOS/MSC	19-Oct-22	O/C	TSN 0				
SN:UNAA23216	HRS	1799.9		TSN 0				
	ENC	1273		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4971CL01	MOS/MSC	19-Oct-22	O/C					
SN:PDANE480	HRS	1799.9						
	ENC	1273						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4971CL01	MOS/MSC	19-Oct-22	O/C					
SN:PDAHBNH01	HRS	1799.9						
	ENC	1273						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725045	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4622CL01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HLA062AA595	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725045	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE-RING							Component ATA:72
PN:35C4622CL01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HLA062AA576	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCW0744	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2645	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2646	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2653	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2654	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2664	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2670	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY2672	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9553	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9560	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9563	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCW0756	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9573	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9577	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9588	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9615	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9623	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9629	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9641	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9643	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9648	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCY9650	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCW0999	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA0950	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA0954	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA0961	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1037	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1041	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1042	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1047	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1052	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1058	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1060	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCW1002	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1061	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA1081	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2850	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2854	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2857	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2862	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2866	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2869	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2875	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2877	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCW1010	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWDA2884	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HWCW1016	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HCX2990	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 1 ENGINE - NO.8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HCY2636	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 1 ENGINE - NO.9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:HCY2643	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCW0695	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY2633	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY2637	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY2658	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY2660	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY2667	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9546	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9554	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9556	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9572	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY9579	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCW0748	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY9585	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY9586	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY9613	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY9619	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9622	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9625	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9638	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9640	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9653	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HCY9657	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCW0755	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0946	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0952	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0955	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0960	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0962	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0967	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0978	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0979	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0985	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0987	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCW0758	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA0991	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA1039	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA1053	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA1063	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA1077	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA1080	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA2847	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA2848	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA2851	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA2856	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCW1011	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWDA2860	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 2 ENGINE - NO.6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCW1020	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCX2991	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY2628	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - NO.9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:35C5521-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:HWCY2630	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726010	NO. 1 ENGINE - FLANGED ROLLER BEARING							Component ATA:72
PN:3107449-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN293520	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726010	NO. 2 ENGINE - FLANGED ROLLER BEARING							Component ATA:72
PN:3107449-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN291888	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726015	NO. 1 ENGINE - STARTER GEARSHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C3615-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FCN306919	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726015	NO. 2 ENGINE - STARTER GEARSHAFT BALL FLANGED BEARING							Component ATA:72
PN:35C3615-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FCN295894	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726020	NO. 1 ENGINE - ACCESSORY DRIVE GEAR SHAFT							Component ATA:72
PN:35C5333-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:PKAAA282391	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726020	NO. 2 ENGINE - ACCESSORY DRIVE GEAR SHAFT							Component ATA:72
PN:35C5333-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:PKAAA292627	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726025	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY							Component ATA:72
PN:35C5141-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:RWA64C367	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726025	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY							Component ATA:72
PN:35C5141-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:RWA72C433	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727010	NO. 1 ENGINE - BYPASS DUCT ASSEMBLY							Component ATA:72
PN:35C5332-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:FDA6189445	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
727010	NO. 2 ENGINE - BYPASS DUCT ASSEMBLY							Component ATA:72
PN:35C5332-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:FDA6210502	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-04-000-801	NO. 1 ENGINE - FUEL MANIFOLD							Component ATA:73
PN:35C6429-01	MOS	19-Oct-22		TSN 0				
SN:DEAAB83178	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-04-000-801	NO. 2 ENGINE - FUEL MANIFOLD							Component ATA:73
PN:35C6429-01	MOS	19-Oct-22		TSN 0				
SN:DEAAB83605	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-10-05-000-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
	MOS	18-May-26						
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PROC. REF: LMM 73-10-05, LMM 73-10-05PROC. REF: LMM 73-10-05, LMM 73-10-05								
PKG:2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-05-000-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
	MOS	18-May-26						
	HRS	2522	800 (+10%)		(3322) 3322	3402	722.3 (+80)	
	ENC	1824						
PROC. REF: LMM 73-10-05, LMM 73-10-05PROC. REF: LMM 73-10-05, LMM 73-10-05								PKG:2
73-10-05-220-801	NO. 1 ENGINE - DETAILED INSPECT THE FUEL FILTER							Service ATA:73
	MOS	18-May-26	12 (+30d)		18-May-27	17-Jun-27	286 d (+30)	
	HRS	2522						
	ENC	1824						
PROC. REF: LMM 73-10-05PROC. REF: LMM 73-10-05								
73-10-05-220-801	NO. 2 ENGINE - DETAILED INSPECT THE FUEL FILTER							Service ATA:73
	MOS	18-May-26	12 (+30d)		18-May-27	17-Jun-27	286 d (+30)	
	HRS	2522						
	ENC	1824						
PROC. REF: LMM 73-10-05PROC. REF: LMM 73-10-05								
73-10-07-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-10-07PROC. REF: LMM 73-10-07								PKG:1
73-10-07-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-10-07PROC. REF: LMM 73-10-07								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-02-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-20-02PROC. REF: LMM 73-20-02								PKG:1
73-20-02-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-20-02PROC. REF: LMM 73-20-02								PKG:1
73-21-01	LH ENG FULL AUTHORITY DIGITAL FADEC							Component ATA:73
PN:1009211-3-005	MOS/MSC	23-Dec-15	O/C					
SN:2011010011	HRS	889.4		TSN 2375				
	AFL	635		TSN 2109				
PROC. REF: AMM 73-21-01, AMM 73-21-01PROC. REF: AMM 73-21-01, AMM 73-21-01								
73-21-01	RH ENG FULL AUTHORITY DIGITAL FADEC							Component ATA:73
PN:1009211-3-005	MOS/MSC	23-Dec-15	O/C					
SN:2010070017	HRS	889.4		TSN 2018.67				
	AFL	635		TSN 1933				
PROC. REF: AMM 73-21-01, AMM 73-21-01PROC. REF: AMM 73-21-01, AMM 73-21-01								
73-21-02	NO.1 W205 FADEC CH B FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-21-02	NO.2 W205 FADEC CH B FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-21-03	NO.1 W203 FADEC CH A FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-21-03	NO.2 W203 FADEC CH A FUS CTRL HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-21-09	NO.1 W307 FADEC CH B HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-21-09	NO.2 W307 FADEC CH B HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-21-10	NO.1 W305 FADEC CH A HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
73-21-10	NO.2 W305 FADEC CH A HARNESS							Component ATA:73
PN:PN	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-30-02-212-801	^S	NO. 1 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON						Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-30-02PROC. REF: LMM 73-30-02								PKG:1
73-30-02-212-801	^S	NO. 2 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON						Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-30-02PROC. REF: LMM 73-30-02								PKG:1
73-30-02-215-801	^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR						Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-30-02PROC. REF: LMM 73-30-02								PKG:1
73-30-02-215-801	^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR						Service ATA:73
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 73-30-02PROC. REF: LMM 73-30-02								PKG:1
73-33-01	LH ENG FUEL FLOW METER							Component ATA:73
PN:8TJ300AAF2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:22478	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01PROC. REF: AMM 73-33-01, AMM 73-33-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-33-01	RH ENG FUEL FLOW METER							Component ATA:73
PN:8TJ300AAF2	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:22495	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01PROC. REF: AMM 73-33-01, AMM 73-33-01								
731002	NO. 1 ENGINE - FUEL TO OIL HEAT EXCHANGER							Component ATA:73
PN:35C4540-03	MOS	19-Jan-10		TSN 0				OVERHAUL
SN:WA38127	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	900.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 73-10-02, LMM 73-10-02PROC. REF: LMM 73-10-02, LMM 73-10-02								
731002	NO. 2 ENGINE - FUEL TO OIL HEAT EXCHANGER							Component ATA:73
PN:35C4540-03	MOS	20-Jan-10		TSN 0				OVERHAUL
SN:WA38135	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	900.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 73-10-02, LMM 73-10-02PROC. REF: LMM 73-10-02, LMM 73-10-02								
732101	NO. 1 ENGINE - FUEL METERING UNIT							Component ATA:73
PN:1009000-4	MOS	01-Nov-11		TSR 2				OVERHAUL
SN:F68617	HRS	232.9	3500 (+100)	TSN 0, TSR 0	(3732.9) 3732.9	3832.9	1133.2 (+100)	
	ENC	146		TSR 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01								
732101	NO. 2 ENGINE - FUEL METERING UNIT							Component ATA:73
PN:1009000-4	MOS	01-Nov-11		TSR 1				OVERHAUL
SN:F70313	HRS	232.9	3500 (+100)	TSN 0, TSR 0	(3732.9) 3732.9	3832.9	1133.2 (+100)	
	ENC	146		TSR 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732108	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732108	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732110	NO. 1 ENGINE - ENGINE ELECTRICAL WIRING HARNESS - DO A SPECIAL DETAILEDINSPECTION							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732110	NO. 2 ENGINE - ENGINE ELECTRICAL WIRING HARNESS - DO A SPECIAL DETAILEDINSPECTION							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732244	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL							Component ATA:73
PN:1009211-3-005	MOS/MSC	23-Dec-15	O/C					
SN:2011010011	HRS	889.4		TSN 2375.5				
	ENC	635		TSN 2109				
PROC. REF: LMM 73-20-03, LMM 73-20-03PROC. REF: LMM 73-20-03, LMM 73-20-03								
732244	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL							Component ATA:73
PN:1009211-2-005	MOS/MSC	23-Dec-15	O/C					
SN:2010070017	HRS	889.4						
	ENC	635						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: LMM 73-20-03, LMM 73-20-03PROC. REF: LMM 73-20-03, LMM 73-20-03								
733002	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR							Component ATA:73
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-30-02, LMM 73-30-02PROC. REF: LMM 73-30-02, LMM 73-30-02								
733002	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR							Component ATA:73
PN:35C5593-01	MOS/MSC	22-Dec-10	O/C					
SN:WDA113325	HRS							
	ENC							
PROC. REF: LMM 73-30-02, LMM 73-30-02PROC. REF: LMM 73-30-02, LMM 73-30-02								
733010	NO. 1 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR							Component ATA:73
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
733010	NO. 2 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR							Component ATA:73
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
733020	NO. 1 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-01, LMM 73-30-01PROC. REF: LMM 73-30-01, LMM 73-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733020	NO. 2 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-01, LMM 73-30-01PROC. REF: LMM 73-30-01, LMM 73-30-01								
733030	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR (POP-UP) - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-02, LMM 73-30-02PROC. REF: LMM 73-30-02, LMM 73-30-02								
733030	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR (POP-UP) - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:73
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 73-30-02, LMM 73-30-02PROC. REF: LMM 73-30-02, LMM 73-30-02								
ATA 74 - IGNITION								
74-00-01-720-801 ^S	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF THE IGNITION SYSTEM							Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:1
74-00-01-720-801 ^S	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF THE IGNITION SYSTEM							Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-10-01-212-801	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER						Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-10-01PROC. REF: LMM 74-10-01								PKG:1
74-10-01-212-801	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER						Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-10-01PROC. REF: LMM 74-10-01								PKG:1
74-20-01-212-801	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES						Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-20-01PROC. REF: LMM 74-20-01								PKG:1
74-20-01-212-801	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES						Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-20-01PROC. REF: LMM 74-20-01								PKG:1
74-20-02-220-801	^S	NO. 1 ENGINE - INSPECT THE IGNITION IGNITERS						Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-20-02, LMM 74-20-02PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-20-02-220-801	^S	NO. 2 ENGINE - INSPECT THE IGNITION IGNITERS						Service ATA:74
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 74-20-02, LMM 74-20-02PROC. REF: LMM 74-20-02, LMM 74-20-02								PKG:1
741001		NO. 1 ENGINE - IGNITION EXCITER						Component ATA:74
PN:35C5472-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:WDA109872	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-10-01, LMM 74-10-01PROC. REF: LMM 74-10-01, LMM 74-10-01								
741001		NO. 2 ENGINE - IGNITION EXCITER						Component ATA:74
PN:35C5472-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:WDA109773	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-10-01, LMM 74-10-01PROC. REF: LMM 74-10-01, LMM 74-10-01								
741002		NO. 1 ENGINE - LEFT IGNITER CABLE						Component ATA:74
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								
741002		NO. 2 ENGINE - LEFT IGNITER CABLE						Component ATA:74
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								
741003		NO. 1 ENGINE - RIGHT IGNITER CABLE						Component ATA:74
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741003	NO. 2 ENGINE - RIGHT IGNITER CABLE							Component ATA:74
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								
741004	NO. 1 ENGINE - INBOARD SPARK IGNITER							Component ATA:74
PN:35C2353-02	MOS/MSC	19-Oct-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1799.9		TSN 0				
	ENC	1273		TSN 0				
PROC. REF: LMM 74-20-02PROC. REF: LMM 74-20-02								
741004	NO. 2 ENGINE - INBOARD SPARK IGNITER							Component ATA:74
PN:35C2353-02	MOS/MSC	19-Oct-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1799.9		TSN 0				
	ENC	1273		TSN 0				
PROC. REF: LMM 74-20-02PROC. REF: LMM 74-20-02								
741005	NO. 1 ENGINE - OUTBOARD SPARK IGNITER							Component ATA:74
PN:35C2353-02	MOS/MSC	19-Oct-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1799.9		TSN 0				
	ENC	1273		TSN 0				
PROC. REF: LMM 74-20-02PROC. REF: LMM 74-20-02								
741005	NO. 2 ENGINE - OUTBOARD SPARK IGNITER							Component ATA:74
PN:35C2353-02	MOS/MSC	19-Oct-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1799.9		TSN 0				
	ENC	1273		TSN 0				
PROC. REF: LMM 74-20-02PROC. REF: LMM 74-20-02								
741010	NO. 1 ENGINE - IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 74-10-01PROC. REF: LMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741010	NO. 2 ENGINE - IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 74-10-01PROC. REF: LMM 74-10-01								
741020	NO. 1 ENGINE - LEFT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								
741020	NO. 2 ENGINE - LEFT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								
741030	NO. 1 ENGINE - RIGHT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								
741030	NO. 2 ENGINE - RIGHT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:74
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 74-20-01, LMM 74-20-01PROC. REF: LMM 74-20-01, LMM 74-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-212-801	^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA						Service ATA:75
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 75-30-01PROC. REF: LMM 75-30-01								PKG:1
75-30-01-212-801	^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA						Service ATA:75
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 75-30-01PROC. REF: LMM 75-30-01								PKG:1
75-30-01-830-801	^S	NO. 1 ENGINE - RIGGING THE BLEED VALVE ACTUATOR (BVA)						Service ATA:75
PN:35C2851-02	MOS/MSC	19-Jan-10	A/R					
SN:16720801	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01								
75-30-01-830-801	^S	NO. 2 ENGINE - RIGGING THE BLEED VALVE ACTUATOR (BVA)						Service ATA:75
PN:35C2851-02	MOS/MSC	20-Jan-10	A/R					
SN:16739828	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01PROC. REF: MM 75-30-01								
751003		NO. 1 ENGINE - BLEED VALVE ACTUATOR						Component ATA:75
PN:35C2851-02	MOS	19-Jan-10		TSN 0				OVERHAUL
SN:16720801	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	900.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 75-30-01, LMM 75-30-01PROC. REF: LMM 75-30-01, LMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
751003	NO. 2 ENGINE - BLEED VALVE ACTUATOR							Component ATA:75
PN:35C2851-02	MOS	20-Jan-10		TSN 0				OVERHAUL
SN:16739828	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	900.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 75-30-01, LMM 75-30-01PROC. REF: LMM 75-30-01, LMM 75-30-01								
ATA 76 - ENGINE CONTROLS								
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY							Component ATA:76
PN:6990010-11	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:1175	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 77 - ENGINE INDICATING								
77-20-02-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 77-20-02PROC. REF: LMM 77-20-02								PKG:1
77-20-02-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 77-20-02PROC. REF: LMM 77-20-02								PKG:1
77-20-02-215-801	NO. 1 ENGINE - ELECTRICAL FUNCTIONAL CHECK OF THE T6 THERMOCOUPLE SYSTEM (ON AIRCRAFT)							Service ATA:77
	MOS/MSC	19-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-02-215-801	NO. 2 ENGINE - ELECTRICAL FUNCTIONAL CHECK OF THE T6 THERMOCOUPLE SYSTEM (ON AIRCRAFT)							Service ATA:77
	MOS/MSC	20-Jan-10	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02								
77-20-02-710-801	NO. 1 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	04-Jun-25	36 (+30d)		04-Jun-28	04-Jul-28	669 d (+30)	
	HRS	2224.4	1750 (+50)		(3974.4) 3974.4	4024.4	1374.7 (+50)	
	ENC	1614						
PROC. REF: LMM 77-20-02PROC. REF: LMM 77-20-02								
77-20-02-710-801	NO. 2 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	04-Jun-25	36 (+30d)		04-Jun-28	04-Jul-28	669 d (+30)	
	HRS	2224.4	1750 (+50)		(3974.4) 3974.4	4024.4	1374.7 (+50)	
	ENC	1614						
PROC. REF: LMM 77-20-02PROC. REF: LMM 77-20-02								
77-20-02-750-801	NO. 1 ENGINE - FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS ASSEMBLY (REMOVED)							Service ATA:77
	MOS/MSC	19-Oct-22	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	1799.9						
	ENC	1273						
PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02								
77-20-02-750-801	NO. 2 ENGINE - FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS ASSEMBLY (REMOVED)							Service ATA:77
	MOS/MSC	19-Oct-22	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	1799.9						
	ENC	1273						
PROC. REF: MM 77-20-02PROC. REF: MM 77-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772002	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY							Component ATA:77
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-20-02, LMM 77-20-02PROC. REF: LMM 77-20-02, LMM 77-20-02								
772002	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY							Component ATA:77
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 77-20-02, LMM 77-20-02PROC. REF: LMM 77-20-02, LMM 77-20-02								
772010	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 77-20-02, LMM 77-20-02PROC. REF: LMM 77-20-02, LMM 77-20-02								
772010	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 77-20-02, LMM 77-20-02PROC. REF: LMM 77-20-02, LMM 77-20-02								
772103	NO. 1 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:35C5571-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:DP09-1594	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772103	NO. 2 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:35C5571-01	MOS/MSC	19-Dec-24	O/C					
SN:DP10-1743	HRS	2047.4						
	ENC	1478						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772110	NO. 1 ENGINE - DO A DCU INTEGRITY VERIFACTION							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 77-40-01, LMM 77-40-01PROC. REF: LMM 77-40-01, LMM 77-40-01								
772110	NO. 2 ENGINE - DO A DCU INTEGRITY VERIFACTION							Service ATA:77
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 77-40-01, LMM 77-40-01PROC. REF: LMM 77-40-01, LMM 77-40-01								
ATA 79 - OIL								
79-00-00-640-803	NO. 1 ENGINE - OIL CHANGE INTERVAL							Service ATA:79
	MOS/MSC	19-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
79-00-00-640-803	NO. 2 ENGINE - OIL CHANGE INTERVAL							Service ATA:79
	MOS/MSC	20-Jan-10	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
79-20-01-000-801	NO. 1 ENGINE - DISCARD OIL FILTER							Service ATA:79
	MOS	04-Jun-25						
	HRS	2224.4	800 (+10%)		(3024.4) 3024.4	3104.4	424.7 (+80)	
	ENC	1614						
PROC. REF: LMM 79-20-01, LMM 79-20-01PROC. REF: LMM 79-20-01, LMM 79-20-01								

PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20-01-000-801	NO. 2 ENGINE - DISCARD OIL FILTER							Service ATA:79
	MOS	04-Jun-25						
	HRS	2224.4	800 (+10%)		(3024.4) 3024.4	3104.4	424.7 (+80)	
	ENC	1614						
PROC. REF: LMM 79-20-01, LMM 79-20-01PROC. REF: LMM 79-20-01, LMM 79-20-01								PKG:2
79-20-03-000-805-A	NO. 1 ENGINE - DISCARD THE NO. 4 BEARING OIL-PRESSURE TUBE							Component ATA:79
PN:35C6509	MOS	19-Oct-22		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-03, LMM 79-20-03								
79-20-03-000-805-A	NO. 2 ENGINE - DISCARD THE NO. 4 BEARING OIL-PRESSURE TUBE							Component ATA:79
PN:35C6509	MOS	19-Oct-22		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	1799.9	1750 (+50)	TSN 0	(3549.9) 3549.9	3599.9	950.2 (+50)	
	ENC	1273		TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-03, LMM 79-20-03								
79-30-01-720-801 ^S	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
79-30-01-720-801 ^S	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-02-210-802	^S	NO. 1 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON						Service ATA:79
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 79-30-02PROC. REF: LMM 79-30-02								PKG:1
79-30-02-210-802	^S	NO. 2 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON						Service ATA:79
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 79-30-02PROC. REF: LMM 79-30-02								PKG:1
79-30-02-215-801	^S	NO. 1 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR						Service ATA:79
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 79-30-02PROC. REF: LMM 79-30-02								PKG:1
79-30-02-215-801	^S	NO. 2 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR						Service ATA:79
	MOS	18-May-26	12 (+30d)					
	HRS	2522	800 (+10%)					
	ENC	1824						
PROC. REF: LMM 79-30-02PROC. REF: LMM 79-30-02								PKG:1
79-31-01		LH ENG OIL TEMPERATURE PRESSURE SENSOR						Component ATA:79
PN:PT9903-275-40012	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0809-2508	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-01, AMM 79-31-01PROC. REF: AMM 79-31-01, AMM 79-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-31-01	RH ENG OIL TEMPERATURE PRESSURE SENSOR							Component ATA:79
PN:PT9903-275-40012	MOS/MSC	23-Mar-10	O/C	TSN 0				
SN:0809-2509	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-01, AMM 79-31-01PROC. REF: AMM 79-31-01, AMM 79-31-01								
792007	NO. 1 ENGINE - AIR COOLED OIL COOLER							Component ATA:79
PN:35C2495-05	MOS	19-Jan-10		TSN 0				OVERHAUL
SN:WA37899	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	900.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-07, LMM 79-20-07								
792007	NO. 2 ENGINE - AIR COOLED OIL COOLER							Component ATA:79
PN:35C2495-05	MOS	20-Jan-10		TSN 0				OVERHAUL
SN:WA37925	HRS	0	3500 (+100)	TSN 0	(3500) 3500	3600	900.3 (+100)	
	ENC	0		TSN 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-07, LMM 79-20-07PROC. REF: LMM 79-20-03, LMM 79-20-03, LMM 79-20-07, LMM 79-20-07								
792010	NO. 1 ENGINE - P3 AIR COOLER ASSEMBLY							Component ATA:79
PN:35C5545-01	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:TYAB1718	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - P3 AIR COOLER ASSEMBLY							Component ATA:79
PN:35C5545-01	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:TYAB1724	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793001	NO. 1 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: LMM 79-30-01, LMM 79-30-01PROC. REF: LMM 79-30-01, LMM 79-30-01								
793001	NO. 2 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01, LMM 79-30-01PROC. REF: LMM 79-30-01, LMM 79-30-01								
793002	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR							Component ATA:79
PN:PN	MOS/MSC	19-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-02, LMM 79-30-02PROC. REF: LMM 79-30-02, LMM 79-30-02								
793002	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR							Component ATA:79
PN:PN	MOS/MSC	20-Jan-10	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-30-02, LMM 79-30-02PROC. REF: LMM 79-30-02, LMM 79-30-02								
793010	NO. 1 ENGINE - CHIP DETECTOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS	19-Oct-22						
	HRS	1799.9	3500 (+100)		(5299.9) 5299.9	5399.9	2700.2 (+100)	
	ENC	1273						
PROC. REF: LMM 79-30-01, LMM 79-30-01PROC. REF: LMM 79-30-01, LMM 79-30-01								
793010	NO. 2 ENGINE - CHIP DETECTOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS	19-Oct-22						
	HRS	1799.9	3500 (+100)		(5299.9) 5299.9	5399.9	2700.2 (+100)	
	ENC	1273						
PROC. REF: LMM 79-30-01, LMM 79-30-01PROC. REF: LMM 79-30-01, LMM 79-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 100 Serial: 50000121 RegNo: N130EC HRS: 2599.7 AFL: 1870 As Of: 03-Aug-2026

05-Aug-2026 11:22 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793020	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR (POP-UP) - DO A DETAIL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 79-30-02, LMM 79-30-02PROC. REF: LMM 79-30-02, LMM 79-30-02								
793020	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR (POP-UP) - DO A DETAIL INSPECTION AND FUNCTIONAL TEST							Service ATA:79
	MOS							
	HRS	EFF	3500 (+100)		(3500) 3500 *	3600	900.3 (+100)	
	ENC							
PROC. REF: LMM 79-30-02, LMM 79-30-02PROC. REF: LMM 79-30-02, LMM 79-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task