



CARGO TRANSFER PROCEDURES



CBC 1107 EX: CHEM 1239 EX: AEP 10040

AEP 10001 thru AEP 10040
 JEFFBOAT HULL 13-2809 thru 13-2828 and 13-2861 thru 13-2880
 5,000 BBL/HR MAX TRANSFER RATE



CARGO TRANSFER PROCEDURES CBC 1107 EX: CHEM 1239 EX: AEP 10040

AEP 10001 thru AEP 10040
JEFFBOAT HULL 13-2809 thru 13-2828 and 13-2861 thru 13-2880
5,000 BBL/HR MAX TRANSFER RATE



CARGO TRANSFER PROCEDURES CBC 1107 EX: CHEM 1239 EX: AEP 10040

AEP 10001 thru AEP 10040
JEFFBOAT HULL 13-2809 thru 13-2828 and 13-2861 thru 13-2880
5,000 BBL/HR MAX TRANSFER RATE

