



SAGGING LINTEL?

Repair cracked brick above the garage with a routine Ox lintel repair.

BRICK & LINTEL REPAIR

Common Symptoms

- Visible sag in lintel
- Vertical cracks above garage opening
- Stair step cracks above garage opening



Bricks are carefully removed to access the lintel.



Additional support is provided during the lintel repair.



The lag bolts that are installed hold the lintel in place.



Avoid Misdiagnosis

- Foundation piers will not correct a sagging lintel. Piers may only cause more damage and will not correct brick cracks above the garage door opening.
- Horizontal cracks above the opening may point to a rusted lintel. A rusted lintel requires full replacement.



Removing the brick exposes the lintel. Rusted lintels must be replaced.

The Ox Difference

- A simple, yet reliable repair, typically one day
- Transferable warranty
- High standard of quality workmanship
- Free estimates and evidence-based repair plans
- No hidden clauses. No fine print.
- More experience. More satisfied customers.
- Guaranteed Ox Strong!