

ODC Daily Coaling Plan

25/07/2025

Geologist Contact: 0473 223 132



Location	Coal Type	Destination	Comments
T02	C_VU1_VU3	SP_O	
	C_VL1	VL Pad	DO not mine past RL95
T03	C_VU1_VU3		
	C_VL1	VL Pad	
	C_LL1	SP_C	Thin seam – take care when mining Tip Stockpile South to North
	C_LL2T_LL2B	SP_G	
	C_LL3B	SP_R	Thin seam – take care when mining. Stockpiled separately on R (western side)
T04	C_LL1	SP_C	Thin seam – take care when mining
	C_LL2T_LL2B	SP_P	
	C_LL3B	SP_M	
	C_VU1_VU3		
	C_VL1	VL_PAD	
T05 Ramp 6 De-Stack	C_LL3B	SP_F	
	C_LL2T_LL2B	SP_D	
	C_VU1_VU3	SP_A	
T05	C_LL1	SP_C	Thin seam – take care when mining
	C_LL2T_LL2B	SP_D	
	C_LL3B	SP_F	
	C_VU1_VU3	SP_A	

Roof and Floor Photos

If mining through coal roof / floor on nights, or when no inspection has occurred. Can photos of the cleaned roof/floor please be taken prior to mining.


**Please Do the Supervisor
Coal Inspection**



LL3 Roof




Flitch 102.5



T04/S01 123 RL

COAL CODE	STOCKPILE	COMMENTS
C_VU1_VU3		
C_VL1	VL Pad	
C_LL1	SP_C	Thin seam – take care when mining
C_LL2B_LL2T	SP_P	
C_LL3B	SP_M	Keep a gap between existing coal please


Terrace 4




- NOTES:
1. Post blast, drop into RL123 in front of Leichhardt coal and advance west.

T05/S01 144 RL


COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_C	Thin seam – take care when mining
C_LL2T_LL2B	SP_D	
C_LL3B	SP_R	Eastern Side
C_VU1_VU3	SP_A	
C_VL1	VL Pad	



Expect inconsistence
Flat LL3



ROM



Comments

Communicate any direct

feed start and finish time to

CHPP control.

When stockpile C is exhausted change to Blend 2 utilising the LL1 on Stockpile A

Once stockpile V is exhausted change to Blend 3

Stack Blend 6 and Blend 3 onto the Southern Side of the Coke Product Pile

Blends

	Feed 1	Feed 2	Feed 3	Ratio	ROM Loaders	ROM Trucks	Direct Feed	Comments
Blend 1	SP-C	SP-D	SP-R	1:1:1	1	2	No	1 x LL1 (T03S01) : 1 x LL2 (T05S02) : 1 x LL3 (T05S02)
Blend 2	SP-A	SP-D	SP-R	1:1:1	1	2	No	1 x LL1 (T04S01) : 1 x LL2 (T05S02) : 1 x LL3 (T05S02)
Blend 3	SP-O			Straight	1	2	No	VU (T02S01)
Blend 4								
Blend 5	SP-G	SP-A		1:2	1	1	No	1 x LL2 (T03S02): 2 x VU (T05S01)
Blend 6	SP-O	SP-V		2:1	1	1	No	2 x VU (T02S01): 1 x VL
Wet weather								

Plant Settings

[illegible]