







- INSTALLATION NOTES:**
1. Set door speeds and verify proper door operation prior to final connection of sensor system.
 2. Technician **MUST WALK TEST** to verify function and detection patterns comply with ANSI/BHMA A156.10 requirements.

TTX II CONTROL SETTING NOTES:
 For Software Version below 1.1, verify that Solid 2 is set to Flashing 2 and Solid 4 is set to Flashing 2.

For Software Versions 1.1 or greater, verify that Solid 2 is set to Flashing 5



NOTE:
 For Knowing Act applications all activation devices must connect to purple wires on OC-907 CT.
 (N/O, Dry Contact)
 Push / Pull Activation **MUST BE DISABLED** at the TTX Door Control.



Title: Tormax TTX II Single with Elite Pro		Drawing # 01TORTTXIIHELIP01
Drawing By: JAS	Date: 10/21/24	Sheet: 1 of 1
Optex Technologies Inc. 10741 Walker St., Suite 300, Cypress, CA 90630 Office: (800)877-6656, Fax: (310)214-8644		