




Dipswitch 1, 5 & 14 = ON,
15 & 16 = OFF

Dipswitch 1, 3, 5, 14 & 15 = ON,
16 = OFF

Notes:

1. Verify proper door operation prior to final connection of sensors.
2. Set System 20 control, AUX 04 IN=SIS, AUX 0 OUT=TEST SENSOR
3. Interior i-One XT dipswitch, 15 & 16 OFF, dipswitch 1, 5 & 14 ON
Exterior i-One XT dipswitch 16 OFF, dipswitch 1, 3, 5, 14 & 15 ON
4. Technician must perform a field test to verify substantial compliance with ANSI/BHMA A156.10 Section 8.

Title: 16300150 RECORD SYSTEM 20 with i-oneX T		Drawing # 16300150
Drawing By: JCK	Date: 5-9-16	Sheet: 1 of 1
OPTEX Technologies Inc. 18730 S. Wilmington Ave. Unit 100 Rancho Dominguez, CA. 90220 800-877-6656 FAX 310-898-1098		