





Dorma ESA II




- Notes:
1. Verify proper door operation prior to final connections of sensors.
 2. Mandatory Dipswitch Setting ■ set dipswitch 9 OFF (DOWN) and 10 & 11 ON (UP).
 3. Alternate frequency dipswitches 5 & 6, when installing two or more sensors in near promity with one another.
 4. Technician must perform a field test to verify substantial compliance with ANSI/BHMA A156.10 Section 8.



EXTERIOR OA-FLEX T



INTERIOR OA-FLEX T



Title: 16300220 Dorma ESA II with OA-FLEX T		Drawing # 16300220
Drawing By: RNG	Date: 07/19/17	Sheet: 1 of 1
OPTEx Technologies Inc. 18730 S. Wilmington Ave. Unit 100 Rancho Dominguez, CA. 90220 800-877-6656 FAX 310-898-1098		