

Instruction Guide

Table of Contents

Components List	:
•	
Access Point Connection Instructions	4,5



Components List



Kit Includes:


- (1) Cloud Gateway Ultra w/ Power Supply Cord
- (5) Access Points & Mounting Options
- (5) PoE Adapter (15W)
- (1) USB C Cord
- (5) 3 FT Ethernet Cord
- (1) 1M Patch Cable
- (1) 1 FT Patch Cable



Access Point Connection Instructions


Step 1

Connect Ethernet Cable from WAN port (To Kit) on Cloud Gateway Ultra (White Box) to ethernet port on BLEND or CONNECT Kit.



Step 2

Plug Cloud Gateway Ultra (white box) into power source via USB C cord.



Step 3

Power on the BLEND or CONNECT Kit. (if not already on).




Access Point Connection Instructions

Step 4

Connect & Stage Access Point 1 (AP1) to Cloud Gateway Ultra (White Box)

a. Connect a patch cable from LAN port (To AP 1) to PoE Adapter on < ··· > side, then connect an ethernet cord on the lightning bolt side to AP 1, plug in power cord to power source and PoE Adapter.



Step 5

Stage 4 Access Points AP2 AP3 AP4 AP5, Ethernet Cable, and PoE Adapter in desired locations for extended Wi-Fi.

NOTE: Wi-Fi strength will begin to decline at larger straight-line distances from the Cloud Gateway Ultra / Starlink Case

It is recommended to keep each Access Point within 50 feet of another.

Step 6

Connect via your device's settings Wi-Fi.

