



Status Report

GLOBAL 5000

S/N 9359 OM-NTN

OWNER: NOTINO S.R.O.

ADDRESS: -

OFFICE:

FAX:

OPERATOR: ELITE JET S.R.O.

ADDRESS: PESTOVATELSKA 2
BRATISLAVA 821 04

OFFICE: +421 911 777 777

FAX:

CAMO: ELITE JET S.R.O.

ADDRESS: OPAVSKA 26
BRATISLAVA BRATISLAVA 83101

OFFICE: +421 902 955 910

FAX:

ANALYST: ATHANASIOS FILIAS
EMAIL: ATHANASIOS.FILIAS@CAMPSYSTEMS.EU

+33.1.55.93.47.72 (DIRECT)
+33-1.55.93.45.80 (MAIN)
WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : ATA:05, 08, 11, 12, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 44, 45, 46, 49, 52, 53, 54, 55, 56, 57, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80;Spl.
Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL / REGNO: 9359/OM-NTN	MODEL: GLOBAL 5000	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 30-JUL-2009		LAST ACTUALS: 3445:56 A/C HRS as of 26-FEB-2025 1389 AFL as of 26-FEB-2025	
APU	SERIAL / PART: P-487/WE3800714-1	MODEL: RE220 (GX)	MANUFACTURER: HONEYWELL
INSTALLED ON: 30-AUG-2010		LAST ACTUALS:	
0	APU HRS 0 A/C HRS	3158	APU HRS as of 26-FEB-2025
0	APUS	3308	APUS as of 26-FEB-2025
ENGINE NO. 1	SERIAL / PART: 12833/BR710	MODEL: BR700-710A2-20 (CIMMS)	MANUFACTURER: ROLLS-ROYCE DERBY PLC
INSTALLED ON: 30-AUG-2010		LAST ACTUALS:	
0	ENG. HRS 0 A/C HRS	3445:56	ENG. HRS as of 26-FEB-2025
0	ENC	1390	ENC as of 26-FEB-2025
ENGINE NO. 2	SERIAL / PART: 12834/BR710	MODEL: BR700-710A2-20 (CIMMS)	MANUFACTURER: ROLLS-ROYCE DERBY PLC
INSTALLED ON: 30-AUG-2010		LAST ACTUALS:	
0	ENG. HRS 0 A/C HRS	3445:56	ENG. HRS as of 26-FEB-2025
0	ENC	1390	ENC as of 26-FEB-2025



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 1 ENGINE - NO. 1 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57556	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.225	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 10 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57516	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.270	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 11 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57484	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.275	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 12 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57789	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.280	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 13 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57418	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.285	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 1 ENGINE - NO. 14 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57930	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.290	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 15 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57955	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.295	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 16 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57948	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.300	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 17 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57764	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.305	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 18 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE56984	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.310	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 1 ENGINE - NO. 19 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57946	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.315	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 2 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57970	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.230	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 20 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57967	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.320	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 21 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57929	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.325	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 22 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:202542RGE108218	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.330	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 1 ENGINE - NO. 23 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57786	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.335	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 24 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57767	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.340	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 3 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57737	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.235	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 4 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57721	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.240	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 5 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE58078	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.245	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 1 ENGINE - NO. 6 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57718	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.250	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 7 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE57938	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.255	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 8 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE58008	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.260	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 1 ENGINE - NO. 9 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSO 0				LIFE LIMIT
SN:RGE56782	HRS	2444:24		TSN 2444:24, TSO 0				
WC#: 72.265	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 1 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21		TSN 139				LIFE LIMIT
SN:RGE59099	HRS	2444:24		TSN 2444:24				
WC#: 72.225	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 2 ENGINE - NO. 10 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59105	HRS	2444:24		TSN 2444:24				
WC#: 72.270	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 11 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59152	HRS	2444:24		TSN 2444:24				
WC#: 72.275	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 12 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59118	HRS	2444:24		TSN 2444:24				
WC#: 72.280	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 13 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59225	HRS	2444:24		TSN 2444:24				
WC#: 72.285	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 14 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59215	HRS	2444:24		TSN 2444:24				
WC#: 72.290	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 2 ENGINE - NO. 15 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58363	HRS	2444:24		TSN 2444:24				
WC#: 72.295	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 16 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59190	HRS	2444:24		TSN 2444:24				
WC#: 72.300	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 17 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58990	HRS	2444:24		TSN 2444:24				
WC#: 72.305	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 18 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE57593	HRS	2444:24		TSN 2444:24				
WC#: 72.310	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 19 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59154	HRS	2444:24		TSN 2444:24				
WC#: 72.315	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 2 ENGINE - NO. 2 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58582	HRS	2444:24		TSN 2444:24				
WC#: 72.230	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 20 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58026	HRS	2444:24		TSN 2444:24				
WC#: 72.320	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 21 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59214	HRS	2444:24		TSN 2444:24				
WC#: 72.325	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 22 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58199	HRS	2444:24		TSN 2444:24				
WC#: 72.330	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 23 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE57520	HRS	2444:24		TSN 2444:24				
WC#: 72.335	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 2 ENGINE - NO. 24 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59090	HRS	2444:24		TSN 2444:24				
WC#: 72.340	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 3 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59122	HRS	2444:24		TSN 2444:24				
WC#: 72.235	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 4 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59156	HRS	2444:24		TSN 2444:24				
WC#: 72.240	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 5 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE59157	HRS	2444:24		TSN 2444:24				
WC#: 72.245	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 6 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58220	HRS	2444:24		TSN 2444:24				
WC#: 72.250	ENC	746	10000	TSN 746	(10000) 9999		8610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-003	NO. 2 ENGINE - NO. 7 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58364	HRS	2444:24		TSN 2444:24				
WC#: 72.255	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 8 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE56528	HRS	2444:24		TSN 2444:24				
WC#: 72.260	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-003	NO. 2 ENGINE - NO. 9 LP COMPRESSOR ROTOR BLADE							Component ATA:05
PN:FW33513	MOS	05-Feb-21						LIFE LIMIT
SN:RGE58835	HRS	2444:24		TSN 2444:24				
WC#: 72.265	ENC	746	10000	TSN 746	(10000) 9999		8610	
05-00-03-870-004	NO. 1 ENGINE - NO. 1 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE42660	HRS	2444:24		TSN 0				
WC#: 72.100	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 10 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52510	HRS	2444:24		TSN 0				
WC#: 72.145	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 1 ENGINE - NO. 11 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52521	HRS	2444:24		TSN 0				
WC#: 72.150	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 12 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52528	HRS	2444:24		TSN 0				
WC#: 72.155	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 13 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE45449	HRS	2444:24		TSN 0				
WC#: 72.160	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 14 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52529	HRS	2444:24		TSN 0				
WC#: 72.165	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 15 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52508	HRS	2444:24		TSN 0				
WC#: 72.170	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 1 ENGINE - NO. 16 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54264	HRS	2444:24		TSN 0				
WC#: 72.175	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 17 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52512	HRS	2444:24		TSN 0				
WC#: 72.180	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 18 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54257	HRS	2444:24		TSN 0				
WC#: 72.185	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 19 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52509	HRS	2444:24		TSN 0				
WC#: 72.190	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 2 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52530	HRS	2444:24		TSN 0				
WC#: 72.105	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 1 ENGINE - NO. 20 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52524	HRS	2444:24		TSN 0				
WC#: 72.195	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 21 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52514	HRS	2444:24		TSN 0				
WC#: 72.200	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 22 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54262	HRS	2444:24		TSN 0				
WC#: 72.205	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 23 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52531	HRS	2444:24		TSN 0				
WC#: 72.210	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 24 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52525	HRS	2444:24		TSN 0				
WC#: 72.215	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 1 ENGINE - NO. 3 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52513	HRS	2444:24		TSN 0				
WC#: 72.110	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 4 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52523	HRS	2444:24		TSN 0				
WC#: 72.115	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 5 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE44760	HRS	2444:24		TSN 0				
WC#: 72.120	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 6 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52511	HRS	2444:24		TSN 0				
WC#: 72.125	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 7 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE42681	HRS	2444:24		TSN 0				
WC#: 72.130	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 1 ENGINE - NO. 8 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE45228	HRS	2444:24		TSN 0				
WC#: 72.135	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 1 ENGINE - NO. 9 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54260	HRS	2444:24		TSN 0				
WC#: 72.140	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 1 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE44595	HRS	2444:24		TSN 0				
WC#: 72.100	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 10 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52515	HRS	2444:24		TSN 0				
WC#: 72.145	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 11 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52520	HRS	2444:24		TSN 0				
WC#: 72.150	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 2 ENGINE - NO. 12 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54263	HRS	2444:24		TSN 0				
WC#: 72.155	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 13 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE48247	HRS	2444:24		TSN 0				
WC#: 72.160	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 14 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54258	HRS	2444:24		TSN 0				
WC#: 72.165	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 15 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54259	HRS	2444:24		TSN 0				
WC#: 72.170	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 16 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54247	HRS	2444:24		TSN 0				
WC#: 72.175	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004		NO. 2 ENGINE - NO. 17 LP COMPRESSOR ANNULUS FILLER						Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52519	HRS	2444:24		TSN 0				
WC#: 72.180	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004		NO. 2 ENGINE - NO. 18 LP COMPRESSOR ANNULUS FILLER						Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54245	HRS	2444:24		TSN 0				
WC#: 72.185	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004		NO. 2 ENGINE - NO. 19 LP COMPRESSOR ANNULUS FILLER						Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54242	HRS	2444:24		TSN 0				
WC#: 72.190	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004		NO. 2 ENGINE - NO. 2 LP COMPRESSOR ANNULUS FILLER						Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54261	HRS	2444:24		TSN 0				
WC#: 72.105	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004		NO. 2 ENGINE - NO. 20 LP COMPRESSOR ANNULUS FILLER						Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54255	HRS	2444:24		TSN 0				
WC#: 72.195	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 2 ENGINE - NO. 21 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE55712	HRS	2444:24		TSN 0				
WC#: 72.200	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 22 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54256	HRS	2444:24		TSN 0				
WC#: 72.205	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 23 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52522	HRS	2444:24		TSN 0				
WC#: 72.210	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 24 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54265	HRS	2444:24		TSN 0				
WC#: 72.215	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 3 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE45274	HRS	2444:24		TSN 0				
WC#: 72.110	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004	NO. 2 ENGINE - NO. 4 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE45516	HRS	2444:24		TSN 0				
WC#: 72.115	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 5 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE45269	HRS	2444:24		TSN 0				
WC#: 72.120	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 6 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52516	HRS	2444:24		TSN 0				
WC#: 72.125	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 7 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54246	HRS	2444:24		TSN 0				
WC#: 72.130	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-004	NO. 2 ENGINE - NO. 8 LP COMPRESSOR ANNULUS FILLER							Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE54266	HRS	2444:24		TSN 0				
WC#: 72.135	ENC	746	9700	TSN 0	(10446) 10445		9056	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-004		NO. 2 ENGINE - NO. 9 LP COMPRESSOR ANNULUS FILLER						Component ATA:05
PN:FW77117	MOS	05-Feb-21		TSN 0				LIFE LIMIT
SN:200027LRE52518	HRS	2444:24		TSN 0				
WC#: 72.140	ENC	746	9700	TSN 0	(10446) 10445		9056	
05-00-03-870-005		NO. 1 ENGINE - INTERMEDIATE CASE						Component ATA:05
PN:BRR22752	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:01583	HRS	0		TSN 0				
WC#: 72.350	ENC	0	20000	TSN 0	(20000) 19999	20000	18610	
05-00-03-870-005		NO. 2 ENGINE - INTERMEDIATE CASE						Component ATA:05
PN:BRR22752	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:01578	HRS	0		TSN 0				
WC#: 72.350	ENC	0	20000	TSN 0	(20000) 19999	20000	18610	
05-00-03-870-006		NO. 1 ENGINE - REAR BEARING SUPPORT STRUCTURE						Component ATA:05
PN:BRR23504	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01565	HRS	0		TSN 0				
WC#: 72.355	ENC	0		TSN 0				
05-00-03-870-006		NO. 2 ENGINE - REAR BEARING SUPPORT STRUCTURE						Component ATA:05
PN:BRR23504	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01637	HRS	0		TSN 0				
WC#: 72.355	ENC	0		TSN 0				
05-00-03-870-007		NO. 1 ENGINE - NO. 4 STUB SHAFT						Component ATA:05
PN:BRR24545	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:957	HRS	0		TSN 0				
WC#: 72.465	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-03-870-007	NO. 2 ENGINE - NO. 4 STUB SHAFT							Component ATA:05
PN:BRR24545	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:956	HRS	0		TSN 0				
WC#: 72.465	ENC	0		TSN 0				
05-00-04-870-001	NO. 1 ENGINE - NOSE CONE FAIRING							Component ATA:05
PN:BRR24368	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BA82092	HRS	0		TSN 0				
WC#: 72.420	ENC	0		TSN 0				
05-00-04-870-001	NO. 2 ENGINE - NOSE CONE FAIRING							Component ATA:05
PN:BRR24368	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BA82194	HRS	0		TSN 0				
WC#: 72.420	ENC	0		TSN 0				
05-00-04-870-002	NO. 1 ENGINE - NO. 1 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.430	ENC	0		TSN 0				
05-00-04-870-002	NO. 1 ENGINE - NO. 2 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.435	ENC	0		TSN 0				
05-00-04-870-002	NO. 1 ENGINE - NO. 3 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.440	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-00-04-870-002	NO. 1 ENGINE - NO. 4 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.445	ENC	0		TSN 0				
05-00-04-870-002	NO. 2 ENGINE - NO. 1 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.430	ENC	0		TSN 0				
05-00-04-870-002	NO. 2 ENGINE - NO. 2 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.435	ENC	0		TSN 0				
05-00-04-870-002	NO. 2 ENGINE - NO. 3 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.440	ENC	0		TSN 0				
05-00-04-870-002	NO. 2 ENGINE - NO. 4 STAGE 4 AIR PIPE							Component ATA:05
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.445	ENC	0		TSN 0				
05-10-01-870-002	NO. 1 ENGINE - LP COMPRESSOR DISK							Component ATA:05
PN:FW33927	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:STDK53104	HRS	0		TSN 0				
WC#: 72.220	ENC	0	4800	TSN 0	(4800) 4799	4800	3410	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-870-002	NO. 2 ENGINE - LP COMPRESSOR DISK							Component ATA:05
PN:FW33927	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:STDK53105	HRS	0		TSN 0				
WC#: 72.220	ENC	0	4800	TSN 0	(4800) 4799	4800	3410	
05-10-01-870-003	NO. 1 ENGINE - FAN SHAFT							Component ATA:05
PN:BRR23914	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:CL27165	HRS	0		TSN 0				
WC#: 72.345	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-01-870-003	NO. 2 ENGINE - FAN SHAFT							Component ATA:05
PN:BRR23914	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:CL26836	HRS	0		TSN 0				
WC#: 72.345	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-01-870-004	NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK							Component ATA:05
PN:BRR24382	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:2878	HRS	0		TSN 0				
WC#: 72.405	ENC	0	15000	TSN 0	(15000) 14999	15000	13610	
05-10-01-870-004	NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 1 - 6) DISK							Component ATA:05
PN:BRR24382	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:2926	HRS	0		TSN 0				
WC#: 72.405	ENC	0	15000	TSN 0	(15000) 14999	15000	13610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-870-005	NO. 1 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK							Component ATA:05
PN:BRR24357	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:3842	HRS	0		TSN 0				
WC#: 72.410	ENC	0	15000	TSN 0	(15000) 14999	15000	13610	
05-10-01-870-005	NO. 2 ENGINE - HP COMPRESSOR ROTOR (STAGES 7 - 10) DISK							Component ATA:05
PN:BRR24357	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:3844	HRS	0		TSN 0				
WC#: 72.410	ENC	0	15000	TSN 0	(15000) 14999	15000	13610	
05-10-01-870-006	NO. 1 ENGINE - CURVIC RING							Component ATA:05
PN:BRH20340	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:7020	HRS	0		TSN 0				
WC#: 72.450	ENC	0	15000	TSN 0	(15000) 14999	15000	13610	
05-10-01-870-006	NO. 2 ENGINE - CURVIC RING							Component ATA:05
PN:BRR20340	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:6977	HRS	0		TSN 0				
WC#: 72.450	ENC	0	15000	TSN 0	(15000) 14999	15000	13610	
05-10-01-870-007	NO. 1 ENGINE - HP TURBINE ROTOR STAGE 1 DISK							Component ATA:05
PN:BRR23952	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:LDRQA03709	HRS	0		TSN 0				
WC#: 72.455	ENC	0	6200	TSN 0	(6200) 6199		4810	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-870-007	NO. 2 ENGINE - HP TURBINE ROTOR STAGE 1 DISK							Component ATA:05
PN:BRR23952	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:LDRQA03612	HRS	0		TSN 0				
WC#: 72.455	ENC	0	6200	TSN 0	(6200) 6199		4810	
05-10-01-870-008	NO. 1 ENGINE - HP TURBINE ROTOR STAGE 2 DISK							Component ATA:05
PN:BRR22008	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:LDRQA03607	HRS	0		TSN 0				
WC#: 72.460	ENC	0	10500	TSN 0	(10500) 10499		9110	
05-10-01-870-008	NO. 2 ENGINE - HP TURBINE ROTOR STAGE 2 DISK							Component ATA:05
PN:BRR22008	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:LDRQA03582	HRS	0		TSN 0				
WC#: 72.460	ENC	0	10500	TSN 0	(10500) 10499		9110	
05-10-01-870-009	NO. 1 ENGINE - LP TURBINE ROTOR STAGE 1 DISK							Component ATA:05
PN:BRR15535	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:6973	HRS	0		TSN 0				
WC#: 72.470	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-01-870-009	NO. 2 ENGINE - LP TURBINE ROTOR STAGE 1 DISK							Component ATA:05
PN:BRR15535	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:6986	HRS	0		TSN 0				
WC#: 72.470	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-870-010	NO. 1 ENGINE - LP TURBINE ROTOR STAGE 2 DISK							Component ATA:05
PN:BRR11896	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:6993	HRS	0		TSN 0				
WC#: 72.475	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-01-870-010	NO. 2 ENGINE - LP TURBINE ROTOR STAGE 2 DISK							Component ATA:05
PN:BRR11896	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:6991	HRS	0		TSN 0				
WC#: 72.475	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-01-870-011	NO. 1 ENGINE - LP TURBINE ROTOR SHAFT							Component ATA:05
PN:BRR19612	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:SBAN1404	HRS	0		TSN 0				
WC#: 72.485	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-01-870-011	NO. 2 ENGINE - LP TURBINE ROTOR SHAFT							Component ATA:05
PN:BRR19612	MOS	30-Jul-09		TSN 0				LIFE LIMIT
SN:SBAN1218	HRS	0		TSN 0				
WC#: 72.485	ENC	0	25000	TSN 0	(25000) 24999	25000	23610	
05-10-05-870-001	NO. 1 ENGINE - FUEL PUMP VESPEL COUPLING							Component ATA:05
PN:PN	MOS	30-Jul-09		TSN 0				
SN:UNKNOWN	HRS	0	3500	TSN 0	(3500) 3500		54:04	
	ENC	0		TSN 0				
PROC. REF: EMM 73-11-01, EMM 73-11-01PROC. REF: EMM 73-11-01, EMM 73-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-05-870-001	NO. 2 ENGINE - FUEL PUMP VESPEL COUPLING							Component ATA:05
PN:PN	MOS	30-Jul-09		TSN 0				
SN:UNKNOWN	HRS	0	3500	TSN 0	(3500) 3500		54:04	
	ENC	0		TSN 0				
PROC. REF: EMM 73-11-01, EMM 73-11-01PROC. REF: EMM 73-11-01, EMM 73-11-01								
05-51-01-210-801	GENERAL VISUAL INSPECTION AFTER AN OVERWEIGHT LANDING							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 01 210 801PROC. REF: AMM 05 51 01 210 801								
05-51-02-210-801	GENERAL VISUAL INSPECTION AFTER A HARD LANDING							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 02 210 801PROC. REF: AMM 05 51 02 210 801								
05-51-03-210-801	GENERAL VISUAL INSPECTION AFTER EXTREME TURBULENCE/MANEUVER							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 03 210 801PROC. REF: AMM 05 51 03 210 801								
05-51-04-210-801	GENERAL VISUAL INSPECTION AFTER LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 04 210 801PROC. REF: AMM 05 51 04 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-51-05-210-801	GENERAL VISUAL INSPECTION OF THE FLAPS, THE SLATS AND THE LANDING GEAR AFTER AN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 05 210 801PROC. REF: AMM 05 51 05 210 801								
05-51-06-210-801	GENERAL VISUAL INSPECTION AFTER A TIRE BURST ON THE NOSE LANDING GEAR (NLG)							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 06 210 801PROC. REF: AMM 05 51 06 210 801								
05-51-06-210-802	GENERAL VISUAL INSPECTION AFTER A TIRE BURST ON THE MAIN LANDING GEAR (MLG)							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 06 210 802PROC. REF: AMM 05 51 06 210 802								
05-51-06-210-803	GENERAL VISUAL INSPECTION AFTER A TIRE DEFLATES							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 06 210 803PROC. REF: AMM 05 51 06 210 803								
05-51-07-210-801	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AFTER AN OVERHEAT INDICATION							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 07 210 801PROC. REF: AMM 05 51 07 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-51-10-210-801	GENERAL VISUAL INSPECTION OF THE AC MOTOR-DRIVEN PUMP (ACMP) AFTER DRY OPERATION							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 10 210 801PROC. REF: AMM 05 51 10 210 801								
05-51-11-210-801	GENERAL VISUAL INSPECTION OF THE ENGINE DRIVEN PUMP (EDP) AFTER DRY OPERATION							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 11 210 801PROC. REF: AMM 05 51 11 210 801								
05-51-12-281-801	ACIDITY CHECK OF THE HYDRAULIC FLUID AFTER SYSTEM OVERHEAT							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 12 281 801PROC. REF: AMM 05 51 12 281 801								
05-51-13-220-801	DETAILED DIMENSIONAL INSPECTION OF AIRCRAFT FOR SYMMETRY AND ALIGNMENT							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 13 220 801PROC. REF: AMM 05 51 13 220 801								
05-51-14-210-801	CONTAMINATION CHECK							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 14 210 801PROC. REF: AMM 05 51 14 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-51-39-220-801	DETAILED INSPECTION AFTER A HYDRAULIC FLUID SPILL OR LEAK							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 39 220 801PROC. REF: AMM 05 51 39 220 801								
05-51-43-210-801	INSPECTION AFTER THE AIRCRAFT IS PARKED IN STRONG WINDS OR WINDGUSTS							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 43 210 801PROC. REF: AMM 05 51 43 210 801								
05-51-43-210-802	INSPECTION AFTER THE AIRCRAFT IS TAXIED IN STRONG WINDS OR WINDGUSTS							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 43 210 802PROC. REF: AMM 05 51 43 210 802								
05-51-45-210-801	GENERAL VISUAL INSPECTION AFTER A BIRD STRIKE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 45 210 801PROC. REF: AMM 05 51 45 210 801								
05-51-46-210-801	INSPECTION AFTER RAPID CONTROL REVERSAL							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 46 210 801PROC. REF: AMM 05 51 46 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-51-48-210-801	GENERAL VISUAL INSPECTION AFTER VOLCANIC ASH CONTAMINATION							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 48 210 801PROC. REF: AMM 05 51 48 210 801								
05-51-49-210-801	GENERAL VISUAL INSPECTION AFTER FIRE EXTINGUISHING FOAM CONTAMINATION							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 49 210 801PROC. REF: AMM 05 51 49 210 801								
05-51-50-210-801	INSPECTION OF AIRCRAFT AFTER CONTAMINATION WIH SALT-BASED RUNWAY DE-ICING PRODUCTS							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 50 210 801PROC. REF: AMM 05 51 50 210 801								
05-51-51-110-801	CLEANING AFTER BATTERY ELECTROLYTE SPILLAGE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 51 110 801PROC. REF: AMM 05 51 51 110 801								
05-51-52-910-801	DEMAGNETIZATION OF THE AIRCRAFT COMPONENTS AND/OR STRUCTURES							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 05 51 52 910 801PROC. REF: AMM 05 51 52 910 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-52-01-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER SURGE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-01-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER SURGE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-02-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-02-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-03-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER INGESTION OF VOLCANIC ASH							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-52-03-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER INGESTION OF VOLCANIC ASH							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-04-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER BIRD STRIKE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-04-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER BIRD STRIKE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-05-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER SHOCK LOAD							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-05-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER SHOCK LOAD							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-52-06-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER SHEDDING/INGESTION OF ICE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-06-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER SHEDDING/INGESTION OF ICE							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-07-220-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER IN-FLIGHT SHUTDOWN							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-07-220-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE AFTER IN-FLIGHT SHUTDOWN							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-52-08-220-801	NO. 1 ENGINE - DETAILED INSPECTION AFTER AN EMERGENCY ABORTED TAKE-OFF OR EMERGENCY STOP USING REVERSE THRUST							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-52-08-220-801	NO. 2 ENGINE - DETAILED INSPECTION AFTER AN EMERGENCY ABORTED TAKE-OFF OR EMERGENCY STOP USING REVERSE THRUST							Service ATA:05
	MOS/MSC	30-Jul-09	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
BR710-05-10-01-870-002 NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK								
PN:FW33927	MOS/MSC	30-Jul-09	-					Service ATA:05
SN:STDK53104	HRS	0						
WC#: 72.505	ENC	0						
PROC. REF: EMM 72-31-01PROC. REF: EMM 72-31-01								
BR710-05-10-01-870-002 NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR DISK								
PN:FW33927	MOS/MSC	30-Jul-09	-					Service ATA:05
SN:STDK53105	HRS	0						
WC#: 72.505	ENC	0						
PROC. REF: EMM 72-31-01PROC. REF: EMM 72-31-01								
ATA 08 - LEVELING AND WEIGHING								
ELJ 080010 ^U	CARRY OUT RE-WEIGHING OF AIRCRAFT							Service ATA:08
	MOS	18-Feb-22	48		18-Feb-26		356 d	CUSTOMER CODE
	HRS	2452:23						
	AFL	753						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 11 - PLACARDS AND MARKINGS								
11-30-50-621 ^U	GENERAL VISUAL INSPECTION OF THE CABIN PLACARDS							Service ATA:11
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
ELJ 110010 ^U	CARRY OUT MANDATORY PLACARD INSPECTION NOTE: MANDATORY PLACARD INSPECTION TO BE PERFORMED IAW AIPC CHAPTER 11. FOR BILINGUAL REQUIREMENT ON SAFETY PLACARDS. KINDLY REFER CAR OPS 1 740							Service ATA:11
	MOS	15-Oct-24	12		15-Oct-25		230 d	CUSTOMER CODE
	HRS	3314:03						
	AFL	1328						
ATA 12 - SERVICING								
ELJ120010 ^U	TIRE PRESSURE CHECK							Service ATA:12
	MOS/MSC	20-Jan-25	A/R					
	HRS	3398:31						
	AFL	1371						
PROC. REF: MSC 12-15-00PROC. REF: MSC 12-15-00								
ATA 21 - AIR CONDITIONING								
21-21-00-201	OPERATIONAL TEST OF THE RECIRC SWITCH							Service ATA:21
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 21.005	AFL	745						
PROC. REF: AMM 21 21 00 710 802PROC. REF: AMM 21 21 00 710 802								
21-21-05-900-801-01	LH TRIM DUCT							Component ATA:21
PN:GG438-2066-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01098	HRS	0		TSN 0				
WC#: 21.085	AFL	0		TSN 0				
PROC. REF: AMM 21 60 29 000 801, AMM 21 60 29 400 801PROC. REF: AMM 21 60 29 000 801, AMM 21 60 29 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-21-05-900-801-02	RH TRIM DUCT							Component ATA:21
PN:GG438-2066-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01100	HRS	0		TSN 0				
WC#: 21.085	AFL	0		TSN 0				
PROC. REF: AMM 21 60 29 000 801, AMM 21 60 29 400 801PROC. REF: AMM 21 60 29 000 801, AMM 21 60 29 400 801								
21-21-05-900-801-03	CENTER TRIM DUCT							Component ATA:21
PN:GG438-2066-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01099	HRS	0		TSN 0				
WC#: 21.085	AFL	0		TSN 0				
PROC. REF: AMM 21 60 29 000 801, AMM 21 60 29 400 801PROC. REF: AMM 21 60 29 000 801, AMM 21 60 29 400 801								
21-21-05-900-802-01	MIX MANIFOLD							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.090	AFL	0		TSN 0				
PROC. REF: AMM 21 21 05 000 801, AMM 21 21 05 400 801PROC. REF: AMM 21 21 05 000 801, AMM 21 21 05 400 801								
21-21-09-900-801-01	LH (MIX MANIFOLD) TEMPERATURE SENSOR							Component ATA:21
PN:GG436-2015-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09589	HRS	0		TSN 0				
WC#: 21.095	AFL	0		TSN 0				
PROC. REF: AMM 21 21 09 000 801, AMM 21 21 09 400 801PROC. REF: AMM 21 21 09 000 801, AMM 21 21 09 400 801								
21-21-09-900-801-02	RH (MIX MANIFOLD) TEMPERATURE SENSOR							Component ATA:21
PN:GG436-2015-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09578	HRS	0		TSN 0				
WC#: 21.095	AFL	0		TSN 0				
PROC. REF: AMM 21 21 09 000 801, AMM 21 21 09 400 801PROC. REF: AMM 21 21 09 000 801, AMM 21 21 09 400 801								
21-21-17-201	OPERATIONAL TEST OF THE BULKHEAD CHECK VALVES							Service ATA:21
	MOS	05-Jun-23	180 (+3m/-3m)		05-Jun-38	05-Sep-38	4846 d (+92)	MRIP
	HRS	2913:47	3000 (+50/-50)		5913:47	5963:47	2467:51 (+50)	
WC#: 21.010	AFL	1041						
PROC. REF: AMM 21 21 17 710 801PROC. REF: AMM 21 21 17 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-21-17-900-801-01		LH BULKHEAD CHECK VALVE						Component ATA:21
PN:GG436-2029-1	MOS/MSC	05-Jun-23	O/C	TSN 0				
SN:00455	HRS	2913:47		TSN 0				
WC#: 21.100	AFL	1041		TSN 0				
PROC. REF: AMM 21 21 17 000 801, AMM 21 21 17 400 801PROC. REF: AMM 21 21 17 000 801, AMM 21 21 17 400 801								
21-21-17-900-801-02		RH BULKHEAD CHECK VALVE						Component ATA:21
PN:GG436-2029-1	MOS/MSC	05-Jun-23	O/C	TSN 0				
SN:00979	HRS	2913:47		TSN 0				
WC#: 21.100	AFL	1041		TSN 0				
PROC. REF: AMM 21 21 17 000 801, AMM 21 21 17 400 801PROC. REF: AMM 21 21 17 000 801, AMM 21 21 17 400 801								
21-21-21-900-801-01		LH RECIRCULATION FAN						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.105	AFL	0		TSN 0				
PROC. REF: AMM 21 21 21 000 801, AMM 21 21 21 400 801PROC. REF: AMM 21 21 21 000 801, AMM 21 21 21 400 801								
21-21-21-900-801-02		RH RECIRCULATION FAN						Component ATA:21
PN:GG433-2030-11	MOS/MSC	21-Aug-18	O/C					
SN:0830	HRS	2336:42						
WC#: 21.105	AFL	714						
PROC. REF: AMM 21 21 21 000 801, AMM 21 21 21 400 801PROC. REF: AMM 21 21 21 000 801, AMM 21 21 21 400 801								
21-21-25-201		DISCARD LH RECIRCULATION FILTER						Service ATA:21
PN:GG431-2031-1	MOS	10-Mar-23						
SN:10624	HRS	2845:10	1000 (+50/-50)		3845:10	3895:10	399:14 (+50)	
	AFL	999						
PROC. REF: AMM 21 21 25 961 801PROC. REF: AMM 21 21 25 961 801								
21-21-25-201		DISCARD RH RECIRCULATION FILTER						Service ATA:21
PN:GG431-2031-1	MOS	10-Mar-23						
SN:10620	HRS	2845:10	1000 (+50/-50)		3845:10	3895:10	399:14 (+50)	
	AFL	999						
PROC. REF: AMM 21 21 25 961 801PROC. REF: AMM 21 21 25 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-21-25-900-801-01	LH RECIRCULATION FILTER							Component ATA:21
PN:GG431-2031-1	MOS/MSC	10-Mar-23	O/C	TSN 0				
SN:10624	HRS	2845:10		TSN 0				
WC#: 21.110	AFL	999		TSN 0				
PROC. REF: AMM 21 21 25 000 801, AMM 21 21 25 400 801PROC. REF: AMM 21 21 25 000 801, AMM 21 21 25 400 801								
21-21-25-900-801-02	RH RECIRCULATION FILTER							Component ATA:21
PN:GG431-2031-1	MOS/MSC	10-Mar-23	O/C	TSN 0				
SN:10620	HRS	2845:10		TSN 0				
WC#: 21.110	AFL	999		TSN 0				
PROC. REF: AMM 21 21 25 000 801, AMM 21 21 25 400 801PROC. REF: AMM 21 21 25 000 801, AMM 21 21 25 400 801								
21-31-00-101	OPERATIONAL TEST OF THE EMERGENCY DEPRESSURIZATION FUNCTION (CMR**)							Service ATA:21
	MOS	21-Jul-21						CMR
	HRS	2446:06	1500 (+50/-50)		3946:06	3996:06	500:10 (+50)	
WC#: 21.020	AFL	747						
PROC. REF: AMM 21 31 00 710 803PROC. REF: AMM 21 31 00 710 803								
21-31-00-103	FUNCTIONAL TEST OF THE CABIN-PRESSURE LEAKAGE RATE (CMR**)							Service ATA:21
	MOS	05-Feb-21	120 (+3m/-3m)	Adj 3	05-May-31	05-Aug-31	2258 d (+92)	
	HRS	2444:24						
WC#: 21.025	AFL	745						
PROC. REF: AMM 21 31 00 720 804PROC. REF: AMM 21 31 00 720 804								
21-31-00-201	OPERATIONAL TEST OF THE MANUAL MODE							Service ATA:21
	MOS	21-Jul-21	135 (+3m/-3m)		21-Oct-32	21-Jan-33	2793 d (+92)	MRIP
	HRS	2446:06	2250 (+50/-50)		4696:06	4746:06	1250:10 (+50)	
WC#: 21.030	AFL	747						
PROC. REF: AMM 21 31 00 710 802PROC. REF: AMM 21 31 00 710 802								
21-31-00-203	OPERATIONAL TEST OF THE DITCHING FUNCTION							Service ATA:21
	MOS	10-Mar-23	180 (+3m/-3m)	Adj 3	10-Jun-38	10-Sep-38	4851 d (+92)	MRIP
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 21.035	AFL	999						
PROC. REF: AMM 21 31 00 710 804PROC. REF: AMM 21 31 00 710 804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-01-900-801-01		LH CABIN PRESSURE CONTROLLER						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.120	AFL	0		TSN 0				
PROC. REF: AMM 21 31 01 000 801, AMM 21 31 01 400 801PROC. REF: AMM 21 31 01 000 801, AMM 21 31 01 400 801								
21-31-01-900-801-02		RH CABIN PRESSURE CONTROLLER						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.120	AFL	0		TSN 0				
PROC. REF: AMM 21 31 01 000 801, AMM 21 31 01 400 801PROC. REF: AMM 21 31 01 000 801, AMM 21 31 01 400 801								
21-31-05-900-801-01		FWD OUTFLOW VALVE						Component ATA:21
PN:GG435-3002-21	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00878	HRS	0		TSN 0				
WC#: 21.125	AFL	0		TSN 0				
PROC. REF: AMM 21 31 05 000 801, AMM 21 31 05 400 801PROC. REF: AMM 21 31 05 000 801, AMM 21 31 05 400 801								
21-31-05-900-801-02		AFT OUTFLOW VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.125	AFL	0		TSN 0				
PROC. REF: AMM 21 31 05 000 801, AMM 21 31 05 400 801PROC. REF: AMM 21 31 05 000 801, AMM 21 31 05 400 801								
21-31-09-101		FUNCTIONAL TEST OF THE SAFETY VALVES (CMR*)						Service ATA:21
	MOS	10-Mar-23						CMR
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 21.040	AFL	999						
PROC. REF: AMM 21 31 09 720 801PROC. REF: AMM 21 31 09 720 801								
21-31-09-900-801-01		LH SAFETY VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.130	AFL	0		TSN 0				
PROC. REF: AMM 21 31 09 000 801, AMM 21 31 09 400 801PROC. REF: AMM 21 31 09 000 801, AMM 21 31 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-09-900-801-02	RH SAFETY VALVE							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.130	AFL	0		TSN 0				
PROC. REF: AMM 21 31 09 000 801, AMM 21 31 09 400 801PROC. REF: AMM 21 31 09 000 801, AMM 21 31 09 400 801								
21-31-11-201	DISCARD THE SAFETY VALVES FILTERS							Service ATA:21
	MOS	10-Mar-23						
	HRS	2845:10	3000 (+50/-50)		5845:10	5895:10	2399:14 (+50)	
WC#: 21.045	AFL	999						
PROC. REF: AMM 21 31 11 961 801PROC. REF: AMM 21 31 11 961 801								
21-41-50-621 ^U	OPERATIONAL TEST OF THE CABIN SUPPLEMENTAL HEAT							Service ATA:21
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
21-51-01-900-801-01	LH FLOW SENSOR VENTURI UROSEAL CONNECTOR							Component ATA:21
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4290	HRS	0		TSN 0				
WC#: 21.135	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 21 51 01 000 801, AMM 21 51 01 400 801PROC. REF: CMM 30-12-06, AMM 21 51 01 000 801, AMM 21 51 01 400 801								
21-51-01-900-801-02	RH FLOW SENSOR VENTURI UROSEAL CONNECTOR							Component ATA:21
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4201	HRS	0		TSN 0				
WC#: 21.135	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 21 51 01 000 801, AMM 21 51 01 400 801PROC. REF: CMM 30-12-06, AMM 21 51 01 000 801, AMM 21 51 01 400 801								
21-51-01-900-802-01	LEFT BLEED FILTER UROSEAL CONNECTOR							Component ATA:21
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4314	HRS	0		TSN 0				
WC#: 21.140	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 21 51 05 000 801, AMM 21 51 05 400 801PROC. REF: CMM 30-12-06, AMM 21 51 05 000 801, AMM 21 51 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-51-01-900-802-02		RIGHT BLEED FILTER UROSEAL CONNECTOR						Component ATA:21
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4392	HRS	0		TSN 0				
WC#: 21.140	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 21 51 05 000 801, AMM 21 51 05 400 801PROC. REF: CMM 30-12-06, AMM 21 51 05 000 801, AMM 21 51 05 400 801								
21-51-01-900-803-01		L/H FLOW CONTROL VALVE UROSEAL CONNECTOR						Component ATA:21
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4412	HRS	0		TSN 0				
WC#: 21.145	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 21 51 25 000 801, AMM 21 51 25 400 801PROC. REF: CMM 30-12-06, AMM 21 51 25 000 801, AMM 21 51 25 400 801								
21-51-01-900-803-02		R/H FLOW CONTROL VALVE UROSEAL CONNECTOR						Component ATA:21
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4418	HRS	0		TSN 0				
WC#: 21.145	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 21 51 25 000 801, AMM 21 51 25 400 801PROC. REF: CMM 30-12-06, AMM 21 51 25 000 801, AMM 21 51 25 400 801								
21-51-02-900-801-01		LH VENTURI FLOW SENSOR						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.150	AFL	0		TSN 0				
PROC. REF: AMM 21 51 01 000 801, AMM 21 51 01 400 801PROC. REF: AMM 21 51 01 000 801, AMM 21 51 01 400 801								
21-51-02-900-801-02		RH VENTURI FLOW SENSOR						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.150	AFL	0		TSN 0				
PROC. REF: AMM 21 51 01 000 801, AMM 21 51 01 400 801PROC. REF: AMM 21 51 01 000 801, AMM 21 51 01 400 801								
21-51-05-900-801-01		LH BLEED FILTER						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.155	AFL	0		TSN 0				
PROC. REF: AMM 21 51 05 000 801, AMM 21 51 05 400 801PROC. REF: AMM 21 51 05 000 801, AMM 21 51 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-51-05-900-801-02	RH BLEED FILTER							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.155	AFL	0		TSN 0				
PROC. REF: AMM 21 51 05 000 801, AMM 21 51 05 400 801PROC. REF: AMM 21 51 05 000 801, AMM 21 51 05 400 801								
21-51-09-201	RESTORATION LH OZONE CONVERTER OF THE OZONE CONVERTER							Service ATA:21
PN:GG431-2001-3	MOS	10-Mar-23						
SN:7378	HRS	2845:10	3000 (+50/-50)	TAC 2821:24	5845:10 (M)	5895:10	2399:14 (+50)	
	AFL	999						
PROC. REF: AMM 21 51 09 615 801PROC. REF: AMM 21 51 09 615 801								
21-51-09-201	RESTORATION RH OZONE CONVERTER OF THE OZONE CONVERTER							Service ATA:21
PN:GG431-2001-3	MOS	10-Mar-23						
SN:6854	HRS	2845:10	3000 (+50/-50)	TAC 8435:24	5845:10 (M)	5895:10	2399:14 (+50)	
	AFL	999						
PROC. REF: AMM 21 51 09 615 801PROC. REF: AMM 21 51 09 615 801								
21-51-09-900-801-01	LH OZONE CONVERTER							Component ATA:21
PN:GG431-2001-3	MOS/MSC	10-Mar-23	O/C					
SN:7378	HRS	2845:10		TSN 2821:24				
WC#: 21.160	AFL	999		TSN 726				
PROC. REF: CMM 21-51-12, AMM 21 51 09 000 801, AMM 21 51 09 400 801PROC. REF: CMM 21-51-12, AMM 21 51 09 000 801, AMM 21 51 09 400 801								
21-51-09-900-801-02	RH OZONE CONVERTER							Component ATA:21
PN:GG431-2001-3	MOS/MSC	10-Mar-23	O/C					
SN:6854	HRS	2845:10		TSN 8435:24				
WC#: 21.160	AFL	999		TSN 3633				
PROC. REF: CMM 21-51-12, AMM 21 51 09 000 801, AMM 21 51 09 400 801PROC. REF: CMM 21-51-12, AMM 21 51 09 000 801, AMM 21 51 09 400 801								
21-51-13-900-801-01	LH PACK INLET FLOW SENSOR							Component ATA:21
PN:GG436-2003-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2218	HRS	0		TSN 0				
WC#: 21.165	AFL	0		TSN 0				
PROC. REF: AMM 21 51 13 000 801, AMM 21 51 13 400 801PROC. REF: AMM 21 51 13 000 801, AMM 21 51 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-51-13-900-801-02		RH PACK INLET FLOW SENSOR					Component	ATA:21
PN:GG436-2003-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2240	HRS	0		TSN 0				
WC#: 21.165	AFL	0		TSN 0				
PROC. REF: AMM 21 51 13 000 801, AMM 21 51 13 400 801PROC. REF: AMM 21 51 13 000 801, AMM 21 51 13 400 801								
21-51-17-900-801-01		LH PACK INLET PRESSURE SENSOR					Component	ATA:21
PN:GG436-2004-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2227	HRS	0		TSN 0				
WC#: 21.170	AFL	0		TSN 0				
PROC. REF: AMM 21 51 17 000 801, AMM 21 51 17 400 801PROC. REF: AMM 21 51 17 000 801, AMM 21 51 17 400 801								
21-51-17-900-801-02		RH PACK INLET PRESSURE SENSOR					Component	ATA:21
PN:GG436-2004-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2229	HRS	0		TSN 0				
WC#: 21.170	AFL	0		TSN 0				
PROC. REF: AMM 21 51 17 000 801, AMM 21 51 17 400 801PROC. REF: AMM 21 51 17 000 801, AMM 21 51 17 400 801								
21-51-21-900-801-01		LH PACK INLET TEMPERATURE SENSOR					Component	ATA:21
PN:GG436-2005-3	MOS/MSC	26-Aug-11	O/C					
SN:01951R	HRS	375:35						
WC#: 21.175	AFL	154						
PROC. REF: AMM 21 51 21 000 801, AMM 21 51 21 400 801PROC. REF: AMM 21 51 21 000 801, AMM 21 51 21 400 801								
21-51-21-900-801-02		RH PACK INLET TEMPERATURE SENSOR					Component	ATA:21
PN:GG436-2005-3	MOS/MSC	26-Jul-12	O/C	TSN 7				
SN:10333R	HRS	770:30		TSN 0				
WC#: 21.175	AFL	266		TSN 0				
PROC. REF: AMM 21 51 21 000 801, AMM 21 51 21 400 801PROC. REF: AMM 21 51 21 000 801, AMM 21 51 21 400 801								
21-51-25-900-801-01		LH SUPPLY DUCT					Component	ATA:21
PN:GG468-4042-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0576	HRS	0		TSN 0				
WC#: 21.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-51-25-900-801-02	RH SUPPLY DUCT							Component ATA:21
PN:GG468-4042-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0579	HRS	0		TSN 0				
WC#: 21.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-51-25-900-802-01	LH SUPPLY DUCT ASSY							Component ATA:21
PN:GG468-4043-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0388	HRS	0		TSN 0				
WC#: 21.185	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-51-25-900-802-02	RH SUPPLY DUCT ASSY							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.185	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-51-25-900-803-01	LH SENSE LINE- TUBE ASSY							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-51-25-900-804-01	LH FLOW CONTROL VALVE							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.195	AFL	0		TSN 0				
PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801								
21-51-25-900-804-02	RH FLOW CONTROL VALVE							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.195	AFL	0		TSN 0				
PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801PROC. REF: AMM 21 51 25 000 801, AMM 21 51 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-00-101	OPERATIONAL TEST OF THE MANUAL MODE OF THE AIR CONDITIONING SYSTEM (CMR**)							Service ATA:21
	MOS	05-Feb-21						CMR
	HRS	2444:24	1500 (+50/-50)		3944:24	3994:24	498:28 (+50)	
WC#: 21.055	AFL	745						
PROC. REF: AMM 21 52 00 710 802PROC. REF: AMM 21 52 00 710 802								
21-52-01-900-801-01	LH COOLING PACK							Component ATA:21
PN:GG431-2007-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00871	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-52-01-900-801-02	RH COOLING PACK							Component ATA:21
PN:GG431-2007-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00872	HRS	0		TSN 0				
WC#: 21.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-52-01-900-802-01	LH PLENUM							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.205	AFL	0		TSN 0				
PROC. REF: AMM 21 52 01 000 801, AMM 21 52 01 400 801PROC. REF: AMM 21 52 01 000 801, AMM 21 52 01 400 801								
21-52-01-900-802-02	RH PLENUM							Component ATA:21
PN:GG431-2008-5	MOS/MSC	01-Mar-24	O/C	TSN 0				
SN:GG431-05168	HRS	3116:53		TSN 0				
WC#: 21.205	AFL	1170		TSN 0				
PROC. REF: AMM 21 52 01 000 801, AMM 21 52 01 400 801PROC. REF: AMM 21 52 01 000 801, AMM 21 52 01 400 801								
21-52-05-900-801-01	LH DUAL HEAT EXCHANGER							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.210	AFL	0		TSN 0				
PROC. REF: AMM 21 52 05 000 801, AMM 21 52 05 400 801PROC. REF: AMM 21 52 05 000 801, AMM 21 52 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-05-900-801-02	RH DUAL HEAT EXCHANGER							Component ATA:21
PN:GG474-2009-1	MOS/MSC	01-Mar-24	O/C	TSN 0				
SN:51476	HRS	3116:53		TSN 0				
WC#: 21.210	AFL	1170		TSN 0				
PROC. REF: AMM 21 52 05 000 801, AMM 21 52 05 400 801PROC. REF: AMM 21 52 05 000 801, AMM 21 52 05 400 801								
21-52-09-900-801-01	LH AIR CYCLE MACHINE ACM							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.215	AFL	0		TSN 0				
PROC. REF: AMM 21 52 09 000 801, AMM 21 52 09 400 801PROC. REF: AMM 21 52 09 000 801, AMM 21 52 09 400 801								
21-52-09-900-801-02	RH AIR CYCLE MACHINE ACM							Component ATA:21
PN:GG431-2010-3	MOS/MSC	01-Mar-24	O/C	TSR 0				
SN:01584	HRS	3116:53		TSR 0				
WC#: 21.215	AFL	1170		TSR 0				
PROC. REF: AMM 21 52 09 000 801, AMM 21 52 09 400 801PROC. REF: AMM 21 52 09 000 801, AMM 21 52 09 400 801								
21-52-13-900-801-01	LH (DISCHARGE) PACK INLET TEMPERATURE SENSOR							Component ATA:21
PN:GG436-2005-3	MOS/MSC	12-Sep-12	O/C	TSN 17				
SN:10607R	HRS	796:30		TSN 0				
WC#: 21.220	AFL	285		TSN 0				
PROC. REF: AMM 21 52 13 000 801, AMM 21 52 13 400 801PROC. REF: AMM 21 52 13 000 801, AMM 21 52 13 400 801								
21-52-13-900-801-02	RH (DISCHARGE) PACK INLET TEMPERATURE SENSOR							Component ATA:21
PN:GG436-2005-3	MOS/MSC	17-Dec-13	O/C	TSN 12				
SN:11377R	HRS	1134:30		TSN 0				
WC#: 21.220	AFL	373		TSN 0				
PROC. REF: AMM 21 52 13 000 801, AMM 21 52 13 400 801PROC. REF: AMM 21 52 13 000 801, AMM 21 52 13 400 801								
21-52-17-900-801-01	LH COMPRESSOR PNEUMATIC OVERHEAT SENSOR							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.225	AFL	0		TSN 0				
PROC. REF: AMM 21 52 17 000 801, AMM 21 52 17 400 801PROC. REF: AMM 21 52 17 000 801, AMM 21 52 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-17-900-801-02		RH COMPRESSOR PNEUMATIC OVERHEAT SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.225	AFL	0		TSN 0				
PROC. REF: AMM 21 52 17 000 801, AMM 21 52 17 400 801PROC. REF: AMM 21 52 17 000 801, AMM 21 52 17 400 801								
21-52-21-900-801-01		LH REHEATER CONDENSER					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.230	AFL	0		TSN 0				
PROC. REF: AMM 21 52 21 000 801, AMM 21 52 21 400 801PROC. REF: AMM 21 52 21 000 801, AMM 21 52 21 400 801								
21-52-21-900-801-02		RH REHEATER CONDENSER					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.230	AFL	0		TSN 0				
PROC. REF: AMM 21 52 21 000 801, AMM 21 52 21 400 801PROC. REF: AMM 21 52 21 000 801, AMM 21 52 21 400 801								
21-52-25-900-801-01		LH (PACK) TEMPERATURE SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.235	AFL	0		TSN 0				
PROC. REF: AMM 21 52 25 000 801, AMM 21 52 25 400 801PROC. REF: AMM 21 52 25 000 801, AMM 21 52 25 400 801								
21-52-25-900-801-02		RH (PACK) TEMPERATURE SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.235	AFL	0		TSN 0				
PROC. REF: AMM 21 52 25 000 801, AMM 21 52 25 400 801PROC. REF: AMM 21 52 25 000 801, AMM 21 52 25 400 801								
21-52-29-900-801-01		LH WATER EXTRACTOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.240	AFL	0		TSN 0				
PROC. REF: AMM 21 52 29 000 801, AMM 21 52 29 400 801PROC. REF: AMM 21 52 29 000 801, AMM 21 52 29 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-29-900-801-02	RH WATER EXTRACTOR							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.240	AFL	0		TSN 0				
PROC. REF: AMM 21 52 29 000 801, AMM 21 52 29 400 801PROC. REF: AMM 21 52 29 000 801, AMM 21 52 29 400 801								
21-52-33-900-801-01	LH TEMPERATURE CONTROL VALVE							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.245	AFL	0		TSN 0				
PROC. REF: AMM 21 52 33 000 801, AMM 21 52 33 400 801PROC. REF: AMM 21 52 33 000 801, AMM 21 52 33 400 801								
21-52-33-900-801-02	RH TEMPERATURE CONTROL VALVE							Component ATA:21
PN:GG436-2017-5	MOS/MSC	01-Mar-24	O/C					
SN:02603	HRS	3116:53						
WC#: 21.245	AFL	1170						
PROC. REF: AMM 21 52 33 000 801, AMM 21 52 33 400 801PROC. REF: AMM 21 52 33 000 801, AMM 21 52 33 400 801								
21-52-37-900-801-01	LH (PACK DISCHARGE) TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
PROC. REF: AMM 21 52 37 000 801, AMM 21 52 37 400 801PROC. REF: AMM 21 52 37 000 801, AMM 21 52 37 400 801								
21-52-37-900-801-02	RH (PACK DISCHARGE) TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
PROC. REF: AMM 21 52 37 000 801, AMM 21 52 37 400 801PROC. REF: AMM 21 52 37 000 801, AMM 21 52 37 400 801								
21-52-41-900-801-01	LH ANTI-ICING PRESSURE SENSOR							Component ATA:21
PN:GG436-2033-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2120	HRS	0		TSN 0				
WC#: 21.255	AFL	0		TSN 0				
PROC. REF: AMM 21 52 41 000 801, AMM 21 52 41 400 801PROC. REF: AMM 21 52 41 000 801, AMM 21 52 41 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-41-900-801-02		RH ANTI-ICING PRESSURE SENSOR						Component ATA:21
PN:GG436-2033-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2136	HRS	0		TSN 0				
WC#: 21.255	AFL	0		TSN 0				
PROC. REF: AMM 21 52 41 000 801, AMM 21 52 41 400 801PROC. REF: AMM 21 52 41 000 801, AMM 21 52 41 400 801								
21-52-49-900-801-01		LH PACK DISCHARGE DUCT						Component ATA:21
PN:GG438-2050-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0517	HRS	0		TSN 0				
WC#: 21.260	AFL	0		TSN 0				
PROC. REF: AMM 21 52 49 000 801, AMM 21 52 49 400 801PROC. REF: AMM 21 52 49 000 801, AMM 21 52 49 400 801								
21-52-53-900-801-01		RH PACK DISCHARGE DUCT						Component ATA:21
PN:GG438-2049-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0473	HRS	0		TSN 0				
WC#: 21.260	AFL	0		TSN 0				
PROC. REF: AMM 21 52 53 000 801, AMM 21 52 53 400 801PROC. REF: AMM 21 52 53 000 801, AMM 21 52 53 400 801								
21-53-01-900-801-01		LH WATER SPRAYER						Component ATA:21
PN:GG431-2022-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:02499	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
PROC. REF: AMM 21 53 01 000 801, AMM 21 53 01 400 801PROC. REF: AMM 21 53 01 000 801, AMM 21 53 01 400 801								
21-53-01-900-801-02		RH WATER SPRAYER						Component ATA:21
PN:GG431-2022-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:02491	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
PROC. REF: AMM 21 53 01 000 801, AMM 21 53 01 400 801PROC. REF: AMM 21 53 01 000 801, AMM 21 53 01 400 801								
21-53-05-101		OPERATIONAL TEST OF THE RAM AIR VALVE (CMR**)						Service ATA:21
	MOS	05-Feb-21						CMR
	HRS	2444:24	1500 (+50/-50)		3944:24	3994:24	498:28 (+50)	
WC#: 21.060	AFL	745						
PROC. REF: AMM 21 53 05 710 801PROC. REF: AMM 21 53 05 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-53-05-900-801-01		EMERGENCY RAM AIR VALVE					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.275	AFL	0		TSN 0				
PROC. REF: AMM 21 53 05 000 801, AMM 21 53 05 400 801PROC. REF: AMM 21 53 05 000 801, AMM 21 53 05 400 801								
21-53-09-900-801-01		LH RAM AIR FLEXIBLE DUCT					Component	ATA:21
PN:GG438-2056-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00178	HRS	0		TSN 0				
WC#: 21.265	AFL	0		TSN 0				
PROC. REF: AMM 21 53 09 000 801, AMM 21 53 09 400 801PROC. REF: AMM 21 53 09 000 801, AMM 21 53 09 400 801								
21-53-09-900-801-02		RH RAM AIR FLEXIBLE DUCT					Component	ATA:21
PN:GG438-2056-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00183	HRS	0		TSN 0				
WC#: 21.265	AFL	0		TSN 0				
PROC. REF: AMM 21 53 09 000 801, AMM 21 53 09 400 801PROC. REF: AMM 21 53 09 000 801, AMM 21 53 09 400 801								
21-53-17-900-801-01		LH MAIN HEAT EXCHANGER DIFFUSER					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.280	AFL	0		TSN 0				
PROC. REF: AMM 21 53 17 000 801, AMM 21 53 17 400 801PROC. REF: AMM 21 53 17 000 801, AMM 21 53 17 400 801								
21-53-17-900-801-02		RH MAIN HEAT EXCHANGER DIFFUSER					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.280	AFL	0		TSN 0				
PROC. REF: AMM 21 53 17 000 801, AMM 21 53 17 400 801PROC. REF: AMM 21 53 17 000 801, AMM 21 53 17 400 801								
21-53-21-900-801-01		SPLITTER RAM AIR DUCT					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.285	AFL	0		TSN 0				
PROC. REF: AMM 21 53 21 000 801, AMM 21 53 21 400 801PROC. REF: AMM 21 53 21 000 801, AMM 21 53 21 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-53-33-900-801-01		RAM-AIR CHECK VALVE						Component ATA:21
PN:GG436-2068-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00499	HRS	0		TSN 0				
WC#: 21.290	AFL	0		TSN 0				
PROC. REF: AMM 21 53 33 000 801, AMM 21 53 33 400 801PROC. REF: AMM 21 53 33 000 801, AMM 21 53 33 400 801								
21-53-33-900-802-01		RAM-AIR INTAKE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.295	AFL	0		TSN 0				
PROC. REF: AMM 21 53 33 000 801, AMM 21 53 33 400 801PROC. REF: AMM 21 53 33 000 801, AMM 21 53 33 400 801								
21-54-00-101		OPERATIONAL TEST OF THE UNDERSPEED MONITOR OF THE AVIONICS BAY AND AVIONICS RACK FANS (CMR**)						Service ATA:21
	MOS	10-Mar-23						CMR
	HRS	2845:10	1500 (+50/-50)	Adj 50	4395:10	4445:10	949:14 (+50)	
WC#: 21.065	AFL	999						
PROC. REF: AMM 21 54 00 710 803PROC. REF: AMM 21 54 00 710 803								
21-54-01-900-802-01		NO. 1 COOLING IRS FAN						Component ATA:21
PN:26012423-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:8938	HRS	0		TSN 0				
WC#: 21.300	AFL	0		TSN 0				
PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802								
21-54-01-900-802-02		NO. 2 COOLING IRS FAN						Component ATA:21
PN:26012423-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:8989	HRS	0		TSN 0				
WC#: 21.300	AFL	0		TSN 0				
PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802								
21-54-01-900-802-03		NO. 3 COOLING IRS FAN						Component ATA:21
PN:26012423-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:8993	HRS	0		TSN 0				
WC#: 21.300	AFL	0		TSN 0				
PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802PROC. REF: AMM 21 54 01 000 802, AMM 21 54 01 400 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-54-37-900-801-01		NO. 1 AVIONICS EXHAUST FAN						Component ATA:21
PN:GG433-2047-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0659	HRS	0		TSN 0				
WC#: 21.305	AFL	0		TSN 0				
PROC. REF: AMM 21 54 37 000 801, AMM 21 54 37 400 801PROC. REF: AMM 21 54 37 000 801, AMM 21 54 37 400 801								
21-54-37-900-801-02		NO. 2 AVIONICS EXHAUST FAN						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.305	AFL	0		TSN 0				
PROC. REF: AMM 21 54 37 000 801, AMM 21 54 37 400 801PROC. REF: AMM 21 54 37 000 801, AMM 21 54 37 400 801								
21-54-41-900-801-01		AVIONICS EXHAUST-FAN CONVERTER						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.310	AFL	0		TSN 0				
PROC. REF: AMM 21 54 41 000 801, AMM 21 54 41 400 801PROC. REF: AMM 21 54 41 000 801, AMM 21 54 41 400 801								
21-54-41-900-801-02 ^U		NO. 2 AVIONICS FAN CONVERTER						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
21-54-61-101		VISUAL CHECK OF THE AVIONICS RACK DUCTS (CMR**)						Service ATA:21
	MOS	10-Mar-23					CMR	
	HRS	2845:10	1500 (+50/-50)	Adj 50	4395:10	4445:10	949:14 (+50)	
WC#: 21.070	AFL	999						
PROC. REF: AMM 21 54 61 210 801PROC. REF: AMM 21 54 61 210 801								
21-54-69-201		DISCARD THE AVIONICS RACK FILTER						Service ATA:21
	MOS	10-Mar-23						
	HRS	2845:10	1500 (+50/-50)		4345:10	4395:10	899:14 (+50)	
WC#: 21.075	AFL	999						
PROC. REF: AMM 21 54 69 961 801PROC. REF: AMM 21 54 69 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-60-00-101		OPERATIONAL TEST OF THE AUXILIARY PRESSURIZATION FUNCTION (CMR**)						Service ATA:21
	MOS	05-Feb-21						CMR
	HRS	2444:24	1500 (+50/-50)		3944:24	3994:24	498:28 (+50)	
WC#: 21.080	AFL	745						
PROC. REF: AMM 21 60 00 710 802PROC. REF: AMM 21 60 00 710 802								
21-60-01-900-801-01		EMERGENCY CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-60-05-900-801-01		LH TRIM AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.325	AFL	0		TSN 0				
PROC. REF: AMM 21 60 05 000 801, AMM 21 60 05 400 801PROC. REF: AMM 21 60 05 000 801, AMM 21 60 05 400 801								
21-60-05-900-801-02		RH TRIM AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.325	AFL	0		TSN 0				
PROC. REF: AMM 21 60 05 000 801, AMM 21 60 05 400 801PROC. REF: AMM 21 60 05 000 801, AMM 21 60 05 400 801								
21-60-09-900-801-01		LH HOT AIR SHUT-OFF VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.330	AFL	0		TSN 0				
PROC. REF: AMM 21 60 09 000 801, AMM 21 60 09 400 801PROC. REF: AMM 21 60 09 000 801, AMM 21 60 09 400 801								
21-60-09-900-801-02		RH HOT AIR SHUT-OFF VALVE						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.330	AFL	0		TSN 0				
PROC. REF: AMM 21 60 09 000 801, AMM 21 60 09 400 801PROC. REF: AMM 21 60 09 000 801, AMM 21 60 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-60-13-900-801-01		LH TRIM AIR VALVE					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.335	AFL	0		TSN 0				
PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801								
21-60-13-900-801-02		RH TRIM AIR VALVE					Component	ATA:21
PN:GG436-2038-7	MOS/MSC	05-Feb-21	O/C					
SN:1744	HRS	2444:24						
WC#: 21.335	AFL	745						
PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801								
21-60-13-900-801-03		CENTER TRIM AIR VALVE					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.335	AFL	0		TSN 0				
PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801PROC. REF: AMM 21 60 13 000 801, AMM 21 60 13 400 801								
21-60-17-900-801-01		LH (DUCT AFT CABIN) TEMPERATURE SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801								
21-60-17-900-801-02		RH (DUCT FWD CABIN) TEMPERATURE SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801								
21-60-17-900-801-03		CENTER (DUCT FLT COMPARTMENT) TEMPERATURE SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.340	AFL	0		TSN 0				
PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801PROC. REF: AMM 21 60 17 000 801, AMM 21 60 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-60-21-900-801-01		LH AIR CONDITIONING SYSTEM CONTROLLER						Component ATA:21
PN:GG546-2040-13	MOS/MSC	05-Feb-21	O/C	TSN 139				
SN:00912	HRS	2444:24		TSN 2444:24				
WC#: 21.345	AFL	745		TSN 745				
PROC. REF: AMM 21 60 21 000 801, AMM 21 60 21 400 801PROC. REF: AMM 21 60 21 000 801, AMM 21 60 21 400 801								
21-60-21-900-801-02		RH AIR CONDITIONING SYSTEM CONTROLLER						Component ATA:21
PN:GG546-2040-15	MOS/MSC	05-Feb-21	O/C					
SN:1140	HRS	2444:24						
WC#: 21.345	AFL	745						
PROC. REF: AMM 21 60 21 000 801, AMM 21 60 21 400 801PROC. REF: AMM 21 60 21 000 801, AMM 21 60 21 400 801								
21-60-25-900-801-01		COCKPIT VENTILATED TEMPERATURE SENSOR						Component ATA:21
PN:GG436-2041-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:04457	HRS	0		TSN 0				
WC#: 21.350	AFL	0		TSN 0				
PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801								
21-60-25-900-801-02		FWD CABIN VENTILATED TEMPERATURE SENSOR						Component ATA:21
PN:GG436-2041-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4504	HRS	0		TSN 0				
WC#: 21.350	AFL	0		TSN 0				
PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801								
21-60-25-900-801-03		AFT CABIN VENTILATED TEMPERATURE SENSOR						Component ATA:21
PN:GG436-2041-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:04519	HRS	0		TSN 0				
WC#: 21.350	AFL	0		TSN 0				
PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801PROC. REF: AMM 21 60 25 000 801, AMM 21 60 25 400 801								
21-71-17-900-801-01		HUMIDIFIER CONTROL UNIT						Component ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.355	AFL	0		TSN 0				
PROC. REF: AMM 21 71 17 000 801, AMM 21 71 17 400 801, AMM 21 71 17 961 801PROC. REF: AMM 21 71 17 000 801, AMM 21 71 17 400 801, AMM 21 71 17 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-71-21-900-801-02		HUMIDIFIER LEVEL SENSOR					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.360	AFL	0		TSN 0				
PROC. REF: AMM 21 71 21 000 801, AMM 21 71 21 400 801, AMM 21 71 21 961 801PROC. REF: AMM 21 71 21 000 801, AMM 21 71 21 400 801, AMM 21 71 21 961 801								
212221-001 ^U		AVIONICS FAN					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.115	AFL	0		TSN 0				
212300-701 ^U		(GALLEY) EXHAUST FAN					Component	ATA:21
PN:011835	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:I09337887	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
212300-702 ^U		(FWD VANITY) EXHAUST FAN					Component	ATA:21
PN:011836	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:I09257521	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
215453-001 ^U		AVIONICS FAN CONVERTER					Component	ATA:21
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.315	AFL	0		TSN 0				
ATA 22 - AUTO FLIGHT								
22-11-01-900-801-01		GUIDANCE PANEL					Component	ATA:22
PN:7022010-905	MOS/MSC	12-Nov-23	O/C	TSR 0				
SN:09111271	HRS	3047:06		TSR 0				
WC#: 22.005	AFL	1128		TSR 0				
PROC. REF: AMM 22 11 01 000 801, AMM 22 11 01 400 801PROC. REF: AMM 22 11 01 000 801, AMM 22 11 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-12-01-900-801-01	AILERON PARALLEL SERVO							Component ATA:22
PN:4015373-823	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0810H238	HRS	0		TSN 0				
WC#: 22.010	AFL	0		TSN 0				
PROC. REF: AMM 22 12 01 000 801, AMM 22 12 01 400 801PROC. REF: AMM 22 12 01 000 801, AMM 22 12 01 400 801								
22-12-05-900-801-01	LEFT MLG WHEEL WELL AILERON SERVO BRACKET							Component ATA:22
PN:4015374-813	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0809H237	HRS	0		TSN 0				
WC#: 22.015	AFL	0		TSN 0				
PROC. REF: AMM 22 12 05 000 801, AMM 22 12 05 400 801PROC. REF: AMM 22 12 05 000 801, AMM 22 12 05 400 801								
22-12-09-900-801-01	ELEVATOR PARALLEL SERVO							Component ATA:22
PN:4015373-834	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0810H234	HRS	0		TSN 0				
WC#: 22.020	AFL	0		TSN 0				
PROC. REF: AMM 22 12 09 000 801, AMM 22 12 09 400 801PROC. REF: AMM 22 12 09 000 801, AMM 22 12 09 400 801								
22-12-13-900-801-01	FS1076.0 WL203.8 ELEVATOR SERVO BRACKET							Component ATA:22
PN:4015374-906	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0811H251	HRS	0		TSN 0				
WC#: 22.025	AFL	0		TSN 0				
PROC. REF: AMM 22 12 13 000 801, AMM 22 12 13 400 801PROC. REF: AMM 22 12 13 000 801, AMM 22 12 13 400 801								
22-13-01-101	DISCARD THE LH RUDDER YAW DAMPER LINEAR ACTUATOR (AIRCRAFT S/N 9127 TO 9174 PRE SB700-1A11-31-007), PART NO. 7002800-804							Service ATA:22
PN:7002800-804	MOS/MSC		N/A					
SN:1002H559	HRS							
	AFL							
PROC. REF: AMM 22 13 01 961 801PROC. REF: AMM 22 13 01 961 801								
22-13-01-101	DISCARD THE RH RUDDER YAW DAMPER LINEAR ACTUATOR (AIRCRAFT S/N 9127 TO 9174 PRE SB700-1A11-31-007), PART NO. 7002800-804							Service ATA:22
PN:7002800-804	MOS/MSC		N/A					
SN:98031109	HRS							
	AFL							
PROC. REF: AMM 22 13 01 961 801PROC. REF: AMM 22 13 01 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-13-01-900-801-01	LH LINEAR RUDDER ACTUATOR							Component ATA:22
PN:7002800-804	MOS/MSC	24-Oct-24	O/C	TSO 0				
SN:1002H559	HRS	3324:09		TSO 0				
WC#: 22.030	AFL	1336		TSO 0				
PROC. REF: AMM 22 13 01 000 801, AMM 22 13 01 400 801PROC. REF: AMM 22 13 01 000 801, AMM 22 13 01 400 801								
22-13-01-900-801-02	RH LINEAR RUDDER ACTUATOR							Component ATA:22
PN:7002800-804	MOS/MSC	15-Oct-24	O/C	TSR 0				
SN:98031109	HRS	3314:03		TSR 0				
WC#: 22.030	AFL	1328		TSR 0				
PROC. REF: AMM 22 13 01 000 801, AMM 22 13 01 400 801PROC. REF: AMM 22 13 01 000 801, AMM 22 13 01 400 801								
ATA 23 - COMMUNICATIONS								
23-11-01-900-801-01	NO. 1 VHF COMMUNICATION UNIT							Component ATA:23
PN:7510733-666	MOS/MSC	17-Oct-23	O/C	TSR 0				
SN:0810C277	HRS	3029:02		TSR 0				
WC#: 23.020	AFL	1119		TSR 0				
PROC. REF: AMM 23 11 01 000 801, AMM 23 11 01 400 801PROC. REF: AMM 23 11 01 000 801, AMM 23 11 01 400 801								
23-11-01-900-801-02	NO. 2 VHF COMMUNICATION UNIT							Component ATA:23
PN:7510733-666	MOS/MSC	31-Aug-23	O/C	TSR 30				
SN:0603A433	HRS	2993:11		TSR 548:47				
WC#: 23.020	AFL	1092		TSR 347				
PROC. REF: AMM 23 11 01 000 801, AMM 23 11 01 400 801PROC. REF: AMM 23 11 01 000 801, AMM 23 11 01 400 801								
23-11-05-900-801-01	NO. 1 COMM VHF TOP ANTENNA							Component ATA:23
PN:S65-8280-10	MOS/MSC	05-Feb-21	O/C					
SN:310-34180	HRS	2444:24						
WC#: 23.025	AFL	745						
PROC. REF: AMM 23 11 05 000 801, AMM 23 11 05 400 801PROC. REF: AMM 23 11 05 000 801, AMM 23 11 05 400 801								
23-11-05-900-801-02	NO. 2 COMM VHF BOTTOM ANTENNA							Component ATA:23
PN:S65-8280-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0550	HRS	0		TSN 0				
WC#: 23.025	AFL	0		TSN 0				
PROC. REF: AMM 23 11 05 000 801, AMM 23 11 05 400 801PROC. REF: AMM 23 11 05 000 801, AMM 23 11 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-12-01-900-801-01		LH HF (HF9031A) RECEIVER						Component ATA:23
PN:822-0101-002	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4423	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: AMM 23 12 01 000 801, AMM 23 12 01 400 801PROC. REF: AMM 23 12 01 000 801, AMM 23 12 01 400 801								
23-12-01-900-801-02		RH HF (HF9031A) RECEIVER						Component ATA:23
PN:822-0101-002	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4465	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: AMM 23 12 01 000 801, AMM 23 12 01 400 801PROC. REF: AMM 23 12 01 000 801, AMM 23 12 01 400 801								
23-12-05-900-801-01		NO. 1 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER						Component ATA:23
PN:622-8114-002	MOS/MSC	21-Jul-21	O/C					
SN:9269	HRS	2446:06						
WC#: 23.040	AFL	747						
PROC. REF: AMM 23 12 05 000 801, AMM 23 12 05 400 801PROC. REF: AMM 23 12 05 000 801, AMM 23 12 05 400 801								
23-12-05-900-801-02		NO. 2 VERTICAL STABILIZER ANTENNA (HF9041A) COUPLER						Component ATA:23
PN:622-8114-002	MOS/MSC	21-Jul-21	O/C					
SN:9732	HRS	2446:06						
WC#: 23.040	AFL	747						
PROC. REF: AMM 23 12 05 000 801, AMM 23 12 05 400 801PROC. REF: AMM 23 12 05 000 801, AMM 23 12 05 400 801								
23-22-01-900-801-01		SELCAL DECODER						Component ATA:23
PN:1200008-002	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6038	HRS	0		TSN 0				
WC#: 23.045	AFL	0		TSN 0				
PROC. REF: AMM 23 22 01 000 801, AMM 23 22 01 400 801PROC. REF: AMM 23 22 01 000 801, AMM 23 22 01 400 801								
23-40-01-900-801-01		LH INTERPHONE						Component ATA:23
PN:600-59146-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:7275	HRS	0		TSN 0				
WC#: 23.055	AFL	0		TSN 0				
PROC. REF: AMM 23 40 01 000 801, AMM 23 40 01 400 801PROC. REF: AMM 23 40 01 000 801, AMM 23 40 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-40-01-900-801-02	RH INTERPHONE							Component ATA:23
PN:600-59146-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:7256	HRS	0		TSN 0				
WC#: 23.055	AFL	0		TSN 0				
PROC. REF: AMM 23 40 01 000 801, AMM 23 40 01 400 801PROC. REF: AMM 23 40 01 000 801, AMM 23 40 01 400 801								
23-51-05-900-801-01	NO. 1 AUDIO CONTROL PANEL							Component ATA:23
PN:7511001-985	MOS/MSC	29-Jul-11	O/C					
SN:0901D472	HRS	353:45						
WC#: 23.050	AFL	136						
PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801								
23-51-05-900-801-02	NO. 2 AUDIO CONTROL PANEL							Component ATA:23
PN:7511001-985	MOS/MSC	29-Jul-11	O/C	TSR 1				
SN:0703B877	HRS	353:45		TSR 0				
WC#: 23.050	AFL	136		TSR 0				
PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801								
23-51-05-900-801-03	NO. 3 AUDIO CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.050	AFL	0		TSN 0				
PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801PROC. REF: AMM 23 51 05 000 801, AMM 23 51 05 400 801								
23-51-50-621 ^U	OPERATIONAL TEST OF THE PASSENGER ADDRESS SYSTEM							Service ATA:23
	MOS	15-Oct-24					STLMC	
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
23-61-01-201	FUNCTIONAL TEST OF THE STATIC DISCHARGERS							Service ATA:23
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 23.010	AFL	747						
PROC. REF: AMM 23 61 01 720 801PROC. REF: AMM 23 61 01 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-71-00-201	OPERATIONAL TEST COCKPIT VOICE RECORDER OF THE VOICE RECORDER SYSTEM							Service ATA:23
	MOS	10-Mar-23	180 (+3m/-3m)	Adj 3	10-Jun-38	10-Sep-38	4851 d (+92)	MRIP
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 23.015	AFL	999						
PROC. REF: AMM 23 71 00 710 801PROC. REF: AMM 23 71 00 710 801								
23-71-01-900-801-01	COCKPIT VOICE RECORDER							Component ATA:23
PN:980-6022-001	MOS/MSC	22-Apr-19	O/C					
SN:CVR120-12821	HRS	2378:21						
WC#: 23.060	AFL	728						
PROC. REF: AMM 23 71 01 000 801, AMM 23 71 01 400 801PROC. REF: AMM 23 71 01 000 801, AMM 23 71 01 400 801								
23-71-05-900-801-01	CVR CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.070	AFL	0		TSN 0				
PROC. REF: AMM 23 71 05 000 801, AMM 23 71 05 400 801PROC. REF: AMM 23 71 05 000 801, AMM 23 71 05 400 801								
23-71-09-900-801-01	MICROPHONE							Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.065	AFL	0		TSN 0				
PROC. REF: AMM 23 71 09 000 801, AMM 23 71 09 400 801PROC. REF: AMM 23 71 09 000 801, AMM 23 71 09 400 801								
23-71-13-201	RESTORATION OF THE RECORDER INDEPENDENT POWER SUPPLY (RIPS)							Service ATA:23
PN:PN	MOS		45 (+3m/-3m)		10-Oct-27 (M)	10-Jan-28	955 d (+92)	MRB
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 23 71 13 840 801PROC. REF: AMM 23 71 13 840 801								
23-71-17-900-801-01	IMPACT SWITCH							Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.075	AFL	0		TSN 0				
PROC. REF: AMM 23 71 17 000 801, AMM 23 71 17 400 801PROC. REF: AMM 23 71 17 000 801, AMM 23 71 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-71-21-201		DISCARD BATTERY - (23-71-21-201)						Service ATA:23
PN:PN	MOS/MSC	10-Mar-23	DUE		01-Mar-30 (M)		1828 d	MRB
SN:UNKNOWN	HRS	2845:10						
WC#: 23.080	AFL	999						
PROC. REF: AMM 23 71 21 960 802PROC. REF: AMM 23 71 21 960 802								
23-71-21-202		OPERATIONAL TEST CVR ULB UNDERWATER LOCATOR BEACON - (23-71-21-202)						Service ATA:23
PN:DK120/90	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	RECOMMENDED
SN:AT187057	HRS							
WC#: 23.080	AFL							
PROC. REF: AMM 23 71 21 710 801PROC. REF: AMM 23 71 21 710 801								
23-71-21-900-802-01		CVR ULB UNDERWATER LOCATOR BEACON						Component ATA:23
PN:DK120/90	MOS/MSC	10-Mar-23	O/C	TSN 0				
SN:AT187057	HRS	2845:10		TSN 0				
WC#: 23.080	AFL	999		TSN 0				
PROC. REF: AMM 23 71 21 000 802, AMM 23 71 21 400 802PROC. REF: AMM 23 71 21 000 802, AMM 23 71 21 400 802								
23-71-21-900-803-01		CVR (ULD) UNDERWATER LOCATOR BEACON BATTERY						Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, AMM 23 71 21 000 802, AMM 23 71 21 400 802PROC. REF: GENERIC NO REF, AMM 23 71 21 000 802, AMM 23 71 21 400 802								
23-81-01-900-802-01		LH RADIO MANAGEMENT UNIT						Component ATA:23
PN:7013270-977	MOS/MSC	05-Feb-21	O/C					
SN:9026657	HRS	2444:24						
WC#: 23.085	AFL	745						
PROC. REF: AMM 23 81 01 000 802, AMM 23 81 01 400 802PROC. REF: AMM 23 81 01 000 802, AMM 23 81 01 400 802								
23-81-01-900-802-02		RH RADIO MANAGEMENT UNIT						Component ATA:23
PN:7013270-977	MOS/MSC	05-Feb-21	O/C					
SN:9026658	HRS	2444:24						
WC#: 23.085	AFL	745						
PROC. REF: AMM 23 81 01 000 802, AMM 23 81 01 400 802PROC. REF: AMM 23 81 01 000 802, AMM 23 81 01 400 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231101-701 ^U	#3 VHF COMMUNICATION UNIT							Component ATA:23
PN:7510700-833	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:0910C629	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
231300-701 ^U	HST 2110 (#1) HIGH SPEED TRANSCEIVER							Component ATA:23
PN:822-2232-020	MOS/MSC	16-Jun-22	O/C	TSR 0				
SN:16Y8HF	HRS	2557:30		TSR 0				
	AFL	821		TSR 0				
231301-701 ^U	SATCOM SRT-2100 TRANSCEIVER							Component ATA:23
PN:822-1785-001	MOS/MSC	17-May-16	O/C	TSO 3				
SN:146689	HRS	1925:27		TSO 0				
	AFL	584		TSO 0				
231302-701 ^U	ANTENNA DRIVER UNIT							Component ATA:23
PN:0811-A-0001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:1789	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
231303-701 ^U	DIPLEXER/LNA UNIT							Component ATA:23
PN:1242-A-0006	MOS/MSC	05-Feb-21	O/C	TSR 0				
SN:2030	HRS	2444:24		TSR 0				
	AFL	745		TSR 0				
231304-701 ^U	CNX-200 ACCELERATOR							Component ATA:23
PN:1110-A-0501-20	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:852	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231305-701 ^U	WIRELESS LAN (AV. BAY) UNIT							Component ATA:23
PN:822-2210-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:17TV11	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
231306-701 ^U	AEROCOM 3000 CTU UNIT							Component ATA:23
PN:350000-10-010000	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:AE3K-583	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
231307-701 ^U	NO.1 IRIDIUM COMM. ICS-100 SYSTEM							Component ATA:23
PN:500616-2	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3477	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
231310-701 ^U	AMT- 50 SATCOM ANTENNA							Component ATA:23
PN:0476-A-00377	MOS/MSC	24-Jun-22	O/C	TSR 0				
SN:1710	HRS	2567:42		TSN 7690, TSR 0				
	AFL	831		TSN 1995, TSR 0				
231310-702 ^U	SATCOM ANTENNA							Component ATA:23
PN:0486-D-00061	MOS/MSC	05-Feb-21	O/C					
SN:1440	HRS	2444:24						
	AFL	745						
231330-701 ^U	COMMUNICATION CONVERGENCE (CCU) UNIT							Component ATA:23
PN:1233-A-0100	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:112	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232100-701 ^U	COCKPIT PRINTER UNIT							Component ATA:23
PN:706300-1111	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:48403643	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
232100-702 ^U	FAX/PRINTER/SCANNER - WORKSTATION MACHINE							Component ATA:23
PN:CC377A	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:CNC2409542	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
232101-702 ^U	PRINT (CREW REST) SERVER							Component ATA:23
PN:AD123900-000	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:169	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
232300-701 ^U	TELELINK (ADLU) UNIT							Component ATA:23
PN:8400021-01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:10564	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
233000-701 ^U	SPEAKER, PA (A571) AMPLIFIER							Component ATA:23
PN:251-003	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:60448	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
235105-701 ^U	AUDIO CONTROL UNIT							Component ATA:23
PN:7511001-985	MOS/MSC	27-Jul-11	O/C					
SN:0703B877	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
238101-003 ^U	A25 RMU PANEL							Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.090	AFL	0		TSN 0				
238101-004 ^U	A26 RMU PANEL							Component ATA:23
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.090	AFL	0		TSN 0				
ELJ 230010 ^U	CVR READOUT AND INTELLIGIBILITY TEST (AS PER AMM 23-71-00- 730-801).(NOTE- AS PER CAR M.302)							Service ATA:23
	MOS	15-Oct-24	24		15-Oct-26		595 d	
	HRS	3314:03						
	AFL	1328						
ATA 24 - ELECTRICAL POWER								
24-00-00-301	OPERATIONAL TEST (CYCLING) OF THERMAL CIRCUIT BREAKERS							Service ATA:24
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	OPTIONAL
	HRS	3168:27						
WC#: 24.005	AFL	1205						
PROC. REF: AMM 24 00 00 710 802PROC. REF: AMM 24 00 00 710 802								
24-00-01-900-801-01	JB3 JUNCTION BOX							Component ATA:24
PN:514-0039-0002	MOS/MSC	05-Feb-21	O/C					
SN:382	HRS	2444:24						
WC#: 24.035	AFL	745						
PROC. REF: CMM 24-00-01, AMM 24 00 01 000 801, AMM 24 00 01 400 801PROC. REF: CMM 24-00-01, AMM 24 00 01 000 801, AMM 24 00 01 400 801								
24-00-05-900-801-01	JB4 JUNCTION BOX							Component ATA:24
PN:GC575-0004-403	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:381	HRS	0		TSN 0				
WC#: 24.035	AFL	0		TSN 0				
PROC. REF: CMM 24-00-01, AMM 24 00 05 000 801, AMM 24 00 05 400 801PROC. REF: CMM 24-00-01, AMM 24 00 05 000 801, AMM 24 00 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-00-09-900-801-01	JB5 JUNCTION BOX							Component ATA:24
PN:514-0041-0003	MOS/MSC	05-Feb-21	O/C					
SN:382	HRS	2444:24						
WC#: 24.035	AFL	745						
PROC. REF: CMM 24-00-01, AMM 24 00 09 000 801, AMM 24 00 09 400 801PROC. REF: CMM 24-00-01, AMM 24 00 09 000 801, AMM 24 00 09 400 801								
24-00-13-900-801-01	JB6 JUNCTION BOX							Component ATA:24
PN:514-0042-0003	MOS/MSC	05-Feb-21	O/C					
SN:392	HRS	2444:24						
WC#: 24.035	AFL	745						
PROC. REF: CMM 24-00-01, AMM 24 00 13 000 801, AMM 24 00 13 400 801PROC. REF: CMM 24-00-01, AMM 24 00 13 000 801, AMM 24 00 13 400 801								
24-03-50-621 ^U	OPERATIONAL TEST OF THE CABIN POWER SHUT-OFF SWITCH							Service ATA:24
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
24-12-00-900-801-01	NO. 1 VFG OIL PIPE							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-12-00-900-801-02	NO. 2 VFG OIL PIPE							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24-21-01-201	DETAILED INSPECTION OF THE MAIN GENERATOR OIL SUPPLY							Service ATA:24
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 24.010	AFL	745						
PROC. REF: AMM 24 12 00 220 801PROC. REF: AMM 24 12 00 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-21-01-900-801-01		NO. 1 (LH OUTBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR						Component ATA:24
PN:GL511-1103-9	MOS/MSC	16-Sep-14	O/C					
SN:4193	HRS	1444:25						
WC#: 24.045	AFL	446						
PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801								
24-21-01-900-801-02		NO. 2 (LH INBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR						Component ATA:24
PN:GL511-1103-9	MOS/MSC	16-Sep-14	O/C					
SN:4191	HRS	1444:25						
WC#: 24.045	AFL	446						
PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801								
24-21-01-900-801-03		NO. 3 (RH OUTBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR						Component ATA:24
PN:GL511-1103-9	MOS/MSC	16-Sep-14	O/C					
SN:2949	HRS	1444:25						
WC#: 24.045	AFL	446						
PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801								
24-21-01-900-801-04		NO. 4 (RH INBD) VARIABLE FREQUENCY AC (40KVA) GENERATOR						Component ATA:24
PN:GL511-1103-9	MOS/MSC	16-Sep-14	O/C					
SN:3065	HRS	1444:25						
WC#: 24.045	AFL	446						
PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801PROC. REF: AMM 24 21 01 000 801, AMM 24 21 01 400 801								
24-22-01-900-801-01		NO.5 APU AC (40/45 KVA) GENERATOR						Component ATA:24
PN:GL511-1204-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2214	HRS	0		TSN 0				
WC#: 24.050	AFL	0		TSN 0				
PROC. REF: AMM 24 22 01 000 801, AMM 24 22 01 400 801PROC. REF: AMM 24 22 01 000 801, AMM 24 22 01 400 801								
24-23-01-101		OPERATIONAL TEST OF THE RAM AIR TURBINE (RAT) (CMR*)						Service ATA:24
	MOS	10-Mar-23	24 (+3m/-3m)	Adj 3	10-Jun-25	10-Sep-25	103 d (+92)	
	HRS	2845:10						
WC#: 24.015	AFL	999						
PROC. REF: AMM 24 23 01 710 801PROC. REF: AMM 24 23 01 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-23-01-102		FUNCTIONAL TEST RAM AIR TURBINE OF THE (RAT) HEATER (CMR*)						Service ATA:24
PN:GL456-1101-7	MOS	10-Mar-23	24 (+3m/-3m)	Adj 3	10-Jun-25	10-Sep-25	103 d (+92)	CMR
SN:0430	HRS	2845:10						
WC#: 24.020	AFL	999						
PROC. REF: AMM 24 23 33 720 804PROC. REF: AMM 24 23 33 720 804								
24-23-01-900-801-01		RAM AIR TURBINE						Component ATA:24
PN:GL456-1101-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0430	HRS	0		TSN 0				
WC#: 24.055	AFL	0		TSN 0				
PROC. REF: CMM 24-23-01, AMM 24 23 01 000 801, AMM 24 23 01 400 801PROC. REF: CMM 24-23-01, AMM 24 23 01 000 801, AMM 24 23 01 400 801								
24-23-01-900-802-01		GENERATOR- RAT CONTROL						Component ATA:24
PN:GL456-1201-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0464	HRS	0		TSN 0				
WC#: 24.060	AFL	0		TSN 0				
PROC. REF: AMM 24 23 01 000 801, AMM 24 23 01 400 801PROC. REF: AMM 24 23 01 000 801, AMM 24 23 01 400 801								
24-23-09-900-801-01		DEPLOY RAT ACTUATOR						Component ATA:24
PN:GL456-1301-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0462	HRS	0		TSN 0				
WC#: 24.065	AFL	0		TSN 0				
PROC. REF: AMM 24 23 09 000 801, AMM 24 23 09 400 801PROC. REF: AMM 24 23 09 000 801, AMM 24 23 09 400 801								
24-23-13-900-801-01		RAT MANUAL RELEASE CABLE						Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.070	AFL	0		TSN 0				
PROC. REF: AMM 24 23 13 000 801, AMM 24 23 13 400 801PROC. REF: AMM 24 23 13 000 801, AMM 24 23 13 400 801								
24-23-17-900-801-01		DOOR RAT LINK						Component ATA:24
PN:GL456-1501-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0467	HRS	0		TSN 0				
WC#: 24.075	AFL	0		TSN 0				
PROC. REF: AMM 24 23 17 000 801, AMM 24 23 17 400 801PROC. REF: AMM 24 23 17 000 801, AMM 24 23 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-23-21-900-801-01	RAT PUMP							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.080	AFL	0		TSN 0				
PROC. REF: AMM 24 23 21 000 801, AMM 24 23 21 400 801PROC. REF: AMM 24 23 21 000 801, AMM 24 23 21 400 801								
24-23-25-900-801-01	RAT UPLOCK							Component ATA:24
PN:GL456-1601-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0455	HRS	0		TSN 0				
WC#: 24.085	AFL	0		TSN 0				
PROC. REF: AMM 24 23 25 000 801, AMM 24 23 25 400 801PROC. REF: AMM 24 23 25 000 801, AMM 24 23 25 400 801								
24-24-01-900-801-01	NO.1 (LH) GENERATOR CONTROL UNIT GCU							Component ATA:24
PN:GL511-3104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2265	HRS	0		TSN 0				
WC#: 24.090	AFL	0		TSN 0				
PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801								
24-24-01-900-801-02	NO.2 (LH) GENERATOR CONTROL UNIT GCU							Component ATA:24
PN:GL511-3104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2277	HRS	0		TSN 0				
WC#: 24.090	AFL	0		TSN 0				
PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801								
24-24-01-900-801-03	NO.3 (RH) GENERATOR CONTROL UNIT GCU							Component ATA:24
PN:GL511-3104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2280	HRS	0		TSN 0				
WC#: 24.090	AFL	0		TSN 0				
PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801								
24-24-01-900-801-04	NO.4 (RH) GENERATOR CONTROL UNIT GCU							Component ATA:24
PN:GL511-3104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2339	HRS	0		TSN 0				
WC#: 24.090	AFL	0		TSN 0				
PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-24-01-900-801-05	NO.5 APU GENERATOR CONTROL UNIT GCU							Component ATA:24
PN:GL511-3104-1	MOS/MSC	28-Oct-10	O/C					
SN:1334	HRS	49:28						
WC#: 24.090	AFL	18						
PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801PROC. REF: AMM 24 24 01 000 801, AMM 24 24 01 400 801								
24-25-00-201	DISCARD OF THE NO. 1 (LH OUTBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER							Service ATA:24
	MOS	10-Mar-23						
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
	AFL	999						
PROC. REF: AMM 24 12 03 961 801PROC. REF: AMM 24 12 03 961 801								
24-25-00-201	DISCARD OF THE NO. 2 (LH INBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER							Service ATA:24
	MOS	10-Mar-23						
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
	AFL	999						
PROC. REF: AMM 24 12 03 961 801PROC. REF: AMM 24 12 03 961 801								
24-25-00-201	DISCARD OF THE NO. 3 (RH OUTBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER							Service ATA:24
	MOS	10-Mar-23						
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
	AFL	999						
PROC. REF: AMM 24 12 03 961 801PROC. REF: AMM 24 12 03 961 801								
24-25-00-201	DISCARD OF THE NO. 4 (RH INBD) VARIABLE FREQUENCY GENERATOR (VFG) OIL FILTER							Service ATA:24
	MOS	10-Mar-23						
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
	AFL	999						
PROC. REF: AMM 24 12 03 961 801PROC. REF: AMM 24 12 03 961 801								
24-25-00-202	VISUAL CHECK OF THE DIFFERENTIAL PRESSURE INDICATOR							Service ATA:24
	MOS	10-Mar-23						
	HRS	2845:10	1000 (+50/-50)		3845:10	3895:10	399:14 (+50)	
WC#: 24.030	AFL	999						
PROC. REF: AMM 24 12 00 210 801PROC. REF: AMM 24 12 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-26-59-621	U	OPERATIONAL TEST OF THE RESIDUAL CURRENT DEVICE						Service ATA:24
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
24-31-01-900-801-01		NO. 1 TRANSFORMER RECTIFIER UNIT TRU						Component ATA:24
PN:GL511-2102-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1516	HRS	0		TSN 0				
WC#: 24.095	AFL	0		TSN 0				
PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801								
24-31-01-900-801-02		NO. 2 TRANSFORMER RECTIFIER UNIT TRU						Component ATA:24
PN:GL511-2102-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1517	HRS	0		TSN 0				
WC#: 24.095	AFL	0		TSN 0				
PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801								
24-31-01-900-801-03		NO. 3 TRANSFORMER RECTIFIER UNIT TRU						Component ATA:24
PN:GL511-2102-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1519	HRS	0		TSN 0				
WC#: 24.095	AFL	0		TSN 0				
PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801								
24-31-01-900-801-04		NO. 4 TRANSFORMER RECTIFIER UNIT TRU						Component ATA:24
PN:GL511-2102-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1549	HRS	0		TSN 0				
WC#: 24.095	AFL	0		TSN 0				
PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801PROC. REF: AMM 24 31 01 000 801, AMM 24 31 01 400 801								
24-32-01-203		RESTORATION OF THE AVIONICS BATTERY						Service ATA:24
PN:024054-000	MOS	15-Oct-24	8 (+10%/-10%)		14-Jun-25	08-Jul-25	107 d (+24)	MRB
SN:090520025BAC1	HRS	3314:03						
WC#: 24.100	AFL	1328						
Restoration Date:: 14-Oct-24								
PROC. REF: BULLETINS , AMM 24 32 01 610 802PROC. REF: BULLETINS , AMM 24 32 01 610 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-01-900-801-01	AVIONICS BATTERY							Component ATA:24
PN:024054-000	MOS/MSC	15-Oct-24	O/C	TSO 0				
SN:090520025BAC1	HRS	3314:03		TSO 0				
WC#: 24.100	AFL	1328		TSO 0				
PROC. REF: AMM 24 32 01 000 801, AMM 24 32 01 400 801PROC. REF: AMM 24 32 01 000 801, AMM 24 32 01 400 801								
24-32-05-900-801-01	AVIONIC BAY BATTERY CHARGER							Component ATA:24
PN:GL511-2401-9	MOS/MSC	29-Jul-15	O/C	TSR 15				
SN:A158	HRS	1778:44		TSR 0				
WC#: 24.105	AFL	545		TSR 0				
PROC. REF: CMM 24-32-01, AMM 24 32 05 000 801, AMM 24 32 05 400 801PROC. REF: CMM 24-32-01, AMM 24 32 05 000 801, AMM 24 32 05 400 801								
24-32-05-900-801-02	APU BATTERY CHARGER							Component ATA:24
PN:GL511-2401-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E835	HRS	0		TSN 0				
WC#: 24.110	AFL	0		TSN 0				
PROC. REF: CMM 24-32-01, AMM 24 32 05 000 801, AMM 24 32 05 400 801PROC. REF: CMM 24-32-01, AMM 24 32 05 000 801, AMM 24 32 05 400 801								
24-32-09-203	RESTORATION APU BATTERY (24-32-09-203)							Service ATA:24
PN:024055-000	MOS	15-Oct-24	8 (+10%/-10%)		14-Jun-25	08-Jul-25	107 d (+24)	MRB
SN:09052000F6CC6	HRS	3314:03						
WC#: 24.010	AFL	1328						
Restoration Date:: 14-Oct-24								
PROC. REF: BULLETINS , AMM 24 32 09 610 802PROC. REF: BULLETINS , AMM 24 32 09 610 802								
24-32-09-900-801-01	APU BATTERY							Component ATA:24
PN:024055-000	MOS/MSC	15-Oct-24	O/C	TSO 0				
SN:09052000F6CC6	HRS	3314:03		TSO 0				
WC#: 24.010	AFL	1328		TSO 0				
PROC. REF: AMM 24 32 09 000 801, AMM 24 32 09 400 801PROC. REF: AMM 24 32 09 000 801, AMM 24 32 09 400 801								
24-41-01-900-801-01	CTA CURRENT TRANSFORMER							Component ATA:24
PN:GL516-1101-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1869	HRS	0		TSN 0				
WC#: 24.120	AFL	0		TSN 0				
PROC. REF: AMM 24 41 05 000 801, AMM 24 41 05 400 801PROC. REF: AMM 24 41 05 000 801, AMM 24 41 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-41-05-900-801-01		CURRENT TRANSFORMER UNIT					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24 41 05 000 801, AMM 24 41 05 400 801PROC. REF: AMM 24 41 05 000 801, AMM 24 41 05 400 801								
24-51-17-900-801-01		AC TO DC CONVERTER					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.125	AFL	0		TSN 0				
PROC. REF: AMM 24 51 17 000 801, AMM 24 51 17 400 801PROC. REF: AMM 24 51 17 000 801, AMM 24 51 17 400 801								
24-51-17-900-801-02		FREQUENCY CONVERTER					Component	ATA:24
PN:1-002-0102-1968	MOS/MSC	09-Nov-11	O/C	TSR 4				
SN:HT001521	HRS	480		TSR 0				
WC#: 24.125	AFL	180		TSR 0				
PROC. REF: AMM 24 51 17 000 801, AMM 24 51 17 400 801PROC. REF: AMM 24 51 17 000 801, AMM 24 51 17 400 801								
24-51-37-900-801-01		K2 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-37-900-801-02		K3 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-37-900-801-03		K5 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-51-37-900-801-04		K7 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-37-900-801-05		K8 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-37-900-801-06		K10 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-37-900-801-07		K11 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-37-900-801-08		K13 ACPC ZC-SERIES CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801PROC. REF: AMM 24 51 37 000 801, AMM 24 51 37 400 801								
24-51-41-900-801-01		K4 CONTACTOR					Component	ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-51-41-900-801-02	K6 CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801								
24-51-41-900-801-03	K9 CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801								
24-51-41-900-801-04	K12 CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801								
24-51-41-900-801-05	K1 CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801PROC. REF: AMM 24 51 41 000 801, AMM 24 51 41 400 801								
24-51-53-900-801-01	AC POWER CENTER							Component ATA:24
PN:GL512-1101-19	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0588	HRS	0		TSN 0				
WC#: 24.135	AFL	0		TSN 0				
PROC. REF: CMM 24-51-02, AMM 24 51 53 000 801, AMM 24 51 53 400 801PROC. REF: CMM 24-51-02, AMM 24 51 53 000 801, AMM 24 51 53 400 801								
24-61-00-900-801-01	DCPC DC POWER CENTER							Component ATA:24
PN:GL512-3101-15	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0590	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 00 000 801, AMM 24 61 00 400 801PROC. REF: AMM 24 61 00 000 801, AMM 24 61 00 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-61-00-900-801-02	DCPC DC POWER CENTER							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 00 000 801, AMM 24 61 00 400 801PROC. REF: AMM 24 61 00 000 801, AMM 24 61 00 400 801								
24-61-53-900-801-01	K1 DCPC L-SERIES CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801								
24-61-53-900-801-02	K2 DCPC L-SERIES CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801								
24-61-53-900-801-03	K3 DCPC L-SERIES CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801								
24-61-53-900-801-04	K4 DCPC L-SERIES CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801								
24-61-53-900-801-05	K5 DCPC L-SERIES CONTACTOR							Component ATA:24
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801PROC. REF: AMM 24 61 53 000 801, AMM 24 61 53 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-62-01-900-801-01		NO. 1 SPDA SECONDARY POWER DISTRIBUTION						Component ATA:24
PN:GL512-3201-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1876	HRS	0		TSN 0				
WC#: 24.145	AFL	0		TSN 0				
PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801								
24-62-01-900-801-02		NO. 2 SPDA SECONDARY POWER DISTRIBUTION						Component ATA:24
PN:GL512-3201-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1917	HRS	0		TSN 0				
WC#: 24.145	AFL	0		TSN 0				
PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801								
24-62-01-900-801-03		NO. 3 SPDA SECONDARY POWER DISTRIBUTION						Component ATA:24
PN:GL512-3201-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1953	HRS	0		TSN 0				
WC#: 24.145	AFL	0		TSN 0				
PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801								
24-62-01-900-801-04		NO. 4 SPDA SECONDARY POWER DISTRIBUTION						Component ATA:24
PN:GL512-3201-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1929	HRS	0		TSN 0				
WC#: 24.145	AFL	0		TSN 0				
PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801PROC. REF: AMM 24 62 01 000 801, AMM 24 62 01 400 801								
24-62-05-900-801-01		APU START (ASCA) CONTACTOR						Component ATA:24
PN:GL512-3301-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0629	HRS	0		TSN 0				
WC#: 24.150	AFL	0		TSN 0				
PROC. REF: AMM 24 62 05 000 801, AMM 24 62 05 400 801PROC. REF: AMM 24 62 05 000 801, AMM 24 62 05 400 801								
24-64-00-201		OPERATIONAL TEST OF THE DC OVERRIDE SYSTEM						Service ATA:24
	MOS	15-Oct-24	30 (+3m/-3m)	Adj 3	15-Jul-27	15-Oct-27	868 d (+92)	MRIP
	HRS	3314:03	500 (+50/-50)	Adj 50	3864:03	3914:03	418:07 (+50)	
	AFL	1328						
PROC. REF: AMM 24 64 00 710 801PROC. REF: AMM 24 64 00 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-70-01-900-801-01		LH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT						Component ATA:24
PN:GL542-3101-19	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1472	HRS	0		TSN 0				
WC#: 24.155	AFL	0		TSN 0				
PROC. REF: AMM 24 70 01 000 801, AMM 24 70 01 400 801PROC. REF: AMM 24 70 01 000 801, AMM 24 70 01 400 801								
24-70-01-900-801-02		RH EMS ELECTRICAL MANAGEMENT SYSTEM CONTROL DISPLAY UNIT						Component ATA:24
PN:GL542-3101-19	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1477	HRS	0		TSN 0				
WC#: 24.155	AFL	0		TSN 0				
PROC. REF: AMM 24 70 01 000 801, AMM 24 70 01 400 801PROC. REF: AMM 24 70 01 000 801, AMM 24 70 01 400 801								
241202-001		NO. 1 ENGINE - VFG OIL AIR COOLED COOLER						Component ATA:24
PN:50043001-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:50043-1419	HRS	0		TSN 0				
WC#: 24.005	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
241202-001		NO. 2 ENGINE - VFG OIL AIR COOLED COOLER						Component ATA:24
PN:50043001-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:50043-1418	HRS	0		TSN 0				
WC#: 24.005	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
241202-002		NO. 1 ENGINE - VFG OIL AIR COOLED COOLER						Component ATA:24
PN:50042001-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:50042-1418	HRS	0		TSN 0				
WC#: 24.005	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
241202-002		NO. 2 ENGINE - VFG OIL AIR COOLED COOLER						Component ATA:24
PN:50042001-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:50042-1417	HRS	0		TSN 0				
WC#: 24.005	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242333-701 ^U	RAT HEATER							Component ATA:24
PN:771770	MOS/MSC	31-Oct-12	O/C	TSN 4				
SN:UNKNOWN	HRS	869:06		TSN 0				
	AFL	308		TSN 0				
247000-701 ^U	NO.1 AC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10719B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09081465C	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247000-702 ^U	NO.2 AC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10719B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09011253C	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247000-703 ^U	NO.3 AC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10719B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09091479C	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247000-704 ^U	NO.4 AC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10719B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09091470C	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247000-705 ^U	NO.5 AC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10719B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09091474C	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
247001-701 ^U	NO.1 ACPDE PERSONALITY MODULE							Component ATA:24
PN:10722B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09101255	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247001-702 ^U	NO.2 ACPDE PERSONALITY MODULE							Component ATA:24
PN:10722B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09101258	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247001-703 ^U	NO.3 ACPDE PERSONALITY MODULE							Component ATA:24
PN:10722B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09101259	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247001-704 ^U	NO.4 ACPDE PERSONALITY MODULE							Component ATA:24
PN:10722B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09101265	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247001-705 ^U	NO.5 ACPDE PERSONALITY MODULE							Component ATA:24
PN:10722B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09101264	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247002-701 ^U	NO.1 DC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10718B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09111401A	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
247002-702 ^U	NO.2 DC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10718B01E01	MOS/MSC	13-Oct-11	O/C	TSR 2				
SN:08071068A	HRS	449		TSN 1765:06, TSR 0				
	AFL	176		TSN 569, TSR 0				
247002-703 ^U	NO.3 DC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10718B01E01	MOS/MSC	05-Jun-23	O/C	TSR 0				
SN:10121735B	HRS	2913:47		TSR 0				
	AFL	1041		TSR 0				
247002-704 ^U	NO.4 DC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10718B01E01	MOS/MSC	04-Jan-11	O/C	TSN 0				
SN:10091648A	HRS	132:18		TSN 0				
	AFL	44		TSN 0				
247002-705 ^U	NO.5 DC POWER DISTRIBUTION EQUIPMENT							Component ATA:24
PN:10718B01E01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09111403A	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247003-701 ^U	NO.1 DCPDE PERSONALITY MODULE							Component ATA:24
PN:10720B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09111446	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
247003-702 ^U	NO.2 DCPDE PERSONALITY MODULE							Component ATA:24
PN:10720B01E00	MOS/MSC	13-Oct-11	O/C	TSN 2				
SN:11021871	HRS	449		TSN 0				
	AFL	176		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
247003-703 ^U	NO.3 DCPDE PERSONALITY MODULE							Component ATA:24
PN:10720B01E00	MOS/MSC	26-Jan-11	O/C	TSN 5				
SN:09111451	HRS	139:11		TSN 111:05				
	AFL	49		TSN 38				
247003-704 ^U	NO.4 DCPDE PERSONALITY MODULE							Component ATA:24
PN:10720B01E00	MOS/MSC	30-Dec-10	O/C	TSN 0				
SN:10071642	HRS	132:18		TSN 0				
	AFL	44		TSN 0				
247003-705 ^U	NO.5 DCPDE PERSONALITY MODULE							Component ATA:24
PN:10720B01E00	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09111450	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-00-900-801-01	PILOT SEAT							Component ATA:25
PN:GC721-1001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:95-1400	HRS	0		TSN 0				
WC#: 25.030	AFL	0		TSN 0				
PROC. REF: AMM 25 11 00 000 801, AMM 25 11 00 400 801PROC. REF: AMM 25 11 00 000 801, AMM 25 11 00 400 801								
25-11-00-900-801-02	COPILOT SEAT							Component ATA:25
PN:GC721-1001-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:97-1400	HRS	0		TSN 0				
WC#: 25.030	AFL	0		TSN 0				
PROC. REF: AMM 25 11 00 000 801, AMM 25 11 00 400 801PROC. REF: AMM 25 11 00 000 801, AMM 25 11 00 400 801								
25-11-05-201	OPERATIONAL TEST OF THE INERTIA REELS AND THE INERTIA REELS CONTROL							Service ATA:25
	MOS	05-Feb-21	60 (+3m/-3m)	05-Feb-26	05-May-26	343 d (+89)	MRIP	
	HRS	2444:24	1000 (+50/-50)	3444:24	3494:24	TOL (+48:28)		
WC#: 25.005	AFL	745						
PROC. REF: AMM 25 11 05 710 801PROC. REF: AMM 25 11 05 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-09-201	GENERAL VISUAL INSPECTION OF THE SAFETY STRAPS							Service ATA:25
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 25.010	AFL	745						
PROC. REF: AMM 25 11 09 210 801PROC. REF: AMM 25 11 09 210 801								
25-13-01-900-801-01	L/H PILOT - PILOT FLOOR MAT HEATER							Component ATA:25
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.035	AFL	0		TSN 0				
PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801								
25-13-01-900-801-02	R/H PILOT - PILOT FLOOR MAT HEATER							Component ATA:25
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.035	AFL	0		TSN 0				
PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801								
25-13-01-900-801-03	L/H COPILOT - PILOT FLOOR MAT HEATER							Component ATA:25
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801								
25-13-01-900-801-04	R/H COPILOT - PILOT FLOOR MAT HEATER							Component ATA:25
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801PROC. REF: AMM 25 13 01 000 801, AMM 25 13 01 400 801								
25-13-50-621 ^U	DETAILED INSPECTION OF THE JUMPSEAT ATTACHMENT							Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-13-50-622	U	OPERATIONAL TEST OF THE JUMPSEAT INERTIA REELS						Service ATA:25
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
25-13-50-623	U	GENERAL VISUAL INSPECTION OF THE JUMPSEAT RESTRAINTS						Service ATA:25
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
25-13-50-624	U	OPERATIONAL TEST OF THE JUMPSEAT						Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						
25-21-50-621	U	GENERAL VISUAL INSPECTION OF THE PASSENGER SEAT RESTRAINTS						Service ATA:25
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
25-21-50-622	U	DETAILED INSPECTION OF THE PASSENGER SEATS (INCLUDING DIVANS)						Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1000		3845:10		399:14	
	AFL	999						
25-21-50-623	U	OPERATIONAL TEST OF THE PASSENGER SEAT INERTIA REELS (INCLUDING DIVANS)						Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-24-69-621	U	GENERAL VISUAL INSPECTION OF THE AVIONICS RACK DECOMPRESSION PANEL						Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						
25-30-50-622	U	GENERAL VISUAL INSPECTION OF THE GALLEY WASTE CONTAINER						Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						
25-30-50-624	U	REPLACEMENT OF THE GALLEY CHILLER FILTER						Service ATA:25
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
25-40-50-621	U	GENERAL VISUAL INSPECTION OF THE LAVATORY WASTE CONTAINER						Service ATA:25
	MOS	10-Mar-23						STLMC
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						
25-60-00-201		RESTORATION COPILOT LIFE VEST (25-60-00-201)						Service ATA:25
PN:P01074-201WC	MOS/MSC	05-Feb-21	DUE		12-Oct-29 (M)		1688 d	MRB
SN:19120880077	HRS	2444:24						
WC#: 25.050	AFL	745						
PROC. REF: AMM 25 60 00 840 802PROC. REF: AMM 25 60 00 840 802								
25-60-00-201		RESTORATION PILOT LIFE VEST (25-60-00-201)						Service ATA:25
PN:P01074-201WC	MOS/MSC	05-Feb-21	DUE		10-Dec-29 (M)		1747 d	MRB
SN:19120880073	HRS	2444:24						
WC#: 25.045	AFL	745						
PROC. REF: AMM 25 60 00 840 802PROC. REF: AMM 25 60 00 840 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-60-00-202		RESTORATION FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - PBE (25-60-00-202)						Service ATA:25
PN:119003-21	MOS/MSC	02-Jan-18	DUE		31-Oct-27 (M)		976 d	MRB
SN:0A4-41557M	HRS	2265:06						
WC#: 25.055	AFL	682						
PROC. REF: AMM 25 60 00 840 801PROC. REF: AMM 25 60 00 840 801								
25-60-00-203		DISCARD FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - PBE (25-60-00-203)						Service ATA:25
PN:119003-21	MOS/MSC	02-Jan-18	DUE		31-Oct-27 (M)		976 d	LIFE LIMIT
SN:0A4-41557M	HRS	2265:06						
WC#: 25.055	AFL	682						
PROC. REF: AMM 25 60 00 960 801PROC. REF: AMM 25 60 00 960 801								
25-60-00-208		DETAILED INSPECTION COPILOT LIFE VEST (25-60-00-208)						Service ATA:25
PN:P01074-201WC	MOS	05-Feb-21	60 (+3m/-3m)	Adj 3	05-May-26	05-Aug-26	432 d (+92)	MRIP
SN:19120880077	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 25.050	AFL	745						
PROC. REF: AMM 25 60 00 220 801PROC. REF: AMM 25 60 00 220 801								
25-60-00-208		DETAILED INSPECTION PILOT LIFE VEST (25-60-00-208)						Service ATA:25
PN:P01074-201WC	MOS	05-Feb-21	60 (+3m/-3m)	Adj 3	05-May-26	05-Aug-26	432 d (+92)	MRIP
SN:19120880073	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 25.045	AFL	745						
PROC. REF: AMM 25 60 00 220 801PROC. REF: AMM 25 60 00 220 801								
25-60-00-209		DETAILED INSPECTION FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - PBE (25-60-00-209)						Service ATA:25
PN:119003-21	MOS	21-Jul-21	60 (+3m/-3m)	Adj 3	21-Oct-26	21-Jan-27	601 d (+92)	MRIP
SN:0A4-41557M	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 25.055	AFL	747						
PROC. REF: AMM 25 60 00 220 802PROC. REF: AMM 25 60 00 220 802								
25-60-00-210		RESTORATION OF THE CREW FLASHLIGHTS						Service ATA:25
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 25.015	AFL	999						
PROC. REF: CMM 25-60-02, AMM 25 60 00 840 803PROC. REF: CMM 25-60-02, AMM 25 60 00 840 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-60-00-900-801-01	FLIGHT COMPARTMENT PROTECTIVE BREATHING EQUIPMENT - PBE							Component ATA:25
PN:119003-21	MOS/MSC	02-Jan-18	H/T	TSN 2				
SN:0A4-41557M	HRS	2265:06		TSN 0				
WC#: 25.055	AFL	682		TSN 0				
PROC. REF: CMM 25-2499-200PROC. REF: CMM 25-2499-200								
25-60-00-900-802-01	PILOT LIFE VEST							Component ATA:25
PN:P01074-201WC	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:19120880073	HRS	2444:24		TSN 0				
WC#: 25.045	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-60-00-900-802-02	COPILOT LIFE VEST							Component ATA:25
PN:P01074-201WC	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:19120880077	HRS	2444:24		TSN 0				
WC#: 25.050	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-60-50-622 ^U	DETAILED INSPECTION OF THE DITCHING LINE							Service ATA:25
	MOS	10-Mar-23	30		10-Sep-25		195 d	STLMC
	HRS	2845:10						
	AFL	999						
25-60-52-621 ^U	DETAILED INSPECTION OF THE CREW FLASHLIGHTS							Service ATA:25
	MOS	20-Jan-25	3		20-Apr-25		52 d	STLMC
	HRS	3398:31						
	AFL	1371						
25-61-00-201	OPERATIONAL TEST EMERGENCY LOCATOR TRANSMITTER SYSTEM (25-61-00-201)							Service ATA:25
PN:453-5004	MOS	21-Jul-21	45 (+3m/-3m)	Adj 3	21-Jul-25	21-Oct-25	144 d (+92)	MRB
SN:11475	HRS	2446:06						
WC#: 25.060	AFL	747						
PROC. REF: AMM 25 61 00 710 801PROC. REF: AMM 25 61 00 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-01-201		DISCARD OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY						Service ATA:25
PN:452-0133	MOS/MSC	15-May-24	DUE		01-Jul-29 (M)		1585 d	MRB
SN:1008136-008	HRS	3168:27						
WC#: 25.060	AFL	1205						
PROC. REF: AMM 25 61 01 961 801PROC. REF: AMM 25 61 01 961 801								
25-61-01-900-801-01		EMERGENCY LOCATOR TRANSMITTER						Component ATA:25
PN:453-5004	MOS/MSC	05-Feb-21	O/C					
SN:11475	HRS	2444:24						
WC#: 25.060	AFL	745						
PROC. REF: AMM 25 61 01 000 801, AMM 25 61 01 400 801PROC. REF: AMM 25 61 01 000 801, AMM 25 61 01 400 801								
25-61-01-900-802-01		EMERGENCY LOCATOR TRANSMITTER BATTERY						Component ATA:25
PN:452-0133	MOS/MSC	15-May-24	O/C	TSN 0				
SN:1008136-008	HRS	3168:27		TSN 0				
	AFL	1205		TSN 0				
PROC. REF: GENERIC NO REF, AMM 25 61 01 000 802, AMM 25 61 01 400 802PROC. REF: GENERIC NO REF, AMM 25 61 01 000 802, AMM 25 61 01 400 802								
25-61-05-900-801-01		ELT ANTENNA						Component ATA:25
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.065	AFL	0		TSN 0				
PROC. REF: AMM 25 61 05 000 801, AMM 25 61 05 400 801PROC. REF: AMM 25 61 05 000 801, AMM 25 61 05 400 801								
25-61-17-900-801-01		ELT - NAV INTERFACE UNIT						Component ATA:25
PN:453-6500	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:07226	HRS	0		TSN 0				
WC#: 25.070	AFL	0		TSN 0				
PROC. REF: AMM 25 61 17 000 801, AMM 25 61 17 400 801PROC. REF: AMM 25 61 17 000 801, AMM 25 61 17 400 801								
25-62-50-621 ^U		DETAILED INSPECTION OF THE PASSENGER LIFE VESTS						Service ATA:25
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-50-623 ^U	DETAILED INSPECTION OF THE LIFE RAFT							Service ATA:25
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
25-72-01-201	GENERAL VISUAL INSPECTION OF THE AVIONICS RACK INBOARD SMOKE SEALING PROVISIONS							Service ATA:25
	MOS	28-Sep-17	120 (+3m/-3m)		28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2242:56	2000 (+50/-50)		4242:56	4292:56	797 (+50)	
WC#: 25.020	AFL	677						
PROC. REF: AMM 25 72 01 210 801PROC. REF: AMM 25 72 01 210 801								
25-72-01-202	GENERAL VISUAL INSPECTION OF THE AVIONICS RACK SURROUND SMOKE SEALING PROVISIONS							Service ATA:25
	MOS	30-Jul-10	180 (+3m/-3m)		30-Jul-25	30-Oct-25	153 d (+92)	MRB
	HRS	0						
WC#: 25.025	AFL	0						
PROC. REF: AMM 25 72 01 210 802PROC. REF: AMM 25 72 01 210 802								
25-CUS-701 ^U	RH FWD DIVAN LIFE RAFT ELT BATTERY							Component ATA:25
PN:3RK00201	MOS/MSC	19-Feb-22	O/C					
SN:149563	HRS	2453:47						
	AFL	754						
25-CUS-702 ^U	RH AFT DIVAN LIFE RAFT ELT BATTERY							Component ATA:25
PN:PN	MOS/MSC	15-Oct-24	O/C					
SN:151997	HRS	3314:03						
	AFL	1328						
25-CUS-703 ^U	LH DIVAN LIFE RAFT ELT BATTERY							Component ATA:25
PN:PN-UNKNOWN	MOS/MSC	03-Nov-21	O/C					
SN:152017	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
250000 ^U	FIRST AID KIT							Component ATA:25
PN:AFAK	MOS/MSC		DUE		01-May-25 (M)		63 d	MANDATORY
SN:240400225-73582	HRS							
	AFL							
252000-701 ^U	JUMP SEAT (TSO C127) ASSEMBLY							Component ATA:25
PN:1513000-3	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:46680	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252000-704 ^U	#1 LH - SINGLE - AFT FACING SEAT ASSEMBLY							Component ATA:25
PN:70025213986-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:090930-01	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252000-705 ^U	#1 RH - SINGLE - AFT FACING SEAT ASSEMBLY							Component ATA:25
PN:70025213979-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:090930-02	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252000-706 ^U	#2 LH - SINGLE - FWD FACING SEAT ASSEMBLY							Component ATA:25
PN:70025213988-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:090930-03	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252000-707 ^U	#2 RH - SINGLE - FWD FACING SEAT ASSEMBLY							Component ATA:25
PN:70025213981-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:090930-04	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252000-708 ^U	#3 LH - DOUBLE - AFT FACING SEAT ASSEMBLY							Component ATA:25
PN:70025213990-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:090930-05	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252000-710 ^U	#4 LH - DOUBLE - FWD FACING SEAT ASSEMBLY							Component ATA:25
PN:70025213992-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:090930-06	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252001-701 ^U	MID RHS DIVAN							Component ATA:25
PN:41329001-291	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:5357763 S&D	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252001-702 ^U	RH AFT DIVAN							Component ATA:25
PN:41329001-293	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:5357986N S&D	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252001-703 ^U	LH AFT DIVAN							Component ATA:25
PN:41329001-295	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:5358010 S&D	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
252101-701 ^U	DIVAN MIDDLE RESTRAINT SYSTEM ASSY							Component ATA:25
PN:3128-1-020-8043	MOS/MSC	12-Sep-12	O/C	TSN 1				
SN:A0812	HRS	796:30		TSN 0				
	AFL	285		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
253000-701 ^U	HIGH TEMPERATURE OVEN UNIT							Component ATA:25
PN:400-1317-01-L	MOS/MSC	17-May-22	O/C	TSR 0				
SN:13-11-53118	HRS	2534:36		TSR 0				
	AFL	798		TSR 0				
253001-701 ^U	OVEN CONTROLLER							Component ATA:25
PN:400-1377-01	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09-11-46418	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
253002-701 ^U	MICROWAVE OVEN UNIT							Component ATA:25
PN:400-2577-01	MOS/MSC	05-Feb-21	O/C	TSN 104, TSR 0				
SN:12-03-50098	HRS	2444:24		TSN 1673:54, TSR 0				
	AFL	745		TSN 479, TSR 0				
253003-701 ^U	AIR CHILLER UNIT							Component ATA:25
PN:319-4	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:570	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
253004-701 ^U	EXPRESSO COFFEE MAKER MACHINE							Component ATA:25
PN:AL-EX15-200E-17	MOS/MSC	12-Sep-17	O/C	TSR 1				
SN:1631	HRS	2242:18		TSR 0				
	AFL	675		TSR 0				
256000-003 ^U	INFANT LIFE VEST (DIVAN AFT CABIN RH)							Component ATA:25
PN:216200-0	MOS/MSC	05-Jun-23	DUE	TSN 0	01-Mar-32 (M)		2559 d	CUSTOMER CODE
SN:219809	HRS	2913:47		TSN 0				
	AFL	1041		TSN 0				
Expiry Date: : 01-Mar-32								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256000-004 ^U	INFANT LIFE VEST (DIVAN MID CABIN AFT)							Component ATA:25
PN:216200-0	MOS/MSC	18-Feb-22	DUE	TSN 0	01-Sep-29 (M)		1647 d	CUSTOMER CODE
SN:182281	HRS	2452:23		TSN 0				
	AFL	753		TSN 0				
Expiry Date: : 01-Sep-29								
256000-005 ^U	ADULT/CHILD (SPARE) LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	10-Apr-17	DUE		30-Sep-26 (M)		580 d	CUSTOMER CODE
SN:16091360085	HRS	2095:10						
	AFL	637						
256000-006 ^U	ADULT/CHILD (SPARE) LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	10-Apr-17	DUE		30-Sep-26 (M)		580 d	CUSTOMER CODE
SN:16091360078	HRS	2095:10						
	AFL	637						
256000-007 ^U	ADULT/CHILD (SPARE) LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	10-Apr-17	DUE	TSN 6	22-Sep-26 (M)		572 d	CUSTOMER CODE
SN:16091360100	HRS	2095:10		TSN 0				
	AFL	637		TSN 0				
256000-008 ^U	INFANT LIFE VEST (DIVAN AFT)							Component ATA:25
PN:P0640-101	MOS/MSC	05-Jun-23	DUE	TSN 0	01-Mar-32 (M)		2559 d	CUSTOMER CODE
SN:219784	HRS	2913:47		TSN 0				
	AFL	1041		TSN 0				
Expiry Date: : 01-Mar-32								
256101-001C ^U	DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY (25-61-01-202)							Service ATA:25
PN:453-5004	MOS/MSC	05-Feb-21	N/A					
SN:11475	HRS	2444:24						
	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
258083-701A ^U	DETAILED INSPECTION FIRST AID KIT (DO NOT OPEN IF SEALED)(25-60-50-621)							Service ATA:25
	MOS	15-May-24	15		01-May-25 (M)		63 d	STLMC
	HRS	3168:27						
	AFL	1205						
259336-701 ^U	RH FWD DIVAN LIFE RAFT							Component ATA:25
PN:69FASA-6K2-1-104	MOS/MSC	15-Oct-24	O/C	TSN 68, TSO 0				
SN:6SA-00100	HRS	3314:03		TSN 950:56, TSO 0				
	AFL	1328		TSN 605, TSO 0				
259336-701B ^U	RESTORATION RH FWD DIVAN LIFE RAFT (25-62-50-624)							Service ATA:25
PN:69FASA-6K2-1-104	MOS	15-Oct-24	36		15-Oct-27		960 d	
SN:6SA-00100	HRS	3314:03						
	AFL	1328						
259336-701C ^U	REPLACE RH FWD DIVAN LIFE RAFT ELT BATTERY							Service ATA:25
PN:3RK00201	MOS/MSC	15-Oct-24	DUE		01-Nov-29 (M)		1708 d	
SN:149563	HRS	3314:03						
	AFL	1328						
Expiry Date: : 01-Nov-29								
259336-702 ^U	RH AFT DIVAN LIFE RAFT							Component ATA:25
PN:69FASA-6K2-1-104	MOS/MSC	15-Oct-24	O/C	TSN 31, TSO 0				
SN:6SA-00199	HRS	3314:03		TSN 838:41, TSO 0				
	AFL	1328		TSN 566, TSO 0				
259336-702B ^U	RESTORATION RH AFT DIVAN LIFE RAFT (25-62-50-624)							Service ATA:25
PN:69FASA-6K2-1-104	MOS	15-Oct-24	36		01-Sep-27 (M)		916 d	
SN:6SA-00199	HRS	3314:03						
	AFL	1328						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259336-702C ^U		REPLACE RH AFT DIVAN LIFE RAFT ELT BATTERY						Service ATA:25
PN:PN	MOS/MSC	15-Oct-24	DUE		01-Sep-27 (M)		916 d	
SN:151997	HRS	3314:03						
	AFL	1328						
Expiry Date: : 01-Sep-27								
259336-703 ^U		LH DIVAN LIFE RAFT						Component ATA:25
PN:69FASA-6K2-1-104	MOS/MSC	15-Oct-24	O/C	TSN 31, TSO 0				
SN:6SA-00200	HRS	3314:03		TSN 838:41, TSO 0				
	AFL	1328		TSN 566, TSO 0				
259336-703B ^U		RESTORATION LH DIVAN LIFE RAFT (25-62-50-624)						Service ATA:25
PN:69FASA-6K2-1-104	MOS	15-Oct-24	36		01-Sep-27 (M)		916 d	
SN:6SA-00200	HRS	3314:03						
	AFL	1328						
259336-703C ^U		REPLACE LH DIVAN LIFE RAFT ELT BATTERY						Service ATA:25
PN:PN-UNKNOWN	MOS/MSC	15-Oct-24	DUE		01-Sep-27 (M)		916 d	
SN:152017	HRS	3314:03						
	AFL	1328						
Expiry Date: : 01-Sep-27								
259500-701 ^U		SWITCH PANEL						Component ATA:25
PN:2601-1-7-T17SA	MOS/MSC	10-Feb-11	O/C					
SN:3L10G	HRS	144:17						
	AFL	53						
259500-702 ^U		SWITCH PANEL						Component ATA:25
PN:2601-1-7-T17SA	MOS/MSC	10-Feb-11	O/C					
SN:3L10D	HRS	144:17						
	AFL	53						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259500-703 ^U	SWITCH PANEL							Component ATA:25
PN:2601-1-14-T17SA	MOS/MSC	10-Feb-11	O/C					
SN:3LOTF	HRS	144:17						
	AFL	53						
259500-704 ^U	SWITCH PANEL							Component ATA:25
PN:2601-1-14-T17SA	MOS/MSC	10-Feb-11	O/C					
SN:3LOTD	HRS	144:17						
	AFL	53						
259536-701 ^U	LIFE VEST (DIVAN AFT CABIN RH MID)							Component ATA:25
PN:63600-191	MOS/MSC	18-Feb-22	O/C	TSN 31, TSO 0				
SN:L4146718	HRS	2452:23		TSN 15:13, TSO 0				
	AFL	753		TSN 11, TSO 0				
259536-701B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-21	120	01-Sep-31		2377 d		
SN:L4146718	HRS							
	AFL							
259536-702 ^U	LIFE VEST (DIVAN MID CABIN RH MID)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881839	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-702B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120	01-Sep-29		1647 d		
SN:L4881839	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259536-703 ^U	LIFE VEST (DIVAN MID CABIN RH FWD)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881841	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-703B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881841	HRS							
	AFL							
259536-704 ^U	LIFE VEST (RH#2)							Component ATA:25
PN:63600-191	MOS/MSC	18-Feb-22	O/C	TSN 31, TSO 0				
SN:L4146714	HRS	2452:23		TSN 15:13, TSO 0				
	AFL	753		TSN 11, TSO 0				
259536-704B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-21	120		01-Sep-31		2377 d	
SN:L4146714	HRS							
	AFL							
259536-705 ^U	LIFE VEST (LH#1)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881844	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-705B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881844	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
259536-706 ^U	LIFE VEST (DIVAN AFT CABIN RH AFT)							Component	ATA:25
PN:63600-191	MOS/MSC	18-Feb-22	O/C	TSN 12, TSO 0					
SN:L4881846	HRS	2452:23		TSN 7:59, TSO 0					
	AFL	753		TSN 8, TSO 0					
259536-706B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service	ATA:25
PN:63600-191	MOS	01-Sep-21	120	01-Sep-31			2377 d		
SN:L4881846	HRS								
	AFL								
259536-707 ^U	LIFE VEST (DIVAN AFT CABIN LH AFT)							Component	ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0					
SN:L5067363	HRS	2444:24		TSN 0					
	AFL	745		TSN 0					
259536-707B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service	ATA:25
PN:63600-191	MOS	01-Apr-20	120	01-Apr-30			1859 d		
SN:L5067363	HRS								
	AFL								
259536-708 ^U	LIFE VEST (DIVAN AFT CABIN RH FWD)							Component	ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0					
SN:L5067367	HRS	2444:24		TSN 0					
	AFL	745		TSN 0					
259536-708B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service	ATA:25
PN:63600-191	MOS	01-Apr-20	120	01-Apr-30			1859 d		
SN:L5067367	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259536-709 ^U	LIFE VEST (LH#3)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4116789	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-709B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Mar-18	120		01-Mar-28		1098 d	
SN:L4116789	HRS							
	AFL							
259536-710 ^U	LIFE VEST (RH#4)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881812	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-710B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881812	HRS							
	AFL							
259536-711 ^U	LIFE VEST (DBL SEAT FACING FWD O/B)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881817	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-711B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881817	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259536-712 ^U	LIFE VEST (DBL SEAT FACING AFT I/B)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881834	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-712B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881834	HRS							
	AFL							
259536-713 ^U	LIFE VEST (DBL SEAT FACING AFT O/B)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881836	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-713B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881836	HRS							
	AFL							
259536-714 ^U	LIFE VEST (DIVAN AFT CABIN LH MID)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L5101595	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-714B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Jun-20	120		01-Jun-30		1920 d	
SN:L5101595	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259536-715 ^U	LIFE VEST (DBL SEAT FACING FWD I/B)							Component ATA:25
PN:63600-191	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4881838	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-715B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-191	MOS	01-Sep-19	120		01-Sep-29		1647 d	
SN:L4881838	HRS							
	AFL							
259536-716 ^U	CABIN LIFE VEST							Component ATA:25
PN:63600-591	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L4948313	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
259536-716B ^U	RESTORE CABIN LIFE VEST (25-62-50-622)							Service ATA:25
PN:63600-591	MOS	01-Nov-19	120		01-Nov-29		1708 d	
SN:L4948313	HRS							
	AFL							
259810-701 ^U	COCKPIT LH FLASHLIGHT							Component ATA:25
PN:P2-07-0022-001	MOS/MSC	20-Jan-25	O/C	TSN 0				
SN:NSN	HRS	3398:31		TSN 0				
	AFL	1371		TSN 0				
259810-702 ^U	COCKPIT RH FLASHLIGHT							Component ATA:25
PN:P2-07-0022-001	MOS/MSC	20-Jan-25	O/C	TSN 0				
SN:NSN	HRS	3398:31		TSN 0				
	AFL	1371		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259900-701 ^U	POWER DISABLE, CABIN SEATS SWITCH							Component ATA:25
PN:SP2209746	MOS/MSC	30-Sep-11	O/C	TSN 0				
SN:MP640624-02-02	HRS	442		TSN 0				
	AFL	173		TSN 0				
351102-701A ^U	DETAILED INSPECTION WARDROBE PROTECTIVE BREATHING EQUIPMENT - PBE (35-11-50-623)							Service ATA:25
PN:MR-10037N	MOS	15-May-24						STLMC
SN:E1702150	HRS	3168:27	500		3668:27		222:31	
	AFL	1205						
ELJ 250010 ^U	DETAIL INSPECTION EMERGENCY LOCATOR TRANSMITTER DETAIL INSPECTION OF ELT BATTERY COMPARTMENT AND RELATED CIRCUIT BOARD FOR CORROSION (AS PER AMM 25-61-01-220-801)							Service ATA:25
PN:453-5004	MOS/MSC	15-May-24	C/C					CUSTOMER CODE
SN:11475	HRS	3168:27						
	AFL	1205						
ATA 26 - FIRE PROTECTION								
26-10-01-201	OPERATIONAL TEST OF THE FIRE-DETECTION-AND- EXTINGUISHING (FIDEEX) CONTROL-CIRCUITS, ARM AND DISCHARGE CIRCUITS							Service ATA:26
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 26.005	AFL	745						
PROC. REF: AMM 26 10 01 710 802PROC. REF: AMM 26 10 01 710 802								
26-10-01-900-801-01	LH FS987 ALARM FIDEEX CONTROL							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.045	AFL	0		TSN 0				
PROC. REF: AMM 26 10 01 000 801, AMM 26 10 01 400 801PROC. REF: AMM 26 10 01 000 801, AMM 26 10 01 400 801								
26-12-00-201	FUNCTIONAL TEST OF THE APU FIRE DETECTION SYSTEM							Service ATA:26
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 26.010	AFL	999						
PROC. REF: AMM 26 12 00 720 801PROC. REF: AMM 26 12 00 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-12-01-900-801-01	EDUCTOR LOOP A SENSING ELEMENT							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.050	AFL	0		TSN 0				
PROC. REF: AMM 26 12 01 000 801, AMM 26 12 01 400 801PROC. REF: AMM 26 12 01 000 801, AMM 26 12 01 400 801								
26-12-01-900-801-02	EDUCTOR LOOP B SENSING ELEMENT							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.050	AFL	0		TSN 0				
PROC. REF: AMM 26 12 01 000 801, AMM 26 12 01 400 801PROC. REF: AMM 26 12 01 000 801, AMM 26 12 01 400 801								
26-12-05-900-801-01	RIGHT HATCH LOOP A SENSING ELEMENT							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.055	AFL	0		TSN 0				
PROC. REF: AMM 26 12 05 000 801, AMM 26 12 05 400 801PROC. REF: AMM 26 12 05 000 801, AMM 26 12 05 400 801								
26-12-05-900-801-02	RIGHT HATCH LOOP B SENSING ELEMENT							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.055	AFL	0		TSN 0				
PROC. REF: AMM 26 12 05 000 801, AMM 26 12 05 400 801PROC. REF: AMM 26 12 05 000 801, AMM 26 12 05 400 801								
26-12-09-900-801-01	LEFT STRUT LOOP A SENSING ELEMENT							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.060	AFL	0		TSN 0				
PROC. REF: AMM 26 12 09 000 801, AMM 26 12 09 400 801PROC. REF: AMM 26 12 09 000 801, AMM 26 12 09 400 801								
26-12-09-900-801-02	LEFT STRUT LOOP B SENSING ELEMENT							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.060	AFL	0		TSN 0				
PROC. REF: AMM 26 12 09 000 801, AMM 26 12 09 400 801PROC. REF: AMM 26 12 09 000 801, AMM 26 12 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-13-00-201	FUNCTIONAL TEST OF THE MAIN LANDING GEAR (MLG) OVERHEAT-DETECTION SYSTEM							Service ATA:26
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 26.015	AFL	999						
PROC. REF: AMM 26 13 00 720 801PROC. REF: AMM 26 13 00 720 801								
26-13-01-900-801-01	LEFT MLG WHEEL WELL SENSING ELEMENT							Component ATA:26
PN:GK774-0023-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:016	HRS	0		TSN 0				
WC#: 26.065	AFL	0		TSN 0				
PROC. REF: AMM 26 13 01 000 801, AMM 26 13 01 400 801PROC. REF: AMM 26 13 01 000 801, AMM 26 13 01 400 801								
26-13-01-900-801-02	RIGHT MLG WHEEL WELL SENSING ELEMENT							Component ATA:26
PN:GK774-0023-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:016	HRS	0		TSN 0				
WC#: 26.065	AFL	0		TSN 0				
PROC. REF: AMM 26 13 01 000 801, AMM 26 13 01 400 801PROC. REF: AMM 26 13 01 000 801, AMM 26 13 01 400 801								
26-21-00-201	GENERAL VISUAL INSPECTION OF THE SINGLE-PATH DISCHARGE LINES							Service ATA:26
	MOS	28-Sep-17	180 (+3m/-3m)		28-Sep-32	28-Dec-32	2770 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		5242:56	5292:56	1797 (+50)	
WC#: 26.020	AFL	677						
PROC. REF: AMM 26 21 00 210 801PROC. REF: AMM 26 21 00 210 801								
26-21-01-201	FUNCTIONAL TEST (HYDROSTATIC TEST) NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE (26-21-01-201)							Service ATA:26
PN:GK774-0020-3	MOS	01-Oct-20	120		01-Oct-30		2042 d	MRB
SN:0263BD	HRS							
WC#: 26.070	AFL							
HydroCheck Date: : 01-Oct-20								
PROC. REF: AMM 26 21 01 790 801PROC. REF: AMM 26 21 01 790 801								
26-21-01-201	FUNCTIONAL TEST (HYDROSTATIC TEST) NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE (26-21-01-201)							Service ATA:26
PN:GK774-0020-3	MOS	01-Nov-20	120		01-Nov-30		2073 d	MRB
SN:16451EL	HRS							
WC#: 26.075	AFL							
HydroCheck Date: : 01-Nov-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: AMM 26 21 01 790 801PROC. REF: AMM 26 21 01 790 801								
26-21-01-202 FUNCTIONAL TEST NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH (26-21-01-202)								
PN:GK774-0020-3	MOS	01-Oct-20	120 (+3m/-3m)		01-Oct-30	01-Jan-31	2042 d (+92)	Service ATA:26
SN:0263BD	HRS							MRB
WC#: 26.070	AFL							
PROC. REF: AMM 26 21 01 720 801PROC. REF: AMM 26 21 01 720 801								
26-21-01-202 FUNCTIONAL TEST NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTAINER PRESSURE-SWITCH (26-21-01-202)								
PN:GK774-0020-3	MOS	01-Nov-20	120 (+3m/-3m)		01-Nov-30	01-Feb-31	2073 d (+92)	Service ATA:26
SN:16451EL	HRS							MRB
WC#: 26.075	AFL							
PROC. REF: AMM 26 21 01 720 801PROC. REF: AMM 26 21 01 720 801								
26-21-01-203 FUNCTIONAL TEST NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT (26-21-01-203)								
PN:GK774-0020-3	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	Service ATA:26
SN:0263BD	HRS	2444:24						MRB
WC#: 26.070	AFL	745						
PROC. REF: AMM 26 21 01 720 802PROC. REF: AMM 26 21 01 720 802								
26-21-01-203 FUNCTIONAL TEST NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE CONTENTS WEIGHT (26-21-01-203)								
PN:GK774-0020-3	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	Service ATA:26
SN:16451EL	HRS	2444:24						MRB
WC#: 26.075	AFL	745						
PROC. REF: AMM 26 21 01 720 802PROC. REF: AMM 26 21 01 720 802								
26-21-01-900-801-01 NO.1 FWD ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								
PN:GK774-0020-3	MOS/MSC	05-Feb-21	O/C					Component ATA:26
SN:0263BD	HRS	2444:24						
WC#: 26.070	AFL	745						
PROC. REF: CMM 26-21-65, AMM 26 21 01 000 801, AMM 26 21 01 400 801PROC. REF: CMM 26-21-65, AMM 26 21 01 000 801, AMM 26 21 01 400 801								
26-21-01-900-801-02 NO.2 AFT ,ENGINE/APU FIRE EXTINGUISHER BOTTLE								
PN:GK774-0020-3	MOS/MSC	05-Feb-21	O/C	TSO 0				Component ATA:26
SN:16451EL	HRS	2444:24		TSO 0				
WC#: 26.075	AFL	745		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: CMM 26-21-65, AMM 26 21 01 000 801, AMM 26 21 01 400 801PROC. REF: CMM 26-21-65, AMM 26 21 01 000 801, AMM 26 21 01 400 801								
26-21-05-201	DISCARD APU AFT DISCHARGE CARTRIDGE							Service ATA:26
	MOS	01-Nov-18	120		29-Oct-28 (M)		1340 d	LIFE LIMIT
	HRS							
	AFL							
PROC. REF: AMM 26 21 05 961 801PROC. REF: AMM 26 21 05 961 801								
26-21-05-201	DISCARD APU FWD DISCHARGE CARTRIDGE							Service ATA:26
	MOS	01-Nov-18	120		29-Oct-28 (M)		1340 d	LIFE LIMIT
	HRS							
	AFL							
PROC. REF: AMM 26 21 05 961 801PROC. REF: AMM 26 21 05 961 801								
26-21-05-201	DISCARD ENG. 1 AFT DISCHARGE CARTRIDGE							Service ATA:26
	MOS	01-Aug-18	120		29-Jul-28 (M)		1248 d	LIFE LIMIT
	HRS							
	AFL							
PROC. REF: AMM 26 21 05 961 801PROC. REF: AMM 26 21 05 961 801								
26-21-05-201	DISCARD ENG. 1 FWD DISCHARGE CARTRIDGE							Service ATA:26
	MOS	01-Aug-18	120		29-Jul-28 (M)		1248 d	LIFE LIMIT
	HRS							
	AFL							
PROC. REF: AMM 26 21 05 961 801PROC. REF: AMM 26 21 05 961 801								
26-21-05-201	DISCARD ENG. 2 AFT DISCHARGE CARTRIDGE							Service ATA:26
	MOS	01-Nov-18	120		29-Oct-28 (M)		1340 d	LIFE LIMIT
	HRS							
	AFL							
PROC. REF: AMM 26 21 05 961 801PROC. REF: AMM 26 21 05 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-05-201	DISCARD ENG. 2 FWD DISCHARGE CARTRIDGE							Service ATA:26
	MOS	01-Nov-18	120		29-Oct-28 (M)		1340 d	LIFE LIMIT
	HRS							
	AFL							
PROC. REF: AMM 26 21 05 961 801PROC. REF: AMM 26 21 05 961 801								
26-21-05-900-801-01	ENGINE NO. 1 (LEFT) EXTINGUISHER CARTRIDGE (26-21-05-201)							Component ATA:26
PN:GK774-0026-1	MOS/MSC	22-Apr-19	H/T	TSN 0				
SN:AFA1011	HRS	2378:21						
WC#: 26.080	AFL	728						
PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801								
26-21-05-900-801-02	ENGINE NO. 1 (RIGHT) EXTINGUISHER CARTRIDGE (26-21-05-201)							Component ATA:26
PN:GK774-0026-1	MOS/MSC	22-Apr-19	H/T	TSN 0				
SN:AFA1034	HRS	2378:21						
WC#: 26.080	AFL	728						
PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801								
26-21-05-900-801-03	ENGINE NO. 2 (LEFT) EXTINGUISHER CARTRIDGE (26-21-05-201)							Component ATA:26
PN:GK774-0026-1	MOS/MSC	22-Apr-19	H/T	TSN 0				
SN:AFC6152	HRS	2378:21						
WC#: 26.080	AFL	728						
PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801								
26-21-05-900-801-04	ENGINE NO. 2 (RIGHT) EXTINGUISHER CARTRIDGE (26-21-05-201)							Component ATA:26
PN:GK774-0026-1	MOS/MSC	22-Apr-19	H/T	TSN 0				
SN:AFC6155	HRS	2378:21						
WC#: 26.080	AFL	728						
PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801								
26-21-05-900-801-05	APU FWD EXTINGUISHER (26-21-05-201) CARTRIDGE							Component ATA:26
PN:GK774-0026-1	MOS/MSC	22-Apr-19	H/T	TSN 0				
SN:AFC6216	HRS	2378:21						
WC#: 26.085	AFL	728						
PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-05-900-801-06	APU AFT EXTINGUISHER (26-21-05-201) CARTRIDGE							Component ATA:26
PN:GK774-0026-1	MOS/MSC	22-Apr-19	H/T	TSN 0				
SN:AFC6291	HRS	2378:21						
WC#: 26.085	AFL	728						
PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801PROC. REF: AMM 26 21 05 000 801, AMM 26 21 05 400 801								
26-21-13-201	OPERATIONAL TEST OF THE ENGINE FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS							Service ATA:26
	MOS	21-Jul-21	180 (+3m/-3m)		21-Jul-36	21-Oct-36	4162 d (+92)	MRIP
	HRS	2446:06	3000 (+50/-50)		5446:06	5496:06	2000:10 (+50)	
WC#: 26.030	AFL	747						
PROC. REF: AMM 26 21 13 710 811PROC. REF: AMM 26 21 13 710 811								
26-21-13-202	OPERATIONAL TEST OF THE APU FIRE-HANDLE CIRCUIT, RELATED CIRCUITS AND RELAYS							Service ATA:26
	MOS	28-Sep-17	180 (+3m/-3m)		28-Sep-32	28-Dec-32	2770 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		5242:56	5292:56	1797 (+50)	
WC#: 26.035	AFL	677						
PROC. REF: AMM 26 21 13 710 812PROC. REF: AMM 26 21 13 710 812								
26-21-13-900-801-01	FIRE S/O ENGINE LH HANDLE							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.090	AFL	0		TSN 0				
PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801								
26-21-13-900-801-02	FIRE S/O ENGINE RH HANDLE							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.090	AFL	0		TSN 0				
PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801								
26-21-13-900-801-03	FIRE S/O ENGINE APU HANDLE							Component ATA:26
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.090	AFL	0		TSN 0				
PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801PROC. REF: AMM 26 21 13 000 801, AMM 26 21 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-45-201	OPERATIONAL TEST OF THE DISCHARGE CHECK VALVES							Service ATA:26
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 26.040	AFL	745						
PROC. REF: AMM 26 21 45 710 801PROC. REF: AMM 26 21 45 710 801								
26-23-00-201	FUNCTIONAL TEST FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE (WEIGHT TEST) (26-23-00-201)							Service ATA:26
PN:30H673	MOS	15-Oct-24	15 (+3m/-3m)		08-Jan-26	08-Apr-26	315 d (+90)	MRB
SN:A-24024716	HRS	3314:03						
WC#: 26.095	AFL	1328						
WeightCheck Date : : 08-Oct-24								
PROC. REF: AMM 26 23 01 720 801PROC. REF: AMM 26 23 01 720 801								
26-23-01-900-801-01	FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:30H673	MOS/MSC	05-Feb-21	O/C	TSO 0				
SN:A-24024716	HRS	2444:24		TSO 0				
WC#: 26.095	AFL	745		TSO 0				
PROC. REF: AMM 26 23 01 000 801, AMM 26 23 01 400 801PROC. REF: AMM 26 23 01 000 801, AMM 26 23 01 400 801								
261000-701 ^U	SMOKE (FWD VANITY) DETECTOR							Component ATA:26
PN:473597-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3494	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
261000-702 ^U	SMOKE (AFT LAVATORY) DETECTOR							Component ATA:26
PN:473597-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3535	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
261000-703 ^U	SMOKE (BAGGAGE COMPARTMENT) DETECTOR							Component ATA:26
PN:473597-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3542	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261117-001	NO. 1 ENGINE - FIRE CORE WIRE							Component ATA:26
PN:473899	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0694	HRS	0		TSN 0				
WC#: 26.010	ENC	0		TSN 0				
PROC. REF: EMM 26-11-17, EMM 26-11-17PROC. REF: EMM 26-11-17, EMM 26-11-17								
261117-001	NO. 2 ENGINE - FIRE CORE WIRE							Component ATA:26
PN:473899	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0692	HRS	0		TSN 0				
WC#: 26.010	ENC	0		TSN 0				
PROC. REF: EMM 26-11-17, EMM 26-11-17PROC. REF: EMM 26-11-17, EMM 26-11-17								
262301-001B ^U	RESTORATION FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER BOTTLE (26-23-00-202)							Service ATA:26
PN:30H673	MOS	02-Oct-20	144		02-Oct-32		2774 d	MRB
SN:A-24024716	HRS							
WC#: 26.095	AFL							
262308-701 ^U	FIRE EXTINGUISHER-FWD CABIN							Component ATA:26
PN:BA21741SR-5	MOS/MSC	17-Oct-23	O/C	TSN 0				
SN:127603	HRS	3029:02		TSN 0				
	AFL	1119		TSN 0				
262308-701A ^U	DETAILED INSPECTION FIRE EXTINGUISHER BOTTLE FWD CABIN (26-21-50-621)							Service ATA:26
PN:BA21741SR-5	MOS	15-Oct-24	12		15-Oct-25		230 d	STLMC
SN:127603	HRS	3314:03						
	AFL	1328						
262308-701B ^U	RESTORATION FIRE EXTINGUISHER BOTTLE FWD CABIN (26-21-50-622)							Service ATA:26
PN:BA21741SR-5	MOS	22-May-23	72		22-May-29		1545 d	STLMC
SN:127603	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262308-702 ^U	FIRE EXTINGUISHER AFT CABIN							Component ATA:26
PN:BA21741SR-5	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:115744	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
262308-702A ^U	DETAILED INSPECTION FIRE EXTINGUISHER BOTTLE AFT CABIN (26-21-50-621)							Service ATA:26
PN:BA21741SR-5	MOS	15-Oct-24	12		15-Oct-25		230 d	STLMC
SN:115744	HRS	3314:03						
	AFL	1328						
262308-702B ^U	RESTORATION FIRE EXTINGUISHER BOTTLE AFT CABIN (26-21-50-622)							Service ATA:26
PN:BA21741SR-5	MOS	14-Nov-19	72		14-Nov-25		260 d	STLMC
SN:115744	HRS							
	AFL							
262320-701 ^U	AFT WARDROBE FIRE EXTINGUISHER (AFT WARDROBE) BOTTLE							Component ATA:26
PN:466090	MOS/MSC	24-Oct-24	O/C	TSN 0				
SN:I23015360	HRS	3324:09		TSN 0				
	AFL	1336		TSN 0				
262320-701A ^U	DETAILED INSPECTION AFT WARDROBE FIRE EXTINGUISHER (AFT WARDROBE) BOTTLE (26-21-50-621)							Service ATA:26
PN:466090	MOS	24-Oct-24	12		24-Oct-25		239 d	STLMC
SN:I23015360	HRS	3324:09						
	AFL	1336						
262320-701B ^U	RESTORATION AFT WARDROBE FIRE EXTINGUISHER (AFT WARDROBE) BOTTLE (26-21-50-622)							Service ATA:26
PN:466090	MOS	24-Oct-24	72		24-Oct-30		2065 d	STLMC
SN:I23015360	HRS	3324:09						
	AFL	1336						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-201	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE FORWARD AVIONICS COMPARTMENT, FS202.75+32.00 TO FS280.00+32.00							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.005	AFL	745						
PROC. REF: AMM 27 00 00 220 802PROC. REF: AMM 27 00 00 220 802								
27-00-00-202	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MAIN AVIONICS COMPARTMENT, FS280.00 +32.00 TO FS557.00							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.010	AFL	745						
PROC. REF: AMM 27 00 00 220 803PROC. REF: AMM 27 00 00 220 803								
27-00-00-203	DETAILED INSPECTION OF THE AILERON, ELEVATOR AND RUDDER CONTROL CABLES IN THE MID- LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00							Service ATA:27
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 27.015	AFL	745						
PROC. REF: AMM 27 00 00 220 804PROC. REF: AMM 27 00 00 220 804								
27-00-00-204	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL AND MID WING-TO-FUSELAGE FAIRING							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.020	AFL	745						
PROC. REF: AMM 27 10 00 220 801PROC. REF: AMM 27 10 00 220 801								
27-00-00-205	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE FLIGHT COMPARTMENT, FS202.75+32.00 TO FS280.00+32.00							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.025	AFL	745						
PROC. REF: AMM 27 10 00 220 802PROC. REF: AMM 27 10 00 220 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-206	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MID AND OUTBOARD WING BOX, WS178.00 TO WS536.50							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.030	AFL	745						
PROC. REF: AMM 27 10 00 220 803PROC. REF: AMM 27 10 00 220 803								
27-00-00-207	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD WING TRAILING EDGE, WS47.62 TO WS178.00							Service ATA:27
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 27.035	AFL	999						
PROC. REF: AMM 27 10 00 220 804PROC. REF: AMM 27 10 00 220 804								
27-00-00-208	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT POWER DISTRIBUTION/ECS COMPARTMENT, FS781.00 TO FS861.00							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.040	AFL	745						
PROC. REF: AMM 27 00 00 220 807PROC. REF: AMM 27 00 00 220 807								
27-00-00-209	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT, FS861.00 TO FS987.55							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.045	AFL	745						
PROC. REF: AMM 27 00 00 220 808PROC. REF: AMM 27 00 00 220 808								
27-00-00-210	DETAILED INSPECTION OF THE ELEVATOR AND RUDDER CONTROL CABLES IN THE FUSELAGE/STABILIZER SECTION, FS987.55 TO REAR SPAR							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.050	AFL	745						
PROC. REF: AMM 27 00 00 220 809PROC. REF: AMM 27 00 00 220 809								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-211	DETAILED INSPECTION OF THE ELEVATOR CONTROL CABLES IN THE VERTICAL STABILIZER , FRONT SPAR TO REAR SPAR							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.055	AFL	745						
PROC. REF: AMM 27 30 00 220 801PROC. REF: AMM 27 30 00 220 801								
27-00-00-212	OPERATIONAL TEST OF THE AILERON, ELEVATOR AND RUDDER CONTROL POWER- CONTROL UNITS (PCU)							Service ATA:27
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 27.060	AFL	747						
PROC. REF: AMM 27 00 00 710 801PROC. REF: AMM 27 00 00 710 801								
27-10-00-201	LUBRICATION OF THE AILERON POWER-CONTROL UNIT (PCU) TOGGLE-LINK SLOTTED BEARINGS							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 12 22 00 640 838PROC. REF: AMM 12 22 00 640 838								
27-11-00-900-801-01	LH MLG WHEEL WELL ROD							Component ATA:27
PN:GC415-0030-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12263	HRS	0		TSN 0				
WC#: 27.215	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-11-00-900-801-02	RH MLG WHEEL WELL ROD							Component ATA:27
PN:GC415-0030-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12269	HRS	0		TSN 0				
WC#: 27.215	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-11-05-201	FUNCTIONAL TEST OF THE ROLL DISCONNECT MECHANISM							Service ATA:27
	MOS	28-Sep-17	120 (+3m/-3m)		28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		5242:56	5292:56	1797 (+50)	
WC#: 27.065	AFL	677						
PROC. REF: AMM 27 11 05 720 801PROC. REF: AMM 27 11 05 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-05-202	OPERATIONAL TEST OF THE ROLL DISCONNECT MECHANISM							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 27.070	AFL	745						
PROC. REF: AMM 27 11 05 710 801PROC. REF: AMM 27 11 05 710 801								
27-11-05-900-801-01	ROLL DISCONNECT ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.210	AFL	0		TSN 0				
PROC. REF: AMM 27 11 05 000 801, AMM 27 11 05 400 801PROC. REF: AMM 27 11 05 000 801, AMM 27 11 05 400 801								
27-11-09-900-801-01	AILERON TORQUE TUBE							Component ATA:27
PN:GC413-1200-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D792306	HRS	0		TSN 0				
WC#: 27.225	AFL	0		TSN 0				
PROC. REF: AMM 27 11 09 000 801, AMM 27 11 09 400 801PROC. REF: AMM 27 11 09 000 801, AMM 27 11 09 400 801								
27-11-13-900-801-01	LH ROLL SPOILER TRANSDUCER							Component ATA:27
PN:GT415-6006-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:L1277	HRS	0		TSN 0				
WC#: 27.220	AFL	0		TSN 0				
PROC. REF: AMM 27 11 13 000 801, AMM 27 11 13 400 801, AMM 27 11 13 720 801, AMM 27 11 13 820 801PROC. REF: AMM 27 11 13 000 801, AMM 27 11 13 400 801, AMM 27 11 13 720 801, AMM 27 11 13 820 801								
27-11-13-900-801-02	RH ROLL SPOILER TRANSDUCER							Component ATA:27
PN:GT415-6006-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N5078	HRS	0		TSN 0				
WC#: 27.220	AFL	0		TSN 0				
PROC. REF: AMM 27 11 13 000 801, AMM 27 11 13 400 801, AMM 27 11 13 720 801, AMM 27 11 13 820 801PROC. REF: AMM 27 11 13 000 801, AMM 27 11 13 400 801, AMM 27 11 13 720 801, AMM 27 11 13 820 801								
27-11-17-900-801-01	LH TENSION AILERON REGULATOR							Component ATA:27
PN:GC415-1600-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR272	HRS	0		TSN 0				
WC#: 27.235	AFL	0		TSN 0				
PROC. REF: AMM 27 11 17 000 801, AMM 27 11 17 400 801PROC. REF: AMM 27 11 17 000 801, AMM 27 11 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-17-900-801-02	RH TENSION AILERON REGULATOR							Component ATA:27
PN:GC415-1600-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR264	HRS	0		TSN 0				
WC#: 27.235	AFL	0		TSN 0				
PROC. REF: AMM 27 11 17 000 801, AMM 27 11 17 400 801PROC. REF: AMM 27 11 17 000 801, AMM 27 11 17 400 801								
27-11-21-900-801-01	LEFT AILERON POSITION TRANSDUCER							Component ATA:27
PN:GT415-0200-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N5023	HRS	0		TSN 0				
WC#: 27.240	AFL	0		TSN 0				
PROC. REF: AMM 27 11 21 000 801, AMM 27 11 21 400 801PROC. REF: AMM 27 11 21 000 801, AMM 27 11 21 400 801								
27-11-21-900-801-02	RIGHT AILERON POSITION TRANSDUCER							Component ATA:27
PN:GT415-0200-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N5777	HRS	0		TSN 0				
WC#: 27.240	AFL	0		TSN 0				
PROC. REF: AMM 27 11 21 000 801, AMM 27 11 21 400 801PROC. REF: AMM 27 11 21 000 801, AMM 27 11 21 400 801								
27-11-25-101	FUNCTIONAL TEST OF THE AILERON POWER-CONTROL UNIT (PCU) (CMR*)							Service ATA:27
	MOS	21-Jul-21					CMR	
	HRS	2446:06	1500		3946:06		500:10	
WC#: 27.075	AFL	747						
PROC. REF: AMM 27 11 25 720 801PROC. REF: AMM 27 11 25 720 801								
27-11-25-102	FUNCTIONAL TEST OF THE AILERON PCU BUNGEE (CMR**)							Service ATA:27
	MOS	10-Mar-23					CMR	
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 27.080	AFL	999						
PROC. REF: AMM 27 11 25 720 802PROC. REF: AMM 27 11 25 720 802								
27-11-25-900-801-01	NO. 1 AILERON PCU							Component ATA:27
PN:GT411-1700-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1488	HRS	0		TSN 0				
WC#: 27.245	AFL	0		TSN 0				
PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-25-900-801-02	NO. 2 AILERON PCU							Component ATA:27
PN:GT411-1700-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1486	HRS	0		TSN 0				
WC#: 27.245	AFL	0		TSN 0				
PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801								
27-11-25-900-801-03	NO. 3 AILERON PCU							Component ATA:27
PN:GT411-1700-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1501	HRS	0		TSN 0				
WC#: 27.245	AFL	0		TSN 0				
PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801								
27-11-25-900-801-04	NO. 4 AILERON PCU							Component ATA:27
PN:GT411-1700-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1503	HRS	0		TSN 0				
WC#: 27.245	AFL	0		TSN 0				
PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801PROC. REF: AMM 27 11 25 000 801, AMM 27 11 25 400 801								
27-11-25-900-802-01	LH OUTBD WING ROD CONTROL							Component ATA:27
PN:GC415-0030-45	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY13262	HRS	0		TSN 0				
WC#: 27.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-11-25-900-802-02	RH OUTBD WING ROD CONTROL							Component ATA:27
PN:GC415-0030-45	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY13243	HRS	0		TSN 0				
WC#: 27.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-11-35-101	FUNCTIONAL TEST OF THE AILERON CABLE TENSION - FLIGHT COMPARTMENT CABLES (CMR**)							Service ATA:27
	MOS	15-May-24	30 (+3m/-3m)	15-Nov-26 (M)	15-Feb-27	626 d (+92)	CMR	
	HRS	3168:27						
	AFL	1205						
PROC. REF: AMM 27 11 35 720 801PROC. REF: AMM 27 11 35 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-35-102	FUNCTIONAL TEST OF THE AILERON CABLE TENSION - FUSELAGE CABLES (CMR**)							Service ATA:27
	MOS	15-May-24	30 (+3m/-3m)		15-Nov-26 (M)	15-Feb-27	626 d (+92)	CMR
	HRS	3168:27						
	AFL	1205						
PROC. REF: AMM 27 11 35 720 802PROC. REF: AMM 27 11 35 720 802								
27-11-35-103	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL (POST SB 700-1A11-27-044 PART G OR PART H OR PART I OR PART J OR PART K OR PART L OR PART M OR PART P) (CMR**)							Service ATA:27
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 27 11 35 220 801PROC. REF: AMM 27 11 35 220 801								
27-11-35-104	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE WING TRAILING EDGE, AT THE INNER, MID AND OUTER FLAP AREAS (POST SB 700-1A11-27-044 PART K OR PART L OR PART M OR PART P) (CMR**)							Service ATA:27
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 27 11 35 220 802PROC. REF: AMM 27 11 35 220 802								
27-11-35-201	FUNCTIONAL TEST OF THE AILERON CABLE - WING CABLES							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 27 11 35 720 803PROC. REF: AMM 27 11 35 720 803								
27-12-05-900-801-01	AILERON-MLG WHEEL WELL TRIM ACTUATOR							Component ATA:27
PN:GT412-1500-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2983	HRS	0		TSN 0				
WC#: 27.255	AFL	0		TSN 0				
PROC. REF: AMM 27 12 05 000 801, AMM 27 12 05 400 801PROC. REF: AMM 27 12 05 000 801, AMM 27 12 05 400 801								
27-20-00-201	LUBRICATION OF THE RUDDER POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 12 22 00 640 839PROC. REF: AMM 12 22 00 640 839								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-00-201	GENERAL VISUAL INSPECTION OF THE SINGLE-RUDDER CONTROL-PATH AND PCU LINKAGE CENTERING-SPRINGS							Service ATA:27
	MOS	30-Jul-09	240 (+3m/-3m)		30-Jul-29	30-Oct-29	1614 d (+92)	MRIP
	HRS	0	4500 (+50/-50)		4500	4550	1054:04 (+50)	
WC#: 27.085	AFL	0						
PROC. REF: AMM 27 21 00 210 802PROC. REF: AMM 27 21 00 210 802								
27-21-00-900-801-01	LH FWD AVIONINCS BAY ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-21-00-900-801-02	RH FWD AVIONINCS BAY ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-21-00-900-801-03	FWD AVIONINCS BAY ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-21-01-900-801-01	RUDDER (STABILIXER QUARDANT) ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-21-01-900-802-02	RUDDER LINEAR FEEL UNIT							Component ATA:27
PN:GC415-2360-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR1080	HRS	0		TSN 0				
WC#: 27.290	AFL	0		TSN 0				
PROC. REF: AMM 27 21 01 000 802, AMM 27 21 01 400 802PROC. REF: AMM 27 21 01 000 802, AMM 27 21 01 400 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-05-201	OPERATIONAL TEST OF THE RUDDER LOAD LIMITER							Service ATA:27
	MOS	30-Jul-09	240 (+3m/-3m)		30-Jul-29	30-Oct-29	1614 d (+92)	MRIP
	HRS	0	4500 (+50/-50)		4500	4550	1054:04 (+50)	
WC#: 27.090	AFL	0						
PROC. REF: AMM 27 21 05 710 801PROC. REF: AMM 27 21 05 710 801								
27-21-05-900-801-01	RUDDER LIMITER							Component ATA:27
PN:GC415-2400-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR0337	HRS	0		TSN 0				
WC#: 27.300	AFL	0		TSN 0				
PROC. REF: AMM 27 21 05 000 801, AMM 27 21 05 400 801PROC. REF: AMM 27 21 05 000 801, AMM 27 21 05 400 801								
27-21-05-900-802-01	LH LINEAR YAW DAMPER ACTUATOR ASSEMBLY							Component ATA:27
PN:GC415-2565-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0810H396	HRS	0		TSN 0				
WC#: 27.305	AFL	0		TSN 0				
PROC. REF: AMM 55 30 13 000 807, AMM 55 30 13 400 807PROC. REF: AMM 55 30 13 000 807, AMM 55 30 13 400 807								
27-21-05-900-802-02	RH LINEAR YAW DAMPER ACTUATOR ASSEMBLY							Component ATA:27
PN:GC415-2565-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0801H409	HRS	0		TSN 0				
WC#: 27.305	AFL	0		TSN 0				
PROC. REF: AMM 55 30 13 000 807, AMM 55 30 13 400 807PROC. REF: AMM 55 30 13 000 807, AMM 55 30 13 400 807								
27-21-05-900-803-01	RUDDER LIMITER UNIT							Component ATA:27
PN:GC413-2600-7/03	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D672638	HRS	0		TSN 0				
WC#: 27.340	AFL	0		TSN 0				
PROC. REF: AMM 27 21 05 000 801, AMM 27 21 05 400 801PROC. REF: AMM 27 21 05 000 801, AMM 27 21 05 400 801								
27-21-09-101	OPERATIONAL TEST OF THE RUDDER POWER-CONTROL UNIT (PCU) INPUT LIMITERS (CMR**)							Service ATA:27
	MOS	10-Mar-23						CMR
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 27.095	AFL	999						
PROC. REF: AMM 27 21 09 710 801PROC. REF: AMM 27 21 09 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-09-900-801-01		NO. 1 LOAD LIMITER						Component ATA:27
PN:GC415-2790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR1233	HRS	0		TSN 0				
WC#: 27.310	AFL	0		TSN 0				
PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801								
27-21-09-900-801-02		NO. 2 LOAD LIMITER						Component ATA:27
PN:GC415-2790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR0907	HRS	0		TSN 0				
WC#: 27.310	AFL	0		TSN 0				
PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801								
27-21-09-900-801-03		NO. 3 LOAD LIMITER						Component ATA:27
PN:GC415-2790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR0896	HRS	0		TSN 0				
WC#: 27.310	AFL	0		TSN 0				
PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801PROC. REF: AMM 27 21 09 000 801, AMM 27 21 09 400 801								
27-21-13-101		FUNCTIONAL TEST OF THE RUDDER POWER-CONTROL UNITS (PCU) (CMR**)						Service ATA:27
	MOS	10-Mar-23						CMR
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 27.100	AFL	999						
PROC. REF: AMM 27 21 13 720 801PROC. REF: AMM 27 21 13 720 801								
27-21-17-900-801-01		RUDDER POSITION TRANSDUCER						Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.315	AFL	0		TSN 0				
PROC. REF: AMM 27 21 17 000 801, AMM 27 21 17 400 801PROC. REF: AMM 27 21 17 000 801, AMM 27 21 17 400 801								
27-21-21-900-801-01		NO. 1 RUDDER PCU						Component ATA:27
PN:GT411-2800-7	MOS/MSC	15-May-24	O/C	TSR 0				
SN:1290	HRS	3168:27		TSR 0				
WC#: 27.320	AFL	1205		TSR 0				
PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-21-900-801-02		NO. 2 RUDDER PCU					Component	ATA:27
PN:GT411-2800-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1122	HRS	0		TSN 0				
WC#: 27.320	AFL	0		TSN 0				
PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801								
27-21-21-900-801-03		NO. 3 RUDDER PCU					Component	ATA:27
PN:GT411-2800-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1121	HRS	0		TSN 0				
WC#: 27.320	AFL	0		TSN 0				
PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801								
27-21-21-900-802-01		RUDDER					Component	ATA:27
PN:GS268-0001-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B364	HRS	0		TSN 0				
WC#: 27.325	AFL	0		TSN 0				
PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801PROC. REF: AMM 27 21 21 000 801, AMM 27 21 21 400 801								
27-21-25-900-801-01		LOB PEDAL RUDDER PILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.260	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-25-900-801-02		LIB PEDAL RUDDER PILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.260	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-25-900-801-03		RIB PEDAL RUDDER COPILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.265	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-25-900-801-04		ROB PEDAL RUDDER COPILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.265	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-25-900-801-05		LOB PEDAL PILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.270	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-25-900-801-06		LIB PEDAL PILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.270	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-25-900-801-07		RIB PEDAL COPILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.275	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-25-900-801-08		ROB PEDAL COPILOT ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.275	AFL	0		TSN 0				
PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801PROC. REF: AMM 27 21 25 000 801, AMM 27 21 25 400 801								
27-21-27-101		FUNCTIONAL TEST OF THE RUDDER CABLE TENSION (CMR**)					Service	ATA:27
	MOS	15-May-24	30 (+3m/-3m)	15-Nov-26 (M)	15-Feb-27	626 d (+92)	CMR	
	HRS	3168:27						
	AFL	1205						
PROC. REF: AMM 27 21 27 720 801PROC. REF: AMM 27 21 27 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-22-05-900-801-01	RUDDER FS1047, WL54 TRIM ACTUATOR							Component ATA:27
PN:GT412-2550-3	MOS/MSC	15-Oct-24	O/C					
SN:1018	HRS	3314:03						
WC#: 27.330	AFL	1328						
PROC. REF: AMM 27 22 05 000 801, AMM 27 22 05 400 801PROC. REF: AMM 27 22 05 000 801, AMM 27 22 05 400 801								
27-23-00-201	VISUAL CHECK OF THE RUDDER TRAVEL-LIMITING SYSTEM							Service ATA:27
	MOS	30-Jul-09	240 (+3m/-3m)		30-Jul-29	30-Oct-29	1614 d (+92)	MRIP
	HRS	0	4500 (+50/-50)		4500	4550	1054:04 (+50)	
WC#: 27.105	AFL	0						
PROC. REF: AMM 27 23 00 210 801PROC. REF: AMM 27 23 00 210 801								
27-23-01-900-801-01	LEFT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.335	AFL	0		TSN 0				
PROC. REF: AMM 27 23 01 000 801, AMM 27 23 01 400 801PROC. REF: AMM 27 23 01 000 801, AMM 27 23 01 400 801								
27-23-01-900-801-02	RIGHT TRAVEL LIMIT (RUDDER) TRIM ACTUATOR							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.335	AFL	0		TSN 0				
PROC. REF: AMM 27 23 01 000 801, AMM 27 23 01 400 801PROC. REF: AMM 27 23 01 000 801, AMM 27 23 01 400 801								
27-23-05-900-801-01	MID VERTICAL. STAB - RIB NO. 4 - NO. 5 ROD CONTROL							Component ATA:27
PN:GC415-0030-41	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12337	HRS	0		TSN 0				
WC#: 27.350	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-23-05-900-801-02	LIMITER OUTPUT ROD CONTROL							Component ATA:27
PN:GC415-0030-43	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12454	HRS	0		TSN 0				
WC#: 27.355	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-23-05-900-801-03		MLG WHEEL WELL ROD					Component	ATA:27
PN:GC415-0030-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-11928	HRS	0		TSN 0				
WC#: 27.345	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-23-09-900-801-01		LH RUDDER POSITION TRANSDUCER					Component	ATA:27
PN:GT415-2950-1	MOS/MSC	18-Jun-21	O/C					
SN:3571	HRS	2444:24						
WC#: 27.360	AFL	745						
PROC. REF: AMM 27 23 09 000 801, AMM 27 23 09 400 801PROC. REF: AMM 27 23 09 000 801, AMM 27 23 09 400 801								
27-23-09-900-801-02		RH RUDDER POSITION TRANSDUCER					Component	ATA:27
PN:GT415-2950-1	MOS/MSC	13-Jun-14	O/C	TSN 1				
SN:2661	HRS			TSN 0				
WC#: 27.360	AFL			TSN 0				
PROC. REF: AMM 27 23 09 000 801, AMM 27 23 09 400 801PROC. REF: AMM 27 23 09 000 801, AMM 27 23 09 400 801								
27-30-00-201		LUBRICATION OF THE ELEVATOR POWER-CONTROL UNIT (PCU) SLOTTED BEARINGS					Service	ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)	05-Feb-26	05-May-26	343 d (+89)	MRB	
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 12 22 00 640 840PROC. REF: AMM 12 22 00 640 840								
27-31-00-900-801-01		LH ELEVATOR MID VERTICAL STAB ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.370	AFL	0		TSN 0				
PROC. REF: AMM 27 31 15 000 801, AMM 27 31 15 400 801PROC. REF: AMM 27 31 15 000 801, AMM 27 31 15 400 801								
27-31-00-900-801-02		RH ELEVATOR MID VERTICAL STAB ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.370	AFL	0		TSN 0				
PROC. REF: AMM 27 31 15 000 801, AMM 27 31 15 400 801PROC. REF: AMM 27 31 15 000 801, AMM 27 31 15 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-00-900-802-01	LH ASSEMBLY COLUMN							Component ATA:27
PN:GC415-3149-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09359	HRS	0		TSN 0				
WC#: 27.380	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-00-900-802-02	RH ASSEMBLY COLUMN							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.380	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-00-900-803-01	LH MID VERTICAL STABILIZER ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.375	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-00-900-803-02	RH MID VERTICAL STABILIZER ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.375	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-05-201	FUNCTIONAL TEST OF THE PITCH DISCONNECT MECHANISM							Service ATA:27
	MOS	28-Sep-17	120 (+3m/-3m)		28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		5242:56	5292:56	1797 (+50)	
WC#: 27.110	AFL	677						
PROC. REF: AMM 27 31 05 720 801PROC. REF: AMM 27 31 05 720 801								
27-31-05-202	OPERATIONAL TEST OF THE PITCH DISCONNECT MECHANISM							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 27.115	AFL	745						
PROC. REF: AMM 27 31 05 710 801PROC. REF: AMM 27 31 05 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-05-900-801-01		PITCH DISCONNECT MECHANISM					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.385	AFL	0		TSN 0				
PROC. REF: AMM 27 31 05 000 801, AMM 27 31 05 400 801PROC. REF: AMM 27 31 05 000 801, AMM 27 31 05 400 801								
27-31-09-900-802-01		PITCH LOCK SOLENOID					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.390	AFL	0		TSN 0				
PROC. REF: AMM 27 31 09 000 802, AMM 27 31 09 400 802PROC. REF: AMM 27 31 09 000 802, AMM 27 31 09 400 802								
27-31-13-900-801-01		LEFT ELEVATOR LOAD LIMITER					Component	ATA:27
PN:GC415-3550-3	MOS/MSC	05-Feb-21	O/C					
SN:FR1164	HRS	2444:24						
WC#: 27.395	AFL	745						
PROC. REF: AMM 27 31 13 000 801, AMM 27 31 13 400 801PROC. REF: AMM 27 31 13 000 801, AMM 27 31 13 400 801								
27-31-13-900-801-02		RIGHT ELEVATOR LOAD LIMITER					Component	ATA:27
PN:GC412-3550-3	MOS/MSC	05-Feb-21	O/C					
SN:FR1132	HRS	2444:24						
WC#: 27.395	AFL	745						
PROC. REF: AMM 27 31 13 000 801, AMM 27 31 13 400 801PROC. REF: AMM 27 31 13 000 801, AMM 27 31 13 400 801								
27-31-13-900-802-01		HORIZONTAL STABILIZER ROD CONTROL					Component	ATA:27
PN:GC415-0030-25	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12770	HRS	0		TSN 0				
WC#: 27.400	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-13-900-803-01		LH HORIZONTAL STAB ROD CONTROL					Component	ATA:27
PN:GC415-0030-31	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12972	HRS	0		TSN 0				
WC#: 27.400	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-13-900-804-01	HORIZONTAL STAB ROD CONTROL							Component ATA:27
PN:GC415-0030-39	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12948	HRS	0		TSN 0				
WC#: 27.400	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-13-900-805-01	LH ELEVATOR ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.405	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-13-900-806-01	RH HORIZONTAL STAB ROD CONTROL							Component ATA:27
PN:GC415-0030-31	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:TY-12968	HRS	0		TSN 0				
WC#: 27.410	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-13-900-807-01	RH ELEVATOR ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.415	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-17-201	OPERATIONAL TEST OF THE ELEVATOR POWER-CONTROL UNIT (PCU) LOAD LIMITERS							Service ATA:27
	MOS	28-Sep-17	180 (+3m/-3m)		28-Sep-32	28-Dec-32	2770 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		5242:56	5292:56	1797 (+50)	
WC#: 27.120	AFL	677						
PROC. REF: AMM 27 31 17 710 801PROC. REF: AMM 27 31 17 710 801								
27-31-17-900-801-01	NO. 1 LOAD LIMITER							Component ATA:27
PN:GC415-3790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR1353	HRS	0		TSN 0				
WC#: 27.420	AFL	0		TSN 0				
PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-17-900-801-02	NO. 2 LOAD LIMITER							Component ATA:27
PN:GC415-3790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR1345	HRS	0		TSN 0				
WC#: 27.420	AFL	0		TSN 0				
PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801								
27-31-17-900-801-03	NO. 3 LOAD LIMITER							Component ATA:27
PN:GC415-3790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR1343	HRS	0		TSN 0				
WC#: 27.420	AFL	0		TSN 0				
PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801								
27-31-17-900-801-04	NO. 4 LOAD LIMITER							Component ATA:27
PN:GC415-3790-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR1338	HRS	0		TSN 0				
WC#: 27.420	AFL	0		TSN 0				
PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801PROC. REF: AMM 27 31 17 000 801, AMM 27 31 17 400 801								
27-31-19-101	DETAILED INSPECTION OF THE BEARING IN THE ELEVATOR TORQUE TUBE ASSEMBLY (CMR**)							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)	05-Feb-26	05-May-26	343 d (+89)	AIRWORTHINESS	
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 27 31 19 220 801PROC. REF: AMM 27 31 19 220 801								
27-31-21-101	FUNCTIONAL TEST OF THE ELEVATOR POWER-CONTROL UNITS (PCU) (CMR*)							Service ATA:27
	MOS	10-Mar-23					CMR	
	HRS	2845:10	1500	4345:10		899:14		
WC#: 27.125	AFL	999						
PROC. REF: AMM 27 31 21 720 801PROC. REF: AMM 27 31 21 720 801								
27-31-21-900-801-01	NO. 1 ELEVATOR PCU							Component ATA:27
PN:GT411-3800-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1535	HRS	0		TSN 0				
WC#: 27.425	AFL	0		TSN 0				
PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-21-900-801-02		NO. 2 ELEVATOR PCU					Component	ATA:27
PN:GT411-3800-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1533	HRS	0		TSN 0				
WC#: 27.425	AFL	0		TSN 0				
PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801								
27-31-21-900-801-03		NO. 3 ELEVATOR PCU					Component	ATA:27
PN:GT411-3800-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1518	HRS	0		TSN 0				
WC#: 27.425	AFL	0		TSN 0				
PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801								
27-31-21-900-801-04		NO. 4 ELEVATOR PCU					Component	ATA:27
PN:GT411-3800-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1542	HRS	0		TSN 0				
WC#: 27.425	AFL	0		TSN 0				
PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801PROC. REF: AMM 27 31 21 000 801, AMM 27 31 21 400 801								
27-31-25-900-801-01		LEFT ELEVATOR POSITION TRANSDUCER					Component	ATA:27
PN:GT415-0200-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N9531	HRS	0		TSN 0				
WC#: 27.430	AFL	0		TSN 0				
PROC. REF: AMM 27 31 25 000 801, AMM 27 31 25 400 801PROC. REF: AMM 27 31 25 000 801, AMM 27 31 25 400 801								
27-31-25-900-801-02		RIGHT ELEVATOR POSITION TRANSDUCER					Component	ATA:27
PN:GT415-0200-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:M9512	HRS	0		TSN 0				
WC#: 27.430	AFL	0		TSN 0				
PROC. REF: AMM 27 31 25 000 801, AMM 27 31 25 400 801PROC. REF: AMM 27 31 25 000 801, AMM 27 31 25 400 801								
27-31-29-900-801-01		LH ELEVATOR					Component	ATA:27
PN:GS278-0001-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B360	HRS	0		TSN 0				
WC#: 27.435	AFL	0		TSN 0				
PROC. REF: AMM 27 31 29 000 801, AMM 27 31 29 400 801PROC. REF: AMM 27 31 29 000 801, AMM 27 31 29 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-29-900-801-02		RH ELEVATOR					Component	ATA:27
PN:GS278-0001-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B360	HRS	0		TSN 0				
WC#: 27.435	AFL	0		TSN 0				
PROC. REF: AMM 27 31 29 000 801, AMM 27 31 29 400 801PROC. REF: AMM 27 31 29 000 801, AMM 27 31 29 400 801								
27-31-33-900-801-01		LH FORWARD QUADRANT					Component	ATA:27
PN:GC413-3300-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D908970	HRS	0		TSN 0				
WC#: 27.365	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-33-900-801-02		RH FORWARD QUADRANT					Component	ATA:27
PN:GC413-3350-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E043636	HRS	0		TSN 0				
WC#: 27.365	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-33-900-802-01		LH FWD AVIONINCS BAY ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-33-900-802-02		RH FWD AVIONINCS BAY ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-31-33-900-803-01		LH ELEVATOR TENSION REGULATOR					Component	ATA:27
PN:GC415-3305-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR419	HRS	0		TSN 0				
WC#: 27.445	AFL	0		TSN 0				
PROC. REF: AMM 27 31 33 000 801, AMM 27 31 33 400 801PROC. REF: AMM 27 31 33 000 801, AMM 27 31 33 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-33-900-803-02	RH ELEVATOR TENSION REGULATOR							Component ATA:27
PN:GC415-3305-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:FR405	HRS	0		TSN 0				
WC#: 27.445	AFL	0		TSN 0				
PROC. REF: AMM 27 31 33 000 801, AMM 27 31 33 400 801PROC. REF: AMM 27 31 33 000 801, AMM 27 31 33 400 801								
27-31-35-201	FUNCTIONAL TEST OF THE ELEVATOR CABLE TENSION							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 27 31 35 720 801PROC. REF: AMM 27 31 35 720 801								
27-32-01-900-801-01	RIGHT FORWARD STALL PROTECTION COMPUTER							Component ATA:27
PN:GH582-3001-19	MOS/MSC	26-May-11	O/C					
SN:527	HRS	252:35		TSN 490:48				
WC#: 27.450	AFL	85		TSN 178				
PROC. REF: AMM 27 32 01 000 801, AMM 27 32 01 400 801PROC. REF: AMM 27 32 01 000 801, AMM 27 32 01 400 801								
27-32-05-900-801-01	PILOT STICK SHAKER							Component ATA:27
PN:GH582-3003-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1371	HRS	0		TSN 0				
WC#: 27.455	AFL	0		TSN 0				
PROC. REF: AMM 27 32 05 000 801, AMM 27 32 05 400 801PROC. REF: AMM 27 32 05 000 801, AMM 27 32 05 400 801								
27-32-05-900-801-02	COPILOT STICK SHAKER							Component ATA:27
PN:GH582-3003-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1343	HRS	0		TSN 0				
WC#: 27.455	AFL	0		TSN 0				
PROC. REF: AMM 27 32 05 000 801, AMM 27 32 05 400 801PROC. REF: AMM 27 32 05 000 801, AMM 27 32 05 400 801								
27-32-09-900-801-01	LH AOA SENSOR							Component ATA:27
PN:GH582-3002-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:793	HRS	0		TSN 0				
WC#: 27.460	AFL	0		TSN 0				
PROC. REF: AMM 27 32 09 000 801, AMM 27 32 09 400 801PROC. REF: AMM 27 32 09 000 801, AMM 27 32 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-32-09-900-801-02		RH AOA SENSOR					Component	ATA:27
PN:GH582-3002-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:801	HRS	0		TSN 0				
WC#: 27.460	AFL	0		TSN 0				
PROC. REF: AMM 27 32 09 000 801, AMM 27 32 09 400 801PROC. REF: AMM 27 32 09 000 801, AMM 27 32 09 400 801								
27-32-13-900-802-01		MACH TRANSDUCER					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.465	AFL	0		TSN 0				
PROC. REF: AMM 27 32 13 000 802, AMM 27 32 13 400 802PROC. REF: AMM 27 32 13 000 802, AMM 27 32 13 400 802								
27-32-17-900-801-01		LH STICK PUSHER ACTUATOR					Component	ATA:27
PN:GH582-3005-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:80166	HRS	0		TSN 0				
WC#: 27.470	AFL	0		TSN 0				
PROC. REF: AMM 27 32 17 000 801, AMM 27 32 17 400 801PROC. REF: AMM 27 32 17 000 801, AMM 27 32 17 400 801								
27-32-17-900-801-02		RH STICK PUSHER ACTUATOR					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.470	AFL	0		TSN 0				
PROC. REF: AMM 27 32 17 000 801, AMM 27 32 17 400 801PROC. REF: AMM 27 32 17 000 801, AMM 27 32 17 400 801								
27-32-21-900-801-01		ASSY CAPSTAN					Component	ATA:27
PN:GH582-3006-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:80167	HRS	0		TSN 0				
WC#: 27.475	AFL	0		TSN 0				
PROC. REF: AMM 27 32 21 000 801, AMM 27 32 21 400 801PROC. REF: AMM 27 32 21 000 801, AMM 27 32 21 400 801								
27-33-01-900-801-01		LH ELEVATOR ROD CONTROL					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-33-01-900-801-02	RH ELEVATOR ROD CONTROL							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-33-01-900-802-01	LH PITCH WHEEL SIMULATOR							Component ATA:27
PN:GC415-3490-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:739	HRS	0		TSN 0				
WC#: 27.485	AFL	0		TSN 0				
PROC. REF: AMM 27 33 01 000 801, AMM 27 33 01 400 801PROC. REF: AMM 27 33 01 000 801, AMM 27 33 01 400 801								
27-33-01-900-802-02	RH PITCH WHEEL SIMULATOR							Component ATA:27
PN:GC415-3490-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:748	HRS	0		TSN 0				
WC#: 27.485	AFL	0		TSN 0				
PROC. REF: AMM 27 33 01 000 801, AMM 27 33 01 400 801PROC. REF: AMM 27 33 01 000 801, AMM 27 33 01 400 801								
27-33-05-900-801-01	LEFT PITCH FEEL TRIM ACTUATOR							Component ATA:27
PN:GT412-1500-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2907	HRS	0		TSN 0				
WC#: 27.490	AFL	0		TSN 0				
PROC. REF: AMM 27 33 05 000 801, AMM 27 33 05 400 801PROC. REF: AMM 27 33 05 000 801, AMM 27 33 05 400 801								
27-33-05-900-801-02	RIGHT PITCH FEEL TRIM ACTUATOR							Component ATA:27
PN:GT412-1500-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2903	HRS	0		TSN 0				
WC#: 27.490	AFL	0		TSN 0				
PROC. REF: AMM 27 33 05 000 801, AMM 27 33 05 400 801PROC. REF: AMM 27 33 05 000 801, AMM 27 33 05 400 801								
27-41-00-201	LUBRICATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR							Service ATA:27
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	
	HRS	3168:27	500 (+50/-50)	Adj 50	3718:27	3768:27	272:31 (+50)	
	AFL	1205						
PROC. REF: AMM 12 22 00 640 812PROC. REF: AMM 12 22 00 640 812								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-41-00-202	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.130	AFL	745						
PROC. REF: AMM 27 41 09 220 802PROC. REF: AMM 27 41 09 220 802								
27-41-01-900-801-01	PILOT CONTROL WHEEL							Component ATA:27
PN:GC415-1100-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0217	HRS	0		TSN 0				
WC#: 27.495	AFL	0		TSN 0				
PROC. REF: AMM 27 41 01 000 801, AMM 27 41 01 400 801PROC. REF: AMM 27 41 01 000 801, AMM 27 41 01 400 801								
27-41-01-900-801-02	COPILOT CONTROL WHEEL							Component ATA:27
PN:GC415-1100-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0213	HRS	0		TSN 0				
WC#: 27.495	AFL	0		TSN 0				
PROC. REF: AMM 27 41 01 000 801, AMM 27 41 01 400 801PROC. REF: AMM 27 41 01 000 801, AMM 27 41 01 400 801								
27-41-09-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (EXCLUDING AIRCRAFT ATTACHMENT PINS)							Service ATA:27
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 27.135	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 27 41 09 280 801PROC. REF: AMM 27 41 09 280 801								
27-41-09-103	DETAILED INSPECTION OF PITCH TRIM ACTUATOR (CMR*)							Service ATA:27
	MOS	15-Oct-24						CMR
	HRS	3314:03	500		3814:03		368:07	
WC#: 27.140	AFL	1328						
PROC. REF: AMM 27 41 09 220 801PROC. REF: AMM 27 41 09 220 801								
27-41-09-106	RESTORATION PITCH TRIM ACTUATOR OF THE (GEAR HOUSING REPLACEMENT), PART NO. GT412-4001-5							Service ATA:27
PN:GT412-4001-7	MOS/MSC	01-Jan-09	N/A					
SN:0389	HRS							
WC#: 27.145	AFL							
PROC. REF: AMM 27 41 29 610 801PROC. REF: AMM 27 41 29 610 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-41-09-107	RESTORATION OF THE PITCH TRIM ACTUATOR, PART NO. GT412-4001-7							Service ATA:27
PN:GT412-4001-7	MOS	30-Jul-09						RESTORE
SN:0389	HRS	0						
	AFL	0	7500		7500		6111	
PROC. REF: AMM 27 41 09 840 801PROC. REF: AMM 27 41 09 840 801								
27-41-09-900-801-01	PITCH TRIM ACTUATOR							Component ATA:27
PN:GT412-4001-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0389	HRS	0		TSN 0				
WC#: 27.500	AFL	0		TSN 0				
PROC. REF: AMM 27 41 09 000 801, AMM 27 41 09 400 801PROC. REF: AMM 27 41 09 000 801, AMM 27 41 09 400 801								
27-41-17-900-801-01	DRIVE UNIT - HORIZONTAL STAB MOTOR							Component ATA:27
PN:GT415-4002-11	MOS/MSC	05-Feb-16	O/C	TSR 12				
SN:2025	HRS	1866:41		TSR 0				
WC#: 27.505	AFL	571		TSR 0				
PROC. REF: AMM 27 41 17 000 801, AMM 27 41 17 400 801PROC. REF: AMM 27 41 17 000 801, AMM 27 41 17 400 801								
27-50-00-201	LUBRICATION OF THE FLAP DRIVE TORQUE-TUBE SPLINES							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.150	AFL	745						
PROC. REF: AMM 12 22 00 640 827PROC. REF: AMM 12 22 00 640 827								
27-50-00-202	LUBRICATION OF THE SLAT DRIVE TORQUE-TUBE SPLINES							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.155	AFL	745						
PROC. REF: AMM 12 22 00 640 828PROC. REF: AMM 12 22 00 640 828								
27-50-00-203	LUBRICATION OF THE FLAP ACTUATOR BALLSCREWS AND BALLNUTS							Service ATA:27
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	MRB
	HRS	3168:27						
WC#: 27.160	AFL	1205						
PROC. REF: AMM 12 22 00 640 829PROC. REF: AMM 12 22 00 640 829								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-00-204	LUBRICATION OF THE SLAT ACTUATOR BALLSCREWS							Service ATA:27
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	MRB
	HRS	3168:27						
WC#: 27.165	AFL	1205						
PROC. REF: AMM 12 22 00 640 830PROC. REF: AMM 12 22 00 640 830								
27-50-00-205	LUBRICATION OF THE FLAP ROLLERS							Service ATA:27
	MOS	18-Feb-22	60 (+3m/-3m)		18-Feb-27 (M)	18-May-27	721 d (+89)	MRIP
	HRS	2452:23	1500 (+50/-50)	Adj 50	4002:23	4052:23	556:27 (+50)	
WC#: 27.170	AFL	753						
PROC. REF: AMM 12 22 00 640 831PROC. REF: AMM 12 22 00 640 831								
27-50-00-206	LUBRICATION OF THE SLAT ROLLERS							Service ATA:27
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 27.175	AFL	745						
PROC. REF: AMM 12 22 00 640 832PROC. REF: AMM 12 22 00 640 832								
27-50-00-207	LUBRICATION OF THE FLAP SKEW SENSOR NO. 1 (A/C 9001 AND SUBS), AND FLAP SKEW SENSORS NO. 2, 3 AND 4, (A/C 9128 TO 9178, PRE SB 700-1A11-27-006)							Service ATA:27
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 27.180	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 12 22 00 640 835PROC. REF: AMM 12 22 00 640 835								
27-51-01-900-801-01	FLAP/SLAT LEVER							Component ATA:27
PN:GT415-5600-5	MOS/MSC	03-Dec-10	O/C	TSR 0				
SN:D0144	HRS	92:17		TSR 0				
WC#: 27.510	AFL	32		TSR 0				
PROC. REF: AMM 27 51 01 000 801, AMM 27 51 01 400 801PROC. REF: AMM 27 51 01 000 801, AMM 27 51 01 400 801								
27-51-05-900-801-01	LH SFCU FAN							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.515	AFL	0		TSN 0				
PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-05-900-801-02	RH SFCU FAN							Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.515	AFL	0		TSN 0				
PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801								
27-51-05-900-802-01	LH FLAP/SLAT CONTROL UNIT							Component ATA:27
PN:GT415-5900-17	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1381	HRS	0		TSN 0				
WC#: 27.520	AFL	0		TSN 0				
PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801								
27-51-05-900-802-02	RH FLAP/SLAT CONTROL UNIT							Component ATA:27
PN:GT415-5900-17	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1389	HRS	0		TSN 0				
WC#: 27.520	AFL	0		TSN 0				
PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801PROC. REF: AMM 27 51 05 000 801, AMM 27 51 05 400 801								
27-52-01-900-801-01	LEFT MLG WHEEL WELL FLAP TORQUE TUBE							Component ATA:27
PN:GT415-5201-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2701	HRS	0		TSN 0				
WC#: 27.525	AFL	0		TSN 0				
PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801								
27-52-01-900-801-02	LIB FLAP TORQUE TUBE							Component ATA:27
PN:GT415-5201-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2942	HRS	0		TSN 0				
WC#: 27.530	AFL	0		TSN 0				
PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801								
27-52-01-900-801-03	RIB FLAP TORQUE TUBE							Component ATA:27
PN:GT415-5201-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2944	HRS	0		TSN 0				
WC#: 27.530	AFL	0		TSN 0				
PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801PROC. REF: AMM 27 52 01 000 801, AMM 27 52 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-52-09-900-801-01		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5002-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2862	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-801-02		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5002-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2857	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-801-03		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5005-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2827	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-801-04		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5004-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2826	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-801-05		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5006-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2851	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-801-06		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5006-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2839	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-52-09-900-801-07		FLAP ACTUATOR					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-801-08		FLAP ACTUATOR					Component	ATA:27
PN:GT412-5008-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2813	HRS	0		TSN 0				
WC#: 27.540	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-01		LEFT NO.1 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-02		LEFT NO.2 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-03		LEFT NO.3 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-04		LEFT NO.4 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:GT412-5011-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4211	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-52-09-900-802-05		RIGHT NO.1 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-06		RIGHT NO.2 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:GT412-5008-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2836	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-07		RIGHT NO.3 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-09-900-802-08		RIGHT NO.4 FLAP ACTUATOR GEARBOX					Component	ATA:27
PN:GT412-5011-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4237	HRS	0		TSN 0				
WC#: 27.535	AFL	0		TSN 0				
PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801PROC. REF: AMM 27 52 09 000 801, AMM 27 52 09 400 801								
27-52-13-900-801-01		FLAP LH WS131.500 T/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5101-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3680	HRS	0		TSN 0				
WC#: 27.545	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-13-900-801-02		FLAP LH WS199.000 T/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5101-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3685	HRS	0		TSN 0				
WC#: 27.545	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-52-13-900-801-03 FLAP RH WS131.500 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5101-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3165	HRS	0		TSN 0				
WC#: 27.545	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-13-900-801-04 FLAP RH WS199.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5101-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3681	HRS	0		TSN 0				
WC#: 27.545	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-21-900-801-01 LH INBOARD FLAP								Component ATA:27
PN:KGC991-1556-27	MOS/MSC	05-Feb-21	O/C	TSN 139				
SN:0362	HRS	2444:24		TSN 2444:24				
WC#: 57.725	AFL	745		TSN 745				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-21-900-801-02 RH INBOARD FLAP								Component ATA:27
PN:KGC991-1556-28	MOS/MSC	05-Feb-21	O/C					
SN:353	HRS	2444:24						
WC#: 57.725	AFL	745						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-25-900-801-01 LH MIDDLE FLAP								Component ATA:27
PN:GM148-1002-29	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0361	HRS	0		TSN 0				
WC#: 57.725	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-25-900-801-02 RH MIDDLE FLAP								Component ATA:27
PN:GM148-1002-30	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0359	HRS	0		TSN 0				
WC#: 57.725	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-52-29-900-801-01		LH OUTBOARD FLAP					Component	ATA:27
PN:GM148-1003-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0361	HRS	0		TSN 0				
WC#: 57.725	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-29-900-801-02		RH OUTBOARD FLAP					Component	ATA:27
PN:GM148-1003-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0359	HRS	0		TSN 0				
WC#: 57.725	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
27-52-49-900-801-01		LEFT FLAP FLAP/SLAT RESOLVER					Component	ATA:27
PN:GT415-5300-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1728	HRS	0		TSN 0				
WC#: 27.550	AFL	0		TSN 0				
PROC. REF: AMM 27 52 49 000 801, AMM 27 52 49 400 801PROC. REF: AMM 27 52 49 000 801, AMM 27 52 49 400 801								
27-52-49-900-801-02		RIGHT FLAP FLAP/SLAT RESOLVER					Component	ATA:27
PN:GT415-5300-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1665	HRS	0		TSN 0				
WC#: 27.550	AFL	0		TSN 0				
PROC. REF: AMM 27 52 49 000 801, AMM 27 52 49 400 801PROC. REF: AMM 27 52 49 000 801, AMM 27 52 49 400 801								
27-52-53-900-801-01		LEFT FLAP ASSYMETRY BRAKE					Component	ATA:27
PN:GT415-5500-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2903	HRS	0		TSN 0				
WC#: 27.555	AFL	0		TSN 0				
PROC. REF: AMM 27 52 53 000 801, AMM 27 52 53 400 801PROC. REF: AMM 27 52 53 000 801, AMM 27 52 53 400 801								
27-52-53-900-801-02		RIGHT FLAP ASSYMETRY BRAKE					Component	ATA:27
PN:GT415-5500-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2900	HRS	0		TSN 0				
WC#: 27.555	AFL	0		TSN 0				
PROC. REF: AMM 27 52 53 000 801, AMM 27 52 53 400 801PROC. REF: AMM 27 52 53 000 801, AMM 27 52 53 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-52-57-101	DETAILED INSPECTION OF THE FLAP ROLLERS (CMR*)							Service ATA:27
	MOS	10-Mar-23						CMR
	HRS	2845:10	3000 (+50/-50)		5845:10	5895:10	2399:14 (+50)	
WC#: 27.185	AFL	999						
PROC. REF: AMM 27 52 57 220 801PROC. REF: AMM 27 52 57 220 801								
27-53-01-900-801-01	LH SLAT NO. 3 SLAT TORQUE TUBE							Component ATA:27
PN:GT415-5200-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2936	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-02	RIGHT SLAT NO. 3 SLAT TORQUE TUBE							Component ATA:27
PN:GT415-5200-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2922	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-03	LEFT SLAT NO.1 SLAT TORQUE TUBE							Component ATA:27
PN:GT415-5200-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2924	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-04	RIGHT SLAT NO. 1 SLAT TORQUE TUBE							Component ATA:27
PN:GT415-5200-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2925	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-05	LH SLAT NO. 4 SLAT TORQUE TUBE							Component ATA:27
PN:GT415-5200-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2939	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-900-801-06		RIGHT SLAT NO. 4 SLAT TORQUE TUBE					Component	ATA:27
PN:GT415-5200-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2937	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-07		LH SLAT NO. 1 TORQUE TUBE					Component	ATA:27
PN:GT415-5201-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2931	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-08		RH SLAT NO. 2 TORQUE TUBE					Component	ATA:27
PN:GT415-5201-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2925	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-09		LH SLAT NO. 1 TORQUE TUBE					Component	ATA:27
PN:GT415-5201-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2812	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-10		RH SLAT NO. 2 TORQUE TUBE					Component	ATA:27
PN:GT415-5201-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2926	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-01-900-801-11		LH SLAT NO. 1 TORQUE TUBE					Component	ATA:27
PN:GT415-5207-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2917	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-900-801-12	RH SLAT NO. 2 TORQUE TUBE							Component ATA:27
PN:GT415-5207-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2920	HRS	0		TSN 0				
WC#: 27.560	AFL	0		TSN 0				
PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801PROC. REF: AMM 27 53 01 000 801, AMM 27 53 01 400 801								
27-53-09-101	FUNCTIONAL TEST OF THE SLAT SYSTEM ACTUATORS (CMR**)							Service ATA:27
	MOS	10-Mar-23						CMR
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 27.190	AFL	999						
PROC. REF: AMM 27 53 09 720 804PROC. REF: AMM 27 53 09 720 804								
27-53-09-900-801-01	LEFT NO.1 SLAT ACTUATOR							Component ATA:27
PN:GT412-5601-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2845	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-02	RIGHT NO. 1 SLAT ACTUATOR							Component ATA:27
PN:GT412-5601-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2847	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-03	LEFT NO.2 SLAT ACTUATOR							Component ATA:27
PN:GT412-5602-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2851	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-04	RIGHT NO. 2 SLAT ACTUATOR							Component ATA:27
PN:GT412-5602-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2836	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-09-900-801-05		LEFT NO.3 SLAT ACTUATOR						Component ATA:27
PN:GT412-5603-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2863	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-06		RIGHT NO. 3 SLAT ACTUATOR						Component ATA:27
PN:GT412-5603-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2853	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-07		LEFT NO.4 SLAT ACTUATOR						Component ATA:27
PN:GT412-5604-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2859	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-08		RIGHT NO. 4 SLAT ACTUATOR						Component ATA:27
PN:GT412-5604-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2806	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-09		LEFT NO.5 SLAT ACTUATOR						Component ATA:27
PN:GT412-5605-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2835	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-10		RIGHT NO. 5 SLAT ACTUATOR						Component ATA:27
PN:GT412-5605-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2855	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-09-900-801-11		LEFT NO.6 SLAT ACTUATOR					Component	ATA:27
PN:GT412-5606-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2838	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-12		RIGHT NO. 6 SLAT ACTUATOR					Component	ATA:27
PN:GT412-5606-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2841	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-13		LEFT NO.7 SLAT ACTUATOR					Component	ATA:27
PN:GT412-5607-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2679	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-14		RIGHT NO. 7 SLAT ACTUATOR					Component	ATA:27
PN:GT412-5607-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2857	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-15		LEFT NO.8 SLAT ACTUATOR					Component	ATA:27
PN:GT412-5609-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2821	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								
27-53-09-900-801-16		RIGHT NO. 8 SLAT ACTUATOR					Component	ATA:27
PN:GT412-5608-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2829	HRS	0		TSN 0				
WC#: 27.565	AFL	0		TSN 0				
PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801PROC. REF: AMM 27 53 09 000 801, AMM 27 53 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-13-900-801-01 FLAP LH WS163.416 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5416	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-02 FLAP LH WS250.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5460	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-03 FLAP LH WS420.911 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6183	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-04 FLAP RH WS163.416 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6195	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-05 FLAP RH WS250.000 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6203	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-06 FLAP RH WS420.911 T/E DRIVE SHAFT RETAIN BEARING								Component ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6227	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-13-900-801-07		SLAT LH WS92.954 L/EDRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5448	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-08		SLAT LH WS265.000 L/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5575	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-09		SLAT LH WS391.000 L/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6207	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-10		SLAT RH WS92.954 L/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5504	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-11		SLAT RH WS265.000 L/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5568	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								
27-53-13-900-801-12		SLAT RH WS391.000 L/E DRIVE SHAFT RETAIN BEARING					Component	ATA:27
PN:GT415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6090	HRS	0		TSN 0				
WC#: 27.570	AFL	0		TSN 0				
PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801PROC. REF: AMM 27 53 13 000 801, AMM 27 53 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-17-900-801-01		LH NO.1 SLAT					Component	ATA:27
PN:GM128-1011-21	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0199	HRS	0		TSN 0				
WC#: 27.575	AFL	0		TSN 0				
PROC. REF: AMM 27 53 17 000 801, AMM 27 53 17 400 801PROC. REF: AMM 27 53 17 000 801, AMM 27 53 17 400 801								
27-53-17-900-801-02		RH NO.1 SLAT					Component	ATA:27
PN:GM128-1011-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0199	HRS	0		TSN 0				
WC#: 27.575	AFL	0		TSN 0				
PROC. REF: AMM 27 53 17 000 801, AMM 27 53 17 400 801PROC. REF: AMM 27 53 17 000 801, AMM 27 53 17 400 801								
27-53-21-900-801-01		LH NO.2 SLAT					Component	ATA:27
PN:GM128-1012-17	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0204	HRS	0		TSN 0				
WC#: 27.580	AFL	0		TSN 0				
PROC. REF: AMM 27 53 21 000 801, AMM 27 53 21 400 801PROC. REF: AMM 27 53 21 000 801, AMM 27 53 21 400 801								
27-53-21-900-801-02		RH NO.2 SLAT					Component	ATA:27
PN:GM128-1012-18	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0204	HRS	0		TSN 0				
WC#: 27.580	AFL	0		TSN 0				
PROC. REF: AMM 27 53 21 000 801, AMM 27 53 21 400 801PROC. REF: AMM 27 53 21 000 801, AMM 27 53 21 400 801								
27-53-25-900-801-01		LH NO.3 SLAT					Component	ATA:27
PN:GM128-1013-15	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0205	HRS	0		TSN 0				
WC#: 27.585	AFL	0		TSN 0				
PROC. REF: AMM 27 53 25 000 801, AMM 27 53 25 400 801PROC. REF: AMM 27 53 25 000 801, AMM 27 53 25 400 801								
27-53-25-900-801-02		RH NO.3 SLAT					Component	ATA:27
PN:GM128-1013-16	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0203	HRS	0		TSN 0				
WC#: 27.585	AFL	0		TSN 0				
PROC. REF: AMM 27 53 25 000 801, AMM 27 53 25 400 801PROC. REF: AMM 27 53 25 000 801, AMM 27 53 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-29-900-801-01		LH NO.4 SLAT					Component	ATA:27
PN:GM128-1014-23	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB0205	HRS	0		TSN 0				
WC#: 27.595	AFL	0		TSN 0				
PROC. REF: AMM 27 53 29 000 801, AMM 27 53 29 400 801PROC. REF: AMM 27 53 29 000 801, AMM 27 53 29 400 801								
27-53-29-900-801-02		RH NO.4 SLAT					Component	ATA:27
PN:GM128-1014-24	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB02010	HRS	0		TSN 0				
WC#: 27.595	AFL	0		TSN 0				
PROC. REF: AMM 27 53 29 000 801, AMM 27 53 29 400 801PROC. REF: AMM 27 53 29 000 801, AMM 27 53 29 400 801								
27-53-33-900-801-01		SLAT FLAP/SLAT PDU					Component	ATA:27
PN:GT415-5001-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2826	HRS	0		TSN 0				
WC#: 27.600	AFL	0		TSN 0				
PROC. REF: AMM 27 53 33 000 801, AMM 27 53 33 400 801PROC. REF: AMM 27 53 33 000 801, AMM 27 53 33 400 801								
27-53-33-900-801-02		FLAP FLAP/SLAT PDU					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.600	AFL	0		TSN 0				
PROC. REF: AMM 27 53 33 000 801, AMM 27 53 33 400 801PROC. REF: AMM 27 53 33 000 801, AMM 27 53 33 400 801								
27-53-37-900-801-01		LH ELECTRICAL SLAT/FLAP PDU MOTOR					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.590	AFL	0		TSN 0				
PROC. REF: AMM 27 53 37 000 801, AMM 27 53 37 400 801PROC. REF: AMM 27 53 37 000 801, AMM 27 53 37 400 801								
27-53-37-900-801-02		RH ELECTRICAL SLAT/FLAP PDU MOTOR					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.590	AFL	0		TSN 0				
PROC. REF: AMM 27 53 37 000 801, AMM 27 53 37 400 801PROC. REF: AMM 27 53 37 000 801, AMM 27 53 37 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-41-900-801-01		LEFT SLAT FLAP/SLAT RESOLVER						Component ATA:27
PN:GT415-5300-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1646	HRS	0		TSN 0				
WC#: 27.605	AFL	0		TSN 0				
PROC. REF: AMM 27 53 41 000 801, AMM 27 53 41 400 801PROC. REF: AMM 27 53 41 000 801, AMM 27 53 41 400 801								
27-53-41-900-801-02		RIGHT SLAT FLAP/SLAT RESOLVER						Component ATA:27
PN:GT415-5300-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B1724	HRS	0		TSN 0				
WC#: 27.605	AFL	0		TSN 0				
PROC. REF: AMM 27 53 41 000 801, AMM 27 53 41 400 801PROC. REF: AMM 27 53 41 000 801, AMM 27 53 41 400 801								
27-53-45-900-801-01		LEFT SLAT ASSYMETRY BRAKE						Component ATA:27
PN:GT415-5500-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2893	HRS	0		TSN 0				
WC#: 27.610	AFL	0		TSN 0				
PROC. REF: AMM 27 53 45 000 801, AMM 27 53 45 400 801PROC. REF: AMM 27 53 45 000 801, AMM 27 53 45 400 801								
27-53-45-900-801-02		RIGHT SLAT ASSYMETRY BRAKE						Component ATA:27
PN:GT415-5500-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2901	HRS	0		TSN 0				
WC#: 27.610	AFL	0		TSN 0				
PROC. REF: AMM 27 53 45 000 801, AMM 27 53 45 400 801PROC. REF: AMM 27 53 45 000 801, AMM 27 53 45 400 801								
27-60-00-101		OPERATIONAL TEST OF THE SPOILER POWER-CONTROL UNITS (PCU) (CMR**)						Service ATA:27
	MOS	21-Jul-21						CMR
	HRS	2446:06	1500 (+50/-50)		3946:06	3996:06	500:10 (+50)	
WC#: 27.195	AFL	747						
PROC. REF: AMM 27 60 00 710 801PROC. REF: AMM 27 60 00 710 801								
27-61-01-900-801-01		FLIGHT SPOILER CONTROL LEVER (FS235 WL89 LBL2)						Component ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.615	AFL	0		TSN 0				
PROC. REF: AMM 27 61 01 000 801, AMM 27 61 01 400 801PROC. REF: AMM 27 61 01 000 801, AMM 27 61 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-61-05-201	OPERATIONAL TEST OF THE FLIGHT-CONTROL UNIT (FCU) BACK-UP MODULES							Service ATA:27
	MOS	10-Mar-23	180 (+3m/-3m)	Adj 3	10-Jun-38	10-Sep-38	4851 d (+92)	MRIP
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 27.200	AFL	999						
PROC. REF: AMM 27 61 05 710 801PROC. REF: AMM 27 61 05 710 801								
27-61-05-900-801-01	NO. 1 FLIGHT CONTROL UNIT FCU							Component ATA:27
PN:GT415-0100-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1085	HRS	0		TSN 0				
WC#: 27.620	AFL	0		TSN 0				
PROC. REF: AMM 27 61 05 000 801, AMM 27 61 05 400 801PROC. REF: AMM 27 61 05 000 801, AMM 27 61 05 400 801								
27-61-05-900-801-02	NO. 2 FLIGHT CONTROL UNIT FCU							Component ATA:27
PN:GT415-0100-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1097	HRS	0		TSN 0				
WC#: 27.620	AFL	0		TSN 0				
PROC. REF: AMM 27 61 05 000 801, AMM 27 61 05 400 801PROC. REF: AMM 27 61 05 000 801, AMM 27 61 05 400 801								
27-62-01-900-801-01	LOB MULTIFUNCTION SPOILER PCU							Component ATA:27
PN:GT411-6001-9	MOS/MSC	10-Mar-23	O/C	TSR 0				
SN:4345C	HRS	2845:10		TSR 0				
WC#: 27.625	AFL	999		TSR 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-01-900-801-02	LOB MULTIFUNCTION FLIGHT SPOILER PCU							Component ATA:27
PN:GT411-6001-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3016A	HRS	0		TSN 0				
WC#: 27.625	AFL	0		TSN 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-01-900-801-03	LIB MULTIFUNCTION SPOILER PCU							Component ATA:27
PN:GT411-6001-9	MOS/MSC	10-Mar-23	O/C	TSR 0				
SN:7662C	HRS	2845:10		TSR 0				
WC#: 27.625	AFL	999		TSR 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-62-01-900-801-04		LIB MULTIFUNCTION FLIGHT SPOILER PCU					Component	ATA:27
PN:GT411-6001-9	MOS/MSC	18-Dec-12	O/C	TSR 3				
SN:3180A	HRS	877:15		TSN 165, TSR 0				
WC#: 27.625	AFL	311		TSN 128, TSR 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-01-900-801-05		RIB MULTIFUNCTION SPOILER PCU					Component	ATA:27
PN:GT411-6001-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3027A	HRS	0		TSN 0				
WC#: 27.630	AFL	0		TSN 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-01-900-801-06		RIB MULTIFUNCTION FLIGHT SPOILER PCU					Component	ATA:27
PN:GT411-6001-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3042AB	HRS	0		TSN 0				
WC#: 27.630	AFL	0		TSN 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-01-900-801-07		ROB MULTIFUNCTION SPOILER PCU					Component	ATA:27
PN:GT411-6001-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3038A	HRS	0		TSN 0				
WC#: 27.630	AFL	0		TSN 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-01-900-801-08		ROB MULTIFUNCTION FLIGHT SPOILER PCU					Component	ATA:27
PN:376300-1009	MOS/MSC	16-Oct-14	O/C	TSR 10				
SN:3486C	HRS	1486:57		TSR 0				
WC#: 27.630	AFL	457		TSR 0				
PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801PROC. REF: AMM 27 62 01 000 801, AMM 27 62 01 400 801								
27-62-09-900-801-01		LOB FLIGHT SPOILER					Component	ATA:27
PN:GM168-1500-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0360	HRS	0		TSN 0				
WC#: 27.635	AFL	0		TSN 0				
PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-62-09-900-801-02		LIB FLIGHT SPOILER					Component	ATA:27
PN:GM168-1400-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0361	HRS	0		TSN 0				
WC#: 27.635	AFL	0		TSN 0				
PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801								
27-62-09-900-801-03		RIB FLIGHT SPOILER					Component	ATA:27
PN:GM168-1400-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0362	HRS	0		TSN 0				
WC#: 27.635	AFL	0		TSN 0				
PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801								
27-62-09-900-801-04		ROB FLIGHT SPOILER					Component	ATA:27
PN:GM168-1500-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0360	HRS	0		TSN 0				
WC#: 27.635	AFL	0		TSN 0				
PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801PROC. REF: AMM 27 62 09 000 801, AMM 27 62 09 400 801								
27-63-01-900-801-01		INBOARD SELECTOR, GROUND SPOILER VALVE					Component	ATA:27
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.640	AFL	0		TSN 0				
PROC. REF: AMM 27 63 01 000 801, AMM 27 63 01 400 801PROC. REF: AMM 27 63 01 000 801, AMM 27 63 01 400 801								
27-63-01-900-801-02		OUTBOARD SELECTOR, GROUND SPOILER VALVE					Component	ATA:27
PN:GT411-6003-3	MOS/MSC	30-Jul-21	O/C					
SN:0279	HRS	2447:29						
WC#: 27.640	AFL	748						
PROC. REF: AMM 27 63 01 000 801, AMM 27 63 01 400 801PROC. REF: AMM 27 63 01 000 801, AMM 27 63 01 400 801								
27-63-05-900-801-01		LOB GROUND SPOILER ACTUATOR					Component	ATA:27
PN:GT411-6002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1516	HRS	0		TSN 0				
WC#: 27.645	AFL	0		TSN 0				
PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-63-05-900-801-02	LIB GROUND SPOILER ACTUATOR							Component ATA:27
PN:GT411-6002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1514	HRS	0		TSN 0				
WC#: 27.645	AFL	0		TSN 0				
PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801								
27-63-05-900-801-03	RIB GROUND SPOILER ACTUATOR							Component ATA:27
PN:GT411-6002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1526	HRS	0		TSN 0				
WC#: 27.645	AFL	0		TSN 0				
PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801								
27-63-05-900-801-04	ROB GROUND SPOILER ACTUATOR							Component ATA:27
PN:GT411-6002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1528	HRS	0		TSN 0				
WC#: 27.645	AFL	0		TSN 0				
PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801PROC. REF: AMM 27 63 05 000 801, AMM 27 63 05 400 801								
ATA 28 - FUEL								
28-10-00-201	DETAILED INSPECTION OF THE VENT TUBING VAPOR-BARRIER COATING							Service ATA:28
	MOS	05-Feb-21	180 (+3m/-3m)	05-Feb-36	05-May-36	3995 d (+90)	MRB	
	HRS	2444:24						
WC#: 28.005	AFL	745						
PROC. REF: AMM 28 10 00 220 801PROC. REF: AMM 28 10 00 220 801								
28-10-00-202	DETAILED INSPECTION OF THE CENTER-TANK VAPOR-BARRIER COATING							Service ATA:28
	MOS	05-Feb-21	120 (+3m/-3m)	05-Feb-31	05-May-31	2169 d (+89)	MRB	
	HRS	2444:24						
WC#: 28.010	AFL	745						
PROC. REF: AMM 28 10 00 220 802PROC. REF: AMM 28 10 00 220 802								
28-11-00-201	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL SURFACES							Service ATA:28
	MOS	21-Jul-21	60 (+3m/-3m)	21-Jul-26	21-Oct-26	509 d (+92)	MRIP	
	HRS	2446:06	1000 (+50/-50)	3446:06	3496:06	0:10 (+50)		
WC#: 28.015	AFL	747						
PROC. REF: AMM 28 11 00 210 802PROC. REF: AMM 28 11 00 210 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-00-202	GENERAL VISUAL INSPECTION OF THE WING-TANK EXTERNAL COMPONENTS							Service ATA:28
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 28.020	AFL	747						
PROC. REF: AMM 28 11 00 210 803PROC. REF: AMM 28 11 00 210 803								
28-11-01-900-801-01	LH LOWER PANEL, WING ACCESS DOOR							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 28 11 01 000 801, AMM 28 11 01 400 801PROC. REF: AMM 28 11 01 000 801, AMM 28 11 01 400 801								
28-11-01-900-801-02	RH LOWER PANEL, WING ACCESS DOOR							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: AMM 28 11 01 000 801, AMM 28 11 01 400 801PROC. REF: AMM 28 11 01 000 801, AMM 28 11 01 400 801								
28-11-05-201	DETAILED INSPECTION OF THE WATER DRAIN VALVES							Service ATA:28
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06						
WC#: 28.025	AFL	747						
PROC. REF: AMM 28 11 05 220 801PROC. REF: AMM 28 11 05 220 801								
28-11-05-900-801-01	LH (BL42.0 FSTA 640.4) WATER DRAIN VALVE							Component ATA:28
PN:GP422-1107-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1661	HRS	0		TSN 0				
WC#: 28.075	AFL	0		TSN 0				
PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801								
28-11-05-900-801-02	LH (WS52.5 LWR STR#10-#11) WATER DRAIN VALVE							Component ATA:28
PN:GP422-1107-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1740	HRS	0		TSN 0				
WC#: 28.075	AFL	0		TSN 0				
PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-05-900-801-03	RH (BL42.0 FSTA 634.00) WATER DRAIN VALVE							Component ATA:28
PN:GP422-1107-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1821	HRS	0		TSN 0				
WC#: 28.075	AFL	0		TSN 0				
PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801								
28-11-05-900-801-04	RH (WS52.5 LWR STR#10-#11) WATER DRAIN VALVE							Component ATA:28
PN:GP422-1107-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1733	HRS	0		TSN 0				
WC#: 28.075	AFL	0		TSN 0				
PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801								
28-11-05-900-802-01	AFT DRAIN TANK VALVE							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801PROC. REF: AMM 28 11 05 000 801, AMM 28 11 05 400 801								
28-11-09-900-801-01	LH WING TANK PRESSURE RELIEF VALVE							Component ATA:28
PN:GP422-1109-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1103	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801								
28-11-09-900-801-02	RH WING TANK PRESSURE RELIEF VALVE							Component ATA:28
PN:GP422-1109-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1104	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801								
28-11-09-900-801-03	CENTER TANK PRESSURE RELIEF VALVE							Component ATA:28
PN:GP422-1109-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1076	HRS	0		TSN 0				
WC#: 28.085	AFL	0		TSN 0				
PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-09-900-801-04		AFT TANK PRESSURE RELIEF VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.105	AFL	0		TSN 0				
PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801PROC. REF: AMM 28 11 09 000 801, AMM 28 11 09 400 801								
28-11-25-900-801-01		LEFT GRAVITY FILL CAP					Component	ATA:28
PN:GP425-1104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1320	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801								
28-11-25-900-801-02		RIGHT FORWARD GRAVITY FILL CAP					Component	ATA:28
PN:GP425-1104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1327	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801								
28-11-25-900-801-03		RIGHT AFT GRAVITY FILL CAP					Component	ATA:28
PN:GP425-1104-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1316	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801PROC. REF: AMM 28 11 25 000 801, AMM 28 11 25 400 801								
28-11-29-900-801-01		LH WING TANK GRAVITY FILL ADAPTER					Component	ATA:28
PN:GP425-1105-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0845	HRS	0		TSN 0				
WC#: 28.095	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-11-29-900-801-02		CENTER WING TANK GRAVITY FILL ADAPTER					Component	ATA:28
PN:GP425-1105-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0846	HRS	0		TSN 0				
WC#: 28.095	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-11-29-900-801-03	RH WING TANK GRAVITY FILL ADAPTER							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-12-13-900-801-01	LH FLEXIBLE, AUXILIARY TANK FUEL CELL							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.115	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-12-13-900-801-02	RH FLEXIBLE, AUXILIARY TANK FUEL CELL							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.115	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-13-00-201	FUNCTIONAL TEST OF THE FUEL VENT TUBING							Service ATA:28
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 28.030	AFL	745						
PROC. REF: AMM 28 13 00 720 801PROC. REF: AMM 28 13 00 720 801								
28-13-00-202	OPERATIONAL TEST OF THE VENT SYSTEM							Service ATA:28
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 28.035	AFL	747						
PROC. REF: AMM 28 13 00 710 801PROC. REF: AMM 28 13 00 710 801								
28-13-05-900-801-01	LH SURGE BOX							Component ATA:28
PN:GC426-0101-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:GSC0150-08	HRS	0		TSN 0				
WC#: 28.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-13-05-900-801-02	RH SURGE BOX							Component ATA:28
PN:GC426-0101-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:GSC0150-08	HRS	0		TSN 0				
WC#: 28.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-20-01-900-801-01	COCKPIT OVERHEAD FUEL CONTROL PANEL							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.130	AFL	0		TSN 0				
PROC. REF: AMM 28 20 01 000 801, AMM 28 20 01 400 801PROC. REF: AMM 28 20 01 000 801, AMM 28 20 01 400 801								
28-21-00-201	FUNCTIONAL TEST OF THE FUEL-FEED TUBING SHROUDS							Service ATA:28
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 28.040	AFL	745						
PROC. REF: AMM 28 21 00 720 801PROC. REF: AMM 28 21 00 720 801								
28-21-00-202	VISUAL CHECK OF THE SHROUD DRAINS							Service ATA:28
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 28.045	AFL	747						
PROC. REF: AMM 28 21 00 210 801PROC. REF: AMM 28 21 00 210 801								
28-21-01-900-801-01	LEFT FORWARD AC BOOST PUMP CARTRIDGE							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.135	AFL	0		TSN 0				
PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801								
28-21-01-900-801-02	RIGHT FORWARD AC BOOST PUMP CARTRIDGE							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.135	AFL	0		TSN 0				
PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-01-900-801-03		LEFT AFT AC BOOST PUMP CARTRIDGE						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.135	AFL	0		TSN 0				
PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801								
28-21-01-900-801-04		RIGHT AFT AC BOOST PUMP CARTRIDGE						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.135	AFL	0		TSN 0				
PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801PROC. REF: AMM 28 21 01 000 801, AMM 28 21 01 400 801								
28-21-05-900-801-01		LEFT FORWARD AC BOOST PUMP CANISTER						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801								
28-21-05-900-801-02		LEFT AFT AC BOOST PUMP CANISTER						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801								
28-21-05-900-801-03		RIGHT FORWARD AC BOOST PUMP CANISTER						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801								
28-21-05-900-801-04		RIGHT AFT AC BOOST PUMP CANISTER						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801PROC. REF: AMM 28 21 05 000 801, AMM 28 21 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-09-900-801-01		LOB PRESSURE SWITCH						Component ATA:28
PN:GP422-1306-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2530	HRS	0		TSN 0				
WC#: 28.145	AFL	0		TSN 0				
PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801								
28-21-09-900-801-02		LIB PRESSURE SWITCH						Component ATA:28
PN:GP422-1306-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2526	HRS	0		TSN 0				
WC#: 28.145	AFL	0		TSN 0				
PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801								
28-21-09-900-801-03		RIB PRESSURE SWITCH						Component ATA:28
PN:GP422-1306-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2536	HRS	0		TSN 0				
WC#: 28.145	AFL	0		TSN 0				
PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801								
28-21-09-900-801-04		ROB PRESSURE SWITCH						Component ATA:28
PN:GP422-1306-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2525	HRS	0		TSN 0				
WC#: 28.145	AFL	0		TSN 0				
PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801PROC. REF: AMM 28 21 09 000 801, AMM 28 21 09 400 801								
28-21-13-900-801-01		LH DC AUXILIARY PUMP ASSY						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.150	AFL	0		TSN 0				
PROC. REF: AMM 28 21 13 000 801, AMM 28 21 13 400 801PROC. REF: AMM 28 21 13 000 801, AMM 28 21 13 400 801								
28-21-13-900-801-02		RH DC AUXILIARY PUMP ASSY						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.150	AFL	0		TSN 0				
PROC. REF: AMM 28 21 13 000 801, AMM 28 21 13 400 801PROC. REF: AMM 28 21 13 000 801, AMM 28 21 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-21-900-801-01	LH CENTER TRANSFER - DC AUX PRESSURE SWITCH							Component ATA:28
PN:GP422-1306-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2213	HRS	0		TSN 0				
WC#: 28.155	AFL	0		TSN 0				
PROC. REF: AMM 28 21 21 000 801, AMM 28 21 21 400 801PROC. REF: AMM 28 21 21 000 801, AMM 28 21 21 400 801								
28-21-21-900-801-02	RH CENTER TRANSFER - DC AUX PRESSURE SWITCH							Component ATA:28
PN:GP422-1306-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2260	HRS	0		TSN 0				
WC#: 28.155	AFL	0		TSN 0				
PROC. REF: AMM 28 21 21 000 801, AMM 28 21 21 400 801PROC. REF: AMM 28 21 21 000 801, AMM 28 21 21 400 801								
28-21-25-900-801-01	LH EJECTOR VENT SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.160	AFL	0		TSN 0				
PROC. REF: AMM 28 21 25 000 801, AMM 28 21 25 400 801PROC. REF: AMM 28 21 25 000 801, AMM 28 21 25 400 801								
28-21-25-900-801-02	RH EJECTOR VENT SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.160	AFL	0		TSN 0				
PROC. REF: AMM 28 21 25 000 801, AMM 28 21 25 400 801PROC. REF: AMM 28 21 25 000 801, AMM 28 21 25 400 801								
28-21-29-201	OPERATIONAL (INTERNAL LEAK) TEST OF THE ENGINE FEED SHUTOFF-VALVES							Service ATA:28
	MOS	10-Mar-23	180 (+3m/-3m)	Adj 3	10-Jun-38	10-Sep-38	4851 d (+92)	MRIP
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 28.050	AFL	999						
PROC. REF: AMM 28 21 29 710 802PROC. REF: AMM 28 21 29 710 802								
28-21-29-900-801-01	LH ENGINE FEED SOV ACTUATOR							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.165	AFL	0		TSN 0				
PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-29-900-801-02		RH ENGINE FEED SOV ACTUATOR					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.165	AFL	0		TSN 0				
PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801								
28-21-29-900-802-01		LEFT ENGINE FEED SHUTOFF VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.170	AFL	0		TSN 0				
PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801								
28-21-29-900-802-02		RIGHT ENGINE FEED SHUTOFF VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.170	AFL	0		TSN 0				
PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801PROC. REF: AMM 28 21 29 000 801, AMM 28 21 29 400 801								
28-21-33-900-801-01		LH SHUT-OFF VALVE ACTUATOR					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.125	AFL	0		TSN 0				
PROC. REF: AMM 28 21 33 000 801, AMM 28 21 33 400 801PROC. REF: AMM 28 21 33 000 801, AMM 28 21 33 400 801								
28-21-33-900-801-02		RH SHUT-OFF VALVE ACTUATOR					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.125	AFL	0		TSN 0				
PROC. REF: AMM 28 21 33 000 801, AMM 28 21 33 400 801PROC. REF: AMM 28 21 33 000 801, AMM 28 21 33 400 801								
28-21-37-900-801-01		APU BODY VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.175	AFL	0		TSN 0				
PROC. REF: AMM 28 21 37 000 801, AMM 28 21 37 400 801PROC. REF: AMM 28 21 37 000 801, AMM 28 21 37 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-41-900-801-01		APU SHUT-OFF VALVE ACTUATOR					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.125	AFL	0		TSN 0				
PROC. REF: AMM 28 21 41 000 801, AMM 28 21 41 400 801PROC. REF: AMM 28 21 41 000 801, AMM 28 21 41 400 801								
28-21-45-900-801-01		LH SHUTOFF CROSSFEED VALVE					Component	ATA:28
PN:GP422-1412-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1122	HRS	0		TSN 0				
WC#: 28.180	AFL	0		TSN 0				
PROC. REF: AMM 28 21 45 000 801, AMM 28 21 45 400 801PROC. REF: AMM 28 21 45 000 801, AMM 28 21 45 400 801								
28-21-45-900-801-02		RH SHUTOFF CROSSFEED VALVE					Component	ATA:28
PN:GP422-1412-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1133	HRS	0		TSN 0				
WC#: 28.180	AFL	0		TSN 0				
PROC. REF: AMM 28 21 45 000 801, AMM 28 21 45 400 801PROC. REF: AMM 28 21 45 000 801, AMM 28 21 45 400 801								
28-21-53-900-801-01		LH CHECK FEED VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.185	AFL	0		TSN 0				
PROC. REF: AMM 28 21 53 000 801, AMM 28 21 53 400 801PROC. REF: AMM 28 21 53 000 801, AMM 28 21 53 400 801								
28-21-53-900-801-02		RH CHECK FEED VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.185	AFL	0		TSN 0				
PROC. REF: AMM 28 21 53 000 801, AMM 28 21 53 400 801PROC. REF: AMM 28 21 53 000 801, AMM 28 21 53 400 801								
28-21-57-900-801-01		LEFT CHECK FEED VALVE					Component	ATA:28
PN:GP422-1410-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1681	HRS	0		TSN 0				
WC#: 28.190	AFL	0		TSN 0				
PROC. REF: AMM 28 21 57 000 801, AMM 28 21 57 400 801PROC. REF: AMM 28 21 57 000 801, AMM 28 21 57 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-57-900-801-02		RIGHT CHECK FEED VALVE						Component ATA:28
PN:GP422-1410-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1682	HRS	0		TSN 0				
WC#: 28.190	AFL	0		TSN 0				
PROC. REF: AMM 28 21 57 000 801, AMM 28 21 57 400 801PROC. REF: AMM 28 21 57 000 801, AMM 28 21 57 400 801								
28-21-61-900-801-01		LH (FUEL FEED SYSTEM)CHECK DC AUX PUMP VALVE						Component ATA:28
PN:GP422-1405-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3356	HRS	0		TSN 0				
WC#: 28.195	AFL	0		TSN 0				
PROC. REF: AMM 28 21 61 000 801, AMM 28 21 61 400 801PROC. REF: AMM 28 21 61 000 801, AMM 28 21 61 400 801								
28-21-61-900-801-02		RH (FUEL FEED SYSTEM) CHECK DC AUX PUMP VALVE						Component ATA:28
PN:GP422-1405-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3358	HRS	0		TSN 0				
WC#: 28.195	AFL	0		TSN 0				
PROC. REF: AMM 28 21 61 000 801, AMM 28 21 61 400 801PROC. REF: AMM 28 21 61 000 801, AMM 28 21 61 400 801								
28-22-00-202		OPERATIONAL TEST OF THE WING TO WING MANUAL-TRANSFER SYSTEM						Service ATA:28
	MOS	21-Jul-21	180 (+3m/-3m)	21-Jul-36	21-Oct-36	4162 d (+92)	MRIP	
	HRS	2446:06	3000 (+50/-50)	5446:06	5496:06	2000:10 (+50)		
WC#: 28.055	AFL	747						
PROC. REF: AMM 28 22 00 710 801PROC. REF: AMM 28 22 00 710 801								
28-22-01-900-801-01		LH SHUTOFF WING TRANSFER VALVE						Component ATA:28
PN:GP422-1304-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0778	HRS	0		TSN 0				
WC#: 28.200	AFL	0		TSN 0				
PROC. REF: AMM 28 22 01 000 801, AMM 28 22 01 400 801PROC. REF: AMM 28 22 01 000 801, AMM 28 22 01 400 801								
28-22-01-900-801-02		RH SHUTOFF WING TRANSFER VALVE						Component ATA:28
PN:GP422-1304-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0776	HRS	0		TSN 0				
WC#: 28.200	AFL	0		TSN 0				
PROC. REF: AMM 28 22 01 000 801, AMM 28 22 01 400 801PROC. REF: AMM 28 22 01 000 801, AMM 28 22 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-05-900-801-01	LH AFT TANK TRANSFER PUMP ASSEMBLY							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-22-05-900-801-02	RH AFT TANK TRANSFER PUMP ASSEMBLY							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-22-05-900-801-03	AFT SHUT-OFF VALVE ACTUATOR							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.125	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-22-09-900-801-01	LH CENTER TRANSFER PUMP CARTRIDGE							Component ATA:28
PN:GP422-1307-11	MOS/MSC	04-Sep-15	O/C	TSN 4				
SN:4BK114	HRS	1792:10		TSN 0				
WC#: 28.205	AFL	551		TSN 0				
PROC. REF: AMM 28 22 09 000 801, AMM 28 22 09 400 801PROC. REF: AMM 28 22 09 000 801, AMM 28 22 09 400 801								
28-22-09-900-801-02	RH CENTER TRANSFER PUMP CARTRIDGE							Component ATA:28
PN:GP422-1307-11	MOS/MSC	04-Sep-15	O/C	TSN 4				
SN:4BK118	HRS	1792:10		TSN 0				
WC#: 28.205	AFL	551		TSN 0				
PROC. REF: AMM 28 22 09 000 801, AMM 28 22 09 400 801PROC. REF: AMM 28 22 09 000 801, AMM 28 22 09 400 801								
28-22-17-900-801-01	LH AC CENTER PRESSURE SWITCH							Component ATA:28
PN:GP422-1306-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2036	HRS	0		TSN 0				
WC#: 28.210	AFL	0		TSN 0				
PROC. REF: AMM 28 22 17 000 801, AMM 28 22 17 400 801PROC. REF: AMM 28 22 17 000 801, AMM 28 22 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-17-900-801-02		RH AC CENTER PRESSURE SWITCH						Component ATA:28
PN:GP422-1306-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2083	HRS	0		TSN 0				
WC#: 28.210	AFL	0		TSN 0				
PROC. REF: AMM 28 22 17 000 801, AMM 28 22 17 400 801PROC. REF: AMM 28 22 17 000 801, AMM 28 22 17 400 801								
28-22-21-900-801-01		LH CHECK CENTER TANK TRANSFER VALVE						Component ATA:28
PN:GP422-1305-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1007	HRS	0		TSN 0				
WC#: 28.215	AFL	0		TSN 0				
PROC. REF: AMM 28 22 21 000 801, AMM 28 22 21 400 801PROC. REF: AMM 28 22 21 000 801, AMM 28 22 21 400 801								
28-22-21-900-801-02		RH CHECK CENTER TANK TRANSFER VALVE						Component ATA:28
PN:GP422-1305-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1008	HRS	0		TSN 0				
WC#: 28.215	AFL	0		TSN 0				
PROC. REF: AMM 28 22 21 000 801, AMM 28 22 21 400 801PROC. REF: AMM 28 22 21 000 801, AMM 28 22 21 400 801								
28-22-33-900-801-01		S/O AFT TANK REFUEL VALVE						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.265	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-22-49-900-801-01		LOB FUEL TRANSFERT SYSTEM - DC AUX PUMP VALVE CHECK						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.220	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-22-49-900-801-02		LIB FUEL TRANSFERT SYSTEM VALVE CHECK						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.225	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-49-900-801-03		RIB FUEL TRANSFERT SYSTEM VALVE CHECK						Component ATA:28
PN:GP422-1405-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3359	HRS	0		TSN 0				
WC#: 28.225	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-22-49-900-801-04		ROB FUEL TRANSFERT SYSTEM - DC AUX PUMP VALVE CHECK						Component ATA:28
PN:GP422-1405-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3357	HRS	0		TSN 0				
WC#: 28.225	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-23-01-900-801-01		EXTERNAL REFUEL/DEFUEL PANEL						Component ATA:28
PN:GP541-1102-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1168	HRS	0		TSN 0				
WC#: 28.230	AFL	0		TSN 0				
PROC. REF: AMM 28 23 01 000 801, AMM 28 23 01 400 801PROC. REF: AMM 28 23 01 000 801, AMM 28 23 01 400 801								
28-23-05-900-801-01		RH REFUEL ADAPTOR CAP						Component ATA:28
PN:GP541-1102-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:31220	HRS	0		TSN 0				
WC#: 28.235	AFL	0		TSN 0				
PROC. REF: AMM 28 23 05 000 801, AMM 28 23 05 400 801PROC. REF: AMM 28 23 05 000 801, AMM 28 23 05 400 801								
28-23-05-900-802-01		REFUEL/DE-FUEL ADAPTOR						Component ATA:28
PN:GP425-1102-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01979	HRS	0		TSN 0				
WC#: 28.240	AFL	0		TSN 0				
PROC. REF: AMM 28 23 05 000 801, AMM 28 23 05 400 801PROC. REF: AMM 28 23 05 000 801, AMM 28 23 05 400 801								
28-23-13-900-801-01		LEFT TANK MANIFOLD REFUEL/DEFUEL CONTROL						Component ATA:28
PN:GP425-1101-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1374	HRS	0		TSN 0				
WC#: 28.245	AFL	0		TSN 0				
PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-23-13-900-801-02		CENTER TANK MANIFOLD REFUEL/DEFUEL CONTROL					Component	ATA:28
PN:GP425-1101-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1376	HRS	0		TSN 0				
WC#: 28.245	AFL	0		TSN 0				
PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801								
28-23-13-900-801-03		RIGHT TANK MANIFOLD REFUEL/DEFUEL CONTROL					Component	ATA:28
PN:GP425-1101-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1380	HRS	0		TSN 0				
WC#: 28.245	AFL	0		TSN 0				
PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801PROC. REF: AMM 28 23 13 000 801, AMM 28 23 13 400 801								
28-23-17-900-801-01		LH CHECK REFUEL VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.250	AFL	0		TSN 0				
PROC. REF: AMM 28 23 17 000 801, AMM 28 23 17 400 801PROC. REF: AMM 28 23 17 000 801, AMM 28 23 17 400 801								
28-23-17-900-801-02		RH CHECK REFUEL VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.250	AFL	0		TSN 0				
PROC. REF: AMM 28 23 17 000 801, AMM 28 23 17 400 801PROC. REF: AMM 28 23 17 000 801, AMM 28 23 17 400 801								
28-23-21-900-801-01		CHECK REFUEL/DEFUEL VALVE					Component	ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.255	AFL	0		TSN 0				
PROC. REF: AMM 28 23 21 000 801, AMM 28 23 21 400 801PROC. REF: AMM 28 23 21 000 801, AMM 28 23 21 400 801								
28-23-25-900-801-01		LH SHUTOFF DEFUEL VALVE					Component	ATA:28
PN:GP422-1412-4	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:AA172337	HRS	0		TSN 0				
WC#: 28.260	AFL	0		TSN 0				
PROC. REF: AMM 28 23 25 000 801, AMM 28 23 25 400 801PROC. REF: AMM 28 23 25 000 801, AMM 28 23 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-23-25-900-801-02		RH SHUTOFF DEFUEL VALVE						Component ATA:28
PN:GP422-1412-4	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:AA171150	HRS	0		TSN 0				
WC#: 28.260	AFL	0		TSN 0				
PROC. REF: AMM 28 23 25 000 801, AMM 28 23 25 400 801PROC. REF: AMM 28 23 25 000 801, AMM 28 23 25 400 801								
28-24-00-201		OPERATIONAL TEST OF THE FUEL RETURN TO TANK (FRTT) CHECK VALVES						Service ATA:28
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 28.060	AFL	745						
PROC. REF: AMM 28 26 00 710 802PROC. REF: AMM 28 26 00 710 802								
28-27-05-900-801-01		LH EJECTOR PUMP VALVE						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.270	AFL	0		TSN 0				
PROC. REF: AMM 28 27 05 000 801, AMM 28 27 05 400 801PROC. REF: AMM 28 27 05 000 801, AMM 28 27 05 400 801								
28-27-05-900-801-02		RH EJECTOR PUMP VALVE						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.270	AFL	0		TSN 0				
PROC. REF: AMM 28 27 05 000 801, AMM 28 27 05 400 801PROC. REF: AMM 28 27 05 000 801, AMM 28 27 05 400 801								
28-27-17-900-801-01		LH CENTER TRANSFERT PUMP - DC AUX PUMP VALVE CHECK						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.275	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-27-17-900-801-02		RH CENTER TRANSFERT PUMP - DC AUX PUMP VALVE CHECK						Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.275	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-00-101	FUNCTIONAL TEST OF THE TEMPERATURE SENSORS (CMR**)							Service ATA:28
	MOS	05-Feb-21	120 (+3m/-3m)	Adj 3	05-May-31	05-Aug-31	2258 d (+92)	
	HRS	2444:24						
WC#: 28.065	AFL	745						
PROC. REF: AMM 28 41 25 720 801PROC. REF: AMM 28 41 25 720 801								
28-41-01-900-801-01	RIGHT MAIN AVIONIC BAY FMQG COMPUTER							Component ATA:28
PN:GP546-1501-13	MOS/MSC	22-Apr-19	O/C					
SN:0819	HRS	2378:21						
WC#: 28.280	AFL	728						
PROC. REF: AMM 28 41 01 000 801, AMM 28 41 01 400 801PROC. REF: AMM 28 41 01 000 801, AMM 28 41 01 400 801								
28-41-05-900-801-01	FUEL W/COMP (L36.71 IN) - UPPER STR NO. 18 - NO. 19 PROBE							Component ATA:28
PN:GP422-1514-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0385	HRS	0		TSN 0				
WC#: 28.290	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-05-900-801-02	LH (L 35.88 IN) FUEL PROBE							Component ATA:28
PN:GP422-1514-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0769	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-05-900-801-03	RH (L 35.88 IN) FUEL PROBE							Component ATA:28
PN:GP422-1514-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0399	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-05-900-801-04	RH (L 35.88 IN) FUEL PROBE							Component ATA:28
PN:GP422-1514-1	MOS/MSC	17-Dec-13	O/C					
SN:0286	HRS	1134:30						
WC#: 28.285	AFL	373						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-01	LH (L 36.17 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0644	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-02	LH (L 27.81 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-2	MOS/MSC	28-Jul-18	O/C					
SN:0222	HRS	2323:37						
WC#: 28.285	AFL	709						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-03	RH (L 27.81 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-2	MOS/MSC	17-Dec-13	O/C	TSN 160				
SN:0076	HRS	1134:30		TSN 0				
WC#: 28.285	AFL	373		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-04	LH (L 17.51 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-7	MOS/MSC	21-Aug-18	O/C					
SN:1599	HRS	2336:42						
WC#: 28.285	AFL	714						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-05	RH (L 17.51 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-7	MOS/MSC	01-Mar-18	O/C					
SN:0315	HRS	2266:05						
WC#: 28.285	AFL	683						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-06	LH (L 28.85 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0782	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-07	RH (L 28.85 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0633	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-08	LH (L 30.77 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-4	MOS/MSC	01-Mar-18	O/C					
SN:0098	HRS	2266:05						
WC#: 28.285	AFL	683						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-09	RH (L 30.77 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-4	MOS/MSC	21-Aug-18	O/C	TSN 0				
SN:1862	HRS	2336:42		TSN 0				
WC#: 28.285	AFL	714		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-10	LH (L 20.16 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0735	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-11	RH (L 20.16 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0736	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-12	LH (L 18.38 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-6	MOS/MSC	01-Mar-18	O/C					
SN:1190	HRS	2266:05						
WC#: 28.285	AFL	683						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-13	RH (L 18.38 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-6	MOS/MSC	21-Aug-18	O/C					
SN:1328	HRS	2336:42						
WC#: 28.285	AFL	714						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-14	RH (L 17.51 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0652	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-15	RH (L 36,71 IN) FUEL PROBE							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-16	LH (L 14.65 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0761	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-17	RH (L 14.65 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-8	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0729	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-18	LH (L 9.63 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-9	MOS/MSC	01-Mar-18	O/C					
SN:1462	HRS	2266:05						
WC#: 28.285	AFL	683						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-19	RH (L 9.63 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0755	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-20	LH (L 9.33 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-10	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0799	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-21	RH (L 9.33 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-10	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0728	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-22	LH (L 8.98 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-11	MOS/MSC	28-Jul-18	O/C					
SN:0633	HRS	2323:37						
WC#: 28.285	AFL	709						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-23	RH (L 8.98 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-11	MOS/MSC	21-Aug-18	O/C	TSN 0				
SN:1732	HRS	2336:42		TSN 0				
WC#: 28.285	AFL	714		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-24	LH (L 8.12 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-12	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0747	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-25	RH (L 8.12 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-12	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0748	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-26	LH (L 6.53 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0766	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-27	RH (L 6.53 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0622	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-28	LH (L 7.61 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0764	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-29	RH (L 7.61 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0765	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-09-900-801-30	LH (L 21.67 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-15	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0737	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-31	RH (L 21.67 IN) FUEL PROBE							Component ATA:28
PN:GP422-1501-15	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0738	HRS	0		TSN 0				
WC#: 28.285	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28-41-17-900-801-01	LH (WS415.4 LWR STR#10-#11) FUEL HIGH LEVEL SENSOR							Component ATA:28
PN:GP422-1505-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1591	HRS	0		TSN 0				
WC#: 28.295	AFL	0		TSN 0				
PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801								
28-41-17-900-801-02	LH (WS66.00 LWR STR#16-#17) FUEL HIGH LEVEL SENSOR							Component ATA:28
PN:GP422-1505-1	MOS/MSC	04-Sep-15	O/C					
SN:0153	HRS	1791:58						
WC#: 28.295	AFL	551						
PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801								
28-41-17-900-801-03	RH (WS415.4 LWR STR#10-#11) FUEL HIGH LEVEL SENSOR							Component ATA:28
PN:GP422-1505-1	MOS/MSC	22-Apr-19	O/C					
SN:3340	HRS	2378:21						
WC#: 28.295	AFL	728						
PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801								
28-41-17-900-801-04	RH (WS66.00 LWR STR#16-#17) FUEL HIGH LEVEL SENSOR							Component ATA:28
PN:GP422-1505-1	MOS/MSC	21-Aug-18	O/C	TSN 0				
SN:3607	HRS	2336:42		TSN 0				
WC#: 28.295	AFL	714		TSN 0				
PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801PROC. REF: AMM 28 41 17 000 801, AMM 28 41 17 400 801								
28-41-21-900-801-01	DENSIOMETER ENCLOSURE							Component ATA:28
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.300	AFL	0		TSN 0				
PROC. REF: AMM 28 41 21 000 801, AMM 28 41 21 400 801PROC. REF: AMM 28 41 21 000 801, AMM 28 41 21 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-21-900-801-02	FUEL Densiometer							Component ATA:28
PN:PN	MOS/MSc	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.305	AFL	0		TSN 0				
PROC. REF: AMM 28 41 21 000 801, AMM 28 41 21 400 801PROC. REF: AMM 28 41 21 000 801, AMM 28 41 21 400 801								
28-41-25-900-801-01	LH (WS66.00 LWR STR#7-#8) FUEL TEMP SENSOR							Component ATA:28
PN:GP422-1508-3	MOS/MSc	30-Jul-09	O/C	TSN 0				
SN:02167	HRS	0		TSN 0				
WC#: 28.310	AFL	0		TSN 0				
PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801								
28-41-25-900-801-02	LH (CANT RIB LWR STR#8-#9) FUEL TEMP SENSOR							Component ATA:28
PN:GP422-1508-3	MOS/MSc	30-Jul-09	O/C	TSN 0				
SN:02168	HRS	0		TSN 0				
WC#: 28.310	AFL	0		TSN 0				
PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801								
28-41-25-900-801-03	RH (WS108.5 LWR STR#7-#8) FUEL TEMP SENSOR							Component ATA:28
PN:GP422-1508-3	MOS/MSc	30-Jul-09	O/C	TSN 0				
SN:02170	HRS	0		TSN 0				
WC#: 28.310	AFL	0		TSN 0				
PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801								
28-41-25-900-801-04	RH (WS199.0 LWR STR#7-#8) FUEL TEMP SENSOR							Component ATA:28
PN:GP422-1508-3	MOS/MSc	30-Jul-09	O/C	TSN 0				
SN:02175	HRS	0		TSN 0				
WC#: 28.310	AFL	0		TSN 0				
PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801								
28-41-25-900-801-05	RH (WS66.00 LWR STR#7-#8) FUEL TEMP SENSOR							Component ATA:28
PN:GP422-1508-3	MOS/MSc	30-Jul-09	O/C	TSN 0				
SN:02169	HRS	0		TSN 0				
WC#: 28.310	AFL	0		TSN 0				
PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801PROC. REF: AMM 28 41 25 000 801, AMM 28 41 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282301-701 ^U	REFUEL/DEFUEL PANEL							Component ATA:28
PN:GP541-1102-2	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:1164	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
ATA 29 - HYDRAULIC POWER								
29-12-00-201	VISUAL CHECK OF THE NO. 1 AND NO. 2 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS							Service ATA:29
	MOS	10-Mar-23						MRIP
	HRS	2845:10	1000 (+50/-50)		3845:10	3895:10	399:14 (+50)	
WC#: 29.005	AFL	999						
PROC. REF: AMM 29 12 00 210 802PROC. REF: AMM 29 12 00 210 802								
29-12-01-900-801-01	NO. 1 ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:GX472-0010-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K0802	HRS	0		TSN 0				
WC#: 29.035	AFL	0		TSN 0				
PROC. REF: AMM 29 12 01 000 801, AMM 29 12 01 400 801PROC. REF: AMM 29 12 01 000 801, AMM 29 12 01 400 801								
29-12-01-900-801-02	NO. 2 ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:GX472-0010-1	MOS/MSC	27-Jan-19	O/C	TSR 0				
SN:K1562	HRS	2346:58		TSR 0				
WC#: 29.035	AFL	719		TSR 0				
PROC. REF: AMM 29 12 01 000 801, AMM 29 12 01 400 801PROC. REF: AMM 29 12 01 000 801, AMM 29 12 01 400 801								
29-12-05-900-801-01	1B AC MOTOR PUMP							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.040	AFL	0		TSN 0				
PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801								
29-12-05-900-801-02	2B AC MOTOR PUMP							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.040	AFL	0		TSN 0				
PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-12-05-900-801-03	3A AC MOTOR PUMP							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.040	AFL	0		TSN 0				
PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801								
29-12-05-900-801-04	3B AC MOTOR PUMP							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.040	AFL	0		TSN 0				
PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801PROC. REF: AMM 29 12 05 000 801, AMM 29 12 05 400 801								
29-12-25-900-801-01	NO. 1 HYDRAULIC RESERVOIR							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.045	AFL	0		TSN 0				
PROC. REF: AMM 29 12 25 000 801, AMM 29 12 25 400 801PROC. REF: AMM 29 12 25 000 801, AMM 29 12 25 400 801								
29-12-25-900-801-02	NO. 2 HYDRAULIC RESERVOIR							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.045	AFL	0		TSN 0				
PROC. REF: AMM 29 12 25 000 801, AMM 29 12 25 400 801PROC. REF: AMM 29 12 25 000 801, AMM 29 12 25 400 801								
29-12-33-101	OPERATIONAL TEST OF THE FIREWALL HYDRAULIC SHUTOFF-VALVES (CMR**)							Service ATA:29
	MOS	15-May-24						CMR
	HRS	3168:27	1500		4668:27		1222:31	
WC#: 29.010	AFL	1205						
PROC. REF: AMM 29 12 33 710 801PROC. REF: AMM 29 12 33 710 801								
29-12-33-900-801-01	NO. 1 S/O FIREWALL VALVE							Component ATA:29
PN:GX473-0126-1	MOS/MSC	03-Apr-14	O/C	TSN 1				
SN:TA4588	HRS	1196:50		TSN 0				
WC#: 29.050	AFL	392		TSN 0				
PROC. REF: AMM 29 12 33 000 801, AMM 29 12 33 400 801PROC. REF: AMM 29 12 33 000 801, AMM 29 12 33 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-12-33-900-801-02		NO. 2 S/O FIREWALL VALVE					Component	ATA:29
PN:975237-501	MOS/MSC	15-May-24	O/C	TSO 0				
SN:TA4090	HRS	3168:27		TSO 0				
WC#: 29.050	AFL	1205		TSO 0				
PROC. REF: AMM 29 12 33 000 801, AMM 29 12 33 400 801PROC. REF: AMM 29 12 33 000 801, AMM 29 12 33 400 801								
29-12-37-900-801-02		NO.2 HYDRAULIC SYSTEM PRIORITY VALVE					Component	ATA:29
PN:GX473-0060-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:PN0808	HRS	0		TSN 0				
WC#: 29.055	AFL	0		TSN 0				
PROC. REF: AMM 29 12 37 000 801, AMM 29 12 37 400 801PROC. REF: AMM 29 12 37 000 801, AMM 29 12 37 400 801								
29-12-45-900-801-01		NO. 1 HEAT EXCHANGER BYPASS VALVE					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.060	AFL	0		TSN 0				
PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801								
29-12-45-900-801-02		NO. 2 HEAT EXCHANGER BYPASS VALVE					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.060	AFL	0		TSN 0				
PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801								
29-12-45-900-801-03		NO. 3 HEAT EXCHANGER BYPASS VALVE					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.060	AFL	0		TSN 0				
PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801PROC. REF: AMM 29 12 45 000 801, AMM 29 12 45 400 801								
29-12-61-900-801-01		LH CHECK VALVE					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.065	AFL	0		TSN 0				
PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-12-61-900-801-02		RH CHECK VALVE						Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.065	AFL	0		TSN 0				
PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801								
29-12-61-900-801-03		CENTER CHECK VALVE						Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.065	AFL	0		TSN 0				
PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801PROC. REF: AMM 29 12 61 000 801, AMM 29 12 61 400 801								
29-13-00-101		OPERATIONAL (INTERNAL LEAK) TEST OF THE NO. 3 HYDRAULIC SYSTEM (CMR*)						Service ATA:29
	MOS	21-Jul-21						CMR
	HRS	2446:06	1500 (+50/-50)		3946:06	3996:06	500:10 (+50)	
WC#: 29.015	AFL	747						
PROC. REF: AMM 29 13 00 790 802PROC. REF: AMM 29 13 00 790 802								
29-13-00-201		VISUAL CHECK OF THE NO. 3 HYDRAULIC FILTER DIFFERENTIAL-PRESSURE INDICATORS						Service ATA:29
	MOS	10-Mar-23						MRIP
	HRS	2845:10	1000 (+50/-50)		3845:10	3895:10	399:14 (+50)	
WC#: 29.020	AFL	999						
PROC. REF: AMM 29 13 00 210 802PROC. REF: AMM 29 13 00 210 802								
29-13-05-900-801-01		NO. 1 MANIFOLD FILTER						Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.070	AFL	0		TSN 0				
PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801								
29-13-05-900-801-02		NO. 2 MANIFOLD FILTER						Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.070	AFL	0		TSN 0				
PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-13-05-900-801-03	NO. 3 MANIFOLD FILTER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.070	AFL	0		TSN 0				
PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801PROC. REF: AMM 29 13 05 000 801, AMM 29 13 05 400 801								
29-13-21-201	FUNCTIONAL TEST OF THE NO. 3 HYDRAULIC SYSTEM ACCUMULATOR							Service ATA:29
	MOS	18-Feb-22	60 (+3m/-3m)	Adj -201d	01-Aug-26	01-Nov-26	520 d (+92)	MRIP
	HRS	2452:23	1000 (+50/-50)	Adj 50	3502:23	3552:23	56:27 (+50)	
WC#: 29.025	AFL	753						
PROC. REF: AMM 29 13 21 720 801PROC. REF: AMM 29 13 21 720 801								
29-13-21-900-801-01	NO. 3 SYSTEM HYDRAULIC ACCUMULATOR							Component ATA:29
PN:GX473-0100-7	MOS/MSC	22-Dec-14	O/C	TSN 1				
SN:60190-3183	HRS	1550:52		TSN 0				
WC#: 29.075	AFL	475		TSN 0				
PROC. REF: AMM 29 13 21 000 801, AMM 29 13 21 400 801PROC. REF: AMM 29 13 21 000 801, AMM 29 13 21 400 801								
29-13-29-900-801-01	NO. 3 HYDRAULIC RESERVOIR							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.080	AFL	0		TSN 0				
PROC. REF: AMM 29 13 29 000 801, AMM 29 13 29 400 801PROC. REF: AMM 29 13 29 000 801, AMM 29 13 29 400 801								
29-13-33-900-801-01	RELIEF/BLEED VALVE							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.085	AFL	0		TSN 0				
PROC. REF: AMM 29 13 33 000 801, AMM 29 13 33 400 801PROC. REF: AMM 29 13 33 000 801, AMM 29 13 33 400 801								
29-13-37-900-801-01	NO. 1 HEAT EXCHANGER							Component ATA:29
PN:GX474-0010-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4173	HRS	0		TSN 0				
WC#: 29.090	AFL	0		TSN 0				
PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-13-37-900-801-02		NO. 2 HEAT EXCHANGER						Component ATA:29
PN:GX474-0010-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4193	HRS	0		TSN 0				
WC#: 29.090	AFL	0		TSN 0				
PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801								
29-13-37-900-801-03		NO. 3 HEAT EXCHANGER						Component ATA:29
PN:GX474-0010-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4186	HRS	0		TSN 0				
WC#: 29.090	AFL	0		TSN 0				
PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801PROC. REF: AMM 29 13 37 000 801, AMM 29 13 37 400 801								
29-13-49-900-801-01		NO. 1 CHECK IN LINE VALVE						Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.095	AFL	0		TSN 0				
PROC. REF: AMM 29 13 49 000 801, AMM 29 13 49 400 801PROC. REF: AMM 29 13 49 000 801, AMM 29 13 49 400 801								
29-13-53-900-801-01		NO.3 HYDRAULIC SYSTEM PRIORITY VALVE						Component ATA:29
PN:GX473-0060-3	MOS/MSC	17-Dec-12	O/C					
SN:PN020	HRS	877:15		TSN 3931:02				
WC#: 29.055	AFL	311		TSN 1395				
PROC. REF: AMM 29 12 37 000 801, AMM 29 12 37 400 801PROC. REF: AMM 29 12 37 000 801, AMM 29 12 37 400 801								
29-13-57-900-801-01		MANIFOLD VALVE						Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.100	AFL	0		TSN 0				
PROC. REF: AMM 29 13 57 000 801, AMM 29 13 57 400 801PROC. REF: AMM 29 13 57 000 801, AMM 29 13 57 400 801								
29-14-00-201		FUNCTIONAL TEST OF THE RAM AIR TURBINE (RAT) HYDRAULIC FLUID-HEATING SYSTEM						Service ATA:29
	MOS	28-Sep-17	180 (+3m/-3m)	28-Sep-32	28-Dec-32	2770 d (+91)	MRIP	
	HRS	2242:56	3000 (+50/-50)	5242:56	5292:56	1797 (+50)		
WC#: 29.030	AFL	677						
PROC. REF: AMM 29 14 00 720 801PROC. REF: AMM 29 14 00 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-14-01-900-801-01	NO. 1 CHECK RESTRICTOR VALVE							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.105	AFL	0		TSN 0				
PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801								
29-14-01-900-801-02	NO. 2 CHECK RESTRICTOR VALVE							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.105	AFL	0		TSN 0				
PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801								
29-14-01-900-801-03	NO. 3 CHECK RESTRICTOR VALVE							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.105	AFL	0		TSN 0				
PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801PROC. REF: AMM 29 14 01 000 801, AMM 29 14 01 400 801								
29-31-01-900-801-01	NO. 1 PRESSURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.110	AFL	0		TSN 0				
PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801								
29-31-01-900-801-02	NO. 2 PRESSURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.110	AFL	0		TSN 0				
PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801								
29-31-01-900-801-03	NO. 3 PRESSURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.110	AFL	0		TSN 0				
PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801PROC. REF: AMM 29 31 01 000 801, AMM 29 31 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-31-05-900-801-01		1A PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.115	AFL	0		TSN 0				
PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801								
29-31-05-900-801-02		1B PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.115	AFL	0		TSN 0				
PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801								
29-31-05-900-801-03		2A PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.115	AFL	0		TSN 0				
PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801								
29-31-05-900-801-04		2B PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.115	AFL	0		TSN 0				
PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801								
29-31-05-900-801-05		NO. 3A PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.115	AFL	0		TSN 0				
PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801								
29-31-05-900-801-06		NO. 3B PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.115	AFL	0		TSN 0				
PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801PROC. REF: AMM 29 31 05 000 801, AMM 29 31 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-33-01-900-801-01	NO. 1 TEMPERATURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.120	AFL	0		TSN 0				
PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801								
29-33-01-900-801-02	NO. 2 TEMPERATURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.120	AFL	0		TSN 0				
PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801								
29-33-01-900-801-03	NO. 3 TEMPERATURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.120	AFL	0		TSN 0				
PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801PROC. REF: AMM 29 33 01 000 801, AMM 29 33 01 400 801								
ATA 30 - ICE AND RAIN PROTECTION								
30-11-01-900-801-01	LH MODULATING VALVE							Component ATA:30
PN:GG436-4001-13	MOS/MSC	21-Aug-18	O/C					
SN:00980	HRS	2336:42						
WC#: 30.025	AFL	714						
PROC. REF: AMM 30 11 01 000 801, AMM 30 11 01 400 801PROC. REF: AMM 30 11 01 000 801, AMM 30 11 01 400 801								
30-11-01-900-801-02	RH MODULATING VALVE							Component ATA:30
PN:GG436-4001-13	MOS/MSC	05-Jun-23	O/C	TSR 0				
SN:02026	HRS	2913:47		TSR 0				
WC#: 30.025	AFL	1041		TSR 0				
PROC. REF: AMM 30 11 01 000 801, AMM 30 11 01 400 801PROC. REF: AMM 30 11 01 000 801, AMM 30 11 01 400 801								
30-11-05-900-801-01	LEFT SLAT NO. 4 TEMPERATURE SENSOR							Component ATA:30
PN:GG436-4078-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1337	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-05-900-801-02	RIGHT SLAT NO. 4 TEMPERATURE SENSOR							Component ATA:30
PN:GG436-4078-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1335	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801								
30-11-05-900-802-01	LH WAI TEMPERATURE SENSOR							Component ATA:30
PN:GG436-4003-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1856	HRS	0		TSN 0				
WC#: 30.035	AFL	0		TSN 0				
PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801								
30-11-05-900-802-02	RH WAI TEMPERATURE SENSOR							Component ATA:30
PN:GG436-4003-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1858	HRS	0		TSN 0				
WC#: 30.035	AFL	0		TSN 0				
PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801PROC. REF: AMM 30 11 05 000 801, AMM 30 11 05 400 801								
30-11-09-202	OPERATIONAL TEST OF THE WING XBLEED SYSTEM							Service ATA:30
	MOS	21-Jul-21	135 (+3m/-3m)		21-Oct-32	21-Jan-33	2793 d (+92)	MRIP
	HRS	2446:06	2250 (+50/-50)		4696:06	4746:06	1250:10 (+50)	
WC#: 30.005	AFL	747						
PROC. REF: AMM 30 11 00 710 802PROC. REF: AMM 30 11 00 710 802								
30-11-09-900-801-01	WAI ISOLATION VALVE							Component ATA:30
PN:GG436-4004-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01073	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
PROC. REF: AMM 30 11 09 000 801, AMM 30 11 09 400 801PROC. REF: AMM 30 11 09 000 801, AMM 30 11 09 400 801								
30-12-05-102	DISCARD THE WING ANTI-ICING TELESCOPIC-DUCT (LH), PART NO. GG468-4022-3 (SERIAL NUMBERS NOT COVERED BY TASK 30-12-05-101*)							Service ATA:30
PN:GG468-4022-3	MOS	30-Jul-09						LIFE LIMIT
SN:0411	HRS	0	15000		15000		11554:04	
	AFL	0						
PROC. REF: AMM 30 12 05 961 801PROC. REF: AMM 30 12 05 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-05-104	DISCARD THE WING ANTI-ICING TELESCOPIC-DUCT (RH), PART NO. GG468-4022-4 (SERIAL NUMBERS NOT COVERED BY TASK 30-12-05-103*)							Service ATA:30
PN:GG468-4022-4	MOS	30-Jul-09						LIFE LIMIT
SN:0417	HRS	0	15000		15000		11554:04	
	AFL	0						
PROC. REF: AMM 30 12 05 961 801PROC. REF: AMM 30 12 05 961 801								
30-12-05-900-801-01	LH SLAT NO. 1 TELESCOPIC, A/I SUPPLY LH DUCT							Component ATA:30
PN:GG468-4022-3	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:0411	HRS	0		TSN 0				
WC#: 30.045	AFL	0		TSN 0				
PROC. REF: AMM 30 12 05 000 801, AMM 30 12 05 400 801PROC. REF: AMM 30 12 05 000 801, AMM 30 12 05 400 801								
30-12-05-900-801-02	RH SLAT NO. 1 TELESCOPIC, A/I SUPPLY RH DUCT							Component ATA:30
PN:GG468-4022-4	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:0417	HRS	0		TSN 0				
WC#: 30.045	AFL	0		TSN 0				
PROC. REF: AMM 30 12 05 000 801, AMM 30 12 05 400 801PROC. REF: AMM 30 12 05 000 801, AMM 30 12 05 400 801								
30-12-09-900-801-01	NO. 1 COUPLING COVER							Component ATA:30
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
30-12-09-900-801-02	NO. 2 COUPLING COVER							Component ATA:30
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
30-12-09-900-801-03	NO. 3 COUPLING COVER							Component ATA:30
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-09-900-801-04	NO. 4 COUPLING COVER							Component ATA:30
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
30-12-09-900-801-05	NO. 5 COUPLING COVER							Component ATA:30
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
30-12-09-900-804-01	ANTI-ICE SUPPLY CENTER DUCT							Component ATA:30
PN:GG468-4033-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0308	HRS	0		TSN 0				
WC#: 30.055	AFL	0		TSN 0				
PROC. REF: AMM 30 12 09 000 804, AMM 30 12 09 400 804PROC. REF: AMM 30 12 09 000 804, AMM 30 12 09 400 804								
30-12-13-101	DISCARD THE LH WING ANTI-ICING FLEXIBLE-JOINTS, PART NO. GG468-4025-1							Service ATA:30
PN:GG468-4025-1	MOS	30-Jul-09						LIFE LIMIT
SN:0961	HRS	0	15000		15000		11554:04	
	AFL	0						
PROC. REF: AMM 30 12 13 961 801PROC. REF: AMM 30 12 13 961 801								
30-12-13-101	DISCARD THE RH WING ANTI-ICING FLEXIBLE-JOINTS, PART NO. GG468-4025-1							Service ATA:30
PN:GG468-4025-1	MOS	30-Jul-09						LIFE LIMIT
SN:0956	HRS	0	15000		15000		11554:04	
	AFL	0						
PROC. REF: AMM 30 12 13 961 801PROC. REF: AMM 30 12 13 961 801								
30-12-13-900-801-01	LH FLEXIBLE JOINT							Component ATA:30
PN:GG468-4025-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:0961	HRS	0		TSN 0				
WC#: 30.060	AFL	0		TSN 0				
PROC. REF: AMM 30 12 13 000 801, AMM 30 12 13 400 801PROC. REF: AMM 30 12 13 000 801, AMM 30 12 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-13-900-801-02	RH FLEXIBLE JOINT							Component ATA:30
PN:GG468-4025-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:0956	HRS	0		TSN 0				
WC#: 30.060	AFL	0		TSN 0				
PROC. REF: AMM 30 12 13 000 801, AMM 30 12 13 400 801PROC. REF: AMM 30 12 13 000 801, AMM 30 12 13 400 801								
30-21-05-201	GENERAL VISUAL INSPECTION OF THE COWL ANTI-ICING-VALVE DUCTS							Service ATA:30
	MOS	21-Jul-21	180 (+3m/-3m)		21-Jul-36	21-Oct-36	4162 d (+92)	MRIP
	HRS	2446:06	3000 (+50/-50)		5446:06	5496:06	2000:10 (+50)	
WC#: 30.010	AFL	747						
PROC. REF: AMM 30 21 05 210 802PROC. REF: AMM 30 21 05 210 802								
30-21-05-900-802-01	LH ENGINE NOSE COWL ANTI-ICE VALVE							Component ATA:30
PN:510-0020-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D0987	HRS	0		TSN 0				
WC#: 30.065	AFL	0		TSN 0				
PROC. REF: AMM 30 21 05 000 802, AMM 30 21 05 400 802PROC. REF: AMM 30 21 05 000 802, AMM 30 21 05 400 802								
30-21-05-900-802-02	RH ENGINE NOSE COWL ANTI-ICE VALVE							Component ATA:30
PN:510-0020-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D0911	HRS	0		TSN 0				
WC#: 30.065	AFL	0		TSN 0				
PROC. REF: AMM 30 21 05 000 802, AMM 30 21 05 400 802PROC. REF: AMM 30 21 05 000 802, AMM 30 21 05 400 802								
30-31-01-900-801-01	NO. 1 HEATER/BRAKE TEMPERATURE MONITOR-							Component ATA:30
PN:GH569-0017-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:949	HRS	0		TSN 0				
WC#: 30.070	AFL	0		TSN 0				
PROC. REF: AMM 30 31 01 000 801, AMM 30 31 01 400 801PROC. REF: AMM 30 31 01 000 801, AMM 30 31 01 400 801								
30-31-01-900-801-02	NO. 2 HEATER/BRAKE TEMPERATURE MONITOR-							Component ATA:30
PN:GH569-0017-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:942	HRS	0		TSN 0				
WC#: 30.070	AFL	0		TSN 0				
PROC. REF: AMM 30 31 01 000 801, AMM 30 31 01 400 801PROC. REF: AMM 30 31 01 000 801, AMM 30 31 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-41-00-202	FUNCTIONAL TEST OF THE WINDSHIELD RAIN-REPELLANT LAYER							Service ATA:30
	MOS	15-Oct-24	12 (+10%/-10%)		15-Oct-25 (M)	21-Nov-25	230 d (+37)	
	HRS	3314:03	750 (+50/-50)		4064:03 (M)	4114:03	618:07 (+50)	
WC#: 30.015	AFL	1328						
PROC. REF: AMM 30 40 00 720 801PROC. REF: AMM 30 40 00 720 801								
30-41-00-301	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL							Service ATA:30
	MOS	15-Oct-24	15 (+3m/-3m)		15-Jan-26 (M)	15-Apr-26	322 d (+90)	OPTIONAL
	HRS	3314:03	750 (+50/-50)		4064:03 (M)	4114:03	618:07 (+50)	
	AFL	1328						
PROC. REF: AMM 56 10 01 220 801PROC. REF: AMM 56 10 01 220 801								
30-41-01-900-801-01	LH WINDSHIELD TEMPERATURE CONTROLLER							Component ATA:30
PN:GC584-1001-4	MOS/MSC	08-Jun-12	O/C	TSR 1				
SN:0531	HRS	731:55		TSR 0				
WC#: 30.075	AFL	238		TSR 0				
PROC. REF: AMM 30 41 01 000 801, AMM 30 41 01 400 801PROC. REF: AMM 30 41 01 000 801, AMM 30 41 01 400 801								
30-41-01-900-801-02	RH WINDSHIELD TEMPERATURE CONTROLLER							Component ATA:30
PN:GC584-1001-4	MOS/MSC	08-Jun-12	O/C					
SN:0848	HRS	731:55						
WC#: 30.075	AFL	238						
PROC. REF: AMM 30 41 01 000 801, AMM 30 41 01 400 801PROC. REF: AMM 30 41 01 000 801, AMM 30 41 01 400 801								
30-81-01-201	OPERATIONAL TEST OF THE ICE DETECTORS							Service ATA:30
	MOS	21-Jul-21	90 (+3m/-3m)		21-Jan-29 (M)	21-Apr-29	1424 d (+90)	MRIP
	HRS	2446:06	1500 (+50/-50)		3946:06	3996:06	500:10 (+50)	
WC#: 30.020	AFL	747						
PROC. REF: AMM 30 81 01 710 801PROC. REF: AMM 30 81 01 710 801								
30-81-01-900-801-01	LH ICE DETECTOR							Component ATA:30
PN:GG436-4006-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:20605	HRS	0		TSN 0				
WC#: 30.080	AFL	0		TSN 0				
PROC. REF: AMM 30 81 01 000 801, AMM 30 81 01 400 801PROC. REF: AMM 30 81 01 000 801, AMM 30 81 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-81-01-900-801-02	RH ICE DETECTOR							Component ATA:30
PN:GG436-4006-9	MOS/MSC	03-Jul-14	O/C	TSR 6				
SN:01072	HRS	1340:24		TSR 0				
WC#: 30.080	AFL	425		TSR 0				
PROC. REF: AMM 30 81 01 000 801, AMM 30 81 01 400 801PROC. REF: AMM 30 81 01 000 801, AMM 30 81 01 400 801								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-17-01-900-801-01	CIRCUIT BREAKER PANEL							Component ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.035	AFL	0		TSN 0				
PROC. REF: AMM 31 17 01 000 801, AMM 31 17 01 400 801PROC. REF: AMM 31 17 01 000 801, AMM 31 17 01 400 801								
31-21-01-900-801-01	LH DIGITAL CLOCK							Component ATA:31
PN:APE4190-030	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:556	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
PROC. REF: AMM 31 21 01 000 801, AMM 31 21 01 400 801PROC. REF: AMM 31 21 01 000 801, AMM 31 21 01 400 801								
31-21-01-900-801-02	RH DIGITAL CLOCK							Component ATA:31
PN:APE4190-030	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:557	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
PROC. REF: AMM 31 21 01 000 801, AMM 31 21 01 400 801PROC. REF: AMM 31 21 01 000 801, AMM 31 21 01 400 801								
31-31-00-201	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (CONTROL COLUMN AND RUDDER PEDAL PARAMETERS)							Service ATA:31
	MOS	21-Jul-21	240 (+3m/-3m)		21-Jul-41	21-Oct-41	5988 d (+92)	MRIP
	HRS	2446:06	4500 (+50/-50)		6946:06	6996:06	3500:10 (+50)	
WC#: 31.005	AFL	747						
PROC. REF: AMM 31 31 00 710 802PROC. REF: AMM 31 31 00 710 802								
31-31-00-203	FUNCTIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) FORCESENSORS, (POST SB 700-1A11-31-001)							Service ATA:31
	MOS/MSC	30-Jul-09	N/A					
	HRS	0						
WC#: 31.010	AFL	0						
PROC. REF: AMM 31 31 00 720 801PROC. REF: AMM 31 31 00 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-01-900-801-01	FLIGHT DATA RECORDER							Component ATA:31
PN:980-4700-041	MOS/MSC	20-Nov-16	O/C					
SN:SSFDR-17003	HRS	2035:31						
WC#: 31.045	AFL	620						
PROC. REF: AMM 31 31 01 000 801, AMM 31 31 01 400 801PROC. REF: AMM 31 31 01 000 801, AMM 31 31 01 400 801								
31-31-05-900-801-01	ACCELEROMETER							Component ATA:31
PN:971-4193-001	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12568	HRS	0		TSN 0				
WC#: 31.050	AFL	0		TSN 0				
PROC. REF: AMM 31 31 05 000 801, AMM 31 31 05 400 801PROC. REF: AMM 31 31 05 000 801, AMM 31 31 05 400 801								
31-31-09-201	OPERATIONAL TEST FDR ULB UNDERWATER LOCATOR BEACON (31-31-09-201)							Service ATA:31
PN:DK120/90	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	RECOMMENDED
SN:AT187058	HRS							
WC#: 31.055	AFL							
PROC. REF: AMM 31 31 09 710 802PROC. REF: AMM 31 31 09 710 802								
31-31-09-202	DISCARD BATTERY (31-31-09-202)							Service ATA:31
PN:PN	MOS/MSC	10-Mar-23	DUE		01-Mar-30 (M)		1828 d	MRB
SN:UNKNOWN	HRS	2845:10						
WC#: 31.055	AFL	999						
PROC. REF: AMM 31 31 09 961 801PROC. REF: AMM 31 31 09 961 801								
31-31-09-900-801-01	FDR ULB UNDERWATER LOCATOR BEACON							Component ATA:31
PN:DK120/90	MOS/MSC	10-Mar-23	O/C	TSN 0				
SN:AT187058	HRS	2845:10		TSN 0				
WC#: 31.055	AFL	999		TSN 0				
PROC. REF: AMM 31 31 09 000 801, AMM 31 31 09 400 801PROC. REF: AMM 31 31 09 000 801, AMM 31 31 09 400 801								
31-31-09-900-802-01	FDR (ULD) UNDERWATER LOCATOR BEACON BATTERY							Component ATA:31
PN:PN	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, AMM 31 31 09 000 802, AMM 31 31 09 400 802PROC. REF: GENERIC NO REF, AMM 31 31 09 000 802, AMM 31 31 09 400 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-33-00-301	DOWNLOAD OF THE QUICK ACCESS RECORDER (POST SB 700-1A11-31-008)							Service ATA:31
	MOS	15-Oct-24						MPD
	HRS	3314:03	300 (+10%/-10%)		3614:03 (M)	3644:03	168:07 (+30)	
	AFL	1328						
PROC. REF: AMM 31 33 00 970 801PROC. REF: AMM 31 33 00 970 801								
31-41-00-301	DISCARD OF THE NO.1 INTEGRATED AVIONICS COMPUTER (IAC) BATTERY							Service ATA:31
PN:7017300-61014	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25	15-Nov-25	169 d (+92)	OPTIONAL
SN:00102179	HRS	3168:27						
	AFL	1205						
PROC. REF: AMM 31 41 01 961 801PROC. REF: AMM 31 41 01 961 801								
31-41-00-301	DISCARD OF THE NO.2 INTEGRATED AVIONICS COMPUTER (IAC) BATTERY							Service ATA:31
PN:7017300-61014	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25	15-Nov-25	169 d (+92)	OPTIONAL
SN:00052015	HRS	3168:27						
	AFL	1205						
PROC. REF: AMM 31 41 01 961 801PROC. REF: AMM 31 41 01 961 801								
31-41-00-301	DISCARD OF THE NO.3 INTEGRATED AVIONICS COMPUTER (IAC) BATTERY							Service ATA:31
PN:7017300-61014	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	OPTIONAL
SN:09034030	HRS	3168:27						
	AFL	1205						
PROC. REF: AMM 31 41 01 961 801PROC. REF: AMM 31 41 01 961 801								
31-41-01-900-801-01	NO.1 INTEGRATED AVIONICS COMPUTER							Component ATA:31
PN:7017300-61014	MOS/MSC	15-Oct-24	O/C					
SN:00102179	HRS	3314:03						
WC#: 31.060	AFL	1328						
PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801								
31-41-01-900-801-02	NO.2 INTEGRATED AVIONICS COMPUTER							Component ATA:31
PN:7017300-61014	MOS/MSC	15-Oct-24	O/C					
SN:00052015	HRS	3314:03						
WC#: 31.060	AFL	1328						
PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-41-01-900-801-03		NO.3 INTEGRATED AVIONICS COMPUTER						Component ATA:31
PN:7017300-61014	MOS/MSC	17-May-22	O/C					
SN:09034030	HRS	2534:36						
WC#: 31.060	AFL	798						
PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801PROC. REF: AMM 31 41 01 000 801, AMM 31 41 01 400 801								
31-41-05-900-801-01		NO. 1 CONFIGURATION IAC MODULE						Component ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.065	AFL	0		TSN 0				
PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801								
31-41-05-900-801-02		NO. 2 CONFIGURATION IAC MODULE						Component ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.065	AFL	0		TSN 0				
PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801								
31-41-05-900-801-03		NO. 3 CONFIGURATION IAC MODULE						Component ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.065	AFL	0		TSN 0				
PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801PROC. REF: AMM 31 41 05 000 801, AMM 31 41 05 400 801								
31-42-01-900-801-01		NO. 1 DATA ACQUISITION (DAU) UNIT						Component ATA:31
PN:10604B03M09	MOS/MSC	05-Jun-16	O/C					
SN:02091093	HRS	1925:27						
WC#: 31.070	AFL	585						
PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801								
31-42-01-900-801-02		NO. 2 DATA ACQUISITION (DAU) UNIT						Component ATA:31
PN:10604B03M09	MOS/MSC	10-Mar-23	O/C	TSR 10				
SN:9712535	HRS	2845:10		TSR 310:34				
WC#: 31.070	AFL	999		TSR 201				
PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-42-01-900-801-03		NO. 3 DATA ACQUISITION (DAU) UNIT						Component ATA:31
PN:10604B03M09	MOS/MSC	03-Dec-10	O/C					
SN:5031305	HRS	92:17						
WC#: 31.070	AFL	32						
PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801								
31-42-01-900-801-04		NO. 4 DATA ACQUISITION (DAU) UNIT						Component ATA:31
PN:10604B03M09	MOS/MSC	10-Mar-23	O/C					
SN:08091918	HRS	2845:10						
WC#: 31.070	AFL	999						
PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801PROC. REF: AMM 31 42 01 000 801, AMM 31 42 01 400 801								
31-43-01-900-801-01		FWD LAMP DRIVER						Component ATA:31
PN:LT45D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2338	HRS	0		TSN 0				
WC#: 31.075	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
31-43-01-900-801-02		LAMP - FS223 DRIVER						Component ATA:31
PN:LT45D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2409	HRS	0		TSN 0				
WC#: 31.075	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
31-43-01-900-801-03		AFT LAMP DRIVER						Component ATA:31
PN:LT45D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2319	HRS	0		TSN 0				
WC#: 31.075	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
31-44-01-900-801-01		LH ISOLATION COUPLER						Component ATA:31
PN:5008500-002	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:14820	HRS	0		TSN 0				
WC#: 31.080	AFL	0		TSN 0				
PROC. REF: AMM 31 44 01 000 801, AMM 31 44 01 400 801PROC. REF: AMM 31 44 01 000 801, AMM 31 44 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-44-01-900-801-02	RH ISOLATION COUPLER							Component ATA:31
PN:5008500-002	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:14794	HRS	0		TSN 0				
WC#: 31.080	AFL	0		TSN 0				
PROC. REF: AMM 31 44 01 000 801, AMM 31 44 01 400 801PROC. REF: AMM 31 44 01 000 801, AMM 31 44 01 400 801								
31-61-00-201	OPERATIONAL TEST OF THE EICAS DISPLAY REVERSION							Service ATA:31
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 31.015	AFL	999						
PROC. REF: AMM 31 61 00 710 803PROC. REF: AMM 31 61 00 710 803								
31-61-00-202	OPERATIONAL TEST OF THE PRIMARY FLIGHT DISPLAY REVERSION							Service ATA:31
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 31.020	AFL	999						
PROC. REF: AMM 31 61 00 710 802PROC. REF: AMM 31 61 00 710 802								
31-61-00-203	OPERATIONAL TEST OF THE IRS REVERSION							Service ATA:31
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 31.025	AFL	999						
PROC. REF: AMM 31 61 00 710 805PROC. REF: AMM 31 61 00 710 805								
31-61-00-204	OPERATIONAL TEST OF THE ADC REVERSION							Service ATA:31
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 31.030	AFL	999						
PROC. REF: AMM 31 61 00 710 806PROC. REF: AMM 31 61 00 710 806								
31-61-01-900-801-01	PILOT PFD DISPLAY UNIT							Component ATA:31
PN:K9321060A13	MOS/MSC	18-Feb-22	O/C	TSN 0				
SN:2890042919	HRS	2452:23		TSN 0				
WC#: 31.085	AFL	753		TSN 0				
PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-61-01-900-801-02	PILOT MFD DISPLAY UNIT							Component ATA:31
PN:K9321060A13	MOS/MSC	18-Feb-22	O/C	TSN 0				
SN:2890042920	HRS	2452:23		TSN 0				
WC#: 31.090	AFL	753		TSN 0				
PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801								
31-61-01-900-801-03	PILOT EICAS DISPLAY UNIT							Component ATA:31
PN:K9321060A13	MOS/MSC	18-Feb-22	O/C	TSN 0				
SN:2890042922	HRS	2452:23		TSN 0				
WC#: 31.095	AFL	753		TSN 0				
PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801								
31-61-01-900-801-04	COPILOT EICAS DISPLAY UNIT							Component ATA:31
PN:K9321060A13	MOS/MSC	18-Feb-22	O/C	TSN 0				
SN:2890042923	HRS	2452:23		TSN 0				
WC#: 31.100	AFL	753		TSN 0				
PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801								
31-61-01-900-801-05	COPILOT MFD DISPLAY UNIT							Component ATA:31
PN:K9321060A13	MOS/MSC	18-Feb-22	O/C	TSN 0				
SN:2890043181	HRS	2452:23		TSN 0				
WC#: 31.105	AFL	753		TSN 0				
PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801								
31-61-01-900-801-06	COPILOT PFD DISPLAY UNIT							Component ATA:31
PN:K9321060A13	MOS/MSC	18-Feb-22	O/C	TSN 0				
SN:2890043914	HRS	2452:23		TSN 0				
WC#: 31.110	AFL	753		TSN 0				
PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801PROC. REF: AMM 31 61 01 000 801, AMM 31 61 01 400 801								
31-61-05-900-801-01	LH PANEL- PFD CONTROLLER CONTROL							Component ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.115	AFL	0		TSN 0				
PROC. REF: AMM 31 61 05 000 801, AMM 31 61 05 400 801PROC. REF: AMM 31 61 05 000 801, AMM 31 61 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-61-05-900-801-02		RH PANEL- PFD CONTROLLER CONTROL					Component	ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.115	AFL	0		TSN 0				
PROC. REF: AMM 31 61 05 000 801, AMM 31 61 05 400 801PROC. REF: AMM 31 61 05 000 801, AMM 31 61 05 400 801								
31-61-09-900-801-01		LH MFD CONTROLLER					Component	ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.120	AFL	0		TSN 0				
PROC. REF: AMM 31 61 09 000 801, AMM 31 61 09 400 801PROC. REF: AMM 31 61 09 000 801, AMM 31 61 09 400 801								
31-61-09-900-801-02		RH MFD CONTROLLER					Component	ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.120	AFL	0		TSN 0				
PROC. REF: AMM 31 61 09 000 801, AMM 31 61 09 400 801PROC. REF: AMM 31 61 09 000 801, AMM 31 61 09 400 801								
31-61-13-900-801-01		EICAS (EC-900) CONTROLLER					Component	ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.125	AFL	0		TSN 0				
PROC. REF: AMM 31 61 13 000 801, AMM 31 61 13 400 801PROC. REF: AMM 31 61 13 000 801, AMM 31 61 13 400 801								
31-61-17-900-801-01		PANEL - REVERSION CONTROLLER CONTROL					Component	ATA:31
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.130	AFL	0		TSN 0				
PROC. REF: AMM 31 61 17 000 801, AMM 31 61 17 400 801PROC. REF: AMM 31 61 17 000 801, AMM 31 61 17 400 801								
313301-701 ^U		QUICK ACCESS RECORDER					Component	ATA:31
PN:804-0105	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:16629	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
ELJ 310010 ^U	FDR READOUT AND ANALYSIS OF RECORDED DATA (AS PER AMM 31- 31-00-970-801) .. (NOTE- AS PER CAR M .302) -							Service ATA:31
	MOS	15-Oct-24	24		15-Oct-26		595 d	
	HRS	3314:03						
	AFL	1328						
ATA 32 - LANDING GEAR								
32-00-00-301	CLEANING OF THE LANDING GEAR AND UNDERCARRIAGE AREA							Service ATA:32
	MOS/MSC	30-Jul-09	A/R					OPTIONAL
	HRS	0						
	AFL	0						
PROC. REF: AMM 12 21 00 110 810PROC. REF: AMM 12 21 00 110 810								
32-10-00-201	RESTORATION LH MLG GEAR ASSY OF THE MAIN LANDING GEAR (32-10-00-201)							Service ATA:32
PN:21100-113	MOS	30-Jul-09	240 (+3m/-3m)		30-Jul-29	30-Oct-29	1614 d (+92)	MRB
SN:09MDT0687	HRS	0						
WC#: 32.215	AFL	0						
PROC. REF: AMM 32 11 00 615 801PROC. REF: AMM 32 11 00 615 801								
32-10-00-201	RESTORATION RH MLG GEAR ASSY OF THE MAIN LANDING GEAR (32-10-00-201)							Service ATA:32
PN:21100-114	MOS	30-Jul-09	240 (+3m/-3m)		30-Jul-29	30-Oct-29	1614 d (+92)	MRB
SN:09MDT0681	HRS	0						
WC#: 32.225	AFL	0						
PROC. REF: AMM 32 11 00 615 801PROC. REF: AMM 32 11 00 615 801								
32-10-00-202	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PIN							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.005	AFL	745						
PROC. REF: AMM 32 10 00 220 802PROC. REF: AMM 32 10 00 220 802								
32-10-00-203	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.010	AFL	745						
PROC. REF: AMM 32 10 00 220 803PROC. REF: AMM 32 10 00 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10-00-204	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK-STRUT ASSEMBLY (INTERNAL)							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.015	AFL	0						
PROC. REF: AMM 32 11 01 280 801PROC. REF: AMM 32 11 01 280 801								
32-10-00-206	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) PINTLE PINS							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.020	AFL	0						
PROC. REF: AMM 32 10 00 280 802PROC. REF: AMM 32 10 00 280 802								
32-10-00-207	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) (ATTACHMENT PINS AND LUGS)							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.025	AFL	0						
PROC. REF: AMM 32 10 00 280 803PROC. REF: AMM 32 10 00 280 803								
32-10-00-208	DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.030	AFL	745						
PROC. REF: AMM 32 10 00 220 805PROC. REF: AMM 32 10 00 220 805								
32-10-00-209	SPECIAL DETAILED INSPECTION OF THE TRAILING ARM/AXLE ASSEMBLY							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.030	AFL	0						
PROC. REF: AMM 32 10 00 280 804PROC. REF: AMM 32 10 00 280 804								
32-10-00-210	DETAILED INSPECTION OF THE SHOCK STRUT ASSEMBLY (INTERNAL)							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.035	AFL	745						
PROC. REF: AMM 32 11 01 220 804PROC. REF: AMM 32 11 01 220 804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-10-00-211	DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.040	AFL	745						
PROC. REF: AMM 32 11 17 220 801PROC. REF: AMM 32 11 17 220 801								
32-10-00-212	SPECIAL DETAILED INSPECTION OF THE SIDE BRACE ACTUATOR (INTERNAL)							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.040	AFL	0						
PROC. REF: AMM 32 11 17 280 801PROC. REF: AMM 32 11 17 280 801								
32-10-00-213	DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.045	AFL	745						
PROC. REF: AMM 32 32 01 220 801PROC. REF: AMM 32 32 01 220 801								
32-10-00-214	SPECIAL DETAILED INSPECTION OF THE RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.045	AFL	0						
PROC. REF: AMM 32 32 01 280 801PROC. REF: AMM 32 32 01 280 801								
32-11-00-201	LUBRICATION OF THE MAIN LANDING GEAR (MLG) AND COMPONENTS							Service ATA:32
	MOS	20-Jan-25	15 (+3m/-3m)	Adj 3	20-Jul-26	20-Oct-26	508 d (+92)	MRIP
	HRS	3398:31	250 (+10%/-10%)	Adj 25	3673:31	3698:31	227:35 (+25)	
WC#: 32.050	AFL	1371						
PROC. REF: AMM 12 22 00 640 802PROC. REF: AMM 12 22 00 640 802								
32-11-00-900-801-01	LH PINTLE PIN							Component ATA:32
PN:21112-101	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1682	HRS	0		TSN 0				
WC#: 32.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-900-801-02	RH PINTLE PIN							Component ATA:32
PN:21112-102	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1687	HRS	0		TSN 0				
WC#: 32.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-00-900-802-01	LH CROSS PINTLE PIN							Component ATA:32
PN:21116-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC0859	HRS	0		TSN 0				
WC#: 32.205	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-00-900-802-02	RH CROSS PINTLE PIN							Component ATA:32
PN:21116-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC0854	HRS	0		TSN 0				
WC#: 32.205	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-00-900-803-01	LH MLG SIDE-STAY LOWER PIN							Component ATA:32
PN:21113-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1701	HRS	0		TSN 0				
WC#: 32.420	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-00-900-803-02	RH MLG SIDE-STAY LOWER PIN							Component ATA:32
PN:21113-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1685	HRS	0		TSN 0				
WC#: 32.420	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-00-900-804-01	LH MLG GEAR ASSY							Component ATA:32
PN:21100-113	MOS/MSC	05-Feb-21	O/C	TSR 0				
SN:09MDT0687	HRS	2444:24		TSN 2444:24, TSR 0				
WC#: 32.210	AFL	745		TSN 745, TSR 0				
PROC. REF: CMM 32-10-11, AMM 32 11 00 000 801, AMM 32 11 00 400 801PROC. REF: CMM 32-10-11, AMM 32 11 00 000 801, AMM 32 11 00 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-900-804-02	RH MLG GEAR ASSY							Component ATA:32
PN:21100-114	MOS/MSC	05-Feb-21	O/C	TSR 0				
SN:09MDT0681	HRS	2444:24		TSN 2444:24, TSR 0				
WC#: 32.220	AFL	745		TSN 745, TSR 0				
PROC. REF: CMM 32-10-11, AMM 32 11 00 000 801, AMM 32 11 00 400 801PROC. REF: CMM 32-10-11, AMM 32 11 00 000 801, AMM 32 11 00 400 801								
32-11-01-102	DISCARD THE LH MAIN LANDING GEAR (MLG) UPPER CONNECTING SHOCK STRUT/MAIN FITTING PIN, PART NO. 21260 AND 21274-1							Service ATA:32
PN:21274-1	MOS	30-Jul-09						LIFE LIMIT
SN:08CPS0869	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 01 961 802PROC. REF: AMM 32 11 01 961 802								
32-11-01-102	DISCARD THE RH MAIN LANDING GEAR (MLG) UPPER CONNECTING SHOCK STRUT/MAIN FITTING PIN, PART NO. 21260 AND 21274-1							Service ATA:32
PN:21274-1	MOS	30-Jul-09						LIFE LIMIT
SN:08CPS0846	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 01 961 802PROC. REF: AMM 32 11 01 961 802								
32-11-01-103	DISCARD THE LH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER, PART NO. 21206 AND 21209							Service ATA:32
PN:21208-109	MOS	30-Jul-09						LIFE LIMIT
SN:08GGC00121	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 01 961 803PROC. REF: AMM 32 11 01 961 803								
32-11-01-103	DISCARD THE RH MAIN LANDING GEAR (MLG) SHOCK STRUT CYLINDER, PART NO. 21206 AND 21209							Service ATA:32
PN:21208-109	MOS	30-Jul-09						LIFE LIMIT
SN:08GGC00124	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 01 961 803PROC. REF: AMM 32 11 01 961 803								
32-11-01-104	DISCARD THE LH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON, PART NO. 21216 AND 21218							Service ATA:32
PN:21217-107	MOS	30-Jul-09						LIFE LIMIT
SN:08GGC00131	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 01 961 804PROC. REF: AMM 32 11 01 961 804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-01-104	DISCARD THE RH MAIN LANDING GEAR (MLG) SHOCK STRUT PISTON, PART NO. 21216 AND 21218							Service ATA:32
PN:21217-107	MOS	30-Jul-09						LIFE LIMIT
SN:08GGC00102	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 01 961 804PROC. REF: AMM 32 11 01 961 804								
32-11-01-105	DISCARD LH MLG LOWER CONNECTING SHOCK STRUT/TRAILING ARM PIN - (PN 21194-1)							Service ATA:32
PN:21194-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1036	HRS	0						
	AFL	0	11423		11423		10034	
PROC. REF: AMM 32 11 01 961 801PROC. REF: AMM 32 11 01 961 801								
32-11-01-105	DISCARD THE RH MLG LOWER CONNECTING SHOCK STRUT/TRAILING ARM PIN - (PN 21194-1)							Service ATA:32
PN:21194-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC0988	HRS	0						
	AFL	0	11423		11423		10034	
PROC. REF: AMM 32 11 01 961 801PROC. REF: AMM 32 11 01 961 801								
32-11-01-201	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT EXTENSION							Service ATA:32
	MOS	15-May-24	45 (+3m/-3m)		15-Feb-28 (M)	15-May-28	1083 d (+90)	MRIP
	HRS	3168:27	750 (+50/-50)	Adj 25:57	3944:24	3994:24	498:28 (+50)	
WC#: 32.055	AFL	1205						
PROC. REF: AMM 32 11 01 220 801PROC. REF: AMM 32 11 01 220 801								
32-11-01-900-801-01	LH (MLG) SHOCK STRUT CYLINDER							Component ATA:32
PN:21208-109	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08GGC00121	HRS	0		TSN 0				
WC#: 32.235	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-01-900-801-02	RH (MLG) SHOCK STRUT CYLINDER							Component ATA:32
PN:21208-109	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08GGC00124	HRS	0		TSN 0				
WC#: 32.235	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-01-900-802-01	LH MLG LOWER CONNECTING SHOCK STRUT/TRAILING ARM PIN							Component ATA:32
PN:21194-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1036	HRS	0		TSN 0				
WC#: 32.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-01-900-802-02	RH MLG LOWER CONNECTING SHOCK STRUT/TRAILING ARM PIN							Component ATA:32
PN:21194-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC0988	HRS	0		TSN 0				
WC#: 32.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-01-900-803-01	LH MLG UPPER CONNECTING SHOCK STRUT/MAIN FITTING PIN							Component ATA:32
PN:21274-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08CPS0869	HRS	0		TSN 0				
WC#: 32.245	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-01-900-803-02	RH MLG UPPER CONNECTING SHOCK STRUT/MAIN FITTING PIN							Component ATA:32
PN:21274-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08CPS0846	HRS	0		TSN 0				
WC#: 32.245	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-01-900-804-01	LH (MLG) SHOCK STRUT PISTON							Component ATA:32
PN:21217-107	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08GGC00131	HRS	0		TSN 0				
WC#: 32.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-01-900-804-02	RH (MLG) SHOCK STRUT PISTON							Component ATA:32
PN:21217-107	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08GGC00102	HRS	0		TSN 0				
WC#: 32.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-01-900-805-01	LH MLG SHOCK STRUT							Component ATA:32
PN:21200-113	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0911	HRS	0		TSN 0				
WC#: 32.230	AFL	0		TSN 0				
PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801								
32-11-01-900-805-02	RH MLG SHOCK STRUT							Component ATA:32
PN:21200-113	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0902	HRS	0		TSN 0				
WC#: 32.230	AFL	0		TSN 0				
PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801PROC. REF: AMM 32 11 01 000 801, AMM 32 11 01 400 801								
32-11-09-101	DISCARD THE LH MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE, PART NO. 21410							Service ATA:32
	MOS	30-Jul-09						LIFE LIMIT
	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 09 961 801PROC. REF: AMM 32 11 09 961 801								
32-11-09-101	DISCARD THE RH MAIN LANDING GEAR (MLG) TRAILING ARM/AXLE, PART NO. 21410							Service ATA:32
PN:21410-105	MOS	30-Jul-09						LIFE LIMIT
SN:H0681	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 09 961 801PROC. REF: AMM 32 11 09 961 801								
32-11-09-102	DISCARD THE LH MAIN LANDING GEAR (MLG) PIVOT PIN, PART NO. 21114							Service ATA:32
PN:21114-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1694	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 09 961 802PROC. REF: AMM 32 11 09 961 802								
32-11-09-102	DISCARD THE RH MAIN LANDING GEAR (MLG) PIVOT PIN, PART NO. 21114							Service ATA:32
PN:21114-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1672	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 09 961 802PROC. REF: AMM 32 11 09 961 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-09-900-801-01		LEFT HAND MLG TRAILING ARM/AXLE ASSEMBLY						Component ATA:32
PN:21410-105	MOS/MSC	05-Feb-16	H/T					
SN:H0706	HRS	1866:41		TSN 2015				
WC#: 32.255	AFL	571		TSN 741				
PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801								
32-11-09-900-801-02		RIGHT HAND MLG TRAILING ARM/AXLE ASSEMBLY						Component ATA:32
PN:21410-105	MOS/MSC	30-Jul-09	H/T	TSO 0				
SN:H0681	HRS	0		TSN 0, TSO 0				
WC#: 32.255	AFL	0		TSO 0				
PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801PROC. REF: AMM 32 11 09 000 801, AMM 32 11 09 400 801								
32-11-09-900-802-01		LH MLG PIVOT PIN						Component ATA:32
PN:21114-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1694	HRS	0		TSN 0				
WC#: 32.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-09-900-802-02		RH MLG PIVOT PIN						Component ATA:32
PN:21114-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC1672	HRS	0		TSN 0				
WC#: 32.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-13-900-801-01		LOB MLG HARNESS ASSY						Component ATA:32
PN:21802-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:379	HRS	0		TSN 0				
WC#: 32.265	AFL	0		TSN 0				
PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801								
32-11-13-900-801-02		LIB MLG HARNESS ASSY						Component ATA:32
PN:21801-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:373	HRS	0		TSN 0				
WC#: 32.265	AFL	0		TSN 0				
PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-13-900-801-03	RIB MLG HARNESS ASSY							Component ATA:32
PN:21803-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:372	HRS	0		TSN 0				
WC#: 32.265	AFL	0		TSN 0				
PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801								
32-11-13-900-801-04	ROB MLG HARNESS ASSY							Component ATA:32
PN:21804-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:380	HRS	0		TSN 0				
WC#: 32.265	AFL	0		TSN 0				
PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801PROC. REF: CMM 32-60-03, AMM 32 11 13 000 801, AMM 32 11 13 400 801								
32-11-17-101	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE-STAY LOWER-PIN, PART NO. 21113							Service ATA:32
PN:21113-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1701	HRS	0						
	AFL	0	11599		11599		10210	
PROC. REF: AMM 32 11 17 961 801PROC. REF: AMM 32 11 17 961 801								
32-11-17-101	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE-STAY LOWER-PIN, PART NO. 21113							Service ATA:32
PN:21113-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1685	HRS	0						
	AFL	0	11599		11599		10210	
PROC. REF: AMM 32 11 17 961 801PROC. REF: AMM 32 11 17 961 801								
32-11-17-102	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE ROD END, PART NO. 21510							Service ATA:32
PN:21510-3	MOS	05-Feb-21						LIFE LIMIT
SN:08-22	HRS	2444:24						
	AFL	745	9018	TAC 745	9018		7629	
PROC. REF: AMM 32 11 17 961 802PROC. REF: AMM 32 11 17 961 802								
32-11-17-102	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE ROD END, PART NO. 21510							Service ATA:32
PN:21510-3	MOS	05-Feb-21						LIFE LIMIT
SN:08-18	HRS	2444:24						
	AFL	745	9018	TAC 745	9018		7629	
PROC. REF: AMM 32 11 17 961 802PROC. REF: AMM 32 11 17 961 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-17-103	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON, PART NO. 21512							Service ATA:32
PN:21512-2	MOS	05-Feb-21						LIFE LIMIT
SN:2093	HRS	2444:24						
	AFL	745	9018		9763		8374	
PROC. REF: AMM 32 11 17 961 803PROC. REF: AMM 32 11 17 961 803								
32-11-17-103	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE PISTON, PART NO. 21512							Service ATA:32
PN:21512-2	MOS	05-Feb-21						LIFE LIMIT
SN:2094	HRS	2444:24						
	AFL	745	9018		9763		8374	
PROC. REF: AMM 32 11 17 961 803PROC. REF: AMM 32 11 17 961 803								
32-11-17-104	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER, PART NO. 21521							Service ATA:32
PN:21521-1	MOS	05-Feb-21						LIFE LIMIT
SN:DAY2230	HRS	2444:24						
	AFL	745	9018		9763		8374	
PROC. REF: AMM 32 11 17 961 804PROC. REF: AMM 32 11 17 961 804								
32-11-17-104	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE BRACE CYLINDER, PART NO. 21521							Service ATA:32
PN:21521-1	MOS	05-Feb-21						LIFE LIMIT
SN:DAY904	HRS	2444:24						
	AFL	745	9018	TAC 745	9018		7629	
PROC. REF: AMM 32 11 17 961 804PROC. REF: AMM 32 11 17 961 804								
32-11-17-106	DISCARD THE LH MAIN LANDING GEAR (MLG) SIDE-STAY UPPER-PIN, PART NO. GM227-1725							Service ATA:32
PN:GM227-1725-23	MOS	30-Jul-09		TAC 0				LIFE LIMIT
SN:002	HRS	0		TAC 0				
	AFL	0	25000	TAC 0	25000		23611	
PROC. REF: AMM 32 11 17 961 805PROC. REF: AMM 32 11 17 961 805								
32-11-17-106	DISCARD THE RH MAIN LANDING GEAR (MLG) SIDE-STAY UPPER-PIN, PART NO. GM227-1725							Service ATA:32
PN:GM227-1725-23	MOS	30-Jul-09		TAC 0				LIFE LIMIT
SN:025	HRS	0		TAC 0				
	AFL	0	25000	TAC 0	25000		23611	
PROC. REF: AMM 32 11 17 961 805PROC. REF: AMM 32 11 17 961 805								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-17-900-801-01		LH (MLG) SIDE BRACE ROD END					Component	ATA:32
PN:21510-3	MOS/MSC	05-Feb-21	H/T					
SN:08-22	HRS	2444:24		TSN 2444:24				
WC#: 32.275	AFL	745		TSN 745				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-801-02		RH (MLG) SIDE BRACE ROD END					Component	ATA:32
PN:21510-3	MOS/MSC	05-Feb-21	H/T					
SN:08-18	HRS	2444:24		TSN 2444:24				
WC#: 32.275	AFL	745		TSN 745				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-802-01		LH (MLG) SIDE BRACE PISTON					Component	ATA:32
PN:21512-2	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:2093	HRS	2444:24		TSN 0				
WC#: 32.280	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-802-02		RH (MLG) SIDE BRACE PISTON					Component	ATA:32
PN:21512-2	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:2094	HRS	2444:24		TSN 0				
WC#: 32.280	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-803-01		LH (MLG) SIDE BRACE CYLINDER					Component	ATA:32
PN:21521-1	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:DAY2230	HRS	2444:24		TSN 0				
WC#: 32.285	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-803-02		RH (MLG) SIDE BRACE CYLINDER					Component	ATA:32
PN:21521-1	MOS/MSC	05-Feb-21	H/T					
SN:DAY904	HRS	2444:24		TSN 2444:24				
WC#: 32.285	AFL	745		TSN 745				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-17-900-805-01	LH MLG SIDE-STAY UPPER PIN ASSY							Component ATA:32
PN:GM227-1725-23	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:002	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-805-02	RH MLG SIDE-STAY UPPER PIN ASSY							Component ATA:32
PN:GM227-1725-23	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:025	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-11-17-900-806-01	LH MLG SIDE BRACE ASSEMBLY							Component ATA:32
PN:21501-109	MOS/MSC	05-Feb-21	O/C					
SN:636	HRS	2444:24						
WC#: 32.270	AFL	745						
PROC. REF: CMM 32-30-23, AMM 32 11 17 000 801, AMM 32 11 17 400 801PROC. REF: CMM 32-30-23, AMM 32 11 17 000 801, AMM 32 11 17 400 801								
32-11-17-900-806-02	RH MLG SIDE BRACE ASSEMBLY							Component ATA:32
PN:21500-107	MOS/MSC	05-Feb-21	O/C					
SN:00634	HRS	2444:24						
WC#: 32.270	AFL	745						
PROC. REF: CMM 32-30-23, AMM 32 11 17 000 801, AMM 32 11 17 400 801PROC. REF: CMM 32-30-23, AMM 32 11 17 000 801, AMM 32 11 17 400 801								
32-11-29-101	DISCARD THE LH MAIN LANDING GEAR (MLG) MAIN FITTING, PART NO. 21310							Service ATA:32
PN:21310-105	MOS	30-Jul-09						LIFE LIMIT
SN:08WHM0490	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 29 961 801PROC. REF: AMM 32 11 29 961 801								
32-11-29-101	DISCARD THE RH MAIN LANDING GEAR (MLG) MAIN FITTING, PART NO. 21310							Service ATA:32
PN:21310-106	MOS	30-Jul-09						LIFE LIMIT
SN:08WHM0498	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 29 961 801PROC. REF: AMM 32 11 29 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-29-102	DISCARD THE LH MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO. 21112							Service ATA:32
PN:21112-101	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1682	HRS	0						
	AFL	0	11706		11706		10317	
PROC. REF: AMM 32 11 29 961 802PROC. REF: AMM 32 11 29 961 802								
32-11-29-102	DISCARD THE RH MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO. 21112							Service ATA:32
PN:21112-102	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC1687	HRS	0						
	AFL	0	11706		11706		10317	
PROC. REF: AMM 32 11 29 961 802PROC. REF: AMM 32 11 29 961 802								
32-11-29-103	DISCARD THE LH MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN, PART NO. 21116-1							Service ATA:32
PN:21116-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC0859	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 29 961 803PROC. REF: AMM 32 11 29 961 803								
32-11-29-103	DISCARD THE RH MAIN LANDING GEAR (MLG) PINTLE PIN/CROSS PIN, PART NO. 21116-1							Service ATA:32
PN:21116-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC0854	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 11 29 961 803PROC. REF: AMM 32 11 29 961 803								
32-12-00-201	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOORS							Service ATA:32
	MOS	20-Jan-25	15 (+3m/-3m)	Adj 3	20-Jul-26	20-Oct-26	508 d (+92)	MRIP
	HRS	3398:31	250 (+10%/-10%)	Adj 25	3673:31	3698:31	227:35 (+25)	
WC#: 32.060	AFL	1371						
PROC. REF: AMM 12 22 00 640 819PROC. REF: AMM 12 22 00 640 819								
32-12-00-202	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOOR ACTUATOR							Service ATA:32
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 32.065	AFL	999						
PROC. REF: AMM 12 22 00 640 834PROC. REF: AMM 12 22 00 640 834								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-12-01-900-801-01		LH OUTBOARD MLG DOOR					Component	ATA:32
PN:GM329-1011-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0371	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32 12 01 000 801, AMM 32 12 01 400 801PROC. REF: AMM 32 12 01 000 801, AMM 32 12 01 400 801								
32-12-01-900-801-02		RH OUTBOARD MLG DOOR					Component	ATA:32
PN:GM329-1011-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0367	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32 12 01 000 801, AMM 32 12 01 400 801PROC. REF: AMM 32 12 01 000 801, AMM 32 12 01 400 801								
32-12-05-900-801-01		LH INBOARD MLG DOOR					Component	ATA:32
PN:GS328-0001-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11146	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
PROC. REF: AMM 32 12 05 000 801, AMM 32 12 05 400 801PROC. REF: AMM 32 12 05 000 801, AMM 32 12 05 400 801								
32-12-05-900-801-02		RH INBOARD MLG DOOR					Component	ATA:32
PN:GS328-0001-4	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11146	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
PROC. REF: AMM 32 12 05 000 801, AMM 32 12 05 400 801PROC. REF: AMM 32 12 05 000 801, AMM 32 12 05 400 801								
32-12-09-900-801-01		LEFT HAND MLG MAIN FITTING					Component	ATA:32
PN:21310-105	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08WHM0490	HRS	0		TSN 0				
WC#: 32.300	AFL	0		TSN 0				
PROC. REF: AMM 32 12 09 000 801, AMM 32 12 09 400 801PROC. REF: AMM 32 12 09 000 801, AMM 32 12 09 400 801								
32-12-09-900-801-02		RIGHT HAND MLG MAIN FITTING					Component	ATA:32
PN:21310-106	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08WHM0498	HRS	0		TSN 0				
WC#: 32.300	AFL	0		TSN 0				
PROC. REF: AMM 32 12 09 000 801, AMM 32 12 09 400 801PROC. REF: AMM 32 12 09 000 801, AMM 32 12 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-20-00-201	RESTORATION OF THE NOSE LANDING GEAR							Service ATA:32
PN:GW318-2000-1	MOS	30-Jul-09	240 (+3m/-3m)		30-Jul-29	30-Oct-29	1614 d (+92)	MRB
SN:09MDT0468	HRS	0						
WC#: 32.325	AFL	0						
PROC. REF: AMM 32 21 00 615 801PROC. REF: AMM 32 21 00 615 801								
32-20-00-204	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.070	AFL	745						
PROC. REF: AMM 32 21 00 220 801PROC. REF: AMM 32 21 00 220 801								
32-20-00-205	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) PINTLE PINS							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.070	AFL	0						
PROC. REF: AMM 32 21 00 280 801PROC. REF: AMM 32 21 00 280 801								
32-20-00-206	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.075	AFL	745						
PROC. REF: AMM 32 21 00 220 802PROC. REF: AMM 32 21 00 220 802								
32-20-00-207	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) (ATTACHMENT PINS AND LUGS)							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.075	AFL	0						
PROC. REF: AMM 32 21 00 280 802PROC. REF: AMM 32 21 00 280 802								
32-20-00-208	DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.080	AFL	745						
PROC. REF: AMM 32 21 00 220 803PROC. REF: AMM 32 21 00 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-20-00-209	SPECIAL DETAILED INSPECTION OF THE SLIDING TUBE (INTERNAL), STEERING AND AXLE ASSEMBLY							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.080	AFL	0						
PROC. REF: AMM 32 21 00 280 803PROC. REF: AMM 32 21 00 280 803								
32-20-00-210	DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.085	AFL	745						
PROC. REF: AMM 32 33 01 220 801PROC. REF: AMM 32 33 01 220 801								
32-20-00-211	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR RETRACTION ACTUATOR (INTERNAL)							Service ATA:32
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 32.085	AFL	0						
PROC. REF: AMM 32 33 01 280 801PROC. REF: AMM 32 33 01 280 801								
32-21-00-201	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND COMPONENTS							Service ATA:32
	MOS	20-Jan-25	15 (+3m/-3m)	Adj 3	20-Jul-26	20-Oct-26	508 d (+92)	MRIP
	HRS	3398:31	250 (+10%/-10%)	Adj 25	3673:31	3698:31	227:35 (+25)	
WC#: 32.090	AFL	1371						
PROC. REF: AMM 12 22 00 640 801PROC. REF: AMM 12 22 00 640 801								
32-21-00-900-801-01	NLG GEAR ASSY							Component ATA:32
PN:GW318-2000-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0468	HRS	0		TSN 0				
WC#: 32.325	AFL	0		TSN 0				
PROC. REF: AMM 32 21 00 000 801, AMM 32 21 00 400 801PROC. REF: AMM 32 21 00 000 801, AMM 32 21 00 400 801								
32-21-01-101	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT AXLE, PART NO. 1286-0201/-0203/-0204							Service ATA:32
PN:1286-0204	MOS	05-Feb-21						LIFE LIMIT
SN:L2602	HRS	2444:24						
	AFL	745	15000		15745		14356	
PROC. REF: AMM 32 21 17 961 801PROC. REF: AMM 32 21 17 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-01-102	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT PISTON (SLIDING TUBE), PART NO. 1286-0001 AND 1286-0077							Service ATA:32
PN:1286-0077	MOS	05-Feb-21						LIFE LIMIT
SN:L1100	HRS	2444:24						
	AFL	745	15000		15745		14356	
PROC. REF: AMM 32 21 01 961 803PROC. REF: AMM 32 21 01 961 803								
32-21-01-103	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT MAIN FITTING, PART NO. 1286-0101/-0109							Service ATA:32
PN:1286-0109	MOS	05-Feb-21						LIFE LIMIT
SN:L2613	HRS	2444:24						
	AFL	745	11739		12484		11095	
PROC. REF: AMM 32 21 01 961 802PROC. REF: AMM 32 21 01 961 802								
32-21-01-107	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT RETRACTION ACTUATOR BOLT, PART NO. 1285-0007/-0041							Service ATA:32
PN:PN	MOS	30-Jul-09		TAC 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TAC 0				
	AFL	0	15000	TAC 0	15000		13611	
PROC. REF: AMM 32 33 01 961 802PROC. REF: AMM 32 33 01 961 802								
32-21-01-108	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT LH STEERING ACTUATOR BOLT, PART NO. 1285-0010							Service ATA:32
	MOS	30-Jul-09						LIFE LIMIT
	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 51 21 961 801PROC. REF: AMM 32 51 21 961 801								
32-21-01-108	DISCARD THE NOSE LANDING GEAR (NLG) SHOCK STRUT RH STEERING ACTUATOR BOLT, PART NO. 1285-0010							Service ATA:32
	MOS	30-Jul-09						LIFE LIMIT
	HRS	0						
	AFL	0	15000		15000		13611	
PROC. REF: AMM 32 51 21 961 801PROC. REF: AMM 32 51 21 961 801								
32-21-01-201	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK STRUT EXTENSION							Service ATA:32
	MOS	15-May-24	45 (+3m/-3m)	Adj 3	15-Feb-28 (M)	15-May-28	1083 d (+90)	MRIP
	HRS	3168:27	750 (+50/-50)	Adj 25:57	3944:24	3994:24	498:28 (+50)	
WC#: 32.095	AFL	1205						
PROC. REF: AMM 32 21 01 220 801PROC. REF: AMM 32 21 01 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-01-900-801-01		NOSE LANDING GEAR MAIN FITTING					Component	ATA:32
PN:1286-0109	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:L2613	HRS	2444:24		TSN 0				
WC#: 32.370	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-01-900-802-01		NOSE LANDING GEAR SHOCK STRUT PISTON SLIDING TUBE					Component	ATA:32
PN:1286-0077	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:L1100	HRS	2444:24		TSN 0				
WC#: 32.350	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-01-900-803-01		NLG SHOCK STRUT					Component	ATA:32
PN:22175-109	MOS/MSC	05-Feb-21	O/C	TSR 0				
SN:516	HRS	2444:24		TSR 0				
WC#: 32.340	AFL	745		TSR 0				
PROC. REF: CMM 32-21-01, AMM 32 21 01 000 801, AMM 32 21 01 400 801PROC. REF: CMM 32-21-01, AMM 32 21 01 000 801, AMM 32 21 01 400 801								
32-21-01-900-804-01		NLG PINTLE PIN					Component	ATA:32
PN:1285-0006	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L1459	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-01-900-805-01		NLG DRAG BRACE					Component	ATA:32
PN:22500-105	MOS/MSC	05-Feb-21	O/C	TSO 139, TSR 0				
SN:09MDT0476	HRS	2444:24		TSN 2444:24, TSO 2444:24, TSR 0				
WC#: 32.310	AFL	745		TSN 745, TSR 0				
PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801								
32-21-03-900-801-01		NOSE LANDING GEAR STRUT					Component	ATA:32
PN:1286A0000-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00486	HRS	0		TSN 0				
WC#: 32.330	AFL	0		TSN 0				
PROC. REF: AMM 32 21 03 000 801, AMM 32 21 03 400 801PROC. REF: AMM 32 21 03 000 801, AMM 32 21 03 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-05-101	DISCARD THE NOSE LANDING GEAR (NLG) UPPER DRAG BRACE, PART NO. 22511							Service ATA:32
PN:22511-101	MOS	30-Jul-09						LIFE LIMIT
SN:07ALT0054	HRS	0						
	AFL	0	13028		13028		11639	
PROC. REF: AMM 32 21 05 961 805PROC. REF: AMM 32 21 05 961 805								
32-21-05-102	DISCARD THE NOSE LANDING GEAR (NLG) LOWER DRAG BRACE, PART NO. 22516							Service ATA:32
PN:22516-103	MOS	30-Jul-09						LIFE LIMIT
SN:08ALT0068	HRS	0						
	AFL	0	11967		11967		10578	
PROC. REF: AMM 32 21 05 961 802PROC. REF: AMM 32 21 05 961 802								
32-21-05-105	DISCARD THE NOSE LANDING GEAR (NLG) DRAG BRACE APEX PIN, PART NO. 22530							Service ATA:32
PN:22530-1	MOS	30-Jul-09						LIFE LIMIT
SN:08EXC0399	HRS	0						
	AFL	0	11635		11635		10246	
PROC. REF: AMM 32 21 05 961 803PROC. REF: AMM 32 21 05 961 803								
32-21-05-106	DISCARD THE LH NOSE LANDING GEAR (NLG) DRAG BRACE TRUNNION PIN, PART NO. 22534							Service ATA:32
PN:22534-1	MOS	30-Jul-09						LIFE LIMIT
SN:08CPS0874	HRS	0						
	AFL	0	11667		11667		10278	
PROC. REF: AMM 32 21 05 961 804PROC. REF: AMM 32 21 05 961 804								
32-21-05-106	DISCARD THE RH NOSE LANDING GEAR (NLG) DRAG BRACE TRUNNION PIN, PART NO. 22534							Service ATA:32
PN:22534-1	MOS	30-Jul-09						LIFE LIMIT
SN:08CPS0835	HRS	0						
	AFL	0	11667		11667		10278	
PROC. REF: AMM 32 21 05 961 804PROC. REF: AMM 32 21 05 961 804								
32-21-05-900-801-01	NLG UPPER DRAG BRACE							Component ATA:32
PN:22511-101	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:07ALT0054	HRS	0		TSN 0				
WC#: 32.310	AFL	0		TSN 0				
PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-05-900-802-01		NLG LOWER DRAG BRACE					Component	ATA:32
PN:22516-103	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08ALT0068	HRS	0		TSN 0				
WC#: 32.310	AFL	0		TSN 0				
PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801PROC. REF: CMM 32-70-07, AMM 32 21 05 000 801, AMM 32 21 05 400 801								
32-21-05-900-803-01		LH NLG DRAG BRACE TRUNNION PIN					Component	ATA:32
PN:22534-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08CPS0874	HRS	0		TSN 0				
WC#: 32.355	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-05-900-803-02		RH NLG DRAG BRACE TRUNNION PIN					Component	ATA:32
PN:22534-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08CPS0835	HRS	0		TSN 0				
WC#: 32.355	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-05-900-804-01		NLG APEX DRAG BRACE PIN					Component	ATA:32
PN:22530-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08EXC0399	HRS	0		TSN 0				
WC#: 32.780	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-05-900-805-01		DOWNLOCK NLG ACTUATOR					Component	ATA:32
PN:22570-101	MOS/MSC	05-Feb-21	O/C					
SN:09MDT0714	HRS	2444:24		TSN 2444:24				
WC#: 32.335	AFL	745		TSN 745				
PROC. REF: AMM 32 21 05 000 801, AMM 32 21 05 400 801PROC. REF: AMM 32 21 05 000 801, AMM 32 21 05 400 801								
32-21-05-900-806-01		NLG DRAG BRACE FORWARD STABILIZER LINK					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.345	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-05-900-807-01		NLG DRAG BRACE AFT STABILIZER LINK					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.345	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-07-900-801-01		NLG LOWER PIN					Component	ATA:32
PN:1285-0042	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L0879	HRS	2444:24		TSN 0				
WC#: 32.360	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-07-900-801-02		NLG PIVOT PIN					Component	ATA:32
PN:1285-0006	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:L1451	HRS	2444:24		TSN 0				
WC#: 32.365	AFL	745		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-21-09-900-801-01		LH NLG HARNESS					Component	ATA:32
PN:22800-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:374	HRS	0		TSN 0				
WC#: 32.375	AFL	0		TSN 0				
PROC. REF: CMM 32-60-04, AMM 32 21 09 000 801, AMM 32 21 09 400 801PROC. REF: CMM 32-60-04, AMM 32 21 09 000 801, AMM 32 21 09 400 801								
32-21-09-900-802-01		RH NLG HARNESS					Component	ATA:32
PN:22801-107	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:360	HRS	0		TSN 0				
WC#: 32.375	AFL	0		TSN 0				
PROC. REF: CMM 32-60-04, AMM 32 21 09 000 802, AMM 32 21 09 400 802PROC. REF: CMM 32-60-04, AMM 32 21 09 000 802, AMM 32 21 09 400 802								
32-21-17-900-801-01		NOSE LANDING GEAR SHOCK STRUT AXLE					Component	ATA:32
PN:1286-0204	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:L2602	HRS	2444:24		TSN 0				
WC#: 32.305	AFL	745		TSN 0				
PROC. REF: AMM 32 21 00 000 801, AMM 32 21 00 400 801PROC. REF: AMM 32 21 00 000 801, AMM 32 21 00 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-22-00-101	SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR FORWARD DOORS							Service ATA:32
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 32.100	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-32-20-001, NDT MT-32-20-001PROC. REF: NDT ET-32-20-001, NDT MT-32-20-001								
32-22-00-201	LUBRICATION OF THE NOSE LANDING GEAR (NLG) DOORS							Service ATA:32
	MOS	20-Jan-25	15 (+3m/-3m)	Adj 3	20-Jul-26	20-Oct-26	508 d (+92)	MRIP
	HRS	3398:31	250 (+10%/-10%)	Adj 25	3673:31	3698:31	227:35 (+25)	
WC#: 32.105	AFL	1371						
PROC. REF: AMM 12 22 00 640 803PROC. REF: AMM 12 22 00 640 803								
32-22-00-202	DETAILED INSPECTION OF THE NOSE-GEAR-DOOR HINGES AND ACTUATOR ATTACHMENT FITTING							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.110	AFL	745						
PROC. REF: AMM 32 22 01 220 801PROC. REF: AMM 32 22 01 220 801								
32-22-05-900-801-01	NLG AFT DOOR ASSY							Component ATA:32
PN:GS328-0005-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B419	HRS	0		TSN 0				
WC#: 32.380	AFL	0		TSN 0				
PROC. REF: AMM 32 22 05 000 801, AMM 32 22 05 400 801PROC. REF: AMM 32 22 05 000 801, AMM 32 22 05 400 801								
32-22-17-900-801-01	LH NLG FWD DOOR ASSY							Component ATA:32
PN:GS328-0003-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B363	HRS	0		TSN 0				
WC#: 32.385	AFL	0		TSN 0				
PROC. REF: AMM 32 22 17 000 801, AMM 32 22 17 400 801PROC. REF: AMM 32 22 17 000 801, AMM 32 22 17 400 801								
32-22-17-900-801-02	RH NLG FWD DOOR ASSY							Component ATA:32
PN:GS328-0004-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B359	HRS	0		TSN 0				
WC#: 32.385	AFL	0		TSN 0				
PROC. REF: AMM 32 22 17 000 801, AMM 32 22 17 400 801PROC. REF: AMM 32 22 17 000 801, AMM 32 22 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-31-01-900-801-01		LANDING GEAR CONTROL PANEL						Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.395	AFL	0		TSN 0				
PROC. REF: AMM 32 31 01 000 801, AMM 32 31 01 400 801PROC. REF: AMM 32 31 01 000 801, AMM 32 31 01 400 801								
32-31-05-900-801-01		LANDING GEAR CONTROL HANDLE						Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0		TSN 0				
PROC. REF: AMM 32 31 05 000 801, AMM 32 31 05 400 801PROC. REF: AMM 32 31 05 000 801, AMM 32 31 05 400 801								
32-31-09-101		VISUAL CHECK OF THE LANDING-GEAR ELECTRONIC CONTROL UNIT (LG ECU) (CMR**)						Service ATA:32
	MOS	10-Mar-23						CMR
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 32.115	AFL	999						
PROC. REF: AMM 32 31 09 210 801PROC. REF: AMM 32 31 09 210 801								
32-31-09-900-801-01		LANDING GEAR ECU						Component ATA:32
PN:GW415-5100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E474	HRS	0		TSN 0				
WC#: 32.400	AFL	0		TSN 0				
PROC. REF: AMM 32 31 09 000 801, AMM 32 31 09 400 801PROC. REF: AMM 32 31 09 000 801, AMM 32 31 09 400 801								
32-31-13-900-801-01		NO. 2 SYSTEM L/G CONTROL SELECTOR VALVE						Component ATA:32
PN:GW415-6025-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:NGL/2103/08	HRS	0		TSN 0				
WC#: 32.405	AFL	0		TSN 0				
PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801								
32-31-13-900-801-02		NO. 3 SYSTEM L/G CONTROL SELECTOR VALVE						Component ATA:32
PN:GW415-6025-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:NGL/2105/08	HRS	0		TSN 0				
WC#: 32.405	AFL	0		TSN 0				
PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-31-13-900-801-03	L/G DOOR CONTROL SELECTOR VALVE							Component ATA:32
PN:GW415-6025-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:NGL/2127/08	HRS	0		TSN 0				
WC#: 32.405	AFL	0		TSN 0				
PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801PROC. REF: AMM 32 31 13 000 801, AMM 32 31 13 400 801								
32-31-21-900-801-01	CHECK, SIDE BRACE CONTROL VALVE							Component ATA:32
PN:GW415-6075-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:NGL/1392/08	HRS	0		TSN 0				
WC#: 32.410	AFL	0		TSN 0				
PROC. REF: AMM 32 31 21 000 801, AMM 32 31 21 400 801PROC. REF: AMM 32 31 21 000 801, AMM 32 31 21 400 801								
32-32-01-105	DISCARD THE LH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 21600							Service ATA:32
PN:21600-101	MOS	30-Jul-09						LIFE LIMIT
SN:09MDT0778	HRS	0						
	AFL	0	25000		25000		23611	
PROC. REF: AMM 32 32 01 961 801PROC. REF: AMM 32 32 01 961 801								
32-32-01-105	DISCARD THE RH MAIN LANDING GEAR (MLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 21600							Service ATA:32
PN:21600-102	MOS	05-Feb-21						LIFE LIMIT
SN:09MDT0760	HRS	2444:24						
	AFL	745	25000	TAC 745	25000		23611	
PROC. REF: AMM 32 32 01 961 801PROC. REF: AMM 32 32 01 961 801								
32-32-01-900-801-01	LH MLG RETRACTION ACTUATOR ASSEMBLY							Component ATA:32
PN:21600-101	MOS/MSC	05-Feb-21	H/T	TSN 139, TSR 0				
SN:09MDT0778	HRS	2444:24		TSN 2444:24, TSR 0				
WC#: 32.415	AFL	745		TSN 745, TSR 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-801-02	RH MLG RETRACTION ACTUATOR ASSEMBLY							Component ATA:32
PN:21600-102	MOS/MSC	05-Feb-21	H/T	TSN 139, TSR 0				
SN:09MDT0760	HRS	2444:24		TSN 2444:24, TSR 0				
WC#: 32.415	AFL	745		TSN 745, TSR 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-01-900-802-01		LH MLG RETRACTION ACTUATOR PIN					Component	ATA:32
PN:21118-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:08EXC0818	HRS	0		TSN 0				
WC#: 32.430	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-802-02		RH MLG RETRACTION ACTUATOR PIN					Component	ATA:32
PN:21118-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:08EXC0802	HRS	0		TSN 0				
WC#: 32.430	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-803-01		LH (MLG) RETRACTION ACTUATOR CYLINDER					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.435	AFL	0		TSN 0				
PROC. REF: CMM 32-30-27PROC. REF: CMM 32-30-27								
32-32-01-900-803-02		RH (MLG) RETRACTION ACTUATOR CYLINDER					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.435	AFL	0		TSN 0				
PROC. REF: CMM 32-30-27PROC. REF: CMM 32-30-27								
32-32-01-900-804-01		LH (MLG) RETRACTION ACTUATOR PISTON					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.440	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-804-02		RH (MLG) RETRACTION ACTUATOR PISTON					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.440	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-01-900-805-01	LH (MLG) RETRACTION ACTUATOR ROD END							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.445	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-805-02	RH (MLG) RETRACTION ACTUATOR ROD END							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.445	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-806-01	LH (MLG) RETRACTION ACTUATOR GLAND NUT							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.450	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-01-900-806-02	RH (MLG) RETRACTION ACTUATOR GLAND NUT							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.450	AFL	0		TSN 0				
PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801PROC. REF: AMM 32 32 01 000 801, AMM 32 32 01 400 801								
32-32-05-107	DISCARD THE LH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY, PART NO. 21900							Service ATA:32
PN:21900-103	MOS	30-Jul-09						LIFE LIMIT
SN:08SM00051	HRS	0						
	AFL	0	25000		25000		23611	
PROC. REF: AMM 32 32 05 961 801PROC. REF: AMM 32 32 05 961 801								
32-32-05-107	DISCARD THE RH MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY, PART NO. 21900							Service ATA:32
PN:21900-104	MOS	30-Jul-09						LIFE LIMIT
SN:08SM00056	HRS	0						
	AFL	0	25000		25000		23611	
PROC. REF: AMM 32 32 05 961 801PROC. REF: AMM 32 32 05 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-05-900-801-01	LH MLG UPLOCK							Component ATA:32
PN:21900-103	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08SM00051	HRS	0		TSN 0				
WC#: 32.455	AFL	0		TSN 0				
PROC. REF: CMM 32-30-24, AMM 32 32 05 000 801, AMM 32 32 05 400 801PROC. REF: CMM 32-30-24, AMM 32 32 05 000 801, AMM 32 32 05 400 801								
32-32-05-900-801-02	RH MLG UPLOCK							Component ATA:32
PN:21900-104	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08SM00056	HRS	0		TSN 0				
WC#: 32.455	AFL	0		TSN 0				
PROC. REF: CMM 32-30-24, AMM 32 32 05 000 801, AMM 32 32 05 400 801PROC. REF: CMM 32-30-24, AMM 32 32 05 000 801, AMM 32 32 05 400 801								
32-32-05-900-802-01	LH (MLG) UPLOCK ASSEMBLY SIDE PLATE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.460	AFL	0		TSN 0				
PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801								
32-32-05-900-802-02	RH (MLG) UPLOCK ASSEMBLY SIDE PLATE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.460	AFL	0		TSN 0				
PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801								
32-32-05-900-803-01	LH (MLG) UPLOCK ASSEMBLY LATCH							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.465	AFL	0		TSN 0				
PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801								
32-32-05-900-803-02	RH (MLG) UPLOCK ASSEMBLY LATCH							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.465	AFL	0		TSN 0				
PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801PROC. REF: AMM 32 32 05 000 801, AMM 32 32 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-05-900-804-01	LH (MLG) UPLOCK ASSEMBLY LOCK LEVER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.470	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-05-900-804-02	RH (MLG) UPLOCK ASSEMBLY LOCK LEVER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.470	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-05-900-805-01	LH (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.475	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-05-900-805-02	RH (MLG) UPLOCK ASSEMBLY ACTUATOR CYLINDER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.475	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-05-900-806-01	LH (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-05-900-806-02	RH (MLG) UPLOCK ASSEMBLY ACTUATOR PISTON							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-05-900-807-01	LH (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.485	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-05-900-807-02	RH (MLG) UPLOCK ASSEMBLY MANUAL RELEASE LEVER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.485	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-32-09-900-801-01	LH MLG DOOR INBOARD ACTUATOR							Component ATA:32
PN:GW412-2000-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0629	HRS	0		TSN 0				
WC#: 32.490	AFL	0		TSN 0				
PROC. REF: CMM 32-30-32, AMM 32 32 09 000 801, AMM 32 32 09 400 801PROC. REF: CMM 32-30-32, AMM 32 32 09 000 801, AMM 32 32 09 400 801								
32-32-09-900-801-02	RH MLG DOOR INBOARD ACTUATOR							Component ATA:32
PN:GW412-2000-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0628	HRS	0		TSN 0				
WC#: 32.490	AFL	0		TSN 0				
PROC. REF: CMM 32-30-32, AMM 32 32 09 000 801, AMM 32 32 09 400 801PROC. REF: CMM 32-30-32, AMM 32 32 09 000 801, AMM 32 32 09 400 801								
32-32-13-101	DISCARD THE LH MAIN-GEAR DOOR UPLOCK, PART NO. GW415-2200-5/6							Service ATA:32
PN:GW415-2200-5	MOS	30-Jul-09						LIFE LIMIT
SN:09SM00002	HRS	0						
	AFL	0	6250		6250		4861	
PROC. REF: AMM 32 32 13 961 801PROC. REF: AMM 32 32 13 961 801								
32-32-13-101	DISCARD THE RH MAIN-GEAR DOOR UPLOCK, PART NO. GW415-2200-5/6							Service ATA:32
PN:GW415-2200-6	MOS	30-Jul-09						LIFE LIMIT
SN:08SM00048	HRS	0						
	AFL	0	6250		6250		4861	
PROC. REF: AMM 32 32 13 961 801PROC. REF: AMM 32 32 13 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-13-900-801-01	LH MLG DOOR INBOARD UPLOCK							Component ATA:32
PN:GW415-2200-5	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:09SM00002	HRS	0		TSN 0				
WC#: 32.495	AFL	0		TSN 0				
PROC. REF: CMM 32-30-28, AMM 32 32 13 000 801, AMM 32 32 13 400 801PROC. REF: CMM 32-30-28, AMM 32 32 13 000 801, AMM 32 32 13 400 801								
32-32-13-900-801-02	RH MLG DOOR INBOARD UPLOCK							Component ATA:32
PN:GW415-2200-6	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08SM00048	HRS	0		TSN 0				
WC#: 32.580	AFL	0		TSN 0				
PROC. REF: CMM 32-30-28, AMM 32 32 13 000 801, AMM 32 32 13 400 801PROC. REF: CMM 32-30-28, AMM 32 32 13 000 801, AMM 32 32 13 400 801								
32-32-25-900-801-01	CHECK, BRAKE CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.500	AFL	0		TSN 0				
PROC. REF: AMM 32 43 29 000 801, AMM 32 43 29 400 801PROC. REF: AMM 32 43 29 000 801, AMM 32 43 29 400 801								
32-33-01-105	DISCARD THE NOSE LANDING GEAR (NLG) RETRACTION ACTUATOR ASSEMBLY, PART NO. 22400-101/-103							Service ATA:32
PN:22400-103	MOS	30-Jul-09						LIFE LIMIT
SN:09MDT0308	HRS	0						
	AFL	0	20000		20000		18611	
PROC. REF: AMM 32 33 01 961 801PROC. REF: AMM 32 33 01 961 801								
32-33-01-111	RESTORATION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-1A11-32-022 PART C)							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 32 21 01 610 801PROC. REF: AMM 32 21 01 610 801								
32-33-01-112	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) SHOCK-STRUT ASSEMBLY TO RETRACTION-ACTUATOR MAIN-FITTING JOINT (POST SB 700-1A11-32-022 PART C)							Service ATA:32
	MOS/MSC	30-Jul-09	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32 21 00 220 804PROC. REF: AMM 32 21 00 220 804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
32-33-01-900-801-01		NLG RETRACTION ACTUATOR						Component	ATA:32
PN:22400-103	MOS/MSC	05-Feb-21	H/T	TSN 139, TSR 0					
SN:09MDT0308	HRS	2444:24	TSN 2444:24, TSR 0						
WC#: 32.510	AFL	745	TSN 745, TSR 0						
PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801									
32-33-01-900-802-01		NLG RETRACTION ACTUATOR CYLINDER						Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.515	AFL	0	TSN 0						
PROC. REF: CMM 32-30-25, AMM 32 33 01 000 801, AMM 32 33 01 400 801PROC. REF: CMM 32-30-25, AMM 32 33 01 000 801, AMM 32 33 01 400 801									
32-33-01-900-803-01		NLG RETRACTION ACTUATOR PISTON						Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.520	AFL	0	TSN 0						
PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801									
32-33-01-900-804-01		NLG RETRACTION ACTUATOR GLAND NUT						Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.525	AFL	0	TSN 0						
PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801									
32-33-01-900-805-01		NLG RETRACTION ACTUATOR ROD END						Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.530	AFL	0	TSN 0						
PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801									
32-33-01-900-811-01		NLG SHOCK STRUT RETRACTION ACTUATOR BOLT						Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	H/T	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 32.315	AFL	0	TSN 0						
PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801PROC. REF: AMM 32 33 01 000 801, AMM 32 33 01 400 801									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-33-05-106	DISCARD THE NOSE LANDING GEAR (NLG) UPLOCK ASSEMBLY, PART NO. 22600-101/-103							Service ATA:32
PN:22600-103	MOS	30-Jul-09						LIFE LIMIT
SN:09SM00003	HRS	0						
	AFL	0	25000		25000		23611	
PROC. REF: AMM 32 33 05 961 801PROC. REF: AMM 32 33 05 961 801								
32-33-05-900-801-01	NLG UPLOCK							Component ATA:32
PN:22600-103	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:09SM00003	HRS	0		TSN 0				
WC#: 32.535	AFL	0		TSN 0				
PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801								
32-33-05-900-802-01	NLG UPLOCK ACTUATOR CYLINDER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.540	AFL	0		TSN 0				
PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801								
32-33-05-900-803-01	NLG UPLOCK ACTUATOR PISTON							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.545	AFL	0		TSN 0				
PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801								
32-33-05-900-804-01	NLG UPLOCK ASSEMBLY HOOK							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.550	AFL	0		TSN 0				
PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801								
32-33-05-900-805-01	NLG UPLOCK ASSEMBLY LOCK LEVER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.555	AFL	0		TSN 0				
PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-33-05-900-806-01	NLG UPLOCK ASSEMBLY STOP PIN							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.560	AFL	0		TSN 0				
PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801PROC. REF: AMM 32 33 05 000 801, AMM 32 33 05 400 801								
32-33-09-900-801-01	NLG FWD DOOR ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.565	AFL	0		TSN 0				
PROC. REF: CMM 32-30-30, AMM 32 33 09 000 801, AMM 32 33 09 400 801PROC. REF: CMM 32-30-30, AMM 32 33 09 000 801, AMM 32 33 09 400 801								
32-33-13-101	DISCARD THE NOSE-GEAR FORWARD-DOOR UPLOCK, PART NO. GW415-2300-1							Service ATA:32
PN:GW415-2300-3	MOS/MSC	30-Jul-09	N/A					
SN:09MDT0477	HRS	0						
	AFL	0						
PROC. REF: AMM 32 33 13 961 801PROC. REF: AMM 32 33 13 961 801								
32-33-13-900-801-01	NLG FORWARD DOOR UPLOCK							Component ATA:32
PN:GW415-2300-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0477	HRS	0		TSN 0				
WC#: 32.570	AFL	0		TSN 0				
PROC. REF: CMM 32-30-31, AMM 32 33 13 000 802, AMM 32 33 13 400 802PROC. REF: CMM 32-30-31, AMM 32 33 13 000 802, AMM 32 33 13 400 802								
32-33-14-900-801-01	NLG DOOR QUADRANT							Component ATA:32
PN:GW413-1000-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DCL-348	HRS	0		TSN 0				
WC#: 32.575	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-34-00-101	FUNCTIONAL TEST OF THE LANDING-GEAR EMERGENCY EXTENSION (CMR*)							Service ATA:32
	MOS	21-Jul-21						AIRWORTHINESS
	HRS	2446:06	1500		3946:06		500:10	
	AFL	747						
PROC. REF: AMM 32 34 00 720 801PROC. REF: AMM 32 34 00 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-34-00-202	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE NOSE LANDING-GEAR WHEEL-WELL, FS202.75+32.00 TO FS280.00+32.00							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.125	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 34 00 220 801PROC. REF: AMM 32 34 00 220 801								
32-34-00-203	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE FORWARD AVIONICS COMPARTMENT, FS202.75+32.00 TO FS280.00+32.00							Service ATA:32
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 32.130	AFL	745						
PROC. REF: AMM 32 34 00 220 802PROC. REF: AMM 32 34 00 220 802								
32-34-00-204	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MAIN AVIONICS COMPARTMENT, FS280.00+32.00 TO FS557.00							Service ATA:32
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 32.135	AFL	745						
PROC. REF: AMM 32 34 00 220 803PROC. REF: AMM 32 34 00 220 803								
32-34-00-205	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CONTROL PATH IN THE MID-LOWER FUSELAGE COMPARTMENT, FS557.00 TO FS781.00							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 32.140	AFL	745						
PROC. REF: AMM 32 34 00 220 804PROC. REF: AMM 32 34 00 220 804								
32-34-00-206	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY EXTENSION CONTROL PATH IN THE MAIN LANDING-GEAR WHEEL-WELL, FS719.30 TO FS781.00							Service ATA:32
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 32.145	AFL	745						
PROC. REF: AMM 32 34 00 220 805PROC. REF: AMM 32 34 00 220 805								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-34-01-900-801-01	MLG QUADRANT							Component ATA:32
PN:GW413-7000-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DCL363	HRS	0		TSN 0				
WC#: 32.585	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-34-01-900-802-01	NOSE LANDING GEAR QUADRANT							Component ATA:32
PN:GW413-2000-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DCL-373	HRS	0		TSN 0				
WC#: 32.590	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-34-01-900-803-01	MANUAL RELEASE HANDLE							Component ATA:32
PN:GW415-7100-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0394	HRS	0		TSN 0				
WC#: 32.595	AFL	0		TSN 0				
PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801								
32-34-02-900-801-01	MANUAL RELEASE QUADRANT							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.600	AFL	0		TSN 0				
PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801PROC. REF: AMM 32 34 01 000 801, AMM 32 34 01 400 801								
32-34-05-900-801-01	HYD S/O DUMP MANUAL RELEASE VALVE							Component ATA:32
PN:GW415-6101-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09MDT0481	HRS	0		TSN 0				
WC#: 32.605	AFL	0		TSN 0				
PROC. REF: AMM 32 34 05 000 801, AMM 32 34 05 400 801PROC. REF: AMM 32 34 05 000 801, AMM 32 34 05 400 801								
32-34-05-900-801-02	HYDRAULIC DUMP VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.610	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-34-09-900-801-01	MAIN LANDING GEAR MRS ALTERNATE POWER VALVE							Component ATA:32
PN:GW415-6051-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:08MDT0483	HRS	0		TSN 0				
WC#: 32.505	AFL	0		TSN 0				
PROC. REF: AMM 32 34 09 000 801, AMM 32 34 09 400 801PROC. REF: AMM 32 34 09 000 801, AMM 32 34 09 400 801								
32-34-09-900-801-02	ALTERNATE POWER VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.615	AFL	0		TSN 0				
PROC. REF: AMM 32 34 09 000 801, AMM 32 34 09 400 801PROC. REF: AMM 32 34 09 000 801, AMM 32 34 09 400 801								
32-40-00-201	FUNCTIONAL TEST OF THE BRAKE ACCUMULATORS							Service ATA:32
	MOS	15-Oct-24	30 (+3m/-3m)	Adj 3	15-Jul-27	15-Oct-27	868 d (+92)	MRIP
	HRS	3314:03	500 (+50/-50)		3814:03 (M)	3864:03	368:07 (+50)	
WC#: 32.150	AFL	1328						
PROC. REF: AMM 32 40 00 720 801, AMM 32 43 37 720 801, AMM 32 44 05 720 801PROC. REF: AMM 32 40 00 720 801, AMM 32 43 37 720 801, AMM 32 44 05 720 801								
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 1 ASSY MLG WHEEL - (32-41-01-201)							Service ATA:32
PN:KGC991-1119-9	MOS/MSC	21-Jul-21	T/C					MRB
SN:1984	HRS	2446:06						
WC#: 32.620	AFL	747						
PROC. REF: AMM 32 41 01 280 801PROC. REF: AMM 32 41 01 280 801								
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 2 ASSY MLG WHEEL - (32-41-01-201)							Service ATA:32
PN:3-1599	MOS/MSC	21-Jul-21	T/C					MRB
SN:1959	HRS	2446:06						
WC#: 32.620	AFL	747						
PROC. REF: AMM 32 41 01 280 801PROC. REF: AMM 32 41 01 280 801								
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 3 ASSY MLG WHEEL - (32-41-01-201)							Service ATA:32
PN:3-1599	MOS/MSC	21-Jul-21	T/C					MRB
SN:1981	HRS	2446:06						
WC#: 32.620	AFL	747						
PROC. REF: AMM 32 41 01 280 801PROC. REF: AMM 32 41 01 280 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-01-201	SPECIAL DETAILED INSPECTION NO. 4 ASSY MLG WHEEL - (32-41-01-201)							Service ATA:32
PN:3-1599	MOS/MSC	21-Jul-21	T/C					MRB
SN:1970	HRS	2446:06						
WC#: 32.620	AFL	747						
PROC. REF: AMM 32 41 01 280 801PROC. REF: AMM 32 41 01 280 801								
32-41-01-202	DETAILED INSPECTION NO. 1 ASSY MLG WHEEL - (32-41-01-202)							Service ATA:32
PN:KGC991-1119-9	MOS/MSC	21-Jul-21	T/C					MRB
SN:1984	HRS	2446:06						
WC#: 32.620	AFL	747						
PROC. REF: AMM 32 41 01 220 801PROC. REF: AMM 32 41 01 220 801								
32-41-01-202	DETAILED INSPECTION NO. 2 ASSY MLG WHEEL - (32-41-01-202)							Service ATA:32
PN:3-1599	MOS/MSC	21-Jul-21	T/C					MRB
SN:1959	HRS	2446:06						
WC#: 32.620	AFL	747						
PROC. REF: AMM 32 41 01 220 801PROC. REF: AMM 32 41 01 220 801								
32-41-01-202	DETAILED INSPECTION NO. 3 ASSY MLG WHEEL - (32-41-01-202)							Service ATA:32
PN:3-1599	MOS/MSC	24-Jun-24	T/C					MRB
SN:1981	HRS	3221:01						
WC#: 32.620	AFL	1253						
PROC. REF: AMM 32 41 01 220 801PROC. REF: AMM 32 41 01 220 801								
32-41-01-202	DETAILED INSPECTION NO. 4 ASSY MLG WHEEL - (32-41-01-202)							Service ATA:32
PN:3-1599	MOS/MSC	24-Jun-24	T/C					MRB
SN:1970	HRS	3221:01						
WC#: 32.620	AFL	1253						
PROC. REF: AMM 32 41 01 220 801PROC. REF: AMM 32 41 01 220 801								
32-41-01-900-801-01	NO. 1 ASSY MLG WHEEL							Component ATA:32
PN:KGC991-1119-9	MOS/MSC	20-Jan-25	O/C	TSO 42, TSR 0				
SN:1984	HRS	3398:31		TSO 952:25, TSR 0				
WC#: 32.620	AFL	1371		TSO 624, TSR 0				
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-01-900-801-02		NO. 2 ASSY MLG WHEEL						Component ATA:32
PN:3-1599	MOS/MSC	15-May-24	O/C	TSO 34, TSR 20				
SN:1959	HRS	3168:27	TSO 722:21, TSR 471:45					
WC#: 32.620	AFL	1205	TSO 458, TSR 287					
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801								
32-41-01-900-801-03		NO. 3 ASSY MLG WHEEL						Component ATA:32
PN:3-1599	MOS/MSC	24-Jun-24	O/C	TSO 35, TSR 19				
SN:1981	HRS	3221:01	TSO 774:55, TSR 470:52					
WC#: 32.620	AFL	1253	TSO 506, TSR 302					
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801								
32-41-01-900-801-04		NO. 4 ASSY MLG WHEEL						Component ATA:32
PN:3-1599	MOS/MSC	24-Jun-24	O/C	TSO 35, TSR 19				
SN:1970	HRS	3221:01	TSO 774:55, TSR 470:52					
WC#: 32.620	AFL	1253	TSO 506, TSR 302					
PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: CMM 32-48-22, CMM 32-48-30, AMM 32 41 01 000 801, AMM 32 41 01 400 801								
32-41-01-900-802-01		NO. 1 MLG TIRE						Component ATA:32
PN:382K02-1	MOS/MSC	20-Jan-25	O/C	TSN 0				
SN:40970737	HRS	3398:31	TSN 0					
WC#: 32.620	AFL	1371	TSN 0					
PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801								
32-41-01-900-802-02		NO. 2 MLG TIRE						Component ATA:32
PN:382K02-1	MOS/MSC	15-May-24	O/C	TSN 0				
SN:40020988	HRS	3168:27	TSN 0					
WC#: 32.620	AFL	1205	TSN 0					
PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801								
32-41-01-900-802-03		NO. 3 MLG TIRE						Component ATA:32
PN:382K02-1	MOS/MSC	24-Jun-24	O/C	TSN 0				
SN:40400843	HRS	3221:01	TSN 0					
WC#: 32.620	AFL	1253	TSN 0					
PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-01-900-802-04	NO. 4 MLG TIRE							Component ATA:32
PN:382K02-1	MOS/MSC	24-Jun-24	O/C	TSN 0				
SN:41341008	HRS	3221:01		TSN 0				
WC#: 32.620	AFL	1253		TSN 0				
PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801PROC. REF: AMM 32 41 01 000 801, AMM 32 41 01 400 801								
32-42-01-201	SPECIAL DETAILED INSPECTION LH ASSY NLG WHEEL - (32-42-01-201)							Service ATA:32
PN:3-1560	MOS/MSC	25-Jul-21	T/C				MRB	
SN:1330	HRS	2446:06						
WC#: 32.625	AFL	747						
PROC. REF: AMM 32 42 01 280 801PROC. REF: AMM 32 42 01 280 801								
32-42-01-201	SPECIAL DETAILED INSPECTION RH ASSY NLG WHEEL - (32-42-01-201)							Service ATA:32
PN:3-1560	MOS/MSC	25-Jul-21	T/C				MRB	
SN:1326	HRS	2446:06						
WC#: 32.625	AFL	747						
PROC. REF: AMM 32 42 01 280 801PROC. REF: AMM 32 42 01 280 801								
32-42-01-202	DETAILED INSPECTION LH ASSY NLG WHEEL - (32-42-01-202)							Service ATA:32
PN:3-1560	MOS/MSC	05-Jun-23	T/C				MRB	
SN:1330	HRS	2913:47						
WC#: 32.625	AFL	1041						
PROC. REF: AMM 32 42 01 220 801PROC. REF: AMM 32 42 01 220 801								
32-42-01-202	DETAILED INSPECTION RH ASSY NLG WHEEL - (32-42-01-202)							Service ATA:32
PN:3-1560	MOS/MSC	05-Jun-23	T/C				MRB	
SN:1326	HRS	2913:47						
WC#: 32.625	AFL	1041						
PROC. REF: AMM 32 42 01 220 801PROC. REF: AMM 32 42 01 220 801								
32-42-01-900-801-01	LH ASSY NLG WHEEL							Component ATA:32
PN:3-1560	MOS/MSC	20-Jan-25	O/C	TSR 0				
SN:1330	HRS	3398:31		TSR 0				
WC#: 32.625	AFL	1371		TSR 0				
PROC. REF: CMM 32-48-23, AMM 32 42 01 000 801, AMM 32 42 01 400 801PROC. REF: CMM 32-48-23, AMM 32 42 01 000 801, AMM 32 42 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-42-01-900-801-02	RH ASSY NLG WHEEL							Component ATA:32
PN:3-1560	MOS/MSC	20-Jan-25	O/C	TSR 0				
SN:1326	HRS	3398:31		TSR 0				
WC#: 32.625	AFL	1371		TSR 0				
PROC. REF: CMM 32-48-23PROC. REF: CMM 32-48-23								
32-42-01-900-802-01	LH NLG TIRE							Component ATA:32
PN:217K22-1	MOS/MSC	20-Jan-25	O/C	TSN 0				
SN:42020559	HRS	3398:31		TSN 0				
WC#: 32.625	AFL	1371		TSN 0				
PROC. REF: AMM 32 42 01 000 801, AMM 32 42 01 400 801PROC. REF: AMM 32 42 01 000 801, AMM 32 42 01 400 801								
32-42-01-900-802-02	RH NLG TIRE							Component ATA:32
PN:217K22-1	MOS/MSC	20-Jan-25	O/C	TSN 0				
SN:42060661	HRS	3398:31		TSN 0				
WC#: 32.625	AFL	1371		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-43-01-900-801-01	BRAKE CONTROL UNIT							Component ATA:32
PN:GW415-7125-5	MOS/MSC	22-Apr-15	O/C	TSR 13				
SN:656A	HRS	1657:57		TSR 0				
WC#: 32.630	AFL	514		TSR 0				
PROC. REF: AMM 32 43 01 000 801, AMM 32 43 01 400 801PROC. REF: AMM 32 43 01 000 801, AMM 32 43 01 400 801								
32-43-05-900-801-01	LEFT NO.1 POSITION BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.635	AFL	0		TSN 0				
PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801								
32-43-05-900-801-02	LEFT NO.2 POSITION BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.635	AFL	0		TSN 0				
PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-05-900-801-03	RIGHT NO. 1 POSITION BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.640	AFL	0		TSN 0				
PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801								
32-43-05-900-801-04	RIGHT NO. 2 POSITION BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.640	AFL	0		TSN 0				
PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801PROC. REF: AMM 32 43 05 000 801, AMM 32 43 05 400 801								
32-43-07-201	VISUAL CHECK OF THE BRAKE-PEDAL RETURN SPRING							Service ATA:32
	MOS	15-May-24	45 (+3m/-3m)	Adj 3	15-Feb-28 (M)	15-May-28	1083 d (+90)	MRIP
	HRS	3168:27	750 (+50/-50)	Adj 25:57	3944:24	3994:24	498:28 (+50)	
WC#: 32.160	AFL	1205						
PROC. REF: AMM 32 43 07 210 801PROC. REF: AMM 32 43 07 210 801								
32-43-09-900-801-01	LEFT FORWARD BRAKE CONTROL VALVE							Component ATA:32
PN:GW415-6150-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1679	HRS	0		TSN 0				
WC#: 32.645	AFL	0		TSN 0				
PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801								
32-43-09-900-801-02	RIGHT FORWARD BRAKE CONTROL VALVE							Component ATA:32
PN:GW415-6150-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1615	HRS	0		TSN 0				
WC#: 32.645	AFL	0		TSN 0				
PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801								
32-43-09-900-801-03	LEFT AFT BRAKE CONTROL VALVE							Component ATA:32
PN:GW415-6150-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1670	HRS	0		TSN 0				
WC#: 32.650	AFL	0		TSN 0				
PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-09-900-801-04	RIGHT AFT BRAKE CONTROL VALVE							Component ATA:32
PN:GW415-6150-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1671	HRS	0		TSN 0				
WC#: 32.650	AFL	0		TSN 0				
PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801PROC. REF: AMM 32 43 09 000 801, AMM 32 43 09 400 801								
32-43-13-201	FUNCTIONAL TEST OF THE BRAKE DISK FOR DRIVE SLOT ENLARGEMENT							Service ATA:32
	MOS	10-Mar-23	30 (+3m/-3m)	Adj 3	10-Dec-25	10-Mar-26	286 d (+90)	MRB
	HRS	2845:10						
	AFL	999						
PROC. REF: AMM 32 43 13 720 801PROC. REF: AMM 32 43 13 720 801								
32-43-13-301	RESTORATION (REPLATING) OF THE BRAKE ASSEMBLY - TORQUE TUBE							Service ATA:32
	MOS/MSC		-					OPTIONAL
	HRS							
	AFL							
PROC. REF: AMM 32 43 13 840 801PROC. REF: AMM 32 43 13 840 801								
32-43-13-900-801-01	NO. 1 MLG BRAKE							Component ATA:32
PN:27200-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1564	HRS	0		TSN 0				
WC#: 32.655	AFL	0		TSN 0				
PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801								
32-43-13-900-801-02	NO. 2 MLG BRAKE							Component ATA:32
PN:27200-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1547	HRS	0		TSN 0				
WC#: 32.655	AFL	0		TSN 0				
PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801								
32-43-13-900-801-03	NO. 3 MLG BRAKE							Component ATA:32
PN:27200-105	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1584	HRS	0		TSN 0				
WC#: 32.655	AFL	0		TSN 0				
PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-13-900-801-04	NO. 4 MLG BRAKE							Component ATA:32
PN:GW313-2001-3	MOS/MSC	30-Dec-22	O/C	TSO 0				
SN:2152	HRS	2788:49		TSO 0				
WC#: 32.655	AFL	972		TSO 0				
PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801PROC. REF: CMM 32-48-21, AMM 32 43 13 000 801, AMM 32 43 13 400 801								
32-43-17-900-801-01	LEFT FORWARD BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:GW415-1350-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:7566-4-123	HRS	0		TSN 0				
WC#: 32.660	AFL	0		TSN 0				
PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801								
32-43-17-900-801-02	RIGHT FORWARD BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:GW415-1350-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:7566-4-133	HRS	0		TSN 0				
WC#: 32.660	AFL	0		TSN 0				
PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801								
32-43-17-900-801-03	LEFT AFT BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:GW415-1350-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:7566-4-117	HRS	0		TSN 0				
WC#: 32.660	AFL	0		TSN 0				
PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801								
32-43-17-900-801-04	RIGHT AFT BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:GW415-1350-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:7566-4-113	HRS	0		TSN 0				
WC#: 32.660	AFL	0		TSN 0				
PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801PROC. REF: AMM 32 43 17 000 801, AMM 32 43 17 400 801								
32-43-21-900-801-01	LOB SHUTTLE VALVE							Component ATA:32
PN:GW415-6200-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1548	HRS	0		TSN 0				
WC#: 32.665	AFL	0		TSN 0				
PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-21-900-801-02	LIB SHUTTLE VALVE							Component ATA:32
PN:GW415-6200-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1546	HRS	0		TSN 0				
WC#: 32.665	AFL	0		TSN 0				
PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801								
32-43-21-900-801-03	RIB SHUTTLE VALVE							Component ATA:32
PN:GW415-6200-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1549	HRS	0		TSN 0				
WC#: 32.665	AFL	0		TSN 0				
PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801								
32-43-21-900-801-04	ROB SHUTTLE VALVE							Component ATA:32
PN:GW415-6200-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1540	HRS	0		TSN 0				
WC#: 32.665	AFL	0		TSN 0				
PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801PROC. REF: AMM 32 43 21 000 801, AMM 32 43 21 400 801								
32-43-25-101	OPERATIONAL TEST OF THE BRAKE SHUTOFF VALVE (CMR*)							Service ATA:32
	MOS	15-Oct-24						AIRWORTHINESS
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
PROC. REF: AMM 32 43 25 710 801PROC. REF: AMM 32 43 25 710 801								
32-43-25-900-801-01	LH SHUTOFF VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.670	AFL	0		TSN 0				
PROC. REF: AMM 32 43 25 000 801, AMM 32 43 25 400 801PROC. REF: AMM 32 43 25 000 801, AMM 32 43 25 400 801								
32-43-25-900-801-02	RH SHUTOFF VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.670	AFL	0		TSN 0				
PROC. REF: AMM 32 43 25 000 801, AMM 32 43 25 400 801PROC. REF: AMM 32 43 25 000 801, AMM 32 43 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-29-900-801-01	NO. 2 SYS PRESSURE CHECK, BRAKE CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.675	AFL	0		TSN 0				
PROC. REF: AMM 32 43 29 000 801, AMM 32 43 29 400 801PROC. REF: AMM 32 43 29 000 801, AMM 32 43 29 400 801								
32-43-33-900-801-01	NO. 1 HYDRAULIC FUSE VALVE							Component ATA:32
PN:GW415-1300-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1572	HRS	0		TSN 0				
WC#: 32.680	AFL	0		TSN 0				
PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801								
32-43-33-900-801-02	NO. 2 HYDRAULIC FUSE VALVE							Component ATA:32
PN:GW415-1300-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1569	HRS	0		TSN 0				
WC#: 32.680	AFL	0		TSN 0				
PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801								
32-43-33-900-801-03	NO. 3 HYDRAULIC FUSE VALVE							Component ATA:32
PN:GW415-1300-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1570	HRS	0		TSN 0				
WC#: 32.685	AFL	0		TSN 0				
PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801								
32-43-33-900-801-04	NO. 4 HYDRAULIC FUSE VALVE							Component ATA:32
PN:GW415-1300-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1567	HRS	0		TSN 0				
WC#: 32.685	AFL	0		TSN 0				
PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801PROC. REF: AMM 32 43 33 000 801, AMM 32 43 33 400 801								
32-43-37-101	DISCARD THE NO. 2 BRAKE ACCUMULATOR, PART NO. GW415-1250-1							Service ATA:32
	MOS	30-Jul-09						LIFE LIMIT
	HRS	0						
	AFL	0	8366		8366		6977	
PROC. REF: AMM 32 43 37 961 801PROC. REF: AMM 32 43 37 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-37-900-801-01	NO. 2 BRAKE ACCUMULATOR							Component ATA:32
PN:GW415-1250-1	MOS/MSC	04-Sep-15	H/T	TSN 1				
SN:60185-2363NAE	HRS	1792:10		TSN 0				
WC#: 32.690	AFL	551		TSN 0				
PROC. REF: AMM 32 43 37 000 801, AMM 32 43 37 400 801PROC. REF: AMM 32 43 37 000 801, AMM 32 43 37 400 801								
32-43-41-900-801-01	PRESSURE GAUGE AND CHARGING VALVE							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.695	AFL	0		TSN 0				
PROC. REF: AMM 32 43 41 000 801, AMM 32 43 41 400 801PROC. REF: AMM 32 43 41 000 801, AMM 32 43 41 400 801								
32-43-45-900-801-01	GROUND LIFT/AUTO BRAKE CONTROL PANEL							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.705	AFL	0		TSN 0				
PROC. REF: AMM 32 43 45 000 801, AMM 32 43 45 400 801PROC. REF: AMM 32 43 45 000 801, AMM 32 43 45 400 801								
32-43-45-900-802-01	AUTOBRAKE SWITCH							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.700	AFL	0		TSN 0				
PROC. REF: AMM 32 43 47 000 801, AMM 32 43 47 400 801PROC. REF: AMM 32 43 47 000 801, AMM 32 43 47 400 801								
32-43-49-900-801-01	NO.2 HYDRAULIC SYSTEM PRESSURE SWITCH							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.710	AFL	0		TSN 0				
PROC. REF: AMM 32 43 49 000 801, AMM 32 43 49 400 801PROC. REF: AMM 32 43 49 000 801, AMM 32 43 49 400 801								
32-43-51-900-801-01	NO.3 HYDRAULIC SYSTEM PRESSURE SWITCH							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.710	AFL	0		TSN 0				
PROC. REF: AMM 32 43 51 000 801, AMM 32 43 51 400 801PROC. REF: AMM 32 43 51 000 801, AMM 32 43 51 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-53-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WHEEL SPEED TRANSDUCERS CONNECTORS							Service ATA:32
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 32 43 53 210 802PROC. REF: AMM 32 43 53 210 802								
32-43-53-900-801-01	NO. 1 MLG WHEEL SPEED TRANSDUCER							Component ATA:32
PN:GW415-1050-9	MOS/MSC	04-Sep-15	O/C	TSN 2				
SN:3562	HRS	1792:10		TSN 0				
WC#: 32.715	AFL	551		TSN 0				
PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801								
32-43-53-900-801-02	NO. 2 MLG WHEEL SPEED TRANSDUCER							Component ATA:32
PN:GW415-1050-9	MOS/MSC	04-Sep-15	O/C	TSN 2				
SN:3607	HRS	1792:10		TSN 0				
WC#: 32.715	AFL	551		TSN 0				
PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801								
32-43-53-900-801-03	NO. 3 MLG WHEEL SPEED TRANSDUCER							Component ATA:32
PN:GW415-1050-9	MOS/MSC	04-Sep-15	O/C	TSN 2				
SN:3608	HRS	1792:10		TSN 0				
WC#: 32.715	AFL	551		TSN 0				
PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801								
32-43-53-900-801-04	NO. 4 MLG WHEEL SPEED TRANSDUCER							Component ATA:32
PN:GW415-1050-9	MOS/MSC	04-Sep-15	O/C	TSN 2				
SN:3609	HRS	1792:10		TSN 0				
WC#: 32.715	AFL	551		TSN 0				
PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801PROC. REF: AMM 32 43 53 000 801, AMM 32 43 53 400 801								
32-44-01-900-801-01	PARKING BRAKE VALVE							Component ATA:32
PN:GW415-6225-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0405	HRS	0		TSN 0				
WC#: 32.720	AFL	0		TSN 0				
PROC. REF: AMM 32 44 01 000 801, AMM 32 44 01 400 801PROC. REF: AMM 32 44 01 000 801, AMM 32 44 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-05-101	DISCARD THE NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1/-3							Service ATA:32
	MOS	30-Jul-09						LIFE LIMIT
	HRS	0						
	AFL	0	5816		5816		4427	
PROC. REF: AMM 32 44 05 961 801PROC. REF: AMM 32 44 05 961 801								
32-44-05-900-801-01	NO. 3 BRAKE ACCUMULATOR							Component ATA:32
PN:GW415-1200-3	MOS/MSC	04-Sep-15	H/T					
SN:60188-0018	HRS	1792:10						
WC#: 32.725	AFL	551						
PROC. REF: AMM 32 44 05 000 801, AMM 32 44 05 400 801PROC. REF: AMM 32 44 05 000 801, AMM 32 44 05 400 801								
32-44-09-900-801-01	PARKING BRAKE HANDLE							Component ATA:32
PN:24700-107	MOS/MSC	22-Nov-16	O/C	TSN 0				
SN:J34399-7	HRS	2035:31		TSN 0				
WC#: 32.730	AFL	620		TSN 0				
PROC. REF: AMM 32 44 09 000 801, AMM 32 44 09 400 801PROC. REF: AMM 32 44 09 000 801, AMM 32 44 09 400 801								
32-51-01-900-801-01	STEERING CONTROL UNIT							Component ATA:32
PN:GW415-8100-3	MOS/MSC	16-Sep-14	O/C	TSR 16				
SN:08-384	HRS	1444:25		TSR 0				
WC#: 32.735	AFL	446		TSR 0				
PROC. REF: AMM 32 51 01 000 801, AMM 32 51 01 400 801PROC. REF: AMM 32 51 01 000 801, AMM 32 51 01 400 801								
32-51-05-900-801-01	STEERING CONTROL HANDWHEEL							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.745	AFL	0		TSN 0				
PROC. REF: CMM 32-50-18, AMM 32 51 05 000 801, AMM 32 51 05 400 801PROC. REF: CMM 32-50-18, AMM 32 51 05 000 801, AMM 32 51 05 400 801								
32-51-09-900-801-01	LH RUDDER CONTROL RVDT							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.750	AFL	0		TSN 0				
PROC. REF: AMM 32 51 09 000 801, AMM 32 51 09 400 801PROC. REF: AMM 32 51 09 000 801, AMM 32 51 09 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-51-09-900-801-02		RH RUDDER CONTROL RVDT					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.750	AFL	0		TSN 0				
PROC. REF: AMM 32 51 09 000 801, AMM 32 51 09 400 801PROC. REF: AMM 32 51 09 000 801, AMM 32 51 09 400 801								
32-51-13-900-801-01		LH STEERING SOLENOID VALVE					Component	ATA:32
PN:GW415-6275-3	MOS/MSC	15-Oct-24	O/C					
SN:0886	HRS	3314:03		TSN 4519				
WC#: 32.755	AFL	1328		TSN 1068				
PROC. REF: AMM 32 51 13 000 801, AMM 32 51 13 400 801PROC. REF: AMM 32 51 13 000 801, AMM 32 51 13 400 801								
32-51-17-900-801-01		STEERING MANIFOLD					Component	ATA:32
PN:1289A0000-01	MOS/MSC	05-Feb-21	O/C	TSR 0				
SN:01198	HRS	2444:24		TSN 3732:24, TSR 0				
WC#: 32.760	AFL	745		TSN 1367, TSR 0				
PROC. REF: AMM 32 51 17 000 801, AMM 32 51 17 400 801PROC. REF: AMM 32 51 17 000 801, AMM 32 51 17 400 801								
32-51-21-900-801-01		LH STEERING ACTUATOR					Component	ATA:32
PN:1287A0000-04	MOS/MSC	05-Feb-21	O/C					
SN:1287A00LI002162	HRS	2444:24		TSN 2522:39				
WC#: 32.770	AFL	745		TSN 967				
PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801								
32-51-21-900-801-02		RH STEERING ACTUATOR					Component	ATA:32
PN:1288A0000-04	MOS/MSC	05-Feb-21	O/C					
SN:1288A00LI002107	HRS	2444:24		TSN 1910:24				
WC#: 32.770	AFL	745		TSN 726				
PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801								
32-51-21-900-802-01		NLG SHOCK STRUT STEERING ACTUATOR BOLT					Component	ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.320	AFL	0		TSN 0				
PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801PROC. REF: AMM 32 51 21 000 801, AMM 32 51 21 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-51-22-900-801-01	LH SWIVEL, STEERING ACTUATOR MANIFOLD							Component ATA:32
PN:1285A0100-03	MOS/MSC	05-Feb-21	O/C					
SN:00437	HRS	2444:24		TSN 2444:24				
WC#: 32.765	AFL	745		TSN 745				
PROC. REF: AMM 32 51 22 000 801, AMM 32 51 22 400 801PROC. REF: AMM 32 51 22 000 801, AMM 32 51 22 400 801								
32-51-22-900-801-02	RH SWIVEL, STEERING ACTUATOR MANIFOLD							Component ATA:32
PN:1285A0300-03	MOS/MSC	05-Feb-21	O/C					
SN:00262	HRS	2444:24		TSN 2444:24				
WC#: 32.765	AFL	745		TSN 745				
PROC. REF: AMM 32 51 22 000 801, AMM 32 51 22 400 801PROC. REF: AMM 32 51 22 000 801, AMM 32 51 22 400 801								
32-51-29-900-801-01	PRESSURE STEERING CONTROL SWITCH							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.740	AFL	0		TSN 0				
PROC. REF: AMM 32 51 29 000 801, AMM 32 51 29 400 801PROC. REF: AMM 32 51 29 000 801, AMM 32 51 29 400 801								
32-51-33-900-801-01	HYDRAULIC COMPENSATOR							Component ATA:32
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.775	AFL	0		TSN 0				
PROC. REF: AMM 32 51 33 000 801, AMM 32 51 33 400 801PROC. REF: AMM 32 51 33 000 801, AMM 32 51 33 400 801								
32-60-00-201	VISUAL CHECK OF THE LANDING GEAR POSITION AND WARNING SYSTEM							Service ATA:32
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 32.170	AFL	747						
PROC. REF: AMM 32 60 00 210 801PROC. REF: AMM 32 60 00 210 801								
32-ZL-00-201	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR (NLG) ASSEMBLY							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.175	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 20 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 20 00 210 801, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-ZL-00-202	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - LH							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.180	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 10 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 10 00 210 801, SPM 20-70-00-210-801								
32-ZL-00-203	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR ASSEMBLY - RH							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.180	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 10 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 10 00 210 801, SPM 20-70-00-210-801								
32-ZL-00-204	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - LH							Service ATA:32
	MOS	17-May-22						MRB
	HRS	2534:36						
WC#: 32.185	AFL	798	900 (+50/-50)		1698	1748	309 (+50)	
PROC. REF: AMM 32 20 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 32 20 00 210 802, SPM 20-70-00-210-801								
32-ZL-00-205	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - RH							Service ATA:32
	MOS	17-May-22						MRB
	HRS	2534:36						
WC#: 32.185	AFL	798	900 (+50/-50)		1698	1748	309 (+50)	
PROC. REF: AMM 32 20 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 32 20 00 210 802, SPM 20-70-00-210-801								
32-ZL-00-206	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR DOOR - AFT							Service ATA:32
	MOS	17-May-22						MRB
	HRS	2534:36						
WC#: 32.185	AFL	798	900 (+50/-50)		1698	1748	309 (+50)	
PROC. REF: AMM 32 20 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 32 20 00 210 802, SPM 20-70-00-210-801								
32-ZL-00-207	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - LH							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.190	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 12 05 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 12 05 210 801, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-ZL-00-208	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) INBOARD DOOR - RH							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.190	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 12 05 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 12 05 210 801, SPM 20-70-00-210-801								
32-ZL-00-209	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - LH							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.195	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 12 01 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 12 01 210 801, SPM 20-70-00-210-801								
32-ZL-00-210	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) OUTBOARD DOOR - RH							Service ATA:32
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 32.195	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 32 12 01 210 801, SPM 20-70-00-210-801PROC. REF: AMM 32 12 01 210 801, SPM 20-70-00-210-801								
321100-701 ^U	LH MLG DOOR HINGE PIN							Component ATA:32
PN:21123-1	MOS/MSC	30-Jul-09	O/C					
SN:08EXC0813	HRS	0						
	AFL	0						
321100-702 ^U	RH MLG DOOR HINGE PIN							Component ATA:32
PN:21123-1	MOS/MSC	30-Jul-09	O/C					
SN:08EXC0823	HRS	0						
	AFL	0						
321100-703 ^U	LH MLG SIDE STAY NUT							Component ATA:32
PN:21129-5	MOS/MSC	30-Jul-09	O/C					
SN:08CPS0880	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321100-704 ^U	RH MLG SIDE STAY NUT							Component ATA:32
PN:21129-5	MOS/MSC	30-Jul-09	O/C					
SN:08CPS0877	HRS	0						
	AFL	0						
322100-702 ^U	NLG TORQUE LINK PIN							Component ATA:32
PN:1286-0003	MOS/MSC	05-Feb-21	O/C					
SN:1223609/008	HRS	2444:24			TSN 2444:24			
	AFL	745			TSN 745			
322100-703 ^U	NLG TORQUE LINK PIN							Component ATA:32
PN:1286-0003	MOS/MSC	05-Feb-21	O/C					
SN:1223609/009	HRS	2444:24			TSN 2444:24			
	AFL	745			TSN 745			
322100-704 ^U	NLG BOLT							Component ATA:32
PN:1286-0009	MOS/MSC	05-Feb-21	O/C					
SN:1230505/002	HRS	2444:24			TSN 2444:24			
	AFL	745			TSN 745			
322100-705 ^U	NLG SLEEVE - MANIF BOLT							Component ATA:32
PN:1286-0033	MOS/MSC	05-Feb-21	O/C					
SN:1238309/018	HRS	2444:24			TSN 2444:24			
	AFL	745			TSN 745			
322100-706 ^U	NLG STEERING SLEEVE							Component ATA:32
PN:1286-0506	MOS/MSC	05-Feb-21	O/C					
SN:444	HRS	2444:24			TSN 2444:24			
	AFL	745			TSN 745			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
322100-707 ^U	NLG STEERING COLLAR							Component ATA:32
PN:1286-0605	MOS/MSC	05-Feb-21	O/C					
SN:1240054/003	HRS	2444:24		TSN 2444:24				
	AFL	745		TSN 745				
322100-708 ^U	NLG STEERING PLATE							Component ATA:32
PN:1286-0705	MOS/MSC	05-Feb-21	O/C					
SN:441	HRS	2444:24		TSN 2444:24				
	AFL	745		TSN 745				
322100-709 ^U	NLG TORQUE LINK							Component ATA:32
PN:1286-2401	MOS/MSC	30-Jul-09	O/C					
SN:1239445/008	HRS	0						
	AFL	0						
322100-710 ^U	NLG TORQUE LINK							Component ATA:32
PN:22179-1	MOS/MSC	30-Jul-09	O/C					
SN:1239445/010	HRS	0						
	AFL	0						
322100-713 ^U	NLG LOCKING NUT							Component ATA:32
PN:1286-0074	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:AP15722	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
324311-701 ^U	#1 QUICK DISCONNECT COUPLER							Component ATA:32
PN:15406-06A-E17	MOS/MSC	30-Jul-09	O/C					
SN:3348	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324311-702 ^U	#2 QUICK DISCONNECT COUPLER							Component ATA:32
PN:15406-06A-E17	MOS/MSC	30-Jul-09	O/C					
SN:3349	HRS	0						
	AFL	0						
324311-703 ^U	#3 QUICK DISCONNECT COUPLER							Component ATA:32
PN:15406-06A-E17	MOS/MSC	30-Jul-09	O/C					
SN:3340	HRS	0						
	AFL	0						
324311-704 ^U	#4 QUICK DISCONNECT COUPLER							Component ATA:32
PN:15406-06A-E17	MOS/MSC	30-Jul-09	O/C					
SN:3333	HRS	0						
	AFL	0						
324313-001A ^U	RESTORATION NO. 1 MLG BRAKE (32-43-13-202)							Service ATA:32
PN:27200-105	MOS/MSC	30-Jul-09	N/A					MRB
SN:1564	HRS	0						
	AFL	0						
324313-002A ^U	RESTORATION NO. 2 MLG BRAKE (32-43-13-202)							Service ATA:32
PN:27200-105	MOS/MSC	30-Jul-09	N/A					MRB
SN:1547	HRS	0						
	AFL	0						
324313-003A ^U	RESTORATION NO. 3 MLG BRAKE (32-43-13-202)							Service ATA:32
PN:27200-105	MOS/MSC	30-Jul-09	N/A					MRB
SN:1584	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324313-004A ^U	RESTORATION NO. 4 MLG BRAKE (32-43-13-202)							Service ATA:32
PN:GW313-2001-3	MOS/MSC	30-Dec-22	N/A					MRB
SN:2152	HRS	2788:49						
	AFL	972						
324361-701 ^U	NO. 1 BRAKE TEMPERATURE SENSOR							Component ATA:32
PN:GW436-1001-1	MOS/MSC	08-Aug-17	O/C	TSN 0				
SN:N4874	HRS	2199:14		TSN 0				
	AFL	666		TSN 0				
324361-702 ^U	NO. 2 BRAKE TEMPERATURE SENSOR							Component ATA:32
PN:GW436-1001-1	MOS/MSC	08-Aug-17	O/C					
SN:H8789	HRS	2199:14						
	AFL	666						
324361-703 ^U	NO. 3 BRAKE TEMPERATURE SENSOR							Component ATA:32
PN:GW436-1001-1	MOS/MSC	30-Jul-09	O/C					
SN:H8053	HRS	0						
	AFL	0						
324361-704 ^U	NO. 4 BRAKE TEMPERATURE SENSOR							Component ATA:32
PN:GW436-1001-1	MOS/MSC	30-Jul-09	O/C					
SN:H8058	HRS	0						
	AFL	0						
ATA 33 - LIGHTS								
33-00-00-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING TIP LIGHTS AND COMPONENTS CONNECTORS AND GROUND STUDS							Service ATA:33
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 33 00 00 210 801PROC. REF: AMM 33 00 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-11-01-900-802-01		LH 0.1A DC/AC INVERTER					Component	ATA:33
PN:GC531-0003-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0773	HRS	0		TSN 0				
WC#: 33.035	AFL	0		TSN 0				
PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802								
33-11-01-900-802-02		RH 0.1A DC/AC INVERTER					Component	ATA:33
PN:GC531-0003-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0833	HRS	0		TSN 0				
WC#: 33.035	AFL	0		TSN 0				
PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802								
33-11-01-900-803-01		LEFT 7.5A CONVERTER					Component	ATA:33
PN:GC531-0001-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1114	HRS	0		TSN 0				
WC#: 33.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-11-01-900-803-02		RIGHT FORWARD 7.5A CONVERTER					Component	ATA:33
PN:GC531-0001-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1168	HRS	0		TSN 0				
WC#: 33.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-11-01-900-803-03		RIGHT AFT 7.5A CONVERTER					Component	ATA:33
PN:GC531-0001-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1116	HRS	0		TSN 0				
WC#: 33.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-11-01-900-804-01		LH 15A DC/DC CONVERTER					Component	ATA:33
PN:GC531-0002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0750	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-11-01-900-804-02	RH 15A DC/DC CONVERTER							Component ATA:33
PN:GC531-0002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0742	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-11-01-900-805-01	LH 0.5A DC/AC INVERTER							Component ATA:33
PN:GC531-0004-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0769	HRS	0		TSN 0				
WC#: 33.040	AFL	0		TSN 0				
PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802								
33-11-01-900-805-02	RH 0.5A DC/AC INVERTER							Component ATA:33
PN:GC531-0004-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0706	HRS	0		TSN 0				
WC#: 33.040	AFL	0		TSN 0				
PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802PROC. REF: AMM 33 11 01 000 802, AMM 33 11 01 400 802								
33-13-05-900-801-01	LH READING LIGHT							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.045	AFL	0		TSN 0				
PROC. REF: AMM 33 13 05 000 801, AMM 33 13 05 400 801PROC. REF: AMM 33 13 05 000 801, AMM 33 13 05 400 801								
33-13-05-900-801-02	RH READING LIGHT							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.045	AFL	0		TSN 0				
PROC. REF: AMM 33 13 05 000 801, AMM 33 13 05 400 801PROC. REF: AMM 33 13 05 000 801, AMM 33 13 05 400 801								
33-24-50-621 ^U	OPERATIONAL TEST OF THE ORDINANCE SIGN							Service ATA:33
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-31-01-900-801-01		NOSE GEAR BAY/TAIL LIGHT					Component	ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.050	AFL	0		TSN 0				
PROC. REF: AMM 33 31 01 000 801, AMM 33 31 01 400 801PROC. REF: AMM 33 31 01 000 801, AMM 33 31 01 400 801								
33-31-09-900-801-01		APU COMPARTMENT LIGHT					Component	ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.055	AFL	0		TSN 0				
PROC. REF: AMM 33 31 09 000 801, AMM 33 31 09 400 801PROC. REF: AMM 33 31 09 000 801, AMM 33 31 09 400 801								
33-31-13-900-801-01		NO. 1 MAIN LIGHT					Component	ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-31-13-900-801-02		NO. 2 MAIN LIGHT					Component	ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-31-13-900-801-03		NO. 3 MAIN LIGHT					Component	ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-31-17-900-801-01		LH FS381 AUTO SHUT-OFF BOX					Component	ATA:33
PN:GE534-0001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1499807	HRS	0		TSN 0				
WC#: 33.065	AFL	0		TSN 0				
PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-31-17-900-801-02	LH FS909 AUTO SHUT-OFF BOX							Component ATA:33
PN:GE534-0001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1470105	HRS	0		TSN 0				
WC#: 33.065	AFL	0		TSN 0				
PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801								
33-31-17-900-801-03	RH AUTO SHUT OFF (DVC) LIGHT							Component ATA:33
PN:GE534-0001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1483735	HRS	0		TSN 0				
WC#: 33.070	AFL	0		TSN 0				
PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801PROC. REF: AMM 33 31 17 000 801, AMM 33 31 17 400 801								
33-40-01-900-801-01	EXTERNAL LIGHTS CONTROL PANEL							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33 40 01 000 801, AMM 33 40 01 400 801PROC. REF: AMM 33 40 01 000 801, AMM 33 40 01 400 801								
33-40-50-621 ^U	OPERATIONAL TEST OF THE OPTIONAL EXTERIOR LIGHTS							Service ATA:33
	MOS	24-Jun-24					STLMC	
	HRS	3221:01	500		3721:01		275:05	
	AFL	1253						
33-41-01-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE WING LANDING AND TAXI LIGHTS CONNECTORS							Service ATA:33
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 33 41 01 210 801PROC. REF: AMM 33 41 01 210 801								
33-41-01-900-801-01	LH LANDING LIGHT LENS							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.075	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-41-01-900-801-02	RH LANDING LIGHT LENS							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.075	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
33-41-01-900-802-01	LH WING LANDING/TAXI LIGHT							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.080	AFL	0		TSN 0				
PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801								
33-41-01-900-802-02	RH WING LANDING/TAXI LIGHT							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.080	AFL	0		TSN 0				
PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801PROC. REF: AMM 33 41 01 000 801, AMM 33 41 01 400 801								
33-41-03-900-801-01	PULSE CONTROL UNIT							Component ATA:33
PN:1152B	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:QR00445	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33 41 03 000 801, AMM 33 41 03 400 801PROC. REF: AMM 33 41 03 000 801, AMM 33 41 03 400 801								
33-41-05-900-801-01	LH NLG LIGHT							Component ATA:33
PN:2LA409800-05	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1477535	HRS	0		TSN 0				
WC#: 33.085	AFL	0		TSN 0				
PROC. REF: AMM 33 41 05 000 801, AMM 33 41 05 400 801PROC. REF: AMM 33 41 05 000 801, AMM 33 41 05 400 801								
33-41-05-900-801-02	RH NLG LIGHT							Component ATA:33
PN:2LA409800-05	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1477536	HRS	0		TSN 0				
WC#: 33.085	AFL	0		TSN 0				
PROC. REF: AMM 33 41 05 000 801, AMM 33 41 05 400 801PROC. REF: AMM 33 41 05 000 801, AMM 33 41 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-42-01-900-801-01		LH WING NAVIGATION (RED) LIGHT						Component ATA:33
PN:2LA007181-22	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:4819233	HRS	2444:24		TSN 0				
WC#: 33.090	AFL	745		TSN 0				
PROC. REF: AMM 33 42 01 000 801, AMM 33 42 01 400 801PROC. REF: AMM 33 42 01 000 801, AMM 33 42 01 400 801								
33-42-01-900-801-02		RH WING NAVIGATION (GREEN) LIGHT						Component ATA:33
PN:2LA007182-22	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:4699883	HRS	2444:24		TSN 0				
WC#: 33.090	AFL	745		TSN 0				
PROC. REF: AMM 33 42 01 000 801, AMM 33 42 01 400 801PROC. REF: AMM 33 42 01 000 801, AMM 33 42 01 400 801								
33-42-09-900-801-01		NOSE GEAR BAY/TAIL LIGHT						Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.095	AFL	0		TSN 0				
PROC. REF: AMM 33 42 09 000 801, AMM 33 42 09 400 801PROC. REF: AMM 33 42 09 000 801, AMM 33 42 09 400 801								
33-42-13-900-801-01		FAILURE IND (MID CENTER FUSE) BOX						Component ATA:33
PN:GE536-0001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1491598	HRS	0		TSN 0				
WC#: 33.100	AFL	0		TSN 0				
PROC. REF: AMM 33 42 13 000 801, AMM 33 42 13 400 801PROC. REF: AMM 33 42 13 000 801, AMM 33 42 13 400 801								
33-43-01-900-801-01		LH STROBE WING LIGHT						Component ATA:33
PN:2LA006178-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1486986	HRS	0		TSN 0				
WC#: 33.105	AFL	0		TSN 0				
PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801								
33-43-01-900-801-02		RH STROBE WING LIGHT						Component ATA:33
PN:2LA006178-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1486992	HRS	0		TSN 0				
WC#: 33.105	AFL	0		TSN 0				
PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-43-01-900-801-03		STROBE WING LIGHT						Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.105	AFL	0		TSN 0				
PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801PROC. REF: AMM 33 43 01 000 801, AMM 33 43 01 400 801								
33-43-05-900-801-01		STROBE (TAIL) LIGHT						Component ATA:33
PN:2LA006181-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1505437	HRS	0		TSN 0				
WC#: 33.110	AFL	0		TSN 0				
PROC. REF: AMM 33 43 05 000 801, AMM 33 43 05 400 801PROC. REF: AMM 33 43 05 000 801, AMM 33 43 05 400 801								
33-43-09-201		GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE LOWER STROBE/ANTICOLLISION LIGHT CONNECTOR						Service ATA:33
	MOS	05-Feb-21	120 (+3m/-3m)	05-Feb-31	05-May-31	2169 d (+89)	MRB	
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 33 43 09 210 801PROC. REF: AMM 33 43 09 210 801								
33-43-09-900-801-01		UPPER STROBE, ANTICOLLISION FUSELAGE LIGHT						Component ATA:33
PN:2LA003849-22	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:4593782	HRS	2444:24		TSN 0				
WC#: 33.115	AFL	745		TSN 0				
PROC. REF: AMM 33 43 09 000 801, AMM 33 43 09 400 801PROC. REF: AMM 33 43 09 000 801, AMM 33 43 09 400 801								
33-43-09-900-801-02		LOWER STROBE, ANTICOLLISION FUSELAGE LIGHT						Component ATA:33
PN:2LA003849-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1511959	HRS	0		TSN 0				
WC#: 33.115	AFL	0		TSN 0				
PROC. REF: AMM 33 43 09 000 801, AMM 33 43 09 400 801PROC. REF: AMM 33 43 09 000 801, AMM 33 43 09 400 801								
33-44-01-900-801-01		LH WING/TAIL STROBE LIGHT POWER SUPPLY						Component ATA:33
PN:8ES456038-03	MOS/MSC	16-Oct-17	O/C	TSN 53				
SN:2338847	HRS	2243:12		TSN 0				
WC#: 33.120	AFL	678		TSN 0				
PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-44-01-900-801-02		RH WING/TAIL STROBE LIGHT POWER SUPPLY						Component ATA:33
PN:8ES456038-03	MOS/MSC	10-Mar-23	O/C	TSN 0				
SN:5479412	HRS	2845:10		TSN 0				
WC#: 33.120	AFL	999		TSN 0				
PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801PROC. REF: AMM 33 44 01 000 801, AMM 33 44 01 400 801								
33-44-01-900-802-01		TAIL WING/TAIL STROBE LIGHT POWER SUPPLY						Component ATA:33
PN:8ES007046-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1443453	HRS	0		TSN 0				
WC#: 33.120	AFL	0		TSN 0				
PROC. REF: AMM 33 44 01 000 802, AMM 33 44 01 400 802PROC. REF: AMM 33 44 01 000 802, AMM 33 44 01 400 802								
33-44-05-900-801-01		UPPER STROBE/ANTICOLLISION LIGHT POWER SUPPLY						Component ATA:33
PN:8ES006794-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1460473	HRS	0		TSN 0				
WC#: 33.125	AFL	0		TSN 0				
PROC. REF: AMM 33 44 05 000 801, AMM 33 44 05 400 801PROC. REF: AMM 33 44 05 000 801, AMM 33 44 05 400 801								
33-44-05-900-801-02		LOWER STROBE/ANTICOLLISION LIGHT POWER SUPPLY						Component ATA:33
PN:8ES006794-22	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1488696	HRS	0		TSN 0				
WC#: 33.125	AFL	0		TSN 0				
PROC. REF: AMM 33 44 05 000 801, AMM 33 44 05 400 801PROC. REF: AMM 33 44 05 000 801, AMM 33 44 05 400 801								
33-45-01-900-801-01		LH SCANLITE WING						Component ATA:33
PN:2LA455189-50	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1482269	HRS	0		TSN 0				
WC#: 33.130	AFL	0		TSN 0				
PROC. REF: AMM 33 45 01 000 801, AMM 33 45 01 400 801PROC. REF: AMM 33 45 01 000 801, AMM 33 45 01 400 801								
33-45-01-900-801-02		RH SCANLITE WING						Component ATA:33
PN:2LA455189-50	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1482264	HRS	0		TSN 0				
WC#: 33.130	AFL	0		TSN 0				
PROC. REF: AMM 33 45 01 000 801, AMM 33 45 01 400 801PROC. REF: AMM 33 45 01 000 801, AMM 33 45 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-46-01-900-801-01	LH LOGO LIGHT							Component ATA:33
PN:2LA455179-50	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1565649	HRS	0		TSN 0				
WC#: 33.135	AFL	0		TSN 0				
PROC. REF: AMM 33 46 01 000 801, AMM 33 46 01 400 801PROC. REF: AMM 33 46 01 000 801, AMM 33 46 01 400 801								
33-46-01-900-801-02	RH LOGO LIGHT							Component ATA:33
PN:2LA455179-50	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1565650	HRS	0		TSN 0				
WC#: 33.135	AFL	0		TSN 0				
PROC. REF: AMM 33 46 01 000 801, AMM 33 46 01 400 801PROC. REF: AMM 33 46 01 000 801, AMM 33 46 01 400 801								
33-50-00-201	FUNCTIONAL TEST OF THE EMERGENCY LIGHTS POWER-SUPPLIES							Service ATA:33
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	MRB
	HRS	3168:27						
WC#: 33.015	AFL	1205						
PROC. REF: AMM 33 51 09 720 801PROC. REF: AMM 33 51 09 720 801								
33-50-00-202	OPERATIONAL TEST OF THE EMERGENCY LIGHTS							Service ATA:33
	MOS	15-May-24	60 (+3m/-3m)	Adj 3	15-Aug-29	15-Nov-29	1630 d (+92)	MRIP
	HRS	3168:27	1000 (+50/-50)	Adj 50	4218:27	4268:27	772:31 (+50)	
WC#: 33.020	AFL	1205						
PROC. REF: AMM 33 51 00 710 801PROC. REF: AMM 33 51 00 710 801								
33-51-01-900-801-01	EMERGENCY - FS797-813 (MHI) LIGHT							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.140	AFL	0		TSN 0				
PROC. REF: AMM 33 51 01 000 801, AMM 33 51 01 400 801PROC. REF: AMM 33 51 01 000 801, AMM 33 51 01 400 801								
33-51-05-900-801-01	EMERGENCY EXIT - OVER WING LIGHT							Component ATA:33
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.145	AFL	0		TSN 0				
PROC. REF: AMM 33 51 05 000 801, AMM 33 51 05 400 801PROC. REF: AMM 33 51 05 000 801, AMM 33 51 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-51-09-900-801-01		NO.1 EMERGENCY LIGHTING POWER SUPPLY						Component ATA:33
PN:8ES409800-00	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4338	HRS	0		TSN 0				
WC#: 33.155	AFL	0		TSN 0				
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801								
33-51-09-900-801-02		NO.2 EMERGENCY LIGHTING POWER SUPPLY						Component ATA:33
PN:8ES409800-00	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:4340	HRS	0		TSN 0				
WC#: 33.160	AFL	0		TSN 0				
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801								
33-51-09-900-801-03		NO.3 EMERGENCY LIGHTING POWER SUPPLY						Component ATA:33
PN:8ES409800-00	MOS/MSC	15-Oct-24	O/C	TSN 0				
SN:6133571	HRS	3314:03		TSN 0				
WC#: 33.165	AFL	1328		TSN 0				
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801								
33-51-09-900-801-04		NO.4 EMERGENCY LIGHTING POWER SUPPLY						Component ATA:33
PN:8ES409800-00	MOS/MSC	07-Jul-13	O/C	TSN 4				
SN:2279105	HRS			TSN 0				
WC#: 33.170	AFL			TSN 0				
PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801PROC. REF: CMM 33-51-27, CMM 33-51-95, AMM 33 51 09 000 801, AMM 33 51 09 400 801								
33-51-09-900-803-01		PASSENGER DOOR LIGHT						Component ATA:33
PN:GE535-0001-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1466703	HRS	0		TSN 0				
WC#: 33.150	AFL	0		TSN 0				
PROC. REF: AMM 33 51 01 000 801, AMM 33 51 01 400 801PROC. REF: AMM 33 51 01 000 801, AMM 33 51 01 400 801								
33-51-50-621 ^U		OPERATIONAL TEST OF THE CABIN EMERGENCY LIGHTING SYSTEM						Service ATA:33
	MOS	15-Oct-24						STLMC
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
335109-701 ^U	NO. 1 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK							Component ATA:33
PN:8ES360000-00	MOS/MSC	15-May-24	O/C	TSN 0				
SN:23919	HRS	3168:27		TSN 0				
	AFL	1205		TSN 0				
335109-702 ^U	NO. 2 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK							Component ATA:33
PN:8ES360000-00	MOS/MSC	15-May-24	O/C	TSN 0				
SN:23955	HRS	3168:27		TSN 0				
	AFL	1205		TSN 0				
335109-703 ^U	NO. 3 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK							Component ATA:33
PN:8ES360000-00	MOS/MSC	15-May-24	O/C	TSN 0				
SN:23577	HRS	3168:27		TSN 0				
	AFL	1205		TSN 0				
335109-704 ^U	NO. 4 EMERGENCY LIGHT POWER SUPPLY BATTERY PACK							Component ATA:33
PN:8ES360000-00	MOS/MSC	15-Oct-24	O/C	TSN 0				
SN:25213	HRS	3314:03		TSN 0				
	AFL	1328		TSN 0				
ATA 34 - NAVIGATION								
34-11-00-101	FUNCTIONAL TEST OF THE AIR DATA COMPUTER (RVSM QUALIFIED A/C) (CMR*)							Service ATA:34
	MOS	10-Mar-23	24 (+3m/-3m)	Adj 3	10-Jun-25	10-Sep-25	103 d (+92)	
	HRS	2845:10						
WC#: 34.005	AFL	999						
PROC. REF: AMM 34 11 00 720 801PROC. REF: AMM 34 11 00 720 801								
34-11-00-202	FUNCTIONAL TEST OF THE PITOT-STATIC SYSTEMS							Service ATA:34
	MOS	17-Oct-23	30 (+3m/-3m)	Adj 3	17-Jul-26	17-Oct-26	505 d (+92)	MRB
	HRS	3029:02						
WC#: 34.010	AFL	1119						
PROC. REF: AMM 34 11 00 720 802PROC. REF: AMM 34 11 00 720 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-01-201	DETAILED INSPECTION OF THE PITOT-STATIC PROBES							Service ATA:34
	MOS	17-Oct-23	30 (+3m/-3m)	Adj 3	17-Jul-26	17-Oct-26	505 d (+92)	MRB
	HRS	3029:02						
WC#: 34.015	AFL	1119						
PROC. REF: AMM 34 11 01 220 801PROC. REF: AMM 34 11 01 220 801								
34-11-01-900-801-01	NO. 1 PITOT STATIC PROBE							Component ATA:34
PN:0856TT1	MOS/MSC	16-Aug-21	H/T	TSN 0				
SN:317309	HRS	2448:43		TSN 0				
WC#: 34.040	AFL	749		TSN 0				
PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801								
34-11-01-900-801-02	NO. 2 PITOT STATIC PROBE							Component ATA:34
PN:0856TT4	MOS/MSC	16-Aug-21	H/T	TSN 0				
SN:321763	HRS	2448:43		TSN 0				
WC#: 34.040	AFL	749		TSN 0				
PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801								
34-11-01-900-801-03	NO. 3 PITOT STATIC PROBE							Component ATA:34
PN:0856TT3	MOS/MSC	16-Aug-21	H/T	TSN 0				
SN:318133	HRS	2448:43		TSN 0				
WC#: 34.040	AFL	749		TSN 0				
PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801								
34-11-01-900-801-04	STANDBY PITOT STATIC PROBE							Component ATA:34
PN:0856TT2	MOS/MSC	16-Aug-21	H/T	TSN 0				
SN:316447	HRS	2448:43		TSN 0				
WC#: 34.040	AFL	749		TSN 0				
PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801PROC. REF: CMM 34-10-68, AMM 34 11 01 000 801, AMM 34 11 01 400 801								
34-11-03-201	SERVICING OF THE VISUAL DRAINS							Service ATA:34
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	MRB
	HRS	3168:27						
WC#: 34.020	AFL	1205						
PROC. REF: AMM 34 11 03 616 801PROC. REF: AMM 34 11 03 616 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-05-900-801-01	TOTAL TEMPERATURE SENSOR							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.045	AFL	0		TSN 0				
PROC. REF: AMM 34 11 05 000 801, AMM 34 11 05 400 801PROC. REF: AMM 34 11 05 000 801, AMM 34 11 05 400 801								
34-11-09-900-801-01	NO. 1 MICRO AIR DATA COMPUTER							Component ATA:34
PN:7030700-70708	MOS/MSC	16-Aug-21	O/C					
SN:09032237	HRS	2448:43						
WC#: 34.050	AFL	749						
PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801								
34-11-09-900-801-02	NO. 2 MICRO AIR DATA COMPUTER							Component ATA:34
PN:7030700-70708	MOS/MSC	30-Jul-21	O/C					
SN:09032236	HRS	2447:29						
WC#: 34.055	AFL	748						
PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801								
34-11-09-900-801-03	NO. 3 MICRO AIR DATA COMPUTER							Component ATA:34
PN:7030700-70708	MOS/MSC	16-Aug-21	O/C					
SN:09032238	HRS	2448:43						
WC#: 34.060	AFL	749						
PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801PROC. REF: AMM 34 11 09 000 801, AMM 34 11 09 400 801								
34-12-01-201	FUNCTIONAL TEST OF THE STANDBY AIRSPEED/ALTIMETER INDICATOR (A/C 9002 TO 9157)							Service ATA:34
	MOS/MSC		N/A					
	HRS							
WC#: 34.025	AFL							
PROC. REF: AMM 34 12 01 720 801PROC. REF: AMM 34 12 01 720 801								
34-12-03-900-801-01	STANDBY INSTRUMENT INDICATOR							Component ATA:34
PN:C16221RA01	MOS/MSC	26-Jul-12	O/C	TSN 36				
SN:C16221017340	HRS	770:30		TSN 770:30				
WC#: 34.070	AFL	266		TSN 266				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-13-00-101	DISCARD THE NO. 1 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY)							Service ATA:34
PN:0856TT1	MOS	16-Aug-21						LIFE LIMIT
SN:317309	HRS	2448:43	9600		12048:43		8602:47	
	AFL	749						
PROC. REF: AMM 34 11 01 961 801PROC. REF: AMM 34 11 01 961 801								
34-13-00-101	DISCARD THE NO. 2 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY)							Service ATA:34
PN:0856TT4	MOS	16-Aug-21						LIFE LIMIT
SN:321763	HRS	2448:43	9600		12048:43		8602:47	
	AFL	749						
PROC. REF: AMM 34 11 01 961 801PROC. REF: AMM 34 11 01 961 801								
34-13-00-101	DISCARD THE NO. 3 PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY)							Service ATA:34
PN:0856TT3	MOS	16-Aug-21						LIFE LIMIT
SN:318133	HRS	2448:43	9600		12048:43		8602:47	
	AFL	749						
PROC. REF: AMM 34 11 01 961 801PROC. REF: AMM 34 11 01 961 801								
34-13-00-101	DISCARD THE STANDBY PITOT-STATIC PROBE, PART NO. 0856TT1/2/3/4 (FOR RVSM OPERATORS ONLY)							Service ATA:34
PN:0856TT2	MOS	16-Aug-21						LIFE LIMIT
SN:316447	HRS	2448:43	9600		12048:43		8602:47	
	AFL	749						
PROC. REF: AMM 34 11 01 961 801PROC. REF: AMM 34 11 01 961 801								
34-13-00-201	FUNCTIONAL TEST OF THE INTEGRATED ELECTRONIC STANDBY INSTRUMENT (A/C 9158 AND SUBS)							Service ATA:34
	MOS	17-Oct-23	30 (+3m/-3m)	Adj 3	17-Jul-26	17-Oct-26	505 d (+92)	
	HRS	3029:02						
WC#: 34.030	AFL	1119						
PROC. REF: AMM 34 12 03 720 801PROC. REF: AMM 34 12 03 720 801								
34-21-01-900-801-01	STANDBY ATTITUDE HORIZON INDICATOR							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.075	AFL	0		TSN 0				
PROC. REF: AMM 34 21 01 000 801, AMM 34 21 01 400 801PROC. REF: AMM 34 21 01 000 801, AMM 34 21 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-22-01-900-801-01	STANDBY COMPASS							Component ATA:34
PN:WL1001KCA1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BC5010109	HRS	0		TSN 0				
WC#: 34.080	AFL	0		TSN 0				
PROC. REF: AMM 34 22 01 000 801, AMM 34 22 01 400 801PROC. REF: AMM 34 22 01 000 801, AMM 34 22 01 400 801								
34-32-00-201	DETAILED INSPECTION OF THE ELECTRO-OPTICAL UNIT HYGROMETER SENSOR (IF HUDS INSTALLED)							Service ATA:34
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		3444:24	3494:24	TOL (+48:28)	
WC#: 34.035	AFL	745						
PROC. REF: AMM 34 32 13 220 801PROC. REF: AMM 34 32 13 220 801								
34-41-03-900-801-01	NOSE RADOME RECEIVER/TRANSMITTER ANTENNA							Component ATA:34
PN:7021450-801	MOS/MSC	11-Nov-11	O/C	TSR 1				
SN:099051457	HRS	480		TSR 0				
WC#: 34.085	AFL	180		TSR 0				
PROC. REF: AMM 34 41 03 000 801, AMM 34 41 03 400 801PROC. REF: AMM 34 41 03 000 801, AMM 34 41 03 400 801								
34-41-05-900-801-01	LH WEATHER RADAR CONTROLLER							Component ATA:34
PN:7008471-415	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0811A948	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
PROC. REF: AMM 34 41 05 000 801, AMM 34 41 05 400 801PROC. REF: AMM 34 41 05 000 801, AMM 34 41 05 400 801								
34-41-05-900-801-02	RH WEATHER RADAR CONTROLLER							Component ATA:34
PN:7008471-417	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0901B033	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
PROC. REF: AMM 34 41 05 000 801, AMM 34 41 05 400 801PROC. REF: AMM 34 41 05 000 801, AMM 34 41 05 400 801								
34-42-01-900-801-01	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER							Component ATA:34
PN:965-0976-040-224-224	MOS/MSC	28-Jun-12	O/C	TSR 1				
SN:EMK5-32845	HRS	758:06		TSR 0				
WC#: 34.095	AFL	255		TSR 0				
PROC. REF: AMM 34 42 01 000 801, AMM 34 42 01 400 801PROC. REF: AMM 34 42 01 000 801, AMM 34 42 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-43-01-900-801-01	TCAS PROCESSOR							Component ATA:34
PN:7517900-10020	MOS/MSC	19-Aug-13	O/C					
SN:00033241	HRS	1056:36						
WC#: 34.100	AFL	360						
PROC. REF: AMM 34 43 01 000 801, AMM 34 43 01 400 801PROC. REF: AMM 34 43 01 000 801, AMM 34 43 01 400 801								
34-43-05-900-801-01	TCAS LOWER TCAS ANTENNA							Component ATA:34
PN:S65-5366-10L	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:9316	HRS	0		TSN 0				
WC#: 34.105	AFL	0		TSN 0				
PROC. REF: AMM 34 43 05 000 801, AMM 34 43 05 400 801PROC. REF: AMM 34 43 05 000 801, AMM 34 43 05 400 801								
34-43-09-900-801-01	UPPER DIRECTIONAL TCAS ANTENNA							Component ATA:34
PN:7514081-914	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:ANE31698	HRS	0		TSN 0				
WC#: 34.110	AFL	0		TSN 0				
PROC. REF: AMM 34 43 09 000 801, AMM 34 43 09 400 801PROC. REF: AMM 34 43 09 000 801, AMM 34 43 09 400 801								
34-44-01-900-801-01	NO. 1 RADIO ALTIMETER RECEIVER							Component ATA:34
PN:822-0615-207	MOS/MSC	15-May-24	O/C	TSR 0				
SN:4K8MK	HRS	3168:27		TSR 0				
WC#: 34.115	AFL	1205		TSR 0				
PROC. REF: AMM 34 44 01 000 801, AMM 34 44 01 400 801PROC. REF: AMM 34 44 01 000 801, AMM 34 44 01 400 801								
34-44-01-900-801-02	NO. 2 RADIO ALTIMETER RECEIVER							Component ATA:34
PN:822-0615-207	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2V6JF	HRS	0		TSN 0				
WC#: 34.115	AFL	0		TSN 0				
PROC. REF: AMM 34 44 01 000 801, AMM 34 44 01 400 801PROC. REF: AMM 34 44 01 000 801, AMM 34 44 01 400 801								
34-44-05-201	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE RADIO ALTIMETER ANTENNAS CONNECTORS							Service ATA:34
	MOS	05-Feb-21	60 (+3m/-3m)	05-Feb-26	05-May-26	343 d (+89)	MRB	
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 34 44 05 210 801PROC. REF: AMM 34 44 05 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-44-05-900-801-01	TRANSCEIVER NO. 1 RADIO ALTIMETER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.120	AFL	0		TSN 0				
PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801								
34-44-05-900-801-02	TRANSCEIVER NO. 2 RADIO ALTIMETER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.120	AFL	0		TSN 0				
PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801								
34-44-05-900-801-03	RECEIVER NO. 1 RADIO ALTIMETER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.125	AFL	0		TSN 0				
PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801								
34-44-05-900-801-04	RECEIVER NO. 2 RADIO ALTIMETER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.125	AFL	0		TSN 0				
PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801PROC. REF: AMM 34 44 05 000 801, AMM 34 44 05 400 801								
34-45-01-900-801-01	NO. 1 IRU							Component ATA:34
PN:HG2001GD03	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:56022213	HRS	0		TSN 0				
WC#: 34.130	AFL	0		TSN 0				
PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801								
34-45-01-900-801-02	NO. 2 IRU							Component ATA:34
PN:HG2001GD03	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:56022214	HRS	0		TSN 0				
WC#: 34.130	AFL	0		TSN 0				
PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-45-01-900-801-03	NO. 3 IRU							Component ATA:34
PN:HG2001GD03	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:56022237	HRS	0		TSN 0				
WC#: 34.130	AFL	0		TSN 0				
PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801PROC. REF: AMM 34 45 01 000 801, AMM 34 45 01 400 801								
34-45-05-900-801-01	MSU TRIPLEX MODE SELECT CONTROL PANEL							Component ATA:34
PN:CG2015AC10	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.135	AFL	0		TSN 0				
PROC. REF: AMM 34 45 05 000 801, AMM 34 45 05 400 801PROC. REF: AMM 34 45 05 000 801, AMM 34 45 05 400 801								
34-46-01-900-801-01	CONTROL DISPLAY (IRS) UNIT							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.140	AFL	0		TSN 0				
PROC. REF: AMM 34 46 01 000 801, AMM 34 46 01 400 801PROC. REF: AMM 34 46 01 000 801, AMM 34 46 01 400 801								
34-47-01-900-801-01	LIGHTNING LP-860 PROCESSOR							Component ATA:34
PN:7011822-904	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09072143	HRS	0		TSN 0				
WC#: 34.145	AFL	0		TSN 0				
PROC. REF: AMM 34 47 01 000 801, AMM 34 47 01 400 801PROC. REF: AMM 34 47 01 000 801, AMM 34 47 01 400 801								
34-47-05-900-801-01	LIGHTNING, LSS SENSOR							Component ATA:34
PN:7014062-901	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09051467	HRS	0		TSN 0				
WC#: 34.150	AFL	0		TSN 0				
PROC. REF: AMM 34 47 05 000 801, AMM 34 47 05 400 801PROC. REF: AMM 34 47 05 000 801, AMM 34 47 05 400 801								
34-47-05-900-802-01	(AT-850) ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.155	AFL	0		TSN 0				
PROC. REF: AMM 34 47 05 000 801, AMM 34 47 05 400 801PROC. REF: AMM 34 47 05 000 801, AMM 34 47 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-51-01-900-801-01	NO. 1 RECEIVER NAVIGATION UNIT							Component ATA:34
PN:7510100-631	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0903C110	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
PROC. REF: AMM 34 51 01 000 801, AMM 34 51 01 400 801PROC. REF: AMM 34 51 01 000 801, AMM 34 51 01 400 801								
34-51-01-900-801-02	NO. 2 RECEIVER NAVIGATION UNIT							Component ATA:34
PN:7510100-631	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0903C111	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
PROC. REF: AMM 34 51 01 000 801, AMM 34 51 01 400 801PROC. REF: AMM 34 51 01 000 801, AMM 34 51 01 400 801								
34-51-05-900-801-01	LH VOR/ILS (WHITE) ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.165	AFL	0		TSN 0				
PROC. REF: AMM 34 51 05 000 801, AMM 34 51 05 400 801PROC. REF: AMM 34 51 05 000 801, AMM 34 51 05 400 801								
34-51-05-900-801-02	RH VOR/ILS (WHITE) ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.165	AFL	0		TSN 0				
PROC. REF: AMM 34 51 05 000 801, AMM 34 51 05 400 801PROC. REF: AMM 34 51 05 000 801, AMM 34 51 05 400 801								
34-51-09-900-801-01	VOR/LOC PHASING COUPLER							Component ATA:34
PN:SSPD-113-38	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:666-2003	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: AMM 34 51 09 000 801, AMM 34 51 09 400 801PROC. REF: AMM 34 51 09 000 801, AMM 34 51 09 400 801								
34-51-17-900-801-01	GLIDE SLOPE ANTENNA							Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.175	AFL	0		TSN 0				
PROC. REF: AMM 34 51 17 000 801, AMM 34 51 17 400 801PROC. REF: AMM 34 51 17 000 801, AMM 34 51 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-51-21-900-801-01		GLIDESLOPE ANTENNA DIPLEXER						Component ATA:34
PN:DMH24-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:25115	HRS	0		TSN 0				
WC#: 34.180	AFL	0		TSN 0				
PROC. REF: AMM 34 51 21 000 801, AMM 34 51 21 400 801PROC. REF: AMM 34 51 21 000 801, AMM 34 51 21 400 801								
34-51-25-900-801-01		BOTTOM MARKER BEACON ANTENNA						Component ATA:34
PN:S35-1000-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:102-7808	HRS	0		TSN 0				
WC#: 34.185	AFL	0		TSN 0				
PROC. REF: AMM 34 51 25 000 801, AMM 34 51 25 400 801PROC. REF: AMM 34 51 25 000 801, AMM 34 51 25 400 801								
34-52-01-900-801-01		NO. 1 ADF (AT-860) ANTENNA						Component ATA:34
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: AMM 34 52 01 000 801, AMM 34 52 01 400 801PROC. REF: AMM 34 52 01 000 801, AMM 34 52 01 400 801								
34-52-01-900-801-02		NO. 2 ADF (AT-860) ANTENNA						Component ATA:34
PN:7510300-901	MOS/MSC	01-Aug-16	O/C	TSN 4				
SN:1504N712	HRS	1980:38		TSN 0				
WC#: 34.190	AFL	604		TSN 0				
PROC. REF: AMM 34 52 01 000 801, AMM 34 52 01 400 801PROC. REF: AMM 34 52 01 000 801, AMM 34 52 01 400 801								
34-53-01-900-801-01		NO.1 LOWER DME ANTENNA						Component ATA:34
PN:S65-5366-10L	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:9301	HRS	0		TSN 0				
WC#: 34.195	AFL	0		TSN 0				
PROC. REF: AMM 34 53 01 000 801, AMM 34 53 01 400 801PROC. REF: AMM 34 53 01 000 801, AMM 34 53 01 400 801								
34-53-01-900-801-02		NO.2 LOWER DME ANTENNA						Component ATA:34
PN:S65-5366-10L	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:9313	HRS	0		TSN 0				
WC#: 34.195	AFL	0		TSN 0				
PROC. REF: AMM 34 53 01 000 801, AMM 34 53 01 400 801PROC. REF: AMM 34 53 01 000 801, AMM 34 53 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-54-01-900-801-01		NO.1 UPPER ATC ANTENNA						Component ATA:34
PN:S65-5366-10L	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:9332	HRS	0		TSN 0				
WC#: 34.200	AFL	0		TSN 0				
PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801								
34-54-01-900-801-02		NO.2 UPPER ATC ANTENNA						Component ATA:34
PN:S65-5366-10L	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:9333	HRS	0		TSN 0				
WC#: 34.200	AFL	0		TSN 0				
PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801								
34-54-01-900-801-03		NO.1 LOWER ATC ANTENNA						Component ATA:34
PN:S65-5366-10L	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:185-15362	HRS	2444:24		TSN 0				
WC#: 34.200	AFL	745		TSN 0				
PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801								
34-54-01-900-801-04		NO.2 LOWER ATC ANTENNA						Component ATA:34
PN:S65-5366-10L	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:185-15356	HRS	2444:24		TSN 0				
WC#: 34.200	AFL	745		TSN 0				
PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801PROC. REF: AMM 34 54 01 000 801, AMM 34 54 01 400 801								
34-55-01-900-801-01		NO. 1 GLOBAL POSITIONING SENSOR UNIT						Component ATA:34
PN:HG2021GD04	MOS/MSC	21-Aug-13	O/C					
SN:0859	HRS	1056:36						
WC#: 34.205	AFL	360						
PROC. REF: AMM 34 55 01 000 801, AMM 34 55 01 400 801PROC. REF: AMM 34 55 01 000 801, AMM 34 55 01 400 801								
34-55-01-900-801-02		NO. 2 GLOBAL POSITIONING SENSOR UNIT						Component ATA:34
PN:HG2021GD04	MOS/MSC	21-Aug-13	O/C					
SN:0953	HRS	1056:36						
WC#: 34.205	AFL	360						
PROC. REF: AMM 34 55 01 000 801, AMM 34 55 01 400 801PROC. REF: AMM 34 55 01 000 801, AMM 34 55 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-55-05-900-801-01	GPS ANTENNA NO.1							Component ATA:34
PN:S67-1575-137	MOS/MSC	21-Aug-13	O/C	TSN 0				
SN:773-1633	HRS	1056:36		TSN 0				
WC#: 34.210	AFL	360		TSN 0				
PROC. REF: AMM 34 55 05 000 801, AMM 34 55 05 400 801PROC. REF: AMM 34 55 05 000 801, AMM 34 55 05 400 801								
34-55-05-900-801-02	GPS ANTENNA NO.2							Component ATA:34
PN:S67-1575-137	MOS/MSC	21-Aug-13	O/C	TSN 0				
SN:773-1634	HRS	1056:36		TSN 0				
WC#: 34.210	AFL	360		TSN 0				
PROC. REF: AMM 34 55 05 000 801, AMM 34 55 05 400 801PROC. REF: AMM 34 55 05 000 801, AMM 34 55 05 400 801								
34-61-01-900-801-01	NO. 1 FMS CDU UNIT							Component ATA:34
PN:2888-09-1	MOS/MSC	17-May-22	O/C					
SN:C459631	HRS	2534:36						
WC#: 34.215	AFL	798						
PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801								
34-61-01-900-801-02	NO. 2 FMS CDU UNIT							Component ATA:34
PN:2888-09-1	MOS/MSC	14-Jul-19	O/C					
SN:C433560	HRS	2437:10						
WC#: 34.215	AFL	742						
PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801								
34-61-01-900-801-03	NO. 3 FMS CDU UNIT							Component ATA:34
PN:2888-09-1	MOS/MSC	17-May-22	O/C	TSN 154				
SN:C459411	HRS	2534:36		TSN 2534:36				
WC#: 34.215	AFL	798		TSN 798				
PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801PROC. REF: AMM 34 61 01 000 801, AMM 34 61 01 400 801								
34-62-01-900-801-01	FMS DATA LOADER							Component ATA:34
PN:G7226-01	MOS/MSC	17-Nov-17	O/C					
SN:235	HRS	2265:06						
WC#: 34.220	AFL	682						
PROC. REF: AMM 34 62 01 000 801, AMM 34 62 01 400 801PROC. REF: AMM 34 62 01 000 801, AMM 34 62 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-CUS-001A ^U	UPDATE DATABASE EGPWS							Service ATA:34
PN:N/A	MOS/MSC	10-Mar-23	A/R					CUSTOMER CODE
SN:475	HRS	2845:10						
	AFL	999						
343200-701 ^U	OPTICAL PROJECTOR UNIT							Component ATA:34
PN:GT546-0003-3	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:554	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
343201-701 ^U	OPTICAL COMBINER UNIT							Component ATA:34
PN:GT546-0004-5	MOS/MSC	19-Sep-22	O/C	TSR 0				
SN:145	HRS	2696:42		TSR 0				
	AFL	918		TSR 0				
343202-701 ^U	HUD COMPUTER							Component ATA:34
PN:GT546-0001-7	MOS/MSC	05-Jun-23	O/C	TSR 0				
SN:643	HRS	2913:47		TSR 0				
	AFL	1041		TSR 0				
343300-701 ^U	INFRARED WINDOW							Component ATA:34
PN:GT546-1001-1	MOS/MSC	14-Jun-15	O/C	TSN 1				
SN:15131175	HRS	1735:58		TSN 0				
	AFL	536		TSN 0				
343301-701 ^U	INFRARED SENSOR UNIT							Component ATA:34
PN:GT546-1000-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09401213	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
343302-701 ^U	EVS HEATER CONTROLLER							Component ATA:34
PN:GT546-1002-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:733623IN00207	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
343303-701 ^U	AC IDENTIFICATION (AIT) TAG							Component ATA:34
PN:GT546-1003-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:09210838	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
343304-701 ^U	EVS HEATED FAIRING							Component ATA:34
PN:GC214-0166-1	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:0223	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
ATA 35 - OXYGEN								
35-10-05-201	RESTORATION LH FULL FACE CREW OXYGEN MASK (35-10-05-201)							Service ATA:35
PN:MF10-08-01	MOS	10-Nov-20	75		18-Nov-26 (M)		629 d	RECOMMENDED
SN:SE19075	HRS							
WC#: 35.035	AFL							
PROC. REF: AMM 35 11 05 615 801PROC. REF: AMM 35 11 05 615 801								
35-10-05-201	RESTORATION RH FULL FACE CREW OXYGEN MASK (35-10-05-201)							Service ATA:35
PN:MF10-08-01	MOS	16-Aug-22	75		18-Aug-28 (M)		1268 d	RECOMMENDED
SN:SE172611	HRS	2696:42						
WC#: 35.040	AFL	918						
PROC. REF: AMM 35 11 05 615 801PROC. REF: AMM 35 11 05 615 801								
35-11-01-201	DISCARD LEFT LOWER OXYGEN CYLINDER & REGULATOR BOTTLE							Service ATA:35
	MOS	01-Sep-15	180		01-Sep-30		2012 d	LIFE LIMIT
	HRS							
	AFL							
Manufacture Date:: 01-Sep-15								
PROC. REF: AMM 35 11 01 960 802PROC. REF: AMM 35 11 01 960 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-01-201	DISCARD LEFT UPPER OXYGEN CYLINDER & REGULATOR BOTTLE							Service ATA:35
	MOS	01-Sep-15	180		01-Sep-30		2012 d	LIFE LIMIT
	HRS							
	AFL							
Manufacture Date:: 01-Sep-15								
PROC. REF: AMM 35 11 01 960 802PROC. REF: AMM 35 11 01 960 802								
35-11-01-201	DISCARD RIGHT LOWER OXYGEN CYLINDER & REGULATOR BOTTLE							Service ATA:35
	MOS	01-Sep-15	180		01-Sep-30		2012 d	LIFE LIMIT
	HRS							
	AFL							
Manufacture Date:: 01-Sep-15								
PROC. REF: AMM 35 11 01 960 802PROC. REF: AMM 35 11 01 960 802								
35-11-01-201	DISCARD RIGHT UPPER OXYGEN CYLINDER & REGULATOR BOTTLE							Service ATA:35
	MOS	01-Apr-12	180		01-Apr-27		763 d	LIFE LIMIT
	HRS							
	AFL							
Manufacture Date:: 01-Apr-12								
PROC. REF: AMM 35 11 01 960 802PROC. REF: AMM 35 11 01 960 802								
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE LEFT LOWER OXYGEN CYLINDER & REGULATOR BOTTLE							Service ATA:35
PN:806371-130	MOS	11-Dec-20	60		11-Dec-25		287 d	MRB
SN:C08040569	HRS							
WC#: 35.025	AFL							
HydroCheck Date: : 11-Dec-20								
PROC. REF: AMM 35 11 01 720 801PROC. REF: AMM 35 11 01 720 801								
35-11-01-202	FUNCTIONAL TEST (HYDROSTATIC) OF THE LEFT UPPER OXYGEN CYLINDER & REGULATOR BOTTLE							Service ATA:35
PN:806371-130	MOS	11-Dec-20	60		11-Dec-25		287 d	MRB
SN:ALT279-26689	HRS							
WC#: 35.015	AFL							
HydroCheck Date: : 11-Dec-20								
PROC. REF: AMM 35 11 01 720 801PROC. REF: AMM 35 11 01 720 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-01-202		FUNCTIONAL TEST (HYDROSTATIC) OF THE RIGHT LOWER OXYGEN CYLINDER & REGULATOR BOTTLE						Service ATA:35
PN:806371-130	MOS	11-Dec-20	60		11-Dec-25		287 d	MRB
SN:ALT279-26670	HRS							
WC#: 35.030	AFL							
HydroCheck Date: : 11-Dec-20								
PROC. REF: AMM 35 11 01 720 801PROC. REF: AMM 35 11 01 720 801								
35-11-01-202		FUNCTIONAL TEST (HYDROSTATIC) OF THE RIGHT UPPER OXYGEN CYLINDER & REGULATOR BOTTLE						Service ATA:35
PN:806371-130	MOS	01-Oct-20	60		01-Oct-25		216 d	MRB
SN:C12060539	HRS							
WC#: 35.020	AFL							
HydroCheck Date: : 01-Oct-20								
PROC. REF: AMM 35 11 01 720 801PROC. REF: AMM 35 11 01 720 801								
35-11-01-900-801-01		LEFT UPPER OXYGEN CYLINDER & REGULATOR BOTTLE						Component ATA:35
PN:806371-130	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:ALT279-26689	HRS	2444:24						
WC#: 35.015	AFL	745						
PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801								
35-11-01-900-801-02		RIGHT UPPER OXYGEN CYLINDER & REGULATOR BOTTLE						Component ATA:35
PN:806371-130	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:C12060539	HRS	2444:24						
WC#: 35.020	AFL	745						
PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801								
35-11-01-900-801-03		LEFT LOWER OXYGEN CYLINDER & REGULATOR BOTTLE						Component ATA:35
PN:806371-130	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:C08040569	HRS	2444:24						
WC#: 35.025	AFL	745						
PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801								
35-11-01-900-801-04		RIGHT LOWER OXYGEN CYLINDER & REGULATOR BOTTLE						Component ATA:35
PN:806371-130	MOS/MSC	05-Feb-21	H/T	TSN 0				
SN:ALT279-26670	HRS	2444:24						
WC#: 35.030	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801PROC. REF: AMM 35 11 01 000 801, AMM 35 11 01 400 801									
35-11-05-900-801-01	LH FULL FACE CREW OXYGEN MASK							Component	ATA:35
PN:MF10-08-01	MOS/MSC	05-Feb-21	O/C	TSO 0					
SN:SE19075	HRS	2444:24	TSO 0						
WC#: 35.035	AFL	745	TSO 0						
PROC. REF: AMM 35 11 05 000 801, AMM 35 11 05 400 801PROC. REF: AMM 35 11 05 000 801, AMM 35 11 05 400 801									
35-11-05-900-801-02	RH FULL FACE CREW OXYGEN MASK							Component	ATA:35
PN:MF10-08-01	MOS/MSC	19-Sep-22	O/C	TSO 0					
SN:SE172611	HRS	2696:42	TSO 0						
WC#: 35.040	AFL	918	TSO 0						
PROC. REF: AMM 35 11 05 000 801, AMM 35 11 05 400 801PROC. REF: AMM 35 11 05 000 801, AMM 35 11 05 400 801									
35-11-09-900-801-01	LH STOWAGE BOX							Component	ATA:35
PN:MXP411-3	MOS/MSC	05-Feb-21	O/C	TSN 0					
SN:SE124337	HRS	2444:24	TSN 0						
WC#: 35.045	AFL	745	TSN 0						
PROC. REF: AMM 35 11 09 000 801, AMM 35 11 09 400 801PROC. REF: AMM 35 11 09 000 801, AMM 35 11 09 400 801									
35-11-09-900-801-02	RH STOWAGE BOX							Component	ATA:35
PN:MXP411-3	MOS/MSC	10-Mar-23	O/C	TSO 0					
SN:SE56545	HRS	2845:10	TSO 0						
WC#: 35.045	AFL	999	TSO 0						
PROC. REF: CMM VENDOR FLAG FIRE, AMM 35 11 09 000 801, AMM 35 11 09 400 801PROC. REF: CMM VENDOR FLAG FIRE, AMM 35 11 09 000 801, AMM 35 11 09 400 801									
35-11-50-621 ^U	OPERATIONAL TEST OF THE CREW OXYGEN SYSTEM MODIFICATIONS MASKS							Service	ATA:35
	MOS	15-May-24	15	15-Aug-25			169 d	STLMC	
	HRS	3168:27							
	AFL	1205							
35-12-09-900-801-01	OXYGEN PRESSURE TRANSDUCER							Component	ATA:35
PN:GC481-0070-5	MOS/MSC	30-Jul-09	O/C	TSN 0					
SN:6697	HRS	0	TSN 0						
WC#: 35.050	AFL	0	TSN 0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35 12 09 000 801, AMM 35 12 09 400 801PROC. REF: AMM 35 12 09 000 801, AMM 35 12 09 400 801								
35-20-05-900-801-01	S/O THERAPEUTIC OXYGEN VALVE							Component ATA:35
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.010	AFL	0		TSN 0				
PROC. REF: AMM 35 20 05 000 801, AMM 35 20 05 400 801PROC. REF: AMM 35 20 05 000 801, AMM 35 20 05 400 801								
35-21-01-201	FUNCTIONAL TEST OF THE PASSENGER OXYGEN CONTROL PANEL							Service ATA:35
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 35.005	AFL	999						
PROC. REF: AMM 35 21 01 720 801PROC. REF: AMM 35 21 01 720 801								
35-21-01-900-801-01	PASSENGER OXYGEN CONTROL PANEL / ALTIMETRIC VALVE							Component ATA:35
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.055	AFL	0		TSN 0				
PROC. REF: AMM 35 21 01 000 801, AMM 35 21 01 400 801PROC. REF: AMM 35 21 01 000 801, AMM 35 21 01 400 801								
35-21-01-900-801-02 ^U	RH- ALTIMETRIC VALVE							Component ATA:35
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.055	AFL	0		TSN 0				
35-21-01-900-802-01 ^U	PASSENGER OXYGEN CONTROLLER							Component ATA:35
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.060	AFL	0		TSN 0				
35-21-50-621 ^U	OPERATIONAL TEST OF THE PASSENGER OXYGEN SYSTEM							Service ATA:35
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-50-622 ^U FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM								
	MOS	15-May-24	15		15-Aug-25		169 d	Service ATA:35
	HRS	3168:27						STLMC
	AFL	1205						
351102-701 ^U WARDROBE PROTECTIVE BREATHING EQUIPMENT - PBE								
PN:MR-10037N	MOS/MSC	05-Feb-21	A/R	TSN 0				Component ATA:35
SN:E1702150	HRS	2444:24		TSN 0				
	AFL	745		TSN 0				
351102-701B ^U RESTORE WARDROBE PROTECTIVE BREATHING EQUIPMENT - PBE (35-11-50-624)								
PN:MR-10037N	MOS/MSC	18-Feb-22	DUE		01-Nov-27 (M)		977 d	Service ATA:35
SN:E1702150	HRS	2452:23						STLMC
	AFL	753						
351103-701 ^U PILOT (SWEEP-ON 2000) CREW OXYGEN MASK								
PN:174252-14	MOS/MSC	18-Feb-22	O/C	TSO 0				Component ATA:35
SN:25031	HRS	2452:23		TSO 0				
	AFL	753		TSO 0				
351103-701B ^U RESTORATION PILOT (SWEEP-ON 2000) CREW OXYGEN MASK (35-11-50-622)								
PN:174252-14	MOS	03-Jun-21	75		03-Sep-27		918 d	Service ATA:35
SN:25031	HRS							STLMC
	AFL							
351103-702 ^U COPILOT (SWEEP-ON 2000) CREW OXYGEN MASK								
PN:174252-14	MOS/MSC	19-Feb-22	O/C	TSO 0				Component ATA:35
SN:11292	HRS	2453:47		TSO 0				
	AFL	754		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351103-702B ^U	RESTORATION COPILOT (SWEEP-ON 2000) CREW OXYGEN MASK (35-11-50-622)							Service ATA:35
PN:174252-14	MOS	25-Aug-21	75		25-Nov-27		1001 d	STLMC
SN:11292	HRS							
	AFL							
351103-703 ^U	3RD CREW OXYGEN MASK							Component ATA:35
PN:MC20-004	MOS/MSC	18-Feb-22	O/C	TSO 0				
SN:SE28424I	HRS	2452:23		TSO 0				
	AFL	753		TSO 0				
351103-703B ^U	RESTORATION 3RD CREW OXYGEN MASK (35-11-50-622)							Service ATA:35
PN:MC20-004	MOS	06-Jan-22	75		01-Jan-28 (M)		1038 d	STLMC
SN:SE28424I	HRS							
	AFL							
ATA 36 - PNEUMATIC								
36-11-01-900-801-01	LH HIGH PRESSURE BLEED VALVE							Component ATA:36
PN:GG436-1001-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00857	HRS	0		TSN 0				
WC#: 36.005	AFL	0		TSN 0				
PROC. REF: AMM 36 11 01 000 801, AMM 36 11 01 400 801PROC. REF: AMM 36 11 01 000 801, AMM 36 11 01 400 801								
36-11-01-900-801-02	RH HIGH PRESSURE BLEED VALVE							Component ATA:36
PN:GG436-1001-9	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00858	HRS	0		TSN 0				
WC#: 36.005	AFL	0		TSN 0				
PROC. REF: AMM 36 11 01 000 801, AMM 36 11 01 400 801PROC. REF: AMM 36 11 01 000 801, AMM 36 11 01 400 801								
36-11-05-900-801-01	LH CHECK INTERMEDIATE PRESSURE VALVE							Component ATA:36
PN:GG436-1002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00863	HRS	0		TSN 0				
WC#: 36.010	AFL	0		TSN 0				
PROC. REF: AMM 36 11 05 000 801, AMM 36 11 05 400 801PROC. REF: AMM 36 11 05 000 801, AMM 36 11 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-05-900-801-02	RH CHECK INTERMEDIATE PRESSURE VALVE							Component ATA:36
PN:GG436-1002-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:00848	HRS	0		TSN 0				
WC#: 36.010	AFL	0		TSN 0				
PROC. REF: AMM 36 11 05 000 801, AMM 36 11 05 400 801PROC. REF: AMM 36 11 05 000 801, AMM 36 11 05 400 801								
36-11-09-900-801-01	LH BLEED PRESS - REGULATING & S/O VALVE							Component ATA:36
PN:GG436-1055-3	MOS/MSC	10-Mar-23	O/C					
SN:13902	HRS	2845:10						
WC#: 36.015	AFL	999						
PROC. REF: AMM 36 11 09 000 801, AMM 36 11 09 400 801PROC. REF: AMM 36 11 09 000 801, AMM 36 11 09 400 801								
36-11-09-900-801-02	RH BLEED PRESS - REGULATING & S/O VALVE							Component ATA:36
PN:GG436-1055-1	MOS/MSC	13-Dec-18	O/C					
SN:00192	HRS	2346:06						
WC#: 36.015	AFL	718						
PROC. REF: AMM 36 11 09 000 801, AMM 36 11 09 400 801PROC. REF: AMM 36 11 09 000 801, AMM 36 11 09 400 801								
36-11-13-900-803-01	LH PRECOOLER							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.020	AFL	0		TSN 0				
PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801								
36-11-13-900-803-02	RH PRECOOLER							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.020	AFL	0		TSN 0				
PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801PROC. REF: AMM 36 11 13 000 801, AMM 36 11 13 400 801								
36-11-13-900-804-01	LH PLENUM INLET							Component ATA:36
PN:GG468-4072-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0374	HRS	0		TSN 0				
WC#: 36.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-13-900-804-02	RH PLENUM INLET							Component ATA:36
PN:GG468-4072-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0368	HRS	0		TSN 0				
WC#: 36.025	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36-11-17-900-801-01	LEFT HAND FAN AIR VALVE UROSEAL CONNECTOR							Component ATA:36
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4194	HRS	0		TSN 0				
WC#: 36.030	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 36 11 17 000 801, AMM 36 11 17 400 801PROC. REF: CMM 30-12-06, AMM 36 11 17 000 801, AMM 36 11 17 400 801								
36-11-17-900-801-02	RIGHT HAND FAN AIR VALVE UROSEAL CONNECTOR							Component ATA:36
PN:GG468-4054-15	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:4352	HRS	0		TSN 0				
WC#: 36.030	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 36 11 17 000 801, AMM 36 11 17 400 801PROC. REF: CMM 30-12-06, AMM 36 11 17 000 801, AMM 36 11 17 400 801								
36-11-17-900-802-01	LH FAN AIR VALVE							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.035	AFL	0		TSN 0				
PROC. REF: AMM 36 11 17 000 801, AMM 36 11 17 400 801PROC. REF: AMM 36 11 17 000 801, AMM 36 11 17 400 801								
36-11-17-900-802-02	RH FAN AIR VALVE							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.035	AFL	0		TSN 0				
PROC. REF: AMM 36 11 17 000 801, AMM 36 11 17 400 801PROC. REF: AMM 36 11 17 000 801, AMM 36 11 17 400 801								
36-11-21-201	DISCARD OF THE LH PNEUMATIC TEMPERATURE THERMOSTAT (THC) FILTER							Service ATA:36
PN:PN	MOS	28-Sep-17						
SN:UNKNOWN	HRS	2242:56	2250		4492:56		1047	
	AFL	677						
PROC. REF: AMM 36 11 21 961 801PROC. REF: AMM 36 11 21 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-21-201	DISCARD OF THE RH PNEUMATIC TEMPERATURE THERMOSTAT (THC) FILTER							Service ATA:36
PN:PN	MOS	28-Sep-17						
SN:UNKNOWN	HRS	2242:56	2250		4492:56		1047	
	AFL	677						
PROC. REF: AMM 36 11 21 961 801PROC. REF: AMM 36 11 21 961 801								
36-11-21-900-801-01	LH PNEUMATIC TEMP THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.040	AFL	0		TSN 0				
PROC. REF: CMM 36-12-05, AMM 36 11 21 000 801, AMM 36 11 21 400 801PROC. REF: CMM 36-12-05, AMM 36 11 21 000 801, AMM 36 11 21 400 801								
36-11-21-900-801-02	RH PNEUMATIC TEMP THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.040	AFL	0		TSN 0				
PROC. REF: CMM 36-12-05, AMM 36 11 21 000 801, AMM 36 11 21 400 801PROC. REF: CMM 36-12-05, AMM 36 11 21 000 801, AMM 36 11 21 400 801								
36-11-21-900-802-01	LH TEMPERATURE CONTROL THERMOSTAT FILTER							Component ATA:36
PN:CG0752503458N02	MOS/MSC	28-Sep-17	O/C	TSN 0				
SN:UNKNOWN	HRS	2242:56		TSN 0				
	AFL	677		TSN 0				
PROC. REF: AMM 36 11 21, AMM 36 11 21PROC. REF: AMM 36 11 21, AMM 36 11 21								
36-11-21-900-802-02	RH TEMPERATURE CONTROL THERMOSTAT FILTER							Component ATA:36
PN:CG0752503458N02	MOS/MSC	28-Sep-17	O/C	TSN 0				
SN:UNKNOWN	HRS	2242:56		TSN 0				
	AFL	677		TSN 0				
PROC. REF: AMM 36 11 21, AMM 36 11 21PROC. REF: AMM 36 11 21, AMM 36 11 21								
36-11-25-900-801-01	LH BLEED PRESSURE TRANSDUCER							Component ATA:36
PN:GG436-1007-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2220	HRS	0		TSN 0				
WC#: 36.045	AFL	0		TSN 0				
PROC. REF: AMM 36 11 25 000 801, AMM 36 11 25 400 801PROC. REF: AMM 36 11 25 000 801, AMM 36 11 25 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-25-900-801-02	RH BLEED PRESSURE TRANSDUCER							Component ATA:36
PN:GG436-1007-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2224	HRS	0		TSN 0				
WC#: 36.045	AFL	0		TSN 0				
PROC. REF: AMM 36 11 25 000 801, AMM 36 11 25 400 801PROC. REF: AMM 36 11 25 000 801, AMM 36 11 25 400 801								
36-11-29-900-801-01	LEFT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR							Component ATA:36
PN:GG468-4054-17	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:3352	HRS	0		TSN 0				
WC#: 36.050	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801								
36-11-29-900-801-02	RIGHT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR							Component ATA:36
PN:GG468-4054-17	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:3359	HRS	0		TSN 0				
WC#: 36.050	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801								
36-11-29-900-801-03	APU CROSS BLEED VALVE UROSEAL CONNECTOR							Component ATA:36
PN:GG468-4054-19	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:3847	HRS	0		TSN 0				
WC#: 36.050	AFL	0		TSN 0				
PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801PROC. REF: CMM 30-12-06, AMM 36 11 29 000 801, AMM 36 11 29 400 801								
36-11-29-900-802-01	LH BOOT							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.055	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36-11-29-900-802-02	RH BOOT							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.055	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-29-900-803-01	CROSS BLEED VALVE							Component ATA:36
PN:GG436-1008-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:01066	HRS	0		TSN 0				
WC#: 36.060	AFL	0		TSN 0				
PROC. REF: AMM 36 11 29 000 801, AMM 36 11 29 400 801PROC. REF: AMM 36 11 29 000 801, AMM 36 11 29 400 801								
36-11-29-900-804-01	COUPLING COVER							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.065	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36-11-33-900-801-01	LH BLEED MANAGEMENT (BMC) CONTROLLER							Component ATA:36
PN:GG546-1017-13	MOS/MSC	26-May-17	O/C					
SN:0840	HRS	2159:23						
WC#: 36.070	AFL	651						
PROC. REF: AMM 36 11 33 000 801, AMM 36 11 33 400 801PROC. REF: AMM 36 11 33 000 801, AMM 36 11 33 400 801								
36-11-33-900-801-02	RH BLEED MANAGEMENT (BMC) CONTROLLER							Component ATA:36
PN:GG546-1017-13	MOS/MSC	26-May-17	O/C					
SN:0846	HRS	2159:23						
WC#: 36.070	AFL	651						
PROC. REF: AMM 36 11 33 000 801, AMM 36 11 33 400 801PROC. REF: AMM 36 11 33 000 801, AMM 36 11 33 400 801								
36-11-37-900-801-01	LH IP PRESSURE TRANSDUCER							Component ATA:36
PN:GG436-1018-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1012	HRS	0		TSN 0				
WC#: 36.075	AFL	0		TSN 0				
PROC. REF: AMM 36 11 37 000 801, AMM 36 11 37 400 801PROC. REF: AMM 36 11 37 000 801, AMM 36 11 37 400 801								
36-11-37-900-801-02	RH IP PRESSURE TRANSDUCER							Component ATA:36
PN:GG436-1018-1	MOS/MSC	13-Dec-18	O/C					
SN:10912	HRS	2346:06						
WC#: 36.075	AFL	718						
PROC. REF: AMM 36 11 37 000 801, AMM 36 11 37 400 801PROC. REF: AMM 36 11 37 000 801, AMM 36 11 37 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-41-900-801-01	HP GROUND CONNECTION							Component ATA:36
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.080	AFL	0		TSN 0				
PROC. REF: AMM 36 11 41 000 801, AMM 36 11 41 400 801PROC. REF: AMM 36 11 41 000 801, AMM 36 11 41 400 801								
36-11-41-900-802-01	DUCT							Component ATA:36
PN:GG468-4066-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0372	HRS	0		TSN 0				
WC#: 36.085	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36-11-61-101	DISCARD APU CROSS BLEED VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-19	MOS	30-Jul-09						LIFE LIMIT
SN:3847	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD L/H FLOW CONTROL VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4412	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD LEFT BLEED FILTER UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4314	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD LEFT HAND FAN AIR VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4194	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-61-101	DISCARD LEFT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-17	MOS	30-Jul-09						LIFE LIMIT
SN:3352	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD LH FLOW SENSOR VENTURI UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4290	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD R/H FLOW CONTROL VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4418	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD RH FLOW SENSOR VENTURI UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4201	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD RIGHT BLEED FILTER UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4392	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
36-11-61-101	DISCARD RIGHT HAND FAN AIR VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-15	MOS	30-Jul-09						LIFE LIMIT
SN:4352	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-61-101	DISCARD RIGHT SIDE CROSS BLEED VALVE UROSEAL CONNECTOR							Service ATA:36
PN:GG468-4054-17	MOS	30-Jul-09						LIFE LIMIT
SN:3359	HRS	0	8000		8000		4554:04	
	AFL	0						
PROC. REF: AMM 36 11 61 961 801PROC. REF: AMM 36 11 61 961 801								
ATA 37 - VACUUM								
380020-701 ^U	AFT LAV WATER SHUT OFF VALVE							Component ATA:37
PN:4E4348-7	MOS/MSC	15-May-24	O/C	TSR 0				
SN:N1336403	HRS	3168:27		TSR 0				
	AFL	1205		TSR 0				
ATA 38 - WATER/WASTE								
38-11-50-621 ^U	GENERAL VISUAL INSPECTION OF THE POTABLE WATER SYSTEM (PWS) DISTRIBUTION CIRCUIT							Service ATA:38
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
38-11-50-622 ^U OPERATIONAL TEST OF THE WATER SUPPLY SHUT-OFF CIRCUIT								
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
38-13-50-621 ^U RESTORATION OF THE WATER TREATMENT UNIT								
PN:09-130021-102	MOS	05-Jun-23						STLMC
SN:1-0971	HRS	2913:47	2000		4913:47		1467:51	
	AFL	1041						
38-30-50-621 ^U GENERAL VISUAL INSPECTION OF THE WASTE WATER DRAIN CIRCUIT								
	MOS	10-Mar-23	30		10-Sep-25		195 d	STLMC
	HRS	2845:10						
	AFL	999						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
38-30-50-622 ^U GENERAL VISUAL INSPECTION OF THE WASTE WATER DISPOSAL SYSTEM								
	MOS	15-Oct-24	45		15-Jul-28		1234 d	Service ATA:38
	HRS	3314:03						STLMC
	AFL	1328						
38-30-50-623 ^U CLEANING OF THE WASTE VACUUM PIPES								
	MOS	15-Oct-24						Service ATA:38
	HRS	3314:03	500		3814:03		368:07	STLMC
	AFL	1328						
38-30-52-621 ^U CLEANING OF THE WASTE/WATER SEPARATOR								
	MOS	30-Jul-09						Service ATA:38
	HRS	0	5000		5000		1554:04	STLMC
	AFL	0						
38-32-69-621 ^U OPERATIONAL TEST (BITE) OF THE WASTE SYSTEM LOGIC CONTROL MODULE								
	MOS	15-Oct-24						Service ATA:38
	HRS	3314:03	500		3814:03		368:07	STLMC
	AFL	1328						
380007-701 ^U WATER STERILIZER UNIT UNIT								
PN:09-130021-102	MOS/MSC	05-Jun-23	O/C	TSR 0				Component ATA:38
SN:1-0971	HRS	2913:47		TSR 0				
	AFL	1041		TSR 0				
381001-701 ^U EIB CONTROL PANEL								
PN:5E2651-10	MOS/MSC	07-Nov-12	O/C	TSN 27				Component ATA:38
SN:U181	HRS	869:06		TSN 841				
	AFL	308		TSN 297				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381100-701 ^U	TOILET (FWD LAVATORY) ASSEMBLY							Component ATA:38
PN:7900371	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:0006	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
381101-701 ^U	WATER (FWD LAVATORY) HEATER							Component ATA:38
PN:4E4099-2	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:N0935002	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
381115-701 ^U	FWD DRAIN VALVE							Component ATA:38
PN:4E4348-1	MOS/MSC	07-Aug-24	O/C					
SN:N0525206	HRS	3251:33						
	AFL	1279						
381200-701 ^U	GALLEY WATER HEATER							Component ATA:38
PN:4E4099-3	MOS/MSC	05-Feb-21	O/C	TSN 126				
SN:N0935605	HRS	2444:24		TSN 2416:18				
	AFL	745		TSN 734				
381300-701 ^U	TOILET (AFT LAVATORY) ASSEMBLY							Component ATA:38
PN:7900268	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:0007	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
381301-701 ^U	WATER (AFT LAVATORY) HEATER							Component ATA:38
PN:4E4099-3	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:N0935607	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381310-701 ^U	AFT LAV FLUSH SWITCH PANEL							Component ATA:38
PN:2600-1-1-T17SA	MOS/MSC	05-Jun-14	O/C	TSN 1				
SN:43P39K	HRS	1240:07		TSN 0				
	AFL	414		TSN 0				
381400-701 ^U	WATER CONTROL PANEL							Component ATA:38
PN:4E3600-1	MOS/MSC	30-Sep-11	O/C	TSN 0				
SN:U0336	HRS	442		TSN 0				
	AFL	173		TSN 0				
ELJ380010 ^U	INSPECT UV FILTER OF POTABLE WATER TREATMENT UNIT (WTU) TO VALIDATE THE REMAINING HOURS FOR RESTORATION OF UV LAMP AND CHARCOAL FILTER SEE PART B OF SB 700-1A11-38-016 FOR INSTRUCTIONS.							Service ATA:38
	MOS	15-Oct-24	12		15-Oct-25		230 d	
	HRS	3314:03						
	AFL	1328						
ATA 44 - CABIN SYSTEMS								
441001-701 ^U	GALLEY TOUCHSCREEN EQT (TSE) 10.4" MONITOR-							Component ATA:44
PN:1308520-100	MOS/MSC	04-May-12	O/C	TSR 6				
SN:2DWJP	HRS	668:15		TSR 0				
	AFL	225		TSR 0				
441002-703 ^U	FWD 24" MONITOR-							Component ATA:44
PN:866-0023-002	MOS/MSC	27-Jan-19	O/C	TSN 101				
SN:DM0159	HRS	2346:58		TSN 2318:52				
	AFL	719		TSN 708				
441002-704 ^U	AFT 24" MONITOR-							Component ATA:44
PN:866-0023-002	MOS/MSC	27-Jan-19	O/C	TSN 101				
SN:DM0198	HRS	2346:58		TSN 2318:52				
	AFL	719		TSN 708				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
441004-701 ^U	ETHERNET SWITCHING (MCE #1) EQUIPMENT							Component ATA:44
PN:822-1943-002	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3LLNP	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441004-702 ^U	ETHERNET SWITCHING (MCE #2) EQUIPMENT							Component ATA:44
PN:822-1943-002	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3LLPF	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441005-701 ^U	MOVING MAP (MME) #1 EQUIPMENT							Component ATA:44
PN:822-1881-101	MOS/MSC	17-Oct-23	O/C	TSO 0				
SN:3TWLX	HRS	3029:02		TSO 0				
	AFL	1119		TSO 0				
441006-701 ^U	PROCESSOR / MASS STORAGE EQUIP. (MCE #1) EQUIPMENT							Component ATA:44
PN:822-1880-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3LLTL	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441006-702 ^U	PROCESSOR / MASS STORAGE EQUIP. (MCE #2) EQUIPMENT							Component ATA:44
PN:822-1880-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3TWHL	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441007-701 ^U	MCE #1 POWER SUPPLY							Component ATA:44
PN:822-1879-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3LLLN	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
441007-702 ^U	MCE #2 POWER SUPPLY							Component ATA:44
PN:822-1879-001	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3LLLY	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441008-701 ^U	NO. 1 ZONE DISTRIBUTION EQUIPMENT							Component ATA:44
PN:1308523-101	MOS/MSC	15-Oct-24	O/C	TSO 0				
SN:4JF2D	HRS	3314:03		TSO 0				
	AFL	1328		TSO 0				
441008-702 ^U	NO. 2 ZONE DISTRIBUTION EQUIPMENT							Component ATA:44
PN:1308523-101	MOS/MSC	15-Oct-24	O/C					
SN:2VJBD	HRS	3314:03						
	AFL	1328						
441008-703 ^U	NO. 3 ZONE DISTRIBUTION EQUIPMENT							Component ATA:44
PN:1308523-101	MOS/MSC	15-Oct-24	O/C	TSR 0				
SN:35WVV	HRS	3314:03		TSR 0				
	AFL	1328		TSR 0				
441008-704 ^U	NO. 4 ZONE DISTRIBUTION EQUIPMENT							Component ATA:44
PN:1308523-101	MOS/MSC	21-Sep-12	O/C					
SN:3JRGB	HRS	801:24						
	AFL	291						
441009-701 ^U	NO.1 RELAY DRIVE (RDE) EQUIPMENT							Component ATA:44
PN:2052-1-10	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3KMNR	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
441009-702 ^U	NO.2 RELAY DRIVE (RDE) EQUIPMENT							Component ATA:44
PN:2052-1-10	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3KMNW	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441009-703 ^U	NO.3 RELAY DRIVE (RDE) EQUIPMENT							Component ATA:44
PN:2052-1-10	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3KMNT	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
441009-704 ^U	NO.4 RELAY DRIVE (RDE) EQUIPMENT							Component ATA:44
PN:2052-1-10	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3KMNX	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
442001-701 ^U	VIDEO ENCODER (VEE) - #2 EQUIPMENT							Component ATA:44
PN:1308525-100	MOS/MSC	17-May-22	O/C	TSO 0				
SN:3JRPR	HRS	2534:36		TSO 0				
	AFL	798		TSO 0				
442002-701 ^U	AUDIO (A563) AMPLIFIER							Component ATA:44
PN:3600-1-2	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:3KMYC	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
442005-701 ^U	ETHERNET PLAYER CD/DVD/MP3 (CREW REST) UNIT							Component ATA:44
PN:866-0025-001	MOS/MSC	16-Aug-21	O/C					
SN:004357	HRS	2448:43						
	AFL	749						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
442005-702 ^U	ETHERNET PLAYER CD/DVD/MP3 (CREW REST) UNIT							Component ATA:44
PN:866-0025-001	MOS/MSC	16-Aug-21	O/C					
SN:004729	HRS	2448:43						
	AFL	749						
442307-701 ^U	CONFIGURATION DATA (CDM) MODULE							Component ATA:44
PN:822-2248-001	MOS/MSC	16-Jun-22	O/C	TSN 0				
SN:4DHDX3	HRS	2557:30		TSN 0				
	AFL	821		TSN 0				
ATA 45 - CENTRAL MAINT SYSTEM								
45-45-00-201	VISUAL CHECK OF THE ENGINE MAINTENANCE ALERTS							Service ATA:45
	MOS	15-Oct-24						MRIP
	HRS	3314:03	500 (+50/-50)	Adj 31:07	3814:03 (M)	3864:03	368:07 (+50)	
WC#: 45.005	AFL	1328						
PROC. REF: AMM 71 00 00 210 803PROC. REF: AMM 71 00 00 210 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 46 - INFORMATION SYSTEMS								
46-20-50-601 ^U	OPERATIONAL TEST OF THE ELECTRONIC FLIGHT BAG INTERNAL BATTERY PACK							Service ATA:46
	MOS	15-May-24	15		15-Aug-25		169 d	STLMC
	HRS	3168:27						
	AFL	1205						
461013-701 ^U	ENHANCED EXPANSION MODULE (EEMU) - #1 UNIT							Component ATA:46
PN:245-604170-105	MOS/MSC	04-Aug-11	O/C					
SN:1369	HRS	352:27						
	AFL	136						
461013-702 ^U	ENHANCED EXPANSION MODULE (EEMU) - #2 UNIT							Component ATA:46
PN:245-604170-105	MOS/MSC	04-Aug-11	O/C					
SN:1506	HRS	352:27						
	AFL	136						
462001-701 ^U	ELECTRONIC DISPLAY (EDU) - #1 UNIT							Component ATA:46
PN:245-604128-000	MOS/MSC	20-Dec-15	O/C	TSN 64				
SN:0860	HRS	1866:26		TSN 1838:37				
	AFL	570		TSN 559				
462001-702 ^U	ELECTRONIC DISPLAY (EDU) - #2 UNIT							Component ATA:46
PN:245-604128-000	MOS/MSC	01-Mar-18	O/C	TSN 91, TSR 47				
SN:1836	HRS	2266:05		TSR 0				
	AFL	683		TSR 0				
ATA 49 - AIRBORNE AUXILIARY POWER								
49-11-00-201	VISUAL CHECK OF THE SUPPORT MOUNTINGS							Service ATA:49
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 49.005	AFL	999						
PROC. REF: AMM 49 11 00 210 801PROC. REF: AMM 49 11 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49-11-01-201	VISUAL CHECK OF THE MOUNTING STRUTS							Service ATA:49
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 49.010	AFL	999						
PROC. REF: AMM 49 11 01 210 801PROC. REF: AMM 49 11 01 210 801								
49-14-05-101	DISCARD THE APU DOOR LINEAR ACTUATOR, PART NO. 8653M9							Service ATA:49
PN:8653M12	MOS/MSC	30-Jul-09	N/A					
SN:08100124	HRS	0						
	AFL	0						
PROC. REF: AMM 49 14 05 961 801PROC. REF: AMM 49 14 05 961 801								
49-14-05-900-801-01	LINEAR ACTUATOR							Component ATA:49
PN:8653M12	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:08100124	HRS	0		TSN 0				
WC#: 49.040	AFL	0		TSN 0				
PROC. REF: AMM 49 14 05 000 801, AMM 49 14 05 400 801PROC. REF: AMM 49 14 05 000 801, AMM 49 14 05 400 801								
49-15-00-201	GENERAL VISUAL INSPECTION OF THE OIL-COOLER DUCT AND BOOT ASSEMBLY							Service ATA:49
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 49.015	AFL	999						
PROC. REF: AMM 49 15 00 210 801PROC. REF: AMM 49 15 00 210 801								
49-15-09-201	GENERAL VISUAL INSPECTION OF THE INLET DUCT AND BOOT ASSEMBLY							Service ATA:49
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 49.020	AFL	999						
PROC. REF: AMM 49 15 00 210 802PROC. REF: AMM 49 15 00 210 802								
49-18-00-201	APU - GENERAL VISUAL INSPECTION OF THE APU DRAIN LINES							Service ATA:49
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2374	1000 (+50/-50)		3374	3424	216 (+50)	
	APUS	2180						
PROC. REF: AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49-18-00, AMM 49 18 00 210 801, AMM 49-18-00, AMM 49 18 00 210 801, AMM 49 18 00 210 801PROC. REF: AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49 18 00 210 801, AMM 49-18-00, AMM 49 18 00 210 801, AMM 49-18-00, AMM 49 18 00 210 801, AMM 49 18 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49-21-00-301	APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (PRE SB RE220-49-7813)							Service ATA:49
	MOS/MSC	30-Jul-09	N/A					OPTIONAL
	HRS	0						
	APUS	0						
PROC. REF: AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49 21 00 170 801PROC. REF: AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49 21 00 170 801								
49-21-00-302	APU - CLEANING OF THE AUXILIARY POWER UNIT (APU) COMBUSTOR (POST SB RE220-49-7813 AND APU S/N P-286 AND SUBS)							Service ATA:49
	MOS	03-May-17						OPTIONAL
	HRS	1971	2000 (+50/-50)	Adj 29	4000	4050	842 (+50)	
	APUS	1792						
PROC. REF: AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49 21 00 170 801PROC. REF: AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49-21-00, AMM 49 21 00 170 801, AMM 49 21 00 170 801								
49-24-00-201	APU - DISCARD THE COMPRESSOR IMPELLER							Service ATA:49
PN:WB3822573-1	MOS	30-Jul-09						LIFE LIMIT
SN:08-03501-19005	HRS	0						
	APUS	0	20000		20000		16692	
PROC. REF: AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49 10 00 961 803PROC. REF: AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49 10 00 961 803								
49-24-00-202	APU - DISCARD THE FIRST STAGE AXIAL TURBINE DISK							Service ATA:49
PN:WK3840141-3	MOS	30-Jul-09						LIFE LIMIT
SN:082241001586	HRS	0						
	APUS	0	20000		20000		16692	
PROC. REF: AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49 10 00 961 802PROC. REF: AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49 10 00 961 802								
49-24-00-203	APU - DISCARD THE SECOND STAGE AXIAL TURBINE DISK							Service ATA:49
PN:WE897994-3	MOS	30-Jul-09						MRB
SN:09-01345-00390	HRS	0	20000		20000		16842	
	APUS	0						
PROC. REF: AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49 10 00 961 801PROC. REF: AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49 10 00 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49-30-00-204	APU - GENERAL VISUAL INSPECTION OF THE APU FUEL-SYSTEM COMPONENTS							Service ATA:49
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2404	1000 (+50/-50)	Adj 50	3454	3504	296 (+50)	
	APUS	2222						
PROC. REF: AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49-30-00, AMM 49 30 00 210 804, AMM 49-30-00, AMM 49 30 00 210 804, AMM 49 30 00 210 804PROC. REF: AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49 30 00 210 804, AMM 49-30-00, AMM 49 30 00 210 804, AMM 49-30-00, AMM 49 30 00 210 804, AMM 49 30 00 210 804								
49-42-00-301	APU - CLEANING OF THE STARTER MOTOR OF BRUSH DUST MATERIAL							Service ATA:49
	MOS	15-May-24						OPTIONAL
	HRS	2937	750 (+50/-50)		3687	3737	529 (+50)	
	APUS							
PROC. REF: AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49-42-01, AMM 49 42 01 110 801, AMM 49-42-01, AMM 49 42 01 110 801, AMM 49 42 01 110 801PROC. REF: AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49 42 01 110 801, AMM 49-42-01, AMM 49 42 01 110 801, AMM 49-42-01, AMM 49 42 01 110 801, AMM 49 42 01 110 801								
49-42-01-201	APU - DETAILED INSPECTION OF THE STARTER MOTOR							Service ATA:49
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2374	1000 (+50/-50)		3374	3424	216 (+50)	
	APUS	2180						
PROC. REF: AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49-42-01, AMM 49 42 01 220 801, AMM 49-42-01, AMM 49 42 01 220 801, AMM 49 42 01 220 801PROC. REF: AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49 42 01 220 801, AMM 49-42-01, AMM 49 42 01 220 801, AMM 49-42-01, AMM 49 42 01 220 801, AMM 49 42 01 220 801								
49-52-00-301	APU - CLEANING OF THE LOAD-CONTROL-VALVE INLET FILTER (LOAD CONTROL VALVE P/N 3291210-3)							Service ATA:49
	MOS/MSC		N/A					
	HRS							
	APUS							
PROC. REF: AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49-52-05, AMM 49 52 05 160 801, AMM 49-52-05, AMM 49 52 05 160 801, AMM 49 52 05 160 801PROC. REF: AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49 52 05 160 801, AMM 49-52-05, AMM 49 52 05 160 801, AMM 49-52-05, AMM 49 52 05 160 801, AMM 49 52 05 160 801								
49-61-01-900-801-01	FADEC CONTROLLER							Component ATA:49
PN:2118990-3	MOS/MSC	27-Jul-15	O/C					
SN:114-K0125	HRS	1778:44		TSN 4493:54				
WC#: 49.045	AFL	545						
PROC. REF: AMM 49 61 01 000 801, AMM 49 61 01 400 801PROC. REF: AMM 49 61 01 000 801, AMM 49 61 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49-62-00-201	APU - OPERATIONAL TEST OF THE APU EMERGENCY SHUTDOWN (APU SHUTDOWN SWITCH AND AFT SERVICE CONTROL PANEL APU SHUT-OFF SWITCH)							Service ATA:49
	MOS	21-Jul-21	135 (+3m/-3m)	Adj 3	21-Jan-33	21-Apr-33	2885 d (+90)	MRIP
	HRS	2404	2250 (+50/-50)		4654	4704	1496 (+50)	
	APUS	2222						
PROC. REF: AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49-62-00, AMM 49 62 00 710 802, AMM 49-62-00, AMM 49 62 00 710 802, AMM 49 62 00 710 802PROC. REF: AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49 62 00 710 802, AMM 49-62-00, AMM 49 62 00 710 802, AMM 49-62-00, AMM 49 62 00 710 802, AMM 49 62 00 710 802								
49-70-00-201	VISUAL CHECK OF THE APU INDICATING SYSTEM							Service ATA:49
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		3446:06	3496:06	0:10 (+50)	
WC#: 49.025	AFL	747						
PROC. REF: AMM 49 70 00 210 801PROC. REF: AMM 49 70 00 210 801								
49-80-05-201	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT							Service ATA:49
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 49.030	AFL	999						
PROC. REF: AMM 49 80 05 210 801PROC. REF: AMM 49 80 05 210 801								
49-80-05-900-801-01	APU EXHAUST DUCT ASSY (LOWER) INSULATION							Component ATA:49
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
49-80-05-900-802-01	THERMAL BLANKET							Component ATA:49
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.055	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
49-80-05-900-803-01	EXHAUST TAILPIPE DUCT							Component ATA:49
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.060	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
PROC. REF: AMM 49 80 05 000 801, AMM 49 80 05 400 801PROC. REF: AMM 49 80 05 000 801, AMM 49 80 05 400 801								
49-80-09-201	GENERAL VISUAL INSPECTION OF THE APU-EXHAUST TAILPIPE-DUCT SEAL							Service ATA:49
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 49.035	AFL	999						
PROC. REF: AMM 49 80 09 210 801PROC. REF: AMM 49 80 09 210 801								
49-90-00-204	APU - GENERAL VISUAL INSPECTION OF THE APU OIL-SYSTEM COMPONENTS							Service ATA:49
	MOS	18-Feb-22	60 (+3m/-3m)		18-Feb-27	18-May-27	721 d (+89)	MRIP
	HRS	2452:23	1000 (+50/-50)		3452:23	3502:23	294:23 (+50)	
	APUS							
PROC. REF: AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49-90-00, AMM 49 90 00 210 804, AMM 49-90-00, AMM 49 90 00 210 804, AMM 49 90 00 210 804PROC. REF: AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49 90 00 210 804, AMM 49-90-00, AMM 49 90 00 210 804, AMM 49-90-00, AMM 49 90 00 210 804, AMM 49 90 00 210 804								
49-90-29-201	APU - DISCARD THE APU OIL-FILTER ELEMENT							Service ATA:49
	MOS	15-May-24						MRB
	HRS	2937	1500 (+50/-50)		4437	4487	1279 (+50)	
	APUS							
PROC. REF: AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49-90-29, AMM 49 90 29 961 801, AMM 49-90-29, AMM 49 90 29 961 801, AMM 49 90 29 961 801PROC. REF: AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49 90 29 961 801, AMM 49-90-29, AMM 49 90 29 961 801, AMM 49-90-29, AMM 49 90 29 961 801, AMM 49 90 29 961 801								
49-90-29-202	APU - DISCARD THE APU-GENERATOR SCAVENGE-OIL FILTER-ELEMENT							Service ATA:49
	MOS	15-May-24						MRB
	HRS	2937	1500 (+50/-50)		4437	4487	1279 (+50)	
	APUS							
PROC. REF: AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49-90-29, AMM 49 90 29 961 802, AMM 49-90-29, AMM 49 90 29 961 802, AMM 49 90 29 961 802PROC. REF: AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49 90 29 961 802, AMM 49-90-29, AMM 49 90 29 961 802, AMM 49-90-29, AMM 49 90 29 961 802, AMM 49 90 29 961 802								
490002-001	APU - WIRING HARNESS							Component ATA:49
PN:WE3888471-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09-16226-22116	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 12 01 000 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801PROC. REF: AMM 49 12 01 000 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801, AMM 49 12 01 000 801, AMM 49 12 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
492001-001	APU - IMPELLER							Component ATA:49
PN:WB3822573-1	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:08-03501-19005	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49 10 00 961 803PROC. REF: AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49-10-00, AMM 49 10 00 961 803, AMM 49 10 00 961 803, AMM 49 10 00 961 803								
492002-001	APU - FIRST STAGE TURBINE ROTOR ASSEMBLY							Component ATA:49
PN:WK3840141-3	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:082241001586	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49 10 00 961 802PROC. REF: AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49-10-00, AMM 49 10 00 961 802, AMM 49 10 00 961 802, AMM 49 10 00 961 802								
492003-001	APU - SECOND STAGE TURBINE ROTOR ASSEMBLY							Component ATA:49
PN:WE897994-3	MOS/MSC	30-Jul-09	H/T	TSN 0				
SN:09-01345-00390	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49 10 00 961 801PROC. REF: AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49-10-00, AMM 49 10 00 961 801, AMM 49 10 00 961 801, AMM 49 10 00 961 801								
493001-001	APU - FUEL CONTROL UNIT FCU							Component ATA:49
PN:441950-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:CUB20521	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801PROC. REF: AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801, AMM 49 30 01 000 801, AMM 49 30 01 400 801								
494001-002	APU - STARTER MOTOR							Component ATA:49
PN:2704554-2	MOS/MSC	05-Feb-21	O/C	TSN 139, TSR 0				
SN:1612	HRS			TSR 0				
	APUS			TSR 0				
PROC. REF: AMM 49 42 01 000 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801PROC. REF: AMM 49 42 01 000 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801, AMM 49 42 01 000 801, AMM 49 42 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
494101-001	APU - IGNITION EXCITER							Component ATA:49
PN:WE3876295-6	MOS/MSC	10-Mar-23	O/C	TSO 0				
SN:J13300014	HRS	2707		TSO 0				
	APUS	2596		TSO 0				
PROC. REF: AMM 49 41 01 000 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801PROC. REF: AMM 49 41 01 000 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801, AMM 49 41 01 000 801, AMM 49 41 01 400 801								
495101-001	APU - SURGE VALVE							Component ATA:49
PN:3291212-4	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1026	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 51 01 000 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801PROC. REF: AMM 49 51 01 000 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801, AMM 49 51 01 000 801, AMM 49 51 01 400 801								
495205-001	APU - LOAD CONTROL VALVE							Component ATA:49
PN:3291210-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1785	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 52 05 000 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801PROC. REF: AMM 49 52 05 000 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801, AMM 49 52 05 000 801, AMM 49 52 05 400 801								
496102-001	APU - INLET PRESSURE SENSOR							Component ATA:49
PN:WE3876283-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:091121420994	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 61 13 000 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801PROC. REF: AMM 49 61 13 000 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801, AMM 49 61 13 000 801, AMM 49 61 13 400 801								
496103-001	APU - SPEED SENSOR							Component ATA:49
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 61 17 000 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801PROC. REF: AMM 49 61 17 000 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801, AMM 49 61 17 000 801, AMM 49 61 17 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
496105-001	APU - NO. 1 EXHAUST GAS TEMPERATURE SENSOR							Component ATA:49
PN:WE3876352-2	MOS/MSC	04-May-12	O/C	TSN 2				
SN:MFR50413-1101069	HRS	559		TSN 0				
	APUS	621		TSN 0				
PROC. REF: AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801PROC. REF: AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801								
496105-002	APU - NO. 2 EXHAUST GAS TEMPERATURE SENSOR							Component ATA:49
PN:WE3876352-2	MOS/MSC	04-May-12	O/C	TSN 2				
SN:MFR50413-1101012	HRS	559		TSN 0				
	APUS	621		TSN 0				
PROC. REF: AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801PROC. REF: AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801, AMM 49 61 05 000 801, AMM 49 61 05 400 801								
499001-001	APU - OIL COOLER							Component ATA:49
PN:160534-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1717	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49 90 37 000 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801PROC. REF: AMM 49 90 37 000 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801, AMM 49 90 37 000 801, AMM 49 90 37 400 801								
499002-001	APU - LUBE PUMP							Component ATA:49
PN:WE3881781-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:VE2465	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
499035-001	APU - DIFFERENTIAL PRESSURE-GENERATOR SWITCH							Component ATA:49
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
499053-001	APU - APU GEARBOX							Component ATA:49
PN:WK3805055-6	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:092241010418	HRS	0		TSN 0				
	APUS	0		TSN 0				
499110	APU - SOAP OIL CHECK							Service ATA:49
	MOS/MSC	21-Jul-21	A/R					
	HRS	2404						
	APUS	2222						
49APU1	APU							Component ATA:49
PN:WE3800714-1	MOS/MSC		E/C					
SN:P-487	HRS							
WC#: 49.APU1	AFL							
PROC. REF: AMM 49 10 00 000 801, AMM 49 10 00 400 801PROC. REF: AMM 49 10 00 000 801, AMM 49 10 00 400 801								
ATA 52 - DOORS								
52-10-00-207	LUBRICATION OF THE PASSENGER DOOR							Service ATA:52
	MOS	18-Feb-22	90 (+3m/-3m)		18-Aug-29 (M)	18-Nov-29	1633 d (+92)	MRIP
	HRS	2452:23	1500 (+50/-50)	Adj 50	4002:23	4052:23	556:27 (+50)	
WC#: 52.005	AFL	753						
PROC. REF: AMM 12 22 00 640 808PROC. REF: AMM 12 22 00 640 808								
52-11-00-101	DETAILED INSPECTION OF THE OUTER-SKIN OF THE PASSENGER DOOR							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 52.010	AFL	0	T:5255		5255		3866	
PROC. REF: AMM 52 11 00 220 803PROC. REF: AMM 52 11 00 220 803								
52-11-00-102	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE FRAMES							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 52.015	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-52-10-001PROC. REF: NDT ET-52-10-001								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-00-103	DETAILED INSPECTION OF THE PASSENGER DOOR MOUNTING SIDE-FRAMES, STOPS, SKIN AND STIFFENERS - INTERNAL							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 52.020	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 52 11 00 220 806PROC. REF: AMM 52 11 00 220 806								
52-11-00-105	GENERAL VISUAL INSPECTION OF THE SKIN EXTERNAL SURFACE							Service ATA:52
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 52.025	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 52 11 00 210 808PROC. REF: AMM 52 11 00 210 808								
52-11-00-106	VISUAL CHECK OF THE PASSENGER-DOOR VENT-FLAP MECHANISM (CMR*)							Service ATA:52
	MOS	15-Oct-24						AIRWORTHINESS
	HRS	3314:03	500		3814:03		368:07	
	AFL	1328						
PROC. REF: AMM 52 11 00 210 807PROC. REF: AMM 52 11 00 210 807								
52-11-00-201	FUNCTIONAL TEST OF THE PASSENGER DOOR MECHANISM							Service ATA:52
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRIP
	HRS	2446:06	2250 (+50/-50)		4696:06	4746:06	1250:10 (+50)	
WC#: 52.030	AFL	747						
PROC. REF: AMM 52 11 00 720 801PROC. REF: AMM 52 11 00 720 801								
52-11-00-202	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PASSENGER DOOR							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.035	AFL	745						
PROC. REF: AMM 52 11 00 220 801PROC. REF: AMM 52 11 00 220 801								
52-11-00-203	DETAILED INSPECTION OF THE STOPS AND ABUTMENTS OF THE PASSENGER DOOR							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.040	AFL	745						
PROC. REF: AMM 52 11 00 220 802PROC. REF: AMM 52 11 00 220 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-00-900-801-01	PASSENGER DOOR ASSY							Component ATA:52
PN:GS328-0010-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB/GX/S090	HRS	0		TSN 0				
WC#: 52.170	AFL	0		TSN 0				
PROC. REF: AMM 52 11 00 000 801, AMM 52 11 00 400 801PROC. REF: AMM 52 11 00 000 801, AMM 52 11 00 400 801								
52-11-21-201	DETAILED INSPECTION OF THE HANDRAILS ATTACHMENT TO THE FUSELAGE							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.050	AFL	745						
PROC. REF: AMM 52 11 21 220 801PROC. REF: AMM 52 11 21 220 801								
52-11-25-101	RESTORATION OF PASSENGER DOOR ACTUATOR MOTOR PART NO. GS321-0591-9 (GEARHEAD, PART NO. 2H4A321809A)							Service ATA:52
PN:GS321-0591-9	MOS	15-Oct-24						OVERHAUL
SN:F0719	HRS	3314:03						
	AFL	1328	850		2178		789	
PROC. REF: AMM 52 11 25 610 801PROC. REF: AMM 52 11 25 610 801								
52-11-25-900-801-01	PASSENGER DOOR ACTUATOR MOTOR							Component ATA:52
PN:GS321-0591-9	MOS/MSC	15-Oct-24	O/C	TSR 0				
SN:F0719	HRS	3314:03		TSN 3923:12, TSR 0				
WC#: 52.175	AFL	1328		TSN 1608, TSR 0				
PROC. REF: AMM 52 11 25 000 801, AMM 52 11 25 400 801PROC. REF: AMM 52 11 25 000 801, AMM 52 11 25 400 801								
52-11-29-900-801-01	PASSENGER DOOR AIRSTAIR							Component ATA:52
PN:GS328-0009-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:SB/GX/11153	HRS	0		TSN 0				
WC#: 52.180	AFL	0		TSN 0				
PROC. REF: AMM 52 11 29 000 801, AMM 52 11 29 400 801PROC. REF: AMM 52 11 29 000 801, AMM 52 11 29 400 801								
52-11-41-101	DISCARD NO. 1 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1							Service ATA:52
PN:GS321-0580-1	MOS	15-Oct-24						LIFE LIMIT
SN:11001	HRS	3314:03						
	AFL	1328	650		1978		589	
PROC. REF: AMM 52 11 41 961 801PROC. REF: AMM 52 11 41 961 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-41-101	DISCARD NO. 2 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1							Service ATA:52
PN:GS321-0580-1	MOS	15-Oct-24						LIFE LIMIT
SN:11005	HRS	3314:03						
	AFL	1328	650		1978		589	
PROC. REF: AMM 52 11 41 961 801PROC. REF: AMM 52 11 41 961 801								
52-11-41-101	DISCARD NO. 3 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1							Service ATA:52
PN:GS321-0580-1	MOS	15-Oct-24						LIFE LIMIT
SN:11006	HRS	3314:03						
	AFL	1328	650		1978		589	
PROC. REF: AMM 52 11 41 961 801PROC. REF: AMM 52 11 41 961 801								
52-11-41-101	DISCARD NO. 4 PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1							Service ATA:52
PN:GS321-0580-1	MOS	15-Oct-24						LIFE LIMIT
SN:11004	HRS	3314:03						
	AFL	1328	650		1978		589	
PROC. REF: AMM 52 11 41 961 801PROC. REF: AMM 52 11 41 961 801								
52-11-41-101	DISCARD THE PASSENGER DOOR TENSATOR SPRING, PART NO. GS321-0580-1							Service ATA:52
	MOS	15-Oct-24						LIFE LIMIT
	HRS	3314:03						
	AFL	1328	650		1978		589	
PROC. REF: AMM 52 11 41 961 801PROC. REF: AMM 52 11 41 961 801								
52-11-41-900-801-01	NO. 1 PASSENGER DOOR TENSATOR SPRING							Component ATA:52
PN:GS321-0580-1	MOS/MSC	15-Oct-24	H/T	TSN 0				
SN:11001	HRS	3314:03		TSN 0				
	AFL	1328		TSN 0				
PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801								
52-11-41-900-801-02	NO. 2 PASSENGER DOOR TENSATOR SPRING							Component ATA:52
PN:GS321-0580-1	MOS/MSC	15-Oct-24	H/T	TSN 0				
SN:11005	HRS	3314:03		TSN 0				
	AFL	1328		TSN 0				
PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-11-41-900-801-03	NO. 3 PASSENGER DOOR TENSATOR SPRING							Component ATA:52
PN:GS321-0580-1	MOS/MSC	15-Oct-24	H/T	TSN 0				
SN:11006	HRS	3314:03		TSN 0				
	AFL	1328		TSN 0				
PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801								
52-11-41-900-801-04	NO. 4 PASSENGER DOOR TENSATOR SPRING							Component ATA:52
PN:GS321-0580-1	MOS/MSC	15-Oct-24	H/T	TSN 0				
SN:11004	HRS	3314:03		TSN 0				
	AFL	1328		TSN 0				
PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801PROC. REF: AMM 52 11 41 000 801, AMM 52 11 41 400 801								
52-11-61-900-801-01 ^U	DOORSTEP ACTUATOR							Component ATA:52
PN:500-1-21600-003	MOS/MSC	19-Sep-22	O/C	TSR 0				
SN:0490	HRS	2696:42		TSN 4096:23, TSR 0				
	AFL	918		TSN 1050, TSR 0				
52-21-00-103	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE OVERWING EMERGENCY EXIT							Service ATA:52
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 52.065	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 52 21 00 210 803PROC. REF: AMM 52 21 00 210 803								
52-21-00-104	DETAILED INSPECTION OF THE OVER-WING EMERGENCY EXIT DOOR							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 52 21 00 220 803PROC. REF: AMM 52 21 00 220 803								
52-21-00-201	OPERATIONAL TEST OF THE OVER-WING EMERGENCY-EXIT							Service ATA:52
	MOS	15-May-24	15 (+3m/-3m)		15-Aug-25 (M)	15-Nov-25	169 d (+92)	MRB
	HRS	3168:27						
WC#: 52.070	AFL	1205						
PROC. REF: AMM 52 21 00 710 801PROC. REF: AMM 52 21 00 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-21-00-202	FUNCTIONAL TEST OF THE OVER-WING EMERGENCY-EXIT EXIT PULL SIGN							Service ATA:52
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 52.075	AFL	999						
PROC. REF: AMM 52 21 00 720 802PROC. REF: AMM 52 21 00 720 802								
52-21-00-203	LUBRICATION OF THE OVER-WING EMERGENCY-EXIT DOOR							Service ATA:52
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 52.080	AFL	999						
PROC. REF: AMM 12 22 00 640 805PROC. REF: AMM 12 22 00 640 805								
52-21-00-204	DETAILED INSPECTION OF THE LATCH FITTINGS AND DOOR STOP FITTINGS OF THE OVER-WING EMERGENCY EXIT							Service ATA:52
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 52.085	AFL	745						
PROC. REF: AMM 52 21 00 220 801PROC. REF: AMM 52 21 00 220 801								
52-21-00-205	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE OVER-WING EMERGENCY EXIT							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.090	AFL	745						
PROC. REF: AMM 52 21 00 220 802PROC. REF: AMM 52 21 00 220 802								
52-21-00-900-801-01	OVERWING EMERGENCY EXIT DOOR ASSY							Component ATA:52
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.185	AFL	0		TSN 0				
PROC. REF: AMM 52 21 00 000 801, AMM 52 21 00 400 801PROC. REF: AMM 52 21 00 000 801, AMM 52 21 00 400 801								
52-30-00-101	DETAILED INSPECTION OF THE BAGGAGE DOOR							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 52.095	AFL	0	T:7500	7500			6111	
PROC. REF: AMM 52 30 00 220 809PROC. REF: AMM 52 30 00 220 809								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30-00-105	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SKIN BETWEEN DOOR UPPER SKIN EDGE AND VENT DOOR							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 52.100	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-52-31-001PROC. REF: NDT ET-52-31-001								
52-30-00-106	DETAILED INSPECTION OF THE VENT DOOR OF THE BAGGAGE DOOR							Service ATA:52
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 52.105	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 52 30 00 220 808PROC. REF: AMM 52 30 00 220 808								
52-30-00-107	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR							Service ATA:52
	MOS							AIRWORTHINESS
	HRS							
WC#: 52.110	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-52-30-002PROC. REF: NDT ET-52-30-002								
52-30-00-108	GENERAL VISUAL INSPECTION OF THE EXTERNAL SURFACE OF BAGGAGE DOOR SKIN INCLUDING DOOR HANDLE RECESS							Service ATA:52
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 52.115	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 52 30 00 210 806PROC. REF: AMM 52 30 00 210 806								
52-30-00-201	DETAILED INSPECTION OF THE SURROUND ANGLES AND STOP FITTINGS OF THE BAGGAGE DOOR							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.120	AFL	745						
PROC. REF: AMM 52 30 00 220 803PROC. REF: AMM 52 30 00 220 803								
52-30-00-202	DETAILED INSPECTION OF THE INTERNAL SUPPORT STRUCTURE OF THE BAGGAGE DOOR							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.125	AFL	745						
PROC. REF: AMM 52 30 00 220 805PROC. REF: AMM 52 30 00 220 805								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30-00-301	LUBRICATION OF THE BAGGAGE DOOR							Service ATA:52
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	OPTIONAL
	HRS	2845:10						
WC#: 52.130	AFL	999						
PROC. REF: AMM 12 22 00 640 806PROC. REF: AMM 12 22 00 640 806								
52-31-00-900-801-01	BAGGAGE COMPARTMENT DOOR ASSY							Component ATA:52
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.190	AFL	0		TSN 0				
PROC. REF: AMM 52 31 00 000 801, AMM 52 31 00 400 801PROC. REF: AMM 52 31 00 000 801, AMM 52 31 00 400 801								
52-31-09-101	DETAILED INSPECTION OF THE BAGGAGE DOOR SEAL (CMR**)							Service ATA:52
	MOS	15-Oct-24	15 (+3m/-3m)		15-Jan-26 (M)	15-Apr-26	322 d (+90)	CMR**
	HRS	3314:03						
WC#: 52.135	AFL	1328						
PROC. REF: AMM 52 31 09 220 801PROC. REF: AMM 52 31 09 220 801								
52-41-00-201	DETAILED INSPECTION OF THE AFT EQUIPMENT-COMPARTMENT DOOR SEAL							Service ATA:52
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 52.140	AFL	999						
PROC. REF: AMM 52 41 09 220 801PROC. REF: AMM 52 41 09 220 801								
52-41-00-900-801-01	REAR EQUIPMENT BAY DOOR							Component ATA:52
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.195	AFL	0		TSN 0				
PROC. REF: AMM 52 41 00 000 801, AMM 52 41 00 400 801PROC. REF: AMM 52 41 00 000 801, AMM 52 41 00 400 801								
52-42-01-900-801-01	FORWARD EQUIPMENT COMPARTMENT DOOR							Component ATA:52
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.215	AFL	0		TSN 0				
PROC. REF: AMM 52 42 01 000 801, AMM 52 42 01 400 801PROC. REF: AMM 52 42 01 000 801, AMM 52 42 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-43-00-900-801-01	LH ASSY - ACCESS DOOR							Component ATA:52
PN:GC219-0104-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E020970	HRS	0		TSN 0				
WC#: 52.200	AFL	0		TSN 0				
PROC. REF: AMM 52 43 00 000 801, AMM 52 43 00 400 801PROC. REF: AMM 52 43 00 000 801, AMM 52 43 00 400 801								
52-43-00-900-801-02	RH ASSY - ACCESS DOOR							Component ATA:52
PN:GC219-0104-4	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D981172	HRS	0		TSN 0				
WC#: 52.200	AFL	0		TSN 0				
PROC. REF: AMM 52 43 00 000 801, AMM 52 43 00 400 801PROC. REF: AMM 52 43 00 000 801, AMM 52 43 00 400 801								
52-44-25-900-801-01	CASTING DOOR							Component ATA:52
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.205	AFL	0		TSN 0				
PROC. REF: AMM 52 44 25 000 801, AMM 52 44 25 400 801PROC. REF: AMM 52 44 25 000 801, AMM 52 44 25 400 801								
52-44-37-900-801-01	DOOR CASTING							Component ATA:52
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 52.210	AFL	0		TSN 0				
PROC. REF: AMM 52 44 37 000 801, AMM 52 44 37 400 801PROC. REF: AMM 52 44 37 000 801, AMM 52 44 37 400 801								
52-71-50-621 ^U	OPERATIONAL TEST OF THE CABIN DOOR ANNUNCIATION SYSTEM							Service ATA:52
	MOS	10-Mar-23					STLMC	
	HRS	2845:10	1500		4345:10		899:14	
	AFL	999						
52-ZL-00-201	GENERAL VISUAL INSPECTION OF THE OVER-WING EMERGENCY EXIT - EXTERNAL							Service ATA:52
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 52.145	AFL	745						
PROC. REF: AMM 52 21 00 210 804, SPM 20-70-00-210-801PROC. REF: AMM 52 21 00 210 804, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-ZL-00-202	GENERAL VISUAL INSPECTION OF THE LATCH MECHANISM OF THE OVER-WING EMERGENCY EXIT							Service ATA:52
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 52.150	AFL	745						
PROC. REF: AMM 52 21 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 52 21 00 210 802, SPM 20-70-00-210-801								
52-ZL-00-203	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - INBOARD SIDE							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.155	AFL	745						
PROC. REF: AMM 52 30 00 210 807, SPM 20-70-00-210-801PROC. REF: AMM 52 30 00 210 807, SPM 20-70-00-210-801								
52-ZL-00-204	GENERAL VISUAL INSPECTION OF THE BAGGAGE DOOR - OUTBOARD SIDE							Service ATA:52
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 52.160	AFL	745						
PROC. REF: AMM 52 30 00 210 804, SPM 20-70-00-210-801PROC. REF: AMM 52 30 00 210 804, SPM 20-70-00-210-801								
52-ZL-00-205	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR - EXTERNAL							Service ATA:52
	MOS	15-Oct-24	24 (+3m/-3m)		15-Oct-26 (M)	15-Jan-27	595 d (+92)	MRB
	HRS	3314:03						
WC#: 52.165	AFL	1328						
PROC. REF: AMM 52 11 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 52 11 00 210 801, SPM 20-70-00-210-801								
524301-701 ^U	LH APU ACCESS DOOR							Component ATA:52
PN:GD239-6751-3	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:SB0282	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
524301-702 ^U	RH APU ACCESS DOOR							Component ATA:52
PN:GD239-6775-3	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:SB0280	HRS	28:06		TSN 0				
	AFL	11		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-101	DETAILED INSPECTION OF THE NOSE WHEEL WELL AND FRAME, FS251.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.005	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 819PROC. REF: AMM 53 10 00 220 819								
53-10-00-102	DETAILED INSPECTION OF THE LANDING GEAR BOX							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.010	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 820PROC. REF: AMM 53 10 00 220 820								
53-10-00-103	DETAILED INSPECTION OF THE FLOOR ATTACHMENT TO THE BULKHEAD, FS202.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.015	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 821PROC. REF: AMM 53 10 00 220 821								
53-10-00-104	DETAILED INSPECTION OF THE BULKHEAD, FS202.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.020	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 822PROC. REF: AMM 53 10 00 220 822								
53-10-00-105	GENERAL VISUAL INSPECTION OF THE FRAME, FS251.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.025	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 210 822PROC. REF: AMM 53 10 00 210 822								
53-10-00-106	SPECIAL DETAILED INSPECTION OF THE SKIN SPLICE AND FRAME SPLICE, FS280.00+32.00 - EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.030	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-10-004, NDT RT-53-10-001PROC. REF: NDT ET-53-10-004, NDT RT-53-10-001								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-107	DETAILED INSPECTION OF THE FRAME, FS280.00+32.00 - INTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.035	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 825PROC. REF: AMM 53 10 00 220 825								
53-10-00-108	SPECIAL DETAILED INSPECTION OF THE SPLICE AT STRINGERS 16A AND 23							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.040	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-10-005PROC. REF: NDT ET-53-10-005								
53-10-00-109	DETAILED INSPECTION OF THE SHEET METAL FRAME, FS210.00+32.00, FS220.00+32.00, FS235.00+32.00, FS265.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.045	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 826PROC. REF: AMM 53 10 00 220 826								
53-10-00-110	DETAILED INSPECTION OF THE STRINGERS 16A AND 23, FROM FS202.00+32.00 TO FS280.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.050	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 827PROC. REF: AMM 53 10 00 220 827								
53-10-00-112	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUND STRUCTURE							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.055	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-10-006, NDT ET-53-10-007PROC. REF: NDT ET-53-10-006, NDT ET-53-10-007								
53-10-00-114	DETAILED INSPECTION OF THE COCKPIT SKIN PANELS							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.060	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 840PROC. REF: AMM 53 10 00 220 840								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-115	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW CENTER POST							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.065	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-10-001PROC. REF: NDT ET-53-10-001								
53-10-00-116	SPECIAL DETAILED INSPECTION OF THE COCKPIT WINDOW LOWER SILL AT THE CENTER POST ATTACHMENT NEAR BLO							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.070	AFL		T:6620		6620		5231	
PROC. REF: NDT ET-53-10-002PROC. REF: NDT ET-53-10-002								
53-10-00-117	DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD, FS202.75+32.00, ABOVE FLOOR							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.075	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 220 836PROC. REF: AMM 53 10 00 220 836								
53-10-00-118	DETAILED INSPECTION OF THE FORWARD FACE OF BULKHEAD, FS202.75+32.00 WEB, BELOW FLOOR							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.080	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 220 811PROC. REF: AMM 53 10 00 220 811								
53-10-00-119	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN, FS169.00+32.00 TO FS280.00+32.00							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.085	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 210 802PROC. REF: AMM 53 10 00 210 802								
53-10-00-120	DETAILED INSPECTION OF THE LONGITUDINAL AND CIRCUMFERENTIAL SKIN JOINTS, FS202.75+32.00 TO FS280.00+32.00							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.090	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 220 814PROC. REF: AMM 53 10 00 220 814								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-121	DETAILED INSPECTION OF THE NLG AND PRESSURIZED PANEL CUTOUT SURROUND STRUCTURE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.095	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 220 815PROC. REF: AMM 53 10 00 220 815								
53-10-00-122	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW CUTOUT SURROUND STRUCTURE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.100	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 220 816PROC. REF: AMM 53 10 00 220 816								
53-10-00-123	DETAILED INSPECTION OF THE PRESSURIZED SURFACES OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.105	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 10 00 220 818PROC. REF: AMM 53 10 00 220 818								
53-10-00-124	DETAILED INSPECTION OF THE ACCESS PANEL SURROUND STRUCTURE							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.110	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 839PROC. REF: AMM 53 10 00 220 839								
53-10-00-125	DETAILED INSPECTION OF THE SKIN SPLICE, FS280.00+32.00 -EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 10 00 220 841PROC. REF: AMM 53 10 00 220 841								
53-10-00-126	DETAILED INSPECTION OF THE COCKPIT WINDOW SURROUNDSTRUCTURE, GUSSET AND SIDE PLATES							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:6639		6639		5250	
PROC. REF: AMM 53 10 00 220 842PROC. REF: AMM 53 10 00 220 842								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-201	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS169.00+32.00 TO FS202.75+32.00, ABOVE FLOOR							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.115	AFL	745						
PROC. REF: AMM 53 10 00 220 835PROC. REF: AMM 53 10 00 220 835								
53-10-00-202	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS169.00+32.00 TO FS202.75+32.00, BELOW FLOOR							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.120	AFL	745						
PROC. REF: AMM 53 10 00 220 837PROC. REF: AMM 53 10 00 220 837								
53-10-00-203	DETAILED INSPECTION OF THE INTERNAL FORWARD FUSELAGE SKIN/STRUCTURE AND FS280.00 BULKHEAD FORWARD FACE, FS202.75 TO FS280.00+32.00, ABOVE WL79.50							Service ATA:53
	MOS	30-Jul-10	T:180 (+3m/-3m)		30-Jul-25	30-Oct-25	153 d (+92)	MRB
	HRS	0						
WC#: 53.125	AFL	0						
PROC. REF: AMM 53 10 00 220 833PROC. REF: AMM 53 10 00 220 833								
53-10-00-205	DETAILED INSPECTION OF THE PILOT AND COPILOT SEAT TRACKS							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.130	AFL	745						
PROC. REF: AMM 53 10 00 220 813PROC. REF: AMM 53 10 00 220 813								
53-10-00-207	DETAILED INSPECTION OF THE FLOOR STRUCTURE, FS202.75+32.00 TO FS280.00+32.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.135	AFL	745						
PROC. REF: AMM 53 10 00 220 807PROC. REF: AMM 53 10 00 220 807								
53-10-00-208	DETAILED INSPECTION OF THE FORWARD JACKING POINT, FS278.00+32.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.140	AFL	745						
PROC. REF: AMM 53 10 00 220 834PROC. REF: AMM 53 10 00 220 834								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-209	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE-WINDOW SURROUND STRUCTURE AND RETAINERS							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MPD
	HRS	2444:24						
WC#: 53.145	AFL	745						
PROC. REF: AMM 53 10 00 220 802PROC. REF: AMM 53 10 00 220 802								
53-10-00-210	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) WHEEL WELL STRUCTURE							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.150	AFL	745						
PROC. REF: AMM 53 10 00 220 805PROC. REF: AMM 53 10 00 220 805								
53-10-00-211	DETAILED INSPECTION OF THE INTERNAL STRUCTURE, FS202.75+32.00 TO FS280.00+32.00, BELOW FLOOR							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.155	AFL	745						
PROC. REF: AMM 53 10 00 220 806PROC. REF: AMM 53 10 00 220 806								
53-10-00-212	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION OF THE FLIGHT COMPARTMENT CONNECTORS							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 53 10 00 210 824PROC. REF: AMM 53 10 00 210 824								
53-10-00-213	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE FORWARD FACE OF THE FORWARD PRESSURE BULKHEAD CONNECTORS, FS202.00+32.00							Service ATA:53
	MOS	30-Jul-10	180 (+3m/-3m)		30-Jul-25	30-Oct-25	153 d (+92)	MRB
	HRS	0						
	AFL	0						
PROC. REF: AMM 53 10 00 210 825PROC. REF: AMM 53 10 00 210 825								
53-11-01-900-801-01	FLOOR - FLIGHT COMPARTMENT PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1060	AFL	0		TSN 0				
PROC. REF: AMM 53 11 01 000 801, AMM 53 11 01 400 801PROC. REF: AMM 53 11 01 000 801, AMM 53 11 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-11-05-900-801-01	ASSEMBLY CRAWLWAY - FS277 STR27 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1065	AFL	0		TSN 0				
PROC. REF: AMM 53 11 05 000 801, AMM 53 11 05 400 801, AMM 53 21 05 000 802, AMM 53 21 05 400 802PROC. REF: AMM 53 11 05 000 801, AMM 53 11 05 400 801, AMM 53 21 05 000 802, AMM 53 21 05 400 802								
53-20-00-101	DETAILED INSPECTION OF THE FUSELAGE UPPER SKIN AND LONGITUDINAL JOINTS FROM, FS381.00+32.00 TO FS557.00 - EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.160	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 864PROC. REF: AMM 53 20 00 220 864								
53-20-00-104	SPECIAL DETAILED INSPECTION OF THE FUSELAGE KEEL BEAM							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.165	AFL	0	T:6082		6082		4693	
PROC. REF: NDT ET-53-20-001PROC. REF: NDT ET-53-20-001								
53-20-00-105	SPECIAL DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.170	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-20-006PROC. REF: NDT ET-53-20-006								
53-20-00-106	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR AND THE STIFFENERS OF THE PRESSURE BULKHEAD FROM FS557.00 TO FS574.50							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.175	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-20-002PROC. REF: NDT ET-53-20-002								
53-20-00-109	SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE JOINTS FROM, FS281.00+32.00 TO FS557.00 - EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.180	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-20-007, NDT UT-53-20-001PROC. REF: NDT ET-53-20-007, NDT UT-53-20-001								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-110	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM, FS281.00+32.00 TO FS381.00+32.00 - EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.185	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 863PROC. REF: AMM 53 20 00 220 863								
53-20-00-117	DETAILED INSPECTION OF THE PASSENGER DOOR CUTOUT STRUCTURE AND FITTINGS							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.190	AFL	0	T:5848		5848		4459	
PROC. REF: AMM 53 20 00 220 851PROC. REF: AMM 53 20 00 220 851								
53-20-00-118	SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS381.00+32.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.195	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-20-003PROC. REF: NDT ET-53-20-003								
53-20-00-119	SPECIAL DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BARREL JOINTS, FS381.00+32.00 AND FS557.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.200	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-20-005PROC. REF: NDT ET-53-20-005								
53-20-00-120	SPECIAL DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.205	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-20-004PROC. REF: NDT ET-53-20-004								
53-20-00-122	DETAILED INSPECTION OF THE MACHINED FITTINGS AND SKIN AROUND THE SERVICE DOOR, FS295.00+32.00 TOFS310.00+32.00 AND STR22R TO STR24R							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.210	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 832PROC. REF: AMM 53 20 00 220 832								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-123	DETAILED INSPECTION OF THE AVIONICS BAY DOOR AND SURROUNDING SKIN							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.215	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 862PROC. REF: AMM 53 20 00 220 862								
53-20-00-124	DETAILED INSPECTION OF THE WING INSPECTION LIGHT INSTALLATION							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.220	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 865PROC. REF: AMM 53 20 00 220 865								
53-20-00-125	DETAILED INSPECTION OF THE STRINGERS AND FRAMES FROM, FS381.00+32.00 TO FS557.00							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.225	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 860PROC. REF: AMM 53 20 00 220 860								
53-20-00-126	DETAILED INSPECTION OF THE FUSELAGE STRINGERS AND FRAMES FROM, FS281.00+32.00 TO FS381.00+32.00							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.230	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 20 00 220 861PROC. REF: AMM 53 20 00 220 861								
53-20-00-127	GENERAL VISUAL INSPECTION OF THE PRESSURE BULKHEAD FS557.00							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.235	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 20 00 210 817PROC. REF: AMM 53 20 00 210 817								
53-20-00-128	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE, FS381.00+32.00 TO FS557.00 AND STR6L TO STR6R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.240	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 210 801PROC. REF: AMM 53 20 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-129	GENERAL VISUAL INSPECTION OF THE LOWER EXTERNAL SKIN OF THE FUSELAGE, FS381.00+32.00 TO FS557.00 AND STR6L TO STR6R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.245	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 210 802PROC. REF: AMM 53 20 00 210 802								
53-20-00-130	DETAILED INSPECTION OF THE EXTERNAL AVIONICS- COMPARTMENT ACCESS SURROUND STRUCTURE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.250	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 834PROC. REF: AMM 53 20 00 220 834								
53-20-00-131	DETAILED INSPECTION OF THE AFT FACE OF PRESSURE BULKHEAD BELOW WL71.50, FS557.00							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.255	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 809PROC. REF: AMM 53 20 00 220 809								
53-20-00-132	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS557.00 TO FS574.60 AND BL46L TO BL46R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.260	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 810PROC. REF: AMM 53 20 00 220 810								
53-20-00-133	GENERAL VISUAL INSPECTION OF THE EXTERNAL TOP SKIN OF THE FUSELAGE, FS281.00+32.00 TO FS381.00+32.00 AND STR2L TO STR7R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.265	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 210 804PROC. REF: AMM 53 20 00 210 804								
53-20-00-134	GENERAL VISUAL INSPECTION OF THE EXTERNAL LEFT SIDE AND LOWER SKIN, FS281.00+32.00 TO FS381.00+32.00 AND STR2L TO STR25L							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.270	AFL	0	T:3750		3750		2361	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53 20 00 210 805PROC. REF: AMM 53 20 00 210 805								
53-20-00-135	DETAILED INSPECTION OF THE SILLS, FRAME, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.275	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 821PROC. REF: AMM 53 20 00 220 821								
53-20-00-136	GENERAL VISUAL INSPECTION OF THE EXTERNAL RIGHT SIDE AND LOWER SKIN, FS281.00+32.00 TO FS381.00+32.00 AND STR7R TO STR25R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.280	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 210 806PROC. REF: AMM 53 20 00 210 806								
53-20-00-137	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE WINDOW SURROUND CUTOUTS							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.285	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 836PROC. REF: AMM 53 20 00 220 836								
53-20-00-138	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS281.00+32.00 TO FS381.00+32.00, STR2L, STR7R, STR14L, STR19R AND STR25L							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.290	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 840PROC. REF: AMM 53 20 00 220 840								
53-20-00-139	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS381.00+32.00 TO FS557.00, STR6R, STR6L, STR20R AND STR20L							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.295	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 838PROC. REF: AMM 53 20 00 220 838								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-140	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE SERVICE DOOR CUTOUT, FS295.00+32.00 TO FS310.00+32.00 AND STR22R TO STR24R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.300	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 20 00 220 835PROC. REF: AMM 53 20 00 220 835								
53-20-00-201	DETAILED INSPECTION OF THE INTERNAL FUSELAGE SKIN AND STRUCTURE, FS281.00+32.00 TO FS861.00, ABOVE WL71.50							Service ATA:53
	MOS	30-Jul-10	T:240 (+3m/-3m)		30-Jul-30	30-Oct-30	1979 d (+92)	MRB
	HRS	0						
WC#: 53.305	AFL	0						
PROC. REF: AMM 53 20 00 220 801PROC. REF: AMM 53 20 00 220 801								
53-20-00-202	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE, FS381.00+32.00 TO FS557.00, BELOW WL71.50							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.310	AFL	745						
PROC. REF: AMM 53 20 00 220 802PROC. REF: AMM 53 20 00 220 802								
53-20-00-203	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND STRUCTURE, FS381.00+32.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.315	AFL	745						
PROC. REF: AMM 53 20 00 220 839PROC. REF: AMM 53 20 00 220 839								
53-20-00-204	DETAILED INSPECTION OF THE KEEL BEAM, FS501.00 TO FS574.00 AND BL4.6L TO BL4.6R							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.320	AFL	745						
PROC. REF: AMM 53 20 00 220 803PROC. REF: AMM 53 20 00 220 803								
53-20-00-205	DETAILED INSPECTION OF THE OVER-WING LONGERON, FS525.00 TO FS574.00 AND STR19L AND STR19R							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.325	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53 20 00 220 805PROC. REF: AMM 53 20 00 220 805								
53-20-00-206	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.330	AFL	745						
PROC. REF: AMM 53 20 00 220 806PROC. REF: AMM 53 20 00 220 806								
53-20-00-207	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW WL71.50, FS557.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.335	AFL	745						
PROC. REF: AMM 53 20 00 220 854PROC. REF: AMM 53 20 00 220 854								
53-20-00-208	DETAILED INSPECTION OF THE TOP SIDE OF THE PRESSURE FLOOR, FS557 TO FS574.50 AND BL46L TO BL46R							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.340	AFL	745						
PROC. REF: AMM 53 20 00 220 807PROC. REF: AMM 53 20 00 220 807								
53-20-00-209	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS381.00+32.00 TO FS557.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.345	AFL	745						
PROC. REF: AMM 53 20 00 220 808PROC. REF: AMM 53 20 00 220 808								
53-20-00-210	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS381.00+32.00 TO FS557.00 AS VISIBLE FROM THE CRAWLWAY							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.350	AFL	745						
PROC. REF: AMM 53 20 00 220 817PROC. REF: AMM 53 20 00 220 817								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-212	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50, FS281.00+32.00 TO FS381.00+32.00							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.355	AFL	745						
PROC. REF: AMM 53 20 00 220 812PROC. REF: AMM 53 20 00 220 812								
53-20-00-213	DETAILED INSPECTION OF THE INTERNAL STRUCTURE BELOW WL71.50, FS281.00+32.00 TO FS381.00+32.00, AS VISIBLE WITH THE FLOOR PANELS INSTALLED							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.360	AFL	745						
PROC. REF: AMM 53 20 00 220 813PROC. REF: AMM 53 20 00 220 813								
53-20-00-214	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS281.00+32.00 TO FS381.00+32.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.365	AFL	745						
PROC. REF: AMM 53 20 00 220 818PROC. REF: AMM 53 20 00 220 818								
53-20-00-215	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE, FS281.00+32.00 TO FS381.00+32.00 AS VISIBLE FROM THE CRAWLWAY							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.370	AFL	745						
PROC. REF: AMM 53 20 00 220 819PROC. REF: AMM 53 20 00 220 819								
53-20-00-216	DETAILED INSPECTION OF THE FLOOR STRUCTURE IN THE WAY OF THE PASSENGER DOOR STEP, FS310.00+32.00 TO FS347.00+32.00							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.375	AFL	745						
PROC. REF: AMM 53 20 00 220 820PROC. REF: AMM 53 20 00 220 820								
53-20-00-217	DETAILED INSPECTION OF THE SILLS, FRAMES, SKIN AND EDGE MEMBERS AROUND THE PASSENGER DOOR CUTOUT							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.380	AFL	745						
PROC. REF: AMM 53 20 00 220 821PROC. REF: AMM 53 20 00 220 821								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-218	DETAILED INSPECTION OF THE INTERNAL SKIN AROUND THE PASSENGER DOOR CUTOUT							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.385	AFL	745						
PROC. REF: AMM 53 20 00 220 837PROC. REF: AMM 53 20 00 220 837								
53-20-00-219	DETAILED INSPECTION OF THE FITTINGS AND HINGES ON THE FUSELAGE FOR THE PASSENGER DOOR							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.390	AFL	745						
PROC. REF: AMM 53 20 00 220 822PROC. REF: AMM 53 20 00 220 822								
53-20-00-221	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS281.00+32.00 TO FS381.00+32.00, STR19R AND STR25L							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.395	AFL	745						
PROC. REF: AMM 53 20 00 220 824PROC. REF: AMM 53 20 00 220 824								
53-20-00-223	DETAILED INSPECTION OF THE FUSELAGE LONGITUDINAL JOINTS, FS381.00+32.00 TO FS557.00 - STR20L AND STR20R							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.400	AFL	745						
PROC. REF: AMM 53 20 00 220 826PROC. REF: AMM 53 20 00 220 826								
53-20-00-225	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS381.00+32.00, BELOW WL71.50							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.405	AFL	745						
PROC. REF: AMM 53 20 00 220 828PROC. REF: AMM 53 20 00 220 828								
53-20-00-227	DETAILED INSPECTION OF THE FUSELAGE BARREL JOINT, FS557.00, BELOW WL71.50							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.410	AFL	745						
PROC. REF: AMM 53 20 00 220 830PROC. REF: AMM 53 20 00 220 830								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-00-229	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR, FS295.00+32.00 TO FS310.00+32.00 AND STR22R TO STR24R							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.415	AFL	745						
PROC. REF: AMM 53 20 00 220 832PROC. REF: AMM 53 20 00 220 832								
53-20-00-230	DETAILED INSPECTION OF THE MACHINED FITTING AND SKIN AROUND THE SERVICE DOOR, FS295.00+32.00 TO FS310.00+32.00 AND STR22R TO STR24R AS VISIBLE FROM THE CRAWLWAY							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.420	AFL	745						
PROC. REF: AMM 53 20 00 220 833PROC. REF: AMM 53 20 00 220 833								
53-20-00-245	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE AVIONICS RACKS CONNECTORS							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 53 20 00 220 866PROC. REF: AMM 53 20 00 220 866								
53-20-00-246	DETAILED INSPECTION OF THE GROUND STUDS FOR L/HIRF PROTECTION IN THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00+32.00 AND FS557.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 53 20 00 220 867PROC. REF: AMM 53 20 00 220 867								
53-30-00-102	SPECIAL DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 TO FS781.00, STRINGER 6							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.430	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-30-002PROC. REF: NDT ET-53-30-002								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-103	DETAILED INSPECTION OF THE PANEL JOINT, FS557.00 AND FS797.00, STRINGERS 18L TO 18R							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.435	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 836PROC. REF: AMM 53 30 00 220 836								
53-30-00-104	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE CABIN WINDOW CUTOUTS, FS557.00 TO FS797.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.440	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 833PROC. REF: AMM 53 30 00 220 833								
53-30-00-105	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTER FLANGE, FS574.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.445	AFL	0	T:7500		7500		6111	
PROC. REF: NDT UT-53-30-002PROC. REF: NDT UT-53-30-002								
53-30-00-106	SPECIAL DETAILED INSPECTION REAR SPAR FRAME, FS719.30							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.450	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-30-004, NDT UT-53-30-001PROC. REF: NDT ET-53-30-004, NDT UT-53-30-001								
53-30-00-107	DETAILED INSPECTION OF THE INTERMEDIATE FRAMES							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.455	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 839PROC. REF: AMM 53 30 00 220 839								
53-30-00-110	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.465	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-30-011, NDT ET-53-30-013, NDT UT-53-30-005PROC. REF: NDT ET-53-30-011, NDT ET-53-30-013, NDT UT-53-30-005								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-111	DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS AND BEAMS FROM FS719.30 TO FS781.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.470	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 837PROC. REF: AMM 53 30 00 220 837								
53-30-00-113	DETAILED INSPECTION OF THE KEEL BEAM, FS719.30 TO FS781.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.475	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 812PROC. REF: AMM 53 30 00 220 812								
53-30-00-114	SPECIAL DETAILED INSPECTION OF THE REAR SPAR BULKHEAD, FS719.30							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.480	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-30-014, NDT UT-53-30-008PROC. REF: NDT ET-53-30-014, NDT UT-53-30-008								
53-30-00-115	DETAILED INSPECTION OF THE FRAME, FS781.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.485	AFL	0	T:6654		6654		5265	
PROC. REF: AMM 53 30 00 220 832PROC. REF: AMM 53 30 00 220 832								
53-30-00-116	DETAILED INSPECTION OF THE REAR SPAR FRAME, FS719.30							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.490	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 834PROC. REF: AMM 53 30 00 220 834								
53-30-00-118	SPECIAL DETAILED INSPECTION OF THE PRESSURE FLOOR PANELS FROM FS719.30 TO FS781.00							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.495	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-015, NDT UT-53-30-004PROC. REF: NDT ET-53-30-015, NDT UT-53-30-004								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-119	SPECIAL DETAILED INSPECTION OF STRINGER 6 FROM FS574.00 TO FS781.00							Service ATA:53
	MOS							05-10-25
	HRS							AIRWORTHINESS
WC#: 53.500	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-012PROC. REF: NDT ET-53-30-012								
53-30-00-120	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME OUTBOARD AND INBOARD FLANGES, FS574.00							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.505	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-003PROC. REF: NDT ET-53-30-003								
53-30-00-121	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS574.00							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.510	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-008PROC. REF: NDT ET-53-30-008								
53-30-00-122	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAME ATTACHMENT TO THE CENTER WING BOX, FS719.30							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.515	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-005PROC. REF: NDT ET-53-30-005								
53-30-00-123	SPECIAL DETAILED INSPECTION OF THE FRAME SPLICE, STRINGERS 5 AND 15, FS574.50 AND FS719.30							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.520	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-007PROC. REF: NDT ET-53-30-007								
53-30-00-124	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE NOT BEHIND THE FAIRING, FS557.00 TO FS797.60							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.525	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 210 802PROC. REF: AMM 53 30 00 210 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-125	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BEHIND THE FAIRING, FS557.00 TO FS797.60							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.530	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 210 804PROC. REF: AMM 53 30 00 210 804								
53-30-00-126	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVERWING EMERGENCY EXIT							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.535	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 220 803PROC. REF: AMM 53 30 00 220 803								
53-30-00-127	DETAILED INSPECTION OF THE EXTERNAL SKIN OF CABIN WINDOW CUTOUTS, SURROUND STRUCTURE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.540	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 220 830PROC. REF: AMM 53 30 00 220 830								
53-30-00-128	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR FS719.30 TO FS781.00 AND BL35L TO BL35R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.545	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 220 808PROC. REF: AMM 53 30 00 220 808								
53-30-00-129	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00- EXTERNAL							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.550	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 220 825PROC. REF: AMM 53 30 00 220 825								
53-30-00-130	DETAILED INSPECTION OF THE CIRCUMFERENTIAL SKIN JOINT AT FS557.00 AND LONGITUDINAL SKIN JOINTS AT STR6 AND STR18, L AND R							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.555	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 30 00 220 835PROC. REF: AMM 53 30 00 220 835								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-131	SPECIAL DETAILED INSPECTION OF THE EMERGENCY DOOR CUTOUT AND LATCH FITTING							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.560	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-006PROC. REF: NDT ET-53-30-006								
53-30-00-132	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN AND SPLICE STRAP AT STRINGER 18							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.565	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-30-010, NDT UT-53-30-007PROC. REF: NDT ET-53-30-010, NDT UT-53-30-007								
53-30-00-133	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN SPLICES ATFS737.00 FROM STR15 TO STR19 AND AT STR15 BETWEENFS737.00 AND FS787.70							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-30-016, NDT UT-53-30-009PROC. REF: NDT ET-53-30-016, NDT UT-53-30-009								
53-30-00-134	SPECIAL DETAILED INSPECTION OF THE REAR SPAR FRAMEOUTER-CAP, FS719.30 AT BL47.61							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT UT-53-30-003PROC. REF: NDT UT-53-30-003								
53-30-00-135	DETAILED INSPECTION OF THE FUSELAGE SKIN PANEL ANDSTRINGER 18 - INTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 843PROC. REF: AMM 53 30 00 220 843								
53-30-00-136	SPECIAL DETAILED INSPECTION OF THE FRAME, FS781.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-30-017, NDT UT-53-30-010PROC. REF: NDT ET-53-30-017, NDT UT-53-30-010								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-137	DETAILED INSPECTION OF THE CENTER FUSELAGE SKINPANEL-ASSEMBLY FROM FS557.00 TO FS797.60							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 841PROC. REF: AMM 53 30 00 220 841								
53-30-00-138	DETAILED INSPECTION OF THE FRAME SPLICE, FS574.00 TOFS781.00, STR5 AND STR15							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 30 00 220 842PROC. REF: AMM 53 30 00 220 842								
53-30-00-201	DETAILED INSPECTION OF THE FRONT SPAR FRAME ABOVE WL71.50, FS574.50							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.570	AFL	745						
PROC. REF: AMM 53 30 00 220 801PROC. REF: AMM 53 30 00 220 801								
53-30-00-202	DETAILED INSPECTION OF THE FRONT SPAR FRAME BELOW WL71.50, FS574.50							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.575	AFL	745						
PROC. REF: AMM 53 30 00 220 810PROC. REF: AMM 53 30 00 220 810								
53-30-00-203	DETAILED INSPECTION OF THE REAR SPAR FRAME ABOVE WL71.50, FS719.30							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.580	AFL	745						
PROC. REF: AMM 53 30 00 220 802PROC. REF: AMM 53 30 00 220 802								
53-30-00-204	DETAILED INSPECTION OF THE REAR SPAR FRAME BELOW WL71.50, FS719.30							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.585	AFL	745						
PROC. REF: AMM 53 30 00 220 813PROC. REF: AMM 53 30 00 220 813								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-205	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT -EXTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.590	AFL	745						
PROC. REF: AMM 53 30 00 220 803PROC. REF: AMM 53 30 00 220 803								
53-30-00-206	DETAILED INSPECTION OF THE SURROUND STRUCTURE FOR THE OVER-WING EMERGENCY EXIT - INTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.595	AFL	745						
PROC. REF: AMM 53 30 00 220 827PROC. REF: AMM 53 30 00 220 827								
53-30-00-207	DETAILED INSPECTION OF THE FITTINGS ON THE FRAME OF THE OVER-WING EMERGENCY EXIT							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.600	AFL	745						
PROC. REF: AMM 53 30 00 220 804PROC. REF: AMM 53 30 00 220 804								
53-30-00-208	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE CABIN WINDOW CUTOUTS							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.605	AFL	745						
PROC. REF: AMM 53 30 00 220 805PROC. REF: AMM 53 30 00 220 805								
53-30-00-210	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE FUSELAGE BELOW WL71.50, FS557.00 TO FS797.60							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.610	AFL	745						
PROC. REF: AMM 53 30 00 220 815PROC. REF: AMM 53 30 00 220 815								
53-30-00-211	DETAILED INSPECTION OF THE TOP OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.615	AFL	745						
PROC. REF: AMM 53 30 00 220 807PROC. REF: AMM 53 30 00 220 807								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-212	DETAILED INSPECTION OF THE LOWER SIDE OF THE PRESSURE FLOOR, FS719.30 TO FS781.00 AND BL35L TO BL35R							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.620	AFL	745						
PROC. REF: AMM 53 30 00 220 808PROC. REF: AMM 53 30 00 220 808								
53-30-00-213	DETAILED INSPECTION OF THE PRESSURE FLOOR BEAMS, FS713.10 TO FS781.00, BL0.0, BL9, BL19, BL27 AND BL35							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.625	AFL	745						
PROC. REF: AMM 53 30 00 220 809PROC. REF: AMM 53 30 00 220 809								
53-30-00-214	DETAILED INSPECTION OF THE KEEL BEAM STRUCTURE, FS719.30 TO FS781.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.630	AFL	745						
PROC. REF: AMM 53 30 00 220 812PROC. REF: AMM 53 30 00 220 812								
53-30-00-215	DETAILED INSPECTION OF THE PRESSURE BULKHEADS, FS719.30 AND FS781.00 - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.635	AFL	745						
PROC. REF: AMM 53 30 00 220 825PROC. REF: AMM 53 30 00 220 825								
53-30-00-428 ^U	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE CABIN WINDOW CUTOUTS, FS557.00 TO FS797.00LOCATION: FS729.30, FS759.00							Service ATA:53
	MOS							
	HRS							
	AFL		T:6520		6520		5131	
53-40-00-101	DETAILED INSPECTION OF THE FUSELAGE SKIN FROM FS781.00 TO FS861.00 - EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.640	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 846PROC. REF: AMM 53 40 00 220 846								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-102	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN LONGITUDINAL JOINTS							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.645	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-009, NDT ET-53-40-010, NDT ET-53-40-015, NDT UT-53-40-005PROC. REF: NDT ET-53-40-009, NDT ET-53-40-010, NDT ET-53-40-015, NDT UT-53-40-005								
53-40-00-103	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE AND PRESSURE BULKHEAD							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.650	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 833PROC. REF: AMM 53 40 00 220 833								
53-40-00-104	DETAILED INSPECTION OF THE FRAMES AT FS925.00 AND FS987.00 AND THE REAR FUSELAGE LONGERON PLATFORM							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.655	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 840PROC. REF: AMM 53 40 00 220 840								
53-40-00-105	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD AT FS861.00, AND THE FLOOR BEAMS FS789.00 TO FS861.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.660	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 832PROC. REF: AMM 53 40 00 220 832								
53-40-00-106	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN FROM FS861.00 TO CANTED FRAME AT FS1066.00 - EXTERNAL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.665	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 210 802PROC. REF: AMM 53 40 00 210 802								
53-40-00-108	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, LOWER SILL							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.670	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 834PROC. REF: AMM 53 40 00 220 834								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-109	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, FRAME AND REINFORCING STRAP							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.675	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 835PROC. REF: AMM 53 40 00 220 835								
53-40-00-110	DETAILED INSPECTION OF THE REAR-PRESSURE BULKHEAD UPPER-HORIZONTAL-BEAM							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.680	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 847PROC. REF: AMM 53 40 00 220 847								
53-40-00-111	DETAILED INSPECTION OF THE PRESSURE BULKHEAD AT FS861.00 VERTICAL STIFFENERS AND BAGGAGE DOOR SILL FITTING							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.685	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 822PROC. REF: AMM 53 40 00 220 822								
53-40-00-113	SPECIAL DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAM JOINTS							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.690	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-004PROC. REF: NDT ET-53-40-004								
53-40-00-114	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT AT FS813.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.695	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-002PROC. REF: NDT ET-53-40-002								
53-40-00-115	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE UPPER SILL JOINT, FORWARD OF FS861.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.700	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-003PROC. REF: NDT ET-53-40-003								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-117	GENERAL VISUAL INSPECTION OF THE REAR FUSELAGE KEEL BEAM							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.705	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 839PROC. REF: AMM 53 40 00 220 839								
53-40-00-119	DETAILED INSPECTION OF THE REAR-FUSELAGE SKIN ENGINE-MOUNT-CUTOUTS							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.710	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 848PROC. REF: AMM 53 40 00 220 848								
53-40-00-120	SPECIAL DETAILED INSPECTION OF THE INNER FLAP TRACK SUPPORT-FITTINGS ON THE REAR FUSELAGE							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.715	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-005PROC. REF: NDT ET-53-40-005								
53-40-00-121	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT-SPAR							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.720	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 849PROC. REF: AMM 53 40 00 220 849								
53-40-00-122	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER MID-SPAR							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.725	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 843PROC. REF: AMM 53 40 00 220 843								
53-40-00-123	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER REAR-SPAR							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.730	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 844PROC. REF: AMM 53 40 00 220 844								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-124	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SUPPORT FRAMES FOR THE ENGINE BEAMS, INNER FLANGE							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.735	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-001PROC. REF: NDT ET-53-40-001								
53-40-00-125	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE VERTICAL STABILIZER FRONT SPAR, INBOARD FLANGE							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.740	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-008PROC. REF: NDT ET-53-40-008								
53-40-00-126	DETAILED INSPECTION OF THE FLOOR STRUCTURE, SEAT RAIL AND LATERAL FLOOR BEAMS							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.745	AFL		T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 831PROC. REF: AMM 53 40 00 220 831								
53-40-00-127	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CIRCUMFERENTIAL JOINTS							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.750	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-53-40-011, NDT ET-53-40-013, NDT ET-53-40-014, NDT UT-53-40-003, NDT UT-53-40-004PROC. REF: NDT ET-53-40-011, NDT ET-53-40-013, NDT ET-53-40-014, NDT UT-53-40-003, NDT UT-53-40-004								
53-40-00-128	DETAILED INSPECTION OF THE FUSELAGE SKIN AROUND THE BAGGAGE DOOR							Service ATA:53
	MOS							AIRWORTHINESS
	HRS							
WC#: 53.755	AFL		T:7450		7450		6061	
PROC. REF: AMM 53 40 00 220 820PROC. REF: AMM 53 40 00 220 820								
53-40-00-129	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE PRESSURIZED FUSELAGE, FS797.00 TO FS861.00							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.760	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 40 00 210 826PROC. REF: AMM 53 40 00 210 826								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-130	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS OF THE PRESSURE SHELL NOT COVERED BY WING -TO-FUSELAGE FAIRINGS							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.765	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 40 00 220 815PROC. REF: AMM 53 40 00 220 815								
53-40-00-131	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.770	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 40 00 220 821PROC. REF: AMM 53 40 00 220 821								
53-40-00-132	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BENEATH THE WING-TO-FUSELAGE FAIRING IN THE PRESSURIZED ZONE							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.775	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 40 00 210 808PROC. REF: AMM 53 40 00 210 808								
53-40-00-133	DETAILED INSPECTION OF THE CIRCUMFERENTIAL AND LONGITUDINAL SKIN JOINTS BENEATH WING-TO-FUSELAGE FAIRING							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.780	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 40 00 220 816PROC. REF: AMM 53 40 00 220 816								
53-40-00-134	DETAILED INSPECTION OF THE PRESSURE BULKHEAD FORWARD WEB BELOW FLOOR							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.785	AFL	0	T:3750		3750		2361	
PROC. REF: AMM 53 40 00 220 817PROC. REF: AMM 53 40 00 220 817								
53-40-00-135	DETAILED INSPECTION OF THE PRESSURE BULKHEAD WEB ABOVE FLOOR							Service ATA:53
	MOS	30-Jul-09						HASC
	HRS	0						
WC#: 53.790	AFL	0	T:3750		3750		2361	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53 40 00 220 818PROC. REF: AMM 53 40 00 220 818								
53-40-00-137	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEADAT FS861.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-017PROC. REF: NDT ET-53-40-017								
53-40-00-138	SPECIAL DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUNDSTRUCTURE - PRESSURE BULKHEAD							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-016, NDT UT-53-40-006PROC. REF: NDT ET-53-40-016, NDT UT-53-40-006								
53-40-00-139	SPECIAL DETAILED INSPECTION OF THE REAR FUSELAGE SKINCUTOUTS FROM FS781.00 TO FS1066.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-53-40-012, NDT UT-53-40-002PROC. REF: NDT ET-53-40-012, NDT UT-53-40-002								
53-40-00-140	DETAILED INSPECTION OF THE REAR FUSELAGE SKIN CUTOUTS FROMFS781.00 TO FS1066.00							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 40 00 220 851PROC. REF: AMM 53 40 00 220 851								
53-40-00-201	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE VERTICAL STABILIZER, FS945.00 TO THE REAR SPAR OF THE VERTICAL STABILIZER							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.795	AFL	745						
PROC. REF: AMM 53 40 00 220 803PROC. REF: AMM 53 40 00 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-202	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE PYLON, FS877.25 TO THE REAR SPAR OF THE VERTICAL STABILIZER							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.800	AFL	745						
PROC. REF: AMM 53 40 00 220 804PROC. REF: AMM 53 40 00 220 804								
53-40-00-203	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE FUSELAGE BELOW THE WING-TO-FUSELAGE FAIRING, AND THE AFT KEEL BEAM, FS781.00 TO FS945.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.805	AFL	745						
PROC. REF: AMM 53 40 00 220 805PROC. REF: AMM 53 40 00 220 805								
53-40-00-204	DETAILED INSPECTION OF THE STOP FITTINGS OF THE BAGGAGE DOOR ON THE FUSELAGE							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.810	AFL	745						
PROC. REF: AMM 53 40 00 220 801PROC. REF: AMM 53 40 00 220 801								
53-40-00-205	DETAILED INSPECTION OF THE INTERNAL SURROUND STRUCTURE OF THE BAGGAGE DOOR, FORWARD OF THE PRESSURE BULKHEAD							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.815	AFL	745						
PROC. REF: AMM 53 40 00 220 802PROC. REF: AMM 53 40 00 220 802								
53-40-00-206	DETAILED INSPECTION OF THE BAGGAGE DOOR CUTOUT SURROUND STRUCTURE							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.820	AFL	745						
PROC. REF: AMM 53 40 00 220 821PROC. REF: AMM 53 40 00 220 821								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-208	DETAILED INSPECTION OF THE INTERNAL FUSELAGE STRUCTURE AND FORWARD FACE OF THE REAR PRESSURE BULKHEAD BELOW THE FLOOR, AND THE FLOOR STRUCTURE OF THE BAGGAGE COMPARTMENT							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.825	AFL	745						
PROC. REF: AMM 53 40 00 220 807PROC. REF: AMM 53 40 00 220 807								
53-40-00-209	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR							Service ATA:53
	MOS	30-Jul-10	T:180 (+3m/-3m)		30-Jul-25	30-Oct-25	153 d (+92)	MRB
	HRS	0						
WC#: 53.830	AFL	0						
PROC. REF: AMM 53 40 00 220 808PROC. REF: AMM 53 40 00 220 808								
53-40-00-210	DETAILED INSPECTION OF THE STRUCTURE OF THE AFT FACE OF THE REAR PRESSURE BULKHEAD							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.835	AFL	745						
PROC. REF: AMM 53 40 00 220 809PROC. REF: AMM 53 40 00 220 809								
53-40-00-211	DETAILED INSPECTION OF THE UPPER SILL AND STOP BACKUP STRUCTURE OF THE BAGGAGE DOOR, AFT OF THE PRESSURE BULKHEAD							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.840	AFL	745						
PROC. REF: AMM 53 40 00 220 810PROC. REF: AMM 53 40 00 220 810								
53-40-00-213	DETAILED INSPECTION OF THE AFT EQUIPMENT COMPARTMENT INTERIOR STRUCTURE , FS861.00, VERTICAL-STABILIZER REAR-SPAR FRAME							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.845	AFL	745						
PROC. REF: AMM 53 40 00 220 812PROC. REF: AMM 53 40 00 220 812								
53-40-00-215	DETAILED INSPECTION OF THE FORWARD ENGINE-MOUNT FRAME-ASSEMBLY							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.850	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53 40 00 220 814PROC. REF: AMM 53 40 00 220 814								
53-40-00-216	DETAILED INSPECTION OF THE SUPPORT STRUCTURE OF THE INNER FLAP INBOARD TRACK							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.855	AFL	745						
PROC. REF: AMM 53 40 00 220 811PROC. REF: AMM 53 40 00 220 811								
53-40-00-217	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AFT FACE OF THE AFT PRESSURE BULKHEAD CONNECTORS - FS861.00							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 53 40 00 210 831PROC. REF: AMM 53 40 00 210 831								
53-40-00-415 ^U	DETAILED INSPECTION OF THE BAGGAGE DOOR SURROUND STRUCTURE, INNER DOUBLERLOCATION: FS813.00 TO FS861.00, STR16L TO STR19L							Service ATA:53
	MOS							
	HRS							
	AFL		T:7500		7500		6111	
53-41-01-900-801-01	FLOOR -FS781-813 MID PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1070	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-02	FLOOR - FS813-861 RH BL27-35 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1075	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-01-900-801-03	FLOOR - FS781-813 RH BL27-35 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1080	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-04	FLOOR - FS781-813 LH BL27-35 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1085	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-05	FLOOR - FS781-813 RH BL 9-27 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1090	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-06	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-07	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-08	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-01-900-801-09		FLOOR - FS577-785 PANEL						Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-10		FLOOR - FS577-785 PANEL						Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-11		FLOOR - FS577-785 PANEL						Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-12		FLOOR - FS577-785 PANEL						Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-13		FLOOR - FS577-785 PANEL						Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-14		FLOOR - FS577-785 PANEL						Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-01-900-801-15	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-16	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-17	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-18	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-19	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-20	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-01-900-801-21	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-22	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-23	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-24	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-25	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-26	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-01-900-801-27	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-41-01-900-801-28	FLOOR - FS577-785 PANEL							Component ATA:53
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.1095	AFL	0		TSN 0				
PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801PROC. REF: AMM 53 41 01 000 801, AMM 53 41 01 400 801								
53-42-00-420 ^U	SPECIAL DETAILED INSPECTION OF THE FUSELAGE SKIN PANEL AND BULKHEAD OUTER CAP - FS861.00, STRINGER 7L TO 8L							Service ATA:53
	MOS							05-10-26
	HRS							AIRWORTHINESS
	AFL	0	T:7500		7500	7500	6111	
53-50-00-101	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR CAP AND CRUCIFORM FITTING							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.860	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 50 00 220 806PROC. REF: AMM 53 50 00 220 806								
53-50-00-102	DETAILED INSPECTION OF THE VERTICAL STABILIZER ATTACHMENT AT THE FUSELAGE FRAMES							Service ATA:53
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 53.865	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 53 50 00 220 810PROC. REF: AMM 53 50 00 220 810								
53-50-00-201	DETAILED INSPECTION OF THE AFT ENGINE-MOUNT FRAME-ASSEMBLY							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.870	AFL	745						
PROC. REF: AMM 53 50 00 220 801PROC. REF: AMM 53 50 00 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-50-00-202	DETAILED INSPECTION OF THE MID SPAR FRAME							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.875	AFL	745						
PROC. REF: AMM 53 50 00 220 802PROC. REF: AMM 53 50 00 220 802								
53-50-00-203	DETAILED INSPECTION OF THE REAR SPAR FRAME							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.880	AFL	745						
PROC. REF: AMM 53 50 00 220 803PROC. REF: AMM 53 50 00 220 803								
53-50-00-204	DETAILED INSPECTION OF THE STRUT ATTACH AND BACKUP FITTINGS OF THE APU MOUNT STRUCTURE							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.885	AFL	745						
PROC. REF: AMM 53 50 00 220 804PROC. REF: AMM 53 50 00 220 804								
53-60-01-900-801-01	RADOME							Component ATA:53
PN:GC219-0504-7	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:D835032	HRS	0		TSN 0				
WC#: 53.1100	AFL	0		TSN 0				
PROC. REF: AMM 53 60 01 000 801, AMM 53 60 01 400 801PROC. REF: AMM 53 60 01 000 801, AMM 53 60 01 400 801								
53-ZL-00-201	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - INTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.890	AFL	745						
PROC. REF: AMM 53 10 00 210 803, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 803, SPM 20-70-00-210-801								
53-ZL-00-202	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL LH							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.895	AFL	745						
PROC. REF: AMM 53 10 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 806, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-ZL-00-203	GENERAL VISUAL INSPECTION OF THE LOWER NOSE COMPARTMENT - INTERNAL RH							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.900	AFL	745						
PROC. REF: AMM 53 10 00 210 807, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 807, SPM 20-70-00-210-801								
53-ZL-00-204	GENERAL VISUAL INSPECTION OF THE NOSE WHEEL WELL							Service ATA:53
	MOS	15-May-24						MRB
	HRS	3168:27						
WC#: 53.905	AFL	1205	450 (+10%/-10%)		1655	1700	266 (+45)	
PROC. REF: AMM 53 10 00 210 818, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 818, SPM 20-70-00-210-801								
53-ZL-00-205	GENERAL VISUAL INSPECTION OF THE MID LOWER FUSELAGE, SLAT DRIVE COMPARTMENT - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.910	AFL	745						
PROC. REF: AMM 53 10 00 210 809, SPM 20-70-00-210-801, SPM 51-25-00-110-801PROC. REF: AMM 53 10 00 210 809, SPM 20-70-00-210-801, SPM 51-25-00-110-801								
53-ZL-00-206	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS781.00 TO FS861.00, BELOW WL71.5 - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.915	AFL	745						
PROC. REF: AMM 53 40 00 210 825, SPM 20-70-00-210-801PROC. REF: AMM 53 40 00 210 825, SPM 20-70-00-210-801								
53-ZL-00-207	GENERAL VISUAL INSPECTION OF THE AFT WING-TO-FUSELAGE FAIRING - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.920	AFL	745						
PROC. REF: AMM 53 61 09 210 801, SPM 20-70-00-210-801PROC. REF: AMM 53 61 09 210 801, SPM 20-70-00-210-801								
53-ZL-00-208	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.925	AFL	745						
PROC. REF: AMM 53 30 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 806, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-ZL-00-209	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR WHEEL WELL							Service ATA:53
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 53.930	AFL	747						
PROC. REF: AMM 53 30 00 210 807, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 807, SPM 20-70-00-210-801								
53-ZL-00-210	GENERAL VISUAL INSPECTION OF THE LOWER MID-FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR - INTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.935	AFL	745						
PROC. REF: AMM 53 30 00 210 808, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 808, SPM 20-70-00-210-801								
53-ZL-00-211	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX LOWER SURFACE - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.940	AFL	745						
PROC. REF: AMM 53 30 00 210 811, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 811, SPM 20-70-00-210-801								
53-ZL-00-212	GENERAL VISUAL INSPECTION OF THE CENTER WING BOX - INTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.945	AFL	745						
PROC. REF: AMM 53 30 00 210 812, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 812, SPM 20-70-00-210-801								
53-ZL-00-213	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00+32.00 AND FS557.00 - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.950	AFL	745						
PROC. REF: AMM 53 20 00 210 813, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 813, SPM 20-70-00-210-801								
53-ZL-00-214	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00+32.00 AND FS557.00, AND BETWEEN STR22L AND STR22R - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.955	AFL	745						
PROC. REF: AMM 53 20 00 210 816, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 816, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-ZL-00-215	GENERAL VISUAL INSPECTION OF THE LOWER FORWARD FUSELAGE, BETWEEN FS280.00+32.00 AND FS557.00, AND BETWEEN STR18L AND STR22L, AND STR18R AND STR22R - INTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.960	AFL	745						
PROC. REF: AMM 53 20 00 210 814, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 814, SPM 20-70-00-210-801								
53-ZL-00-216	GENERAL VISUAL INSPECTION OF THE WING-TO-FUSELAGE FAIRINGS - EXTERNAL							Service ATA:53
	MOS	21-Jul-21						MRB
	HRS	2446:06						
WC#: 53.965	AFL	747	1800 (+50/-50)	Adj 50	2597	2647	1208 (+50)	
PROC. REF: AMM 53 20 00 210 810, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 810, SPM 20-70-00-210-801								
53-ZL-00-217	GENERAL VISUAL INSPECTION OF THE FUSELAGE NOSE SECTION - EXTERNAL							Service ATA:53
	MOS	10-Mar-23	180 (+3m/-3m)	Adj 3	10-Jun-38	10-Sep-38	4851 d (+92)	MRIP
	HRS	2845:10	3000 (+50/-50)	Adj 50	5895:10	5945:10	2449:14 (+50)	
WC#: 53.970	AFL	999						
PROC. REF: AMM 53 20 00 210 815, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 815, SPM 20-70-00-210-801								
53-ZL-00-218	GENERAL VISUAL INSPECTION OF THE NOSE SECTION OF THE FORWARD EQUIPMENT COMPARTMENT - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.975	AFL	745						
PROC. REF: AMM 53 10 00 210 817, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 817, SPM 20-70-00-210-801								
53-ZL-00-219	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT							Service ATA:53
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 53.980	AFL	999						
PROC. REF: AMM 53 10 00 210 819, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 819, SPM 20-70-00-210-801								
53-ZL-00-220	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT, EXCLUDING BAGGAGE DOOR - EXTERNAL							Service ATA:53
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 53.985	AFL	747						
PROC. REF: AMM 53 40 00 210 805, SPM 20-70-00-210-801PROC. REF: AMM 53 40 00 210 805, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-ZL-00-221	GENERAL VISUAL INSPECTION OF THE ELECTRICAL POWER CONTROL-CENTER - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.990	AFL	745						
PROC. REF: AMM 53 40 00 210 827, SPM 20-70-00-210-801, SPM 51-25-00-110-801PROC. REF: AMM 53 40 00 210 827, SPM 20-70-00-210-801, SPM 51-25-00-110-801								
53-ZL-00-222	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT - INTERNAL							Service ATA:53
	MOS	05-Feb-21	180 (+3m/-3m)		05-Feb-36	05-May-36	3995 d (+90)	MRB
	HRS	2444:24						
WC#: 53.995	AFL	745						
PROC. REF: AMM 53 40 00 210 830, SPM 20-70-00-210-801PROC. REF: AMM 53 40 00 210 830, SPM 20-70-00-210-801								
53-ZL-00-223	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1000	AFL	745						
PROC. REF: AMM 53 30 00 210 805, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 805, SPM 20-70-00-210-801								
53-ZL-00-224	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE COMPARTMENT ABOVE THE CABIN FLOOR - INTERNAL							Service ATA:53
	MOS	05-Feb-21	180 (+3m/-3m)		05-Feb-36	05-May-36	3995 d (+90)	MRB
	HRS	2444:24						
WC#: 53.1005	AFL	745						
PROC. REF: AMM 53 30 00 210 809, SPM 20-70-00-210-801PROC. REF: AMM 53 30 00 210 809, SPM 20-70-00-210-801								
53-ZL-00-225	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00+32.00 AND FS557.00, EXCLUDING THE PASSENGER DOOR - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1010	AFL	745						
PROC. REF: AMM 53 20 00 210 811, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 811, SPM 20-70-00-210-801								
53-ZL-00-226	GENERAL VISUAL INSPECTION OF THE UPPER FORWARD FUSELAGE, BETWEEN FS280.00+32.00 AND FS557.00, ABOVE WL71.50, EXCLUDING THE PASSENGER DOOR - INTERNAL							Service ATA:53
	MOS	05-Feb-21	180 (+3m/-3m)		05-Feb-36	05-May-36	3995 d (+90)	MRB
	HRS	2444:24						
WC#: 53.1015	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53 20 00 210 812, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 812, SPM 20-70-00-210-801								
53-ZL-00-227	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - EXTERNAL							Service ATA:53
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 53.1020	AFL	747						
PROC. REF: AMM 53 40 00 210 811, SPM 20-70-00-210-801PROC. REF: AMM 53 40 00 210 811, SPM 20-70-00-210-801								
53-ZL-00-228	GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE - INTERNAL							Service ATA:53
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 53.1025	AFL	999						
PROC. REF: AMM 53 40 00 210 812, SPM 20-70-00-210-801PROC. REF: AMM 53 40 00 210 812, SPM 20-70-00-210-801								
53-ZL-00-229	GENERAL VISUAL INSPECTION OF THE TAIL CONE - EXTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1030	AFL	745						
PROC. REF: AMM 53 50 00 210 804, SPM 20-70-00-210-801PROC. REF: AMM 53 50 00 210 804, SPM 20-70-00-210-801								
53-ZL-00-230	GENERAL VISUAL INSPECTION OF THE TAIL CONE - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1035	AFL	745						
PROC. REF: AMM 53 50 00 210 805, SPM 20-70-00-210-801PROC. REF: AMM 53 50 00 210 805, SPM 20-70-00-210-801								
53-ZL-00-231	GENERAL VISUAL INSPECTION OF THE FUSELAGE FROM FS987.50 TO THE VERTICAL-STABILIZER REAR-SPAR DATUM-LINE - INTERNAL							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1040	AFL	745						
PROC. REF: AMM 53 50 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 53 50 00 210 806, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-ZL-00-232	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL LH							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1045	AFL	745						
PROC. REF: AMM 53 10 00 210 820, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 820, SPM 20-70-00-210-801								
53-ZL-00-233	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS COMPARTMENT - INTERNAL RH							Service ATA:53
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1050	AFL	745						
PROC. REF: AMM 53 10 00 210 820, SPM 20-70-00-210-801PROC. REF: AMM 53 10 00 210 820, SPM 20-70-00-210-801								
53-ZL-00-234	GENERAL VISUAL INSPECTION OF THE ABOVE FLOOR AVIONIC RACK LOCATED BETWEEN FS281.00+32.00 AND FS 319.60+32.00							Service ATA:53
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 53.1055	AFL	745						
PROC. REF: AMM 53 20 00 210 818, SPM 20-70-00-210-801PROC. REF: AMM 53 20 00 210 818, SPM 20-70-00-210-801								
ATA 54 - NACELLES/PYLONS								
54-50-00-201	DETAILED INSPECTION OF THE VERTICAL FLANGE OF THE PYLON DRAG ANGLES - PS30.00 TO PS151.00							Service ATA:54
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 54.005	AFL	745						
PROC. REF: AMM 54 50 00 220 801PROC. REF: AMM 54 50 00 220 801								
54-50-00-202	DETAILED INSPECTION OF THE PYLON CENTER BOX INTERNAL STRUCTURE - PS30.00 TO PS151.00							Service ATA:54
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 54.010	AFL	745						
PROC. REF: AMM 54 50 00 220 802PROC. REF: AMM 54 50 00 220 802								
54-50-01-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE PYLONS CONNECTORS							Service ATA:54
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 54 50 01 220 801PROC. REF: AMM 54 50 01 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-51-00-101	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM ATTACHMENT-LUGS							Service ATA:54
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 54.015	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-54-50-002PROC. REF: NDT ET-54-50-002								
54-51-00-102	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, UPPER AND LOWER CAPS							Service ATA:54
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 54.020	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-54-50-004PROC. REF: NDT ET-54-50-004								
54-51-00-103	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM THRUST-STRUT							Service ATA:54
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 54.025	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-54-50-001PROC. REF: NDT ET-54-50-001								
54-51-00-106	SPECIAL DETAILED INSPECTION OF THE ENGINE BEAM PYLON, FUSELAGE JOINT							Service ATA:54
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 54.035	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-54-50-003PROC. REF: NDT ET-54-50-003								
54-51-00-107	DETAILED INSPECTION OF THE ENGINE PYLON SKINS AND DRAGANGLES							Service ATA:54
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 54 51 00 220 804PROC. REF: AMM 54 51 00 220 804								
54-52-05-900-801-01	LH PYLON LEADING EDGE							Component ATA:54
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 54.045	AFL	0		TSN 0				
PROC. REF: AMM 54 52 05 000 801, AMM 54 52 05 400 801PROC. REF: AMM 54 52 05 000 801, AMM 54 52 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-52-05-900-801-02	RH PYLON LEADING EDGE							Component ATA:54
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 54.045	AFL	0		TSN 0				
PROC. REF: AMM 54 52 05 000 801, AMM 54 52 05 400 801PROC. REF: AMM 54 52 05 000 801, AMM 54 52 05 400 801								
54-ZL-00-201	GENERAL VISUAL INSPECTION OF THE PYLON - LH EXTERNAL							Service ATA:54
	MOS	21-Jul-21	60 (+3m/-3m)	21-Jul-26	21-Oct-26	509 d (+92)	MRB	
	HRS	2446:06						
WC#: 54.040	AFL	747						
PROC. REF: AMM 54 50 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 54 50 00 210 801, SPM 20-70-00-210-801								
54-ZL-00-202	GENERAL VISUAL INSPECTION OF THE PYLON - RH EXTERNAL							Service ATA:54
	MOS	21-Jul-21	60 (+3m/-3m)	21-Jul-26	21-Oct-26	509 d (+92)	MRB	
	HRS	2446:06						
WC#: 54.040	AFL	747						
PROC. REF: AMM 54 50 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 54 50 00 210 801, SPM 20-70-00-210-801								
ATA 55 - STABILIZERS								
55-10-00-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE-ACTUATOR FITTING-LUGS INCLUDING PINS							Service ATA:55
	MOS	30-Jul-09					AIRWORTHINESS	
	HRS	0						
WC#: 55.005	AFL	0	T:7500	7500		6111		
PROC. REF: NDT ET-55-10-003, NDT MT-55-10-003, NDT UT-55-10-001PROC. REF: NDT ET-55-10-003, NDT MT-55-10-003, NDT UT-55-10-001								
55-10-00-102	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT FITTINGS							Service ATA:55
	MOS	30-Jul-09					AIRWORTHINESS	
	HRS	0						
WC#: 55.010	AFL	0	T:7500	7500		6111		
PROC. REF: NDT ET-55-10-001, NDT MT-55-10-001PROC. REF: NDT ET-55-10-001, NDT MT-55-10-001								
55-10-00-103	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTING LUGS AND PINS							Service ATA:55
	MOS	30-Jul-09					AIRWORTHINESS	
	HRS	0						
WC#: 55.015	AFL	0	T:7500	7500		6111		

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: NDT ET-55-10-002, NDT MT-55-10-002PROC. REF: NDT ET-55-10-002, NDT MT-55-10-002								
55-10-00-104	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER REAR SPAR JOINT							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.020	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-10-007PROC. REF: NDT ET-55-10-007								
55-10-00-105	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL-STABILIZER							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.025	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 10 00 220 807PROC. REF: AMM 55 10 00 220 807								
55-10-00-108	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PCU FITTINGS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.030	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-10-004, NDT PT-55-10-001PROC. REF: NDT ET-55-10-004, NDT PT-55-10-001								
55-10-00-109	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE HINGE-FITTINGS							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
WC#: 55.035	AFL		T:7500		7500		6111	
PROC. REF: AMM 55 10 00 220 811PROC. REF: AMM 55 10 00 220 811								
55-10-00-110	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER FRONT SPAR JOINT							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
WC#: 55.040	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-55-10-008PROC. REF: NDT ET-55-10-008								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00-201	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS AND STRAPS OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.045	AFL	745						
PROC. REF: AMM 55 10 00 220 802PROC. REF: AMM 55 10 00 220 802								
55-10-00-202	DETAILED INSPECTION OF THE CENTER BOX RIBS AND FITTINGS OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.050	AFL	745						
PROC. REF: AMM 55 10 00 220 804PROC. REF: AMM 55 10 00 220 804								
55-10-00-203	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER HINGE, SUPPORT, AND BACKUP FITTINGS AT RIBS 4, 5, 9 AND 12							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.055	AFL	745						
PROC. REF: AMM 55 10 00 220 805PROC. REF: AMM 55 10 00 220 805								
55-10-00-204	DETAILED INSPECTION OF THE EXTERNAL SKIN OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.060	AFL	0	T:7500 (+50/-50)	7500	7550	6111 (+50)		
PROC. REF: AMM 55 10 00 220 806PROC. REF: AMM 55 10 00 220 806								
55-10-00-205	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.065	AFL	0	T:3750 (+50/-50)	3750	3800	2361 (+50)		
PROC. REF: AMM 55 10 00 220 807PROC. REF: AMM 55 10 00 220 807								
55-10-00-900-803-01	HORIZONTAL STABILIZER							Component ATA:55
PN:GS258-0001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B359	HRS	0		TSN 0				
WC#: 55.350	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-05-900-801-01	BULLET FAIRING ASSY							Component ATA:55
PN:GS248-0002-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B362	HRS	0		TSN 0				
WC#: 55.360	AFL	0		TSN 0				
PROC. REF: AMM 55 10 05 000 801, AMM 55 10 05 400 801PROC. REF: AMM 55 10 05 000 801, AMM 55 10 05 400 801								
55-10-05-900-813-01	LH TIP FAIRING							Component ATA:55
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 55.355	AFL	0		TSN 0				
PROC. REF: AMM 55 10 05 000 813, AMM 55 10 05 400 813PROC. REF: AMM 55 10 05 000 813, AMM 55 10 05 400 813								
55-10-05-900-813-02	RH TIP FAIRING							Component ATA:55
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 55.355	AFL	0		TSN 0				
PROC. REF: AMM 55 10 05 000 813, AMM 55 10 05 400 813PROC. REF: AMM 55 10 05 000 813, AMM 55 10 05 400 813								
55-10-09-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE BASEPLATE							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.070	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-10-006PROC. REF: NDT ET-55-10-006								
55-10-09-102	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TAILPLANE CENTER-LINE JOINT-STRAPS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.075	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-10-005PROC. REF: NDT ET-55-10-005								
55-10-09-103	DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.080	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 10 09 220 803PROC. REF: AMM 55 10 09 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-09-104	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER PIVOT-FITTING SUPPORT-STRUCTURE							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
WC#: 55.085	AFL		T:7500		7500		6111	
PROC. REF: AMM 55 10 09 220 801PROC. REF: AMM 55 10 09 220 801								
55-10-09-105	SPECIAL DETAILED INSPECTION OF THE ATTACHMENT OF THE ACTUATOR FITTING TO THE HORIZONTAL-STABILIZER YAW RESTRAINT							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
WC#: 55.090	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-55-10-009PROC. REF: NDT ET-55-10-009								
55-20-00-101	SPECIAL DETAILED INSPECTION OF THE ELEVATOR, ACTUATOR AND HINGE FITTING							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.095	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-20-001PROC. REF: NDT ET-55-20-001								
55-20-00-102	DETAILED INSPECTION OF THE ELEVATOR - COMPOSITE PARTS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.100	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 20 00 220 802PROC. REF: AMM 55 20 00 220 802								
55-20-00-201	SPECIAL DETAILED INSPECTION OF THE UPPER AND LOWER SKINS OF THE ELEVATOR							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.105	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	
PROC. REF: AMM 55 20 00 280 801PROC. REF: AMM 55 20 00 280 801								
55-20-00-202	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE ELEVATOR							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.110	AFL	0	T:7500 (+50/-50)		7500	7550	6111 (+50)	
PROC. REF: AMM 55 20 00 220 801PROC. REF: AMM 55 20 00 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-05-201	DETAILED INSPECTION OF THE FITTINGS OF THE ELEVATOR							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.115	AFL	745						
PROC. REF: AMM 55 20 05 220 801PROC. REF: AMM 55 20 05 220 801								
55-30-00-102	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGER PANELS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.120	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 00 210 810PROC. REF: AMM 55 30 00 210 810								
55-30-00-103	SPECIAL DETAILED INSPECTION OF THE SURROUND STRUCTURE OF THE ACCESS HOLE ON THE VERTICAL STABILIZER							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.125	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-30-003PROC. REF: NDT ET-55-30-003								
55-30-00-104	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER PIVOT AND ACTUATOR FITTINGS FOR THE HORIZONTAL STABILIZER							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.130	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-30-002, NDT ET-55-30-006, NDT ET-55-30-007, NDT ET-55-30-008, NDT UT-55-30-001PROC. REF: NDT ET-55-30-002, NDT ET-55-30-006, NDT ET-55-30-007, NDT ET-55-30-008, NDT UT-55-30-001								
55-30-00-105	DETAILED INSPECTION OF THE BACKUP STRUCTURE OF THE HORIZONTAL-STABILIZER ACTUATOR ATTACHMENT TO THE VERTICAL STABILIZER							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.135	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 00 220 809PROC. REF: AMM 55 30 00 220 809								
55-30-00-106	DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT-SPAR STRAP							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.140	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 00 220 810PROC. REF: AMM 55 30 00 220 810								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-00-107	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER RUDDER HINGE FITTINGS AND PINS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.145	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-30-001, NDT PT-55-30-001PROC. REF: NDT ET-55-30-001, NDT PT-55-30-001								
55-30-00-111	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TRIM-ACTUATOR PIN							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.150	AFL	0	T:7500		7500		6111	
PROC. REF: NDT MT-55-30-001PROC. REF: NDT MT-55-30-001								
55-30-00-112	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER DRAG ANGLES							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.155	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 00 210 809PROC. REF: AMM 55 30 00 210 809								
55-30-00-113	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER SIDE-STAYS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.160	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-30-005PROC. REF: NDT ET-55-30-005								
55-30-00-114	DETAILED INSPECTION OF THE VERTICAL STABILIZER CLOSING RIB							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.165	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 00 220 807PROC. REF: AMM 55 30 00 220 807								
55-30-00-115	SPECIAL DETAILED INSPECTION OF THE RUDDER WISHBONE							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.170	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-30-004PROC. REF: NDT ET-55-30-004								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-00-116	DETAILED INSPECTION OF THE RUDDER WISHBONE							Service ATA:55
	MOS							AIRWORTHINESS
	HRS							
WC#: 55.170	AFL		T:7500		7500		6111	
PROC. REF: AMM 55 30 00 220 808PROC. REF: AMM 55 30 00 220 808								
55-30-00-117	DETAILED INSPECTION OF THE VERTICAL STABILIZER SKIN/STRINGERPANELS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 00 220 806PROC. REF: AMM 55 30 00 220 806								
55-30-00-118	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER DRAGANGLES							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-30-009PROC. REF: NDT ET-55-30-009								
55-30-00-202	DETAILED INSPECTION OF THE STABILIZER DRAG ANGLES - FRONT SPAR DATUM TO REAR SPAR DATUM							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.180	AFL	745						
PROC. REF: AMM 55 30 00 220 802PROC. REF: AMM 55 30 00 220 802								
55-30-00-203	DETAILED INSPECTION OF THE FRONT SPAR, WEB AND STRAPS OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.185	AFL	745						
PROC. REF: AMM 55 30 00 220 805PROC. REF: AMM 55 30 00 220 805								
55-30-00-205	GENERAL VISUAL INSPECTION OF THEVERTICAL-STABILIZER SKIN OUTER-SURFACESCOVERED BY ACCESS PANELS AND RUDDER SEAL							Service ATA:55
	MOS	27-Feb-20	60 (+3m/-3m)		27-Feb-25	27-May-25	0 d (+89)	MRB
	HRS	0						
	AFL	0						
PROC. REF: AMM 55 30 00 210 812PROC. REF: AMM 55 30 00 210 812								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-00-206	GENERAL VISUAL INSPECTION OF THE VERTICAL-STABILIZER SKIN OUTER-SURFACES COVERED BY THE DORSAL AND BULLET FAIRINGS							Service ATA:55
	MOS	27-Feb-20	T:60 (+3m/-3m)		27-Feb-25	27-May-25	0 d (+89)	MRB
	HRS	0						
	AFL	0						
PROC. REF: AMM 55 30 00 210 813PROC. REF: AMM 55 30 00 210 813								
55-30-00-900-801-01	VERTICAL STAB BOX ASSY							Component ATA:55
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 55.370	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
55-30-01-101	GENERAL VISUAL INSPECTION OF THE CAPS OF THE REAR SPAR OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.190	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 01 210 801PROC. REF: AMM 55 30 01 210 801								
55-30-01-102	DETAILED INSPECTION OF THE VERTICAL STABILIZER MID-SPAR CAP							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.195	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 30 01 220 808PROC. REF: AMM 55 30 01 220 808								
55-30-01-201	DETAILED INSPECTION OF THE HORIZONTAL LEGS, FRONT-SPAR JOINT LEGS, AND SHEAR ANGLE OF THE VERTICAL-STABILIZER FRONT SPAR-TO-FUSELAGE INTERFACE-FITTINGS							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.200	AFL	745						
PROC. REF: AMM 55 30 01 220 803PROC. REF: AMM 55 30 01 220 803								
55-30-01-203	DETAILED INSPECTION OF THE FITTINGS AND WISHBONE ATTACHMENTS OF THE RUDDER AND REAR SPAR AFT FACE AND RUDDER HINGE OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.205	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: AMM 55 30 01 220 806PROC. REF: AMM 55 30 01 220 806								
55-30-01-204	DETAILED INSPECTION OF THE TIP CANTED RIB AND THE RIB FITTINGS OF THE VERTICAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.210	AFL	745						
PROC. REF: AMM 55 30 01 220 807PROC. REF: AMM 55 30 01 220 807								
55-30-01-205	DETAILED INSPECTION OF THE INTERNAL STRUCTURE AND REAR SPAR FORWARD FACE OF THE VERTICAL STABILIZER AND WISHBONE ATTACHEMENTS TO THE VERTICAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.215	AFL	745						
PROC. REF: AMM 55 30 01 220 809PROC. REF: AMM 55 30 01 220 809								
55-30-01-206	DETAILED INSPECTION OF THE ATTACHMENTS AND FITTINGS OF THE WISHBONE TO THE VERTICAL STABILIZER							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.220	AFL	745						
PROC. REF: AMM 55 30 01 220 810PROC. REF: AMM 55 30 01 220 810								
55-30-01-207	DETAILED INSPECTION OF THE LOWER ATTACHMENT PINS OF THE PITCH TRIM ACTUATOR							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.225	AFL	745						
PROC. REF: AMM 55 30 01 220 811PROC. REF: AMM 55 30 01 220 811								
55-30-01-208	DETAILED INSPECTION OF THE LOWER ATTACHMENT BOLTS OF THE PITCH TRIM ACTUATOR							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.230	AFL	745						
PROC. REF: AMM 55 30 01 220 812PROC. REF: AMM 55 30 01 220 812								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-01-209	DETAILED INSPECTION OF THE RUDDER HINGE PINS							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.235	AFL	745						
PROC. REF: AMM 55 30 01 220 813PROC. REF: AMM 55 30 01 220 813								
55-30-09-900-801-01	VERTICAL STABILIZER LEADING EDGE							Component ATA:55
PN:GS248-0003-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:B363	HRS	0		TSN 0				
WC#: 55.365	AFL	0		TSN 0				
PROC. REF: AMM 55 30 09 000 801, AMM 55 30 09 400 801PROC. REF: AMM 55 30 09 000 801, AMM 55 30 09 400 801								
55-40-00-101	SPECIAL DETAILED INSPECTION OF THE RUDDER ACTUATOR BRACKET LUGS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.240	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-40-001PROC. REF: NDT ET-55-40-001								
55-40-00-102	DETAILED INSPECTION OF THE RUDDER STRUCTURE - COMPOSITE PARTS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.245	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 55 40 00 220 803PROC. REF: AMM 55 40 00 220 803								
55-40-00-103	SPECIAL DETAILED INSPECTION OF THE RUDDER HINGE FITTINGS							Service ATA:55
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 55.250	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-55-40-002PROC. REF: NDT ET-55-40-002								
55-40-00-201	SPECIAL DETAILED INSPECTION OF THE SKINS OF THE RUDDER, EXTERNAL							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.255	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	
PROC. REF: AMM 55 40 00 280 801PROC. REF: AMM 55 40 00 280 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-00-203	DETAILED INSPECTION OF THE RIBS AND SPAR OF THE RUDDER							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.260	AFL	0	T:7500 (+50/-50)		7500	7550	6111 (+50)	
PROC. REF: AMM 55 40 00 220 801PROC. REF: AMM 55 40 00 220 801								
55-40-00-205	DETAILED INSPECTION OF THE BACKUP FITTINGS OF THE RUDDER							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.265	AFL	745						
PROC. REF: AMM 55 40 00 220 805PROC. REF: AMM 55 40 00 220 805								
55-ZL-00-201	GENERAL VISUAL INSPECTION OF THE RAM AIR INTAKE AND DORSAL FAIRING - INTERNAL							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.270	AFL	745						
PROC. REF: AMM 55 30 05 210 801, SPM 20-70-00-210-801PROC. REF: AMM 55 30 05 210 801, SPM 20-70-00-210-801								
55-ZL-00-202	GENERAL VISUAL INSPECTION OF THE RAM AIR DORSAL FAIRING AND THE LEADING EDGE OF THE VERTICAL STABILIZER - EXTERNAL							Service ATA:55
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRB
	HRS	2446:06						
WC#: 55.275	AFL	747						
PROC. REF: AMM 55 30 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 55 30 00 210 802, SPM 20-70-00-210-801								
55-ZL-00-203	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL LH							Service ATA:55
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 55.280	AFL	747						
PROC. REF: AMM 55 30 00 210 803, SPM 20-70-00-210-801PROC. REF: AMM 55 30 00 210 803, SPM 20-70-00-210-801								
55-ZL-00-204	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - EXTERNAL RH							Service ATA:55
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 55.285	AFL	747						
PROC. REF: AMM 55 30 00 210 803, SPM 20-70-00-210-801PROC. REF: AMM 55 30 00 210 803, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-ZL-00-205	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.290	AFL	745						
PROC. REF: AMM 55 30 00 210 804, SPM 20-70-00-210-801PROC. REF: AMM 55 30 00 210 804, SPM 20-70-00-210-801								
55-ZL-00-206	GENERAL VISUAL INSPECTION OF THE HORIZONTAL-STABILIZER BULLET FAIRING - EXTERNAL							Service ATA:55
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 55.295	AFL	747						
PROC. REF: AMM 55 10 05 210 801, SPM 20-70-00-210-801PROC. REF: AMM 55 10 05 210 801, SPM 20-70-00-210-801								
55-ZL-00-207	GENERAL VISUAL INSPECTION OF THE HORIZONTAL- STABILIZER BULLET FAIRING - INTERNAL							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.300	AFL	745						
PROC. REF: AMM 55 10 05 210 802, SPM 20-70-00-210-801PROC. REF: AMM 55 10 05 210 802, SPM 20-70-00-210-801								
55-ZL-00-208	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER LEADING EDGE - INTERNAL							Service ATA:55
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 55.305	AFL	745						
PROC. REF: AMM 55 30 09 210 801, SPM 20-70-00-210-801PROC. REF: AMM 55 30 09 210 801, SPM 20-70-00-210-801								
55-ZL-00-209	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE RUDDER - INTERNAL							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.310	AFL	745						
PROC. REF: AMM 55 40 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 55 40 00 210 802, SPM 20-70-00-210-801								
55-ZL-00-210	GENERAL VISUAL INSPECTION OF THE RUDDER - EXTERNAL							Service ATA:55
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRB
	HRS	2446:06						
WC#: 55.315	AFL	747						
PROC. REF: AMM 55 40 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 55 40 00 210 801, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-ZL-00-211	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL LH							Service ATA:55
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRB
	HRS	2446:06						
WC#: 55.320	AFL	747						
PROC. REF: AMM 55 10 00 210 803, SPM 20-70-00-210-801PROC. REF: AMM 55 10 00 210 803, SPM 20-70-00-210-801								
55-ZL-00-212	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL RH							Service ATA:55
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRB
	HRS	2446:06						
WC#: 55.325	AFL	747						
PROC. REF: AMM 55 10 00 210 803, SPM 20-70-00-210-801PROC. REF: AMM 55 10 00 210 803, SPM 20-70-00-210-801								
55-ZL-00-213	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL LH							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.330	AFL	0	3750 (+50/-50)	3750	3800	2361 (+50)		
PROC. REF: AMM 55 10 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 55 10 00 210 806, SPM 20-70-00-210-801								
55-ZL-00-214	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER LEADING-EDGE - INTERNAL RH							Service ATA:55
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 55.335	AFL	0	3750 (+50/-50)	3750	3800	2361 (+50)		
PROC. REF: AMM 55 10 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 55 10 00 210 806, SPM 20-70-00-210-801								
55-ZL-00-215	GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL LH							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.340	AFL	745						
PROC. REF: AMM 55 10 00 210 808, SPM 20-70-00-210-801PROC. REF: AMM 55 10 00 210 808, SPM 20-70-00-210-801								
55-ZL-00-216	GENERAL VISUAL INSPECTION OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - EXTERNAL RH							Service ATA:55
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 55.345	AFL	745						
PROC. REF: AMM 55 10 00 210 808, SPM 20-70-00-210-801PROC. REF: AMM 55 10 00 210 808, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-01-900-801-01		LH WINDSHIELD ASSEMBLY						Component ATA:56
PN:GC331-0001-13	MOS/MSC	26-Dec-18	O/C					
SN:4157	HRS	2346:06						
WC#: 56.005	AFL	718						
PROC. REF: CMM 56-10-01, AMM 56 10 01 000 801, AMM 56 10 01 400 801PROC. REF: CMM 56-10-01, AMM 56 10 01 000 801, AMM 56 10 01 400 801								
56-10-01-900-801-02		RH WINDSHIELD ASSEMBLY						Component ATA:56
PN:GC331-0001-14	MOS/MSC	17-Oct-23	O/C	TSN 0				
SN:7396	HRS	3029:02		TSN 0				
WC#: 56.005	AFL	1119		TSN 0				
PROC. REF: CMM 56-10-01, AMM 56 10 01 000 801, AMM 56 10 01 400 801PROC. REF: CMM 56-10-01, AMM 56 10 01 000 801, AMM 56 10 01 400 801								
56-10-01-900-802-01		SIDE POST (LH) SPLICE STRAP						Component ATA:56
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 56 10 01 000 801, AMM 56 10 01 400 801PROC. REF: AMM 56 10 01 000 801, AMM 56 10 01 400 801								
56-10-01-900-802-02		SIDE POST (RH) SPLICE STRAP						Component ATA:56
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.010	AFL	0		TSN 0				
PROC. REF: AMM 56 10 01 000 801, AMM 56 10 01 400 801PROC. REF: AMM 56 10 01 000 801, AMM 56 10 01 400 801								
56-10-05-900-801-01		LH SIDE WINDOW						Component ATA:56
PN:GC331-0003-7	MOS/MSC	29-Nov-22	O/C	TSN 0				
SN:7073	HRS	2750:09		TSN 0				
WC#: 56.015	AFL	951		TSN 0				
PROC. REF: CMM 56-10-02, AMM 56 10 05 000 801, AMM 56 10 05 400 801PROC. REF: CMM 56-10-02, AMM 56 10 05 000 801, AMM 56 10 05 400 801								
56-10-05-900-801-02		RH SIDE WINDOW						Component ATA:56
PN:GC331-0003-8	MOS/MSC	29-Nov-22	O/C	TSN 0				
SN:6206	HRS	2750:09		TSN 0				
WC#: 56.015	AFL	951		TSN 0				
PROC. REF: CMM 56-10-02, AMM 56 10 05 000 801, AMM 56 10 05 400 801PROC. REF: CMM 56-10-02, AMM 56 10 05 000 801, AMM 56 10 05 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-01-900-801-01		LEFT NO.1 ASSY CABIN WINDOW						Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:13380	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-02		RIGHT NO. 1 ASSY CABIN WINDOW						Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:15057	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-03		LEFT NO.2 ASSY CABIN WINDOW						Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:13381	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-04		RIGHT NO. 2 ASSY CABIN WINDOW						Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:15173	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-05		LEFT NO.3 ASSY CABIN WINDOW						Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:13382	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-06		RIGHT NO. 3 ASSY CABIN WINDOW						Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:13378	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-01-900-801-07	LEFT NO.4 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:13383	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-08	RIGHT NO. 4 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:15058	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-09	LEFT NO.5 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12851	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-10	RIGHT NO. 5 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12858	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-11	LEFT NO.6 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12852	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-12	RIGHT NO. 6 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12859	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-01-900-801-13	LEFT NO.7 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12853	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-14	RIGHT NO. 7 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:15124	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-15	LEFT NO.8 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12854	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-16	RIGHT NO. 8 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12860	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-17	LEFT NO.9 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12855	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-18	RIGHT NO. 9 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12862	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-01-900-801-19	LEFT NO.10 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12856	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-20	RIGHT NO. 10 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12863	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-21	LEFT NO.11 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12857	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-22	RIGHT NO. 11 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12864	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-23	LEFT NO.12 ASSY CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-24	RIGHT NO. 12 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:12883	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-01-900-801-25	LEFT NO.13 ASSY CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: CMM 56-20-00, AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-26	RIGHT NO. 13 ASSY CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11068	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-27	#14 RH FWD PASS WINDOW							Component ATA:56
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801								
56-20-01-900-801-28	#15 RH FWD PASS WINDOW							Component ATA:56
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801PROC. REF: AMM 56 20 01 000 801, AMM 56 20 01 400 801								
562001-701 ^U	(FWD LAVATORY) CABIN WINDOW							Component ATA:56
PN:GC333-0001-13	MOS/MSC	30-Aug-10	O/C	TSN 0				
SN:15075	HRS	28:06		TSN 0				
	AFL	11		TSN 0				
ATA 57 - WINGS								
57-00-00-900-801-01	LEFT HAND WING ASSEMBLY							Component ATA:57
PN:GM118-1001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0359	HRS	0		TSN 0				
WC#: 57.695	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-900-801-02	RIGHT HAND WING ASSEMBLY							Component ATA:57
PN:GM118-1001-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0359	HRS	0		TSN 0				
WC#: 57.695	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-10-00-101	SPECIAL DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL ACCESS-HOLES							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.005	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-10-003PROC. REF: NDT ET-57-10-003								
57-10-00-102	DETAILED INSPECTION OF THE AC TRANSFER-PUMP LOWER PANEL							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.010	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 811PROC. REF: AMM 57 10 00 220 811								
57-10-00-103	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE-STAY FITTING							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.015	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-10-008PROC. REF: NDT ET-57-10-008								
57-10-00-104	SPECIAL DETAILED INSPECTION OF THE CENTER WING LOWER PANEL SPLICE, BL47.61							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.020	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-10-004, NDT UT-57-10-001PROC. REF: NDT ET-57-10-004, NDT UT-57-10-001								
57-10-00-106	DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.025	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 813PROC. REF: AMM 57 10 00 220 813								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-107	DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER WING							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.030	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 817PROC. REF: AMM 57 10 00 220 817								
57-10-00-108	DETAILED INSPECTION OF THE CENTER-WING UPPER PANEL							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.035	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 814PROC. REF: AMM 57 10 00 220 814								
57-10-00-109	DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.040	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 815PROC. REF: AMM 57 10 00 220 815								
57-10-00-110	SPECIAL DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 TRUSS SUPPORT PLATE							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.045	AFL	0	T:7400		7400		6011	
PROC. REF: NDT ET-57-10-005, NDT MT-57-10-002PROC. REF: NDT ET-57-10-005, NDT MT-57-10-002								
57-10-00-111	SPECIAL DETAILED INSPECTION OF THE LOWER-CAP OF THE CENTER-WING FRONT SPAR							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.050	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-10-012PROC. REF: NDT ET-57-10-012								
57-10-00-112	DETAILED INSPECTION OF THE LOWER CAP OF THE CENTER-WINGREAR SPAR							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 818PROC. REF: AMM 57 10 00 220 818								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-113	DETAILED INSPECTION OF THE INTERMEDIATE RIB, BL27.00 CHORD FLANGES							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.055	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 816PROC. REF: AMM 57 10 00 220 816								
57-10-00-114	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.060	AFL		T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 810PROC. REF: AMM 57 10 00 220 810								
57-10-00-115	DETAILED INSPECTION OF THE CENTER-WING LOWER-PANEL SPLICE, BL47.61							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.065	AFL		T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 812PROC. REF: AMM 57 10 00 220 812								
57-10-00-116	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR ROOT-SPLICE LOWER CAP							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.070	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-10-006, NDT UT-57-10-003PROC. REF: NDT ET-57-10-006, NDT UT-57-10-003								
57-10-00-117	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE OF THE CENTER-WING							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.075	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-10-014PROC. REF: NDT ET-57-10-014								
57-10-00-118	SPECIAL DETAILED INSPECTION OF THE KEEL BEAM RIB, BL4.75							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.080	AFL		T:3666		3666		2277	
PROC. REF: NDT ET-57-10-002, NDT MT-57-10-001PROC. REF: NDT ET-57-10-002, NDT MT-57-10-001								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-119	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAP BL0.0 TO BL27.0							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.085	AFL		T:7500		7500		6111	
PROC. REF: NDT RT-57-10-003PROC. REF: NDT RT-57-10-003								
57-10-00-121	SPECIAL DETAILED INSPECTION OF THE REAR-SPAR LOWER-CAPAND WING SKIN BETWEEN LBL44.00 AND RBL44.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT RT-57-10-005PROC. REF: NDT RT-57-10-005								
57-10-00-122	DETAILED INSPECTION OF THE KEEL BEAM RIB TRUSS-BEAMPINS, BL4.75							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 820PROC. REF: AMM 57 10 00 220 820								
57-10-00-123	SPECIAL DETAILED INSPECTION OF THE WING FRONT-SPARLOWER-CAP AND WEB AT KEEL BEAM ATTACHMENTS, BL4.75							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT UT-57-10-002PROC. REF: NDT UT-57-10-002								
57-10-00-124	DETAILED INSPECTION OF THE FRONT SPAR LOWER CAP OF THECENTER WING FROM LBL47.60 TO RBL47.60							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 10 00 220 819PROC. REF: AMM 57 10 00 220 819								
57-10-00-125	SPECIAL DETAILED INSPECTION OF THE CENTER WING FRONT-SPARLOWER-CAP AND WEB AT FS574.50 FROM LBL47.60 TORBL47.60							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT RT-57-10-004PROC. REF: NDT RT-57-10-004								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-201	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.090	AFL	745						
PROC. REF: AMM 57 10 00 220 801PROC. REF: AMM 57 10 00 220 801								
57-10-00-202	DETAILED INSPECTION OF THE CENTER WING FRONT SPAR AFT FACE, AND CENTER WING UPPER PANEL, LOWER PANEL AND RIBS - INTERNAL LBL47.6 TO RBL47.6							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.095	AFL	745						
PROC. REF: AMM 57 10 00 220 802PROC. REF: AMM 57 10 00 220 802								
57-10-00-203	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.100	AFL	745						
PROC. REF: AMM 57 10 00 220 803PROC. REF: AMM 57 10 00 220 803								
57-10-00-204	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR OF THE CENTER WING - LBL47.6 TO RBL47.6							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.105	AFL	745						
PROC. REF: AMM 57 10 00 220 804PROC. REF: AMM 57 10 00 220 804								
57-10-00-205	DETAILED INSPECTION OF THE UPPER FACE OF THE CENTER WING UPPER PANEL							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.110	AFL	745						
PROC. REF: AMM 57 10 00 220 805PROC. REF: AMM 57 10 00 220 805								
57-10-00-206	DETAILED INSPECTION OF THE LOWER FACE OF THE CENTER WING LOWER PANEL							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.115	AFL	745						
PROC. REF: AMM 57 10 00 220 806PROC. REF: AMM 57 10 00 220 806								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-208	DETAILED INSPECTION OF THE OUTER FACE OF THE CENTER WING ROOT RIB							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.120	AFL	745						
PROC. REF: AMM 57 10 00 220 808PROC. REF: AMM 57 10 00 220 808								
57-10-00-209	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) SIDE STAY FITTING							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.125	AFL	745						
PROC. REF: AMM 57 10 00 220 809PROC. REF: AMM 57 10 00 220 809								
57-20-00-101	DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WCS537.40							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.130	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 826PROC. REF: AMM 57 20 00 220 826								
57-20-00-102	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - EXTERNAL							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.135	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 827PROC. REF: AMM 57 20 00 220 827								
57-20-00-103	DETAILED INSPECTION OF THE WING LOWER-SKIN FUEL-SYSTEM-HOLES							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.140	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 813PROC. REF: AMM 57 20 00 220 813								
57-20-00-104	SPECIAL DETAILED INSPECTION OF THE LOWER WING-PLANK STRINGER-RUNOUT							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.145	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-014PROC. REF: NDT ET-57-20-014								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-105	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) LOWER STRAP, WS85.50							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.150	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-013, NDT RT-57-20-005PROC. REF: NDT ET-57-20-013, NDT RT-57-20-005								
57-20-00-106	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) FITTING JOINT							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.155	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-008, NDT RT-57-20-002PROC. REF: NDT ET-57-20-008, NDT RT-57-20-002								
57-20-00-108	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS178.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.165	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-002PROC. REF: NDT ET-57-20-002								
57-20-00-109	SPECIAL DETAILED INSPECTION OF THE REAR SPAR SPLICE, WS287.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.170	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-009, NDT RT-57-20-007PROC. REF: NDT ET-57-20-009, NDT RT-57-20-007								
57-20-00-110	SPECIAL DETAILED INSPECTION OF THE LOWER SKIN SPLICE AT THE FRONT SPAR, CANTED RIB NO. 2 TO CWS390.90							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.175	AFL	0	T:3808		3808		2419	
PROC. REF: NDT ET-57-20-001PROC. REF: NDT ET-57-20-001								
57-20-00-111	DETAILED INSPECTION OF THE LOWER-SKIN SPANWISE-SPLICE							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.180	AFL	0	T:6232		6232		4843	
PROC. REF: AMM 57 20 00 220 824PROC. REF: AMM 57 20 00 220 824								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-112	DETAILED INSPECTION OF THE OUTER WING FRONT AND REAR SPAR CAPS AND SKIN							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.185	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 829PROC. REF: AMM 57 20 00 220 829								
57-20-00-113	GENERAL VISUAL INSPECTION OF THE WING UPPER-SKIN							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.190	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 210 814PROC. REF: AMM 57 20 00 210 814								
57-20-00-114	DETAILED INSPECTION OF THE WING RIBS AT WS66.00, WS178.00, WS287.00 AND CWS464.20							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.195	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 816PROC. REF: AMM 57 20 00 220 816								
57-20-00-115	DETAILED INSPECTION OF THE WING RIB AT WS85.50							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.200	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 817PROC. REF: AMM 57 20 00 220 817								
57-20-00-116	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS66.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.205	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-003PROC. REF: NDT ET-57-20-003								
57-20-00-119	SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION-FITTING							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.210	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-007, NDT RT-57-20-001PROC. REF: NDT ET-57-20-007, NDT RT-57-20-001								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-120	SPECIAL DETAILED INSPECTION OF THE SPLICE ON THE LOWER SKIN OF THE WING, WCS537.40							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.215	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-20-012PROC. REF: NDT ET-57-20-012								
57-20-00-121	DETAILED INSPECTION OF THE WING LOWER FUEL-ACCESS-HOLES - INTERNAL							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.220	AFL		T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 830PROC. REF: AMM 57 20 00 220 830								
57-20-00-122	DETAILED INSPECTION OF THE LOWER SKIN AT THE SPANWISE-SPLICE							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.225	AFL		T:4823		4823		3434	
PROC. REF: AMM 57 20 00 220 815PROC. REF: AMM 57 20 00 220 815								
57-20-00-123	DETAILED INSPECTION OF THE LOWER SKIN AT THE FRONT AND REAR SPAR JOINTS							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.230	AFL		T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 831PROC. REF: AMM 57 20 00 220 831								
57-20-00-125	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS178.00							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.235	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-20-004PROC. REF: NDT ET-57-20-004								
57-20-00-126	SPECIAL DETAILED INSPECTION OF THE WING RIB AT WS287.00							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.240	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-20-005PROC. REF: NDT ET-57-20-005								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-127	SPECIAL DETAILED INSPECTION OF THE WING RIB AT CWS464.20							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.245	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-20-006PROC. REF: NDT ET-57-20-006								
57-20-00-128	DETAILED INSPECTION OF THE WING RIB AT WS85.50							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.250	AFL		T:7500		7500		6111	
PROC. REF: AMM 57 20 00 220 832PROC. REF: AMM 57 20 00 220 832								
57-20-00-129	SPECIAL DETAILED INSPECTION OF THE LOWER SPLICE OF THE FRONTSPAR, WS275.60 AND WS549.55							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-20-011, NDT UT-57-20-001PROC. REF: NDT ET-57-20-011, NDT UT-57-20-001								
57-20-00-201	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE WING							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.255	AFL	745						
PROC. REF: AMM 57 20 00 220 801PROC. REF: AMM 57 20 00 220 801								
57-20-00-202	DETAILED INSPECTION OF THE AFT FACE OF THE FRONT SPAR OF THE WING - BL47.61 TO CWS537.40							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.260	AFL	745						
PROC. REF: AMM 57 20 00 220 802PROC. REF: AMM 57 20 00 220 802								
57-20-00-203	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR SPAR OF THE WING - BL47.61 TO CWS537.40							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.265	AFL	745						
PROC. REF: AMM 57 20 00 220 803PROC. REF: AMM 57 20 00 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-204	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR AND AUXILIARY SPAR OF THE WING							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.270	AFL	745						
PROC. REF: AMM 57 20 00 220 804PROC. REF: AMM 57 20 00 220 804								
57-20-00-205	DETAILED INSPECTION OF THE LOWER WING SURFACE COVERED BY THE FUEL ACCESS PANELS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.275	AFL	745						
PROC. REF: AMM 57 20 00 220 805PROC. REF: AMM 57 20 00 220 805								
57-20-00-206	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - BL47.61 TO CWS537.40							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.280	AFL	745						
PROC. REF: AMM 57 20 00 220 806PROC. REF: AMM 57 20 00 220 806								
57-20-00-207	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE WING - CWS537.40 TO WS536.50							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.285	AFL	745						
PROC. REF: AMM 57 20 00 220 807PROC. REF: AMM 57 20 00 220 807								
57-20-00-210	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) TRUNNION FITTING AND BAY							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.290	AFL	745						
PROC. REF: AMM 57 20 00 220 810PROC. REF: AMM 57 20 00 220 810								
57-20-00-212	DETAILED INSPECTION OF THE AILERON SUPPORT FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.295	AFL	745						
PROC. REF: AMM 57 20 00 220 812PROC. REF: AMM 57 20 00 220 812								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-20-00-213	DETAILED INSPECTION OF THE INTERNAL WING STRUCTURE BETWEEN THE REAR SPAR AND AUXILIARY SPAR, WS85.00 TO WS178.00							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26 (M)	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.300	AFL	745						
PROC. REF: AMM 57 20 00 220 821PROC. REF: AMM 57 20 00 220 821								
57-30-00-101	SPECIAL DETAILED INSPECTION OF THE WINGLET INSTALLATION							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.305	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-30-001PROC. REF: NDT ET-57-30-001								
57-30-00-102	DETAILED INSPECTION OF THE WINGLET - EXTERNAL SURFACES							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 30 00 220 804PROC. REF: AMM 57 30 00 220 804								
57-30-00-202	DETAILED INSPECTION OF THE WINGLET ATTACHMENT FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.315	AFL	745						
PROC. REF: AMM 57 30 00 220 802PROC. REF: AMM 57 30 00 220 802								
57-30-00-900-801-01	LEFT WINGLET							Component ATA:57
PN:GM178-1000-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0362	HRS	0		TSN 0				
WC#: 57.715	AFL	0		TSN 0				
PROC. REF: AMM 57 30 00 000 801, AMM 57 30 00 400 801PROC. REF: AMM 57 30 00 000 801, AMM 57 30 00 400 801								
57-30-00-900-801-02	RIGHT WINGLET							Component ATA:57
PN:GM178-1000-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0362	HRS	0		TSN 0				
WC#: 57.715	AFL	0		TSN 0				
PROC. REF: AMM 57 30 00 000 801, AMM 57 30 00 400 801PROC. REF: AMM 57 30 00 000 801, AMM 57 30 00 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-30-17-900-801-01	LH WING TIP LENS							Component ATA:57
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.720	AFL	0		TSN 0				
PROC. REF: CMM 33-42-22, AMM 57 30 17 000 801, AMM 57 30 17 400 801PROC. REF: CMM 33-42-22, AMM 57 30 17 000 801, AMM 57 30 17 400 801								
57-30-17-900-801-02	RH WING TIP LENS							Component ATA:57
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.720	AFL	0		TSN 0				
PROC. REF: CMM 33-42-22, AMM 57 30 17 000 801, AMM 57 30 17 400 801PROC. REF: CMM 33-42-22, AMM 57 30 17 000 801, AMM 57 30 17 400 801								
57-42-00-101	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TRACKS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.320	AFL	0	T:7500		7500		6111	
PROC. REF: NDT MT-57-42-002PROC. REF: NDT MT-57-42-002								
57-42-00-103	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TRACKS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.320	AFL	0	T:7500		7500		6111	
PROC. REF: NDT MT-57-42-003PROC. REF: NDT MT-57-42-003								
57-42-00-104	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TRACKS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.320	AFL	0	T:7500		7500		6111	
PROC. REF: NDT MT-57-42-004PROC. REF: NDT MT-57-42-004								
57-42-00-105	SPECIAL DETAILED INSPECTION OF THE NO. 4 SLAT TRACKS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.320	AFL	0	T:7500		7500		6111	
PROC. REF: NDT MT-57-42-005PROC. REF: NDT MT-57-42-005								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-42-00-107	SPECIAL DETAILED INSPECTION OF THE NO. 1 SLAT TO TRACK ATTACHMENTS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.325	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-42-007PROC. REF: NDT ET-57-42-007								
57-42-00-108	SPECIAL DETAILED INSPECTION OF THE NO. 2 SLAT TO TRACK ATTACHMENTS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.325	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-42-006PROC. REF: NDT ET-57-42-006								
57-42-00-109	DETAILED INSPECTION OF THE SLAT TRACK ATTACHMENT LUGS, SLAT NO.3 AND NO. 4							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.325	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 42 02 220 809PROC. REF: AMM 57 42 02 220 809								
57-42-00-111	SPECIAL DETAILED INSPECTION OF THE NO. 3 SLAT TO TRACK ATTACHMENTS							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.325	AFL		T:7500		7500		6111	
PROC. REF: NDT ET-57-42-008PROC. REF: NDT ET-57-42-008								
57-42-00-201	DETAILED INSPECTION OF THE NO.1 SLAT SUPPORT FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.330	AFL	745						
PROC. REF: AMM 57 42 00 220 801PROC. REF: AMM 57 42 00 220 801								
57-42-00-202	DETAILED INSPECTION OF THE NO. 2, NO. 3, NO. 4 SLAT SUPPORT FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.335	AFL	745						
PROC. REF: AMM 57 42 00 220 802PROC. REF: AMM 57 42 00 220 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-42-02-101	DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 1 AND NO. 2							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.340	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 42 02 220 810PROC. REF: AMM 57 42 02 220 810								
57-42-02-103	DETAILED INSPECTION OF THE SLAT BODY, SLAT NO. 3 AND NO. 4							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.340	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 42 02 220 811PROC. REF: AMM 57 42 02 220 811								
57-42-02-104	SPECIAL DETAILED INSPECTION NO. 4 SLAT BODIES INTERCONNECT PIN							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.345	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-42-004, NDT MT-57-42-006PROC. REF: NDT ET-57-42-004, NDT MT-57-42-006								
57-42-02-105	SPECIAL DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 ROLLER PINS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.350	AFL	0	T:7500		7500		6111	
PROC. REF: NDT MT-57-42-001, NDT PT-57-42-001PROC. REF: NDT MT-57-42-001, NDT PT-57-42-001								
57-42-02-106	DETAILED INSPECTION OF THE SLAT NO. 1 TO NO. 4 SUPPORT RIBS							Service ATA:57
	MOS							AIRWORTHINESS
	HRS							
WC#: 57.355	AFL		T:7500		7500		6111	
PROC. REF: AMM 57 42 02 220 812PROC. REF: AMM 57 42 02 220 812								
57-42-02-201	DETAILED INSPECTION OF THE NO.1 SLAT TRACK RAILS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.360	AFL	745						
PROC. REF: AMM 57 42 02 220 801PROC. REF: AMM 57 42 02 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-42-02-202	DETAILED INSPECTION OF THE NO. 1 SLAT RAIL SUPPORT FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.365	AFL	745						
PROC. REF: AMM 57 42 02 220 802PROC. REF: AMM 57 42 02 220 802								
57-42-02-203	DETAILED INSPECTION OF THE NO.1 SLAT BODY							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.370	AFL	745						
PROC. REF: AMM 57 42 02 220 803PROC. REF: AMM 57 42 02 220 803								
57-42-02-204	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT TRACK RAILS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.375	AFL	745						
PROC. REF: AMM 57 42 02 220 804PROC. REF: AMM 57 42 02 220 804								
57-42-02-205	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT RAIL SUPPORT FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.380	AFL	745						
PROC. REF: AMM 57 42 02 220 805PROC. REF: AMM 57 42 02 220 805								
57-42-02-206	DETAILED INSPECTION OF THE NO. 2, NO. 3 AND NO. 4 SLAT BODIES							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.385	AFL	745						
PROC. REF: AMM 57 42 02 220 806PROC. REF: AMM 57 42 02 220 806								
57-51-00-101	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS47.80							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.390	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-003, NDT MT-57-51-001PROC. REF: NDT ET-57-51-003, NDT MT-57-51-001								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-00-102	SPECIAL DETAILED INSPECTION OF THE FLAP SUPPORT STRUCTURE, WS178.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.395	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-004, NDT MT-57-51-002PROC. REF: NDT ET-57-51-004, NDT MT-57-51-002								
57-51-00-103	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS287.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.400	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-001, NDT MT-57-51-003PROC. REF: NDT ET-57-51-001, NDT MT-57-51-003								
57-51-00-104	SPECIAL DETAILED INSPECTION OF THE FLAP TRACK, WS404.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.405	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-002, NDT MT-57-51-004PROC. REF: NDT ET-57-51-002, NDT MT-57-51-004								
57-51-00-105	SPECIAL DETAILED INSPECTION OF THE FLAP CARRIAGE, WS47.80, WS178.00, WS287.00 AND WS404.00.							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.410	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-005PROC. REF: NDT ET-57-51-005								
57-51-00-106	SPECIAL DETAILED INSPECTION OF THE FLAP SIDE FITTING, WS47.80							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.415	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-006, NDT MT-57-51-006, NDT PT-57-51-006PROC. REF: NDT ET-57-51-006, NDT MT-57-51-006, NDT PT-57-51-006								
57-51-00-107	SPECIAL DETAILED INSPECTION OF THE FLAP RAIL FORWARD FITTING, WS287.00 AND WS404.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.420	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-007, NDT MT-57-51-007PROC. REF: NDT ET-57-51-007, NDT MT-57-51-007								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-00-108	SPECIAL DETAILED INSPECTION OF THE FLAP BODY FITTING (METALLIC), WS178.00, WS287.00 AND WS404.00							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.425	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-008PROC. REF: NDT ET-57-51-008								
57-51-00-109	SPECIAL DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAP (METALLIC) END RIBS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.430	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-51-009PROC. REF: NDT ET-57-51-009								
57-51-00-110	DETAILED INSPECTION OF THE INBOARD, MID AND OUTBOARD FLAPS (COMPOSITE)							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.435	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 51 00 220 802PROC. REF: AMM 57 51 00 220 802								
57-51-00-201	SPECIAL DETAILED INSPECTION OF THE INBOARD-FLAP INTERNAL RIBS AND INBOARD FITTINGS							Service ATA:57
	MOS		T:60 (+3m/-3m)		30-Aug-25 (M)	30-Nov-25	184 d (+92)	MRB
	HRS							
	AFL							
PROC. REF: AMM 57 51 00 290 801PROC. REF: AMM 57 51 00 290 801								
57-51-00-202	SPECIAL DETAILED INSPECTION OF THE MID-FLAP INTERNAL RIBS							Service ATA:57
	MOS		T:120 (+3m/-3m)		19-Dec-33	19-Mar-34	3217 d (+90)	MRB
	HRS	0						
	AFL	0						
PROC. REF: AMM 57 51 00 290 802PROC. REF: AMM 57 51 00 290 802								
57-51-00-203	SPECIAL DETAILED INSPECTION OF THE OUTBOARD-FLAP INTERNAL RIBS							Service ATA:57
	MOS		T:120 (+3m/-3m)		19-Dec-33	19-Mar-34	3217 d (+90)	MRB
	HRS	0						
	AFL	0						
PROC. REF: AMM 57 51 00 290 803PROC. REF: AMM 57 51 00 290 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-05-201	DETAILED INSPECTION OF THE FLAP TRACK RAILS - WS47.80, WS178.00, WS287.00 AND WS404.00							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.440	AFL	745						
PROC. REF: AMM 57 51 05 220 801PROC. REF: AMM 57 51 05 220 801								
57-51-05-202	DETAILED INSPECTION OF THE FLAP SUPPORT FITTINGS - WS47.80, WS178.00, WS287.00 AND WS404.00							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.445	AFL	745						
PROC. REF: AMM 57 51 05 220 817PROC. REF: AMM 57 51 05 220 817								
57-51-05-203	DETAILED INSPECTION OF THE INNER-FLAP INNER-FITTINGS AND END RIBS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.450	AFL	745						
PROC. REF: AMM 57 51 05 220 809PROC. REF: AMM 57 51 05 220 809								
57-51-05-204	DETAILED INSPECTION OF THE INNER-FLAP OUTER-FITTINGS AND THE MIDDLE-FLAP INNER-FITTINGS AND END RIBS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.455	AFL	745						
PROC. REF: AMM 57 51 05 220 810PROC. REF: AMM 57 51 05 220 810								
57-51-05-205	DETAILED INSPECTION OF THE MIDDLE-FLAP OUTER-FITTINGS AND THE OUTER-FLAP INNER-FITTINGS AND END RIBS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.460	AFL	745						
PROC. REF: AMM 57 51 05 220 811PROC. REF: AMM 57 51 05 220 811								
57-51-05-206	DETAILED INSPECTION OF THE OUTER-FLAP OUTER-FITTINGS AND END RIBS							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.465	AFL	745						
PROC. REF: AMM 57 51 05 220 812PROC. REF: AMM 57 51 05 220 812								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-51-05-207	DETAILED INSPECTION OF THE INNER FLAPS UPPER AND LOWER SKIN							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.470	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	
PROC. REF: AMM 57 51 05 220 813PROC. REF: AMM 57 51 05 220 813								
57-51-05-208	SPECIAL DETAILED INSPECTION OF THE INNER FLAPS TRAILING EDGE UPPER AND LOWER SKIN AND CORE							Service ATA:57
	MOS	19-Sep-22						MRB
	HRS	2696:42						
WC#: 57.475	AFL	918	950 (+50/-50)	Adj 32	1900	1950	511 (+50)	
PROC. REF: AMM 57 51 05 280 801PROC. REF: AMM 57 51 05 280 801								
57-51-05-209	DETAILED INSPECTION OF THE MIDDLE/OUTBOARD UPPER AND LOWER FLAPS SKIN							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.480	AFL	0	T:3750 (+50/-50)		3750	3800	2361 (+50)	
PROC. REF: AMM 57 51 05 220 815PROC. REF: AMM 57 51 05 220 815								
57-51-05-210	SPECIAL DETAILED INSPECTION OF THE MIDDLE/OUTER FLAP PANEL TRAILING EDGE UPPER AND LOWER SKIN AND CORE							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.485	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	
PROC. REF: AMM 57 51 05 280 802PROC. REF: AMM 57 51 05 280 802								
57-60-00-101	SPECIAL DETAILED INSPECTION OF THE AILERON CENTER-HINGE ASSEMBLY							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.490	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-60-001, NDT PT-57-60-001PROC. REF: NDT ET-57-60-001, NDT PT-57-60-001								
57-60-00-103	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE AND OUTER-HINGE ASSEMBLIES							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.495	AFL	0	T:7500		7500		6111	
PROC. REF: NDT PT-57-60-002PROC. REF: NDT PT-57-60-002								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-00-104	DETAILED INSPECTION OF THE AILERONS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.500	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 60 00 220 805PROC. REF: AMM 57 60 00 220 805								
57-60-00-105	SPECIAL DETAILED INSPECTION OF THE AILERON INNER-HINGE ANDOUTER-HINGE FITTING ASSEMBLIES							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
	AFL	0	T:7500		7500		6111	
PROC. REF: NDT ET-57-60-002PROC. REF: NDT ET-57-60-002								
57-60-00-201	DETAILED INSPECTION OF THE AILERON HINGE FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.505	AFL	745						
PROC. REF: AMM 57 60 00 220 804PROC. REF: AMM 57 60 00 220 804								
57-60-00-202	SPECIAL DETAILED INSPECTION OF THE AILERON SKIN							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.510	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	
PROC. REF: AMM 57 60 00 280 801PROC. REF: AMM 57 60 00 280 801								
57-60-00-203	DETAILED INSPECTION OF THE AILERON SPAR							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.515	AFL	0	T:7500 (+50/-50)		7500	7550	6111 (+50)	
PROC. REF: AMM 57 60 00 220 803PROC. REF: AMM 57 60 00 220 803								
57-60-00-900-801-01	LEFT AILERON							Component ATA:57
PN:GM158-1000-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0366	HRS	0		TSN 0				
WC#: 57.730	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-00-900-801-02	RIGHT AILERON							Component ATA:57
PN:GM158-1000-6	MOS/MSC	05-Feb-21	O/C	TSR 0				
SN:0365	HRS	2444:24		TSR 0				
WC#: 57.730	AFL	745		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-70-00-101	SPECIAL DETAILED INSPECTION OF THE SPOILERS (NO. 1 TO NO. 6) HINGE FITTINGS							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.520	AFL	0	T:3066		3066		1677	
PROC. REF: NDT ET-57-70-001, NDT PT-57-70-001PROC. REF: NDT ET-57-70-001, NDT PT-57-70-001								
57-70-00-102	DETAILED INSPECTION OF THE SPOILERS NO. 1 TO NO. 6							Service ATA:57
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 57.525	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 57 70 00 220 801PROC. REF: AMM 57 70 00 220 801								
57-71-00-201	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.530	AFL	745						
PROC. REF: AMM 57 71 00 220 803PROC. REF: AMM 57 71 00 220 803								
57-71-00-202	DETAILED INSPECTION OF THE GROUND-SPOILER SUPPORT-FITTINGS - BL47.61AND WS178.00							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.535	AFL	745						
PROC. REF: AMM 57 71 00 220 801PROC. REF: AMM 57 71 00 220 801								
57-71-00-203	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER SKIN							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.540	AFL	0	T:3750 (+50/-50)		3750	3800	2361 (+50)	
PROC. REF: AMM 57 71 00 280 801PROC. REF: AMM 57 71 00 280 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-71-00-900-801-01	GROUND OUTBOARD LH SPOILER							Component ATA:57
PN:GM168-1200-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0361	HRS	0		TSN 0				
WC#: 57.735	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-71-00-900-801-02	GROUND INBOARD LH SPOILER							Component ATA:57
PN:GM168-1100-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0363	HRS	0		TSN 0				
WC#: 57.735	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-71-00-900-801-03	GROUND INBOARD RH SPOILER							Component ATA:57
PN:GM168-1100-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0363	HRS	0		TSN 0				
WC#: 57.735	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-71-00-900-801-04	GROUND OUTBOARD RH SPOILER							Component ATA:57
PN:GM168-1200-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0363	HRS	0		TSN 0				
WC#: 57.735	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-72-00-201	DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SUPPORT-FITTINGS							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)	05-Feb-31	05-May-31	2169 d (+89)	MRB	
	HRS	2444:24						
WC#: 57.545	AFL	745						
PROC. REF: AMM 57 72 00 220 801PROC. REF: AMM 57 72 00 220 801								
57-72-00-202	DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER HINGE FITTINGS - WS178.00 AND WS404.00							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)	05-Feb-31	05-May-31	2169 d (+89)	MRB	
	HRS	2444:24						
WC#: 57.550	AFL	745						
PROC. REF: AMM 57 72 00 220 803PROC. REF: AMM 57 72 00 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-72-00-203	SPECIAL DETAILED INSPECTION OF THE MULTI-FUNCTION SPOILER SKIN - WS178.00 AND WS404.00							Service ATA:57
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 57.555	AFL	0	T:3750 (+50/-50)		3750	3800	2361 (+50)	
PROC. REF: AMM 57 72 00 280 801PROC. REF: AMM 57 72 00 280 801								
57-72-00-900-801-01	OUTBOARD LEFT SPOILERON							Component ATA:57
PN:GM168-1800-31	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0363	HRS	0		TSN 0				
WC#: 57.740	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-72-00-900-801-02	INBOARD LEFT SPOILERON							Component ATA:57
PN:GM168-1700-31	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0362	HRS	0		TSN 0				
WC#: 57.740	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-72-00-900-801-03	INBOARD RIGHT SPOILERON							Component ATA:57
PN:GM168-1700-32	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0361	HRS	0		TSN 0				
WC#: 57.745	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-72-00-900-801-04	OUTBOARD RIGHT SPOILERON							Component ATA:57
PN:GM168-1800-32	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0362	HRS	0		TSN 0				
WC#: 57.745	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57-ZL-00-201	GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL LH							Service ATA:57
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 57.560	AFL	999						
PROC. REF: AMM 57 40 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 57 40 00 210 802, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-ZL-00-202	GENERAL VISUAL INSPECTION OF THE WING LEADING EDGE SLATS - EXTERNAL RH							Service ATA:57
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 57.565	AFL	999						
PROC. REF: AMM 57 40 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 57 40 00 210 802, SPM 20-70-00-210-801								
57-ZL-00-203	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL LH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.570	AFL	745						
PROC. REF: AMM 57 40 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00PROC. REF: AMM 57 40 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00								
57-ZL-00-204	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AND SLATS - INTERNAL RH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.575	AFL	745						
PROC. REF: AMM 57 40 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00PROC. REF: AMM 57 40 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801, SPM 51-25-00-110-802, SPM 51-25-00-110-803, SPM WM-20-12-00								
57-ZL-00-205	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL LH							Service ATA:57
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 57.580	AFL	999						
PROC. REF: AMM 57 20 00 210 804, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 804, SPM 20-70-00-210-801								
57-ZL-00-206	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS47.60 AND WS178.00 - EXTERNAL RH							Service ATA:57
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 57.585	AFL	999						
PROC. REF: AMM 57 20 00 210 804, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 804, SPM 20-70-00-210-801								
57-ZL-00-207	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL LH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.590	AFL	745						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57 20 00 210 805, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 805, SPM 20-70-00-210-801								
57-ZL-00-208	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX - INTERNAL RH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.595	AFL	745						
PROC. REF: AMM 57 20 00 210 805, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 805, SPM 20-70-00-210-801								
57-ZL-00-209	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL LH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.600	AFL	745						
PROC. REF: AMM 57 20 00 210 815, SPM 20-70-00-210-801, SPM 51-23-00-390-821PROC. REF: AMM 57 20 00 210 815, SPM 20-70-00-210-801, SPM 51-23-00-390-821								
57-ZL-00-210	GENERAL VISUAL INSPECTION OF THE INBOARD WING BOX BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN WS85.50 AND WS178.00 - INTERNAL RH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.605	AFL	745						
PROC. REF: AMM 57 20 00 210 815, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 815, SPM 20-70-00-210-801								
57-ZL-00-211	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL LH							Service ATA:57
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 57.610	AFL	747						
PROC. REF: AMM 57 20 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 806, SPM 20-70-00-210-801								
57-ZL-00-212	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS178.00 AND WS287.00 - EXTERNAL RH							Service ATA:57
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 57.615	AFL	747						
PROC. REF: AMM 57 20 00 210 806, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 806, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-ZL-00-213	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL LH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.620	AFL	745						
PROC. REF: AMM 57 20 00 210 807, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 807, SPM 20-70-00-210-801								
57-ZL-00-214	GENERAL VISUAL INSPECTION OF THE MID-WING BOX - INTERNAL RH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.625	AFL	745						
PROC. REF: AMM 57 20 00 210 807, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 807, SPM 20-70-00-210-801								
57-ZL-00-215	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL LH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.630	AFL	745						
PROC. REF: AMM 57 20 00 210 808, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 808, SPM 20-70-00-210-801								
57-ZL-00-216	GENERAL VISUAL INSPECTION OF THE WING BETWEEN WS287.00 AND WS544.00 - EXTERNAL RH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.635	AFL	745						
PROC. REF: AMM 57 20 00 210 808, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 808, SPM 20-70-00-210-801								
57-ZL-00-217	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL LH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.640	AFL	745						
PROC. REF: AMM 57 20 00 210 809, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 809, SPM 20-70-00-210-801								
57-ZL-00-218	GENERAL VISUAL INSPECTION OF THE OUTBOARD WING BOX - INTERNAL RH							Service ATA:57
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 57.645	AFL	745						
PROC. REF: AMM 57 20 00 210 809, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 809, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-ZL-00-219	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL LH							Service ATA:57
	MOS	17-May-22						MRB
	HRS	2534:36						
WC#: 57.650	AFL	798	900 (+50/-50)		1698	1748	309 (+50)	
PROC. REF: AMM 57 20 00 210 810, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 810, SPM 20-70-00-210-801								
57-ZL-00-220	GENERAL VISUAL INSPECTION OF THE INBOARD WING BETWEEN THE AUXILIARY SPAR AND THE REAR SPAR, BETWEEN BL47.60 AND WS85.50 - INTERNAL RH							Service ATA:57
	MOS	17-May-22						MRB
	HRS	2534:36						
WC#: 57.655	AFL	798	900 (+50/-50)		1698	1748	309 (+50)	
PROC. REF: AMM 57 20 00 210 810, SPM 20-70-00-210-801PROC. REF: AMM 57 20 00 210 810, SPM 20-70-00-210-801								
57-ZL-00-221	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL LH							Service ATA:57
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 57.660	AFL	747						
PROC. REF: AMM 57 30 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 57 30 00 210 801, SPM 20-70-00-210-801								
57-ZL-00-222	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL RH							Service ATA:57
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRB
	HRS	2446:06						
WC#: 57.665	AFL	747						
PROC. REF: AMM 57 30 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 57 30 00 210 801, SPM 20-70-00-210-801								
57-ZL-00-223	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL LH							Service ATA:57
	MOS	21-Jul-21						MRB
	HRS	2446:06						
WC#: 57.670	AFL	747	1800 (+50/-50)	Adj 50	2597	2647	1208 (+50)	
PROC. REF: AMM 57 51 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 57 51 00 210 801, SPM 20-70-00-210-801								
57-ZL-00-224	GENERAL VISUAL INSPECTION OF THE INBOARD FLAPS - EXTERNAL RH							Service ATA:57
	MOS	21-Jul-21						MRB
	HRS	2446:06						
WC#: 57.675	AFL	747	1800 (+50/-50)	Adj 50	2597	2647	1208 (+50)	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57 51 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 57 51 00 210 801, SPM 20-70-00-210-801								
57-ZL-00-225	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - LH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.680	AFL	745						
PROC. REF: AMM 57 51 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 57 51 00 210 802, SPM 20-70-00-210-801								
57-ZL-00-226	GENERAL VISUAL INSPECTION OF THE INBOARD-FLAP ACTUATOR SUPPORT-FITTINGS - RH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.685	AFL	745						
PROC. REF: AMM 57 51 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 57 51 00 210 802, SPM 20-70-00-210-801								
57-ZL-00-227	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL LH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.690	AFL	745						
PROC. REF: AMM 57 00 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 57 00 00 210 801, SPM 20-70-00-210-801								
57-ZL-00-228	GENERAL VISUAL INSPECTION OF THE MIDDLE FLAPS, OUTBOARD FLAPS AND AILERONS - EXTERNAL RH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.695	AFL	745						
PROC. REF: AMM 57 00 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 57 00 00 210 801, SPM 20-70-00-210-801								
57-ZL-00-229	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - LH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.700	AFL	745						
PROC. REF: AMM 57 00 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 57 00 00 210 802, SPM 20-70-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-ZL-00-230	GENERAL VISUAL INSPECTION OF THE AILERON HINGE FITTINGS - RH							Service ATA:57
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 57.705	AFL	745						
PROC. REF: AMM 57 00 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 57 00 00 210 802, SPM 20-70-00-210-801								
ATA 71 - POWER PLANT								
71-00-00-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE ENGINE COMPONENTS ELECTRICAL CONNECTORS							Service ATA:71
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 71 00 00 220 801PROC. REF: AMM 71 00 00 220 801								
71-10-00-201	GENERAL VISUAL INSPECTION OF THE COWLS							Service ATA:71
	MOS	05-Feb-21	60 (+3m/-3m)	Adj 3	05-May-26	05-Aug-26	432 d (+92)	MRIP
	HRS	2444:24	1500 (+50/-50)		3944:24	3994:24	498:28 (+50)	
WC#: 71.005	AFL	745						
PROC. REF: AMM 71 10 00 210 801PROC. REF: AMM 71 10 00 210 801								
71-10-00-202	GENERAL VISUAL INSPECTION OF THE COWL DOOR SEALS							Service ATA:71
	MOS	21-Jul-21	60 (+3m/-3m)	Adj 3	21-Oct-26	21-Jan-27	601 d (+92)	MRIP
	HRS	2446:06	1500 (+50/-50)		3946:06	3996:06	500:10 (+50)	
WC#: 71.010	AFL	747						
PROC. REF: AMM 71 10 00 210 802PROC. REF: AMM 71 10 00 210 802								
71-11-01-201	DETAILED INSPECTION INLET- COWL AERODYNAMIC SURFACES							Service ATA:71
	MOS	19-Sep-22	60 (+3m/-3m)	Adj 9d	28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2696:42	3000 (+50/-50)	Adj 50	5746:42	5796:42	2300:46 (+50)	
WC#: 71.015	AFL	918						
PROC. REF: AMM 71 11 01 220 802PROC. REF: AMM 71 11 01 220 802								
71-11-01-202	DETAILED INSPECTION OF THE INLET-COWL FASTENERS AND ATTACHMENT RING							Service ATA:71
	MOS	19-Sep-22	60 (+3m/-3m)	Adj 9d	28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2696:42	3000 (+50/-50)	Adj 50	5746:42	5796:42	2300:46 (+50)	
WC#: 71.020	AFL	918						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 11 01 220 803PROC. REF: AMM 71 11 01 220 803								
71-11-01-203	GENERAL VISUAL INSPECTION OF THE INLET-COWL REAR-BULKHEAD FIREWALL-MATERIAL (EXTERNAL SURFACES)							Service ATA:71
	MOS	19-Sep-22	60 (+3m/-3m)	Adj 9d	28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2696:42	3000 (+50/-50)	Adj 50	5746:42	5796:42	2300:46 (+50)	
WC#: 71.025	AFL	918						
PROC. REF: AMM 71 11 01 210 802PROC. REF: AMM 71 11 01 210 802								
71-11-01-900-801-01	LH ENGINE NOSE COWL							Component ATA:71
PN:07C0001-005	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E349	HRS	0		TSN 0				
WC#: 71.115	AFL	0		TSN 0				
PROC. REF: AMM 71 11 01 000 801, AMM 71 11 01 400 801PROC. REF: AMM 71 11 01 000 801, AMM 71 11 01 400 801								
71-11-01-900-801-02	RH ENGINE NOSE COWL							Component ATA:71
PN:07C0001-006	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E395	HRS	0		TSN 0				
WC#: 71.115	AFL	0		TSN 0				
PROC. REF: AMM 71 11 01 000 801, AMM 71 11 01 400 801PROC. REF: AMM 71 11 01 000 801, AMM 71 11 01 400 801								
71-12-01-101	DETAILED INSPECTION OF THE UPPER FAN-COWL-DOOR							Service ATA:71
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 71.030	AFL	0	T:7500		7500		6111	
PROC. REF: AMM 71 12 01 220 801PROC. REF: AMM 71 12 01 220 801								
71-12-01-201	DETAILED INSPECTION OF THE UPPER COWLS							Service ATA:71
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 71.035	AFL	745						
PROC. REF: AMM 71 12 01 220 801PROC. REF: AMM 71 12 01 220 801								
71-12-01-202	SPECIAL DETAILED INSPECTION OF THE UPPER COWLS							Service ATA:71
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 71.040	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 12 01 280 801PROC. REF: AMM 71 12 01 280 801								
71-12-01-900-801-01	LH ENGINE FAN DOOR UPPER COWL							Component ATA:71
PN:07D4001-001	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E405/SB4533	HRS	0		TSN 0				
WC#: 71.120	AFL	0		TSN 0				
PROC. REF: AMM 71 12 01 000 801, AMM 71 12 01 400 801PROC. REF: AMM 71 12 01 000 801, AMM 71 12 01 400 801								
71-12-01-900-801-02	RH ENGINE FAN DOOR UPPER COWL							Component ATA:71
PN:07D4001-002	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E348/SB3943	HRS	0		TSN 0				
WC#: 71.120	AFL	0		TSN 0				
PROC. REF: AMM 71 12 01 000 801, AMM 71 12 01 400 801PROC. REF: AMM 71 12 01 000 801, AMM 71 12 01 400 801								
71-13-01-201	FUNCTIONAL TEST OF THE LOWER-COWL PRESSURE-RELIEF DOORS							Service ATA:71
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
WC#: 71.045	AFL	999						
PROC. REF: AMM 71 13 01 720 801PROC. REF: AMM 71 13 01 720 801								
71-13-01-900-801-01	LH ENGINE FAN DOOR LOWER COWL							Component ATA:71
PN:07D4002-001	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E348/SB3944	HRS	0		TSN 0				
WC#: 71.125	AFL	0		TSN 0				
PROC. REF: AMM 71 13 01 000 801, AMM 71 13 01 400 801PROC. REF: AMM 71 13 01 000 801, AMM 71 13 01 400 801								
71-13-01-900-801-02	RH ENGINE FAN DOOR LOWER COWL							Component ATA:71
PN:07D4003-001	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E348/SB3945	HRS	0		TSN 0				
WC#: 71.125	AFL	0		TSN 0				
PROC. REF: AMM 71 13 01 000 801, AMM 71 13 01 400 801PROC. REF: AMM 71 13 01 000 801, AMM 71 13 01 400 801								
71-14-01-201	GENERAL VISUAL INSPECTION OF THE FIXED COWL SEALS							Service ATA:71
	MOS	19-Sep-22	60 (+3m/-3m)	Adj 9d	28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2696:42	3000 (+50/-50)	Adj 50	5746:42	5796:42	2300:46 (+50)	
WC#: 71.050	AFL	918						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 14 01 210 801PROC. REF: AMM 71 14 01 210 801								
71-14-01-202	DETAILED INSPECTION OF THE FIXED COWL							Service ATA:71
	MOS	19-Sep-22	60 (+3m/-3m)	Adj 9d	28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2696:42	3000 (+50/-50)	Adj 50	5746:42	5796:42	2300:46 (+50)	
WC#: 71.055	AFL	918						
PROC. REF: AMM 71 14 01 220 801PROC. REF: AMM 71 14 01 220 801								
71-14-01-900-801-01	L/H APRON ASSY							Component ATA:71
PN:07E0001-023	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E347	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-14-01-900-801-02	R/H APRON ASSY							Component ATA:71
PN:07E0001-024	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E347	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-20-00-201	DETAILED INSPECTION OF THE MOUNTS							Service ATA:71
	MOS	10-Mar-23	120 (+3m/-3m)		10-Dec-25 (M)	10-Mar-26	286 d (+90)	MRB
	HRS	2845:10						
WC#: 71.060	AFL	999						
PROC. REF: AMM 71 20 00 220 801PROC. REF: AMM 71 20 00 220 801								
71-20-00-202	DETAILED INSPECTION OF THE CASING LUGS FOR THE FRONT MOUNTS							Service ATA:71
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRB
	HRS	2444:24						
WC#: 71.065	AFL	745						
PROC. REF: AMM 71 20 00 220 802PROC. REF: AMM 71 20 00 220 802								
71-21-01-101	SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT BEAM AND LINKS							Service ATA:71
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 71.070	AFL	0	T:7500		7500		6111	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-21-01-102		SPECIAL DETAILED INSPECTION OF THE THRUST STRUT						Service ATA:71
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 71.075	AFL	0	T:7500		7500		6111	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-21-01-103		SPECIAL DETAILED INSPECTION OF THE FRONT MOUNT LINK PINS, THRUST STRUT PINS, THRUST PIN AND PYLON ATTACHMENT PINS						Service ATA:71
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 71.080	AFL	0	T:7500		7500		6111	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-21-05-900-801-01		FWD, L/H PIN						Component ATA:71
PN:BRR15809	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:196388019	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-21-05-900-801-02		FWD, R/H PIN						Component ATA:71
PN:BRR15809	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:196388026	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-21-06-900-801-01		AFT L/H PIN						Component ATA:71
PN:BRR15824	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:196387028	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-21-06-900-801-02		AFT R/H PIN						Component ATA:71
PN:BRR15824	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:196387014	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-01-101		SPECIAL DETAILED INSPECTION OF THE REAR MOUNT BEAM AND LINKS						Service ATA:71
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 71.085	AFL	0	T:7500		7500		6111	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-01-102		SPECIAL DETAILED INSPECTION OF THE REAR MOUNT LINK AND PYLON ATTACHMENT PINS						Service ATA:71
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 71.090	AFL	0	T:7500		7500		6111	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-02-900-801-01		NO. 1 MOUNT BEAM TO LINK PIN						Component ATA:71
PN:BRR15835	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBB1501	HRS	0		TSN 0				
WC#: 71.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-02-900-801-02		NO. 2 MOUNT BEAM TO LINK PIN						Component ATA:71
PN:BRR15835	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBB1504	HRS	0		TSN 0				
WC#: 71.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-02-900-801-03		NO. 3 MOUNT BEAM TO LINK PIN						Component ATA:71
PN:BRR15835	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBB1503	HRS	0		TSN 0				
WC#: 71.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-02-900-801-04		NO. 4 MOUNT BEAM TO LINK PIN						Component ATA:71
PN:BRR15835	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBB1505	HRS	0		TSN 0				
WC#: 71.150	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-03-900-801-01AFT LH UPPER MOUNT BEAM TO PYLON PIN								Component ATA:71
PN:BRR15840	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBD1540	HRS	0		TSN 0				
WC#: 71.155	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-03-900-801-02AFT LH LOWER MOUNT BEAM TO PYLON PIN								Component ATA:71
PN:BRR15840	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBD1532	HRS	0		TSN 0				
WC#: 71.155	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-03-900-801-03AFT RH UPPER MOUNT BEAM TO PYLON PIN								Component ATA:71
PN:BRR15840	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBD1546	HRS	0		TSN 0				
WC#: 71.155	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-03-900-801-04AFT RH LOWER MOUNT BEAM TO PYLON PIN								Component ATA:71
PN:BRR15840	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBD1545	HRS	0		TSN 0				
WC#: 71.155	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-07-900-801-01LINK TO MOUNT RING, L/H LOWER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBC1531	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-07-900-801-02LINK TO MOUNT RING L/H UPPER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBC1529	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-07-900-801-03 LINK TO MOUNT RING, R/H LOWER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBC1536	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-22-07-900-801-04 LINK TO MOUNT RING, R/H UPPER PIN								Component ATA:71
PN:BRR15838	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBC1535	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71-23-01-900-801-01 LEFT UPPER FRONT MOUNT LINK ASSEMBLY								Component ATA:71
PN:BRR24405	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:THEAP12673	HRS	0		TSN 0				
WC#: 71.130	AFL	0		TSN 0				
PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-801-02 RIGHT UPPER FRONT MOUNT LINK ASSEMBLY								Component ATA:71
PN:BRR24405	MOS/MSC	05-Feb-21	O/C					
SN:THEAP12675	HRS	2444:24						
WC#: 71.130	AFL	745						
PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-801-03 LEFT LOWER FRONT MOUNT LINK ASSEMBLY								Component ATA:71
PN:BRR24405	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:THEAP12676	HRS	0		TSN 0				
WC#: 71.130	AFL	0		TSN 0				
PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-801-04 RIGHT LOWER FRONT MOUNT LINK ASSEMBLY								Component ATA:71
PN:BRR24405	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:228537AABD512	HRS	2444:24		TSN 0				
WC#: 71.130	AFL	745		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-802-01	NO. 1 MOUNT TO BEAM ATTACH PIN							Component ATA:71
PN:BRR15812	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:194562040	HRS	0		TSN 0				
WC#: 71.135	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-802-02	NO. 2 MOUNT TO BEAM ATTACH PIN							Component ATA:71
PN:BRR15812	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:200340002	HRS	0		TSN 0				
WC#: 71.135	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-802-03	NO. 3 MOUNT TO BEAM ATTACH PIN							Component ATA:71
PN:BRR15812	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:200340003	HRS	0		TSN 0				
WC#: 71.135	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-802-04	NO. 4 MOUNT TO BEAM ATTACH PIN							Component ATA:71
PN:BRR15812	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:200340008	HRS	0		TSN 0				
WC#: 71.135	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-803-01	FWD LH UPPER PYLON ATTACHMENT PIN							Component ATA:71
PN:BRR15805	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBA1562	HRS	0		TSN 0				
WC#: 71.140	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-803-02	FWD LH LOWER PYLON ATTACHMENT PIN							Component ATA:71
PN:BRR15805	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBA1561	HRS	0		TSN 0				
WC#: 71.140	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-803-03		FWD RH UPPER PYLON ATTACHMENT PIN					Component	ATA:71
PN:BRR15805	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBA1564	HRS	0		TSN 0				
WC#: 71.140	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-23-01-900-803-04		FWD RH LOWER PYLON ATTACHMENT PIN					Component	ATA:71
PN:BRR15805	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:KWBA1563	HRS	0		TSN 0				
WC#: 71.140	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801, AMM 71 23 01 000 801, AMM 71 23 01 400 801								
71-24-01-900-801-01		L/H BEAM REAR MOUNT ASSEMBLY					Component	ATA:71
PN:BRR24391	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BSTDK0425	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-801-02		R/H BEAM REAR MOUNT ASSEMBLY					Component	ATA:71
PN:BRR24400	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BSTDK0427	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-801-03		L/H BEAM OF REAR MOUNT ASSEMBLY					Component	ATA:71
PN:BRR24407	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BSEAP0175	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-801-04		R H BEAM OF REAR MOUNT ASSEMBLY					Component	ATA:71
PN:BRR24407	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BSEAP0184	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-802-01	LEFT UPPER REAR MOUNT LINK ASSEMBLY							Component ATA:71
PN:BRR24413	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:THEAP12305	HRS	0		TSN 0				
WC#: 71.145	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-802-02	RIGHT UPPER REAR MOUNT LINK ASSEMBLY							Component ATA:71
PN:BRR24413	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:THEAP12100	HRS	0		TSN 0				
WC#: 71.145	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-802-03	LEFT LOWER REAR MOUNT LINK ASSEMBLY							Component ATA:71
PN:BRR24413	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:THEAP12306	HRS	0		TSN 0				
WC#: 71.145	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-24-01-900-802-04	RIGHT LOWER REAR MOUNT LINK ASSEMBLY							Component ATA:71
PN:BRR24413	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:THEAP12101	HRS	0		TSN 0				
WC#: 71.145	AFL	0		TSN 0				
PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801PROC. REF: AMM 71 24 01 000 801, AMM 71 24 01 400 801								
71-ZL-00-201	GENERAL VISUAL INSPECTION OF THE NACELLE - RH							Service ATA:71
	MOS	21-Jul-21	120 (+3m/-3m)	21-Jul-31	21-Oct-31	2335 d (+92)	MRIP	
	HRS	2446:06	3000 (+50/-50)	5446:06	5496:06	2000:10 (+50)		
WC#: 71.095	AFL	747						
PROC. REF: AMM 71 00 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 71 00 00 210 802, SPM 20-70-00-210-801								
71-ZL-00-202	GENERAL VISUAL INSPECTION OF THE NACELLE - LH							Service ATA:71
	MOS	21-Jul-21	120 (+3m/-3m)	21-Jul-31	21-Oct-31	2335 d (+92)	MRIP	
	HRS	2446:06	3000 (+50/-50)	5446:06	5496:06	2000:10 (+50)		
WC#: 71.100	AFL	747						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 00 00 210 802, SPM 20-70-00-210-801PROC. REF: AMM 71 00 00 210 802, SPM 20-70-00-210-801								
71-ZL-00-203	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL LH							Service ATA:71
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRIP
	HRS	2444:24	3000 (+50/-50)		5444:24	5494:24	1998:28 (+50)	
WC#: 71.105	AFL	745						
PROC. REF: AMM 71 00 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 71 00 00 210 801, SPM 20-70-00-210-801								
71-ZL-00-204	GENERAL VISUAL INSPECTION OF THE ENGINE - INTERNAL RH							Service ATA:71
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRIP
	HRS	2444:24	3000 (+50/-50)		5444:24	5494:24	1998:28 (+50)	
WC#: 71.110	AFL	745						
PROC. REF: AMM 71 00 00 210 801, SPM 20-70-00-210-801PROC. REF: AMM 71 00 00 210 801, SPM 20-70-00-210-801								
717102-001	NO. 1 ENGINE - DRAINS EJECTOR PUMP							Component ATA:71
PN:CV41-14-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09-0407239	HRS	0		TSN 0				
WC#: 71.005	ENC	0		TSN 0				
PROC. REF: AMM 73 12 15 210 801PROC. REF: AMM 73 12 15 210 801								
717102-001	NO. 2 ENGINE - DRAINS EJECTOR PUMP							Component ATA:71
PN:CV41-14-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09-0407238	HRS	0		TSN 0				
WC#: 71.005	ENC	0		TSN 0				
PROC. REF: AMM 73 12 15 210 801PROC. REF: AMM 73 12 15 210 801								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:BR710	MOS/MSC		E/C					
SN:12833	HRS							
WC#: 71.EN1	AFL							
PROC. REF: AMM 71 00 00 000 801, AMM 71 00 00 400 801PROC. REF: AMM 71 00 00 000 801, AMM 71 00 00 400 801								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:BR710	MOS/MSC		E/C					
SN:12834	HRS							
WC#: 71.EN2	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71 00 00 000 801, AMM 71 00 00 400 801PROC. REF: AMM 71 00 00 000 801, AMM 71 00 00 400 801								
ATA 72 - ENGINE								
72-21-04-900-801-01	LH THRUST STRUT							Component ATA:72
PN:BRR17672	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:F5563	HRS	0		TSN 0				
WC#: 72.005	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-21-04-900-801-02	RH THRUST STRUT							Component ATA:72
PN:BRR15817	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:F5809	HRS	0		TSN 0				
WC#: 72.005	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-30-01-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS							Service ATA:72
	MOS	18-Feb-22	60 (+3m/-3m)		18-Feb-27 (M)	18-May-27	721 d (+89)	MRIP
	HRS	2452:23	2000 (+50/-50)	Adj 50	(4502:23) 4502:23	4552:23	1056:27 (+50)	
WC#: 72.005	ENC	754						
PROC. REF: AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 50 00 220 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801PROC. REF: AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 50 00 220 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801								
72-30-01-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP-COMPRESSOR CASE LINERS							Service ATA:72
	MOS	18-Feb-22	60 (+3m/-3m)		18-Feb-27 (M)	18-May-27	721 d (+89)	MRIP
	HRS	2452:23	2000 (+50/-50)	Adj 50	(4502:23) 4502:23	4552:23	1056:27 (+50)	
WC#: 72.005	ENC	754						
PROC. REF: AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 50 00 220 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801PROC. REF: AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801, AMM 72 50 00 220 801, AMM 72 30 01 210 801, AMM 72 30 01 210 801								
72-31-02-201	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES							Service ATA:72
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		(3444:24) 3444:24	3494:24	TOL (+48:28)	
WC#: 72.010	ENC	746						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801PROC. REF: AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801								
72-31-02-201	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR BLADES							Service ATA:72
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		(3444:24) 3444:24	3494:24	TOL (+48:28)	
WC#: 72.010	ENC	746						
PROC. REF: AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801PROC. REF: AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801, AMM 72 31 02 220 801								
72-31-02-202	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS							Service ATA:72
	MOS	18-Feb-22	60 (+3m/-3m)		18-Feb-27 (M)	18-May-27	721 d (+89)	MRIP
	HRS	2452:23	1000 (+50/-50)	Adj 34:34	(3486:57) 3486:57	3536:57	41:01 (+50)	
WC#: 72.015	ENC	754						
PROC. REF: AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802PROC. REF: AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802								
72-31-02-202	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ANNULUS FILLERS							Service ATA:72
	MOS	18-Feb-22	60 (+3m/-3m)		18-Feb-27 (M)	18-May-27	721 d (+89)	MRIP
	HRS	2452:23	1000 (+50/-50)	Adj 34:34	(3486:57) 3486:57	3536:57	41:01 (+50)	
WC#: 72.015	ENC	754						
PROC. REF: AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802PROC. REF: AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802, AMM 72 31 02 220 802								
72-31-02-203	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]							Service ATA:72
	MOS/MSC	30-Jul-09	N/A					
	HRS	0						
WC#: 72.510	ENC	0						
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-31-02-203	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (**)]							Service ATA:72
	MOS/MSC	30-Jul-09	N/A					
	HRS	0						
WC#: 72.510	ENC	0						
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								
72-31-02-203 OPT 1	NO. 1 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (***) OPTION 1]]							Service ATA:72
	MOS	30-Jul-09						
	HRS	0	4000 (+400/-400)		(4000) 4000	4400	554:04 (+400)	
WC#: 72.515	ENC	0	3000		(3000) 2999		1610	
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								
72-31-02-203 OPT 1	NO. 2 ENGINE - RESTORATION OF THE LP COMPRESSOR FAN BLADES [RR TLM - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM AND DRY FILM LUBRICANT (***) OPTION 1]]							Service ATA:72
	MOS	30-Jul-09						
	HRS	0	4000 (+400/-400)		(4000) 4000	4400	554:04 (+400)	
WC#: 72.515	ENC	0	3000		(3000) 2999		1610	
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								
72-31-02-203 OPT 2/1	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (***) OPTION 2 - FIRST REQUIREMENT)							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-31-02-203 OPT 2/1	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT DRY FILM LUBRICANT (***) OPTION 2 - FIRST REQUIREMENT)							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								
72-31-02-203 OPT 2/2	NO. 1 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (***) OPTION 2 - SECOND REQUIREMENT)							Service ATA:72
	MOS							
	HRS		8000 (+400/-400)		(8000) 8000 (M)	8400	4554:04 (+400)	
WC#: 72.525	ENC		3000		(3000) 2999 (M)		1610	
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								
72-31-02-203 OPT 2/2	NO. 2 ENGINE - REFURBISH COMPRESSOR ROTOR BLADE ROOT COPPER NICKEL INDIUM COATING (***) OPTION 2 - SECOND REQUIREMENT)							Service ATA:72
	MOS							
	HRS		8000 (+400/-400)		(8000) 8000 (M)	8400	4554:04 (+400)	
WC#: 72.525	ENC		3000		(3000) 2999 (M)		1610	
PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801PROC. REF: AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801, AMM 72 31 02 610 801								
72-31-02-301	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700-72-100981)							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							
PROC. REF: AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801PROC. REF: AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801								
72-31-02-301	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE LP-COMPRESSOR FAN-TRACK-LINER (PRE SB BR700-72-100981)							Service ATA:72
	MOS/MSC		N/A					
	HRS							
	ENC							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801PROC. REF: AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801, AMM 72 31 02 280 801								
72-32-02-201	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES							Service ATA:72
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		(3444:24) 3444:24	3494:24	TOL (+48:28)	
WC#: 72.020	ENC	746						
PROC. REF: AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801PROC. REF: AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801								
72-32-02-201	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR OUTLET GUIDE- VANES							Service ATA:72
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		(3444:24) 3444:24	3494:24	TOL (+48:28)	
WC#: 72.020	ENC	746						
PROC. REF: AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801PROC. REF: AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801, AMM 72 32 02 220 801								
72-32-02-202	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES							Service ATA:72
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		(3444:24) 3444:24	3494:24	TOL (+48:28)	
WC#: 72.025	ENC	746						
PROC. REF: AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802PROC. REF: AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802								
72-32-02-202	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP-COMPRESSOR ENGINE STATOR-VANES							Service ATA:72
	MOS	05-Feb-21	60 (+3m/-3m)		05-Feb-26	05-May-26	343 d (+89)	MRIP
	HRS	2444:24	1000 (+50/-50)		(3444:24) 3444:24	3494:24	TOL (+48:28)	
WC#: 72.025	ENC	746						
PROC. REF: AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802PROC. REF: AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802, AMM 72 32 02 220 802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

[illegible]

440 of 492



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-38-01-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTAKE ROTATING FAIRING							Service ATA:72
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	2000 (+50/-50)		(4446:06) 4446:06	4496:06	1000:10 (+50)	
WC#: 72.040	ENC	748						
PROC. REF: AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801PROC. REF: AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801, AMM 72 38 01 210 801								
72-40-00-203	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER							Service ATA:72
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)	Adj 50	(3895:10) 3895:10	3945:10	449:14 (+50)	
WC#: 72.045	ENC	1000						
PROC. REF: AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801PROC. REF: AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801								
72-40-00-203	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE COMBUSTION LINER							Service ATA:72
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)	Adj 50	(3895:10) 3895:10	3945:10	449:14 (+50)	
WC#: 72.045	ENC	1000						
PROC. REF: AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801PROC. REF: AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801, AMM 72 40 00 220 801								
72-40-00-204	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES							Service ATA:72
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)	Adj 50	(3895:10) 3895:10	3945:10	449:14 (+50)	
WC#: 72.050	ENC	1000						
PROC. REF: AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802PROC. REF: AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802								
72-40-00-204	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINES BLADES							Service ATA:72
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)	Adj 50	(3895:10) 3895:10	3945:10	449:14 (+50)	
WC#: 72.050	ENC	1000						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802PROC. REF: AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802, AMM 72 40 00 220 802								
72-40-00-205	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES							Service ATA:72
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)	Adj 50	(3895:10) 3895:10	3945:10	449:14 (+50)	
WC#: 72.055	ENC	1000						
PROC. REF: AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803PROC. REF: AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803								
72-40-00-205	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE HP TURBINE STAGE-1 NOZZLE GUIDE-VANES							Service ATA:72
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)	Adj 50	(3895:10) 3895:10	3945:10	449:14 (+50)	
WC#: 72.055	ENC	1000						
PROC. REF: AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803PROC. REF: AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803, AMM 72 40 00 220 803								
72-50-00-204	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM							Service ATA:72
	MOS	27-Feb-20	120 (+3m/-3m)		27-Feb-30	27-May-30	1826 d (+89)	MRIP
	HRS	0	5000 (+50/-50)		(5000) 5000	5050	1554:04 (+50)	
WC#: 72.520	ENC	0						
PROC. REF: AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801PROC. REF: AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801								
72-50-00-204	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY SHUTDOWN SYSTEM							Service ATA:72
	MOS	27-Feb-20	120 (+3m/-3m)		27-Feb-30	27-May-30	1826 d (+89)	MRIP
	HRS	0	5000 (+50/-50)		(5000) 5000	5050	1554:04 (+50)	
WC#: 72.520	ENC	0						
PROC. REF: AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801PROC. REF: AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801, AMM 72 50 00 280 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-50-00-205	NO. 1 ENGINE - DETAILED INSPECTION OF THE EMERGENCY SHUTDOWNSYSTEM							Service ATA:72
	MOS	27-Feb-20	120 (+3m/-3m)		27-Feb-30	27-May-30	1826 d (+89)	MRIP
	HRS	0	5000 (+50/-50)		(5000) 5000	5050	1554:04 (+50)	
	AFL	0						
	ENC	0						
PROC. REF: AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801PROC. REF: AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801								
72-50-00-205	NO. 2 ENGINE - DETAILED INSPECTION OF THE EMERGENCY SHUTDOWNSYSTEM							Service ATA:72
	MOS	27-Feb-20	120 (+3m/-3m)		27-Feb-30	27-May-30	1826 d (+89)	MRIP
	HRS	0	5000 (+50/-50)		(5000) 5000	5050	1554:04 (+50)	
	AFL	0						
	ENC	0						
PROC. REF: AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801PROC. REF: AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801, AMM 72 50 00 220 801								
72-71-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	15-Oct-24	120 (+3m/-3m)	Adj 1d	16-Oct-34	16-Jan-35	3518 d (+92)	MRIP
	HRS	3314:03	2000 (+50/-50)		(5314:03) 5314:03 (M)	5364:03	1868:07 (+50)	
WC#: 72.060	ENC	1329						
PROC. REF: AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801PROC. REF: AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801								
72-71-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	15-Oct-24	120 (+3m/-3m)	Adj 1d	16-Oct-34	16-Jan-35	3518 d (+92)	MRIP
	HRS	3314:03	2000 (+50/-50)		(5314:03) 5314:03 (M)	5364:03	1868:07 (+50)	
WC#: 72.060	ENC	1329						
PROC. REF: AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801PROC. REF: AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801, AMM 72 71 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720001-001	NO. 1 ENGINE - 31 LP COMPRESSOR FAN MODULE							Component ATA:72
PN:M31-113	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:31101867	HRS	0		TSN 0				
WC#: 72.065	ENC	0		TSN 0				
PROC. REF: EMM 72-31-01, EMM 72-31-01PROC. REF: EMM 72-31-01, EMM 72-31-01								
720001-001	NO. 2 ENGINE - 31 LP COMPRESSOR FAN MODULE							Component ATA:72
PN:M31-113	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:31101868	HRS	0		TSN 0				
WC#: 72.065	ENC	0		TSN 0				
PROC. REF: EMM 72-31-01, EMM 72-31-01PROC. REF: EMM 72-31-01, EMM 72-31-01								
720002-001	NO. 1 ENGINE - 32 INTERMEDIATE CASE MODULE							Component ATA:72
PN:M32-121	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:32121734	HRS	0		TSN 0				
WC#: 72.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720002-001	NO. 2 ENGINE - 32 INTERMEDIATE CASE MODULE							Component ATA:72
PN:M32-121	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:32121735	HRS	0		TSN 0				
WC#: 72.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720003-001	NO. 1 ENGINE - 33 HP COMPRESSOR MODULE							Component ATA:72
PN:M33-114	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:33121736	HRS	0		TSN 0				
WC#: 72.075	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720003-001	NO. 2 ENGINE - 33 HP COMPRESSOR MODULE							Component ATA:72
PN:M33-114	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:33121737	HRS	0		TSN 0				
WC#: 72.075	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720004-001	NO. 1 ENGINE - 34 LP COMPRESSOR CASE MODULE							Component ATA:72
PN:M34-110	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:34101855	HRS	0		TSN 0				
WC#: 72.080	ENC	0		TSN 0				
PROC. REF: EMM 72-31-01, EMM 72-31-01PROC. REF: EMM 72-31-01, EMM 72-31-01								
720004-001	NO. 2 ENGINE - 34 LP COMPRESSOR CASE MODULE							Component ATA:72
PN:M34-110	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:34101856	HRS	0		TSN 0				
WC#: 72.080	ENC	0		TSN 0				
PROC. REF: EMM 72-31-01, EMM 72-31-01PROC. REF: EMM 72-31-01, EMM 72-31-01								
720005-001	NO. 1 ENGINE - MODULE 41 - COMBUSTION & HP TURBINE							Component ATA:72
PN:M41-125	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:41121735	HRS	0		TSN 0				
WC#: 72.085	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720005-001	NO. 2 ENGINE - MODULE 41 - COMBUSTION & HP TURBINE							Component ATA:72
PN:M41-125	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:41121736	HRS	0		TSN 0				
WC#: 72.085	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720006-001	NO. 1 ENGINE - 51 LP TURBINE MODULE							Component ATA:72
PN:M51-111	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:51101855	HRS	0		TSN 0				
WC#: 72.090	ENC	0		TSN 0				
PROC. REF: EMM 72-31-01, EMM 72-31-01PROC. REF: EMM 72-31-01, EMM 72-31-01								
720006-001	NO. 2 ENGINE - 51 LP TURBINE MODULE							Component ATA:72
PN:M51-111	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:51101856	HRS	0		TSN 0				
WC#: 72.090	ENC	0		TSN 0				
PROC. REF: EMM 72-31-01, EMM 72-31-01PROC. REF: EMM 72-31-01, EMM 72-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720007-001	NO. 1 ENGINE - 61 ACCESSORY GEARBOX MODULE							Component ATA:72
PN:M61-204	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:61121734	HRS	0		TSN 0				
WC#: 72.095	ENC	0		TSN 0				
PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01								
720007-001	NO. 2 ENGINE - 61 ACCESSORY GEARBOX MODULE							Component ATA:72
PN:M61-204	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:61121735	HRS	0		TSN 0				
WC#: 72.095	ENC	0		TSN 0				
PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01								
723204-001	NO. 1 ENGINE - NO 3 BEARING							Component ATA:72
PN:BRR22056	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1481	HRS	0		TSN 0				
WC#: 72.360	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723204-001	NO. 2 ENGINE - NO 3 BEARING							Component ATA:72
PN:BRR22056	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1484	HRS	0		TSN 0				
WC#: 72.360	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-001	NO. 1 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6302	HRS	0		TSN 0				
WC#: 72.365	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-001	NO. 2 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6163	HRS	0		TSN 0				
WC#: 72.365	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723205-002	NO. 1 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6303	HRS	0		TSN 0				
WC#: 72.370	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-002	NO. 2 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6164	HRS	0		TSN 0				
WC#: 72.370	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-003	NO. 1 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6304	HRS	0		TSN 0				
WC#: 72.375	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-003	NO. 2 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6165	HRS	0		TSN 0				
WC#: 72.375	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-004	NO. 1 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6305	HRS	0		TSN 0				
WC#: 72.380	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723205-004	NO. 2 ENGINE - LPC TRIM BALANCE PROBE							Component ATA:72
PN:1022-1-11	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:6166	HRS	0		TSN 0				
WC#: 72.380	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723206-001	NO. 1 ENGINE - BEARING OUTER RING							Component ATA:72
PN:BRR12474	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1597	HRS	0		TSN 0				
WC#: 72.385	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723206-001	NO. 2 ENGINE - BEARING OUTER RING							Component ATA:72
PN:BRR12474	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1596	HRS	0		TSN 0				
WC#: 72.385	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723206-002	NO. 1 ENGINE - BEARING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.390	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723206-002	NO. 2 ENGINE - BEARING ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.390	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723207-001	NO. 1 ENGINE - INNER REAR BEARING							Component ATA:72
PN:BRR23643	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1428	HRS	0		TSN 0				
WC#: 72.395	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723207-001	NO. 2 ENGINE - INNER REAR BEARING							Component ATA:72
PN:BRR23643	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1514	HRS	0		TSN 0				
WC#: 72.395	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723208-001	NO. 1 ENGINE - FRONT LPC BEARING							Component ATA:72
PN:BRR24148	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1485	HRS	0		TSN 0				
WC#: 72.400	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723208-001	NO. 2 ENGINE - FRONT LPC BEARING							Component ATA:72
PN:BRR24148	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1525	HRS	0		TSN 0				
WC#: 72.400	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723303-001	NO. 1 ENGINE - ASSEMBLY OF HPC NOZZLE							Component ATA:72
PN:FW32678	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1153	HRS	0		TSN 0				
WC#: 72.415	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723303-001	NO. 2 ENGINE - ASSEMBLY OF HPC NOZZLE							Component ATA:72
PN:FW32678	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1145	HRS	0		TSN 0				
WC#: 72.415	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723802-001	NO. 1 ENGINE - NOSE CONE ASSEMBLY							Component ATA:72
PN:BRR24229	MOS/MSC	05-Feb-21	O/C	TSN 0				
SN:20833513126489	HRS	2444:24		TSN 0				
WC#: 72.425	AFL			TSN 0				
	ENC	746						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723802-001	NO. 2 ENGINE - NOSE CONE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.425	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725123-001	NO. 1 ENGINE - STUB SHAFT ASSEMBLY							Component ATA:72
PN:BRR40703	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1428	HRS	0		TSN 0				
WC#: 72.480	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725123-001	NO. 2 ENGINE - STUB SHAFT ASSEMBLY							Component ATA:72
PN:BRR40703	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1420	HRS	0		TSN 0				
WC#: 72.480	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725613-001	NO. 1 ENGINE - REAR MOUNT RING							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.490	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725613-001	NO. 2 ENGINE - REAR MOUNT RING							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.490	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726100-001	NO. 1 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:39600221	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5158	HRS	0		TSN 0				
WC#: 72.495	ENC	0		TSN 0				
PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01								
726100-001	NO. 2 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:39600221	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5151	HRS	0		TSN 0				
WC#: 72.495	ENC	0		TSN 0				
PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01PROC. REF: EMM 72-61-01, EMM 72-61-01, EMM 72-61-01, EMM 72-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726102-001	NO. 1 ENGINE - GRAVITY OIL FILLER							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.500	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726102-001	NO. 2 ENGINE - GRAVITY OIL FILLER							Component ATA:72
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.500	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ELJ 720010 ^U	CARRY OUT ECTM DOWNLOAD							Service ATA:72
	DAYS	27-Feb-25	30		27-Mar-25 (M)		28 d	CUSTOMER CODE
	HRS	3445:56						
	AFL	1389						
ATA 73 - ENGINE FUEL AND CONTROL								
73-00-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS							Service ATA:73
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		(3446:06) 3446:06	3496:06	0:10 (+50)	
WC#: 73.005	ENC	748						
PROC. REF: AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801PROC. REF: AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801								
73-00-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL SYSTEM COMPONENTS							Service ATA:73
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		(3446:06) 3446:06	3496:06	0:10 (+50)	
WC#: 73.005	ENC	748						
PROC. REF: AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801PROC. REF: AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801, AMM 73 00 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-12-01-201	NO. 1 ENGINE - DISCARD THE LP FUEL FILTER							Service ATA:73
	MOS	10-Mar-23						MRIP
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 73.010	ENC	1000						
PROC. REF: AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801PROC. REF: AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801								
73-12-01-201	NO. 2 ENGINE - DISCARD THE LP FUEL FILTER							Service ATA:73
	MOS	10-Mar-23						MRIP
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 73.010	ENC	1000						
PROC. REF: AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801PROC. REF: AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801, AMM 73 12 01 961 801								
73-21-05-201	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE T20/P20 SENSORS CONNECTORS							Service ATA:73
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 73 21 05 220 801PROC. REF: AMM 73 21 05 220 801								
731101-001	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:828200-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1772	HRS	0		TSN 0				
WC#: 73.030	ENC	0		TSN 0				
PROC. REF: EMM 73-11-01, EMM 73-11-01PROC. REF: EMM 73-11-01, EMM 73-11-01								
731101-001	NO. 2 ENGINE - FUEL PUMP							Component ATA:73
PN:828200-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1774	HRS	0		TSN 0				
WC#: 73.030	ENC	0		TSN 0				
PROC. REF: EMM 73-11-01, EMM 73-11-01PROC. REF: EMM 73-11-01, EMM 73-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731102-001	NO. 1 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR							Component ATA:73
PN:0154HY	MOS/MSC	20-Jun-12	O/C	TSN 6				
SN:N9339	HRS	739:20		TSN 0				
WC#: 73.185	ENC	241		TSN 0				
731102-001	NO. 2 ENGINE - INLET COWL PROBE / TAT (P20/T20) SENSOR							Component ATA:73
PN:0154HY	MOS/MSC	01-Jun-12	O/C					
SN:N0009	HRS	720:18						
WC#: 73.185	ENC	235						
731201-001	NO. 1 ENGINE - TUBE ASSY							Component ATA:73
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.035	ENC	0		TSN 0				
PROC. REF: EMM 73-11-01, EMM 73-11-01PROC. REF: EMM 73-11-01, EMM 73-11-01								
731201-001	NO. 2 ENGINE - TUBE ASSY							Component ATA:73
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.035	ENC	0		TSN 0				
PROC. REF: EMM 73-11-01, EMM 73-11-01PROC. REF: EMM 73-11-01, EMM 73-11-01								
731301-001	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30589	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-001	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31744	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-002	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30590	HRS	0		TSN 0				
WC#: 73.045	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-002	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31745	HRS	0		TSN 0				
WC#: 73.045	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-003	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30591	HRS	0		TSN 0				
WC#: 73.050	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-003	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31746	HRS	0		TSN 0				
WC#: 73.050	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-004	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30592	HRS	0		TSN 0				
WC#: 73.055	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-004	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31747	HRS	0		TSN 0				
WC#: 73.055	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-005	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30593	HRS	0		TSN 0				
WC#: 73.060	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-005	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31748	HRS	0		TSN 0				
WC#: 73.060	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-006	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30594	HRS	0		TSN 0				
WC#: 73.065	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-006	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31749	HRS	0		TSN 0				
WC#: 73.065	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-007	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30595	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-007	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31750	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-008	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30596	HRS	0		TSN 0				
WC#: 73.075	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-008	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31751	HRS	0		TSN 0				
WC#: 73.075	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-009	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30597	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-009	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31752	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-010	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30598	HRS	0		TSN 0				
WC#: 73.085	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-010	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31753	HRS	0		TSN 0				
WC#: 73.085	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-011	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30599	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-011	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31754	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-012	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30600	HRS	0		TSN 0				
WC#: 73.095	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-012	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31755	HRS	0		TSN 0				
WC#: 73.095	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-013	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30601	HRS	0		TSN 0				
WC#: 73.100	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-013	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31756	HRS	0		TSN 0				
WC#: 73.100	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-014	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30602	HRS	0		TSN 0				
WC#: 73.105	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-014	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31757	HRS	0		TSN 0				
WC#: 73.105	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-015	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30603	HRS	0		TSN 0				
WC#: 73.110	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-015	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31758	HRS	0		TSN 0				
WC#: 73.110	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-016	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30604	HRS	0		TSN 0				
WC#: 73.115	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-016	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31759	HRS	0		TSN 0				
WC#: 73.115	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-017	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30605	HRS	0		TSN 0				
WC#: 73.120	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-017	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31760	HRS	0		TSN 0				
WC#: 73.120	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-018	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30606	HRS	0		TSN 0				
WC#: 73.125	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-018	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31761	HRS	0		TSN 0				
WC#: 73.125	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-019	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30607	HRS	0		TSN 0				
WC#: 73.130	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-019	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31762	HRS	0		TSN 0				
WC#: 73.130	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731301-020	NO. 1 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N30608	HRS	0		TSN 0				
WC#: 73.135	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731301-020	NO. 2 ENGINE - FUEL BURNER							Component ATA:73
PN:6940426E14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:N31763	HRS	0		TSN 0				
WC#: 73.135	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731302-001	NO. 1 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD							Component ATA:73
PN:8910-214	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:15892789	HRS	0		TSN 0				
WC#: 73.140	ENC	0		TSN 0				
PROC. REF: EMM 73-13-02, EMM 73-13-02PROC. REF: EMM 73-13-02, EMM 73-13-02								
731302-001	NO. 2 ENGINE - SPLITTER & OVERSPEED UNIT MANIFOLD							Component ATA:73
PN:8910-214	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16526539	HRS	0		TSN 0				
WC#: 73.140	ENC	0		TSN 0				
PROC. REF: EMM 73-13-02, EMM 73-13-02PROC. REF: EMM 73-13-02, EMM 73-13-02								
731303-001	NO. 1 ENGINE - FUEL RETURN TANK TRANSFERS VALVE							Component ATA:73
PN:8910-312	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16531937	HRS	0		TSN 0				
WC#: 73.145	ENC	0		TSN 0				
PROC. REF: EMM 73-14-01, EMM 73-14-01PROC. REF: EMM 73-14-01, EMM 73-14-01								
731303-001	NO. 2 ENGINE - FUEL RETURN TANK TRANSFERS VALVE							Component ATA:73
PN:8910-312	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16375329	HRS	0		TSN 0				
WC#: 73.145	ENC	0		TSN 0				
PROC. REF: EMM 73-14-01, EMM 73-14-01PROC. REF: EMM 73-14-01, EMM 73-14-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732101-001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC							Component ATA:73
PN:EECU1000-01AC	MOS/MSC	22-Apr-15	O/C					
SN:BX960011	HRS	1657:57						
WC#: 73.150	ENC	515						
PROC. REF: EMM 73-21-01, EMM 73-21-01, EMM 73-21-01, EMM 73-21-01PROC. REF: EMM 73-21-01, EMM 73-21-01, EMM 73-21-01, EMM 73-21-01								
732101-001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROLLER EEC							Component ATA:73
PN:EECU1000-01AB	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:BX960240	HRS	0		TSN 0				
WC#: 73.150	ENC	0		TSN 0				
PROC. REF: EMM 73-21-01, EMM 73-21-01, EMM 73-21-01, EMM 73-21-01PROC. REF: EMM 73-21-01, EMM 73-21-01, EMM 73-21-01, EMM 73-21-01								
732101-002 ^U	NO. 1 ENGINE - EEC FIRE BOX COVER							Component ATA:73
PN:KH73771	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-002 ^U	NO. 2 ENGINE - EEC FIRE BOX COVER							Component ATA:73
PN:KH73771	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-003 ^U	NO. 1 ENGINE - EEC FIRE BOX BASE							Component ATA:73
PN:KH73770	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-003 ^U	NO. 2 ENGINE - EEC FIRE BOX BASE							Component ATA:73
PN:KH73770	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732101-004 ^U	NO. 1 ENGINE - EEC PORT SHIELD							Component ATA:73
PN:KH73768	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-004 ^U	NO. 2 ENGINE - EEC PORT SHIELD							Component ATA:73
PN:KH73768	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-005 ^U	NO. 1 ENGINE - EEC STARBOARD SHIELD							Component ATA:73
PN:KH73769	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-005 ^U	NO. 2 ENGINE - EEC STARBOARD SHIELD							Component ATA:73
PN:KH73769	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-006 ^U	NO. 1 ENGINE - EEC COVER PLATE							Component ATA:73
PN:KH73772	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						
732101-006 ^U	NO. 2 ENGINE - EEC COVER PLATE							Component ATA:73
PN:KH73772	MOS/MSC	05-Apr-18	O/C					
SN:UNKNOWN	HRS	2282:35						
	ENC	689						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732102-001	NO. 1 ENGINE - FUEL UNIT METER							Component ATA:73
PN:8061-977	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16471759	HRS	0		TSN 0				
WC#: 73.155	ENC	0		TSN 0				
PROC. REF: EMM 73-21-03, EMM 73-21-03PROC. REF: EMM 73-21-03, EMM 73-21-03								
732102-001	NO. 2 ENGINE - FUEL UNIT METER							Component ATA:73
PN:8061-977	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16467706	HRS	0		TSN 0				
WC#: 73.155	ENC	0		TSN 0				
PROC. REF: EMM 73-21-03, EMM 73-21-03PROC. REF: EMM 73-21-03, EMM 73-21-03								
732103-001	NO. 1 ENGINE - DEDICATED GENERATOR ROTOR							Component ATA:73
PN:83311-430242	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5310	HRS	0		TSN 0				
WC#: 73.160	ENC	0		TSN 0				
PROC. REF: EMM 73-21-04, EMM 73-21-04PROC. REF: EMM 73-21-04, EMM 73-21-04								
732103-001	NO. 2 ENGINE - DEDICATED GENERATOR ROTOR							Component ATA:73
PN:83311-430242	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5312	HRS	0		TSN 0				
WC#: 73.160	ENC	0		TSN 0				
PROC. REF: EMM 73-21-04, EMM 73-21-04PROC. REF: EMM 73-21-04, EMM 73-21-04								
732104-001	NO. 1 ENGINE - DEDICATED GENERATOR STATOR							Component ATA:73
PN:514842-1	MOS/MSC	25-Jul-23	O/C	TSN 0				
SN:N22430019	HRS	2956:23		TSN 0				
WC#: 73.165	ENC	1072		TSN 0				
PROC. REF: EMM 73-21-04, EMM 73-21-04PROC. REF: EMM 73-21-04, EMM 73-21-04								
732104-001	NO. 2 ENGINE - DEDICATED GENERATOR STATOR							Component ATA:73
PN:83311-430117	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:5298	HRS	0		TSN 0				
WC#: 73.165	ENC	0		TSN 0				
PROC. REF: EMM 73-21-04, EMM 73-21-04PROC. REF: EMM 73-21-04, EMM 73-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732104-002	NO. 1 ENGINE - DATA ENTRY PLUG							Component ATA:73
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.170	ENC	0		TSN 0				
PROC. REF: EMM 73-21-02, EMM 73-21-02PROC. REF: EMM 73-21-02, EMM 73-21-02								
732104-002	NO. 2 ENGINE - DATA ENTRY PLUG							Component ATA:73
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.170	ENC	0		TSN 0				
PROC. REF: EMM 73-21-02, EMM 73-21-02PROC. REF: EMM 73-21-02, EMM 73-21-02								
732105-001	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE							Component ATA:73
PN:TC428-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAD2544	HRS	0		TSN 0				
WC#: 73.175	ENC	0		TSN 0				
PROC. REF: EMM 73-21-07, EMM 73-21-07PROC. REF: EMM 73-21-07, EMM 73-21-07								
732105-001	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE							Component ATA:73
PN:TC428-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAD2525	HRS	0		TSN 0				
WC#: 73.175	ENC	0		TSN 0				
PROC. REF: EMM 73-21-07, EMM 73-21-07PROC. REF: EMM 73-21-07, EMM 73-21-07								
732105-002	NO. 1 ENGINE - T30 THERMOCOUPLE PROBE							Component ATA:73
PN:TC428-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAD2226	HRS	0		TSN 0				
WC#: 73.180	ENC	0		TSN 0				
PROC. REF: EMM 73-21-07, EMM 73-21-07PROC. REF: EMM 73-21-07, EMM 73-21-07								
732105-002	NO. 2 ENGINE - T30 THERMOCOUPLE PROBE							Component ATA:73
PN:TC428-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAD2556	HRS	0		TSN 0				
WC#: 73.180	ENC	0		TSN 0				
PROC. REF: EMM 73-21-07, EMM 73-21-07PROC. REF: EMM 73-21-07, EMM 73-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733101-001	NO. 1 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-217-49	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:170436-623	HRS	0		TSN 0				
WC#: 73.190	ENC	0		TSN 0				
PROC. REF: EMM 73-31-01, EMM 73-31-01PROC. REF: EMM 73-31-01, EMM 73-31-01								
733101-001	NO. 2 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-217-49	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:170436-621	HRS	0		TSN 0				
WC#: 73.190	ENC	0		TSN 0				
PROC. REF: EMM 73-31-01, EMM 73-31-01PROC. REF: EMM 73-31-01, EMM 73-31-01								
733303-001	NO. 1 ENGINE - FUEL LOW PRESSURE SWITCH							Component ATA:73
PN:21SN04-433	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K010803	HRS	0		TSN 0				
WC#: 73.195	ENC	0		TSN 0				
PROC. REF: EMM 73-33-01, EMM 73-33-01, EMM 73-33-01, EMM 73-33-01PROC. REF: EMM 73-33-01, EMM 73-33-01, EMM 73-33-01, EMM 73-33-01								
733303-001	NO. 2 ENGINE - FUEL LOW PRESSURE SWITCH							Component ATA:73
PN:21SN04-433	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K010802	HRS	0		TSN 0				
WC#: 73.195	ENC	0		TSN 0				
PROC. REF: EMM 73-33-01, EMM 73-33-01, EMM 73-33-01, EMM 73-33-01PROC. REF: EMM 73-33-01, EMM 73-33-01, EMM 73-33-01, EMM 73-33-01								
733401-001	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH							Component ATA:73
PN:21SN04-430	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K008364	HRS	0		TSN 0				
WC#: 73.200	ENC	0		TSN 0				
PROC. REF: EMM 73-34-01, EMM 73-34-01PROC. REF: EMM 73-34-01, EMM 73-34-01								
733401-001	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESS SWITCH							Component ATA:73
PN:21SN04-430	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K008361	HRS	0		TSN 0				
WC#: 73.200	ENC	0		TSN 0				
PROC. REF: EMM 73-34-01, EMM 73-34-01PROC. REF: EMM 73-34-01, EMM 73-34-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-30-01-201 ^U	NO. 1 ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH							Service ATA:74
	MOS	15-Oct-24	30 (+3m/-3m)		15-Apr-27 (M)	15-Jul-27	777 d (+91)	MRIP
	HRS	3314:03	500		(3814:03) 3814:03		368:07	
WC#: 74.005	ENC	1329						
74-30-01-201 ^U	NO. 2 ENGINE - OPERATIONAL TEST OF THE IGNITION SWITCH							Service ATA:74
	MOS	15-Oct-24	30 (+3m/-3m)		15-Apr-27 (M)	15-Jul-27	777 d (+91)	MRIP
	HRS	3314:03	500		(3814:03) 3814:03		368:07	
WC#: 74.005	ENC	1329						
741001-001	NO. 1 ENGINE - EXCITER UNIT IGNITION							Component ATA:74
PN:9060440-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:04484728	HRS	0		TSN 0				
WC#: 74.010	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01, EMM 74-10-01PROC. REF: EMM 74-10-01, EMM 74-10-01								
741001-001	NO. 2 ENGINE - EXCITER UNIT IGNITION							Component ATA:74
PN:9060440-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09118373	HRS	0		TSN 0				
WC#: 74.010	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01, EMM 74-10-01PROC. REF: EMM 74-10-01, EMM 74-10-01								
741001-002	NO. 1 ENGINE - EXCITER UNIT IGNITION							Component ATA:74
PN:9060440-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:08524972	HRS	0		TSN 0				
WC#: 74.015	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01, EMM 74-10-01PROC. REF: EMM 74-10-01, EMM 74-10-01								
741001-002	NO. 2 ENGINE - EXCITER UNIT IGNITION							Component ATA:74
PN:9060440-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:09118379	HRS	0		TSN 0				
WC#: 74.015	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01, EMM 74-10-01PROC. REF: EMM 74-10-01, EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742001-001	NO. 1 ENGINE - LH IGNITOR PLUG							Component ATA:74
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.020	ENC	0		TSN 0				
PROC. REF: EMM 74-20-02, EMM 74-20-02PROC. REF: EMM 74-20-02, EMM 74-20-02								
742001-001	NO. 2 ENGINE - LH IGNITOR PLUG							Component ATA:74
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.020	ENC	0		TSN 0				
PROC. REF: EMM 74-20-02, EMM 74-20-02PROC. REF: EMM 74-20-02, EMM 74-20-02								
742001-002	NO. 1 ENGINE - RH IGNITOR PLUG							Component ATA:74
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.025	ENC	0		TSN 0				
PROC. REF: EMM 74-20-02, EMM 74-20-02PROC. REF: EMM 74-20-02, EMM 74-20-02								
742001-002	NO. 2 ENGINE - RH IGNITOR PLUG							Component ATA:74
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.025	ENC	0		TSN 0				
PROC. REF: EMM 74-20-02, EMM 74-20-02PROC. REF: EMM 74-20-02, EMM 74-20-02								
ATA 75 - AIR								
752201-001	NO. 1 ENGINE - AIR BUFFER VALVE							Component ATA:75
PN:8910-512	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16470662	HRS	0		TSN 0				
WC#: 75.010	ENC	0		TSN 0				
PROC. REF: EMM 75-22-01, EMM 75-22-01PROC. REF: EMM 75-22-01, EMM 75-22-01								
752201-001	NO. 2 ENGINE - AIR BUFFER VALVE							Component ATA:75
PN:8910-512	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16471796	HRS	0		TSN 0				
WC#: 75.010	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
PROC. REF: EMM 75-22-01, EMM 75-22-01PROC. REF: EMM 75-22-01, EMM 75-22-01								
753101-001	NO. 1 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HAA160	HRS	0		TSN 0				
WC#: 75.015	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-001	NO. 2 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HBA426	HRS	0		TSN 0				
WC#: 75.015	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-002	NO. 1 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HAA161	HRS	0		TSN 0				
WC#: 75.020	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-002	NO. 2 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HBA427	HRS	0		TSN 0				
WC#: 75.020	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-003	NO. 1 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HAA162	HRS	0		TSN 0				
WC#: 75.025	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-003	NO. 2 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HBA428	HRS	0		TSN 0				
WC#: 75.025	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-004	NO. 1 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HAA163	HRS	0		TSN 0				
WC#: 75.030	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753101-004	NO. 2 ENGINE - HPC BLEED HANDLING VALVE							Component ATA:75
PN:EB100420D	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HBA429	HRS	0		TSN 0				
WC#: 75.030	ENC	0		TSN 0				
PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03PROC. REF: EMM 75-31-03, EMM 75-31-03, EMM 75-31-03, EMM 75-31-03								
753102-001	NO. 1 ENGINE - BLEED SOLENOID BLOCK VALVE							Component ATA:75
PN:EA100118G	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HAB162	HRS	0		TSN 0				
WC#: 75.035	ENC	0		TSN 0				
PROC. REF: EMM 75-31-02, EMM 75-31-02PROC. REF: EMM 75-31-02, EMM 75-31-02								
753102-001	NO. 2 ENGINE - BLEED SOLENOID BLOCK VALVE							Component ATA:75
PN:EA100118G	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:HCB018	HRS	0		TSN 0				
WC#: 75.035	ENC	0		TSN 0				
PROC. REF: EMM 75-31-02, EMM 75-31-02PROC. REF: EMM 75-31-02, EMM 75-31-02								
753103-001	NO. 1 ENGINE - VANE STATOR VARIABLE ACTUATOR							Component ATA:75
PN:8100-115	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16467788	HRS	0		TSN 0				
WC#: 75.040	ENC	0		TSN 0				
PROC. REF: EMM 75-31-01, EMM 75-31-01PROC. REF: EMM 75-31-01, EMM 75-31-01								
753103-001	NO. 2 ENGINE - VANE STATOR VARIABLE ACTUATOR							Component ATA:75
PN:8100-115	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:16469270	HRS	0		TSN 0				
WC#: 75.040	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
PROC. REF: EMM 75-31-01, EMM 75-31-01PROC. REF: EMM 75-31-01, EMM 75-31-01								
ATA 76 - ENGINE CONTROLS								
76-10-01-900-801-01	THROTTLE QUADRANT						Component	ATA:76
PN:GH562-3001-5	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:E0398	HRS	0		TSN 0				
WC#: 76.005	AFL	0		TSN 0				
PROC. REF: AMM 76 10 01 000 801, AMM 76 10 01 400 801PROC. REF: AMM 76 10 01 000 801, AMM 76 10 01 400 801								
ATA 77 - ENGINE INDICATING								
77-31-04-900-801-01	EVMU ENGINE VIBRATION MONITORING UNIT						Component	ATA:77
PN:GB544-1001-1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:AD72114	HRS	0		TSN 0				
WC#: 77.005	AFL	0		TSN 0				
PROC. REF: AMM 77 31 04 000 801, AMM 77 31 04 400 801PROC. REF: AMM 77 31 04 000 801, AMM 77 31 04 400 801								
771201-001	NO. 1 ENGINE - N2 SHAFT SPEED PROBE						Component	ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11516	HRS	0		TSN 0				
WC#: 77.010	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
771201-001	NO. 2 ENGINE - N2 SHAFT SPEED PROBE						Component	ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11438	HRS	0		TSN 0				
WC#: 77.010	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
771201-002	NO. 1 ENGINE - N2 SHAFT SPEED PROBE						Component	ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11517	HRS	0		TSN 0				
WC#: 77.015	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771201-002	NO. 2 ENGINE - N2 SHAFT SPEED PROBE							Component ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11439	HRS	0		TSN 0				
WC#: 77.015	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
771201-003	NO. 1 ENGINE - N2 SHAFT SPEED PROBE							Component ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11518	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
771201-003	NO. 2 ENGINE - N2 SHAFT SPEED PROBE							Component ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11440	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
771201-004	NO. 1 ENGINE - N2 SHAFT SPEED PROBE							Component ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11519	HRS	0		TSN 0				
WC#: 77.025	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
771201-004	NO. 2 ENGINE - N2 SHAFT SPEED PROBE							Component ATA:77
PN:889-3-13	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:11441	HRS	0		TSN 0				
WC#: 77.025	ENC	0		TSN 0				
PROC. REF: EMM 77-12-01, EMM 77-12-01PROC. REF: EMM 77-12-01, EMM 77-12-01								
772101-001	NO. 1 ENGINE - NO. 1 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05533	HRS	0		TSN 0				
WC#: 77.030	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772101-001	NO. 2 ENGINE - NO. 1 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05477	HRS	0		TSN 0				
WC#: 77.030	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-002	NO. 1 ENGINE - NO. 2 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05534	HRS	0		TSN 0				
WC#: 77.035	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-002	NO. 2 ENGINE - NO. 2 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05479	HRS	0		TSN 0				
WC#: 77.035	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-003	NO. 1 ENGINE - NO. 3 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05536	HRS	0		TSN 0				
WC#: 77.040	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-003	NO. 2 ENGINE - NO. 3 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05481	HRS	0		TSN 0				
WC#: 77.040	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-004	NO. 1 ENGINE - NO. 4 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05537	HRS	0		TSN 0				
WC#: 77.045	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772101-004	NO. 2 ENGINE - NO. 4 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05484	HRS	0		TSN 0				
WC#: 77.045	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-005	NO. 1 ENGINE - NO. 5 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05538	HRS	0		TSN 0				
WC#: 77.050	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-005	NO. 2 ENGINE - NO. 5 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05535	HRS	0		TSN 0				
WC#: 77.050	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-006	NO. 1 ENGINE - NO. 6 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05541	HRS	0		TSN 0				
WC#: 77.055	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-006	NO. 2 ENGINE - NO. 6 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05551	HRS	0		TSN 0				
WC#: 77.055	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772101-007	NO. 1 ENGINE - NO. 7 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05544	HRS	0		TSN 0				
WC#: 77.060	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772101-007	NO. 2 ENGINE - NO. 7 THERMOCOUPLE PROBE							Component ATA:77
PN:TC429-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:RRAE05564	HRS	0		TSN 0				
WC#: 77.060	ENC	0		TSN 0				
PROC. REF: EMM 77-21-01, EMM 77-21-01PROC. REF: EMM 77-21-01, EMM 77-21-01								
772201-001	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE							Component ATA:77
PN:920-4-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3259	HRS	0		TSN 0				
WC#: 77.065	ENC	0		TSN 0				
PROC. REF: EMM 77-23-01, EMM 77-23-01PROC. REF: EMM 77-23-01, EMM 77-23-01								
772201-001	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE							Component ATA:77
PN:920-4-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3257	HRS	0		TSN 0				
WC#: 77.065	ENC	0		TSN 0				
PROC. REF: EMM 77-23-01, EMM 77-23-01PROC. REF: EMM 77-23-01, EMM 77-23-01								
772201-002	NO. 1 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE							Component ATA:77
PN:920-4-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3260	HRS	0		TSN 0				
WC#: 77.070	ENC	0		TSN 0				
PROC. REF: EMM 77-23-01, EMM 77-23-01PROC. REF: EMM 77-23-01, EMM 77-23-01								
772201-002	NO. 2 ENGINE - TURBINE DISC OVERHEAT THERMOCOUPLE							Component ATA:77
PN:920-4-14	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:3258	HRS	0		TSN 0				
WC#: 77.070	ENC	0		TSN 0				
PROC. REF: EMM 77-23-01, EMM 77-23-01PROC. REF: EMM 77-23-01, EMM 77-23-01								
ATA 78 - EXHAUST								
78-10-01-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE							Service ATA:78
	MOS	21-Jul-21	60 (+3m/-3m)	21-Jul-26	21-Oct-26	509 d (+92)	MRIP	
	HRS	2446:06	1000 (+50/-50)	(3446:06) 3446:06	3496:06	0:10 (+50)		
	AFL	747						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
	ENC	0	PROC. REF: AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801PROC. REF: AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801					
78-10-01-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE							Service ATA:78
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		(3446:06) 3446:06	3496:06	0:10 (+50)	
	AFL	747						
	ENC	0	PROC. REF: AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801PROC. REF: AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801, AMM 78 10 01 210 801					
78-10-02-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST CONE							Service ATA:78
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		(3446:06) 3446:06	3496:06	0:10 (+50)	
	AFL	747						
	ENC	0	PROC. REF: AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801PROC. REF: AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801					
78-10-02-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EXHAUST CONE							Service ATA:78
	MOS	21-Jul-21	60 (+3m/-3m)		21-Jul-26	21-Oct-26	509 d (+92)	MRIP
	HRS	2446:06	1000 (+50/-50)		(3446:06) 3446:06	3496:06	0:10 (+50)	
	AFL	747						
	ENC	0	PROC. REF: AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801PROC. REF: AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801, AMM 78 10 02 210 801					
78-30-00-201	GENERAL VISUAL INSPECTION OF THE THRUST-REVERSER THERMAL BLANKET							Service ATA:78
	MOS/MSC	N/A						
	HRS							
WC#: 78.015	AFL							
PROC. REF: AMM 78 30 00 210 805PROC. REF: AMM 78 30 00 210 805								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-30-00-204	FUNCTIONAL TEST OF THE THRUST REVERSER							Service ATA:78
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRIP
	HRS	2446:06	4500 (+50/-50)		6946:06	6996:06	3500:10 (+50)	
WC#: 78.020	AFL	747						
PROC. REF: AMM 78 30 00 720 802PROC. REF: AMM 78 30 00 720 802								
78-30-00-205	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER P-SEALS AND SEAL DEPRESSORS/SUPPORT							Service ATA:78
	MOS	10-Mar-23	30 (+3m/-3m)		10-Sep-25	10-Dec-25	195 d (+91)	MRB
	HRS	2845:10						
	AFL	999						
PROC. REF: AMM 78 30 00 210 808PROC. REF: AMM 78 30 00 210 808								
78-30-00-206	DETAILED INSPECTION OF THE L/HIRF PROTECTION OF THE THRUST REVERSERS ELECTRICAL CONNECTORS							Service ATA:78
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
	AFL	745						
PROC. REF: AMM 78 30 00 220 801PROC. REF: AMM 78 30 00 220 801								
78-30-00-900-801-01	LEFT THRUST REVERSER							Component ATA:78
PN:07G0001-013	MOS/MSC	05-Feb-21	O/C	TSN 139				
SN:LH701	HRS	2444:24		TSN 2444:24				
WC#: 78.065	AFL	745		TSN 745				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-30-00-900-802-01	RIGHT THRUST REVERSER							Component ATA:78
PN:07G0001-015	MOS/MSC	05-Feb-21	O/C	TSN 139				
SN:RH702	HRS	2444:24		TSN 2444:24				
WC#: 78.065	AFL	745		TSN 745				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-31-01-101	DETAILED INSPECTION OF THE THRUST REVERSER UPPER DOOR							Service ATA:78
	MOS	30-Jul-09						AIRWORTHINESS
	HRS	0						
WC#: 78.025	AFL	0	T:7500	7500			6111	
PROC. REF: AMM 78 31 01 220 803PROC. REF: AMM 78 31 01 220 803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-31-01-201	DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (METALLIC)							Service ATA:78
	MOS	05-Feb-21	120 (+3m/-3m)		05-Feb-31	05-May-31	2169 d (+89)	MRB
	HRS	2444:24						
WC#: 78.030	AFL	745						
PROC. REF: AMM 78 31 01 220 802PROC. REF: AMM 78 31 01 220 802								
78-31-01-202	SPECIAL DETAILED INSPECTION OF THE UPPER PIVOTING DOORS (COMPOSITE)							Service ATA:78
	MOS	30-Jul-09						MRB
	HRS	0						
WC#: 78.035	AFL	0	T:1875 (+50/-50)		1875	1925	486 (+50)	
PROC. REF: AMM 78 31 01 280 801PROC. REF: AMM 78 31 01 280 801								
78-31-01-900-801-01	UPPER LEFT THRUST REVERSER DOOR							Component ATA:78
PN:04G2037-003	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UL1491	HRS	0		TSN 0				
WC#: 78.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-32-01-900-801-01	UPPER RIGHT THRUST REVERSER DOOR							Component ATA:78
PN:04G2037-004	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UR1309	HRS	0		TSN 0				
WC#: 78.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-01-900-801-01	LH ISOLATION THRUST REVERSER VALVE							Component ATA:78
PN:P472A0001-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0061364	HRS	0		TSN 0				
WC#: 78.075	AFL	0		TSN 0				
PROC. REF: AMM 78 33 01 000 801, AMM 78 33 01 400 801PROC. REF: AMM 78 33 01 000 801, AMM 78 33 01 400 801								
78-33-01-900-801-02	RH ISOLATION THRUST REVERSER VALVE							Component ATA:78
PN:P472A0001-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0062254	HRS	0		TSN 0				
WC#: 78.075	AFL	0		TSN 0				
PROC. REF: AMM 78 33 01 000 801, AMM 78 33 01 400 801PROC. REF: AMM 78 33 01 000 801, AMM 78 33 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-33-02-900-801-01		LH DIRECTIONAL CONTROL UNIT DCU						Component ATA:78
PN:P473A0001-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0061013	HRS	0		TSN 0				
WC#: 78.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-02-900-801-02		RH DIRECTIONAL CONTROL UNIT DCU						Component ATA:78
PN:P473A0001-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW727-08	HRS	0		TSN 0				
WC#: 78.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-03-201		DETAILED INSPECTION OF THE THRUST REVERSER UNIT (TRU) PRIMARY-DOOR ACTUATOR-ROD END						Service ATA:78
	MOS	EFF	60 (+3m/-3m)		17-Aug-25 *	17-Nov-25	171 d (+92)	MRB
	HRS							
	AFL							
PROC. REF: AMM 78 33 03 220 801PROC. REF: AMM 78 33 03 220 801								
78-33-03-900-801-01		LEFT UPPER THRUST REVERSER DOOR ACTUATOR						Component ATA:78
PN:P471A0001-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0061407	HRS	0		TSN 0				
WC#: 78.085	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-03-900-801-02		LEFT LOWER THRUST REVERSER DOOR ACTUATOR						Component ATA:78
PN:P471A0001-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0060928	HRS	0		TSN 0				
WC#: 78.085	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-03-900-801-03		RIGHT UPPER THRUST REVERSER DOOR ACTUATOR						Component ATA:78
PN:P471A0001-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3073-08	HRS	0		TSN 0				
WC#: 78.085	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-33-03-900-801-04		RIGHT LOWER THRUST REVERSER DOOR ACTUATOR						Component ATA:78
PN:P471A0001-01	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3068-08	HRS	0		TSN 0				
WC#: 78.085	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-04-900-801-01		LOB PRIMARY LOCK ACTUATOR						Component ATA:78
PN:P466A0001-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0061239	HRS	0		TSN 0				
WC#: 78.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-04-900-801-02		LIB PRIMARY LOCK ACTUATOR						Component ATA:78
PN:P466A0001-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A0061240	HRS	0		TSN 0				
WC#: 78.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-04-900-801-03		RIB PRIMARY LOCK ACTUATOR						Component ATA:78
PN:P466A0001-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3358-08	HRS	0		TSN 0				
WC#: 78.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-04-900-801-04		ROB PRIMARY LOCK ACTUATOR						Component ATA:78
PN:P466A0001-02	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3359-08	HRS	0		TSN 0				
WC#: 78.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-05-101		OPERATIONAL TEST OF THE TERTIARY LOCK (CMR**)						Service ATA:78
	MOS	27-Feb-20						CMR
	HRS	0	4500 (+50/-50)	4500	4550	1054:04 (+50)		
WC#: 78.040	AFL	0						
PROC. REF: AMM 78 33 05 710 801PROC. REF: AMM 78 33 05 710 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-33-05-201	GENERAL VISUAL INSPECTION OF THE TERTIARY LOCK HOOK							Service ATA:78
	MOS	28-Sep-17	120 (+3m/-3m)		28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		5242:56	5292:56	1797 (+50)	
WC#: 78.045	AFL	677						
PROC. REF: AMM 78 33 05 210 802PROC. REF: AMM 78 33 05 210 802								
78-33-05-203	GENERAL VISUAL INSPECTION OF THE PIVOTING DOOR KEEPER BAR							Service ATA:78
	MOS	18-Feb-22	120 (+3m/-3m)		18-Feb-32	18-May-32	2547 d (+90)	MRIP
	HRS	2452:23	3000 (+50/-50)		5452:23	5502:23	2006:27 (+50)	
	AFL	753						
PROC. REF: AMM 78 33 05 210 803PROC. REF: AMM 78 33 05 210 803								
78-33-05-900-801-01	LEFT UPPER T/R TERTIARY LOCK							Component ATA:78
PN:P516A0001-00	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3268-08	HRS	0		TSN 0				
WC#: 78.095	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-05-900-801-02	LEFT LOWER T/R TERTIARY LOCK							Component ATA:78
PN:P516A0001-00	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3264-08	HRS	0		TSN 0				
WC#: 78.095	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-05-900-801-03	RIGHT UPPER T/R TERTIARY LOCK							Component ATA:78
PN:P516A0001-00	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3114-08	HRS	0		TSN 0				
WC#: 78.095	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-33-05-900-801-04	RIGHT LOWER T/R TERTIARY LOCK							Component ATA:78
PN:P516A0001-00	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:DAW3115-08	HRS	0		TSN 0				
WC#: 78.095	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-34-01-900-801-01		LEFT UPPER INBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	28-Jun-12	O/C	TSN 1				
SN:3444	HRS	758:06		TSN 0				
WC#: 78.105	AFL	255		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-01-900-801-02		LEFT UPPER OUTBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0639	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-01-900-801-03		LEFT LOWER OUTBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0640	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-01-900-801-04		LEFT LOWER INBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0618	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-01-900-801-05		RIGHT UPPER INBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0674	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-01-900-801-06		RIGHT UPPER OUTBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0666	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-34-01-900-801-07		RIGHT LOWER OUTBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0683	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-01-900-801-08		RIGHT LOWER INBOARD STOW SWITCH					Component	ATA:78
PN:T7013-2	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0678	HRS	0		TSN 0				
WC#: 78.105	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-02-900-801-01		NO. 1 DOOR POSITION (LDVT) TRANSMITTER					Component	ATA:78
PN:133F025-005	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A101865	HRS	0		TSN 0				
WC#: 78.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-02-900-801-02		NO. 2 DOOR POSITION (LDVT) TRANSMITTER					Component	ATA:78
PN:133F025-005	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A101871	HRS	0		TSN 0				
WC#: 78.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-02-900-801-03		NO. 3 DOOR POSITION (LDVT) TRANSMITTER					Component	ATA:78
PN:133F025-005	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A101863	HRS	0		TSN 0				
WC#: 78.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
78-34-02-900-801-04		NO. 4 DOOR POSITION (LDVT) TRANSMITTER					Component	ATA:78
PN:133F025-005	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:A101864	HRS	0		TSN 0				
WC#: 78.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-34-03-900-801-01	THRUST REVERSER BOX							Component ATA:78
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.055	AFL	0		TSN 0				
PROC. REF: AMM 78 34 03 000 801, AMM 78 34 03 400 801PROC. REF: AMM 78 34 03 000 801, AMM 78 34 03 400 801								
78-ZL-00-201	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - LH							Service ATA:78
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRIP
	HRS	2446:06						
WC#: 78.050	AFL	747	1800 (+50/-50)	Adj 50	2597	2647	1208 (+50)	
PROC. REF: AMM 78 30 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801PROC. REF: AMM 78 30 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801								
78-ZL-00-202	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - RH							Service ATA:78
	MOS	21-Jul-21	120 (+3m/-3m)		21-Jul-31	21-Oct-31	2335 d (+92)	MRIP
	HRS	2446:06						
WC#: 78.050	AFL	747	1800 (+50/-50)	Adj 50	2597	2647	1208 (+50)	
PROC. REF: AMM 78 30 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801PROC. REF: AMM 78 30 00 210 801, SPM 20-70-00-210-801, SPM 51-25-00-110-801								
ATA 79 - OIL								
79-11-00-201	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK							Service ATA:79
	MOS	15-Oct-24	120 (+3m/-3m)	Adj 1d	16-Oct-34	16-Jan-35	3518 d (+92)	MRIP
	HRS	3314:03	2000 (+50/-50)		(5314:03) 5314:03 (M)	5364:03	1868:07 (+50)	
WC#: 79.005	ENC	1329						
PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801								
79-11-00-201	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK							Service ATA:79
	MOS	15-Oct-24	120 (+3m/-3m)	Adj 1d	16-Oct-34	16-Jan-35	3518 d (+92)	MRIP
	HRS	3314:03	2000 (+50/-50)		(5314:03) 5314:03 (M)	5364:03	1868:07 (+50)	
WC#: 79.005	ENC	1329						
PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-11-00-202	NO. 1 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK							Service ATA:79
	MOS	28-Sep-17	120 (+3m/-3m)		28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		(5242:56) 5242:56	5292:56	1797 (+50)	
WC#: 79.010	ENC	678						
PROC. REF: AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801PROC. REF: AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801								
79-11-00-202	NO. 2 ENGINE - FUNCTIONAL TEST OF THE ENGINE OIL TANK							Service ATA:79
	MOS	28-Sep-17	120 (+3m/-3m)		28-Sep-27	28-Dec-27	943 d (+91)	MRIP
	HRS	2242:56	3000 (+50/-50)		(5242:56) 5242:56	5292:56	1797 (+50)	
WC#: 79.010	ENC	678						
PROC. REF: AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801PROC. REF: AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801, AMM 79 11 00 720 801								
79-11-00-204	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)							Service ATA:79
	MOS/MSC	30-Jul-09	N/A					MRB
	HRS	0						
WC#: 79.015	ENC	0						
PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801								
79-11-00-204	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL TANK (POST SB BR700-72-100455)							Service ATA:79
	MOS/MSC	30-Jul-09	N/A					MRB
	HRS	0						
WC#: 79.015	ENC	0						
PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801PROC. REF: AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801, AMM 79 11 00 210 801								
79-12-01-900-801-01	OIL REPLENISHMENT TANK ASSY							Component ATA:79
PN:GC639-0011-3	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:0405	HRS	0		TSN 0				
WC#: 79.005	AFL	0		TSN 0				
PROC. REF: AMM 79 12 01 000 801, AMM 79 12 01 400 801PROC. REF: AMM 79 12 01 000 801, AMM 79 12 01 400 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-12-02-900-801-01	OIL REPLENISHMENT PUMP							Component ATA:79
PN:GC639-0013-1	MOS/MSC	17-Oct-23	O/C	TSR 0				
SN:10BT50	HRS	3029:02		TSR 0				
WC#: 79.010	AFL	1119		TSR 0				
PROC. REF: AMM 79 12 02 000 801, AMM 79 12 02 400 801PROC. REF: AMM 79 12 02 000 801, AMM 79 12 02 400 801								
79-12-04-900-801-01	RH SELECTOR VALVE							Component ATA:79
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.015	AFL	0		TSN 0				
PROC. REF: AMM 79 12 04 000 801, AMM 79 12 04 400 801PROC. REF: AMM 79 12 04 000 801, AMM 79 12 04 400 801								
79-21-02-201	NO. 1 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT							Service ATA:79
PN:QA08196	MOS	10-Mar-23					MRB	
SN:UNKNOWN	HRS	2845:10	1000 (+50/-50)	(3845:10) 3845:10	3895:10	399:14 (+50)		
WC#: 79.020	ENC	1000						
PROC. REF: AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801PROC. REF: AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801								
79-21-02-201	NO. 2 ENGINE - DISCARD THE PRESSURE FILTER ELEMENT							Service ATA:79
PN:QA08196	MOS	10-Mar-23					MRB	
SN:UNKNOWN	HRS	2845:10	1000 (+50/-50)	(3845:10) 3845:10	3895:10	399:14 (+50)		
WC#: 79.020	ENC	1000						
PROC. REF: AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801PROC. REF: AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801, AMM 79 21 02 961 801								
79-21-04-201	NO. 1 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR							Service ATA:79
	MOS	10-Mar-23					MRB	
	HRS	2845:10	1000 (+50/-50)	(3845:10) 3845:10	3895:10	399:14 (+50)		
WC#: 79.025	ENC	1000						
PROC. REF: AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801PROC. REF: AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-21-04-201	NO. 2 ENGINE - DETAILED INSPECTION OF THE FRONT-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR							Service ATA:79
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 79.025	ENC	1000						
PROC. REF: AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801PROC. REF: AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801, AMM 79 21 04 220 801								
79-21-04-202	NO. 1 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR							Service ATA:79
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 79.030	ENC	1000						
PROC. REF: AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802PROC. REF: AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802								
79-21-04-202	NO. 2 ENGINE - DETAILED INSPECTION OF THE REAR-BEARING-CHAMBER MAGNETIC CHIP-DETECTOR							Service ATA:79
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 79.030	ENC	1000						
PROC. REF: AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802PROC. REF: AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802, AMM 79 21 04 220 802								
79-21-04-203	NO. 1 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR							Service ATA:79
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 79.035	ENC	1000						
PROC. REF: AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803PROC. REF: AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803								
79-21-04-203	NO. 2 ENGINE - DETAILED INSPECTION OF THE ACCESSORY-GEARBOX MAGNETIC CHIP-DETECTOR							Service ATA:79
	MOS	10-Mar-23						MRB
	HRS	2845:10	1000 (+50/-50)		(3845:10) 3845:10	3895:10	399:14 (+50)	
WC#: 79.035	ENC	1000						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803PROC. REF: AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803, AMM 79 21 04 220 803								
79-31-02-900-801-01	OIL PROBE							Component ATA:79
PN:PN	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.020	AFL	0		TSN 0				
PROC. REF: AMM 79 31 02 000 801, AMM 79 31 02 400 801PROC. REF: AMM 79 31 02 000 801, AMM 79 31 02 400 801								
792101-001	NO. 1 ENGINE - OIL UNIT PUMP							Component ATA:79
PN:LR47000C	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:C0717	HRS	0		TSN 0				
WC#: 79.045	ENC	0		TSN 0				
PROC. REF: EMM 79-21-01, EMM 79-21-01PROC. REF: EMM 79-21-01, EMM 79-21-01								
792101-001	NO. 2 ENGINE - OIL UNIT PUMP							Component ATA:79
PN:LR47000C	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:C0758	HRS	0		TSN 0				
WC#: 79.045	ENC	0		TSN 0				
PROC. REF: EMM 79-21-01, EMM 79-21-01PROC. REF: EMM 79-21-01, EMM 79-21-01								
792102-001	NO. 1 ENGINE - PRESSURE FILTER ELEMENT							Component ATA:79
PN:QA08196	MOS/MSC	10-Mar-23	H/T	TSN 0				
SN:UNKNOWN	HRS	2845:10		TSN 0				
WC#: 79.050	ENC	1000		TSN 0				
PROC. REF: EMM 79-21-02, EMM 79-21-02PROC. REF: EMM 79-21-02, EMM 79-21-02								
792102-001	NO. 2 ENGINE - PRESSURE FILTER ELEMENT							Component ATA:79
PN:QA08196	MOS/MSC	10-Mar-23	H/T	TSN 0				
SN:UNKNOWN	HRS	2845:10		TSN 0				
WC#: 79.050	ENC	1000		TSN 0				
PROC. REF: EMM 79-21-02, EMM 79-21-02PROC. REF: EMM 79-21-02, EMM 79-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792201-001	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3803	HRS	0		TSN 0				
WC#: 79.055	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-001	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3438	HRS	0		TSN 0				
WC#: 79.055	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-002	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U4975	HRS	0		TSN 0				
WC#: 79.060	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-002	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3439	HRS	0		TSN 0				
WC#: 79.060	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-003	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3795	HRS	0		TSN 0				
WC#: 79.065	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-003	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3441	HRS	0		TSN 0				
WC#: 79.065	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792201-004	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U0106	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-004	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3331	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-005	NO. 1 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U2301	HRS	0		TSN 0				
WC#: 79.075	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792201-005	NO. 2 ENGINE - FUEL/OIL TEMP TRANSDUCER							Component ATA:79
PN:1122806	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:U3435	HRS	0		TSN 0				
WC#: 79.075	ENC	0		TSN 0				
PROC. REF: EMM 79-32-01, EMM 79-32-01PROC. REF: EMM 79-32-01, EMM 79-32-01								
792202-001	NO. 1 ENGINE - OIL, FUEL COOLED COOLER							Component ATA:79
PN:55007001-41	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:55007-1360	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: EMM 79-22-01, EMM 79-22-01PROC. REF: EMM 79-22-01, EMM 79-22-01								
792202-001	NO. 2 ENGINE - OIL, FUEL COOLED COOLER							Component ATA:79
PN:55007001-41	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:55007-1359	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: EMM 79-22-01, EMM 79-22-01PROC. REF: EMM 79-22-01, EMM 79-22-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793301-001	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER							Component ATA:79
PN:PDCR300164001M1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2735058	HRS	0		TSN 0				
WC#: 79.085	ENC	0		TSN 0				
PROC. REF: EMM 79-33-01, EMM 79-33-01PROC. REF: EMM 79-33-01, EMM 79-33-01								
793301-001	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER							Component ATA:79
PN:PDCR300164001M1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2915991	HRS	0		TSN 0				
WC#: 79.085	ENC	0		TSN 0				
PROC. REF: EMM 79-33-01, EMM 79-33-01PROC. REF: EMM 79-33-01, EMM 79-33-01								
793301-002	NO. 1 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER							Component ATA:79
PN:PDCR300164001M1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2879056	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: EMM 79-33-01, EMM 79-33-01PROC. REF: EMM 79-33-01, EMM 79-33-01								
793301-002	NO. 2 ENGINE - OIL DIFFERENTIAL PRESSURE TRANSDUCER							Component ATA:79
PN:PDCR300164001M1	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:2915992	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: EMM 79-33-01, EMM 79-33-01PROC. REF: EMM 79-33-01, EMM 79-33-01								
793401-001	NO. 1 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH							Component ATA:79
PN:21SN04-472	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K010585	HRS	0		TSN 0				
WC#: 79.095	ENC	0		TSN 0				
PROC. REF: EMM 79-34-01, EMM 79-34-01PROC. REF: EMM 79-34-01, EMM 79-34-01								
793401-001	NO. 2 ENGINE - OIL FILTER DIFFERENTIAL PRESS SWITCH							Component ATA:79
PN:21SN04-472	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:K010594	HRS	0		TSN 0				
WC#: 79.095	ENC	0		TSN 0				
PROC. REF: EMM 79-34-01, EMM 79-34-01PROC. REF: EMM 79-34-01, EMM 79-34-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
---------	------	-----	----------	----------	---------------------------	-----------	-----------	-------------

793402-001 NO. 1 ENGINE - OIL FILTER POP-UP INDICATOR					Component	ATA:79
PN:QA07508	MOS/MSC	30-Jul-09	O/C	TSN 0		
SN:RT4-1076	HRS	0		TSN 0		
WC#: 79.100	ENC	0		TSN 0		
PROC. REF: EMM 79-34-02, EMM 79-34-02PROC. REF: EMM 79-34-02, EMM 79-34-02						

793402-001 NO. 2 ENGINE - OIL FILTER POP-UP INDICATOR					Component	ATA:79
PN:QA07508	MOS/MSC	30-Jul-09	O/C	TSN 0		
SN:RT4-1075	HRS	0		TSN 0		
WC#: 79.100	ENC	0		TSN 0		
PROC. REF: EMM 79-34-02, EMM 79-34-02PROC. REF: EMM 79-34-02, EMM 79-34-02						

[illegible][illegible]

801101-001 NO. 1 ENGINE - AIR TURBINE STARTER ASSY					Component	ATA:80
PN:3505934-8	MOS/MSC	30-Jul-09	O/C	TSN 0		
SN:0209-2299	HRS	0		TSN 0		
WC#: 80.015	ENC	0		TSN 0		
PROC. REF: EMM 80-11-01, EMM 80-11-01PROC. REF: EMM 80-11-01, EMM 80-11-01						

© CAMP SYSTEMS



Status Report

Model: GLOBAL 5000 Serial: 9359 RegNo: OM-NTN HRS: 3445:56 AFL: 1389 As Of: 26-Feb-2025

27-Feb-2025 07:23 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 80 - STARTING								
801101-001	NO. 2 ENGINE - AIR TURBINE STARTER ASSY							Component ATA:80
PN:3505934-11	MOS/MSC	14-Jul-19	O/C					
SN:0102-1106	HRS	2437:10						
WC#: 80.015	ENC	743						
PROC. REF: EMM 80-11-01, EMM 80-11-01PROC. REF: EMM 80-11-01, EMM 80-11-01								
801102-001	NO. 1 ENGINE - AIR STARTER VALVE							Component ATA:80
PN:3291182-4	MOS/MSC	05-Apr-12	O/C	TSN 33				
SN:1108-2416	HRS	632:10		TSN 632:10				
WC#: 80.020	ENC	221		TSN 221				
PROC. REF: EMM 80-11-03, EMM 80-11-03PROC. REF: EMM 80-11-03, EMM 80-11-03								
801102-001	NO. 2 ENGINE - AIR STARTER VALVE							Component ATA:80
PN:3291182-4	MOS/MSC	30-Jul-09	O/C	TSN 0				
SN:1208-2440	HRS	0		TSN 0				
WC#: 80.020	ENC	0		TSN 0				
PROC. REF: EMM 80-11-03, EMM 80-11-03PROC. REF: EMM 80-11-03, EMM 80-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task