

OK-AML

Next Maintenance

Date: **30/09/2025 (in 5 months)**
RST - Restoration (Repair) of ELT/NAV Interface Module

Flight hours: **4952.3 (364.7 rem.)**
Engine no. 1 - Do TLD Clearing Procedure

Cycles: **4609 (450 rem.)**
SVC - Servicing of Main Landing Gear Shock Absorber

Next Pilot Maintenance

Date: **14/05/2025 (in 9 days)**
Electronic Charts according to 14-day chart cycle Serials with Chartview or Flitecharts

Date: **14/05/2025 (in 9 days)**
Navigation Database update according to 28-day AIRAC cycle

Date: **10/06/2025 (in a month)**
Safetaxi, Airport Director and Obstacle update according to 56-day cycle Serials with Perspective Avionics

Date: **11/05/2025 (in 6 days)**
CHECK HYDRAULICK LEVEL

Date: **12/05/2025 (in 7 days)**
Download and submit CMC data

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
00. AMM CHAPTER 5-30-00 - SCHEDULED MAINTENANCE PACKAGES							
Inspection							
	12 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-80	Yes	12 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
	120 MO / 60 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-90	Yes	60 MN (±1 MN) <i>First 120 MN (±1 MN)</i>	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
	120 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-87	Yes	120 MN (±1 MN)	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
	1600 FH INSPECTION PACKAGE	Inspection	AMM SMR 05-30-10	Yes	1600 FH (±30 FH)	Date: 27/09/2022 Flight hours: 3404.6	Flight hours: 5004.6 (417 rem.)
	24 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-81	Yes	24 MN (±1 MN)	Date: 25/09/2023	Date: 30/09/2025 (in 5 months)
	2400 FH INSPECTION PACKAGE	Inspection	AMM SMR 05-30-20	Yes	2400 FH (±30 FH)	Date: 18/09/2021 Flight hours: 2854.6	Flight hours: 5254.6 (667 rem.)
	3200 FH / 60 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-42	Yes	3200 FH (±30 FH) 60 MN (±1 MN)	Date: 23/10/2020 Flight hours: 2451.3	Date: 31/10/2025 (in 6 months) Flight hours: 5651.3 (1063.7 rem.)
	3200 FH INSPECTION PACKAGE	Inspection	AMM SMR 05-30-40	Yes	3200 FH (±30 FH)	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 6307.7 (1720.1 rem.)
	36 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-82	Yes	36 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2027 (in 3 years)
	48 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-83	Yes	48 MN (±1 MN)	Date: 25/09/2023	Date: 30/09/2027 (in 2 years)
	5600 FH INSPECTION PACKAGE	Inspection	AMM SMR 05-30-50	Yes	5600 FH (±30 FH)	Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
	60 MO INSPECTION PACKAGE	Inspection	AMM SMR 05-30-84	Yes	60 MN (±1 MN)	Date: 23/10/2020	Date: 30/09/2025 (in 5 months)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	6400 FH INSPECTION PACKAGE	Inspection	AMM SMR 05-30-60	Yes	6400 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
	800 FH INSPECTION PACKAGE	Inspection	AMM SMR 05-30-01	Yes	800 FH (±30 FH)	Date: 07/11/2024 Flight hours: 4322.3	Flight hours: 5122.3 (534.7 rem.)
01. AMM CHAPTER 4-10-00: SYSTEM AIRWORTHINESS LIMITATIONS							
Special Inspection							
22-11-00-001	FUNCTIONAL CHECK OF AUTOPILOT SERVOS PN: 011-01904-00	Special Inspection Airworthy	AMM TASK 22-11-00-720-801-A/500 Aileron servo (SN:1GK025864) Elevator servo (SN:1GK013833) Rudder...	Yes	12 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL	Special Inspection Airworthy	AMM TASK 26-21-00-720-801-A/500	Yes	2400 FH (±30 FH)	Date: 18/09/2021 Flight hours: 2854.6	Flight hours: 5254.6 (667 rem.)
26-21-03-001	FUNCTIONAL CHECK OF ENGINE EXTINGUISHING BOTTLE SN: 70510A1 PN: 33000073-1	Special Inspection Airworthy	AMM TASK 26-21-03-720-803-A/500 Tolerance not applicable	Yes	120 MN	Date: 07/11/2024	Date: 30/11/2034 (in 10 years)
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR	Special Inspection Airworthy	AMM TASK 27-03-01-710-802-A/500	Yes	6400 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/INTEGRITY	Special Inspection Airworthy	AMM TASK 27-14-03-720-801-A/500	Yes	6000 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6000 (1412.4 rem.)
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM	Special Inspection Airworthy	AMM TASK 27-14-02-210-801-A/600	Yes	6400 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
27-24-02-001	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH	Special Inspection Airworthy	AMM TASK 27-24-03-720-801-A/500	Yes	6000 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6000 (1412.4 rem.)
27-24-02-002	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM	Special Inspection Airworthy	AMM TASK 27-24-02-210-801-A/600	Yes	6400 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR	Special Inspection Airworthy	AMM TASK 27-41-01-210-801-A/600	Yes	6400 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH	Special Inspection Airworthy	AMM TASK 27-40-00-720-801-A/500	Yes	6000 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6000 (1412.4 rem.)
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO-BACK	Special Inspection Airworthy	AMM TASK 27-41-01-710-801-A/500	Yes	6400 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
27-51-01-002	DETAILED INSPECTION OF FLAP ACTUATOR	Special Inspection Airworthy	AMM TASK 27-51-01-210-801-A/600 LEFT (NO.1 INBOARD, NO.2 OUTBOARD, NO.3 OUTBOARD) RIGHT (NO.1 INBOAR...	Yes	7200 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER	Special Inspection Airworthy	AMM TASK 27-51-01-720-801-A/500	Yes	7200 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
28-21-	OPERATIONAL CHECK	Special	AMM TASK 28-21-07-710-801-A/500 (LEFT AND RIGHT)	Yes	800 FH (±30 FH)	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SYSTEM	Airworthy				Flight hours: 4322.3	5122.3 (534.7 rem.)
29-15-04-001	OPERATIONAL CHECK NO. 2 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE SN: AA510100 PN: 3032428-001	Special Inspection Airworthy	AMM TASK 29-15-04-710-801-A/500	Yes	3200 FH (±30 FH) 48 MN (±1 MN)	Date: 25/09/2023 Flight hours: 3860.7	Date: 30/09/2027 (in 2 years) Flight hours: 7060.7 (2473.1 rem.)
29-15-04-001	OPERATIONAL CHECK NO. 1 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE SN: AA510098 PN: 3032428-001	Special Inspection Airworthy	AMM TASK 29-15-04-710-801-A/500	Yes	3200 FH (±30 FH) 48 MN (±1 MN)	Date: 25/09/2023 Flight hours: 3860.7	Date: 30/09/2027 (in 2 years) Flight hours: 7060.7 (2473.1 rem.)
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM	Special Inspection Airworthy	AMM TASK 32-35-00-720-801-A/500	Yes	1600 FH (±30 FH) 24 MN (±1 MN)	Date: 25/09/2023 Flight hours: 3860.7	Date: 30/09/2025 (in 5 months) Flight hours: 5460.7 (873.1 rem.)
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES	Special Inspection Airworthy	AMM TASK 32-35-00-210-801-A/600	Yes	1600 FH (±30 FH) 24 MN (±1 MN)	Date: 25/09/2023 Flight hours: 3860.7	Date: 30/09/2025 (in 5 months) Flight hours: 5460.7 (873.1 rem.)
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE	Special Inspection Airworthy	AMM TASK 32-43-11-710-801-A/500	Yes	800 FH (±30 FH)	Date: 07/11/2024 Flight hours: 4322.3	Flight hours: 5122.3 (534.7 rem.)
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	Special Inspection Airworthy	AMM TASK 35-00-00-710-801-A/500	Yes	2400 FH (±30 FH) 36 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/09/2027 (in 2 years) Flight hours: 6722.3 (2134.7 rem.)
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX	Special Inspection Airworthy	AMM TASK 35-11-02-710-801-A/500	Yes	800 FH (±30 FH) 12 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/11/2025 (in 7 months) Flight hours: 5122.3 (534.7 rem.)
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE	Special Inspection Airworthy	AMM TASK 35-21-00-720-801-A/500	Yes	2400 FH (±30 FH) 36 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/11/2027 (in 3 years) Flight hours: 6722.3 (2134.7 rem.)
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE	Special Inspection Airworthy	AMM TASK 35-21-00-710-801-A/500	Yes	2400 FH (±30 FH) 36 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/09/2027 (in 2 years) Flight hours: 6722.3 (2134.7 rem.)
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS	Special Inspection Airworthy	AMM TASK 36-21-01-710-801-A/500	Yes	6400 FH (±30 FH)	Date: 26/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
Overhaul							
35-02-01-004	RESTORATION (HYDROSTATIC TEST) OF OXYGEN CYLINDER.	Overhaul Airworthy	Restoration (Hydrostatic Test) of Oxygen Cylinder. - AMM TASK 35-02-01-920-802-A/200 NOTE: Tolerance...	Yes	60 MN	Date: 16/08/2023	Date: 31/08/2028 (in 3 years)
Life Limit							

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
26-21-07-001	DISCARD OF ENGINE FIRE EXTINGUISHING BOTTLE CARTRIDGE NO.2 SN: 1931RK PN: 30903963-1	Life Limit Airworthy	AMM TASK 26-21-07-960-801-A/200 Tolerance not applicable	Yes	120 MN	Date: 07/11/2024	Date: 30/11/2034 (in 10 years)
26-21-07-001	DISCARD OF ENGINE FIRE EXTINGUISHING BOTTLE CARTRIDGE NO.1 SN: 0032RL PN: 30903962-1	Life Limit Airworthy	AMM TASK 26-21-07-960-801-A/200 Tolerance not applicable	Yes	120 MN	Date: 07/11/2024	Date: 30/11/2034 (in 10 years)
02. AMM CHAPTER 4-20-00: STRUCTURES AIRWORTHINESS LIMITATIONS (ALI)							
Special Inspection							
27-64-01-01-901	MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK.	Special Inspection Airworthy	NDT PART 6 TASK 27-64-00-250-875-A	Yes	10000 CYC 12500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
27-64-01-01-902	MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL DETAILED INSPECTION OF BELL CRANK AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 27-64-00-213-875-A	Yes	5000 CYC 6250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
27-64-01-02-901	MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS.	Special Inspection Airworthy	NDT PART 7 TASK 27-64-00-240-875-A	Yes	5000 CYC 6250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
52-10-01-01-901	MAIN DOOR STRUCTURE - EXTERNAL GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 52-10-00-212-875-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
52-10-01-02-901	MAIN DOOR STRUCTURE - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS.	Special Inspection Airworthy	NDT PART 5 TASK 52-10-00-211-875-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
52-10-01-02-902	MAIN DOOR STRUCTURE - EXTERNAL DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS	Special Inspection Airworthy	NDT PART 5 TASK 52-10-00-214-875-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
52-10-02-01-901	MAIN DOOR LATCH MECHANISM - EXTERNAL GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX	Special Inspection Airworthy	NDT PART 5 TASK 52-10-00-212-876-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
52-20-01-01-901	EMERGENCY DOOR STRUCTURE - INTERNAL GENERAL	Special Inspection Airworthy	NDT PART 5 TASK 52-20-00-211-875-A	Yes	7500 FH 6000 CYC First	Date: 26/09/2015 Flight hours:	Flight hours: 17500

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	OF SPAR AND FRAMES.				14000 CYC	0 Cycles: 0	Cycles: 14000 (9841 rem.)
52-20-01-01-902	EMERGENCY DOOR STRUCTURE - EXTERNAL DETAILED INSPECTION OF DOOR SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 52-20-00-214-875-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-01-01-901	FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPICES).	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-213-875-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-01-01-902	FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-214-875-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-02-01-901	FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-211-875-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-02-01-902	FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-214-876-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-03-01-901	FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-211-876-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-03-01-902	FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-214-877-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-04-01-901	FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL DETAILED INSPECTION OF LONGITUDINAL SPLICE.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-213-876-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-04-01-902	FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL DETAILED INSPECTION OF SKIN-TO-SPLICE AREA.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-214-878-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-10-05-01-901	FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL DETAILED VISUAL INSPECTION	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-213-877-A	Yes	11250 FH 9000 CYC First 17500 FH	Date: 26/09/2015 Flight hours: 0	Flight hours: 17500 (12912.4 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	OF PRESSURE BULKHEAD.						Cycles: 14000 (9841 rem.)
53-10-07-01-901	NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-290-875-A	Yes	15000 FH 12000 CYC First 15000 FH 12000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 15000 (10412.4 rem.) Cycles: 12000 (7841 rem.)
53-10-07-02-901	NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - EXTERNAL DETAILED INSPECTION OF WHEEL WEEL STRUCTURE.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-214-879-A	Yes	15000 FH 12000 CYC First 15000 FH 12000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 15000 (10412.4 rem.) Cycles: 12000 (7841 rem.)
53-10-07-02-902	NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL DETAILED INSPECTION OF WHEEL WEEL STRUCTURE.	Special Inspection Airworthy	NDT PART 5 TASK 53-10-00-213-878-A	Yes	15000 FH 12000 CYC First 15000 FH 12000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 15000 (10412.4 rem.) Cycles: 12000 (7841 rem.)
53-20-01-01-901	CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-883-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-01-01-902	CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-875-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-02-01-901	CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-875-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-02-01-902	CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-876-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-03-01-901	CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-876-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-03-01-902	CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-877-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-04-01-901	CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE -	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE.						
53-20-04-01-902	CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN-SPLICE.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-20-04-02-901	CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN).	Special Inspection Airworthy	NDT PART 6 TASK 53-20-00-250-875-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-04-02-902	CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-211-880-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-05-01-901	CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-211-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-20-05-02-901	CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-878-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-05-03-901	CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-879-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-05-04-901	CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-879-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
53-20-05-05-901	CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-211-877-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-06-01-901	PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-880-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-06-01-902	PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-880-A	Yes	3000 CYC 3750 FH First 7000 CYC 8750 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 7000 (2841 rem.) Flight hours: 8750 (4162.4 rem.)
53-20-07-01-901	EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPICE AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-881-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-20-07-01-902	EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-881-A	Yes	7500 FH 6000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
53-20-08-01-901	PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-211-878-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-20-08-01-902	PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-214-882-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-20-10-01-901	CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-211-879-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-20-10-01-902	CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-213-882-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
53-20-10-02-901	CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS.	Special Inspection Airworthy	NDT PART 5 TASK 53-20-00-212-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-01-01-901	AFT FUSELAGE UPPER SKIN PANEL - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-211-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-01-01-902	AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-02-01-901	AFT FUSELAGE SIDE SKIN PANEL - INTERNAL DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-213-875-A	Yes	1000 CYC 1250 FH First 10000 CYC 12500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 10000 (5841 rem.) Flight hours: 12500 (7912.4 rem.)
53-30-02-01-902	AFT FUSELAGE SIDE SKIN PANEL - INTERNAL GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-211-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-02-01-903	AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-214-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-03-01-901	AFT FUSELAGE LOWER SKIN PANEL - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-211-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-03-01-902	AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-214-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-04-01-901	AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-214-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-04-01-902	AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL DETAILED INSPECTION OF	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-213-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	CIRCUMFERENTIAL SPLICES.						
53-30-05-02-901	AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-213-877-A	Yes	3000 CYC 3750 FH First 8000 CYC 10000 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 8000 (3841 rem.) Flight hours: 10000 (5412.4 rem.)
53-30-06-01-901	AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-213-878-A	Yes	1000 CYC 1250 FH First 10000 CYC 12500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 10000 (5841 rem.) Flight hours: 12500 (7912.4 rem.)
53-30-06-01-902	AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-211-879-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-06-01-903	AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-214-880-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-07-01-901	AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-211-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
53-30-07-01-902	AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 53-30-00-214-879-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
54-50-01-01-901	PYLON FORWARD BEAM - INTERNAL GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 54-50-00-211-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
54-50-02-01-901	PYLON AFT BEAM - INTERNAL GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 54-50-00-211-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
54-50-03-01-901	PYLON MAIN BOX - EXTERNAL GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 54-52-00-212-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
54-50-03-01-902	PYLON MAIN BOX - INTERNAL DETAILED INSPECTION OF STRINGERS AND	Special Inspection Airworthy	NDT PART 5 TASK 54-52-00-213-875-A	Yes	9000 CYC 11250 FH First 14000 CYC	Date: 26/09/2015 Cycles: 0 Flight hours:	Cycles: 14000 (9841 rem.) Flight hours:

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
						17500 (12912.4 rem.)	
54-50-04-01-901	PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY.	Special Inspection Airworthy	NDT PART 5 TASK 54-52-00-211-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
54-50-05-01-901	PYLON YOKES - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS.	Special Inspection Airworthy	NDT PART 6 TASK 54-55-00-250-875-A	Yes	6000 CYC 7500 FH First 12000 CYC 15000 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 12000 (7841 rem.) Flight hours: 15000 (10412.4 rem.)
54-50-05-02-901	PYLON YOKES - INTERNAL DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES.	Special Inspection Airworthy	NDT PART 5 TASK 54-55-00-213-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
54-50-06-01-901	AFT MOUNT FITTINGS - INTERNAL DETAILED INSPECTION OF AFT MOUNT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 54-55-00-213-876-A	Yes	12000 CYC 15000 FH First 12000 CYC 15000 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 12000 (7841 rem.) Flight hours: 15000 (10412.4 rem.)
54-50-06-01-902	AFT MOUNT FITTINGS - EXTERNAL DETAILED INSPECTION OF AFT MOUNT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 54-55-00-214-876-A	Yes	12000 CYC 15000 FH First 12000 CYC 15000 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 12000 (7841 rem.) Flight hours: 15000 (10412.4 rem.)
55-10-01-01-901	FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-213-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-02-01-901	HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF FRONT, REAR SPARS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-02-01-902	HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-03-01-901	HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF SKIN, STRINGERS AND STRAPS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-290-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-03-01-902	HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-214-876-A	Yes	9000 CYC 11250 FH First 14000 CYC	Date: 26/09/2015 Cycles: 0 Flight hours:	Cycles: 14000 (9841 rem.) Flight hours:

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	INSPECTION OF SKIN AND ATTACHMENTS.						17500 (12912.4 rem.)
55-10-04-01-901	HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-290-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-05-01-901	HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-290-879-A	Yes	3700 CYC 4625 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-05-02-901	HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES.	Special Inspection Airworthy	NDT PART 6 TASK 55-10-00-250-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-05-02-902	HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-290-880-A	Yes	3700 CYC 4625 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-05-03-901	HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-290-878-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-05-04-901	HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-213-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-05-05-901	HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE.	Special Inspection Airworthy	NDT PART 6 TASK 55-10-00-250-877-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-07-01-901	HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL GENERAL VISUAL INSPECTION OF HINGES.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-212-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-08-01-901	HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-213-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
55-10-09-01-901	HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-214-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-09-01-902	HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-213-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-10-10-01-901	HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL DETAILED INSPECTION OF FITTING AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-10-00-214-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-20-01-01-901	ELEVATOR MAIN BOX - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 55-20-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-20-01-01-902	ELEVATOR MAIN BOX - EXTERNAL DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE.	Special Inspection Airworthy	NDT PART 5 TASK 55-20-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-20-02-01-901	ELEVATOR HINGE FITTINGS - INTERNAL DETAILED INSPECTION OF ELEVATOR HINGE PINS.	Special Inspection Airworthy	NDT PART 5 TASK 55-20-00-213-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-20-02-02-901	ELEVATOR HINGE FITTINGS - INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR HINGES.	Special Inspection Airworthy	NDT PART 5 TASK 55-20-00-211-876-A	Yes	11250 FH 9000 CYC First 17500 FH 14000 CYC	Date: 26/09/2015 Flight hours: 0 Cycles: 0	Flight hours: 17500 (12912.4 rem.) Cycles: 14000 (9841 rem.)
55-20-03-01-901	ELEVATOR TORQUE TUBE ASSY - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE.	Special Inspection Airworthy	NDT PART 6 TASK 55-20-00-250-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-20-03-02-901	ELEVATOR TORQUE TUBE ASSY - INTERNAL SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE.	Special Inspection Airworthy	NDT PART 8 TASK 55-20-00-230-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-20-04-001	INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-20-00-211-851-A Task included per ANAC AD 2020-01-01 and FAA AD 2020-12-08.	Yes	60 MN	Date: 23/10/2020	Date: 31/10/2025 (in 6 months)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
55-20-04-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS	Special Inspection Airworthy	NDT PART 5 TASK 55-20-00-290-852-A Task included per ANAC AD 2020-01-01 and FAA AD 2020-12-08.	Yes	60 MN	Date: 23/10/2020	Date: 31/10/2025 (in 6 months)
55-30-01-01-901	VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE.	Special Inspection Airworthy	NDT PART 6 TASK 55-30-00-250-877-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-01-02-901	VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-213-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-01-03-901	VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL DETAILED INSPECTION OF BOLT.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-213-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-01-04-901	VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS.	Special Inspection Airworthy	NDT PART 6 TASK 55-30-00-250-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-02-01-901	VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-213-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-02-03-901	VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL DETAILED INSPECTION OF PIN	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-213-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-02-04-901	VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5.	Special Inspection Airworthy	NDT PART 6 TASK 55-30-00-250-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-02-05-901	VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	DETAILED INSPECTION (BOREScope) OF RIB 7.						
55-30-02-06-901	VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF RIB 6 AND RIB 8.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-290-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-02-07-901	VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF RIB 5 , L PROFILES AND SHROUDS	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-290-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-03-01-901	VERTICAL STABILIZER MAIN BOX - EXTERNAL DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-03-01-902	VERTICAL STABILIZER MAIN BOX - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-290-878-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-04-01-901	VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL GENERAL VISUAL INSPECTION OF HINGES	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-211-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-05-01-901	HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL DETAILED INSPECTION OF FITTING 1 AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-214-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-30-06-01-901	HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 55-30-00-213-879-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-40-01-01-901	RUDDER MAIN BOX - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF SKIN, SPARS, RIBS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 55-40-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-40-	RUDDER MAIN BOX -	Special	NDT PART 5 TASK 55-40-00-214-875-A	Yes	9000 CYC	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
902	INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS.	Airworthy			First 14000 CYC 17500 FH	Cycles: 0 Flight hours: 0	(9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-40-02-01-901	RUDDER HINGE FITTINGS - INTERNAL DETAILED INSPECTION OF PINS OF RUDDER HINGES.	Special Inspection Airworthy	NDT PART 5 TASK 55-40-00-213-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-40-02-02-901	RUDDER HINGE FITTINGS - INTERNAL GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS.	Special Inspection Airworthy	NDT PART 5 TASK 55-40-00-211-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-40-03-01-901	RUDDER TORQUE TUBE ASSEMBLY - INTERNAL GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS.	Special Inspection Airworthy	NDT PART 5 TASK 55-40-00-211-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
55-40-04-002	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS	Special Inspection Airworthy	NDT PART 5 TASK 55-40-00-211-851-A Task included per ANAC AD 2020-01-01 and FAA AD 2020-12-08	Yes	60 MN	Date: 23/10/2020	Date: 31/10/2025 (in 6 months)
55-40-04-003	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS	Special Inspection Airworthy	NDT PART 5 TASK 55-40-00-290-852-A Task included per ANAC AD 2020-01-01 and FAA AD 2020-12-08.	Yes	60 MN	Date: 23/10/2020	Date: 31/10/2025 (in 6 months)
56-10-03-01-901	WINDSHIELD FRAME AND FASTENERS - EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS.	Special Inspection Airworthy	NDT PART 6 TASK 56-10-00-250-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-01-01-901	WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-214-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-02-01-901	WING FRONT SPAR - INTERNAL DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-213-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-03-01-901	WING REAR SPAR - INTERNAL DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-213-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-04-01-901	WING ROOT SPAR - INTERNAL DETAILED INSPECTION OF WING ROOT SPAR.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-213-877-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
57-10-05-01-901	WING MIDDLE SPAR - INTERNAL GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-211-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-07-01-901	WING LOWER SKIN PANEL - INTERNAL GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-211-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-07-01-902	WING LOWER SKIN PANEL - EXTERNAL DETAILED INSPECTION OF WING SKIN.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-214-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-08-01-901	WING RIBS - INTERNAL DETAILED INSPECTION OF MACHINED RIBS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-213-878-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-08-02-901	WING RIBS - EXTERNAL DETAILED INSPECTION OF MAIN LANDING GEAR RIBS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-214-877-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-11-01-901	WING CENTRAL SPLICES - INTERNAL DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-213-879-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-11-01-902	WING CENTRAL SPLICES - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF UPPER SKIN SPLICES, INCLUDING FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-290-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-10-12-01-901	KINK LOWER SKIN SPLICE - INTERNAL DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-10-00-213-880-A	No	4000 CYC 5000 FH First 10000 CYC 12500 FH	Not Applicable	
57-50-01-01-901	WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS.	Special Inspection Airworthy	NDT PART 5 TASK 57-50-00-213-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-01-01-902	WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS.	Special Inspection Airworthy	NDT PART 6 TASK 57-50-00-250-878-A	Yes	6000 CYC 7500 FH First 9000 CYC 11250 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 9000 (4841 rem.) Flight hours: 11250 (6662.4 rem.)
57-50-	WING TRAILING EDGE	Special	NDT PART 6 TASK 57-50-00-250-875-A	Yes	6000 CYC	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
901	CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS.	Airworthy			First 14000 CYC 17500 FH	Cycles: 0 Flight hours: 0	(9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-01-03-901	WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-50-00-214-875-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-01-04-901	WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS.	Special Inspection Airworthy	NDT PART 5 TASK 57-50-00-214-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-01-05-901	WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 6 TASK 57-50-00-250-879-A	Yes	5000 CYC 6250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-01-05-902	WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 57-50-00-213-878-A	Yes	5000 CYC 6250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-02-01-901	WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 6 TASK 57-50-00-250-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-02-01-902	WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 57-50-00-213-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-02-02-901	WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS.	Special Inspection Airworthy	NDT PART 6 TASK 57-50-00-250-877-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-50-02-02-902	WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS.	Special Inspection Airworthy	NDT PART 5 TASK 57-50-00-213-877-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
902	ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL DETAILED INSPECTION OF MLG TRUNNIONS.	Airworthy			First 14000 CYC 17500 FH	Cycles: 0 Flight hours: 0	(9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-52-01-01-901	FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE.	Special Inspection Airworthy	NDT PART 5 TASK 57-52-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-52-01-01-902	FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL DETAILED INSPECTION OF MAIN BOX AND VANE.	Special Inspection Airworthy	NDT PART 5 TASK 57-52-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-52-02-01-901	FLAP INBOARD RIBS - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS.	Special Inspection Airworthy	NDT PART 5 TASK 57-52-00-290-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-52-03-01-901	FLAP INBOARD TRACKS - EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS.	Special Inspection Airworthy	NDT PART 6 TASK 57-52-00-250-875-A	Yes	6000 CYC 7500 FH First 9000 CYC 11250 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 9000 (4841 rem.) Flight hours: 11250 (6662.4 rem.)
57-52-04-01-901	FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP ACTUATOR FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 57-52-00-290-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-52-04-02-901	FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING.	Special Inspection Airworthy	NDT PART 6 TASK 57-52-00-250-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-01-01-901	FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE.	Special Inspection Airworthy	NDT PART 5 TASK 57-53-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-01-01-902	FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL DETAILED INSPECTION OF MAIN BOX AND VANE.	Special Inspection Airworthy	NDT PART 5 TASK 57-53-00-214-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-02-01-901	FLAP OUTBOARD RIBS - INTERNAL SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS.	Special Inspection Airworthy	NDT PART 5 TASK 57-53-00-290-876-A	Yes	6000 CYC 7500 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-03-01-	FLAP OUTBOARD TRACKS - EXTERNAL	Special Inspection	NDT PART 6 TASK 57-53-00-250-875-A	Yes	6000 CYC 7500 FH	Date: 26/09/2015	Cycles: 9000

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	INSPECTION (EDDY CURRENT) OF FLAP TRACKS.				9000 CYC 11250 FH	Flight hours: 0	Flight hours: 11250 (6662.4 rem.)
57-53-04-01-901	FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 57-53-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-04-02-901	FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 57-53-00-214-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-04-03-901	FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 5 TASK 57-53-00-290-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-53-04-04-901	FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING.	Special Inspection Airworthy	NDT PART 6 TASK 57-53-00-250-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON	Special Inspection Airworthy	NDT PART 5 TASK 57-60-00-214-851-A Task included per ANAC AD 2020-01-01 and FAA AD 2020-12-08.	Yes	60 MN	Date: 23/10/2020	Date: 31/10/2025 (in 6 months)
57-60-01-01-901	AILERON MAIN BOX - INTERNAL SPECIAL DETAILED INSPECTION (BOREScope) OF SKIN, SPARS, RIBS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-60-00-290-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-60-01-01-902	AILERON MAIN BOX - EXTERNAL DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS.	Special Inspection Airworthy	NDT PART 5 TASK 57-60-00-214-875-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-60-01-02-901	AILERON MAIN BOX - EXTERNAL DETAILED INSPECTION OF AILERON ROOT RIBS.	Special Inspection Airworthy	NDT PART 5 TASK 57-60-00-214-876-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-60-02-01-901	AILERON HINGE FITTINGS - EXTERNAL DETAILED INSPECTION OF AILERON HINGES PINS.	Special Inspection Airworthy	NDT PART 5 TASK 57-60-00-214-877-A	Yes	9000 CYC 11250 FH First 14000 CYC 17500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
57-60-02-02-	AILERON HINGE FITTINGS - EXTERNAL	Special Inspection	NDT PART 5 TASK 57-60-00-214-878-A	Yes	9000 CYC 11250 FH	Date: 26/09/2015	Cycles: 14000

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	INSPECTION OF AILERON HINGES FITTINGS.				14000 CYC 17500 FH	Flight hours: 0	Flight hours: 17500 (12912.4 rem.)
71-21-01-01-901	ENGINE FORWARD MOUNTING ASSEMBLY RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS).	Special Inspection Airworthy	AMM TASK 71-20-00-920-801-A/200 The flight cycles / flight hours accumulated shall be based on the...	Yes	6000 CYC 7500 FH First 6000 CYC 7500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 6000 (1841 rem.) Flight hours: 7500 (2912.4 rem.)
71-22-01-01-901	ENGINE AFT MOUNTING ASSEMBLY - INTERNAL DETAILED INSPECTION AFT MOUNT BOLTS TORQUE SEAL.	Special Inspection Airworthy	NDT PART 5 TASK 71-22-00-213-876-A	Yes	3600 CYC 4500 FH First 3600 CYC 4500 FH	Date: 25/09/2023 Cycles: 3591 Flight hours: 3860.7	Cycles: 7191 (3032 rem.) Flight hours: 8360.7 (3773.1 rem.)
71-22-01-01-902	ENGINE AFT MOUNTING ASSEMBLY RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS).	Special Inspection Airworthy	AMM TASK 71-20-00-920-801-A/200 The flight cycles / flight hours accumulated shall be based on the...	Yes	6000 CYC 7500 FH First 6000 CYC 7500 FH	Date: 26/09/2015 Cycles: 0 Flight hours: 0	Cycles: 6000 (1841 rem.) Flight hours: 7500 (2912.4 rem.)
Life Limit							
27-50-01-01-901	FLAP MECHANICAL COMPONENT - INTERNAL DETAILED INSPECTION OF ACTUATOR PINS	Life Limit Airworthy	NDT PART 5 TASK 27-51-00-213-875-A	Yes	14000 CYC 17500 FH	Date: 22/09/2015 Cycles: 0 Flight hours: 0	Cycles: 14000 (9841 rem.) Flight hours: 17500 (12912.4 rem.)
03. AMM CHAPTER 4-30-00: TABLE 1 - FLIGHT CONTROLS LIFE-LIMITED ITEMS							
Life Limit							
27-001	FLAP ACTUATOR - OUTBOARD 3	Life Limit Airworthy		No	1800 FH	Date: 22/09/2015 Flight hours: 0	None
27-002	FLAP ACTUATOR - OUTBOARD 2	Life Limit Airworthy	475000-2009	No	1800 FH	Date: 22/09/2015 Flight hours: 0	None
27-003	FLAP ACTUATOR - INBOARD 1	Life Limit Airworthy		No	1800 FH	Date: 22/09/2015 Flight hours: 0	None
27-004	ROLL TRIM ACTUATOR SN: 0337 PN: 470500-1005	Life Limit Airworthy		Yes	12000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
27-005	YAW TRIM ACTUATOR SN: 0332 PN: 470600-1005	Life Limit Airworthy		Yes	12000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
27-006	PITCH TRIM ACTUATOR SN: 0341 PN: 467500-1003	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-007	LEFT SPOILER ACTUATOR SN: 0518 PN: 456800-1003	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-007	RIGHT SPOILER ACTUATOR	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015	Flight hours:

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
PN: 456800-1003						Flight hours: 0	35000 (30412.4 rem.)
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR SN: 1577 PN: SYLC53058	Life Limit Airworthy	PROC. REF: AMM 27-70-01, AMM 27-70-01PROC. REF: AMM 27-70-01, AMM 27-70-01	Yes	On-Condition	Date: 26/09/2015	
27-009	RUDDER BOOSTER ACTUATOR SN: 0309T PN: 9125-3	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-010	TOGGLE LINK SN: 0614 PN: 456870-1001	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-011	STICK PUSHER ACTUATOR SN: 0336T PN: 9124-1	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-012	POWER DRIVE UNIT SN: 0363 PN: 467700-1003	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-013	FLAP POSITION SENSOR UNIT SN: 0056 PN: 457310-1001	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-014	FLEX SHAFT SN: SSW0611 PN: 457360-1005	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-015	FLEX SHAFT SN: SSW0680 PN: 457360-1007	Life Limit Airworthy		Yes	35000 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 35000 (30412.4 rem.)
27-016	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR SN: 0658 PN: 475100-1013	Life Limit Airworthy		Yes	7200 FH	Date: 26/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
27-016	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR SN: 0657 PN: 475100-1013	Life Limit Airworthy		Yes	7200 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
27-017	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR SN: 1349 PN: 475000-2013	Life Limit Airworthy		Yes	7200 FH	Date: 26/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
27-017	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR SN: 1348 PN: 475000-2013	Life Limit Airworthy		Yes	7200 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
27-018	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR SN: 1308 PN: 475000-1013	Life Limit Airworthy		Yes	7200 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)
27-018	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR SN: 1309 PN: 475000-1013	Life Limit Airworthy		Yes	7200 FH	Date: 26/09/2015 Flight hours: 0	Flight hours: 7200 (2612.4 rem.)

04. - AMM CHAPTER 4-30-00: TABLE 2 - LANDING GEAR LIFE-LIMITED ITEMS

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING SN: 1558643/001 PN: 2317-1201-503	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING SN: 1570240/001 PN: 2317-1201-504	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-003	LEFT PINTLE PIN SN: 1568828/007 PN: 2317-1101-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-003	RIGHT PINTLE PIN SN: 1571218/006 PN: 2317-1101-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-004	RIGHT PINTLE PIN SN: 1570276/007 PN: 2317-1102-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-004	LEFT PINTLE PIN SN: 1570276/009 PN: 2317-1102-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE SN: 1567108/006 PN: 2317-1103-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE SN: 1567108/002 PN: 2317-1103-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE SN: 1558260/011 PN: 2317-1107-005	Life Limit Airworthy		Yes	15300 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 15300 (11141 rem.)
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE SN: 1558260/004 PN: 2317-1107-005	Life Limit Airworthy		Yes	15300 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 15300 (11141 rem.)
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN SN: 1558134/006 PN: 2317-1109-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN SN: 1558134/005 PN: 2317-1109-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT SN: 1565262/017 PN: 2317-1126-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT SN: 1565262/022 PN: 2317-1126-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE SN: 1570559/002 PN: 2317-1502-003	Life Limit Airworthy		Yes	15300 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 15300 (11141 rem.)
32-101	RIGHT MAIN	Life Limit		Yes	15300 CYC	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	TRAILING ARM WHEEL AXLE SN: 1570559/004 PN: 2317-1502-003					Cycles: 0	(11141 rem.)
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE SN: 1565074/002 PN: 2317-1503-005	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE SN: 1565939/003 PN: 2317-1503-005	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT SN: 1559033/006 PN: 2317-1509-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT SN: 1559033/010 PN: 2317-1509-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-104	LEFT MAIN LANDING GEAR TRAILING ARM SN: 1570375/001 PN: 2317-1513-501	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM SN: 1575178/001 PN: 2317-1513-502	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN SN: 1565266/016 PN: 2317-1505-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN SN: 1565266/013 PN: 2317-1505-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER SN: 1577777/002 PN: 2317-3011-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER SN: 1579751/003 PN: 2317-3011-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE SN: 1565671/001 PN: 2317-3021-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE SN: 1577779/002 PN: 2317-3021-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-203	LEFT MAIN LANDING	Life Limit		Yes	16800 CYC	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	ABSORBER BEARING SN: 1558132/004 PN: 2317-3001-003					Cycles: 0	(12641 rem.)
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING SN: 1558132/012 PN: 2317-3001-003	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT SN: 1569580/005 PN: 2317-3004-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT SN: 1569580/003 PN: 2317-3004-001	Life Limit Airworthy		Yes	16800 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 16800 (12641 rem.)
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER SN: 1499159/001 PN: 2117-3034-501	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER SN: 1559583/001 PN: 2117-3034-501	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-302	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON PN: 2117-3001-001	Life Limit Airworthy	2117-3001-001	No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-302	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON PN: 2117-3001-001	Life Limit Airworthy	2117-3001-001	No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-303	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER PN: 2117-3010-001	Life Limit Airworthy		No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-303	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER PN: 2117-3010-001	Life Limit Airworthy		No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD SN: 71820/0024 PN: 2117-3008-901	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD SN: 77001/0006 PN: 2117-3008-901	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON SN: 1492950/015 PN: 2117-3009-007	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON SN: 1568952/005 PN: 2117-3009-007	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-306	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN PN: 2117-3019-001	Life Limit Airworthy		No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-306	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN PN: 2117-3019-001	Life Limit Airworthy		No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-307	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE PN: 2117-3007-001	Life Limit Airworthy		No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-307	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE PN: 2117-3007-001	Life Limit Airworthy		No	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP SN: 1551179/011 PN: 2117-3011-001	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP SN: 1494828/010 PN: 2117-3011-001	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING SN: 1504169/008 PN: 2117-3013-001	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING SN: 1573988/005 PN: 2117-3013-001	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT SN: 1498708/014 PN: 2117-3015-001	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT SN: 1562336/015 PN: 2117-3015-001	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END SN: 00386 PN: MTMKS14ALGA1	Life Limit Airworthy		Yes	10500 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 10500 (6341 rem.)
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR	Life Limit Airworthy		Yes	10500 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 10500 (6341 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
PN: MTMKS14ALGA1							
32-312	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER SN: 10035 PN: 2117-3027-901	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-312	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER SN: 15030 PN: 2117-3027-901	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-313	NUT PN: 2117-3029-001	Life Limit Airworthy		No	28000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 28000 (23841 rem.)
32-314	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN SN: 1566173/007 PN: 2117-3019-003	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-314	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN SN: 1559168/011 PN: 2117-3019-003	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-315	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE SN: 1554001/016 PN: 2117-3007-003	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-315	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE SN: 1565449/019 PN: 2117-3007-003	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-316	DIS - DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON SN: 1541222/011 PN: 2117-3001-003	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-316	DIS - DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON SN: 1559184/007 PN: 2117-3001-003	Life Limit Airworthy		Yes	12000 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 12000 (7841 rem.)
32-400	NOSE LANDING GEAR SHOCK STRUT SN: 00327 PN: 2317-5100-403	Life Limit Airworthy		Yes	On-Condition	Date: 22/09/2015	
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT SN: 00361 PN: 2310-1144-005	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT SN: 1565146/015 PN: 2310-1173-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-403	RIGHT NOSE	Life Limit		Yes	11200 CYC	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SHOCK STRUT PINTLE PIN SN: 1566144/005 PN: 2317-5105-001					Cycles: 0	(7041 rem.)
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN SN: 1566144/002 PN: 2317-5105-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING SN: 1574112/001 PN: 2317-5301-503	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER SN: 00349 PN: 2117-4000-403	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE SN: 1705158/006 PN: 2317-5101-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK SN: 1566064/010 PN: 2317-5201-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK SN: 1566064/011 PN: 2317-5201-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN SN: 1551622/005 PN: 2317-6003-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE SN: 1562828/009 PN: 2310-1165-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN SN: 00811 PN: 57675-1	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT SN: 00344 PN: 2310-1183-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK SN: 1574107/003 PN: 2317-5191-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK SN: 1569170/001 PN: 2317-5227-501	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-502	NOSE LANDING GEAR	Life Limit		Yes	11200 CYC	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	LOWER BEARING SN: 1567595/005 PN: 2317-5113-005					Cycles: 0	(7041 rem.)
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER SN: 1570563/001 PN: 2317-5237-501	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-600	NOSE LANDING GEAR DRAG BRACE SN: 00328 PN: 2317-6000-403	Life Limit Airworthy		Yes	On-Condition	Date: 22/09/2015	
32-601	NOSE LANDING GEAR UPPER DRAG BRACE SN: 1551116/002 PN: 2317-6114-501	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-602	NOSE LANDING GEAR LOWER DRAG BRACE SN: 1565877/004 PN: 2317-6201-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN SN: 1557999/011 PN: 2317-6001-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN SN: 1557999/009 PN: 2317-6001-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-604	NOSE LANDING GEAR DRAG BRACE PIN SN: 1551622/012 PN: 2317-6003-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-701	NOSE LANDING GEAR UPPER LOCKING STAY SN: 1562850/002 PN: 2317-6521-003	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-702	NOSE LANDING GEAR LOWER LOCKING STAY SN: 1571898/001 PN: 2317-6531-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT SN: 1565542/005 PN: 2310-1734-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT SN: 1565542/011 PN: 2310-1734-001	Life Limit Airworthy		Yes	11200 CYC	Date: 22/09/2015 Cycles: 0	Cycles: 11200 (7041 rem.)
05. AMM CHAPTER 5-20-00: SCHEDULED MAINTENANCE REQUIREMENTS							
Special Inspection							
21-21-02-001	OPC - OPERATIONAL CHECK OF INLET AIR CHECK VALVE	Special Inspection	AMM TASK 21-21-02-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
21-23-03-002	OPC - OPERATIONAL CHECK OF RAM AIR VALVE	Special Inspection	AMM TASK 21-23-03-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
21-23-04-001	OPC - OPERATIONAL CHECK OF RAM AIR CHECK VALVES	Special Inspection	AMM TASK 21-23-04-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
21-24-01-001	OPC - OPERATIONAL CHECK OF IFE/CMS COOLING FAN	Special Inspection	AMM TASK 21-24-01-710-801-A/500	No	6400 FH	Not Applicable	
21-31-00-004	OPC - OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS	Special Inspection	AMM TASK 21-31-00-710-802-A/500	Yes	5600 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
21-31-00-005	OPC - OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL	Special Inspection	AMM TASK 21-31-00-710-804-A/500	Yes	5600 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
21-31-03-001	OPC - OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE	Special Inspection	AMM TASK 21-31-03-710-801-A/500	Yes	5600 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
21-52-08-001	GVI - GENERAL VISUAL INSPECTION OF VCS CONDENSER	Special Inspection	AMM TASK 21-52-08-210-801-A/600	Yes	1600 FH	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5004.7 (417.1 rem.)
21-61-06-001	OPC - OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR	Special Inspection	AMM TASK 21-61-06-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
23-51-00-001	OPC - OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE	Special Inspection	AMM TASK 23-51-00-710-802-A/500	Yes	3200 FH	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 6307.7 (1720.1 rem.)
24-36-02-001	OPC - OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)	Special Inspection	AMM TASK 24-36-02-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
26-11-01-002	OPC - OPERATIONAL CHECK OF ENGINE FIRE DETECTOR	Special Inspection	AMM TASK 26-11-01-710-801-A/500	Yes	800 FH	Date: 07/11/2024 Flight hours: 4322.3	Flight hours: 5122.3 (534.7 rem.)
26-21-05-001	OPC - OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)	Special Inspection	AMM TASK 26-21-05-710-801-A/500	Yes	2400 FH	Date: 18/09/2021 Flight hours: 2854.7	Flight hours: 5254.7 (667.1 rem.)
27-21-00-001	GVI - GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS	Special Inspection	AMM TASK 27-21-00-210-801-A/600	Yes	3200 FH 60 MN	Date: 23/10/2020 Flight hours: 2451.5	Date: 31/10/2025 (in 6 months) Flight hours: 5651.5 (1063.9 rem.)
27-23-00-001	OPC - OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM	Special Inspection	AMM TASK 27-23-00-710-801-A/500	Yes	1600 FH	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5004.7 (417.1 rem.)
27-36-03-001	OPC - OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH	Special Inspection	AMM TASK 27-36-03-710-801-A/500	Yes	1600 FH	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5004.7 (417.1 rem.)
27-65-01-001	GVI - GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)	Special Inspection	AMM TASK 27-65-00-210-801-A/600	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
28-12-03-001	OPC - OPERATIONAL CHECK OF FLOAT VENT VALVE	Special Inspection	AMM TASK 28-12-03-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
28-23-	GVI - GENERAL	Special	AMM TASK 28-23-05-212-801-A/600	Yes	3200 FH	Date:	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	OF PRESSURE REFUELING ADAPTER					Flight hours: 3107.7	6307.7 (1720.1 rem.)
29-12-02-002	OPC - OPERATIONAL CHECK OF EDP CHECK VALVE	Special Inspection	AMM TASK 29-10-00-710-802-A/500	Yes	5600 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
30-12-00-001	OPC - OPERATIONAL CHECK OF WING/H- STAB ANTI□ICING SYSTEM	Special Inspection	AMM TASK 30-10-00-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
30-21-03-001	SDI - BORESCOPE INSPECTION OF PICCOLO TUBE	Special Inspection	AMM TASK 30-21-03-220-801-A/600	Yes	5600 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
31-42-00-001	OPC - OPERATIONAL CHECK OF HSDB SWITCH REVERSION	Special Inspection	AMM TASK 31-42-00-710-801-A/500	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
31-61-00-001	OPC - OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) SN: 1F1100284 PN: 011-01910-10	Special Inspection	AMM TASK 31-61-00-710-801-A/500	Yes	3200 FH	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 6307.7 (1720.1 rem.)
31-61-00-001	OPC - OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) SN: 1F1105055 PN: 011-01910-10	Special Inspection	AMM TASK 31-61-00-710-801-A/500	Yes	3200 FH	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 6307.7 (1720.1 rem.)
31-61-00-001	OPC - OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) SN: 1F1105042 PN: 011-01910-10	Special Inspection	AMM TASK 31-61-00-710-801-A/500	Yes	3200 FH	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 6307.7 (1720.1 rem.)
32-41-02-001	OPC - OPERATIONAL CHECK OF BRAKE PEDAL TRANSDUCER	Special Inspection	AMM TASK 32-41-02-710-801-A/500 (LH AND RH)	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
33-48-00-002	GVI - GENERAL VISUAL INSPECTION OF NAVIGATION LIGHTS	Special Inspection	AMM TASK 33-48-00-210-801-A/600 LEFT (NO.1 AND NO.2) RIGHT (NO.1 AND NO.2)	Yes	2400 FH	Date: 18/09/2021 Flight hours: 2854.7	Flight hours: 5254.7 (667.1 rem.)
33-49-00-002	GVI - GENERAL VISUAL INSPECTION OF STROBE LIGHTS	Special Inspection	AMM TASK 33-49-00-210-801-A/600 (NO. 1 AND NO.2)	Yes	2400 FH	Date: 18/09/2021 Flight hours: 2854.6	Flight hours: 5254.6 (667 rem.)
36-11-01-001	RST - RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER	Special Inspection	AMM TASK 36-11-01-100-801-A/700	Yes	2400 FH (±30 FH)	Date: 18/09/2021 Flight hours: 2854.7	Flight hours: 5254.7 (667.1 rem.)
36-11-01-002	OPC - OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION	Special Inspection	AMM TASK 36-11-00-710-801-A/500	Yes	800 FH	Date: 07/11/2024 Flight hours: 4322.3	Flight hours: 5122.3 (534.7 rem.)
36-11-04-001	RST - RESTORATION (CLEANING) OF FAN- AIR VALVE (FAV) FILTER	Special Inspection	AMM TASK 36-11-04-100-801-A/700	Yes	2400 FH	Date: 18/09/2021 Flight hours: 2854.6	Flight hours: 5254.6 (667 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
36-11-06-001	OPC - OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION	Special Inspection	AMM TASK 36-11-06-710-801-A/500	Yes	800 FH	Date: 07/11/2024 Flight hours: 4322.3	Flight hours: 5122.3 (534.7 rem.)
36-11-06-002	RST - RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER	Special Inspection	AMM TASK 36-11-06-100-801-A/700	Yes	6400 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 6400 (1812.4 rem.)
52-20-01-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE	Special Inspection	NDT PART 5 TASK 52-20-00-211-851-A	Yes	60 MN First 120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
53-20-08-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE	Special Inspection	NDT PART 5 TASK 53-20-00-211-878-A	Yes	60 MN First 120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
55-20-01-002	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX	Special Inspection	NDT PART 5 TASK 55-20-00-290-851-A	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
55-30-01-002	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER	Special Inspection	NDT PART 5 TASK 55-30-00-290-851-A	Yes	60 MN First 120 MN	Date: 23/10/2020	Date: 31/10/2025 (in 6 months)
55-40-01-002	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX	Special Inspection	NDT PART 5 TASK 55-40-00-290-851-A	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
57-10-00-002	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN	Special Inspection	NDT PART 5 TASK 57-10-00-290-851-A	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
57-52-00-001	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP	Special Inspection	NDT PART 5 TASK 57-52-00-290-851-A	Yes	60 MN First 120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
57-53-00-001	SDI - SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP	Special Inspection	NDT PART 5 TASK 57-53-00-290-851-A	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
71-11-00-001	GVI - GENERAL VISUAL INSPECTION OF UPPER MID COW	Special Inspection	AMM TASK 71-11-00-212-801-A/600	Yes	5600 FH	Date: 22/09/2015 Flight hours: 0	Flight hours: 5600 (1012.4 rem.)
H242-001	GVI - INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE	Special Inspection	AMM TASK 05-42-00-210-810-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
Z210-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION	Special Inspection	AMM TASK 05-41-00-210-802-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z220-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION	Special Inspection	AMM TASK 05-41-00-210-804-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z230-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION	Special Inspection	AMM TASK 05-42-00-210-802-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z310-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION	Special Inspection	AMM TASK 05-43-00-210-802-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z320-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION	Special Inspection	AMM TASK 05-43-00-210-804-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z330-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER	Special Inspection	AMM TASK 05-44-00-210-804-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z340-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER	Special Inspection	AMM TASK 05-44-00-210-802-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z410-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON	Special Inspection	AMM TASK 05-46-00-210-802-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Z430-002	GVI - INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE	Special Inspection	AMM TASK 05-46-00-210-804-A/600	Yes	120 MN	Date: 22/09/2015	Date: 30/09/2025 (in 5 months)
Life Limit							
52-13-21-001	DIS - DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR	Life Limit	AMM TASK 52-13-21-900-801-A/400	No	5600 FH	Not Applicable	
52-13-22-001	DIS - DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE	Life Limit	AMM TASK 52-13-22-900-801-A/400	No	800 FH	Not Applicable	
52-13-22-004	DIS - DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES	Life Limit	AMM TASK 52-13-22-900-801-A/400 Suppressed Requirement	No	3200 FH (±30 FH)	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 6307.7 (1720.1 rem.)
52-13-23-001	DIS - DISCARD OF MAIN DOOR BALANCING MECHANISM PINION SHAFT	Life Limit	AMM TASK 52-13-23-900-801-A/400	No	5600 FH	Not Applicable	
06. AMM CHAPTER 5-20-01: SPECIAL INTERVALS							
Special Inspection							

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
27-11-02-001	FNC - FUNCTIONAL CHECK OFAILERON CONTROL CABLES TENSION	Special Inspection	AMM TASK 27-11-02-720-801-A/500 NOTE: Additional tension check at the first 12 MO applicable for...	Yes	3200 FH (±30 FH) 60 MN (±1 MN) First 12 MN (±1 MN)	Date: 18/09/2021 Flight hours: 2854.7	Date: 30/09/2026 (in a year) Flight hours: 6054.7 (1467.1 rem.)
27-21-02-001	FNC - FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION	Special Inspection	AMM TASK 27-21-02-720-801-A/500 NOTE: Additional tension check at the first 12 MO applicable for...	Yes	3200 FH (±30 FH) 60 MN (±1 MN) First 12 MN (±1 MN)	Date: 18/09/2021 Flight hours: 2854.6	Date: 30/09/2026 (in a year) Flight hours: 6054.6 (1467 rem.)
27-31-02-001	FNC - FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION	Special Inspection	AMM TASK 27-31-02-720-801-A/500 NOTE: Additional tension check at the first 12 MO applicable for...	Yes	3200 FH (±30 FH) 60 MN (±1 MN) First 12 MN (±1 MN)	Date: 18/09/2021 Flight hours: 2854.7	Date: 30/09/2026 (in a year) Flight hours: 6054.7 (1467.1 rem.)
28-21-10-001	OPC - OPERATIONAL CHECK OF FUEL XFEED VALVE	Special Inspection	AMM TASK 28-21-10-710-801-A/500	Yes	12000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
30-21-02-001	FNC - FUNCTIONAL CHECK OF ENGINE ANTI-ICING PRESSURE TRANSDUCER	Special Inspection	AMM TASK 30-21-02-720-801-A/500 (LEFT AND RIGHT)	Yes	12000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
32-11-00-003	LUB - LUBRICATION OF MAIN LANDING GEAR	Special Inspection	AMM TASK 12-21-00-640-801-A/300	Yes	650 CYC (±30 CYC) 12 MN (±1 MN)	Date: 07/11/2024 Cycles: 3959	Date: 30/11/2025 (in 7 months) Cycles: 4609 (450 rem.)
32-11-03-004	SVC - SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER	Special Inspection	AMM TASK 12-14-02-610-802-A/300	Yes	650 CYC (±30 CYC) 12 MN (±1 MN)	Date: 07/11/2024 Cycles: 3959	Date: 30/11/2025 (in 7 months) Cycles: 4609 (450 rem.)
32-21-00-003	LUB - LUBRICATION OF NOSE LANDING GEAR	Special Inspection	AMM TASK 12-21-00-640-802-A/300	Yes	650 CYC (±30 CYC) 12 MN (±1 MN)	Date: 07/11/2024 Cycles: 3959	Date: 30/11/2025 (in 7 months) Cycles: 4609 (450 rem.)
32-21-05-004	SVC - SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER	Special Inspection	AMM TASK 12-14-03-610-802-A/300	Yes	650 CYC (±30 CYC) 12 MN (±1 MN)	Date: 07/11/2024 Cycles: 3959	Date: 30/11/2025 (in 7 months) Cycles: 4609 (450 rem.)
56-10-01-002	FNC - FUNCTIONAL CHECK (TORQUE) OF COPILOT WINDSHIELD ATTACHING BOLTS SN: 15022H1347 PN: NP-195301-4	Special Inspection	AMM TASK 56-10-00-720-801-A/500 NOTE: Threshold is applicable after Windshield/ Side Window installa...	Yes	1600 FH (±30 FH) First 800 FH (±30 FH)	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5004.7 (417.1 rem.)
56-10-01-002	FNC - FUNCTIONAL CHECK (TORQUE) OF COPILOT SIDE WINDOW ATTACHING BOLTS SN: 15013H0286 PN: NP-195302-4	Special Inspection	AMM TASK 56-10-00-720-801-A/500 NOTE: Threshold is applicable after Windshield/ Side Window installa...	Yes	1600 FH (±30 FH) First 800 FH (±30 FH)	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5004.7 (417.1 rem.)
56-10-01-002	FNC - FUNCTIONAL CHECK (TORQUE) OF PILOT WINDSHIELD ATTACHING BOLTS SN: 14322H5558 PN: NP-195301-3	Special Inspection	AMM TASK 56-10-00-720-801-A/500 NOTE: Threshold is applicable after Windshield/ Side Window installa...	Yes	1600 FH (±30 FH) First 800 FH (±30 FH)	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5004.7 (417.1 rem.)
56-10-01-002	FNC - FUNCTIONAL CHECK (TORQUE) OF PILOT SIDE WINDOW	Special Inspection	AMM TASK 56-10-00-720-801-A/500 NOTE: Threshold is applicable after Windshield/ Side Window installa...	Yes	1600 FH (±30 FH) First 800 FH (±30 FH)	Date: 27/09/2022 Flight hours:	Flight hours: 5004.7

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
PN: NP-195302-3							
Overhaul							
21-52-01-004	RST - RESTORATION (OVERHAUL) OF CDM COMPRESSOR SN: 662 PN: 1133640-8	Overhaul	AMM TASK 21-52-01-920-801-A/200 2000 FH or 2000 CDM Hours (As per Operator discretion)	Yes	2000 FH (±30 FH)	Date: 25/11/2024 Flight hours: 4338.1	Flight hours: 6338.1 (1750.5 rem.)
Life Limit							
21-52-01-002	DIS - DISCARD OF COMPRESSOR DRIVE MODULE BELT SN: 8011425045 PN: 1133636-3	Life Limit	AMM TASK 21-52-01-960-801-A/200 I: 2000 FH or I: 2000 CDM Hours (As per Operator discretion)	Yes	2000 FH (±30 FH)	Date: 27/09/2022 Flight hours: 3404.7	Flight hours: 5404.7 (817.1 rem.)
33-48-00-001	DIS - DISCARD LEFT NO. 1 NAVIGATION LIGHT SN: 000751 PN: 84004-7	Life Limit Airworthy	AMM TASK 33-48-00-960-801-A/200	Yes	12000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
33-48-00-001	DIS - DISCARD RIGHT NO. 2 NAVIGATION LIGHT SN: 000213 PN: 84075-2	Life Limit Airworthy	AMM TASK 33-48-00-960-801-A/200	Yes	12000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
33-48-00-001	DIS - DISCARD RIGHT NO. 1 NAVIGATION LIGHT SN: 000754 PN: 84004-7	Life Limit Airworthy	AMM TASK 33-48-00-960-801-A/200	Yes	12000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
33-48-00-001	DIS - DISCARD LEFT NO. 2 NAVIGATION LIGHT SN: 000185 PN: 84075-1	Life Limit Airworthy	AMM TASK 33-48-00-960-801-A/200	Yes	12000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 12000 (7412.4 rem.)
33-49-00-001	DIS - DISCARD NO. 2 STROBE LIGHT SN: 000303 PN: 84036-4	Life Limit Airworthy	AMM TASK 33-49-00-960-801-A/200	Yes	8000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 8000 (3412.4 rem.)
33-49-00-001	DIS - DISCARD NO. 1 STROBE LIGHT SN: 000371 PN: 84036-3	Life Limit Airworthy	AMM TASK 33-49-00-960-801-A/200	Yes	8000 FH (±30 FH)	Date: 22/09/2015 Flight hours: 0	Flight hours: 8000 (3412.4 rem.)
07. AMM CHAPTER 5-20-02: COMPONENT-RELATED INSPECTION TIME LIMITS							
Special Inspection							
24-36-01-004	FNC - FUNCTIONAL CHECK OF MAIN BATTERIES 1 AND 2	Special Inspection	AMM TASK 24-36-01-720-801-A/500 AIPC 24-36-01 NOTE: From the Installation Date	No	300 CYC (±30 CYC) 6 MN (±1 MN)	Not Applicable	
24-36-01-005	FNC - FUNCTIONAL CHECK OF MAIN BATTERIES 1 AND 2	Special Inspection	AMM TASK 24-36-01-720-801-A/500 AIPC 24-36-01 NOTE: From the Installation Date (Threshold 12 MO is...	No	6 MN (±1 MN) First 12 MN (±1 MN)	Not Applicable	
25-21-04-003	DET - DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG SYSTEM	Special Inspection	AMM TASK 25-21-04-210-801-A/600 AIPC 25-21-02 NOTE: From the Acft Maintenance Start Counting Date	Yes	48 MN (±1 MN)	Date: 18/09/2021	Date: 30/09/2025 (in 5 months)
25-21-04-004	OPC - OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY	Special Inspection	AMM TASK 25-21-04-710-801-A/500 NOTE: From the Acft Maintenance Start Counting Date	Yes	48 MN (±1 MN)	Date: 18/09/2021	Date: 30/09/2025 (in 5 months)
25-61-00-001	OPC - OPERATIONAL CHECK OF ELT SYSTEM SN: LX1100160043 PN: 51821502-02	Special Inspection	AMM TASK 25-61-00-710-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable...	Yes	12 MN	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
25-61-00-002	GVI - GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR	Special Inspection	AMM TASK 25-61-00-210-801-A/600 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable).	Yes	12 MN	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
PN: S1821502-02							
26-24-01-001	FNC - WEIGHT CHECK OF PORTABLE FIRE EXTINGUISHER	Special Inspection	AMM TASK 26-24-01-720-801-A/500	No	12 MN	Not Applicable	
26-24-01-004	FNC - WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER SN: 017957 PN: P3APP003010A	Special Inspection	AMM TASK 26-24-01-720-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable).	Yes	24 MN	Date: 07/11/2024	Date: 30/11/2026 (in 2 years)
26-24-01-004	FNC - WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER SN: 012985 PN: P3APP003010A	Special Inspection	AMM TASK 26-24-01-720-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable).	Yes	24 MN	Date: 07/11/2024	Date: 30/11/2026 (in 2 years)
33-52-01-001	FNC - FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 1 (COCKPIT UNDERFLOOR) SN: 007610 PN: 7450LS-00	Special Inspection	AMM TASK 33-52-01-720-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable...	Yes	12 MN <i>First</i> 18 MN	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
33-52-01-001	FNC - FUNCTIONAL CHECK OF EMERGENCY LIGHT BATTERY 2 (CENTER COMPT) SN: 007612 PN: 7450LS-00	Special Inspection	AMM TASK 33-52-01-720-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable...	Yes	12 MN <i>First</i> 18 MN	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
33-52-01-002	FNC - FUNCTIONAL CHECK OF EMERGENCY LIGHTS BATTERY	Special Inspection	AMM TASK 33-52-01-720-801-A/500 NOTE: From the Installation Date	No	6 MN (±1 MN)	Not Applicable	
34-11-00-001	FNC - FUNCTIONAL CHECK OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001) SN: C16786012532 PN: C16786DA01	Special Inspection	AMM TASK 34-11-00-720-801-A/500 NOTE: From the Last Accomplishment Date.	Yes	24 MN (±1 MN)	Date: 25/09/2023	Date: 30/09/2025 (in 5 months)
34-11-02-001	RST - RESTORATION (CLEANING) OF PITOT-STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001) SN: 312774 PN: 0856UT4	Special Inspection	AMM TASK 34-11-02-100-801-A/700 NOTE: From the Last Accomplishment Date.	Yes	24 MN (±1 MN)	Date: 25/09/2023	Date: 30/09/2025 (in 5 months)
34-52-00-001	FNC - FUNCTIONAL CHECK OF TRANSPONDER SYSTEM SN: NXE15066 PN: 9006000-55000	Special Inspection	AMM TASK 34-52-00-720-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable).	Yes	24 MN	Date: 25/09/2023	Date: 30/09/2025 (in 5 months)
35-02-01-001	FNC - FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR SN: 449998704 PN: 4441122-050	Special Inspection	AMM TASK 35-02-01-720-801-A/500 NOTE: From the Last Accomplishment Date (Tolerance NOT Applicable...	Yes	60 MN	Date: 16/08/2023	Date: 31/08/2028 (in 3 years)
35-11-02-001	DET - DETAILED VISUAL INSPECTION OF LEFT CREW SEATBELT	Special Inspection	AMM TASK 35-11-02-213-801-A/600 NOTE: From the Acft Maintenance Start Counting Date	Yes	24 MN (±1 MN)	Date: 25/09/2023	Date: 30/09/2025 (in 5 months)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
PN: 174232-93							
35-11-02-001	DET - DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK SN: 37217 PN: 174232-93	Special Inspection	AMM TASK 35-11-02-213-801-A/600 NOTE: From the Acft Maintenance Start Counting Date	Yes	24 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2026 (in 2 years)
35-11-02-003	DET - DETAILED VISUAL INSPECTION OF CREW OXYGEN MASKS	Special Inspection	AMM TASK 35-11-02-213-801-A/600 NOTE: From the Acft Maintenance Start Counting Date	No	12 MN (±1 MN)	Not Applicable	
Overhaul							
21-31-01-001	RST - RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) SN: 2119286-01554 PN: 2119286-10	Overhaul	AMM TASK 21-31-01-920-801-A/200 AIPC 21-31-01 NOTE: Based on Component TSN or TSO	Yes	5600 FH (±30 FH)	Date: 15/03/2022 Flight hours: 3107.7	Flight hours: 8707.7 (4120.1 rem.)
21-31-02-001	RST - RESTORATION (REPAIR) OF OUTFLOW VALVE SN: 103922-00474 PN: 103922-1	Overhaul	AMM TASK 21-31-02-920-801-A/200 AIPC 21-31-02 NOTE: Based on Component TSN or TSO	Yes	7200 FH (±30 FH)	Date: 08/01/2022 Flight hours: 3059.3	Flight hours: 10259.3 (5671.7 rem.)
24-31-01-001	STARTER GENERATOR - ENGINE 1 (RST - RESTORATION (OVERHAUL)) SN: S00279XL PN: 400SG180Q-4	Overhaul	AMM TASK 24-31-01-920-801-A/200 AIPC 24-31-01 NOTE: Based on Component TSN or TSO	Yes	800 FH (±30 FH)	Date: 09/08/2024 Flight hours: 4224.7	Flight hours: 5033.2 (445.6 rem.)
24-31-01-001	STARTER GENERATOR - ENGINE 2 (RST - RESTORATION (OVERHAUL)) SN: S04255 PN: 400SG180Q-4	Overhaul	AMM TASK 24-31-01-920-801-A/200 AIPC 24-31-01 NOTE: Based on Component TSN or TSO	Yes	800 FH (±30 FH)	Date: 09/08/2024 Flight hours: 4224.7	Flight hours: 5033.2 (445.6 rem.)
24-31-01-003	STARTER GENERATOR ENGINE 1 (RST - RESTORATION (OVERHAUL))	Overhaul	AMM TASK 24-31-01-920-801-A/200 AIPC 24-31-01 NOTE: Based on Component TSN or TSO	No	400 FH (±30 FH)	Not Applicable	
24-31-01-003	STARTER GENERATOR ENGINE 2 (RST - RESTORATION (OVERHAUL))	Overhaul	AMM TASK 24-31-01-920-801-A/200 AIPC 24-31-01 NOTE: Based on Component TSN or TSO	No	400 FH (±30 FH)	Not Applicable	
25-21-04-001	RST - RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY SN: A29JUL21-13 PN: 508358-415	Overhaul	AMM TASK 25-21-04-920-802-A/200 AIPC 25-21-02 NOTE: From the Manufacturing Date (Tolerance NOT...	Yes	84 MN	Date: 16/08/2021	Date: 31/08/2028 (in 3 years)
25-61-05-001	RST - RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE	Overhaul	AMM TASK 25-61-07-960-801-A/200 NOTE: From the Last Memory Replacement (Tolerance NOT Applicable)....	Yes	120 MN 16000 FH	Date: 22/09/2015 Flight hours: 0	Date: 30/09/2025 (in 5 months) Flight hours: 16000 (11412.4 rem.)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST SN: L6334700 PN: 636600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 25/04/2025	Date: 03/12/2029 (in 5 years)
25-62-	RST - RESTORATION	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or	Yes	60 MN	Date:	Date:

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	LIFE VEST SN: L6334625 PN: 63600-101				120 MN		(in 9 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST SN: L5961260 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 25/04/2025	Date: 30/09/2033 (in 8 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	No	60 MN First 120 MN	Not Applicable	
25-62-02-001	RST - RESTORATION (OVERHAUL) OF TOILET LIFE VEST SN: L6334703 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 30/04/2015	Date: 31/08/2034 (in 9 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF PILOT LIFE VEST	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 07/11/2024	Date: 30/11/2029 (in 5 years)
25-62-02-001	INSPECT INFANT LIFE VEST	Overhaul		Yes	60 MN	Date: 16/10/2020	Date: 31/10/2025 (in 6 months)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST SN: L5961259 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 25/04/2025	Date: 30/09/2033 (in 8 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST SN: L5961263 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 25/04/2025	Date: 30/09/2033 (in 8 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	No	60 MN First 120 MN	Not Applicable	
25-62-02-001	RST - RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST SN: L5961255 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 25/04/2025	Date: 30/09/2033 (in 8 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 07/11/2024	Date: 30/11/2029 (in 5 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST SN: L6334736 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 30/04/2025	Date: 31/08/2034 (in 9 years)
25-62-02-001	RST - RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST SN: L5965168 PN: 63600-101	Overhaul	AMM TASK 25-62-02-900-801-A/200 120 MO - For new or overhauled (re-vacuumed packed) Life Vest OR I...	Yes	60 MN First 120 MN	Date: 25/04/2025	Date: 31/10/2033 (in 8 years)
25-66-01-001	RST - RESTORATION (OVERHAUL) OF LIFE RAFT	Overhaul	AMM TASK 25-66-01-900-801-A/200 NOTE: From the Manufacturing Date (Tolerance NOT Applicable).	No	36 MN	Not Applicable	
32-11-01-001	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH) SN: 00313 PN: 2317-1100-405	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-11-01-002	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SN: 00317 PN: 2317-1100-406						Cycles: 12000 (7841 rem.)
32-11-02-001	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH) SN: 00463 PN: 2117-3000-409	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-11-02-002	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH) SN: 00696 PN: 2117-3000-409	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	12000 CYC (±30 CYC) 120 MN (±1 MN)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-11-03-001	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH) SN: 00675 PN: 2317-3000-403	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-11-03-002	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH) SN: 00677 PN: 2317-3000-403	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-11-04-001	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH) SN: 00317 PN: 2317-1500-405	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-11-04-002	RST - RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH) SN: 00319 PN: 2317-1500-406	Overhaul	AMM TASK 32-11-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-21-01-001	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY SN: 00327 PN: 2317-5100-403	Overhaul	AMM TASK 32-21-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-21-04-001	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY SN: 00322 PN: 2317-6500-403	Overhaul	AMM TASK 32-21-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-21-05-001	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER SN: 00332 PN: 2317-5170-403	Overhaul	AMM TASK 32-21-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-21-09-001	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY SN: 00328 PN: 2317-6000-403	Overhaul	AMM TASK 32-21-00-920-801-A/200 NOTE: From the Acft Maintenance Start Counting Date.	Yes	120 MN (±1 MN) 12000 CYC (±30 CYC)	Date: 22/09/2015 Cycles: 0	Date: 30/09/2025 (in 5 months) Cycles: 12000 (7841 rem.)
32-45-01-003	RST - RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR	Overhaul	AMM TASK 32-45-00-920-801-A/200 NOTE: Or at the next subsequent tire change after 1500 flight cycles...	Yes	1500 CYC (±30 CYC)	Date: 23/08/2023 Cycles:	Cycles: 5055 (896 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
PN: DAP00098-02							
32-45-01-003	RST - RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY SN: 5076TD PN: DAP00098-02	Overhaul	AMM TASK 32-45-00-920-801-A/200 NOTE: Or at the next subsequent tire change after 1500 flight cycles...	Yes	1500 CYC (±30 CYC)	Date: 23/08/2023 Cycles: 3555	Cycles: 5055 (896 rem.)
32-45-11-003	RST - RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY SN: 5079JS PN: DAP00099-02	Overhaul	AMM TASK 32-45-00-920-801-A/200 NOTE: Or at the next subsequent tire change after 1500 flight cycles...	Yes	1500 CYC (±30 CYC)	Date: 23/03/2023 Cycles: 3375	Cycles: 4875 (716 rem.)
35-11-02-002	RST - RESTORATION (OVERHAUL) OF CREW LEFT OXYGEN MASKS SN: 43043 PN: 174232-93	Overhaul	AMM TASK 35-11-02-920-801-A/200 NOTE: From the Manufacturing Date	Yes	3600 FH (±30 FH) 72 MN (±1 MN)	Date: 25/09/2023 Flight hours: 3860.7	Date: 30/09/2029 (in 4 years) Flight hours: 7460.7 (2873.1 rem.)
35-11-02-002	RST - RESTORATION (OVERHAUL) OF CREW RIGHT OXYGEN MASKS SN: 37217 PN: 174232-93	Overhaul	AMM TASK 35-11-02-920-801-A/200 NOTE: From the Manufacturing Date	Yes	3600 FH (±30 FH) 72 MN (±1 MN)	Date: 27/09/2022 Flight hours: 3404.7	Date: 30/09/2028 (in 3 years) Flight hours: 7004.7 (2417.1 rem.)
Life Limit							
24-36-01-003	DIS - DISCARD OF AFT MAIN BATTERY SN: G03234745 PN: 7638-48P	Life Limit	AMM TASK 24-36-01-960-801-A/200 NOTE: From the Installation Date	Yes	24 MN (±1 MN) 600 CYC (±30 CYC)	Date: 14/02/2025 Cycles: 4068	Date: 28/02/2027 (in 2 years) Cycles: 4668 (509 rem.)
24-36-01-003	DIS - DISCARD OF FORWARD MAIN BATTERY SN: G03242162 PN: 7639-34	Life Limit	AMM TASK 24-36-01-960-801-A/200 NOTE: From the Installation Date	Yes	24 MN (±1 MN) 600 CYC (±30 CYC)	Date: 14/02/2025 Cycles: 4068	Date: 28/02/2027 (in 2 years) Cycles: 4668 (509 rem.)
25-21-04-002	DIS - DISCARD OF SEAT BELT AIRBAG INFLATOR GAS CYLINDER SN: AS2D3FEYAAU PN: 510184-401	Life Limit	AMM TASK 25-21-04-960-801-A/200 AIPC 25-21-02 NOTE: From the Manufacturing Date (Tolerance NOT...	Yes	120 MN	Date: 15/03/2025	Date: 31/03/2035 (in 10 years)
25-61-04-001	DIS - DISCARD OF ELT BATTERY SN: 21010701 PN: S1820506-01C	Life Limit	AMM TASK 25-61-04-960-801-A/200 Discard according to Expiration Date (Tolerance NOT Applicable)	Yes		None	Date: 01/09/2027 (in 2 years)
25-62-01-001	VCK - VISUAL CHECK OF FIRST AID KIT PN: S6-01-0005-320	Life Limit	AMM TASK 25-62-01-200-801-A/600 Discard according to Expiration Date (Tolerance NOT Applicable).	Yes	12 MN	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
26-24-01-002	DIS - DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER SN: 012985 PN: P3APP003010A	Life Limit	AMM TASK 26-24-01-960-801-A/200 NOTE: From the Manufacturing Date (Tolerance NOT Applicable). PN:...	Yes	144 MN	Date: 03/09/2019	Date: 30/09/2031 (in 6 years)
26-24-01-002	DIS - DISCARD OF CABIN PORTABLE FIRE EXTINGUISHER SN: 017957 PN: P3APP003010A	Life Limit	AMM TASK 26-24-01-960-801-A/200 NOTE: From the Manufacturing Date (Tolerance NOT Applicable). PN:...	Yes	144 MN	Date: 12/11/2019	Date: 30/11/2031 (in 7 years)
26-24-01-003	DIS - DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER	Life Limit	AMM TASK 26-24-01-960-801-A/200 NOTE: From the Manufacturing Date (Tolerance NOT Applicable).	No	120 MN	Not Applicable	
26-24-01-003	DIS - DISCARD OF CABIN PORTABLE FIRE EXTINGUISHER	Life Limit	AMM TASK 26-24-01-960-801-A/200 NOTE: From the Manufacturing Date (Tolerance NOT Applicable).	No	120 MN	Not Applicable	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
31-31-03-001	DIS - DISCARD OF CVDJR/ULB BATTERY SN: AT111042 PN: DK120/90	Life Limit	AMM TASK 31-31-03-960-801-A/200 Discard according to Expiration Date (Tolerance NOT Applicable).	Yes		Date: 29/10/2024	Date: 29/02/2032 (in 7 years)
31-33-03-001	DIS - DISCARD OF FDR/ULB BATTERY SN: AT111041 PN: DK120/90	Life Limit	AMM TASK 31-33-03-960-801-A/200 Discard according to Expiration Date (Tolerance NOT Applicable). PN...	Yes		Date: 29/10/2024	Date: 29/02/2032 (in 7 years)
33-52-01-003	DIS - DISCARD OF LH REAR EMERGENCY LIGHT BATTERY	Life Limit	AMM TASK 33-52-01-960-801-A/200 NOTE: From the Manufacturing Date PN:7450LS-00 SN:005517	No	60 MN (±1 MN)	Not Applicable	
33-52-01-003	DIS - DISCARD OF RH FWD EMERGENCY LIGHT BATTERY	Life Limit	AMM TASK 33-52-01-960-801-A/200 NOTE: From the Manufacturing Date PN:7450LS-00 SN:005476	No	60 MN (±1 MN)	Not Applicable	
35-02-01-003	DIS - DISCARD OF OXYGEN CYLINDER	Life Limit	AMM TASK 35-02-01-960-801-A/200 NOTE: From the Manufacturing Date (Tolerance NOT Applicable).	Yes	180 MN	Date: 16/08/2023	Date: 31/08/2038 (in 13 years)
35-31-01-001	DIS - DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)	Life Limit	AMM TASK 35-31-01-960-801-A/200 NOTE: From the Manufacturing Date PN:MR-10022NEMB SN:E1503502	Yes	126 MN (±1 MN)	Date: 22/09/2015	Date: 31/03/2026 (in a year)
08. CAMO REQUIREMENTS							
Equipment							
AA/01	SEMI-ANNUAL EQUIPMENT CHECK	Equipment	Equipment check according to the checklist. https://docs.google.com/spreadsheets/d/1fECdjtlhfom8iwS...	Yes	6 MN (±1 MN)	None	Date: 30/04/2025 (6 days ago)
31. PWC EMM (PART 3072702): 5-20-00 ON-WING LOW UTILIZATION ENGINE INSPECTION							
Special Inspection							
72-00-00-280-818	ON-WING LOW UTILIZATION ENGINE INSPECTION	Special Inspection	(1) A low utilization engine is defined as an engine that has not been subject to disassembly and...	No	11 YR (±1 MN)	Not Applicable	
32. PWC EMM (PART NO.3072702) : 5-20-00 TABLE 1							
Inspection							
	ENGINE N.1 800 H INSPECTION / 12 MONTHS	Inspection	Scheduled Maintenance Checks according to the EMM PART NO.3072702-Table 1	Yes	800 FH (±30 FH) 12 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/11/2025 (in 7 months) Flight hours: 5122.3 (534.7 rem.)
	ENGINE N.2 800 H INSPECTION / 12 MONTHS	Inspection	Scheduled Maintenance Checks according to the EMM PART NO.3072702-Table 1	Yes	800 FH (±30 FH) 12 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/11/2025 (in 7 months) Flight hours: 5122.3 (534.7 rem.)
Special Inspection							
71-00-00-760-823	ENGINE NO. 1 - DO TLD CLEARING PROCEDURE	Special Inspection	OPC After the inspection is completed, the LTD status should be cleared. (Ref. Task 71-00-00-760-...	Yes	630 FH 12 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/11/2025 (in 7 months) Flight hours: 4952.3 (364.7 rem.)
71-00-00-760-823	ENGINE NO. 2 - DO TLD CLEARING PROCEDURE	Special Inspection	OPC After the inspection is completed, the LTD status should be cleared. (Ref. Task 71-00-00-760-...	Yes	630 FH 12 MN (±1 MN)	Date: 07/11/2024 Flight hours: 4322.3	Date: 30/11/2025 (in 7 months) Flight hours: 4952.3 (364.7 rem.)
72-00-00-640-802	ENGINE NO. 2 - CHECK THE ENGINE OIL LEVEL	Special Inspection Pilot Maintenance	Daily/Preflight (Ref. NOTE). NOTE: These actions are performed by the flight crew as part of the...	Yes		Date: 30/10/2019	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
72-00-00-640-802	ENGINE NO. 1 - CHECK THE ENGINE OIL LEVEL	Special Inspection Pilot Maintenance	Daily/Preflight (Ref. NOTE). NOTE: These actions are performed by the flight crew as part of the...	Yes		Date: 30/10/2019	
72-00-00-640-806, 72-00-00-640-806-01	ENGINE NO.2 - OIL CHANGE INTERVAL	Special Inspection	Oil quality is to be monitored on-condition and analyzed periodically as observations warrant	Yes	On-Condition	Date: 30/10/2019	
72-00-00-640-806, 72-00-00-640-806-01	ENGINE NO.1 - OIL CHANGE INTERVAL	Special Inspection	Oil quality is to be monitored on-condition and analyzed periodically as observations warrant	Yes	On-Condition	Date: 30/10/2019	
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION PROCEDURES	Special Inspection Airworthy	EEC Fault Isolation	Yes	12 MN 630 FH	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION PROCEDURES	Special Inspection Airworthy	EEC Fault Isolation	Yes	12 MN 630 FH	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
72-60-01-212-801	ENGINE NO.1 - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES	Special Inspection		Yes	1200 FH	Date: 07/11/2024 Flight hours: 4324.3	Flight hours: 5524.3 (936.7 rem.)
72-60-01-212-801	ENGINE NO.2 - INSPECT THE AGB HYDRAULIC PUMP GEARSHAFT SPLINES	Special Inspection		Yes	1200 FH	Date: 07/11/2024 Flight hours: 4324.3	Flight hours: 5524.3 (936.7 rem.)
73-10-05-212-801	ENGINE NO.2 - INSPECT THE FUEL FILTER	Special Inspection	GVI	Yes	12 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
73-10-05-212-801	ENGINE NO.1 - INSPECT THE FUEL FILTER	Special Inspection	GVI	Yes	12 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
77-20-02-750-801	DO AN OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM	Special Inspection	OPC	No	1600 FH 36 MN	Not Applicable	
77-20-02-750-801	DO AN OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM ENGINE 1	Special Inspection	OPC	Yes	2500 FH (±50 FH) 36 MN (+1 MN)	Date: 27/09/2022 Flight hours: 3359.4	Date: 30/09/2025 (in 5 months) Flight hours: 5859.4 (1271.8 rem.)
77-20-02-750-801	DO AN OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM ENGINE 2	Special Inspection	OPC	Yes	2500 FH (±50 FH) 36 MN (+1 MN)	Date: 27/09/2022 Flight hours: 3404.7	Date: 30/09/2025 (in 5 months) Flight hours: 5904.7 (1317.1 rem.)
Life Limit							
72-00-00-000-802	DISCARD THE GAS GENERATOR CASE - RH	Life Limit	Ref. Overhaul Manual	No	10000 CYC	Not Applicable	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
72-00-000-802	DISCARD THE GAS GENERATOR CASE - RH	Life Limit	Ref. Overhaul Manual	Yes	10000 CYC	Date: 26/09/2015 Cycles: 0	Cycles: 10000 (5841 rem.)
72-00-000-802	DISCARD THE GAS GENERATOR CASE - LH	Life Limit	Ref. Overhaul Manual	Yes	10000 CYC	Date: 26/09/2015 Cycles: 0	Cycles: 10000 (5841 rem.)
72-00-000-802	DISCARD THE GAS GENERATOR CASE - LH	Life Limit	Ref. Overhaul Manual	No	10000 CYC	Not Applicable	
72-00-51-030-002	DISCARD HP TURBINE NUT AND KEYWASHER-AT OVERHAUL - RH	Life Limit	Ref. Overhaul Manual	Yes	5000 FH (± 100 FH)	Date: 27/05/2015 Flight hours: 0	Flight hours: 5000 (412.4 rem.)
72-00-51-030-002	DISCARD HP TURBINE NUT AND KEYWASHER-AT OVERHAUL - LH	Life Limit	Ref. Overhaul Manual	Yes	5000 FH (± 100 FH)	Date: 27/05/2015 Flight hours: 0	Flight hours: 5000 (412.4 rem.)
73-10-04-000-801	REMOVAL OF FUEL MANIFOLD ADAPTER-ASSEMBLIES - LH	Life Limit Airworthy		Yes	9900 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 9900 (5741 rem.)
73-10-04-000-801	REMOVAL OF FUEL MANIFOLD ADAPTER-ASSEMBLIES - RH	Life Limit Airworthy		Yes	9900 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 9900 (5741 rem.)
73-10-05-000-801,73-10-05-400-801	DISCARD THE FUEL FILTER - LH	Life Limit Airworthy	DIS	Yes	800 FH	Date: 07/11/2024 Flight hours: 4324.3	Flight hours: 5124.3 (536.7 rem.)
73-10-05-000-801,73-10-05-400-801	DISCARD THE FUEL FILTER - RH	Life Limit Airworthy	DIS	Yes	800 FH	Date: 07/11/2024 Flight hours: 4324.3	Flight hours: 5124.3 (536.7 rem.)
79-20-01-000-801,79-20-01-400-801	DISCARD THE OIL FILTER - LH	Life Limit Airworthy	DIS	Yes	800 FH	Date: 07/11/2024 Flight hours: 4324.3	Flight hours: 5124.3 (536.7 rem.)
79-20-01-000-801,79-20-01-400-801	DISCARD THE OIL FILTER - RH	Life Limit Airworthy	DIS	Yes	800 FH	Date: 07/11/2024 Flight hours: 4324.3	Flight hours: 5124.3 (536.7 rem.)
34. PWC EMM (PART NO.3072702): 00-00-00 TABLE 2: PW535E / PW535E1 ROTOR COMPONENTS-SERVICE LIFE							
Life Limit							
72-00-000-802	NO. 1 ENGINE - LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL SN: PKAAA605365 PN: 3073356-01	Life Limit Airworthy		Yes	30000 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 30000 (25841 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
72-00-000-802	NO. 2 ENGINE - LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL SN: PKAAA609012 PN: 3073356-01	Life Limit Airworthy		Yes	30000 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 30000 (25841 rem.)
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR SN: A003M242 PN: 3073311-01	Life Limit Airworthy		Yes	15000 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 15000 (10841 rem.)
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR SN: A003M4Y1 PN: 3073311-01	Life Limit Airworthy		Yes	15000 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 15000 (10841 rem.)
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR SN: TXA1D4810 PN: 3073292-01	Life Limit Airworthy		Yes	15000 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 15000 (10841 rem.)
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR SN: TXA1D4695 PN: 3073292-01	Life Limit Airworthy		Yes	15000 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 15000 (10841 rem.)
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR SN: A003M3CB PN: 3072981-01	Life Limit Airworthy		Yes	13500 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR SN: A003LLE0 PN: 3072981-01	Life Limit Airworthy		Yes	13500 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR SN: EAAD000R249 PN: 3056210-01	Life Limit Airworthy		Yes	13500 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR SN: EAAD000R132 PN: 3056210-01	Life Limit Airworthy		Yes	13500 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK SN: A003M5Y0 PN: 3053812-01	Life Limit Airworthy		Yes	13500 CYC	Date: 27/12/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK SN: A003M8MX PN: 3053812-01	Life Limit Airworthy		Yes	13500 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK SN: A003M2C7 PN: 3053743-01	Life Limit Airworthy		Yes	13500 CYC	Date: 27/12/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK SN: A003MEWX PN: 3053743-01	Life Limit Airworthy		Yes	13500 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 13500 (9341 rem.)

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK SN: A003LHDP PN: 3053331-01	Life Limit Airworthy		Yes	10000 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 10000 (5841 rem.)
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK SN: A003M5WL PN: 3053331-01	Life Limit Airworthy		Yes	10000 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 10000 (5841 rem.)
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER SN: A003M3BX PN: 3052661-01	Life Limit Airworthy		Yes	13500 CYC	Date: 21/06/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER SN: EAAD000R328 PN: 3052661-01	Life Limit Airworthy		Yes	13500 CYC	Date: 27/05/2015 Cycles: 0	Cycles: 13500 (9341 rem.)
35. PWC EMM (PART NO.3072702): 5-20-00 ENGINE OVERHAUL							
Overhaul							
05-20-00-210-801	ENGINE OVERHAUL RH SN: PCE-DG0616 PN: PW535E	Overhaul Airworthy	P/N: PW535E S/N: PCE-DG0616 (1) The TBO for the PW535E series engines is 5000 flight hours. An...	Yes	5000 FH (±100 FH)	Date: 23/07/2015 Flight hours: 0	Flight hours: 5000 (412.4 rem.)
05-20-00-210-801	ENGINE OVERHAUL LH SN: PCE-DG0603 PN: PW535E	Overhaul Airworthy	P/N: PW535E S/N: PCE-DG0603 (1) The TBO for the PW535E series engines is 5000 flight hours. An...	Yes	5000 FH (±100 FH)	Date: 23/07/2015 Flight hours: 0	Flight hours: 5000 (412.4 rem.)
41. SPECIAL MAINTENANCE IN ACCORDANCE WITH REQUIREMENTS OF THE COMPETENT AUTHORITY CAA-ST-092-6-/07							
Special Inspection							
EASA SIB No: 2019-09	ELT INSPECTION AND OPERATIONAL CHECK	Special Inspection	ELT Inspection and operational check (according to EASA SIB No: 2019-09)	No	12 MN	Not Applicable	
	AIRCRAFT WEIGHING AND BALANCING	Special Inspection	airplane operated under Part-CAT	Yes	48 MN	Date: 25/09/2023	Date: 30/09/2027 (in 2 years)
	AIRCRAFT WEIGHING AND BALANCING	Special Inspection	airplane operated under Part-NCC	No	72 MN	Not Applicable	
	IFR RADIO-COMMUNICATION AND NAVIGATION EQUIPMENT TEST	Special Inspection Airworthy	In accordance with point paragraph I of Appendix A to CAA-ST-092-6-/07.	Yes	12 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
	MAGNETIC COMPASS SWING COMPENSATION	Special Inspection	In accordance with point paragraph I of Appendix A to CAA-ST-092-6-/07.	Yes	12 MN (±1 MN)	Date: 07/11/2024	Date: 30/11/2025 (in 7 months)
	PITOT-STATIC SYSTEM, ALTIMETER AND ALTITUDE ENCODER TEST	Special Inspection Airworthy	In accordance with point paragraph I of Appendix A to CAA-ST-092-6-/07. After any disconnect/conne...	Yes	On-Condition	Date: 26/09/2015	
	PITOT-STATIC SYSTEM, ALTIMETER AND ALTITUDE ENCODER TEST	Special Inspection	In accordance with Appendix A to CAA-ST-092-6-/07. Airplanes operated under IFR	No	24 MN	Not Applicable	
	SECONDARY RADAR TRANSPONDER TEST	Special Inspection	(according to EASA SIB No: 2011-15)	No	24 MN	Not Applicable	
61. AIRWORTHINESS DIRECTIVE							
Airworthiness Directive							
	2012-03-01	Airworthiness Directive	Rudder, Elevator, Ailerons, and their Tabs - Inspection	No		Date: 22/09/2015	

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	2015-01-01	Airworthiness Directive	Outboard Wing Leading Edge Piccolo Tubes Installation - Inspection	No			Not Applicable
	2014-04-01	Airworthiness Directive	Brake Assembly - Inspection NOT APPLICABLE - TO P/N INSTALLED PN DAP000097-03 EQUIPPED	No			Not Applicable
	2016-04-02	Airworthiness Directive	Optimized Performance Analyzer (OPERA) Software Configuration / Airplane Flight Manual (AFM) Limitat...	No			Not Applicable
	2016-05-01	Airworthiness Directive	Passenger Seat Attachment Fittings - Inspection	No			Not Applicable
	2017-11-01	Airworthiness Directive	Aileron, Rudder and Elevator Trim Tab - Inspection / Rework	No			Not Applicable
	2020-09-01	Airworthiness Directive	Control Surface Mass-balance Weights and Attachments - Inspection / Replacement	Yes		Date: 23/10/2020	
	2023-04-01	Airworthiness Directive	Garmin G3000 Avionics System - Software Update N/A DUE TO SB505-31-0023 PREVIOUSLY COMPLIED WITH	No			Not Applicable
	2023-05-03R2	Airworthiness Directive	Monuments Structural Reinforcements / Replacement of Fasteners	No			Not Applicable
	2023-07-01	Airworthiness Directive	Refreshment Center and Forward Cabinet - Modification	Yes		None	Date: 30/09/2025 (in 5 months)
	CF-2023-60 PARA B - REPLACE THE BOLTS P/N MS9696 AND P/N MS9489-06 WITH NEW AT THE NEXT SHEDULED HSI OR OVH	Airworthiness Directive	Gas generator case to turbine support case retaining bolts – Inadequate fatigue life (HSI or Engine...	Yes		None	Flight hours: 5000 (412.4 rem.)

92. DATABASE

Database Update

ELECTRONIC CHARTS ACCORDING TO 14-DAY CHART CYCLE SERIALS WITH CHARTVIEW OR FLITECHARTS	Database Update Pilot Maintenance	Perform electronic chart update: Garmin Perspective – MFD bottom card. Note: Operation with outdate...	Yes	14 D (-7 D)	Date: 30/04/2025	Date: 14/05/2025 (in 9 days)
NAVIGATION DATABASE UPDATE ACCORDING TO 28-DAY AIRAC CYCLE	Database Update Pilot Maintenance	Perform navigation database update: Garmin Perspective – update bothPFD and MFD with SD cards. Note...	Yes	28 D (-5 D)	Date: 16/04/2025	Date: 14/05/2025 (in 9 days)
SAFETAXI, AIRPORT DIRECTOR AND OBSTACLE UPDATE ACCORDING TO 56-DAY CYCLE SERIALS WITH PERSPECTIVE AVIONICS	Database Update Pilot Maintenance	Perform Safetaxi, Airport Directory, Obstacles updated – both PFD and MFD bottom cards. Note:...	Yes	56 D (-5 D)	Date: 15/04/2025	Date: 10/06/2025 (in a month)
TERRAIN DATABASE (WHEN UPDATE AVAILABLE) SERIALS WITH PERSPECTIVE AND SERIALS WITH AVIDYNE WITH TAWS	Database Update	Perform Terrain database update: • Garmin Perspective – both PFD/MFD bottom card Note: Operation...	Yes		Date: 10/08/2020	

PILOT MAINTENANCE

Special Inspection

CHECK HYDRAULICK LEVEL	Special Inspection Pilot Maintenance	Without spoilers - https://www.youtube.com/watch?v=olOdF70G1yY With spoilers - https://www.youtube....	Yes	15 D	Date: 26/04/2025	Date: 11/05/2025 (in 6 days)
------------------------	---	--	-----	------	---------------------	------------------------------------

NOT ASSIGNED

Special Inspection

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
24-36-005	CAPACITY CHECK FORWARD MAIN BATTERY	Special Inspection	After initial installation, Gill requires the first capacity check of the battery to be performed...	Yes	6 MN First 12 MN	Date: 14/02/2025	Date: 28/02/2026 (in 10 months)
24-36-005	CAPACITY CHECK AFT MAIN BATTERY	Special Inspection	After initial installation, Gill requires the first capacity check of the battery to be performed...	Yes	6 MN First 12 MN	Date: 14/02/2025	Date: 28/02/2026 (in 10 months)
720060	NO. 2 ENGINE - HOT SECTION INSPECTION	Special Inspection		Yes	2500 FH (+50 FH)	Date: 23/10/2020 Flight hours: 2406.2	Flight hours: 4906.2 (318.6 rem.)
720060	NO. 1 ENGINE - HOT SECTION INSPECTION	Special Inspection		Yes	2500 FH (+50 FH)	Date: 23/10/2020 Flight hours: 2451.4	Flight hours: 4951.4 (363.8 rem.)
	DOWNLOAD AND SUBMIT CMC DATA	Special Inspection Pilot Maintenance		Yes	15 D	Date: 27/04/2025	Date: 12/05/2025 (in 7 days)
Airworthiness Directive							
2014-19-01	2014-19-01	Airworthiness Directive	We are superseding an airworthiness directive (AD) 2013-22-20 for Embraer S.A. Model EMB-505 airpla...	No			Not Applicable
2016-22-02	2016-22-02	Airworthiness Directive	We are adopting a new airworthiness directive (AD) for Embraer S.A. Models EMB- 500 and EMB-505...	No			Not Applicable
2018-07-10	2018-07-10	Airworthiness Directive	We are adopting a new airworthiness directive (AD) for Embraer S.A. Models EMB- 500 and EMB-505...	No			Not Applicable
2020-05-03	2020-05-03	Airworthiness Directive	Aircraft Flight Manual - Operational Envelope Temperature / Minimum Airspeed Limitation - Amendment	Yes		Date: 24/06/2020	
2021-0185R2	2021-0185R2	Airworthiness Directive	Within 30 days after the effective date of this AD, or within 12 months after the last inspection,...	Yes	12 MN	None	Date: 30/09/2025 (in 5 months)
2021-24-21	2021-24-21	Airworthiness Directive	The FAA is adopting a new airworthiness directive (AD) for certain Embraer S.A. Model EMB-500 and...	No			Not Applicable
2022-05-12	2022-05-12	Airworthiness Directive	The FAA is superseding Airworthiness Directive (AD) 2020-12-08 for all Embraer S.A. Model EMB-505...	No			Not Applicable
2023-05-03R01	2023-05-03R01	Airworthiness Directive	Analyzes carried out identified that some of the monuments installed on Embraer model EMB-505 aircra...	No			Not Applicable
2023-10-02	2023-10-02	Airworthiness Directive	The FAA is superseding Airworthiness Directive (AD) 2021-23-12, which applied to all transport and...	No			Not Applicable
2023-21-04	2023-21-04	Airworthiness Directive	The FAA is adopting a new airworthiness directive (AD) for certain Embraer S.A. (Embraer) Model EMB...	No			Not Applicable
2023-21-06	2023-21-06	Airworthiness Directive	The FAA is correcting an airworthiness directive (AD) that published in the Federal Register . That...	No			Not Applicable
2023-22-11	2023-22-11	Airworthiness Directive	The FAA is adopting a new airworthiness directive (AD) for certain Embraer S.A. (Embraer) Model EMB...	No			Not Applicable
	BR-2023-02-01R3	Airworthiness Directive	Flight Controls - Aileron Autopilot Servo Mount Clutch Retaining Bolt - Replacement	Yes	36 MN	Date: 23/03/2023	Date: 31/03/2026 (in a year)
	EASA AD BR-2025-04-01	Airworthiness Directive		No			Not Applicable
Service Bulletin							
	SB505-00-0001-REV01 PART 1 + PART 2	Service Bulletin Recommended	REMOVAL OF ICING LIMITATION ABOVE 30,000 FT	No			Not Applicable
	SB505-00-0002	Service Bulletin Optional	FAA CERTIFICATION REQUIREMENTS	No			Not Applicable
	SB505-00-0003	Service	GENERAL - ANAC CERTIFICATION REQUIREMENTS	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
		Optional					
	SB505-00-0004-REV01	Service Bulletin Optional	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION	No			Not Applicable
	SB505-00-0005 PART 1 + PART 2	Service Bulletin Recommended	GENERAL - INSPECTION OF THE TURNBUCKLES	No			Not Applicable
	SB505-00-0006-REV06	Service Bulletin Optional	SB505-00-0006-REV06 - GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR...	No			Not Applicable
	SB505-00-0007 PART 1 + PART 2	Service Bulletin Optional	GENERAL - VIBRATION DATA RECORD INSTALLATION/REMOVAL	No			Not Applicable
	SB505-00-0008-REV28	Service Bulletin Optional	GENERAL - DESIGN WEIGHT INCREASE FOR OPERATING RANGE	No			Not Applicable
	SB505-00-0009-REV03	Service Bulletin Optional	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS	No			Not Applicable
	SB505-00-0010-REV02 PART 1	Service Bulletin Optional	GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0010-REV02 PART 2	Service Bulletin Optional	GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0011	Service Bulletin Optional	GENERAL - CONVERSION FROM FAA TO ANAC CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0012	Service Bulletin Optional	GENERAL - G3000 - CUSTOMIZED UNITS CONFIGURATION (IMPERIAL UNITS)	No			Not Applicable
	SB505-00-0013-REV02	Service Bulletin Optional	GENERAL - G1000 - CONVERSION FROM EASA TO FAA CERTIFICATION BA	No			Not Applicable
	SB505-00-0014-REV04	Service Bulletin Optional	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0015	Service Bulletin Optional	GENERAL - G3000 - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS RE	No			Not Applicable
	SB505-00-0016-REV03	Service Bulletin Optional	GENERAL - G3000 - CONVERSION FROM FAA TO TCCA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0017-REV09 PART 1	Service Bulletin Optional	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION B	No			Not Applicable
	SB505-00-0017-REV09 PART 2	Service Bulletin Recommended	GENERAL - G3000 - CONVERSION FROM FAA TO EASA CERTIFICATION BA	No			Not Applicable
	SB505-00-0018-REV13	Service Bulletin Optional	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS FOR AIRCRAFT EQUIPPED WITH...	No			Not Applicable
	SB505-00-0019	Service Bulletin Recommended	GENERAL - INSPECTION OF THE TURNBUCKLES	No			Not Applicable
	SB505-00-0020-REV03	Service Bulletin Optional	GENERAL - CONVERSION FROM EASA TO ANAC CERTIFICATION BASIS	No			Not Applicable
	SB505-00-0021-REV02	Service Bulletin Optional	GENERAL - CONVERSION FROM FAA TO ANAC CERTIFICATION BASIS REQU	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-00-0022	Service Bulletin Optional	GENERAL - G3000 - CONVERSION FROM TCCA TO FAA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0023	Service Bulletin Optional	GENERAL - INSTALLATION OF FUSELAGE REGISTRATION PLACARD	No			Not Applicable
	SB505-00-0025	Service Bulletin Optional	GENERAL - REGISTRATION PLATE REPLACEMENT	No			Not Applicable
	SB505-00-0026	Service Bulletin Recommended	GENERAL - W201 HARNESS ROUTING IMPROVEMENT	No			Not Applicable
	SB505-00-0027	Service Bulletin Recommended	GENERAL - W302 HARNESS ROUTING IMPROVEMENT	No			Not Applicable
	SB505-00-0028-REV01 PART 1	Service Bulletin Optional	GENERAL - PROVISIONS FOR DIVAN INSTALLATION	No			Not Applicable
	SB505-00-0028-REV01 PART 2	Service Bulletin Recommended	GENERAL - PROVISIONS FOR DIVAN INSTALLATION	No			Not Applicable
	SB505-00-0029-REV01	Service Bulletin Optional	GENERAL - G1000- CONVERSION FROM FAA TO TCCA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-00-0030	Service Bulletin Optional	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT)	No			Not Applicable
	SB505-00-0031	Service Bulletin Optional	GENERAL - CONVERSION FROM ANAC TO EASA CERTIFICATION BASIS REQUIREMENTS	No			Not Applicable
	SB505-21-0001	Service Bulletin Recommended	AIR CONDITIONING - CPCS CONTROLLER (ECMU) HARDWARE CORRECTION	No			Not Applicable
	SB505-21-0002 PART 1	Service Bulletin Recommended	AIR CONDITIONING - INSPECTION/CORRECTION OF THE BAGGAGE HEATING WIRING	No			Not Applicable
	SB505-21-0002 PART 2	Service Bulletin Recommended	AIR CONDITIONING - INSPECTION/CORRECTION OF THE BAGGAGE HEATING WIRING	No			Not Applicable
	SB505-21-0003	Service Bulletin Recommended	AIR CONDITIONING - PRESSURE RELIEF VALVE (PRV) REPLACEMENT	No			Not Applicable
	SB505-21-0004	Service Bulletin Recommended	AIR CONDITIONING - REPLACEMENT OF THE CABIN EVAPORATOR	No			Not Applicable
	SB505-21-0005-REV01	Service Bulletin Recommended	AIR CONDITIONING - REPLACEMENT OF FLOW CONTROL SHUT OFF VALVE (FCSOV)	No			Not Applicable
	SB505-21-0006	Service Bulletin Recommended	AIR CONDITIONING - COCKPIT AIR DISTRIBUTION IMPROVEMENTS	No			Not Applicable
	SB505-21-0007	Service Bulletin Recommended	AIR CONDITIONING - REPLACEMENT OF ECS TEMPERATURE CONTROLLER TC-6	No			Not Applicable
	SB505-21-0008	Service Bulletin Recommended	AIR CONDITIONING - WATER DRAIN INSTALLATION TO THE BLEED LINE	No			Not Applicable
	SB505-21-0009 PART 1	Service Bulletin Recommended	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION SYSTEM	No			Not Applicable
	SB505-21-0009 PART 2	Service Bulletin Recommended	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-21-0009 PART 3	Service Bulletin Recommended	AIR CONDITIONING - IMPROVEMENTS TO COCKPIT AIR DISTRIBUTION SYSTEM	No			Not Applicable
	SB505-21-0010-REV04	Service Bulletin Recommended	AIR CONDITIONING - WATER DRIPPING PROTECTION	No			Not Applicable
	SB505-21-0011	Service Bulletin Recommended	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT	No			Not Applicable
	SB505-21-0012-REV05	Service Bulletin Optional	AIR CONDITIONING - AFT CARGO COMPARTMENT HEATING SYSTEM - INSTALLATION	No			Not Applicable
	SB505-21-0013	Service Bulletin Optional	AIR CONDITIONING - CHECK VALVE AND MUFFLER MODIFICATION	No			Not Applicable
	SB505-21-0014	Service Bulletin Optional	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT	No			Not Applicable
	SB505-21-0015-REV03	Service Bulletin Optional	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) - REPLACEMENT	Yes			None
	SB505-22-0001-REV01 PART 1	Service Bulletin Recommended	AUTO FLIGHT - VENTRAL RUDDER - WATER DEFLECTOR INSTALLATION AND SERVO ACTUATORS MOUNTING BOLTS...	No			Not Applicable
	SB505-22-0001-REV01 PART 2	Service Bulletin Recommended	AUTO FLIGHT - VENTRAL RUDDER - WATER DEFLECTOR INSTALLATION	No			Not Applicable
	SB505-22-0002	Service Bulletin Recommended	AUTO FLIGHT - AUTOPILOT SERVOS CONTROL-CABLES INSPECTION	No			Not Applicable
	SB505-22-0004-REV04	Service Bulletin Recommended	AUTO FLIGHT - REPLACEMENT OF THE AILERON SERVO ASSEMBLY BOLT	Yes		Date: 23/03/2023	
	SB505-22-0004-REV05	Service Bulletin Recommended	Aircraft that have complied with the previous issue of this bulletin do not need any additional...	Yes		None	Not Applied
	SB505-22-0006	Service Bulletin Optional	AUTO FLIGHT - AILERON SERVO ASSEMBLY - PARTS REPLACEMENT	Yes		None	
	SB505-22-0007	Service Bulletin Optional	AUTO FLIGHT - AUTOTHROTTLE INSTALLATION	No			Not Applicable
	SB505-22-0007-REV02	Service Bulletin Optional	AUTO FLIGHT - AUTOTHROTTLE INSTALLATION	No			Not Applicable
	SB505-23-0001 PART 1	Service Bulletin Recommended	COMMUNICATIONS - PROTECTION TO HF (HIGH FREQUENCY COMMUNICATION SYSTEM) WIRES	No			Not Applicable
	SB505-23-0001 PART 2	Service Bulletin Recommended	COMMUNICATIONS - PROTECTION TO HF (HIGH FREQUENCY COMMUNICATION SYSTEM) WIRES	No			Not Applicable
	SB505-23-0002	Service Bulletin Optional	COMMUNICATIONS - INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (DLMS)	No			Not Applicable
	SB505-23-0003-REV03	Service Bulletin Optional	COMMUNICATIONS - INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (	No			Not Applicable
	SB505-23-0004-REV03 PART 1	Service Bulletin Optional	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNI...	No			Not Applicable
	SB505-23-0004-REV03 PART 2	Service Bulletin Optional	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNI...	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-23-0004-REV03 PART 3	Service Bulletin Optional	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNI...	No			Not Applicable
	SB505-23-0004-REV03 PART 4	Service Bulletin Mandatory	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER -TO-PILOT DATA LINK COMMUNI...	No			Not Applicable
	SB505-23-0005-REV04 PART 1	Service Bulletin Optional	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION)	No			Not Applicable
	SB505-23-0005-REV04 PART 2	Service Bulletin Mandatory	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT D	No			Not Applicable
	SB505-23-0006-REV05 PART 1	Service Bulletin Optional	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION)	No			Not Applicable
	SB505-23-0006-REV05 PART 2	Service Bulletin Optional	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION)	No			Not Applicable
	SB505-23-0006-REV05 PART 3	Service Bulletin Mandatory	COMMUNICATIONS - G3000 - INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION)	No			Not Applicable
	SB505-23-0007	Service Bulletin Recommended	COMMUNICATIONS - NEW STATIC DISCHARGER ON AILERON - INSTALLATION	No			Not Applicable
	SB505-23-0008	Service Bulletin Optional	COMMUNICATIONS - HF AND SELCAL SYSTEM INSTALLATION	No			Not Applicable
	SB505-24-0001	Service Bulletin Optional	ELECTRICAL POWER - AC ELECTRICAL OUTLET CONNECTOR PROTECTION	No			Not Applicable
	SB505-24-0003	Service Bulletin Recommended	ELECTRICAL POWER - NEW ATTACHMENT FOR THE AP AILERON SERVO ACTUATOR ELECTRICAL CABLE	No			Not Applicable
	SB505-24-0004 PART 1	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE ELECTRICAL BONDING JUMPER	No			Not Applicable
	SB505-24-0004 PART 2	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE ELECTRICAL BONDING JUMPER	No			Not Applicable
	SB505-24-0005	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE STARTERS GENERATORS	No			Not Applicable
	SB505-24-0006 PART 1	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS	No			Not Applicable
	SB505-24-0006 PART 2	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS	No			Not Applicable
	SB505-24-0006 PART 3	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS	No			Not Applicable
	SB505-24-0007-REV01	Service Bulletin Recommended	ELECTRICAL POWER - MODIFICATION OF THE EMERGENCY BUS CONTACTOR (EBC) 1 GROUND WIRE	No			Not Applicable
	SB505-24-0008 PART 1	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU	No			Not Applicable
	SB505-24-0008 PART 2	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU	No			Not Applicable
	SB505-24-0008 PART 3	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-24-0009	Service Bulletin Recommended	ELECTRICAL POWER - BATTERIES AND GPU RECEPTACLE POWER CABLES - INSPECTION AND SPACER INSTALLATION	No			Not Applicable
	SB505-24-0010	Service Bulletin Recommended	ELECTRICAL POWER - INSTALLATION OF SPACER BETWEEN HARNESS W111 AND STRUCTURE	No			Not Applicable
	SB505-24-0011	Service Bulletin Recommended	ELECTRICAL POWER - INSTALLATION OF BRACKET TO REMOVE CHAFING BETWEEN W207 AND PEDAL M	No			Not Applicable
	SB505-24-0012	Service Bulletin Recommended	ELECTRICAL POWER - CHANGE IN W201 HARNESS ROUTING IN THE COCKPIT	No			Not Applicable
	SB505-24-0014-REV01	Service Bulletin Recommended	ELECTRICAL POWER - GCU (GENERATOR CONTROL UNIT) REPLACEMENT	No			Not Applicable
	SB505-24-0015-REV05	Service Bulletin Recommended	ELECTRICAL POWER - REPLACEMENT OF THE MAIN BATTERY_2	No			Not Applicable
	SB505-24-0017-REV11	Service Bulletin Optional	ELECTRICAL POWER - NEW STARTER GENERATOR INSTALLATION	No			Not Applicable
	SB505-24-0019	Service Bulletin Optional	ELECTRICAL POWER - POWER OUTLETS WITH USB - INSTALLATION IN SIDELEDGES	No			Not Applicable
	SB505-25-0001	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - LAVATORY TOILET LID IMPROVEMENT	No			Not Applicable
	SB505-25-0002	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS	No			Not Applicable
	SB505-25-0003	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - INSPECTION OF THE FASTEN SEAT BELTS PLACARDS	No			Not Applicable
	SB505-25-0004-REV08	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION	No			Not Applicable
	SB505-25-0005	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE RH/LH SIDELEDGE LOWER PANEL	No			Not Applicable
	SB505-25-0006	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - COCKPIT CURTAIN IMPROVEMENT	No			Not Applicable
	SB505-25-0007	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - LH FORWARD CABINET - INSTALLATION OF ARM LINK ON THE TRAY COMPARTMENT DOOR	No			Not Applicable
	SB505-25-0008	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - CURTAIN PLACARD INSTALLATION IN THE COCKPIT	No			Not Applicable
	SB505-25-0009	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - PLACARDS AND EXTERNAL INSCRIPTIONS REPLACEMENT - CZECH/ENGLISH LANGUAGE	No			Not Applicable
	SB505-25-0010	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - INTERIOR CONFIGURATION CONVERSION FROM WENGUE TO SAPELE	No			Not Applicable
	SB505-25-0011-REV05	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT	No			Not Applicable
	SB505-25-0012	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS	No			Not Applicable
	SB505-25-0014	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - LEFT HAND FORWARD CABINET - REPLACEMENT	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-25-0015	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - STOP INSTALLATION TO THE LH FORWARD CABINET	No			Not Applicable
	SB505-25-0016-REV01	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - ENHANCED SEAT INSTALLATION	No			Not Applicable
	SB505-25-0017	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - CARPET REPLACEMENT	No			Not Applicable
	SB505-25-0018	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - FULL FUNCTION SEAT INSTALLATION	No			Not Applicable
	SB505-25-0019	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - AFT LAVATORY CABINET REPLACEMENT	No			Not Applicable
	SB505-25-0020	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION	No			Not Applicable
	SB505-25-0021 PART 1	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - DECAL AND TECHNICAL INSCRIPTION - PORTUGUESE/ENGLISH	No			Not Applicable
	SB505-25-0021 PART 2	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - DECAL AND TECHNICAL INSCRIPTION - PORTUGUESE/ENGLISH	No			Not Applicable
	SB505-25-0022-REV01	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - PASSENGER CABIN CARPET REPLACEMENT	No			Not Applicable
	SB505-25-0023-REV01	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - INSTALLATION OF THE ELT (EMERGENCY LOCATOR TRANSMITTER) / NAV (NAVIGATION)	No			Not Applicable
	SB505-25-0024-REV03 PART 1	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPOSITIONING OF THE HATCHET	No			Not Applicable
	SB505-25-0024-REV03 PART 2	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPOSITIONING OF THE HATCHET	No			Not Applicable
	SB505-25-0025-REV01 PART 1	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF CUSHION OF BELTED TOILET AND DIVAN	No			Not Applicable
	SB505-25-0025-REV01 PART 2	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF CUSHION OF BELTED TOILET AND DIVAN	No			Not Applicable
	SB505-25-0027-REV06	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - CENTRAL MIRROR INSTALLATION IN AFT LAVATORY PARTITION	Yes		None	Not Applied
	SB505-25-0028	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS	No			Not Applicable
	SB505-25-0029-REV01 PART 1	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - FRENCH/...	No			Not Applicable
	SB505-25-0029-REV01 PART 2	Service Bulletin Optional	REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCR	No			Not Applicable
	SB505-25-0030-REV03	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - HATCHET INSTALLATION	No			Not Applicable
	SB505-25-0031-REV03	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - PROTECTIVE BREATHING EQUIPMENT INSTALLATION	No			Not Applicable
	SB505-25-0032-REV05	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-25-0033-REV01	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS - POLISH/ENGLISH LANGUAGE	No			Not Applicable
	SB505-25-0034	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - HINDI/...	No			Not Applicable
	SB505-25-0035-REV02	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - IDENTIFICATION PLATE INSTALLATION AT THE MAIN ENTRY DOOR	No			Not Applicable
	SB505-25-0036-REV03	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - GERMAN/...	No			Not Applicable
	SB505-25-0037	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - LH FWD REFRESHMENT CENTER INSTALLATION	No			Not Applicable
	SB505-25-0038-REV04 PART 1	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - DIVAN INSTALLATION	No			Not Applicable
	SB505-25-0038-REV04 PART 2	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - DIVAN INSTALLATION	No			Not Applicable
	SB505-25-0038-REV04 PART 3	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - DIVAN INSTALLATION	No			Not Applicable
	SB505-25-0039	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS SPANISH - ENGLISH	No			Not Applicable
	SB505-25-0040	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - PORTUGUESE...	No			Not Applicable
	SB505-25-0041	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - FIRST AID KIT REPLACEMENT - ANAC	No			Not Applicable
	SB505-25-0042	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - SEAT TRACK STUD PLUNGER REPLACEMENT	No			Not Applicable
	SB505-25-0043	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - FLOOR SILL CARPET INSTALLATION	No			Not Applicable
	SB505-25-0043	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - FLOOR SILL CARPET INSTALLATION	No			Not Applicable
	SB505-25-0044	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - LH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION	Yes		None	Date: 30/09/2025 (in 5 months)
	SB505-25-0045	Service Bulletin Recommended	EQUIPMENT/FURNISHINGS - LATERAL LONGITUDINAL SHAFTS OF THE SEAT - INSPECTION	No			Not Applicable
	SB505-25-0046-REV03 PART 1	Service Bulletin Mandatory	EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFOR	No			Not Applicable
	SB505-25-0046-REV03 PART 2	Service Bulletin Mandatory	EQUIPMENT/FURNISHINGS - RH REFRESHMENT CENTER AND LH FORWARD CABINET REINFORCEMENTS INSTALLATION	No			Not Applicable
	SB505-25-0048-REV03	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - INSTALLATION OF DNA SEATS	No			Not Applicable
	SB505-25-0049	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - CARPET REPLACEMENT	No			Not Applicable
	SB505-25-0050	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - DIVAN CUSHIONS - REPLACEMENT	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-25-0051	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - PASSENGER CABIN CARPET - REPLACEMENT	No			Not Applicable
	SB505-25-0052-REV01	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - EQUIPMENT/FURNISHINGS - LH REFRESHMENT CENTER INSTALLATION	No			Not Applicable
	SB505-25-0053 PART 1	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - COCKPIT SUNSHADE COVER - INSTALLATION	Yes		None	
	SB505-25-0053 PART 2	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - COCKPIT SUNSHADE COVER - INSTALLATION	Yes		None	
	SB505-25-0054 PART 1	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - COCKPIT SUN VISOR - REMOVAL	Yes		None	Date: 30/09/2025 (in 5 months)
	SB505-25-0054 PART 2	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - COCKPIT SUN VISOR - REMOVAL	Yes		None	Date: 30/09/2025 (in 5 months)
	SB505-25-0055	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - COCKPIT SUN VISOR (BLUE FILM) - INSTALLATION	Yes		None	
	SB505-25-0057	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - COCKPIT SUNSHADE - INSTALLATION	Yes		None	Date: 30/09/2025 (in 5 months)
	SB505-25-0059	Service Bulletin Optional	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE INTERNAL PLACARDS AND EXTERNAL INSCRIPTIONS - ENGLISH/...	No			Not Applicable
	SB505-26-0001	Service Bulletin Recommended	FIRE PROTECTION - INSPECTION/REPLACEMENT OF THE BAGGAGE-COMPARTMENT SMOKE DETECTOR	No			Not Applicable
	SB505-26-0002-REV01	Service Bulletin Recommended	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT	No			Not Applicable
	SB505-26-0003-REV01	Service Bulletin Optional	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT	No			Not Applicable
	SB505-26-0004-REV01	Service Bulletin Optional	FIRE PROTECTION - PORTABLE HALON FIRE EXTINGUISHER REPLACEMENT	Yes		Date: 20/05/2020	
	SB505-26-0005	Service Bulletin Optional	FIRE PROTECTION - PORTABLE HALON FIRE EXTINGUISHER - REPLACEMENT	Yes		None	Not Applied
	SB505-27-0001-REV01	Service Bulletin Optional	FLIGHT CONTROLS - CONTROL YOKE MAP HOLDER REPLACEMENT	No			Not Applicable
	SB505-27-0001-REV01	Service Bulletin Optional	FLIGHT CONTROLS - CONTROL YOKE MAP HOLDER REPLACEMENT	No			Not Applicable
	SB505-27-0002	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE)	No			Not Applicable
	SB505-27-0003-REV03	Service Bulletin Optional	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS	No			Not Applicable
	SB505-27-0004	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF THE MULTIFUNCTION SPOILER-SURFACE SENSOR, CONTROL WHEEL, AND PCU	No			Not Applicable
	SB505-27-0005	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF THE TRIM ACTUATOR CONTROLLER (TAC)	No			Not Applicable
	SB505-27-0006	Service Bulletin Recommended	FLIGHT CONTROLS - RUDDER GUST LOCK ACTUATOR INSPECTION/REPLACEMENT	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-27-0007	Service Bulletin Mandatory	FLIGHT CONTROLS - ELECTRICAL WIRING MODIFICATION IN THE COPILOT CONTROL WHEEL CONNECTOR 2	No			Not Applicable
	SB505-27-0008-REV02 PART 1	Service Bulletin Optional	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK	No			Not Applicable
	SB505-27-0008-REV02 PART 2	Service Bulletin Optional	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK	No			Not Applicable
	SB505-27-0009-REV01	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007 TO FCE 462900...	No			Not Applicable
	SB505-27-0010	Service Bulletin Recommended	FLIGHT CONTROLS - INSPECTION / REPLACEMENT OF THE FLAP SYSTEM LEVER	No			Not Applicable
	SB505-27-0011-REV04 PART 1	Service Bulletin Optional	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION	No			Not Applicable
	SB505-27-0011-REV04 PART 2	Service Bulletin Optional	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION	No			Not Applicable
	SB505-27-0011-REV04 PART 3	Service Bulletin Optional	FLIGHT CONTROLS - ACTIVATION OF THE FLAP FULL POSITION	No			Not Applicable
	SB505-27-0012 PART 1	Service Bulletin Recommended	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING	No			Not Applicable
	SB505-27-0012 PART 2	Service Bulletin Recommended	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING	No			Not Applicable
	SB505-27-0012 PART 3	Service Bulletin Recommended	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING	No			Not Applicable
	SB505-27-0013	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE 462900-1005/-0007/ 462900-1009...	No			Not Applicable
	SB505-27-0014	Service Bulletin Optional	FLIGHT CONTROLS - CHECK OF LOCK WASHERS OF THE TOGGLE LINKS FOR INSTALLATION DAMAGE	No			Not Applicable
	SB505-27-0017	Service Bulletin Recommended	FLIGHT CONTROLS - RUDDER GUST LOCK SYSTEM - REPLACEMENT OF GUST LOCK LEVER AND ACTUATOR	No			Not Applicable
	SB505-27-0018-REV05 PART 1	Service Bulletin Optional	FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE	No			Not Applicable
	SB505-27-0018-REV05 PART 2	Service Bulletin Optional	FLIGHT CONTROLS - ACTIVATION OF THE STEEP APPROACH MODE	No			Not Applicable
	SB505-27-0019	Service Bulletin Recommended	FLIGHT CONTROLS - G3000 - REMOVAL OF THE STALL WARNING DISCRETE SIGNAL FROM THE REMOTE AUDIO CONTROL...	No			Not Applicable
	SB505-27-0022-REV01	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF THE FLIGHT CONTROL ELECTRONICS (FCE1 AND FCE2)	No			Not Applicable
	SB505-27-0023-REV01 PART 1	Service Bulletin Recommended	FLIGHT CONTROLS - PROVISIONING OF THE ELECTRICAL HARNESS TO RUDDER GUST LOCK ANNUNCIATION SYSTEM	No			Not Applicable
	SB505-27-0023-REV01 PART 2	Service Bulletin Recommended	FLIGHT CONTROLS - PROVISIONING OF THE ELECTRICAL HARNESS TO RUDDER GUST LOCK ANNUNCIATION SYSTEM	Yes		Date: 23/09/2019	
	SB505-27-0024-REV01	Service Bulletin Recommended	FLIGHT CONTROLS - REPLACEMENT OF HORIZONTAL-STABILIZER PITCH TRIM ACTUATOR	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-27-0025	Service Bulletin Recommended	FLIGHT CONTROLS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT	No			Not Applicable
	SB505-27-0026	Service Bulletin Recommended	FLIGHT CONTROLS - CABLES INSPECTION	No			Not Applicable
	SB505-27-0029 PART 1 + PART 2	Service Bulletin Recommended	FLIGHT CONTROLS - AILERON PULLEYS INSPECTION	No			Not Applicable
	SB505-27-0030	Service Bulletin Optional	FLIGHT CONTROLS - PTA POSITION SENSOR FILTER INSTALLATION	Yes		Date: 23/03/2023	
	SB505-27-0031-REV03 PART 1 + PART 2	Service Bulletin Optional	FLIGHT CONTROLS - FLIGHT CONTROL ELECTRONICS (FCE) CONTROL PANEL INSTALLATION	No			Not Applicable
	SB505-27-0032-REV01 PART 1 - PART 9	Service Bulletin Recommended	FLIGHT CONTROLS - ELEVATOR, AILERON AND RUDDER PIANO HINGE AND PIN INSPECTIONS AND REPLACEMENT	No			Not Applicable
	SB505-27-0034-REV01	Service Bulletin Mandatory	FLIGHT CONTROLS - INSPECTION AND ADJUSTMENT OF THE BACKLASH OF THE HORIZONTAL STABILIZER	No			Not Applicable
	SB505-27-A028-REV02 PART 1 + PART 2	Service Bulletin Recommended	FLIGHT CONTROLS - AILERON TRIM TAB, RUDDER TRIM TAB AND ELEVATOR AUTOTAB INSPECTION AND TORQUE	No			Not Applicable
	SB505-28-0001-REV03 PART 1	Service Bulletin Recommended	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC	No			Not Applicable
	SB505-28-0001-REV03 PART 2	Service Bulletin Recommended	FUEL - INSTALLATION OF THE FUEL CONTACTOR DC	No			Not Applicable
	SB505-28-0002	Service Bulletin Recommended	FUEL - INSTALLATION OF THE FUEL PUMP DC CONTACTOR	No			Not Applicable
	SB505-28-0003 PART 1 + PART 2	Service Bulletin Recommended	FUEL - MOTIVE FLOW LINE AND FEED LINE FUEL TUBES INSPECTION AND REPLACEMENT	No			Not Applicable
	SB505-28-0004	Service Bulletin Recommended	FUEL - FUEL TANK AND FUEL SYSTEM COMPONENTS - INSPECTION	No			Not Applicable
	SB505-29-0001	Service Bulletin Recommended	HYDRAULIC POWER - HYDRAULIC RESERVOIR REPLACEMENT	No			Not Applicable
	SB505-29-0002	Service Bulletin Recommended	HYDRAULIC POWER - INSPECTION/FLUSHING OF THE HYDRAULIC SYSTEM LINE	No			Not Applicable
	SB505-29-0003 PART 1 + PART 2	Service Bulletin Recommended	HYDRAULIC POWER - HYDRAULIC RESERVOIR INSPECTION / REPLACEMENT	No			Not Applicable
	SB505-29-0005	Service Bulletin Optional	HYDRAULIC POWER - HYDRAULIC ACCUMULATOR REPLACEMENT	No			Not Applicable
	SB505-29-0006-REV01	Service Bulletin Recommended	HYDRAULIC POWER - INSPECTION OF ENGINE DRIVEN PUMP ASSEMBLY	No			Not Applicable
	SB505-29-0007-REV01 PART 1 + PART 2	Service Bulletin Recommended	HYDRAULIC POWER - HYDRAULIC LINES (ALUMINUM TUBES) INSPECTION AND REPLACEMENT	No			Not Applicable
	SB505-30-0001	Service Bulletin Recommended	ICE AND RAIN PROTECTION - INSPECTION / UPLOAD OF ICE DETECTOR FUNCTION	No			Not Applicable
	SB505-30-0002-REV02	Service Bulletin Recommended	ICE AND RAIN PROTECTION - RH PITOT STANDBY HEATER - SIGNAL RESISTORS - REMOVAL	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-30-0004	Service Bulletin Optional	ICE AND RAIN PROTECTION - ICE DETECTOR INSTALLATION	No			Not Applicable
	SB505-30-A003	Service Bulletin Recommended	ICE AND RAIN PROTECTION - INSPECTION OF THE PICCOLO TUBE INSTALLATION	No			Not Applicable
	SB505-31-0001	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43 AVIONICS SOFTWARE AN	No			Not Applicable
	SB505-31-0002-REV32	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION SYSTEM	No			Not Applicable
	SB505-31-0003-REV08	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL)	No			Not Applicable
	SB505-31-0004-REV02	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 54 AVIONICS SOFTWARE AND CMC LOAD 10...	No			Not Applicable
	SB505-31-0005 PART 1	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11	No			Not Applicable
	SB505-31-0005 PART 2	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11	No			Not Applicable
	SB505-31-0006-REV02	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - FDR - FLIGHT DATA RECORDER SYSTEM INSTALLATION	No			Not Applicable
	SB505-31-0007	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.16 AVIONICS SOFTWARE, CMC LOAD 0.98 AND...	No			Not Applicable
	SB505-31-0008	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.42 AVIONICS SOFTWARE, CMC LOAD 1.0 AND...	No			Not Applicable
	SB505-31-0009	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - FDR (FLIGHT DATA RECORDER) AND IMPACT SWITCH INSTALLATION	No			Not Applicable
	SB505-31-0010	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - G1000 - DOWNGRADE FROM LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11...	No			Not Applicable
	SB505-31-0011	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - CONVERSION OF PROVISIONED AIRCRAFT FROM G1000 AVIONICS CONFIGURATION...	No			Not Applicable
	SB505-31-0012	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.51 AVIONICS SOFTWARE, CMC LOAD 3.02 AND...	No			Not Applicable
	SB505-31-0013	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.4	No			Not Applicable
	SB505-31-0014	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - FDR (FLIGHT DATA RECORDER) AND FDR IMPACT SWITCH REMOVAL	No			Not Applicable
	SB505-31-0015 - REV01	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 4.60 AVIONICS SOFTW	No			Not Applicable
	SB505-31-0016-REV02	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - REPLACEMENT OF THE GTC 570 COOLING FAN	No			Not Applicable
	SB505-31-0017-REV02	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 13.25 AVIONICS SOFTWARE, CMC LOAD V4.04...	Yes		Date: 06/09/2016	
	SB505-31-0018	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 83.25 AVIONICS SOFTWARE AND CMC LOAD 13.3	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-31-0019-REV04	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - CVDR REPLACEMENT	No			Not Applicable
	SB505-31-0020	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - DEACTIVATION OF CVDR BULK ERASE	No			Not Applicable
	SB505-31-0021 - REV01 PART 1	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3...	Yes		Date: 20/05/2020	
	SB505-31-0021 - REV01 PART 2	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.00 AVIONICS SOFTWARE, CMC LOAD V4.3...	Yes		Date: 20/05/2020	
	SB505-31-0022 PART 1	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.00 AVIONICS SOFTWARE AND CMC LOAD 14....	No			Not Applicable
	SB505-31-0022 PART 2	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.00 AVIONICS SOFTWARE AND CMC LOAD 14....	No			Not Applicable
	SB505-31-0023-REV02	Service Bulletin Mandatory	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 18.10 AVIONICS SOFTWARE AND CMC LOAD V5....	Yes		Date: 29/03/2019	
	SB505-31-0024	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - CVDR - DATA RATE CORRECTION	No			Not Applicable
	SB505-31-0025-REV01 PART 1	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.10 AVIONICS SOFTWARE AND CMC LOAD 15.0...	No			Not Applicable
	SB505-31-0025-REV01 PART 2	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.10 AVIONICS SOFTWARE AND CMC LOAD 15.0...	No			Not Applicable
	SB505-31-0025-REV01 PART 3	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 92.10 AVIONICS SOFTWARE AND CMC LOAD 15.0...	No			Not Applicable
	SB505-31-0026	Service Bulletin Recommended	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 26.01 AVIONICS SOFTWARE AND CMC LOAD V7....	No			Not Applicable
	SB505-31-0027	Service Bulletin Optional	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G3000 LOAD 29.07 AVIONICS SOFTWARE AND CMC LOAD V8....	No			Not Applicable
	SB505-32-0001	Service Bulletin Recommended	LANDING GEAR - REPLACEMENT OF THE NLG SHOCK STRUT PLACARD	No			Not Applicable
	SB505-32-0002-REV01	Service Bulletin Optional	LANDING GEAR - BRAKE SYSTEM TROUBLESHOOTING	No			Not Applicable
	SB505-32-0003-REV02	Service Bulletin Recommended	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT	No			Not Applicable
	SB505-32-0004	Service Bulletin Optional	LANDING GEAR - RETURN AIRCRAFT HYDRAULIC LINE TO ORIGINAL CONFIGURATION	No			Not Applicable
	SB505-32-0005-REV02	Service Bulletin Recommended	LANDING GEAR - REPLACEMENT OF THE BRAKE CONTROL UNIT (BCU DAP00100-03/-04/-05 TO BCU DAP00100-06)	No			Not Applicable
	SB505-32-0006	Service Bulletin Recommended	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT	No			Not Applicable
	SB505-32-0008	Service Bulletin Recommended	LANDING GEAR - CORRECTION OF THE WHEEL AXLE TORQUE OF MLG AND NLG	No			Not Applicable
	SB505-32-0011 PART 1 + PART 2	Service Bulletin Recommended	LANDING GEAR - PRECAUTIONARY INSPECTION IN THE CARBON DISCS OF THE MLG BRAKE	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-32-0012	Service Bulletin Recommended	LANDING GEAR - MAIN LANDING GEAR LOCKING ACTUATOR INSPECTION	No			Not Applicable
	SB505-32-0013	Service Bulletin Optional	LANDING GEAR - REPLACEMENT OF THE BRAKE ASSEMBLY	No			Not Applicable
	SB505-32-0014 PART 1 + PART 2	Service Bulletin Mandatory	LANDING GEAR - MLG LOCKING ACTUATOR - CAMBER ANGLE ALTERATION AND NUT REPLACEMENT	No			Not Applicable
	SB505-32-0015-REV01	Service Bulletin Recommended	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT	No			Not Applicable
	SB505-32-0016-REV01	Service Bulletin Optional	LANDING GEAR - SPIN BRAKE PAD REMOVAL	No			Not Applicable
	SB505-32-0017 PART 1 + PART 2 + PART 3	Service Bulletin Recommended	LANDING GEAR - EMERGENCY AND NORMAL BRAKE,DOWN LOCK ACTUATOR,RETRACTION AND EXTENSION HYDR	No			Not Applicable
	SB505-32-0018-REV01 PART 1 + PART 2	Service Bulletin Recommended	LANDING GEAR - INSPECTION ON THE MLG TRAILING ARM	Yes		Date: 08/03/2016	
	SB505-32-0019-REV02	Service Bulletin Recommended	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT	Yes		Date: 21/09/2017	
	SB505-32-0020	Service Bulletin Recommended	LANDING GEAR - INSPECTION OF THE AXLE AND REPLACEMENT OF THE BUSHING OF THE MAIN LANDING GEAR	No			Not Applicable
	SB505-32-0021	Service Bulletin Recommended	LANDING GEAR - EMERGENCY/PARKING BRAKE VALVE INSPECTION AND REPLACEMENT	No			Not Applicable
	SB505-33-0002	Service Bulletin Recommended	LIGHTS - REPLACEMENT OF LIGHTS CONTROL PANEL	No			Not Applicable
	SB505-33-0003/02 PART 1	Service Bulletin Recommended	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH	No			Not Applicable
	SB505-33-0003/02 PART 2	Service Bulletin Recommended	LIGHTS - INSTALLATION OF THE EMERGENCY LIGHTS INERTIAL SWITCH	No			Not Applicable
	SB505-33-0004-REV02 PART 1	Service Bulletin Optional	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION	No			Not Applicable
	SB505-33-0004-REV02 PART 1	Service Bulletin Optional	LIGHTS - NEW EMERGENCY LIGHTING SYSTEM INSTALLATION	No			Not Applicable
	SB505-33-0005	Service Bulletin Recommended	LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 TO PN 6434-00	No			Not Applicable
	SB505-33-0006	Service Bulletin Optional	LIGHTS - EXIT SIGN REPLACEMENT - CZECH/ENGLISH LANGUAGE	No			Not Applicable
	SB505-33-0007	Service Bulletin Recommended	LIGHTS - REPLACEMENT OF THE EMERGENCY LIGHTING SYSTEM BATTERY FROM PN 5434-00 OR PN 6434-00 TO PN...	No			Not Applicable
	SB505-33-0008	Service Bulletin Optional	LIGHTS - EXIT SIGN REPLACEMENT - HINDI/ENGLISH LANGUAGE	No			Not Applicable
	SB505-33-0009	Service Bulletin Optional	LIGHTS - EXIT IDENTIFIER-SIGNS INSTALLATION	No			Not Applicable
	SB505-33-0010	Service Bulletin Optional		No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-34-0002	Service Bulletin Recommended	NAVIGATION - INTERFERENCE BETWEEN AHRS UNIT2 AND HARNESS W102	No			Not Applicable
	SB505-34-0003-REV08 PART 1	Service Bulletin Optional	NAVIGATION - ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS)	No			Not Applicable
	SB505-34-0003-REV08 PART 2	Service Bulletin Mandatory	ACTIVATION OF THE CHARTVIEW (JEPPESEN ELECTRONIC CHARTS)	No			Not Applicable
	SB505-34-0006-REV01	Service Bulletin Optional	NAVIGATION - IASP (INTEGRATED AIR DATA AND STALL PROTECTION PROBE) REPLACEMENT	No			Not Applicable
	SB505-34-0007-REV04	Service Bulletin Optional	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - INSTALLATION	No			Not Applicable
	SB505-34-0008	Service Bulletin Optional	NAVIGATION - ADF (AUTOMATIC DIRECTION FINDER) SYSTEM - REMOVAL	No			Not Applicable
	SB505-34-0009	Service Bulletin Optional	NAVIGATION - INSTALLATION OF THE TCAS (TRAFFIC CREW ALERT SYSTEM) II AND RADAR ALTIMETER SYSTEMS	No			Not Applicable
	SB505-34-0010-REV22 PART 1	Service Bulletin Optional	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0010-REV22 PART 2	Service Bulletin Recommended	NAVIGATION - G1000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0011-REV20 PART 1	Service Bulletin Optional	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0011-REV20 PART 2	Service Bulletin Optional	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	Yes			None
	SB505-34-0011-REV20 PART 3	Service Bulletin Optional	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0011-REV20 PART 4	Service Bulletin Recommended	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0011-REV20 PART 5	Service Bulletin Recommended	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0011-REV20 PART 6	Service Bulletin Optional	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	No			Not Applicable
	SB505-34-0011-REV20 PART 7	Service Bulletin Optional	NAVIGATION - G3000 - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION	Yes			None
	SB505-34-0012-REV07	Service Bulletin Optional	NAVIGATION - INSTALLATION OF THE RUNWAY INCURSION/EXCURSION AWARENESS AND AVOIDANCE SYSTEM - SURFACE...	No			Not Applicable
	SB505-34-0013-REV09	Service Bulletin Optional	NAVIGATION - INSTALLATION OF THE REACTIVE WINDSHEAR DETECTION SYSTEM	No			Not Applicable
	SB505-34-0014-REV02	Service Bulletin Optional	NAVIGATION - GROUND CLUTTER SUPPRESSION/TURBULENCE DETECTION SYSTEM ACTIVATION	No			Not Applicable
	SB505-34-0015	Service Bulletin Optional	NAVIGATION - INSTALLATION OF THE TCAS (TRAFFIC CREW ALERT SYSTEM) II AND XPDR (TRANSPONDER) 1/2...	No			Not Applicable
	SB505-34-0016	Service Bulletin Optional	NAVIGATION - INSTALLATION OF THE DME (DISTANCE MEASURING EQUIPMENT) SYSTEM	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-34-0017-REV01	Service Bulletin Optional	NAVIGATION - G1000 - REPLACEMENT OF SATELLITE WEATHER AND RADIO RECEIVER	No			Not Applicable
	SB505-34-0018	Service Bulletin Optional	NAVIGATION - G3000 - REPLACEMENT OF SATELLITE WEATHER AND RADIO RECEIVER	No			Not Applicable
	SB505-34-0019-REV01	Service Bulletin Optional	NAVIGATION - REPLACEMENT OF THE WEATHER RADAR	No			Not Applicable
	SB505-34-0020-REV01	Service Bulletin Optional	NAVIGATION - NXT-600 NACV PARAMETER ADJUSTMENT	No			Not Applicable
	SB505-34-0021	Service Bulletin Optional	NAVIGATION - G1000-GROUND CLUTTER SUPPRESSION/TURBULENCE DETECTION SYSTEM ACTIVATION	No			Not Applicable
	SB505-34-0022	Service Bulletin Optional	NAVIGATION - PREDICTIVE WINDSHEAR ACTIVATION	No			Not Applicable
	SB505-34-0023	Service Bulletin Optional	NAVIGATION - RUNWAY OVERRUN AND AWARENESS ALERTING SYSTEM (ROAAS) ACTIVATION	No			Not Applicable
	SB505-34-0024	Service Bulletin Mandatory	NAVIGATION - RADIO ALTIMETER SYSTEM - BAND-PASS FILTER INSTALLATION - G1000 SYSTEM	No			Not Applicable
	SB505-34-0025	Service Bulletin Recommended	NAVIGATION - RADIO ALTIMETER SYSTEM - BAND-PASS FILTER INSTALLATION - G3000 SYSTEM	Yes		None	Date: 30/09/2025 (in 5 months)
	SB505-34-0026	Service Bulletin Optional	NAVIGATION - AUTOMATIC 3D VOLUMETRIC SCANNING FUNCTION REMOVAL	No			Not Applicable
	SB505-34-0027	Service Bulletin Recommended	NAVIGATION - RADIO ALTIMETER SYSTEM - BAND-PASS FILTER INSTALLATION FOR AIRCRAFT WITH ELECTRICAL...	No			Not Applicable
	SB505-34-0029	Service Bulletin Optional	NAVIGATION - AUTOMATIC 3D VOLUMETRIC SCANNING FUNCTION INSTALLATION	No			Not Applicable
	SB505-35-0001	Service Bulletin Recommended	OXYGEN - REPLACEMENT OF THE OXYGEN CYLINDER BRACKETS	No			Not Applicable
	SB505-35-0002	Service Bulletin Recommended	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR)	No			Not Applicable
	SB505-35-0003-REV01	Service Bulletin Recommended	OXYGEN - INSTALLATION OF BLEED VENT VALVE TO THE OXYGEN LINE	No			Not Applicable
	SB505-35-0004-REV01	Service Bulletin Optional	OXYGEN - 77 CU. FT OXYGEN CYLINDER INSTALLATION	No			Not Applicable
	SB505-36-0001-REV01	Service Bulletin Recommended	PNEUMATIC - REPLACEMENT OF THE AMS CONTROLLER	No			Not Applicable
	SB505-36-0002	Service Bulletin Recommended	PNEUMATIC - AMS CONTROLLER SOFTWARE UPDATE	No			Not Applicable
	SB505-36-0004	Service Bulletin Mandatory	PNEUMATIC - FAN AIR LINE REPLACEMENT	No			Not Applicable
	SB505-36-0005	Service Bulletin Recommended	PNEUMATIC - INSPECTION AND INSTALLATION OF A NEW FIXATION POINT TO THE BLEED LEAK 1 DETECTOR SYSTEM...	No			Not Applicable
	SB505-36-0006	Service Bulletin Recommended	PNEUMATIC - AMS CONTROLLER (-204) SOFTWARE UPDATE	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-36-0007	Service Bulletin Recommended	PNEUMATIC - AMS CONTROLLER (-202 AND -203) SOFTWARE UPDATE	No			Not Applicable
	SB505-38-0001-REV03	Service Bulletin Optional	WATER/WASTE - LAVATORY WATER SYSTEM AND SINK CABINET INSTALLATION	No			Not Applicable
	SB505-38-0002-REV04	Service Bulletin Recommended	WATER/WASTE - WASTE TANK DRAIN LINE MODIFICATION	No			Not Applicable
	SB505-38-0003	Service Bulletin Recommended	WATER/WASTE - REWORK OF THE WASTE TANK - MODIFICATION TO RECIRCULATING TOILET ASSEMBLY P/N RTA9147-...	No			Not Applicable
	SB505-38-0004-REV02	Service Bulletin Optional	WATER/WASTE - WASTE TANK REPLACEMENT	No			Not Applicable
	SB505-44-0001 PART 1	Service Bulletin Optional	CABIN SYSTEMS - 7" LCD (LIQUID CRYSTAL LIQUID) MONITORS INSTALLATION	No			Not Applicable
	SB505-44-0001 PART 2	Service Bulletin Optional	CABIN SYSTEMS - 7" LCD (LIQUID CRYSTAL LIQUID) MONITORS INSTALLATION	No			Not Applicable
	SB505-44-0003-REV37	Service Bulletin Optional	CABIN SYSTEMS - ACTIVATION OF THE AIRBORNE BROADBAND INTERNET SYSTEM (ABIS)	No			Not Applicable
	SB505-44-0004-REV01 PART 1	Service Bulletin Mandatory	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) EQUIPMENT INSTALLATION	No			Not Applicable
	SB505-44-0004-REV01 PART 2	Service Bulletin Optional	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) EQUIPMENT INSTALLATION	No			Not Applicable
	SB505-44-0005	Service Bulletin Optional	CABIN SYSTEMS - VIP CONTROL PANEL REPLACEMENT	No			Not Applicable
	SB505-44-0006-REV01	Service Bulletin Optional	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT) WIRELESS EQUIPMENT INSTALLATION	No			Not Applicable
	SB505-44-0007	Service Bulletin Optional	CABIN SYSTEMS - IFE (IN FLIGHT ENTERTAINMENT EQUIPMENT) WIRED AUDIO FEATURE - INSTALLATION	No			Not Applicable
	SB505-44-0008-REV01	Service Bulletin Optional	CABIN SYSTEMS - AVIATOR 300 HSD SYSTEM INSTALLATION	No			Not Applicable
	SB505-44-0009	Service Bulletin Mandatory	CABIN SYSTEMS - AVIATOR 300 HSD SYSTEM INSTALLATION	No			Not Applicable
	SB505-44-0010	Service Bulletin Optional	CABIN SYSTEMS - GOGO AVANCE L5 ATG 4G SYSTEM INSTALLATION	No			Not Applicable
	SB505-45-0001	Service Bulletin Recommended	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER (CMC) LOAD V2.0...	No			Not Applicable
	SB505-45-0002	Service Bulletin Recommended	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER (CMC) LOAD V2.01A...	No			Not Applicable
	SB505-45-0003-REV02	Service Bulletin Optional	CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANCE COMPUTER (CMC) LOAD V5.30...	Yes		Date: 15/03/2022	
	SB505-45-0004	Service Bulletin Optional	CENTRAL MAINTENANCE SYSTEM - CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANC...	No			Not Applicable
	SB505-45-0005	Service Bulletin Recommended	CENTRAL MAINTENANCE SYSTEM - CENTRAL MAINTENANCE SYSTEM - G3000 - INSTALLATION OF CENTRAL MAINTENANC...	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-46-0001-REV01	Service Bulletin Optional	INFORMATION SYSTEMS - FLIGHT STREAM SYSTEM ACTIVATION	No			Not Applicable
	SB505-50-0001	Service Bulletin Optional	BAGGAGE AND ACCESSORY COMPARTMENTS - TOWBAR HEAD STORAGE INSTALLATION	No			Not Applicable
	SB505-52-0001	Service Bulletin Recommended	DOORS - IMPROVEMENT ON THE BATTERY AND AFT BAGGAGE DOOR LOCK CAM	No			Not Applicable
	SB505-52-0002-REV02	Service Bulletin Recommended	DOORS - RH WING-TO-FUSELAGE AFT FAIRING ACCESS DOOR IMPROVEMENT	No			Not Applicable
	SB505-52-0003-REV02 PART 1	Service Bulletin Recommended	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT	No			Not Applicable
	SB505-52-0003-REV02 PART 2	Service Bulletin Recommended	DOORS - MAIN DOOR REWORK AND LININGS REPLACEMENT	No			Not Applicable
	SB505-52-0004-REV01	Service Bulletin Optional	DOORS - MOVABLE FLOOR TRIM INSTALLATION	No			Not Applicable
	SB505-52-0005-REV02 PART 1	Service Bulletin Recommended	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION	Yes		Date: 06/09/2018	
	SB505-52-0005-REV02 PART 2	Service Bulletin Recommended	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION	No			Not Applicable
	SB505-52-0005-REV02 PART 2	Service Bulletin Recommended	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION	Yes		Date: 06/09/2018	
	SB505-52-0005-REV02 PART 3	Service Bulletin Recommended	DOORS - MAIN-DOOR BALANCING-MECHANISM MODIFICATION	Yes		Date: 06/09/2018	
	SB505-52-0006	Service Bulletin Optional	DOORS - MAIN DOOR - METALLIC SILL INSTALLATION	No			Not Applicable
	SB505-53-0001-REV06	Service Bulletin Optional	FUSELAGE - REINFORCEMENT ON THE FLOOR STRUCTURE	No			Not Applicable
	SB505-53-0002	Service Bulletin Recommended	FUSELAGE - RADOME BONDING PLATE INSTALLATION	No			Not Applicable
	SB505-53-0003-REV02 - SUPERSEDED BY SB505-53-0005 REV 01	Service Bulletin Recommended	FUSELAGE - AFT FUSELAGE GRATE REPLACEMENT	No			Not Applicable
	SB505-53-0004	Service Bulletin Optional	FUSELAGE - POLYURETHANE FILM INSTALLATION	No			Not Applicable
	SB505-53-0005-REV01 - NOT APPLICABLE DUE TO PRE SB 505-53-0003 STATUS - MT	Service Bulletin Recommended	FUSELAGE - AFT FUSELAGE GRATE - TO RETURN TO PREVIOUS CONFIGURATION	No			Not Applicable
	SB505-53-0006 PART 1 + PART 2	Service Bulletin Recommended	FUSELAGE - INSTALLATION OF RIVETS ON FRAME 19	No			Not Applicable
	SB505-53-005 - NOT APPLICABLE DUE TO PRE SB 505-53-0003 STATUS - MT	Service Bulletin Recommended	FUSELAGE - AFT FUSELAGE GRATE - TO RETURN TO PREVIOUS CONFIGURATION	No		Date: 06/09/2016	
	SB505-54-0001-REV01	Service Bulletin Recommended	NACELLES/PYLONS - REINFORCEMENTS IN YOKE GUSSETS	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-54-0002-REV01	Service Bulletin Recommended	NACELLES/PYLONS - FIXED BUSHING OF THE YOKE 2	No			Not Applicable
	SB505-54-0003	Service Bulletin Recommended	NACELLES/PYLONS - REPLACEMENT OF THE FIXED BUSHING RIVETS	No			Not Applicable
	SB505-55-0001	Service Bulletin Recommended	STABILIZERS - REPLACEMENT OF THE BOLTS OF THE RUDDER MASS BALANCE	No			Not Applicable
	SB505-55-0002	Service Bulletin Recommended	STABILIZERS - REPLACEMENT OF THE BOLTS OF ELEVATOR MASS BALANCE	No			Not Applicable
	SB505-55-0003	Service Bulletin Recommended	STABILIZERS - ELIMINATION OF INTERFERENCE BETWEEN THE BOLTS THAT ATTACH VERTICAL STABILIZER AND AFT...	No			Not Applicable
	SB505-55-0004-REV01 PART 1	Service Bulletin Recommended	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT	Yes		Date: 23/10/2020	
	SB505-55-0004-REV01 PART 2	Service Bulletin Recommended	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT	Yes		Date: 23/10/2020	
	SB505-55-0004-REV01 PART 3	Service Bulletin Recommended	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE REPLACEMENT	Yes		Date: 23/10/2020	
	SB505-55-A004-REV06	Service Bulletin Recommended	STABILIZERS - ELEVATOR, AILERON AND RUDDER MASS-BALANCE AND ATTACHMENT PARTS INSPECTION AND REPLACEMENT...	No			Not Applicable
	SB505-56-0001 PART 1	Service Bulletin Mandatory	WINDOWS - PASSENGER CABIN WINDOWS IMPROVEMENTS	No			Not Applicable
	SB505-56-0001 PART 2	Service Bulletin Optional	WINDOWS - PASSENGER CABIN WINDOWS IMPROVEMENTS	No			Not Applicable
	SB505-56-0002-REV02 PART 1	Service Bulletin Recommended	WINDOWS - PASSENGER CABIN WINDOWS REWORK	No			Not Applicable
	SB505-56-0002-REV02 PART 2	Service Bulletin Recommended	WINDOWS - PASSENGER CABIN WINDOWS REWORK	No			Not Applicable
	SB505-56-0002-REV02 PART 3	Service Bulletin Recommended	WINDOWS - PASSENGER CABIN WINDOWS REWORK	No			Not Applicable
	SB505-56-0003-REV02 PART 1	Service Bulletin Recommended	WINDOWS - NEW PAX WINDOW TRANSPARENCIES	No			Not Applicable
	SB505-56-0003-REV02 PART 2	Service Bulletin Recommended	WINDOWS - NEW PAX WINDOW TRANSPARENCIES	No			Not Applicable
	SB505-57-0001	Service Bulletin Recommended	WINGS - BOLTS REPLACEMENT OF THE AILERON TAB MECHANISM FITTING	No			Not Applicable
	SB505-57-0002 PART 1	Service Bulletin Recommended	WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES	No			Not Applicable
	SB505-57-0002 PART 2	Service Bulletin Recommended	WINGS - ADDITION OF DRAIN HOLES TO THE CONTROL SURFACES	No			Not Applicable
	SB505-57-0003	Service Bulletin Recommended	WINGS - AILERON DRAIN HOLES INSPECTION	No			Not Applicable
	SB505-57-0004 PART 1	Service Bulletin Recommended	WINGS - INSPECTION AND DRILLING OF DRAIN HOLES TO THE CONTROL SURFACES	No			Not Applicable

No.	Name	Type	Description	Applicability	Interval	Last Compliance	Next Compliance
	SB505-57-0004 PART 2	Service Bulletin Recommended	WINGS - INSPECTION AND DRILLING OF DRAIN HOLES TO THE CONTROL SURFACES	No			Not Applicable
	SB505-57-0005-REV01	Service Bulletin Recommended	WINGS - ELIMINATION OF THE AILERON TAB FITTING BOLT INTERFERENCE	No			Not Applicable
	SB505-57-0007-REV02	Service Bulletin Recommended	WINGS - ELECTRICAL BONDING CORRECTION FOR SEAL REINFORCEMENT AND LOCK STOPPER	No			Not Applicable
	SB505-57-0008	Service Bulletin Recommended	WINGS - OUTBOARD-FLAP LOWER SHROUD SEAL REPLACEMENT	No			Not Applicable
	SB505-57-0009-REV01	Service Bulletin Mandatory	WINGS - WING REPLACEMENT	No			Not Applicable
	SB505-71-000-REV02	Service Bulletin Recommended	POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET	No			Not Applicable
	SB505-71-0001-REV03	Service Bulletin Recommended	POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET	No			Not Applicable
	SB505-71-0002	Service Bulletin Optional	POWERPLANT - ASSISTANCE TO REPLACE RH ENGINE AIR INLET	No			Not Applicable
	SB505-71-0003	Service Bulletin Recommended	POWERPLANT - REPLACEMENT OF THE ENGINE AIR INLET	No			Not Applicable
	SB505-71-0004	Service Bulletin Recommended	POWERPLANT - INSPECTION OF ENGINE FORWARD MOUNT ASSEMBLY	No			Not Applicable
	SB505-71-0005 PART 1	Service Bulletin Recommended	POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS	No			Not Applicable
	SB505-71-0005 PART 2	Service Bulletin Recommended	POWERPLANT - REINFORCEMENT OF THE NACELLE MID COWLS	No			Not Applicable
	SB505-71-0006 PART 1	Service Bulletin Recommended	POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET	No			Not Applicable
	SB505-71-0006 PART 2	Service Bulletin Recommended	POWERPLANT - REPETITIVE INSPECTION ON THE ENGINE AIR INLET	No			Not Applicable
	SB505-71-0007	Service Bulletin Optional	POWERPLANT - DRAIN MAST REPLACEMENT	No			Not Applicable
	SB505-71-0009 PART 1 + PART 2	Service Bulletin Optional	POWERPLANT - REPLACEMENT OF LH/RH ENGINE UPPER AND LOWER MID COWLS STUD ASSEMBLY	Yes			None
	SB505-73-0001-REV01	Service Bulletin Recommended	ENGINE FUEL AND CONTROL - NEW FADEC (FULL-AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE -...	No			Not Applicable
	SB505-73-0002-REV01 PART 1 + PART 2	Service Bulletin Recommended	ENGINE FUEL AND CONTROL - ENGINE FUEL PRESSURE TUBE REPLACEMENT	Yes		Date: 06/09/2016	
Other							
	EFB-IPAD	Other	OKAML-1 (H19C9TDCWH), OKAML-2 (G9RR9H75L4)	Yes		Date: 09/10/2024	
	POPLATKY ZA VYUŽÍVÁNÍ KMITOČTŮ	Other	Account number: 19-60426011/0710, Konstantní symbol: 308, Variabilní symbol: XXXXYYYYYY (XXXX = rok...	Yes	First 12 MN	Date: 15/04/2024	Date: 15/01/2025 (4 months ago)