



Status Report

HAWKER 400XP

S/N RK-552 OK-BZZ

OWNER: TATRA LEASING, A.S.

ADDRESS: HODŽOVO NÁMESTIE 3
BRATISLAVA 81106

OFFICE:

FAX:

OPERATOR: JETBEE CZECH S.R.O

ADDRESS: K LETISTI 1073/25
PRAGUE 6 161 00

OFFICE: 420 605 991 191

FAX:

ANALYST: PIERRE-ALEXIS DI ROSA

EMAIL: PA.DIROS@CAMPSYSTEMS.EU

+33 (0) 1.55.93.45.80 (OFFICE)

+33 (0) 1.53.01.66.18 (EFAX-CARDS)

WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;PN/SN-UNKNOWN Components:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE

AIRCRAFT	SERIAL/REGNO: RK-552/OK-BZZ	MODEL: HAWKER 400XP	MANUFACTURER: TEXTRON AVIATION INC.
-----------------	------------------------------------	----------------------------	--

CERTIFICATION DATE: 17-MAR-2008

LAST ACTUALS:

4607:07 A/C HRS as of 29-NOV-2022

3829 AFL as of 29-NOV-2022

327 ACH as of 29-NOV-2022

ENGINE NO. 1	SERIAL/PART: PCE-JG0091/JT15D-5R	MODEL: JT15D-5R	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	---	------------------------	---

INSTALLED ON: 15-FEB-2022

3611:4 ENG. HRS 3833:39 A/C HRS
2 ENC
3222

LAST ACTUALS:

4385:11 ENG. HRS as of 29-NOV-2022

3697 ENC as of 29-NOV-2022

ENGINE NO. 2	SERIAL/PART: PCE-JG0092/JT15D-5R	MODEL: JT15D-5R	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	---	------------------------	---

INSTALLED ON: 15-FEB-2022

3611:4 ENG. HRS 3833:39 A/C HRS
2 ENC
3222

LAST ACTUALS:

4385:11 ENG. HRS as of 29-NOV-2022

3697 ENC as of 29-NOV-2022



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
BC20-151020	REVIEW	05-20-00	INSPECTIONS SCHEDULE	NEXTANT	REV.B-REQUIREMENT CHANGE FORM			Service ATA:00
	MOS/MSC	03-Dec-15	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF BC20							
BC20-151112	REVIEW	NEXTANT 005-20-00	REV C-REQUIREMENT CHANGE FORM					Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF BC20							
BC20-160130	REVIEW	BEECHJET 400A/HAWKER 400XP, MMS IFA, REVISION A3, DATED OCTOBER 01, 2015-CAMP	CHANGE FORM					Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF BC20							
BC20-160204	REVIEW	BEECHJET 400A/HAWKER 400XP, AMM, REVISION C28, OCTOBER 01, 2015-RCF						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF BC20							
BC20-161001	REVIEW	BEECHJET 400A/HAWKER 400XP, AMM, REVISION C29						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF BC20							
BC20-161001A	REVIEW	REVIEW BEECHJET 400A/HAWKER 400XP, SRM, REVISION C16						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
	PROC. REF: RCF BC20							

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
BC20-171018	REVIEW AUDIT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF BC20								
BC20-171220	REVIEW AUDIT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF BC20								
BC20-180307	REVIEW AUDIT SUMMARY CHANGE FORM - CODE CONVERT CVR TASKS							Component ATA:00
	MOS/MSC	10-Oct-19	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF BC20								
BC20-180329	REVIEW AUDIT SUMMARY CHANGE FORM - DESCRIPTION CHANGE 323001,323002, 323003 AND DELETE 323020,323021,323022							Service ATA:00
	MOS/MSC	10-Oct-19	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF BC20								
BC20-180404	REVIEW AUDIT SUMMARY CHANGE FORM - ASSOCIATE OXYGEN VALVE AND PASSENGER OXYGEN VALVE O-RING REPLACEMENT							Service ATA:00
	MOS/MSC	10-Oct-19	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF BC20								
BC20-180723	REVIEW AUDIT SUMMARY CHANGE FORM-TASK CODE CONVERSION FOR A/C INSPECTION							Service ATA:00
	MOS/MSC	10-Oct-19	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF BC20								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
BC20-210212	REVIEW AUDIT SUMMARY CHANGE FORM FOR NEXTANT REVISION K							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF BC20								
BC20-210908	REVIEW AUDIT SUMMARY CHANGE FORM - TASK CODE CHANGE							Service ATA:00
	MOS/MSC		-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF BC20								
CZ CAA ^U ARC (AIRWORTHINESS REVIEW CERTIFICATE) RENEWAL								
	MOS	14-May-21	12		27-May-23 ^M		179 d	Service ATA:00
	HRS	3409:02						
	AFL							
E017-160503	NO. 1 ENGINE - REVIEW PWC, JT15D-5/-5R, ENGINE MAINTENANCE MANUAL (PN 3033442) REVISION NO. 41.0, DATED APR 04/2016-RCF							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-160503	NO. 2 ENGINE - REVIEW PWC, JT15D-5/-5R, ENGINE MAINTENANCE MANUAL (PN 3033442) REVISION NO. 41.0, DATED APR 04/2016-RCF							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-161219	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 41.1							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E017-161219	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 41.1							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-180423	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 42.0							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-180423	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 42.0							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-181022	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 43.0							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-181022	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 43.0							Service ATA:00
	MOS/MSC	10-Oct-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-190429	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 44.0							Service ATA:00
	MOS/MSC	04-Jun-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E017-190429	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 44.0							Service ATA:00
	MOS/MSC	04-Jun-19	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E017							
E017-191021	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 45.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E017							
E017-191021	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 45.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E017							
E017-201026	NO. 1 ENGINE - REVIEW JTD15-5/-5R EMM REV 47.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E017							
E017-201026	NO. 2 ENGINE - REVIEW JTD15-5/-5R EMM REV 47.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E017							
E017-201217	NO. 1 ENGINE - REVIEW SB JT15D-72-7003 REV 41							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
	PROC. REF: RCF E017							

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E017-201217	NO. 2 ENGINE - REVIEW SB JT15D-72-7003 REV 41							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-210426	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 48.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-210426	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 48.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-210709	NO. 1 ENGINE - REVIEW SB JT15D-72-7002 REV 44							Service ATA:00
	MOS/MSC	26-Jul-21	-					REQUIREMENT CHANGE FORMS
	HRS	3498:33						
	ENC	3150						
PROC. REF: RCF E017								
E017-210709	NO. 2 ENGINE - REVIEW SB JT15D-72-7002 REV 44							Service ATA:00
	MOS/MSC	26-Jul-21	-					REQUIREMENT CHANGE FORMS
	HRS	3498:33						
	ENC	3150						
PROC. REF: RCF E017								
E017-211025	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 49.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E017-211025	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 49.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-220425	NO. 1 ENGINE - REVIEW JT15D-5/-5R EMM REV 50.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-220425	NO. 2 ENGINE - REVIEW JT15D-5/-5R EMM REV 50.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E017								
E017-221107	NO. 1 ENGINE - REVIEW SB JT15D-72-7003 REV 42							Service ATA:00
	MOS/MSC	22-Nov-22	-					REQUIREMENT CHANGE FORMS
	HRS	4382:57						
	ENC	3695						
PROC. REF: RCF E017								
E017-221107	NO. 2 ENGINE - REVIEW SB JT15D-72-7003 REV 42							Service ATA:00
	MOS/MSC	22-Nov-22	-					REQUIREMENT CHANGE FORMS
	HRS	4382:57						
	ENC	3695						
PROC. REF: RCF E017								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-USER-01 ^U	CHECK FIRST AID KIT							Service ATA:05
	MOS	26-Sep-21	24		31-Jan-23 ^M		63 d	
	HRS	4464:01						
	AFL	3746						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05000I	INSPECTION I							Service ATA:05
	MOS/MSC	22-Oct-08	-					
	HRS	196:06		Adj 3:54				
WC#: 05.020	AFL	142						
PROC. REF: AMM 05000I								
055200	ACCOMPLISH INSPECTION AFTER OPERATIONS IN OR AROUND VOLCANIC ASH							Service ATA:05
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
WC#: 05.045	AFL	0						
PROC. REF: AMM 05-50-00								
057110	NO. 1 ENGINE - ENGINE MINOR INSPECTION							Package ATA:05
	MOS	31-Aug-22			RTS			
	HRS	4162:51	200 (+20)					
	ENC	3563						
PROC. REF: EMM 72-00-00 WO#: JB2022-BZZ-018,JB2022-BZZ-023								
057110	NO. 2 ENGINE - ENGINE MINOR INSPECTION							Package ATA:05
	MOS	31-Aug-22			RTS			
	HRS	4162:51	200 (+20)					
	ENC	3563						
PROC. REF: EMM 72-00-00 WO#: JB2022-BZZ-018,JB2022-BZZ-023								
05A000 ^S	INSPECTION A							Service ATA:05
	MOS	29-Jul-21						
	HRS	3498:33	200 ^S (+20)	Adj -19:54				
WC#: 05.010	AFL	3150						
PROC. REF: AMM 05-20-00								
05B000 ^S	INSPECTION B							Service ATA:05
	MOS	29-Jul-21						
	HRS	3498:33	400 ^S (+20)					
WC#: 05.010	AFL	3150						
PROC. REF: IP 27-60-20-01								
05C000 ^S	INSPECTION C							Service ATA:05
	MOS	04-Sep-16						
	HRS	2409:22	1200 ^S (+20)					
WC#: 05.010	AFL	2103						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05D000 ^S	INSPECTION D							Service ATA:05
	MOS	17-Mar-08						
	HRS	0	T:5000 ^S (+20)					
WC#: 05.015	AFL	0						
PROC. REF: AMM 05-20-00								
H05000A	IFA-A INSPECTION							Package ATA:05
	MOS	31-Aug-22	12		31-Aug-23		275 d	
	HRS	4384:47	400 (+40)	Adj -8:10	4776:37	4816:37	169:30 (+40)	
WC#: 05.025	AFL	3695						
PKG:2								
H05000B	IFA-B INSPECTION							Package ATA:05
	MOS	07-May-22						
	HRS	3976:37	800 (+40)		4776:37	4816:37	169:30 (+40)	
WC#: 05.030	AFL	3438						
PKG:3								
H05000C	IFA-C INSPECTION							Package ATA:05
	MOS	07-May-22						
	HRS	3976:37	1600 (+40)		5576:37	5616:37	969:30 (+40)	
WC#: 05.035	AFL	3438						
PKG:4								
H05000D	IFA-D INSPECTION							Package ATA:05
	MOS	17-Mar-08						
	HRS	0	T:6400 (+40)		6400	6440	1792:53 (+40)	
WC#: 05.040	AFL	0						
PKG:5								
H050200	200 HOUR INTERVAL SCHEDULED SPECIAL INSPECTIONS							Package ATA:05
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
	AFL	3695						
PKG:1								
WO#: JB2022-BZZ-009,JB2022-BZZ-018,JB2022-BZZ-023								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 08 - LEVELING AND WEIGHING								
082000	CAA HB11/CAW 48 RE-WEIGH OF AIRCRAFT							Service ATA:08
	MOS	15-Apr-20	48		15-Apr-24		503 d	
	HRS	3278:39						
	AFL	2968						
PROC. REF: GENERIC NO REF								
ATA 11 - PLACARDS AND MARKINGS								
H110001 ^S	INSPECT INTERIOR PLACARDS AND DECALS - PILOTS COMPARTMENT							Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H110002 ^S	INSPECT INTERIOR PLACARDS AND DECALS - CABIN SECTION							Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H110003 ^S	INSPECT EXTERIOR PLACARDS AND DECALS - FORWARD FUSELAGE							Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H110004 ^S	INSPECT EXTERIOR PLACARDS AND DECALS- MIDFUSELAGE							Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H110005 ^S	INSPECT EXTERIOR PLACARDS AND DECALS -LEFT-HAND WING							Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 11 - PLACARDS AND MARKINGS								
H110006 ^S		INSPECT EXTERIOR PLACARDS AND DECALS -RIGHT-HAND WING						Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H110008 ^S		INSPECT EXTERIOR PLACARDS AND DECALS - AFT FUSELAGE						Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H110009 ^S		INSPECT EXTERIOR PLACARDS AND DECALS - VERTICAL STABILIZER						Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H110011 ^S		INSPECT EXTERIOR PLACARDS AND DECALS -LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H110012 ^S		INSPECT EXTERIOR PLACARDS AND DECALS -RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:11
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 12 - SERVICING								
12200I	ACCOMPLISH INITIAL INSPECTION LUBRICATION							Service ATA:12
	MOS/MSC	30-Oct-08	-					
	HRS	196:06		Adj 3:54				
WC#: 12.040	AFL	142						
PROC. REF: AMM 12-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
123001	LUBRICATE SPOILER DRIVE SERVO MOUNT CLUTCH TEETH							Service ATA:12
PN:622-5027-102	MOS	07-May-22	48		07-May-26		1255 d	
SN:2NV2X	HRS	3976:37	6500 (+20)		10476:37	10496:37	5869:30 (+20)	
WC#: 12.090	AFL	3438						
PROC. REF: AMM 12-20-00								
123002	LUBRICATE ELEVATOR DRIVE SERVO MOUNT CLUTCH TEETH							Service ATA:12
PN:622-6717-104	MOS	07-May-22	48		07-May-26		1255 d	
SN:2X926	HRS	3976:37	6500 (+20)		10476:37	10496:37	5869:30 (+20)	
WC#: 12.090	AFL	3438						
PROC. REF: AMM 12-20-00								
123003	LUBRICATE RUDDER DRIVE SERVO MOUNT CLUTCH TEETH							Service ATA:12
PN:622-6717-104	MOS	07-May-22	48		07-May-26		1255 d	
SN:2TXYF	HRS	3976:37	6500 (+20)		10476:37	10496:37	5869:30 (+20)	
WC#: 12.090	AFL	3438						
PROC. REF: AMM 12-20-00								
H120001 ^s	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - PILOT'S COMPARTMENT							Service ATA:12
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
PKG:2								
H120002 ^s	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - CABIN SECTION							Service ATA:12
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
PKG:2								
H120003 ^s	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - FORWARD FUSELAGE							Service ATA:12
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
PKG:2								
H120004 ^s	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - MIDFUSELAGE							Service ATA:12
	MOS	07-May-22	12 ^s					
	HRS	3976:37	400 ^s					
	AFL	3438						

?-Insufficient Information ^s-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H120005 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - LEFT-HAND WING						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H120006 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - RIGHT-HAND WING						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H120007 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - LANDING GEAR AND BRAKES						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H120008 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - AFT FUSELAGE						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H120009 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - VERTICAL STABILIZER						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H120010 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - HORIZONTAL STABILIZER						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H120011 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:12
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H120012	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - RIGHT-HAND POWER PLANT, PYLON AND NACELLE							Service ATA:12
	MOS	31-Aug-22	12		31-Aug-23		275 d	
	HRS	4384:47	400		4784:47		177:40	
	AFL	3695						
H120013	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - LEFT-HAND THRUST REVERSER							Service ATA:12
	MOS	31-Aug-22	12		31-Aug-23		275 d	
	HRS	4384:47	400		4784:47		177:40	
	AFL	3695						
H120014	LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - RIGHT-HAND THRUST REVERSER							Service ATA:12
	MOS	31-Aug-22	12		31-Aug-23		275 d	
	HRS	4384:47	400		4784:47		177:40	
	AFL	3695						
H120015 ^S	LUBRICATE ITEMS - PILOTS COMPARTMENT							Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H120017 ^S	LUBRICATE ITEMS - FORWARD FUSELAGE							Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H120018 ^S	LUBRICATE ITEMS - MIDFUSELAGE							Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H120019 ^S	LUBRICATE ITEMS - LEFT-HAND WING							Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H120020 ^S		LUBRICATE ITEMS-RIGHT-HAND WING						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H120021 ^S		LUBRICATE ITEMS -LANDING GEAR AND BRAKES						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H120022 ^S		LUBRICATE ITEMS - AFT FUSELAGE						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H120023 ^S		LUBRICATE ITEMS - VERTICAL STABILIZER						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H120024 ^S		LUBRICATE ITEMS - HORIZONTAL STABILIZER						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H120025 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - PILOT'S COMPARTMENT						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120027 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - FORWARD FUSELAGE						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H120028 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - MIDFUSELAGE						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120029 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - LEFT-HAND WING						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120030 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - RIGHT-HAND WING						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120031 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - LANDING GEAR AND BRAKES						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120032 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - AFT FUSELAGE						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120033 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - VERTICAL STABILIZER						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H120034 ^S		LUBRICATE ITEMS AS SPECIFIED IN CHAPTER 12 - HORIZONTAL STABILIZER						Service ATA:12
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H120035 ^S		LUBRICATE LEFT MAIN LANDING GEAR 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.100	AFL	3695						
								PKG:1
H120036 ^S		LUBRICATE RIGHT MAIN LANDING GEAR 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.100	AFL	3695						
								PKG:1
H120037 ^S		LUBRICATE LEFT THRUST REVERSER - 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.110	AFL	3695						
								PKG:1
H120038 ^S		LUBRICATE RIGHT THRUST REVERSER 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.110	AFL	3695						
								PKG:1
H120039 ^S		LUBRICATE LEFT WING FLAP ASSEMBLY 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.120	AFL	3695						
								PKG:1
H120040 ^S		LUBRICATE RIGHT WING FLAP ASSEMBLY 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.120	AFL	3695						
								PKG:1
H120041 ^S		LUBRICATE NOSE LANDING GEAR 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.130	AFL	3695						
								PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H120042 ^S		LUBRICATE MAIN LANDING GEAR AND NOSE LANDING GEAR DOORS - 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.140	AFL	3695						
								PKG:1
H120043 ^S		LUBRICATE LEFT WING FUEL CAPS 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.150	AFL	3695						
								PKG:1
H120044 ^S		LUBRICATE RIGHT WING FUEL CAPS 200 HOUR IFA						Service ATA:12
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 12.150	AFL	3695						
								PKG:1
								WO#: JB2022-BZZ-009
H122000 ^U		PERFORM LUBRICATION IAW IFA-MM SUPPLEMENT 12-20-00 LUBRICATION SCHEDULE						Service ATA:12
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200					
	AFL	3695						
								WO#: JB2022-BZZ-018,JB2022-BZZ-023
ATA 21 - AIR CONDITIONING								
210036	AIR CONDITIONING DRIVE MOTOR							Component ATA:21
PN:PN	MOS	17-Mar-08		TSN 0				OVERHAUL
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.530	AFL	0		TSN 0				
	ACH	0	3000	TSN 0	3000		2673	
PROC. REF: GENERIC CMM								
211003	EMERGENCY PRESSURE VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.020	AFL	0		TSN 0				
PROC. REF: AMM 21-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
211025	BLEED AIR PRESSURE SWITCH							Component ATA:21
PN:45AS48008-011	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:4034824	HRS	0		TSN 0				
WC#: 21.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
211031	TEST VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.040	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
212001	CEILING AIR OUTLET SHUTOFF VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.050	AFL	0		TSN 0				
PROC. REF: AMM 21-20-00								
212007	COCKPIT MODE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
212013	DIFFUSER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
212029	NO. 1 DEFOGGER BLOWER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.070	AFL	0		TSN 0				
PROC. REF: AMM 30-40-00, AMM 30-40-00								
212035	NO. 2 DEFOGGER BLOWER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.070	AFL	0		TSN 0				
PROC. REF: AMM 30-40-00, AMM 30-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212041	CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213001	CABIN PRESSURE CONTROL MODULE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
213007	PNEUMATIC RELAY							Component ATA:21
PN:130358-3	MOS/MSC	14-Jul-18	O/C					
SN:JBC318	HRS	2879:40						
WC#: 21.080	AFL	2577						
PROC. REF: AMM 21-30-00								
213013	LEFT HAND CABIN ALTITUDE PRESSURE REGULATOR							Component ATA:21
PN:102466-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:97-B0508	HRS	0		TSN 0				
WC#: 21.080	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213014	RIGHT HAND CABIN ALTITUDE PRESSURE REGULATOR							Component ATA:21
PN:102466-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:26-B0375	HRS	0		TSN 0				
WC#: 21.080	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213015	VACUUM REGULATOR							Component ATA:21
PN:2103401-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1255	HRS	0		TSN 0				
WC#: 21.110	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213016	PRESSURE CONTROL REGULATOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213037	S2 SOLENOID VALVE							Component ATA:21
PN:101-380021-7	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-0516156	HRS	0		TSN 0				
WC#: 21.130	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213038	S3 SOLENOID VALVE							Component ATA:21
PN:101-380021-7	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-0516158	HRS	0		TSN 0				
WC#: 21.130	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213039	MANUAL CONTROL VALVE							Component ATA:21
PN:45AS63001-005	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:97-6467	HRS	0		TSN 0				
WC#: 21.140	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213040	LEFT OUTFLOW SAFETY VALVE							Component ATA:21
PN:45AS63001-025	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:18-G0940	HRS	0		TSN 0				
WC#: 21.150	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213041	RIGHT OUTFLOW SAFETY VALVE							Component ATA:21
PN:45AS63001-025	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:117-G0930	HRS	0		TSN 0				
WC#: 21.150	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213098	DUMP VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.160	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213103	CABIN AIR PRESSURE CONTROLLER							Component ATA:21
PN:130356-9	MOS/MSC	12-Jun-08	O/C					
SN:97-A0388	HRS	112						
WC#: 21.170	AFL	89						
PROC. REF: AMM 21-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213115	CABIN PRESSURE AUXILIARY VOLUME TANK							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.180	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
213151	CABIN ALTITUDE SWITCH							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.210	AFL	0		TSN 0				
PROC. REF: AMM 21-30-00								
215001	REFRIGERATION UNIT							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.220	AFL	0		TSN 0				
PROC. REF: AMM 21-50-00								
215007	AIR CONDITIONING UNIT							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.225	AFL	0		TSN 0				
PROC. REF: CMM ICA-HOF90103								
215012	CABIN TEMPERATURE MODULATOR VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215013	COCKPIT TEMPERATURE MODULATOR VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215014	TURBINE COOLING BY-PASS VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215015	EJECTOR SHUT-OFF VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215016	RAM AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215018	ZONE NO. 2 MODULATOR SHUT-OFF VALVE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215025	AIR TEMPERATURE BULB							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215031	ENVIRONMENTAL CONTROL VALVE							Component ATA:21
PN:45AS63018-171	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:926	HRS	0		TSN 0				
WC#: 21.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215035	COOLING TURBINE							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.275	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215037	PRIMARY HEAT EXCHANGER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215043	SECONDARY HEAT EXCHANGER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215049	CABIN THERMAL SWITCH							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
215060	CABIN TEMPERATURE INDICATOR							Component ATA:21
PN:5003-3016	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:830	HRS	0		TSN 0				
WC#: 21.470	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
215100	INSPECT AIR-CONDITIONING SYSTEM (500 HOUR)							Service ATA:21
	MOS	15-Apr-20						
	HRS	3278:39						
WC#: 21.500	AFL	2968						
	ACH	224:42	500 (+20)		775 ^M	795	448 (+20)	
PROC. REF: GENERIC CMM								
215155	INSPECT FREON AIR-CONDITIONING SYSTEM COMPRESSOR/CONDENSER MODULE							Service ATA:21
	MOS/MSC	17-Mar-08	O/C					
	HRS	0						
WC#: 21.520	AFL	0						
PROC. REF: GENERIC NO REF								
216001	COCKPIT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.290	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216002	CABIN TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.290	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216003	COCKPIT HIGH LIMIT SENSOR							Component ATA:21
PN:45AS63018-127	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:7741	HRS	0		TSN 0				
WC#: 21.300	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00								
216004	CABIN HIGH LIMIT SENSOR							Component ATA:21
PN:45AS63018-127	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:7702	HRS	0		TSN 0				
WC#: 21.300	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00								
216005	LOW LIMIT SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.310	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00								
216006	COCKPIT DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.310	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216007	CABIN DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.310	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216008	FORWARD DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216009	AFT DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
216043	COCKPIT TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.330	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216044	CABIN TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:19A3008	MOS/MSC	12-Jun-14	O/C	TSN 0				
SN:922	HRS	1669:17		TSN 0				
WC#: 21.330	AFL	1409		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216067	COCKPIT TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.350	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216068	CABIN TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.350	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216069	NO. 2 CABIN MODE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.350	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00								
216073	OVERTEMPERATURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.360	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216079	NO. 1 CABIN MODE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.370	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216080	COCKPIT MODE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.370	AFL	0		TSN 0				
PROC. REF: AMM 21-60-00, AMM 21-60-00, AMM 21-61-00, AMM 21-61-00								
216090	CABIN ALTITUDE DIFFERENTIAL PRESSURE INDICATOR							Component ATA:21
PN:45AS86832-005	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:508437	HRS	0		TSN 0				
WC#: 21.215	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
217001	WATER SEPARATOR							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.220	AFL	0		TSN 0				
PROC. REF: AMM 21-70-00								
217013	COALESCER							Component ATA:21
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.390	AFL	0		TSN 0				
PROC. REF: AMM 21-70-00								
218035	FORWARD EVAPORATOR MODULE							Component ATA:21
PN:1134310-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:138	HRS	0		TSN 0				
WC#: 21.480	AFL	0		TSN 0				
PROC. REF: CMM 21-00-12, CMM 21-00-34, AMM 21-51-00								
218040	AFT EVAPORATOR MODULE							Component ATA:21
PN:1134310-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:144	HRS	0		TSN 0				
WC#: 21.480	AFL	0		TSN 0				
PROC. REF: CMM 21-00-12, CMM 21-00-34, AMM 21-51-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
218045	COMPRESSOR CONDENSER							Component ATA:21
PN:1134400-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:595	HRS	0		TSN 0				
WC#: 21.490	AFL	0		TSN 0				
PROC. REF: CMM 21-00-12, CMM 21-00-34, AMM 21-51-00								
H210001 ^S	INSPECT FWD & AFT EVAPORATOR BOX ASSEMBLIES (RK-78,RK-87 AND AFTER) -CABIN SECTION							Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3,4								
H210002 ^S	INSPECT OUTFLOW SAFETY VALVE POPPET SEATS (AS VIEWED FROMNOSE AVIONICS COMPARTMENT							Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H210003 ^S	INSPECT ENVIRONMENTAL CONTROL UNIT (ECU) AND DUCTING - AFT FUSELAGE							Service ATA:21
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H2100035 ^S	INSPECT OVERHEAD AIR OUTLET - CABIN SECTION							Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H210006 ^S	INSPECT AIR-CONDITIONING CONTROL SWITCH PANEL(CO-PILOTS SIDEPANEL) (RK-78, RK-87 AND AFTER) -- PILOTS COMPARTMENT							Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
H210008 ^S		INSPECT VAPOR CYCLE COOLING SYSTEM - EVAPORATORS(RK-78, RK-87 AND AFTER) - CABIN SECTION						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210010 ^S		INSPECT ENVIRONMENTAL CONTROL UNIT (ECU) AND DUCTING - AFT FUSELAGE						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210011 ^S		INSPECT VAPOR CYCLE COOLING SYSTEM (RK-78, RK-87 AND AFTER) - AFT FUSELAGE						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H210012 ^S		INSPECT VAPOR CYCLE COOLING SYSTEM - COMPRESSORCONDENSER MODULE (RK-78, RK-87 AND AFTER) - AFT FUSELAGE						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210016 ^S		INSPECT COCKPIT SIDE WINDOW DEFOG BLOWER - PILOTS COMPARTMENT						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H210017 ^S		INSPECT CEILING AIR OUTLET SHUTOFF VALVE (RK-1 THRU RK-97AND RK-99 THRU RK-109) - PILOTS COMPARTMENT						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H210018 ^S		INSPECT ENVIRONMENTAL CONTROL UNIT (ECU) AND DUCTING(PANELS 311RL AND 312FR REMOVED) - AFT FUSELAGE						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
H210019 ^S		CABIN PRESSURE CONTROL SYSTEM - PERFORM CABIN PRESSURIZATION SYSTEM OPERATIONAL TEST						Service ATA:21
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H210020 ^S		INSPECT ENVIRONMENTAL CONTROL UNIT -ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H210021 ^S		INSPECT ENVIRONMENTAL SYSTEM - ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210022 ^S		INSPECT CABIN PRESSURE CONTROL SYSTEM - PERFORM CABINPRESSURE CONTROL SYSTEM CHECK -ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H210023 ^S		INSPECT ENVIRONMENTAL SYSTEM - CABIN SECTION						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210028 ^S		INSPECT PRESSURIZATION CONTROL COMPONENTS AIRFILTERS/SCREENS						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
H210029 ^S		INSPECT CABIN PRESSURE CONTROL FILTER CARTRIDGEASSEMBLY (BELOW FLOOR PANELS)-PILOT'S COMPARTMENT						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210030 ^S		INSPECT PRESSURIZATION CONTROL SYSTEM-PILOT'S COMPARTMENT						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H210034 ^S		INSPECT COMPRESSOR/CONDENSER MODULE (COMPRESSOR/CONDENSER MODULE REMOVED) (RK-78, RK-87 AND AFTER - SCHEDULED D INSPECTIONCS						Service ATA:21
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H210035 ^S		INSPECT OVERHEAD AIR OUTLET						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H210036 ^S		INSPECT VENTILATION BLOWER SYSTEM-PILOT'S COMPARTMENT						Service ATA:21
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
ATA 22 - AUTO FLIGHT								
221043	SPOILER DRIVE SERVO							Component ATA:22
PN:622-5027-102	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NV2X	HRS	0		TSN 0				
WC#: 22.010	AFL	0		TSN 0				
PROC. REF: AMM 22-13-00, AMM 22-13-00, AMM 22-13-00							WO#: JB2022-BZZ-016	

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221044	ELEVATOR DRIVE SERVO							Component ATA:22
PN:622-6717-104	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2X926	HRS	0		TSN 0				
WC#: 22.010	AFL	0		TSN 0				
PROC. REF: AMM 22-13-00, AMM 22-13-00							WO#: JB2022-BZZ-016	
221050	RUDDER DRIVE SERVO							Component ATA:22
PN:622-6717-104	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2TXYF	HRS	0		TSN 0				
WC#: 22.030	AFL	0		TSN 0				
PROC. REF: AMM 22-13-00, AMM 22-13-00, AMM 22-13-00							WO#: JB2022-BZZ-016	
221055	SPOILER SERVO DRIVE MOUNT							Component ATA:22
PN:822-0260-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2LK3M	HRS	0		TSN 0				
WC#: 22.020	AFL	0		TSN 0				
PROC. REF: AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00								
221056	ELEVATOR SERVO DRIVE MOUNT							Component ATA:22
PN:622-6718-101	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NV6W	HRS	0		TSN 0				
WC#: 22.020	AFL	0		TSN 0				
PROC. REF: AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00								
221057	RUDDER SERVO DRIVE MOUNT							Component ATA:22
PN:622-6718-101	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2TY4L	HRS	0		TSN 0				
WC#: 22.020	AFL	0		TSN 0				
PROC. REF: AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00, AMM 22-13-00								
221074	MODE CONTROL PANEL							Component ATA:22
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221075	AUTOPILOT CONTROLLER PANEL							Component ATA:22
PN:622-6208-204	MOS/MSC	12-Jun-14	O/C	TSO 0				
SN:2NNYJ	HRS	1669:17		TSO 0				
WC#: 22.050	AFL	1409		TSO 0				
PROC. REF: AMM 22-13-00								
227010	INSPECT SPOILER (ROLL) SERVO MOUNT SLIP CLUTCH.							Service ATA:22
	MOS	17-Mar-08						
	HRS	0	12200 (+20)		12200	12220	7592:53 (+20)	
WC#: 22.060	AFL	0						
PROC. REF: GENERIC CMM								
227012	INSPECT ELEVATOR SERVO MOUNT SLIP CLUTCH							Service ATA:22
	MOS	17-Mar-08						
	HRS	0	12200 (+20)		12200	12220	7592:53 (+20)	
WC#: 22.070	AFL	0						
PROC. REF: GENERIC CMM								
227014	INSPECT RUDDER SERVO MOUNT SLIP CLUTCH							Service ATA:22
	MOS	17-Mar-08						
	HRS	0	12200 (+20)		12200	12220	7592:53 (+20)	
WC#: 22.080	AFL	0						
PROC. REF: GENERIC CMM								
ATA 23 - COMMUNICATIONS								
231001	NO. 1 VHF COMMUNICATIONS TRANSCEIVER							Component ATA:23
PN:822-1115-001	MOS/MSC	18-Jul-11	O/C					
SN:2D32F	HRS	567:32						
WC#: 23.010	AFL	507						
231002	NO. 2 VHF COMMUNICATIONS TRANSCEIVER							Component ATA:23
PN:822-1115-001	MOS/MSC	18-Jul-11	O/C					
SN:1UDC	HRS	567:32						
WC#: 23.010	AFL	507						
231079	NO. 1 VHF COMMUNICATION ANTENNA							Component ATA:23
PN:S65-8280-42	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:323-1178	HRS	0		TSN 0				
WC#: 23.020	AFL	0		TSN 0				
PROC. REF: AMM 34-59-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231080	NO. 2 VHF COMMUNICATION ANTENNA							Component ATA:23
PN:S65-8280-42	MOS/MSC	27-Sep-17	O/C					
SN:323-2407	HRS	2572:52						
WC#: 23.020	AFL	2281						
PROC. REF: AMM 34-59-00								
231082	FLIGHT PHONE ANTENNA							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233001	CABIN FLIGHT PHONE HANDSET							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233002	COCKPIT FLIGHT PHONE HANDSET							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233004	COCKPIT FLIGHT PHONE (C118E) FORWARD CONTROL							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233006	COCKPIT FLIGHT PHONE (C118E) AFT CONTROL							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233008	FLIGHT PHONE(RT18D) TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233010	FLIGHT PHONE CONTROLLER							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
233015	LEFT RADIO TUNING UNIT							Component ATA:23
PN:822-1825-111	MOS/MSC	27-Sep-17	O/C					
SN:1WVF	HRS	2572:52						
WC#: 23.070	AFL	2281						
PROC. REF: GENERIC NO REF								
233020	RIGHT RADIO TUNING UNIT							Component ATA:23
PN:822-1825-111	MOS/MSC	07-Jan-19	O/C					
SN:1664	HRS	3097:45						
WC#: 23.070	AFL	2776						
PROC. REF: GENERIC NO REF								
235013	PILOT AUDIO CONTROL PANEL							Component ATA:23
PN:128-340100-3	MOS/MSC	02-May-19	O/C					
SN:4466	HRS	3166:35						
WC#: 23.060	AFL	2852						
PROC. REF: GENERIC NO REF								
235014	COPILOT AUDIO CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
235020	VLF RECEIVER							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.070	AFL	0		TSN 0				
PROC. REF: GENERIC CMM								
235025	NO. 1 AUDIO AMPLIFIER							Component ATA:23
PN:438-001	MOS/MSC	22-Oct-10	O/C					
SN:5239	HRS	362:12						
WC#: 23.090	AFL	324						
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
235030	NO. 2 AUDIO AMPLIFIER							Component ATA:23
PN:438-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:5143	HRS	0		TSN 0				
WC#: 23.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
235035	AURAL WARNING TONE GENERATOR							Component ATA:23
PN:603	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:931	HRS	0		TSN 0				
WC#: 23.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
237002	COCKPIT VOICE RECORDER							Component ATA:23
PN:2100-1020-00	MOS/MSC	16-Apr-19	O/C					
SN:000488480	HRS	3152:40						
WC#: 31.030	AFL	2836						
PROC. REF: AMM 23-70-00, AMM 23-70-00								
237014	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Component ATA:23
PN:DK120/90	MOS	16-Apr-19	72	TSN 0	01-Feb-26 ^M		1160 d	OVERHAUL
SN:AT126833	HRS	3152:40		TSN 0				
WC#: 31.030	AFL	2836		TSN 0				
237016	FUNCTIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Service ATA:23
	MOS	24-Feb-21	24		24-Feb-23		87 d	
	HRS	3386:14						
WC#: 31.030	AFL	3077						
237017	REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service ATA:23
PN:DK120/90	MOS/MSC	16-Apr-19	DUE		01-Feb-26 ^M		1160 d	
SN:AT126833	HRS	3152:40						
WC#: 31.030	AFL	2836						
PROC. REF: CMM 23-70-01								
237018	INSPECT/CLEAN COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON SWITCH							Service ATA:23
	MOS	24-Feb-21	24		24-Feb-23		87 d	
	HRS	3386:14						
WC#: 31.030	AFL	3077						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237019	COCKPIT VOICE RECORDER IMPACT SWITCH							Component ATA:23
PN:6895-D-1-X-2.5-2.5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:7227	HRS	0		TSN 0				
WC#: 31.025	AFL	0		TSN 0				
PROC. REF: AMM 23-70-00, AMM 23-70-00								
237020	COCKPIT VOICE RECORDER CONTROL UNIT							Component ATA:23
PN:93-A151-30	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:486802	HRS	0		TSN 0				
WC#: 31.035	AFL	0		TSN 0				
PROC. REF: AMM 23-70-00, AMM 23-70-00								
238031	LEFT CONTROL PANEL DISPLAY							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
238034	RIGHT CONTROL PANEL DISPLAY							Component ATA:23
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
H230001 ^S	INSPECT ANTENNA - FORWARD FUSELAGE							Service ATA:23
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H230002 ^S	INSPECT ANTENNA - MIDFUSELAGE							Service ATA:23
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H230003 ^S	INSPECT ANTENNA - AFT FUSELAGE							Service ATA:23
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
H230004 ^S		INSPECT COCKPIT WARNING SYSTEM - PILOTS COMPARTMENT						Service ATA:23
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 24 - ELECTRICAL POWER								
240012	CHECK/TEST STANDBY BATTERY POWER SUPPLY						Service	ATA:24
PN:501-1228-04	MOS	15-Feb-22	12 (+10d/-10d)		15-Feb-23	25-Feb-23	78 d (+10)	
SN:83871	HRS	3833:39						
WC#: 24.055	AFL	3354						
PROC. REF: SL 80, CMM 24-30-02								
240013	CHECK/TEST AHRS BATTERY POWER SUPPLY						Service	ATA:24
PN:501-1228-04	MOS	15-Feb-22	12 (+10d/-10d)		15-Feb-23	25-Feb-23	78 d (+10)	
SN:11852	HRS	3833:39						
WC#: 24.005	AFL	3354						
PROC. REF: SL 80, CMM 24-30-02								
240021	STANDBY BATTERY POWER SUPPLY						Component	ATA:24
PN:501-1228-04	MOS/MSC	24-Feb-21	O/C	TSR 10				
SN:83871	HRS	3386:14		TSR 109:56				
WC#: 24.055	AFL	3077		TSR 112				
PROC. REF: AMM 24-20-00								
240022	AHRS BATTERY POWER SUPPLY						Component	ATA:24
PN:501-1228-04	MOS/MSC	24-Feb-21	O/C					
SN:11852	HRS	3386:14						
WC#: 24.005	AFL	3077						
PROC. REF: GENERIC NO REF								
241000 ^U	FAIL ANNUNCIATOR PCB INVERTER						Component	ATA:24
PN:128-364094-5	MOS/MSC	22-Oct-10	O/C					
SN:04050501ICT	HRS	362:12						
	AFL	324						
241001 ^U	NO. 1 INVERTER CONTROL PCB ASSY						Component	ATA:24
PN:128-364116-5	MOS/MSC	23-Aug-11	O/C					
SN:01051003ICT	HRS	600:11						
	AFL	531						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242001	NO. 1 INVERTER							Component ATA:24
PN:SPC5(B)	MOS/MSC	05-Aug-16	O/C	TSO 1				
SN:1319	HRS	2395:32		TSO 0				
WC#: 24.010	AFL	2090		TSO 0				
PROC. REF: AMM 24-20-00								
242002	NO. 2 INVERTER							Component ATA:24
PN:SPC5(B)	MOS/MSC	19-Jul-12	O/C	TSO 0				
SN:1306	HRS	844:34		TSO 0				
WC#: 24.010	AFL	747		TSO 0				
PROC. REF: AMM 24-20-00								
242013	AC VOLTMETER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.020	AFL	0		TSN 0				
243001	NO. 1 GENERATOR CONTROL UNIT							Component ATA:24
PN:45AS88801-025	MOS/MSC	17-Mar-08	O/C					
SN:P1431	HRS	0						
WC#: 24.060	AFL	0						
PROC. REF: AMM 24-30-00								
243002	NO. 2 GENERATOR CONTROL UNIT							Component ATA:24
PN:45AS88801-025	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:P1422	HRS	0		TSN 0				
WC#: 24.060	AFL	0		TSN 0				
PROC. REF: AMM 24-30-00								
243013	DC INSTRUMENT CLUSTER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.070	AFL	0		TSN 0				
PROC. REF: AMM 24-30-00								
243019	BATTERY FEED PROTECTION UNIT							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.080	AFL	0		TSN 0				
PROC. REF: AMM 24-31-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243022	BATTERY GROUND FAULT PROTECTION PANEL							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243025	BATTERY							Component ATA:24
PN:RG-380E/40L	MOS	31-Aug-22	24	TSN 0	31-Aug-24		641 d	LIFE LIMIT
SN:41231360	HRS	4384:47	1200	TSN 0	5584:47		977:40	
WC#: 24.090	AFL	3695		TSN 0				
PROC. REF: CMM 24-30-99, CMM 24-30-71, AMM 24-31-00, AMM 24-32-00								
243026	PERFORM BATTERY CAPACITY TEST (LEAD ACID ONLY)(RK-98 AND AFTER)							Service ATA:24
PN:RG-380E/40L	MOS	31-Aug-22	3	TAC 0	31-Aug-23 ^M		275 d	IFA
SN:41231360	HRS	4384:47	200 (+40)	TAC 0	5384:47 ^M	5424:47	777:40 (+40)	
WC#: 24.090	AFL	3695		TAC 0				
PROC. REF: CMM 24-30-71, CMM 24-30-71, AMM 24-32-00 WO#: JB2021-BZZ-003,JB2022-BZZ-020								
243043	NO. 1 ENGINE STARTER/GENERATOR							Component ATA:24
PN:23080-050	MOS	31-Aug-22		TSO 0				REPLACE
SN:P1208	HRS	4384:47	1000	TSO 0	5384:47		777:40	
WC#: 24.110	AFL	3695		TSO 0				
PROC. REF: AMM 80-10-00, AMM 80-10-00								
243044	NO. 2 ENGINE STARTER/GENERATOR							Component ATA:24
PN:23080-050	MOS	31-Aug-22		TSO 0				REPLACE
SN:P1485	HRS	4384:47	1000	TSO 0	5384:47		777:40	
WC#: 24.110	AFL	3695		TSO 0				
PROC. REF: AMM 80-10-00, AMM 80-10-00								
243073	LEFT OVERCURRENT SENSOR RELAY							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243074	RIGHT OVERCURRENT SENSOR RELAY							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243085	BATTERY TEMPERATURE INDICATOR							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0		TSN 0				
PROC. REF: AMM 24-31-00								
243091	LEFT STARTER/GENERATOR POSITIVE GROUND FAULT CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243092	LEFT STARTER/GENERATOR NEGATIVE GROUND FAULT CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243093	RIGHT STARTER/GENERATOR POSITIVE GROUND FAULT CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243094	RIGHT STARTER/GENERATOR NEGATIVE GROUND FAULT CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243095	FORWARD FUSELAGE CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
243096	AFT FUSELAGE CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243121	LEFT INDICATOR PANEL							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.040	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
243122	RIGHT INDICATOR PANEL							Component ATA:24
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.040	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
243123	ANNUNCIATOR PANEL							Component ATA:24
PN:45AS88860-025	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:494	HRS	0		TSN 0				
WC#: 24.040	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
H240001 ^s	INSPECT ELECTRICAL COMPONENTS - PILOTS COMPARTMENT							Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^s					
	AFL	3438						
PKG:3								
H240002 ^s	INSPECT BATTERY INSTALLATION - AFT FUSELAGE							Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^s					
	AFL	3438						
PKG:3								
H240004 ^s	INSPECT ELECTRICAL EQUIPMENT (SIDE JUNCTION) PANEL,POWER RELAY PANEL, RESISTOR RELAY (LOAD SHED)PANEL, CIRCUIT BREAKER PANELS AND ASSOCIATEDWIRING-PILOT'S COMPARTMENT							Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	1600 ^s					
	AFL	3438						
PKG:4								

?-Insufficient Information ^s-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
H240005 ^S		INSPECT ELECTRICAL COMPONENTS - AREA INSPECTION - CABIN SECTION						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H240008 ^S		INSPECT BATTERY, EXTERNAL POWER AND GENERATORGROUNDING TERMINALS AND HARDWARE - AFT FUSELAGE						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H240009 ^S		INSPECT ELECTRICAL COMPONENTS - AREA INSPECTION - AFT FUSELAGE						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H240011 ^S		INSPECT INVERTER SYSTEM - ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H240014 ^S		INSPECT ELECTRICAL COMPONENTS - AREA INSPECTION (WITHINTERIOR PANELS REMOVED) - CABIN SECTION						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H240015 ^S		INSPECT GENERATOR CONTROL UNITS (GCU)- CABIN SECTION						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H240016 ^S		INSPECT ELECTRICAL AND AVIONICS COMPARTMENT - FORWARD FUSELAGE						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
H240018 ^S		INSPECT DC GENERATION AND CONTROL SYSTEM -ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:24
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H240019 ^S		INSPECT LEFT STARTER-GENERATOR						Service ATA:24
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 24.160	AFL	3695						
PROC. REF: AMM 80-10-00								PKG:1
H240020 ^S		INSPECT RIGHT STARTER-GENERATOR						Service ATA:24
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 24.160	AFL	3695						
PROC. REF: AMM 80-10-00								PKG:1
H240021 ^S		CHECK BATTERY (NI-CAD ONLY), ELECTROLYTE LEVEL AND CHARGE (DEEP CYCLE IF NECESSARY).						Service ATA:24
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 24.170	AFL	3695						
PROC. REF: GENERIC CMM								PKG:1
ATA 25 - EQUIPMENT/FURNISHINGS								
251001	PILOT SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.010	AFL	0		TSN 0				
PROC. REF: AMM 25-10-00, AMM 25-11-00								
251002	COPILOT SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.010	AFL	0		TSN 0				
PROC. REF: AMM 25-10-00, AMM 25-11-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252001	RIGHT NO.1 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.020	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								
252002	RIGHT NO.2 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.020	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								
252003	RIGHT NO.3 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.020	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								
252004	LEFT NO.1 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								
252005	LEFT NO.2 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								
252017	LEFT NO.3 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								
252018	NO. 1 SWIVEL SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: AMM 25-21-00, AMM 25-22-00, AMM 25-22-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252019	TOILET SEAT							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
256001	EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:453-5000	MOS/MSC	14-Jun-21	O/C					
SN:10068	HRS	3409:02						
WC#: 25.050	AFL	3097						
PROC. REF: AMM 25-61-00								
256003	ELT ANTENNA							Component ATA:25
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.060	AFL	0		TSN 0				
PROC. REF: AMM 25-61-00								
256005	EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:PN	MOS/MSC	01-Oct-20	O/C					
SN:UNKNOWN	HRS	3339:36						
	AFL	3032						
256011	REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY							Service ATA:25
PN:PN	MOS/MSC	01-Oct-20	DUE		01-May-24 ^M		519 d	
SN:UNKNOWN	HRS	3339:36						
WC#: 25.050	AFL	3032						
PROC. REF: AMM 25-61-00								
256012	INSPECT/FUNCTIONAL CHECK EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:453-5000	MOS	15-Feb-22	12		15-Feb-23		78 d	MANDATORY
SN:10068	HRS	3833:39						
WC#: 25.050	AFL	3354						
PROC. REF: FAR 91.207(D) , AMM 25-61-00								
256014	PILOT LIFE VEST							Component ATA:25
PN:P01074-207C	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:21070900024	HRS	3866:17		TSN 0				
WC#: 25.070	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256015	COPILOT LIFE VEST							Component ATA:25
PN:P01074-207C	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:21070900025	HRS	3866:17		TSN 0				
WC#: 25.070	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256016	NO. 3 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580243	HRS	3866:17		TSN 0				
WC#: 25.080	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256017	NO. 4 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580244	HRS	3866:17		TSN 0				
WC#: 25.080	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256018	NO. 5 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580245	HRS	3866:17		TSN 0				
WC#: 25.085	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256019	NO. 6 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580246	HRS	3866:17		TSN 0				
WC#: 25.085	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256020	NO. 7 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580247	HRS	3866:17		TSN 0				
WC#: 25.090	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256021	NO. 8 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580248	HRS	3866:17		TSN 0				
WC#: 25.090	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256022	NO. 9 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580249	HRS	3866:17		TSN 0				
WC#: 25.095	AFL	3375		TSN 0				
PROC. REF: AMM 25-60-00								
256023	NO. 10 LIFE VEST							Component ATA:25
PN:P01074-207	MOS/MSC	01-Mar-22	O/C	TSN 0				
SN:22010580251	HRS	3866:17		TSN 0				
WC#: 25.095	AFL	3375		TSN 0				
256030	RECERTIFY PILOT LIFE VEST							Service ATA:25
PN:P01074-207C	MOS	13-Jan-22	120		13-Jan-32		3332 d	
SN:21070900024	HRS							
WC#: 25.070	AFL							
PROC. REF: GENERIC NO REF								
256031	RECERTIFY CO-PILOT LIFE VEST							Service ATA:25
PN:P01074-207C	MOS	13-Jan-22	120		13-Jan-32		3332 d	
SN:21070900025	HRS							
WC#: 25.070	AFL							
PROC. REF: GENERIC NO REF								
256032	RECERTIFY NO. 3 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580243	HRS							
WC#: 25.080	AFL							
PROC. REF: GENERIC NO REF								
256033	RECERTIFY NO. 4 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580244	HRS							
WC#: 25.080	AFL							
PROC. REF: GENERIC NO REF								
256034	RECERTIFY NO. 5 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580245	HRS							
WC#: 25.085	AFL							
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256035	RECERTIFY NO. 6 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580246	HRS							
WC#: 25.085	AFL							
PROC. REF: GENERIC NO REF								
256036	RECERTIFY NO. 7 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580247	HRS							
WC#: 25.090	AFL							
PROC. REF: GENERIC NO REF								
256037	RECERTIFY NO. 8 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580248	HRS							
WC#: 25.090	AFL							
PROC. REF: GENERIC NO REF								
256038	RECERTIFY NO. 9 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580249	HRS							
WC#: 25.095	AFL							
PROC. REF: GENERIC NO REF								
256039	RECERTIFY NO.10 LIFE VEST							Service ATA:25
PN:P01074-207	MOS	17-Feb-22	120		17-Feb-32		3367 d	
SN:22010580251	HRS							
WC#: 25.095	AFL							
PROC. REF: GENERIC NO REF								
256050	INSPECT AFT FUSELAGE BAGGAGE COMPARTMENT HOOK FASTENER (VELCRO)							Service ATA:25
	MOS	31-Aug-22						AIRWORTHINESS
	HRS	4384:47	400 (+20)	Adj -12:32	4772:15	4792:15	165:08 (+20)	
WC#: 25.120	AFL	3695						
PROC. REF: AMM 25-50-00								
256052	REPLACE AFT BAGGAGE COMPARTMENT VELCRO (HOOK ONLY)							Service ATA:25
	MOS	27-Sep-17						LIFE LIMIT
	HRS	2572:52	2600		5172:52		565:45	
WC#: 25.115	AFL	2281						
PROC. REF: AMM 25-50-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
H240007 ^S		INSPECT ELECTRICAL AND AVIONICS COMPONENTS - AREA INSPECTION (FORWARD OF THE PRESSURE BULKHEAD; AVIONICS REMOVAL NOT REQUIRED) - FORWARD FUSELAGE						Service ATA:25
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H250001 ^S		INSPECT PILOT'S AND COPILOT'S SEATS - PILOT'S COMPARTMENT						Service ATA:25
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H250002 ^S		INSPECT SMOKE GOGGLES - PILOT'S COMPARTMENT						Service ATA:25
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H250003 ^S		INSPECT DIVIDER AND PARTITIONS - CABIN SECTION						Service ATA:25
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H250004 ^S		INSPECT PASSENGER AND TOILET SEAT - CABIN SECTION						Service ATA:25
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H250005 ^S		INSPECT REFRESHMENT CENTER AND STORAGE CABINETS - CABIN SECTION						Service ATA:25
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
H250007 ^S	INSPECT SEAT RAILS AND ATTACHMENTS - CABIN SECTION							Service ATA:25
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H250009 ^S	INSPECT RELIEF TUBE - PILOTS COMPARTMENT							Service ATA:25
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H250010 ^S	INSPECT PASSENGER AND TOILET SEAT - CABIN SECTION							Service ATA:25
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 26 - FIRE PROTECTION								
261001	LEFT ENGINE FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.010	AFL	0		TSN 0				
PROC. REF: AMM 26-10-00, AMM 26-10-00								
261002	RIGHT ENGINE FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.010	AFL	0		TSN 0				
PROC. REF: AMM 26-10-00, AMM 26-10-00								
261013	LEFT ENGINE FIRE DETECTION SENSOR							Component ATA:26
PN:244-25282	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:073107	HRS	0		TSN 0				
WC#: 26.020	AFL	0		TSN 0				
PROC. REF: AMM 26-10-00, AMM 26-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261014	RIGHT ENGINE FIRE DETECTION SENSOR							Component ATA:26
PN:244-25282	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:073201	HRS	0		TSN 0				
WC#: 26.020	AFL	0		TSN 0				
PROC. REF: AMM 26-10-00, AMM 26-10-00								
262003	COCKPIT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:C352TS	MOS/MSC	07-Mar-19	O/C	TSN 0				
SN:F50309872	HRS	3137:52		TSN 0				
WC#: 26.060	AFL	2819		TSN 0				
PROC. REF: AMM 26-21-00								
262004	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:C352TS	MOS/MSC	15-Feb-22	O/C	TSN 0				
SN:G-45678812	HRS	3833:39		TSN 0				
WC#: 26.070	AFL	3354		TSN 0				
PROC. REF: AMM 26-21-00								
262005	HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C352TS	MOS	15-Feb-19	144		15-Feb-31		3000 d	MANDATORY
SN:F50309872	HRS							
WC#: 26.060	AFL							
PROC. REF: GENERIC CMM								
262006	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C352TS	MOS		144		01-Aug-23 ^M		245 d	MANDATORY
SN:G-45678812	HRS							
WC#: 26.070	AFL							
PROC. REF: GENERIC CMM								
262023	NO. 1 ENGINE FIRE EXTINGUISHER							Component ATA:26
PN:30400018-1	MOS/MSC	02-Jul-19	O/C	TSO 0				
SN:32757B1	HRS	3229		TSO 0				
WC#: 26.040	AFL	2910		TSO 0				
PROC. REF: AMM 26-20-00								
262024	NO. 2 ENGINE FIRE EXTINGUISHER							Component ATA:26
PN:30400018-1	MOS/MSC	16-Apr-19	O/C	TSO 0				
SN:40898B1	HRS	3152:40		TSO 0				
WC#: 26.050	AFL	2836		TSO 0				
PROC. REF: AMM 26-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262025	INSPECT/HYDROSTATIC TEST NO. 1 ENGINE FIRE EXTINGUISHER							Service ATA:26
PN:30400018-1	MOS	01-Feb-19	60		01-Feb-24		429 d	AIRWORTHINESS
SN:32757B1	HRS							
WC#: 26.040	AFL							
PROC. REF: GENERIC NO REF								
262026	INSPECT/HYDROSTATIC TEST NO. 2 ENGINE FIRE EXTINGUISHER							Service ATA:26
PN:30400018-1	MOS	04-Dec-18	60		04-Dec-23		370 d	AIRWORTHINESS
SN:40898B1	HRS							
WC#: 26.050	AFL							
PROC. REF: GENERIC NO REF								
262037	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (SERVICE LIFE)							Service ATA:26
	MOS	02-Jul-19	48		02-Jul-23		215 d	SCRAP
	HRS							
WC#: 26.040	AFL							
PROC. REF: AMM 26-20-00								
262038	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (SERVICE LIFE)							Service ATA:26
	MOS	16-Apr-19	48		16-Apr-23		138 d	SCRAP
	HRS							
WC#: 26.050	AFL							
PROC. REF: AMM 26-20-00								
262039	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (SERVICE LIFE)							Service ATA:26
	MOS	02-Jul-19	48		02-Jul-23		215 d	SCRAP
	HRS							
WC#: 26.040	AFL							
PROC. REF: AMM 26-20-00								
262040	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (SERVICE LIFE)							Service ATA:26
	MOS	16-Apr-19	48		16-Apr-23		138 d	SCRAP
	HRS							
WC#: 26.050	AFL							
PROC. REF: AMM 26-20-00								
262042	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (LIFE LIMIT)							Service ATA:26
	MOS	19-Mar-19	72		19-Mar-25		841 d	LIFE LIMIT
	HRS							
WC#: 26.040	AFL							
PROC. REF: AMM 26-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262043	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (LIFE LIMIT)							Service ATA:26
	MOS	01-Sep-18	72		01-Sep-24		642 d	LIFE LIMIT
	HRS							
WC#: 26.050	AFL							
PROC. REF: AMM 26-20-00								
262044	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (LIFE LIMIT)							Service ATA:26
	MOS	19-Mar-19	72		19-Mar-25		841 d	LIFE LIMIT
	HRS							
WC#: 26.040	AFL							
PROC. REF: AMM 26-20-00								
262045	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (LIFE LIMIT)							Service ATA:26
	MOS	01-Sep-18	72		01-Sep-24		642 d	LIFE LIMIT
	HRS							
WC#: 26.050	AFL							
PROC. REF: AMM 26-20-00								
262049	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	15-Feb-22	12		15-Feb-23		78 d	
	HRS							
WC#: 26.060	AFL							
PROC. REF: GENERIC CMM								
262050	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	15-Feb-22	12		15-Feb-23		78 d	
	HRS							
WC#: 26.070	AFL							
PROC. REF: GENERIC CMM								
262079	CABIN BAGGAGE SMOKE DETECTOR							Component ATA:26
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
H260002 ^S	INSPECT FIRE EXTINGUISHER SYSTEM - AFT FUSELAGE							Service ATA:26
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
H260003 ^S		INSPECT FIRE EXTINGUISHER SYSTEM - AFT FUSELAGE						Service ATA:26
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H260004 ^S		INSPECT FIRE DETECTION SYSTEM - AFT FUSELAGE						Service ATA:26
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H260005 ^S		INSPECT FIRE EXTINGUISHER SYSTEM - AFT FUSELAGE						Service ATA:26
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H260006 ^S		INSPECT FIRE DETECTION SYSTEM - PILOTS COMPARTMENT						Service ATA:26
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H260106 ^S		INSPECT ENGINE FIRE EXTINGUISHER TUBING AND DETECTOR LOOP - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:26
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H260206 ^S		INSPECT ENGINE FIRE EXTINGUISHER TUBING AND DETECTOR LOOP - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:26
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 27 - FLIGHT CONTROLS								
270001 ^U		SPEED BRAKE SOLENOID VALVE						Component ATA:27
PN:PN	MOS/MSC	16-Apr-19	O/C					
SN:UNKNOWN	HRS	3152:40						
	AFL	2836						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271001	LEFT ROLL TRIM ACTUATOR							Component ATA:27
PN:45AS61014-107	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:71001	HRS	0		TSN 0				
WC#: 27.010	AFL	0		TSN 0				
PROC. REF: AMM 27-10-00, AMM 27-10-00								
271002	RIGHT ROLL TRIM ACTUATOR							Component ATA:27
PN:45AS61014-108	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:70603	HRS	0		TSN 0				
WC#: 27.010	AFL	0		TSN 0				
PROC. REF: AMM 27-10-00, AMM 27-10-00								
271023	ROLL TRIM POSITION INDICATOR							Component ATA:27
PN:45AS86848-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07110994A	HRS	0		TSN 0				
WC#: 27.030	AFL	0		TSN 0				
PROC. REF: AMM 31-10-00								
272001	RUDDER							Component ATA:27
PN:45A24001-211	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 27.050	AFL	0		TSN 0				
PROC. REF: AMM 27-20-00, AMM 27-20-00								
272007	RUDDER TRIM TAB ACTUATOR							Component ATA:27
PN:45AS61014-111	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:61002	HRS	0		TSN 0				
WC#: 27.060	AFL	0		TSN 0				
PROC. REF: AMM 27-20-00, AMM 27-20-00								
272013	UPPER RUDDER HINGE ASSEMBLY							Component ATA:27
PN:45A23205-001	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:08270704ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.070	AFL	0		TSN 0				
PROC. REF: AMM 27-20-00								
272014	LOWER RUDDER HINGE ASSEMBLY							Component ATA:27
PN:45A23204-001	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:07120704ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.070	AFL	0		TSN 0				
PROC. REF: AMM 27-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272041	RUDDER TRIM POSITION INDICATOR							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
272101 ^U	INBD LEFT ENGINE BLEED PRESSURE (MT 105) TRANSDUCER							Component ATA:27
PN:APTE233A-1750300A	MOS/MSC	13-Aug-10	O/C	TSN 0				
SN:6293-5-386	HRS	287:13		TSN 0				
	AFL	246		TSN 0				
272103 ^U	OUTBD LEFT ENGINE BLEED PRESSURE (MT 107) TRANSDUCER							Component ATA:27
PN:APTE233A-1750300A	MOS/MSC	13-Aug-10	O/C	TSN 0				
SN:6293-5-402	HRS	287:13		TSN 0				
	AFL	246		TSN 0				
272104 ^U	INBD RIGHT ENGINE BLEED PRESSURE (MT 104) TRANSDUCER							Component ATA:27
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
272106 ^U	OUTBD RIGHT ENGINE BLEED PRESSURE (MT 106) TRANSDUCER							Component ATA:27
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
273001	LEFT ELEVATOR							Component ATA:27
PN:45A22002-641	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK553	HRS	0		TSN 0				
WC#: 27.160	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00, AMM 27-30-00								
273002	RIGHT ELEVATOR							Component ATA:27
PN:45A22002-642	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 27.160	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00, AMM 27-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273013	LEFT INBOARD ELEVATOR HINGE ASSEMBLY							Component ATA:27
PN:45A21188-005	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:10260701SAL	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.170	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00								
273014	RIGHT INBOARD ELEVATOR HINGE ASSEMBLY							Component ATA:27
PN:45A21188-005	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:10190701SAL	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.170	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00								
273015	LEFT OUTBOARD ELEVATOR HINGE ASSEMBLY							Component ATA:27
PN:45A21187-001	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:10260701SAL	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.180	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00								
273016	RIGHT OUTBOARD ELEVATOR HINGE ASSEMBLY							Component ATA:27
PN:45A21187-001	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:10190701SAL	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.180	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00								
273037	PILOT COLUMN CONTROL							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.190	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00, AMM 27-30-00								
273038	COPILOT COLUMN CONTROL							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.190	AFL	0		TSN 0				
PROC. REF: AMM 27-30-00, AMM 27-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274001	HORIZONTAL STABILIZER							Component ATA:27
PN:45A21001-663	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 27.240	AFL	0		TSN 0				
PROC. REF: AMM 27-40-00, AMM 27-40-00, AMM 27-40-00, AMM 27-40-00, AMM 27-40-00								
274007	PITCH TRIM ACTUATOR							Component ATA:27
PN:45AS61023-143	MOS	19-Aug-20		TSO 0				LIFE LIMIT*
SN:ET0499	HRS	3313:12	1800	TSO 0	5113:12		506:05	
WC#: 27.250	AFL	3004		TSO 0				
PROC. REF: AMM 27-40-00, AMM 27-40-00, AMM 27-40-00								
274034	PITCH TRIM POSITION INDICATOR							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.280	AFL	0		TSN 0				
PROC. REF: AMM 31-10-00								
274046	STABILIZER TRIM POSITION TRANSMITTER							Component ATA:27
PN:45AS86805-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07J216	HRS	0		TSN 0				
WC#: 27.300	AFL	0		TSN 0				
PROC. REF: AMM 27-40-00, AMM 27-40-00, AMM 27-40-00								
275001	LEFT MAIN FLAP ASSEMBLY							Component ATA:27
PN:45A16001-031	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 27.310	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275002	RIGHT MAIN FLAP ASSEMBLY							Component ATA:27
PN:45A16001-032	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK553	HRS	0		TSN 0				
WC#: 27.310	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275003	LEFT AFT FLAP ASSEMBLY							Component ATA:27
PN:45A16241-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 27.320	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275004	RIGHT AFT FLAP ASSEMBLY							Component ATA:27
PN:45A16241-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK548	HRS	0		TSN 0				
WC#: 27.320	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275025	LEFT FLAP ACTUATOR							Component ATA:27
PN:45AS61021-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1606	HRS	0		TSN 0				
WC#: 27.330	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00, AMM 27-50-00								
275026	RIGHT FLAP ACTUATOR							Component ATA:27
PN:45AS61021-010	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1591	HRS	0		TSN 0				
WC#: 27.330	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00, AMM 27-50-00								
275043	LEFT FLAP ASYMMETRY DETECTOR							Component ATA:27
PN:45AS86805-017	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:71318	HRS	0		TSN 0				
WC#: 27.340	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275044	RIGHT FLAP ASYMMETRY DETECTOR							Component ATA:27
PN:45AS86805-017	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:71315	HRS	0		TSN 0				
WC#: 27.340	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275047	LEFT FLAP FOLLOW-UP SWITCH							Component ATA:27
PN:45AS61015-025	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:01H133	HRS	0		TSN 0				
WC#: 27.350	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00, AMM 27-50-00, AMM 27-50-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275048	RIGHT FLAP FOLLOW-UP SWITCH							Component ATA:27
PN:45AS61015-023	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07C237	HRS	0		TSN 0				
WC#: 27.350	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00, AMM 27-50-00, AMM 27-50-00								
275051	LEFT FLAP POSITION TRANSMITTER							Component ATA:27
PN:45AS86805-033	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07L116	HRS	0		TSN 0				
WC#: 27.360	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275052	RIGHT FLAP POSITION TRANSMITTER							Component ATA:27
PN:45AS86805-031	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07H325	HRS	0		TSN 0				
WC#: 27.360	AFL	0		TSN 0				
PROC. REF: AMM 27-50-00, AMM 27-50-00								
275055	REPLACE LEFT WING FLAP BOLTS							Service ATA:27
	MOS	17-Mar-08						LIFE LIMIT
	HRS	0	22400		22400		17792:53	
WC#: 27.370	AFL	0						
PROC. REF: GENERIC NO REF								
275056	REPLACE RIGHT WING FLAP BOLTS							Service ATA:27
	MOS	17-Mar-08						LIFE LIMIT
	HRS	0	22400		22400		17792:53	
WC#: 27.370	AFL	0						
PROC. REF: GENERIC NO REF								
275089	LEFT MAIN FLAP CENTER RAIL SUPPORT ASSEMBLY							Component ATA:27
PN:132-100033-13	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:021407012ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.380	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275090	RIGHT MAIN FLAP CENTER RAIL SUPPORT ASSEMBLY							Component ATA:27
PN:132-100033-14	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:022607006ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.380	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275091	LEFT MAIN FLAP OUTBOARD RAIL SUPPORT ASSEMBLY							Component ATA:27
PN:45A10420-021	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:09100701SAL	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.410	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275092	RIGHT MAIN FLAP OUTBOARD RAIL SUPPORT ASSEMBLY							Component ATA:27
PN:45A10420-022	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:11060701SLN	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.410	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275093	LEFT MAIN FLAP INBOARD RAIL SUPPORT ASSEMBLY							Component ATA:27
PN:45A10422-031	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:09100701SAL	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.290	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275094	RIGHT MAIN FLAP INBOARD RAIL SUPPORT ASSEMBLY							Component ATA:27
PN:45A10422-032	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:11060701SLN	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.290	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275095	LEFT AFT FLAP OUTBOARD RAIL							Component ATA:27
PN:45A16087-013	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:06082007013ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275096	RIGHT AFT FLAP OUTBOARD RAIL							Component ATA:27
PN:45A16087-014	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:030107018ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275097	LEFT AFT FLAP INBOARD RAIL							Component ATA:27
PN:45A16127-003	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:0811060026ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275098	RIGHT AFT FLAP INBOARD RAIL							Component ATA:27
PN:45A16127-004	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:0902060060ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 27.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275131	FLAP SYSTEM LEFT LOCK VALVE							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275132	FLAP SYSTEM RIGHT LOCK VALVE							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
275155	FLAP POSITION INDICATOR							Component ATA:27
PN:45AS86805-029	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07H250A	HRS	0		TSN 0				
WC#: 27.220	AFL	0		TSN 0				
PROC. REF: AMM 31-10-00								
276001	LEFT INBOARD SPOILER							Component ATA:27
PN:45A10020-603	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:12190703	HRS	0	14600	TSN 0	14600		9992:53	
WC#: 27.210	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00, AMM 27-60-00								
276002	RIGHT INBOARD SPOILER							Component ATA:27
PN:45A10020-604	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:12050703	HRS	0	14600	TSN 0	14600		9992:53	
WC#: 27.210	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00, AMM 27-60-00								
276003	LEFT OUTBOARD SPOILER							Component ATA:27
PN:45A10020-713	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:12210702	HRS	0	14600	TSN 0	14600		9992:53	
WC#: 27.200	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00, AMM 27-60-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276004	RIGHT OUTBOARD SPOILER							Component ATA:27
PN:45A10020-714	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:11190701	HRS	0	14600	TSN 0	14600		9992:53	
WC#: 27.200	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00, AMM 27-60-00								
276013	SPEED BRAKE ACTUATOR							Component ATA:27
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.150	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00, AMM 27-60-00								
276031	LEFT SPOILER LEFT HINGE							Component ATA:27
PN:45A10505-003	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:19070271	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00								
276032	RIGHT SPOILER LEFT HINGE							Component ATA:27
PN:45A10505-004	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:119070363	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00								
276033	LEFT SPOILER RIGHT HINGE							Component ATA:27
PN:45A10505-003	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:19070279	HRS	0		TSN 0				
WC#: 27.130	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00								
276034	RIGHT SPOILER RIGHT HINGE							Component ATA:27
PN:45A10505-004	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:119070387	HRS	0		TSN 0				
WC#: 27.130	AFL	0		TSN 0				
PROC. REF: AMM 27-60-00								
276055	LEFT SPOILER FITTINGS							Component ATA:27
PN:45A10511-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:050320070063ICT	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276056	RIGHT SPOILER FITTINGS							Component ATA:27
PN:45A10511-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:050320070131ICT	HRS	0		TSN 0				
WC#: 27.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
H270001 ^S	INSPECT RUDDER PEDALS (ABOVE FLOOR PANELS) - PILOT'S COMPARTMENT							Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H270002 ^S	INSPECT PITCH TRIM POSITION TRANSMITTER AND LINKAGE - HORIZONTAL STABILIZER							Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H270003 ^S	INSPECT PITCH TRIM OPERATION - HORIZONTAL STABILIZER							Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
PKG:4								
H270005 ^S	INSPECT RUDDER TRIM TAB AND HINGE - VERTICAL STABILIZER							Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H270006 ^S	INSPECT CONTROL COLUMN (ABOVE FLOOR PANELS) - PILOT'S COMPARTMENT							Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H270008 ^S	INSPECT SPOILER OPERATION - MIDFUSELAGE							Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270009 ^S		INSPECT RUDDER OPERATION - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270010 ^S		INSPECT RUDDER TRIM - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270024 ^S		INSPECT CONTROL CABLES - AFT FUSELAGE						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270025 ^S		INSPECT CONTROL CABLES - AFT FUSELAGE						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270027 ^S		INSPECT ELEVATOR CABLES (WHERE ACCESSIBLE THROUGH ACCESSPANELS) - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270028 ^S		INSPECT ELEVATOR QUADRANT ASSEMBLY, PUSHROD ANDCONNECTING HARDWARE, STOP BOLTS AND DOWNSPRING - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270030 ^S		INSPECT RUDDER TRIM OPERATION - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270031 ^S		INSPECT ELEVATOR HINGES AND BOLTS, TORQUE TUBE ANDHORN LEVER, LEVER AND LINK ASSEMBLY, STOP BOLTSAND HEATER HORN/COUNTER BALANCE - HORIZONTAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270032 ^S		INSPECT ELEVATOR OPERATION - HORIZONTAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270034 ^S		INSPECT/LUBRICATE PITCH TRIM ACTUATOR AND ATTACH BRACKET ASSEMBLY						Service ATA:27
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: H270034	AFL	3695						
PROC. REF: AMM 27-40-00, AMM 27-40-00-201								PKG:1
H270035 ^S		INSPECT PITCH TRIM OPERATION - HORIZONTAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270037 ^S		INSPECT RUDDER TRIM ACTUATOR AND LINKAGE - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270038 ^S		INSPECT SPOILER SYSTEM - MIDFUSELAGE						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270039 ^S		INSPECT FLIGHT CONTROL SECTOR MODULE-PILOT'S COMPARTMENT						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270041 ^S		INSPECT ELEVATOR, RUDDER AND SPOILER CONTROL CABLES,PULLEYS AND BRACKETS - CABIN SECTION						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270042 ^S		INSPECT RUDDER PEDALS (BELOW FLOOR PANELS)-PILOT'S COMPARTMENT						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270044 ^S		INSPECT RUDDER TORQUE TUBE ATTACHMENT AND TRIM TABACTUATOR ATTACHMENT- SCHEDULED D INSPECTIONCS						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H270045 ^S		INSPECT ELEVATOR TORQUE TUBE- SCHEDULED D INSPECTIONCS						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H270047 ^S		INSPECT CONTROL YOKE - PILOT'S COMPARTMENT						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270048 ^S		TENSION CHECK LEFT WING FLAP CABLES AND INTERCONNECT CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.040	AFL	0						
PROC. REF: AMM 27-50-00								
H270049 ^S		TENSION CHECK RIGHT WING FLAP CABLES AND INTERCONNECT CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.040	AFL	0						
PROC. REF: AMM 27-50-00								
H270050 ^S		TENSION CHECK LEFT WING SPOILER CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.080	AFL	0						
PROC. REF: AMM 27-60-00								
H270051 ^S		TENSION CHECK RIGHT WING SPOILER CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.080	AFL	0						
PROC. REF: AMM 27-60-00								
H270052 ^S		TENSION CHECK RUDDER CONTROL CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.110	AFL	0						
PROC. REF: AMM 27-20-00								
H270053 ^S		TENSION CHECK RUDDER SERVO CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.390	AFL	0						
PROC. REF: AMM 22-13-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270054 ^S		TENSION CHECK ELEVATOR CONTROL CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.420	AFL	0						
PROC. REF: AMM 27-30-00								
H270055 ^S		TENSION CHECK ELEVATOR SERVO CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.430	AFL	0						
PROC. REF: AMM 22-13-00								
H270056 ^S		TENSION CHECK SPOILER SERVO CABLES (200-FLYING HOURS AFTER CONTROL CABLE REPLACEMENT)						Service ATA:27
	MOS	17-Mar-08						
	HRS	0	T:200 ^S (+40)					
WC#: 27.440	AFL	0						
PROC. REF: AMM 22-13-00								
H270057 ^S		TENSION CHECK LEFT WING FLAP CABLES AND INTERCONNECT CABLES						Service ATA:27
	MOS/MSC	07-May-22	A/R ^S					
	HRS	3976:37						
WC#: 27.450	AFL	3438						
PROC. REF: AMM 27-50-00								
H270058 ^S		TENSION CHECK RIGHT WING FLAP CABLES AND INTERCONNECT CABLES						Service ATA:27
	MOS/MSC	07-May-22	A/R ^S					
	HRS	3976:37						
WC#: 27.450	AFL	3438						
PROC. REF: AMM 27-50-00								
H270059 ^S		TENSION CHECK LEFT WING SPOILER CABLES						Service ATA:27
	MOS/MSC	07-May-22	A/R ^S					
	HRS	3976:37						
WC#: 27.460	AFL	3438						
PROC. REF: AMM 27-60-00								
H270060 ^S		TENSION CHECK RIGHT WING SPOILER CABLES						Service ATA:27
	MOS/MSC	07-May-22	A/R ^S					
	HRS	3976:37						
WC#: 27.460	AFL	3438						
PROC. REF: AMM 27-60-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270061 ^S		INSPECT CONTROL COLUMN (BELOW FLOOR PANELS)-PILOT'S COMPARTMENT						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270062 ^S		INSPECT FLAP OPERATION (PERFORM IN CONJUNCTION WITH LH WING)- RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270062 ^S		INSPECT FLAP OPERATION (PERFORM IN CONJUNCTION WITH RH WING)- LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270102 ^S		INSPECT WING FLAPS SYSTEM (FLAPS EXTENDED) - (EXTERNAL INSPECTION ONLY) - LEFT-HAND WING						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270103 ^S		INSPECT ROLL TRIM TAB, HINGE AND COUNTERBALANCE (EXTERNAL INSPECTION ONLY) - LEFT-HAND WING						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270104 ^S		INSPECT SPOILER PANELS AND HINGES - LEFT-HAND WING						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270105 ^S		INSPECT ROLL TRIM OPERATION - PERFORM THE ROLL TRIM SYSTEM OPERATIONAL TEST -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270109 ^S		INSPECT WING FLAPS SYSTEM (FLAPS EXTENDED) -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270111 ^S		INSPECT FLAP OPERATION (PERFORM IN CONJUNCTION WITH RH WINGINSPECTION) -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270113 ^S		INSPECT ROLL TRIM ACTUATOR, ATTACHMENT, DRIVE LINKAGE,POTENTIOMETER AND NEUTRAL SWITCH -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270114 ^S		INSPECT ROLL TRIM OPERATION- LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270115 ^S		INSPECT SPOILER SECTOR AND PUSHRODS -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270116 ^S		INSPECT SPOILER CABLES -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270118 ^S		INSPECT SPEED BRAKE OPERATION - MIDFUSELAGE						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270143 ^S		INSPECT SPOILER FAIRLEADS, WS 54.2 (1377)- LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270147 ^S		INSPECT LEFT SPOILER BRACKET SUPPORT FITTING (P/N45A62036) -LEFT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270202 ^S		INSPECT WING FLAPS SYSTEM (FLAPS EXTENDED) - (EXTERNAL INSPECTION ONLY) - RIGHT-HAND WING						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270203 ^S		INSPECT ROLL TRIM TAB, HINGE AND COUNTERBALANCE (EXTERNAL INSPECTION ONLY) - RIGHT-HAND WING						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270204 ^S		INSPECT SPOILER PANELS AND HINGES - RIGHT-HAND WING						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270205 ^S		INSPECT ROLL TRIM OPERATION - PERFORM THE ROLL TRIM SYSTEM OPERATIONAL TEST -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270209 ^S		INSPECT WING FLAPS SYSTEM (FLAPS EXTENDED) -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270211 ^S		INSPECT FLAP OPERATION (PERFORM IN CONJUNCTION WITH RH WINGINSPECTION) -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270213 ^S		INSPECT ROLL TRIM ACTUATOR, ATTACHMENT, DRIVE LINKAGE,POTENTIOMETER AND NEUTRAL SWITCH -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270214 ^S		INSPECT ROLL TRIM OPERATION- RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270215 ^S		INSPECT SPOILER SECTOR AND PUSHRODS -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270216 ^S		INSPECT SPOILER CABLES -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270243 ^S		INSPECT SPOILER FAIRLEADS, WS 54.2 (1377)- RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H270247 ^S		INSPECT LEFT SPOILER BRACKET SUPPORT FITTING (P/N45A62036) -RIGHT-HAND WING						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H270250 ^S		INSPECT RUDDER OPERATION - PERFORM OPERATIONAL TEST - VERTICAL STABILIZER						Service ATA:27
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H270251 ^S		INSPECT VERTICAL STABILIZER TIP FAIRINGS - VERTICAL STABILIZER						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H270252 ^S		PERFORM THE PITCH TRIM ACTUATOR INSPECTION/CHECK - BACKLASH - VERTICAL STABILIZER						Service ATA:27
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 28 - FUEL								
281001	LEFT CENTER TANK							Component ATA:28
PN:128-384025-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-53262	HRS	0		TSN 0				
WC#: 28.010	AFL	0		TSN 0				
								PROC. REF: AMM 28-11-00
281002	RIGHT CENTER TANK							Component ATA:28
PN:128-384025-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-53266	HRS	0		TSN 0				
WC#: 28.010	AFL	0		TSN 0				
								PROC. REF: AMM 28-11-00
281003	AFT FUSELAGE TANK							Component ATA:28
PN:128-384023-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-53246	HRS	0		TSN 0				
WC#: 28.020	AFL	0		TSN 0				
								PROC. REF: AMM 28-11-00, AMM 28-11-00, AMM 28-11-00, AMM 28-11-00

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281012	DETAIL INSPECT FUSELAGE FILLER FUEL TANK (128-920022)							Service ATA:28
	MOS	27-Sep-17						
	HRS	2572:52	2400 (+20)		4972:52	4992:52	365:45 (+20)	
WC#: 28.210	AFL	2281						
PROC. REF: AMM 05-20-02								
281013	LEFT FORWARD FLAPPER CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281014	LEFT MIDDLE FLAPPER CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281015	LEFT AFT FLAPPER CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281016	RIGHT FORWARD FLAPPER CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281017	RIGHT MIDDLE FLAPPER CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281018	RIGHT AFT FLAPPER CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281019	LEFT WING CARRY THRU FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.030	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
281021	RIGHT WING CARRY THRU FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.040	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
281022	RIGHT WING AFT INBOARD FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281023	LEFT WING SURGE SPACE VENT VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.050	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
281024	RIGHT WING SURGE SPACE VENT VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.050	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
281027	LEFT LEVEL CONTROL VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281028	RIGHT LEVEL CONTROL VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281029	LEFT INBOARD WING TANK SNIFFLE VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281030	RIGHT INBOARD WING TANK SNIFFLE VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281031	AFT FUSELAGE TANK SNIFFLE VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.090	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281032	LEFT VENT FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
281033	RIGHT VENT FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
281037	LEFT OUTBOARD WING TANK SNIFFLE VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
281044	RIGHT OUTBOARD WING TANK SNIFFLE VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282001	LEFT FUEL BOOST PUMP							Component ATA:28
PN:45AS48015-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:5BC52	HRS	0		TSN 0				
WC#: 28.120	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282002	RIGHT FUEL BOOST PUMP							Component ATA:28
PN:45AS48015-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:3BC42	HRS	0		TSN 0				
WC#: 28.120	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282003	LEFT PRIMARY JET FUEL PUMP							Component ATA:28
PN:45AS48018-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1858	HRS	0		TSN 0				
WC#: 28.130	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282004	RIGHT PRIMARY JET FUEL PUMP							Component ATA:28
PN:45AS48018-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1857	HRS	0		TSN 0				
WC#: 28.130	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282005	LEFT FORWARD FUEL TRANSFER JET PUMP							Component ATA:28
PN:128-389033-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:746	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282006	RIGHT FORWARD FUEL TRANSFER JET PUMP							Component ATA:28
PN:128-389033-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:750	HRS	0		TSN 0				
WC#: 28.140	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282008	LEFT AFT FUEL TRANSFER JET PUMP							Component ATA:28
PN:128-389033-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:767	HRS	0		TSN 0				
WC#: 28.025	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282009	RIGHT AFT FUEL TRANSFER JET PUMP							Component ATA:28
PN:128-389033-6	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:745	HRS	0		TSN 0				
WC#: 28.025	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282010	LEFT FUEL BOOSTER TRANSFER PUMP							Component ATA:28
PN:45AS48015-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:3BC22	HRS	0		TSN 0				
WC#: 28.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282011	RIGHT FUEL BOOSTER TRANSFER PUMP							Component ATA:28
PN:45AS48015-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:10BC103	HRS	0		TSN 0				
WC#: 28.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282048	FUEL CROSSFEED VALVE							Component ATA:28
PN:45AS48017-1	MOS/MSC	14-Jul-18	O/C					
SN:L57130	HRS	2879:40						
WC#: 28.160	AFL	2577						
PROC. REF: AMM 28-21-00								
282049	LEFT CROSSFEED VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.160	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282050	RIGHT CROSSFEED VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.160	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282051	LEFT FUEL TRANSFER SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282052	RIGHT FUEL TRANSFER SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282053	LEFT FUEL FEED SHUT-OFF VALVE							Component ATA:28
PN:1321-518316	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1691	HRS	0		TSN 0				
WC#: 28.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282054	RIGHT FUEL FEED SHUT-OFF VALVE							Component ATA:28
PN:1321-518316	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1711	HRS	0		TSN 0				
WC#: 28.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282055	LEFT MOTIVE FLOW SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.190	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282056	RIGHT MOTIVE FLOW SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.190	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282057	LEFT MANUAL DEFUEL VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.200	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
282058	RIGHT MANUAL DEFUEL VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.200	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282169	LEFT FUEL FILTER							Component ATA:28
PN:3071620-01	MOS/MSC	31-Aug-22	O/C	TSN 0				
SN:UNKNOWN	HRS	4384:47		TSN 0				
WC#: 28.220	AFL	3695		TSN 0				
PROC. REF: AMM 28-21-00								
282170	RIGHT FUEL FILTER							Component ATA:28
PN:3071620-01	MOS/MSC	31-Aug-22	O/C	TSN 0				
SN:UNKNOWN	HRS	4384:47		TSN 0				
WC#: 28.220	AFL	3695		TSN 0				
PROC. REF: AMM 28-21-00								
282200	LEFT (TRANSFER FUEL) LOW PRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282201	RIGHT (TRANSFER FUEL) LOW PRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282209	LEFT (FUEL FEED) LOW PRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282213	RIGHT (FUEL FEED) LOW PRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
282219	LEFT WING NO. 1 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.250	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282220	RIGHT WING NO. 1 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.250	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
282221	LEFT WING NO. 2 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.260	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
282222	RIGHT WING NO. 2 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.260	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
282223	LEFT WING NO. 3 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.270	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
282224	RIGHT WING NO. 3 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.270	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
282225	LEFT WING NO. 4 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.280	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								
282226	RIGHT WING NO. 4 DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.280	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284001	WING FUEL TANK QUANTITY INDICATOR							Component ATA:28
PN:128-384030-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0717	HRS	0		TSN 0				
WC#: 28.290	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00								
284002	FUSELAGE FUEL TANK QUANTITY INDICATOR							Component ATA:28
PN:128-384031-3	MOS/MSC	20-Apr-14	O/C					
SN:0888	HRS	1594:04						
WC#: 28.300	AFL	1355						
PROC. REF: AMM 28-41-00								
284005	FUEL QUANTITY AMPLIFIER							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.310	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
284013	CALIBRATE WING FUEL TANK QUANTITY INDICATOR							Service ATA:28
PN:128-384030-1	MOS	29-Jul-21	24		29-Jul-23		242 d	
SN:0717	HRS	3498:33						
WC#: 28.290	AFL	3150						
PROC. REF: AMM 28-41-00								
284014	CALIBRATE FUSELAGE FUEL TANK QUANTITY INDICATOR							Service ATA:28
PN:128-384031-3	MOS	29-Jul-21	24		29-Jul-23		242 d	
SN:0888	HRS	3498:33						
WC#: 28.300	AFL	3150						
PROC. REF: AMM 28-41-00								
284035	LEFT WING INBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN13107	HRS	0		TSN 0				
WC#: 28.150	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284036	RIGHT WING INBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN13108	HRS	0		TSN 0				
WC#: 28.150	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284037	AUXILIARY FUEL TANK FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-13	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN12530	HRS	0		TSN 0				
WC#: 28.360	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284038	MID-FUSELAGE TANK OUTBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-9	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN14477	HRS	0		TSN 0				
WC#: 28.360	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284039	MID-FUSELAGE TANK INBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-7	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN13615	HRS	0		TSN 0				
WC#: 28.400	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00								
284040	AFT FUSELAGE TANK FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-11	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN14335	HRS	0		TSN 0				
WC#: 28.400	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00								
284041	LEFT WING TANK INBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-3	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN12992	HRS	0		TSN 0				
WC#: 28.410	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284042	RIGHT WING TANK INBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-3	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN2989	HRS	0		TSN 0				
WC#: 28.410	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284043	LEFT WING TANK CENTER FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN13318	HRS	0		TSN 0				
WC#: 28.420	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284044	RIGHT WING TANK CENTER FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN13321	HRS	0		TSN 0				
WC#: 28.420	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284045	LEFT WING TANK OUTBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN13286	HRS	0		TSN 0				
WC#: 28.430	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284046	RIGHT WING TANK OUTBOARD FUEL QUANTITY TRANSMITTER							Component ATA:28
PN:128-389001-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MN3284	HRS	0		TSN 0				
WC#: 28.430	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00, AMM 28-41-00								
284050	LEFT FORWARD FUSELAGE FUEL TANK							Component ATA:28
PN:128-384016-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-52026	HRS	0		TSN 0				
WC#: 28.320	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00, AMM 28-11-00								
284051	RIGHT AFT FUEL FILLER TANK							Component ATA:28
PN:128-384018-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-54147	HRS	0		TSN 0				
WC#: 28.330	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00, AMM 28-11-00, AMM 28-11-00, AMM 28-11-00								
284052	RIGHT FORWARD FUSELAGE FUEL TANK							Component ATA:28
PN:128-384017-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-53163	HRS	0		TSN 0				
WC#: 28.320	AFL	0		TSN 0				
PROC. REF: AMM 28-11-00, AMM 28-11-00								
284057	DETAIL INSPECT LEFT FORWARD AUXILIARY FUEL TANK							Service ATA:28
	MOS	27-Sep-17						AIRWORTHINESS
	HRS	2572:52	2400 (+20)		4972:52	4992:52	365:45 (+20)	
WC#: 28.350	AFL	2281						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284058	DETAIL INSPECT RIGHT FORWARD AUXILIARY FUEL TANK							Service ATA:28
	MOS	27-Sep-17						AIRWORTHINESS
	HRS	2572:52	2400 (+20)		4972:52	4992:52	365:45 (+20)	
WC#: 28.350	AFL	2281						
284115	FUEL TEMPERATURE INDICATOR							Component ATA:28
PN:9053-3023	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:949	HRS	0		TSN 0				
WC#: 28.380	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00								
284121	LEFT TANK LOW LEVEL FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.390	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
284122	RIGHT TANK LOW LEVEL FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.390	AFL	0		TSN 0				
PROC. REF: AMM 28-21-00								
284123	LEFT WING FUEL OVERPRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.370	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00								
284124	RIGHT WING FUEL OVERPRESSURE SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.370	AFL	0		TSN 0				
PROC. REF: AMM 28-41-00								
284126	LEFT WING NO. 1 FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.460	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284127	LEFT WING NO. 2 FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.460	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
284128	RIGHT WING NO. 1 FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.470	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
284129	RIGHT WING NO. 2 FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.470	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
H240017 ^s	INSPECT ELECTRICAL WIRING AND CONNECTORS (BELOW FLOORPANELS)-PILOT'S COMPARTMENT							Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^s					
	AFL	3438						
								PKG:4
H280001 ^s	INSPECT FUEL STORAGE AREA - MIDFUSELAGE							Service ATA:28
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
								PKG:2
H280002 ^s	INSPECT FUEL SYSTEM PLUMBING AND COMPONENT MOUNTING+AO77 (RK-1 THRU RK-507 WITHOUT KIT 128-9008 INSTALLED) - MIDFUSELAGE							Service ATA:28
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
								PKG:2

?-Insufficient Information ^s-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
H280003 ^S		INSPECT FUEL FILTER ELEMENT (RK-1 THRU RK-507 WITHOUT KIT 128-9008 INSTALLED) - MIDFUSELAGE						Service ATA:28
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H280005 ^S		INSPECT MOTIVE-FLOW SHUTOFF VALVE, CROSSFEED VALVE, AND FUEL SHUTOFF VALVE (RK-1 THRU RK-507 WITHOUT KIT 128-9008 INSTALLED) - MIDFUSELAGE						Service ATA:28
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H280006 ^S		INSPECT FUEL SYSTEM PLUMBING AND COMPONENT MOUNTING (RK-106 THRU RK-507 WITH KIT 128-9008 INSTALLED; RK-508 ANDAFTER) - MIDFUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H280007 ^S		INSPECT MOTIVE-FLOW SHUTOFF VALVE, CROSSFEED VALVE,AND FUEL SHUTOFF VALVE (RK-106 THRU RK-507 WITH KIT128-9008 INSTALLED; RK-508 AND AFTER) - MIDFUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H280008 ^S		INSPECT FLAME ARRESTER (P/N 128-920211) - AFT FUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280009 ^S		ANTI-VAPOR SYSTEM - AFT FUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
H280010 ^S		INSPECT VENT SURGE TANK - AFT FUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280011 ^S		INSPECT FUSELAGE AUXILIARY FUEL STORAGE AREAS - CABIN SECTION						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280012 ^S		INSPECT MID- FUSELAGE FUEL STORAGE AREAS - MIDFUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280018 ^S		INSPECT FUSELAGE AUXILIARY FUEL TANK ASSEMBLY (P/N128-920185-1, -7, -19 AND 128-920186-1, -7, -19) - CABIN SECTION						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280018D ^S		INSPECT FUEL TANK, FUSELAGE FILLER (128-920022) (OUTER TANKINSPECTION ONLY)- SCHEDULED D INSPECTIONS						Service ATA:28
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H280019 ^S		INSPECT AFT FUSELAGE FUEL STORAGE AREA - AFT FUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280020 ^S		FILLER TANK FUEL STORAGE AREA - AFT FUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
H280022 ^S		INSPECT MIDFUSELAGE FUEL TANK (P/N 45A30901)- SCHEDULED D INSPECTIONCS						Service ATA:28
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H280023 ^S		INSPECT AFT FUEL CELL COMPARTMENT (P/N 45A34891)- SCHEDULED D INSPECTIONCS						Service ATA:28
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H280024 ^S		INSPECT AFT FUEL CELL COMPARTMENT (P/N 45A34891)- SCHEDULED D INSPECTIONCS						Service ATA:28
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H280025 ^S		INSPECT FUEL FILL SYSTEM FLAME ARRESTOR (P/N 128-920212) - MIDFUSELAGE						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280026 ^S		INSPECT FUEL SYSTEM - ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280027 ^S		INSPECT FUEL QUANTITY INDICATORS - PILOT'S COMPARTMENT						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280106 ^S		INSPECT FUEL COLLECTOR TANK- LEFT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
H280116 ^S		INSPECT FUEL VENT SYSTEM- LEFT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280117 ^S		INSPECT WING OVERPRESSURE SWITCH- LEFT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280126 ^S		FUEL LEVEL CONTROL SHUT-OFF VALVE (P/N1323-518100M2)- LEFT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280206 ^S		INSPECT FUEL COLLECTOR TANK- RIGHT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280216 ^S		INSPECT FUEL VENT SYSTEM- RIGHT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280217 ^S		INSPECT WING OVERPRESSURE SWITCH- RIGHT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H280226 ^S		FUEL LEVEL CONTROL SHUT-OFF VALVE (P/N1323-518100M2)- RIGHT-HAND WING						Service ATA:28
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291001	HYDRAULIC PACKAGE							Component ATA:29
PN:45AS65021-015	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:724	HRS	0		TSN 0				
WC#: 29.010	AFL	0		TSN 0				
PROC. REF: AMM 29-10-00								
291002	HYDRAULIC VALVE PACKAGE							Component ATA:29
PN:45AS65022-023	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:741	HRS	0		TSN 0				
WC#: 29.020	AFL	0		TSN 0				
PROC. REF: AMM 29-10-00								
291043	LEFT HYDRAULIC ISOLATION VALVE							Component ATA:29
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.030	AFL	0		TSN 0				
PROC. REF: AMM 29-10-00								
291044	RIGHT HYDRAULIC ISOLATION VALVE							Component ATA:29
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.030	AFL	0		TSN 0				
PROC. REF: AMM 29-10-00								
291055	NO. 1 ENGINE HYDRAULIC PUMP							Component ATA:29
PN:45AS65020-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MX714184C	HRS	0		TSN 0				
WC#: 29.040	AFL	0		TSN 0				
PROC. REF: AMM 29-10-00								
291056	NO. 2 ENGINE HYDRAULIC PUMP							Component ATA:29
PN:45AS65020-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MX714180C	HRS	0		TSN 0				
WC#: 29.040	AFL	0		TSN 0				
PROC. REF: AMM 29-10-00								
293001	HYDRAULIC PRESSURE TRANSDUCER							Component ATA:29
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.050	AFL	0		TSN 0				
PROC. REF: AMM 29-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293007	HYDRAULIC PRESSURE INDICATOR							Component ATA:29
PN:45AS86846-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:O7080941BA	HRS	0		TSN 0				
WC#: 29.060	AFL	0		TSN 0				
PROC. REF: AMM 29-30-00, AMM 29-30-00								
293013	HYDRAULIC LOW LEVEL SWITCH							Component ATA:29
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.070	AFL	0		TSN 0				
PROC. REF: AMM 29-30-00, AMM 29-30-00								
293014	LEFT HYDRAULIC LOW PRESSURE SWITCH							Component ATA:29
PN:45AS65572-009	MOS/MSC	27-Sep-17	O/C					
SN:K4800	HRS	2572:52						
WC#: 29.080	AFL	2281						
PROC. REF: AMM 29-30-00, AMM 29-30-00								
293015	RIGHT HYDRAULIC LOW PRESSURE SWITCH							Component ATA:29
PN:45AS65572-009	MOS/MSC	27-Sep-17	O/C					
SN:K4791	HRS	2572:52						
WC#: 29.080	AFL	2281						
PROC. REF: AMM 29-30-00, AMM 29-30-00								
H290001 ^S	INSPECT HYDRAULIC RESERVOIR - AFT FUSELAGE							Service ATA:29
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H290002 ^S	INSPECT HYDRAULIC PACKAGE, SYSTEM PLUMBING, COMPONENTS - AFT FUSELAGE							Service ATA:29
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H290003 ^S	INSPECT HYDRAULIC PACKAGE FLUID FILTER ELEMENTS - AFT FUSELAGE							Service ATA:29
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
H290004 ^S		INSPECT HYDRAULIC PACKAGE AIR FILTER - AFT FUSELAGE						Service ATA:29
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H290006 ^S		INSPECT HYDRAULIC PLUMBING - CABIN SECTION						Service ATA:29
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H290101 ^S		INSPECT LEFT BRAKE HYDRAULIC/PNEUMATIC LINES AND HOSES -LANDING GEAR AND BRAKES						Service ATA:29
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H290104 ^S		INSPECT HYDRAULIC LINES - LEFT-HAND THRUST REVERSER						Service ATA:29
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H290201 ^S		INSPECT RIGHT BRAKE HYDRAULIC/PNEUMATIC LINES ANDHOSES -LANDING GEAR AND BRAKES						Service ATA:29
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H290204 ^S		INSPECT HYDRAULIC LINES - RIGHT-HAND THRUST REVERSER						Service ATA:29
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 30 - ICE AND RAIN PROTECTION								
301001	WING ANTI-ICE CONTROL VALVE							Component ATA:30
PN:45AS66001-011	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0991A	HRS	0		TSN 0				
WC#: 30.010	AFL	0		TSN 0				

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-10-00								
301007	LEFT WING S054 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301008	RIGHT WING S052 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.020	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301009	LEFT WING S158 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301010	RIGHT WING S157 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301011	LEFT WING S191 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301012	RIGHT WING S192 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.040	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301013	LEFT WING S055 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301014	RIGHT WING S053 OVERTEMP SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
PROC. REF: AMM 30-10-00, AMM 30-10-00								
301067	ANTI-ICE TEMPERATURE CONTROLLER							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
301073	DEICE TIMER UNIT							Component ATA:30
PN:128-384054-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1248	HRS	0		TSN 0				
WC#: 30.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
301079	LEFT HORIZONTAL STABILIZER HEATER MAT							Component ATA:30
PN:128-380078-9	MOS/MSC	13-Aug-10	O/C	TSN 0				
SN:MBDL130	HRS	287:13		TSN 0				
WC#: 30.080	AFL	246		TSN 0				
PROC. REF: AMM 30-12-00								
301080	RIGHT HORIZONTAL STABILIZER HEATER MAT							Component ATA:30
PN:128-380078-10	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:MZXR750	HRS	0		TSN 0				
WC#: 30.080	AFL	0		TSN 0				
PROC. REF: AMM 30-12-00								
301081	LEFT ELEVATOR HORN HEATER MAT							Component ATA:30
PN:45AS66010-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-33741	HRS	0		TSN 0				
WC#: 30.090	AFL	0		TSN 0				
PROC. REF: AMM 30-12-00, AMM 30-12-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301082	RIGHT ELEVATOR HORN HEATER MAT							Component ATA:30
PN:45AS66010-020	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:05-40012	HRS	0		TSN 0				
WC#: 30.090	AFL	0		TSN 0				
PROC. REF: AMM 30-12-00, AMM 30-12-00								
301103	WING ANTI-ICE DUCT SWITCH							Component ATA:30
PN:45AS48008-003	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:H050843A	HRS	0		TSN 0				
WC#: 30.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
302001	LEFT NACELLE INLET BLEED AIR VALVE							Component ATA:30
PN:45AS63019-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1894	HRS	0		TSN 0				
WC#: 30.130	AFL	0		TSN 0				
PROC. REF: AMM 30-20-00, AMM 30-20-00								
302002	RIGHT NACELLE INLET BLEED AIR VALVE							Component ATA:30
PN:45AS63019-009	MOS/MSC	06-Nov-19	O/C					
SN:1651	HRS	3252:30						
WC#: 30.130	AFL	2932						
PROC. REF: AMM 30-20-00, AMM 30-20-00								
302005	LEFT PRESSURE REGULATOR SHUTOFF VALVE							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.210	AFL	0		TSN 0				
PROC. REF: AMM 21-10-00								
302006	RIGHT PRESSURE REGULATOR SHUTOFF VALVE							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.210	AFL	0		TSN 0				
PROC. REF: AMM 21-10-00								
302013	LEFT NACELLE TEMPERATURE SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.140	AFL	0		TSN 0				
PROC. REF: AMM 30-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
302014	RIGHT NACELLE TEMPERATURE SWITCH							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.140	AFL	0		TSN 0				
PROC. REF: AMM 30-20-00								
304007	LEFT WINDSHIELD WIPER MOTOR							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
304008	RIGHT WINDSHIELD WIPER MOTOR							Component ATA:30
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
304019	LEFT WINDSHIELD TEMPERATURE CONTROL							Component ATA:30
PN:HYZ50310	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:6477C	HRS	0		TSN 0				
WC#: 30.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
304020	RIGHT WINDSHIELD TEMPERATURE CONTROL							Component ATA:30
PN:HYZ50310	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:6480C	HRS	0		TSN 0				
WC#: 30.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
H300006 ^S	INSPECT HORIZONTAL STABILIZER DEICE SYSTEM - PILOTS COMPARTMENT							Service ATA:30
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H300007 ^S	INSPECT WINDSHIELD WIPERS (RK-1 THRU RK-242 WITHOUT KIT 128-5405 INSTALLED) - FORWARD FUSELAGE							Service ATA:30
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
H300008 ^S		INSPECT WINDSHIELD WIPERS (RK-1 THRU RK-242 WITHOUT KIT 128-5405INSTALLED) - FORWARD FUSELAGE						Service ATA:30
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H300009 ^S		INSPECT WINDSHIELD HEAT -FORWARD FUSELAGE						Service ATA:30
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H300010 ^S		INSPECT WING LEADING EDGE ANTI-ICE SYSTEM -ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:30
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H300011 ^S		PERFORM LEFT ELEVATOR HORN INSPECTION/CHECK						Service ATA:30
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 30.150	AFL	3695						
PROC. REF: AMM 30-12-00								PKG:1
H300012 ^S		PERFORM RIGHT ELEVATOR HORN INSPECTION/CHECK						Service ATA:30
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 30.150	AFL	3695						
PROC. REF: AMM 30-12-00								PKG:1
H300013 ^S		DETAILED INSPECTION DEICE SYSTEM TERMINAL BOARDS (TB011 & TB061)						Service ATA:30
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
	AFL	3695						
								PKG:1
H300105 ^S		INSPECT NACELLE ANTI-ICING DUCT -LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:30
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
H300205 ^S		INSPECT NACELLE ANTI-ICING DUCT -RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:30
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 31 - INDICATING/RECORDING SYSTEMS								
312001	PILOT CLOCK							Component ATA:31
PN:128-380060-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:O1057	HRS	0		TSN 0				
WC#: 31.010	AFL	0		TSN 0				
PROC. REF: AMM 31-20-10, AMM 31-20-20								
312002	COPILOT CLOCK							Component ATA:31
PN:128-380060-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1147	HRS	0		TSN 0				
WC#: 31.020	AFL	0		TSN 0				
PROC. REF: AMM 31-20-10, AMM 31-20-20								
312050	FLIGHT DATA RECORDER							Component ATA:31
PN:S800-2000-00	MOS/MSC	16-Apr-19	O/C					
SN:02259	HRS	3152:40						
WC#: 31.045	AFL	2836						
PROC. REF: AMM 31-30-00, AMM 31-30-00								
312052	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							Component ATA:31
PN:DK120	MOS	24-Feb-21	72	TSN 24	24-Feb-25		818 d	OVERHAUL
SN:AT126775	HRS	3386:14						
WC#: 31.045	AFL	3077						
PROC. REF: GENERIC CMM								
312055	REPLACE FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service ATA:31
PN:DK120	MOS/MSC	24-Feb-21	DUE		07-Feb-26 ^M		1166 d	
SN:AT126775	HRS	3386:14						
WC#: 31.045	AFL	3077						
PROC. REF: GENERIC CMM								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
312060	FUNCTION TEST UNDERWATER LOCATOR BEACON FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							Service ATA:31
	MOS	07-Oct-21	24		07-Oct-23		312 d	
	HRS	3611:43						
WC#: 31.045	AFL	3222						
PROC. REF: GENERIC CMM								
312065 ^U	INSPECT/CLEAN FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON SWITCH							Service ATA:31
	MOS	24-Feb-21	24		24-Feb-23		87 d	
	HRS	3386:14						
WC#: 31.045	AFL	3077						
PROC. REF: GENERIC CMM								
312067	INSPECTION CHECK FLIGHT DATA RECORDER							Service ATA:31
	MOS	15-Feb-22	12		15-Feb-23		78 d	
	HRS	3833:39						
WC#: 31.045	AFL	3354						
PROC. REF: AMM 31-30-00								
314001	NO. 1 ENVIRONMENTAL (IEC) CONTROL							Component ATA:31
PN:822-0333-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2P50V	HRS	0		TSN 0				
WC#: 31.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
314004	NO. 2 ENVIRONMENTAL (IEC) CONTROL							Component ATA:31
PN:822-0333-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2T55N	HRS	0		TSN 0				
WC#: 31.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
314013	NO. 1 FLIGHT MANAGEMENT FMC-5000 CARD							Component ATA:31
PN:822-0891-008	MOS/MSC	16-Apr-19	O/C	TSR 0				
SN:1C70	HRS	3152:40		TSR 0				
WC#: 31.060	AFL	2836		TSR 0				
314013A ^U	REPLACE NO. 1 DUAL FMC BATTERY (SB 25 INSTALLED)							Service ATA:31
	MOS	01-Mar-19	48		01-Mar-23		92 d	VENDOR RECOMMENDATION
	HRS							
	AFL							

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314013A ^U	REPLACE NO. 2 DUAL FMC BATTERY (SB 25 INSTALLED)							Service ATA:31
	MOS	16-Apr-19	48		16-Apr-23		138 d	VENDOR RECOMMENDATION
	HRS	3152:40						
	AFL	2836						
314016	NO. 2 FLIGHT MANAGEMENT FMC-5000 CARD							Component ATA:31
PN:822-0891-008	MOS/MSC	01-Mar-19	O/C	TSR 0				
SN:2RW3Y	HRS			TSR 0				
WC#: 31.060	AFL			TSR 0				
314050	MAINTENANCE DIAGNOSTIC COMPUTER							Component ATA:31
PN:622-9818-751	MOS/MSC	15-Apr-20	O/C	TSR 0				
SN:2886X	HRS	3278:23		TSR 0				
WC#: 34.800	AFL	2968		TSR 0				
PROC. REF: GENERIC NO REF								
314050A ^U	REPLACE MAINTENANCE DIAGNOSTIC COMPUTER ONBOARD BATTERY							Service ATA:31
	MOS	15-Apr-20	48		15-Apr-24		503 d	
	HRS	3278:39						
	AFL	2968						
ATA 32 - LANDING GEAR								
321001	INSPECT LEFT MAIN GEAR STRUT LEFT MAIN GEAR STRUT							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.010	AFL	0	5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: CMM 32-10-00, CMM 32-11-00								
321002	INSPECT RIGHT MAIN GEAR STRUT RIGHT MAIN GEAR STRUT							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.010	AFL	0	5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: CMM 32-10-00, CMM 32-11-00								
321003	INSPECT LEFT MAIN GEAR SIDE STRUT LEFT MAIN GEAR SIDE STRUT							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.030	AFL	0	5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: CMM 32-12-00, CMM 32-13-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321004	INSPECT RIGHT MAIN GEAR SIDE STRUT RIGHT MAIN GEAR SIDE STRUT							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.030	AFL	0	5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: CMM 32-12-00, CMM 32-13-00								
321005	LEFT MAIN GEAR STRUT							Component ATA:32
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.010	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: AMM 32-10-00								
321006	RIGHT MAIN GEAR STRUT							Component ATA:32
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.010	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: AMM 32-10-00								
321007	LEFT MAIN LANDING GEAR SHOCK STRUT							Component ATA:32
PN:128-810085-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:72	HRS	0		TSN 0				
WC#: 32.250	AFL	0		TSN 0				
PROC. REF: AMM 32-10-00								
321008	RIGHT MAIN LANDING GEAR SHOCK STRUT							Component ATA:32
PN:128-810085-618	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:10310701ICT	HRS	0		TSN 0				
WC#: 32.250	AFL	0		TSN 0				
PROC. REF: AMM 32-10-00								
321009	LEFT MAIN GEAR SIDE STRUT							Component ATA:32
PN:128-810081-5	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:OOO62	HRS	0		TSN 0				
WC#: 32.030	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: AMM 32-10-00, AMM 32-10-00								
321010	RIGHT MAIN GEAR SIDE STRUT							Component ATA:32
PN:128-810081-6	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:OOO62	HRS	0		TSN 0				
WC#: 32.030	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: AMM 32-10-00, AMM 32-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321047	LEFT MAIN LANDING GEAR SUPPORT FITTING							Component ATA:32
PN:45A10207-019	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:08130701SAL	HRS	0		TSN 0				
WC#: 32.050	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: GENERIC NO REF								
321048	RIGHT MAIN LANDING GEAR SUPPORT FITTING							Component ATA:32
PN:45A10207-020	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:10160701SAL	HRS	0		TSN 0				
WC#: 32.050	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: GENERIC NO REF								
321049	EDDY CURRENT INSPECT LEFT MAIN LANDING GEAR SUPPORT FITTING							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	T:5000 (+20)		5000	5020	392:53 (+20)	
WC#: 32.050	AFL	0						
PROC. REF: AMM 57-40-00								
321050	EDDY CURRENT INSPECT RIGHT MAIN LANDING GEAR SUPPORT FITTING							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	T:5000 (+20)		5000	5020	392:53 (+20)	
WC#: 32.050	AFL	0						
PROC. REF: AMM 57-40-00								
321060	REPLACE LEFT MAIN LANDING GEAR TORQUE LINK BOLT							Service ATA:32
	MOS	17-Mar-08						LIFE LIMIT
	HRS	0						
WC#: 32.420	AFL	0	9800		9800		5971	
PROC. REF: AMM 32-10-00								
321065	REPLACE RIGHT MAIN LANDING GEAR TORQUE LINK BOLT							Service ATA:32
	MOS	17-Mar-08						LIFE LIMIT
	HRS	0						
WC#: 32.420	AFL	0	9800		9800		5971	
PROC. REF: AMM 32-10-00								
322001	INSPECT NOSE GEAR STRUT NOSE GEAR STRUT							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.060	AFL	0	5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: CMM 32-20-00, CMM 32-21-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
322002	NOSE GEAR SHOCK STRUT							Component ATA:32
PN:128-820028-6011	MOS/MSC	25-Mar-11	O/C	TSN 36				
SN:11100701ICT	HRS	456:31		TSN 456:31				
WC#: 32.080	AFL	413		TSN 413				
PROC. REF: GENERIC NO REF								
322003	NOSE GEAR STRUT							Component ATA:32
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.060	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: AMM 32-20-00								
322009	INSPECT NOSE GEAR DRAG STRUT ASSEMBLY NOSE GEAR DRAG STRUT ASSEMBLY							Service ATA:32
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.035	AFL	0	5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: CMM 32-22-00, CMM 32-23-00								
322010	NOSE GEAR DRAG STRUT ASSEMBLY							Component ATA:32
PN:128-820044-1	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:OOO60	HRS	0		TSN 0				
WC#: 32.035	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: AMM 32-20-00								
322031	NOSE WHEEL SHIMMY DAMPER							Component ATA:32
PN:45100-41	MOS/MSC	17-Oct-18	O/C					
SN:00218	HRS	3052						
WC#: 32.090	AFL	2728						
PROC. REF: AMM 32-20-00, AMM 32-20-00								
322043	LEFT NOSE LANDING GEAR FITTING							Component ATA:32
PN:45A31311-021	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:02150704ICT	HRS	0		TSN 0				
WC#: 32.440	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: GENERIC NO REF								
322044	RIGHT NOSE LANDING GEAR FITTING							Component ATA:32
PN:45A31311-022	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:04040701ICT	HRS	0		TSN 0				
WC#: 32.440	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323000	LEFT MAIN LANDING GEAR RETRACTION CYLINDER							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323002	RIGHT MAIN LANDING GEAR RETRACTION CYLINDER							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.110	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323003	NOSE LANDING GEAR RETRACTION CYLINDER							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323004	LEFT MAIN LANDING GEAR UPLOCK MECHANISM ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00, AMM 32-30-00								
323005	RIGHT MAIN LANDING GEAR UPLOCK MECHANISM ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00, AMM 32-30-00								
323006	NOSE GEAR UPLOCK MECHANISM ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.150	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00, AMM 32-30-00								
323007	LEFT MAIN LANDING GEAR DOWNLOCK MECHANISM ACTUATOR							Component ATA:32
PN:45AS38510-007	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1571	HRS	0		TSN 0				
WC#: 32.160	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323008	RIGHT MAIN LANDING GEAR DOWNLOCK MECHANISM ACTUATOR							Component ATA:32
PN:45AS38510-008	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1538	HRS	0		TSN 0				
WC#: 32.160	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323009	NOSE GEAR DOWNLOCK MECHANISM ACTUATOR							Component ATA:32
PN:45AS39503-005	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:811	HRS	0		TSN 0				
WC#: 32.170	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323010	LEFT MAIN LANDING GEAR DOOR ACTUATOR							Component ATA:32
PN:45AS38515-007	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1717	HRS	0		TSN 0				
WC#: 32.180	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323011	RIGHT MAIN LANDING GEAR DOOR ACTUATOR							Component ATA:32
PN:45AS38515-008	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1684	HRS	0		TSN 0				
WC#: 32.180	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323015	EDDY CURRENT INSPECT LEFT MAIN LANDING GEAR RETRACTION CYLINDER							Service ATA:32
	MOS	17-Mar-08						
	HRS	0	T:7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.450	AFL	0	T:5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: AMM 20-80-03								
323016	EDDY CURRENT INSPECT RIGHT MAIN LANDING GEAR RETRACTION CYLINDER							Service ATA:32
	MOS	17-Mar-08						
	HRS	0	T:7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.450	AFL	0	T:5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: AMM 20-80-03								
323017	EDDY CURRENT INSPECT NOSE LANDING GEAR RETRACTION CYLINDER							Service ATA:32
	MOS	17-Mar-08						
	HRS	0	T:7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 32.460	AFL	0	T:5000 (+15)		5000	5015	1171 (+15)	
PROC. REF: AMM 20-80-03								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323018 ^U S VISUAL INSPECT LH MAIN LANDING GEAR DOOR, INNER SKIN NEAR PROTECTOR Service ATA:32								
	MOS	05-Oct-12						RESCINDED
	HRS	948:35						
	AFL	823						
323019 ^U S REPAIR/REPLACE LH MAIN LANDING GEAR DOOR ASSEMBLY Service ATA:32								
	MOS/MSC	05-Oct-12	DUE ^S					
	HRS	948:35						
	AFL	823						
323061 LEFT MAIN LANDING GEAR DOOR UPLOCK RELEASE CYLINDER Component ATA:32								
PN:45AS38516-007	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1609	HRS	0		TSN 0				
WC#: 32.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323062 RIGHT MAIN LANDING GEAR DOOR UPLOCK RELEASE CYLINDER Component ATA:32								
PN:45AS38516-008	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1618	HRS	0		TSN 0				
WC#: 32.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323063 NOSE LANDING GEAR UPLOCK RELEASE CYLINDER Component ATA:32								
PN:45AS39502-007	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2353	HRS	0		TSN 0				
WC#: 32.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323079 AIR STORAGE BOTTLE Component ATA:32								
PN:23111321-1	MOS	01-Mar-22	180	TSN 2	01-Jan-37		5147 d	LIFE LIMIT
SN:1823	HRS	3866:17						
WC#: 32.200	AFL	3375						
PROC. REF: AMM 32-30-00								
323085 HYDROSTATIC TEST AIR STORAGE BOTTLE Service ATA:32								
PN:23111321-1	MOS	27-Jan-22	36		27-Jan-25		790 d	AIRWORTHINESS
SN:1823	HRS							
WC#: 32.200	AFL							
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323087	EMERGENCY BRAKE/GEAR DOWN PRESSURE INDICATOR							Component ATA:32
PN:132-380062-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07H292	HRS	0		TSN 0				
WC#: 32.210	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
323091	LANDING GEAR CONTROL UNIT							Component ATA:32
PN:122-382038-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:555	HRS	0		TSN 0				
WC#: 32.220	AFL	0		TSN 0				
PROC. REF: AMM 32-30-00								
323093	REPLACE LEFT MAIN LANDING GEAR DOOR OPENING CABLE							Service ATA:32
	MOS	27-Sep-17						LIFE LIMIT
	HRS	2572:52	2400		4972:52	4972:52	365:45	
WC#: 32.230	AFL	2281						
PROC. REF: GENERIC NO REF								
323094	REPLACE RIGHT MAIN LANDING GEAR DOOR OPENING CABLE							Service ATA:32
	MOS	27-Sep-17						LIFE LIMIT
	HRS	2572:52	2400		4972:52	4972:52	365:45	
WC#: 32.230	AFL	2281						
PROC. REF: GENERIC NO REF								
323097	LEFT MAIN LANDING GEAR FITTING ASSEMBLY							Component ATA:32
PN:45A33506-007	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:1290701ICT	HRS	0		TSN 0				
WC#: 32.240	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: GENERIC NO REF								
323098	RIGHT MAIN LANDING GEAR FITTING ASSEMBLY							Component ATA:32
PN:45A33506-008	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:10290702ICT	HRS	0		TSN 0				
WC#: 32.240	AFL	0	15000	TSN 0	15000		11171	
PROC. REF: GENERIC NO REF								
324001	LEFT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5010720-1	MOS/MSC	31-Aug-22	O/C					
SN:DEC00-1526	HRS	4384:47						
WC#: 32.260	AFL	3695						
PROC. REF: AMM 32-40-00, AMM 32-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324002	RIGHT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5010720-1	MOS/MSC	31-Aug-22	O/C					
SN:AUG00-1505	HRS	4384:47						
WC#: 32.270	AFL	3695						
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324003	NOSE GEAR WHEEL							Component ATA:32
PN:5006450-5	MOS/MSC	31-Aug-22	O/C					
SN:MAY05-2629	HRS	4384:47						
WC#: 32.280	AFL	3695						
PROC. REF: AMM 32-40-00								
324008	INSPECT NOSE GEAR WHEEL							Service ATA:32
PN:5006450-5	MOS/MSC	31-Aug-22	T/C					
SN:MAY05-2629	HRS	4384:47						
WC#: 32.280	AFL	3695						
PROC. REF: AMM 32-40-00								
324009	INSPECT LEFT MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5010720-1	MOS/MSC	31-Aug-22	T/C					
SN:DEC00-1526	HRS	4384:47						
WC#: 32.260	AFL	3695						
PROC. REF: AMM 32-40-00								
324010	INSPECT RIGHT MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5010720-1	MOS/MSC	31-Aug-22	T/C					
SN:AUG00-1505	HRS	4384:47						
WC#: 32.270	AFL	3695						
PROC. REF: AMM 32-40-00								
324055	LEFT MAIN LANDING GEAR TIRE							Component ATA:32
PN:PN	MOS/MSC	31-Aug-22	O/C					
SN:UNKNOWN	HRS	4384:47						
WC#: 32.260	AFL	3695						
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324056	RIGHT MAIN LANDING GEAR TIRE							Component ATA:32
PN:PN	MOS/MSC	31-Aug-22	O/C					
SN:UNKNOWN	HRS	4384:47						
WC#: 32.270	AFL	3695						
PROC. REF: AMM 32-40-00, AMM 32-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324057	NOSE GEAR TIRE							Component ATA:32
PN:PN	MOS/MSC	31-Aug-22	O/C					
SN:UNKNOWN	HRS	4384:47						
WC#: 32.280	AFL	3695						
PROC. REF: AMM 32-40-00								
324073	LEFT MAIN GEAR BRAKE ASSEMBLY							Component ATA:32
PN:400-8002-97	MOS/MSC	30-Jun-22	O/C	TSO 0				
SN:NOV05-1252	HRS	4172:47		TSO 0				
WC#: 32.310	AFL	3558		TSO 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324074	RIGHT MAIN GEAR BRAKE ASSEMBLY							Component ATA:32
PN:400-8002-97	MOS/MSC	30-Jun-22	O/C	TSO 0				
SN:AUG95-334	HRS	4172:47		TSO 0				
WC#: 32.310	AFL	3558		TSO 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324096	CLEAN POWER BRAKE CONTROL VALVE FILTERS							Service ATA:32
	MOS	07-May-19						
	HRS	3976:37	1000 (+20)		4976:37	4996:37	369:30 (+20)	
WC#: 32.330	AFL	3438						
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324097	ANTI-SKID POWER BRAKE VALVE							Component ATA:32
PN:38-771	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:900	HRS	0		TSN 0				
WC#: 32.340	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324098	EMERGENCY BRAKE CONTROL VALVE							Component ATA:32
PN:45A65261-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:V345	HRS	0		TSN 0				
WC#: 32.350	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324099	LEFT MIXING VALVE							Component ATA:32
PN:C100169	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1425A	HRS	0		TSN 0				
WC#: 32.360	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324100	RIGHT MIXING VALVE							Component ATA:32
PN:C100169	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1427A	HRS	0		TSN 0				
WC#: 32.360	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324101	LEFT PARKING BRAKE VALVE							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.370	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324102	RIGHT PARKING BRAKE VALVE							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.370	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324139	HYDRAULIC EMERGENCY ACCUMULATOR							Component ATA:32
PN:33-073-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1034	HRS	0		TSN 0				
WC#: 32.380	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324145	ANTI-SKID CONTROL BOX							Component ATA:32
PN:42-901	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:916	HRS	0		TSN 0				
WC#: 32.390	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00								
324151	BRAKE FLUID RESERVOIR							Component ATA:32
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.410	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324157	PILOT LEFT MASTER BRAKE CYLINDER							Component ATA:32
PN:PN	MOS/MSC	27-Sep-17	O/C					
SN:UNKNOWN	HRS	2572:52						
WC#: 32.040	AFL	2281						
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324158	PILOT RIGHT MASTER BRAKE CYLINDER							Component ATA:32
PN:45AS38401-012	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:3286	HRS	0		TSN 0				
WC#: 32.040	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324159	COPILOT LEFT MASTER BRAKE CYLINDER							Component ATA:32
PN:45AS38401-012	MOS/MSC	07-May-22	O/C					
SN:2484	HRS	3976:37						
WC#: 32.290	AFL	3438						
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324160	COPILOT RIGHT MASTER BRAKE CYLINDER							Component ATA:32
PN:45AS38401-011	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:3295	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
PROC. REF: AMM 32-40-00, AMM 32-40-00								
324181	LEFT WHEEL SPEED TRANSDUCER							Component ATA:32
PN:140-03110	MOS	09-Apr-18	120	TSN 120, Adj -23	30-Jun-26 ^M		1309 d	REPLACE
SN:2231	HRS	2721:25	5000	TSN 7614:20, Adj -107:05	7614:20 ^M		3007:13	
WC#: 32.300	AFL	2437		Adj -112				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
324182	RIGHT WHEEL SPEED TRANSDUCER							Component ATA:32
PN:140-03110	MOS	09-Apr-18	120	TSN 120, Adj -23	30-Jun-26 ^M		1309 d	REPLACE
SN:2232	HRS	2721:25	5000	TSN 7614:20, Adj -107:05	7614:20 ^M		3007:13	
WC#: 32.300	AFL	2437		Adj -112				
PROC. REF: AMM 32-40-00, AMM 32-40-00, AMM 32-40-00								
H320001 ^S	INSPECT NOSE WHEEL AND TIRE - LANDING GEAR AND BRAKES							Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320002 ^S		INSPECT NOSE LANDING GEAR STRUT ASSEMBLY - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320003 ^S		INSPECT NOSE LANDING GEAR WHEEL WELL -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320009 ^S		LANDING GEAR EXTENSION/RETRACTION SYSTEM - PERFORM NORMAL EMERGENCY EXTENSION RETRACTION VERIFICATION CHECK - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320013 ^S		INSPECT MASTER BRAKE CYLINDERS (ABOVE FLOOR PANELS) - PILOTS COMPARTMENT						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320014 ^S		INSPECT NITROGEN SYSTEM - FORWARD FUSELAGE						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320015 ^S		INSPECT BRAKE SYSTEM - MID FUSELAGE						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320017 ^S		INSPECT NOSE LANDING GEAR DRAG STRUT ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320018 ^S		INSPECT NOSE LANDING GEAR UPLOCK ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320019 ^S		INSPECT NOSE LANDING GEAR EMERGENCY EXTENSION CABLE -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320020 ^S		INSPECT NOSE LANDING GEAR STRUT ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320023 ^S		INSPECT EMERGENCY LANDING GEAR-PILOT'S COMPARTMENT						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320024 ^S		INSPECT BRAKE SYSTEM - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320026 ^S		INSPECT ANTI-SKID SYSTEM -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320030 ^S		INSPECT NOSE LANDING GEAR SHIMMY DAMPER - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320031 ^S		INSPECT EMERGENCY LANDING GEAR CABLES - CABIN SECTION						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320032 ^S		INSPECT EMERGENCY BRAKE-PILOT'S COMPARTMENT						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320035 ^S		INSPECT MAIN LANDING GEAR DOOR ACTUATOR FITTING- SCHEDULED D INSPECTIONCS						Service ATA:32
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H320036 ^S		INSPECT NOSE LANDING GEAR SUPPORT FITTING (P/N 45A31311)- SCHEDULED D INSPECTIONCS						Service ATA:32
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H320037 ^S		INSPECT NOSE WHEEL AND TIRE -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320038 ^S		INSPECT NOSE WHEEL STEERING SYSTEM -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320039 ^S		INSPECT BRAKE SYSTEM ACCUMULATOR - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320040 ^S		INSPECT LANDING GEAR SYSTEM -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320041 ^S		INSPECT MANUAL BRAKE SYSTEM - PILOTS COMPARTMENT						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320104 ^S		INSPECT LEFT MAIN WHEEL - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320105 ^S		INSPECT LEFT BRAKE ASSEMBLY - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320106 ^S		INSPECT LEFT MAIN LANDING GEAR STRUT ASSEMBLY - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320107 ^S		INSPECT LEFT MAIN ACTUATOR BRACKET -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320108 ^S		INSPECT LEFT MAIN WHEEL WELL AND AREA INSPECTION (PANELREMOVAL NOT REQUIRED) -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320109 ^S		INSPECT LEFT BRAKE ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320120 ^S		INSPECT LEFT LANDING GEAR SAFETY SWITCH -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320121 ^S		INSPECT LEFT MAIN LANDING GEAR SIDE STRUT ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320122 ^S		INSPECT LEFT MAIN LANDING GEAR AND DOOR UPLOCK HOOKAND UPLOCK ASSEMBLIES -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320123 ^S		INSPECT LEFT MAIN GEAR ATTACH FITTINGS, SUPPORTINGSPARS, RIB AND UPLOCK FITTING - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320124 ^S		INSPECT LEFT MAIN LANDING GEAR STRUT ASSEMBLY						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320125 ^S		INSPECT LEFT MAIN WHEEL -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320126 ^S		INSPECT LEFT MAIN WHEEL WELL - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320204 ^S		INSPECT RIGHT MAIN WHEEL - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320205 ^S		INSPECT RIGHT BRAKE ASSEMBLY - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320206 ^S		INSPECT RIGHT MAIN LANDING GEAR STRUT ASSEMBLY - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H320207 ^S		INSPECT RIGHT MAIN ACTUATOR BRACKET -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320208 ^S		INSPECT RIGHT MAIN WHEEL WELL AND AREA INSPECTION (PANELREMOVAL NOT REQUIRED) -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320209 ^S		INSPECT RIGHT BRAKE ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320220 ^S		INSPECT RIGHT LANDING GEAR SAFETY SWITCH -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320221 ^S		INSPECT RIGHT MAIN LANDING GEAR SIDE STRUT ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320222 ^S		INSPECT RIGHT MAIN LANDING GEAR AND DOOR UPLOCK HOOKAND UPLOCK ASSEMBLIES -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320223 ^S		INSPECT RIGHT MAIN GEAR ATTACH FITTINGS, SUPPORTINGSPARS, RIB AND UPLOCK FITTING - LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H320224 ^S		INSPECT RIGHT MAIN LANDING GEAR STRUT ASSEMBLY -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H320225 ^S		INSPECT RIGHT MAIN WHEEL -LANDING GEAR AND BRAKES						Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H320226 ^S	INSPECT RIGHT MAIN WHEEL WELL - AREA INSPECTION (PANELSREMOVED) - LANDING GEAR AND BRAKES							Service ATA:32
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
ATA 33 - LIGHTS								
331001	INSTRUMENT LIGHT (PS103) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.010	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
331002	INSTRUMENT LIGHT (PS104) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.010	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
331003	INSTRUMENT LIGHT (PS105) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
331004	INSTRUMENT LIGHT (PS106) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								
331005	INSTRUMENT LIGHT (PS107) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0		TSN 0				
PROC. REF: AMM 33-11-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331010	LEFT FORWARD INTERIOR LIGHT (4034) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.025	AFL	0		TSN 0				
PROC. REF: AMM 33-20-00, AMM 33-20-00								
331012	AFT INTERIOR LIGHT (4035) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.025	AFL	0		TSN 0				
PROC. REF: AMM 33-20-00, AMM 33-20-00								
331014	RIGHT FORWARD INTERIOR LIGHT (4036) POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.025	AFL	0		TSN 0				
PROC. REF: AMM 33-20-00, AMM 33-20-00								
334001	LEFT WING NAVIGATION/ANTI-COLLISION LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334002	RIGHT WING NAVIGATION/ANTI-COLLISION LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.030	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334003	TAIL ANTI-COLLISION LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.040	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334004	LEFT LANDING LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.050	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00, AMM 33-40-00, AMM 33-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334005	RIGHT LANDING LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.050	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00, AMM 33-40-00, AMM 33-40-00								
334006	LEFT TAIL FLOOD LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334007	RIGHT TAIL FLOOD LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334008	TAIL NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.045	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334009	FORWARD RECOGNITION LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.065	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334011	WING ICE INSPECTION LIGHT							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.070	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								
334031	ANTI-COLLISION LIGHT POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.080	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334037	LEFT LANDING LIGHT ACTUATOR							Component ATA:33
PN:45AS88830-007	MOS/MSC	27-Sep-17	O/C					
SN:001108	HRS	2572:52		TSO 0				
WC#: 33.090	AFL	2281		TSO 0				
PROC. REF: AMM 33-40-00, AMM 33-40-00								
334038	RIGHT LANDING LIGHT ACTUATOR							Component ATA:33
PN:45AS88830-007	MOS/MSC	27-Sep-17	O/C					
SN:90203	HRS	2572:52		TSO 0				
WC#: 33.090	AFL	2281		TSO 0				
PROC. REF: AMM 33-40-00, AMM 33-40-00								
334061	TAIL ROTATING BEACON							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.100	AFL	0		TSN 0				
PROC. REF: AMM 33-40-00, AMM 33-40-00								
335030	FORWARD EMERGENCY LIGHT POWER SUPPLY							Component ATA:33
PN:87-5106-2	MOS/MSC	06-Nov-19	O/C					
SN:5013	HRS	3252:30						
WC#: 33.150	AFL	2932						
PROC. REF: AMM 33-51-00, AMM 33-51-00							WO#: JB2022-BZZ-023	
335031	REPLACE FORWARD EMERGENCY LIGHT POWER SUPPLY BATTERY							Service ATA:33
PN:87-5106-2	MOS	06-Nov-19	36		RTS			
SN:5013	HRS	3252:30						
WC#: 33.150	AFL	2932						
PROC. REF: AMM 33-51-00							WO#: JB2022-BZZ-023	
335032	AFT EMERGENCY LIGHT POWER SUPPLY							Component ATA:33
PN:87-5106-2	MOS/MSC	06-Nov-19	O/C					
SN:1223391	HRS	3252:30						
WC#: 33.160	AFL	2932						
PROC. REF: AMM 33-51-00, AMM 33-51-00							WO#: JB2022-BZZ-023	
335033	REPLACE AFT EMERGENCY LIGHT POWER SUPPLY BATTERY							Service ATA:33
PN:87-5106-2	MOS	06-Nov-19	36		RTS			
SN:1223391	HRS	3252:30						
WC#: 33.160	AFL	2932						
PROC. REF: AMM 33-51-00							WO#: JB2022-BZZ-023	

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
335066	NO. 1 LAMP DIMMER							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335067	NO. 2 LAMP DIMMER							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335068	NO. 3 LAMP DIMMER							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
335069	NO. 4 LAMP DIMMER							Component ATA:33
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
H330001 ^S	INSPECT CABIN INTERIOR LIGHTS - CABIN SECTION							Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H330003 ^S	PERFORM EMERGENCY LIGHTING SYSTEM OPERATIONAL INSPECTION - (RK-98, RK-110 AND AFTER) CABIN SECTION							Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H330004 ^S	INSPECT FORWARD RECOGNITION LIGHT ASSEMBLY - VERTICAL STABILIZER							Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
H330005 ^S		INSPECT TAIL FLOOD LIGHTS - HORIZONTAL STABILIZER						Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H330006 ^S		INSPECT COCKPIT ADVISORY, CAUTION AND WARNING LIGHTS - PILOT'S COMPARTMENT						Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H330007 ^S		INSPECT EMERGENCY LIGHTING SYSTEM - CABIN SECTION						Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H330008 ^S		INSPECT FLIGHT COMPARTMENT LIGHTING - PILOTS COMPARTMENT						Service ATA:33
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H330009 ^S		INSPECT EXTERIOR LIGHTING - PILOTS COMPARTMENT						Service ATA:33
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H330010 ^S		INSPECT EMERGENCY LIGHTING SYSTEM(RK-1 THRU RK-109, EXCEPT RK-98) - CABIN SECTION						Service ATA:33
	MOS							
	HRS		800 ^S					
	AFL							
								PKG:3
H330011 ^S		INSPECT EMERGENCY LIGHTING SYSTEM(RK-98, RK-110 AND AFTER) - CABIN SECTION						Service ATA:33
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
H330012 ^S	INSPECT ANTI-COLLISION LIGHT ASSEMBLY - RIGHT-HAND WING							Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H330013 ^S	INSPECT ANTI-COLLISION LIGHT ASSEMBLY - LEFT-HAND WING							Service ATA:33
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 34 - NAVIGATION								
341001	LEFT PITOT TUBE							Component ATA:34
PN:PH1100-MU-L-1	MOS/MSC	27-Sep-17	O/C					
SN:AS09165019	HRS	2572:52						
WC#: 34.010	AFL	2281						
PROC. REF: AMM 34-12-00								
341002	RIGHT PITOT TUBE							Component ATA:34
PN:PH1100MU-R-1	MOS/MSC	03-May-12	O/C	TSN 0				
SN:1920506	HRS	768:08		TSN 0				
WC#: 34.010	AFL	681		TSN 0				
PROC. REF: AMM 34-12-00								
341013	LEFT LOWER PILOT STATIC PORT							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.020	AFL	0		TSN 0				
PROC. REF: AMM 34-12-00, AMM 34-12-00								
341014	RIGHT UPPER PILOT STATIC PORT							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.020	AFL	0		TSN 0				
PROC. REF: AMM 34-12-00, AMM 34-12-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341015	LEFT UPPER COPILOT STATIC PORT							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				
PROC. REF: AMM 34-12-00, AMM 34-12-00								
341016	RIGHT LOWER COPILOT STATIC PORT							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				
PROC. REF: AMM 34-12-00, AMM 34-12-00								
341017	THIRD SYSTEM STATIC PORT							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341043	LEAK CHECK PILOT PITOT STATIC SYSTEM (FAR 91.411)							Service ATA:34
	MOS	07-Oct-21	24		07-Oct-23		312 d	
	HRS	3611:43						
WC#: 34.145	AFL	3222						
PROC. REF: AMM 34-12-00								
341044	LEAK CHECK CO-PILOT PITOT STATIC SYSTEM (FAR 91.411)							Service ATA:34
	MOS	07-Oct-21	24		07-Oct-23		312 d	
	HRS	3611:43						
WC#: 34.145	AFL	3222						
PROC. REF: AMM 34-12-00								
341052	STANDBY MACH/AIRSPEED INDICATOR							Component ATA:34
PN:128-380023-7	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:AM420	HRS	0		TSN 0				
WC#: 34.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341055	PILOT MACH/AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341056	COPILOT MACH/AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341058	COPILOT INSTANTANEOUS VERTICAL SPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341062	(DRI-55) RADIO ALTITUDE INDICATOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.100	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341063	ANGLE OF ATTACK INDICATOR							Component ATA:34
PN:30AN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0762	HRS	0		TSN 0				
WC#: 34.110	AFL	0		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341065	CABIN RATE OF CLIMB INDICATOR							Component ATA:34
PN:35060-1164	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:364353	HRS	0		TSN 0				
WC#: 34.120	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341117	STANDBY ALTIMETER							Component ATA:34
PN:132739-42	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1045557	HRS	0		TSN 0				
WC#: 34.090	AFL	0		TSN 0				
WO#: JB2021-BZZ-006								
341125	TEST STANDBY ALTIMETER FAR 91.411							Service ATA:34
PN:132739-42	MOS	07-Oct-21	24		07-Oct-23		312 d	MANDATORY
SN:1045557	HRS							
WC#: 34.090	AFL							
PROC. REF: FAR 91.411								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341127	MACH/AIRSPEED WARNING HORN							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341128	ALTITUDE ALERT WARNING HORN							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.160	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341129	GEAR WARNING HORN							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341130	TRIM WARNING HORN							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341139	FUNCTIONAL TEST MACH OVERSPEED WARNING SYSTEM							Service ATA:34
	MOS	07-Oct-21	24		07-Oct-23		312 d	
	HRS	3611:43						
WC#: 34.730	AFL	3222						
PROC. REF: AMM 34-12-00								
341145	NO.1 AIR DATA COMPUTER							Component ATA:34
PN:822-0389-633	MOS/MSC	12-Jun-14	O/C	TSO 0				
SN:248WB	HRS	1669:17		TSO 0				
WC#: 34.190	AFL	1409		TSO 0				
WO#: JB2021-BZZ-006								
341146	NO.2 AIR DATA COMPUTER							Component ATA:34
PN:822-0389-633	MOS/MSC	06-Nov-19	O/C					
SN:2VBLJ	HRS	3252:30						
WC#: 34.200	AFL	2932						
WO#: JB2021-BZZ-006								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341147	LEFT STALL WARNING COMPUTER							Component ATA:34
PN:0020BG1	MOS/MSC	27-Sep-17	O/C					
SN:22838	HRS	2572:52						
WC#: 34.210	AFL	2281						
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341148	RIGHT STALL WARNING COMPUTER							Component ATA:34
PN:20BG1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:23583	HRS	0		TSN 0				
WC#: 34.210	AFL	0		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341169	TEST NO.1 AIR DATA COMPUTER FAR 91.411							Service ATA:34
PN:822-0389-633	MOS	07-Oct-21	24		07-Oct-23		312 d	MANDATORY
SN:248WB	HRS							
WC#: 34.190	AFL							
PROC. REF: FAR 91.411								
341170	TEST NO.2 AIR DATA COMPUTER FAR 91.411							Service ATA:34
PN:822-0389-633	MOS	07-Oct-21	24		07-Oct-23		312 d	MANDATORY
SN:2VBLJ	HRS							
WC#: 34.200	AFL							
PROC. REF: FAR 91.411								
341176	VISUALLY INSPECT AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) WIRING (IF INSTALLED) RK-483 AND AFTER-OPTIONAL							Service ATA:34
	MOS/MSC	23-Nov-12	N/R					
	HRS							
WC#: 34.810	AFL							
341177	DETAIL INSPECT AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) ANTENNA FUSELAGE FEED-THROUGH (FS 378.54 - LOWER FUSELAGE (IF INSTALLED))							Service ATA:34
	MOS/MSC	23-Nov-12	N/R					
	HRS							
WC#: 34.820	AFL							
PROC. REF: MMS 05-20-01								
341185	NO. 1 NAVIGATION DATA COMPUTER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341186	NO. 2 NAVIGATION DATA COMPUTER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341193	(55B) RADIO ALTITUDE TRANSCEIVER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
341195	RADIO ALTIMETER CONVERTER							Component ATA:34
PN:622-7209-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2L96L	HRS	0		TSN 0				
WC#: 34.245	AFL	0		TSN 0				
341199	RADIO ALTITUDE RECEIVER ANTENNA							Component ATA:34
PN:S67-2002-14	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:546-8673	HRS	0		TSN 0				
WC#: 34.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
341200	CHECK AIR DATA SYSTEM FOR RVSM ACCURACY, MEASURE STEP HEIGHT OF THE STATIC PORT.							Service ATA:34
	MOS	07-Oct-21	24		07-Oct-23		312 d	
	HRS	3611:43						
WC#: 34.790	AFL	3222						
PROC. REF: AMM 34-10-01								
341211	LEFT ANGLE OF ATTACK TRANSMITTER							Component ATA:34
PN:0861EB1	MOS/MSC	11-Apr-12	O/C	TSN 0				
SN:1369	HRS	764:32		TSN 0				
WC#: 34.280	AFL	673		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341212	RIGHT ANGLE OF ATTACK TRANSMITTER							Component ATA:34
PN:0861EB	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1513	HRS	0		TSN 0				
WC#: 34.280	AFL	0		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341223	LEFT STALL WARNING SHAKER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.290	AFL	0		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341224	RIGHT STALL WARNING SHAKER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.290	AFL	0		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341235	ANGLE OF ATTACK INDEXER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.300	AFL	0		TSN 0				
PROC. REF: AMM 34-11-00, AMM 34-11-00								
341300	RADIO ALTITUDE TRANSMITTER ANTENNA							Component ATA:34
PN:S67-2002-14	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:546-8691	HRS	0		TSN 0				
WC#: 34.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342001	STANDBY MAGNETIC COMPASS							Component ATA:34
PN:CB2100T6D	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RA-01856	HRS	0		TSN 0				
WC#: 34.310	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342002 ^U	SWING CHECK STANDBY MAGNETIC COMPASS IAW AMM 34-21-00							Service ATA:34
	MOS	15-Feb-22	12		15-Feb-23		78 d	
	HRS	3833:39						
	AFL	3354						
342005 ^U	SWING CHECK NO. 1 MAIN COMPASS LH MAIN COMPASS (AHRS) IAW AMM 34-20-00							Service ATA:34
	MOS	15-Feb-22	12		15-Feb-23		78 d	
	HRS	3833:39						
	AFL	3354						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342007 ^U	SWING CHECK NO. 2 MAIN COMPASS RH MAIN COMPASS (AHRS) IAW AMM 34-20-00							Service ATA:34
	MOS	15-Feb-22	12		15-Feb-23		78 d	
	HRS	3833:39						
	AFL	3354						
342037	NO. 1 COMPASS FLUX VALVE							Component ATA:34
PN:622-5812-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:38742	HRS	0		TSN 0				
WC#: 34.350	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342038	NO. 2 COMPASS FLUX VALVE							Component ATA:34
PN:622-5812-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:38222	HRS	0		TSN 0				
WC#: 34.350	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342056	THIRD ATTITUDE INDICATOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.370	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342151	NO. 1 ALTITUDE SENSOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.500	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342152	NO. 1 AIR SPEED SENSOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.510	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342153	NO. 2 ALTITUDE SENSOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.500	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342154	NO. 2 AIR SPEED SENSOR							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.510	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
342180	STANDBY GYRO							Component ATA:34
PN:122-382015-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1271	HRS	0		TSN 0				
WC#: 34.520	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
343013	VOR/LOC ANTENNA COUPLER							Component ATA:34
PN:DMH21-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:34566	HRS	0		TSN 0				
WC#: 34.540	AFL	0		TSN 0				
343014	GLIDESLOPE COUPLER							Component ATA:34
PN:101-380043	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:19097	HRS	0		TSN 0				
WC#: 34.550	AFL	0		TSN 0				
343015	NAVIGATION/MARKER COUPLER							Component ATA:34
PN:101-380042	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:35347	HRS	0		TSN 0				
WC#: 34.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
343025	NO. 1 VOR/LOC ANTENNA							Component ATA:34
PN:S65-247-12	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:6968	HRS	0		TSN 0				
WC#: 34.560	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
343026	NO. 2 VOR/LOC ANTENNA							Component ATA:34
PN:S65-247-12	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:6969	HRS	0		TSN 0				
WC#: 34.560	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
343027	GLIDESLOPE ANTENNA							Component ATA:34
PN:RGS10-48	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:13005	HRS	0		TSN 0				
WC#: 34.570	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
343028	MARKER BEACON ANTENNA							Component ATA:34
PN:DMN27-3	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:16090	HRS	0		TSN 0				
WC#: 34.580	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
344001	WEATHER RADAR							Component ATA:34
PN:622-8440-004	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2MYTK	HRS	0		TSN 0				
WC#: 34.590	AFL	0		TSN 0				
344002	CLEAN/INSPECT/LUBRICATE WEATHER RADAR							Service ATA:34
	MOS/MSC	17-Mar-08	O/C					
	HRS	0						
WC#: 34.220	AFL	0						
345000	NO. 1 ADF RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2K9WW	HRS	0		TSN 0				
WC#: 34.620	AFL	0		TSN 0				
345001	NO. 2 ADF RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2K9WY	HRS	0		TSN 0				
WC#: 34.620	AFL	0		TSN 0				
345002	NO. 1 NAVIGATION RECEIVER							Component ATA:34
PN:622-7194-201	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NGWL	HRS	0		TSN 0				
WC#: 34.630	AFL	0		TSN 0				
345003	NO. 2 NAVIGATION RECEIVER							Component ATA:34
PN:622-7194-201	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NGWM	HRS	0		TSN 0				
WC#: 34.630	AFL	0		TSN 0				

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345004 ^S	CHECK VOR ACCURACY	FAR 91.171						Service ATA:34
	DAYS	14-Mar-08	30 ^S					
	HRS							
WC#: 34.525	AFL							
PROC. REF: FAR 91.171								
345024	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2R8NK	HRS	0		TSN 0				
WC#: 34.650	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345025	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	05-Aug-16	O/C	TSO 11				
SN:GD0F	HRS	2395:32		TSO 0				
WC#: 34.650	AFL	2090		TSO 0				
PROC. REF: GENERIC NO REF								
345026	NO. 1 TRANSPONDER TRANSCEIVER							Component ATA:34
PN:622-9210-502	MOS/MSC	14-Jun-21	O/C					
SN:2X6DP	HRS	3409:02						
WC#: 34.660	AFL	3097						
PROC. REF: AMM 34-57-01								
							WO#: JB2021-BZZ-006	
345027	NO. 2 TRANSPONDER TRANSCEIVER							Component ATA:34
PN:622-9210-502	MOS/MSC	14-Jun-21	O/C					
SN:2X6DB	HRS	3409:02						
WC#: 34.660	AFL	3097						
PROC. REF: AMM 34-57-01								
							WO#: JB2021-BZZ-006	
345043	TEST NO. 1 TRANSPONDER TRANSCEIVER	FAR 91.413						Service ATA:34
PN:622-9210-502	MOS	07-Oct-21	24		07-Oct-23		312 d	MANDATORY
SN:2X6DP	HRS							
WC#: 34.660	AFL							
PROC. REF: FAR 91.413								
345044	TEST NO. 2 TRANSPONDER TRANSCEIVER	FAR 91.413						Service ATA:34
PN:622-9210-502	MOS	07-Oct-21	24		07-Oct-23		312 d	MANDATORY
SN:2X6DB	HRS							
WC#: 34.660	AFL							
PROC. REF: FAR 91.413								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345085	ADF ANTENNA							Component ATA:34
PN:622-7383-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2RC7J	HRS	0		TSN 0				
WC#: 34.710	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345086	NO. 1 DME ANTENNA							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:116219	HRS	0		TSN 0				
WC#: 34.720	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345087	NO. 1 TRANSPONDER ANTENNA							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:116216	HRS	0		TSN 0				
WC#: 34.700	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01								
345088	NO. 2 TRANSPONDER ANTENNA							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:116225	HRS	0		TSN 0				
WC#: 34.700	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01								
345090	NO. 2 DME ANTENNA							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:116218	HRS	0		TSN 0				
WC#: 34.720	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345098	VLF (LOOP) ANTENNA							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.640	AFL	0		TSN 0				
345610	NO. 1 FLIGHT CONTROL COMPUTER							Component ATA:34
PN:822-1019-313	MOS/MSC	12-Jun-14	O/C					
SN:GDMG	HRS	1669:17						
WC#: 34.230	AFL	1409						

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345615	NO. 2 FLIGHT CONTROL COMPUTER							Component ATA:34
PN:822-1019-313	MOS/MSC	12-Jun-14	O/C					
SN:2RWPL	HRS	1669:17						
WC#: 34.230	AFL	1409						
345620	AUTO TRIM COUPLER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.390	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345635	NO. 1A IAPS/IO CONCENTRATOR							Component ATA:34
PN:622-9814-514	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2WW1R	HRS	0		TSN 0				
WC#: 34.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345640	NO. 1B IAPS/IO CONCENTRATOR							Component ATA:34
PN:622-9814-514	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2WW1P	HRS	0		TSN 0				
WC#: 34.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345645	NO. 2A IAPS/IO CONCENTRATOR							Component ATA:34
PN:622-9814-514	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2WWCX	HRS	0		TSN 0				
WC#: 34.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345650	NO. 2B IAPS/IO CONCENTRATOR							Component ATA:34
PN:622-9814-514	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2WWCY	HRS	0		TSN 0				
WC#: 34.460	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345655	NO. 1A IAPS/IO POWER SUPPLY							Component ATA:34
PN:622-9945-021	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2T6WD	HRS	0		TSN 0				
WC#: 34.225	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345660	NO. 1B IAPS/IO POWER SUPPLY							Component ATA:34
PN:622-9945-021	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2T6WJ	HRS	0		TSN 0				
WC#: 34.225	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345665	NO. 2A IAPS/IO POWER SUPPLY							Component ATA:34
PN:622-9945-021	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2T6WK	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345670	NO. 2B IAPS/IO POWER SUPPLY							Component ATA:34
PN:622-9945-021	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2T6WN	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345675	NO. 1 ATTITUDE HEADING COMPUTER							Component ATA:34
PN:622-9336-400	MOS/MSC	25-Mar-11	O/C					
SN:2FVGN	HRS	456:31						
WC#: 34.600	AFL	418						
PROC. REF: GENERIC NO REF								
345680	NO. 2 ATTITUDE HEADING COMPUTER							Component ATA:34
PN:622-9336-400	MOS/MSC	25-Mar-11	O/C					
SN:2FVGM	HRS	456:31						
WC#: 34.600	AFL	418						
PROC. REF: GENERIC NO REF								
345685	NO. 1 UNIT (ICU-85) COMPENSATOR							Component ATA:34
PN:622-6189-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:170Y3N	HRS	0		TSN 0				
WC#: 34.680	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345690	NO. 2 UNIT (ICU-85) COMPENSATOR							Component ATA:34
PN:622-6189-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:170Y3P	HRS	0		TSN 0				
WC#: 34.680	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345695	NO. 1 AIR DATA MODULE							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.690	AFL	0		TSN 0				
345700	NO. 2 AIR DATA MODULE							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.690	AFL	0		TSN 0				
345705	DATA ACQUISITION UNIT							Component ATA:34
PN:622-9344-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2G97M	HRS	0		TSN 0				
WC#: 34.670	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345710	PILOT SENSOR UNIT DISPLAY							Component ATA:34
PN:622-9735-001	MOS/MSC	15-Sep-11	O/C					
SN:29XXN	HRS	622:23						
WC#: 34.610	AFL	547						
PROC. REF: GENERIC NO REF								
345715	COPILOT SENSOR UNIT DISPLAY							Component ATA:34
PN:622-9735-001	MOS/MSC	15-Sep-11	O/C					
SN:36CHX	HRS	622:23						
WC#: 34.610	AFL	547						
PROC. REF: GENERIC NO REF								
345720	SENSOR DISPLAY DRIVER UNIT							Component ATA:34
PN:622-9347-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NP4R	HRS	0		TSN 0				
WC#: 34.530	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345725	PILOT MODE SELECT PANEL							Component ATA:34
PN:622-8330-003	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NP4T	HRS	0		TSN 0				
WC#: 34.490	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345730	COPILOT MODE SELECT PANEL							Component ATA:34
PN:622-8330-003	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2NP6Y	HRS	0		TSN 0				
WC#: 34.490	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345735	PILOT CONTROL DISPLAY UNIT							Component ATA:34
PN:822-0892-015	MOS/MSC	02-Jul-19	O/C					
SN:604	HRS	3229						
WC#: 34.480	AFL	2910						
PROC. REF: GENERIC NO REF								
345740	COPILOT CONTROL DISPLAY UNIT							Component ATA:34
PN:822-0892-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2CR6Y	HRS	0		TSN 0				
WC#: 34.480	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345745	COURSE HEADING PANEL							Component ATA:34
PN:622-7397-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:170Y24	HRS	0		TSN 0				
WC#: 34.470	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345750	SIGNAL INTERFACE ADAPTER							Component ATA:34
PN:622-9732-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2VC0Y	HRS	0		TSN 0				
WC#: 34.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345755	CONTROL DISPLAY COUPLER							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
345760	DATA BASE UNIT							Component ATA:34
PN:822-2215-102	MOS/MSC	03-Mar-19	O/C	TSN 0				
SN:4GN574	HRS	3135:50		TSN 0				
WC#: 34.420	AFL	2816		TSN 0				
PROC. REF: AMM 34-59-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346001	RECEIVER COMPUTER UNIT							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.340	AFL	0		TSN 0				
346005	IAPS/CARD CAGE							Component ATA:34
PN:822-1029-101	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2P5TK	HRS	0		TSN 0				
WC#: 34.410	AFL	0		TSN 0				
346020	PILOT PRIMARY FLIGHT DISPLAY							Component ATA:34
PN:622-9345-203	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2TB7K	HRS	0		TSN 0				
WC#: 34.380	AFL	0		TSN 0				
346025	PILOT MULTIFUNCTION DISPLAY							Component ATA:34
PN:622-9345-203	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2TBFR	HRS	0		TSN 0				
WC#: 34.380	AFL	0		TSN 0				
346030	COPILOT MULTIFUNCTION DISPLAY							Component ATA:34
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.380	AFL	0		TSN 0				
346035	COPILOT PRIMARY FLIGHT DISPLAY							Component ATA:34
PN:622-9434-213	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2TBFP	HRS	0		TSN 0				
WC#: 34.360	AFL	0		TSN 0				
346045	PILOT AIR DATA REFERENCE PANEL							Component ATA:34
PN:622-9500-011	MOS/MSC	09-Jul-15	O/C					
SN:2KHRF	HRS	2041:06						
WC#: 34.330	AFL	1752						
346050	COPILOT AIR DATA REFERENCE PANEL							Component ATA:34
PN:622-9500-011	MOS/MSC	09-Jul-15	O/C	TSN 88				
SN:2X56B	HRS	2041:06		TSN 2041:02				
WC#: 34.330	AFL	1752		TSN 1752				

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346055	PILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:822-0328-011	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:170Y0D	HRS	0		TSN 0				
WC#: 34.320	AFL	0		TSN 0				
346060	COPILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:822-0328-011	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:170Y0G	HRS	0		TSN 0				
WC#: 34.320	AFL	0		TSN 0				
346063	NO. 1 GPS ANTENNA							Component ATA:34
PN:C1-429-200	MOS/MSC	15-Apr-20	O/C	TSN 0				
SN:629847	HRS	3278:23		TSN 0				
WC#: 34.740	AFL	2968		TSN 0				
PROC. REF: AMM 34-58-00								
346065	NO. 1 GPS RECEIVER							Component ATA:34
PN:822-2189-004	MOS/MSC	15-Apr-20	O/C	TSR 0				
SN:395CW	HRS	3278:23		TSR 0				
WC#: 34.750	AFL	2968		TSR 0				
PROC. REF: GENERIC NO REF								
346070	TCAS TRANSCEIVER							Component ATA:34
PN:822-1294-032	MOS/MSC	09-Jul-15	O/C					
SN:159686	HRS	2041:06						
WC#: 34.760	AFL	1752						
PROC. REF: GENERIC NO REF								
346075	UPPER TCAS DIRECTIONAL ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2W9WR	HRS	0		TSN 0				
WC#: 34.770	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
346080	LOWER TCAS DIRECTIONAL ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:261-77680	HRS	0		TSN 0				
WC#: 34.780	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
H340001 ^S		INSPECT PITOT/STATIC SYSTEM - FORWARD FUSELAGE						Service ATA:34
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H340003 ^S		INSPECT AOA TRANSMITTER PROBE - FORWARD FUSELAGE						Service ATA:34
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H340004 ^S		INSPECT PRIMARY FLIGHT DISPLAY (PFD) AND MULTIFUNCTION DISPLAY (MFD) COOLING FANS - PILOTS COMPARTMENT						Service ATA:34
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H340005 ^S		INSPECT FLIGHT INFORMATION DISPLAYS AND INSTRUMENTS - PILOT'S COMPARTMENT						Service ATA:34
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H340008 ^S		INSPECT STALL WARNING SYSTEM - PILOTS COMPARTMENT						Service ATA:34
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H340010 ^S		INSPECT PITOT TUBES - FORWARD FUSELAGE						Service ATA:34
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
H340011 ^S		INSPECT PITOT, STATIC AND AOA SENSOR - PERFORM PITOT/STATICAND AOA HEATING SYSTEM OPERATIONAL CHECK - FORWARD FUSELAGE						Service ATA:34
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H341101 ^S		INSPECT AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) (RK-483AND AFTER - OPTIONAL) -PILOTS COMPARTMENT						Service ATA:34
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H341178 ^S		INSPECT AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) (OPTIONALEQUIPMENT - RK-483 AND AFTER) - AFT FUSELAGE						Service ATA:34
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 35 - OXYGEN								
350012	PROTECTIVE BREATHING EQUIPMENT AVOX SYSTEMS PBE							Component ATA:35
PN:802300-14	MOS	28-Nov-17	120		30-Sep-27		1766 d	LIFE LIMIT
SN:E17090502	HRS	2623:18						
WC#: 35.130	AFL	2343						
			Manufacture Date:: 30-Sep-17	PROC. REF: GENERIC NO REF				
351001	OXYGEN CYLINDER							Component ATA:35
PN:176419-77	MOS	07-May-22	180		31-Mar-27 ^M		1583 d	LIFE LIMIT
SN:ALT281-53558	HRS	3976:37						
WC#: 35.010	AFL	3438						
								PROC. REF: AMM 35-11-00
351007	HYDROSTATIC TEST OXYGEN CYLINDER							Service ATA:35
PN:176419-77	MOS	22-Apr-22	60		30-Apr-25 ^M		883 d	AIRWORTHINESS
SN:ALT281-53558	HRS							
WC#: 35.010	AFL							
								PROC. REF: AMM 35-11-00

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351013	OXYGEN CYLINDER REGULATOR							Component ATA:35
PN:172400-14	MOS	07-May-22	72		30-Apr-25 ^M		883 d	OVERHAUL
SN:3231	HRS	3976:37						
WC#: 35.010	AFL	3438						
PROC. REF: AMM 35-11-00								
351025	OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:99-384042-3	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:3202	HRS	0		TSN 0				
WC#: 35.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
351029	PILOT OXYGEN MASK							Component ATA:35
PN:174262-12	MOS	15-Feb-22	72	TSO 7	15-Jul-27		1689 d	OVERHAUL
SN:22273	HRS	3833:39		TSO 0				
WC#: 35.020	AFL	3354		TSO 0				
PROC. REF: AMM 35-10-00								
351030	COPILOT OXYGEN MASK							Component ATA:35
PN:174252-92	MOS	15-Apr-20	72	TSO 0	15-Apr-26		1233 d	OVERHAUL
SN:16649	HRS	3281:44		TSO 0				
WC#: 35.020	AFL	2973		TSO 0				
PROC. REF: AMM 35-10-00								
351031	PILOT OXYGEN MASK REGULATOR							Component ATA:35
PN:128-380067-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:22505	HRS	0		TSN 0				
WC#: 35.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
351032	COPILOT OXYGEN MASK REGULATOR							Component ATA:35
PN:128-380067-15	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:20362	HRS	0		TSN 0				
WC#: 35.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
352001	NO. 1 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.050	AFL	1752						
PROC. REF: AMM 35-21-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
352002	NO. 02 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.050	AFL	1752						
PROC. REF: AMM 35-21-00								
352003	NO. 03 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.060	AFL	1752						
PROC. REF: AMM 35-21-00								
352004	NO. 04 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.060	AFL	1752						
PROC. REF: AMM 35-21-00								
352005	NO. 05 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.070	AFL	1752						
PROC. REF: AMM 35-21-00								
352006	NO. 06 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.070	AFL	1752						
PROC. REF: AMM 35-21-00								
352007	NO. 07 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.080	AFL	1752						
PROC. REF: AMM 35-21-00								
352008	NO. 08 PASSENGER OXYGEN MASK							Component ATA:35
PN:PN-UNKNOWN	MOS	09-Jul-15	96	TSN 1	09-Jun-23		192 d	
SN:UNKNOWN	HRS	2041:06						
WC#: 35.080	AFL	1752						
PROC. REF: AMM 35-21-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
352065	REPLACE PASSENGER OXYGEN CONTROL VALVE O-RINGS							Service ATA:35
	MOS	15-Apr-20	48		15-Apr-24		503 d	
	HRS	3278:39						
WC#: 35.110	AFL	2968						
PROC. REF: AMM 35-21-00								
352070	PASSENGER OXYGEN CONTROL VALVE							Component ATA:35
PN:101-384032-7	MOS/MSC	15-Apr-20	O/C	TSN 145				
SN:4581B	HRS	3278:39		TSN 3280:44				
WC#: 35.120	AFL	2968		TSN 2971				
PROC. REF: AMM 35-21-00								
H350001 ^S	INSPECT PILOT'S AND COPILOT'S OXYGEN SYSTEM - PILOTS COMPARTMENT							Service ATA:35
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H350002 ^S	INSPECT PASSENGER OXYGEN SYSETM - PILOTS COMPARTMENT							Service ATA:35
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H350004 ^S	INSPECT OXYGEN SYSTEM - FORWARD FUSELAGE							Service ATA:35
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H350005 ^S	INSPECT PILOT'S AND COPILOT'S OXYGEN SYSTEM - PERFORM FLIGHT CREW MASK - INSPECTION/CHECK - PILOT'S COMPARTMENT							Service ATA:35
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PROC. REF: GENERIC BLANK								
PKG:2								
H350006 ^S	INSPECT PROTECTIVE BREATHING EQUIPMENT (PBE) P/N 802300-XX (IF INSTALLED) - PILOT'S COMPARTMENT							Service ATA:35
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PROC. REF: GENERIC BLANK								
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
H350007 ^S		INSPECT PORTABLE OXYGEN & MASK - CABIN SECTION						Service ATA:35
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H350008 ^S		INSPECT PASSENGER OXYGEN SYSTEM - CABIN SECTION						Service ATA:35
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H350009 ^S		INSPECT OXYGEN SYSTEM - FORWARD FUSELAGE						Service ATA:35
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 36 - PNEUMATIC								
361001	NO. 1 BLEED AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.010	AFL	0		TSN 0				
PROC. REF: AMM 36-10-00								
361002	NO. 2 BLEED AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.010	AFL	0		TSN 0				
PROC. REF: AMM 36-10-00								
361003	FLOW INCREASING VALVE							Component ATA:36
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361013	BLEED AIR PRESSURE REGULATOR							Component ATA:36
PN:38E85-7B	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:N074359	HRS	0		TSN 0				
WC#: 36.030	AFL	0		TSN 0				
PROC. REF: AMM 36-10-00								
361019	SUCTION PRESSURE EJECTOR							Component ATA:36
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.040	AFL	0		TSN 0				
PROC. REF: AMM 36-10-00, AMM 36-10-00								
361025	DOOR SEAL VALVE							Component ATA:36
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.050	AFL	0		TSN 0				
PROC. REF: AMM 36-10-00								
361030	LEFT HAND BLEED AIR ACTUATOR VALVE							Component ATA:36
PN:3034144	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:F67698	HRS	0		TSN 0				
WC#: 36.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
361031	INSPECT LEFT HAND BLEED AIR SUPPLY TUBE							Service ATA:36
	MOS	31-Aug-22						AIRWORTHINESS
	HRS	4384:47	400 (+20)	Adj -86:14	4698:33	4718:33	91:26 (+20)	
WC#: 36.070	AFL	3695						
PROC. REF: ALM 04-00-02								
361032	INSPECT RIGHT HAND BLEED AIR SUPPLY TUBE							Service ATA:36
	MOS	31-Aug-22						AIRWORTHINESS
	HRS	4384:47	400 (+20)	Adj -86:14	4698:33	4718:33	91:26 (+20)	
WC#: 36.070	AFL	3695						
PROC. REF: ALM 04-00-02								
361035	RIGHT HAND BLEED AIR ACTUATOR VALVE							Component ATA:36
PN:3034144	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:F67693	HRS	0		TSN 0				
WC#: 36.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
H360001 ^S		INSPECT BLEED AIR SYSTEM CHECK VALVES -ENGINE GROUND RUN AND OPERATIONAL CHECKS						Service ATA:36
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 52 - DOORS								
521001	ENTRANCE DOOR ASSEMBLY							Component ATA:52
PN:45A30103-631	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK-552	HRS	0		TSN 0				
WC#: 52.010	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00								
522001	EMERGENCY EXIT DOOR							Component ATA:52
PN:45A30203-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 52.030	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00								
522027	REPLACE EMERGENCY EXIT DOOR HANDLE (PULL)(SELF-ILLUMINATING) PLACARD							Service ATA:52
	MOS	22-Jan-21	60		22-Jan-26		1150 d	LIFE LIMIT
	HRS							
WC#: 52.020	AFL							
PROC. REF: GENERIC NO REF								
522028	REPLACE EMERGENCY EXIT DOOR HANDLE COVER (PULL)(SELF-ILLUMINATING) PLACARD							Service ATA:52
	MOS	11-Jan-21	60		11-Jan-26		1139 d	LIFE LIMIT
	HRS							
WC#: 52.020	AFL							
PROC. REF: GENERIC NO REF								
526001 ^U	ENTRANCE STEPS DOOR							Component ATA:52
PN:128-430283-29	MOS/MSC	13-Aug-10	O/C	TSN 0				
SN:06161001ICT	HRS	287:13		TSN 0				
	AFL	246		TSN 0				
H520002 ^S	INSPECT AVIONICS ACCESS DOORS - FORWARD FUSELAGE							Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
H520003 ^S		INSPECT LANDING LIGHT AND DOORS - FORWARD FUSELAGE						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520004 ^S		INSPECT NOSE LANDING GEAR DOORS - LANDING GEAR AND BRAKES						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520005 ^S		INSPECT NOSE LANDING GEAR DOORS -LANDING GEAR AND BRAKES -LANDING GEAR AND BRAKES						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H520006 ^S		INSPECT BAGGAGE DOORS - AFT FUSELAGE						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H520007 ^S		INSPECT FUEL TANK FILLER RECEPTACLE AND DOOR - AFT FUSELAGE						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520008 ^S		INSPECT DOOR WARNING SYSTEM - CABIN SECTION						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H520009 ^S		INSPECT ENTRANCE DOOR LATCH AND LOCK MECHANISM- CABIN SECTION						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
PROC. REF: GENERIC BLANK								
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
H520010 ^S		INSPECT EMERGENCY EXIT LATCH AND LOCK MECHANISM- CABIN SECTION						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H520011 ^S		INSPECT EXTERNAL POWER RECEPTACLE - AFT FUSELAGE						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H520014 ^S		INSPECT EMERGENCY EXIT DOOR (EMERGENCY EXIT DOOR REMOVED) - CABIN SECTION						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H520015 ^S		INSPECT MAIN ENTRANCE DOOR - CABIN SECTION						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H520017 ^S		INSPECT ENTRANCE DOOR- SCHEDULED D INSPECTIONS						Service ATA:52
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H520018 ^S		INSPECT ENTRANCE DOOR LAND AND SUPPORT FRAMES LATCH PIN RECEPTACLES AND DOOR LAND GUIDES SCHEDULED D INSPECTIONS						Service ATA:52
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
H520019 ^S		VISUALLY INSPECT ENTRANCE DOOR STEPS						Service ATA:52
	MOS	31-Aug-22						
	HRS	4384:47	200 ^S (+40)					
WC#: 52.040	AFL	3695						
								PKG:1
H520032 ^S		INSPECT MOISTURE DRAIN HOLES AND VALVES - CABIN SECTION						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H520105 ^S		INSPECT LEFT MAIN LANDING GEAR DOORS - LANDING GEAR AND BRAKES						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520113 ^S		INSPECT LEFT MAIN LANDING GEAR DOOR BEAMS AND FITTINGS - LANDING GEAR AND BRAKES						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H520119 ^S		INSPECT REMOTE OIL ACCESS DOOR (RK-78, RK-87 THRU RK-390, RK-392 WITH KIT 128-9007-0001 INSTALLED, RK-391, RK-393 AND AFTER) - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520120 ^S		INSPECT OIL FILLER DOOR - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
H520205 ^S		INSPECT RIGHT MAIN LANDING GEAR DOORS - LANDING GEAR AND BRAKES						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520213 ^S		INSPECT RIGHT MAIN LANDING GEAR DOOR BEAMS AND FITTINGS - LANDING GEAR AND BRAKES						Service ATA:52
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H520219 ^S		INSPECT REMOTE OIL ACCESS DOOR (RK-78, RK-87 THRU RK-390, RK-392 WITH KIT 128-9007-0001 INSTALLED, RK-391, RK-393 AND AFTER) - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H520220 ^S		INSPECT OIL FILLER DOOR - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:52
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 53 - FUSELAGE								
531079	NO. 1 ENGINE FORWARD CARRY-THRU BRACKET							Component ATA:53
PN:45A34361-007	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:06120701ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 53.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
531080	NO. 1 ENGINE AFT CARRY-THRU BRACKET							Component ATA:53
PN:45A34361-010	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:07-11-07ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 53.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
531081	NO. 2 ENGINE FORWARD CARRY-THRU BRACKET							Component ATA:53
PN:45A34361-008	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:05-30-0704ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 53.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
531082	NO. 2 ENGINE AFT CARRY-THRU BRACKET							Component ATA:53
PN:45A34361-011	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:09-07-07-01ICT	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 53.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
531083	INSPECT NO.1 CARRY THROUGH BRACKET WITH 10X MAG GLASS							Service ATA:53
	MOS	31-Aug-22			RTS			AIRWORTHINESS
	HRS	4384:47	200 (+20)					
WC#: 53.030	AFL	3695						
PROC. REF: ALM 04-00-02								
531085	REPLACE NO. 1 ENGINE CARRY-THROUGH BRACKET BOLTS							Service ATA:53
	MOS	15-Feb-22						MANDATORY
	HRS	3833:39	5000		8833:39		4226:32	
WC#: 53.050	AFL	3354						
PROC. REF: AMM 20-10-05								
531090	REPLACE NO. 2 ENGINE CARRY-THROUGH BRACKET BOLTS							Service ATA:53
	MOS	15-Feb-22						MANDATORY
	HRS	3833:39	5000		8833:39		4226:32	
WC#: 53.050	AFL	3354						
PROC. REF: AMM 20-10-05								
532052	DETAIL INSPECT LEFT MAIN LANDING GEAR FITTING ASSEMBLY							Service ATA:53
	MOS	17-Mar-08						MANDATORY
	HRS	0						
WC#: 53.170	AFL	0	T:7000 (+15)		7000	7015	3171 (+15)	
PROC. REF: AMM 53-40-00								
532054	DETAIL INSPECT RIGHT MAIN LANDING GEAR FITTING ASSEMBLY							Service ATA:53
	MOS	17-Mar-08						MANDATORY
	HRS	0						
WC#: 53.170	AFL	0	T:7000 (+15)		7000	7015	3171 (+15)	
PROC. REF: AMM 53-40-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
532056	DETAIL INSPECT LEFT MID FUSELAGE MAIN LANDING GEAR UPLOCK FITTING							Service ATA:53
	MOS	17-Mar-08						MANDATORY
	HRS	0						
WC#: 53.180	AFL	0	T:7000 (+15)		7000	7015	3171 (+15)	
PROC. REF: AMM 53-40-00								
532058	DETAIL INSPECT RIGHT MID FUSELAGE MAIN LANDING GEAR UPLOCK FITTING							Service ATA:53
	MOS	17-Mar-08						MANDATORY
	HRS	0						
WC#: 53.180	AFL	0	T:7000 (+15)		7000	7015	3171 (+15)	
PROC. REF: AMM 53-40-00								
535001	RADOME							Component ATA:53
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.010	AFL	0		TSN 0				
PROC. REF: AMM 53-50-00								
H530001 ^s	INSPECT FUSLEAGE MOISTURE DRAIN - FORWARD FUSELAGE							Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	800 ^s					
	AFL	3438						
PKG:3								
H530002 ^s	INSPECT DORSAL FIN AND VENTRAL FIN - AFT FUSELAGE							Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	800 ^s					
	AFL	3438						
PKG:3								
H530003 ^s	INSPECT WING/FUSELAGE FILLET - MIDFUSELAGE							Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	800 ^s					
	AFL	3438						
PKG:3								
H530004 ^s	INSPECT CENTER PEDESTAL - PILOT'S COMPARTMENT							Service ATA:53
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
PKG:2								

?-Insufficient Information ^s-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H530005 ^S		INSPECT COMPRESSOR/CONDENSER INLET AND EXHAUST PORTS - AFT FUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H530006 ^S		INSPECT RADOME AND LIGHTNING DIVERTER STRIPS - FORWARD FUSELAGE						Service ATA:53
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H530007 ^S		INSPECT AFT FUSELAGE BAGGAGE PANELS - AFT FUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H530010 ^S		INSPECT FLOOR PANELS-PILOT'S COMPARTMENT						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530011 ^S		INSPECT FUSELAGE INNER SKIN AND SPLICE - CABIN SECTION						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530012 ^S		INSPECT AFT PRESSURE BULKHEAD - CABIN SECTION						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530013 ^S		INSPECT MOISTURE DRAIN HOLES AND VALVES-PILOT'S COMPARTMENT						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H530015 ^S		INSPECT FUSELAGE SKIN AND ACCESS DOORS (EXTERIOR INSPECTION ONLY, PANEL REMOVAL IS NOT REQUIRED) - FORWARD FUSELAGE						Service ATA:53
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H530016 ^S		INSPECT FRAME REINFORCEMENT CLIPS (45A33273), FS 279.4(7096) - MIDFUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530017 ^S		INSPECT EMERGENCY GEAR DOWN BRACKET ASSEMBLY ATTACHCLIP, FS 279.4 (7096) - MIDFUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530018 ^S		INSPECT KEEL STRUCTURE - MIDFUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530019 ^S		INSPECT FUSELAGE SKIN - MIDFUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530020 ^S		INSPECT LOWER FRAME AND SPLICE, FS 307.2 (7803) - MIDFUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H530021 ^S		INSPECT FUSELAGE SKIN, ACCESS DOORS AND FAIRINGS - AFT FUSELAGE						Service ATA:53
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H530022 ^S		INSPECT FORWARD ENGINE CARRY-THROUGH BEAM - AFT FUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530023 ^S		INSPECT FAIRING OF VERTICAL STABILIZER-TO-FUSELAGE - - VERTICAL STABILIZER						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530024 ^S		INSPECT VERTICAL STABILIZER FRONT SPAR ATTACHMENT ANDFRAME- VERTICAL STABILIZER						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530025 ^S		INSPECT VERTICAL STABILIZER REAR SPAR ATTACHMENT ANDFRAME - VERTICAL STABILIZER						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530026 ^S		INSPECT LOWER FITTING OF WINDSHIELD CENTER POST - SCHEDULED D INSPECTIONCS						Service ATA:53
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H530027 ^S		INSPECT FRAME AND INTERCOSTALS BEHIND INNER SKIN- SCHEDULED D INSPECTIONCS						Service ATA:53
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H530028 ^S		INSPECT CABIN FRAMES AND STRINGERS- SCHEDULED D INSPECTIONCS						Service ATA:53
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H530029 ^S		INSPECT FLOOR PANELS - CABIN SECTION						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H530030 ^S		INSPECT ELEVATOR CONTROL-COLUMN-SUPPORT BOX (LH & RH)- SCHEDULED D INSPECTIONCS						Service ATA:53
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H530031 ^S		INSPECT AFT FUSELAGE BAGGAGE COMPARTMENT- SCHEDULED D INSPECTIONCS						Service ATA:53
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H530033 ^S		INSPECT RVSM REGION -FORWARD FUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H530034 ^S		INSPECT FUSELAGE SKIN - AFT FUSELAGE						Service ATA:53
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H532001 ^S		INSPECT TAIL CONE - AFT FUSELAGE						Service ATA:53
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
H540007 ^S		INSPECT FORWARD AND AFT ENGINE CARRY-THROUGH- SCHEDULED D INSPECTIONCS						Service ATA:54
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H540008 ^S		INSPECT FRAME AND PYLON RIB- SCHEDULED D INSPECTIONCS						Service ATA:54
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H540101 ^S		INSPECT PYLON SKIN - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H540102 ^S		INSPECT NACELLE - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H540103 ^S		INSPECT ENGINE INLET - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H540104 ^S		INSPECT PYLON NACELLE SEAL -LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H540105 ^S		INSPECT ENGINE/PYLON FIREWALL -LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
H540201 ^S		INSPECT PYLON SKIN - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H540202 ^S		INSPECT NACELLE - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H540203 ^S		INSPECT ENGINE INLET - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H540204 ^S		INSPECT PYLON NACELLE SEAL -RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H540205 ^S		INSPECT ENGINE/PYLON FIREWALL -RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:54
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 55 - STABILIZERS								
551003	PERFORM RADIOGRAPHIC (X-RAY) INSPECTION OF THE HORIZONTAL STABILIZER RIB ASSEMBLIES							Service ATA:55
	MOS	17-Mar-08						AIRWORTHINESS
	HRS	0	T:7400 (+20)		7400	7420	2792:53 (+20)	
WC#: 27.470	AFL	0						
PROC. REF: AMM 55-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H550001 ^S		INSPECT STABILIZER SKIN, LEADING EDGE AND ACCESS PANELS - VERTICAL STABILIZER						Service ATA:55
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H550002 ^S		INSPECT RUDDER ASSEMBLY - VERTICAL STABILIZER						Service ATA:55
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H550003 ^S		INSPECT RUDDER HINGES AND BOLTS, TORQUE TUBE AND BELL CRANK, STOP BOLTS AND RUDDER COUNTER-BALANCE - VERTICAL STABILIZER						Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H550004 ^S		INSPECT STABILIZER SKIN, LEADING EDGES AND ACCESS PANELS - HORIZONTAL STABILIZER						Service ATA:55
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H550005 ^S		INSPECT ELEVATOR ASSEMBLY - HORIZONTAL STABILIZER						Service ATA:55
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H550007 ^S		INSPECT VERTICAL STABILIZER SIDE RAILS AND ROLLER - VERTICAL STABILIZER						Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3

? - Insufficient Information ^S - Suppressed Requirement * - Estimated Due (New Requirement) (EFF) - Effective C/W ^M - Manual Due ^U - User Task ^{Ex} - Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H550008 ^S		INSPECT AFT PIVOT FITTING ASSEMBLY - HORIZONTAL STABILIZER						Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H550009 ^S		INSPECT FRONT AND REAR SPAR AND FITTINGS- HORIZONTAL STABILIZER						Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H550010 ^S		INSPECT ELEVATOR OPERATION - HORIZONTAL STABILIZER						Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H550011 ^S		INSPECT VERTICAL STABILIZER RIBS AND STRINGERS- SCHEDULED D INSPECTIONCS						Service ATA:55
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H550012 ^S		INSPECT HORIZONTAL STABILIZER FRONT AND REAR SPARFITTINGS- SCHEDULED D INSPECTIONCS						Service ATA:55
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H550013 ^S		INSPECT HORIZONTAL STABILIZER STRINGERS AND SKINS -HORIZONTAL STABILIZER STATION (HSS) 0.00 TO HSS 11.81 (300) - HORIZONTAL STABILIZER						Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H550014 ^S		INSPECT	VERTICAL STABILIZER - VERTICAL STABILIZER					Service ATA:55
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
ATA 56 - WINDOWS								
561001	PILOT WINDSHIELD							Component ATA:56
PN:196700-01	MOS/MSC	04-Jan-19	O/C	TSN 0				
SN:0027	HRS	3097:45		TSN 0				
WC#: 56.010	AFL	3046		TSN 0				
PROC. REF: AMM 56-10-00								
561002	COPILOT WINDSHIELD							Component ATA:56
PN:196700-02	MOS/MSC	04-Jan-19	O/C	TSN 0				
SN:0024	HRS	3097:45		TSN 0				
WC#: 56.010	AFL	3046		TSN 0				
PROC. REF: AMM 56-10-00								
561013	PILOT SIDE WINDOW							Component ATA:56
PN:45AS31010-021	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:1623	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56-10-00								
561014	COPILOT SIDE WINDOW							Component ATA:56
PN:45AS31010-022	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:1592	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.020	AFL	0		TSN 0				
PROC. REF: AMM 56-10-00								
562001	CABIN LEFT FORWARD WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.030	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562002	CABIN LEFT 2ND WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.040	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562003	CABIN LEFT 3RD WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.050	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562004	CABIN LEFT 4TH WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.060	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562005	CABIN LEFT 5TH WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.070	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562006	CABIN LEFT 6TH WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.080	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562007	CABIN RIGHT FORWARD WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.030	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562008	CABIN RIGHT 2ND WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.040	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562009	CABIN RIGHT 3RD WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.050	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562010	CABIN RIGHT 4TH WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.060	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562011	CABIN RIGHT 5TH WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.070	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562012	CABIN RIGHT 6TH WINDOW INNER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.080	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562013	CABIN LEFT FORWARD WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.090	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562014	CABIN LEFT 2ND WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.100	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562015	CABIN LEFT 3RD WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.110	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562016	CABIN LEFT 4TH WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.120	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562017	CABIN LEFT 5TH WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.130	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562018	CABIN LEFT 6TH WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.140	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562019	CABIN RIGHT FORWARD WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.090	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562020	CABIN RIGHT 2ND WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.100	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562021	CABIN RIGHT 3RD WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.110	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562022	CABIN RIGHT 4TH WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.120	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562023	CABIN RIGHT 5TH WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.130	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
562024	CABIN RIGHT 6TH WINDOW OUTER PANEL							Component ATA:56
PN:PN	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	TSN 0	20000		15392:53	
WC#: 56.140	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00								
H560001 ^S	INSPECT WINDSHIELD AND FLIGHT COMPARTMENT WINDOWS - FORWARD FUSELAGE							Service ATA:56
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H560002 ^S	INSPECT WINDSHIELD EXTERNAL FRAME AND PROTECTORS - FORWARD FUSELAGE							Service ATA:56
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H560004 ^S	INSPECT WINDSHIELD SURFACE SEAL COATING (RK-1 THRU RK-242 WITH KIT 128-5405 INSTALLED; RK-243 AND AFTER) - FORWARD FUSELAGE							Service ATA:56
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H560005 ^S	INSPECT PASSENGER COMPARTMENT WINDOWS - MIDFUSELAGE							Service ATA:56
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
H560006 ^S		INSPECT LOWER FITTING OF WINDSHIELD CENTER POST - SCHEDULED D INSPECTIONCS						Service ATA:56
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
								PKG:5
H560007 ^S		INSPECT WINDSHIELD GLASS, COCKPIT SIDE WINDOW GLASS, AND RETAINERS (INTERIOR WINDSHIELD TRIM PANELS REMOVED)-PILOT'S COMPARTMENT						Service ATA:56
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H560014 ^S		INSPECT FORWARD PRESSURE BULKHEAD - - FORWARD FUSELAGE						Service ATA:56
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
ATA 57 - WINGS								
571061	INSPECT LEFT WING WING-TO-FUSELAGE ATTACH BOLTS - DETAIL INSPECT FOR CORROSION, WEAR, AND DAMAGE. MAGNETIC PARTICLE INSPECT FOR CRACKS.							Service ATA:57
	MOS	09-Apr-18	60	Adj -23d	17-Mar-23	17-Mar-23	108 d	
	HRS	2721:25						
WC#: 57.020	AFL	2437						
PROC. REF: AMM 57-40-00								
571067	INSPECT RIGHT WING WING-TO-FUSELAGE ATTACH BOLTS - DETAIL INSPECT FOR CORROSION, WEAR, AND DAMAGE. MAGNETIC PARTICLE INSPECT FOR CRACKS.							Service ATA:57
	MOS	09-Apr-18	60	Adj -23d	17-Mar-23	17-Mar-23	108 d	
	HRS	2721:25						
WC#: 57.020	AFL	2437						
PROC. REF: AMM 57-40-00								
576010	LEFT ROLL TRIM ASSEMBLY							Component ATA:57
PN:45A10720-001	MOS/MS	17-Mar-08	O/C	TSN 0				
SN:RK551	HRS	0		TSN 0				
WC#: 57.060	AFL	0		TSN 0				
PROC. REF: AMM 27-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
576020	RIGHT ROLL TRIM ASSEMBLY							Component ATA:57
PN:45A10720-002	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK552	HRS	0		TSN 0				
WC#: 57.060	AFL	0		TSN 0				
PROC. REF: AMM 27-10-00								
H570009 ^S	INSPECT WING ATTACH FITTINGS - MIDFUSELAGE							Service ATA:57
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
PKG:4								
H570012 ^S	INSPECT MAIN FLAP CENTER RAIL ASSEMBLY AND CENTER FLAPROLLERS- SCHEDULED D INSPECTIONCS							Service ATA:57
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
PKG:5								
H570013 ^S	INSPECT WING FRONT AND REAR SPAR FITTINGS- SCHEDULED D INSPECTIONCS							Service ATA:57
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
PKG:5								
H570014 ^S	INSPECT FORWARD AND AFT CARRY-THROUGH (LUGS) (P/N45A33511 AND 45A33512)- SCHEDULED D INSPECTIONCS							Service ATA:57
	MOS	17-Mar-08						
	HRS	0	6400 ^S					
	AFL	0						
PKG:5								
H570102 ^S	INSPECT WING SKIN - LEFT-HAND WING							Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H570103 ^S	INSPECT FUEL TANK FILLER RECEPTACLE - LEFT-HAND WING							Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
H570104 ^S		INSPECT WING TIP AND LENS COVER - LEFT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H570106 ^S		INSPECT WING LEADING AND TRAILING EDGE ASSEMBLIES - LEFT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H570107 ^S		INSPECT WING FUEL STORAGE AND INSPECTION ACCESS PANELS - LEFT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H570111 ^S		INSPECT WING FUEL STORAGE AREA INSPECTION- LEFT-HAND WING						Service ATA:57
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H570112 ^S		INSPECT SPOILER BRACKET (P/N 45A10152) REAR SPAR AREA(WCS 2513) -LEFT-HAND WING						Service ATA:57
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H570202 ^S		INSPECT WING SKIN - RIGHT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H570203 ^S		INSPECT FUEL TANK FILLER RECEPTACLE - RIGHT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
H570204 ^S		INSPECT WING TIP AND LENS COVER - RIGHT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H570206 ^S		INSPECT WING LEADING AND TRAILING EDGE ASSEMBLIES - RIGHT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H570207 ^S		INSPECT WING FUEL STORAGE AND INSPECTION ACCESS PANELS - RIGHT-HAND WING						Service ATA:57
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PROC. REF: GENERIC BLANK								PKG:2
H570211 ^S		INSPECT WING FUEL STORAGE AREA INSPECTION- RIGHT-HAND WING						Service ATA:57
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
								PKG:4
H570212 ^S		INSPECT SPOILER BRACKET (P/N 45A10152) REAR SPAR AREA(WCS 2513) -RIGHT-HAND WING						Service ATA:57
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
ATA 71 - POWER PLANT								
710010	NO. 1 ENGINE - OVERHAUL							Service ATA:71
	MOS	07-Jan-22						OVERHAUL
	HRS	3611:42	3600 (+50/-50)		(7211:42) 7433:38	7261:42	2826:31 (+50)	
	ENC	3222						
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710010	NO. 2 ENGINE - OVERHAUL							Service ATA:71
	MOS	16-Dec-21						OVERHAUL
	HRS	3611:42	3600 (+50/-50)		(7211:42) 7433:38	7261:42	2826:31 (+50)	
	ENC	3222						
PROC. REF: GENERIC NO REF								
710020	NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:71
	MOS	15-Feb-22						
	HRS	3611:43	1800 (+50/-50)		(5411:43) 5633:39	5461:43	1026:32 (+50)	
	ENC	3222						
PROC. REF: EMM 72-00-00								
710020	NO. 2 ENGINE - HOT SECTION INSPECTION							Service ATA:71
	MOS	15-Feb-22						
	HRS	3611:43	1800 (+50/-50)		(5411:43) 5633:39	5461:43	1026:32 (+50)	
	ENC	3222						
PROC. REF: EMM 72-00-00								
710021	NO. 1 ENGINE INTAKE DUCT ASSEMBLY							Component ATA:71
PN:45A30024-603	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK-553	HRS	0		TSN 0				
WC#: 71.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
710022	NO. 2 ENGINE INTAKE DUCT ASSEMBLY							Component ATA:71
PN:45A30024-604	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:RK553RH	HRS	0		TSN 0				
WC#: 71.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
710040	NO. 1 ENGINE - WASH TURBINE							Service ATA:71
	MOS/MSC	09-Jul-15	A/R					
	HRS	2041:02						
	ENC	1752						
PROC. REF: EMM 71-00-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710040	NO. 2 ENGINE - WASH TURBINE							Service ATA:71
	MOS/MSC	09-Jul-15	A/R					
	HRS	2041:02						
	ENC	1752						
PROC. REF: EMM 71-00-00								
712007	NO. 1 ENGINE FORWARD UPPER MOUNT							Component ATA:71
PN:45AS42002-009	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:LK2554	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 71.040	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00								
712008	NO. 2 ENGINE FORWARD UPPER MOUNT							Component ATA:71
PN:45AS42002-009	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:LK2494	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 71.040	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00								
712009	NO. 1 ENGINE FORWARD LOWER MOUNT							Component ATA:71
PN:45AS42002-009	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:LK2582	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 71.050	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00								
712010	NO. 2 ENGINE FORWARD LOWER MOUNT							Component ATA:71
PN:45AS42002-009	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:LK2428	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 71.050	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00								
712011	NO. 1 ENGINE AFT MOUNT							Component ATA:71
PN:45AS42002-011	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:LK1149	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 71.060	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00								
712012	NO. 2 ENGINE AFT MOUNT							Component ATA:71
PN:45AS42002-011	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:LK1180	HRS	0	22400	TSN 0	22400		17792:53	
WC#: 71.060	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712014	INSPECT NO. 1 ENGINE ISOLATOR MOUNTS							Service ATA:71
	MOS	31-Aug-22						MANDATORY
	HRS	4384:47	1800 (+20)		6184:47	6204:47	1577:40 (+20)	
WC#: 71.070	AFL	3695						
PROC. REF: GENERIC NO REF								
712016	INSPECT NO. 2 ENGINE ISOLATOR MOUNTS							Service ATA:71
	MOS	31-Aug-22						MANDATORY
	HRS	4384:47	1800 (+20)		6184:47	6204:47	1577:40 (+20)	
WC#: 71.070	AFL	3695						
PROC. REF: GENERIC NO REF								
712031	REPLACE NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR							Service ATA:71
PN:45AS42002-009	MOS	17-Mar-08						REPLACE
SN:LK2554	HRS	0	7000		7000	7000	2392:53	
WC#: 71.040	AFL	0						
PROC. REF: AMM 71-20-00								
712032	REPLACE NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR							Service ATA:71
PN:45AS42002-009	MOS	17-Mar-08						REPLACE
SN:LK2494	HRS	0	7000		7000	7000	2392:53	
WC#: 71.040	AFL	0						
PROC. REF: AMM 71-20-00								
712033	REPLACE NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR							Service ATA:71
PN:45AS42002-009	MOS	17-Mar-08						REPLACE
SN:LK2582	HRS	0	7000		7000	7000	2392:53	
WC#: 71.050	AFL	0						
PROC. REF: AMM 71-20-00								
712034	REPLACE NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR							Service ATA:71
PN:45AS42002-009	MOS	17-Mar-08						REPLACE
SN:LK2428	HRS	0	7000		7000	7000	2392:53	
WC#: 71.050	AFL	0						
PROC. REF: AMM 71-20-00								
712035	REPLACE NO. 1 ENGINE AFT MOUNT ISOLATOR							Service ATA:71
PN:45AS42002-011	MOS	17-Mar-08						REPLACE
SN:LK1149	HRS	0	7000		7000	7000	2392:53	
WC#: 71.060	AFL	0						
PROC. REF: AMM 71-20-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712036	REPLACE NO. 2 ENGINE AFT MOUNT ISOLATOR							Service ATA:71
PN:45AS42002-011	MOS	17-Mar-08						REPLACE
SN:LK1180	HRS	0	7000		7000	7000	2392:53	
WC#: 71.060	AFL	0						
PROC. REF: AMM 71-20-00								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:JT15D-5R	MOS/MSC	15-Feb-22	E/C					
SN:PCE-JG0091	HRS	3833:39		TSN 3611:42				
WC#: 71.EN1	AFL	3354						
PROC. REF: AMM 71-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:JT15D-5R	MOS/MSC	15-Feb-22	E/C					
SN:PCE-JG0092	HRS	3833:39		TSN 3611:42				
WC#: 71.EN2	AFL	3354						
PROC. REF: AMM 71-00-00								
H710001 ^s	ENGINE SYSTEMS - NOTE: OBSERVE ENGINE GROUND OPERATING PROCEDURES							Service ATA:71
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
PKG:2								
H710102 ^s	INSPECT BLEED AIR SYSTEM - LEFT-HAND POWER PLANT, PYLON AND NACELLE							Service ATA:71
	MOS	31-Aug-22	12 ^s					
	HRS	4384:47	400 ^s					
	AFL	3695						
PKG:2								
H710202 ^s	INSPECT BLEED AIR SYSTEM - RIGHT-HAND POWER PLANT, PYLON AND NACELLE							Service ATA:71
	MOS	07-May-22	12 ^s					
	HRS	3976:37	400 ^s					
	AFL	3438						
ATA 72 - ENGINE								
720100	NO. 1 ENGINE - ENGINE OVERTEMPERATURE							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								

?-Insufficient Information ^s-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720100	NO. 2 ENGINE - ENGINE OVERTEMPERATURE							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720110	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720110	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720120	NO. 1 ENGINE - LOSS OF OIL							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720120	NO. 2 ENGINE - LOSS OF OIL							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720130	NO. 1 ENGINE - ENGINE OVERSPEED							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720130	NO. 2 ENGINE - ENGINE OVERSPEED							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720140	NO. 1 ENGINE - ENGINE WINDMILLING							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720140	NO. 2 ENGINE - ENGINE WINDMILLING							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720150	NO. 1 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720150	NO. 2 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720160	NO. 1 ENGINE - ENGINE DROPPED DURING HANDLING							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720160	NO. 2 ENGINE - ENGINE DROPPED DURING HANDLING							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			
720170	NO. 1 ENGINE - LIGHTNING STRIKE							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
					PROC. REF: EMM 72-00-00			

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720170	NO. 2 ENGINE - LIGHTNING STRIKE							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720180	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720180	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720190	NO. 1 ENGINE - HEAVY/HARD LANDING							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720190	NO. 2 ENGINE - HEAVY/HARD LANDING							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720200	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								
720200	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720210	NO. 1 ENGINE - STARTER GENERATOR FAIL INDICATION							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
				PROC. REF: EMM 72-00-00				
720210	NO. 2 ENGINE - STARTER GENERATOR FAIL INDICATION							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
				PROC. REF: EMM 72-00-00				
720220	NO. 1 ENGINE - HYDRAULIC PUMP FAILURE							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
				PROC. REF: EMM 72-00-00				
720220	NO. 2 ENGINE - HYDRAULIC PUMP FAILURE							Service ATA:72
	MOS/MSC	17-Mar-08	A/R					
	HRS	0						
	ENC	0						
				PROC. REF: EMM 72-00-00				
723010	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3040939	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0028WKB	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	12000	TSN 0	(8303) 8303		8303	
				PROC. REF: GENERIC NO REF				
723010	NO. 2 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3040939	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A00292MX	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	12000	TSN 0	(8303) 8303		8303	
				PROC. REF: GENERIC NO REF				

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723020	NO. 1 ENGINE - LOW BOOST COMPRESSOR HUB							Component ATA:72
PN:3038312	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A002909E	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: GENERIC NO REF								
723020	NO. 2 ENGINE - LOW BOOST COMPRESSOR HUB							Component ATA:72
PN:3038312	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A00293E6	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: GENERIC NO REF								
723030	NO. 1 ENGINE - LOW COMPRESSOR HUB							Component ATA:72
PN:3037911	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0026EN7	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	12000	TSN 0	(8303) 8303		8303	
PROC. REF: GENERIC NO REF								
723030	NO. 2 ENGINE - LOW COMPRESSOR HUB							Component ATA:72
PN:3037911	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0028P7H	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	12000	TSN 0	(8303) 8303		8303	
PROC. REF: GENERIC NO REF								
723040	NO. 1 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-03								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723040	NO. 2 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-03								
725010	NO. 1 ENGINE - HIGH TURBINE ROTOR DISK							Component ATA:72
PN:3036411	MOS	07-Jan-22		TSN 0				LIFE LIMIT
SN:A004W9R1	HRS	3611:42		TSN 0				
	ENC	3222		TSN 0				
	ACCCYC	0	14000	TSN 0	(13525) 13525		13525	
PROC. REF: EMM 72-50-02								
725010	NO. 2 ENGINE - HIGH TURBINE ROTOR DISK							Component ATA:72
PN:3036411	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0029Y2W	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: EMM 72-50-02								
725020	NO. 1 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK							Component ATA:72
PN:3022212	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0028HAP	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: GENERIC NO REF								
725020	NO. 2 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK							Component ATA:72
PN:3022212	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0029APA	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725030	NO. 1 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK							Component ATA:72
PN:3041593	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0029Y26	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: GENERIC NO REF								
725030	NO. 2 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK							Component ATA:72
PN:3041593	MOS	17-Mar-08		TSN 0				LIFE LIMIT
SN:A0029Y25	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	14000	TSN 0	(10303) 10303		10303	
PROC. REF: GENERIC NO REF								
725080	NO. 1 ENGINE - VISUAL INSPECT LOW PRESSURE COMPRESSOR BYPASS STATOR INNER AND OUTER RINGS FOR CRACKS							Service ATA:72
	MOS	15-Feb-22						
	HRS	3611:43	1800 (+50/-50)		(5411:43) 5633:39	5461:43	1026:32 (+50)	
	ENC	3222						
PROC. REF: GENERIC NO REF								
725080	NO. 2 ENGINE - VISUAL INSPECT LOW PRESSURE COMPRESSOR BYPASS STATOR INNER AND OUTER RINGS FOR CRACKS							Service ATA:72
	MOS	15-Feb-22						
	HRS	3611:43	1800 (+50/-50)		(5411:43) 5633:39	5461:43	1026:32 (+50)	
	ENC	3222						
PROC. REF: GENERIC NO REF								
H720001 ^S	INSPECT ENGINE CONTROLS AND CABLE - LEFT-HAND POWER PLANT, PYLON AND NACELLE							Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720004 ^S	INSPECT FUEL AND HYDRAULIC LINES - LEFT-HAND POWER PLANT, PYLON AND NACELLE							Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
H720005 ^S		INSPECT ENGINE ACCESSORIES - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720006 ^S		INSPECT ELECTRICAL HARNESS - LEFT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720008 ^S		INSPECT ENGINE CONTROLS AND CABLE - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720009 ^S		INSPECT ENGINE ACCESSORIES - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720010 ^S		INSPECT FUEL AND HYDRAULIC LINES - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720011 ^S		INSPECT ELECTRICAL HARNESS - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H720012 ^S		INSPECT ENGINE ISOLATOR MOUNTS - RIGHT-HAND POWER PLANT, PYLON AND NACELLE						Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
H720013 ^S	INSPECT ENGINE ISOLATOR MOUNTS - LEFT-HAND POWER PLANT, PYLON AND NACELLE							Service ATA:72
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 73 - ENGINE FUEL AND CONTROL								
731000	NO. 1 ENGINE - FUEL OVERTEMP INDICATOR							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731000	NO. 2 ENGINE - FUEL OVERTEMP INDICATOR							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731001	NO. 1 ENGINE - VISUAL INSPECT FUEL OVERTEMP INDICATOR							Service ATA:73
PN:PN	MOS	31-Aug-22			RTS			
SN:UNKNOWN	HRS	4162:51	200					
	ENC	3563						
PROC. REF: GENERIC NO REF								
731001	NO. 2 ENGINE - VISUAL INSPECT FUEL OVERTEMP INDICATOR							Service ATA:73
PN:PN	MOS	31-Aug-22			RTS			
SN:UNKNOWN	HRS	4162:51	200					
	ENC	3563						
PROC. REF: GENERIC NO REF								
731002 ^S	NO. 1 ENGINE - CHANGE FUEL PUMP OUTLET FILTER (10 MICRON)							Service ATA:73
	MOS	31-Aug-22						
	HRS	4162:51	200 ^S (+10%)					
	ENC	3563						
PROC. REF: EMM 73-10-02								PKG:0
								WO#: JB2022-BZZ-018,JB2022-BZZ-023

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731002 ^S	NO. 2 ENGINE - CHANGE FUEL PUMP OUTLET FILTER (10 MICRON)							Service ATA:73
	MOS	31-Aug-22						
	HRS	4162:51	200 ^S (+10%)					
	ENC	3563						
PROC. REF: EMM 73-10-02							PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023	
731010	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:845401-1	MOS/MSC	07-Jan-22	O/C	TSO 0				
SN:002799	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 73-10-02								
731010	NO. 2 ENGINE - FUEL PUMP							Component ATA:73
PN:845401-1	MOS/MSC	16-Dec-21	O/C	TSO 0				
SN:002798	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 73-10-02								
731013	NO. 1 ENGINE - REPLACE FUEL FILTER							Service ATA:73
	MOS	31-Aug-22			RTS			REPLACE
	HRS	4162:51	200 (+10%)					
	ENC	3563						
PROC. REF: EMM 73-10-13							WO#: JB2022-BZZ-018,JB2022-BZZ-023	
731013	NO. 2 ENGINE - REPLACE FUEL FILTER							Service ATA:73
	MOS	31-Aug-22			RTS			REPLACE
	HRS	4162:51	200 (+10%)					
	ENC	3563						
PROC. REF: EMM 73-10-13							WO#: JB2022-BZZ-018,JB2022-BZZ-023	
731020	NO. 1 ENGINE - FUEL-OIL COOLER							Component ATA:73
PN:D2397-10A	MOS/MSC	07-Jan-22	O/C					
SN:03785198	HRS	3611:42		TSN 3611:42				
	ENC	3222		TSN 3222				
PROC. REF: EMM 73-10-01								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 73 - ENGINE FUEL AND CONTROL									
731020	NO. 2 ENGINE - FUEL-OIL COOLER							Component	ATA:73
PN:D2397-10A	MOS/MSC	16-Dec-21	O/C	TSN 165					
SN:03785197	HRS	3611:42	TSN 3611:42						
	ENC	3222	TSN 3222						
PROC. REF: EMM 73-10-01									
731030	NO. 1 ENGINE - MOTIVE FLOW VALVE							Component	ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	ENC	0	TSN 0						
PROC. REF: GENERIC NO REF									
731030	NO. 2 ENGINE - MOTIVE FLOW VALVE							Component	ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	ENC	0	TSN 0						
PROC. REF: GENERIC NO REF									
731040	NO. 1 ENGINE - FLOW DIVIDER VALVE							Component	ATA:73
PN:25950-2	MOS/MSC	07-Jan-22	O/C	TSN 3611:42					
SN:9959534312	HRS	3611:42	TSN 3222						
	ENC	3222	TSN 3222						
PROC. REF: EMM 73-10-04									
731040	NO. 2 ENGINE - FLOW DIVIDER VALVE							Component	ATA:73
PN:25950-2	MOS/MSC	16-Dec-21	O/C	TSN 165					
SN:9959534310	HRS	3611:42	TSN 3611:42						
	ENC	3222	TSN 3222						
PROC. REF: EMM 73-10-04									
731050	NO. 1 ENGINE - CHECK FUEL MANIFOLD PRESSURE							Service	ATA:73
	MOS/MSC	17-Mar-08	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REF									
731050	NO. 2 ENGINE - CHECK FUEL MANIFOLD PRESSURE							Service	ATA:73
	MOS/MSC	17-Mar-08	A/R						
	HRS	0							
	ENC	0							
PROC. REF: GENERIC NO REF									

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731060 ^S		NO. 1 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR						Service ATA:73
PN:766400-4	MOS	31-Aug-22						
SN:F67698	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: GENERIC BLANK								PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023
731060 ^S		NO. 2 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR						Service ATA:73
PN:766400-4	MOS	31-Aug-22						
SN:F67693	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: GENERIC BLANK								PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023
731065	NO. 1 ENGINE - BLEED VALVE ACTUATOR						Component	ATA:73
PN:766400-4	MOS/MSC	07-Jan-22	O/C					
SN:F67698	HRS	3611:42						
	ENC	3222						
PROC. REF: EMM 73-10-12								WO#: JB2022-BZZ-009,JB2022-BZZ-011
731065	NO. 2 ENGINE - BLEED VALVE ACTUATOR						Component	ATA:73
PN:766400-4	MOS/MSC	16-Dec-21	O/C					
SN:F67693	HRS	3611:42						
	ENC	3222						
PROC. REF: EMM 73-10-12								WO#: JB2022-BZZ-009,JB2022-BZZ-011
731085	NO. 1 ENGINE - SCHEDULE MODULATOR						Component	ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731085	NO. 2 ENGINE - SCHEDULE MODULATOR						Component	ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732020	NO. 1 ENGINE - ELECTRONIC CONTROL COMPUTER							Component ATA:73
PN:780933-6-012	MOS/MSC	07-Jan-22	O/C					
SN:07107880	HRS	3611:42		TSN 3611:42				
	ENC	3222		TSN 3222				
PROC. REF: EMM 73-20-03								
732020	NO. 2 ENGINE - ELECTRONIC CONTROL COMPUTER							Component ATA:73
PN:780933-6-012	MOS/MSC	12-Sep-08	O/C					
SN:5073409	HRS	201:06						
	ENC	143						
PROC. REF: EMM 73-20-03								
732030	NO. 1 ENGINE - HYDROMECHANICAL METERING UNIT							Component ATA:73
PN:790155-10	MOS/MSC	07-Jan-22	O/C	TSO 0				
SN:F67820	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 73-20-02								
732030	NO. 2 ENGINE - HYDROMECHANICAL METERING UNIT							Component ATA:73
PN:790155-10	MOS/MSC	16-Dec-21	O/C	TSO 0				
SN:F67633	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 73-20-02								
732040 ^S	NO. 1 ENGINE - VISUALLY INSPECT ELECTRONIC BLEED VALVE CONTROL							Service ATA:73
PN:PN	MOS	31-Aug-22						
SN:UNKNOWN	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: GENERIC CMM								
PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023								
732040 ^S	NO. 2 ENGINE - VISUALLY INSPECT ELECTRONIC BLEED VALVE CONTROL							Service ATA:73
PN:PN	MOS	31-Aug-22						
SN:UNKNOWN	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: GENERIC CMM								
PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732045	NO. 1 ENGINE - ELECTRONIC BLEED VALVE CONTROL							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF							WO#: JB2022-BZZ-009,JB2022-BZZ-011	
732045	NO. 2 ENGINE - ELECTRONIC BLEED VALVE CONTROL							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF							WO#: JB2022-BZZ-009,JB2022-BZZ-011	
732060 ^S	NO. 1 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS							Service ATA:73
PN:PN	MOS	31-Aug-22						
SN:UNKNOWN	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: EMM 73-20-04							PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023	
732060 ^S	NO. 2 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS							Service ATA:73
PN:PN	MOS	31-Aug-22						
SN:UNKNOWN	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: EMM 73-20-04							PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023	
732065	NO. 1 ENGINE - MAIN WIRING HARNESS							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-04							WO#: JB2022-BZZ-009,JB2022-BZZ-011	
732065	NO. 2 ENGINE - MAIN WIRING HARNESS							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-04							WO#: JB2022-BZZ-009,JB2022-BZZ-011	

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733001	NO. 1 ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:PC900-3A2000PH1-1	MOS/MSC	26-Feb-16	O/C	TSO 4				
SN:520390	HRS	2231:42		TSO 0				
WC#: 73.070	AFL	1940		TSO 0				
PROC. REF: AMM 73-30-00								
733002	NO. 2 ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:PC900-3A2000PH1-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:524918	HRS	0		TSN 0				
WC#: 73.070	AFL	0		TSN 0				
PROC. REF: AMM 73-30-00								
733003	FUEL TOTALIZER INDICATOR							Component ATA:73
PN:AT-208-1	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:07-114	HRS	0		TSN 0				
WC#: 73.080	AFL	0		TSN 0				
PROC. REF: AMM 73-30-00								
733010	NO. 1 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:5/8-1-81-303	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:601830	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
733010	NO. 2 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:5/8-1-81-303	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:601042	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
733031	FUEL FLOW SIGNAL CONDITIONER							Component ATA:73
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.050	AFL	0		TSN 0				
PROC. REF: AMM 73-30-00								
H730001	CHECK LEFT NACELLE MOUNTED FUEL FILTER ASSEMBLY, P/N 307618 (JT15D-5R ONLY)							Service ATA:73
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 73.060	AFL	3695						
PROC. REF: EMM 73-10-13								

PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
H730002	CHECK RIGHT NACELLE MOUNTED FUEL FILTER ASSEMBLY, P/N 307618 (JT15D-5R ONLY)							Service ATA:73
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 73.060	AFL	3695						
PROC. REF: EMM 73-10-13								
PKG:1								
H730003	CHANGE LEFT FUEL PUMP OUTLET FILTER, P/N 3059778 (JT15D-5 AND JT15D-5R)							Service ATA:73
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 73.100	AFL	3695						
PKG:1								
H730004	CHANGE RIGHT FUEL PUMP OUTLET FILTER, P/N 3059778 (JT15D-5 AND JT15D-5R)							Service ATA:73
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 73.110	AFL	3695						
PKG:1								
H730007	INSPECT NO. 1 ENGINE FUEL PUMP OVERTEMPERATURE INDICATOR, P/N 3071526 (JT15D-5R ONLY)							Service ATA:73
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 73.090	AFL	3695						
PROC. REF: GENERIC NO REF								
PKG:1								
H730008	INSPECT NO. 2 ENGINE FUEL PUMP OVERTEMPERATURE INDICATOR, P/N 3071526 (JT15D-5R ONLY)							Service ATA:73
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 73.090	AFL	3695						
PROC. REF: GENERIC NO REF								
PKG:1								
ATA 74 - IGNITION								
740000	NO. 1 ENGINE - OPERATIONAL TEST SPARK IGNITERS							Service ATA:74
	MOS	31-Aug-22			RTS			
	HRS	4162:51	200 (+10%)					
	ENC	3563						
PROC. REF: EMM 74-00-00								
WO#: JB2022-BZZ-018,JB2022-BZZ-023								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 74 - IGNITION									
740000	NO. 2 ENGINE - OPERATIONAL TEST SPARK IGNITERS							Service	ATA:74
	MOS	31-Aug-22			RTS				
	HRS	4162:51	200 (+10%)						
	ENC	3563							
				PROC. REF: EMM 74-00-00		WO#: JB2022-BZZ-018,JB2022-BZZ-023			
741010	NO. 1 ENGINE - IGNITION EXCITER							Component	ATA:74
PN:9060660-2	MOS/MSC	04-Jan-09	O/C						
SN:NNA06465351	HRS	201:42							
	ENC	144							
				PROC. REF: EMM 74-10-01		WO#: JB2022-BZZ-011			
741010	NO. 2 ENGINE - IGNITION EXCITER							Component	ATA:74
PN:3054825-02	MOS/MSC	17-Mar-08	O/C	TSN 0					
SN:NNA07423387	HRS	0		TSN 0					
	ENC	0		TSN 0					
				PROC. REF: EMM 74-10-01		WO#: JB2022-BZZ-011			
741030 ^S	NO. 1 ENGINE - VISUAL INSPECT IGNITION EXCITER							Service	ATA:74
PN:9060660-2	MOS	31-Aug-22							
SN:NNA06465351	HRS	4162:51	200 ^S (+20)						
	ENC	3563							
				PROC. REF: EMM 74-10-01		PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023			
741030 ^S	NO. 2 ENGINE - VISUAL INSPECT IGNITION EXCITER							Service	ATA:74
PN:3054825-02	MOS	31-Aug-22							
SN:NNA07423387	HRS	4162:51	200 ^S (+20)						
	ENC	3563							
				PROC. REF: EMM 74-10-01		PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023			
742002	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION							Service	ATA:74
	MOS	31-Aug-22			RTS				
	HRS	4162:51	200 (+10%)						
	ENC	3563							
				PROC. REF: EMM 74-20-02		WO#: JB2022-BZZ-018,JB2022-BZZ-023			

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742002	NO. 2 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION							Service ATA:74
	MOS	31-Aug-22			RTS			
	HRS	4162:51	200 (+10%)					
	ENC	3563						
				PROC. REF: EMM 74-20-02		WO#: JB2022-BZZ-018,JB2022-BZZ-023		
742010	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG							Component ATA:74
PN:9044810-1	MOS/MSC	31-Aug-22	O/C	TSN 0				
SN:NNA22270014	HRS	4162:51		TSN 0				
	ENC	3563		TSN 0				
				PROC. REF: EMM 74-20-02				
742010	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG							Component ATA:74
PN:9044810-1	MOS/MSC	31-Aug-22	O/C	TSN 0				
SN:NNA22270016	HRS	4162:51		TSN 0				
	ENC	3563		TSN 0				
				PROC. REF: EMM 74-20-02				
742020	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG							Component ATA:74
PN:9044810-1	MOS/MSC	31-Aug-22	O/C	TSN 0				
SN:NNA22270009	HRS	4162:51		TSN 0				
	ENC	3563		TSN 0				
				PROC. REF: EMM 74-20-02				
742020	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG							Component ATA:74
PN:9044810-1	MOS/MSC	31-Aug-22	O/C	TSN 0				
SN:NNA22270015	HRS	4162:51		TSN 0				
	ENC	3563		TSN 0				
				PROC. REF: EMM 74-20-02				
742030	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG CABLE							Component ATA:74
PN:53300-1	MOS/MSC	07-Jan-22	O/C	TSN 0				
SN:285116004001	HRS	3611:42		TSN 0				
	ENC	3222		TSN 0				
				PROC. REF: EMM 74-20-01				
742030	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG CABLE							Component ATA:74
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
				PROC. REF: EMM 74-20-01				

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742040	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG CABLE							Component ATA:74
PN:53300-1	MOS/MSC	07-Jan-22	O/C	TSN 0				
SN:286246008001	HRS	3611:42		TSN 0				
	ENC	3222		TSN 0				
PROC. REF: EMM 74-20-01								
742040	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG CABLE							Component ATA:74
PN:53300-1	MOS/MSC	16-Dec-21	O/C	TSN 0				
SN:284072009001	HRS	3611:42		TSN 0				
	ENC	3222		TSN 0				
PROC. REF: EMM 74-20-01								
H740003	INSPECT NO. 1 ENGINE IGNITOR PLUGS							Service ATA:74
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 74.010	AFL	3695						
PROC. REF: EMM 74-20-02								PKG:1
H740004	INSPECT NO. 2 ENGINE IGNITOR PLUGS							Service ATA:74
	MOS	31-Aug-22			RTS			
	HRS	4384:47	200 (+40)					
WC#: 74.010	AFL	3695						
PROC. REF: EMM 74-20-02								PKG:1

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
750010	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:10018200L	MOS/MSC	07-Jan-22	O/C	TSO 0				
SN:3425	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 75-00-02								
750010	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:3033057	MOS/MSC	16-Dec-21	O/C	TSO 0				
SN:733	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 75-00-02								
751001	NO. 1 ENGINE ANTI ICE VALVE							Component ATA:75
PN:1895-00-1	MOS/MSC	24-Nov-08	O/C					
SN:1648	HRS	201:06						
WC#: 75.020	AFL	145						
PROC. REF: GENERIC NO REF								
751004	NO. 2 ENGINE ANTI ICE VALVE							Component ATA:75
PN:1895-00-1	MOS/MSC	03-Jul-16	O/C	TSO 1				
SN:1632A	HRS	2354:58		TSO 0				
WC#: 75.020	AFL	2057		TSO 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760001	INSPECT THRUST LEVER QUADRANT -PILOT COMPARTMENT							Service ATA:76
	MOS	29-Jul-21						
	HRS	3498:33	1200		4698:33		91:26	
	AFL	3150						
H760001 ^S	INSPECT THRUST LEVER QUADRANT, FORWARD THRUSTCONTROL CABLE, FORWARD BELLCRANK AND ENGINECONTROL ROD ASSEMBLIES-PILOT'S COMPARTMENT							Service ATA:76
	MOS	07-May-22						
	HRS	3976:37	1600 ^S					
	AFL	3438						
PKG:4								
H760004 ^S	INSPECT CENTER PEDESTAL - PILOT'S COMPARTMENT							Service ATA:76
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
PKG:3								
H760104 ^S	INSPECT THROTTLE FEEDBACK CABLE - LEFT-HAND THRUST REVERSER							Service ATA:76
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H760105 ^S	INSPECT FEEDBACK BRACKET ASSEMBLY - LEFT-HAND THRUST REVERSER							Service ATA:76
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H760204 ^S	INSPECT THROTTLE FEEDBACK CABLE - RIGHT-HAND THRUST REVERSER							Service ATA:76
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								
H760205 ^S	INSPECT FEEDBACK BRACKET ASSEMBLY - RIGHT-HAND THRUST REVERSER							Service ATA:76
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
PKG:2								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
770010 ^S	NO. 1 ENGINE - INSPECT T1 PROBE THERMOCOUPLE HARNESS FOR DAMAGE OR PROBES TOUCHING EACH OTHER							Service ATA:77
	MOS	31-Aug-22						
	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: EMM 77-00-01								PKG:0
770010 ^S	NO. 2 ENGINE - INSPECT T1 PROBE THERMOCOUPLE HARNESS FOR DAMAGE OR PROBES TOUCHING EACH OTHER							Service ATA:77
	MOS	31-Aug-22						
	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: EMM 77-00-01								PKG:0
771001	NO. 1 ENGINE N1 (FAN) INDICATOR							Component ATA:77
PN:128-384046-3	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:141965	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: AMM 77-11-00								
771002	NO. 2 ENGINE N1 (FAN) INDICATOR							Component ATA:77
PN:128-384046-3	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:145722	HRS	0		TSN 0				
WC#: 77.010	AFL	0		TSN 0				
PROC. REF: AMM 77-11-00								
771003	NO. 1 ENGINE N2 (TURBINE) INDICATOR							Component ATA:77
PN:128-384045-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:140559	HRS	0		TSN 0				
WC#: 77.020	AFL	0		TSN 0				
PROC. REF: AMM 77-12-00								
771004	NO. 2 ENGINE N2 (TURBINE) INDICATOR							Component ATA:77
PN:128-384045-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:144720	HRS	0		TSN 0				
WC#: 77.020	AFL	0		TSN 0				
PROC. REF: AMM 77-12-00								
771010	NO. 1 ENGINE - N1 SPEED SENSOR PROBE							Component ATA:77
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771010	NO. 2 ENGINE - N1 SPEED SENSOR PROBE							Component ATA:77
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
771020	NO. 1 ENGINE - N2 SPEED SENSOR PROBE							Component ATA:77
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
771020	NO. 2 ENGINE - N2 SPEED SENSOR PROBE							Component ATA:77
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
772010	NO. 1 ENGINE - T1 THERMOCOUPLE HARNESS							Component ATA:77
PN:3070219-01	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:AA85782	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-00-01								
772010	NO. 2 ENGINE - T1 THERMOCOUPLE HARNESS							Component ATA:77
PN:3070219-01	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:AA87223	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-00-01								
772020	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS							Component ATA:77
PN:3119093-01	MOS/MSC	07-Jan-22	O/C	TSO 0				
SN:R20025601	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 77-00-02								
772020	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS							Component ATA:77
PN:3119093-01	MOS/MSC	16-Dec-21	O/C	TSO 0				
SN:R20001301	HRS	3611:42		TSO 0				
	ENC	3222		TSO 0				
PROC. REF: EMM 77-00-02								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772030	NO. 1 ENGINE - VARIABLE RESISTOR							Component ATA:77
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-00-01								
772030	NO. 2 ENGINE - VARIABLE RESISTOR							Component ATA:77
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-00-01								
772061	NO. 1 ENGINE ITT INDICATOR							Component ATA:77
PN:128-384047-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1663A	HRS	0		TSN 0				
WC#: 77.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
772062	NO. 2 ENGINE ITT INDICATOR							Component ATA:77
PN:128-384047-5	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:1671A	HRS	0		TSN 0				
WC#: 77.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
773001	NO. 1 ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:45AS86803-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:18286	HRS	0		TSN 0				
WC#: 77.090	AFL	0		TSN 0				
PROC. REF: AMM 77-31-00								
773002	NO. 2 ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:45AS86803-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:18274	HRS	0		TSN 0				
WC#: 77.090	AFL	0		TSN 0				
PROC. REF: AMM 77-31-00								
773013	ENGINE VIBRATION SIGNAL CONDTIONER							Component ATA:77
PN:45AS86803-011	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:AJ50	HRS	0		TSN 0				
WC#: 77.100	AFL	0		TSN 0				
PROC. REF: AMM 77-31-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
773019	ENGINE VIBRATION INDICATOR							Component ATA:77
PN:45AS86803-007	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:O7090981A	HRS	0		TSN 0				
WC#: 77.110	AFL	0		TSN 0				
PROC. REF: AMM 77-31-00								
ATA 78 - EXHAUST								
781001	NO. 1 ENGINE EXHAUST DUCT ASSEMBLY							Component ATA:78
PN:3119721-01	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:ABCA0065	HRS	0		TSN 0				
WC#: 78.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
781002	NO. 2 ENGINE EXHAUST DUCT ASSEMBLY							Component ATA:78
PN:3119721-01	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:ABCA0063	HRS	0		TSN 0				
WC#: 78.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783001	NO. 1 ENGINE THRUST REVERSER							Component ATA:78
PN:225-0012-513	MOS/MSC	08-Oct-21	O/C					
SN:3933	HRS	3611:43						
WC#: 78.010	AFL	3222						
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783002	NO. 2 ENGINE THRUST REVERSER							Component ATA:78
PN:225-0012-515	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:B4518-2	HRS	0		TSN 0				
WC#: 78.011	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783061	NO. 1 ENGINE INBOARD STANG FAIRING							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783062	NO. 2 ENGINE INBOARD STANG FAIRING							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783063	NO. 1 ENGINE OUTBOARD STANG FAIRING							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783064	NO. 2 ENGINE OUTBOARD STANG FAIRING							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783085	NO. 1 ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783086	NO. 2 ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783087	NO. 1 ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783088	NO. 2 ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.080	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783109	NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.090	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783110	NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.090	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783111	NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.100	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783112	NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.100	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783133	NO. 1 ENGINE INBOARD THRUST REVERSER ACTUATING MECHANISM							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.110	AFL	0		TSN 0				
PROC. REF: GENERIC CMM								
783134	NO. 2 ENGINE INBOARD THRUST REVERSER ACTUATING MECHANISM							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.110	AFL	0		TSN 0				
PROC. REF: GENERIC CMM								
783135	NO. 1 ENGINE OUTBOARD THRUST REVERSER ACTUATING MECHANISM							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.120	AFL	0		TSN 0				
PROC. REF: GENERIC CMM								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783136	NO. 2 ENGINE OUTBOARD THRUST REVERSER ACTUATING MECHANISM							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.120	AFL	0		TSN 0				
PROC. REF: GENERIC CMM								
783157	NO. 1 ENGINE THRUST REVERSER INBOARD STOW LIMIT SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.130	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783158	NO. 2 ENGINE THRUST REVERSER INBOARD STOW LIMIT SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.130	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783159	NO. 1 ENGINE THRUST REVERSER OUTBOARD STOW LIMIT SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.140	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783160	NO. 2 ENGINE THRUST REVERSER OUTBOARD STOW LIMIT SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.140	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783161	NO. 1 ENGINE THRUST REVERSER DEPLOY SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.150	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783162	NO. 2 ENGINE THRUST REVERSER DEPLOY SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.150	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783163	NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.160	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783164	NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.160	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00								
783205	NO. 1 ENGINE THRUST REVERSER SHUT-OFF VALVE							Component ATA:78
PN:13027-6	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:T2317	HRS	0		TSN 0				
WC#: 78.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783206	NO. 2 ENGINE THRUST REVERSER SHUT-OFF VALVE							Component ATA:78
PN:13027-6	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:T2328	HRS	0		TSN 0				
WC#: 78.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
783217	NO. 1 ENGINE THRUST REVERSER CONTROL VALVE							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.175	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783218	NO. 2 ENGINE THRUST REVERSER CONTROL VALVE							Component ATA:78
PN:PN	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.175	AFL	0		TSN 0				
PROC. REF: AMM 78-30-00, AMM 78-30-00								
783229	THRUST REVERSER CONTROL BOX							Component ATA:78
PN:76481-2	MOS/MSC	30-Oct-08	O/C					
SN:1228	HRS	197						
WC#: 78.040	AFL	142						
PROC. REF: AMM 78-30-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
H780004 ^S		INSPECT THRUST REVERSER CONTROL VALVE, ISOLATION VALVE,PRESSURE SWITCH, CHECK VALVE AND HYDRAULIC LINES - AFT FUSELAGE						Service ATA:78
	MOS	07-May-22						
	HRS	3976:37	800 ^S					
	AFL	3438						
								PKG:3
H780101 ^S		INSPECT STANGS AND DOORS - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780102 ^S		INSPECT MECHANICAL ACTUATING MECHANISM - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780103 ^S		INSPECT DEPLOY AND STOW LIMIT SWITCHES - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780105 ^S		INSPECT UPPER AND LOWER DOORS - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780106 ^S		INSPECT FAN DUCT ASSEMBLY - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
H780108 ^S		INSPECT THRUST REVERSER - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780109 ^S		INSPECT HYDRAULIC ACTUATOR - LEFT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780201 ^S		INSPECT STANGS AND DOORS - RIGHT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780202 ^S		INSPECT MECHANICAL ACTUATING MECHANISM - RIGHT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780203 ^S		INSPECT DEPLOY AND STOW LIMIT SWITCHES - RIGHT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780205 ^S		INSPECT UPPER AND LOWER DOORS - RIGHT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780206 ^S		INSPECT FAN DUCT ASSEMBLY - RIGHT-HAND THRUST REVERSER						Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
H780208 ^S	INSPECT THRUST REVERSER - RIGHT-HAND THRUST REVERSER							Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
H780209 ^S	INSPECT HYDRAULIC ACTUATOR - RIGHT-HAND THRUST REVERSER							Service ATA:78
	MOS	31-Aug-22	12 ^S					
	HRS	4384:47	400 ^S					
	AFL	3695						
								PKG:2
ATA 79 - OIL								
792010	NO. 1 ENGINE - CHANGE OIL/DRAIN AND FILL							Service ATA:79
	MOS/MSC	09-Sep-14	O/C					
	HRS	1781:03						
	ENC	1498						
PROC. REF: EMM 72-00-00								
792010	NO. 2 ENGINE - CHANGE OIL/DRAIN AND FILL							Service ATA:79
	MOS/MSC	09-Sep-14	O/C					
	HRS	1781:03						
	ENC	1498						
PROC. REF: EMM 72-00-00								
792015 ^S	NO. 1 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER							Service ATA:79
	MOS	31-Aug-22						
	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: EMM 79-20-01, EMM 79-21-01								PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023
792015 ^S	NO. 2 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER							Service ATA:79
	MOS	31-Aug-22						
	HRS	4162:51	200 ^S (+20)					
	ENC	3563						
PROC. REF: EMM 79-20-01, EMM 79-21-01								PKG:0 WO#: JB2022-BZZ-018,JB2022-BZZ-023

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792020	NO. 1 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER							Service ATA:79
	MOS	30-Jun-22	12		30-Jun-23		213 d	
	HRS	3950:51	800 (+50/-50)		(4750:51) 4972:47	4800:51	365:40 (+50)	
	ENC	3426						
PROC. REF: EMM 79-20-01, EMM 79-21-01								
792020	NO. 2 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER							Service ATA:79
	MOS	30-Jun-22	12		30-Jun-23		213 d	
	HRS	3950:51	800 (+50/-50)		(4750:51) 4972:47	4800:51	365:40 (+50)	
	ENC	3426						
PROC. REF: EMM 79-20-01, EMM 79-21-01								
792110	NO. 1 ENGINE - THERMOSTATIC BYPASS VALVE							Component ATA:79
PN:10951A	MOS	07-Jan-22						
SN:WA30240	HRS	3611:42	4000 (+100)		(7211:43) 7433:39 ^M	7311:43	2826:32 (+100)	
	ENC	3222						
PROC. REF: EMM 79-21-01								
792110	NO. 2 ENGINE - THERMOSTATIC BYPASS VALVE							Component ATA:79
PN:3072805-03	MOS	16-Dec-21		TSN 165, TSO 0				
SN:WA30237	HRS	3611:42	4000 (+100)	TSN 3611:42, TSO 0	(7611:42) 7833:38	7711:42	3226:31 (+100)	
	ENC	3222		TSN 3222, TSO 0				
PROC. REF: EMM 79-21-01								
793001	NO. 1 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:45AS86825-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0743-804	HRS	0		TSN 0				
WC#: 79.030	AFL	0		TSN 0				
PROC. REF: AMM 31-10-00								
793002	NO. 2 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:45AS86825-009	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0740-801	HRS	0		TSN 0				
WC#: 79.030	AFL	0		TSN 0				
PROC. REF: AMM 31-10-00								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793010	NO. 1 ENGINE - OIL PRESSURE TRANSMITTER							Component ATA:79
PN:45AS86825-005	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0742085	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793010	NO. 2 ENGINE - OIL PRESSURE TRANSMITTER							Component ATA:79
PN:45AS86825-005	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:0742081	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793020	NO. 1 ENGINE - LOW OIL PRESSURE WARNING SWITCH							Component ATA:79
PN:45AS48008-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:H051441	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793020	NO. 2 ENGINE - LOW OIL PRESSURE WARNING SWITCH							Component ATA:79
PN:45AS48008-019	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:G041639	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793030	NO. 1 ENGINE - OIL FILTER BYPASS PRESSURE SWITCH							Component ATA:79
PN:45AS42011-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2650	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793030	NO. 2 ENGINE - OIL FILTER BYPASS PRESSURE SWITCH							Component ATA:79
PN:45AS42011-001	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:2659	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793040	NO. 1 ENGINE - OIL TEMPERATURE BULB							Component ATA:79
PN:102-0083	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:O6358	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task



Status Report

Model: HAWKER 400XP Serial: RK-552 RegNo: OK-BZZ HRS: 4607:07 AFL: 3829 As Of: 29-Nov-2022

29-Nov-2022 04:15 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793040	NO. 2 ENGINE - OIL TEMPERATURE BULB							Component ATA:79
PN:102-0083	MOS/MSC	17-Mar-08	O/C	TSN 0				
SN:O6091	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information ^S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W ^M-Manual Due ^U-User Task ^{Ex}-Excluded Task