



MASTER AD/SI REPORT

560XLS+CITATION
XLS+ (MSG)

S/N 560XL-6295 OK-WND

OWNER: AEROPARTNER A.S.
ADDRESS: K LETISTI / HANGAR C
PRAGUE 161 00
OFFICE:
FAX:

OPERATOR: AEROPARTNER A.S.
ADDRESS: K LETISTI / HANGAR C
PRAGUE 161 00
OFFICE:
FAX:

ANALYST: GUILLAUME DUCLOS +33-1.55.93.45.84 (DIRECT)
EMAIL: GUILLAUME.DUCLOS@CAMPSYSTEMS.EU +33-1.55.93.45.80 (MAIN)
WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Mode:WITH COMPLIANCE OR NEXT DUE; Group by Profile or Bulletin:PROFILE TYPE;

AIRCRAFT	SERIAL/REGNO: 560XL-6295/OK-WND	MODEL: 560XLS+CITATION XLS+ (MSG)	MANUFACTURER: TEXTRON AVIATION INC.
	CERTIFICATION DATE: 17-DEC-2020	LAST ACTUALS: 2576:12 A/C HRS as of 07-JAN-2026 1666 AFL as of 07-JAN-2026 928:06 APH as of 13-NOV-2025 1523 APS as of 08-SEP-2025	
APU	SERIAL/PART: P-1098/3800722-1	MODEL: RE100 (XL)	MANUFACTURER: HONEYWELL
	INSTALLED ON: 01-JAN-2021 0 APU HRS 0 A/C HRS 0 APUS	LAST ACTUALS: 928:06 APU HRS as of 13-NOV-2025 1523 APUS as of 08-SEP-2025	
ENGINE NO. 1	SERIAL/PART: PCE-DF0599/30J2934-01	MODEL: PW545C	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
	INSTALLED ON: 01-JAN-2021 0 ENG. HRS 0 A/C HRS 0 ENC	LAST ACTUALS: 2576:12 ENG. HRS as of 07-JAN-2026 1666 ENC as of 07-JAN-2026	
ENGINE NO. 2	SERIAL/PART: PCE-DF0598/30J2934-01	MODEL: PW545C	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
	INSTALLED ON: 01-JAN-2021 0 ENG. HRS 0 A/C HRS 0 ENC	LAST ACTUALS: 2576:12 ENG. HRS as of 07-JAN-2026 1666 ENC as of 07-JAN-2026	



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - AD - 560XLS+CITATION XLS+ (MSG) 560XL-6295/OK-WND							
EASA 2025-0088	NAVIGATION - SATELLITE BASED AUGMENTATION SYSTEMS / GLOBAL POSITIONING SYSTEM RECEIVER - REPLACEMENT					MANDATORY	
	MOS		24		30-APR-2027		
Eff. Date: 30-APR-2025							
EASA 2025-0222	OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS					MANDATORY	Not Applicable - PBE FROM DIFFERENT MANUFACTURER INSTALLED
	MOS			19-NOV-2025			
	DAYS			2550:40			
	HRS			1652			
	AFL						
	MSC		-				
Eff. Date: 20-OCT-2025							
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	Not Applicable - AD N/A - ALL PLACARDS ARE INSTALLED. STRICT NON-SMOKING POLICY IN THE AIRCRAFT
	MOS			12-JAN-2023			
	HRS	1000		820:45			
	AFL			519			
Eff. Date: 28-MAR-2012							
FAA 1998-25-02	SKYWATCH SKY 497					MANDATORY	Not Applicable - AD 98-25-02 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
	MOS			17-DEC-2020			
	HRS			7:24			
	AFL			5			
	MSC		A/R				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2000-03-09	ICING COND FM INFORMATION					MANDATORY	Not Applicable - AD 2000-03-09 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN THE SUSPECT SERIAL RANGE.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	-				
FAA 2000-15-51	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR					MANDATORY	Complied With - AD 2000-15-51 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	-				
Eff. Date: 14-AUG-2000							
FAA 2001-14-09	WIRING OF THE LANDING LIGHT SWITCH AND THE J-BOX FAIRING RELAYS					MANDATORY	Complied With - AD 2001-14-09 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	-				
Eff. Date: 26-JUL-2001							
FAA 2001-23-17	NAVIGATION - GARMIN INTERNATIONAL GNS 430 - MODIFICATION					MANDATORY	Not Applicable - AD 2001-23-17 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	A/R				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due (New Requirement) (FFF)-Effective C/W (EBT)-Estimated Base Time (EBT)



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS			17-DEC-2020		
		HRS			7:24		
		AFL			5		
		MSC	-				
Eff. Date: 05-JUL-2013							
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS			17-DEC-2020		
		DAYS			7:24		
		HRS			5		
		AFL					
		MSC	-				
Eff. Date: 05-JUL-2013							
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS			17-DEC-2020		
		DAYS			7:24		
		HRS			5		
		AFL					
		MSC	-				
Eff. Date: 05-JUL-2013							
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS			17-DEC-2020		
		HRS			7:24		
		AFL			5		
		MSC	-				
Eff. Date: 05-JUL-2013							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	A/R				
Eff. Date: 05-JUL-2013							
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	A/R				
Eff. Date: 05-JUL-2013							
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS					MANDATORY	Not Applicable - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
		MOS		17-DEC-2020			
		DAYS		7:24			
		HRS		5			
		AFL					
		MSC	-				
Eff. Date: 05-JUL-2013							
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	Not Applicable - AD 2014-18-01 IS NOT APPLICABLE DUE TO PAGES 6 & 7 SECTION (C) (3) (V) AND ECR 58032.
		MOS		17-DEC-2020			
		HRS		7:24			
		AFL		5			
		MSC	-				
Eff. Date: 14-OCT-2014							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2017-04-14	ELECTRICAL POWER - INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES					MANDATORY	Complied With - AD 2017-04-14 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS			17-DEC-2020		
		HRS			7:24		
		AFL			5		
		MSC	-				
		Eff. Date: 09-MAR-2017					
FAA 2017-04-14 PARA (G)	ACCOMPLISH GENERAL VISUAL INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES FOR EVIDENCE OF DAMAGE, ALL APPLICABLE ADJUSTMENTS, AND ALL APPLICABLE CORRECTIVE ACTIONS					MANDATORY	Complied With - AD 2017-04-14 PARA (G) HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS			17-DEC-2020		
		DAYS			7:24		
		HRS			5		
		AFL					
		MSC	-				
		Eff. Date: 09-MAR-2017					
FAA 2017-04-14 PARA (H)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD TO TEXTRON AVIATION					MANDATORY	Complied With - AD 2017-04-14 PARA (H) HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS			17-DEC-2020		
		DAYS			7:24		
		HRS			5		
		AFL					
		MSC	-				
		Eff. Date: 09-MAR-2017					
FAA 2020-26-05	ENGINE CONTROLS - LEFT AND RIGHT THROTTLE QUADRANT ASSEMBLY SENSOR LINK AND SENSOR DRIVE ARM PIVOT RIVETS - INSPECTION/CORRECTIVE ACTION					MANDATORY	Not Applicable - NOT APPLICABLE - N/A BY AIRCRAFT S/N
		MOS			05-DEC-2022		
		HRS			795:08		
		AFL			499		
		MSC	-				
		Eff. Date: 17-DEC-2020					

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2023-10-02	INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION					MANDATORY	Complied With - FAA 2023-10-02
	MOS HRS AFL APH MSC			22-SEP-2023 1162:20 753			
	Eff. Date: 26-MAY-2023						
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)					MANDATORY	Complied With - FAA 2023-10-02
	MOS HRS AFL APH MSC			22-SEP-2023 1162:20 753			
	Eff. Date: 26-MAY-2023						
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	Complied With - FAA 2023-10-02
	MOS HRS AFL APH MSC			22-SEP-2023 1162:20 753			
	Eff. Date: 26-MAY-2023						
FAA 2024-26-02	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	Not Applicable - NOT EQUIPPED ON A/C
	MOS HRS AFL MSC			22-AUG-2025 2419:33 1571			
	Eff. Date: 07-MAR-2025						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	Not Applicable - NOT EQUIPPED ON A/C
		MOS		22-AUG-2025			
		HRS		2419:33			
		AFL		1571			
		MSC	-				
Eff. Date: 07-MAR-2025							
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	Not Applicable - NOT EQUIPPED ON A/C
		MOS		22-AUG-2025			
		HRS		2419:33			
		AFL		1571			
		MSC	-				
Eff. Date: 07-MAR-2025							
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	Not Applicable - NOT EQUIPPED ON A/C
		MOS		22-AUG-2025			
		HRS		2419:33			
		AFL		1571			
		MSC	-				
Eff. Date: 07-MAR-2025							
FAA 2025-11-09 PARA (G)	FIRE BOTTLE WIRE TEST AND INSPECTION					MANDATORY	
		MOS					
		DAYS					
		HRS					
		MSC	-				
Eff. Date: 11-JUL-2025							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL:
1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2025-25-02	OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS					MANDATORY	Not Applicable - AS PER S/N
	MOS						
	DAYS			17-DEC-2025			
	HRS			2568:20			
	AFL			1660			
	MSC		-				

Eff. Date: 24-DEC-2025

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex) -Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
APPLIANCE - 560XLS+CITATION XLS+ (MSG) 560XL-6295/OK-WND							
EASA 2025-0297	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE					MANDATORY	
MOS MSC							
Eff. Date: 06-JAN-2026							
EASA 2025-0297 PARA (1)	APPLIANCE ADP - REPLACE THE Affected PBE WITH A PBE NOT Affected BY THIS AD					MANDATORY	
MOS DAYS							
Eff. Date: 06-JAN-2026							
FAA 1994-01-04	NAVIGATION - HONEYWELL TCAS II COMPUTERS PN 4066010-901, -902, -903 - REMOVE / MODIFY					MANDATORY	Complied With - AD 94-01-04 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
MOS HRS AFL MSC							
17-DEC-2020 7:24 5							
A/R							
Eff. Date: 02-FEB-1994							
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)					MANDATORY	Not Applicable - AD 2012-26-15-R1 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
MOS HRS AFL MSC							
17-DEC-2020 7:24 5							
-							
Eff. Date: 03-DEC-2014							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS					MANDATORY	Not Applicable - AD 2020-10-05 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT PROGRAMED FOR THIS OPTION.
SL560XL-34-29		MOS HRS AFL MSC	-	17-DEC-2020 7:24 5			

Eff. Date: 24-JUN-2020

FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT				MANDATORY	
		MOS DAYS	30			

Eff. Date: 14-JAN-2026

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - SB - 560XLS+CITATION XLS+ (MSG) 560XL-6295/OK-WND							
SB 560XL-23-11	COMMUNICATIONS - ATN-B1 CONTROLLER PILOT DATA LINK COMMUNICATIONS (CPDLC) INSTALLATION, SERVICE BULLETIN					OPTIONAL	Complied With
	MOS HRS AFL MSC			12-NOV-2025 2544:52 1649 -			
	Eff. Date: 07-APR-2022						
SB 560XL-24-21	ELECTRICAL POWER - INSTALL NEW RIGHT ALTERNATOR POWER CONTROL UNIT (PCU) (UE016) MOUNTING BRACKET, SERVICE BULLETIN					Complied With - SB560XL-24-21 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.	
	MOS HRS AFL MSC			17-DEC-2020 7:24 5 -			
SL SL560XL-25-20	EQUIPMENT/FURNISHINGS - INSPECTION OF THE INERTIAL REEL AND RESTRAINT SYSTEM, SERVICE LETTER				MANDATORY	Not Applicable - N/A	
	MOS HRS AFL APH MSC			22-SEP-2023 1162:20 753 -			
	Eff. Date: 14-AUG-2023						
SL SL560XL-25-23	EQUIPMENT/FURNISHINGS - PASSENGER SEAT SWIVEL PLATE SWING ARM ASSEMBLY FASTENER INSPECTION FOR PROPER ADHESIVE APPLICATION, SERVICE LETTER				RECOMMENDED	Not Applicable - N/A	
	MOS HRS AFL APH MSC			22-SEP-2023 1162:20 753 -			
	Eff. Date: 05-APR-2023						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 02-JUL-2025							
SL SL560XL-52-10	DOORS - REPLACEMENT OF THE CABIN DOOR PRECATCH HOUSING ASSEMBLY, SERVICE LETTER					RECOMMENDED	Complied With - ACCOMPLISHED CESSNA SL560XL-52-10, CABIN DOOR PRE-CATCH ASSEMBLY REPLACEMENT DATED 28OCT2021.
	MOS			11-JAN-2022			
	HRS			498:48			
	AFL			310			
	MSC	-					
Eff. Date: 28-OCT-2021							
SL SL560XL-76-05	ENGINE CONTROLS - INSPECTION OF THE RIGHT ENGINE THROTTLE QUADRANT ROTARY VARIABLE DIFFERENTIAL TRANSFORMER (RVDT) ELECTRICAL WIRING, SERVICE LETTER					MANDATORY	Complied With - RVDT ELECTRICAL WIRING INSPECTED, NO CHAFING FOUND. WIRING IN GOOD CONDITION, NO CONTACT WITH GUST LOCK ARM.
	MOS			01-MAR-2023			
	DAYS			846:19			
	HRS			533			
	AFL						
	MSC	-					

Eff. Date: 06-FEB-2023

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 1 - AD - PW545C PCE-DF0599/30J2934-01							
TCCA CF-2025-08	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) DISK - IMPROPER REWORK					MANDATORY	Not Applicable - AS PER HP TURBINE DISK S/N
	MOS			23-FEB-2025			
	HRS			2137:25			
	ENC			1395			
	MSC	-					
Eff. Date: 24-FEB-2025							
TCCA CF-2025-08 PART I	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF THE ENGINE TECHNICAL RECORDS (LOG BOOK) OR THE HP TURBINE DISK TO IDENTIFY THE SERIAL NUMBER IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE P&WC SB SECTION 3.A.					MANDATORY	Not Applicable - AS PER HP TURBINE DISK S/N
	MOS			23-FEB-2025			
	HRS			2137:25			
	ENC			1395			
	MSC	-					
Eff. Date: 24-FEB-2025							
TCCA CF-2025-08 PART I.A.	NO. 1 ENGINE - REMOVE THE AFFECTED HPT DISK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE P&WC SB SECTION 3.D.(1)					MANDATORY	Not Applicable - AS PER HP TURBINE DISK S/N
	MOS			23-FEB-2025			
	HRS			2137:25			
	ENC			1395			
	MSC	-					

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 2 - AD - PW545C PCE-DF0598/30J2934-01							
TCCA CF-2025-08	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) DISK - IMPROPER REWORK					MANDATORY	Not Applicable - AS PER HP TURBINE DISK S/N
		MOS		23-FEB-2025			
		HRS		2137:25			
		ENC		1395			
		MSC	-				
Eff. Date: 24-FEB-2025							
TCCA CF-2025-08 PART I	NO. 2 ENGINE - ACCOMPLISH INSPECTION OF THE ENGINE TECHNICAL RECORDS (LOG BOOK) OR THE HP TURBINE DISK TO IDENTIFY THE SERIAL NUMBER IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE P&WC SB SECTION 3.A.					MANDATORY	Not Applicable - AS PER HP TURBINE DISK S/N
		MOS		23-FEB-2025			
		HRS		2137:25			
		ENC		1395			
		MSC	-				
Eff. Date: 24-FEB-2025							
TCCA CF-2025-08 PART I.A.	NO. 2 ENGINE - REMOVE THE AFFECTED HPT DISK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE P&WC SB SECTION 3.D.(1)					MANDATORY	Not Applicable - AS PER HP TURBINE DISK S/N
		MOS		23-FEB-2025			
		HRS		2137:25			
		ENC		1395			
		MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 1 - SB - PW545C PCE-DF0599/30J2934-01							
SB PW500-72-30325 R03	NO. 1 ENGINE - REPLACEMENT OF OIL-PUMP PLAIN SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 30-AUG-2017							
SB PW500-72-30333	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FAN ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 26-JAN-2010							
SB PW500-72-30354 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY-GEARBOX PLAIN-SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 28-APR-2008							
SB PW500-72-30361	NO. 1 ENGINE - REPLACEMENT OUTER FRONT BYPASS DUCT WITH NEW STUDS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 05-MAY-2008							
SB PW500-72-30362	NO. 1 ENGINE - REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 05-JUN-2008							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30365	NO. 1 ENGINE - REPLACEMENT INLET PRESSURE OIL TUBE ASSY, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 09-MAY-2008							
SB PW500-72-30366	NO. 1 ENGINE - REPLACEMENT AIR/OIL SEPARATOR, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 01-MAY-2008							
SB PW500-72-30369 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING, SERVICE BULLETIN				CATEGORY 6	Complied With - AT MANUFACTURE	
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		A/R				
Eff. Date: 02-SEP-2011							
SB PW500-72-30370 R01	NO. 1 ENGINE - REPLACEMENT FUEL METERING UNIT, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
	MOS			17-DEC-2020			
	HRS						
	ENC						

2-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EEE)-Effective C/W (EBT)-Estimated Base Time (EBT)



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30371 R02	NO. 1 ENGINE - INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE, SERVICE BULLETIN					CATEGORY 10	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 11-MAR-2014						
SB PW500-72-30373	NO. 1 ENGINE - REPLACEMENT SECONDARY FUEL PRESSURE TUBE AND SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 15-AUG-2008						
SB PW500-72-30376 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 16-JUN-2016						
SB PW500-72-30379 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF BY-PASS DUCTS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 11-SEP-2015						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

2. Insufficient Information, +: Task exists in Inspection Manual (S), Suppressed Requirement (Ex), Excluded Tasks, *: Estimated Due/Now Requirement (EEF), Effective C/W (ERT), Estimated Baseline Time (EBT)



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due
12-Jan-2026 05:41 AM

-I-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (FFF)-Effective C/W (ERT)-Estimated Base Tim



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 03-MAY-2010							
SB PW500-72-30405 R04	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE MANIFOLD, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 14-MAR-2018							
SB PW500-72-30407 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 30-AUG-2017							
SB PW500-72-30411 R01	NO. 1 ENGINE - REPLACEMENT OF GASKETS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC A/R							
Eff. Date: 22-MAR-2010							
SB PW500-72-30413 R11	NO. 1 ENGINE - INTRODUCTION OF DEEPER SUMP, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 30-NOV-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

2. Insufficient Information, +: Task exists in Inspection Manual (S), Suppressed Requirement (Ex), Excluded Tasks, *: Estimated Due/Now Requirement (EEF), Effective C/W (ERT), Estimated Baseline Time (EBT)



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30420 R06	NO. 1 ENGINE - REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30423 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
Eff. Date: 17-SEP-2012							
SB PW500-72-30426	NO. 1 ENGINE - FAN CASE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
	A/R						
Eff. Date: 08-JUL-2011							
SB PW500-72-30427 R04	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
	-						
Eff. Date: 06-NOV-2018							
SB PW500-72-30428 R06	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
	-						
Eff. Date: 08-FEB-2019							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30429 R06	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
							Eff. Date: 02-AUG-2017
SB PW500-72-30432 R01	NO. 1 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		A/R				
							Eff. Date: 12-MAY-2011
SB PW500-72-30434 R05	NO. 1 ENGINE - REPLACEMENT - MODIFICATION OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				17-DEC-2020	CATEGORY 10	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
							Eff. Date: 15-JUL-2015
SB PW500-72-30436 R04	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
							Eff. Date: 18-APR-2018
SB PW500-72-30438 R05	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				17-DEC-2020	CATEGORY 10	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
							Eff. Date: 15-JUL-2015

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30440 R06	NO. 1 ENGINE - REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30445	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30446 R02	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30447 R01	NO. 1 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30449 R02	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 11-SEP-2015							
SB PW500-72-30453 R03	NO. 1 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 11-AUG-2017							
SB PW500-72-30463 R02	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 18-AUG-2016							
SB PW500-72-30465 R02	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 08-JUL-2016							
SB PW500-72-30466 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 12-JUL-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30470 R01	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30474 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30475 R03	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30478 R04	NO. 1 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30479 R06	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 20-MAY-2016							
SB PW500-72-30480	NO. 1 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 05-DEC-2013							
SB PW500-72-30481	NO. 1 ENGINE - REPLACEMENT OF FUEL SHUT-OFF CABLE, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 06-DEC-2013							
SB PW500-72-30483 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02), SERVICE BULLETIN				17-DEC-2020	CATEGORY 10	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 22-OCT-2014							
SB PW500-72-30485 R02	NO. 1 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 14-AUG-2017							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30491 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 27-JUL-2015						
SB PW500-72-30492 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 10-JAN-2017						
SB PW500-72-30495 R01	NO. 1 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE, SERVICE BULLETIN					CATEGORY 10	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 13-OCT-2016						
SB PW500-72-30496 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 01-OCT-2018						
SB PW500-72-30498 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 20-SEP-2017						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due
12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30502 R04	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 20-OCT-2016							
SB PW500-72-30504 R03	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 15-JAN-2019							
SB PW500-72-30505 R02	NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN				CATEGORY 3	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 21-MAY-2015							
SB PW500-72-30506 R02	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 11-SEP-2015							
SB PW500-72-30508 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				

2-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EEE)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 06-DEC-2018							
SB PW500-72-30510	NO. 1 ENGINE - REPLACEMENT OF PRIMARY AND SECONDARY FUEL TUBE SUPPORT BRACKET, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 29-JAN-2015							
SB PW500-72-30516 R02	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 22-JUN-2015							
SB PW500-72-30517 R01	NO. 1 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 05-JAN-2016							
SB PW500-72-30521 R01	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 18-DEC-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30523 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 30-MAY-2016							
SB PW500-72-30534 R04	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 29-JUN-2018							
SB PW500-72-30535 R01	NO. 1 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 29-SEP-2017							
SB PW500-72-30539 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL SUPPLY PAD, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 01-OCT-2019							
SB PW500-72-30541 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC		-				
Eff. Date: 12-JUN-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30542	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC	-					
Eff. Date: 25-APR-2018							
SB PW500-72-30546 R01	NO. 1 ENGINE - REPLACEMENT OF HPT AIR SEAL, SERVICE BULLETIN					CATEGORY 9	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC	-					
Eff. Date: 06-NOV-2019							
SB PW500-72-30548 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC	-					
Eff. Date: 21-SEP-2018							
SB PW500-72-30550	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS			17-DEC-2020			
	HRS						
	ENC						
	MSC	-					

2-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due/New Requirement) (FFF)-Effective C/W (FRT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 2 - SB - PW545C PCE-DF0598/30J2934-01							
SB PW500-72-30325 R03	NO. 2 ENGINE - REPLACEMENT OF OIL-PUMP PLAIN SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 30-AUG-2017							
SB PW500-72-30333	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF FAN ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 26-JAN-2010							
SB PW500-72-30354 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY-GEARBOX PLAIN-SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 28-APR-2008							
SB PW500-72-30361	NO. 2 ENGINE - REPLACEMENT OUTER FRONT BYPASS DUCT WITH NEW STUDS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 05-MAY-2008							
SB PW500-72-30362	NO. 2 ENGINE - REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 05-JUN-2008							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

2-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due (New Requirement) (FFF)-Effective C/W (FRT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30371 R02	NO. 2 ENGINE - INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE, SERVICE BULLETIN					CATEGORY 10	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 11-MAR-2014						
SB PW500-72-30373	NO. 2 ENGINE - REPLACEMENT SECONDARY FUEL PRESSURE TUBE AND SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 15-AUG-2008						
SB PW500-72-30376 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 16-JUN-2016						
SB PW500-72-30379 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF BY-PASS DUCTS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 11-SEP-2015						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30380	NO. 2 ENGINE - GEARSHAFT / REPLACEMENT GEARBOX-DRIVE-SHAFT-ACCESSORY, GEARBOX DRIVE GEARSHAFT-ASSEMBLY, GEARBOX DRIVE SPLINE BEVEL, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
	MOS HRS ENC MSC			17-DEC-2020			
Eff. Date: 09-DEC-2008							
SB PW500-72-30384 R01	NO. 2 ENGINE - REPLACEMENT OF AIR/OIL SEPARATOR, SERVICE BULLETIN				CATEGORY 6	Complied With - AT MANUFACTURE	
	MOS HRS ENC MSC		A/R	17-DEC-2020			
Eff. Date: 02-SEP-2011							
SB PW500-72-30385	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN				CATEGORY 6	Complied With - AT MANUFACTURE	
	MOS HRS ENC MSC			17-DEC-2020			
Eff. Date: 27-JAN-2009							
SB PW500-72-30389	NO. 2 ENGINE - REPLACEMENT OF CARBON SEAL, NO. 4 BEARING, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
	MOS HRS ENC MSC			17-DEC-2020			
Eff. Date: 05-MAR-2009							
SB PW500-72-30391	NO. 2 ENGINE - REPLACEMENT INLET PRESSURE OIL TUBE ASSY, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
	MOS HRS ENC			17-DEC-2020			



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 03-MAY-2010							
SB PW500-72-30405 R04	NO. 2 ENGINE - REPLACEMENT OF FUEL NOZZLE MANIFOLD, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 14-MAR-2018							
SB PW500-72-30407 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 30-AUG-2017							
SB PW500-72-30411 R01	NO. 2 ENGINE - REPLACEMENT OF GASKETS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC A/R							
Eff. Date: 22-MAR-2010							
SB PW500-72-30413 R11	NO. 2 ENGINE - INTRODUCTION OF DEEPER SUMP, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 30-NOV-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

2. Insufficient Information, +: Task exists in Inspection Manual (S), Suppressed Requirement (Ex), Excluded Tasks, *: Estimated Due/Now Requirement (EEF), Effective C/W (ERT), Estimated Baseline Time (EBT)



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30420 R06	NO. 2 ENGINE - REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30423 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
Eff. Date: 17-SEP-2012							
SB PW500-72-30426	NO. 2 ENGINE - FAN CASE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
	A/R						
Eff. Date: 08-JUL-2011							
SB PW500-72-30427 R04	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
	-						
Eff. Date: 06-NOV-2018							
SB PW500-72-30428 R06	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
	-						
Eff. Date: 08-FEB-2019							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30429 R06	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 02-AUG-2017						
SB PW500-72-30432 R01	NO. 2 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		A/R				
	Eff. Date: 12-MAY-2011						
SB PW500-72-30434 R05	NO. 2 ENGINE - REPLACEMENT - MODIFICATION OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				17-DEC-2020	CATEGORY 10	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 15-JUL-2015						
SB PW500-72-30436 R04	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 18-APR-2018						
SB PW500-72-30438 R05	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				17-DEC-2020	CATEGORY 10	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 15-JUL-2015						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30440 R06	NO. 2 ENGINE - REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30445	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30446 R02	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30447 R01	NO. 2 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			
SB PW500-72-30449 R02	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC			17-DEC-2020			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 11-SEP-2015							
SB PW500-72-30453 R03	NO. 2 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 11-AUG-2017							
SB PW500-72-30463 R02	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 18-AUG-2016							
SB PW500-72-30465 R02	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 08-JUL-2016							
SB PW500-72-30466 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 12-JUL-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30470 R01	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30474 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30475 R03	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30478 R04	NO. 2 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			
SB PW500-72-30479 R06	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-	17-DEC-2020			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 20-MAY-2016							
SB PW500-72-30480	NO. 2 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 05-DEC-2013							
SB PW500-72-30481	NO. 2 ENGINE - REPLACEMENT OF FUEL SHUT-OFF CABLE, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 06-DEC-2013							
SB PW500-72-30483 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02), SERVICE BULLETIN				17-DEC-2020	CATEGORY 10	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 22-OCT-2014							
SB PW500-72-30485 R02	NO. 2 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC -							
Eff. Date: 14-AUG-2017							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30491 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 27-JUL-2015						
SB PW500-72-30492 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 10-JAN-2017						
SB PW500-72-30495 R01	NO. 2 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE, SERVICE BULLETIN					CATEGORY 10	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 13-OCT-2016						
SB PW500-72-30496 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 01-OCT-2018						
SB PW500-72-30498 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
	Eff. Date: 20-SEP-2017						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30502 R04	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 20-OCT-2016							
SB PW500-72-30504 R03	NO. 2 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 15-JAN-2019							
SB PW500-72-30505 R02	NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN				CATEGORY 3	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 21-MAY-2015							
SB PW500-72-30506 R02	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				
Eff. Date: 11-SEP-2015							
SB PW500-72-30508 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS, SERVICE BULLETIN				CATEGORY 7	Complied With - AT MANUFACTURE	
		MOS		17-DEC-2020			
		HRS					
		ENC					
		MSC	-				

2-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due (New Requirement) (FFF)-Effective C/W (FRT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 06-DEC-2018							
SB PW500-72-30510	NO. 2 ENGINE - REPLACEMENT OF PRIMARY AND SECONDARY FUEL TUBE SUPPORT BRACKET, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 29-JAN-2015							
SB PW500-72-30516 R02	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 22-JUN-2015							
SB PW500-72-30517 R01	NO. 2 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN				17-DEC-2020	CATEGORY 6	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 05-JAN-2016							
SB PW500-72-30521 R01	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
MOS HRS ENC MSC							
Eff. Date: 18-DEC-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL: 1666 As Of: 07-Jan-2026

AIRCRAFT
All Bulletins With Compliance or Due

12-Jan-2026 05:41 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW500-72-30523 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 30-MAY-2016						
SB PW500-72-30534 R04	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 29-JUN-2018						
SB PW500-72-30535 R01	NO. 2 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 29-SEP-2017						
SB PW500-72-30539 R01	NO. 2 ENGINE - REPLACEMENT OF FUEL SUPPLY PAD, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 01-OCT-2019						
SB PW500-72-30541 R01	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN				17-DEC-2020	CATEGORY 7	Complied With - AT MANUFACTURE
	MOS HRS ENC MSC		-				
	Eff. Date: 12-JUN-2018						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: 560XLS+CITATION XLS+ (MSG) Serial: 560XL-6295 RegNo: OK-WND HRS: 2576:12 AFL
1666 As Of: 07-Jan-2026

AIRCRAFT

12-Jan-2026 05:41 AM

2-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due/New Requirement) (FFF)-Effective C/W (FRT)-Estimated Base Time