



GENERAL DETAILS

Aircraft Type: BELL 427	Fuel:	Engine Type: PW207D	
Aircraft Fleet: INFLITE 135	Fuel Burn: 0.00 L/Hr	Engine PN: 3049028-01	
Registration: ZK-HHI	Empty Weight: 1987.00 kgs	Engine SN: BF-0066	
Callsign: HHI	Mauw Weight: 2971.00 kgs	Engine 2 PN: 3049028-01	
Serial No: 56069	Company: INFLITE Ltd	Engine 2 SN: BF-0169	

MAINTENANCE DETAILS DATE OF VALUES: 11/03/2026

Airframe	7508.90 hours			
Engine 1	5652.85 hours	6731.00 PT Cycles	5721.00 CT cycles	273.00 IMP Cycles
Engine 2	5271.60 hours	7136.00 PT Cycles	6467.00 CT Cycles	1172.00 IMP Cycles
RINS	546.00 Landings			



AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 3

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
Airframe Dual Limit	300 Hour / 12 Month Cargo Hook System Inspection	BHT-427-MMS-14	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Dual Limit	300 Hour / 12 Month Cargo Hook System Inspection	BHT-427-MMS-14	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Airframe Inspection	MM 5-17	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Airframe Inspection	MM 5-17	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Rotor Brake Oil Change	MM 12-00-00, Table 12-3	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Rotor Brake Oil Change	MM 12-00-00, Table 12-3	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Hydraulic Oil Change	MM 12-00-00, Table 12-3	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Hydraulic Oil Change	MM 12-00-00, Table 12-3	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Hydraulic Filter Servicing	MM 12-00-00, Table 12-3	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Hydraulic Filter Servicing	MM 12-00-00, Table 12-3	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Main Transmission Oil Filter Replacement	MM 12-00-00, Table 12-3	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Main Transmission Oil Filter Replacement	MM 12-00-00, Table 12-3	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Main Transmission Oil Change	MM 12-00-00, Table 12-3	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Main Transmission Oil Change	MM 12-00-00, Table 12-3	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Airframe Components Inspection	MM 5-37	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Airframe Components Inspection	MM 5-37	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	600 Hour / 12 Month Forward Tail Rotor Drive Shaft Lubrication	MM 12-00-00, Table 12-2	600 Airframe Hours	7411.60	8011.60	502.70 Hours
Airframe Dual Limit	600 Hour / 12 Month Forward Tail Rotor Drive Shaft Lubrication	MM 12-00-00, Table 12-2	12 Months	03/10/2025	03/10/2026	158 Days
Airframe Dual Limit	1200 Hour / 24 Month Airframe Components Inspection	MM 5-38	1200 Airframe Hours	7286.75	8486.75	977.85 Hours
Airframe Dual Limit	1200 Hour / 24 Month Airframe Components Inspection	MM 5-38	24 Months	15/07/2024	15/07/2026	78 Days



AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 4

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
AIRFRAME INSPECTIONS- HOURS						
Airframe Hour	25 Hour Component Inspection - Tail Rotor Drive Shaft	MM Chapter 5-32	25 Airframe Hours	0.00	0.00	0.00 Hours
Airframe Hour	50 Hour Main Rotor Blade Leading Edge Crack Conditional Inspection	MM 67-7, 2(a)	50 Airframe Hours	7499.80	7549.80	40.90 Hours
Limitation Note: ORANGE (A-488), RED (A-592)						
Airframe Hour	50 Hour Main Rotor Yoke Assembly Inspection	MM 04-00-00, Table 4-2	50 Airframe Hours	7499.80	7549.80	40.90 Hours
Airframe Hour	100 Hour Vertical Fin Assembly Inspection (Applicable from 1500 Hours TTIS)	MM 04-00-00, Table 4-2	100 Airframe Hours	7411.60	7521.6	12.70 Hours
Airframe Hour	150 Hour Longeron - Upper Aft LH Fuselage Inspection	MM 04-00-00, Table 4-2	150 Airframe Hours	7411.60	7561.60	52.70 Hours
Airframe Hour	150 Hour Intercostal Inspection	MM 04-00-00, Table 4-2	150 Airframe Hours	7411.60	7561.60	52.70 Hours
Airframe Hour	150 Hour Tailboom Horizontal Stabilizer Cutout Inspection	MM 04-00-00, Table 4-2	150 Airframe Hours	7411.60	7561.60	52.70 Hours
Airframe Hour	300 Hour Airframe Inspection	MM 5-16A	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Tailboom Assembly Inspection	MM 04-00-00, Table 4-2	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Main Rotor Blades Inspection	MM 04-00-00, Table 4-2	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Rotor Brake System Inspection	MM 5-41	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Airframe Components Inspection	MM 5-34	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Oil Cooler Blower Hangar Bearings Lubrication	MM 12-00-00, Table 12-2	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Hydraulic Pump Drive Adapter Lubrication	MM 12-00-00, Table 12-2	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Airframe Hour	300 Hour Segmented T/R Driveshaft Hangar Bearings Lubrication	MM 12-00-00, Table 12-2	300 Airframe Hours	7411.60	7711.60	202.70 Hours

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 5

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
Airframe Hour	600 Hour Airframe Components Inspection	MM 5-36	600 Airframe Hours	0.00	7577.4	68.50 Hours
Airframe Hour	1200 Hour IIDS Cooling Fan Inspection	BHT-427-MMS-22	1200 Airframe Hours	0.00	8117.40	608.50 Hours
Airframe Hour	5000 Hour IIDS Cooling Fans Bearing Replacement	BHT-427-MMS-22	5000 Airframe Hours	0.00	11917.40	4408.50 Hours
AIRFRAME INSPECTIONS - CALENDAR		Reference	Period	Last Done	Next Due	Remaining
Airframe Calendar	3 Month LIVE Mount Service	TB 427-09-27	3 Months	16/12/2025	16/03/2026	-43 Days
Airframe Calendar	24 Month Main Rotor Mast Inspection	MM 5-39	24 Months	03/10/2025	03/10/2027	523 Days
Airframe Calendar	24 Month Airframe Components Inspection	MM 5-39	24 Months	03/10/2025	03/10/2027	523 Days
ENGINE 1 INSPECTIONS		Reference	Period	Last Done	Next Due	Remaining
Engine Calendar	Engine #1 - 50 Hour / Weekly LCF Consistency Check (optional)	PW200-72-A28252 Rev 3	7 Days	00/00/0000	00/00/0000	0 Day
Engine Calendar	Engine #1 - 50 Hour / Weekly LCF Consistency Check (optional)	PW200-72-A28252 Rev 3	50 Airframe Hours	0.00	0.00	0.00 Hours
Engine Calendar	Engine #1 - 12 Month Inspection	PW MM 05-20-00	12 Months	03/10/2025	03/10/2026	158 Days
Engine Hour	Engine #1 - 150 Hour Engine Power Check	PW MM 05-20-00	150 Airframe Hours	7411.60	7561.60	52.70 Hours
Engine Hour	Engine #1 -200 Hour Engine Inspection	PW MM 05-20-00	200 Airframe Hours	7411.60	7611.60	102.70 Hours
Engine Hour	Engine #1 - 800 Hour Inspection	PW MM 05-20-00	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	Engine #1 - 800 Hour Engine Oil and Fuel Filter Replacement	MM 12-00-00, Table 12-1 and 12-3	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	Engine #1 - 800 Hour Compressor Air Inlet Screen Inspection	PW MM 05-20-00	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	3000 Hour Engine Oil Replacement	MM Table 12-3	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	Engine #1 - 900 Hour Fuel Nozzles Clean and Functional Check	PW MM 05-20-00	900 Airframe Hours	0.00	7851.85	342.95 Hours

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 6

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
ENGINE 2 INSPECTIONS		Reference	Period	Last Done	Next Due	Remaining
Engine Calendar	Engine #2 - 50 Hour / Weekly LCF Consistency Check (optional)	PW200-72-A28252 Rev 3	7 Days	00/00/0000	00/00/0000	0 Day
Engine Calendar	Engine #2 - 50 Hour / Weekly LCF Consistency Check (optional)	PW200-72-A28252 Rev 3	50 Airframe Hours	0.00	0.00	0.00 Hours
Engine Calendar	Engine #2 - 12 Month Inspection	PW MM 05-20-00	12 Months	03/10/2025	03/10/2026	158 Days
Engine Hour	Engine #2 - 150 Hour Engine Power Check	PW MM 05-20-00	150 Airframe Hours	7411.60	7561.60	52.70 Hours
Engine Hour	Engine #2 - 200 Hour Engine Inspeccion	PW MM 05-20-00	200 Airframe Hours	7411.60	7611.60	102.70 Hours
Engine Hour	Engine #2 - 800 Hour Inspection	PW MM 05-20-00	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	Engine #2 - 800 Hour Engine Oil and fuel Filter Replacement	MM 12-00-00, Table 12-1 and 12-3	800 Engine2 Hours	0.00	7944.85	2673.25 Hours
Engine Hour	Engine #2 - 800 Hour Compressor Air Inlet Screen Inspection	PW MM 05-20-00	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	3000 Hour Engine Oil Replacement	MM Table 12-3	800 Airframe Hours	0.00	7944.85	435.95 Hours
Engine Hour	Engine #2 - 900 Hour Fuel Nozzles Clean and Functional Check	PW MM 05-20-00	900 Airframe Hours	0.00	8044.85	535.95 Hours
OUT OF PHASE INSPECTIONS		Reference	Period	Last Done	Next Due	Remaining
Part 91	Annual Review of Airworthiness	NZCAA Rule Part 43.153 (a)	12 Months	14/03/2025	14/03/2026	-45 Days
Part 91	12 Month First Aid Kit Inspection	AC43-6	12 Months	03/10/2025	03/10/2026	158 Days
Part 91	12 Month Fire Extinguisher Reweigh	AC43-6	12 Months	03/10/2025	03/10/2026	158 Days
Part 91	12 Month Axe Inspection	AC43-6	12 Months	03/10/2025	03/10/2026	158 Days
Part 91	10 Year Aircraft Reweigh	CAR Part 91	120 Months	00/00/0000	21/01/2029	999 Days
AVIONICS INSPECTIONS		Reference	Period	Last Done	Next Due	Remaining
Part 91	100 Hour / 12 Month ELT Inspection	CAR Part 43 App F	100 Airframe Hours	7411.60	7521.6	12.70 Hours
Part 91	100 Hour / 12 Month ELT Inspection	CAR Part 43 App F	12 Months	03/10/2025	03/10/2026	158 Days

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 7

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
Airframe Calendar	24 Month Compass Swing	NZCAA Rule Part 91	24 Months	03/10/2025	03/10/2027	523 Days
Airframe Calendar	24 Month Altimeter Inspection	NZCAA Rule Part 43, Appendix D	24 Months	03/10/2025	03/10/2027	523 Days
Airframe Calendar	24 Month Transponder Inspection	NZCAA Rule Part 43, Appendix E	24 Months	03/10/2025	03/10/2027	523 Days
Airframe Calendar	24 Month Radio Inspection	NZCAA Rule Part 43, Appendix B	24 Months	03/10/2025	03/10/2027	523 Days
Airframe Hour	24 Month Software Review (VFR)	OMM 3.1.5	24 Months	03/10/2025	03/10/2027	523 Days
POST MAINTENANCE INSPECTIONS		Reference	Period	Last Done	Next Due	Remaining
	1 to 5 Hour Tailboom Attachment Hardware Torque Check	BHT-427-MM, Table 5-3	5 Airframe Hours	0.00	0.00	0.00 Hours
	1 to 5 Hour Tail Rotor Hub Mast Nut Torque Check	BHT-427-MM, Table 5-3	5 Airframe Hours	7415.40	0.00	0.00 Hours
	1 to 5 Hour Main Rotor Hub Lower Cone Bolt Torque Check	BHT-427-MM, Table 5-3	5 Airframe Hours	0.00	0.00	0.00 Hours
	1 to 5 Hour Main Rotor Hub Through Bolt Torque Check	BHT-427-MM, Table 5-3	5 Airframe Hours	0.00	0.00	0.00 Hours
	1 to 5 Hour Main Rotor Hub Mast Nut Torque Check	BHT-427-MM, Table 5-3	5 Airframe Hours	7415.40	0.00	0.00 Hours
	1 to 5 Hour Vertical Fin Attachment Hardware Torque Check	BHT-427-MM, Table 5-3	5 Airframe Hours	7415.40	0.00	0.00 Hours
	10 to 25 Hour Tail Rotor Gearbox Torque Check	BHT-427-MM, Table 5-3	25 Airframe Hours	7437.50	0.00	0.00 Hours
	10 to 25 Hour Swashplate Tilt Friction	BHT-427-MM, Table 5-3	25 Airframe Hours	0.00	0.00	0.00 Hours

Components

Part No.	Description	Serial No.	Life At Install	Period	Last Done	Next Due	Remaining
427-015-001-135	Main Rotor Blade	A-488	0.00	On Condition	N/A	On Condition	N/A
427-015-001-135	Main Rotor Blade	A-429	0.00	On Condition	N/A	On Condition	N/A
427-015-001-135	Main Rotor Blade	A-462	0.00	On Condition	N/A	On Condition	N/A

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 8

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining		
427-015-001-135	Main Rotor Blade	A-592	0.00	On Condition	N/A	On Condition	N/A
427-010-100-103 (OH)	Main Rotor Hub Assembly Overhaul	LK4	180.60	2500 Airframe Hours	6790.40	9109.80	1600.90 Hours OH
406-010-108-135 (LL)	Main Rotor Grip	T11670	0.00	1500 Airframe Hours	6609.80	8109.80	600.90 Hours LL
406-010-108-135 (LL)	Main Rotor Grip	T11660	0.00	1500 Airframe Hours	6609.80	8109.80	600.90 Hours LL
406-010-108-135 (LL)	Main Rotor Grip	T11663	0.00	1500 Airframe Hours	6609.80	8109.80	600.90 Hours LL
406-010-108-135 (LL)	Main Rotor Grip	T11667	0.00	1500 Airframe Hours	6609.80	8109.80	600.90 Hours LL
406-010-115-131 (LL)	Upper Plate Assembly	RE1176	0.00	2500 Airframe Hours	6609.80	9109.80	1600.90 Hours LL
406-010-117-129 (LL)	Lower Plate Assembly	AZ1611	0.00	2500 Airframe Hours	6609.80	9109.80	1600.90 Hours LL
406-010-120-113 (LL)	Main Rotor Blade Bolt	A12956	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
406-010-120-113 (LL)	Main Rotor Blade Bolt	A13024	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
406-010-120-113 (LL)	Main Rotor Blade Bolt	A12878	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
406-010-120-113 (LL)	Main Rotor Blade Bolt	ZZ1560	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL



Maintenance Tracking Report

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 9

Maintenance Required	Reference		Period	Last Done	Next Due	Remaining
406-010-120-113 (LL) Main Rotor Blade Bolt	A13023	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
406-010-120-113 (LL) Main Rotor Blade Bolt	ZZ1562	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
406-010-120-113 (LL) Main Rotor Blade Bolt	A12954	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
406-010-120-113 (LL) Main Rotor Blade Bolt	A13040	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
407-010-103-115 (LL) Pitch Horn	RE124	0.00	2500 Airframe Hours	6609.80	9109.80	1600.90 Hours LL
407-010-103-115 (LL) Pitch Horn	RE153	0.00	2500 Airframe Hours	6609.80	9109.80	1600.90 Hours LL
407-010-103-115 (LL) Pitch Horn	RE149	0.00	2500 Airframe Hours	6609.80	9109.80	1600.90 Hours LL
407-010-103-115 (LL) Pitch Horn	RE111	0.00	2500 Airframe Hours	6609.80	9109.80	1600.90 Hours LL
407-310-101-107 (LL) Shear Bearing	LK17131	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
407-310-101-107 (LL) Shear Bearing	LK17146	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
407-310-101-107 (LL) Shear Bearing	LK17106	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL
407-310-101-107 (LL) Shear Bearing	LK17094	0.00	10000 Airframe Hours	6609.80	16609.80	9100.90 Hours LL



AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 10

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
427-010-103-109 (LL) Lower Cone Seat	TI11	5000 Airframe Hours	4644.60	9644.60	2135.70 Hours LL
427-010-105-107 (OH) Drive Ring Set	TI15	5000 Airframe Hours	4111.10	9111.10	1602.20 Hours OH
406-010-413-143 (LL) Tube Assembly	US1186	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-413-143 (LL) Tube Assembly	US1229	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-413-143 (LL) Tube Assembly	US1217	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-413-143 (LL) Tube Assembly	US1220	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-416-101 (LL) Clevis	SUFS1183	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-416-101 (LL) Clevis	SUFS1364	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-416-101 (LL) Clevis	SUFS1196	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-010-416-101 (LL) Clevis	SUFS1354	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-310-404-101 (LL) Rod End Assembly	NH18870	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-310-404-101 (LL) Rod End Assembly	NH18999	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 11

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
406-310-404-101 (LL)	Rod End Assembly NH18910	0.00 5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
406-310-404-101 (LL)	Rod End Assembly NH18985	0.00 5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
427-040-011-101 (OH)	Transmission Mast Assembly Overhaul 56044	0.00 3000 Airframe Hours	5919.80	8919.80	1410.90 Hours OH
427-040-040-101S (LL)	Main Rotor Mast BP00102	0.00 5000 Airframe Hours	5919.80	10919.80	3410.90 Hours LL
427-010-401-101 (OH)	Swashplate and support Assembly Overhaul TI10	0.00 2500 Airframe Hours	6185.00	8685.00	1176.10 Hours OH
206-010-408-103 (LL)	Collective Lever Pin TI102	0.00 5000 Airframe Hours	6185.00	11185.00	3676.10 Hours LL
206-010-408-103 (LL)	Collective Lever Pin TI105	0.00 5000 Airframe Hours	6185.00	11185.00	3676.10 Hours LL
427-010-407-101 (LL)	Collective Lever 42	0.00 10000 Airframe Hours	6185.00	16185.00	8676.10 Hours LL
427-010-403-101 (LL)	Swashplate Sleeve TI38	2487.10 10000 Airframe Hours	6185.00	13697.90	6189.00 Hours LL
427-010-405-101 (LL)	Swashplate Support TI35	2487.10 10000 Airframe Hours	6185.00	13697.90	6189.00 Hours LL
406-010-417-109 (LL)	Bearing and Liner Assembly Swashplate RE828	1300.20 5000 Airframe Hours	6185.00	9884.80	2375.90 Hours LL
406-010-417-109 (LL)	Bearing and Liner Assembly Swashplate A2418	1300.20 5000 Airframe Hours	6185.00	9884.80	2375.90 Hours LL

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 12

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
406-010-419-117 (LL) Cap Assembly Swashplate	RD5050	2500 Airframe Hours	6185.00	8685.00	1176.10 Hours LL
406-010-410-125 (LL) Inner Ring Swashplate	TI637	5000 Airframe Hours	6185.00	8697.90	1189.00 Hours LL
427-010-410-101 (LL) Drive Link Swashplate	TI281	5000 Airframe Hours	6330.40	11330.40	3821.50 Hours LL
427-010-410-101 (LL) Drive Link Swashplate	TI265	5000 Airframe Hours	6330.40	11330.40	3821.50 Hours LL
427-010-408-101 (LL) Drive Lever Swashplate	RE31	5000 Airframe Hours	6330.40	11330.40	3821.50 Hours LL
427-010-408-101 (LL) Drive Lever Swashplate	RE28	5000 Airframe Hours	6330.40	11330.40	3821.50 Hours LL
427-010-418-105 (LL) Anti-Drive Lever Swashplate	030309	10000 Airframe Hours	6185.00	10045.60	2536.70 Hours LL
406-010-432-101 (LL) Anti-Drive Link Swashplate	TIFS486	5000 Airframe Hours	6185.00	8749.90	1241.00 Hours LL
427-040-006-113 (OH) Transmission Assembly Overhaul	A90	5000 Airframe Hours	3944.00	8944.00	1435.10 Hours OH
427-010-201-108 (LL) Pylon Beam Assembly [Position: Right]	TI244	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
427-010-201-107 (LL) Pylon Beam Assembly [Position: Left]	TI243	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
427-340-350-101 (OH) Brake Disc Overhaul	109	5000 Airframe Hours	5731.90	10731.90	3223.00 Hours OH



AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 13

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
427-340-352-105 (OH) Rotor Brake Caliper Overhaul	085	5000 Airframe Hours	3635.30	8635.30	1126.40 Hours OH
427-340-352-106 (OH) Rotor Brake Caliper Overhaul	074	5000 Airframe Hours	2872.50	7872.50	363.60 Hours OH
407-001-025-125 (LL) Upper Collective Tube	US2045	10000 Airframe Hours	6330.40	16330.40	8821.50 Hours LL
407-001-022-149 (LL) Lower Collective Tube	US486	10000 Airframe Hours	0.00	10000.00	2491.10 Hours LL
427-001-502-101 (LL) Actuator Support	HR119	5000 Airframe Hours	4979.60	9979.60	2470.70 Hours LL
427-001-512-101 (LL) Bellcrank Support	TI99	10000 Airframe Hours	0.00	10000.00	2491.10 Hours LL
427-001-522-101 (LL) Collective Bellcrank	TI83	10000 Airframe Hours	0.00	10000.00	2491.10 LL
427-001-535-101 (LL) Idler Link	TI184	5000 Airframe Hours	6429.70	11429.70	3920.80 Hours LL
427-001-535-101 (LL) Idler Link	TI176	5000 Airframe Hours	6429.70	11429.70	3920.80 Hours LL
427-010-204-101 (LL) Pitch Restraint Spring [Position: Left]	LK0285	10000 Airframe Hours	5139.50	15139.50	7630.60 Hours LL
427-010-204-101 (LL) Pitch Restraint Spring	LK0287	10000 Airframe Hours	5139.50	15139.50	7630.60 Hours LL
427-010-207-101 (LL) Stop Fitting Assembly [Position: Left]	RE163	2500 Airframe Hours	7286.75	9194.65	1685.75 Hours LL

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 14

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
427-010-209-101 (LL) Stop Fitting Assembly [Position: Right]	RE209	1500 Airframe Hours	7286.75	7954.35	445.45 Hours LL
206-340-300-105 (OH) Input Driveshaft Overhaul	KC1839	2500 Airframe Hours	6330.40	8830.40	1321.50 Hours OH
206-340-300-105 (OH) Input Driveshaft Overhaul	KC1779	2500 Airframe Hours	6330.40	8830.40	1321.50 Hours OH
427-042-400-105 (OH) Tail Rotor Gearbox Overhaul	A-136	2500 Airframe Hours	7411.60	8626.20	1117.30 OH
407-012-101-109 (OH) Tail Rotor Hub Assembly Overhaul	HB198	2500 Airframe Hours	6315.30	8815.30	1306.40 Hours OH
427-016-001-109 (LL) Tail Rotor Blade	A267	5000 Airframe Hours	6330.40	8794.10	1285.20 Hours LL
427-016-001-109 (LL) Tail Rotor Blade	A265	5000 Airframe Hours	6330.40	8794.10	1285.20 Hours LL
406-012-102-109 (LL) Tail Rotor Yoke	HBFS2096	5000 Airframe Hours	7099.95	12099.95	4591.05 Hours LL
30600-12 (LH) (LL) Cartridge Fire Ext (J1 Port)	01288	10 Years	03/10/2025	30/09/2033	2712 Days LL
30600-12 (RH) (LL) Cartridge Fire Ext (J1 Port)	01302	10 Years	03/10/2025	30/09/2033	2712 Days LL
30600-13 (LH) (LL) Cartridge Fire Ext (J2 Port)	01233	10 Years	03/10/2025	28/02/2035	3228 Days LL
30600-13 (RH) (LL) Cartridge Fire Ext (J2 Port)	01231	10 Years	03/10/2025	28/02/2035	3228 Days LL
23081 -018 (OH) Starter Generator Overhaul	4087	1000 Airframe Hours	7135.75	8135.75	626.85 Hours OH
23081-018 (OH) Starter Generator Overhaul	P1060	1000 Airframe Hours	6660.70	7660.70	151.80 Hours OH

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 15

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
427-536-001-129 (LL) Aft Cross Tube	A26	10000 Landings	12193.00	112193.00	111647.00 RINS LL
427-536-001-125 (LL) Forward Cross Tube	AT85	30000 Landings	34759.00	64759.00	64213.00 RINS LL
528-010-04 (OH) Cargo Hook		0	-	-	- OH
51500-103 (OH) #1 Fire Extinguisher Reservoir	0133	5 Years	27/01/2024	05/06/2026	38 Days OH
51500-105 (OH) #2 Fire Extinguisher Reservoir	*0003	5 Years	31/08/2025	31/08/2030	1586 Days OH
3049028-01 PW207D Engine [Position: Left]	BF-0066	On Condition	N/A	On Condition	N/A
8063-1034 (OH) Fuel Management Module	12161235	4000 Engine1 Hours	3526.20	7526.20	1873.35 Hours OH
3049281-01 (OH) Reduction Gearbox Module [Position: Left]	RGB-BF0066	3500 Engine1 Hours	3526.20	7026.20	1373.35 Hours OH
3049027-01 (OH) Turbomachinery Module Overhaul [Position: Left]	TM-BF0066	3500 Engine1 Hours	3526.20	7026.20	1373.35 Hours OH
3074666-01 (LL) Impeller	A003KT0T	15000 Engine1 IMP Cycles	0.00	15000.00	14727.00 Cycles LL
3048999-01 (LL) Compressor Disc	A000DAK5	10000 Engine1 CT Cycles	5318.00	10000.00	4279.00 Cycles LL
3044188-01 (LL) Turbine Disc	A000E08H	15000 Engine1 PT Cycles	6152.00	15000.00	8269.00 Cycles LL
3049028-01 PW207D Engine [Position: Right]	BF-0169	On Condition	N/A	On Condition	N/A
3049027-01 (OH) Turbomachinery Module Overhaul [Position: Right]	TM-BF0169	4000 Engine2 Hours	4681.10	7944.00	2672.40 Hours OH

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 16

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
3074666-01 (LL) Impeller	A00390H4	15000 Engine2 IMP Cycles	749.00	15000.00	13828.00 Cycles LL
3048999-01 (LL) Compressor Disc	A002BC85	10000 Engine2 CT Cycles	5860.00	10000.00	3533.00 Cycles LL
3044188-01 (LL) Turbine Disc	A002ABW8	15000 Engine2 PT Cycles	6193.00	15000.00	7864.00 Cycles LL
3049281-01 (OH) Reduction Gearbox Module [Position: Right]	RGB-BF0169	4000 Engine2 Hours	737.10	7944.00	2672.40 Hours OH
8063-851 (OH) Fuel Management Module	15498639	4500 Engine2 Hours	737.10	8444.00	3172.40 Hours OH
S1840510-01 (LL) ELT Battery	HHI	7 Years	305.00	30/01/2025	31/03/2031 1798 Days LL

MODIFICATION:

Type	Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
Modifications	25 Hour Air Comm Air Conditioning	SR00418DE (ICA 427EC-200M-1)	25 Airframe Hours	7499.80	7524.80	15.90 Hours
Modifications	6 Month Concorde Lead Acid Battery	SR01456LA (CMM 24-30-71)	6 Months	03/10/2025	03/04/2026	-25 Days
Modifications	12 Month GTR225 VHF, GTX335 Transponder, Aera 660 GPS	5R-13066 (P1609-ICA-R0)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month PMA8000G Audio Panel	5R-12954 (OMM 3.1.6)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Kannard Intergra 406 ELT	P1585-MB-R0 (OMM 3.1.6)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Garmin GNC 420W VHF COMMGPS	SA00801WI (OMM 3.1.6)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Whelen LED Anicol and Position Lights	AC43.42-2B (OMM 3.1.6,	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Davtron M811B Clock	AC43.13-2B (OMM 3.1.6)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Technisonic TDFM-615 FM Radio	TIL OIRE293 (OMM 3.1.6)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Precise Flight Pulselite	SH3319NM (OOPMAN0002)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Baggage Honeycomb Floor Replacement	SR09359RC (AA-03040)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Replacement Passenger Windows	SR02072AT (AA-9812)	12 Months	03/10/2025	03/10/2026	158 Days



AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 17

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
Modifications	12 Month Baggage Floor Protector Kit	SR02070AT (AA-06126)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Avidyne TAS605 TAS	CE-56078-AV4, SA1763GL (OMM 3.1.6)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Cyclic Safety Cover	SR02077AT (AA-95097)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Air Comm Cabin Heater	SR00419DE (ICA 427H-201M-1)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	12 Month Tail Rotor Pedal Lockout Kit	SR02205AT (AA-00053)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	100 Hour / 12 Month Air Comm Air Conditioning	SR00418DE (ICA 427EC-200M-1)	100 Airframe Hours	7411.60	7521.6	12.70 Hours
Modifications	100 Hour / 12 Month Air Comm Air Conditioning	SR00418DE (ICA 427EC-200M-1)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	150 Hour / 12 Month Wire Strike Protection Kit	SR01266NY (PM-965-033A)	150 Airframe Hours	7411.60	7561.60	52.70 Hours
Modifications	150 Hour / 12 Month Wire Strike Protection Kit	SR01266NY (PM-965-033A)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	300 Hour / 12 Month Float Flight Steps	SR02196AT (AA-99048)	300 Airframe Hours	7411.60	7711.60	202.70 Hours
Modifications	300 Hour / 12 Month Float Flight Steps	SR02196AT (AA-99048)	12 Months	03/10/2025	03/10/2026	158 Days
Modifications	1200 Hour / 24 Month Garmin GTR225 Radio	5R-13066 (P1609-ICA-R0)	1200 Airframe Hours	7411.60	8611.60	1102.70 Hours
Modifications	1200 Hour / 24 Month Garmin GTR225 Radio	5R-13066 (P1609-ICA-R0)	24 Months	03/10/2025	03/10/2027	523 Days
Modifications	2000 Hour / 10 Year Garmin GTX 335 ADS-B Transponder	5R-13066 (P1609-ICA-R0)	2000 Airframe Hours	0.00	9112.15	1603.25 Hours
Modifications	2000 Hour / 10 Year Garmin GTX 335 ADS-B Transponder	5R-13066 (P1609-ICA-R0)	10 Years	00/00/0000	25/03/2032	2158 Days

ADs

Types	Subject	AD Number	Based On	Period	Warning	Last Done	Next Due	Remaining
Repetitive ADs	150 Hour Vertical Fin Re-torque	CF-2007-22R1 (ASB 427-06-15 Rev A Part II)	Airframe Hours	150	30 Hours	7411.60	7561.60	52.70
Repetitive ADs	100 Hour Vertical Fin Inspection - Applicable from 1500 Hours TTIS	CF-2017-03 (ASB 427-15-38, Rev A)	Airframe Hours	1500	30 Hours	7286.75	8786.75	1277.85
Types	Subject	AD Number	Based On	Period	Warning	Last Done	Next Due	Remaining/Status

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 18

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining	
Standard ADs	Kannard 406 AF-Compact ELT Modification	EASA 2026-0044	Date (Months) -	1 Months	-	18/05/2026	Not Applicable
Limitation Note: Identify the Kannard ELT Dongle P/N as Per Safran Electronics & Defense Beacons SB S1840501-25-01							
Standard ADs	Kannard 406 AF-Compact ELT Modification	EASA 2026-0044	Date (Months) -	3 Months	-	18/03/2027	Not Applicable
Standard ADs	Replace TX Oil Check Valve	CF2024-42	Date (Months) -	2 Months	-	-	Complied With
Standard ADs	EASA AD 2021-0185R2 - Hand operated fire extinguishers-inspection	EASA AD 2021-0185R2	-	45 Days	-	-	Not Applicable
Standard ADs	FAA AD 2022-05-10 - Goodrich Hoist Inspection	FAA AD 2022-05-10	Airframe Hours -	45 Hours	-	-	Not Applicable
Standard ADs	UK CAA AD G2022-0011 - Pilot and co-pilot seats-inspection	UK CAA AD G2022-0011	-	0	-	-	Not Applicable

SBs

Types	Subject	SB Number	Based On	Period	Warning	Last Done	Next Due	Remaining
Repetitive SBs	300 Hour / 12 Month M/R PCL Inspection	ASB 427-21-45	Airframe Hours	300	30 Hours	7286.75	7586.75	77.85
Repetitive SBs	300 Hour / 12 Month M/R PCL Inspection	ASB 427-21-45	Date (Months)	12	1 Months	03/10/2025	03/10/2026	158
Repetitive SBs	300 Hour Tail Rotor Blade Inspection	ASB 427-10-32	Airframe Hours	300	30 Hours	7411.60	7711.60	202.70
Repetitive SBs	1200 Hour / 24 Month Cyclic Stick Inpection Part 1 and 4	ASB 427-23-46	Airframe Hours	1200	80 Hours	0.00	8352.65	843.75
Repetitive SBs	1200 Hour / 24 Month Cyclic Stick Inpection Part 1 and 4	ASB 427-23-46	Date (Months)	24	3 Months	27/03/2025	27/03/2027	333
Types	Subject	SB Number	Based On	Period	Warning	Last Done	Next Due	Remaining/Status
Standard SBs	ASB 427-26-50 - Drive System Component Bearings	ASB 427-26-50	Airframe Hours	-	500 Hours	3944.00	8944.00	1435.10/Required
Limitation Note: PN 427-040-006-ALL Transmission Assembly								
Standard SBs	ASB 427-26-50 - Drive System Component Bearings	ASB 427-26-50	Airframe Hours	-	250 Hours	7411.60	8626.20	1117.30/Required
Limitation Note: PN 427-042-400-105 T/R Gearbox Assembly Compliance: At next scheduled overhaul of affected components								

AIRCRAFT REGISTRATION: ZK-HHI

DATE: 11/03/2026

PAGE NO: 19

Maintenance Required		Reference			Period	Last Done	Next Due	Remaining
Standard SBs	ASB 427-21-45 - MR Pitch Link Assembly	ASB 427-21-45	Airframe Hours	-	0 Hours	-	-	Complied With
Standard SBs	ASB 427-21-44 - Transmission Oil Check Valve	ASB 427-21-44	Airframe Hours	-	45 Days	-	-	Complied With
Standard SBs	ASB 427-23-46 - Pilot cyclic stick assy inspection	ASB 427-23-46	Airframe Hours	-	45 Hours	-	-	Complied With