

Total projection:

Company

Owner: JetBee Czech s.r.o.
Operator:

Major Assemblies

Airframe	Hawker 4000	RC-57	28-Apr-2026	3634:10 Hrs	1,931 Ldg	Hrs(APU)		
Eng 1	PW308A	PCE-CE0139	28-Apr-2026	3336:58 Hrs	1,988 Enc	2,121.16 ATC1	2,047.64 ATC3	
Eng 2	PW308A	PCE-CE0140	28-Apr-2026	3336:58 Hrs	1,988 Enc	2,121.16 ATC1	2,047.64 ATC3	
APU 1	GTCP36-150[HH]	P-163	15-Apr-2026	Hrs	APUS			

Additional Information

Program Type: Standard

Cost:
Man Hrs:

Analyst: Derick Naude dnaude2@jetsupport.com

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	Component Condition						DUE	Remaining	
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
210001		Air Conditioning - Ozone Converter - Replacement						RE	5-10, AWL, Replacement	≈24-Jan-2031
	21 A/F	Left			Mos					
	5848673-1				Hrs	3540:40	1,800	5340:40	95%	
	0091/0098				Ldg	1,869				
	Ref.:ALM04-00-00, Ref.:AMM21-70-01 (UPDATE NOTE: Converter replaced)									
210001		Air Conditioning - Ozone Converter - Replacement						RE	5-10, AWL, Replacement	≈24-Jan-2031
	21 A/F	Right			Mos					
	5848673-1				Hrs	3540:40	1,800	5340:40	95%	
	0087/0094				Ldg	1,869				
	Ref.:ALM04-00-00, Ref.:AMM21-70-01 (UPDATE NOTE: Converter replaced)									
▼ 24 - ELECTRICAL POWER										
240009		Electrical Power - Power Distribution Assembly - Cleaning						RE	5-10, Replacement	≈11-Dec-2030
	24 A/F	No.3			Mos					
	1706187G				Hrs	3498:50	1,800	5298:50	92%	
	0107				Ldg	1,848				
	Ref.:AMM24-30-01									
240009		Electrical Power - Power Distribution Assembly - Cleaning						RE	5-10, Replacement	≈13-Jul-2030
	24 A/F	No.4			Mos					
	1706188G				Hrs	3350:30	1,800	5150:30	84%	
	0108				Ldg	1,792				
	Ref.:AMM24-30-01									
▼ 25 - EQUIPMENT/FURNISHINGS										
25-00-00-Custom		Infant Kit with Life Vest and Seat Belt (in bag in compartment behind lavatory)						RE (O/C)		
	25 A/F				Mos				[24-Feb-2029]	??%
	Unknown				Hrs	3633:30				
	Unknown				Ldg	1,930				
250001-0219		Life Vest						RE (Due)		
	25 A/F	Infant			Mos				[24-Feb-2029]	??%
	P0640-101	New			Hrs	3633:30				
	22080510087				Ldg	1,930				
	Expiration Date 30-Jun-2026									
250002		Equipment/Furnishings - Cockpit Voice Recorder Underwater Locating Device Battery (P/N 810-2007/K, 810-2008/K)-Replacement						RE	5-10, AWL, Replacement	
	25 A/F				Yrs			6	[31-Dec-2031]	94%
	18717-00				Hrs	3633:30				
	BL106568				Ldg	1,930				
	Manufactured Date 02-Dec-2025									
	Ref.:AMM25-60-10, Ref.:ALM04-00-00									

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
250002	Equipment/Furnishings - Flight Data Recorder Underwater Locating Device Battery (P/N 810-2007/K, 810-2008/K)-Replacement					RE		5-10, AWL, Replacement	
25 A/F					Yrs	23-Jan-2026	6	[31-Dec-2030]	77%
18717-00					Hrs	3633:30			
BL105749					Ldg	1,930			
Manufactured Date 12-Dec-2024									
Ref:ALM04-00-00, Ref:AMM25-60-10									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Copilot				Mos	23-Jan-2026		[10-Apr-2030]	??%
63600-501					Hrs	3633:30			
L6106142					Ldg	1,930			
08-Sep-2016									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Divan - Aft				Mos	23-Jan-2026		[30-Mar-2034]	??%
63600-105					Hrs	3633:30			
N/A					Ldg	1,930			
11-Jun-2018									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Divan - Fwd				Mos	26-Jan-2026		[31-Jan-2033]	??%
63600-105					Hrs	3633:30			
N/A					Ldg	1,930			
12-Jun-2019									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Divan - Mid				Mos	23-Jan-2026		[31-Jan-2033]	??%
63600-105					Hrs	3633:30			
N/A					Ldg	1,930			
12-Jun-2019									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Lavatory				Mos	23-Jan-2026		[31-Aug-2031]	??%
63600-105					Hrs	3633:30			
N/A					Ldg	1,930			
14-Apr-2021									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Left No.1				Mos	23-Jan-2026		[30-Mar-2034]	??%
63600-105					Hrs	3633:30			
L6034454					Ldg	1,930			
14-Apr-2021									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Left No.2				Mos	23-Jan-2026		[30-Apr-2034]	??%
63600-105					Hrs	3633:30			
L6167841					Ldg	1,930			
14-Apr-2021									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement					RE (N/A)		5-10, AWL, Replacement	
25 A/F	Pilot				Mos	23-Jan-2026		[10-Apr-2030]	??%
63600-501					Hrs	3633:30			
L6106141					Ldg	1,930			
08-Sep-2016									
CALM Task:259006, Ref:ALM04-00-00, Ref:SDS25-60-00									

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
250003	Equipment/Furnishings - Life Vest - Replacement							RE (N/A)	5-10, AWL, Replacement
25 A/F	Right No.1							[30-Apr-2034]	??%
63600-105									
L6167840									
14-Apr-2021									
CALM Task:259006, Ref.:ALM04-00-00, Ref.:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement							RE (N/A)	5-10, AWL, Replacement
25 A/F	Right No.2							[30-Apr-2034]	??%
63600-105									
L6167837									
14-Apr-2021									
CALM Task:259006, Ref.:ALM04-00-00, Ref.:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement							RE (N/A)	5-10, AWL, Replacement
25 A/F	Right No.3							[30-Apr-2034]	??%
63600-105									
L6167836									
14-Apr-2021									
CALM Task:259006, Ref.:ALM04-00-00, Ref.:SDS25-60-00									
250003	Equipment/Furnishings - Life Vest - Replacement							RE (N/A)	5-10, AWL, Replacement
25 A/F	Right No.4							[30-Mar-2034]	??%
63600-105									
L6034452									
14-Apr-2021									
CALM Task:259006, Ref.:ALM04-00-00, Ref.:SDS25-60-00									
250004-0201	Life Raft Emergency Locator Transmitter (ELT) Battery							RE (Due)	Custom Task
25 A/F	No.1							30-Jun-2031	??%
Unknown									
68321									
Expiration Date 30-Jun-2031									
250010	Equipment/Furnishings - Emergency Locator Transmitter Battery Pack - Replacement							RE	5-20, AWL, Replacement
25 A/F								[31-Jul-2027]	25%
452-0133									
395709-040									
Manufactured Date 31-Jul-2022									
Ref.:ALM04-00-00, Ref.:AMM25-60-01									
▼ 26 - FIRE PROTECTION									
260000-0210	APU Fire Extinguisher Bottle							RE (Srv)	
26 A/F	No.3							[01-Jul-2028]	??%
33500019-1	Tested/Inspected								
27863C1									
260003	Fire Protection - APU Left Fire Extinguisher Cartridge, Service Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.3							16-Dec-2030	47%
M30903955									
00312									
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - APU Left Fire Extinguisher Cartridge, Total Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.3							01-Jun-2035	61%
M30903955									
00312									
Manufactured Date 01-Jun-2020									
Ref.:ALM04-00-00, Ref.:AMM26-20-04									

Total projection:

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
260003	Fire Protection - Left Fire Extinguisher Cartridge, Service Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.1				Mos	13-Apr-2021	120	13-Apr-2031	50%
M30903955					Hrs	1766:30			
0326					Ldg	925			
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - Left Fire Extinguisher Cartridge, Service Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.2				Mos	16-Dec-2020	120	16-Dec-2030	47%
30903955					Hrs	1723:05			
00299					Ldg	905			
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - Left Fire Extinguisher Cartridge, Total Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.1				Mos	13-Apr-2021	180	11-Dec-2035	65%
M30903955					Hrs	1766:30			
0326					Ldg	925			
Manufactured Date 11-Dec-2020 Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - Left Fire Extinguisher Cartridge, Total Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.2				Mos	16-Dec-2020	180	01-Jun-2035	61%
30903955					Hrs	1723:05			
00299					Ldg	905			
Manufactured Date 01-Jun-2020 Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - No.3 Bottle APU Fire Extinguisher Cartridge, Service Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.3				Mos	16-Dec-2020	120	16-Dec-2030	47%
M30903955					Hrs	1723:05			
00317					Ldg	905			
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - No.3 Bottle APU Fire Extinguisher Cartridge, Total Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.3				Mos	16-Dec-2020	180	01-Jun-2035	61%
M30903955					Hrs	1723:05			
00317					Ldg	905			
Manufactured Date 01-Jun-2020 Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - Right Fire Extinguisher Cartridge, Service Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.1				Mos	16-Dec-2020	120	16-Dec-2030	47%
M30903955					Hrs	1723:05			
00320					Ldg	905			
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - Right Fire Extinguisher Cartridge, Service Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.2				Mos	16-Dec-2020	120	16-Dec-2030	47%
M30903955					Hrs	1723:05			
00301					Ldg	905			
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
260003	Fire Protection - Right Fire Extinguisher Cartridge, Total Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.1				Mos	16-Dec-2020	180	01-Jun-2035	61%
M30903955					Hrs	1723:05			
00320					Ldg	905			
Manufactured Date 01-Jun-2020 Ref.:ALM04-00-00, Ref.:AMM26-20-04									

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
260003	Fire Protection - Right Fire Extinguisher Cartridge, Total Life Limit							RE	5-10, AWL, Life Limit
26 A/F	No.2				Mos	16-Dec-2020	180	01-Jun-2035	61%
M30903955					Hrs	1723:05			
00301					Ldg	905			
Manufactured Date 01-Jun-2020									
Ref.:ALM04-00-00, Ref.:AMM26-20-04									
▼ 27 - FLIGHT CONTROLS									
270001	Flight Controls - Horizontal Stabilizer Trim Actuator (HSTA) - Replacement							RE	5-10, AWL, Replacement ≈05-Dec-2029
27 A/F					Mos	09-Sep-2022			
243100-110					Hrs	2533	2,400	4933	54%
0107A					Ldg	1,331			
Ref.:ALM04-00-00, Ref.:AMM27-40-06									
270006	Flight Controls - Flap Actuator, Replacement							RE	5-10, AWL, Replacement ≈19-Nov-2042
27 A/F	Left Inboard				Mos				
920587-103					Hrs	9,600		9600	62%
868310195					Ldg				
Ref.:ALM04-00-00, Ref.:AMM27-50-05									
270006	Flight Controls - Flap Actuator, Replacement							RE	5-10, AWL, Replacement ≈19-Nov-2042
27 A/F	Left Outboard				Mos				
920585-103					Hrs	9,600		9600	62%
86831-0141					Ldg				
Ref.:ALM04-00-00, Ref.:AMM27-50-05									
270006	Flight Controls - Flap Actuator, Replacement							RE	5-10, AWL, Replacement ≈19-Nov-2042
27 A/F	Right Inboard				Mos				
920587-103					Hrs	9,600		9600	62%
868310192					Ldg				
Ref.:ALM04-00-00, Ref.:AMM27-50-05									
270006	Flight Controls - Flap Actuator, Replacement							RE	5-10, AWL, Replacement ≈19-Nov-2042
27 A/F	Right Outboard				Mos				
920586-103					Hrs	9,600		9600	62%
86831-0164					Ldg				
Ref.:ALM04-00-00, Ref.:AMM27-50-05									
270007	Flight Controls - Flap Power Drive Unit (PDU), Replacement							RE	5-10, Replacement ≈19-Nov-2042
27 A/F					Mos				
920584-101					Hrs	9,600		9600	62%
868310152					Ldg				
Ref.:AMM27-50-04									
270008	Flight Controls - Rudder Power Control Unit (PCU), Replacement							RE	5-10, AWL, Replacement ≈08-Sep-2027
27 A/F	No.1				Mos				
920590-105					Hrs	4,125		4125	12%
0086					Ldg				
Ref.:ALM04-00-00, Ref.:AMM27-20-03									
270008	Flight Controls - Rudder Power Control Unit (PCU), Replacement							RE	5-10, AWL, Replacement ≈08-Sep-2027
27 A/F	No.2				Mos				
920590-105					Hrs	4,125		4125	12%
0168					Ldg				
Ref.:ALM04-00-00, Ref.:AMM27-20-03									
▼ 28 - FUEL									
280001	Fuel - Pressure/Vacuum Relief Valve - Replacement							RE	5-10, AWL, Replacement ≈18-Nov-2047
28 A/F	Left				Mos				
920019-001					Hrs	11,400		11400	68%
0132					Ldg				
Ref.:ALM04-00-00, Ref.:AMM28-10-30									

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
280001	Fuel - Pressure/Vacuum Relief Valve - Replacement							RE 5-10, AWL, Replacement	≈18-Nov-2047
28 A/F	Right								
920019-001									
0133									
Ref.:ALM04-00-00, Ref.:AMM28-10-30									
▼ 29 - HYDRAULIC POWER									
290002	Hydraulic Power - Hydraulic Reservoir - Self Pressurized, Replacement							RE 5-10, AWL, Replacement	≈02-Oct-2071
29 A/F	Left								
71886-5									
0052									
Ref.:ALM04-00-00, Ref.:AMM29-10-07									
290002	Hydraulic Power - Hydraulic Reservoir - Self Pressurized, Replacement							RE 5-10, AWL, Replacement	≈02-Oct-2071
29 A/F	Right								
71886-6									
0097									
Ref.:ALM04-00-00, Ref.:AMM29-10-07									
▼ 32 - LANDING GEAR									
320003	Main Landing Gear (MLG) - Main Fitting Sub Assembly - Replacement							RE 5-10, AWL, Replacement	≈05-Nov-2029
32 A/F	Left								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320003	Main Landing Gear (MLG) - Main Fitting Sub Assembly - Replacement							RE 5-10, AWL, Replacement	≈05-Nov-2029
32 A/F	Right								
Unknown									
Unknown									
Ref.:32CMM, Ref.:AMM32-10-33, Ref.:ALM04-00-00									
320003	Main Landing Gear (MLG) Pintle Pin - Replacement							RE 5-10, AWL, Replacement	≈05-Nov-2029
32 A/F	Left								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320003	Main Landing Gear (MLG) Pintle Pin - Replacement							RE 5-10, AWL, Replacement	≈05-Nov-2029
32 A/F	Right								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320004	Landing Gear - Left Inboard Door Actuator, Replacement							RE 5-10, AWL, Replacement	≈21-Jul-2039
32 A/F	Left								
34100-101									
10MDT0199									
Ref.:ALM04-00-00, Ref.:AMM52-80-40									
320004	Landing Gear - Right Inboard Door Actuator, Replacement							RE 5-10, AWL, Replacement	≈21-Jul-2039
32 A/F	Right								
34100-101									
10MDT0198									
Ref.:ALM04-00-00, Ref.:AMM52-80-40									
320056	Landing Gear - Nose Landing Gear (NLG) Assembly - Replacement							RE 5-10, AWL, Replacement	≈23-Jun-2076
32 A/F									
33000-107									
10MDT0170									
Ref.:ALM04-00-00, Ref.:AMM32-20-01									

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
320057	Landing Gear - Landing Gear Door Mechanism Assy, FWD Door - Replacement							RE 5-10, AWL, Replacement	≈09-Aug-2035
32 A/F					Mos				
34505-111					Hrs	10-Feb-2017			
S0000244B					Ldg	596:55			
Ref:ALM04-00-00, Ref:AMM52-80-25						274	5,000	5,274	67%
320058	Main Landing Gear (MLG) - Main Fitting Sub Assembly - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
ALM:04-00-00, AMM:32-10-33, CMM:32									
320058	Main Landing Gear (MLG) - Main Fitting Sub Assembly - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
ALM:04-00-00, AMM:32-10-33, CMM:32									
320058	Main Landing Gear (MLG) Lower Shock Strut Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
Ref:ALM04-00-00, Ref:AMM32-10-33, Ref:32CMM									
320058	Main Landing Gear (MLG) Lower Shock Strut Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
Ref:ALM04-00-00, Ref:AMM32-10-33, Ref:32CMM									
320058	Main Landing Gear (MLG) Pintle Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
ALM:04-00-00, AMM:32-10-33, CMM:32									
320058	Main Landing Gear (MLG) Pintle Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
ALM:04-00-00, AMM:32-10-33, CMM:32									
320058	Main Landing Gear (MLG) Pivot Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
Ref:ALM04-00-00, Ref:AMM32-10-33, Ref:32CMM									
320058	Main Landing Gear (MLG) Pivot Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
Ref:ALM04-00-00, Ref:AMM32-10-33, Ref:32CMM									
320058	Main Landing Gear (MLG) Shock Strut Assembly - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left				Mos				
Unknown					Hrs				
Unknown					Ldg		12,000	12,000	84%
Ref:ALM04-00-00, Ref:AMM32-10-33, Ref:32CMM									

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
320058	Main Landing Gear (MLG) Shock Strut Assembly - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320058	Main Landing Gear (MLG) Trailing Arm/Axle - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320058	Main Landing Gear (MLG) Trailing Arm/Axle - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320058	Main Landing Gear (MLG) Upper Shock Strut Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Left								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320058	Main Landing Gear (MLG) Upper Shock Strut Pin - Replacement							RE 5-10, AWL, Replacement	≈09-Apr-2054
32 A/F	Right								
Unknown									
Unknown									
Ref.:ALM04-00-00, Ref.:AMM32-10-33, Ref.:32CMM									
320059	Main Landing Gear (MLG) - MLG & Harness Assembly - Replacement							RE 5-10, AWL, Replacement	≈05-Nov-2029
32 A/F	Left								
32000-115									
10MDT0193									
ALM:04-00-00, AMM:32-10-33, CMM:32									
320059	Main Landing Gear (MLG) - MLG & Harness Assembly - Replacement							RE 5-10, AWL, Replacement	≈05-Nov-2029
32 A/F	Right								
32000-116									
10MDT0191									
ALM:04-00-00, AMM:32-10-33, CMM:32									
▼ 33 - LIGHTS									
330001	Lights - Emergency Battery - Replace							RE 5-10, Replacement	
33 A/F	Fwd								
RG-128-3									
70022631									
Ref.:AMM33-50-35 (UPDATE NOTE: Cap test 91,6%)									
330001	Lights - Emergency Battery - Replace							RE 5-10, Replacement	
33 A/F	Mid								
RG-128-3									
70022630									
Ref.:AMM33-50-35 (UPDATE NOTE: Cap test 98,3 %)									
▼ 35 - OXYGEN									
350000-0401	Portable Oxygen Cabin							RE (H/T)	
35 A/F	Tested/Inspected								
176961-15									
613965601									

Total projection:

Hawker 4000 OK-BFF,SN RC-57

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
350001	Oxygen - Oxygen Bottle (Left Lower Aircraft) - Service Life							RE	5-10, AWL, Life Limit
35 A/F	No.1								
4441041-050					Yrs	23-Jan-2026	15	30-Nov-2039	90%
ALT279-39722					Hrs	3633:30			
Manufactured Date 30-Nov-2024					Ldg	1,930			
Ref.:ALM04-00-00, Ref.:AMM35-00-14									
350001	Oxygen - Oxygen Bottle (Left Upper Aircraft) - Service Life							RE	5-10, AWL, Life Limit
35 A/F	No.3								
4441043-022					Yrs	23-Jan-2026	15	31-Jan-2036	65%
00079-3228					Hrs	3633:30			
Manufactured Date 31-Jan-2021					Ldg	1,930			
Ref.:ALM04-00-00, Ref.:AMM35-00-14									
350001	Oxygen - Oxygen Bottle (Right Lower Aircraft) - Service Life							RE	5-10, AWL, Life Limit
35 A/F	No.2								
4441716-050					Yrs	23-Jan-2026	15	31-Aug-2027	9%
LX00320404					Hrs	3633:30			
Manufactured Date 31-Aug-2012					Ldg	1,930			
Ref.:ALM04-00-00, Ref.:AMM35-00-14									
350001	Oxygen - Oxygen Bottle (Right Upper Aircraft) - Service Life							RE	5-10, AWL, Life Limit
35 A/F	No.4								
4441720-022					Yrs	23-Jan-2026	15	31-Aug-2037	75%
ALT280-9005					Hrs	3633:30			
Manufactured Date 31-Aug-2022					Ldg	1,930			
Ref.:ALM04-00-00, Ref.:AMM35-00-14									
350001	Oxygen - Portable Oxygen Cabin - Service Life							RE	5-10, AWL, Life Limit
35 A/F									
176961-15					Yrs	28-Apr-2026	15	[31-Dec-2028]	18%
613965601					Hrs	3634:10			
Manufactured Date 31-Dec-2013					Ldg	1,931			
Ref.:ALM04-00-00, Ref.:AMM35-00-14									
350002	Oxygen - Protective Breathing Equipment - Replacement							RE	5-10, AWL, Replacement
35 A/F									
802300-14					Mos	26-May-2021	120	28-Feb-2031	49%
E21020375					Hrs	1777:20			
Manufactured Date 28-Feb-2021					Ldg	931			
CALM Task:359002, Ref.:ALM04-00-00, Ref.:AMM35-30-02									
▼ 38 - WATER/WASTE									
380002	Water/Waste - Drain Mast, Replacement							RE	5-10, Replacement
38 A/F	Aft								≈17-Jul-2049
4E3264-3					Mos				
MZBX610					Hrs		12,000	12000	70%
Ref.:AMM38-30-30					Ldg				
380002	Water/Waste - Drain Mast, Replacement							RE	5-10, Replacement
38 A/F	Fwd								≈17-Jul-2049
4E3264-3					Mos				
MYGFFWO3					Hrs		12,000	12000	70%
Ref.:AMM38-30-30					Ldg				
▼ 49 - AIRBORNE AUXILIARY POWER									
491000-0101	Compressor Rotor							RE	≈05-Mar-2192
49 APU1									
3822101-1					Mos	16-Jul-2009			
08-13651-04481		1899:40			Hrs	0	100,000	100000	98%
		1,766			APUS	0	100,000	100,000	98%

Total projection:

Hawker 4000 OK-BFF,SN RC-57

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
492000-0101	Turbine Rotor							RE	≈09-Oct-2048
49 APU1					Mos	16-Jul-2009			
3615880-002		1899:40			Hrs	0	10,000	10000	81%
09-156101-01521		1,766			APUS	0	10,000	10,000	82%
▼ 53 - FUSELAGE									
530121	Fuselage - Forward Wing Link - Life Limit							RE	5-10, AWL, Life Limit ≈30-Dec-2043
53 A/F	Left				Mos				
401-433010					Hrs		10,000	10000	64%
Unknown					Ldg				
Ref:ALM04-00-00, Ref:AMM06-50-00									
530121	Fuselage - Forward Wing Link - Life Limit							RE	5-10, AWL, Life Limit ≈30-Dec-2043
53 A/F	Right				Mos				
401-433010					Hrs		10,000	10000	64%
Unknown					Ldg				
Ref:ALM04-00-00, Ref:AMM06-50-00									
▼ 55 - STABILIZERS									
550065	Empennage - Life Limit							RE	04-00-00, 05-10-16, AWL - Life Limit ≈19-Nov-2042
55 A/F					Mos				
Unknown					Hrs		9,600	9600	62%
Unknown					Ldg				
ALM:04-00-00									
▼ 57 - WINGS									
570041	Wings - Left Wing Assembly, Life Limit							RE	5-10, AWL, Life Limit ≈19-Nov-2042
57 A/F	Left				Mos				
401-100011-1					Hrs		9,600	9600	62%
RC-57					Ldg				
Ref:ALM04-00-00									
570041	Wings - Right Wing Assembly, Life Limit							RE	5-10, AWL, Life Limit ≈19-Nov-2042
57 A/F	Right				Mos				
401-100011-2					Hrs		9,600	9600	62%
RC-57					Ldg				
Ref:ALM04-00-00									
570063	Wings - Main Landing Gear (MLG) Support Fitting (P/N 401-111221) - Life Limit							RE	5-10, Life Limit ≈19-Nov-2042
57 A/F	Left				Mos				
Unknown					Hrs		9,600	9600	62%
Unknown					Ldg				
Ref:ALM04-00-00, Ref:AMM32-10-33									
570063	Wings - Main Landing Gear (MLG) Support Fitting (P/N 401-111221) - Life Limit							RE	5-10, Life Limit ≈19-Nov-2042
57 A/F	Right				Mos				
Unknown					Hrs		9,600	9600	62%
Unknown					Ldg				
Ref:ALM04-00-00, Ref:AMM32-10-33									
▼ 72 - ENGINE									
723001-0101	Rotor - HP Compressor (1st Stage)							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG1					Mos	17-Jul-2023			
30C5331-01		3336:58			Hrs	3039:18			
A002X7YC		1,988			Enc	1,838	15,000	15,000	87%

Total projection:

Hawker 4000 OK-BFF,SN RC-57

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
723001-0101	Rotor - HP Compressor (1st Stage)							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG2					Mos	14-Feb-2011			
30C5331-01	New	3336:58			Hrs	0			
A002X7YH		1,988			Enc	0	15,000	15,000	87%
723002-0101	Rotor - HP Compressor (2nd Stage)							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG1					Mos	17-Jul-2023			
30C2132-01		3336:58			Hrs	3039:18			
A002X371		1,988			Enc	1,838	15,000	15,000	87%
723002-0101	Rotor - HP Compressor (2nd Stage)							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG2					Mos	14-Feb-2011			
30C2132-01	New	3336:58			Hrs	0			
A002X066		1,988			Enc	0	15,000	15,000	87%
723003-0101	Rear HP Compressor Case							RE	EMM - Requirement ≈05-Aug-2047
72 ENG1					Mos	11-May-2019			
30C4213-01		3336:58			Hrs	2966:54	11,000	11000	70%
ACE08651301					Enc	1,793			
723003-0101	Rear HP Compressor Case							RE	EMM - Requirement ≈05-Aug-2047
72 ENG2					Mos	14-Feb-2011			
30C4213-01		3336:58			Hrs	0	11,000	11000	70%
ACE09049101					Enc	0			
723003-0101	Rotor - HP Compressor (3rd Stage)							RE	AWL, EMM - Life Limit ≈11-May-2044
72 ENG1					Mos	17-Jul-2023			
30C2133-01		3336:58			Hrs	3039:18			
TXA1C3574		1,988			Enc	1,838	8,500	8,500	77%
723003-0101	Rotor - HP Compressor (3rd Stage)							RE	AWL, EMM - Life Limit ≈11-May-2044
72 ENG2					Mos	14-Feb-2011			
30C2133-01					Hrs	0			
TXA1C2002		1,988			Enc	0	8,500	8,500	77%
723004-0101	Rotor - HP Compressor (4th Stage)							RE	AWL, EMM - Life Limit ≈11-May-2044
72 ENG1					Mos	17-Jul-2023			
30C3454-01		3336:58			Hrs	3039:18			
TXA1C3561		1,988			Enc	1,838	8,500	8,500	77%
723004-0101	Rotor - HP Compressor (4th Stage)							RE	AWL, EMM - Life Limit ≈11-May-2044
72 ENG2					Mos	14-Feb-2011			
30C3454-01	New	3336:58			Hrs	0			
TXA1C3558		1,988			Enc	0	8,500	8,500	77%
723005-0101	Hub-Fan							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG1					Mos	17-Jul-2023			
30C4154-01		3336:58			Hrs	3039:18			
BE101261		1,988			Enc	1,838	15,000	15,000	87%
723005-0101	Hub-Fan							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG2					Mos	14-Feb-2011			
30C4154-01	New	3336:58			Hrs	0			
BE101258		1,988			Enc	0	15,000	15,000	87%

Total projection:

Hawker 4000 OK-BFF,SN RC-57

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
723009-0101	Shaft - LP Compressor							RE	AWL, EMM - Life Limit ≈31-Mar-2064
72 ENG1					Mos	17-Jul-2023			
30C4140-01		3336:58			Hrs	3039:18	17,000	17,000	80%
A002X6PB		1,988			Enc	1,838	16,500	16,500	88%
723009-0101	Shaft - LP Compressor							RE	AWL, EMM - Life Limit ≈31-Mar-2064
72 ENG2					Mos	14-Feb-2011			
30C4140-01	New	3336:58			Hrs	0	17,000	17,000	80%
A002X6PC		1,988			Enc	0	16,500	16,500	88%
723011-0101	No.3 Bearing Front Seal Runner							RE	AWL, EMM - Life Limit ≈25-Aug-2034
72 ENG1					Mos	17-Jul-2023			
30C5659-01		3336:58			Hrs	3039:18			
PKAAA337839		1,988			Enc	1,838	5,000	5,000	60%
723011-0101	No.3 Bearing Front Seal Runner							RE	AWL, EMM - Life Limit ≈18-Aug-2039
72 ENG2					Mos	17-May-2019			
30C5659-01	New	368:28			Hrs	2968:30			
PKAAA793364		194			Enc	1,794	5,000	6,794	96%
723015-0101	Impeller - Inducer							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG1					Mos	17-Jul-2023			
30C4475-01		3336:58			Hrs	3039:18			
A002X4H2		1,988			Enc	1,838	15,000	15,000	87%
723015-0101	Impeller - Inducer							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG2					Mos	14-Feb-2011			
30C4475-01	New	3336:58			Hrs	0	15,000	15,000	87%
A002X4H1		1,988			Enc	0	15,000	15,000	87%
723020-0101	Impeller - Exducer							RE	AWL, EMM - Life Limit ≈25-Aug-2034
72 ENG1					Mos	17-Jul-2023			
30C5049-01		3336:58			Hrs	3039:18			
A002W17K		1,988			Enc	1,838	5,000	5,000	60%
723020-0101	Impeller - Exducer							RE	AWL, EMM - Life Limit ≈18-Aug-2039
72 ENG2					Mos	17-May-2019			
Unknown		368:28			Hrs	2968:30			
Unknown		194			Enc	1,794	5,000	6,794	96%
725001-0101	Disk - HP Turbine (1st-stage)							RE	AWL, EMM - Life Limit ≈22-Aug-2036
72 ENG1					Mos	17-Jul-2023			
30C5371-01		3336:58			Hrs	3039:18			
A002TEP4		2,117			Enc	1,838			
		2,121.16			ATC1	1,966.66	6,100	6,100	65%
725001-0101	Disk - HP Turbine (1st-stage)							RE	AWL, EMM - Life Limit ≈22-Aug-2036
72 ENG2					Mos	14-Feb-2011			
30C5371-01	New				Hrs	0			
A002TEP6					Enc	0			
		2,121.16			ATC1	0	6,100	6,100	65%

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
725002-0101	Disk - HP Turbine (2nd-stage)							RE AWL, EMM - Life Limit	≈21-Apr-2046
72 ENG1					Mos	17-Jul-2023			
30C5372-01		3336:58			Hrs	3039:18			
A002T4K5		2,042			Enc	1,838			
		2,047.64			ATC3	1,893.14	9,500	9,500	78%
725002-0101	Disk - HP Turbine (2nd-stage)							RE AWL, EMM - Life Limit	≈21-Apr-2046
72 ENG2					Mos	14-Feb-2011			
30C5372-01	New				Hrs	0			
A002XECN					Enc	0			
		2,047.64			ATC3	0	9,500	9,500	78%
725003-0101	Disk - LP Turbine (3rd-Stage)							RE AWL, EMM - Life Limit	≈30-Jan-2054
72 ENG1					Mos	17-Jul-2023			
30F1337-05		3336:58			Hrs	3039:18			
FAE41716		1,988			Enc	1,838	12,000	12,000	83%
725003-0101	Disk - LP Turbine (3rd-Stage)							RE AWL, EMM - Life Limit	≈30-Jan-2054
72 ENG2					Mos	14-Feb-2011			
30F1337-05	New	3336:58			Hrs	0			
FAE41661		1,988			Enc	0	12,000	12,000	83%
725004-0101	Disk - LP Turbine (4th Stage)							RE AWL, EMM - Life Limit	≈30-Jan-2054
72 ENG1					Mos	17-Jul-2023			
30F1336-06		3336:58			Hrs	3039:18			
FAE41726		1,988			Enc	1,838	12,000	12,000	83%
725004-0101	Disk - LP Turbine (4th Stage)							RE AWL, EMM - Life Limit	≈30-Jan-2054
72 ENG2					Mos	14-Feb-2011			
30F1336-06	New	3336:58			Hrs	0			
FAE41722		1,988			Enc	0	12,000	12,000	83%
725005-0101	Disk - LP Turbine (5th-Stage)							RE AWL, EMM - Life Limit	≈30-Jan-2054
72 ENG1					Mos	17-Jul-2023			
30F1006-10		3336:58			Hrs	3039:18			
FAE41747		1,988			Enc	1,838	12,000	12,000	83%
725005-0101	Disk - LP Turbine (5th-Stage)							RE AWL, EMM - Life Limit	≈30-Jan-2054
72 ENG2					Mos	14-Feb-2011			
30F1006-10	New	3336:58			Hrs	0			
FAE41749		1,988			Enc	0	12,000	12,000	83%
725020-0101	Cover - Rear HP Turbine							RE AWL, EMM - Life Limit	≈28-May-2062
72 ENG1					Mos	17-Jul-2023			
30C5043-01		3336:58			Hrs	3039:18			
A002XYRK		1,988			Enc	1,838	15,000	15,000	87%
725020-0101	Cover - Rear HP Turbine							RE AWL, EMM - Life Limit	≈28-May-2062
72 ENG2					Mos	14-Feb-2011			
30C5043-01	New	3336:58			Hrs	0			
A002XYRN		1,988			Enc	0	15,000	15,000	87%
725075-0101	Cover - Front HP Turbine							RE AWL, EMM - Life Limit	≈28-May-2062
72 ENG1					Mos	17-Jul-2023			
30C5365-01		3336:58			Hrs	3039:18			
A002XWHF		1,988			Enc	1,838	15,000	15,000	87%

Total projection:

Hawker 4000 OK-BFF,SN RC-57

Task No	Description	TSNI	TSOI	TSRI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	Component Condition							DUE	Remaining
725075-0101	Cover - Front HP Turbine							RE	AWL, EMM - Life Limit ≈28-May-2062
72 ENG2					Mos	14-Feb-2011			
30C5365-01	New	3336:58			Hrs	0			
A002Y374		1,988			Enc	0	15,000	15,000	87%
▼ 79 - OIL									
790000-0101	Chip Detector							RE	EMM - Requirement ≈12-Aug-2028
79 ENG1					Mos	21-Nov-2017			
30C4931-01					Hrs	2362:18	1,800	[4162:18]	46%
AB1380					Enc	1,484			
Ref:79-30-01-mp									
790000-0101	Chip Detector							RE	EMM - Requirement ≈17-Apr-2030
79 ENG2					Mos	14-Feb-2024			
Unknown		368:58			Hrs	3039	1,800	4768	80%
Unknown					Enc				
Ref:79-30-01-mp (UPDATE NOTE: Unit found installed on engine at installation Feb 2024 Status reference KCI List as of 18 jul 2023 TSN 71 Hrs)									