

OWNER: ABS JETS

OPERATOR: ABS JETS

ADDRESS: ABS JETS C/O CAIMITO
ENTERPRISES LIMITED
PRAGUE 6 161 00ADDRESS: ABS JETS C/O CAIMITO
ENTERPRISES LIMITED
PRAGUE 6 161 00

OFFICE: +420 220 111 196

OFFICE: +420 220 111 196

FAX: +420 220 112 623

FAX: +420 220 112 623

ANALYST: DUANE GERDES

+1 912-298-1325 (DIRECT)

EMAIL: DGERDES@CAMPSYSTEMS.COM

+1-631-588-3200 (MAIN)

WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Mode:WITH COMPLIANCE OR NEXT DUE; Group by Profile or Bulletin:PROFILE TYPE;

AIRCRAFT	SERIAL / REGNO: 72113/OK-HUB	MODEL: GVII-G500	MANUFACTURER: GULFSTREAM AEROSPACE CORPORATION
CERTIFICATION DATE: 10-JAN-2023		LAST ACTUALS:	
		590.9 A/C HRS	as of 24-JUN-2026
		409 AFL	as of 24-JUN-2026
		673 APH	as of 06-JUN-2026
		5 APS	as of 06-JUN-2026
APU	SERIAL / PART: P-327/70721406-1	MODEL: HGT400(G)	MANUFACTURER: HONEYWELL
INSTALLED ON: 29-NOV-2022		LAST ACTUALS:	
0 APU HRS	0 A/C HRS	673 APU HRS	as of 06-JUN-2026
0 APUS		5 APUS	as of 06-JUN-2026
ENGINE NO. 1	SERIAL / PART: PCE-GA0486/33B1170-01	MODEL: PW814GA	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 07-DEC-2022		LAST ACTUALS:	
0 ENG. HRS	0 A/C HRS	590.9 ENG. HRS	as of 24-JUN-2026
0 ENC		409 ENC	as of 24-JUN-2026
ENGINE NO. 2	SERIAL / PART: PCE-GA0487/33B1170-01	MODEL: PW814GA	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 05-DEC-2022		LAST ACTUALS:	
0 ENG. HRS	0 A/C HRS	590.9 ENG. HRS	as of 24-JUN-2026
0 ENC		409 ENC	as of 24-JUN-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - AD - GVII-G500 72113/OK-HUB							
FAA 1974-08-09 R03	FAA 1974-08-09 R03 - EQUIPMENT/FURNISHINGS - INSTALLATION OF PLACARDS PROHIBITING SMOKING IN THE LAVATORY AND DISPOSAL OF CIGARETTES IN THE LAVATORY WASTE RECEPTACLES					MANDATORY	Complied With
Eff. Date: 28-MAR-2012		MOS HRS/MSC AFL	1000	11-APR-2023 5.2 2	1005.2	RECURRING	
FAA 2003-26-14	FAA 2003-26-14 - FIRE PROTECTION - REMOVE THE AFFECTED FIRE EXTINGUISHERS FROM SERVICE AND WOULD PREVENT YOU FROM USING THEM IN THE FUTURE					MANDATORY	Not Applicable
Eff. Date: 20-FEB-2004		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
FAA 2020-02-18	FAA 2020-02-18 - FLIGHT CONTROLS - REVISE THE AIRPLANE FLIGHT MANUAL (AFM) BY ATTACHING AN AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS)					MANDATORY	Not Applicable
Eff. Date: 13-FEB-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
FAA 2020-23-04	FAA 2020-23-04 - FUEL - REVISE AIRPLANE FLIGHT MANUAL (AFM) AND AIRPLANE MAINTENANCE MANUAL (AMM) TO INCLUDE INFORMATION PERTAINING TO THE FUEL BOOST PUMP					MANDATORY	Not Applicable
Eff. Date: 24-NOV-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
FAA 2021-15-03 PARA (G)(2)	2021-15-03 PARA (G)(2) REVISE THE EXISTING ALS OR AAIP BY ESTABLISHING 20,000 FLIGHT CYCLE LIFE LIMIT (MANDATORY)					MANDATORY	Not Applicable
Eff. Date: 26-AUG-2021		MOS HRS/MSC AFL	-	11-APR-2023 7.5 3	-		
LBA D-2021-211							
FAA 2021-23-12	FAA 2021-23-12 - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	Complied With
Eff. Date: 09-DEC-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
FAA 2022-10-05	2022-10-05 - FLIGHT CONTROLS - REVISE FLIGHT MANUAL (AFM) TO INCORPORATE REVISED LIMITATIONS AND PROCEDURES (MANDATORY)					MANDATORY	Complied With
Eff. Date: 09-MAY-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
FAA 2023-11-09	2023-11-09 - (ATA) CODE 27 - FLIGHT CONTROLS - UPDATE FLIGHT CONTROL COMPUTER (FCC) SOFTWARE TO CORRECT INAPPROPRIATE ALPHA LIMITER ENGAGEMENT DURING THE LANDING FLARE (MANDATORY)					MANDATORY	Not Applicable - DUE TO S/N
Eff. Date: 18-JUL-2023		DAYS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		
FAA 2024-05-04	FAA 2024-05-04 - REVISE AIRPLANE FLIGHT MANUAL (AFM) AND AIRPLANE MAINTENANCE MANUAL (AMM) TO INCLUDE INFORMATION PERTAINING TO THE FUEL BOOST PUMP (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 02-MAY-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2024-05-04 PARA (G)	FAA 2024-05-04 PARA (G) - REVISE YOUR EXISTING AIRPLANE MAINTENANCE MANUAL (AMM) AND (AFM) (RETAINED FAA 2020-23-04 PARA (G) WITH UPDATED SERVICE INFORMATION) (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 28-MAR-2024		DAYS		01-APR-2024			
		HRS/MSC	-	209.6	-		
		AFL		171			
FAA 2024-05-04 PARA (H)	FAA 2024-05-04 PARA (H) - INSPECT PUMPS AS SPECIFIED IN PARA III.D AND PERFORM ALL APPLICABLE ACTIONS IDENTIFIED AS "RC" (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 02-MAY-2024		MOS		01-APR-2024			
		HRS/MSC	-	209.6	-		
		AFL		171			
FAA 2024-10-15	FAA AD 2024-10-15 ENGINE MOUNT POINT - INSPECTION (MANDATORY)					MANDATORY	Complied With - CB093A COMPLIED WITH
Eff. Date: 07-JUN-2024		MOS		25-JUN-2024			
		HRS/MSC	-	228.7	-		
		AFL		195			
FAA 2024-10-15 PARA (G)	FAA AD 2024-10-15 ENGINE MOUNT HARDWARE INSTALLATION - INSPECTION (MANDATORY)					MANDATORY	Complied With - CB093A COMPLIED WITH
Eff. Date: 07-JUN-2024		DAYS		25-JUN-2024			
		HRS/MSC	-	228.7	-		
		AFL		195			
FAA 2024-10-15 PARA (H)	FAA AD 2024-10-15 REVISION OF AIRCRAFT MAINTENANCE MANUAL (AMM) (MANDATORY)					MANDATORY	Complied With - NO HARDCOPY IN USE. ELECTRONIC AMM UP TO DATE
Eff. Date: 07-JUN-2024		DAYS		25-JUN-2024			
		HRS/MSC	-	228.7	-		
		AFL		195			
FAA 2024-25-03	FUEL - LEFT-WING AND RIGHT-WING ELECTRICAL GROUNDING RECEPTICLES - INSPECT / SEAL (MANDATORY)					MANDATORY	
Eff. Date: 12-FEB-2025		MOS	36		12-FEB-2028		
FAA 2026-01-03	FAA 2026-01-03 - MORE RESTRICTIVE AIRWORTHINESS LIMITATIONS (MANDATORY)					MANDATORY	Complied With
Eff. Date: 24-FEB-2026		DAYS		04-FEB-2026			
		HRS/MSC	-	546.5	-		
		AFL		383			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
APPLIANCE - GVII-G500 72113/OK-HUB							
FAA 2020-21-02	FAA 2020-21-02 - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT					MANDATORY	Not Applicable
Eff. Date: 19-NOV-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
FAA 2020-21-02 PARA (H) & (I)	FAA 2020-21-02 PARA (H) & (I) - DO AN INSPECTION TO DETERMINE THE PART NUMBER AND SERIAL NUMBER OF THE CARGO FIRE EXTINGUISHER HALON BOTTLES INSTALLED IN THE CARGO COMPARTMENT AND REPLACE WITH A SERVICEABLE PART AS REQUIRED					MANDATORY	Not Applicable
Eff. Date: 19-NOV-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
FAA 2020-21-02 PARA (J)	FAA 2020-21-02 PARA (J) - NO PERSON MAY INSTALL ON ANY AIRPLANE AN AFFECTED PART AS IDENTIFIED IN PARAGRAPH (G)(3) OF THIS AD UNLESS THAT PART HAS A CIRCLED LETTER "G" STAMPED AT A DISTANCE 8 OF APPROXIMATELY ONE INCH FROM THE LEFT EDGE OF THE PLACARD, INDICATING THAT THE CARGO FIRE EXTINGUISHER HALON BOTTLE HAS BEEN TESTED AND REFILLED					MANDATORY	Not Applicable
Eff. Date: 19-NOV-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
FAA 2023-10-02	APPLIANCE AD - FAA 2023-10-02 - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION (MANDATORY)					MANDATORY	Not Applicable - NOT ADOPTED BY EASA
Eff. Date: 26-MAY-2023		MOS		31-MAY-2023			
		HRS/MSC	-	54.5	-		
		AFL		57			
FAA 2023-10-02 PARA (H)	APPLIANCE ADP - FAA 2023-10-02 PARA (H) - REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30--JUNE- 2023 - SATISFIED BY FAA 2021-23-12) (MANDATORY)					MANDATORY	Not Applicable - NOT ADOPTED BY EASA
Eff. Date: 26-MAY-2023		MOS		31-MAY-2023			
		HRS/MSC	-	54.5	-		
		AFL		57			
FAA 2023-10-02 PARA (I)	APPLIANCE ADP - FAA 2023-10-02 PARA (I) - REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023) (MANDATORY)					MANDATORY	Not Applicable - NOT ADOPTED BY EASA
Eff. Date: 26-MAY-2023		MOS		31-MAY-2023			
		HRS/MSC	-	54.5	-		
		AFL		57			
FAA 2025-26-06	APPLIANCE AD - FAA 2025-26-06 - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT (MANDATORY)					MANDATORY	Not Applicable
Eff. Date: 14-JAN-2026		DAYS		13-JAN-2026			
		HRS/MSC	-	-	-		
		AFL					
FAA 2026-03-09 PARA (G) EASA (	APPLIANCE ADP - REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD (MANDATORY)					MANDATORY	Not Applicable
Eff. Date: 12-MAR-2026		DAYS					
		HRS/MSC	-	-	-		
		AFL					

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - SB - GVII-G500 72113/OK-HUB							
ACB ACB001	ACB001 - POWERPLANT (ATA 71) - INSPECTION - ENGINE MOUNT HARDWARE, ALERT CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 07-FEB-2024		DAYS		01-APR-2024			
		HRS/MSC	-	209.6	-		
		AFL		171			
ASC ASC001D	ASC001D - NAVIGATION (ATA 34) - TAKE-OFF AND LANDING DATA (TOLD) DATABASE INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 02-MAR-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC004A	ASC004A - INDICATING / RECORDING (ATA 31) - COCKPIT PRINTER - INSTALLATION					OPTIONAL	Complied With
Eff. Date: 16-OCT-2019		DAYS		29-MAR-2023			
		HRS/MSC	-	5.1	-		
		AFL		2			
ASC ASC006	FLIGHT CONTROLS (ATA 27) - REMOTE ELECTRONICS UNIT (REU) SOFTWARE LABEL 41 - UPDATE, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	
Eff. Date: 27-FEB-2026		MOS	36		27-FEB-2029		
ASC ASC007A PART 1	ASC007A PART 1 - AIRWORTHINESS LIMITATIONS (ATA 04) - EUROPEAN UNION AVIATION SAFETY AGENCY (EASA) CERTIFICATION BASIC REQUIREMENTS - STANDARD					OPTIONAL	Complied With
Eff. Date: 13-APR-2021		DAYS		29-MAR-2023			
		HRS/MSC	-	5.1	-		
		AFL		2			
ASC ASC007A PART 2	ASC007A PART 2 - AIRWORTHINESS LIMITATIONS (ATA 04) - EUROPEAN UNION AVIATION SAFETY AGENCY (EASA) CERTIFICATION BASIC REQUIREMENTS - METRIC					CATEGORY 04 - OPTIONAL	Not Applicable - DUE TO PART I INCORPORATION
Eff. Date: 13-APR-2021		MOS		17-MAY-2023			
		HRS/MSC	-	20.8	-		
		AFL		9			
ASC ASC009A	ASC009A - NAVIGATION (ATA 34) - WXR PREDICTIVE WINDSHEAR (PWS) ACTIVATION					OPTIONAL	Complied With
Eff. Date: 15-OCT-2019		DAYS		29-MAR-2023			
		HRS/MSC	-	5.1	-		
		AFL		2			
ASC ASC015A	ASC015A - INTEGRATED MODULAR AVIONICS (ATA 42) - SYMMETRY FLIGHT DECK AVIONICS UPDATE					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 15-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC017	ASC017 - ENGINE FUEL AND CONTROL (ATA 73) - ENGINE ELECTRONIC CONTROL - SOFTWARE UPDATE 5.4.1.2					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 15-MAY-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC018	ASC018 - DOORS (ATA 52) - ELECTRICAL MAIN ENTRY DOOR (EMED) WIRING HARNESS - MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 08-MAR-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ASC ASC020	ASC020 - FUEL (ATA 28) - INTERTANK SHUT-OFF VALVE SINGLE MOTOR ACTUATOR - REPLACEMENT					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 12-JAN-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC021B	ASC021B - INTEGRATED MODULAR AVIONICS (ATA 42) - SYMMETRY FLIGHT DECK AVIONICS UPDATE, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 09-APR-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC022B	ASC022B - ENGINE FUEL AND CONTROL (ATA 73) - ENGINE ELECTRONIC CONTROLLER 5.4.2.4 SOFTWARE UPDATE					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 30-APR-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC023A	ASC023A - FUEL (ATA 28) - PRESSURE REFUEL TUBING - BONDING IMPROVEMENT					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 15-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC024	ASC024 - EQUIPMENT AND FURNISHINGS (ATA 25) - FLIGHT DECK INTERIOR, OVERHEAD TRIM RING - INSTALLATION					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 14-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC025D	ASC025D - FUEL (ATA 28) - FUEL QUANTITY MONITORING SYSTEM SOFTWARE UPDATE					RECOMMENDED	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 31-DEC-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC026B	ASC026B - WINGS (ATA 57) - WING SPLICE BL0, SEAL DAM - INSTALLATION					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 23-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC027	ASC027 - DOORS (ATA 52) - MAIN ENTRANCE DOOR, EXTERNAL DOOR OPEN PUSH-BUTTON - BONDING INSTALLATION					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 15-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC028B	ASC028B - STABILIZER (ATA 55) - KA-BAND FIN CAP RADOME - INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 19-OCT-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC029A	ASC029A - PNEUMATIC SYSTEMS (ATA 36) - ENVIRONMENTAL CONTROL SYSTEM SOFTWARE UPDATE					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 16-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ASC ASC030A	ASC030A - DOORS (ATA 52) - PARABELLUM REMOTE ACCESS TO SECURITY SYSTEM VIDEO					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 19-MAR-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC031	ASC031 - OXYGEN (ATA 35) - CREW OXYGEN MASK UPGRADE - INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 27-MAY-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC032	ASC032 - WINGS (ATA 57) - FLAP YOKE - REPLACEMENT					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 20-NOV-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
FAA 2021-15-03							
ASC ASC033A	ASC033A - DOORS (ATA 52) - ELECTRIC MAIN ENTRY DOOR (EMED) BOTTOM FOLDING STEP MECHANISM - MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 15-SEP-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC033C	ASC033C - DOORS (ATA 52) - ELECTRIC MAIN ENTRY DOOR (EMED) BOTTOM FOLDING STEP MECHANISM - MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable
Eff. Date: 17-MAR-2023		MOS		09-MAY-2023			
		HRS/MSC	-	20.8	-		
		AFL		9			
ASC ASC034	ASC034 - LIGHTS (ATA 33) - EMERGENCY LIGHTING FUSE ASSEMBLIES - REMOVAL, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 08-APR-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC035	ASC035 - PLACARDS AND MARKINGS (ATA 11) - PLACARD, ELECTRIC MAIN ENTRY DOOR (EMED) DELAYED CLOSING - INSTALLATION					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 01-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC036	ASC036 - DOORS (ATA 52) - ELECTRIC MAIN ENTRY DOOR (EMED) DELAYED CLOSING - WIRING MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 08-MAR-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC037A	ASC037A - FLIGHT CONTROLS (ATA 27) - REMOTE ELECTRONICS UNITS (REU) SOFTWARE LABEL 36 - UPDATE					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 23-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC038A	ASC038A - FLIGHT CONTROLS (ATA 27) - ELECTRIC BACKUP MOTOR CONTROL ELECTRONICS (EBMCE) HARDWARE/FIRMWARE MOD 18 - UPDATE					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 23-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ASC ASC039A	ASC039A - FLIGHT CONTROLS (ATA 27) - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE V9.5, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 13-SEP-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
FAA 2020-02-18							
ASC ASC041A	ASC041A - INTEGRATED MODULAR AVIONICS (ATA 42) - DATA CONCENTRATION NETWORK (DCN) SOFTWARE V10.10.12 UPDATE, AIRCRAFT SERVICE CHANGE (RECOMMENDED)					RECOMMENDED	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 09-APR-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC046A	ASC046A - DOORS (ATA 52) - AIRSTAIR BOTTOM FOLDING STEP DAMAGE MITIGATION - MODIFICATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 20-MAY-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC049	ASC049 - INFORMATION SYSTEMS (ATA 46) - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM (AHTMS) V4.0 SOFTWARE UPDATE, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 31-MAY-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC051	ASC051 - HYDRAULIC POWER (ATA 29) - AUXILIARY HYDRAULIC PUMP POWER CABLE BRACKET - INSTALLATION, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 26-AUG-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC054	ASC054 - COMMUNICATIONS (ATA 23) - COMMUNICATION MANAGEMENT FUNCTION (CMF) SATCOM DIRECT (NON - SITA) DATALINK SERVICE PROVIDER, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Complied With
Eff. Date: 07-MAR-2023		MOS		11-MAY-2023			
		HRS/MSC	-	20.8	-		
		AFL		9			
ASC ASC066 PART 1	ACCOMPLISH ASC066 - LANDING GEAR (ATA 32) - MAIN LANDING GEAR DOOR AND FAIRING DOOR STOP BOLT - MODIFICATION, AIRCRAFT SERVICE CHANGE ASC066 PART 1 - MLG DOOR & MLG FAIRING DOOR STOP BOLT MODIFICATION (OPTIONAL)					OPTIONAL	Complied With
Eff. Date: 23-FEB-2024		MOS		22-APR-2025			
		HRS/MSC	-	399.5	-		
		AFL		300			
ASC ASC900A	ASC900A - INTEGRATED MODULAR AVIONICS (ATA 42) - SYMMETRY FLIGHT DECK MASTER OPERATING SYSTEM SOFTWARE UPDATE					CANCELLED	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 15-OCT-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
ASC ASC901B	ASC901B - INTEGRATED MODULAR AVIONICS (ATA 42) - SYMMETRY FLIGHT DECK MASTER OPERATING SYSTEM SOFTWARE UPDATE, AIRCRAFT SERVICE CHANGE (OPTIONAL)					OPTIONAL	Not Applicable - PRODUCTION EQUIVALENT
Eff. Date: 09-APR-2021		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB001	CB001 - REPLACEMENT - LIFE RAFT CONTAINING SRB406 ELT					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 15-MAR-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB002	CB002 - INSPECTION - FLAP ACTUATOR ANTI-ROTATION CLIPS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 29-MAR-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB003	CB003 - EQUIPMENT / FURNISHINGS (ATA 25) - INSTALLATION – DIVAN AIRBAG RESTRAINT SYSTEM ELECTRONIC MODULE ASSEMBLY CONTAINMENT BAG					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 05-APR-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB004	CB004 - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR DOOR ACTUATORS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 17-APR-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB005	CB005 - NACELLES AND PYLONS (ATA 54) - INSPECTION - INLET COWL INSULATION BLANKET INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 19-APR-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB006	CB006 - HYDRAULIC POWER (ATA 29) - INSPECTION - POWER TRANSFER UNIT HYDRAULIC TUBE CLEARANCE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 07-MAY-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB007	CB007 - STANDARD MAINTENANCE PRACTICES - ENGINES (ATA 70) - INSPECTION - ENGINE HYDRAULIC LINES					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 23-MAY-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB008	CB008 - WINGS (ATA 57) - INSPECTION - LOWER WING SKIN FASTENERS OVERCOAT					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 04-JUN-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB009A	CB009A - INSPECTION – FASTENER INSTALLATION AT FUSELAGE STATION (FS) 882.5 SKIN SPLICE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 25-JUN-2019		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB010	CB010 - FUSELAGE STRUCTURE (ATA 53) - INSPECTION - ENGINE MOUNT STRUT FITTINGS INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 25-JUN-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB011	CB011 - INSPECTION - MAIN ENTRANCE DOOR LOWER SEAL RETAINER					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 10-JUL-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB012	CB012 - INSPECTION – BRACKET INSTALLATION AT FUSELAGE STATION (FS) 927, RIGHT SIDE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 26-JUL-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB013	CB013 - WINGS (ATA 57) - INSPECTION - WIRING HARNESS INSTALLATION IN LEFT MAIN LANDING GEAR WHEEL WELL					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 14-AUG-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB014	CB014 - ELECTRICAL POWER (ATA 24), INSPECTION – AC MODULAR POWER TILE HARNESS IN BAGGAGE COMPARTMENT					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 22-AUG-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB015	CB015 - INSPECTION – AUXILIARY POWER UNIT (APU) BLEED AIR DUCT FIRE BOOT CLAMP					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 22-AUG-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB016	CB016 - BATTERY CHARGER, P/N 100-1311-01, UPGRADE TO MOD 11					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 27-AUG-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB017	CB017 - INSPECTION - OPTIONS SOFTWARE CONFIGURATION PART NUMBER					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 27-AUG-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB018	CB018 - PNEUMATIC SYSTEMS (ATA 36) - INSPECTION - RIGHT SIDE FAN AIR VALVE BONDING WIRE INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 18-SEP-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB019	CB019 - EXHAUST (ATA 78) - INSPECTION - THRUST REVERSER DOOR RUB BLOCK SHIMS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 27-SEP-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB020	CB020 - EQUIPMENT AND FURNISHINGS (ATA 25) - INSTALLATION - FLIGHT DECK INTERIOR, OVERHEAD TRIM RING (ASC 024)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 14-OCT-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB021	CB021 - WINGS (ATA 57) - INSTALLATION - WING SPLICE BLO, SEAL DAM (ASC 026B)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 23-OCT-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB022A	CB022A - NACELLES AND PYLONS (ATA 54) - INSPECTION - PYLON RIB SEALING					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 15-NOV-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB023	CB023 - ELECTRICAL WIRING INSTALLATION (ATA 97) - INSPECTION - PEDESTAL NO. 1 HARNESS ASSEMBLY GROUND TERMINALS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 05-DEC-2019		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB024	CB024 - WATER/WASTE (ATA 38) - INSPECTION - WASTE TANK INLET CONNECTIONS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 10-JAN-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB025	CB025 - HYDRAULIC POWER (ATA 29) - INSPECTION - MAIN LANDING GEAR UPLOCK CONTROL - BULKHEAD FITTINGS INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 10-JAN-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB026	CB026 - FUEL (ATA 28) - INSPECTION - FUEL BOOST PUMPS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 07-FEB-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB027	CB027 - EQUIPMENT AND FURNISHINGS (ATA 25) - INSPECTION - PASSENGER SEAT COMPOSITE COMPONENTS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 20-FEB-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB028	CB028 - HYDRAULIC POWER (ATA 29) - REPLACEMENT - RIGHT WING SYSTEM 2 RETURN TUBE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 12-MAR-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB029	CB029 - ENGINE FUEL AND CONTROL (ATA 73) - ENGINE ELECTRONIC CONTROLLER 5.4.2.4 SOFTWARE UPDATE (ASC 022)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 30-APR-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB030	CB030 - ENGINE (ATA 72) - MODIFICATION - FAN CASE REPLACEMENT (PRATT & WHITNEY CANADA SB PW800-72-80173)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 30-APR-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB031	CB031 - FUESELAGE STRUCTURE (ATA 53) - INSPECTION - RADOME HARDWARE INSTALLATIONS FOR TOOLING MARKS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 28-MAY-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB032	CB032 - FUSELAGE (ATA 53) - INSPECTION - RADOME HINGE OVER-TRAVEL STOP					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 11-JUN-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB033	CB033 - FLIGHT CONTROLS (ATA 27) - MODIFICATION - REU SOFTWARE UPDATE (ASC 037) AND EBMCE FIRMWARE UPDATE (ASC 038)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 01-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB034	CB034 - PLACARDS AND MARKINGS (ATA 11) - INSTALLATION - PLACARD, ELECTRIC MAIN ENTRY DOOR (EMED) DELAYED CLOSING (ASC 035)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 01-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB035	CB035 - INTEGRATED MODULAR AVIONICS (ATA 42) - MODIFICATION – SYMMETRY FLIGHT DECK MASTER OPERATING SYSTEM SOFTWARE UPDATE (ASC 901)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 01-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB036	CB036 - COMMUNICATIONS (ATA 23) - INSPECTION - HIGH FREQUENCY ANTENNA COUPLER MOUNTING TRAY FASTENERS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 22-JUL-2020		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB037	CB037 - ELECTRICAL WIRING INSTALLATIONS (ATA 97) - REWORK OF CONNECTOR PINS ON FLIGHT CONTROL HARNESS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 22-JUL-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB038	CB038 - ELECTRICAL POWER (ATA 24) - INSPECTION - APU AND IDG POWER FEEDER CABLES					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 23-JUL-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB039	CB039 - DOORS (ATA 52) - INSPECTION - MAIN ENTRANCE DOOR TELESCOPING - RODS INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 06-AUG-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB040	CB040 - WATER/WASTE (ATA 38) - INSPECTION - WATER SYSTEM PNEUMATIC LINES - WARNING LABELS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 13-AUG-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB041	CB041 - FUEL (ATA 28) - INSPECTION - AUXILIARY POWER UNIT (APU) FUEL SUPPLY LINE INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 23-SEP-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB042	CB042 - NACELLES AND PYLONS (ATA 54) - INSPECTION - ENVIRONMENTAL CONTROL SYSTEM (ECS) DUCT BOOT INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 23-SEP-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB043	CB043 - FUEL (ATA 28) - INSPECTION - FUEL TANK EJECTOR PUMP MOUNTING BRACKET					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 14-OCT-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB044	CB044 - HYDRAULIC POWER (ATA 29) - INSPECTION - SYSTEM 1 RETURN TUBE IN WING INBOARD FIXED TRAILING EDGE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 18-NOV-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB045	CB045 - WINGS (ATA 57) - REPLACEMENT - FLAP YOKE (ASC 032)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 20-NOV-2020		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
FAA 2021-15-03							

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB046A	CB046A - CB046A - FLIGHT CONTROLS (ATA 27), INSPECTION - RUDDER PEDAL ASSEMBLIES - PEDAL ARM WALL THICKNESS					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 18-NOV-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB047	CB047 - FUEL (ATA 28) - INSPECTION - PRESSURE FUELING / DEFUELING ADAPTER FUEL TUBE COUPLING					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 10-FEB-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB048	CB048 - CB048 - AIR CONDITIONING (ATA 21) - INSPECTION - RAM AIR INLET DUCT HARDWARE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 14-APR-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB049	CB049 - CB049 - NACELLES AND PYLONS (ATA 54) - INSPECTION - BONDING TERMINAL INSTALLATION ON ENGINE APRON COWL					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 01-JUN-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB050	CB050 - WINGS (ATA 57) - INSPECTION - FLAP AFT SPAR BEAM SEALING					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 05-AUG-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB051A	CB051A - COMMUNICATIONS (ATA 23) - MODIFICATION - JETWAVE SYSTEM BLV8.1 SOFTWARE RELEASE (HONEYWELL SB JETWAVE-23-0009)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 14-MAR-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB052A	CB052A - NACELLES AND PYLONS (ATA 54) - INSPECTION - ENGINE UPPER FAN COWLS PRESSURE RELIEF DOOR					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 09-SEP-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB053	CB053 - POWERPLANT (ATA 71) - INSPECTION - ENGINE DUCTING V-BAND CLAMP INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 19-OCT-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB054	CB054 - NACELLES AND PYLONS (ATA 54) - INSPECTION - ENGINE APRON COWL BONDING - SEALANT OVERCOAT APPLICATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 11-NOV-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB055	CB055 - DOORS (ATA 52), DEACTIVATION - SECURITY SYSTEM					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 08-DEC-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB056	CB056 - COMMUNICATIONS (ATA 23) - INSPECTION - LEFT NETWORK INTERFACE MODULE CONNECTOR					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 18-FEB-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB057	CB057 - ENGINE (ATA 72) - INSPECTION - ACCESSORY GEARBOX INTEGRATED OIL TANK FIRE BLANKET INSTALLATION (PW800-72-80216)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 10-DEC-2021		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB058	CB058 - DOORS (ATA 52) MODIFICATION - ELECTRICAL MAIN ENTRY DOOR WIRING HARNESS (ASC 018)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 08-MAR-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB059	CB059 - DOORS (ATA 52) - MODIFICATION - WIRING, ELECTRIC MAIN ENTRY DOOR (EMED) DELAYED CLOSING (ASC 036)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 08-MAR-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB060	CB060 - CB060 - DOORS (ATA 52) - MODIFICATION - AIRSTAIR BOTTOM FOLDING STEP DAMAGE MITIGATION (ASC 046)					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 08-MAR-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB061	CB061 - CB061 - INTEGRATED MODULAR AVIONICS (ATA 42), INSPECTION - LEFT MODULAR AVIONICS UNIT (MAU) NETWORK INTERFACE CONTROLLER AND PROCESSOR (NIC/PROC) CONNECTOR BACKSHELL					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 17-MAR-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB062	CB062 - CB062 - FUEL (ATA 28) - INSPECTION - FUEL TANK EJECTOR PUMP SEALANT APPLICATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 12-APR-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		
CB CB063A	CB063A - CB063A - FUSELAGE STRUCTURE (ATA 53) INSPECTION - AUXILIARY POWER UNIT ENCLOSURE					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 26-JUL-2022		MOS HRS/MSC AFL	-	10-JAN-2023 5.03 2	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB064	CB064 - CB064 - NAVIGATION (ATA 34) - ENHANCED VISION SYSTEM (EVS) WINDOW FRAME - MODIFICATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 12-AUG-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB065	CB065 - CB065 - COMMUNICATIONS (ATA 23) INSPECTION - FORWARD BELLY CAMERA MOD LEVEL 1					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 25-AUG-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB066	CB066 - CB066 - FIRE PROTECTION (ATA 26) INSPECTION - ENGINE FIRE BOTTLE THERMAL RELIEF DISCHARGE PORT					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 25-AUG-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB067	CB067 - CB067 - HYDRAULIC POWER (ATA 29) - INSPECTION - AUXILIARY HYDRAULIC PUMP POWER CABLES					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 26-AUG-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB068	CB068 - CB068 - EXHAUST (ATA 78), INSPECTION - THRUST REVERSER FORWARD HARNESS - SUPPORT BRACKET INSTALLATION					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 12-OCT-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB069	CB069 - CB069 - FUEL (ATA 28), INSPECTION - FUEL BOOST PUMP IMPELLER SHAFT KEY					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 19-OCT-2022		MOS		10-JAN-2023			
		HRS/MSC	-	5.03	-		
		AFL		2			
CB CB069A	CB069A - CB069A - FUEL (ATA 28) - INSPECTION - FUEL BOOST PUMP IMPELLER SHAFT KEY					MANDATORY	Not Applicable
Eff. Date: 19-OCT-2022		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
FAA 2024-05-04							
CB CB070	CB070 - CB070 - WINGS (ATA 57) - REPLACEMENT - WING JACK PAD PLACEHOLDER BOLTS					MANDATORY	Not Applicable
Eff. Date: 31-JAN-2023		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CB CB071	CB071 - CB071 - FUSELAGE (ATA 53) - INSPECTION ELECTRICAL GROUND IDENTIFICATION DECAL - FS 199.8					MANDATORY	Not Applicable
Eff. Date: 22-FEB-2023		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CB CB072	CB072 - CB072 - EQUIPMENT AND FURNISHINGS (ATA 25) - REPLACEMENT - AFT FACING DOUBLE SEAT HEADRESTS					MANDATORY	Not Applicable
Eff. Date: 28-FEB-2023		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB073	CB073 - CB073 - FUSELAGE (ATA 53) - INSPECTION WING TO FUSELAGE AFT VERTICAL LINK WASHER INSTALLATION					MANDATORY	Not Applicable
Eff. Date: 07-MAR-2023		MOS HRS/MSC AFL	-	11-APR-2023 7.5 3	-		
CB CB074	CB074 - CB074 - INDICATING / RECORDING SYSTEMS (ATA 31) - REPLACEMENT - OVERHEAD PANEL TOUCH SCREEN HARDWARE (KORRY SB 1401100-25-02)					MANDATORY	Not Applicable
Eff. Date: 15-MAR-2023		MOS HRS/MSC AFL	-	11-APR-2023 7.5 3	-		
CB CB074A	CB074A - INDICATING / RECORDING SYSTEMS (ATA 31) REPLACEMENT - OVERHEAD PANEL TOUCH SCREEN HARDWARE (KORRY SB 1401100-25-02), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 15-MAR-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB075	CB075 - CB075 - OXYGEN (ATA 35) - INSPECTION - PASSENGER OXYGEN CONTROLLER ELECTRICAL HARNESS INSTALLATION					MANDATORY	Not Applicable
Eff. Date: 21-MAR-2023		MOS HRS/MSC AFL	-	11-APR-2023 7.5 3	-		
CB CB075A	CB075A - OXYGEN (ATA 35) - INSPECTION - PASSENGER OXYGEN CONTROLLER ELECTRICAL HARNESS INSTALLATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - INSPECTION OF OXYGEN CONTROLLER HARNESS FOR CORRECT SUPPORT PERFORMED IAW CB075A ACCOMPLISHMENT INSTRUCTIONS AND FOUND PROPERLY SUPPORTED. NO FURTHER ACTION IS REQUIRED.
Eff. Date: 21-MAR-2023		MOS HRS/MSC AFL	-	19-MAY-2025 399.5 300	-		
CB CB079	CB079 - ELECTRICAL POWER (ATA 24) INSPECTION - COCKPIT OVERHEAD CIRCUIT BREAKER PANEL (KORRY ELECTRONICS SB 1401200-25-01), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 15-JUN-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB080	CB080 - EQUIPMENT / FURNISHINGS (ATA 25) REPLACEMENT - COCKPIT OVERHEAD SWITCH PANEL HARDWARE (KORRY ELECTRONICS SB 1401100-25-03), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 15-JUN-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB081	CB081 - DOORS (ATA 52) - REPLACEMENT - ELECTRIC MAIN ENTRANCE DOOR (EMED) MANUAL UNLATCH HANDLE ASSEMBLY, CUSTOMER BULLETIN						Declined - SUPERCEDED BY CB081A
		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB081A	CB081A - DOORS (ATA 52) - REPLACEMENT ELECTRIC MAIN ENTRANCE DOOR (EMED) MANUAL UNLATCH HANDLE ASSEMBLY, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - REPLACEMENT OF MAIN ENTRANCE DOOR UNLATCH HANDLE PERFORMED IAW CB NO. 081A ACCOMPLISHMENT INSTRUCTIONS. MAIN DOOR NORMAL OPERATION TEST PERFORMED IWA GULFSTREAM GVII-G500 AMM TASK 52-10-01 REV. 20 - FOUND OK.PN OFF: 72P5210124M033 SN OFF: MED-72113 / PN ON: 72P5210124M075 SN ON: RD166027
Eff. Date: 07-JUL-2023		MOS HRS/MSC AFL	-	20-MAY-2025 399.5 300	-		
CB CB082	CB082 - FLIGHT CONTROLS (ATA 27) - REPLACEMENT - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ROTARY VARIABLE DIFFERENTIAL TRANSDUCERS (RVDTS), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Declined - SUPERSEDED BY CB082A
Eff. Date: 21-JUL-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB082A	CB082A - FLIGHT CONTROLS (ATA 27) - REPLACEMENT - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ROTARY VARIABLE DIFFERENTIAL TRANSDUCERS (RVDTS), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 21-JUL-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB083	CB083 - LANDING GEAR (ATA 32) - INSPECTION - NOSE LANDING GEAR CONTROL MANIFOLD CONNECTOR, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Declined - CANCELLED/SUPERSEDED
Eff. Date: 04-AUG-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB083A	CB083A - LANDING GEAR (ATA 32) - INSPECTION - NOSE LANDING GEAR CONTROL MANIFOLD CONNECTOR, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 05-SEP-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB084	CB084 - COMMUNICATIONS (ATA 23) - INSTALLATION - GOGO ST4300 SOFTWARE UPGRADE (TB - 150-ADVISORY), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 18-AUG-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB085	CB085 - NAVIGATION (ATA 34) - MODIFICATION - WEATHER RADAR SYSTEM PROCESSOR V3 SOFTWARE RELEASE (HONEYWELL SB 930-1006-34-0003), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - FROM MANUFACTURE
Eff. Date: 12-SEP-2023		MOS HRS/MSC AFL	-	10-FEB-2024 173.5 148	-		
CB CB086	CB086 - NAVIGATION (ATA 34) - MODIFICATION - WEATHER RADAR SYSTEM PROCESSOR V3 PART NUMBER CONVERSION (HONEYWELL SB 930-1003-34-0004), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 12-SEP-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB087	CB087 - EXHAUST (ATA 78) - MODIFICATION - THRUST REVERSER LATCH ACTUATOR, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With
Eff. Date: 26-SEP-2023		MOS HRS/MSC AFL	-	26-JAN-2024 171.3 146	-		
CB CB087A	CB087A - EXHAUST (ATA 78), MODIFICATION - THRUST REVERSER LATCH ACTUATOR, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - PREVIOUSLY COMPLIED WITH
Eff. Date: 26-SEP-2023		MOS HRS/MSC AFL	-	18-JUN-2024 228.7 195	-		
CB CB088	CB088 - ELECTRICAL POWER (ATA 24) - INSPECTION - AIRCRAFT MAIN BATTERIES (SAFT SB0323), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 10-NOV-2023		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB089A	CB089A - FUEL (ATA 28) - SEALANT APPLICATION - OVERWING GROUNDING RECEPTACLE (ASC 064), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With
Eff. Date: 28-NOV-2023		MOS HRS/MSC AFL	-	03-JUN-2026 590.6 408	-		
CB CB090	CB090 - EQUIPMENT/FURNISHINGS (ATA 25) - MODIFICATION - GALLEY MICROWAVE OVEN (SAFRAN SB-MW-159), CUSTOMER BULLETIN						Declined - CANCELLED/SUPERSEDED
		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB090A	CB090A - EQUIPMENT/FURNISHINGS (ATA 25) - MODIFICATION - GALLEY MICROWAVE OVEN (SAFRAN SB-MW-159), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Declined - NEWER REVISION AVAILABLE
Eff. Date: 13-DEC-2023		MOS HRS/MSC AFL	-	18-JUN-2024 228.7 195	-		
CB CB090B	CB090B - EQUIPMENT/FURNISHINGS (ATA 25) - MODIFICATION - GALLEY MICROWAVE OVEN (SAFRAN SB-MW-159), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - GALLEY MICROWAVE OVEN MODIFICATION PERFORMED IAW CB NO. 090B ACCOMPLISHMENT INSTRUCTIONS AND SAFRAN SB NO. SB-MW-159 REV. 01
Eff. Date: 05-DEC-2023		MOS HRS/MSC AFL	-	19-MAY-2025 399.5 300	-		
CB CB091	CB091 - POWERPLANT (ATA 71) - INSPECTION - INLET BARREL ACOUSTIC LINER PERFORATED HOLES, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY S/N
Eff. Date: 12-JAN-2024		MOS HRS/MSC AFL	-	13-JAN-2024 171.3 146	-		
CB CB092	CB092 - POWERPLANT (ATA 71) INSPECTION - ENGINE MOUNT HARDWARE CONFIGURATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Declined - NEWER REVISION AVAILABLE
Eff. Date: 15-FEB-2024		MOS HRS/MSC AFL	-	18-JUN-2024 228.7 195	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB092A	CB092A - POWERPLANT (ATA 71) - INSPECTION - ENGINE MOUNT HARDWARE CONFIGURATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - CUSTOMER BULLETIN (MANDATORY) CB092A: POWERPLANT - INSPECTION - LEFT AND RIGHT ENGINE MOUNT HARDWARE CONFIGURATION PERFORMED IAW PROCEDURE CUSTOMER BULLETIN NO. 092, REVISION A PERFORMED - ALL FITTING AND HARDWARE ORIENTATION FOUND CORRECT ON BOTH ENGINES.
Eff. Date: 15-FEB-2024		MOS HRS/MSC AFL	-	24-MAY-2024 217.9 180	-		
FAA 2024-10-15							
CB CB093	CB093 - DOORS (ATA 52) - INSPECTION - EMERGENCY EXIT DOOR (EED) STOP BOLTS AND FITTINGS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 22-FEB-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		
CB CB094	CB094 - LANDING GEAR (ATA 32) - INSPECTION - MAIN LANDING GEAR DOOR CLEARANCE, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 23-FEB-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		
CB CB095	CB095 - LANDING GEAR (ATA 32) - MODIFICATION - MAIN LANDING GEAR DOOR AND FAIRING DOOR STOP BOLT (ASC 066), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - LH AND RH MAIN LANDING GEAR DOOR AND FAIRING DOOR STOP BOLTS TORQUE CHECK PERFORMED IAW CB NO. 095 - NO JAM NUTS TURNED DURING THE TEST. ASC 066 PART 1 ACCOMPLISHMENT PERFORMED.
Eff. Date: 23-FEB-2024		MOS HRS/MSC AFL	-	21-MAY-2025 399.5 300	-		
CB CB096	CB096 - PNEUMATIC SYSTEMS (ATA 36) - REPLACEMENT - HIGH STAGE VALVE (HSV), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - CUSTOMER BULLETIN CB-096 - PNEUMATIC SYSTEMS (ATA 36) PERFORMED. HIGH STAGE VALVES REPLACED IAW GVII 500 REV. 20 AMM 36-12-01.
Eff. Date: 19-MAR-2024		MOS HRS/MSC AFL	-	29-MAY-2025 399.5 300	-		
CB CB097	CB097 - EXHAUST (ATA 78) - INSPECTION - APRON PIN LATCH RECEPTACLE GAP, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 02-APR-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		
CB CB098	CB098 - HYDRAULIC POWER SYSTEM (ATA 29), INSPECTION - HYDRAULIC PRESSURE TUBE CLEARANCE, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 05-APR-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB099	CB099 - FUEL (ATA 28) - INSPECTION - FUEL QUANTITY MEASURING SYSTEM (FQMS) IN-WING HARNESS (EATON VSB 62826-00), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 08-APR-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		
CB CB100	CB100 - FUEL (ATA 28) - INSPECTION - FUEL QUANTITY MEASURING SYSTEM - DENSITOMETER, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Not Applicable - BY SERIAL NUMBER
Eff. Date: 08-APR-2024		MOS HRS/MSC AFL	-	01-APR-2024 209.6 171	-		
CB CB102	CB102 - PNEUMATIC SYSTEMS (ATA 36) - INSPECTION - TOTAL AIR TEMPERATURE TUBE PRESSURE TEST, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - TOTAL AIR TEMPERATURE TUBES PN: 72P3610006A009/72P3610006A013 AND 72P3610006A003/72P3610006A015 PRESSURE TEST HAS BEEN PERFORMED IAW CB NO. 102 ACCOMPLISHMENT INSTRUCTIONS - TEST PASSED. NO FURTHER ACTION REQUIRED.
Eff. Date: 10-MAY-2024		MOS HRS/MSC AFL	-	27-MAY-2025 399.5 300	-		
CB CB104	CB104 - ELECTRICAL WIRING INSTALLATIONS (ATA 97) - INSPECTION - POWER DISTRIBUTION BOX (PDB) HARNESS GASKETS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - INSPECTION OF POWER DISTRIBUTION BOX (PDB) HARNESS GASKETS ON ELECTRICAL CONNECTORS NO. 311DB03J1/P1, 311DB03J2/P2, 311DB03J3/P3 AND 311DB03J4/P4 PERFORMED IAW CB NO. 104 ACCOMPLISHMENT INSTRUCTIONS. CONDUCTIVE GASKETS FOUND INSTALLED BETWEEN SURFACE AND ALL RECEPTACLES. BASED ON CB NO. 104 STEP III.C.2 NO FURTHER ACTION REQUIRED.
Eff. Date: 11-JUN-2024		MOS HRS/MSC AFL	-	22-MAY-2025 399.5 300	-		
CB CB105A	CB105A - EXHAUST (ATA 78) - REPLACEMENT - THRUST REVERSER DRIVER LINKS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 19-JUN-2024		MOS HRS/MSC	48		19-JUN-2028		
CB CB106	CB106 - FUEL (ATA 28) - INSPECTION - FUEL BOOST PUMP GROUND TERMINALS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - GROUND TERMINALS HAVE BEEN REPLACED.
Eff. Date: 27-JUN-2024		MOS HRS/MSC AFL	-	03-JUN-2026 590.6 408	-		
CB CB108 PART I	ACCOMPLISH CB108 - AUXILIARY POWER UNIT (ATA 49) - INSPECTION / MODIFICATION - APU EXHAUST HEAT INGRESS AND DUCT EXTENSION (ASC 056), CUSTOMER BULLETIN CB108 PART I - PERFORM AN INITIAL VISUAL INSPECTION OF THE HEAT AFFECTED ZONE AROUND THE APU EXHAUST DUCT FOR SOOTING, DISCOLORATION, AND DEFORMATION & APPLICABLE CORRECTIVE ACTION (MANDATORY)					MANDATORY	
Eff. Date: 15-AUG-2024		MOS	36		15-AUG-2027		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB108 PART II	ACCOMPLISH CB108 - AUXILIARY POWER UNIT (ATA 49) - INSPECTION / MODIFICATION - APU EXHAUST HEAT INGRESS AND DUCT EXTENSION (ASC 056), CUSTOMER BULLETIN CB108 PART II - PERFORM SGER-0129, APU EXHAUST DUCT ALIGNMENT, TO REDUCE THE POSSIBILITY OF APU EXHAUST GAS REINGESTION AND SOOTING. (MANDATORY)					MANDATORY	
Eff. Date: 15-AUG-2024		MOS	36		15-AUG-2027		
CB CB108 PART III	ACCOMPLISH CB108 - AUXILIARY POWER UNIT (ATA 49) - INSPECTION / MODIFICATION - APU EXHAUST HEAT INGRESS AND DUCT EXTENSION (ASC 056), CUSTOMER BULLETIN CB108 PART III - INCORPORATES ASC 056, AUXILIARY POWER UNIT (ATA 49) EXHAUST DUCT EXTENSION - INSTALLATION, TO PREVENT APU EXHAUST GAS REINGESTION AND SOOTING (MANDATORY)					MANDATORY	
Eff. Date: 15-AUG-2024		MOS	48		15-AUG-2028		
CB CB111	CB111 - WINGS (ATA 57) - INSPECTION - SINGLE POINT REFUEL SERVICE PANEL LIGHT GROMMET, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - INSPECTION OF SINGLE POINT REFUEL SERVICE PANEL LIGHT FOR GROMMET PRESENCE PERFORMED IAW CB NO. 111 ACCOMPLISHMENT INSTRUCTIONS - GROMMET FOUND INSTALLED. NO FURTHER ACTION REQUIRED.
Eff. Date: 09-OCT-2024		MOS HRS/MSC AFL	-	15-MAY-2025 399.5 300	-		
CB CB112	CB112 - LANDING GEAR (ATA 32) - BRAKE WEAR PIN MODIFICATION (PARKER MEGGITT SB90008562-32-01), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With
Eff. Date: 18-OCT-2024		MOS HRS/MSC AFL	-	16-JUN-2026 590.6 408	-		
CB CB113	CB113 - WINGS (ATA 57) - INSPECTION - WING ELECTRICAL CONNECTOR DECAL INSTALLATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 22-OCT-2024		MOS	48		22-OCT-2028		
CB CB115	CB115 - AIRCRAFT EQUIPMENT AND FURNISHINGS (ATA 25) - INSPECTION - FLIGHT DECK STEPWELL STORAGE BOXES, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - INSPECTION OF FLIGHT DECK STEPWELL STORAGE BOXES FOR CORRECT WEIGHT PLACARDS PERFORMED IAW CB NO. 115 ACCOMPLISHMENT INSTRUCTIONS AND FOUND CORRECT WEIGHT PLACARDS INSTALLED - NO FURTHER ACTION REQUIRED.
Eff. Date: 15-JAN-2025		MOS HRS/MSC AFL	-	19-MAY-2025 399.5 300	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB124	CB124 - ELECTRICAL POWER (ATA 24) - REPLACEMENT - BATTERY CHARGERS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With - INSPECTION OF LEFT, RIGHT, EBHA AND UPS BATTERY CHARGERS PERFORMED IAW CB NO. 124 ACCOMPLISHMENT INSTRUCTIONS. FOLLOWING SNS INSTALLED: LEFT BATTERY CHARGER: 1212985 RIGHT BATTERY CHARGER: 1214024 EBHA BATTERY CHARGER: 1214032 UPS BATTERY CHARGER: 11213011 ONLY EBHA BATTERY CHARGER AFFECTED BY CB.
Eff. Date: 15-APR-2025		MOS		20-MAY-2025			
		HRS/MSC	-	399.5	-		
		AFL		300			
CB CB125	CB125 - WINGS (ATA 57), INSPECTION - WING CABLE TIE MOUNT INSTALLATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With
Eff. Date: 22-MAY-2025		MOS		26-MAY-2026			
		HRS/MSC	-	590.6	-		
		AFL		408			
CB CB128	CB128 - HYDRAULIC POWER (ATA 29), INSPECTION - HYDRAULIC RESERVOIR RELIEF VALVE, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 08-JUL-2025		MOS	36		08-JUL-2028		
CB CB129A	CB129A - FUEL (ATA 28) - INSPECTION – SINGLE POINT REFUELING SYSTEM BRACKET ALIGNMENT, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 06-AUG-2026		MOS	24		06-AUG-2027		
		HRS/MSC					
CB CB130	CB130 - PNEUMATIC SYSTEMS (ATA 36), INSPECTION - AFT EQUIPMENT BAY BLEED DUCT ALIGNMENT, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 15-AUG-2025		MOS	24		15-AUG-2027		
CB CB131	CB131 - EXHAUST (ATA 78), INSPECTION - THRUST REVERSER ASSEMBLY HARDWARE, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 05-SEP-2025		MOS	24		05-SEP-2027		
CB CB133	CB133 - ELECTRICAL POWER (ATA 24), INSPECTION - LEFT MAIN BATTERY CONNECTOR TERMINAL LUGS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 11-SEP-2025		MOS	36		11-SEP-2028		
CB CB134	CB134 - AUXILIARY POWER UNIT (ATA 49) - INSPECTION - BONDING STRAP INSTALLATION, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 29-OCT-2025		MOS	24		29-OCT-2027		
CB CB135	CB135 - LANDING GEAR (ATA 32) INSPECTION - MAIN LANDING GEAR TIRES, CUSTOMER BULLETIN						Not Applicable
Eff. Date: 18-DEC-2025		MOS		28-APR-2026			
		HRS/MSC	-	585	-		
		AFL		405			
CB CB137	CB137 - DOORS (ATA 52) - SECURITY SYSTEM BATTERY - REPLACEMENT (ASC 057), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 28-JAN-2026		MOS	48		28-JAN-2030		

Model: GVII-G500 Serial: 72113 RegNo: OK-HUB HRS: 590.9 AFL: 409 As Of: 24-Jun-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CB CB138	CB138 - EQUIPMENT AND FURNISHINGS (ATA 25) - REPLACEMENT - HEADREST RODS FOR AFT-FACING SINGLE AND DOUBLE SEATS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	Complied With
Eff. Date: 03-FEB-2026		MOS		03-JUN-2026			
		HRS/MSC	-	590.6	-		
		AFL		408			
CB CB138A	EQUIPMENT AND FURNISHINGS (ATA 25) - REPLACEMENT - HEADREST RODS FOR AFT-FACING DOUBLE SEATS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 10-JUN-2026		MOS	12		10-JUN-2027		
CB CB139A	FLIGHT CONTROLS (ATA 27) - INSPECTION - REMOTE ELECTRONICS UNIT (REU) NO. 8 CONNECTORS, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 27-FEB-2026		MOS	24		27-FEB-2028		
		HRS/MSC					
CB CB140	FLIGHT CONTROLS (ATA 27) - REMOTE ELECTRONICS UNIT (REU) SOFTWARE LABEL 41 – UPDATE (ASC 006), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 27-FEB-2026		MOS	36		27-FEB-2029		
CB CB141	DOORS (ATA 52) - MED BOTTOM FOLDING STEP WIRE HARNESS - MODIFICATION (ASC 045), CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 17-APR-2026		MOS	36		17-APR-2029		
CB CB142	FUSELAGE STRUCTURE (ATA 53) - INSPECTION - RADOME ELECTRICAL BONDING, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
Eff. Date: 11-MAY-2026		MOS	24		11-MAY-2028		
CSB CSB001	CE-CSB-72001 - CSB001 - ADVANCED CABIN SERVER (ACS) (GEN 5) CABINVIEW™ SOFTWARE UPGRADE					OPTIONAL	Not Applicable
		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB002	CE-CSB-72002 - CSB002 - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE					OPTIONAL	Not Applicable
		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB003	CE-CSB-72003 - CSB003 CABIN SERVICE BULLETIN 003 GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE V2.1.0					OPTIONAL	Not Applicable
		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB004	CE-CSB-72004 - CSB004 - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE V2.2.3					RECOMMENDED	Not Applicable
Eff. Date: 01-MAY-2020		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB005	CE-CSB-72005 - CSB005 - ADVANCED CABIN SERVER (ACS) (GEN 5) CABINVIEW SOFTWARE UPDATE V2.2.3					OPTIONAL	Not Applicable
Eff. Date: 14-AUG-2020		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
CSB CSB006	CE-CSB-72006 - CSB006 - CABIN SYSTEMS - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) - FIRMWARE UPDATE V2.3.0					RECOMMENDED	Not Applicable
Eff. Date: 22-OCT-2020		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB007A	CE-CSB-72007A - CSB007A - CABIN SYSTEMS - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE V2.4.0, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	Not Applicable
Eff. Date: 13-SEP-2021		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB008	CE-CSB-72008 - CSB008 - CABIN SYSTEMS - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE					RECOMMENDED	Not Applicable
Eff. Date: 06-DEC-2021		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB009	CE-CSB-72009 - CSB009 - CABIN PROCESSOR UNIT (GEN 5) CABINVIEW SOFTWARE UPDATE V2.2.5, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	Not Applicable
Eff. Date: 31-DEC-2021		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB010	CE-CSB-72010 - CSB010 - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE V2.4.4, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	Not Applicable
Eff. Date: 22-APR-2022		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB011	CE-CSB-72011 - CSB011 - CABIN SYSTEMS - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE V2.4.9, CABIN SERVICE BULLETIN (RECOMMENDED)					RECOMMENDED	Not Applicable
Eff. Date: 22-MAR-2023		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
CSB CSB700	CE-CSB-700-G5Z - CSB700 - HEADS UP TECHNOLOGIES SERVICE BULLETIN SOFTWARE UPDATE					RECOMMENDED	Not Applicable
Eff. Date: 12-MAR-2021		MOS		11-APR-2023			
		HRS/MSC	-	7.5	-		
		AFL		3			
STC ST04310AT-D	AIRPLANE INTERIOR ST04310AT-D CERTIFICATE					OPTIONAL	Complied With
		MOS		11-APR-2023			
		HRS/MSC	-	5.2	-		
		AFL		2			
STC ST04312AT-D	STC ST04312AT-D - KA BAND JETWAVE ST04312AT-D CERTIFICATE					OPTIONAL	Complied With
		MOS		11-APR-2023			
		HRS/MSC	-	5.2	-		
		AFL		2			
STC ST04343AT-D	STC ST04343AT-D AIR IONIZER SYSTEM						Complied With
		MOS		11-APR-2023			
		HRS/MSC	O/C	5.2	-		
		AFL		2			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 1 - AD - PW814GA PCE-GA0486/33B1170-01							
TCCA CF-2023-73	NO. 1 ENGINE - TIME LIMITS/MAINTENANCE CHECKS - NEW AIRWORTHINESS LIMITATIONS (MANDATORY)					MANDATORY	Complied With - LIFE LIMITS UPDATED IN CMP AND IN AMP REV.01
Eff. Date: 17-NOV-2023		MOS		07-NOV-2023			
		HRS/MSC	-	150.6	-		
		ENC		138			
TCCA CF-2025-71	NO. 1 ENGINE - TIME LIMITS/MAINTENANCE CHECKS (TLMC) - NEW AIRWORTHINESS LIMITATIONS (MANDATORY)					MANDATORY	Complied With
Eff. Date: 13-JAN-2026		MOS		23-APR-2026			
		HRS/MSC	-	585	-		
		ENC		405			
ENGINE NO. 2 - AD - PW814GA PCE-GA0487/33B1170-01							
TCCA CF-2023-73	NO. 2 ENGINE - TIME LIMITS/MAINTENANCE CHECKS - NEW AIRWORTHINESS LIMITATIONS (MANDATORY)					MANDATORY	Complied With - LIFE LIMITS UPDATED IN CMP AND IN AMP REV.01
Eff. Date: 17-NOV-2023		MOS		07-NOV-2023			
		HRS/MSC	-	150.6	-		
		ENC		138			
TCCA CF-2025-71	NO. 2 ENGINE - TIME LIMITS/MAINTENANCE CHECKS (TLMC) - NEW AIRWORTHINESS LIMITATIONS (MANDATORY)					MANDATORY	Complied With
Eff. Date: 13-JAN-2026		MOS		23-APR-2026			
		HRS/MSC	-	585	-		
		ENC		405			
ENGINE NO. 1 - SB - PW814GA PCE-GA0486/33B1170-01							
SB PW800-26-80270	NO. 1 ENGINE - SB PW800-26-80270 - SB PW800-26-80270 - INTRODUCTION OF TURBOFAN ENGINE JUMPER CABLES (ECS-TO-AGB) OPTION					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-AUG-2022		MOS		09-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80000 R02	NO. 1 ENGINE - SB PW800-72-80000 R02 - SB PW800-72-80000 R02 - INTRODUCTION OF PERMANENT RECORD					CATEGORY 10	Complied With - AT MANUFACTURE
Eff. Date: 15-APR-2021		MOS		09-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80002 R03	NO. 1 ENGINE - SB PW800-72-80002 R03 - PW800-72-80002 R03 - REPLACEMENT OF STATOR AC GENERATOR					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-JAN-2022		MOS		09-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80003 R01	NO. 1 ENGINE - SB PW800-72-80003 R01 - REPLACEMENT OF HPC VARIABLE STAGES 1, 2 AND 3					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 20-FEB-2017		MOS		09-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80004	NO. 1 ENGINE - SB PW800-72-80004 - REPLACEMENT OF HUB TURBINE FIRST AND SECOND STAGE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 04-SEP-2015		MOS		09-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

24-Jun-2026 09:37 AM

Model: GVII-G500 Serial: 72113 RegNo: OK-HUB HRS: 590.9 AFL: 409 As Of: 24-Jun-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80008 R01	NO. 1 ENGINE - SB PW800-72-80008 R01 - REPLACEMENT OF TURBINE BLADES STAGE 5 AND 6 (IC) OPTION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-OCT-2016		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80012	NO. 1 ENGINE - SB PW800-72-80012 - REPLACEMENT OF NO.1 BRG. CARBON SEAL					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 12-APR-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80015	NO. 1 ENGINE - SB PW800-72-80015 - MODIFICATION/REPLACEMENT OF NO.3 BEARING HOUSING ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 05-APR-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80016	NO. 1 ENGINE - SB PW800-72-80016 - REPLACEMENT/MODIFICATION OF NO.3 BEARING BALL FLANGED					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 29-MAR-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80017	NO. 1 ENGINE - SB PW800-72-80017 - REPLACEMENT OF SECONDARY SYSTEM AIR COOLER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 25-AUG-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80021 R01	NO. 1 ENGINE - SB PW800-72-80021 R01 - REPLACEMENT OF MID-TURBINE FRAME MODULE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80025	NO. 1 ENGINE - SB PW800-72-80025 - REPLACEMENT OF AIR COOLER TUBE ASSEMBLY					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80026	NO. 1 ENGINE - SB PW800-72-80026 - REPLACEMENT OF AIR TRANSFER TUBE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80027 R01	NO. 1 ENGINE - SB PW800-72-80027 R01 - REPLACEMENT OF NO. 5 BEARING RADIAL-CONTACT SEAL					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-OCT-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80032	NO. 1 ENGINE - SB PW800-72-80032 - REPLACEMENT OF SEAL HOUSING KEY-WASHER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80045 R03	NO. 1 ENGINE - SB PW800-72-80045 R03 - REPLACEMENT OF PROTECTIVE CAP					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 24-AUG-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80047	NO. 1 ENGINE - SB PW800-72-80047 - REPLACEMENT OF ACTIVE CLEARANCE CONTROL (ACC) MANIFOLD ASSEMBLIES AND AIR DIFFUSER ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80058 R01	NO. 1 ENGINE - SB PW800-72-80058 R01 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR BLEED VALVE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 16-AUG-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80060	NO. 1 ENGINE - SB PW800-72-80060 - REPLACEMENT OF OIL NOZZLE INLET GASKET					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80062 R02	NO. 1 ENGINE - SB PW800-72-80062 R02 - REPLACEMENT OF FRONT AND REAR INNER-BYPASS DUCT SEGMENT ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 03-AUG-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80063	NO. 1 ENGINE - SB PW800-72-80063 - REPLACEMENT OF INNER DIFFUSER CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80064 R01	NO. 1 ENGINE - SB PW800-72-80064 R01 - REPLACEMENT OF THIRD STAGE HIGH PRESSURE COMPRESSOR ROTOR					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 21-AUG-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80065	NO. 1 ENGINE - SB PW800-72-80065 - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80079	NO. 1 ENGINE - SB PW800-72-80079 - REPLACEMENT OF AGB BREATHER TUBE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-JUN-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80081	NO. 1 ENGINE - SB PW800-72-80081 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR FIRST-STAGE VARIABLE VANE					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 28-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80082 R01	NO. 1 ENGINE - SB PW800-72-80082 R01 - REPLACEMENT OF HIGH COMPRESSOR ROTOR SEAL ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80084	NO. 1 ENGINE - SB PW800-72-80084 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR OUTER DUCT SEGMENTS					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 04-AUG-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80085	NO. 1 ENGINE - SB PW800-72-80085 - REPLACEMENT/MODIFICATION OF MID TURBINE FRAME ASSEMBLY					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 12-OCT-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80087 R01	NO. 1 ENGINE - SB PW800-72-80087 R01 - BYPASS MODULE WEIGHT REDUCTION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 17-SEP-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80088	NO. 1 ENGINE - SB PW800-72-80088 - REPLACEMENT OF FIRST STAGE HIGH PRESSURE TURBINE COOL AIR DUCT ASSEMBLY					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 16-JUN-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80090	NO. 1 ENGINE - SB PW800-72-80090 - REPLACEMENT OF MID TURBINE WEIGHT REDUCTION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-JUN-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80093	NO. 1 ENGINE - SB PW800-72-80093 - REPLACEMENT/MODIFICATION OF NO. 3 BEARING HOUSING ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-JUL-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80094	NO. 1 ENGINE - SB PW800-72-80094 - REPLACEMENT OF ACTIVE CLEARANCE CONTROL VALVE (ACCV) BEARING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 08-AUG-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80100 R01	NO. 1 ENGINE - SB PW800-72-80100 R01 - REPLACEMENT OF (LPC FAN-CORE-STATOR) FIRST STAGE VANE ASSEMBLIES					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 19-MAR-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80104 R01	NO. 1 ENGINE - SB PW800-72-80104 R01 - REPLACEMENT OF FAN CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-SEP-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	
SB PW800-72-80106	NO. 1 ENGINE - SB PW800-72-80106 - REPLACEMENT OF ACTIVE CLEARANCE-CONTROL VALVE HOUSING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 08-SEP-2017		MOS HRS/MSC ENC	-	-	09-SEP-2022 -	-	

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

24-Jun-2026 09:37 AM

Model: GVII-G500 Serial: 72113 RegNo: OK-HUB HRS: 590.9 AFL: 409 As Of: 24-Jun-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80108	NO. 1 ENGINE - SB PW800-72-80108 - REPLACEMENT OF FUEL FILTER PRESSURE SENSOR					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 05-MAR-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80110	NO. 1 ENGINE - SB PW800-72-80110 - REPLACEMENT OF HIGH PRESSURE TURBINE STATOR FRONT AIR-SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 12-OCT-2017		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80111 R02	NO. 1 ENGINE - SB PW800-72-80111 R02 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR TIE SHAFT					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 19-MAR-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80112 R01	NO. 1 ENGINE - SB PW800-72-80112 R01 - REPLACEMENT OF NO. 1 BEARING HOUSING ASSEMBLY					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-SEP-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80118 R01	NO. 1 ENGINE - SB PW800-72-80118 R01 - REPLACEMENT OF SECOND STAGE HPT HUB SLEEVE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-DEC-2017		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80123 R01	NO. 1 ENGINE - SB PW800-72-80123 R01 - REPLACEMENT OF HEAT EXCHANGER AND INTEGRATED DRIVE GENERATOR (IDG) AIR COOLED OIL COOLER (ACOC)					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 16-FEB-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80128 R01	NO. 1 ENGINE - SB PW800-72-80128 R01 - REPLACEMENT OF NO.4 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 26-SEP-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80129	NO. 1 ENGINE - SB PW800-72-80129 - REPLACEMENT OF NO.5 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 14-DEC-2017		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80131	NO. 1 ENGINE - SB PW800-72-80131 - REPLACEMENT OF NO.4 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 26-OCT-2017		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80132	NO. 1 ENGINE - SB PW800-72-80132 - REPLACEMENT OF NO.5 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 26-OCT-2017		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80134 R01	NO. 1 ENGINE - SB PW800-72-80134 R01 - INTRODUCTION OF NO.4 AND NO.5 BEARING SEAL OPTIONS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2020		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80138	NO. 1 ENGINE - SB PW800-72-80138 - REPLACEMENT OF TRANSPORTATION CRADLE ASSEMBLY	MOS		09-SEP-2022		OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-NOV-2017		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80140	NO. 1 ENGINE - SB PW800-72-80140 - SB PW800-72-80140 - REPLACEMENT OF LOW PRESSURE COMPRESSOR FAN	MOS		09-SEP-2022		CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 12-JUL-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80141	NO. 1 ENGINE - SB PW800-72-80141 - INTRODUCTION OF HIGH PRESSURE COMPRESSOR FIFTH-STAGE SEGMENT OPTION	MOS		09-SEP-2022		INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 19-JAN-2018		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80142 R01	NO. 1 ENGINE - SB PW800-72-80142 R01 - REPLACEMENT OF ROLLER BEARING	MOS		09-SEP-2022		OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 01-OCT-2018		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80143 R01	NO. 1 ENGINE - SB PW800-72-80143 R01 - REPLACEMENT OF EXHAUST GAS TEMPERATURE THERMOCOUPLES AND TURBINE EXHAUST CASE ASSEMBLY	MOS		09-SEP-2022		OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 23-JAN-2018		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80144	NO. 1 ENGINE - SB PW800-72-80144 - INTRODUCTION OF NO.4 BEARING FRONT CARBON-SEAL (IC) OPTION	MOS		09-SEP-2022		INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-DEC-2017		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80146	NO. 1 ENGINE - SB PW800-72-80146 - REPLACEMENT OF FRONT BYPASS DUCT SEGMENT ASSEMBLY	MOS		09-SEP-2022		RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 21-NOV-2017		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80147	NO. 1 ENGINE - SB PW800-72-80147 - INTRODUCTION OF NO.4 BEARING REAR CARBON-SEAL (IC) OPTION	MOS		09-SEP-2022		INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-DEC-2017		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80149	NO. 1 ENGINE - SB PW800-72-80149 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR OUTER AIR SEAL ASSEMBLY NUTS	MOS		09-SEP-2022		RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 13-FEB-2018		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80150 R01	NO. 1 ENGINE - SB PW800-72-80150 R01 - PW800-72-80150 R01 - REPLACEMENT OF INNER BYPASS DUCT SEGMENTS AND BRACKET ASSEMBLIES	MOS		09-SEP-2022		CATEGORY 3	Complied With - AT MANUFACTURE
Eff. Date: 26-JUL-2021		HRS/MSC	-	-	-		
		ENC					

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80153 R01	NO. 1 ENGINE - SB PW800-72-80153 R01 - PW800-72-80153 R01 - REPLACEMENT OF INNER BYPASS DUCT ASSEMBLY					CATEGORY 3	Not Applicable - ENGINE POST SB 80150
Eff. Date: 15-MAR-2018		MOS HRS/MSC ENC	-	10-FEB-2024 173.5 148	-		
SB PW800-72-80154 R03	NO. 1 ENGINE - SB PW800-72-80154 R03 - REPLACEMENT OF OUTER-FRONT WIRING-HARNESS CLAMP AND RE-ORIENTATION OF HARNESSES					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-2019		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80159	NO. 1 ENGINE - SB PW800-72-80159 - REPLACEMENT OF FLANGE G SELF-LOCKING NUTS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80160	NO. 1 ENGINE - SB PW800-72-80160 - REPLACEMENT OF FIRST STAGE HIGH PRESSURE TURBINE DUCT SEGMENT ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 07-DEC-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80161 R01	NO. 1 ENGINE - SB PW800-72-80161 R01 - REPLACEMENT / MODIFICATION OF FIRST-STAGE LOW PRESSURE COMPRESSOR ROTOR					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 09-SEP-2019		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80162	NO. 1 ENGINE - SB PW800-72-80162 - INTRODUCTION OF MID-TURBINE FRAME REAR-INNER AND REAR-OUTER BAFFLE ASSEMBLY OPTIONS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80163 R01	NO. 1 ENGINE - SB PW800-72-80163 R01 - INNER COMPRESSOR INLET CONE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 17-SEP-2018		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80164 R03	NO. 1 ENGINE - SB PW800-72-80164 R03 - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80165 R03	NO. 1 ENGINE - SB PW800-72-80165 R03 - REPLACEMENT/MODIFICATION OF FUEL METERING UNIT WITH FIRE BLANKETS					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 22-MAR-2021		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80167 R01	NO. 1 ENGINE - SB PW800-72-80167 R01 - INTRODUCTION OF BOTTOM DEAD CENTER FAIRING FIRE SHIELDS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-AUG-2018		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80168 R01	NO. 1 ENGINE - SB PW800-72-80168 R01 - MID-TURBINE FRAME FRONT-INNER SEAL HOUSING AND PISTON RING - REPLACEMENT / MODIFICATION OF					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 07-OCT-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80172 R02	NO. 1 ENGINE - SB PW800-72-80172 R02 - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 10-JAN-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80173	NO. 1 ENGINE - SB PW800-72-80173 - REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 02-APR-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80174 R03	NO. 1 ENGINE - SB PW800-72-80174 R03 - REPLACEMENT OF INNER AND OUTER COMPRESSOR INLET CONE					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-MAY-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80175	NO. 1 ENGINE - SB PW800-72-80175 - REPLACEMENT OF MID-TURBINE FRAME INNER-FRONT SEAL HOUSING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 12-AUG-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80177	NO. 1 ENGINE - SB PW800-72-80177 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR BOREScope PLUG					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80178 R01	NO. 1 ENGINE - SB PW800-72-80178 R01 - INTRODUCTION OF FLIGHT INTO KNOWN ICING CONDITIONS ENGINE CONFIGURATION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80179	NO. 1 ENGINE - SB PW800-72-80179 - REPLACEMENT OF FUEL OIL MANIFOLD					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80181	NO. 1 ENGINE - SB PW800-72-80181 - REPLACEMENT OF FIRST-STAGE HPT STATOR VANE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 05-JUL-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80183 R01	NO. 1 ENGINE - SB PW800-72-80183 R01 - HIGH PRESSURE TURBINE SECOND-STAGE STATOR RING SEGMENT AND VANE CLUSTER - REPLACEMENT OF					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 07-JAN-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80184 R01	NO. 1 ENGINE - SB PW800-72-80184 R01 - INTRODUCTION OF FAN CASE ASSEMBLY, INTERCHANGEABILITY CONTROL (IC) OPTION					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-JUN-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80185	NO. 1 ENGINE - SB PW800-72-80185 - REPLACEMENT OF SECONDARY SYSTEM AIR COOLER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-SEP-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80188 R01	NO. 1 ENGINE - SB PW800-72-80188 R01 - REPLACEMENT OF LOW PRESSURE COMPRESSOR AND STATOR ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-MAY-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80189 R01	NO. 1 ENGINE - SB PW800-72-80189 R01 - INTEGRATED DRIVE GENERATOR TUBE NIPPLE - REPLACEMENT OF					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 01-NOV-2019		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80191 R01	NO. 1 ENGINE - SB PW800-72-80191 R01 - REPLACEMENT/MODIFICATION OF LOW PRESSURE TURBINE STATOR & ROTOR ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 09-JUL-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80192	NO. 1 ENGINE - SB PW800-72-80192 - REPLACEMENT OF OUTER COMPRESSOR INLET CONE ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80193 R01	NO. 1 ENGINE - SB PW800-72-80193 R01 - SB PW800-72-80193 R01 - REPLACEMENT/MODIFICATION OF MID-TURBINE FRAME ASSEMBLY REAR INNER AND OUTER PISTON RINGS					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80194 R01	NO. 1 ENGINE - SB PW800-72-80194 R01 - SB PW800-72-80194 R01 - REPLACEMENT/MODIFICATION OF MID-TURBINE FRAME ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80195 R03	NO. 1 ENGINE - SB PW800-72-80195 R03 - SB PW800-72-80195 R03 - REPLACEMENT OF VIBRATION SENSOR SUPPORT BRACKET ASSEMBLY					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 22-FEB-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80197 R01	NO. 1 ENGINE - SB PW800-72-80197 R01 - MODIFICATION/REPLACEMENT OF LOW PRESSURE TURBINE (LPT) FIFTH-STAGE VANE SEGMENT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80198	NO. 1 ENGINE - SB PW800-72-80198 - REPLACEMENT OF FUEL/OIL SEAL ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 22-JUL-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80199 R03	NO. 1 ENGINE - SB PW800-72-80199 R03 - SB PW800-72-80199 R03 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR ROTORS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-JUN-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80200 R02	NO. 1 ENGINE - SB PW800-72-80200 R02 - PW800-72-80200 R02 - REPLACEMENT OF SECOND STAGE HIGH PRESSURE TURBINE (HPT) DUCT SEGMENT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-JUN-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80201	NO. 1 ENGINE - SB PW800-72-80201 - REPLACEMENT/MODIFICATION OF STAGE FOURTH, FIFTH , SIXTH AND SEVENTH LOW PRESSURE TURBINE (LPT) AIR SEALRINGS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-MAR-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80202	NO. 1 ENGINE - SB PW800-72-80202 - REPLACEMENT OF REAR BYPASS DUCT BRACKET					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 17-AUG-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80203 R02	NO. 1 ENGINE - SB PW800-72-80203 R02 - SB PW800-72-80203 R02 - REPLACEMENT/MODIFICATION OF HIGH PRESSURE COMPRESSOR ROTOR SHAFT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 27-MAY-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80204	NO. 1 ENGINE - SB PW800-72-80204 - REPLACEMENT OF LOW PRESSURE SHAFT NO. 1 CARBON-SEAL AIR-TUBE O-RINGS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 17-AUG-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80205 R02	NO. 1 ENGINE - SB PW800-72-80205 R02 - SB PW800-72-80205 R02 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR PISTON SEAL RING					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-JUN-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80206 R01	NO. 1 ENGINE - SB PW800-72-80206 R01 - SB PW800-72-80206 R01 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR SYNCHRONIZING RINGS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80208	NO. 1 ENGINE - SB PW800-72-80208 - SB PW800-72-80208 - REPLACEMENT/MODIFICATION OF AIR TURBINE STARTER					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 13-AUG-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80213	NO. 1 ENGINE - SB PW800-72-80213 - REPLACEMENT OF INTERMEDIATE CASE					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-2020		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80214 R01	NO. 1 ENGINE - SB PW800-72-80214 R01 - PW800-72-80214 R01 - REPLACEMENT OF NO. 3 BEARING					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 10-MAY-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80215 R03	NO. 1 ENGINE - SB PW800-72-80215 R03 - PW800-72-80215 R03 - REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE LOW-PRESSURE-TURBINE ROTOR & STATOR ASSEMBLY					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 09-SEP-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80217 R01	NO. 1 ENGINE - SB PW800-72-80217 R01 - SB PW800-72-80217 R01 - REPLACEMENT OF FRONT OUTER ELECTRICAL WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-MAY-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80218	NO. 1 ENGINE - SB PW800-72-80218 - PW800-72-80218 - REPLACEMENT OF REAR OUTER ELECTRICAL WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-APR-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80219	NO. 1 ENGINE - SB PW800-72-80219 - REPLACEMENT OF CHANNEL A WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80220 R01	NO. 1 ENGINE - SB PW800-72-80220 R01 - SB PW800-72-80220 R01 - REPLACEMENT OF INNER WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-MAY-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80222	NO. 1 ENGINE - SB PW800-72-80222 - REPLACEMENT OF EXHAUST GAS TURBINE WIRING HARNESS	MOS		09-SEP-2022		CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 22-MAR-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80223 R02	NO. 1 ENGINE - SB PW800-72-80223 R02 - INSPECTION OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN (CATEGORY 3)	MOS				CATEGORY 3	
		HRS/MSC	1500	-	1500	RECURRING	
SB PW800-72-80224	NO. 1 ENGINE - SB PW800-72-80224 - INTRODUCTION OF HIGH SPEED TRIM BALANCE COUNTERWEIGHTS	MOS		09-SEP-2022		CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 28-JAN-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80225	NO. 1 ENGINE - SB PW800-72-80225 - PW800-72-80225 - REPLACEMENT OF VIBRATION SENSOR SUPPORT BRACKET ASSEMBLY	MOS		09-SEP-2022		CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-FEB-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80226	NO. 1 ENGINE - SB PW800-72-80226 - PW800-72-80226 - REPLACEMENT OF HIGH-PRESSURE-TURBINE FRONT-OUTER AIR-SEAL	MOS		09-SEP-2022		CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 08-APR-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80228 R01	NO. 1 ENGINE - SB PW800-72-80228 R01 - SB PW800-72-80228 R01 - REPLACEMENT OF COMBUSTION CHAMBER ASSEMBLY	MOS		09-SEP-2022		CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-JUL-2022		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80230	NO. 1 ENGINE - SB PW800-72-80230 - SB PW800-72-80230 - REPLACEMENT/MODIFICATION OF HIGH-PRESSURE-COMPRESSOR FRONT-HUB AND TIE-SHAFT	MOS		09-SEP-2022		CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80231	NO. 1 ENGINE - SB PW800-72-80231 - SB PW800-72-80231 - REPLACEMENT OF ELECTRONIC ENGINE CONTROL	MOS		09-SEP-2022		CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-OCT-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80232	NO. 1 ENGINE - SB PW800-72-80232 - SB PW800-72-80232 - REPLACEMENT/MODIFICATION OF OUTER-DIFFUSER CASE-ASSEMBLY AND HIGH-PRESSURE-TURBINE CASE-ASSEMBLY	MOS		09-SEP-2022		CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-2021		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80233 R01	NO. 1 ENGINE - SB PW800-72-80233 R01 - PW800-72-80233 R01 - INTRODUCTION OF FUEL-MANIFOLD ASSEMBLY CUSHION-LOOP-CLAMPS	MOS		09-SEP-2022		CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 14-SEP-2021		HRS/MSC	-	-	-		
		ENC					

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80234	NO. 1 ENGINE - SB PW800-72-80234 - SB PW800-72-80234 - REPLACEMENT/MODIFICATION OF ACCESSORY-GEAR-BOX DRIVE-SPLINE-BEVEL-GEAR					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-OCT-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80235	NO. 1 ENGINE - SB PW800-72-80235 - SB PW800-72-80235 - REPLACEMENT OF NO. 4 AND NO. 5 BEARING SEGMENTED-SEAL INTERCHANGEABILITY-CONTROL (IC)					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80237	NO. 1 ENGINE - SB PW800-72-80237 - SB PW800-72-80237 - REPLACEMENT OF IGNITION EXCITER					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 09-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80238	NO. 1 ENGINE - SB PW800-72-80238 - SB PW800-72-80238 - REPLACEMENT/MODIFICATION OF HIGH-PRESSURE-COMPRESSOR SHAFT-SEAL-RING					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80239	NO. 1 ENGINE - SB PW800-72-80239 - SB PW800-72-80239 - REPLACEMENT/MODIFICATION OF HIGH-PRESSURE-COMPRESSOR FRONT-CASE-SET					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80240	NO. 1 ENGINE - SB PW800-72-80240 - SB PW800-72-80240 - REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR HEAT-SHIELD-RETAINER					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80241	NO. 1 ENGINE - SB PW800-72-80241 - SB PW800-72-80241 - REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR INNER-CASE-FLANGES SELF-LOCKING-NUTS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80242	NO. 1 ENGINE - SB PW800-72-80242 - SB PW800-72-80242 - REPLACEMENT OF NO. 4 BEARING REAR-SEAL-RUNNER ASSEMBLY					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 25-NOV-2021		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80243	NO. 1 ENGINE - SB PW800-72-80243 - REPLACEMENT/MODIFICATION OF P2.8 TO MID-TURBINE-FRAME AND P2.9 TO HIGH-PRESSURE-TURBINE AIR-TUBES-ASSEMBLY					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

24-Jun-2026 09:37 AM

Model: GVII-G500 Serial: 72113 RegNo: OK-HUB HRS: 590.9 AFL: 409 As Of: 24-Jun-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80244	NO. 1 ENGINE - SB PW800-72-80244 - SB PW800-72-80244 - REPLACEMENT OF MID-TURBINE-FRAME FLANGE-BOLTS					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 24-NOV-2021		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80246	NO. 1 ENGINE - SB PW800-72-80246 - SB PW800-72-80246 - REPLACEMENT/MODIFICATION OF TRANSPORTATION CRADLE ASSEMBLY					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 12-MAY-2022		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80247	NO. 1 ENGINE - SB PW800-72-80247 - SB PW800-72-80247 - INTRODUCTION OF BEARING OPTION (IC)					CATEGORY 9	Complied With - AT MANUFACTURE
Eff. Date: 02-MAY-2022		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80248	NO. 1 ENGINE - SB PW800-72-80248 - PW800-72-80248 - REPLACEMENT OF FUEL METERING UNIT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-DEC-2021		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80249 R03	NO. 1 ENGINE - SB PW800-72-80249 R03 - PW800-72-80249 R03 - INSPECTION OF MID-TURBINE-FRAME ASSEMBLY						Declined - CANCELLED/SUPERSEDED
		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		
SB PW800-72-80249 R04	NO. 1 ENGINE - PW800-72-80249 R04 - INSPECTION OF MID-TURBINE-FRAME ASSEMBLY, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Declined - NEWER REVISION AVAILABLE
Eff. Date: 23-AUG-2023		MOS HRS/MSC ENC	-	18-JUN-2024 228.7 195	-		
SB PW800-72-80250	NO. 1 ENGINE - SB PW800-72-80250 - SB PW800-72-80250 - MODIFICATION / REPLACEMENT OF ACCESSORY GEARBOX MODULE					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-AUG-2022		MOS HRS/MSC ENC	-	09-SEP-2022 -	-		
SB PW800-72-80251	NO. 1 ENGINE - SB PW800-72-80251 - SB PW800-72-80251 - INSPECTION OF HIGH-PRESSURE-TURBINE (HPT) SECOND-STAGE RING-SEGMENT AND VANE-CLUSTER ASSEMBLY					CATEGORY 3	Declined - CANCELLED/SUPERSEDED
Eff. Date: 04-JAN-2022		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		
SB PW800-72-80252	NO. 1 ENGINE - SB PW800-72-80252 - SB PW800-72-80252 - INSPECTION OF COMBUSTION CHAMBER ASSEMBLY					CATEGORY 3	Declined - CANCELLED/SUPERSEDED
Eff. Date: 04-JAN-2022		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80255	NO. 1 ENGINE - SB PW800-72-80255 - SB PW800-72-80255 - REPLACEMENT/MODIFICATION OF EIGHTH-STAGE HIGH-PRESSURE-COMPRESSOR-ROTOR ASSEMBLY AND REAR-HUB					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80256	NO. 1 ENGINE - SB PW800-72-80256 - SB PW800-72-80256 - REPLACEMENT OF HIGH PRESSURE TURBINE ROTORS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80257	NO. 1 ENGINE - SB PW800-72-80257 - SB PW800-72-80257 - REPLACEMENT OF 5TH, 6TH AND 7TH STAGE HIGH PRESSURE (HP) AXIAL COMPRESSOR ROTORS					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80258	NO. 1 ENGINE - SB PW800-72-80258 - SB PW800-72-80258 - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) COMPONENTS AND 1ST STAGE BLADE					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS HRS/MSC ENC	-	-	09-SEP-2022 -		
SB PW800-72-80258 R01	NO. 1 ENGINE - SB PW800-72-80258 R01 - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) COMPONENTS AND 1ST STAGE BLADE, SERVICE BULLETIN (CATEGORY 7)					CATEGORY 7	Complied With - BY ORIGINAL REVISION
Eff. Date: 07-SEP-2023		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		
SB PW800-72-80258 R02	NO. 1 ENGINE - SB PW800-72-80258 R02 - REPLACEMENT OF HIGH-PRESSURE TURBINE (HPT) COMPONENTS AND FIRST-STAGE BLADE, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Complied With - BY ORIGINAL REVISION
		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		
SB PW800-72-80280	NO. 1 ENGINE - PW800-72-80280 - INSPECTION OF TURBOFAN ENGINE BRACKET BYPASS DUCT JOINT ASSEMBLY RIVETS, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Not Applicable - BY ESN
Eff. Date: 17-MAY-2023		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		
SB PW800-72-80280 R01	NO. 1 ENGINE - PW800-72-80280 R01 - INSPECTION OF BRACKET BYPASS DUCT JOINT ASSEMBLY RIVETS, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Not Applicable - BY ESN
Eff. Date: 14-JUL-2023		MOS HRS/MSC ENC	-	13-JAN-2024 171.3 146	-		
SB PW800-72-80314	NO. 1 ENGINE - PW800-72-80314 - TURBOFAN ENGINE HIGH-PRESSURE-TURBINE FIRST-STAGE-HUBS AND SECOND-STAGE-HUBS - INSPECTION OF, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
Eff. Date: 21-APR-2025		MOS ENC HRS/MSC	-	09-SEP-2022			

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80314 R01	NO. 1 ENGINE - SB PW800-72-80314 R01 - INSPECTION OF HIGH-PRESSURE-TURBINE FIRST-STAGE-HUBS AND SECOND-STAGE-HUBS, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
		MOS ENC	4000		09-SEP-2022 4000		
SB PW800-73-80148	NO. 1 ENGINE - SB PW800-73-80148 - ENGINE FUEL AND CONTROL - REPLACEMENT OF FUEL METERING UNIT (FMU)					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 20-FEB-2018		MOS HRS/MSC ENC	-		09-SEP-2022 -		
SB PW800-73-80169 R04	NO. 1 ENGINE - SB PW800-73-80169 R04 - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-		09-SEP-2022 -		
SB PW800-73-80170 R02	NO. 1 ENGINE - SB PW800-73-80170 R02 - REPLACEMENT OF FUEL METERING UNIT					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-MAY-2019		MOS HRS/MSC ENC	-		09-SEP-2022 -		
SB PW800-73-80291	NO. 1 ENGINE - SB PW800-73-80291 - INSPECTION OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
Eff. Date: 10-JUN-2024		MOS ENC HRS/MSC	-		09-SEP-2022		
SB PW800-73-80291 R01	NO. 1 ENGINE - SB PW800-73-80291 R01 - INSPECTION OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
		MOS ENC	1250		1250		
SB PW800-75-80006 R01	NO. 1 ENGINE - SB PW800-75-80006 R01 - REPLACEMENT OF TUBE AIR COOLER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-OCT-2016		MOS HRS/MSC ENC	-		09-SEP-2022 -		
SB PW800-75-80083	NO. 1 ENGINE - SB PW800-75-80083 - REPLACEMENT OF UPPER DUCT INSULATION BOOT					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-2017		MOS HRS/MSC ENC	-		09-SEP-2022 -		
SB PW800-75-80135 R01	NO. 1 ENGINE - SB PW800-75-80135 R01 - REPLACEMENT OF SECONDARY SYSTEM AIR COOLER					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 16-APR-2018		MOS HRS/MSC ENC	-		09-SEP-2022 -		
ENGINE NO. 2 - SB - PW814GA PCE-GA0487/33B1170-01							
SB PW800-26-80270 (890270.000)	NO. 2 ENGINE - SB PW800-26-80270 - SB PW800-26-80270 - INTRODUCTION OF TURBOFAN ENGINE JUMPER CABLES (ECS-TO-AGB) OPTION					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-AUG-2022		MOS HRS/MSC ENC	-		19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80000 R02	NO. 2 ENGINE - SB PW800-72-80000 R02 - SB PW800-72-80000 R02 - INTRODUCTION OF PERMANENT RECORD					CATEGORY 10	Complied With - AT MANUFACTURE
Eff. Date: 15-APR-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80002 R03	NO. 2 ENGINE - SB PW800-72-80002 R03 - PW800-72-80002 R03 - REPLACEMENT OF STATOR AC GENERATOR					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-JAN-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80003 R01	NO. 2 ENGINE - SB PW800-72-80003 R01 - REPLACEMENT OF HPC VARIABLE STAGES 1, 2 AND 3					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 20-FEB-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80004	NO. 2 ENGINE - SB PW800-72-80004 - REPLACEMENT OF HUB TURBINE FIRST AND SECOND STAGE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 04-SEP-2015		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80008 R01	NO. 2 ENGINE - SB PW800-72-80008 R01 - REPLACEMENT OF TURBINE BLADES STAGE 5 AND 6 (IC) OPTION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-OCT-2016		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80012	NO. 2 ENGINE - SB PW800-72-80012 - REPLACEMENT OF NO.1 BRG. CARBON SEAL					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 12-APR-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80015	NO. 2 ENGINE - SB PW800-72-80015 - MODIFICATION/REPLACEMENT OF NO.3 BEARING HOUSING ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 05-APR-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80016	NO. 2 ENGINE - SB PW800-72-80016 - REPLACEMENT/MODIFICATION OF NO.3 BEARING BALL FLANGED					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 29-MAR-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80017	NO. 2 ENGINE - SB PW800-72-80017 - REPLACEMENT OF SECONDARY SYSTEM AIR COOLER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 25-AUG-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80021 R01	NO. 2 ENGINE - SB PW800-72-80021 R01 - REPLACEMENT OF MID-TURBINE FRAME MODULE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80025	NO. 2 ENGINE - SB PW800-72-80025 - REPLACEMENT OF AIR COOLER TUBE ASSEMBLY					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-JUL-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80026	NO. 2 ENGINE - SB PW800-72-80026 - REPLACEMENT OF AIR TRANSFER TUBE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80027 R01	NO. 2 ENGINE - SB PW800-72-80027 R01 - REPLACEMENT OF NO. 5 BEARING RADIAL-CONTACT SEAL					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-OCT-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80032	NO. 2 ENGINE - SB PW800-72-80032 - REPLACEMENT OF SEAL HOUSING KEY-WASHER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80045 R03	NO. 2 ENGINE - SB PW800-72-80045 R03 - REPLACEMENT OF PROTECTIVE CAP					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 24-AUG-2018		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80047	NO. 2 ENGINE - SB PW800-72-80047 - REPLACEMENT OF ACTIVE CLEARANCE CONTROL (ACC) MANIFOLD ASSEMBLIES AND AIR DIFFUSER ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80058 R01	NO. 2 ENGINE - SB PW800-72-80058 R01 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR BLEED VALVE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 16-AUG-2019		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80060	NO. 2 ENGINE - SB PW800-72-80060 - REPLACEMENT OF OIL NOZZLE INLET GASKET					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80062 R02	NO. 2 ENGINE - SB PW800-72-80062 R02 - REPLACEMENT OF FRONT AND REAR INNER-BYPASS DUCT SEGMENT ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 03-AUG-2018		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		
SB PW800-72-80063	NO. 2 ENGINE - SB PW800-72-80063 - REPLACEMENT OF INNER DIFFUSER CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUL-2017		MOS HRS/MSC ENC	-	19-SEP-2022 -	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80064 R01	NO. 2 ENGINE - SB PW800-72-80064 R01 - REPLACEMENT OF THIRD STAGE HIGH PRESSURE COMPRESSOR ROTOR					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 21-AUG-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80065	NO. 2 ENGINE - SB PW800-72-80065 - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80079	NO. 2 ENGINE - SB PW800-72-80079 - REPLACEMENT OF AGB BREATHER TUBE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-JUN-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80081	NO. 2 ENGINE - SB PW800-72-80081 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR FIRST-STAGE VARIABLE VANE					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 28-JUL-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80082 R01	NO. 2 ENGINE - SB PW800-72-80082 R01 - REPLACEMENT OF HIGH COMPRESSOR ROTOR SEAL ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80084	NO. 2 ENGINE - SB PW800-72-80084 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR OUTER DUCT SEGMENTS					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 04-AUG-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80085	NO. 2 ENGINE - SB PW800-72-80085 - REPLACEMENT/MODIFICATION OF MID TURBINE FRAME ASSEMBLY					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 12-OCT-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80087 R01	NO. 2 ENGINE - SB PW800-72-80087 R01 - BYPASS MODULE WEIGHT REDUCTION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 17-SEP-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80088	NO. 2 ENGINE - SB PW800-72-80088 - REPLACEMENT OF FIRST STAGE HIGH PRESSURE TURBINE COOL AIR DUCT ASSEMBLY					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 16-JUN-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80090	NO. 2 ENGINE - SB PW800-72-80090 - REPLACEMENT OF MID TURBINE WEIGHT REDUCTION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-JUN-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80093	NO. 2 ENGINE - SB PW800-72-80093 - REPLACEMENT/MODIFICATION OF NO. 3 BEARING HOUSING ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-JUL-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80094	NO. 2 ENGINE - SB PW800-72-80094 - REPLACEMENT OF ACTIVE CLEARANCE CONTROL VALVE (ACCV) BEARING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 08-AUG-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80100 R01	NO. 2 ENGINE - SB PW800-72-80100 R01 - REPLACEMENT OF (LPC FAN-CORE-STATOR) FIRST STAGE VANE ASSEMBLIES					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 19-MAR-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80104 R01	NO. 2 ENGINE - SB PW800-72-80104 R01 - REPLACEMENT OF FAN CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-SEP-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80106	NO. 2 ENGINE - SB PW800-72-80106 - REPLACEMENT OF ACTIVE CLEARANCE-CONTROL VALVE HOUSING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 08-SEP-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80108	NO. 2 ENGINE - SB PW800-72-80108 - REPLACEMENT OF FUEL FILTER PRESSURE SENSOR					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 05-MAR-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80110	NO. 2 ENGINE - SB PW800-72-80110 - REPLACEMENT OF HIGH PRESSURE TURBINE STATOR FRONT AIR-SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 12-OCT-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80111 R02	NO. 2 ENGINE - SB PW800-72-80111 R02 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR TIE SHAFT					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 19-MAR-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80112 R01	NO. 2 ENGINE - SB PW800-72-80112 R01 - REPLACEMENT OF NO. 1 BEARING HOUSING ASSEMBLY					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-SEP-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80118 R01	NO. 2 ENGINE - SB PW800-72-80118 R01 - REPLACEMENT OF SECOND STAGE HPT HUB SLEEVE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-DEC-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80123 R01	NO. 2 ENGINE - SB PW800-72-80123 R01 - REPLACEMENT OF HEAT EXCHANGER AND INTEGRATED DRIVE GENERATOR (IDG) AIR COOLED OIL COOLER (ACOC)					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 16-FEB-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80128 R01	NO. 2 ENGINE - SB PW800-72-80128 R01 - REPLACEMENT OF NO.4 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 26-SEP-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80129	NO. 2 ENGINE - SB PW800-72-80129 - REPLACEMENT OF NO.5 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 14-DEC-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80131	NO. 2 ENGINE - SB PW800-72-80131 - REPLACEMENT OF NO.4 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 26-OCT-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80132	NO. 2 ENGINE - SB PW800-72-80132 - REPLACEMENT OF NO.5 BEARING RADIAL-CONTACT CARBON SEAL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 26-OCT-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80134 R01	NO. 2 ENGINE - SB PW800-72-80134 R01 - INTRODUCTION OF NO.4 AND NO.5 BEARING SEAL OPTIONS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80138	NO. 2 ENGINE - SB PW800-72-80138 - REPLACEMENT OF TRANSPORTATION CRADLE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-NOV-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80140	NO. 2 ENGINE - SB PW800-72-80140 - SB PW800-72-80140 - REPLACEMENT OF LOW PRESSURE COMPRESSOR FAN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 12-JUL-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80141	NO. 2 ENGINE - SB PW800-72-80141 - INTRODUCTION OF HIGH PRESSURE COMPRESSOR FIFTH-STAGE SEGMENT OPTION					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 19-JAN-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80142 R01	NO. 2 ENGINE - SB PW800-72-80142 R01 - REPLACEMENT OF ROLLER BEARING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 01-OCT-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

24-Jun-2026 09:37 AM

Model: GVII-G500 Serial: 72113 RegNo: OK-HUB HRS: 590.9 AFL: 409 As Of: 24-Jun-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80143 R01	NO. 2 ENGINE - SB PW800-72-80143 R01 - REPLACEMENT OF EXHAUST GAS TEMPERATURE THERMOCOUPLES AND TURBINE EXHAUST CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 23-JAN-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80144	NO. 2 ENGINE - SB PW800-72-80144 - INTRODUCTION OF NO.4 BEARING FRONT CARBON-SEAL (IC) OPTION					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-DEC-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80146	NO. 2 ENGINE - SB PW800-72-80146 - REPLACEMENT OF FRONT BYPASS DUCT SEGMENT ASSEMBLY					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 21-NOV-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80147	NO. 2 ENGINE - SB PW800-72-80147 - INTRODUCTION OF NO.4 BEARING REAR CARBON-SEAL (IC) OPTION					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-DEC-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80149	NO. 2 ENGINE - SB PW800-72-80149 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR OUTER AIR SEAL ASSEMBLY NUTS					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 13-FEB-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80150 R01	NO. 2 ENGINE - SB PW800-72-80150 R01 - PW800-72-80150 R01 - REPLACEMENT OF INNER BYPASS DUCT SEGMENTS AND BRACKET ASSEMBLIES					CATEGORY 3	Complied With - AT MANUFACTURE
Eff. Date: 26-JUL-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80153 R01	NO. 2 ENGINE - SB PW800-72-80153 R01 - PW800-72-80153 R01 - REPLACEMENT OF INNER BYPASS DUCT ASSEMBLY					CATEGORY 3	Not Applicable - ENGINE POST SB 80150
Eff. Date: 15-MAR-2018		MOS HRS/MSC ENC	-	10-FEB-2024 173.5 148	-		
SB PW800-72-80154 R03	NO. 2 ENGINE - SB PW800-72-80154 R03 - REPLACEMENT OF OUTER-FRONT WIRING-HARNESS CLAMP AND RE-ORIENTATION OF HARNESSES					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80159	NO. 2 ENGINE - SB PW800-72-80159 - REPLACEMENT OF FLANGE G SELF-LOCKING NUTS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80160	NO. 2 ENGINE - SB PW800-72-80160 - REPLACEMENT OF FIRST STAGE HIGH PRESSURE TURBINE DUCT SEGMENT ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 07-DEC-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80161 R01	NO. 2 ENGINE - SB PW800-72-80161 R01 - REPLACEMENT / MODIFICATION OF FIRST-STAGE LOW PRESSURE COMPRESSOR ROTOR					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 09-SEP-2019		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80162	NO. 2 ENGINE - SB PW800-72-80162 - INTRODUCTION OF MID-TURBINE FRAME REAR-INNER AND REAR-OUTER BAFFLE ASSEMBLY OPTIONS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-2018		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80163 R01	NO. 2 ENGINE - SB PW800-72-80163 R01 - INNER COMPRESSOR INLET CONE					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 17-SEP-2018		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80164 R03	NO. 2 ENGINE - SB PW800-72-80164 R03 - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80165 R03	NO. 2 ENGINE - SB PW800-72-80165 R03 - REPLACEMENT/MODIFICATION OF FUEL METERING UNIT WITH FIRE BLANKETS					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 22-MAR-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80167 R01	NO. 2 ENGINE - SB PW800-72-80167 R01 - INTRODUCTION OF BOTTOM DEAD CENTER FAIRING FIRE SHIELDS					INFORMATIONAL	Complied With - AT MANUFACTURE
Eff. Date: 22-AUG-2018		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80168 R01	NO. 2 ENGINE - SB PW800-72-80168 R01 - MID-TURBINE FRAME FRONT-INNER SEAL HOUSING AND PISTON RING - REPLACEMENT / MODIFICATION OF					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 07-OCT-2019		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80172 R02	NO. 2 ENGINE - SB PW800-72-80172 R02 - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 10-JAN-2020		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80173	NO. 2 ENGINE - SB PW800-72-80173 - REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 02-APR-2019		MOS HRS/MSC ENC	-	-	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80174 R03	NO. 2 ENGINE - SB PW800-72-80174 R03 - REPLACEMENT OF INNER AND OUTER COMPRESSOR INLET CONE					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-MAY-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80175	NO. 2 ENGINE - SB PW800-72-80175 - REPLACEMENT OF MID-TURBINE FRAME INNER-FRONT SEAL HOUSING					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 12-AUG-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80177	NO. 2 ENGINE - SB PW800-72-80177 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR BORESCOPE PLUG					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80178 R01	NO. 2 ENGINE - SB PW800-72-80178 R01 - INTRODUCTION OF FLIGHT INTO KNOWN ICING CONDITIONS ENGINE CONFIGURATION					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80179	NO. 2 ENGINE - SB PW800-72-80179 - REPLACEMENT OF FUEL OIL MANIFOLD					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80181	NO. 2 ENGINE - SB PW800-72-80181 - REPLACEMENT OF FIRST-STAGE HPT STATOR VANE ASSEMBLY					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 05-JUL-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80183 R01	NO. 2 ENGINE - SB PW800-72-80183 R01 - HIGH PRESSURE TURBINE SECOND-STAGE STATOR RING SEGMENT AND VANE CLUSTER - REPLACEMENT OF					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 07-JAN-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80184 R01	NO. 2 ENGINE - SB PW800-72-80184 R01 - INTRODUCTION OF FAN CASE ASSEMBLY, INTERCHANGEABILITY CONTROL (IC) OPTION					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-JUN-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80185	NO. 2 ENGINE - SB PW800-72-80185 - REPLACEMENT OF SECONDARY SYSTEM AIR COOLER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-SEP-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80188 R01	NO. 2 ENGINE - SB PW800-72-80188 R01 - REPLACEMENT OF LOW PRESSURE COMPRESSOR AND STATOR ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-MAY-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80189 R01	NO. 2 ENGINE - SB PW800-72-80189 R01 - INTEGRATED DRIVE GENERATOR TUBE NIPPLE - REPLACEMENT OF					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 01-NOV-2019		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80191 R01	NO. 2 ENGINE - SB PW800-72-80191 R01 - REPLACEMENT/MODIFICATION OF LOW PRESSURE TURBINE STATOR & ROTOR ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 09-JUL-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80192	NO. 2 ENGINE - SB PW800-72-80192 - REPLACEMENT OF OUTER COMPRESSOR INLET CONE ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80193 R01	NO. 2 ENGINE - SB PW800-72-80193 R01 - SB PW800-72-80193 R01 - REPLACEMENT/MODIFICATION OF MID-TURBINE FRAME ASSEMBLY REAR INNER AND OUTER PISTON RINGS					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80194 R01	NO. 2 ENGINE - SB PW800-72-80194 R01 - SB PW800-72-80194 R01 - REPLACEMENT/MODIFICATION OF MID-TURBINE FRAME ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80195 R03	NO. 2 ENGINE - SB PW800-72-80195 R03 - SB PW800-72-80195 R03 - REPLACEMENT OF VIBRATION SENSOR SUPPORT BRACKET ASSEMBLY					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 22-FEB-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80197 R01	NO. 2 ENGINE - SB PW800-72-80197 R01 - MODIFICATION/REPLACEMENT OF LOW PRESSURE TURBINE (LPT) FIFTH-STAGE VANE SEGMENT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80198	NO. 2 ENGINE - SB PW800-72-80198 - REPLACEMENT OF FUEL/OIL SEAL ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 22-JUL-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80199 R03	NO. 2 ENGINE - SB PW800-72-80199 R03 - SB PW800-72-80199 R03 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR ROTORS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-JUN-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80200 R02	NO. 2 ENGINE - SB PW800-72-80200 R02 - PW800-72-80200 R02 - REPLACEMENT OF SECOND STAGE HIGH PRESSURE TURBINE (HPT) DUCT SEGMENT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-JUN-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80201	NO. 2 ENGINE - SB PW800-72-80201 - REPLACEMENT/MODIFICATION OF STAGE FOURTH, FIFTH , SIXTH AND SEVENTH LOW PRESSURE TURBINE (LPT) AIR SEALRINGS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-MAR-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80202	NO. 2 ENGINE - SB PW800-72-80202 - REPLACEMENT OF REAR BYPASS DUCT BRACKET					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 17-AUG-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80203 R02	NO. 2 ENGINE - SB PW800-72-80203 R02 - SB PW800-72-80203 R02 - REPLACEMENT/MODIFICATION OF HIGH PRESSURE COMPRESSOR ROTOR SHAFT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 27-MAY-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80204	NO. 2 ENGINE - SB PW800-72-80204 - REPLACEMENT OF LOW PRESSURE SHAFT NO. 1 CARBON-SEAL AIR-TUBE O-RINGS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 17-AUG-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80205 R02	NO. 2 ENGINE - SB PW800-72-80205 R02 - SB PW800-72-80205 R02 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR PISTON SEAL RING					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-JUN-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80206 R01	NO. 2 ENGINE - SB PW800-72-80206 R01 - SB PW800-72-80206 R01 - REPLACEMENT OF HIGH PRESSURE COMPRESSOR SYNCHRONIZING RINGS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80208	NO. 2 ENGINE - SB PW800-72-80208 - SB PW800-72-80208 - REPLACEMENT/MODIFICATION OF AIR TURBINE STARTER					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 13-AUG-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80213	NO. 2 ENGINE - SB PW800-72-80213 - REPLACEMENT OF INTERMEDIATE CASE					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-2020		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	
SB PW800-72-80214 R01	NO. 2 ENGINE - SB PW800-72-80214 R01 - PW800-72-80214 R01 - REPLACEMENT OF NO. 3 BEARING					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 10-MAY-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -	-	

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80215 R03 (890215.000	NO. 2 ENGINE - SB PW800-72-80215 R03 - PW800-72-80215 R03 - REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE LOW-PRESSURE-TURBINE ROTOR & STATOR ASSEMBLY					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 09-SEP-2022		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80217 R01	NO. 2 ENGINE - SB PW800-72-80217 R01 - SB PW800-72-80217 R01 - REPLACEMENT OF FRONT OUTER ELECTRICAL WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-MAY-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80218	NO. 2 ENGINE - SB PW800-72-80218 - PW800-72-80218 - REPLACEMENT OF REAR OUTER ELECTRICAL WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-APR-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80219	NO. 2 ENGINE - SB PW800-72-80219 - REPLACEMENT OF CHANNEL A WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80220 R01	NO. 2 ENGINE - SB PW800-72-80220 R01 - SB PW800-72-80220 R01 - REPLACEMENT OF INNER WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-MAY-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80222	NO. 2 ENGINE - SB PW800-72-80222 - REPLACEMENT OF EXHAUST GAS TURBINE WIRING HARNESS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 22-MAR-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80223 R02	NO. 2 ENGINE - SB PW800-72-80223 R02 - INSPECTION OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
		MOS HRS/MSC	1500	-	1500	RECURRING	
SB PW800-72-80224	NO. 2 ENGINE - SB PW800-72-80224 - INTRODUCTION OF HIGH SPEED TRIM BALANCE COUNTERWEIGHTS					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 28-JAN-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80225	NO. 2 ENGINE - SB PW800-72-80225 - PW800-72-80225 - REPLACEMENT OF VIBRATION SENSOR SUPPORT BRACKET ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-FEB-2021		MOS HRS/MSC ENC	-	-	-		
SB PW800-72-80226	NO. 2 ENGINE - SB PW800-72-80226 - PW800-72-80226 - REPLACEMENT OF HIGH-PRESSURE-TURBINE FRONT-OUTER AIR-SEAL					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 08-APR-2021		MOS HRS/MSC ENC	-	-	-		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80228 R01 (890228.000	NO. 2 ENGINE - SB PW800-72-80228 R01 - SB PW800-72-80228 R01 - REPLACEMENT OF COMBUSTION CHAMBER ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-JUL-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80230	NO. 2 ENGINE - SB PW800-72-80230 - SB PW800-72-80230 - REPLACEMENT/MODIFICATION OF HIGH-PRESSURE-COMPRESSOR FRONT-HUB AND TIE-SHAFT					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80231	NO. 2 ENGINE - SB PW800-72-80231 - SB PW800-72-80231 - REPLACEMENT OF ELECTRONIC ENGINE CONTROL					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-OCT-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80232	NO. 2 ENGINE - SB PW800-72-80232 - SB PW800-72-80232 - REPLACEMENT/MODIFICATION OF OUTER-DIFFUSER CASE-ASSEMBLY AND HIGH-PRESSURE-TURBINE CASE-ASSEMBLY					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80233 R01	NO. 2 ENGINE - SB PW800-72-80233 R01 - PW800-72-80233 R01 - INTRODUCTION OF FUEL-MANIFOLD ASSEMBLY CUSHION-LOOP-CLAMPS					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 14-SEP-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80234	NO. 2 ENGINE - SB PW800-72-80234 - SB PW800-72-80234 - REPLACEMENT/MODIFICATION OF ACCESSORY-GEAR-BOX DRIVE-SPLINE-BEVEL-GEAR					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 21-OCT-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80235	NO. 2 ENGINE - SB PW800-72-80235 - SB PW800-72-80235 - REPLACEMENT OF NO. 4 AND NO. 5 BEARING SEGMENTED-SEAL INTERCHANGEABILITY-CONTROL (IC)					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80237	NO. 2 ENGINE - SB PW800-72-80237 - SB PW800-72-80237 - REPLACEMENT OF IGNITION EXCITER					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 09-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80238	NO. 2 ENGINE - SB PW800-72-80238 - SB PW800-72-80238 - REPLACEMENT/MODIFICATION OF HIGH-PRESSURE-COMPRESSOR SHAFT-SEAL-RING					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

24-Jun-2026 09:37 AM

Model: GVII-G500 Serial: 72113 RegNo: OK-HUB HRS: 590.9 AFL: 409 As Of: 24-Jun-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80239	NO. 2 ENGINE - SB PW800-72-80239 - SB PW800-72-80239 - REPLACEMENT/MODIFICATION OF HIGH-PRESSURE-COMPRESSOR FRONT-CASE-SET					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80240	NO. 2 ENGINE - SB PW800-72-80240 - SB PW800-72-80240 - REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR HEAT-SHIELD-RETAINER					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80241	NO. 2 ENGINE - SB PW800-72-80241 - SB PW800-72-80241 - REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR INNER-CASE-FLANGES SELF-LOCKING-NUTS					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 23-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80242	NO. 2 ENGINE - SB PW800-72-80242 - SB PW800-72-80242 - REPLACEMENT OF NO. 4 BEARING REAR-SEAL-RUNNER ASSEMBLY					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 25-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80243	NO. 2 ENGINE - SB PW800-72-80243 - REPLACEMENT/MODIFICATION OF P2.8 TO MID-TURBINE-FRAME AND P2.9 TO HIGH-PRESSURE-TURBINE AIR-TUBES-ASSEMBLY					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80244	NO. 2 ENGINE - SB PW800-72-80244 - SB PW800-72-80244 - REPLACEMENT OF MID-TURBINE-FRAME FLANGE-BOLTS					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 24-NOV-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80246	NO. 2 ENGINE - SB PW800-72-80246 - SB PW800-72-80246 - REPLACEMENT/MODIFICATION OF TRANSPORTATION CRADLE ASSEMBLY					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 12-MAY-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80247	NO. 2 ENGINE - SB PW800-72-80247 - SB PW800-72-80247 - INTRODUCTION OF BEARING OPTION (IC)					CATEGORY 9	Complied With - AT MANUFACTURE
Eff. Date: 02-MAY-2022		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		
SB PW800-72-80248	NO. 2 ENGINE - SB PW800-72-80248 - PW800-72-80248 - REPLACEMENT OF FUEL METERING UNIT					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-DEC-2021		MOS HRS/MSC ENC	-	-	19-SEP-2022 -		

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80249 R03	NO. 2 ENGINE - SB PW800-72-80249 R03 - PW800-72-80249 R03 - INSPECTION OF MID-TURBINE-FRAME ASSEMBLY						Declined - CANCELLED/SUPERSEDED
		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80249 R04	NO. 2 ENGINE - PW800-72-80249 R04 - INSPECTION OF MID-TURBINE-FRAME ASSEMBLY, SERVICE BULLETIN (CATEGORY 3)						Declined - NEWER REVISION AVAILABLE
Eff. Date: 23-AUG-2023		MOS		18-JUN-2024			
		HRS/MSC	-	228.7	-		
		ENC		195			
SB PW800-72-80250 (890250.000)	NO. 2 ENGINE - SB PW800-72-80250 - SB PW800-72-80250 - MODIFICATION / REPLACEMENT OF ACCESSORY GEARBOX MODULE						Complied With - AT MANUFACTURE
Eff. Date: 05-AUG-2022		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80251	NO. 2 ENGINE - SB PW800-72-80251 - SB PW800-72-80251 - INSPECTION OF HIGH-PRESSURE-TURBINE (HPT) SECOND-STAGE RING-SEGMENT AND VANE-CLUSTER ASSEMBLY						Declined - CANCELLED/SUPERSEDED
Eff. Date: 04-JAN-2022		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80252	NO. 2 ENGINE - SB PW800-72-80252 - SB PW800-72-80252 - INSPECTION OF COMBUSTION CHAMBER ASSEMBLY						Declined - CANCELLED/SUPERSEDED
Eff. Date: 04-JAN-2022		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80255	NO. 2 ENGINE - SB PW800-72-80255 - SB PW800-72-80255 - REPLACEMENT/MODIFICATION OF EIGHTH-STAGE HIGH-PRESSURE-COMPRESSOR-ROTOR ASSEMBLY AND REAR-HUB						Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80256	NO. 2 ENGINE - SB PW800-72-80256 - SB PW800-72-80256 - REPLACEMENT OF HIGH PRESSURE TURBINE ROTORS						Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80257	NO. 2 ENGINE - SB PW800-72-80257 - SB PW800-72-80257 - REPLACEMENT OF 5TH, 6TH AND 7TH STAGE HIGH PRESSURE (HP) AXIAL COMPRESSOR ROTORS						Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-72-80258	NO. 2 ENGINE - SB PW800-72-80258 - SB PW800-72-80258 - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) COMPONENTS AND 1ST STAGE BLADE						Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-2022		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-72-80258 R01	NO. 2 ENGINE - SB PW800-72-80258 R01 - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) COMPONENTS AND 1ST STAGE BLADE, SERVICE BULLETIN (CATEGORY 7)					CATEGORY 7	Complied With - BY ORIGINAL REVISION
Eff. Date: 07-SEP-2023		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80258 R02	NO. 2 ENGINE - SB PW800-72-80258 R02 - REPLACEMENT OF HIGH-PRESSURE TURBINE (HPT) COMPONENTS AND FIRST-STAGE BLADE, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Complied With - BY ORIGINAL REVISION
		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80280	NO. 2 ENGINE - PW800-72-80280 - INSPECTION OF TURBOFAN ENGINE BRACKET BYPASS DUCT JOINT ASSEMBLY RIVETS, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Not Applicable - BY ESN
Eff. Date: 17-MAY-2023		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80280 R01 (890280.000)	NO. 2 ENGINE - PW800-72-80280 R01 - INSPECTION OF BRACKET BYPASS DUCT JOINT ASSEMBLY RIVETS, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	Not Applicable - BY ESN
Eff. Date: 14-JUL-2023		MOS		13-JAN-2024			
		HRS/MSC	-	171.3	-		
		ENC		146			
SB PW800-72-80314	NO. 2 ENGINE - PW800-72-80314 - TURBOFAN ENGINE HIGH-PRESSURE-TURBINE FIRST-STAGE-HUBS AND SECOND-STAGE-HUBS - INSPECTION OF, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
Eff. Date: 21-APR-2025		MOS		19-SEP-2022			
		ENC					
		HRS/MSC	-				
SB PW800-72-80314 R01	NO. 2 ENGINE - SB PW800-72-80314 R01 - INSPECTION OF HIGH-PRESSURE-TURBINE FIRST-STAGE-HUBS AND SECOND-STAGE-HUBS, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
		MOS		19-SEP-2022			
		ENC	4000		4000		
SB PW800-73-80148	NO. 2 ENGINE - SB PW800-73-80148 - ENGINE FUEL AND CONTROL - REPLACEMENT OF FUEL METERING UNIT (FMU)					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 20-FEB-2018		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-73-80169 R04	NO. 2 ENGINE - SB PW800-73-80169 R04 - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-2019		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					
SB PW800-73-80170 R02	NO. 2 ENGINE - SB PW800-73-80170 R02 - REPLACEMENT OF FUEL METERING UNIT					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 13-MAY-2019		MOS		19-SEP-2022			
		HRS/MSC	-	-	-		
		ENC					

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PW800-73-80291	NO. 2 ENGINE - SB PW800-73-80291 - INSPECTION OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
Eff. Date: 10-JUN-2024		MOS ENC HRS/MSC			19-SEP-2022		
			-				
SB PW800-73-80291 R01	NO. 2 ENGINE - SB PW800-73-80291 R01 - INSPECTION OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN (CATEGORY 3)					CATEGORY 3	
		MOS ENC	1250		1250		
SB PW800-75-80006 R01	NO. 2 ENGINE - SB PW800-75-80006 R01 - REPLACEMENT OF TUBE AIR COOLER					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 06-OCT-2016		MOS HRS/MSC ENC	-	-	19-SEP-2022 - -		
SB PW800-75-80083	NO. 2 ENGINE - SB PW800-75-80083 - REPLACEMENT OF UPPER DUCT INSULATION BOOT					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-2017		MOS HRS/MSC ENC	-	-	19-SEP-2022 - -		
SB PW800-75-80135 R01	NO. 2 ENGINE - SB PW800-75-80135 R01 - REPLACEMENT OF SECONDARY SYSTEM AIR COOLER					RECOMMENDED	Complied With - AT MANUFACTURE
Eff. Date: 16-APR-2018		MOS HRS/MSC ENC	-	-	19-SEP-2022 - -		