

Unloading Products

This is an overview of how to unload SuperForm Products. This will help your expectations when product is shipped to your warehouse or jobsite.



Building a better future.

superformicf.com

Products shipped from the SuperForm facility to you

Products from SuperForm are always delivered to you in a 53' semi/van trailer. Always make sure a unit this size can get into a site for delivery. Always provide at least two helpers to unload.

ICF



Tied Packaging
1 bundle weights 20 lbs



Cardboard packaging
1 bundle weights 80 lbs


ICF comes in 2 options; Tied or cardboard. Each option takes roughly an hour to unload with 2-4 helpers.

Insulation

Bagged Insulation Bundles

- EPS+/MAX+ 10** - 75 lbs/bundle
- EPS+/MAX+ 16** - 100 lbs/bundle
- EPS+/MAX+ 20** - 129 lbs/bundle
- EPS+/MAX+ 30** - 110 lbs/bundle
- EPS+/MAX+ 40** - 135 lbs/bundle
- EPS+/MAX+ 60** - 160 lbs/bundle

Insulation always comes in bags unless specified otherwise.



Accessories



Bracing

weight:
2400lbs/crate
50lbs/ICF Brace set



Soprema


weight:
1600lbs/pallet
45lbs/roll

Most accessories are small and easy to handle but some may require a machine unload.

Unloading Options



Tractor



Skid steer



Fork Lift



Hand Bombing

Here are several options for unloading product. Always pull full stacks to the back of the trailer to minimize handling of the blocks.