



## SERVICE BULLETIN #117

06/12/13

### 2333 Hub

Because of a decline in sales, the 2333 hub is being discontinued. Please mark your records to indicate the subject part number will become obsolete with no replacement when inventory is depleted.

If you have any questions regarding this change, please contact our sales department at [sales@webbwheel.com](mailto:sales@webbwheel.com) or technical service department at [engineering@webbwheel.com](mailto:engineering@webbwheel.com).

