



## SERVICE BULLETIN #120

11/15/13

# Obsolete Aluminum Hub

The 4023 aluminum hub and all of its assemblies are now obsolete. The direct replacement is the 2023 ductile iron hub. If you have any questions regarding this change, please contact our sales department at [sales@webbwheel.com](mailto:sales@webbwheel.com) or technical service department at [engineering@webbwheel.com](mailto:engineering@webbwheel.com).

