



## SERVICE BULLETIN #129

07/1/14

# Obsolete Disc Wheel Hubs

Because of a decline in sales, the following disc wheel hub product offerings are being discontinued:

- 1555F
- 15551--MR
- 15551--ML

Please mark your records to indicate the subject part numbers will become obsolete with no replacement when inventory is depleted.

If you have any questions regarding this change, please contact our sales department at [sales@webbwheel.com](mailto:sales@webbwheel.com) or technical service department at [engineering@webbwheel.com](mailto:engineering@webbwheel.com).

