



SERVICE BULLETIN # 151

6/4/2018

Obsolete Part Numbers

Because of a decline in sales, the following part numbers are being made obsolete with inventory. Webb Wheel Products will offer a direct replacement option for these hub assemblies; however, some replacement assemblies will require the wheel studs to be ordered separately. Please see replacement order codes listed below as well as replacement wheel stud options if applicable. If you have any questions regarding this change, please contact our technical service department via email to engineering@webbwheel.com.

Obsolete Order Code	Replacement Order Code	Replacement Wheel Studs
20281--0T	20271--0T-71	NA
20281--3T	20271--0T-71	101162 (8 pcs.)
20281--5T	20271--0T-71	101160 (8 pcs.)
23481--0T	23471--0T	N/A