

Installation Instructions
SID650/150 Lighted Display

1. Disconnect power to unit.
2. Remove upper front panel - return to REMCOR®.
3. Remove upper electric box cover.
4. Put power cord through the opening in the new upper electric box cover; then run it into 4 x 4 lower box.
5. Connect terminals of the power cord to the terminal block: black wire with black wires and white with white. Secure ground wire with other ground wires. Make sure to use star washer under the ground terminal.
6. Install electric box covers.
7. Install new front panel on the unit. Make sure that the end of the power cord will come out through 2" diameter opening. Do not secure top screws.
8. Screw in two 8/32 x 1/2 stainless phillips screw to upper holes about 1/4" in.
9. Open the Lighted Display by removing the top cover and sliding off plexiglass plates.
10. Connect the Lighted Display power cord with the power cord in the 2" diameter hole.
11. Hang the Lighted Display on the top screws.
12. Secure lower screws going through the Lighted Display, Panel, and uprights on the unit.
13. Secure top screws.
14. Secure display mounting with two (2) screws unit is hanging on.
15. Install plexiglass plates in the unit and secure top cover; unit is now ready for operation.

REV D

91361 (391)