

INSTALLATION INSTRUCTIONS

SID LIGHTED DISPLAY

1. Disconnect power to unit.
2. Remove upper front panel and add 2" diameter hole (see Figure 1).
3. Connect harness to power in electric box; be sure ground wire in connected, position harness out the top of electric box and run along top of cabinet and down left side of cabinet, secure harness with self-adhesive mounts and wire ties to side of cabinet, adjust to allow end of harness to exit through new opening on panel.
4. Install reworked upper front panel, fasten with old screws, on top two (2) holes, use two (2) 8-32 round head screws supplied on lower two (2) holes, leave screws out 1/4" approximately. This is for hanging lighted display on.
5. Plug in lighted display push harness into panel; be careful, harness cord must not interfere with gate mechanism.
6. Adjust display mounting with two (2) screws unit is hanging on, if desired.
7. Connect power to unit; unit is ready for operation.

2" DIA. OR LARGER
HOLE. REMOVE ALL
SHARP EDGES.




FIG. 1 FRONT PANEL

REV X
91205 (290)