



RAPTOR REPAIRS

ACCESS & PLANT SERVICES

CERTIFICATE NUMBER	LOLER - 150	RECORD ID	136
--------------------	-------------	-----------	-----

CERTIFICATE OF THOROUGH EXAMINATION

IN ACCORDANCE WITH LOLER 1998, REGULATION 9(3) (a) (i)

MANUFACTURER	Pop up	MACHINE TYPE	Pro 10 iq
FLEET NUMBER	Pu/10-3	YEAR OF MANUFACTURE	2017
SERIAL NUMBER	S3010p-170600945	SAFE WORKING LOAD (kg)	240
SITE ADDRESS		ADDRESS OF PLATFORM OWNER	
Amazon Hull Hu14 3ft		Cliff Lane Warrington Wa13 0sp	

EXAMINATION REPORT FINDINGS

EXAMINATION RESULT	PASS - FIT TO REMAIN IN SERVICE
--------------------	---------------------------------

PREVIOUS EXAMINATION DATE	EXAMINATION DATE	DATE CERTIFICATE EXPIRES
Unknown	17/07/2025	16/1/2026

DECLARATION: I HAVE RECEIVED APPROPRIATE TRAINING ON ALL MAKES OF LIFTING EQUIPMENT. I HAVE EXAMINED THIS EQUIPMENT IN LINE WITH THE APPROPRIATE, PROVISION AND CURRENT LEGISLATION AND THE ABOVE DETAILS ARE CORRECT.

NAME OF THE COMPETENT PERSON/AUTHENTICATOR	Address of Competent Person Raptor Repairs Ltd, The Orchard, Bagsby Road, Owston Ferry, Doncaster, DN91AJ
Mike Everatt - CAP Ref No. 04133	
	