



Inspection Carried Out By:

Hessle Plant Ltd

Carrwood Road
Castleford
West Yorkshire
WF10 4PT

Tel: 01977 550557
E-Mail: mail@hessle.co.uk
Web Site: www.hessle.co.uk

Conducted in accordance with CFTS Publication GN28,
Regulation 9 of the 'Lifting Operations and Lifting Equipment Regulations 1998'
and the 'Provision and Use of Work Equipment Regulations 1998'

Site:	NORTH WEST MEWPS LTD C/O ATTAN RTC HANGAR ONE, EAST LEEDS AIRPORT CHURCH FENTON LS24 9SE	Regular Thorough Examination
-------	--	-------------------------------------

Equip No:	18229	Inspect No:	22047
Make/Model:	LGMG / AS0607WE - 29	Job No:	143962
Serial No:	P338200509	Contact:	
Last Inspection:		Inspected:	26/08/2025
Meter:	47	Printed:	27/08/2025
		Page:	1 of 1

Items to Inspect	Result	Comments
RTE		
Reason For RTE?	Within 6 Month Interval	
Safe Working Load	Yes (Detail)	230kg
Date Of Manufacture	Yes (Detail)	2023
Is this the first examination after installation or assembly at new site/ location?	No	
If Yes to above, has the equipment been installed correctly?	Not Applicable	
A Defects	None	
Timescale For A Defect Repairs	Not Applicable	
B Defects	None	
Timescale For B Defect Repairs	Not Applicable	
C Observations	None	
Particulars of any tests carried out as part of examination	No	
I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28	No Faults Have Been Detected	
Is Machine Safe to use?	Yes	
Date Of Next Inspection	Yes (Detail)	26/02/2026

DECLARATION BY COMPETENT PERSON

I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28

Engineer Name: Rick Kuerschner

Customer Name: Phil

Signature:

Signature

Name of the person authenticating this report on behalf of the author :-

Name:

D. SPARKMAN

Signature:

Name and address of Company responsible for this Thorough Examination

Hessle Fork Trucks - Head Office, Carrwood Road, Castleford, WF10 4PT