



Inspection Carried Out By:

Hessle Plant Ltd

Carrwood Road

Castleford

West Yorkshire

WF10 4PT

Tel: 01977 550557

E-Mail: mail@hessle.co.uk

Web Site: www.hessle.co.uk

Conducted in accordance with CFTS Publication GN28,
Regulation 9 of the 'Lifting Operations and Lifting Equipment Regulations 1998'
and the 'Provision and Use of Work Equipment Regulations 1998'

Site:	UPA - DURHAM UPA COURT UNIT 11 ALL SAINTS IND ESTATE SHILDON DL4 2RD	Regular Thorough Examination
--------------	---	-------------------------------------

Equip No:	17668	Inspect No:	22259
Make/Model:	MANITOU / 100VJR	Job No:	144210
Serial No:	K01136754	Contact:	
Last Inspection:	19/12/2024	Inspected:	05/09/2025
Meter:		Printed:	11/09/2025
		Page:	1 of 1

Items to Inspect	Result	Comments
RTE		
Reason For RTE?	Within 6 Month Interval	
Safe Working Load	Yes (Detail)	200kg
Date Of Manufacture	Yes (Detail)	2024
Is this the first examination after installation or assembly at new site/ location?	No	
If Yes to above, has the equipment been installed correctly?	Not Applicable	
A Defects	None	
Timescale For A Defect Repairs	Not Applicable	
B Defects	None	
Timescale For B Defect Repairs	Not Applicable	
C Observations	None	
Particulars of any tests carried out as part of examination	No	
I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28	No Faults Have Been Detected	
Is Machine Safe to use?	Yes	
Date Of Next Inspection	Yes (Detail)	05/03/2026

DECLARATION BY COMPETENT PERSON

I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28

Engineer Name: Rick Kuerschner

Customer Name: Customer Not Present

Signature:

Signature

:

Name of the person authenticating this report on behalf of the author :-

Name: O. SPERMAN

Signature:

Name and address of Company responsible for this Thorough Examination

Hessle Fork Trucks - Head Office, Carrwood Road, Castleford, WF10 4PT